

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, July 01, 2026

Rules: 0-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/30/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	43	86.7%	9,394	1,291	86.3%	81,359	11,129	86.3%
Central Division	88.0%	66	2	97.0%	2,006	230	88.5%	17,978	1,828	89.8%
Northeast Division	82.0%	106	21	80.2%	3,030	424	86.0%	25,709	4,004	84.4%
Southeast Division	83.0%	74	7	90.5%	2,113	264	87.5%	18,582	2,671	85.6%
Southwest Division	86.0%	77	13	83.1%	2,245	373	83.4%	19,090	2,626	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00580

Endpoint Arrival Dates through 6/30/26

UNCLASSIFIED

7/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	94,735	27,772	71%	3,298,076	984,299	70%	26,939,729	6,472,670	76%
Northeast Corridor	81%	39,050	9,766	75%	1,436,284	379,698	74%	11,845,410	2,783,447	77%
Acela	83%	7,105	1,507	79%	287,384	64,830	77%	2,336,133	602,317	74%
Northeast Regional	79%	31,945	8,259	74%	1,148,900	314,868	73%	9,509,277	2,181,130	77%
Richmond / Newport News / Norfolk	77%	9,877	3,498	65%	351,379	136,259	61%	2,951,397	814,118	72%
Springfield Shuttles	89%	640	5	99%	22,453	5,233	77%	169,022	24,448	86%
Roanoke	79%	3,458	515	85%	110,994	25,338	77%	893,747	175,361	80%
On Spine Northeast Regional	80%	17,970	4,241	76%	664,074	148,038	78%	5,495,111	1,167,203	79%
State Supported	80%	42,027	11,058	74%	1,468,299	373,644	75%	11,777,327	2,360,762	80%
Borealis	80%	542	27	95%	17,756	2,845	84%	150,749	30,365	80%
Capitol Corridor	90%	4,007	445	89%	120,841	17,295	86%	1,003,320	129,527	87%
Carolinian	70%	402	391	3%	33,294	20,154	39%	310,066	115,931	63%
Cascades	75%	2,868	936	67%	96,197	34,306	64%	687,649	188,581	73%
Downeaster	82%	1,475	371	75%	48,869	4,949	90%	396,297	45,289	89%
Empire	78%	5,382	3,689	31%	181,026	62,103	66%	1,454,074	314,524	78%
Adirondack	72%	393	359	9%	11,639	3,148	73%	86,447	25,479	71%
Ethan Allen Express	70%	509	501	2%	17,994	11,974	33%	150,985	47,617	68%
Maple Leaf	70%	793	719	9%	25,977	12,420	52%	175,298	66,986	62%
New York - Albany	85%	2,557	1,528	40%	82,743	20,145	76%	676,989	103,823	85%
New York - Niagara Falls	75%	1,130	582	48%	39,507	13,556	66%	361,189	69,759	81%
Berkshire Flyer	60%	0	0	-	3,166	860	73%	3,166	860	73%
Gold Runner	73%	2,080	869	58%	80,026	35,193	56%	673,876	232,149	66%
Heartland Flyer	70%	193	78	60%	7,792	2,553	67%	55,596	20,500	63%
Hiawatha	90%	1,688	0	100%	60,785	6,856	89%	457,774	50,551	89%
Illinois	78%	2,539	1,033	59%	81,012	27,288	66%	662,080	175,996	73%
Carl Sandburg / Illinois Zephyr	85%	483	213	56%	14,748	4,601	69%	109,539	27,784	75%
Illini / Saluki	85%	750	500	33%	26,216	9,050	65%	233,642	54,014	77%
Lincoln Service	70%	1,306	320	75%	40,048	13,637	66%	318,899	94,198	70%
Keystone	92%	8,375	159	98%	251,397	17,113	93%	2,058,957	209,978	90%
Lincoln / Missouri	70%	748	325	57%	27,786	17,865	36%	208,652	103,889	50%
Mardi Gras Service	80%	389	0	100%	11,514	5,234	55%	110,143	22,144	80%
Michigan	70%	2,210	933	58%	70,965	30,310	57%	519,988	165,050	68%
Blue Water	70%	542	542	0%	16,072	11,028	31%	120,317	45,371	62%
Pere Marquette	85%	176	0	100%	9,278	2,552	72%	67,552	13,337	80%
Wolverine	70%	1,492	391	74%	45,615	16,730	63%	332,119	106,342	68%
Missouri	80%	157	57	64%	7,388	2,176	71%	59,222	13,250	78%
Pacific Surfliner	85%	6,568	1,117	83%	278,343	55,002	80%	2,071,522	325,456	84%
Pennsylvanian	80%	818	62	92%	26,881	7,043	74%	238,742	42,184	82%
Piedmont	80%	630	0	100%	29,170	9,974	66%	313,164	78,495	75%
Vermont	75%	956	566	41%	37,257	15,385	59%	345,456	96,903	72%
Long Distance	70%	13,658	6,948	49%	393,493	230,957	41%	3,277,725	1,325,998	60%
Auto Train	70%	928	928	0%	25,019	10,806	57%	208,914	70,882	66%
California Zephyr	70%	1,077	208	81%	29,371	17,067	42%	259,404	84,877	67%
Cardinal	70%	0	0	-	7,137	4,833	32%	63,637	30,172	53%
City Of New Orleans	75%	0	0	-	16,833	11,620	31%	177,085	49,375	72%
Coast Starlight	70%	1,299	137	89%	37,961	17,404	54%	304,385	104,473	66%
Crescent	70%	953	121	87%	29,436	12,699	57%	249,641	71,500	71%
Empire Builder	70%	1,788	1,064	40%	35,504	24,888	30%	254,280	119,832	53%
Floridian	60%	2,732	1,876	31%	48,190	43,712	9%	430,001	283,428	34%
Lake Shore Ltd	73%	951	866	9%	33,223	12,362	63%	252,786	72,002	72%
Palmetto	70%	460	183	60%	27,788	14,139	49%	247,647	66,049	73%
Silver Meteor	70%	948	395	58%	31,420	19,245	39%	272,374	110,119	60%
Southwest Chief	60%	1,118	877	22%	29,308	23,777	19%	218,456	138,268	37%
Sunset Ltd	70%	398	109	73%	9,993	5,167	48%	78,258	26,646	66%
Texas Eagle	70%	1,006	184	82%	32,310	13,238	59%	260,857	98,375	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000100 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through June 30, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	197,685	3,266,695	605	1,566,813	28,640,081	547

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	9,194	2,413,020	38	73,331	12,386,810	59
INFRASTRUCTURE PLANNED	135	16,626	2,413,020	69	78,894	12,386,810	64
FLEET RELIABILITY	90	24,079	3,266,695	74	251,039	28,640,081	88
TRAIN OPERATIONS	424	147,786	3,266,695	452	1,163,549	28,640,081	406

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/30/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	43	86.7%	9,394	1,291	86.3%	81,359	11,129	86.3%
Central Division	88.0%	66	2	97.0%	2,006	230	88.5%	17,978	1,828	89.8%
Northeast Division	82.0%	106	21	80.2%	3,030	424	86.0%	25,709	4,004	84.4%
Southeast Division	83.0%	74	7	90.5%	2,113	264	87.5%	18,582	2,671	85.6%
Southwest Division	86.0%	77	13	83.1%	2,245	373	83.4%	19,090	2,626	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/30/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	43	86.7%	9,394	1,291	86.3%	81,359	11,129	86.3%
Central Division	88.0%	66	2	97.0%	2,006	230	88.5%	17,978	1,828	89.8%
CDL	95.0%	2	0	100.0%	63	4	93.7%	517	18	96.5%
CHI	86.0%	27	1	96.3%	812	111	86.3%	7,239	864	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	1	1	0.0%	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	60	2	96.7%	536	52	90.3%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	1	1	0.0%	1	1	0.0%
GRR	95.5%	-	-	-	28	0	100.0%	259	8	96.9%
IND	-	-	-	-	1	0	100.0%	1	0	100.0%
KCY	92.0%	2	0	100.0%	59	4	93.2%	538	40	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	176	11	93.8%	1,598	97	93.9%
MSP	96.5%	1	0	100.0%	30	1	96.7%	266	5	98.1%
PDX	86.0%	5	0	100.0%	148	26	82.4%	1,337	166	87.6%
PNT	88.0%	3	0	100.0%	88	4	95.5%	703	58	91.7%
PTH	93.0%	1	0	100.0%	30	0	100.0%	261	10	96.2%
QCY	91.0%	2	1	50.0%	57	5	91.2%	530	39	92.6%
SEA	85.0%	8	0	100.0%	241	48	80.1%	2,142	310	85.5%
SPK	90.0%	1	0	100.0%	30	3	90.0%	266	20	92.5%
STL	89.0%	4	0	100.0%	120	6	95.0%	1,057	90	91.5%
TOL	-	-	-	-	1	1	0.0%	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	60	2	96.7%	530	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	106	21	80.2%	3,030	424	86.0%	25,709	4,004	84.4%
ALB	88.5%	8	0	100.0%	234	9	96.2%	2,014	161	92.0%
BON	87.5%	5	2	60.0%	149	12	91.9%	1,312	140	89.3%
BOS	85.5%	18	2	88.9%	527	41	92.2%	4,640	562	87.9%
BRK	92.5%	5	1	80.0%	147	18	87.8%	1,301	84	93.5%
BTN	82.0%	1	0	100.0%	30	2	93.3%	259	39	84.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	59	5	91.5%	531	50	90.6%
HFD	-	2	1	50.0%	44	1	97.7%	147	8	94.6%
MTR	79.0%	1	1	0.0%	30	5	83.3%	256	46	82.0%
NFL	93.5%	2	0	100.0%	60	0	100.0%	550	22	96.0%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	6	1	83.3%	149	7	95.3%	1,406	223	84.1%
NYP	75.5%	50	12	76.0%	1,375	299	78.3%	11,054	2,462	77.7%
PIT	76.0%	-	-	-	6	5	16.7%	6	5	16.7%
POR	-	-	-	-	3	2	33.3%	8	5	37.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/30/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	43	86.7%	9,394	1,291	86.3%	81,359	11,129	86.3%
Northeast Division	82.0%	106	21	80.2%	3,030	424	86.0%	25,709	4,004	84.4%
SAB	98.0%	-	-	-	28	2	92.9%	259	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SPG	92.5%	5	0	100.0%	159	12	92.5%	1,652	92	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	30	4	86.7%	259	56	78.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	74	7	90.5%	2,113	264	87.5%	18,582	2,671	85.6%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	5	0	100.0%	147	23	84.4%	1,341	132	90.2%
GRO	-	2	1	50.0%	12	5	58.3%	29	10	65.5%
HAR	79.5%	13	1	92.3%	342	29	91.5%	3,023	506	83.3%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	30	3	90.0%	269	34	87.4%
MIA	89.5%	2	1	50.0%	60	14	76.7%	539	60	88.9%
MOE	97.5%	2	0	100.0%	60	1	98.3%	545	8	98.5%
NFK	84.5%	2	0	100.0%	60	17	71.7%	621	109	82.4%
NOL	94.5%	3	0	100.0%	127	8	93.7%	1,150	53	95.4%
NPN	93.0%	2	0	100.0%	60	6	90.0%	513	35	93.2%
PGH	93.0%	1	0	100.0%	30	2	93.3%	271	19	93.0%
PHL	48.0%	5	2	60.0%	142	59	58.5%	1,400	677	51.6%
RGH	95.0%	2	0	100.0%	106	4	96.2%	1,057	41	96.1%
RNK	83.5%	2	0	100.0%	60	6	90.0%	534	77	85.6%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	30	2	93.3%	268	10	96.3%
SFA	88.0%	1	0	100.0%	30	7	76.7%	269	37	86.2%
WAS	84.0%	30	2	93.3%	817	78	90.5%	6,596	841	87.2%
Southwest Division	86.0%	77	13	83.1%	2,245	373	83.4%	19,090	2,626	86.2%
ARN	92.0%	1	0	100.0%	29	2	93.1%	271	19	93.0%
BFD	79.0%	7	1	85.7%	200	53	73.5%	1,686	341	79.8%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	0	100.0%	30	12	60.0%	287	86	70.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	30	2	93.3%	296	34	88.5%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	1	0	100.0%	1	0	100.0%
GTA	90.0%	3	1	66.7%	90	31	65.6%	816	114	86.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	318	38	88.1%	2,676	277	89.6%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	0	100.0%	30	2	93.3%	267	6	97.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/30/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/30/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	43	86.7%	9,394	1,291	86.3%	81,359	11,129	86.3%
Southwest Division	86.0%	77	13	83.1%	2,245	373	83.4%	19,090	2,626	86.2%
OKJ	74.5%	13	6	53.8%	352	101	71.3%	2,899	736	74.6%
RNO	-	-	-	-	1	0	100.0%	2	1	50.0%
SAC	88.5%	16	1	93.8%	447	68	84.8%	3,805	411	89.2%
SAN	90.5%	13	3	76.9%	389	30	92.3%	3,244	294	90.9%
SAS	90.5%	1	0	100.0%	30	4	86.7%	269	27	90.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	1	85.7%	210	17	91.9%	1,907	183	90.4%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	88	13	85.2%	579	60	89.6%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		12	2	83.3%	115	25	78.3%	13	4	69.2%	112	20	82.1%
3	38	30	12	60.0%	271	54	80.1%	29	16	44.8%	269	117	56.5%
4	63	29	9	69.0%	270	42	84.4%	29	22	24.1%	270	179	33.7%
5		29	5	82.8%	269	43	84.0%	30	15	50.0%	266	63	76.3%
6		30	11	63.3%	269	78	71.0%	30	18	40.0%	269	83	69.1%
7		30	7	76.7%	260	35	86.5%	30	13	56.7%	253	61	75.9%
8	273	30	18	40.0%	260	111	57.3%	30	27	10.0%	259	149	42.5%
11		30	8	73.3%	271	50	81.5%	30	9	70.0%	265	54	79.6%
14		30	4	86.7%	272	42	84.6%	30	19	36.7%	270	83	69.3%
19		30	9	70.0%	270	65	75.9%	29	11	62.1%	268	59	78.0%
20		30	2	93.3%	270	18	93.3%	30	10	66.7%	270	47	82.6%
21		30	0	100.0%	267	22	91.8%	30	5	83.3%	266	62	76.7%
22		30	4	86.7%	268	25	90.7%	30	11	63.3%	266	62	76.7%
23		30	0	100.0%	273	5	98.2%	29	15	48.3%	271	69	74.5%
24		30	0	100.0%	273	14	94.9%	30	13	56.7%	272	43	84.2%
25		30	1	96.7%	272	3	98.9%	29	15	48.3%	270	69	74.4%
26		30	2	93.3%	272	5	98.2%	29	14	51.7%	270	52	80.7%
27		30	5	83.3%	258	17	93.4%	30	16	46.7%	254	81	68.1%
28		30	13	56.7%	254	59	76.8%	30	15	50.0%	254	51	79.9%
40	109	30	10	66.7%	266	38	85.7%	30	28	6.7%	265	132	50.2%
41	69	30	11	63.3%	266	102	61.7%	30	28	6.7%	264	196	25.8%
42		30	2	93.3%	272	20	92.6%	30	3	90.0%	270	42	84.4%
43		30	4	86.7%	271	41	84.9%	30	14	53.3%	271	56	79.3%
48		30	4	86.7%	270	53	80.4%	30	3	90.0%	270	38	85.9%
49	31	30	6	80.0%	270	67	75.2%	30	6	80.0%	270	52	80.7%
52	41	30	7	76.7%	269	37	86.2%	30	9	70.0%	268	61	77.2%
53	39	30	3	90.0%	269	34	87.4%	30	14	53.3%	268	85	68.3%
55	64	21	2	90.5%	168	6	96.4%	21	7	66.7%	165	34	79.4%
56		22	2	90.9%	169	22	87.0%	21	5	76.2%	166	26	84.3%
63	146	30	10	66.7%	273	117	57.1%	30	25	16.7%	269	140	48.0%
64	85	30	4	86.7%	271	63	76.8%	30	23	23.3%	271	91	66.4%
66		30	3	90.0%	270	54	80.0%	30	6	80.0%	268	49	81.7%
67	23	22	0	100.0%	187	11	94.1%	22	4	81.8%	187	31	83.4%
68	20	30	5	83.3%	273	55	79.9%	30	8	73.3%	273	103	62.3%
69	106	30	13	56.7%	260	59	77.3%	30	9	70.0%	256	32	87.5%
71		30	0	100.0%	268	3	98.9%	30	10	66.7%	267	66	75.3%
72	14	30	7	76.7%	268	29	89.2%	30	13	56.7%	267	55	79.4%
73		30	5	83.3%	272	16	94.1%	29	11	62.1%	270	126	53.3%
74		28	3	89.3%	270	30	88.9%	28	15	46.4%	268	94	64.9%
75		29	4	86.2%	270	14	94.8%	28	15	46.4%	265	125	52.8%
76		29	1	96.6%	270	26	90.4%	28	6	78.6%	262	104	60.3%
77		29	0	100.0%	269	17	93.7%	29	16	44.8%	267	108	59.6%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		30	6	80.0%	268	20	92.5%	30	10	66.7%	267	50	81.3%
79	84	30	8	73.3%	270	55	79.6%	30	18	40.0%	269	84	68.8%
80		30	6	80.0%	270	28	89.6%	29	13	55.2%	268	49	81.7%
84	40	22	0	100.0%	162	11	93.2%	22	9	59.1%	160	35	78.1%
85		22	1	95.5%	170	16	90.6%	22	11	50.0%	170	61	64.1%
86		22	3	86.4%	170	14	91.8%	22	17	22.7%	169	100	40.8%
89	66	30	6	80.0%	268	58	78.4%	30	11	63.3%	266	70	73.7%
90	71	30	2	93.3%	268	10	96.3%	30	11	63.3%	267	37	86.1%
93		22	0	100.0%	169	18	89.3%	22	7	68.2%	168	37	78.0%
94		22	8	63.6%	200	50	75.0%	22	8	63.6%	198	69	65.2%
95	18	22	0	100.0%	169	3	98.2%	22	11	50.0%	169	59	65.1%
97		30	23	23.3%	270	173	35.9%	30	16	46.7%	268	76	71.6%
98	252	30	4	86.7%	270	21	92.2%	30	15	50.0%	268	80	70.1%
110		21	13	38.1%	166	96	42.2%	21	1	95.2%	163	16	90.2%
111		22	4	81.8%	160	32	80.0%	22	2	90.9%	158	20	87.3%
112		22	1	95.5%	160	16	90.0%	22	1	95.5%	159	17	89.3%
113		22	7	68.2%	91	22	75.8%	22	3	86.4%	90	11	87.8%
119		22	7	68.2%	160	43	73.1%	22	2	90.9%	158	20	87.3%
125	95	22	0	100.0%	170	8	95.3%	22	12	45.5%	170	66	61.2%
129		22	4	81.8%	169	44	74.0%	22	4	81.8%	169	23	86.4%
130		22	2	90.9%	160	16	90.0%	22	3	86.4%	158	15	90.5%
131		22	7	68.2%	162	47	71.0%	22	2	90.9%	162	29	82.1%
134	17	22	3	86.4%	170	21	87.6%	22	3	86.4%	169	26	84.6%
136		22	2	90.9%	170	20	88.2%	21	2	90.5%	168	17	89.9%
137	24	22	2	90.9%	167	30	82.0%	22	9	59.1%	167	52	68.9%
138		22	6	72.7%	170	35	79.4%	22	9	59.1%	169	27	84.0%
141		22	0	100.0%	169	3	98.2%	22	2	90.9%	168	28	83.3%
148	34	22	2	90.9%	169	17	89.9%	22	3	86.4%	167	30	82.0%
151	29	30	11	63.3%	269	86	68.0%	30	10	66.7%	268	84	68.7%
170		22	1	95.5%	165	12	92.7%	22	1	95.5%	164	29	82.3%
171		22	0	100.0%	170	10	94.1%	22	13	40.9%	170	61	64.1%
172	30	22	0	100.0%	169	14	91.7%	22	10	54.5%	167	55	67.1%
173	17	22	2	90.9%	165	23	86.1%	22	12	45.5%	164	73	55.5%
174	16	22	3	86.4%	170	20	88.2%	22	11	50.0%	170	38	77.6%
175	No OS	22	2	90.9%	170	21	87.6%	22	8	63.6%	170	55	67.6%
176		22	3	86.4%	165	14	91.5%	22	1	95.5%	163	15	90.8%
177		22	2	90.9%	170	24	85.9%	22	2	90.9%	170	44	74.1%
178		22	2	90.9%	170	24	85.9%	21	1	95.2%	168	23	86.3%
179		22	5	77.3%	170	19	88.8%	21	10	52.4%	169	58	65.7%
181		22	10	54.5%	166	54	67.5%	22	3	86.4%	164	12	92.7%
182		22	3	86.4%	160	28	82.5%	22	2	90.9%	158	16	89.9%
183		22	4	81.8%	169	48	71.6%	22	1	95.5%	167	33	80.2%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		22	3	86.4%	170	29	82.9%	22	2	90.9%	169	23	86.4%
185		22	2	90.9%	170	36	78.8%	22	1	95.5%	170	11	93.5%
186	18	22	3	86.4%	169	17	89.9%	22	10	54.5%	168	40	76.2%
190		22	8	63.6%	169	62	63.3%	22	3	86.4%	168	37	78.0%
192		22	0	100.0%	167	19	88.6%	22	1	95.5%	167	14	91.6%
193	31	22	11	50.0%	169	71	58.0%	22	15	31.8%	168	80	52.4%
196		22	5	77.3%	169	18	89.3%	22	2	90.9%	168	15	91.1%
197		22	5	77.3%	170	68	60.0%	22	10	54.5%	170	53	68.8%
198		22	3	86.4%	102	14	86.3%	21	4	81.0%	101	16	84.2%
230	53	30	0	100.0%	107	4	96.3%	30	1	96.7%	107	6	94.4%
232		30	1	96.7%	273	11	96.0%	30	1	96.7%	273	17	93.8%
233	34	24	7	70.8%	251	56	77.7%	24	20	16.7%	251	73	70.9%
234	19	30	0	100.0%	273	19	93.0%	30	3	90.0%	273	24	91.2%
235	60	30	6	80.0%	197	27	86.3%	30	11	63.3%	197	41	79.2%
236	29	30	0	100.0%	257	7	97.3%	30	8	73.3%	257	36	86.0%
237		29	3	89.7%	271	52	80.8%	29	4	86.2%	269	43	84.0%
238		30	2	93.3%	197	19	90.4%	30	4	86.7%	196	14	92.9%
239	26	30	5	83.3%	272	72	73.5%	30	6	80.0%	271	30	88.9%
240	24	30	2	93.3%	272	20	92.6%	29	16	44.8%	270	44	83.7%
241	27	30	5	83.3%	273	68	75.1%	30	10	66.7%	273	66	75.8%
243		30	4	86.7%	209	55	73.7%	29	2	93.1%	208	26	87.5%
244		24	1	95.8%	251	10	96.0%	24	4	83.3%	251	38	84.9%
245		30	6	80.0%	154	27	82.5%	30	4	86.7%	153	17	88.9%
280	26	30	0	100.0%	273	11	96.0%	30	10	66.7%	273	50	81.7%
281	42	30	4	86.7%	273	29	89.4%	30	11	63.3%	273	47	82.8%
283	26	30	12	60.0%	273	64	76.6%	30	9	70.0%	273	52	81.0%
284		30	0	100.0%	273	10	96.3%	30	8	73.3%	271	42	84.5%
290	48	30	2	93.3%	273	48	82.4%	30	20	33.3%	271	91	66.4%
291	56	30	19	36.7%	272	75	72.4%	30	20	33.3%	270	58	78.5%
300		30	1	96.7%	257	19	92.6%	30	7	76.7%	255	56	78.0%
301		30	1	96.7%	271	9	96.7%	30	7	76.7%	268	50	81.3%
302		30	3	90.0%	258	31	88.0%	29	9	69.0%	254	72	71.7%
305	44	30	2	93.3%	261	28	89.3%	30	13	56.7%	257	102	60.3%
306		30	2	93.3%	269	15	94.4%	30	13	56.7%	268	71	73.5%
307		30	5	83.3%	261	35	86.6%	30	9	70.0%	258	70	72.9%
311		30	0	100.0%	271	23	91.5%	29	5	82.8%	266	50	81.2%
316	90	29	0	100.0%	268	16	94.0%	29	12	58.6%	265	64	75.8%
318	24	30	4	86.7%	272	26	90.4%	30	22	26.7%	269	124	53.9%
319	37	30	3	90.0%	273	17	93.8%	30	23	23.3%	271	145	46.5%
329		22	1	95.5%	192	8	95.8%	22	1	95.5%	192	13	93.2%
330		26	0	100.0%	231	4	98.3%	26	0	100.0%	231	13	94.4%
331		30	3	90.0%	273	29	89.4%	30	4	86.7%	273	40	85.3%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		30	2	93.3%	273	14	94.9%	30	5	83.3%	273	39	85.7%
334		30	3	90.0%	273	9	96.7%	30	7	76.7%	272	36	86.8%
335	13	30	3	90.0%	273	30	89.0%	30	4	86.7%	271	43	84.1%
336		30	0	100.0%	273	8	97.1%	30	6	80.0%	271	25	90.8%
337		30	0	100.0%	273	17	93.8%	30	4	86.7%	269	33	87.7%
338	14	30	4	86.7%	273	41	85.0%	30	11	63.3%	271	81	70.1%
339		30	4	86.7%	273	46	83.2%	30	6	80.0%	273	48	82.4%
341		29	4	86.2%	262	35	86.6%	27	4	85.2%	257	35	86.4%
342		30	2	93.3%	273	21	92.3%	30	9	70.0%	271	53	80.4%
350		30	2	93.3%	254	17	93.3%	30	21	30.0%	249	136	45.4%
351		30	3	90.0%	256	25	90.2%	29	6	79.3%	254	68	73.2%
352		29	3	89.7%	240	20	91.7%	28	8	71.4%	234	71	69.7%
353		29	0	100.0%	215	12	94.4%	29	5	82.8%	209	35	83.3%
354	52	30	9	70.0%	254	28	89.0%	30	13	56.7%	250	89	64.4%
355		29	1	96.6%	267	27	89.9%	28	9	67.9%	260	85	67.3%
364	36	30	10	66.7%	262	60	77.1%	30	20	33.3%	256	90	64.8%
365	53	30	0	100.0%	261	10	96.2%	30	20	33.3%	259	92	64.5%
370		30	4	86.7%	264	33	87.5%	27	11	59.3%	257	65	74.7%
380		29	1	96.6%	259	24	90.7%	29	7	75.9%	259	49	81.1%
381	23	30	2	93.3%	273	11	96.0%	29	10	65.5%	272	48	82.4%
382	34	29	5	82.8%	272	16	94.1%	29	13	55.2%	272	84	69.1%
383	57	30	2	93.3%	262	25	90.5%	30	18	40.0%	260	105	59.6%
390	29	30	2	93.3%	255	17	93.3%	30	11	63.3%	254	63	75.2%
391	27	30	2	93.3%	258	8	96.9%	30	19	36.7%	255	65	74.5%
392	77	30	1	96.7%	272	5	98.2%	30	12	60.0%	270	78	71.1%
393	23	30	1	96.7%	273	16	94.1%	29	13	55.2%	270	77	71.5%
417		22	6	72.7%	180	38	78.9%	22	3	86.4%	171	17	90.1%
425		21	0	100.0%	182	6	96.7%	21	0	100.0%	182	7	96.2%
448	112	30	5	83.3%	203	39	80.8%	30	10	66.7%	201	68	66.2%
449	71	30	3	90.0%	201	30	85.1%	30	7	76.7%	201	36	82.1%
470		23	3	87.0%	193	34	82.4%	22	2	90.9%	187	23	87.7%
471		22	1	95.5%	183	6	96.7%	22	0	100.0%	183	2	98.9%
473		22	0	100.0%	189	13	93.1%	22	0	100.0%	186	8	95.7%
474		23	7	69.6%	184	51	72.3%	22	13	40.9%	172	47	72.7%
475		21	2	90.5%	187	5	97.3%	21	4	81.0%	187	10	94.7%
478		22	1	95.5%	181	27	85.1%	22	4	81.8%	179	20	88.8%
479		22	4	81.8%	188	29	84.6%	22	6	72.7%	186	22	88.2%
486		22	3	86.4%	192	28	85.4%	22	8	63.6%	186	50	73.1%
494		22	4	81.8%	193	35	81.9%	22	3	86.4%	187	44	76.5%
495		22	0	100.0%	178	3	98.3%	22	0	100.0%	176	3	98.3%
500	42	29	0	100.0%	264	15	94.3%	29	4	86.2%	262	32	87.8%
502		30	2	93.3%	271	15	94.5%	30	3	90.0%	268	56	79.1%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
503		30	5	83.3%	269	25	90.7%	30	15	50.0%	263	74	71.9%
504		30	1	96.7%	273	17	93.8%	30	12	60.0%	271	82	69.7%
505		30	6	80.0%	271	36	86.7%	29	11	62.1%	267	73	72.7%
506		30	5	83.3%	268	38	85.8%	29	6	79.3%	263	41	84.4%
507		30	6	80.0%	273	34	87.5%	30	15	50.0%	273	88	67.8%
508		30	1	96.7%	268	39	85.4%	30	10	66.7%	265	62	76.6%
509		30	1	96.7%	270	12	95.6%	30	9	70.0%	270	63	76.7%
511		30	1	96.7%	265	21	92.1%	30	4	86.7%	264	45	83.0%
516	43	30	3	90.0%	265	27	89.8%	30	20	33.3%	264	123	53.4%
517		30	1	96.7%	273	8	97.1%	29	19	34.5%	269	108	59.9%
518	51	30	6	80.0%	273	35	87.2%	30	25	16.7%	271	183	32.5%
519	33	30	1	96.7%	265	9	96.6%	30	6	80.0%	263	63	76.0%
520		22	6	72.7%	150	24	84.0%	22	1	95.5%	147	9	93.9%
521		22	1	95.5%	188	7	96.3%	22	3	86.4%	188	23	87.8%
522		22	8	63.6%	188	36	80.9%	22	2	90.9%	185	18	90.3%
523		22	0	100.0%	188	6	96.8%	22	2	90.9%	187	22	88.2%
524		22	1	95.5%	188	12	93.6%	21	2	90.5%	186	20	89.2%
525		22	2	90.9%	186	12	93.5%	21	1	95.2%	183	13	92.9%
526		22	6	72.7%	162	29	82.1%	21	1	95.2%	159	12	92.5%
527		22	3	86.4%	188	9	95.2%	21	3	85.7%	187	32	82.9%
528		22	2	90.9%	188	15	92.0%	22	0	100.0%	187	29	84.5%
529	18	22	1	95.5%	188	11	94.1%	22	8	63.6%	187	50	73.3%
530	15	22	2	90.9%	142	14	90.1%	22	4	81.8%	142	26	81.7%
531		22	2	90.9%	162	12	92.6%	22	1	95.5%	162	11	93.2%
532		22	8	63.6%	188	43	77.1%	21	4	81.0%	187	27	85.6%
534	33	22	5	77.3%	147	24	83.7%	21	4	81.0%	145	15	89.7%
535		22	2	90.9%	175	23	86.9%	22	0	100.0%	170	20	88.2%
536		22	6	72.7%	188	49	73.9%	22	2	90.9%	185	37	80.0%
537	12	22	5	77.3%	159	18	88.7%	22	5	77.3%	154	16	89.6%
538		22	2	90.9%	188	23	87.8%	21	5	76.2%	187	37	80.2%
539	16	22	9	59.1%	142	21	85.2%	22	12	45.5%	142	64	54.9%
540		22	3	86.4%	188	35	81.4%	22	2	90.9%	181	18	90.1%
541		22	4	81.8%	187	21	88.8%	20	2	90.0%	182	33	81.9%
542		22	1	95.5%	187	21	88.8%	22	3	86.4%	185	32	82.7%
543		22	4	81.8%	188	19	89.9%	22	5	77.3%	188	50	73.4%
544		22	1	95.5%	186	20	89.2%	22	1	95.5%	183	15	91.8%
545		22	3	86.4%	188	15	92.0%	22	4	81.8%	186	22	88.2%
547		22	4	81.8%	188	37	80.3%	22	4	81.8%	188	44	76.6%
548		18	0	100.0%	184	20	89.1%	18	1	94.4%	183	14	92.3%
549		22	4	81.8%	183	25	86.3%	19	2	89.5%	176	16	90.9%
550		22	1	95.5%	142	14	90.1%	22	8	63.6%	142	31	78.2%
551		22	4	81.8%	184	19	89.7%	22	3	86.4%	176	17	90.3%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		30	3	90.0%	265	21	92.1%	30	2	93.3%	262	29	88.9%
564		30	4	86.7%	265	17	93.6%	30	4	86.7%	257	30	88.3%
566		30	1	96.7%	263	17	93.5%	30	2	93.3%	260	32	87.7%
567		30	2	93.3%	150	8	94.7%	30	1	96.7%	148	6	95.9%
572	31	30	1	96.7%	260	22	91.5%	30	13	56.7%	255	65	74.5%
573		30	5	83.3%	263	40	84.8%	30	7	76.7%	256	44	82.8%
579		30	0	100.0%	150	8	94.7%	30	5	83.3%	145	26	82.1%
580		30	3	90.0%	265	14	94.7%	29	2	93.1%	260	21	91.9%
581	17	30	5	83.3%	265	43	83.8%	30	9	70.0%	263	54	79.5%
584	Cncld	30	4	86.7%	149	17	88.6%	29	19	34.5%	145	82	43.4%
587	203	30	1	96.7%	260	15	94.2%	30	8	73.3%	251	38	84.9%
588	67	30	3	90.0%	150	12	92.0%	29	5	82.8%	149	22	85.2%
591	151	30	3	90.0%	264	18	93.2%	29	6	79.3%	258	29	88.8%
593	Cncld	30	4	86.7%	259	37	85.7%	28	3	89.3%	241	27	88.8%
595	27	29	3	89.7%	260	41	84.2%	28	6	78.6%	257	46	82.1%
600		22	0	100.0%	197	9	95.4%	22	1	95.5%	195	15	92.3%
601		22	2	90.9%	180	72	60.0%	22	0	100.0%	177	23	87.0%
605		22	13	40.9%	187	118	36.9%	22	0	100.0%	183	19	89.6%
607		22	5	77.3%	196	24	87.8%	22	1	95.5%	193	22	88.6%
609		22	0	100.0%	187	22	88.2%	22	1	95.5%	186	15	91.9%
622		18	1	94.4%	103	30	70.9%	17	0	100.0%	101	5	95.0%
626		22	1	95.5%	101	12	88.1%	22	1	95.5%	99	15	84.8%
639		22	4	81.8%	168	37	78.0%	22	1	95.5%	167	19	88.6%
640		22	1	95.5%	187	7	96.3%	22	6	72.7%	185	76	58.9%
641		22	6	72.7%	169	34	79.9%	22	3	86.4%	169	25	85.2%
642		22	3	86.4%	185	9	95.1%	22	1	95.5%	184	23	87.5%
643		22	0	100.0%	199	39	80.4%	21	1	95.2%	196	32	83.7%
644		22	1	95.5%	191	27	85.9%	22	4	81.8%	189	48	74.6%
645		22	3	86.4%	199	38	80.9%	22	6	72.7%	197	39	80.2%
646		22	1	95.5%	188	46	75.5%	22	6	72.7%	186	89	52.2%
647		22	0	100.0%	199	31	84.4%	22	4	81.8%	198	43	78.3%
648		22	3	86.4%	195	50	74.4%	22	0	100.0%	195	31	84.1%
649		22	6	72.7%	200	37	81.5%	22	0	100.0%	197	31	84.3%
650		22	1	95.5%	199	39	80.4%	22	4	81.8%	196	30	84.7%
651		22	1	95.5%	199	16	92.0%	22	3	86.4%	197	39	80.2%
652		22	2	90.9%	200	27	86.5%	22	1	95.5%	196	32	83.7%
653		22	2	90.9%	188	30	84.0%	21	3	85.7%	185	34	81.6%
654		22	0	100.0%	189	36	81.0%	22	0	100.0%	186	16	91.4%
655		22	6	72.7%	197	69	65.0%	22	8	63.6%	195	68	65.1%
656		22	5	77.3%	199	45	77.4%	22	0	100.0%	198	21	89.4%
657		22	1	95.5%	188	26	86.2%	22	5	77.3%	187	28	85.0%
658		22	4	81.8%	199	34	82.9%	22	1	95.5%	197	30	84.8%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		22	2	90.9%	193	9	95.3%	22	2	90.9%	192	24	87.5%
681		22	2	90.9%	193	14	92.7%	22	10	54.5%	188	72	61.7%
682		22	2	90.9%	192	5	97.4%	22	2	90.9%	192	33	82.8%
683	13	22	0	100.0%	175	15	91.4%	22	9	59.1%	174	51	70.7%
684	25	22	8	63.6%	174	27	84.5%	22	5	77.3%	174	38	78.2%
685	Cncld	22	3	86.4%	189	28	85.2%	21	4	81.0%	186	44	76.3%
686		22	3	86.4%	194	33	83.0%	21	2	90.5%	193	36	81.3%
687	36	21	1	95.2%	193	30	84.5%	21	4	81.0%	192	31	83.9%
688		22	4	81.8%	192	9	95.3%	21	3	85.7%	191	30	84.3%
701		30	6	80.0%	205	21	89.8%	30	7	76.7%	202	20	90.1%
702		30	5	83.3%	272	31	88.6%	29	9	69.0%	270	60	77.8%
703		30	15	50.0%	273	77	71.8%	30	12	60.0%	272	70	74.3%
704		30	5	83.3%	204	32	84.3%	29	4	86.2%	199	38	80.9%
710	57	30	5	83.3%	273	69	74.7%	30	13	56.7%	269	73	72.9%
711	51	30	6	80.0%	264	28	89.4%	29	9	69.0%	247	45	81.8%
712		30	11	63.3%	270	71	73.7%	30	15	50.0%	262	87	66.8%
713		20	1	95.0%	146	14	90.4%	20	6	70.0%	133	56	57.9%
714	40	29	14	51.7%	155	58	62.6%	25	16	36.0%	143	58	59.4%
715		30	6	80.0%	272	58	78.7%	26	16	38.5%	253	125	50.6%
716	22	30	9	70.0%	273	107	60.8%	30	12	60.0%	268	102	61.9%
717		30	10	66.7%	259	62	76.1%	26	12	53.8%	241	70	71.0%
718	28	30	17	43.3%	273	136	50.2%	30	13	56.7%	271	91	66.4%
719	22	30	9	70.0%	273	88	67.8%	28	8	71.4%	259	72	72.2%
757		30	2	93.3%	58	3	94.8%	29	3	89.7%	57	4	93.0%
761		30	2	93.3%	269	11	95.9%	30	2	93.3%	266	34	87.2%
765		30	0	100.0%	269	24	91.1%	30	1	96.7%	269	36	86.6%
769	24	30	2	93.3%	269	25	90.7%	30	6	80.0%	263	49	81.4%
770		30	1	96.7%	269	21	92.2%	30	12	60.0%	267	74	72.3%
774		30	0	100.0%	269	16	94.1%	30	7	76.7%	268	56	79.1%
777		30	0	100.0%	154	9	94.2%	29	4	86.2%	153	34	77.8%
782		30	28	6.7%	154	56	63.6%	30	5	83.3%	149	15	89.9%
785		30	4	86.7%	269	17	93.7%	30	7	76.7%	269	46	82.9%
786	121	30	11	63.3%	58	16	72.4%	30	15	50.0%	57	27	52.6%
790	39	30	2	93.3%	269	26	90.3%	29	6	79.3%	266	32	88.0%
794		30	2	93.3%	269	31	88.5%	29	4	86.2%	266	55	79.3%
821		30	2	93.3%	267	6	97.8%	30	10	66.7%	267	103	61.4%
822	27	30	2	93.3%	269	14	94.8%	30	14	53.3%	267	118	55.8%
1333		30	2	93.3%	269	28	89.6%	30	9	70.0%	266	88	66.9%
1340		30	1	96.7%	268	5	98.1%	30	3	90.0%	268	42	84.3%
1689		16	0	100.0%	74	5	93.2%	15	2	86.7%	73	8	89.0%
2102	21	22	4	81.8%	46	12	73.9%	22	2	90.9%	45	4	91.1%
2103		22	1	95.5%	110	10	90.9%	22	3	86.4%	109	9	91.7%

Amtrak On Time Performance

Trains Arriving Through: 6/30/2026

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2104		22	0	100.0%	136	9	93.4%	22	1	95.5%	134	10	92.5%
2107		22	4	81.8%	167	30	82.0%	22	2	90.9%	164	20	87.8%
2108		22	2	90.9%	167	25	85.0%	22	1	95.5%	161	17	89.4%
2109		7	2	71.4%	60	9	85.0%	7	1	85.7%	59	4	93.2%
2112		7	2	71.4%	7	2	71.4%	6	0	100.0%	6	0	100.0%
2113	25	22	1	95.5%	46	3	93.5%	22	3	86.4%	46	7	84.8%
2115		22	3	86.4%	46	5	89.1%	21	1	95.2%	45	4	91.1%
2116	22	7	0	100.0%	7	0	100.0%	7	2	71.4%	7	2	71.4%
2118	40	7	0	100.0%	7	0	100.0%	7	2	71.4%	7	2	71.4%
2119		7	2	71.4%	7	2	71.4%	7	1	85.7%	7	1	85.7%
2120	23	7	3	57.1%	7	3	57.1%	7	3	57.1%	7	3	57.1%
2123		21	3	85.7%	45	6	86.7%	21	6	71.4%	45	13	71.1%
2124	Cncld	22	4	81.8%	139	23	83.5%	21	3	85.7%	137	13	90.5%
2127		7	1	85.7%	7	1	85.7%	6	0	100.0%	6	0	100.0%
2128		7	0	100.0%	7	0	100.0%	7	0	100.0%	7	0	100.0%
2131		7	0	100.0%	7	0	100.0%	7	0	100.0%	7	0	100.0%
2150		22	0	100.0%	160	22	86.3%	22	3	86.4%	157	67	57.3%
2151		22	2	90.9%	109	6	94.5%	22	6	72.7%	107	29	72.9%
2152		7	0	100.0%	68	3	95.6%	7	0	100.0%	67	26	61.2%
2154		7	0	100.0%	72	20	72.2%	7	2	71.4%	69	36	47.8%
2155		22	1	95.5%	169	14	91.7%	21	8	61.9%	165	90	45.5%
2158		7	2	71.4%	7	2	71.4%	7	0	100.0%	7	0	100.0%
2159	Cncld	22	2	90.9%	162	11	93.2%	21	8	61.9%	160	48	70.0%
2160	44	7	0	100.0%	7	0	100.0%	7	4	42.9%	7	4	42.9%
2165	17	7	0	100.0%	7	0	100.0%	7	2	71.4%	7	2	71.4%
2167		22	0	100.0%	159	18	88.7%	22	4	81.8%	159	36	77.4%
2171		22	1	95.5%	96	8	91.7%	22	1	95.5%	93	18	80.6%
2190		22	1	95.5%	168	24	85.7%	22	1	95.5%	166	22	86.7%
2193		20	2	90.0%	165	23	86.1%	20	1	95.0%	163	45	72.4%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2102	NYP	21	CAR	29	CAR	22	BAL-BAL	AM	Door, 3733 NG NB, Cut out doors
2113	WAS	25	DMW	9	DMW	9	XCY-XHM	AM	Held for or routed around MW work or equipment, Other, XMO-XHM, OPR 4 TRK A/C TRACK DEFECT ON 3 TRK BETWEEN MORRIS & GRUNDY
2116	NYP	22	SMW	14	SMW	8	NWK-NYP	AM	Scheduled in track usage program, Other, PORTAL OUTAGE
2118	NYP	40	DDA	21	DDA	21	XPV-WIL	AM	Dragger - no exceptions, Control Point, ., ACTUATED DRAGGER AT MP.55.3. STOPPED TO INSPECT. NO EXCEPTIONS.
2120	NYP	23	SMW	16	SMW	9	MET-NYP	AM	Scheduled in track usage program, Other, PORTAL OUTAGE
2124	XHM	Trn Cancelled							
2159	XHM	Trn Cancelled							
2160	BOS	44	SMW	19	CAR	8	BWI-BWI	AM	Door, ENTIRE TRAIN, DOOR ISSUES.
2165	WAS	17	OTH	16	OTH	6	PHL-WIL	AM	Lost time - N.A.R., PRT
67	NPN	23	OTH	30	ENG	15	XVG-ALX	CS	Radio failure Radio was NOT working well., 330
84	NYP	40	MTI	17	ADA	12	ABE-ABE	AM	Wheelchair
95	NFK	18	WTR	24	CTI	10	WDB-FBG	CS	Follow VRE, 303, Other, WDB
125	NPN	95	FTI	67	FTI	51	FBG-ASD	CS	Had to make reverse move @ FB and XR in order to let VRE and Amtrak pass due to CSX 415 broken down in interlocking 415, Other, cfp 58.9
134	NYP	17	WTR	12	OTH	6	BAL-XPV	AM	Lost time - N.A.R., PURE RUN TIME
137	WAS	24	DSR	40	DSR	21	BRP-STM	MN	Per bulletin Milepost w/Letters, BRP, STM, 30, 2
148	SPG	34	CTI	20	CTI	10	BER-HFD	AM	Meet, CTRAIL, 4415, Milepost, XOW, XOW
151	RNK	29	PTI	42	PTI	18	XVG-ALX	CS	Follow 67, Control Point, Virginia
172	BOS	30	DSR	28	DSR	21	STM-BRP	MN	Per bulletin Milepost, 35.0, 42.0, 15, 2
173	WAS	17	OTH	16	CTI	6	NHV-BRP	MN	Follow Follow water bury branch into Bridgeport, metro north, Control Point, 261-bridgeport
174	BOS	16	HLD	14	CTI	9	STM-BRP	MN	Blocked from station track MNR, Other, BPT station

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
175	WAS	No OS Rpt	ENG	204	ENG	169	BBY-RTE	AM	HEP, 658 EX ES, AM175 rpts lost HEP at BBY,	
186	PHL	18	FTI	48	FTI	48	ASD-FBG	CS	Meet CSX M415 brake issue blocking 2/3 mains. 2/1 at 53.2 1/2 at 58.7 around M415., M415, Milepost, 49.9, 58.7	
193	WAS	31	ITI	16	ITI	16	NYP-NYP	AM	Service, turn, or wye train, 184, LATE TURN OFF AM184	
52	LOR	41	PTI	54	FTI	18	XOU-XFL	CS	Meet Control Point, strawberry, Control Point, santee bluff, csx	
53	SFA	39	CAR	36	CAR	36	LOR-LOR	CS	Toilet 38054	
79	CLT	84	PTI	86	PTI	61	DNC-BNC	NS	Meet NC 78, Siding, Merrill	
683	BRK	13	PTI	13	PTI	13	EXR-DHM	CS	Meet 684, Control Point, rockingham	
684	BON	25	ENG	16	ENG	16	HHL-HHL	MT	Loading problem Engine overheating, 123	
685	BRK	Trn Cancelled								
687	BRK	36	HLD	25	DCS	9	POR-FRE	CS	Issue with automatic road crossing protection copied EC-1 at Mountain, Other, Congress st	
63	TWO	146	RTE	11	RTE	11	ALB-SDY	AM	Run via siding or slower track due to N.A.R. Milepost, 143, 145	
64	NYP	85	WTR	86	WTR	31	UCA-AMS	CS	Heat order Milepost, 237.5, 177.6	
68	NYP	20	WTR	43	WTR	43	SLQ-RSP	CN	Heat order Milepost, 40, 2	
69	MTR	106	CUI	66	CUI	66	XLQ-XLQ	CN	Canada	
230	NYP	53	POL	58	POL	50	CRT-XSD	MN	Right of Way police hold Trespasser Fatality in tunnel so held at Tarrytown till able to pass at Restricted Speed	
233	ALB	34	CTI	16	CTI	16	CRT-POU	MN	Meet Waited for south bound train, MNRR, 858, Control Point, 39	
234	NYP	19	CTI	22	CTI	22	POU-CRT	MN	Meet Waited for northbound 63 and mn 807 to clear 46 due to a kinked rail report at mp42.6, metro north, 807, Control Point, 46	
235	ALB	60	CTI	61	CTI	52	CRT-POU	MN	Meet Stop at CP39 wait for Northbound MN train behind us to pass us. Then wait for southbound MN train to pass us. Then held again at CP 46 for Northbound MN train to pass us. Then follow northbound train from 46 to 72., mn, Control Point, 39, Control Point, 46, Milepost, 46, 72	
236	NYP	29	CTI	27	CTI	27	POU-CRT	MN	Cross over or go around metro north, Amtrak, 69, Control Point, 46	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
239	ALB	26	DCS	28	DCS	28	RHI-HUD	AM	Restrictive signal(s) from known wayside signal failure Stop, Control Point, 103
240	NYP	24	CTI	18	CTI	18	POU-CRT	MN	Meet mn, Control Point, 46
241	ALB	27	DCS	29	DCS	29	RHI-HUD	AM	CTC system failure Signal outage at 103 . Received 241 past 103 . Restricted speed to 109, Control Point, 103
280	NYP	26	SYS	23	CTI	13	POU-CRT	MN	Meet NB, Control Point, 46
281	NFL	42	WTR	54	FTI	26	AMS-UCA	CS	Follow csx, Milepost, 177, 212
283	NFL	26	WTR	27	WTR	15	AMS-UCA	CS	Heat order Other, Mohawk Subdivision
290	NYP	48	PTI	38	RTE	22	POU-CRT	MN	Dispatcher hold Due to track work, held for 2 train, Control Point, 46
291	BTN	56	CTI	34	CTI	34	CRT-POU	MN	Follow metro north, Control Point, 39
49	CHI	31	DCS	59	DCS	59	NYP-NYP	AM	Power switch failure, Other, NYP-NYP, LATE F/SSYD LOST RADIO COMMUNICATION IN YARD
448	BOS	67	WTR	58	WTR	39	PIT-SPG	CS	High winds Milepost, 150, 98
449	ALB	71	WTR	56	WTR	21	WOR-SPG	CS	Heat order Control Point, 45, Other, SPG
72	GRO	14							
89	SAV	66	FTI	54	FTI	37	CHS-YEM	CS	Follow m 493, Milepost, 408.8, 428.0
90	NYP	71	FTI	76	FTI	64	RVR-XDJ	CS	Meet m415, Other, cfp53.2
98	NYP	252	SYS	91	MBO	81	PAK-JAX	CS	Mechanical working on drawbridge Milepost, 651, 651
55	WAS		SMW	16	SMW	14	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD FOR AM148 A/C SINGLE TRACKING LEGGETT-PELHAM BAY DUE TO 2 TRACK OOS
40	CHI	109	PTI	96	PTI	56	MIA-HOL	FL	Wait for station track TriRail had mechanical issues. We had to shove back to Cp Hardy to prepare to cross over from 2 to 1., tri rail 672, Control Point, Hardy
41	MIA	69	WTR	64	DSR	21	JAX-PAK	CS	Per bulletin Milepost w/Letters, A657.0, A657.2, 10, m, Milepost w/Letters, A658.1, A658.7, 50, m, Milepost w/Letters, A659.4, A660.3, 50, m, Milepost w/Letters, A660.3, A662.0, 50, m, Milepost w/Letters, A663.9, A664.3, 25, m, Milepost w/Letters, A697.4, A697.7, 10, m
529	SJC	18	FTI	20	FTI	20	RSV-SAC	UP	Cross over or go around up 9924, Control Point, Citrus Heights?

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
530	SAC	15	MBO	11	MBO	11	MTZ-SUI	UP	For maritime traffic Control Point, vista
534	SAC	33	TEN	40	TEN	40	FFV-DAV	UP	Loading problem Lost load around MP 59.3. Went back to engine to shut everything off and turn back everything back on again per TASI., C2002
537	OKJ	12	PTI	17	PTI	12	MTZ-RIC	UP	Meet amt530, Control Point, san pablo
539	SJC	16	PTI	13	MBO	6	SUI-MTZ	UP	For maritime traffic Control Point, RV035
500	SEA	42	TRS	27	TRS	27	XA4-TUK	BN	Cross over or go around Stopped at CP Thomas and shoved back to Auburn North to go around BNSF 7541, BNSF 7541, Per BNSF, crew inspecting the freight train after it went into emergency due to trespasser on the tracks, Other, Control Point, Thomas
516	VAC	43	ENG	33	ENG	33	EVR-STW	BN	Other electrical failure Master controller issues, code 1583. Stop to adjust MU cables between engine and north most coach., WS1407
518	VAC	51	PTI	45	PTI	31	STW-MVW	BN	Meet amtk 519, Control Point, northmount Vernon
519	SEA	33	FTI	56	FTI	50	X8B-BEL	BN	Meet BN 5153, Siding, Ferndale
8	CHI	273	FTI	210	DBS	87	MOT-RUG	BN	Debris strike We hit a tree that was down on our tracks. It damaged both ditch lights. We replaced one of the ditch lights, and the other one was not repairable., Hit a downed tree , Milepost, 188.9, 188.8
822	OKC	27	FTI	28	DSR	19	FTW-GLE	BN	Per bulletin Milepost, 350.3, 350.4, 30, crossover, Milepost, 353.8, 354, 60, m2, Milepost, 354, 354.1, 70, m2, Milepost, 368.6, 361.1, 30, m1, Milepost, 364.7, 365.1, 60, m1, Milepost, 370.6, 370.7, 30, m, Milepost, 374, 374.1, 60, m, Milepost, 377.5, 378.3, 75, m, Milepost, 379.5, 380, 60, m, Mile
335	MKE	13	DCS	10	DCS	8	SVT-MKA	CP	Issue with automatic road crossing protection #7747 procedure #1 @ 7 mile Rd., coronated with the WWD freight on MT2, Milepost, 70.71, 70.71
338	CHI	14	CTI	8	DCS	6	MKA-SVT	CP	Issue with automatic road crossing protection Procedure #1 at Seven Mile Road, Milepost, 70.71, 70.71
354	PNT	52	PTI	35	FTI	22	XT6-X1W	CR	Meet CP H93, Control Point, Dearborn

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
364	PTH	36	DSR	46	DSR	29	BTL-LNS	CC	Per bulletin Milepost, 180.91, 181.34, 30, m2, Milepost, 181.99, 182.85, 30, m2, Milepost, 184.79, 185.66, 30, m2, Milepost, 192.4, 193.3, 25, m1, Milepost, 194.78, 194.78, 25, m2, Milepost, 196.82, 196.82, 25, m2, Milepost, 201.75, 202.1, 30, mt, Milepost, 202.25, 202.45, 25, mt, Milepost, 205.99,	
365	CHI	53	FTI	63	FTI	51	LPE-FLN	CC	Cross over or go around x275, Milepost, 269, 258	
572	SAN	31	CTI	31	CTI	16	SOL-OLT	SN	Meet NCTD, 635, Control Point, Skripps	
581	LAX	17	CTI	11	CTI	9	SOL-OSD	SN	Meet coaster, Control Point, swami	
584	SAN	Trn Cancelled	PTI	7	PTI	7	LAX-XRJ	SC	Meet Amtk 581, Control Point, Terminal	
587	LAX	203	ENG	151	ENG	131	SNP-SNP	SC	Traction motor 313	
588	SAN	67	SYS	50	SYS	50	SNC-SNP	SC	Blocked by or assisting another, disabled Amtrak train Held siding track at 198.5 waiting for Amtrak 587 mechanical issues, Milepost, 198.5, 198.5	
591	LAX	151	SYS	81	SYS	81	OSD-X98	SN	Blocked by or assisting another, disabled Amtrak train Stopped at songs, waiting for disabled Amtrak 587 to be cleared from single track at San Clemente pier., Control Point, songs	
593	LAX	Trn Cancelled								
595	LAX	27	PTI	25	PTI	25	OSD-X98	SN	Meet 790, Control Point, songs	
769	GTA	24	PTI	32	PTI	21	OSD-X98	SN	Meet Amtk 566, Control Point, Songs	
786	SAN	121	SYS	131	SYS	103	SNC-SNP	SC	Blocked by or assisting another, disabled Amtrak train Train 587	
790	SAN	39	PTI	65	PTI	32	SNC-SNP	SC	Meet 591, Control Point, serra	
710	BFD	57	FTI	61	FTI	45	HNF-COC	BN	Cross over or go around BNSF 4008 E. HFRSBR Working siding @ Guersney. Then pulled into siding to clear out, Control Point, W Guernsey, BNSF 4008 E, HFRSBR	
711	OKJ	51	TRS	25	TRS	15	BFD-WAC	BN	Vehicle on track ahead Vehicle on tracks with train in block ahead. Stopped at w Wasco. Then flagged into block to make station stop, Other, 916	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/30/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
714	BFD	40	PTI	62	PTI	23	OKJ-OKJ	UP	Wait for station track Hold in yard for 711 to be routed to OKJ, and then to OMF., amt 711, Other, yard
716	BFD	22	DSR	23	OTH	15	XPR-ACA	BN	Came to a stop per dispatcher due to fire at mile post 1159.9
718	BFD	28	FTI	23	SYS	16	FNO-HNF	BN	PTC problem or failure (cause unknown) After stopping to pick up a freight train crew PTC put up a red fence., Siding, Bowls
719	OKJ	22	PTI	26	PTI	15	FNO-MDR	BN	Meet 716, Siding, Gregg
3	LAX	38	FTI	79	FTI	27	FLG-KNG	BN	Follow UNKN BNSF W, Milepost, 449.4, 511.3
4	CHI	63	FTI	153	FTI	74	LAP-FMD	BN	Follow Single tracking between 246.2 to 234.3 for Form B 7712., BN 6806, Control Point, East FMD
305	STL	44	DMW	31	DMW	31	CHI-XTF	AM	Hold for defect repair Control Point, 21st
381	QCY	23	DMW	20	DMW	11	GBB-MAC	BN	Waiting for MW clearance Form b blanco, Milepost, 165.4, 165.4
382	CHI	34	FTI	38	FTI	30	MAC-GBB	BN	Follow Mem-Gal 7185, Milepost, 192.0, 166.0, BMSF
383	QCY	57	FTI	39	RTE	20	GBB-MAC	BN	Galesburg yard Knox - Waterman Control Point, Knox
390	CHI	29	WTR	16	ENG	14	HMW-XCS	CC	PTC - On Board Cab Signal or PTC Failure 4628
391	CDL	27	WTR	21	PTI	8	RTL-CHM	CC	Meet AM 390, Siding, Rantoul
392	CHI	77	WTR	46	FTI	16	CEN-EFG	CC	Meet G884, Control Point, Kinmundy
393	CDL	23	DSR	24	WTR	5	HMW-KKI	CC	Heat order Milepost, 24, 55
316	STL	90	FTI	95	FTI	89	LEE-WAR	UP	Meet UP 8961, Siding, Centerview
318	CHI	24	DCS	16	FTI	13	SMT-XTF	CC	Cross Traffic Control Point, Brighton, NS8095
319	KCY	37	PTI	51	PTI	40	SED-WAR	UP	Meet amtk 316, Siding, dresden

Amtrak Initial Terminal Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/30/2026

Terminal	Train	Date	Late	Delay	Cause
GRO	75	06/30	2		
HAR	646	06/30	1		
MIA	98	06/30	6	6	Set out defective car 62014, Car 62014 was replaced with car 62016 due several leaks found in the car.
PHL	110	06/30	3	3	Passenger and/or baggage, LATE BOARDING PASSENGER
PHL	190	06/30	1		
WAS	196	06/30	4	4	Passenger and/or baggage, REDCAP BOARDED PSGR ON WRONG TRAIN
WAS	2124	06/30	(Trn Cxld)		Equipment Issues
BON	685	06/30	(Trn Cxld)		Engine Issue
BON	687	06/30	2	2	Double Trainset Directing passengers to each set based on destination to cut down on in route delays.
BOS	175	06/30	203	2	Mobility Impaired, ADA assist needed extra help
BOS	175	06/30	203	44	Planned set out / pick out of locomotives, cars or section of train, Engine swap E/658
BOS	175	06/30	203	157	Planned set out / pick out of locomotives, cars or section of train, Engine change / Engine issues
BOS	2159	06/30	(Trn Cxld)		Equipment Issues
BRK	684	06/30	1	1	Late arriving bikes
HFD	471	06/30	10	10	Meet, CT Rail, 4404, Control Point, HART, Held for CT4404 to clear
MTR	68	06/30	1		
NHV	55	06/30	89		
NYP	19	06/30	8	8	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	69	06/30	25	25	Service, turn, or wye train, 230, LATE TURN OFF AM230
NYP	89	06/30	5	5	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD BY CATERING
NYP	97	06/30	56	56	Water, commissary, toilet/trash dumping, LATE RELEASE F/SSYD A/C LATE CATERING
NYP	129	06/30	6	6	Follow, AM173, AM134, Other, F-INT, HELD FOR AM173 AND AM134 RTD AHD IN F-INT
NYP	193	06/30	16	16	Service, turn, or wye train, 184, LATE TURN OFF AM184
NYP	233	06/30	8	8	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	235	06/30	2	2	Passenger and/or baggage, BOARDING
NYP	283	06/30	3	3	Passenger and/or baggage, LOADING

Amtrak Initial Terminal Details

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/30/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	291	06/30	18	18	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	649	06/30	15	15	Disabled train ahead, Other, NYP, HELD A/C DELAYED AM98 OPR "A" INT WITH PTC FAILURE
NYP	2127	06/30	2	2	Passenger and/or baggage, BOARDING
TWO	64	06/30	3		
CHI	5	06/30	16	16	Non working PA 38017
QCY	380	06/30	1	1	Issue with automatic road crossing protection Other, MP 258.53 - 30th St.
BFD	719	06/30	11	11	Waited to for equipment to arrive to turn as 719. 710, Other, Bakersfield Station
GTA	782	06/30	6	3	Door 6800, Not getting door lights
GTA	782	06/30	6	3	Wait for station track 14, Siding, ellwood
OKJ	526	06/30	4	4	Meet 11, Control Point, North Jack London
OKJ	532	06/30	5	5	Wait for AMT 537 AMT537, Milepost, 7, 7
OKJ	534	06/30	2	2	Meet We were ready to leave on time but had to wait for Amt 539 to arrive into OKJ before departing., Amt 539, Control Point, N. Jack London
OKJ	536	06/30	1		
OKJ	714	06/30	23	23	Wait for station track Hold in yard for 711 to be routed to OKJ, and then to OMF., amt 711, Other, yard
OKJ	716	06/30	3	3	Left yard late due to train being blue flagged tasi mechanical C2102
SAC	539	06/30	2	2	Meet 528, Control Point, RV988
SAN	573	06/30	5	5	HEP 34082, No blowers no A/C breakers tripped
SAN	593	06/30	(Trn Cxld)		Engine Issue
SAN	769	06/30	4	3	Copy authority / restriction
SAN	769	06/30	4	1	PTC system failure (wayside) PTC went to disengaged status, went live then placed train into emergency., Control Point, Ash
SJC	524	06/30	1	1	PTC- PTC enforced braking Departing SJC on time, PTC didn't recognize signal had us stop at station

Eastern Region

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	95.0	98.6	94.8	342	17
CDOT	95.0	100.0	92.3	92.4	12	0
MARC	95.0	87.9	84.5	90.2	58	7
SEPTA	95.0	95.8	94.4	91.5	215	9
NJT-NED	95.0	92.9	92.5	88.6	338	24
NJT-SED	95.0	100.0	98.7	97.2	24	0

Operating Highlights

Train 69(30) - South of Longueuil, Quebec - Weather

01JUL26: Train 69(30) was delayed on the CN Rouses Point Subdivision south of Saint Lambert Station/MP 70.1 due to operating under heat related speed restrictions.

Train	Delay	Comment
69 (30)	46"	

Train 79(30) - East of Burlington, NC - Passenger Train Interference

01JUL26: Train 79(30) was delayed on the Norfolk Southern Danville District Subdivision at MP 23.9 due to meeting Train 78(30). Train 79(30) was diverted to the siding at Merrill to allow passage.

Train	Delay	Comment
79 (30)	1'01"	

Train 98(30) - South of Florence, SC - Passenger Train Interference

01JUL26: Train 98(30) was delayed on the CSX Charleston Subdivision at MP 296.0 due to being held out of Florence Station/MP 292.6 while Train 53(30) was serviced and refueled.

Train	Delay	Comment
98 (30)	46"	

Train 448(29) - West of Springfield, MA - Weather/High Winds

30JUN26: Train 448(29) was delayed on the CSX Berkshire Subdivision between MP 150 and MP 98 due to high winds warnings.

Train	Delay	Comment
448 (29)	39"	

Disabled CSX Freight Train - South of Fredericksburg, VA - Freight Train Interference

30JUN26: CSX Train M415-30 experienced an unclassified failure on CSXT3457 at MP 52.8 on the CSX RF&P Subdivision. Subsequently, Amtrak Trains 90(30), 186(30), and 125(30) were held and incurred delay. Once the freight train crew was able to resolve the issue and clear a route, Amtrak traffic resumed.

Train	Delay	Comment
125(30)	18"	
186(30)	48"	
90(30)	1'04"	

Train 175(30) Boston, MA - Engine Failure

30JUN26: Train 175(30) with E/658 and 9 cars with 350 customers onboard was delayed in Boston Back Bay station due to losing HEP upon arrival. The crew was speaking with Amtrak Road Foreman and they were going to short loop the engine. The crew was not able to short loop the engine and reversed back into Boston South station where mechanical met the train.

Train	Delay	Comment
175(30)	3'23"	

Train 97(30) New York, NY - Servicing

30JUN26: Train 97(30) with E/656 and 11 cars with 133 customers was delayed departing New York due to the late released from the yard caused by catering.

Train	Delay	Comment
97(30)	56"	

New York to Philadelphia Main Line - Bridge Strike

30JUN26: At 130P-ET A vehicle struck the bridge at Wood Ave., MP 17.26, New York to Philadelphia Main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 219P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
174(30)	04"	

Train 68(30) South of St-Lambert, QC - Heat Orders/Weather

30JUN26: Train 68(30) was delayed on the CN Rouses Point subdivision due to heat orders from MP 40.0 to MP 2.0.

Train	Delay	Comment
68(30)	43"	

Train 684(30) Haverhill, MA - Engine Failure

30JUN26: Train 684(30) 26-FOI-00580 E/123 00000008160 UNCLASSIFIED 7/7/2026 car with 140 customers onboard was delayed on the CSX Portland PLD at MP 93.0 due to E/123 overheating. The crew was trouble shooting and checking the water levels. The train was able to maintain HEP. The crew was able to reset E/123 and clear the faults they did proceed into Boston North station. Upon arrival into Boston North station the equipment was double drafted with train 687(30) and train 685(30) was cancelled.

Train	Delay	Comment
684(30)	16"	HHL
685(30)		CANCELLED
687(30)	02"	DOUBLE DRAFT WITH 685(30)

New York to Philadelphia Main Line - Bridge Strike

30JUN26: At 1019A-ET A vehicle struck the bridge at South St., MP 9.65, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At xxxP, the bridge was inspected and released for normal service.

Train	Delay	Comment
172(30)	08"	
2113(30)	05"	

Philadelphia to Washington Main Line Heat Orders - Weather

30JUN26: There were Level 3 Heat Orders issued from 12P-ET till 7P-ET with 30/25MPH restrictions on the PW Line Limits of Phil Interlocking 5 track, Limits of Phil Interlocking track 2, MP 10- MP 11 2 track, MP 15-MP 16 3 track, MP 49 - MP 50 2 track and Limits of Perry interlocking 2 and 3 tracks.

Train	Delay	Comment
95(30)	03"	
2113(30)	03"	
174(30)	05"	
2155(30)	06"	
84(30)	12"	
119(30)	03"	
2112(30)	03"	
134(30)	06"	
2158(30)	02"	
125(30)	05"	
80(30)	04"	
136(30)	04"	
2123(30)	02"	
178(30)	06"	
2118(30)	04"	
94(30)	05"	
2116(30)	07"	
184(30)	07"	
2158(30)	07"	
2120(30)	06"	
2160(30)	04"	
131(30)	05"	
20(29)	03"	
98(29)	07"	

CSX Heat Orders - Weather

Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Capital, Alleghany, Kanawha, Metropolitan, New River, North End, Peninsula, RF&P, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, South End and Tampa Terminal.

26-FOI-00580

00000008760

UNCLASSIFIED

7/7/2026

Train	Delay	Comment
64 (30)	42"	
25 (30)	15"	
40 (30)	38"	
89 (30)	54"	
449 (30)	56"	
98 (30)	30"	
138 (30)	22"	
79 (30)	57"	
53 (30)	35"	
93 (30)	04"	
283 (30)	27"	
52 (30)	17"	
281 (30)	15"	
40 (30)	50"	
19 (30)	09"	
90 (30)	32"	
186 (30)	24"	
95 (30)	21"	
80 (30)	1'04"	
178 (30)	05"	
448 (29)	17"	
97 (29)	20"	
40 (29)	43"	
48 (29)	18"	
41 (29)	31"	

Empire to Inwood - Police Hold/Trespasser - Police Related

30JUN26: As of 620A-ET, Amtrak Police placed a hold on all tracks between MP1.0/Empire and MP 9.9/Inwood due to a trespasser that jumped off the bridge at 142ND St and Riverside Drive. This was confirmed fatality. Amtrak Police and Local Police were on scene as of 620A-ET. As of 704A-ET Amtrak took over the hold on track 1 and 2 from FDNY. As of 708A-ET, Amtrak released the hold on track 2 only restricted speed MP 5 to MP 6. Still waiting on NY PD Detectives to arrive with no current ETA.

Train 230(30) was held on MNRR Hudson line at MP 25.1. This also caused delay to train 69(30) due to turning off late inbound 230(30).

At 1202P-ET, Amtrak Police removed the hold on track 1 and 2 between Empire and Inwood.

National Response Center Number: 1466537

Train	Delay	Comment
63 (30)	10"	
230 (30)	58"	
69 (30)	33"	
232 (30)	04"	
233 (30)	05"	
234 (30)	06"	
281 (30)	05"	

High Speed Service Adjustments - Engine Failure

30JUN26: Trains 2159(30) and 2162(30) were cancelled due to Next Gen set 22 being shopped for truck hunting.

Train 2119(30) with Next Gen set 11 was shopped upon arrival into Washington this caused train 2124(30) to be cancelled.

Train	Delay	Comment
-------	-------	---------

Train 56(29) Greenfield, MA - M of W Work

29JUN26: Train 56(29) with 56145 and 56146 cars with 138 customers onboard was terminated at Greenfield station due to an excavator on fire on the tracks in Bethel VT that has caused track damage to the rail. Once train 486(29) arrives and turns for 479(29) they will tie on to 56(29) and bring it back to Springfield where they bussed passengers from Springfield to St Albans. Train 55(30) will originate in New Haven with alternate buses from St Albans to New Haven.

Train	Delay	Comment
56(29)	0	TERM GFD W/BUSES
55(30)	1'29"	ORIG NHV W/BUSES

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00580a 00000008160 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Train 3(29) Flagstaff, AZ - Cervine Strike

01JUL26: Train 3(29), operating with locomotives E/50 and E/181, eight cars, and 167 customers onboard, was delayed west of Flagstaff, AZ, at approximately MP 391.5 on the BNSF Seligman Subdivision, after striking an elk. An air hose parted, requiring the crew to stop and perform an inspection and repair. The crew replaced the damaged hose and conducted the required air brake test to ensure the train was safe for operation. Once repairs were completed and all tests were successful, Train 3(29) resumed its westbound trip.

Train	Delay	Comment
3 (29)	35"	

Train 50(30) East of Crawfordsville, IN - Freight Train Interference

30JUN26: Train 50(30), with 118 customers onboard, was delayed at Ames/MP46.1 1 mile east of Crawfordsville, IN/MP147.5 on the CSX Crawfordsville Branch subdivision meeting CSX freight. Once the route was clear, train 50(30) continued east.

Train	Delay	Comment
50 (30)	34"	

Train 307(30) Bloomington-Normal, IL - Freight Train Interference

30JUN26: Train 307(30), with 89 customers onboard, was delayed at Bloomington-Normal, IL/MP124.0 on the UP Joliet subdivision meeting UP freight. Once the route was clear, train 307(30) continued south.

Train	Delay	Comment
307 (30)	34"	

Train 518(30) South of Mount Vernon, WA - Passenger Train Interference

30JUN26: Train 518(30), carrying 226 customers onboard, was delayed just south of Mount Vernon, WA Station, at MP 67.3 on the BNSF Bellingham Subdivision, while holding to meet Amtrak Train 519(30).

Train	Delay	Comment
518 (30)	31"	

Train 587(30) San Clemente Pier, CA - Engine Failure

30JUN26: Train 587(30) ^{26, For 00580 00000008160 UNCLASSIFIED 7/7/2026} departed with CO/GO five locomotives, locomotive E/313, and 129 customers onboard, was delayed at San Clemente Pier (SNP) due to traction issues. While head-end power remained operational, the locomotive fault was deemed unrecoverable after troubleshooting with the CNOC Mechanical Desk and LAX technicians, leaving the train without propulsion.

To mitigate the impact, Train 584(30) was assigned to rescue Train 587(30), and the combined consist operated double-set to Los Angeles. Train 584(30) was terminated at SNC, with customers transferred to Train 786(30) for continued service to San Diego. Additional impacts included:

-Train 593(30) canceled, with customers accommodated on Train 595(30).

-Trains 786(30), 588(30), 790(30), 591(30), and 595(30) experienced delays due to congestion and cascading impacts from the incident.

Once the rescue operation was completed and customers were accommodated, service resumed through the corridor.

Train	Delay	Comment
587(30)	2'42"	SNP
587(30)	45"	SNP-LAX heavy train & inspections
584(30)	TERM SNC	
786(30)	2'08"	
588(30)	1'17"	
591(30)	1'21"	
593(30)	Canceled	
790(30)	53"	
595(30)	29"	

Train 519(30) North of Bellingham, WA - Freight Train Interference

30JUN26: Train 519(30), carrying 183 customers onboard, was delayed north of Bellingham, WA Station, at MP 106.7 on the BNSF Bellingham Subdivision in Ferndale, WA, while holding to meet BNSF 5153.

Train	Delay	Comment
519(30)	50"	

Train 307(30) South of Chicago, IL - Freight Train Interference

30JUN26: Train 307(30), with 155 customers onboard, was delayed at Brighton/MP5.1 5.1 miles south of Chicago Union Station, IL/MP0.0 on the CN Joliet subdivision meeting cross traffic at the BNSF crossing. Once the route was clear, train 307(30) continued south.

Train	Delay	Comment
307(30)	40"	

Train 305(30) South of Chicago, IL - M of W Work

30JUN26: Train 305(30), with 243 customers onboard, was delayed at 21st Street/MP2.7 2.7 miles south of Chicago, IL on the CN Freeport subdivision holding for maintenance of way crews to repair a rail defect. Once the route was open, train 305(30) continued south.

Train	Delay	Comment
305(30)	31"	

Train 319(30) West of Sedalia, MO - Passenger Train Interference

30JUN26: Train 319(30), with 95 customers onboard, was delayed at Dresden/MP197.4 11 miles west of Sedalia, MO/MP188.9 on the UP Sedalia subdivision meeting Amtrak train 316(30). Once the route was clear, train 319(30) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(30)	40"	

Train 1(29)/421(28) East of Tucson, AZ - Freight Train Interference

30JUN26: Train 1(29)/421(28), with 190 customers onboard, was delayed at Kolb siding/MP194.0 10 miles east of Tucson, AZ/MP983.9 on the UP Lordsburg subdivision meeting UP freight UP/7390. Train 1(29)/421(28) was ordered to shove back to Kolb siding from mile post 988.0 to allow UP/7390 to operate into the clear. Once the route was clear, train 1(29)/421(28) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(29)/421(28)	38"	

Train 382(30) East of Macomb, IL - Freight Train Interference

30JUN26: Train 382(30), with 32 customers onboard, was delayed between mile post 192.0 and mile post 166.0 beginning 10 miles east of Macomb, IL/MP202.3 on the BNSF Brookfield subdivision following BNSF freight BN/7185. Once the route was clear, train 382(30) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(30)	30"	

Train 22(30)/422(28) East of Mineola, TX - Vehicle Strike

30JUN26: At 6:01PM CT, train 22(30)/422(28), with engines 57 and 25, 9 cars, and 208 customers onboard, stopped at mile post 126.0 10 miles east of Mineola, TX/MP136.1 on the UP Mineola subdivision after striking an empty chemical truck. The strike occurred at a private crossing, DOT #794696L, equipped with private crossing signage. Weather conditions were sunny. This was not a fatality. No injuries were reported by the customers or crew. Damage was reported to the ditch lights of the equipment. Local police, an Amtrak Road Foreman, an UP Corridor Manager and UP Mechanical Team responded to the scene. UP Mechanical made repairs to the ditch lights. A pregnant customer onboard was removed by EMS after complaining of abdominal pain. Another customer, diabetic, was also removed by EMS. Once the scene was released, train 22(30)/422(28) advanced 1 mile to Fada siding/MP124.9 to await the recrew. The recrew signed up at 8:50PM CT at Ft Worth, TX. Once the recrew had control of the equipment, train 22(30)/422(28) met UP freights MMNMX-30 and ISHEGR-30 before departing Fada siding.

National Response Center Number: 1466627

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(30)/422(28)	6'40"	

Train 3(30) West of Galesburg, IL - Freight Train Interference

30JUN26: Train 3(30), with 260 customers onboard, was delayed at Ormonde/MP191.9 30 miles west of Galesburg, IL/MP162.6 on the BNSF Chillicothe subdivision following BNSF freight BN/6133 across a bridge that opened for marine traffic three times before rail traffic could operate across. Once the route was open, train 3(30) continued west.

Train 20(30) South of Birmingham, AL - Vehicle Strike

30JUN26: At 5:20PM CT, 26-FOI-00580 00000008160 with "UNCLASSIFIED" 341 7/7/2026 350, 8 cars, and 94 customers onboard, struck a vehicle at mile post 153.32 10 miles south of Birmingham, AL/MP143.0 on the NS AGS South subdivision. The strike was a fatality. It occurred at the 32nd Street North crossing, DOT #725393P, a highway crossing at grade equipped with advanced warning signs, pavement markings, and over-traffic flashing lights. The weather was partly cloudy with a head advisory in effect. No injuries were reported by the customers or crew. Minor plow damage was reported to the equipment. Local police, NS management, and an Amtrak Road Foreman responded to the scene. The crew was able to shove the train back to free the equipment from the vehicle, which was pulled into the clear by a tow truck. Once the police released the scene, train 20(30) advanced to Birmingham, AL and held for a recrew. The recrew wen on duty at 7:45PM CT at Meridian, MS. Once the recrew had control of the equipment, train 20(30) departed Birmingham, AL heading north.

National Response Center Number: 1466626

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(30)	3'55"	Vehicle Strike
20(30)	1'30"	Recrew at BHM

Train 316(30) West of Warrensburg, MO - Freight Train Interference

30JUN26: Train 316(30), with 54 customers onboard, was delayed Centerview siding/MP223.7 5 miles west of Warrensburg, MO/MP218.5 on the UP Sedalia subdivision meeting UP freight UP/8961. Once the route was clear, train 316(30) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(30)	1'29"	

Train 3(30) West of Naperville, IL - Freight Train Interference

30JUN26: Train 3(30) was delayed at Montgomery/MP40.2, 11 miles west of Naperville, IL, on the BNSF Chicago Subdivision, crossing-over to operate around BNSF 3954 and BNSF 5010.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(30)	34"	

Train 710(29) East of Hanford, CA - Freight Train Interference

30JUN26: Train 710(29), carrying 86 customers onboard, was delayed approximately 4.5 miles east of Hanford, CA Station, at MP 963.2 on the BNSF Bakersfield Subdivision, while holding to meet BNSF freight train 4008. The train remained stopped until the freight movement cleared into Guernsey Siding, after which Train 710(29) was able to proceed around the meet.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
710(29)	45"	

Train 4(29) East of Albuquerque, NM - Passenger Train Interference

30JUN26: Train 4(29), carrying 188 customers onboard, was delayed east of Albuquerque, NM, while holding at East Domingo (MP 865.4) on the NMRX Glorieta Subdivision to meet Amtrak Train 3(29). Once the opposing movement cleared and the route was released, Train 4(29) resumed its eastbound trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(29)	55"	

Train 11(30) South of Tukwila, WA - Freight Train Interference

30JUN26: Train 11(30), 26-FO-00580, 00000008160, UNCLASSIFIED, 7/7/2026, was delayed approximately 6 miles south of Tukwila, WA at MP 11.7 on the BNSF Bellingham Subdivision. UPEMFTE020 (BNSF 7541) experienced an undesired emergency brake application after the crew attempted to avoid a trespasser on the tracks, which required the oil train to be inspected. Train 11(30) then performed a shoving move before being routed around the stopped train.

Train	Delay	Comment
11(30)	34"	
500(30)	27"	

Train 516(30) East of Everett, WA - Engine Failure

30JUN26: Train 516(30), led by WS1407 and carrying 220 passengers, came to a stop 13 miles east of Everett, WA on the BNSF Bellingham Subdivision due to throttle-related issues. The crew reported master controller fault code 1583 to both Seattle and CNOC Mechanical. The train was halted so the crew could adjust the MU cables between the locomotive and the first coach. After completing the adjustment, the train resumed normal operations.

Train	Delay	Comment
516(30)	33"	

Train 4(28)East of La Plata, MO - Freight Train Interference

30JUN26: Train 4(28) was delayed east of La Plata, MO/MP312.7, on the BNSF Marceline Subdivision, following BNSF 6806 between MP246.2 and MP234.3. BNSF MW working on adjacent track resulting in single track through the area.

Train	Delay	Comment
4(28)	1'14"	

Train 20(30) North of Picayune, MS - M of W Work

30JUN26: Train 20(30) was delayed at MP115.5, 34 miles north of Picayune, MS, on the NS NO and NE District, holding for NS MW to clear ahead. MW was on site dumping ballast following heavy rains through the area. Train 20(30) was delayed holding for open route ahead.

Train	Delay	Comment
20(30)	33"	

Train 365(30) East of Flint, MI - Freight Train Interference

30JUN26: Train 365(30) was delayed at MP275.8, 4 miles east of Flint, MI, on the CN Flint Subdivision, due to CN freight ahead with air issues. Train 365(30) crossed-over to operate around and was then further delayed following westbound freight traffic to MP258.

Train	Delay	Comment
365(30)	51"	

Train 351(30) West of Dearborn, MI - Debris Strike

30JUN26: Train 351(30) 26-FDI-00580 4000000081605 car UNCLASSIFIED 120 7/7/2026 customers, was delayed at MP11.3, 2 miles west of Dearborn, MI, on the MDOT Michigan Line, due to striking a shopping car. There were no reported injuries to passengers or crew. The crew inspected consist and took no exceptions. Train 351(30) was able to proceed west after crew removed shopping cart and performed Class II brake test.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
351(30)	15"	

Train 48/448/(29) East of Sandusky, OH - Freight Train Interference

30JUN26: Train 48/448(29) was delayed east of Sandusky, OH/MP241.5, on the NS Toledo East District, following NS 36N between MP216 and MP207.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448/(29)	34"	

Train 534(30) Fairfield-Vacaville, CA - Third Party Contractor Engine Failure

30JUN26: Train 584(30), operating with CC/C8306, four cars, locomotive E/C2002, and 46 customers onboard, was delayed east of Fairfield-Vacaville, CA Station, at MP 59.5 on the Union Pacific Martinez Subdivision, after the locomotive shut down, resulting in a loss of propulsion while head-end power remained operational. The crew coordinated with Mechanical and was able to restart the locomotive, restoring tractive effort. A Class II brake test was performed, and once the train was verified safe for movement, Train 584(30) resumed operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
534(30)	40"	

Train 7/27(29) East of Staples, MN - Tornado Warning

30JUN26: Train 7/27(29), with 254 customers onboard, was delayed between mile post 115.0 and mile post 127.0 beginning 33 miles east of Staples, MN/MP148.3 on the BNSF Staples subdivision operating through a tornado warning. Downed trees were reported at Randall siding and on the single main track at mile post 123.0. Train 7/27(29) followed two Z trains through the area and found a route around at Philbrook/MP134.0. Once clear of the weather advisory and freight congestion, train 7/27(29) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(29)	51"	

UPRR Level Two Heat Restrictions - Weather

30JUN26: UPRR issued ~~26-FOP-00580~~ ~~20000008160~~ ~~UNCLASSIFIED~~ restrictions were in effect on the following subdivisions:

- Jefferson City Subdivision between St. Louis, MO and Kirkwood, MO MP2.5-MP14 between 1200PM-CT and 600PM-CT,
- Springfield Subdivision between Alton, IL and St. Louis, MO MP262.00-MP281.5 between 1000AM-CT and 900PM-CT,
- Villa Grove Subdivision between Chicago, IL and Dyer, IN MP9.9-MP19.8 between 1100AM-CT and 800PM-CT.

Trains were delayed through the affected areas.

Train	Delay	Comment
318 (30)		
319 (30)		
306 (30)		
21/421 (30)		
50 (30)		
301 (30)	05"	

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27) was cancelled in its entirety with no alternate transportation.
- Train 58(28) was cancelled in its entirety with no alternate transportation.
- Train 59(27) was cancelled in its entirety with no alternate transportation.
- Train 59(28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

29JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 30JUN as follows:

- Train 58(30) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(30) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated	JAN
58(27JUN-01JUL)	Cancelled	
59(27JUN-01JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on MP 588.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24JUN) 421 (07, 14, 16, 19, 21, 23JUN)	Bypass PSN	
2/422 (28)	BYPASS PSN	
1 (27) / 421 (26)	BYPASS PSN	

Maintenance of Way Highlights

Train 21(29) South of Marshall, TX - Scheduled M/W Work

30JUN26: Train 21(29) was delayed south of Marshall, TX/MP66.5, on the UPRR Little Rock Subdivision, due to a planned UPRR signal suspension between MP79.5 and MP84.7. Amtrak road foreman was onboard Train 21(29) between Marshall and Fort Worth, TX. Train 21(29) was delayed operating through the affected work area.

Train	Delay	Comment
21(29)	53"	

BNSF Ottumwa Sub - Scheduled M/W Work 26-072

26JUN26: BNSF has bridge deck replacement trackwork scheduled on the Ottumwa Subdivision Monday, June 29th from 8:00AM to 10:00PM between Osceola, IA and Creston, IA. To accommodate the infrastructure work, Amtrak's California Zephyr Service has been adjusted as follows:

- Train 6(27JUN) will operate as Train 1006(27JUN) and will operate 1-hour earlier between Emeryville and Chicago.
- Train 5(29JUN) will operate as Train 1005(29JUN) and will operate 1-hour later between Chicago and Emeryville.

WBS#: B.TR.100150.6816

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track "UNCLASSIFIED" project 7/7/2026 multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
7 (29)	SPK	BN5412	E/353 fuel faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 518(30) Passenger Removal at Blaine -Improper Documents

30Jun26, Passenger on, PNR 671B7C traveling from Seattle, WA to Vancouver, WA reported During secondary passport inspection passenger did not have proper documentation to enter Canada (Mexican Passport). Did not have visa only an ETA. They were removed from the train in Blaine. Canada Boarder Amtrak Police notified.

Delay: 518(30)

NONE

Consist Deviations

26-FOI-00580

00000008160

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
5 (30)	CHI	C/32032 multiple issues, train 5(30) & 6(3) will operate 1 sleeper short. system work completed. C/34091 will be added to rear for downgraded sleeper pax	Passengers booked to like rooms were available, some rebooked for another date and four passengers down graded to coach.	4	32032
600 (30)	HAR	433xx cafe replaced a cab car	NONE	0	43379
658 (30)	HAR	433xx cafe replaced a cab car	NONE	0	43379
566 (30)	LAX	no bike space or wifi	Passengers notified no wifi no bike space	1	9700
584 (30)	LAX	no bike space or wifi	Passengers notified no wifi no bike space	2	9700
566 (01)	LAX	NO BIKE SPACE OR WIFI	Email sent for passenger notifications no wi-fi and no bike space.	2	9700
584 (01)	LAX	NO BIKE SPACE OR WIFI	Email sent for passenger notifications no wi-fi and no bike space.	0	9700
647 (30)	NYP	433xx cafe replaced a cab car	NONEQ	0	43379
579 (30)	SAN	no bike space or wifi	Passengers notified no wifi no bike space	0	9700
595 (30)	SAN	no bike space or wifi	Passengers notified no wifi no bike space	0	9700
579 (01)	SAN	NO BIKE SPACE OR WIFI	Email sent for passenger notifications no wi-fi and no bike space.	0	9700
595 (01)	SAN	NO BIKE SPACE OR WIFI	Email sent for passenger notifications no wi-fi and no bike space.	0	9700

Reverse Consists

Train Number	Station	Reason
93 (30)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00580	00000008160 "UNCLASSIFIED" 7/7/2026
125 (30)	SPG	Consist reversed Business class seat orientation may have changed At Front	
178 (30)	RNK	Consist reversed Business class seat orientation may have changed At Front	
183 (30)	NYP	Consist reversed Business class seat orientation may have changed At Front	
136 (30)	WAS	Consist reversed Business class seat orientation may have changed At Front	
174 (30)	WAS	Business class change only Business class seating orientation may have changed At Rear	
125 (01)	SPG	Consist reversed Business class seat orientation may have changed At Front	
86 (01)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front	
138 (01)	NFK	Consist reversed Business class seat orientation may have changed At Front	