

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, July 03, 2026

Rules: 0-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/02/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	303	46	84.8%	623	92	85.2%	81,981	11,217	86.3%
Central Division	86.0%	72	7	90.3%	145	14	90.3%	20,184	1,832	90.9%
East Division	82.0%	157	29	81.5%	329	61	81.5%	42,890	6,670	84.4%
West Division	86.0%	74	10	86.5%	149	17	88.6%	18,907	2,715	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00580 00000008158 "UNCLASSIFIED" 7/7/2026

Endpoint Arrival Dates through 7/2/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	101,525	51,661	49%	202,039	91,788	55%	26,472,182	6,333,501	76%
Northeast Corridor	81%	42,891	24,023	44%	85,595	43,206	50%	11,933,382	2,827,257	76%
Acela	83%	9,193	6,241	32%	19,073	10,533	45%	2,356,095	612,905	74%
Northeast Regional	79%	33,698	17,782	47%	66,522	32,673	51%	9,577,287	2,214,352	77%
Richmond / Newport News / Norfolk	77%	10,312	6,129	41%	19,878	12,759	36%	2,971,732	827,062	72%
Springfield Shuttles	89%	780	333	57%	1,482	635	57%	170,520	25,082	85%
Roanoke	79%	4,345	2,947	32%	6,919	3,732	46%	900,774	179,105	80%
On Spine Northeast Regional	80%	18,261	8,373	54%	38,243	15,547	59%	5,534,261	1,183,103	79%
State Supported	80%	46,419	18,528	60%	92,478	31,919	65%	11,197,691	2,161,042	81%
Borealis	80%	587	570	3%	1,145	839	27%	151,907	31,205	79%
Capitol Corridor	90%	3,859	819	79%	8,968	1,607	82%	1,012,383	131,134	87%
Carolinian	70%	522	510	2%	2,100	1,790	15%	312,175	117,730	62%
Cascades	75%	3,454	1,164	66%	6,824	2,458	64%	694,676	191,079	72%
Downeaster	82%	1,632	758	54%	3,378	1,498	56%	399,716	46,806	88%
Empire	78%	6,884	4,507	35%	11,977	6,955	42%	1,466,226	321,604	78%
Adirondack	72%	765	653	15%	925	653	29%	87,387	26,146	70%
Ethan Allen Express	70%	578	563	3%	1,122	1,099	2%	152,127	48,731	68%
Maple Leaf	70%	1,082	721	33%	1,636	1,048	36%	176,969	68,068	62%
New York - Albany	85%	2,807	1,383	51%	5,692	2,477	56%	682,756	106,348	84%
New York - Niagara Falls	75%	1,652	1,187	28%	2,602	1,678	36%	363,821	71,451	80%
Berkshire Flyer	60%	0	0	-	0	0	-	3,166	860	73%
Heartland Flyer	70%	302	157	48%	531	205	61%	56,133	20,707	63%
Hiawatha	90%	2,099	347	83%	3,933	440	89%	461,740	50,991	89%
Illinois	78%	2,684	1,243	54%	5,780	2,472	57%	667,970	178,541	73%
Carl Sandburg / Illinois Zephyr	85%	576	282	51%	1,176	545	54%	110,739	28,347	74%
Illini / Saluki	85%	1,075	479	55%	1,935	780	60%	235,628	54,829	77%
Lincoln Service	70%	1,033	482	53%	2,669	1,147	57%	321,603	95,365	70%
Keystone	92%	7,777	3,079	60%	16,776	5,449	68%	2,076,051	215,450	90%
Lincoln / Missouri	70%	1,055	861	18%	2,003	913	54%	210,676	104,808	50%
Mardi Gras Service	80%	488	13	97%	865	88	90%	111,019	22,232	80%
Michigan	70%	2,637	1,418	46%	4,928	2,302	53%	524,966	167,364	68%
Blue Water	70%	594	592	0%	1,121	1,116	0%	121,449	46,498	62%
Pere Marquette	85%	211	0	100%	358	0	100%	67,924	13,337	80%
Wolverine	70%	1,832	826	55%	3,449	1,186	66%	335,593	107,529	68%
Missouri	80%	368	0	100%	550	12	98%	59,782	13,269	78%
Pacific Surfliner	85%	9,758	1,873	81%	18,117	2,308	87%	2,090,211	327,920	84%
Pennsylvanian	80%	940	317	66%	1,867	932	50%	240,637	43,118	82%
Piedmont	80%	113	20	82%	337	126	63%	313,524	78,621	75%
Vermont	75%	1,260	872	31%	2,399	1,525	36%	347,899	98,463	72%
Long Distance	70%	12,215	9,110	25%	23,966	16,663	30%	3,301,842	1,342,739	59%
Auto Train	70%	920	0	100%	1,853	0	100%	210,767	70,882	66%
California Zephyr	70%	1,048	853	19%	2,039	1,194	41%	261,447	86,071	67%
Cardinal	70%	545	521	4%	545	521	4%	64,208	30,719	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,085	49,375	72%
Coast Starlight	70%	1,291	601	53%	2,430	921	62%	306,823	105,395	66%
Crescent	70%	869	652	25%	1,365	870	36%	251,015	72,372	71%
Empire Builder	70%	1,297	752	42%	2,632	1,874	29%	256,924	121,716	53%
Floridian	60%	1,549	1,504	3%	3,242	3,197	1%	433,272	286,654	34%
Lake Shore Ltd	73%	1,281	1,232	4%	2,351	1,612	31%	255,149	73,619	71%
Palmetto	70%	833	781	6%	1,668	1,518	9%	249,315	67,567	73%
Silver Meteor	70%	1,044	916	12%	1,995	1,749	12%	274,379	111,868	59%
Southwest Chief	60%	1,030	1,014	2%	2,017	1,996	1%	220,478	140,269	36%
Sunset Ltd	70%	0	0	-	355	222	37%	78,627	26,868	66%
Texas Eagle	70%	508	284	44%	1,474	989	33%	262,353	99,364	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000150 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through July 02, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	14,656	214,624	683	1,581,740	28,852,271	548

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,112	64,638	172	74,493	8,285,638	90
INFRASTRUCTURE PLANNED	135	869	64,638	134	79,827	8,285,638	96
FLEET RELIABILITY	90	2,060	214,624	96	255,098	28,852,271	88
TRAIN OPERATIONS	424	10,615	214,624	495	1,172,322	28,852,271	406

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/02/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	303	46	84.8%	623	92	85.2%	81,981	11,217	86.3%
Central Division	86.0%	72	7	90.3%	145	14	90.3%	20,184	1,832	90.9%
East Division	82.0%	157	29	81.5%	329	61	81.5%	42,890	6,670	84.4%
West Division	86.0%	74	10	86.5%	149	17	88.6%	18,907	2,715	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/02/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	303	46	84.8%	623	92	85.2%	81,981	11,217	86.3%
Central Division	86.0%	72	7	90.3%	145	14	90.3%	20,184	1,832	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	4	0	100.0%	521	18	96.5%
CHI	86.0%	27	6	77.8%	53	11	79.2%	7,292	875	88.0%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	4	0	100.0%	540	52	90.4%
FTW	92.5%	1	0	100.0%	2	0	100.0%	298	34	88.6%
GBB	-	-	-	-	-	-	-	1	1	0.0%
GRR	95.5%	-	-	-	1	0	100.0%	260	8	96.9%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	4	0	100.0%	542	40	92.6%
LAX	89.5%	1	0	100.0%	2	0	100.0%	264	40	84.8%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	12	2	83.3%	1,610	99	93.9%
MOE	97.5%	2	0	100.0%	4	1	75.0%	549	9	98.4%
MSP	96.5%	1	0	100.0%	2	0	100.0%	268	5	98.1%
NOL	94.5%	3	0	100.0%	7	0	100.0%	1,157	53	95.4%
OKC	97.0%	1	0	100.0%	2	0	100.0%	269	6	97.8%
PDX	86.0%	4	0	100.0%	8	0	100.0%	1,090	107	90.2%
PNT	88.0%	3	0	100.0%	6	0	100.0%	709	58	91.8%
PTH	93.0%	1	0	100.0%	2	0	100.0%	263	10	96.2%
QCY	91.0%	2	0	100.0%	4	0	100.0%	534	39	92.7%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	2	0	100.0%	271	27	90.0%
SEA	85.0%	7	0	100.0%	14	0	100.0%	1,904	207	89.1%
STL	89.0%	4	0	100.0%	8	0	100.0%	1,065	90	91.5%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	4	0	100.0%	534	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	157	29	81.5%	329	61	81.5%	42,890	6,670	84.4%
ALB	88.5%	8	0	100.0%	16	0	100.0%	2,030	161	92.1%
BON	87.5%	5	2	60.0%	10	4	60.0%	1,322	144	89.1%
BOS	85.5%	14	2	85.7%	32	4	87.5%	4,672	566	87.9%
BRK	92.5%	5	2	60.0%	10	5	50.0%	1,311	89	93.2%
BTN	82.0%	1	0	100.0%	2	0	100.0%	261	39	85.1%
CLT	91.5%	2	0	100.0%	5	0	100.0%	1,346	132	90.2%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	4	2	50.0%	535	52	90.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/02/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	303	46	84.8%	623	92	85.2%	81,981	11,217	86.3%
East Division	82.0%	157	29	81.5%	329	61	81.5%	42,890	6,670	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	13	1	92.3%	26	2	92.3%	3,049	508	83.3%
HFD	-	2	0	100.0%	4	0	100.0%	151	8	94.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	2	0	100.0%	271	34	87.5%
MIA	89.5%	2	0	100.0%	4	0	100.0%	543	60	89.0%
MTR	79.0%	1	0	100.0%	2	0	100.0%	258	46	82.2%
NFK	84.5%	2	2	0.0%	4	3	25.0%	625	112	82.1%
NFL	93.5%	2	0	100.0%	4	0	100.0%	554	22	96.0%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	10	1	90.0%	1,416	224	84.2%
NPN	93.0%	2	0	100.0%	4	0	100.0%	517	35	93.2%
NYP	75.5%	46	12	73.9%	97	25	74.2%	11,151	2,487	77.7%
PGH	93.0%	1	0	100.0%	2	0	100.0%	273	19	93.0%
PHL	48.0%	5	0	100.0%	10	3	70.0%	1,410	680	51.8%
PIT	76.0%	-	-	-	-	-	-	6	5	16.7%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	1	0	100.0%	2	0	100.0%	1,059	41	96.1%
RNK	83.5%	2	0	100.0%	4	0	100.0%	538	77	85.7%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAB	98.0%	1	0	100.0%	2	0	100.0%	261	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	2	0	100.0%	270	10	96.3%
SFA	88.0%	1	0	100.0%	2	0	100.0%	271	37	86.3%
SPG	92.5%	5	1	80.0%	10	1	90.0%	1,662	93	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	2	0	100.0%	261	56	78.5%
WAS	84.0%	26	6	76.9%	57	11	80.7%	6,653	852	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	74	10	86.5%	149	17	88.6%	18,907	2,715	85.6%
ARN	92.0%	1	0	100.0%	2	0	100.0%	273	19	93.0%
BFD	79.0%	6	4	33.3%	13	5	61.5%	1,699	346	79.6%
EMY	72.0%	1	1	0.0%	2	1	50.0%	278	85	69.4%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	6	1	83.3%	822	115	86.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/02/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	303	46	84.8%	623	92	85.2%	81,981	11,217	86.3%
West Division	86.0%	74	10	86.5%	149	17	88.6%	18,907	2,715	85.6%
LAX	89.5%	9	1	88.9%	19	1	94.7%	2,433	237	90.3%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	12	1	91.7%	23	6	73.9%	2,922	742	74.6%
PDX	86.0%	1	0	100.0%	2	0	100.0%	257	59	77.0%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	1	93.8%	32	1	96.9%	3,836	411	89.3%
SAN	90.5%	13	1	92.3%	26	1	96.2%	3,270	295	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	0	100.0%	2	1	50.0%	254	104	59.1%
SJC	89.0%	7	0	100.0%	14	0	100.0%	1,921	182	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	6	0	100.0%	585	60	89.7%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	2	-	100.0%	268	20	92.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	308	2	0	100.0%	273	54	80.2%	2	1	50.0%	271	118	56.5%
4	161	2	0	100.0%	272	42	84.6%	2	2	0.0%	272	181	33.5%
5	47	2	1	50.0%	271	44	83.8%	1	1	0.0%	267	64	76.0%
6	140	2	1	50.0%	270	78	71.1%	2	1	50.0%	270	83	69.3%
7		2	1	50.0%	262	36	86.3%	2	1	50.0%	255	62	75.7%
8	65	2	1	50.0%	262	112	57.3%	2	2	0.0%	261	151	42.1%
11		2	0	100.0%	273	50	81.7%	2	0	100.0%	267	54	79.8%
14		2	0	100.0%	274	41	85.0%	2	0	100.0%	272	83	69.5%
19	No OS	2	1	50.0%	272	66	75.7%	2	2	0.0%	270	61	77.4%
20	123	2	0	100.0%	272	18	93.4%	2	2	0.0%	272	49	82.0%
21	85	2	0	100.0%	269	22	91.8%	2	2	0.0%	268	64	76.1%
22	37	2	0	100.0%	270	25	90.7%	2	2	0.0%	268	64	76.1%
23		2	1	50.0%	275	6	97.8%	2	1	50.0%	273	70	74.4%
24		2	0	100.0%	275	14	94.9%	2	0	100.0%	274	43	84.3%
25		2	0	100.0%	274	3	98.9%	2	0	100.0%	272	69	74.6%
26		2	0	100.0%	274	5	98.2%	2	0	100.0%	272	52	80.9%
27		2	2	0.0%	260	17	93.5%	2	1	50.0%	256	82	68.0%
28		2	0	100.0%	256	59	77.0%	2	0	100.0%	256	51	80.1%
40	302	2	0	100.0%	268	38	85.8%	2	2	0.0%	267	134	49.8%
41	106	2	1	50.0%	268	103	61.6%	2	2	0.0%	266	198	25.6%
42		2	0	100.0%	274	20	92.7%	2	1	50.0%	272	43	84.2%
43	141	2	0	100.0%	273	41	85.0%	2	2	0.0%	273	58	78.8%
48	46	2	1	50.0%	272	54	80.1%	2	2	0.0%	272	40	85.3%
49	143	2	2	0.0%	272	69	74.6%	2	1	50.0%	272	53	80.5%
51	399	1	1	0.0%	113	50	55.8%	1	1	0.0%	109	38	65.1%
52		2	0	100.0%	271	37	86.3%	2	0	100.0%	270	61	77.4%
53		2	0	100.0%	271	34	87.5%	2	0	100.0%	270	85	68.5%
55	86	2	0	100.0%	170	6	96.5%	2	1	50.0%	167	35	79.0%
56	54	2	0	100.0%	171	22	87.1%	2	2	0.0%	168	28	83.3%
63	37	2	2	0.0%	275	119	56.7%	2	2	0.0%	271	142	47.6%
64	28	2	0	100.0%	273	63	76.9%	2	2	0.0%	273	93	65.9%
66		2	0	100.0%	272	54	80.1%	2	0	100.0%	270	49	81.9%
67		1	0	100.0%	188	11	94.1%	2	0	100.0%	189	31	83.6%
68	43	2	0	100.0%	275	55	80.0%	2	2	0.0%	275	105	61.8%
69	42	2	0	100.0%	262	59	77.5%	2	1	50.0%	258	33	87.2%
71	11	2	0	100.0%	270	3	98.9%	2	2	0.0%	269	68	74.7%
78	70	2	0	100.0%	270	20	92.6%	2	1	50.0%	269	51	81.0%
79	85	2	0	100.0%	272	55	79.8%	2	2	0.0%	271	86	68.3%
80	55	2	0	100.0%	272	28	89.7%	2	2	0.0%	270	51	81.1%
85	44	2	0	100.0%	172	16	90.7%	2	2	0.0%	172	63	63.4%
86	33	2	0	100.0%	172	14	91.9%	2	2	0.0%	171	102	40.4%
89	91	2	1	50.0%	270	59	78.1%	2	2	0.0%	268	72	73.1%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
90	89	2	0	100.0%	270	10	96.3%	2	2	0.0%	269	39	85.5%
93	49	2	0	100.0%	171	18	89.5%	2	2	0.0%	170	39	77.1%
94	113	2	2	0.0%	202	52	74.3%	2	2	0.0%	200	71	64.5%
95	125	2	0	100.0%	171	3	98.2%	2	2	0.0%	171	61	64.3%
97	237	2	2	0.0%	272	175	35.7%	2	2	0.0%	270	78	71.1%
98	51	2	0	100.0%	272	21	92.3%	2	2	0.0%	270	82	69.6%
110		2	1	50.0%	168	97	42.3%	2	0	100.0%	165	16	90.3%
111		2	0	100.0%	162	32	80.2%	2	0	100.0%	160	20	87.5%
112		2	0	100.0%	162	16	90.1%	2	0	100.0%	161	17	89.4%
113		2	0	100.0%	93	22	76.3%	2	0	100.0%	92	11	88.0%
125	65	2	0	100.0%	172	8	95.3%	2	2	0.0%	172	68	60.5%
129	54	2	0	100.0%	171	44	74.3%	2	2	0.0%	171	25	85.4%
130		2	0	100.0%	162	16	90.1%	2	0	100.0%	160	15	90.6%
131	18	2	0	100.0%	164	47	71.3%	2	2	0.0%	164	31	81.1%
134	62	2	1	50.0%	172	22	87.2%	2	2	0.0%	171	28	83.6%
136		2	0	100.0%	172	20	88.4%	2	0	100.0%	170	17	90.0%
137	20	2	0	100.0%	169	30	82.2%	2	1	50.0%	169	53	68.6%
138	217	2	1	50.0%	172	36	79.1%	2	2	0.0%	171	29	83.0%
141		2	0	100.0%	171	3	98.2%	2	1	50.0%	170	29	82.9%
148	82	2	0	100.0%	171	17	90.1%	2	1	50.0%	169	31	81.7%
151	32	2	0	100.0%	271	86	68.3%	2	2	0.0%	270	86	68.1%
170		2	0	100.0%	167	12	92.8%	2	0	100.0%	166	29	82.5%
171	94	2	0	100.0%	172	10	94.2%	2	2	0.0%	172	63	63.4%
172	70	2	0	100.0%	171	14	91.8%	2	1	50.0%	169	56	66.9%
174	95	2	0	100.0%	172	20	88.4%	2	2	0.0%	172	40	76.7%
175		2	0	100.0%	172	21	87.8%	2	0	100.0%	172	55	68.0%
177		2	1	50.0%	172	25	85.5%	2	0	100.0%	172	44	74.4%
178	248	2	0	100.0%	172	24	86.0%	2	1	50.0%	170	24	85.9%
179	59	2	1	50.0%	172	20	88.4%	2	1	50.0%	171	59	65.5%
181		2	0	100.0%	168	54	67.9%	2	0	100.0%	166	12	92.8%
182	23	2	0	100.0%	162	28	82.7%	2	1	50.0%	160	17	89.4%
183		2	0	100.0%	171	48	71.9%	2	0	100.0%	169	33	80.5%
184	88	2	1	50.0%	172	30	82.6%	2	2	0.0%	171	25	85.4%
185		2	0	100.0%	172	36	79.1%	2	0	100.0%	172	11	93.6%
186		2	0	100.0%	171	17	90.1%	2	1	50.0%	170	41	75.9%
190		2	0	100.0%	171	62	63.7%	2	0	100.0%	170	37	78.2%
192		2	2	0.0%	169	21	87.6%	2	1	50.0%	169	15	91.1%
197	16	2	1	50.0%	172	69	59.9%	2	2	0.0%	172	55	68.0%
198		2	1	50.0%	104	15	85.6%	2	0	100.0%	103	16	84.5%
230		2	0	100.0%	109	4	96.3%	2	0	100.0%	109	6	94.5%
232		2	0	100.0%	275	11	96.0%	2	0	100.0%	275	17	93.8%
233		2	0	100.0%	253	56	77.9%	2	1	50.0%	253	74	70.8%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
234		2	0	100.0%	275	19	93.1%	2	0	100.0%	275	24	91.3%
235	42	2	0	100.0%	199	27	86.4%	2	2	0.0%	199	43	78.4%
236		2	0	100.0%	259	7	97.3%	2	0	100.0%	259	36	86.1%
237		2	0	100.0%	273	52	81.0%	2	1	50.0%	271	44	83.8%
238		2	0	100.0%	199	19	90.5%	2	0	100.0%	198	14	92.9%
239	42	2	1	50.0%	274	73	73.4%	2	1	50.0%	273	31	88.6%
240		2	0	100.0%	274	20	92.7%	2	1	50.0%	272	45	83.5%
241	59	2	1	50.0%	275	69	74.9%	2	1	50.0%	275	67	75.6%
243	42	2	2	0.0%	211	57	73.0%	2	2	0.0%	210	28	86.7%
244	41	2	0	100.0%	253	10	96.0%	2	2	0.0%	253	40	84.2%
245	107	2	1	50.0%	156	28	82.1%	2	1	50.0%	155	18	88.4%
280		2	0	100.0%	275	11	96.0%	2	0	100.0%	275	50	81.8%
281	42	2	0	100.0%	275	29	89.5%	2	2	0.0%	275	49	82.2%
283	43	2	1	50.0%	275	65	76.4%	2	2	0.0%	275	54	80.4%
284	22	2	0	100.0%	275	10	96.4%	2	2	0.0%	273	44	83.9%
290	28	2	0	100.0%	275	48	82.5%	2	2	0.0%	273	93	65.9%
291	30	2	1	50.0%	274	76	72.3%	2	2	0.0%	272	60	77.9%
300		2	0	100.0%	259	19	92.7%	2	0	100.0%	257	56	78.2%
301		2	0	100.0%	273	9	96.7%	2	0	100.0%	270	50	81.5%
302	62	2	0	100.0%	260	31	88.1%	2	1	50.0%	256	73	71.5%
305	30	2	0	100.0%	263	28	89.4%	2	2	0.0%	259	104	59.8%
306	138	2	0	100.0%	271	15	94.5%	2	2	0.0%	270	73	73.0%
307		2	0	100.0%	263	35	86.7%	2	1	50.0%	260	71	72.7%
311		2	0	100.0%	273	23	91.6%	2	0	100.0%	268	50	81.3%
316		2	0	100.0%	270	16	94.1%	2	0	100.0%	267	64	76.0%
318	53	2	0	100.0%	274	26	90.5%	2	1	50.0%	271	125	53.9%
319	50	2	0	100.0%	275	17	93.8%	2	1	50.0%	273	146	46.5%
329		2	0	100.0%	194	8	95.9%	2	0	100.0%	194	13	93.3%
330		2	0	100.0%	233	4	98.3%	2	0	100.0%	233	13	94.4%
331		2	0	100.0%	275	29	89.5%	2	0	100.0%	275	40	85.5%
332	45	2	0	100.0%	275	14	94.9%	2	1	50.0%	275	40	85.5%
334		2	0	100.0%	275	9	96.7%	2	0	100.0%	274	36	86.9%
335	18	2	0	100.0%	275	30	89.1%	2	2	0.0%	273	45	83.5%
336		2	0	100.0%	275	8	97.1%	2	0	100.0%	273	25	90.8%
337		2	0	100.0%	275	17	93.8%	2	0	100.0%	271	33	87.8%
338		2	2	0.0%	275	43	84.4%	2	1	50.0%	273	82	70.0%
339		2	1	50.0%	275	47	82.9%	2	0	100.0%	275	48	82.5%
341		2	0	100.0%	264	35	86.7%	2	0	100.0%	259	35	86.5%
342		2	0	100.0%	275	21	92.4%	2	0	100.0%	273	53	80.6%
350		2	0	100.0%	256	17	93.4%	2	1	50.0%	251	137	45.4%
351		2	0	100.0%	258	25	90.3%	2	0	100.0%	256	68	73.4%
352	21	2	0	100.0%	242	20	91.7%	2	1	50.0%	236	72	69.5%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
353		2	0	100.0%	217	12	94.5%	2	0	100.0%	211	35	83.4%
354	75	2	1	50.0%	256	29	88.7%	2	1	50.0%	252	90	64.3%
355	69	2	0	100.0%	269	27	90.0%	2	2	0.0%	262	87	66.8%
364	143	2	1	50.0%	264	61	76.9%	2	2	0.0%	258	92	64.3%
365	37	2	0	100.0%	263	10	96.2%	2	2	0.0%	261	94	64.0%
370		2	1	50.0%	266	34	87.2%	1	0	100.0%	258	65	74.8%
380	174	2	0	100.0%	261	24	90.8%	2	2	0.0%	261	51	80.5%
381	18	2	0	100.0%	275	11	96.0%	2	2	0.0%	274	50	81.8%
382	60	2	0	100.0%	274	16	94.2%	2	1	50.0%	274	85	69.0%
383		2	0	100.0%	264	25	90.5%	2	0	100.0%	262	105	59.9%
390		2	0	100.0%	257	17	93.4%	2	0	100.0%	256	63	75.4%
391	28	2	0	100.0%	260	8	96.9%	2	2	0.0%	257	67	73.9%
392	38	2	0	100.0%	274	5	98.2%	2	2	0.0%	272	80	70.6%
393	19	2	0	100.0%	275	16	94.2%	2	2	0.0%	272	79	71.0%
417		2	1	50.0%	182	39	78.6%	2	0	100.0%	173	17	90.2%
425		2	0	100.0%	184	6	96.7%	2	0	100.0%	184	7	96.2%
448	61	2	1	50.0%	205	39	81.0%	2	1	50.0%	203	69	66.0%
449	43	2	1	50.0%	203	31	84.7%	2	2	0.0%	203	38	81.3%
470		2	0	100.0%	195	34	82.6%	2	0	100.0%	189	23	87.8%
471		2	0	100.0%	185	6	96.8%	2	0	100.0%	185	2	98.9%
473		2	0	100.0%	191	13	93.2%	2	0	100.0%	188	8	95.7%
474	46	2	0	100.0%	186	51	72.6%	2	2	0.0%	174	49	71.8%
475	19	2	0	100.0%	189	5	97.4%	2	1	50.0%	189	11	94.2%
478		2	1	50.0%	183	28	84.7%	2	0	100.0%	181	20	89.0%
479	39	2	2	0.0%	190	31	83.7%	2	2	0.0%	188	24	87.2%
486	67	2	1	50.0%	194	29	85.1%	2	2	0.0%	188	52	72.3%
494	119	2	0	100.0%	195	35	82.1%	2	2	0.0%	189	46	75.7%
495		2	0	100.0%	180	3	98.3%	2	0	100.0%	178	3	98.3%
500		2	0	100.0%	266	15	94.4%	2	0	100.0%	264	32	87.9%
502		2	0	100.0%	273	15	94.5%	2	0	100.0%	270	56	79.3%
503	23	2	0	100.0%	271	25	90.8%	2	1	50.0%	265	75	71.7%
504		2	0	100.0%	275	17	93.8%	2	0	100.0%	273	82	70.0%
505	22	2	0	100.0%	273	36	86.8%	2	1	50.0%	269	74	72.5%
506		2	0	100.0%	270	38	85.9%	2	0	100.0%	265	41	84.5%
507	19	2	0	100.0%	275	34	87.6%	2	1	50.0%	275	89	67.6%
508		2	0	100.0%	270	39	85.6%	2	0	100.0%	267	62	76.8%
509		2	0	100.0%	272	12	95.6%	2	0	100.0%	272	63	76.8%
511		2	0	100.0%	267	21	92.1%	2	0	100.0%	266	45	83.1%
516		2	0	100.0%	267	27	89.9%	2	1	50.0%	266	124	53.4%
517	32	2	0	100.0%	275	8	97.1%	2	2	0.0%	271	110	59.4%
518	48	2	0	100.0%	275	35	87.3%	2	2	0.0%	273	185	32.2%
519		2	0	100.0%	267	9	96.6%	2	0	100.0%	265	63	76.2%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
520		2	0	100.0%	152	24	84.2%	2	0	100.0%	149	9	94.0%
521		2	0	100.0%	190	7	96.3%	2	1	50.0%	190	24	87.4%
522		2	0	100.0%	190	36	81.1%	2	0	100.0%	187	18	90.4%
523		2	0	100.0%	190	6	96.8%	2	0	100.0%	189	22	88.4%
524		2	0	100.0%	190	11	94.2%	2	0	100.0%	188	20	89.4%
525		2	0	100.0%	188	12	93.6%	2	0	100.0%	185	13	93.0%
526	12	2	0	100.0%	164	29	82.3%	2	1	50.0%	161	13	91.9%
527		2	0	100.0%	190	9	95.3%	2	0	100.0%	189	32	83.1%
528		2	0	100.0%	190	15	92.1%	2	0	100.0%	189	29	84.7%
529		2	0	100.0%	190	11	94.2%	2	0	100.0%	189	50	73.5%
530	14	2	0	100.0%	144	14	90.3%	2	1	50.0%	144	27	81.3%
531	18	2	0	100.0%	164	12	92.7%	2	1	50.0%	164	12	92.7%
532	12	2	1	50.0%	190	44	76.8%	2	1	50.0%	189	28	85.2%
534		2	0	100.0%	149	24	83.9%	2	0	100.0%	147	15	89.8%
535		2	1	50.0%	177	24	86.4%	2	0	100.0%	172	20	88.4%
536		2	0	100.0%	190	49	74.2%	2	0	100.0%	187	37	80.2%
537		2	0	100.0%	161	18	88.8%	2	0	100.0%	156	16	89.7%
538		2	0	100.0%	190	23	87.9%	2	1	50.0%	189	38	79.9%
539		2	0	100.0%	144	20	86.1%	2	1	50.0%	144	65	54.9%
540		1	1	0.0%	189	36	81.0%	1	0	100.0%	182	18	90.1%
541	18	2	0	100.0%	189	21	88.9%	2	1	50.0%	184	34	81.5%
542		2	0	100.0%	189	21	88.9%	2	1	50.0%	187	33	82.4%
543	42	2	0	100.0%	190	19	90.0%	2	2	0.0%	190	52	72.6%
544		2	0	100.0%	188	20	89.4%	2	0	100.0%	185	15	91.9%
545		2	0	100.0%	190	15	92.1%	2	0	100.0%	188	22	88.3%
547		2	0	100.0%	190	37	80.5%	2	0	100.0%	190	44	76.8%
548		1	0	100.0%	185	20	89.2%	1	0	100.0%	184	14	92.4%
549		2	0	100.0%	185	25	86.5%	2	0	100.0%	178	16	91.0%
550		2	0	100.0%	144	14	90.3%	2	0	100.0%	144	31	78.5%
551		2	0	100.0%	186	19	89.8%	2	0	100.0%	178	17	90.4%
562		2	0	100.0%	267	21	92.1%	2	0	100.0%	264	29	89.0%
564	32	2	0	100.0%	267	17	93.6%	2	1	50.0%	259	31	88.0%
566		2	0	100.0%	265	17	93.6%	2	0	100.0%	262	32	87.8%
567		2	0	100.0%	152	8	94.7%	2	0	100.0%	150	6	96.0%
572	17	2	0	100.0%	262	22	91.6%	2	1	50.0%	257	66	74.3%
573		2	0	100.0%	265	40	84.9%	2	0	100.0%	258	44	82.9%
579		2	0	100.0%	152	8	94.7%	2	0	100.0%	147	26	82.3%
580		2	0	100.0%	267	14	94.8%	2	0	100.0%	262	21	92.0%
581		2	0	100.0%	267	43	83.9%	2	0	100.0%	265	54	79.6%
584	38	2	1	50.0%	151	18	88.1%	2	2	0.0%	147	84	42.9%
587	24	2	0	100.0%	262	15	94.3%	2	1	50.0%	253	39	84.6%
588		2	0	100.0%	152	12	92.1%	2	0	100.0%	151	22	85.4%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591		2	0	100.0%	266	18	93.2%	2	0	100.0%	260	29	88.8%
593		2	0	100.0%	261	37	85.8%	2	1	50.0%	243	28	88.5%
595		2	1	50.0%	262	42	84.0%	2	1	50.0%	259	47	81.9%
600		2	0	100.0%	199	9	95.5%	2	0	100.0%	197	15	92.4%
601		2	1	50.0%	182	73	59.9%	2	0	100.0%	179	23	87.2%
605		2	1	50.0%	189	119	37.0%	2	0	100.0%	185	19	89.7%
607		2	0	100.0%	198	24	87.9%	2	0	100.0%	195	22	88.7%
609	39	2	0	100.0%	189	22	88.4%	2	1	50.0%	188	16	91.5%
626		2	0	100.0%	103	12	88.3%	2	0	100.0%	101	15	85.1%
640		2	0	100.0%	189	7	96.3%	2	0	100.0%	187	76	59.4%
641		2	0	100.0%	171	34	80.1%	2	0	100.0%	171	25	85.4%
642		2	0	100.0%	187	9	95.2%	2	0	100.0%	186	23	87.6%
643		2	0	100.0%	201	39	80.6%	2	0	100.0%	198	32	83.8%
644		2	0	100.0%	193	27	86.0%	2	1	50.0%	191	49	74.3%
645	Cncld	2	0	100.0%	201	38	81.1%	1	1	0.0%	198	40	79.8%
646	17	2	1	50.0%	190	47	75.3%	2	2	0.0%	188	91	51.6%
647	33	2	0	100.0%	201	31	84.6%	2	2	0.0%	200	45	77.5%
648	18	2	0	100.0%	197	50	74.6%	2	1	50.0%	197	32	83.8%
649		2	2	0.0%	202	39	80.7%	2	0	100.0%	199	31	84.4%
650	12	2	0	100.0%	201	39	80.6%	2	2	0.0%	198	32	83.8%
651	27	2	0	100.0%	201	16	92.0%	2	2	0.0%	199	41	79.4%
652	37	2	0	100.0%	202	27	86.6%	2	2	0.0%	198	34	82.8%
653	56	2	0	100.0%	190	30	84.2%	2	2	0.0%	187	36	80.7%
654	Cncld	2	1	50.0%	191	37	80.6%	1	0	100.0%	187	16	91.4%
655	18	2	1	50.0%	199	70	64.8%	2	2	0.0%	197	70	64.5%
656	20	2	0	100.0%	201	45	77.6%	2	1	50.0%	200	22	89.0%
657		2	0	100.0%	190	26	86.3%	2	0	100.0%	189	28	85.2%
658		2	0	100.0%	201	34	83.1%	2	0	100.0%	199	30	84.9%
680		2	2	0.0%	195	11	94.4%	2	0	100.0%	194	24	87.6%
681		2	0	100.0%	195	14	92.8%	2	1	50.0%	190	73	61.6%
682		2	0	100.0%	194	5	97.4%	2	0	100.0%	194	33	83.0%
683	38	2	0	100.0%	177	15	91.5%	2	2	0.0%	176	53	69.9%
684		2	1	50.0%	176	28	84.1%	2	0	100.0%	176	38	78.4%
685	51	2	1	50.0%	191	29	84.8%	2	2	0.0%	188	46	75.5%
686	17	2	0	100.0%	196	33	83.2%	2	2	0.0%	195	38	80.5%
687	46	2	2	0.0%	195	32	83.6%	2	2	0.0%	194	33	83.0%
688	31	2	2	0.0%	194	11	94.3%	2	2	0.0%	193	32	83.4%
689		2	1	50.0%	141	19	86.5%	1	0	100.0%	139	20	85.6%
701		2	1	50.0%	207	22	89.4%	2	0	100.0%	204	20	90.2%
702		2	0	100.0%	274	31	88.7%	2	1	50.0%	272	61	77.6%
703		2	1	50.0%	275	78	71.6%	2	1	50.0%	274	71	74.1%
704		2	0	100.0%	206	32	84.5%	1	0	100.0%	200	38	81.0%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710		2	1	50.0%	275	70	74.5%	2	1	50.0%	271	74	72.7%
711	18	2	1	50.0%	266	29	89.1%	2	1	50.0%	249	46	81.5%
712		2	1	50.0%	272	72	73.5%	2	0	100.0%	264	87	67.0%
715	Cncld	2	1	50.0%	274	59	78.5%	1	1	0.0%	254	126	50.4%
716		2	0	100.0%	275	107	61.1%	2	1	50.0%	270	103	61.9%
717		2	0	100.0%	261	62	76.2%	2	1	50.0%	243	71	70.8%
718	497	2	1	50.0%	275	137	50.2%	2	2	0.0%	273	93	65.9%
719	104	2	1	50.0%	275	89	67.6%	2	2	0.0%	261	74	71.6%
757		2	0	100.0%	60	3	95.0%	2	0	100.0%	59	4	93.2%
761		2	0	100.0%	271	11	95.9%	2	0	100.0%	268	34	87.3%
765		2	0	100.0%	271	24	91.1%	2	0	100.0%	271	36	86.7%
769		2	0	100.0%	271	25	90.8%	2	0	100.0%	265	49	81.5%
770		2	0	100.0%	271	21	92.3%	2	0	100.0%	269	74	72.5%
774		2	0	100.0%	271	16	94.1%	2	0	100.0%	270	56	79.3%
777		2	0	100.0%	156	9	94.2%	2	0	100.0%	155	34	78.1%
782		2	1	50.0%	156	57	63.5%	2	0	100.0%	151	15	90.1%
785		2	0	100.0%	271	17	93.7%	2	0	100.0%	271	46	83.0%
786		2	0	100.0%	60	16	73.3%	2	0	100.0%	59	27	54.2%
790		2	0	100.0%	271	26	90.4%	2	0	100.0%	268	32	88.1%
794	138	2	0	100.0%	271	31	88.6%	2	1	50.0%	268	56	79.1%
821		2	0	100.0%	269	6	97.8%	2	1	50.0%	269	104	61.3%
822	17	2	0	100.0%	271	14	94.8%	2	1	50.0%	269	119	55.8%
1333	199	2	2	0.0%	271	30	88.9%	2	2	0.0%	268	90	66.4%
1340	17	2	0	100.0%	270	5	98.1%	2	1	50.0%	270	43	84.1%
2102		2	0	100.0%	48	12	75.0%	2	0	100.0%	47	4	91.5%
2103		2	0	100.0%	112	10	91.1%	2	0	100.0%	111	9	91.9%
2104		2	0	100.0%	138	9	93.5%	2	0	100.0%	136	10	92.6%
2107		2	1	50.0%	169	31	81.7%	2	0	100.0%	166	20	88.0%
2108	25	2	0	100.0%	169	25	85.2%	2	1	50.0%	163	18	89.0%
2109		2	0	100.0%	62	9	85.5%	2	0	100.0%	61	4	93.4%
2112	28	2	1	50.0%	9	3	66.7%	1	1	0.0%	7	1	85.7%
2113		2	0	100.0%	48	3	93.8%	2	0	100.0%	48	7	85.4%
2115	25	2	0	100.0%	48	5	89.6%	2	2	0.0%	47	6	87.2%
2116	38	2	0	100.0%	9	0	100.0%	2	2	0.0%	9	4	55.6%
2118	76	2	1	50.0%	9	1	88.9%	2	2	0.0%	9	4	55.6%
2119	74	2	0	100.0%	9	2	77.8%	2	2	0.0%	9	3	66.7%
2120	56	2	2	0.0%	9	5	44.4%	1	1	0.0%	8	4	50.0%
2123	32	2	1	50.0%	47	7	85.1%	1	1	0.0%	46	14	69.6%
2124	44	2	2	0.0%	141	25	82.3%	2	2	0.0%	139	15	89.2%
2127	18	2	2	0.0%	9	3	66.7%	2	2	0.0%	8	2	75.0%
2128		2	0	100.0%	9	0	100.0%	2	0	100.0%	9	0	100.0%
2131		2	1	50.0%	9	1	88.9%	2	0	100.0%	9	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 7/2/2026

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2150		2	0	100.0%	162	22	86.4%	2	0	100.0%	159	67	57.9%
2151		2	0	100.0%	111	6	94.6%	2	0	100.0%	109	29	73.4%
2155	72	2	0	100.0%	171	14	91.8%	2	1	50.0%	167	91	45.5%
2158	87	2	0	100.0%	9	2	77.8%	2	2	0.0%	9	2	77.8%
2159	62	2	1	50.0%	164	12	92.7%	2	2	0.0%	162	50	69.1%
2160	73	2	0	100.0%	9	0	100.0%	2	2	0.0%	9	6	33.3%
2162	73	2	0	100.0%	170	13	92.4%	2	1	50.0%	164	78	52.4%
2171	36	2	0	100.0%	98	8	91.8%	2	2	0.0%	95	20	78.9%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	25	CAR	16	CAR	16	PHL-PHL	AM	Heat / AC, 3273 NG NS
2112	NYP	28	WTR	34	WTR	11	XHM-XCY	AM	Heat order, Other, CROY-XCY
2115	WAS	25	WTR	31	WTR	14	XCY-XHM	AM	Heat order, Other, XCY-XHM
2116	NYP	38	WTR	34	WTR	13	BAL-XPV	AM	Heat order, Milepost, 75.0, 74.0, Milepost, 64.0, 62.0, 30 MPH HEAT RESTRICTION ON NO. 2 TRK
2118	NYP	76	WTR	34	ITI	33	WAS-WAS	AM	Service, turn, or wye train, 2155, LATE INBOUND
2119	WAS	74	WTR	37	CAR	20	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, MET WITH MECHANICAL A/C MULTIPLE HOT CARS
2120	NYP	56	ITI	30	ITI	30	WAS-WAS	AM	Service, turn, or wye train, 2159, late inbound
2123	WAS	32	DET	18	DET	18	XCY-XHM	AM	Catenary maintenance , Other, TRE-XHM, CONGESTION ADH OPR 3 TO 2 TRK A/C EMERGENCY PLATE ON 4 TRK AT CROY
2124	NYP	44	ITI	51	ITI	51	WAS-WAS	AM	Service, turn, or wye train, 2119, ITI - LATE INBOUND 2119
2127	WAS	18	DCS	24	DCS	20	XCY-XHM	AM	Power switch failure, Other, HOLMES, HELD AT CROY A/C 43 SWITCH AT HOLMES FAILING
2155	WAS	72	WTR	34	ENG	32	PVD-PVD	AM	Air / Brake, 2115 NG NP, brake fault on 2115, hard reset to clear fault
2158	BOS	87	WTR	30	ENG	25	NHV-XGX	AM	Traction motor, 2124 NG NP, AM2158 loss 4 traction motors, trouble shooting
2159	WAS	62	WTR	47	CAR	18	NHV-NHV	MN	Air / Brake / Wheel 3736, 3737, SERVICE BRAKE FAULT BETWEEN PV4 and PV5. Required us to Deprepare the train set and Reprepare to clear fault.
2160	BOS	73	WTR	25	ENG	19	BWI-XPV	AM	PTC - On Board Cab Signal or PTC Failure, 2117 NG NP, ACSES HELD TRAIN TO 30MPH BETWEEN GRACE AND MP 60
2162	BOS	73	CAR	52	CAR	31	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, ATTEMPTED TO DO 2 FULL HVAC RESETS A/C HOT CARS AND ENGINE
2171	WAS	36	ENG	23	SMW	16	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAM BAY DUE TO 2 TRACK OOS
85	WAS	44	CAR	29	CAR	29	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, MET WITH MECHANICAL A/C MULTIPLE HOT CARS
86	BOS	33	CTI	23	DSR	14	STM-BRP	MN	Per bulletin Milepost, 41.7, 42.0, 15, 2

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
93	NFK	49	CAR	33	CAR	33	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, MET WITH MECHANICAL A/C MULTIPLE HOT CARS
94	BOS	113	WTR	46	FTI	30	QAN-ALX	CS	Follow IO32, Milepost, 78.8, 105.2
95	NFK	125	DSR	52	CTI	35	WDB-FBG	CS	Follow VRE, 303, Other, WBD
125	NPN	65	WTR	54	FTI	14	FBG-ASD	CS	Follow M415, Milepost, 29.5, 14.7
129	WAS	54	DCS	37	DCS	32	TRE-XHM	AM	Power switch failure, Other, CROY, HELD AT CROY A/C 43 SWITCH AT HOLMES FAILING
131	WAS	18	WTR	26	WTR	9	NWK-NBK	AM	Heat order, Other, X94-NBK
134	NYP	62	WTR	34	CAR	23	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, MULTIPLE HOT CARS ADDRESSED BY MECHANICAL
137	WAS	20	WTR	10	WTR	7	RTE-PVD	AM	Heat order, Control Point, Junction, 80MPH S/R MP 227.0
138	NYP	217	WTR	152	WTR	120	NFK-X3V	NS	Heat order Milepost w/Letters, n3.2, p3.1
148	SPG	82	WTR	34	SYS	18	EWR-EWR	AM	Re-crew / job briefing, RE-CREW IN AIRPORT
151	RNK	32	PTI	18	WTR	18	LYH-RNK	NS	Heat order Milepost, 239, 257.4
171	RNK	94	WTR	97	WTR	27	MSS-CLP	NS	Heat order Milepost, 32.6, 67.4
172	BOS	70	CTI	24	INJ	11	PVD-PVD	AM	Injured or sick passenger, medical emergency, child fell in the pit, had to wait for EMS PVD
174	BOS	95	CAR	58	CAR	58	NHV-NHV	AM	Heat / AC, 82522 AX AS, AM174 held in NHV a/c mechanical inspecting cars with no AC
178	BOS	248	WTR	166	WTR	59	CVS-CLP	NS	Heat order Milepost, 112.2, 67.4
179	PHL	59	HLD	23	SVS	22	BOS-BOS	AM	Water, commissary, toilet/trash dumping, Depart BOS late a/c servicing bathrooms on late incoming AM86 BOS
182	NYP	23	WTR	14	WTR	14	XHM-EWR	AM	Heat order, Other, XHM-EWR
184	BOS	88	WTR	45	CAR	20	PHL-PHL	AM	Heat / AC, ENTIRE CONSIST, MET WITH MECHANICAL A/C MULTIPLE HOT CARS
197	WAS	16	DCS	26	DCS	26	NWK-XHM	AM	Power switch failure, Other, CROY, HELD A/C 43 SWITCH AT HOLMES FAILING
474	SPG	46	CON	34	CON	34	NHV-NHV	AM	Hold for connecting train, AM474 held for late AM174
475	NHV	19	WTR	9	WTR	9	WFD-STO	AM	Heat order, Milepost w/Letters, WFD, STS, heat patrol trk 2 and waited for two trains, AM474 and CT4462, to clear

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
479	NHV	39	ITI	41	ITI	41	GFD-GFD	MA	486 late 486
486	GFD	67	WTR	41	WTR	41	HFD-WND	AM	Heat order, Milepost w/Letters, HFD, WND, AM486 delayed due to Heat Patrol
494	GFD	119	CON	109	CON	109	NHV-NHV	AM	Hold for connecting train, late connection of AM94
79	CLT	85	WTR	69	WTR	24	PTB-RMT	CS	Heat order Other, rmt
80	NYP	55	WTR	51	FTI	33	GRO-BNC	NS	Meet NS 351, Control Point, Superior
609	HAR	39	DET	26	DET	18	PAR-PAR	AM	Catenary failure, Control Point, LEAMAN TO RHEEMS, HELD AT PARK A/C DOWNED CATENARY WIRES AND 645 WITH BROKEN PANTOGRAPHS ON NO 2 TRK.
645	HAR	Trn Cancelled	DET	92	DET	92	LNC-LNC	AM	Catenary failure, Control Point, LEAMAN TO RHEEMS, ANNULLED AT LANCASTER A/C BROKEN PANTOGRAPHS DUE TO DOWNED CATENARY WIRES
646	NYP	17	CTI	12	CTI	5	TRE-PJC	AM	Follow, NJT, NJ3840, Other, XH1-PJC
647	HAR	33	PTI	16	WTR	9	EWB-TRE	AM	Heat order, Other, EWB-TRE
648	NYP	18	WTR	33	WTR	15	TRE-NWK	AM	Heat order, Other, TRE-NWK
650	NYP	12	PTI	14	PTI	6	XHM-TRE	AM	Follow, AM2112, Other, XHM-TRE
651	HAR	27	DET	25	DET	11	TRE-XHM	AM	Catenary maintenance , Other, TRE-XHM, CONGESTION OPR 3 TO 2 TRK A/C EMERGENCY AC PLATE ON 4 TRK AT CROY
652	NYP	37	PTI	19	PTI	14	PHL-XHM	AM	Follow, 94, Control Point, ., 94 AHEAD AND HELD TO GET 2123 WEST
653	HAR	56	DCS	20	DCS	20	TRE-XHM	AM	Power switch failure, Other, CROY, HELD A/C SWITCH ISSUES AT HOLMES
654	NYP	Trn Cancelled							
655	HAR	18	OTH	13	WTR	7	NWK-TRE	AM	Heat order, Other, NWK-TRE
656	NYP	20	DET	21	DET	18	ELT-ELT	AM	Catenary failure, Control Point, LEAMAN TO RHEEMS, SINGLE TRACKING LEAMAN TO RHEEMS A/C DOWNED CATENARY WIRES AND 645 WITH BROKEN PANTOGRAPHS ON NO 2 TRK.

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
19	NOL	No OS Rpt	FTI	209	TRS	131	WAS-WAS	AM	Vehicle strike, Other, Vehicle Strike, LATE DSL FROM PIT DUE TO 37 DSL COMING OFF LATE INBOUND 80(1). Necessary to use 80's diesels for 19 due to 20 arriving into WAS 8hrs, 57mins late due to vehicle strike south of BHM.
20	NYP	123	WTR	84	WTR	51	CLP-MSS	NS	Heat order Milepost, 55.9, 10.7
683	BRK	38	WTR	20	PTI	7	EXR-DHM	CS	Meet 684, Control Point, rockingham
685	BRK	51	DCS	30	DCS	25	FRE-BRK	CS	Restrictive signal(s) from unknown cause Required permission to pass BOW Church and Brunswick West. Restricted speed the entire mileage., Stop, Control Point, Church
686	BON	17	WTR	13	PTI	7	ORB-SAO	CS	Meet 683, Control Point, surf
687	BRK	46	DCS	19	PTI	18	WEM-SAO	CS	Meet Dispatcher held us for a 35m late 688., 688, Control Point, wells
688	BON	31	DCS	19	DCS	17	BRK-FRE	CS	Restrictive signal(s) from unknown cause Restricted speed from Brunswick West to the distant signal to Bow., Stop signal, Control Point, Church
63	TWO	37	HLD	5	SVS	4	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
64	NYP	28	WTR	47	FTI	14	ROC-XSV	CS	Follow Followed CSX I020201 from East Palmyra detector to SYR station., CSX I020301, Milepost, 345.0, 291.4
68	NYP	43	WTR	56	WTR	45	SLQ-RSP	CN	Heat order Milepost, 40, 0
69	MTR	42	WTR	61	WTR	48	XLQ-SLQ	CN	Heat order Milepost, 0, 43
235	ALB	42	RTE	14	RTE	10	RHI-HUD	AM	Dispatcher hold Control Point, 114
239	ALB	42	MTI	59	MTI	59	NYP-NYP	AM	Disabled train ahead, Other, F-INT, HELD ON LOOPS A/C AM290 WITH MECHANICAL ISSUES WAS NECESSARY TO LOOP THROUGH SSYD FOR ENGINE E-716 TO LEAD AM290
241	ALB	59	MTI	49	MTI	49	NYP-NYP	AM	Disabled train ahead, Other, F-INT, HELD ON THE LOOPS A/C AM290 WITH MECHANICAL ISSUES LOOPING BACK INTO SSYD
243	ALB	42	ITI	27	ITI	27	NYP-NYP	AM	Service, turn, or wye train, 244, LATE TURN OFF AM244
244	NYP	41	CTI	28	CTI	17	POU-CRT	MN	Follow metro, 882, Control Point, 72, Control Point, 46

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
245	ALB	107	ITI	108	ITI	108	NYP-NYP	AM	Service, turn, or wye train, 68, LATE TURN OFF OF AM68
281	NFL	42	WTR	72	WTR	23	ROM-SYR	CS	Heat order Control Point, 251
283	NFL	43	WTR	36	WTR	20	AMS-UCA	CS	Heat order Other, mohawk subdivision
284	NYP	22	CTI	18	CTI	16	POU-CRT	MN	Follow mn, Control Point, 72
290	NYP	28	CTI	24	CTI	21	POU-CRT	MN	Follow metro north, Milepost, 72, 35
291	BTN	30	WTR	15	WTR	11	CRT-POU	MN	Heat order Control Point, 12, Control Point, 75
48	NYP	46	FTI	72	DCS	28	POU-CRT	MN	Restrictive signal(s) from known wayside signal failure Stop, Control Point, 39
49	CHI	143	WTR	87	FTI	34	SKY-TOL	NS	Follow 334, Control Point, 286
448	BOS	26	FTI	37	FTI	37	ALB-XRD	CS	Cross Traffic csx, csx, Control Point, 187
449	ALB	43	PTI	30	CTI	19	BBY-FRA	MT	Follow Keolis, 541, Control Point, 6, Control Point, 24
43	PGH	141	DSR	67	WTR	60	HAR-XNN	NS	Heat Kink in the rail at 118.3. Engineer stopped train and had NS track foreman walk us by. Milepost, 118.3, 118.3
71	CLT	11	TEN	13	TEN	7	DNC-DNC	NS	Failure of diesel engine NC1755
78	RGH	70	WTR	49	WTR	45	CLT-KAN	NS	Heat order Heat Order 25mph, Milepost, 376, 347.1
89	SAV	91	FTI	67	FTI	58	CHS-YEM	CS	Follow m 491, Milepost, 415.5, 432.0
90	NYP	89	PTI	62	PTI	22	FAY-SSM	CS	Wait for station track 92, Other, a161.1
97	MIA	237	WTR	112	SVS	77	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND SERVICE CARS
98	NYP	51	DMW	113	DMW	113	YEM-CHS	CS	On track equipment #CS72549, Control Point, YEM STA
55	WAS	86	WTR	40	SMW	24	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT-PELHAM BAY DUE TO 2 TRACK OOS
56	SAB	54	DSR	37	WTR	11	NHT-GFD	MA	Heat order Milepost, 1, 110
40	CHI	302	FTI	191	ENG	86	WAS-WAS	AM	Cab signal failure, 339, NO CAB SIGNALS ON DSL 339 WHEN IT ARRIVED, NEC'Y TO FLAT SWITCH DSLS

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
41	MIA	106	WTR	98	POL	30	RVR-PTB	CS	Right of Way police hold Police were clearing an accident on the crossing at wamsley blvd
5	EMY	47	FTI	109	FTI	33	RNO-TRU	UP	Meet up, Control Point, west reno
6	CHI	140	DSR	79	FTI	25	XNV-XSZ	UP	Follow Follow to Low, Siding, Low, UP 8808, intermodal
526	SAC	12	MBO	25	MBO	25	MTZ-SUI	UP	For maritime traffic Control Point, Vista
530	SAC	14	PTI	9	PTI	9	SCC-GAC	UP	Meet amtk 529, Control Point, expressway
531	OKJ	18	MBO	25	MBO	25	SUI-MTZ	UP	For maritime traffic Bridge, Benicia
532	SAC	12	MBO	22	MBO	22	MTZ-SUI	UP	For maritime traffic Control Point, vista
541	OKJ	18	MBO	22	MBO	22	SUI-MTZ	UP	For maritime traffic Control Point, rv035
543	SJC	42	PTI	43	PTI	19	FMT-GAC	UP	Meet AMT 544, Control Point, Albrae
51	CHI	399	WTR	149	FTI	69	CRF-LAF	CS	Meet m641, Control Point, SE switzer
503	EUG	23	FTI	37	FTI	21	KEL-VAN	BN	Meet UP 8063, Control Point, Fruit Valley
505	PDX	22	FTI	11	FTI	11	KEL-VAN	BN	Meet Unknown, Control Point, Vancouver Center
507	EUG	19	DSR	15	PTI	12	PDX-ORC	UP	Meet 508, Siding, clackamas
517	PDX	32	PTI	25	PTI	16	TAC-XNI	ST	Meet AMT 504, Control Point, Rill
518	VAC	48	FTI	21	PTI	13	EVR-STW	BN	Meet amtk 519, Siding, english
8	CHI	65	FTI	143	FTI	28	HAV-MAL	BN	Meet Duck and Tuck, BN 5926, Siding, Lobman
822	OKC	17	DSR	29	DSR	19	FTW-GLE	BN	Per bulletin Milepost, 354, 354.5, 70, main 1, Milepost, 355.5, 355.7, 70, main 1, Milepost, 360.6, 361.1, 30, main 1, Milepost, 364.7, 365.1, 60, main 1, Milepost, 370.6, 370.7, 30, main, Milepost, 374, 374.1, 60, main, Milepost, 379.5, 380, 60, main, Milepost, 383.4, 383.6, 60, main, Milepost, 385
332	CHI	45	DCS	40	DCS	33	GLN-XWA	ME	Power outage A2 Control Point, A3
335	MKE	18	DCS	11	DCS	11	XRO-SVT	CP	Power switch failure West crossover switch issue, maintainer on-site, waiting on CPKC 148 to go by before being routed to MT2, Control Point, Wadsworth
352	PNT	21	FTI	17	DCS	16	KAL-XGO	CC	Power switch failure Switch failure led to manual movement of switch, Control Point, GORD
354	PNT	75	MBO	82	MBO	82	XTF-XH6	NS	Broken bridge Milepost, 509, 503

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
355	CHI	69	PTI	51	FTI	32	XMC-XPI	NS	Cross Traffic unkn, Control Point, 482
364	PTH	143	DCS	66	DCS	51	XPI-XMC	AM	T.O.L Other, 239
365	CHI	37	DSR	47	DSR	31	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, MAIN TWO, Milepost, 221.42, 221.42, 30, MAIN, Milepost, 219.15, 219.15, 25, MAIN, Milepost, 219, 218.5, 30, MAIN, Milepost, 216.1, 215.79, 60, MAIN, Milepost, 214.96, 214.96, 25, MAIN TWO, Milepost, 214.93, 214.93, 25, MAIN ONE, Milepost, 210.40, 210.40, 30
564	SAN	32	CTI	36	CTI	13	XRJ-FUL	BN	Meet Metrolink, 603, Metrolink, 703, Control Point, hobart
572	SAN	17	CTI	12	CTI	12	OSD-SOL	SN	Meet NCTD, 633, Control Point, ponto
584	SAN	38	PTI	26	PTI	15	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	24	CTI	42	CTI	28	OSD-X98	SC	Meet metrolink, Control Point, songs
794	SAN	138	TRS	149	TRS	145	ANA-ANA	SC	Trespasser strike Other, Orange to SNA
711	OKJ	18	PTI	16	PTI	13	SKN-ACA	BN	Meet 710, Control Point, trull
715	OKJ	Trn Cancelled	OTH	34	TCR	22	BFD-BFD	BN	HEP C2104
718	BFD	497	TEN	327	TEN	327	MCD-MDR	BN	Failure of diesel engine Locomotive overheated and shut down., C2104
719	OKJ	104	SVS	51	SVS	51	HNF-FNO	BN	Fuel Stopped at the Fresno yard office for refueling., Other, fresno yard
3	LAX	308	FTI	394	FTI	169	GBB-FMD	BN	Follow Also has bridge open 3 times, BNSF 6133, Control Point, Ormonde
4	CHI	161	FTI	160	FTI	40	KNG-FLG	BN	Follow UNKN BNSF E, Milepost, 475, 385.8
21	SAS	85	DBS	99	DBS	99	XTF-XUD	CC	Debris strike Brake hose had a hole with the debris strike, Not sure , Milepost, 28, 33
22	CHI	37	DSR	64	WTR	40	MVN-LRK	UP	Line manual or spring switch CTC would not work had to line main track for dispatcher manually to track 2 northbound for LRK station, Commercial power outage due to weather, Other, Milepost, 370.0, 368.0
302	CHI	62	FTI	68	FTI	26	SMT-XTF	CC	Cross Traffic unknown, Control Point, corwith
305	STL	30	PTI	21	PTI	15	JOL-DWT	UP	Meet 318, Siding, dewight
306	CHI	138	FTI	138	FTI	132	SMT-XTF	CC	Cross Traffic NA, Other, CORWITH

Amtrak Endpoint OTP Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
380	CHI	174	FTI	154	FTI	106	QCY-MAC	BN	Follow Followed UP 5451 whom followed BN 7321 w/hot wheel on single main, UP 5451 E, BN 7321 E, Milepost, 245.0, 204.0	
381	QCY	18	FTI	13	FTI	11	MAC-QCY	BN	Meet bnsf 5194, Control Point, colchester	
382	CHI	60	RTE	31	FTI	23	MAC-GBB	BN	Cross over or go around Yard New long 3. Freight on MT, Milepost, 168.0, 162.4, 5194, BNSF	
391	CDL	28	WTR	25	FTI	7	EFG-CEN	CC	Cross Traffic UP Freight, Control Point, Kinmundy	
392	CHI	38	WTR	45	WTR	10	CEN-EFG	CC	Heat order Milepost w/Letters, CEN, efg	
393	CDL	19								
318	CHI	53	ADA	32	FTI	21	XUD-SMT	CC	Cross Traffic Unknown freight, Control Point, Canal	
319	KCY	50	DCS	23	DCS	20	XTF-SMT	CC	Restrictive signal(s) from unknown cause Signal dropped at Corwith Twice Talked with CN PTC help Desk Class II and a runner, Stop, Control Point, Corwith	
1333	MSP	199	ENG	67	ENG	67	MKE-CBS	CP	Radio failure Radio failed had to stop and wait for FRE to bring new one, 375	
1340	CHI	17	DSR	18	MBO	14	WIN-LSE	CP	For maritime traffic Bridge, Mississippi	

Amtrak Initial Terminal Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/2/2026

Terminal	Train	Date	Late	Delay	Cause
BON	685	07/02	1		
BON	687	07/02	5	5	Wheelchair 3 wheelchairs came out close to departure
BOS	177	07/02	12	12	Service, turn, or wye train, 172, late turn of AM172
BOS	449	07/02	12	12	Hold for thruway bus, Held until thru bus was full
BOS	449	07/02	12	12	Set out defective car 25085
BRK	680	07/02	1		
BRK	688	07/02	11	9	MU loading issue 90213
BRK	688	07/02	11	2	Restrictive signal(s) from known wayside signal failure Stop signal, Control Point, Brunswick West
GFD	479	07/02	41	41	486 late 486
HAR	654	07/02	(Trn Cxld)		Engine Issue
NFK	94	07/02	9	9	For maritime traffic Milepost, 1.5, 1.5
NFK	138	07/02	17	17	Passengers blocked by a train on the crossing. 811, Milepost, 0.0, 0.0
NYP	19	07/02	25	25	Pick up equipment, LATE F/SSYD WAITING FOR CARS OFF AM50
NYP	49	07/02	82	82	Traction motor, 701 DX DM, LATE RELEASE F/SSYD A/C MECHANICAL ISSUES. CAPPED ENGINE 9707 WITH 701 AND HOT CARS.
NYP	63	07/02	4	4	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	89	07/02	3	3	Water, commissary, toilet/trash dumping, LATE RELEASE FROM SSYD BY CATERING
NYP	97	07/02	65	65	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C SHORTAGE OF EQUIPMENT AND SERVICING
NYP	239	07/02	59	59	Disabled train ahead, Other, F-INT, HELD ON LOOPS A/C AM290 WITH MECHANICAL ISSUES WAS NECESSARY TO LOOP THROUGH SSYD FOR ENGINE E-716 TO LEAD AM290
NYP	241	07/02	49	49	Disabled train ahead, Other, F-INT, HELD ON THE LOOPS A/C AM290 WITH MECHANICAL ISSUES LOOPING BACK INTO SSYD
NYP	243	07/02	27	27	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	649	07/02	2	2	Passenger and/or baggage, BOARDING
NYP	2107	07/02	6	6	Other late crew, LATE ENGINEER
NYP	2127	07/02	2	2	Passenger and/or baggage, BOARDING
NYP	2131	07/02	15	15	Service, turn, or wye train, 2118, LATE TURN OFF AM2118
SPG	417	07/02	8	8	Service, turn, or wye train, 474, late turn of AM474
WAS	184	07/02	4	4	HEP, 82768 AX AS, SHORT MECHANICAL CREWS

Amtrak Initial Terminal Details

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/2/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	192	07/02	4	4	Other late crew, SYS - CREW HAD TO BE ORDERED OUT BECAUSE OF REFUSAL TO DP BECAUSE DOORS KEPT CLOSING.
WAS	198	07/02	5	5	High passenger count, HLD - PAX STILL BOARDING
WAS	2118	07/02	33	33	Service, turn, or wye train, 2155, LATE INBOUND
WAS	2120	07/02	30	30	Service, turn, or wye train, 2159, late inbound
WAS	2124	07/02	51	51	Service, turn, or wye train, 2119, ITI - LATE INBOUND 2119
CHI	5	07/02	4	4	Mobility Impaired Missing coach pax's that was split up with their family was found on the redcap cart up by the sleeping cars.
CHI	7	07/02	10	10	Wheelchair The lower level Portland coach was double booked with 2 big wheel chairs
CHI	41	07/02	208	208	Service, turn, or wye train 40, Delay per chi glasshouse
CHI	50	07/02	261	261	Service, turn, or wye train 5101
CHI	364	07/02	14	14	Engine 4616 had issues with bypass ID4616
CHI	1333	07/02	53	53	Service, turn, or wye train 332
MKE	338	07/02	5	5	Service, turn, or wye train 335
BFD	701	07/02	7	7	Hold for thruway bus
BFD	703	07/02	13	13	Hold for thruway bus
BFD	715	07/02	22	22	HEP C2104
BFD	719	07/02	31	31	Hold for thruway bus Held for four connecting buses
EMY	6	07/02	1		
GTA	782	07/02	2	2	Meet 14, Control Point, CO 358
LAX	584	07/02	2	2	PTC- IETMS incorrect consist
OKJ	540	07/02	5	5	Meet 543, Control Point, ni007
SAC	535	07/02	1	1	Passenger and/or baggage Passenger stepping off the train at the last minute caused us to leave a minute late.
SAN	595	07/02	9	9	Service, turn, or wye train 584

Eastern Region

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.3	98.1	94.8	342	9
CDOT	95.0	90.0	95.0	92.4	20	2
MARC	95.0	63.8	69.0	90.2	58	21
SEPTA	95.0	92.8	93.0	91.5	207	15
NJT-NED	95.0	77.7	83.1	88.6	310	69
NJT-SED	95.0	95.8	95.7	97.2	24	1

Operating Highlights

Train 52(02) South of Kingstree, SC - Passenger Train Interference

03JUL26: Train 52(02) with 426 customers onboard was delayed at milepost 350.0, south of Kingstree, SC on the CSX Charleston subdivision due to meeting passenger train 89(02). Once the passenger train cleared, train 52(02) was able to advance.

Train	Delay	Comment
52(02)	45"	

Train 2124(02) Washington, DC - Initial Terminal Delay

03JUL26: Train 2124(02) with 328 customers was delayed departing Washington, DC on the Amtrak WT Line due to late turn of equipment from train 2119(02).

Train	Delay	Comment
2124(02)	51"	

Train 20(02) Atlanta, GA - Crew Rest- System

03JUL26: Train 20(02) with 160 customers onboard was delayed departing Atlanta, GA on the NS Norcross District due to waiting for the crew to sign up on their rest. Once the crew was with the train, train 20(02) departed Atlanta.

Train	Delay	Comment
20(02)	52"	

Train 89(02) South of Kingstree, SC - Freight Train Interference

03JUL26: Train 89(02) with engine 83, 7 cars, and 115 customers onboard was delayed at milepost 338.3, 6 miles south of Kingstree, SC on the CSX Charleston subdivision due to freight congestion in the area caused by a work train creating a single track condition.

Train	Delay	Comment
89(02)	1'18"	

Train 66(02) South of Manassas, VA - Freight Train Interference

03JUL26: Train 66(02) with engine 318, 5 cars, and 227 customers onboard was delayed beginning at milepost 46.0, 12 miles south of Manassas, VA on the NS Washington District due to crossing over to go around a freight train.

Train	Delay	Comment
66(02)	30"	

Train 494(02) New Haven, CT - Hold for Connection

03JUL26: Train 494(02) with engine 105, 1 car, cab car 9633, and 62 customers was delayed departing New Haven, CT on the Metro North New Haven Line due to waiting for connections off of late train 94(02). Once the customers were boarded, train 494(02) departed at 9:34 PM-ET.

Train	Delay	Comment
494(02)	1'49"	

Train 479(02) Greenfield, MA - Initial Terminal Delay

03JUL26: Train 479(02) with cab car 9636, 1 car, engine 95, and 4 customers onboard was delayed departing Greenfield, MA on the Berkshire and Eastern Railroad Conn River Main Line subdivision due to late turn of equipment from train 486(02). Once the customers were boarded, train 479(02) departed Greenfield.

Train	Delay	Comment
479(02)	41"	

Train 448(01) Albany-Rensselaer, NY - Freight Train Interference

03JUL26: Train 448(01) with engines 88, 99, 4 cars, and 118 customers onboard was delayed at milepost 187.6, Albany-Rensselaer, NY on the Amtrak Hudson Line due to freight train cross traffic. Once the congestion cleared, train 448(01) advanced to the next station.

Train	Delay	Comment
448(01)	37"	

Train 49(02) New York, NY - Engine Failure

02JUL26: Train 49(02) with engine 9707, 712, 9 cars, and 197 customers onboard was delayed departing New York, NY on the Amtrak NYT line due to engine failure of 9707 for mechanical issues. The train was capped with engine 701. Once the engine was added and customers boarded, the train departed New York at 5:02 PM-ET.

Train	Delay	Comment
49(02)	1'22"	

Train 474(02) New Haven, CT - Hold for Connection

02JUL26: Train 474(02) with cab car 9647, 1 car, engine 90, and 77 customers onboard was delayed departing New Haven, CT on the Metro North New Haven Line due to waiting for connections off of late train 174(02). Once the passengers were boarded, train 474 departed the station at 5:05 PM-ET.

Train	Delay	Comment
-------	-------	---------

Train 645(02) Lancaster, PA - Catenary and Pantograph Damage

02JUL26: Train 645(02) with engine 631, 5 "UNCLASSIFIED" engine 7636 and 84 customers onboard was stopped at Lancaster, PA on the Amtrak PH Line due to catenary wire damage between Leaman and Rheems interlocking that damaged the pantograph. The train was terminated in Lancaster due to the damage. The customers were transferred to train 609(02). As a result of the train termination, trains 654(02) and 639(02) were cancelled in entirety. Rescue diesels towed the equipment to Philadelphia.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
645(02)	Terminated LNC	
654(02)	Cancelled	
639(02)	Cancelled	
609(02)	33"	
652(02)	15"	
656(02)	19"	
658(02)	03"	

Train 95(02) South of Woodbridge, VA - Commuter Train Interference

02JUL26: Train 95(02) with engine 350, 9 cars, and 396 customers onboard was delayed beginning at Woodbridge, VA on the CSX RF&P subdivision due to following VRE commuter train 303 between Woodbridge, VA and Fredericksburg, VA. Once the commuter train cleared, train 95(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
95(02)	35"	

Train 2120(02) Washington, DC - Initial Terminal Delay

02JUL26: Train 2120(02) with 340 customers onboard was delayed departing Washington, DC on the Amtrak WT Line due to a late turn of equipment from train 2159(02). Once the passengers were boarded, train 2120(02) departed Washington at 5:35 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2120(02)	30"	

Train 138(02) South of Petersburg, VA - M of W Work

02JUL26: Train 138(02) with engine 381, 9 cars, and 166 customers onboard was delayed at milepost 46.4, 37 miles south of Petersburg, VA on the NS Norfolk District due to holding for a defect to be repaired. Once the repair was made, train 138(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
138(02)	1'31"	

Train 239(02) New York, NY - Initial Terminal Delay

02JUL26: Train 239(02) with engine 708, 5 cars, engine 111, and 285 customers onboard was delayed departing New York, NY on the Amtrak NYT Line due to a change in equipment. Train 290(02) arrived with ACSES issues that required the train to be looped. As a result, train 239(02) used train 280(02) equipment that was being serviced in the yard. Train 239(02) departed New York at 6:46 PM-ET. Train 241(02) was delayed departing New York due to waiting for the train to be looped. Once the train was turned, train 241(02) departed New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
239(02)	59"	

Train 49(02) North of Croton-Harmon, NY - Engine Failure

02JUL26: Train 49(02) with engine 701, 9 cars and 200 customers was stopped at milepost 38.4, 5 miles north of Croton-Harmon, NY on the Metro North Hudson Line due to the train losing head end power. Metro North mechanical personnel responded to the train to assist with the problem. The problem was with the trainline. The train was short looped behind engine 701 and behind the baggage car. Once the problem was rectified, train 49(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49(02)	48"	

Train 20(01) Washington, DC - Engine Failure

02JUL26: Train 20(01) operating with locomotive 628, 8 cars and 189 customers was delayed at Washington during the programmed locomotive change due to locomotive failure of the planned motor. Replacement motor 628 was added the consist and train 20(01) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(01)	35"	

Train 129(02) West of Trenton, NJ - Power Switch Failure

02JUL26: Train 129(02) with engine 604, 9 cars, engine 653, and 555 customers onboard was delayed at milepost 64.8, 11 miles west of Trenton, NJ on the Amtrak NYP Line due to power switch failure. Once there was a clear route, train 129(02) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
129(02)	32"	

Train 94(02) Quantico, VA - Freight Train Interference

02JUL26: Train 94(02) operating with locomotive 182, 9 cars and 419 customers onboard was delayed at Quantico for freight train interference following CSX 1032 from Quantico to Alexandria. After Alexandria train 94(02) was able to proceed without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
94(02)	30"	

Train 19(01) North of Atlanta, GA - Freight Train Interference

02JUL26: Train 19(01) operating with locomotives 37-151, 8 cars and 206 customers was delayed 7 miles north of Atlanta at MP 626 on the NS Greenville-Inman district due to freight train interference. Train 19(01) was blocked from the station track by NS25R after the train set off a detector requiring the crew to walk the train to inspect. Additionally, NS had another freight tied down on the main line blocking all routes to the station. After the crew of NS25R completed the inspection of their equipment they were able to proceed allowing train 19(01) to advance into Atlanta Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(01)	1'42"	

Train 2118(02) Washington, DC - Initial Terminal Delay

02JUL26: Next Gen Acc 26-FOI-00580 00000008158 UNCLASSIFIED 7/7/2026 Train 2118(02) operating with TS 110 was delayed at the initial terminal of Washington due to the late arrival and turn of equipment from train 2155(02) which arrived Washington at 3:12pm-et 1'12" late. After the train was serviced the 245 customers were boarded and train 2118(02) departed Washington.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2118(02)	33"	

Train 138(02) East of Petersburg, VA - Bridge Strike

02JUL26: Train 138(02) was delayed 25 miles east of Petersburg at MP 46 on the NS Norfolk division due to a reported bridge strike at MP 47.5. Due to the location of the bridge an extended period of time was required for NS personnel to respond to the location. After arrival and inspection of the bridge NS authorized train operations to resume with no restrictions. Train 138(02) was able to proceed without restriction.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
138(02)	1'31"	

Train 97(02) New York, NY - Initial Terminal Delay - Servicing

02JUL26: Train 97(02) operating with locomotive 635, 12 cars and 200 customers was delayed at the initial terminal of New York due to needing 1 coach and a diner off 50(30) to fulfill the consist. After the train was made up, servicing was completed and moved into the station the customers were boarded and train 97(02) departed New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(02)	1'05"	

Train 97(02) New York, NY - Dining Car Failure

02JUL26: Train 97(02) departed New York with the dining car, 68012, having no power or refrigeration.

WBS#: B.TR.100150.6847

Train 178(02) South of Lynchburg, VA - Engine Failure

02JUL26: Train 178(02) operating with locomotive 107, 9 cars and 115 customers was delayed 3 miles south of Lynchburg at MP 16 on the NS Blue Ridge division due to loss of HEP and trainline issues. After inspecting the train the crew operated 3 miles into Lynchburg without HEP to make repairs at a station for customer safety. The crew was able to short loop the locomotive and restore the HEP. After HEP was stable the train was able to depart and proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
178(02)	35"	

Train 80(02) North of Greensboro, NC - Freight Train Interference

02JUL26: Train 80(02) operating with locomotive 330, 7 cars and 235 customers was delayed 9 miles north of Greensboro at MP 9 on the NS Goldsboro- Greensboro division for freight train interference meeting NS 351-02 at Superior. After train NS 351-02 cleared Superior train 80(02) was able to advance to the single track and proceed.

Train 19(01) North of Clemson, SC - Trespasser Incident

02JUL26: Train 19(01) operating with locomotives 37-451, 8 cars and 215 customers onboard was delayed 4 miles north of Clemson at MP 511 on the NS Greenville-Inman division due to a tractor trailer stuck on the tracks at MP 516. Local authorities responded and the truck was removed allowing railroad operations to resume.

Train	Delay	Comment
19(01)	41"	

Train 40(01) South of Hamlet, NC - Engine Failure

02JUL26: Train 40(01) operating with locomotives 305-316, 10 cars and 197 customers onboard was delayed 8 miles south of Hamlet at MP 266 on the CSX Hamlet subdivision due to locomotive E/305 experiencing mechanical issues with an I/O Station 45 Fault. The crew trouble shot the locomotive with CNOC Mechanical and were advised to advance to HAM and recycle the locomotive while making the crew change. Trail locomotive E/316 was able to supply HEP and tractive effort for the duration of the troubleshooting.

At Hamlet, the crew recycled the locomotive and were able to clear the stored I/O Station 45 fault allowing e/305 to restore tractive effort. After recycling the locomotive train 40(01) was able to proceed.

After departing Hamlet train 40(01) stopped again at MP 238 when the I/O Station fault returned. The crew working with CNOC Mechanical proceeded to set locomotive E/305 up as a control stand and have E/316 supply all tractive effort and HEP. After reconfiguring the locomotive train 40(01) was able to resume operation.

At Raleigh, an Amtrak Road Foreman assisted the crew with replacing the comm and m/u cables between the locomotives to attempt to regain the communication between both units.

WBS#: B.TR.100150.6845

Train	Delay	Comment
40(01)	29"	CAM-HAM
40(01)	44"	HAM-HAM
40(01)	38"	HAM-SOP
40(01)	14"	SOP-CYN
40(01)	1'05"	RMT-PTB
40(01)	41"	WAS

CSX Heat Orders - Weather

02JUL26: CSX has imposed heat orders between 7p/7/2026 for the following subdivisions: Grand Rapids, Monon, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, Niagara, Old Main Line, Peninsula, RF&P, Richmond Terminal, Rochester, Syracuse Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
25 (02)	17"	MOE-BIX
40 (02)	48"	XDY-LAK
52 (02)	08"	XDD-XPX
53 (02)	24"	XLO-XV7
64 (02)	47"	BUF-XHF
79 (02)	45"	XVG-WLN
80 (02)	32"	RMT-ALX
94 (02)	02"	ALX-XVG
90 (02)	50"	DIL-XDJ
95 (02)	11"	FBG-RVR
98 (02)	32"	XDD-SAV
125 (02)	05"	ALX-WDB
138 (02)	05"	PTB-RVR
171 (02)	03"	XVG-ALX
186 (02)	26"	WBG-QAN
281 (02)	1' 42"	AMS-BUF
283 (02)	22"	AMS-ROM
449 (02)	09"	SPG-PIT
683 (02)	20"	DHM-FRE
685 (02)	13"	XP0-FRE
684 (02)	03"	EXR-XP0
686 (02)	13"	FRE-XP0
687 (02)	05"	XP0-DHM
40 (01)	26"	XSE-PTB
41 (01)	42"	HFY-RVR
97 (01)	26"	JAX-SBG
448 (01)	16"	XRD-SPG

Amtrak Northeast Corridor Heat Orders - Weather

02JUL26: With high temps expected across much of the Northeast Corridor, Amtrak imposed heat orders on the PW Line, NYP Line, PH Line, NHB Line and MRS Lines resulting in delays to trains and causing initial terminal delays to equipment turns off delayed trains.

The high temperatures caused mechanical HVAC failure on multiple trains. The trains took delays trying to troubleshoot the issues.

Train	Delay	Comment
-------	-------	---------

97 (02)	37"	Mechanical			
174 (02)	58"	Mechanical			
85 (02)	29"	Mechanical			
93 (02)	33"	Mechanical			
138 (02)	27"	Mechanical	26-FOI-00580	80000008158	"UNCLASSIFIED" 7/7/2026
184 (02)	42"				
2119 (02)	32"				
2120 (02)	12"				
655 (02)	09"				
171 (02)	36"				
653 (02)	12"				
148 (02)	34"				
136 (02)	15"				
94 (02)	44"				
131 (02)	06"				
125 (02)	13"				
652 (02)	17"				
2118 (02)	34"				
97 (02)	09"				
93 (02)	30"				
85 (02)	30"				
235 (02)	07"				
19 (02)	20"				
2162 (02)	30"				
2160 (02)	21"				
2115 (02)	31"				
2116 (02)	34"				
475 (02)	09"				
129 (02)	10"				
2123 (02)	10"				
2155 (02)	34"				
2158 (02)	26"				
2159 (02)	47"				
55 (02)	04"				
86 (02)	07"				
486 (02)	41"				
651 (02)	06"				
42 (02)	10"				
283 (02)	02"				
291 (02)	02"				
172 (02)	19"				
134 (02)	34"				
649 (02)	07"				
175 (02)	06"				
2119 (02)	05"				
647 (02)	12"				
2171 (02)	06"				
281 (02)	02"				
2112 (02)	34"				
609 (02)	22"				
137 (02)	07"				
95 (02)	20"				
125 (02)	19"				
131 (02)	20"				
645 (02)	16"				
648 (02)	33"				
174 (02)	11"				
182 (02)	14"				
2108 (02)	12"				
2113 (02)	11"				
184 (02)	30"	Mechanical			
2162 (02)	52"	Mechanical			
94 (02)	11"	Mechanical			
148 (02)	13"	Mechanical			
2119 (02)	20"	Mechanical			
171 (02)	17"	Mechanical			
134 (02)	23"	Mechanical			

CN Heat Orders - Weather

02JUL26: CN imposed heat orders between Rouses Point, NY and St. Lambert, QC of 25 mph created delays for trains 68 and 69.

Train	Delay	Comment
-------	-------	---------

Piedmont Service Cancellations - Norfolk Southern Heat Orders - Weather

02JUL26: Due to the heat orders imposed by Norfolk Southern on the Danville District with significant delays expected to trains operating on the route, Piedmont Service trains have been cancelled with alternate busing being provided.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
72 (02)		Cancelled
73 (02)		Cancelled
74 (02)		Cancelled
75 (02)		Cancelled
76 (02)		Cancelled
77 (02)		Cancelled

Norfolk Southern System Wide Heat Orders - Weather

02JUL26: NS has imposed heat orders for near the entirety of their network due to expected ambient temperatures exceeding 100 degrees in locations with expected rail temps exceeding 140 degrees. Trains operating over these routes will operate at speeds of 25 mph with delays expected to be significant.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66 (02)	55"	RNK-LYH
66 (02)	42"	LYH-CVS
78 (02)	45"	CLT-KAN
151 (02)	18"	LYH-RNK
171 (02)	27"	MSS-CLP
171 (02)	13"	XA1-BCV
171 (02)	12"	BCV-MSS
178 (02)	52"	LYH-CVS
178 (02)	68"	CVS-CLP
178 (02)	69"	CLP-MSS
178 (02)	28"	MSS-BCV
178 (02)	17"	BCV-ALX
138 (02)	2'00"	NFK-PTB
20 (01)	51"	CLP-MSS
20 (01)	30"	MSS-XA1
43 (02)	1'00"	

Train 2155(02) Providence, RI - Brakes

02JUL26: Next Gen Acela 2155(02) operating with TS-10 and 281 customers onboard was delayed at Providence due to a service brake fault on TS-10. The crew, in contact with an Amtrak Road Foreman was instructed to reset the trainset successfully allowing the fault to clear. Train 2155(02) was then able to proceed without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2155 (02)	32"	

CSX Heat Orders

01JUL26: CSX has imposed heat order 26-FOI-00580 et al 00000008158 the following UNCLASSIFIED Grand Rapids, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, Niagara, Old Main Line, Peninsula, RF&P, Richmond Terminal, Rochester, Syracuse Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah, and Tampa Terminal.

Train	Delay	Comment
53 (01)	31"	
178 (01)	3"	
281 (01)	47"	
95 (01)	30"	
49 (01)	1' 27"	
40 (01)	55"	
52 (01)	13"	
63 (01)	31"	
64 (01)	57"	
79 (01)	34"	
80 (01)	25"	
89 (01)	48"	
90 (01)	42"	
94 (01)	12"	
98 (01)	41"	
125 (01)	19"	
138 (01)	18"	
186 (01)	8"	
283 (01)	10"	
449 (01)	26"	
683 (01)	13"	
684 (01)	6"	
685 (01)	14"	
686 (01)	17"	
687 (01)	6"	
688 (01)	3"	

NEC Service Adjustments for 07/03/26- Weather

03JUL26: Due to the impending hot weather with Ambient temperatures elevated over 90 degrees the following service adjustments were made: Northeast Regional trains 163, 88, 159, 142, 106, and 107(03) were cancelled in their entirety. Keystone trains 666 and 667(03) were also cancelled in their entirety.

Train	Delay	Comment
163 (03)	Cancelled	
159 (03)	Cancelled	
88 (03)	Cancelled	
142 (03)	Cancelled	
106 (03)	Cancelled	
107 (03)	Cancelled	
666 (03)	Cancelled	
667 (03)	Cancelled	

Piedmont Service Cancellations - Norfolk Southern Heat Orders - Weather

03JUL26: Heat orders dependent on the "UNCLASSIFIED" 7/7/2026 26-FQI-00580 00000008158 the Districts would cause significant delays to the service scheduled through the area. As a result, trains were cancelled with alternate transportation secured. Two buses were secured for train 72(03). One bus operated express stopping and picking up in Charlotte, Greensboro and Raleigh. One bus making all stops. Two buses were secured for train 74(03) and both made all stops. Two buses were secured for train 76(03). One bus made stops in Charlotte, Durham, Cary, and Raleigh. The second bus made stops in Charlotte, Kannapolis, Greensboro, Durham, Cary, and Raleigh. Two buses were secured for train 73(03). One bus made stops in Raleigh, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 75(03). One bus made stops in Raleigh, Cary, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 77(03). One bus made stops in Raleigh, Durham, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Greensboro, Highpoint, Salisbury, and Charlotte. Trains 71(03) and 78(03) were scheduled to make all stops.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(03)	Cancelled	
76(03)	Cancelled	
74(03)	Cancelled	
75(03)	Cancelled	
73(03)	Cancelled	
72(03)	Cancelled	

Train 685(02) Boston, MA - Car Failure

02JUL26: Train 685(02) operating with locomotive 87, 5 cars and 219 customers had car 82698 bad ordered for HVAC inline creating overcapacity conditions. 1 express bus was secured for travel Boston to Portland.

Due to lack of available replacement equipment trains 680(03), 681(03) 686(03) and 687(03) will all be reduced by 1 car for capacity.

WBS#: B.TR.100150.6844

NEC Service Adjustments for 7/02/26 - Weather

30JUN26: Due to the impending hot weather with Ambient temperatures elevated over 90 degrees the following service adjustments were made:

Trains 84(02), 196(02), 176(02), 119(02), 193(02) and 173(02) were cancelled in their entirety.

Legacy Acela trains 2152(02), 2154(02), 2190(02), 2165(02), 2193(02) and 2167(02) were cancelled in their entirety.

This left Washington, New York and Boston with regional protect sets. This also left Legacy protect sets in Washington, New York and Boston.

Diesel Protects were available in Harrisburg, Wilmington, Philadelphia and Baltimore.

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00580a 00000008158 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link broken bolt

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Train 6(01) East of McCook, NE - Weather

03JUL26: Train 6(01) was delayed operating between McCook, NE, beginning at milepost 254, and Hastings, NE, ending at milepost 181 on BNSF Hastings subdivision, due to 60mph high wind speed restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(01)	41"	

Train 354(02) South of Royal Oak, MI - Vehicle on Tracks

03JUL26: Train 354(02), operating with engine 4604, 5 coaches, and 39 customers, was delayed 2 miles south of Royal Oak, MI, on CN Holly subdivision, due to a vehicle on the tracks. Local police responded to the scene with a tow truck to remove the vehicle. Once the vehicle was removed and the tracks were inspected, train 354(02) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(02)	34"	

Train 19(01) East of Meridian, MS - Servicing

03JUL26: Train 19(01) , operating with engines 37/151, 8 coaches, and 161 customers, was delayed 14 miles east of Meridian, MS, on NS AGS South subdivision, due to performing their daily inspection, which had to be completed by midnight. The crew stopped at Smith siding to do the inspection on the 2 locomotives. Once complete train 19(01) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(01)	45"	

Train 21(02) South of Arcadia, MO - Signal

03JUL26: Train 21(02) was delayed operating between Arcadia, MO, and Poplar Bluff, MO, on UP Desoto subdivision due to signal issues that required the train to flag Tip Top siding, milepost 92. Once the train flagged through the affected area they were required to operate at restricted speed from Tip Top siding to Annapolis siding, milepost 107.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(02)	1'35"	

Train 306(02) South of Chicago, IL - Weather

03JUL26: Train 306(02), operating with engine 4611, 5 coaches, and 189 customers, was delayed south, Chicago, IL on CN Joliet subdivision due to a BNSF freight train blocking the route. At the time of the delay, the freight train crew was conducting a brake test when a lightning alert was issued, requiring the crew to suspend operations and take shelter. Once the lightning alert concluded, the BNSF freight crew finished their brake test and was able to get back on the move, clearing a route for train 306(02).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
306(02)	2'12"	

Train 719(02) East of Fresno, CA - Fueling Locomotive

02JUL26: Train 719(02) was delayed 51 minutes at Calwa Yard (M3994) 3 on the BNSF Stockton Subdivision, 3 miles east of Fresno, CA, fueling locomotive E/C2009. The train stopped on Main Track #1, adjacent to the BNSF Calwa Yard, where it was met by a fuel truck. The train departed Bakersfield with only 657 gallons of fuel. The fuel pump was very slow, which extended the anticipated delay. Due to this, the train was then further delayed, due to BNSF needing to operate BN6960 through first, due to hours of service.

Train	Delay	Comment
719(02)	51"	Fueling
719(02)	36"	BN6960

Train 1333(02) East of St. Paul-Minneapolis, MN - Freight Train Interference

03JUL26: Train 1333(02) was delayed 11 mile east of St. Paul-Minneapolis, MN, on CPKC River subdivision, due to holding for a UP freight train to clear the wye. Once the freight cleared and a route was made available, train 1333(02) was able to proceed.

Train	Delay	Comment
1333(02)	34"	

Train 355(02) West of New Buffalo, MI - Freight Train Interference

03JUL26: Train 355(02) was delayed 20 miles west of New Buffalo, MI, on Amtrak Michigan Line, due to cross traffic with unknown freight. Once the freight cleared and a route was made available, train 355(02) was able to proceed.

Train	Delay	Comment
355(02)	32"	
355(02)	32"	

Train 48/448(02) Chicago, IL - Car Failure

02JUL26: Train 48/448(02), operating with engines 374/122, 11 coaches, and 320 customers, experienced hvac failure B-end of sleeper car 25083. As a result the inventory of that car was reduced by half which caused the train to be over capacity. 1 bus was sourced to accommodate affected passengers. That bus operated express from Chicago, IL to Cleveland, OH.

WBS#: B.TR.100150.6848

Train 22(02) North of Marshall, TX - Freight Train Interference

03JUL26: Train 22(02) was delayed 15 miles north of Marshall, TX, on UP Little Rock subdivision, due to following UP7903 from jefferson siding, milepost 51, to Texarkana, AR.

Train	Delay	Comment
22(02)	35"	

Train 719(02) Bakersfield, CA - Hold for Connection

02JUL26: Train 719(02) departed Bakersfield, CA/ MP886.9 on the BNSF Bakersfield Subdivision, due to holding for passengers off four misconnecting busses. These busses were delayed arriving account of being held in traffic for a highway accident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(02)	31"	

Train 382(02) South of Galesburg, IL - Freight Train Interference

02JUL26: Train 382(02), operating with engine 4608, 4 coaches and 87 customers, was delayed south of Galesburg, IL, on BNSF Brookfield subdivision due to heavy freight traffic in the area. Once the freights cleared and a route was made available, train 382(02) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(02)	43"	

Train 364(02) west of New Buffalo, MI - Signal

02JUL26: Train 364(02), operating with engines 4616/4601, 6 coaches, and 279 customers, was delayed 21 miles west of New Buffalo, MI, on Amtrak Michigan Line, due to a TOL at Control Point 238. Maintainers responded to the scene and spiked and wedged the switches in a normal position and trains operating through the affected area were given permission passed the stop signals.

Train 354(02) was also delay operating through this area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(02)	51"	
354(02)	33"	

Train 41(02) Chicago, IL - Initial Terminal Delay

03JUL26: Train 41(02) was delayed 3 hours and 28 minutes departing Chicago, Illinois account late turn of equipment. Train 40(30) arrived in CUS at 1:47pm, 5 hours and 2 minutes late. Train 41(02) was set to the yard at 2:39pm, at approximately 5:00pm E/339 was bad ordered requiring a rip and back due to the engine oil sump needing to be cleaned. Diesel released E/339 at 7:12pm. Train 41 was made up complete at 8:41pm and Mechanical released the train at 9:02pm. Train 41 was set in CUS at 9:27pm. After boarding 274 passengers, Train 41(02) departed Chicago at 10:08pm; 3 hours and 28 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(02)	3'28"	

Train 4(01) Lamy, NM - Passenger Train Interference

02JUL26: Train 4(01) was delayed at Fox/MP820 on the BNSF Glorieta Subdivision, 15 miles east of Lamy, NM due to meeting Train 3(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(01)	45"	

Train 50(02) Chicago, IL - Initial Terminal Delay

03JUL26: Train 50(02) was delayed 4 hours and 21 minutes departing Chicago, Illinois account late turn of equipment. Train 51(01) arrived in CUS at 5:04pm, 6 hours and 39 minutes late. Train 50(02) was set to the yard at 6:25pm. Train 50(02) was made up complete at 7:10pm and released by mechanical at 9:21pm. Train 50(02) was set in CUS at 9:32pm. After boarding 122 passengers, Train 50(02) departed Chicago at 10:16pm; 4 hours and 21 minutes

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(02)	4'21"	

Train 5(30) West of Reno, NV - Freight Train Interference

02JUL26: Train 5(30) was delayed at West Reno RV239/MP239.1 on the UPRR Roseville Subdivision, 1.6 miles west of Reno, NV, due to meeting an unidentified freight unit.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(30)	33"	

Train 21(01) Fort Worth, TX - Car Failure

02JUL26: Train 21(01), E/53-E/58-6 Cars, was delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, due to mechanical working on HVAC issues in multiple cars. Mechanical was able to restore HVAC function on the B-end of C/37013 and fully restore HVAC function on C/31031. Once Mechanical completed their repairs and released the train, train 21(01) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(01)	1'19"	

Train 541(02) East of Martinez, CA - Drawbridge Opening

02JUL26: Train 541(02) was delayed at Benicia/MP 35, 4 miles east of Martinez, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass. Train 532(02) was also delayed holding at Vista/ MP 32.8 holding for the bridge opening.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
532(02)	22"	
541(02)	22"	

Train 5(30) West of Reno, NV - Freight Train Interference

02JUL26: Train 5(30) was delayed at West Reno/MP 239.1, 1 mile west of Reno, NV, on the UPRR Roseville Subdivision due to UP freight (ZG2LT) tripping a high wide detector ahead. Once freight cleared, Train 5(30) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(30)	33"	

Train 51(01) North of Dyer, IN - Freight Train Interference

03JUL26: Train 51(01), operating with engines 372/44, was delayed 2.5 miles north of Dyer, IN, on CSX Elsdon_DG subdivision, due to meeting UP8342 at milepost 19.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
51(01)	15"	

Train 1333(02) West of Milwaukee, WI - Engine Failure

02JUL26: Train 1333(02) was delayed at MP 85.4 on the CPRR Watertown Subdivision, 8.4 miles west of Milwaukee, WI (MP 85.4), due to an inoperative radio in lead engine 375. The Milwaukee Road Foreman responded to the train and provided a replacement radio to the crew. Once the radio was exchanged and operational, Train 1333(02) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(02)	1'07"	

Train 4(01) East of Lamy, NM - Passenger Train Interference

02JUL26: Train 4(01) was delayed at MP 820.2, 15 miles east of Lamy, NM, on the BNSF Glorieta Subdivision due to meet with Train 3(01). The crew held until Train 3(01) cleared route then proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(01)	45"	

Train 531(02) Martinez, CA - Drawbridge Opening

02JUL26: Train 531(02) was delayed at Benicia/MP 35, 4 miles east of Martinez, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge (MP 32.9) being raised for maritime traffic to pass. Train 526(02) was also delayed holding at Vista/ MP 32.8 holding for the bridge opening.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
531(02)	25"	
526(02)	25"	

Train 51(01) North of Crawfordsville, IN - Freight Train Interference

02JUL26: Train 51(01) was delayed 20 miles north of Crawfordsville, IN (MP147.5), on the CSX Monon Subdivision, at Switzer (MP127.5) meeting CSX M641-01.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
51(01)	1'09"	

Train 319(02) North of Summit, IL - Signal

02JUL26: Train 319(02) was delayed 5.2 miles north of Summit, IL (MP11.8), on the CNRR Joliet Subdivision, due to signal failure at Corwith (MP6.6). Once through the area, track speed resumed.

Train 302(02) was held 1.7 miles south of Summit, IL, on the CNRR Joliet Subdivision, at Argo (MP13.5) in order to meet Train 319(02), Additional delay incurred due to a second signal failure at Corwith.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(02)	20"	
302(02)	20"	Meet 319(02)
302(02)	26"	Corwith

Train 6(01) Grand Junction, CO - Medical Emergency

02JUL26: Train 6(01) was delayed at Grand Junction, CO (MP 449.5) on the UPRR Glenwood Springs Subdivision while awaiting the response of emergency medical services for a customer medical emergency. Upon arrival, paramedics evaluated the customer, removed them from the train, and transported them to St. Mary's Hospital for observation. The train resumed operations following the transfer of the customer to emergency responders.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(01)	34"	

Train 23(02) South of Bay Saint Louis, MS - Passenger Train Interference

02JUL26: Train 23(03) held 1.9 miles south of Bay Saint Louis, MS (MP754.5), on the CSX NO&M Subdivision, at SE Nicholson Ave (MP756.4) in order to meet Train 24(02).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
23(02)	35"	

Train 8/28(01) East of Sandpoint, ID - Freight Train Interference

02JUL26: Train 8/28(01) was delayed starting at Elmira/ MP 1366.3, 37 miles east of Sandpoint, ID, on the BNSF Kootenai River Subdivision due to freight interference. The crew followed BN7963 starting at Elmira until Yakt/ MP 1341.9 where they met BN6929. At Leonia/ MP 1350.8, the crew held for meet with BN5159. Train 8/28(01) was further delayed at Wolf Prairie/ MP 1286.2 due to holding for BN5926 and BN7232. Once freights were clear, Train 8/28(01) proceeded east.

Due to lateness, one downline bus was secured for customers making connection to 41(03) in Chicago. The bus operated Red Wing, Winona, Lacrosse, Tomah, and Chicago.

WBS#: B.TR.100150.6846

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(01)	23"	BN7963
8/28(01)	16"	BN6929
8/28(01)	13"	BN5159
8/28(01)	42"	BN5926/BN7232

Train 332(02) East of Glenview, IL - Signal

02JUL26: Train 332(02) was held at MP 3.4 on the Metra C&M Subdivision, 13.9 miles east of Glenview, IL (MP 17.3), due to a reported power outage at Tower A3 (MP 3.1). A signal maintainer responded and resolved the issue, allowing Train 332(02) to continue to Chicago.

Train 1333(02) departed Chicago, IL, 53 minutes late due to late inbound equipment, a required program move, and signal issues. The inbound equipment from Train 332(02) arrived at 10:19AM-CT, 45 minutes late. Upon arrival, a program move was required to remove engine 306 and add engine 375. The switching move was delayed due to an issue with the track light governing the switch needed for the movement. After the track light issue was resolved and the engine swap was completed, Train 1333(02) departed Chicago.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
332(02)	33"	
1333(02)	53"	

Train 364(02) East of Battle Creek, MI - Heat Restrictions

03JUL26: Train 364(02) was operating with engine 4626/4626 coaches, and 189 customers, was delayed operating between Battle Creek, MI, and Lapeer, MI, on CN Flint subdivision, due to heat restrictions.

Train	Delay	Comment
364(02)	32"	

Train 1(01)/421(30) West of Sanderson, TX - Freight Train Interference

02JUL26: Train 1(01)/421(30) was heavily delayed at Maxon (MP 547.0), 31 miles west of Sanderson, TX (MP 516.0), on the UPRR Sanderson Subdivision due to freight interference and a CTC system failure. Earlier that morning, freight train MEWWC-30 (UP 5741) was stopped at Tesnus (MP 553.3) after the train came apart. An overnight lightning strike also caused a CTC failure between Haymond (MP 559.9) and Tesnus. A signal maintainer responded and worked to establish generator power and restore signal operations.

Additional delay was incurred while waiting for the signal maintainer to transport the recrew for MEWWC-30 by hi-rail vehicle to the tied-down train in a remote area. Once the recrew was on board, MEWWC-30 attempted to depart but experienced DPU issues. The crew on Train 1(01)/421(30) expired under the Hours of Service law at 1:45 PM CT. Due to the remote location and limited road access, Train 1(01)/421(30) shoved back to Longfellow (MP 533.9) to wait for a recrew and pilots from Alpine. During that time, MEWWC-30 was able to proceed and clear into the Lenox siding. After the recrew boarded Train 1(01)/421(30), the train resumed its westward movement. Service recovery was enacted during this time which consisted of snack packs, coffee, tea, juice and water for all customers. Coach customers also received complimentary beef stew. Sleeper customers meal service was not affected.

WBS#: B.TR.100150.6843

Train	Delay	Comment
1(01)/421(30)	6'31"	

Train 49(01) West of Sandusky, OH - Freight Train Interference

02JUL26: Train 49(01) was delayed starting 25.6 miles west of Sandusky, OH (MP241.5), on the NSRR Chicago Line, at CP-267 (MP267.1) meeting NS 268. Once the meeting was complete, Train 49(01) had to follow NS 334 until they were able to get by at CP-286 (MP286.9).

Train	Delay	Comment
49(01)	34"	Follow NS 334
49(01)	12"	Meet NS 268

Train 22(02) Fort Worth, TX - Program Move / HVAC Failure

02JUL26: Train 22(02) was delayed at Fort Worth, TX (MP 346.2), on the BNSF Fort Worth Subdivision, for a preventative maintenance locomotive swap. The planned work involved removing engine 59 and adding engine 192. During servicing, engine 315 was found to have an HVAC failure, resulting in engine 192 being placed in the lead position. Once the locomotive swap and equipment adjustments were completed, Train 22(02) departed Fort Worth.

Train	Delay	Comment
22(02)	1'13"	

Train 380(02) East of Quincy, IL - Freight Train Interference

02JUL26: Train 380(02) held 17.7 miles east of Quincy, IL (MP258.6), on the BNSF Brookfield Subdivision, holding behind H-BIRGAL1-29 (UP5451) at Camp Point (MP240.9). This was a result of M-WQMGAL1-01 (BNSF 7321) stopped ahead on the single main line with a hot wheel. BNSF Mechanical was onsite assisting in a wheel change. Once complete, Train 380(02) had to follow UP5451 and BNSF 7321 until they were able to get around at Saluda (MP168.0).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
380(02)	2'32"	

Train 2/422(01) East of Palm Springs, CA - Engine Failure

02JUL26: Train 2/422(01), E/15-E/201-9 cars, was delayed at MP 625.2, 37 miles east of Palm Springs, CA, on the UPRR Yuma Subdivision due to loading issues on E/15. The crew contacted CNOC mechanical to troubleshoot. Once issue was resolved, Train 2/422(01) proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(01)	1'38"	

Train 6(30) East of Holdrege, NE - Debris

02JUL26: At 3:06AM-CT, 6(30) E/79-E/4-9 Cars stopped at MP197.2 on the BNSF Hastings Subdivision, approximately 13.7 miles east of Holdrege, NE (MP210.9), to inspect the train after striking debris on the track at MP204.0. The conductor reported that the debris was part of a building that had been blown onto the track. There were no injuries reported to the crew or the 213 customers onboard. During the inspection, damage was found consisting of bent panels on Baggage Car 61057 and Dorm Car 39021, as well as a main reservoir hose separation between Diner 38067 and Lounge 33044. After the hose was reconnected, 6(30) was back on the move east at 3:24AM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(30)	20"	Debris Strike

Train 718(01) East of Merced, CA - Third Party Contractor Engine Failure

02JUL26: Train 718(01) 26-FOI-00680,00000008158, E/C2104 with 96 passengers onboard, was delayed at Le Grande/MP1041.8 on the BNSF Stockton Subdivision, 14 miles east of Merced, CA. Crew reported a loss of tractive effort and head-end power(H.E.P.) and swiftly worked with TASI mechanical and an Amtrak Road Foreman to troubleshoot the issue. Train 718(01) was briefly able to restore HEP and tractive effort and departed, but shortly stopped again at MP1032.3 with a loss of H.E.P. with an unrecoverable fault. The weather was a reported 60 degrees and passengers onboard were comfortable. All efforts to source alternative busses were exhausted and the decision was made to Terminate Train 704(01) at Corcoran, CA with all passengers transferring to Train 716(01), in order to utilize this equipment to rescue Train 718(01). Train 716(01) had just departed and made a reverse move back to Corcoran in order to accept the transfer of 60 passengers from Train 704(01). Train 716(01) was further delayed west of Bakersfield holding for disposition due to hours of service concerns. After all passengers were transferred, 704's equipment advanced toward Train 718(01). Once coupled to Train 718(01), the train continued east to Bakersfield. Service recovery was initiated onboard all affected trains.

Due to this, Train 713(02) was cancelled in entirety and Train 715(02) operated as a double-set.

Train 718(01) was further delayed east of Fresno due to PTC and Speedometer issues on E/C2104. The crew operated with PTC cut out and at restricted speed through the duration of the trip. The crew expired on hours of holding in Fresno, CA for recrew. Once the recrew arrived and performed job briefing, Train 718(01) departed. Due to the late operation of the double set of equipment, further cancellations were necessary with Train 714(02) and Train 713(03) cancelled in their entirety with customers to next available service.

Train 715(02) was delayed departing Bakersfield, CA due to the late double set of equipment from Train 718/704(01) arriving into Bakersfield at 8:22A-PT. Once the equipment arrived into Bakersfield, it needed to be serviced then wyed. After servicing was complete, and the equipment was wyed, the customers boarded and Train 715(02) was able to depart. Train 715(02) was terminated in Emeryville, CA due to the double set of equipment. Customers traveling between Emeryville and Oakland were reaccommodated on the next available service. The equipment was deadheaded to the Oakland Maintenance facility for servicing.

WBS#: B.TR.100150.6840

Train	Delay	Comment
718(01)	5'27"	Troubleshooting/Coupling 704(01) equipment
704(01)	Term COC	
714(02)	Cancelled	
713(02)	Cancelled	
713(03)	Cancelled	
718(01)	1'24"	Hold FNO for recrew
716(01)	1'30"	Transfer 704(01) pax
716(01)	37"	W/ BFD hold for dispo
715(02)	22"	Turn of double set BFD
715(02)	Term EMY	
718(01)	46"	PTC Issues MDR-BFD

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated	JAN
59(27JUN-04JUL)	Cancelled	
58(27JUN-04JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on MP 588.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL)	00"	BYPASS PSN
1 (01, 04JUL) / 421 (03JUL)	00"	BYPASS PSN

Maintenance of Way Highlights

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
59 (26)	JAN	62		Wheels Gouged

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
517	TAC	1	Pax taken to South Tacoma Station	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00580

00000008158

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
683 (02)	BON	Shopped due to HVAC issues. overcapacity, emailed customer service.			82672
689 (02)	BON	shopped car due to HVAC issues, no impact	0	0	82672
449 (02)	BOS	Operating short coach a/c 25085 shopped in BOS for bad motor and no replacement. Inventory adjusted to reflect consist change. CNOC Csv has been advised over capacity entire route.	Notified Wendy Wilson	51	25085
688 (02)	BRK	shopped car due to HVAC issues. no impact	0	0	82672
642 (02)	HAR	Operating with additional coach and cafe car in lieu of cab car for pax travel and wifi.	No impact	0	82800 43379
562 (02)	LAX	Operating with 9700 in consist unable to accommodate passengers will bike reservations. Inventory has been adjusted. No passenger impacted by this change.	No impact	0	9700
580 (02)	LAX	Operating with 9700 in consist unable to accommodate passengers will bike reservations. Inventory has been adjusted. Cnoc Csv will need to reaccommodate any pax impacted by this.	Passengers notified	6	9700
4 (03)	LAX	Please block H-room on the 0432(03) car. 39011 does not have an H-room.	0	0	39011
573 (02)	SAN	Operating with 9700 in consist unable to accommodate passengers will bike reservations. Inventory has been adjusted. Cnoc Csv will need to reaccommodate any pax impacted by this.	Passengers notified	3	9700
591 (02)	SAN	Operating with 9700 in consist unable to accommodate passengers will bike reservations. Inventory has been adjusted. Cnoc Csv will need to reaccommodate any pax impacted by this.	Passengers notified	2	9700
64 (02)	TWO	Operating one car short a/c 82763 HVAC issues B-End no freon DH inline. Inventory has been adjusted	Passengers notified	64	82763

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00580 00000008158 "UNCLASSIFIED"	7/1/2019		
		to reflect change. CNOC Csv advised over capacity ROC- NYP.			

Reverse Consists

Train Number	Station	Reason
111 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
184 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
185 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
179 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
182 (02)	WAS	Consist reversed Business class seat orientation may have changed At Rear
174 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front