

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, July 04, 2026

Rules: 0-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/03/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	279	48	82.8%	902	140	84.5%	82,260	11,265	86.3%
Central Division	86.0%	73	7	90.4%	218	21	90.4%	20,257	1,839	90.9%
East Division	82.0%	130	23	82.3%	459	84	81.7%	43,020	6,693	84.4%
West Division	86.0%	76	18	76.3%	225	35	84.4%	18,983	2,733	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00580 00000008154 "UNCLASSIFIED" 7/7/2026

Endpoint Arrival Dates through 7/3/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	97,675	46,687	52%	305,029	141,544	54%	26,575,171	6,383,257	76%
Northeast Corridor	81%	34,470	17,504	49%	122,771	62,923	49%	11,970,557	2,846,974	76%
Acela	83%	8,492	4,949	42%	27,923	15,792	43%	2,364,945	618,164	74%
Northeast Regional	79%	25,978	12,555	52%	94,848	47,131	50%	9,605,612	2,228,810	77%
Richmond / Newport News / Norfolk	77%	6,599	3,265	51%	27,392	16,804	39%	2,979,246	831,107	72%
Springfield Shuttles	89%	737	431	42%	2,252	1,080	52%	171,289	25,527	85%
Roanoke	79%	2,762	1,836	34%	9,964	5,828	42%	903,819	181,201	80%
On Spine Northeast Regional	80%	15,880	7,023	56%	55,240	23,419	58%	5,551,258	1,190,975	79%
State Supported	80%	47,763	18,124	62%	142,712	50,776	64%	11,247,925	2,179,899	81%
Borealis	80%	648	203	69%	1,802	1,051	42%	152,564	31,417	79%
Capitol Corridor	90%	3,586	310	91%	12,679	1,935	85%	1,016,094	131,462	87%
Carolinian	70%	2,170	1,684	22%	4,306	3,510	18%	314,381	119,450	62%
Cascades	75%	3,597	1,557	57%	10,607	4,071	62%	698,459	192,692	72%
Downeaster	82%	1,621	876	46%	5,086	2,428	52%	401,424	47,736	88%
Empire	78%	6,135	2,109	66%	18,284	9,186	50%	1,472,533	323,835	78%
Adirondack	72%	473	341	28%	1,411	1,005	29%	87,873	26,498	70%
Ethan Allen Express	70%	508	185	64%	1,644	1,298	21%	152,649	48,930	68%
Maple Leaf	70%	932	140	85%	2,600	1,206	54%	177,933	68,226	62%
New York - Albany	85%	2,353	510	78%	8,130	3,044	63%	685,194	106,915	84%
New York - Niagara Falls	75%	1,457	698	52%	4,087	2,398	41%	365,306	72,171	80%
Berkshire Flyer	60%	412	235	43%	412	235	43%	3,578	1,095	69%
Heartland Flyer	70%	345	323	6%	885	533	40%	56,487	21,035	63%
Hiawatha	90%	2,274	391	83%	6,285	844	87%	464,092	51,395	89%
Illinois	78%	3,107	2,299	26%	8,992	4,824	46%	671,182	180,893	73%
Carl Sandburg / Illinois Zephyr	85%	524	362	31%	1,725	915	47%	111,288	28,717	74%
Illini / Saluki	85%	1,078	730	32%	3,064	1,533	50%	236,757	55,582	77%
Lincoln Service	70%	1,505	1,207	20%	4,203	2,376	43%	323,137	96,594	70%
Keystone	92%	4,971	1,714	66%	22,062	7,315	67%	2,081,337	217,316	90%
Lincoln / Missouri	70%	1,049	522	50%	3,112	1,488	52%	211,785	105,383	50%
Mardi Gras Service	80%	516	229	56%	1,399	317	77%	111,553	22,461	80%
Michigan	70%	2,014	1,490	26%	6,981	3,809	45%	527,019	168,871	68%
Blue Water	70%	611	598	2%	1,738	1,720	1%	122,066	47,102	61%
Pere Marquette	85%	183	180	2%	550	180	67%	68,116	13,517	80%
Wolverine	70%	1,220	712	42%	4,693	1,909	59%	336,837	108,252	68%
Missouri	80%	246	67	73%	811	79	90%	60,043	13,336	78%
Pacific Surfliner	85%	12,553	2,510	80%	31,800	4,900	85%	2,103,894	330,512	84%
Pennsylvanian	80%	990	703	29%	2,881	1,640	43%	241,651	43,826	82%
Piedmont	80%	557	378	32%	894	504	44%	314,081	78,999	75%
Vermont	75%	1,384	759	45%	3,846	2,342	39%	349,346	99,280	72%
Long Distance	70%	15,442	11,059	28%	39,546	27,845	30%	3,317,422	1,353,921	59%
Auto Train	70%	846	412	51%	2,699	412	85%	211,613	71,294	66%
California Zephyr	70%	1,083	503	54%	3,125	1,700	46%	262,533	86,577	67%
Cardinal	70%	0	0	-	547	523	4%	64,210	30,721	52%
City Of New Orleans	75%	0	0	-	0	0	-	177,085	49,375	72%
Coast Starlight	70%	1,329	21	98%	3,766	944	75%	308,159	105,418	66%
Crescent	70%	1,671	1,600	4%	3,091	2,525	18%	252,741	74,027	71%
Empire Builder	70%	1,350	731	46%	3,996	2,609	35%	258,288	122,451	53%
Floridian	60%	1,841	1,839	0%	5,091	5,044	1%	435,121	288,501	34%
Lake Shore Ltd	73%	1,329	972	27%	3,700	2,604	30%	256,498	74,611	71%
Palmetto	70%	1,607	1,377	14%	3,275	2,895	12%	250,922	68,944	73%
Silver Meteor	70%	1,251	1,222	2%	3,256	2,981	8%	275,640	113,100	59%
Southwest Chief	60%	1,085	751	31%	3,105	2,750	11%	221,566	141,023	36%
Sunset Ltd	70%	858	545	36%	1,213	767	37%	79,485	27,413	66%
Texas Eagle	70%	1,192	1,086	9%	2,682	2,091	22%	263,561	100,466	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000154 "UNCLASSIFIED" 7/7/2020

Train Index Dates Through July 03, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	22,104	313,298	706	1,589,404	28,950,946	549

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,771	88,803	199	75,152	8,309,803	90
INFRASTRUCTURE PLANNED	135	1,171	88,803	132	80,129	8,309,803	96
FLEET RELIABILITY	90	3,490	313,298	111	256,487	28,950,946	89
TRAIN OPERATIONS	424	15,672	313,298	500	1,177,636	28,950,946	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/03/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	279	48	82.8%	902	140	84.5%	82,260	11,265	86.3%
Central Division	86.0%	73	7	90.4%	218	21	90.4%	20,257	1,839	90.9%
East Division	82.0%	130	23	82.3%	459	84	81.7%	43,020	6,693	84.4%
West Division	86.0%	76	18	76.3%	225	35	84.4%	18,983	2,733	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/03/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	279	48	82.8%	902	140	84.5%	82,260	11,265	86.3%
Central Division	86.0%	73	7	90.4%	218	21	90.4%	20,257	1,839	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	0	100.0%	6	0	100.0%	523	18	96.6%
CHI	86.0%	27	2	92.6%	80	13	83.8%	7,319	877	88.0%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	6	0	100.0%	542	52	90.4%
FTW	92.5%	1	1	0.0%	3	1	66.7%	299	35	88.3%
GBB	-	-	-	-	-	-	-	1	1	0.0%
GRR	95.5%	1	0	100.0%	2	0	100.0%	261	8	96.9%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	1	50.0%	6	1	83.3%	544	41	92.5%
LAX	89.5%	1	0	100.0%	3	0	100.0%	265	40	84.9%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	18	3	83.3%	1,616	100	93.8%
MOE	97.5%	2	0	100.0%	6	1	83.3%	551	9	98.4%
MSP	96.5%	1	0	100.0%	3	0	100.0%	269	5	98.1%
NOL	94.5%	3	1	66.7%	10	1	90.0%	1,160	54	95.3%
OKC	97.0%	1	0	100.0%	3	0	100.0%	270	6	97.8%
PDX	86.0%	4	1	75.0%	12	1	91.7%	1,094	108	90.1%
PNT	88.0%	3	0	100.0%	9	0	100.0%	712	58	91.9%
PTH	93.0%	1	0	100.0%	3	0	100.0%	264	10	96.2%
QCY	91.0%	2	0	100.0%	6	0	100.0%	536	39	92.7%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	3	0	100.0%	272	27	90.1%
SEA	85.0%	7	0	100.0%	21	0	100.0%	1,911	207	89.2%
STL	89.0%	4	0	100.0%	12	0	100.0%	1,069	90	91.6%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	6	0	100.0%	536	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	130	23	82.3%	459	84	81.7%	43,020	6,693	84.4%
ALB	88.5%	7	0	100.0%	23	0	100.0%	2,037	161	92.1%
BON	87.5%	5	1	80.0%	15	5	66.7%	1,327	145	89.1%
BOS	85.5%	16	0	100.0%	48	4	91.7%	4,688	566	87.9%
BRK	92.5%	5	1	80.0%	15	6	60.0%	1,316	90	93.2%
BTN	82.0%	1	0	100.0%	3	0	100.0%	262	39	85.1%
CLT	91.5%	2	1	50.0%	7	1	85.7%	1,348	133	90.1%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	6	2	66.7%	537	52	90.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/03/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	279	48	82.8%	902	140	84.5%	82,260	11,265	86.3%
East Division	82.0%	130	23	82.3%	459	84	81.7%	43,020	6,693	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	6	0	100.0%	32	2	93.8%	3,055	508	83.4%
HFD	-	-	-	-	4	0	100.0%	151	8	94.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	3	0	100.0%	272	34	87.5%
MIA	89.5%	2	1	50.0%	6	1	83.3%	545	61	88.8%
MTR	79.0%	1	0	100.0%	3	0	100.0%	259	46	82.2%
NFK	84.5%	2	1	50.0%	6	4	33.3%	627	113	82.0%
NFL	93.5%	2	0	100.0%	6	0	100.0%	556	22	96.0%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	4	0	100.0%	14	1	92.9%	1,420	224	84.2%
NPN	93.0%	2	0	100.0%	6	0	100.0%	519	35	93.3%
NYP	75.5%	34	9	73.5%	131	34	74.0%	11,185	2,496	77.7%
PGH	93.0%	1	1	0.0%	3	1	66.7%	274	20	92.7%
PHL	48.0%	4	2	50.0%	14	5	64.3%	1,414	682	51.8%
PIT	76.0%	1	1	0.0%	1	1	0.0%	7	6	14.3%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	1	0	100.0%	3	0	100.0%	1,060	41	96.1%
RNK	83.5%	2	0	100.0%	6	0	100.0%	540	77	85.7%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAB	98.0%	1	0	100.0%	3	0	100.0%	262	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	3	0	100.0%	271	10	96.3%
SFA	88.0%	1	0	100.0%	3	0	100.0%	272	37	86.4%
SPG	92.5%	6	0	100.0%	16	1	93.8%	1,668	93	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	3	0	100.0%	262	56	78.6%
WAS	84.0%	19	5	73.7%	76	16	78.9%	6,672	857	87.2%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	76	18	76.3%	225	35	84.4%	18,983	2,733	85.6%
ARN	92.0%	1	0	100.0%	3	0	100.0%	274	19	93.1%
BFD	79.0%	6	4	33.3%	19	9	52.6%	1,705	350	79.5%
EMY	72.0%	1	1	0.0%	3	2	33.3%	279	86	69.2%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	9	2	77.8%	825	116	85.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/03/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	279	48	82.8%	902	140	84.5%	82,260	11,265	86.3%
West Division	86.0%	76	18	76.3%	225	35	84.4%	18,983	2,733	85.6%
LAX	89.5%	10	3	70.0%	29	4	86.2%	2,443	240	90.2%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	3	76.9%	36	9	75.0%	2,935	745	74.6%
PDX	86.0%	1	0	100.0%	3	0	100.0%	258	59	77.1%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	3	81.3%	48	4	91.7%	3,852	414	89.3%
SAN	90.5%	13	1	92.3%	39	2	94.9%	3,283	296	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	1	0.0%	3	2	33.3%	255	105	58.8%
SJC	89.0%	7	0	100.0%	21	0	100.0%	1,928	182	90.6%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	9	1	88.9%	588	61	89.6%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	3	0	100.0%	269	20	92.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	305	1	0	100.0%	116	8	93.1%	2	1	50.0%	117	24	79.5%
2		2	1	50.0%	117	26	77.8%	1	0	100.0%	113	20	82.3%
3		3	0	100.0%	274	54	80.3%	3	1	66.7%	272	118	56.6%
4	36	3	0	100.0%	273	42	84.6%	3	3	0.0%	273	182	33.3%
5		3	1	66.7%	272	44	83.8%	2	1	50.0%	268	64	76.1%
6	58	3	2	33.3%	271	79	70.8%	3	2	33.3%	271	84	69.0%
7		3	1	66.7%	263	36	86.3%	3	1	66.7%	256	62	75.8%
8	210	3	2	33.3%	263	113	57.0%	3	3	0.0%	262	152	42.0%
11		3	0	100.0%	274	50	81.8%	3	0	100.0%	268	54	79.9%
14		3	0	100.0%	275	41	85.1%	3	0	100.0%	273	83	69.6%
19	117	3	2	33.3%	273	67	75.5%	3	3	0.0%	271	62	77.1%
20	202	3	1	66.7%	273	19	93.0%	3	3	0.0%	273	50	81.7%
21	182	3	0	100.0%	270	22	91.9%	3	3	0.0%	269	65	75.8%
22	85	3	0	100.0%	271	25	90.8%	3	3	0.0%	269	65	75.8%
23		3	1	66.7%	276	6	97.8%	3	1	66.7%	274	70	74.5%
24	102	3	0	100.0%	276	14	94.9%	3	1	66.7%	275	44	84.0%
25	23	3	0	100.0%	275	3	98.9%	3	1	66.7%	273	70	74.4%
26		3	0	100.0%	275	5	98.2%	3	0	100.0%	273	52	81.0%
27		3	2	33.3%	261	17	93.5%	3	1	66.7%	257	82	68.1%
28		3	0	100.0%	257	59	77.0%	3	0	100.0%	257	51	80.2%
40	775	3	1	66.7%	269	39	85.5%	3	3	0.0%	268	135	49.6%
41	204	3	2	33.3%	269	104	61.3%	3	3	0.0%	267	199	25.5%
42	98	3	1	66.7%	275	21	92.4%	3	2	33.3%	273	44	83.9%
43	88	3	0	100.0%	274	41	85.0%	3	3	0.0%	274	59	78.5%
48		3	1	66.7%	273	54	80.2%	3	2	33.3%	273	40	85.3%
49	120	3	3	0.0%	273	70	74.4%	3	2	33.3%	273	54	80.2%
50	No OS	1	1	0.0%	112	27	75.9%	2	2	0.0%	112	65	42.0%
52		3	0	100.0%	272	37	86.4%	3	0	100.0%	271	61	77.5%
53	78	3	0	100.0%	272	34	87.5%	3	1	66.7%	271	86	68.3%
54	42	1	0	100.0%	101	6	94.1%	1	1	0.0%	101	14	86.1%
57		1	0	100.0%	100	4	96.0%	1	0	100.0%	100	6	94.0%
63	47	3	2	33.3%	276	119	56.9%	3	3	0.0%	272	143	47.4%
64		3	0	100.0%	274	63	77.0%	3	2	33.3%	274	93	66.1%
65		2	0	100.0%	85	12	85.9%	1	0	100.0%	84	11	86.9%
66		3	0	100.0%	273	54	80.2%	3	0	100.0%	271	49	81.9%
68	39	3	0	100.0%	276	55	80.1%	3	3	0.0%	276	106	61.6%
69		3	0	100.0%	263	59	77.6%	3	1	66.7%	259	33	87.3%
71	14	3	0	100.0%	271	3	98.9%	3	3	0.0%	270	69	74.4%
78	63	3	0	100.0%	271	20	92.6%	3	2	33.3%	270	52	80.7%
79	64	3	0	100.0%	273	55	79.9%	3	3	0.0%	272	87	68.0%
80	38	3	1	66.7%	273	29	89.4%	3	3	0.0%	271	52	80.8%
82	21	1	0	100.0%	68	7	89.7%	1	1	0.0%	68	21	69.1%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
87	47	1	0	100.0%	104	24	76.9%	1	1	0.0%	104	34	67.3%
89		3	1	66.7%	271	59	78.2%	4	3	25.0%	270	73	73.0%
89	131	3	1	66.7%	271	59	78.2%	4	3	25.0%	270	73	73.0%
90	34	3	0	100.0%	271	10	96.3%	3	3	0.0%	270	40	85.2%
97	141	3	3	0.0%	273	176	35.5%	3	3	0.0%	271	79	70.8%
98	45	3	0	100.0%	273	21	92.3%	3	3	0.0%	271	83	69.4%
99	Cncld	1	0	100.0%	103	12	88.3%	0	0	0.0%	101	57	43.6%
101		1	0	100.0%	67	6	91.0%	1	0	100.0%	67	11	83.6%
103		1	0	100.0%	102	21	79.4%	1	0	100.0%	102	8	92.2%
109		1	0	100.0%	50	8	84.0%	1	0	100.0%	50	5	90.0%
118		1	1	0.0%	102	7	93.1%	1	0	100.0%	102	5	95.1%
124	No OS	1	0	100.0%	101	7	93.1%	1	1	0.0%	100	24	76.0%
126	95	1	1	0.0%	46	8	82.6%	1	1	0.0%	46	9	80.4%
127		1	0	100.0%	46	12	73.9%	1	0	100.0%	46	5	89.1%
135	56	1	0	100.0%	103	17	83.5%	1	1	0.0%	103	52	49.5%
136	31	2	0	100.0%	172	20	88.4%	3	1	66.7%	171	18	89.5%
140	63	1	0	100.0%	102	12	88.2%	1	1	0.0%	101	21	79.2%
143	16	1	0	100.0%	101	9	91.1%	1	1	0.0%	101	23	77.2%
144		1	1	0.0%	68	46	32.4%	1	0	100.0%	67	9	86.6%
146	60	1	1	0.0%	101	17	83.2%	1	1	0.0%	101	35	65.3%
147	150	1	0	100.0%	69	7	89.9%	1	1	0.0%	69	21	69.6%
150	20	1	0	100.0%	100	54	46.0%	1	1	0.0%	98	49	50.0%
151	20	3	0	100.0%	272	86	68.4%	3	3	0.0%	271	87	67.9%
152	17	1	0	100.0%	68	5	92.6%	1	1	0.0%	68	26	61.8%
153		1	1	0.0%	102	9	91.2%	1	0	100.0%	102	14	86.3%
155	158	1	0	100.0%	104	15	85.6%	1	1	0.0%	104	34	67.3%
156	177	1	0	100.0%	104	10	90.4%	1	1	0.0%	104	32	69.2%
158	203	1	1	0.0%	103	16	84.5%	1	1	0.0%	103	21	79.6%
160		1	0	100.0%	101	5	95.0%	1	0	100.0%	99	23	76.8%
161	65	1	0	100.0%	102	9	91.2%	1	1	0.0%	101	64	36.6%
162	28	1	0	100.0%	102	5	95.1%	1	1	0.0%	102	50	51.0%
164	32	1	0	100.0%	104	8	92.3%	1	1	0.0%	104	45	56.7%
165	70	1	0	100.0%	103	27	73.8%	1	1	0.0%	103	41	60.2%
167	41	1	0	100.0%	69	15	78.3%	1	1	0.0%	68	21	69.1%
168	108	1	0	100.0%	67	10	85.1%	1	1	0.0%	67	23	65.7%
178	207	2	0	100.0%	172	24	86.0%	3	2	33.3%	171	25	85.4%
179	43	2	1	50.0%	172	20	88.4%	3	2	33.3%	172	60	65.1%
194	169	1	1	0.0%	68	16	76.5%	1	1	0.0%	67	19	71.6%
195	25	1	0	100.0%	102	4	96.1%	1	1	0.0%	102	53	48.0%
198		2	1	50.0%	104	15	85.6%	3	0	100.0%	104	16	84.6%
230		3	0	100.0%	110	4	96.4%	3	0	100.0%	110	6	94.5%
232		3	0	100.0%	276	11	96.0%	3	0	100.0%	276	17	93.8%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
234	16	3	0	100.0%	276	19	93.1%	3	0	100.0%	276	24	91.3%
235		3	0	100.0%	200	27	86.5%	3	3	0.0%	200	44	78.0%
236		3	0	100.0%	260	7	97.3%	3	0	100.0%	260	36	86.2%
237		3	0	100.0%	274	52	81.0%	3	1	66.7%	272	44	83.8%
238		3	0	100.0%	200	19	90.5%	3	0	100.0%	199	14	93.0%
239		3	1	66.7%	275	73	73.5%	3	1	66.7%	274	31	88.7%
240		3	0	100.0%	275	20	92.7%	3	1	66.7%	273	45	83.5%
241		3	1	66.7%	276	69	75.0%	3	1	66.7%	276	67	75.7%
243	28	3	3	0.0%	212	58	72.6%	3	3	0.0%	211	29	86.3%
245		3	1	66.7%	157	28	82.2%	3	1	66.7%	156	18	88.5%
280		3	0	100.0%	276	11	96.0%	3	0	100.0%	276	50	81.9%
281	37	3	0	100.0%	276	29	89.5%	3	3	0.0%	276	50	81.9%
283	46	3	2	33.3%	276	66	76.1%	3	3	0.0%	276	55	80.1%
284		3	0	100.0%	276	10	96.4%	3	2	33.3%	274	44	83.9%
290		3	0	100.0%	276	48	82.6%	3	2	33.3%	274	93	66.1%
291	40	3	1	66.7%	275	76	72.4%	3	3	0.0%	273	61	77.7%
300	162	3	0	100.0%	260	19	92.7%	3	1	66.7%	258	57	77.9%
301	57	3	0	100.0%	274	9	96.7%	3	1	66.7%	271	51	81.2%
302	52	3	0	100.0%	261	31	88.1%	3	2	33.3%	257	74	71.2%
305	41	3	0	100.0%	264	28	89.4%	3	3	0.0%	260	105	59.6%
306	No OS	3	0	100.0%	272	15	94.5%	3	3	0.0%	271	74	72.7%
307		3	0	100.0%	264	35	86.7%	3	1	66.7%	261	71	72.8%
311		3	0	100.0%	274	23	91.6%	3	0	100.0%	269	50	81.4%
316	34	3	0	100.0%	271	16	94.1%	3	1	66.7%	268	65	75.7%
318		3	1	66.7%	275	27	90.2%	3	1	66.7%	272	125	54.0%
319	67	3	0	100.0%	276	17	93.8%	3	2	33.3%	274	147	46.4%
329		3	0	100.0%	195	8	95.9%	3	0	100.0%	195	13	93.3%
330		3	0	100.0%	234	4	98.3%	3	0	100.0%	234	13	94.4%
331		3	0	100.0%	276	29	89.5%	3	0	100.0%	276	40	85.5%
332		3	0	100.0%	276	14	94.9%	3	1	66.7%	276	40	85.5%
334		3	0	100.0%	276	9	96.7%	3	0	100.0%	275	36	86.9%
335		3	0	100.0%	276	30	89.1%	3	2	33.3%	274	45	83.6%
336		3	1	66.7%	276	9	96.7%	3	0	100.0%	274	25	90.9%
337	12	3	0	100.0%	276	17	93.8%	3	1	66.7%	272	34	87.5%
338		3	2	33.3%	276	43	84.4%	3	1	66.7%	274	82	70.1%
339	19	3	1	66.7%	276	47	83.0%	3	1	66.7%	276	49	82.2%
341	67	3	1	66.7%	265	36	86.4%	3	1	66.7%	260	36	86.2%
342		3	0	100.0%	276	21	92.4%	3	0	100.0%	274	53	80.7%
350	27	3	0	100.0%	257	17	93.4%	3	2	33.3%	252	138	45.2%
351	60	3	0	100.0%	259	25	90.3%	3	1	66.7%	257	69	73.2%
352	235	3	0	100.0%	243	20	91.8%	3	2	33.3%	237	73	69.2%
353		3	0	100.0%	218	12	94.5%	3	0	100.0%	212	35	83.5%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
354	97	3	1	66.7%	257	29	88.7%	3	2	33.3%	253	91	64.0%
355	143	3	0	100.0%	270	27	90.0%	3	3	0.0%	263	88	66.5%
364	74	3	1	66.7%	265	61	77.0%	3	3	0.0%	259	93	64.1%
365	17	3	0	100.0%	264	10	96.2%	3	3	0.0%	262	95	63.7%
370	102	3	1	66.7%	267	34	87.3%	2	1	50.0%	259	66	74.5%
371	113	2	0	100.0%	261	8	96.9%	2	1	50.0%	260	28	89.2%
380	28	3	0	100.0%	262	24	90.8%	3	3	0.0%	262	52	80.2%
381		3	0	100.0%	276	11	96.0%	3	2	33.3%	275	50	81.8%
382	No OS	3	0	100.0%	275	16	94.2%	3	2	33.3%	275	86	68.7%
383	40	3	0	100.0%	265	25	90.6%	3	1	66.7%	263	106	59.7%
390	19	3	0	100.0%	258	17	93.4%	3	1	66.7%	257	64	75.1%
391	26	3	0	100.0%	261	8	96.9%	3	3	0.0%	258	68	73.6%
392	47	3	0	100.0%	275	5	98.2%	3	3	0.0%	273	81	70.3%
393	46	3	0	100.0%	276	16	94.2%	3	3	0.0%	273	80	70.7%
400		1	0	100.0%	83	6	92.8%	1	0	100.0%	81	2	97.5%
405		1	0	100.0%	78	0	100.0%	1	0	100.0%	78	4	94.9%
448	122	3	1	66.7%	206	39	81.1%	3	2	33.3%	204	70	65.7%
449	41	3	1	66.7%	204	31	84.8%	3	3	0.0%	204	39	80.9%
450	34	1	0	100.0%	82	26	68.3%	1	1	0.0%	80	25	68.8%
460	31	1	0	100.0%	81	27	66.7%	1	1	0.0%	78	26	66.7%
461		1	0	100.0%	84	5	94.0%	1	0	100.0%	83	2	97.6%
463		1	0	100.0%	43	4	90.7%	1	0	100.0%	43	0	100.0%
464	38	1	0	100.0%	81	16	80.2%	1	1	0.0%	79	25	68.4%
467	54	1	0	100.0%	43	1	97.7%	1	1	0.0%	42	3	92.9%
488		1	0	100.0%	87	21	75.9%	1	0	100.0%	79	11	86.1%
499		1	0	100.0%	80	11	86.3%	1	0	100.0%	77	6	92.2%
500		3	0	100.0%	267	15	94.4%	3	0	100.0%	265	32	87.9%
502		3	0	100.0%	274	15	94.5%	3	0	100.0%	271	56	79.3%
503	54	3	0	100.0%	272	25	90.8%	3	2	33.3%	266	76	71.4%
504	22	3	0	100.0%	276	17	93.8%	3	1	66.7%	274	83	69.7%
505	18	3	0	100.0%	274	36	86.9%	3	2	33.3%	270	75	72.2%
506	25	3	1	66.7%	271	39	85.6%	3	1	66.7%	266	42	84.2%
507	16	3	0	100.0%	276	34	87.7%	3	2	33.3%	276	90	67.4%
508		3	0	100.0%	271	39	85.6%	3	0	100.0%	268	62	76.9%
509		3	0	100.0%	273	12	95.6%	3	0	100.0%	273	63	76.9%
511		3	0	100.0%	268	21	92.2%	3	0	100.0%	267	45	83.1%
516	40	3	0	100.0%	268	27	89.9%	3	2	33.3%	267	125	53.2%
517	23	3	0	100.0%	276	8	97.1%	3	3	0.0%	272	111	59.2%
518		3	0	100.0%	276	35	87.3%	3	2	33.3%	274	185	32.5%
519		3	0	100.0%	268	9	96.6%	3	0	100.0%	266	63	76.3%
520		3	0	100.0%	153	24	84.3%	3	0	100.0%	150	9	94.0%
521		3	0	100.0%	191	7	96.3%	3	1	66.7%	191	24	87.4%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
522		3	0	100.0%	191	36	81.2%	3	0	100.0%	188	18	90.4%
523		3	0	100.0%	191	6	96.9%	3	0	100.0%	190	22	88.4%
524		3	0	100.0%	191	11	94.2%	3	0	100.0%	189	20	89.4%
525		3	0	100.0%	189	12	93.7%	3	0	100.0%	186	13	93.0%
526		3	0	100.0%	165	29	82.4%	3	1	66.7%	162	13	92.0%
527		3	1	66.7%	191	10	94.8%	3	0	100.0%	190	32	83.2%
528		3	0	100.0%	191	15	92.1%	3	0	100.0%	190	29	84.7%
529		3	0	100.0%	191	11	94.2%	3	0	100.0%	190	50	73.7%
530		3	0	100.0%	145	14	90.3%	3	1	66.7%	145	27	81.4%
531		3	0	100.0%	165	12	92.7%	3	1	66.7%	165	12	92.7%
532	17	3	2	33.3%	191	45	76.4%	3	2	33.3%	190	29	84.7%
534		3	0	100.0%	150	24	84.0%	3	0	100.0%	148	15	89.9%
535		3	1	66.7%	178	24	86.5%	3	0	100.0%	173	20	88.4%
536		3	0	100.0%	191	49	74.3%	3	0	100.0%	188	37	80.3%
537		3	0	100.0%	162	18	88.9%	3	0	100.0%	157	16	89.8%
538		3	0	100.0%	191	23	88.0%	3	1	66.7%	190	38	80.0%
539		3	1	66.7%	145	21	85.5%	3	1	66.7%	145	65	55.2%
540		2	1	50.0%	190	36	81.1%	2	0	100.0%	183	18	90.2%
541		3	0	100.0%	190	21	88.9%	3	1	66.7%	185	34	81.6%
542	31	3	0	100.0%	190	21	88.9%	3	2	33.3%	188	34	81.9%
543		3	0	100.0%	191	19	90.1%	3	2	33.3%	191	52	72.8%
544		3	0	100.0%	189	20	89.4%	3	0	100.0%	186	15	91.9%
545		3	1	66.7%	191	16	91.6%	3	0	100.0%	189	22	88.4%
547		3	0	100.0%	191	37	80.6%	3	0	100.0%	191	44	77.0%
548		2	0	100.0%	186	20	89.2%	2	0	100.0%	185	14	92.4%
549		3	0	100.0%	186	25	86.6%	3	0	100.0%	179	16	91.1%
550		3	0	100.0%	145	14	90.3%	3	0	100.0%	145	31	78.6%
551		3	0	100.0%	187	19	89.8%	3	0	100.0%	179	17	90.5%
562		3	0	100.0%	268	21	92.2%	3	0	100.0%	265	29	89.1%
564		3	0	100.0%	268	17	93.7%	3	1	66.7%	260	31	88.1%
566		3	0	100.0%	266	17	93.6%	3	0	100.0%	263	32	87.8%
567		3	0	100.0%	153	8	94.8%	3	0	100.0%	151	6	96.0%
572		3	0	100.0%	263	22	91.6%	3	1	66.7%	258	66	74.4%
573		3	0	100.0%	266	40	85.0%	3	0	100.0%	259	44	83.0%
579	73	3	0	100.0%	153	8	94.8%	3	1	66.7%	148	27	81.8%
580		3	0	100.0%	268	14	94.8%	3	0	100.0%	263	21	92.0%
581	55	3	0	100.0%	268	43	84.0%	3	1	66.7%	266	55	79.3%
584	30	3	2	33.3%	152	19	87.5%	3	3	0.0%	148	85	42.6%
587		3	0	100.0%	263	15	94.3%	3	1	66.7%	254	39	84.6%
588		3	1	66.7%	153	13	91.5%	3	0	100.0%	152	22	85.5%
591		3	0	100.0%	267	18	93.3%	3	0	100.0%	261	29	88.9%
593		3	0	100.0%	262	37	85.9%	3	1	66.7%	244	28	88.5%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
595		3	1	66.7%	263	42	84.0%	3	1	66.7%	260	47	81.9%
611		1	1	0.0%	39	27	30.8%	1	0	100.0%	39	4	89.7%
624		1	0	100.0%	115	37	67.8%	1	0	100.0%	116	29	75.0%
660		1	0	100.0%	74	11	85.1%	1	0	100.0%	74	25	66.2%
661	12	1	0	100.0%	102	11	89.2%	1	1	0.0%	101	38	62.4%
662		1	0	100.0%	41	0	100.0%	1	0	100.0%	41	1	97.6%
663		1	0	100.0%	74	10	86.5%	1	0	100.0%	74	6	91.9%
664	12	1	0	100.0%	73	6	91.8%	1	1	0.0%	73	7	90.4%
665	42	1	0	100.0%	74	8	89.2%	1	1	0.0%	74	20	73.0%
669	13	1	0	100.0%	73	7	90.4%	1	1	0.0%	73	21	71.2%
670	21	1	0	100.0%	74	10	86.5%	1	1	0.0%	74	14	81.1%
671	22	1	0	100.0%	73	6	91.8%	1	1	0.0%	73	8	89.0%
672	28	1	0	100.0%	74	7	90.5%	1	1	0.0%	74	13	82.4%
674		1	0	100.0%	73	22	69.9%	1	0	100.0%	73	4	94.5%
680		3	2	33.3%	196	11	94.4%	3	0	100.0%	195	24	87.7%
681		3	0	100.0%	196	14	92.9%	3	1	66.7%	191	73	61.8%
682		3	0	100.0%	195	5	97.4%	3	0	100.0%	195	33	83.1%
683	80	3	0	100.0%	178	15	91.6%	3	3	0.0%	177	54	69.5%
684	36	3	2	33.3%	177	29	83.6%	3	1	66.7%	177	39	78.0%
685	48	3	2	33.3%	192	30	84.4%	3	3	0.0%	189	47	75.1%
686	20	3	0	100.0%	197	33	83.2%	3	3	0.0%	196	39	80.1%
687		3	2	33.3%	196	32	83.7%	3	2	33.3%	195	33	83.1%
688		3	2	33.3%	195	11	94.4%	3	2	33.3%	194	32	83.5%
689	34	3	1	66.7%	142	19	86.6%	2	1	50.0%	140	21	85.0%
701		3	2	33.3%	208	23	88.9%	3	0	100.0%	205	20	90.2%
702		3	0	100.0%	275	31	88.7%	3	1	66.7%	273	61	77.7%
703	No OS	3	2	33.3%	276	79	71.4%	3	2	33.3%	275	72	73.8%
704		3	0	100.0%	207	32	84.5%	2	0	100.0%	201	38	81.1%
710		3	2	33.3%	276	71	74.3%	3	1	66.7%	272	74	72.8%
711		3	1	66.7%	267	29	89.1%	3	1	66.7%	250	46	81.6%
712	175	3	1	66.7%	273	72	73.6%	3	1	66.7%	265	88	66.8%
714	49	2	1	50.0%	157	59	62.4%	2	2	0.0%	145	60	58.6%
715		3	1	66.7%	275	59	78.5%	2	1	50.0%	255	126	50.6%
716		3	0	100.0%	276	107	61.2%	3	1	66.7%	271	103	62.0%
717	108	3	1	66.7%	262	63	76.0%	3	2	33.3%	244	72	70.5%
718		3	2	33.3%	276	138	50.0%	3	2	33.3%	274	93	66.1%
719	17	3	2	33.3%	276	90	67.4%	3	3	0.0%	262	75	71.4%
757		3	0	100.0%	61	3	95.1%	3	0	100.0%	60	4	93.3%
761		3	1	66.7%	272	12	95.6%	3	0	100.0%	269	34	87.4%
765		3	0	100.0%	272	24	91.2%	3	0	100.0%	272	36	86.8%
769		3	0	100.0%	272	25	90.8%	3	0	100.0%	266	49	81.6%
770	19	3	0	100.0%	272	21	92.3%	3	1	66.7%	270	75	72.2%

Amtrak On Time Performance

Trains Arriving Through: 7/3/2026

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
774		3	0	100.0%	272	16	94.1%	3	0	100.0%	271	56	79.3%
777		3	0	100.0%	157	9	94.3%	3	0	100.0%	156	34	78.2%
782		3	2	33.3%	157	58	63.1%	3	0	100.0%	152	15	90.1%
785		3	0	100.0%	272	17	93.8%	3	0	100.0%	272	46	83.1%
786	24	3	0	100.0%	61	16	73.8%	3	1	66.7%	60	28	53.3%
790		3	0	100.0%	272	26	90.4%	3	0	100.0%	269	32	88.1%
794		3	1	66.7%	272	32	88.2%	3	1	66.7%	269	56	79.2%
821	35	3	0	100.0%	270	6	97.8%	3	2	33.3%	270	105	61.1%
822	18	3	1	66.7%	272	15	94.5%	3	2	33.3%	270	120	55.6%
1233	55	1	0	100.0%	7	2	71.4%	1	1	0.0%	7	4	42.9%
1246	90	1	1	0.0%	7	6	14.3%	1	1	0.0%	7	2	71.4%
1333		3	2	33.3%	272	30	89.0%	3	2	33.3%	269	90	66.5%
1340	49	3	0	100.0%	271	5	98.2%	3	2	33.3%	271	44	83.8%
2207		1	1	0.0%	19	5	73.7%	1	0	100.0%	19	5	73.7%
2208		1	0	100.0%	3	0	100.0%	1	0	100.0%	3	0	100.0%
2211		1	0	100.0%	2	1	50.0%	1	0	100.0%	2	1	50.0%
2219	87	1	1	0.0%	3	2	33.3%	1	1	0.0%	3	1	66.7%
2224		1	0	100.0%	18	4	77.8%	1	0	100.0%	18	2	88.9%
2250		1	1	0.0%	100	9	91.0%	1	0	100.0%	100	34	66.0%
2252		1	0	100.0%	99	8	91.9%	1	0	100.0%	97	28	71.1%
2254	113	1	0	100.0%	34	0	100.0%	1	1	0.0%	34	9	73.5%
2255	30	1	0	100.0%	100	11	89.0%	1	1	0.0%	99	47	52.5%
2258	104	1	0	100.0%	36	9	75.0%	1	1	0.0%	35	13	62.9%
2259	51	1	0	100.0%	56	23	58.9%	1	1	0.0%	55	26	52.7%
2260	114	1	0	100.0%	3	0	100.0%	1	1	0.0%	3	2	33.3%
2262	88	1	0	100.0%	17	2	88.2%	1	1	0.0%	17	4	76.5%
2265	64	1	0	100.0%	37	3	91.9%	1	1	0.0%	36	21	41.7%
2267	Cncl'd	1	0	100.0%	3	1	66.7%	0	0	0.0%	2	2	0.0%
2271	26	1	0	100.0%	84	9	89.3%	1	1	0.0%	83	43	48.2%
2293		1	0	100.0%	3	0	100.0%	1	0	100.0%	3	1	66.7%

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2219	WAS	87	WTR	67	DET	49	NYP-NYP	AM	Catenary failure, Other, NYP-NYP, HELD A/C WIRE DOWN EAST OF LINCOLN
2254	BOS	113	ENG	67	ENG	67	NYP-XSH	AM	Other electrical failure, 2121 NG NP, NECESSARY TO REVERSE TO NYP A/C HVAC FAILURE
2255	WAS	30	WTR	30	WTR	12	XCY-XHM	AM	Heat order, Other, XMW-XHM
2258	BOS	104	WTR	55	WTR	16	XHM-XCY	AM	Heat order, Other, XHM-XCY, HEAT ORDERS
2259	WAS	51	WTR	44	WTR	13	XCY-XHM	AM	Heat order, Other, XCY-XHM, COMPLIED WITH HEAT RESTRICTONS PER TSRB
2260	BOS	114	DCS	47	DCS	47	XGX-PVD	AM	Power switch failure, Milepost w/Letters, XGX, PVD, 12sw at Atwell is out of correspondence, AM2260 stopped eastbound on track No. 2 at Atwells
2262	BOS	88	WTR	48	DET	18	NWK-NYP	AM	Catenary failure, Other, XHU-XPT , HELD AT SWIFT A/C POWER LOSS SWIFT TO TENTH AVE
2265	WAS	64	WTR	37	DSR	22	NHV-STM	MN	Per bulletin Restricted speed cat pole 533-535. PSGR speed 15 east Norwalk - cp 241. WR 1 in effect., Milepost, 48.6, 33.6, 30, 2
2267	WAS	Trn Cancelled	WTR	59	WTR	41	NYP-PHL	AM	Heat order, Other, X94-XHM, HEAT ORDERS
2271	WAS	26	DET	28	DET	16	NWK-XCY	AM	Catenary failure, Other, XIS-XCY, OPERATED NO.3 TRK A/C NO.1 AND NO.2 TRK O/O/S
82	BOS	21	WTR	20	ENG	11	NHV-OSB	AM	Legitimate wayside HBD or DED actuation, 603 EX ES, AM82 rpts Integrity failure at East Haven HBD/DED on trk 1. Stopped to insp XM4 - XBC
87	NFK	47	WTR	35	WTR	27	MET-XHM	AM	Heat order, Other, MET-XHM, HEAT ORDERS
99	NPN	Trn Cancelled	FTI	437	FTI	437	WAS-XVG	AM	Hold due to freight derailment, G635-30, Milepost, 83, 80
124	PHL	No OS Rpt	FTI	144	FTI	144	RVR-RVR	CS	Hold due to freight derailment Train 99 terminated at RVR. Train turned and held for bus transfers for NB AMT 124., no id, Control Point, GN
126	NYP	95	WTR	51	WTR	18	WAS-WAS	AM	Heat order, Control Point, K INT, MULTIPLE HOT CARS
135	WAS	56	OTH	24	WTR	18	MET-TRE	AM	Heat order, Other, MET-TRE, HEAT ORDERS

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
136	SPG	31	OTH	30	SVS	23	PHL-PHL	AM	Pick up equipment, CAPPED WITH ENG 644 A/C ENG 616 FAULTS
140	SPG	63	WTR	46	DET	35	PHL-PHL	AM	Catenary maintenance , Control Point, NYP, HELD A/C STEADYSPAN NOT WORKING ON ALL TRACKS
143	WAS	16	WTR	10	ENG	6	TRE-XHM	AM	Other electrical failure, 605, CHECKING CARBON STRIPS ON ENG.605
146	SPG	60	DET	24	DET	24	TRE-MET	AM	Catenary failure, Other, XCY-MET, CONGESTION A/C NO.1 AND NO.2 TRK OOS
147	RNK	150	WTR	49	CTI	19	XA1-BCV	NS	Follow Running on approach, VRE, N/A, Milepost, 105.2, 21.3
150	BOS	20	HLD	11	DCS	8	OSB-NLC	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), RESTRICTING, Other, AUTOMATIC SIG, RESTRICTED SPEED FROM THE AUTOMATIC SIG TRACK 2 EAST OF NAN TO SHAWS COVE
151	RNK	20	WTR	18	WTR	18	LYH-RNK	NS	Heat order Milepost, 239.0, 256.0
152	BOS	17	WTR	11	DSR	7	STM-BRP	MN	Per bulletin Milepost, 48.0, 41.0, 30, 2
155	NFK	158	WTR	155	WTR	126	X3V-NFK	NS	Heat order Milepost, 3.1, 0.0, Milepost, 77.6, 1.5
156	NYP	177	WTR	132	WTR	59	CLP-MSS	NS	Heat order Milepost, 67.4, 32.6
158	NYP	203	DSR	135	DSR	128	NFK-X3V	NS	Per bulletin Milepost w/Letters, N3.5, N77.7, 25, both
161	WAS	65	WTR	46	WTR	13	MET-TRE	AM	Heat order, Other, MET-TRE, HEAT ORDERS
162	BOS	28	CTI	22	CTI	15	STM-BRP	MN	Follow metro north, 6518, Milepost, 34, 43
164	BOS	32	HLD	22	WTR	12	NHV-NHV	AM	Heat order, Control Point, XM4, AM164 held for heat patrol clearing
165	WAS	70	ENG	56	ENG	56	NYP-NYP	AM	Undesired emergency application, 650 EX ES, PANTOGRAPH WILL NOT STAY UP
167	PHL	41	POL	22	CON	18	NHV-NHV	MN	Hold for connecting train, Held for 467
168	BOS	108	WTR	47	WTR	20	TRE-MET	AM	Heat order, Other, TRE-MET, HEAT ORDERS
178	BOS	207	WTR	234	WTR	69	CLP-MSS	NS	Heat order Milepost, 67.0, 32.0
179	PHL	43	SYS	31	SYS	31	NHV-BRP	MN	Doing engine move from train 148

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
194	BOS	169	WTR	65	DCS	49	KIN-PVD	AM	Power switch failure, Milepost w/Letters, KIN, PVD, 12sw at Atwell is out of correspondence, AM194 stopped eastbound on track No. 1 at Atwells
195	WAS	25	WTR	25	WTR	7	MET-XHM	AM	Heat order, Other, XH1-XHM
450	SPG	34	SMW	27	SMW	27	WFD-MDN	AM	Diversions around M/W work, Milepost, xhc, xhc, Held for AM147 a/c O/S track 1 between Holt and Willow
460	SPG	31	SMW	22	SMW	22	WFD-MDN	AM	Diversions around M/W work, Other, HOLT, WAIT FOR 461 TO CLEAR
464	SPG	38	SMW	28	SMW	28	WFD-MDN	AM	Diversions around M/W work, Milepost w/Letters, WFD, MDN, AM464 held at Holt for CT6455 to clear single track a/c trk 1 OOS Holt - Willow
467	NHV	54	DCS	47	DCS	43	SPG-WNL	AM	Cab signal or ATS failure (wayside), Control Point, Field, cab signal failure capped 59 MPH
53	SFA	78	PTI	60	PTI	60	XFL-XOU	CS	Meet 98, 52, Control Point, Java, Control Point, Lane
79	CLT	64	WTR	78	WTR	35	SSM-RGH	NS	Heat order Other, NC-Line
80	NYP	38	WTR	55	PTI	15	CLT-CLT	NS	Wait for station track Had to line out behind amt 20, Amt 20, Milepost, 376.0, 376.0
661	HAR	12	OTH	11	OTH	3	EXT-DOW	AM	Lost time - N.A.R.
664	NYP	12	WTR	11	WTR	8	TRE-NWK	AM	Heat order, Other, TRE-NWK
665	HAR	42	DET	29	DET	20	PHL-PHL	AM	Catenary failure, Control Point, JO, REVERSED BACK INTO PENN THEN SINGLE TRACKING OVERBROOK TO ZOO A/C REPORT OF POSSIBLE CATENARY DAMAGE NO 4 TRK JO
669	HAR	13	WTR	27	WTR	23	NWK-TRE	AM	Heat order, Other, X94-TRE, HEAT ORDERS
670	NYP	21	WTR	26	WTR	20	TRE-NWK	AM	Heat order, Other, TRE-NWK, HEAT ORDERS
671	HAR	22	PTI	27	PTI	24	NWK-TRE	AM	Follow, AM2271, Other, NWK-TRE, FOLLOWED AM2271
672	NYP	28	DET	26	DET	26	TRE-NWK	AM	Catenary failure, Other, XCY-XIS, CONGESTION A/C NO.1 AND NO.2 TRK OOS
19	NOL	117	FTI	107	FTI	54	TCL-MEI	NS	Follow 29K, Milepost, 275, 282

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
20	NYP	202	DSR	174	DSR	60	CLP-MSS	NS	Per bulletin Milepost, 67.5, 32.5, 25, All, Milepost, 45.7, 45.7, 10, 1, Milepost, 42, 41.3, 25, 1	
683	BRK	80	PTI	33	PTI	18	EXR-DHM	CS	Meet 684, Control Point, Rockingham	
684	BON	36	DCS	21	DCS	10	BRK-FRE	CS	Restrictive signal(s) from unknown cause Restricted proceed, Other, BRU 8.4	
685	BRK	48	PTI	17	PTI	17	ORB-POR	CS	Meet amt 688, Control Point, Cooks 2 trk	
686	BON	20	WTR	18	WTR	3	FRE-POR	CS	Heat order Other, PSD	
689	BRK	34	DCS	15	SVS	15	POR-FRE	CS	Planned set out / pick out of locomotives, cars or section of train Detached an engine and a coach, Other, Portland station	
63	TWO	47	POL	21	POL	21	BUF-BUF	CS	Removal of passenger by police Highly intoxicated pax passed out in vestibule. Had to be removed by police/EMS	
68	NYP	39	WTR	45	WTR	45	SLQ-RSP	CN	Heat order Milepost, 43, 0	
235	ALB	16	CTI	10	CTI	10	CRT-POU	MN	Follow metro north, 8835, Milepost, 58, 73	
243	ALB	28	ITI	24	ITI	24	NYP-NYP	AM	Service, turn, or wye train, 1246, LATE TURN AM1246	
281	NFL	37	WTR	41	FTI	17	XHF-AMS	CS	Meet csx, Control Point, 175	
283	NFL	46	WTR	33	OTH	22	NYP-NYP	AM	Lost time - N.A.R., LATE F/SSYD F/UNSPECIFIED REASON	
291	VRN	40	CTI	14	CTI	14	CRT-POU	MN	Follow MNRR, 8831, Milepost, 58, 72	
1233	PIT	55	FTI	37	FTI	37	XRD-PIT	CS	Follow csx, Milepost, 176, 155	
1246	NYP	90	FTI	64	ENG	43	PIT-PIT	CS	PTC- IETMS recycle breaker to clear fault Issues logging into ietms, 9702	
49	CHI	120	ENG	130	ENG	82	NYP-NYP	AM	Traction motor, 701 DX DM, LATE RELEASE F/SSYD A/C MECHANICAL ISSUES. CAPPED ENGINE 9707 WITH 701 AND HOT CARS.	
448	BOS	114	FTI	90	FTI	90	XRD-PIT	CS	Meet Z126, M427, Control Point, 171	
449	ALB	41	PTI	34	PTI	26	PIT-XRD	CS	Follow AM1246, Milepost w/Letters, cp 171, cp 187	
42	NYP	98	ENG	31	SYS	29	PGH-PGH	NS	Crew rest Milepost, 353.1, 353.1	
43	PGH	88	WTR	92	WTR	35	LEW-HGD	NS	Heat order Milepost, 179, 202	
71	CLT	14	DSR	14	DSR	13	DNC-GRO	NS	Per bulletin Milepost, 46.7, 46.6, 25, 1, Milepost, 46.4, 46.2, 25, 1, Milepost, 42.2, 42.1, 25, 1, Milepost, 31.7, 31.6, 25, 1	

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
78	RGH	63	WTR	49	WTR	46	CLT-KAN	NS	Heat order NS Heat Order 25mph until 9:00pm, Milepost, 376, 349
89	SAV	131	FTI	78	FTI	78	KTR-CHS	CS	Meet All stop CP North Lane pulled high into Trk 1 had to do the shuffle a CSX Freight was parked in front of Amt 89 waiting on Amt 98 and CSX M40802, Control Point, North Lane, AMT 98, CSXT M40802, AMT 98 / Mixed CSX
90	NYP	34	FTI	46	WTR	20	RMT-PTB	CS	Heat order Other, N.E. Sub
97	MIA	141	SVS	65	SVS	65	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C SHORTAGE OF EQUIPMENT AND SERVICING
98	NYP	45	FTI	52	CTI	24	XDJ-ALX	CS	Follow vre, Milepost, 61.0, 105.2
54	SAB	42	DCS	32	DCS	29	NHT-GFD	MA	Restrictive signal(s) from unknown cause Restricting, Stop and proceed, Control Point, cpr 18, Other, hatfield 20.82
40	CHI	775	ENG	309	FTI	77	XPI-XH6	NS	Follow 29P, Milepost, 482, 497
41	MIA	204	FTI	131	FTI	36	WTI-TOL	NS	Follow 264, Milepost, 292, 289
24	MOE	102	FTI	132	FTI	114	PAG-MOE	CS	Follow CSX 602, Milepost, 696.6, 666.6
25	NOL	23	FTI	51	FTI	28	PAG-BIX	CS	Meet Take Siding, 0800-01, Siding, Gautier
6	CHI	58	FTI	86	FTI	35	BRL-GBB	BN	Blocked from station track BNSF1416, Control Point, A Plant
532	SAC	17	TCR	21	TCR	21	OKJ-OKJ	UP	Hole in air hose 8203 C8203, Changed consist to AMT 537's Equipment
542	SAC	31	MBO	26	MBO	26	MTZ-SUI	UP	For maritime traffic Control Point, vista
50	NYP	No OS Rpt	ITI	261	ITI	261	CHI-CHI	AM	Service, turn, or wye train 5101
503	EUG	54	ENG	35	ENG	28	KEL-KEL	BN	Air / Brake WS1406
504	SEA	22	PTI	20	PTI	20	PDX-VAN	BN	Meet Amtk 503, Amtk 27, Control Point, Willamette River Br
505	PDX	18	DMW	10	DMW	10	XA4-XTW	BN	Held for or routed around MW work or equipment Control Point, pacific
506	SEA	25	FTI	23	FTI	23	PDX-VAN	BN	Meet UP 8063, Control Point, North Portland
507	EUG	16	DSR	21	PTI	16	PDX-ORC	UP	Meet Stop in the Clackamas siding, met AMTK 508, AMTK 508, Siding, Clackamas
516	VAC	40	DBS	42	DBS	42	XF2-X1J	BN	Debris blocking track (no debris strike) Control Point, Still Creek

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
517	PDX	23	PTI	19	PTI	14	TAC-XNI	ST	Meet AMT 504, Control Point, RILL
8	CHI	210	FTI	225	ITI	56	SEA-SEA	BN	Service, turn, or wye train 007, Added locomotive 72 for protect
821	FTW	35	DCS	25	DCS	25	GLE-FTW	BN	Power switch failure Operate switch by hand, with flagging instructions., Siding, South Metro
822	OKC	18	DSR	25	DSR	17	FTW-GLE	BN	Per bulletin Milepost, 353.8, 354.0, 60, main 2, Milepost, 354.0, 354.1, 70, main 2, Milepost, 355.4, 355.5, 60, main 2, Milepost, 355.6, 355.8, 40, main 2, Milepost, 356.5, 356.7, 30, main 2, Milepost, 361.5, 362.9, 60, main 2, Milepost, 364.7, 365.1, 60, main 1, Milepost, 370.6, 370.7, 30, main, M
337	MKE	12	PTI	9	PTI	9	GLN-XRO	ME	Meet 338, Control Point, XRO
339	MKE	19	CTI	28	CTI	20	XWA-GLN	ME	Meet Waited at Morton Grove for 2146 to pass. Single-tracking between Morton Grove and A20; broken rail somewhere on #2., Metra, 2146, Control Point, Morton Grove
341	MKE	67	CTI	37	ITI	28	CHI-CHI	AM	Service, turn, or wye train 1340
350	PNT	27	PTI	22	DMW	16	XT6-X1W	CR	Foreman langmeister at cp Conrail. Received a form D talked by cp Conrail restricted speed . stone car dropping ballast Control Point, conrail
351	CHI	60	INJ	50	INJ	50	XA5-XB0	MI	Injured or sick passenger PNR 37c080 medical emergency. EM arrived refer to form passenger medical emergency
352	PNT	235	DCS	85	DCS	69	JXN-ARB	MI	Restrictive signal(s) from known wayside signal failure Restricting, Milepost w/Letters, CP 52, CP 37
354	PNT	97	TRS	34	TRS	34	DET-ROY	CC	Vehicle on track ahead Hold at CP Moterm. Car on tracks ahead at MP 12.94, Milepost, 12.94, 12.94
355	CHI	143	WTR	83	DBS	72	JXN-ALI	MI	Debris blocking track (no debris strike) Hold at ALI. Power lines reported down at MP 112.97., Milepost, 112.97, 112.97
364	PTH	74	FTI	53	DCS	51	BTL-LNS	CC	Restrictive signal(s) from known wayside signal failure Wayside box failure Clear signal given for route PTC gave restricting, Clear, Milepost, 199.8, 205.99

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	17	DSR	40	DSR	26	LNS-BTL	CC	Per bulletin Milepost, 219.15, 219.15, 25, mt, Milepost, 219, 218.5, 30, mt, Milepost, 216.1, 215.79, 60, mt, Milepost, 214.96, 214.96, 25, m2, Milepost, 214.93, 214.93, 25, m1, Milepost, 210.40, 210.40, 30, m2, Milepost, 205.99, 205.99, 60, mt
370	GRR	102	FTI	52	FTI	26	XTF-XH6	NS	Meet Control Point, 515, NS4083
371	CHI	113	DBS	124	DBS	124	HOM-BAM	CS	Debris strike Tree, Control Point, Pullman
579	LAX	73	POL	62	POL	62	IRV-SNA	SC	Fire department hold Car stop/disabled at Fourth St 175.5
581	LAX	55	CTI	43	CTI	22	SNA-ANA	SC	Follow Restricted proceed @ 1731. Stopped there, due to ML 1858 stopped at orange station with a medical emergency on board their train., Metrolink, 1858, Other, 1731
584	SAN	30	CTI	24	OTH	14	LAX-LAX	SC	AMTK 579 was delayed arriving into LAX. Had to wait until equipment was set and loaded for AMTK 584.
770	SAN	19	CTI	21	CTI	21	SNC-SNP	SC	Meet metrolink, 1663, Control Point, Serra
786	SAN	24	PTI	37	PTI	25	GUA-LPS	UP	Meet Meet AMTK 14, 14, Siding, Narlon
703	SAC	No OS Rpt	TSV	139	TSV	139	BFD-BFD	BN	Held for arrival of AM 714/712 combo, after 714 rescued broken down 712
712	BFD	175	ENG	169	ENG	169	WAC-BFD	BN	Loading problem Would not load., C2009
714	BFD	49	SYS	36	SYS	36	WAC-BFD	BN	Blocked by or assisting another, disabled Amtrak train Coupled to 712 towed to Bakersfield, Siding, wasco
717	OKJ	108	POL	56	POL	50	ACA-XPR	BN	Fire department hold
719	OKJ	17	DCS	28	DCS	28	SKN-ACA	BN	Power switch failure Had to throw switch into hand at w. Stockton, Control Point, w. stockon
4	CHI	36	FTI	112	PTI	45	LMY-LSV	BN	Meet AMTK #3, Siding, FOX
1	LAX	305	FTI	467	FTI	391	SND-ALP	UP	Behind Disable Train Blocking route Disable train severe issues, Control Point, Maxon, up5741
21	SAS	182	FTI	220	FTI	120	FTW-X55	BN	No route on the BNSF waiting for frt to clear The frt crew had some type of medical emergency, Control Point, T 951 Tower 55, BNSF 6041
22	CHI	85	FTI	73	SVS	64	FTW-FTW	TE	Planned Switch

Amtrak Endpoint OTP Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
300	CHI	162	FTI	171	FTI	119	BNL-PON	UP	Freight train with air issues UP 9614, Milepost, 121.0, 121.0
301	STL	57	FTI	71	FTI	47	JOL-BNL	UP	Disabled freight train @ Ballard. Had to put out a bad car. Unknown freight, Control Point, Ballard
302	CHI	52	FTI	25	FTI	25	BNL-BNL	UP	Meet UP 9614, Control Point, 123
305	STL	41	PTI	21	DCS	20	CRV-ALN	UP	Restrictive signal(s) from unknown cause Stop, Control Point, X252
306	CHI	No OS Rpt	WTR	45	WTR	39	SMT-XTF	CC	High winds Control Point, Brighton
380	CHI	28	FTI	21	FTI	14	MAC-GBB	BN	Meet Siding, Abington, BNSF 8269
382	CHI	No OS Rpt	WTR	94	WTR	59	PLO-NPV	BN	High winds Milepost, 112, 4.1
383	QCY	40	WTR	24	WTR	16	KEE-GBB	BN	High winds Milepost, 124, 185
390	CHI	19	PTI	15	PTI	15	CHM-RTL	CC	Meet 3 way meet, 391, Siding, chm
391	CDL	26	HLD	18	HLD	7	CHM-CHM	CC	High passenger count
392	CHI	47	WTR	45	ENG	17	CEN-EFG	CC	Major engine fault ID4626
393	CDL	46	WTR	41	PTI	17	CHM-MAT	CC	Meet Pulled behind 334 to wait for AMT 392 for a shuffle move at N Tuscola., AMT 392, Control Point, N Tuscola
316	STL	34	DCS	46	DCS	28	WAR-SED	UP	Restrictive signal(s) from known wayside signal failure Stop, Other, WAR station, Other, MP 207
319	KCY	67	PTI	46	PTI	17	XWR-XQT	TR	Meet amt318, Control Point, q tower
1340	CHI	49	DMW	37	DMW	37	XRO-GLN	ME	Hold for defect repair Control Point, A-20

Amtrak Initial Terminal Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/3/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	20	07/03	197	197	Service, turn, or wye train 19
BON	685	07/03	10	11	Heat / AC 82672, Mitigating a hot car and the loading of paxs.
BRK	684	07/03	2	2	DTMF code not working, call DS to put signal in. Approach. Control Point, Brunswick West
CLT	80	07/03	15	15	Wait for station track Had to line out behind amt 20, Amt 20, Milepost, 376.0, 376.0
MIA	40	07/03	106	106	Set out defective locomotive 333
NFK	158	07/03	1		
NYP	19	07/03	127	127	Set out defective car, 0000, HELD FOR AM98 TO ADD SLEEPER TO CONSIST
NYP	49	07/03	29	29	Undesired emergency application, 85 DX BD, POWER ISSUES THROUGHOUT CONSIST
NYP	51	07/03	23	23	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	97	07/03	113	113	Set out defective car, 0000, HELD FOR AM98 TO ADD COACH AND SLEEPER TO CONSIST
NYP	153	07/03	21	21	Door, 00000, UNSPECIFIED DOOR ISSUES
NYP	243	07/03	24	24	Service, turn, or wye train, 1246, LATE TURN AM1246
NYP	283	07/03	22	22	Lost time - N.A.R., LATE F/SSYD F/UNSPECIFIED REASON
NYP	2207	07/03	10	10	Delay in Block, PAPERWORK ISSUES
NYP	2219	07/03	49	49	Catenary failure, Other, NYP-NYP, HELD A/C WIRE DOWN EAST OF LINCOLN
PGH	42	07/03	29	29	Crew rest Milepost, 353.1, 353.1
PHL	144	07/03	8	10	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	611	07/03	1		
PIT	1246	07/03	63	43	PTC- IETMS recycle breaker to clear fault Issues logging into ietms, 9702
PIT	1246	07/03	63	20	Late due to 1233 arriving late into Pittsfield
WAS	118	07/03	3	3	Passenger and/or baggage, PAXS STILL BOARDING AFTER DEPARTURE TIME
WAS	126	07/03	23	5	Delay in Block, CNDR REQUESTED TO BE ORDERED OUT FOR DEP DUE TO HOT CARS
WAS	126	07/03	23	18	Heat order, Control Point, K INT, MULTIPLE HOT CARS
WAS	146	07/03	13	13	Water, commissary, toilet/trash dumping, LATE COMMISSARY
WAS	194	07/03	39	39	Other electrical failure, 637, SHOPPED MOTOR
WAS	2250	07/03	3	3	Routine inspections, LATE RELEASE OF EQUIPMENT .ORIGINAL EQUIP SPOTTED @936P, SET CHANGED @342A, NEW SET SPOTTED @235A AND RELEASED @ 403A

Amtrak Initial Terminal Details

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/3/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	07/03	(No OS)		
CHI	341	07/03	28	28	Service, turn, or wye train 1340
FTW	822	07/03	1	1	Wheelchair PNR: 7ADAFa
KCY	318	07/03	1		
MKE	336	07/03	5	2	Copy authority / restriction
MKE	336	07/03	5	3	Restrictive signal(s) from unknown cause Stop, Other, East end depot 4
BFD	701	07/03	1		
BFD	703	07/03	139	139	Held for arrival of AM 714/712 combo, after 714 rescued broken down 712
BFD	717	07/03	13	13	Hold for thruway bus
BFD	719	07/03	13	13	Hold for thruway bus Late bus
EMY	6	07/03	1		
GTA	782	07/03	8	8	Meet 14, Control Point, CO 358
LAX	2	07/03	60		
LAX	584	07/03	13	14	AMTK 579 was delayed arriving into LAX. Had to wait until equipment was set and loaded for AMTK 584.
LAX	588	07/03	2	2	Door 6802
OKJ	532	07/03	21	21	Hole in air hose 8203 C8203, Changed consist to AMT 537's Equipment
OKJ	710	07/03	27	15	Onboard HBD alarm Per TASI Patrick Osei, allegedly alarm caused by bad MU cable somewhere in the consist. TASI advised at 7:25am that they'll be sending mechanical forces to Oakland/Jack London Square to troubleshoot. Arrived at scene at 7:59am, C2123
OKJ	710	07/03	27	12	PTC - On Board Cab Signal or PTC Failure Lost PTC after TASI troubleshooting efforts. Reset PTC breaker/recycle per UP Help PTC desk., C8810
OKJ	718	07/03	9	7	Meet 715, 545, Control Point, north jack london
OKJ	718	07/03	9	2	Door C9807
PDX	506	07/03	2	2	Blue flag displayed at north end of Depot 2 from earlier servicing. Other, Blue Flag protection depot 2
SAC	527	07/03	1		
SAC	539	07/03	1		
SAC	545	07/03	3	3	Door C8808, No door lights
SAN	761	07/03	1		
SEA	8	07/03	94	75	Late baggage car swop due to electrical problems

Amtrak Initial Terminal Details

26-FOI-00580 00000008154 "UNCLASSIFIED" 7/7/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 7/3/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	8	07/03	94	12	Follow Wait for Freight to clear block at north portal., bnsf, Control Point, South portal
SEA	8	07/03	94	7	Shoved out King 8 , yard 1 headroom, King 5 Other, King 8
SLO	794	07/03	8	8	Hold for thruway bus

Eastern Region

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	56.3	66.2	90.2	32	14
SEPTA	95.0	90.5	92.4	91.5	105	10
NJT-NED	95.0	86.5	83.9	88.6	179	24
NJT-SED	95.0	91.7	94.3	97.2	24	2

Operating Highlights

Train 53(03) South of Yemassee, SC - Freight Train Interference

04JUL26: Train 53(03) with engines 364, 380, 38 cars, and 396 customers onboard was delayed at milepost 477.4, 34 miles south of Yemassee, SC on the CSX Charleston subdivision due to disabled CSX freight train 410 ahead. CSX mechanical responded to the scene and was able to rectify the issue. Once the freight train was cleared, train 53(03) was able to advance.

Train	Delay	Comment
53(03)	1'01"	

Train 2267(03) Baltimore, MD - Engine Failure

04JUL26: Train 2267(03) with 218 customers onboard was terminated in Baltimore, MD on the Amtrak PW line due to multiple mechanical issues. The train reported the MCB opening. It was able to be closed. Upon arrival into Baltimore, the train received a parking brake fault. The crew attempted to troubleshoot the problem. In the process, the train lost head end power and was not able to recover it. The customers were detrained into the station to wait for train 135(03) to arrive. The passengers were reaccommodated on train 135(03). The equipment was deadheaded to Washington, DC.

Train	Delay	Comment
2267(03)	Term BAL	

Power Switch Failure West of Providence, RI

04JUL26: A power switch failure was reported at Atwell interlocking on the Amtrak NHB line. Train 2260(03) with 258 customers onboard was delayed waiting for a clear route. Train 194(03) with 317 customers onboard was also delayed.

Train	Delay	Comment
2260(03)	47"	
194(03)	49"	

Train 50(02) Charlottesville, VA - Servicing

04JUL26: Train 50(02) with engine 154, 55 "UNCLASSIFIED", and 184 customers onboard was delayed departing Charlottesville, VA on the Buckingham Branch North Mountain subdivision due to performing necessary daily inspections. Once the inspections were completed, the train advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(02)	57"	

Train 128(03) North of Norfolk, VA - Drawbridge Opening

03JUL26: Train 128(03) with engine 10, 9 cars, and 157 customers onboard was delayed at milepost 6.6, 2 miles north of Norfolk, VA on the NS Norfolk District due to maritime bridge opening. Once the bridge was closed, train 128(03) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
128(03)	30"	

Train 165(03) New York, NY - Engine Failure

03JUL26: Train 165(03) with engine 650, 9 cars, and 517 customers onboard was delayed departing New York, NY on the Amtrak NYT Line due to an undesired emergency brake application and the pantograph dropping. Mechanical responded to the train and was able to rectify the problem. Train 165(03) was able to depart the station at 9:12 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
165(03)	56"	

Train 98(03) South of Jesup, GA - Freight Train Interference

03JUL26: Train 98(03) with engines 206, 368, 10 cars, and 260 customers onboard was delayed at milepost 558.4, 10 miles south of Jesup, GA on the CSX Nahunta subdivision due to meeting CSX freight train 137. Once the freight train cleared, train 98(03) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(03)	39"	

Train 467(03) North of Windsor Locks, CT - Cab Signal Failure

03JUL26: Train 467(03) with cab car 9636, 1 car, engine 95, and 22 customers onboard was delayed at milepost 54.7, 7 miles north of Windsor Locks, CT on the Amtrak MRS line due to cab signal failure. The train was required to operate at a reduced speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
467(03)	43"	

Train 448(02) West of Pittsfield, MA - Freight Train Interference

03JUL26: Train 448(02) with engine 103, 5 cars, and 117 customers onboard was delayed at milepost 171.8, 21 miles west of Pittsfield, MA on the CSX Berkshire subdivision due to meeting CSX freight trains Z126 and M427. Once the freight congestion cleared, train 448(02) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
448(02)	1'30"	

Train 53(03) North of Richmond, VA - Passenger Train Interference

03JUL26: Train 53(03) with engines 130, 139, 5 cars, and 134 customers onboard was delayed at milepost 5.5, 1 mile north of Richmond, VA on the CSX RF&P subdivision due to meeting train 158(03), once the passenger train passed, train 53(03) was able to advance.

Train	Delay	Comment
53(03)	36"	

Train 51(03) South of Manassas, VA - Passenger Train Interference

03JUL26: Train 51(03) with engines 130, 139, 5 cars, and 134 customers onboard was delayed beginning at milepost 36.4, 4 miles south of Manassas on the NS Washington District due to crossing over to go around train 156(03). Once the train was around the passenger train, train 51(03) advanced to the next station.

Train	Delay	Comment
51(03)	1'10"	

Train 97(03) New York, NY - Initial Terminal Delay - Servicing

03JUL26: Train 97(03) operating with locomotive 611, 11 cars and 204 customers was delayed at the initial terminal of New York due to needing car 25058 off inbound 98(02) to fulfill the consist requirement. After the train was released from the yard it was positioned in the station for customer boarding and departed New York.

Train	Delay	Comment
97(03)	1'58"	

Train 19(03) New York, NY - Initial Terminal Delay - Servicing

03JUL26: Train 19(03) operating with locomotive 628, 8 cars and 182 customers was delayed at the initial terminal of New York due to cars 62002 and 69003 being shotted during inspection requiring them to be replaced to fulfill the consist requirement. After the train was released from the yard it was positioned in the station to allow customer boarding and train 19(03) was able to depart New York.

Train	Delay	Comment
19(03)	2'08"	

New York to Philadelphia Line East of New Brunswick - Catenary or Wayside Failure

03JUL26: at 1:55pm-et New Jersey Transit train 7836 stopped on the No.1 track at Lincoln Interlocking with pantograph damage. An emergency plate was placed in effect on the No.1 track between County and Lincoln interlockings. Passenger transfer from NJ7836 to NJ YM30 was executed. A hold was placed on all tracks to allow ET to perform inspections of the affected area. Trains were held at New York and Philadelphia.

3:22pm-et ET performed their inspections and authorized trains to resume operations on No.3 and No.4 tracks at normal speeds with trains 161(03) and NJ7845.

Train	Delay	Comment
2258(03)	09"	
161(03)	08"	
140(03)	35"	
2219(03)	49"	
87(03)	10"	

Train 2254(03) New York, NY - HVAC - Car Failure

03JUL26: Next Gen Accidents 2254(03) operating with TS-23 reported 3 hot cars after departing NYP at Gate Interlocking. Train was reversed back into New York to allow HSR Mechanical to inspect. Upon arrival back in New York HSR was able to de-prepare and re-prepare the trainset to allow the HVAC system to return to normal operating conditions. Train 2254(03) was then able to depart for a second time towards New Haven.

Train 2254(03) again had issues with three reported hot cars and stopped at Providence to reset the train once again. After the train was reset then were able to depart Providence enroute to Boston.

Due to the scheduled equipment turn of 2254(03) to 2293(03) train 2293(03) will operate with TS-23. Capacity has been reduced to accommodate the hot cars and did not result in overcapacity conditions. Modified food service will be made available for the business class passengers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2254(03)	1'06"	NYP

Train 194(03) Washington, DC - Initial Terminal Delay - Engine Failure

03JUL26: Train 194(03) operating with locomotive 637, 9 cars and 423 customers was delayed at the initial terminal of Washington due to locomotive 637 shopping out at departure time for failed air compressor and replaced with locomotive 655. After the new locomotive was added and the necessary testing and documentation was completed the customers were boarded and train 194(03) was able to depart Washington.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
194(03)	39"	

Train 40(03) Miami, FL - Engine Failure

03JUL26: Train 40(03) operating with locomotives 333-118, 10 cars and 103 customers was delayed at the initial terminal of Miami due to locomotive 333 shopping out at departure time for a parking brake failure requiring it to be replaced with locomotive 98. After the locomotives were swapped train 40(03) was able to board their customers and depart Miami.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(01)	1'46"	

Train 53(02) North of DeLand, FL - Commuter Train Interference

03JUL26: Train 53(02) with engines 360, 322, 40 cars and 408 customers onboard was delayed at milepost 749.6, 1 mile north of DeLand, FL on the CFRC CFRC subdivision due to meeting commuter trains 310 and 314. Once the commuter trains were cleared, train 53(02) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(02)	36"	

CSX Heat Orders - Weather

03JUL26: CSX has imposed heat orders between 1 and 7 p.m. impacting trains operating over the affected territories.

Train	Delay	Comment
124 (03)	02"	
155 (03)	26"	
158 (03)	11"	
156 (03)	03"	
281 (03)	22"	
283 (03)	19"	
40 (03)	45"	
40 (02)	57"	
41 (02)	46"	
448 (02)	04"	
449 (03)	18"	
50 (02)	19"	
52 (03)	06"	
53 (03)	26"	
63 (03)	02"	
64 (03)	17"	
683 (03)	14"	
684 (03)	06"	
685 (03)	09"	
686 (03)	18"	
687 (03)	07"	
688 (03)	09"	
79 (03)	43"	
80 (03)	52"	
90 (03)	46"	
97 (02)	30"	
98 (03)	30"	

Amtrak Northeast Corridor Heat Orders - Weather

03JUL26: With high temperatures expected across much of the Northeast Corridor, Amtrak imposed heat orders on the PW Line, NYP Line, PH Line, NHB Line and MRS Lines resulting in delays to trains and causing initial terminal delays to equipment turns off delayed trains.

The high temperatures caused mechanical HVAC failure on multiple trains. The trains took delays trying to troubleshoot the issues.

Train	Delay	Comment
118 (03)	12"	
126 (03)	51"	
127 (03)	07"	
135 (03)	21"	
140 (03)	46"	
143 (03)	10"	
146 (03)	22"	
147 (03)	49"	
152 (03)	11"	
155 (03)	03"	
150 (03)	02"	
156 (03)	22"	
158 (03)	10"	
161 (03)	46"	
164 (03)	22"	
165 (03)	09"	
168 (05)	47"	
19 (03)	38"	
194 (03)	59"	
195 (03)	25"	
20 (02)	14"	
2250 (03)	02"	
2252 (03)	04"	
2254 (03)	17"	
2255 (03)	30"	
2258 (03)	53"	
2259 (03)	37"	
2262 (03)	44"	
2265 (03)	37"	
2271 (03)	05"	
281 (03)	02"	
235 (03)	02"	
291 (03)	07"	
41 (02)	16"	
42 (03)	19"	
450 (03)	03"	
460 (03)	03"	
464 (03)	03"	
48 (02)	02"	
66 (03)	25"	
63 (03)	01"	
665 (03)	19"	
664 (03)	11"	
669 (03)	27"	
670 (03)	26"	
80 (03)	03"	
82 (03)	17"	
87 (03)	35"	
97 (03)	19"	
99 (03)	59"	
19 (03)	09"	Mechanical
97 (03)	21"	Mechanical
168 (03)	19"	Mechanical
235 (03)	02"	Mechanical
146 (03)	03"	Mechanical
2262 (03)	15"	Mechanical
99 (03)	08"	Mechanical
195 (03)	03"	Mechanical
2259 (03)	03"	Mechanical
118 (03)	04"	Mechanical
2219 (03)	32"	
2260 (03)	31"	

CN Heat Orders - Weather

03JUL26: CN imposed heat orders between Ronkonkomi, NY and St. Lambert, QC of 25 mph created delays for trains 68 and 69.

Train	Delay	Comment
68 (03)	45"	
69 (03)	52"	

Norfolk Southern System Heat Orders - Weather

03JUL26: NS has imposed heat orders for near the entirety of their network due to expected ambient temperatures exceeding 100 degrees in locations with expected rail temps exceeding 140 degrees. Trains operating over these routes will operate at speeds of 25 mph with delays expected to be significant.

Train	Delay	Comment
151 (03)	18"	
128 (03)	1'53"	
155 (03)	2'06"	
156 (03)	1'47"	
43 (03)	1'32"	
51 (03)	1'25"	
66 (03)	1'38"	
78 (03)	49"	
79 (03)	35"	
20 (02)	2'28"	
158 (03)	2'08"	

Train 53(02) South of Kingstree, SC - Passenger Train Interference

03JUL26: Train 53(02) with engines 360, 322, 40 cars, and 408 customers onboard was delayed at milepost 341.0, 10 miles south of Kingstree, SC on the CSX Charleston subdivision due to meeting trains 98(02) and 52(02). Once the passenger trains cleared, train 53(02) was able to advance.

Train	Delay	Comment
53 (02)	1'00"	

Train 49/449(02) Rochester, NY - Injured or Sick Passenger

03JUL26: Train 49/449(02) with engines 96, 127, 11 cars, and 250 customers onboard was delayed at Rochester, NY on the CSX Rochester subdivision due to a sick customer needing medical attention.

Train	Delay	Comment
49/449 (02)	39"	

Train 40(01) Harpers Ferry, WV - Police Related

03JUL26: Train 40(01) with engines 330, 316, 10 cars, and 212 customers onboard was delayed at Harpers Ferry, WV on the CSX Cumberland subdivision due to a passenger opening the door and jumping off of the train. It was reported that the elderly passenger was confused and jumped from the train while in the station. Emergency personnel arrived at the train and searched for the customer. Once the customer and emergency services were clear of the tracks, train 40(01) was able to advance to the next station.

Train	Delay	Comment
40 (01)	55"	

Downeaster Service Adjustments - Weather

04JUL26: The following Downeaster train has been cancelled due to the heat and equipment constraints: train 694(04) and 695(04). Customers will be reaccommodated on train 696(04) and train 697(04).

Train	Delay	Comment
694(04)	Cancelled	
695(04)	Cancelled	

CSX Freight Train Derailment on the Peninsula Subdivision

03JUL26: CSX reported a freight train derailment on the Peninsula Subdivision at milepost 83, 8 miles east of Richmond, VA. Three cars had derailed and fallen off of the viaduct into the water. Three cars and one locomotive were leaning. CSX personnel responded to the scene. Train 124(03) with 166 customers onboard was stopped at milepost 80 at 5:00 PM-ET. The train then reversed east to crossing at Charles City Road to transfer customers to buses. The road foreman responded to the train to assist in customer transfer. Buses were secured by station services. Once bus operated from where train 124(03) stood to Richmond Main Street Station and then returned to the train. A total of three buses then transferred the rest of the passengers to Richmond. The buses were then staged at Richmond to take the customers from train 99(03) to their destinations. Train 99(03) was terminated in Richmond and turned for train 124(03). Train 158(03) made train 124(03) stops.

Train 164(04) was originated in Washington, DC. Train 65(03) was terminated in Richmond.

WBS#: B.TR.100151.0828

Train	Delay	Comment
99(03)	Term RVR	
124(03)	6'30"	
164(04)	Orig WAS	
65(03)	Term RVR	

NEC Service Adjustments for 07/03/26 and 07/04/26- Weather

03JUL26: Due to the impending hot weather with Ambient temperatures elevated over 90 degrees the following service adjustments were made: Northeast Regional trains 163, 88, 159, 142, 106, and 107(03-04) were cancelled in their entirety. Keystone trains 666 and 667(03-04) were also cancelled in their entirety.

Train	Delay	Comment
163(03)	Cancelled	
159(03)	Cancelled	
88(03)	Cancelled	
142(03)	Cancelled	
106(03)	Cancelled	
107(03)	Cancelled	
666(03)	Cancelled	
667(03)	Cancelled	
163(04)	Cancelled	
159(04)	Cancelled	
88(04)	Cancelled	
142(04)	Cancelled	
106(04)	Cancelled	
107(04)	Cancelled	
666(04)	Cancelled	
667(04)	Cancelled	

Piedmont Service Cancellations - Norfolk Southern Heat Orders - Weather

03JUL26: Heat orders issued by the Norfolk Southern Districts would cause significant delays to the service scheduled through the area. As a result, trains were cancelled with alternate transportation secured. Two buses were secured for train 72(03). One bus operated express stopping and picking up in Charlotte, Greensboro and Raleigh. One bus making all stops. Two buses were secured for train 74(03) and both made all stops. Two buses were secured for train 76(03). One bus made stops in Charlotte, Durham, Cary, and Raleigh. The second bus made stops in Charlotte, Kannapolis, Greensboro, Durham, Cary, and Raleigh. Two buses were secured for train 73(03). One bus made stops in Raleigh, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 75(03). One bus made stops in Raleigh, Cary, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Burlington, Greensboro, Highpoint, Salisbury, Kannapolis, and Charlotte. Two buses were secured for train 77(03). One bus made stops in Raleigh, Durham, Greensboro, and Charlotte. The second bus made stops in Raleigh, Cary, Durham, Greensboro, Highpoint, Salisbury, and Charlotte. Trains 71(03) and 78(03) were scheduled to make all stops.

04JUL26: The heat orders were continued into 07/04/26. The following trains were cancelled with alternate transportation secured: 72(04), 73(04), 75(04), 76(04), and 77(04).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(03)	Cancelled	
76(03)	Cancelled	
74(03)	Cancelled	
75(03)	Cancelled	
73(03)	Cancelled	
72(03)	Cancelled	
72(04)	Cancelled	
73(04)	Cancelled	
74(04)	Cancelled	
75(04)	Cancelled	
76(04)	Cancelled	
77(04)	Cancelled	

Maintenance of Way Highlights

VR Northern Subdivision - 7/3 - 7/4 - Firework Festivities

03JUL26: The VR Northern Subdivision has firework festivities on Friday, July 3rd resulting in the following adjustment to Amtrak's Ethan Allen Express Service:
-Train 291(03JUL) will terminate at the Ferrisburgh-Vergennes station (VRN) with no alternate transportation. The equipment will deadhead to Burlington at the conclusion of the festivities to turn for Train 290(04JUL).

WBS#: B.TR.100150.6711

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00580a 00000008154 UNCLASSIFIED 7/7/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trilink Bolt missing

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Train 2/422(03) Los Angeles, CA - Initial Terminal/ Servicing

04JUL26: Train 2/422(03) was delayed departing Los Angeles, CA due to a late shopping of a diner and sleeper car and then replacing a heating element on the griddle in the replaced diner car C/38042. Once the equipment was released from the yard, the train proceeded to the station to load 193 customers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(03)	1'00"	

Train 8(03) East of Everett, WA - Freight Train Interference

03JUL26: Train 8(03) was delayed at Gold Bar/MP1756.7 on the BNSF Scenic Subdivision, 26 miles east of Everett, WA meeting BN3888. Once route was clear, Train 8(03) proceeded east at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(03)	32"	

Train 717(03) West of Antioch-Pittsburg, CA - Police Related

03JUL26: Train 717(03) was delayed at Pittsburg/MP1157 on the BNSF Stockton Subdivision, 5 miles west of Antioch-Pittsburg, CA station, due to a hold on all tracks account of a track-side fire at MP1157.5 Once the hold was released, Train 717(03) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
717(03)	50"	

Train 21(02) Austin, TX - Police Related

04JUL26: Train 21(02), operating with engines 63/48, and 7 coaches was delayed holding at Austin, TX on the UP Austin subdivision, due to a vehicle on the tracks 10 miles south of Austin. Police responded with a tow truck to remove the vehicle and a track inspector arrived 90 minutes later to inspect the tracks.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(02)	51"	

Train 28(03) West of Wishram, WA - Police Related

03JUL26: Train 28(03) was delayed at North Dalles/MP93.0 on the BNSF Fallbridge Subdivision, 13 miles west of Wishram, WA, due to a hold on all tracks account of a track-side fire at MP99.3. Once an track inspector arrived and cleared the tracks for train passage by the area, Train 28(03) was able to proceed. They took an additional delay following freight unit BN7646 east towards Wishram, where they were able to be routed by them.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(03)	1'25"	

Train 8(03) Seattle, WA - Initial Terminal/ Servicing

03JUL26: Train 8(03) was delayed at Seattle/MP0.0 on the BNSF Scenic Subdivision, due to a late equipment change for a baggage car that had electrical problems.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(03)	1'34"	

Train 8/28(02) East of Glasgow, MT - Weather

03JUL26: Train 8/28(02) was delayed at Whatley/MP272.9 on the BNSF Glasgow Subdivision, 5 miles east of Glasgow, MT meeting BN7820 that was stopped account of high wind warning in the area. The train was further delayed for high wind warnings between MP262 and MP230 operating reduced speeds.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(02)	48"	High Winds
8/28(02)	30"	BN7820

Train 1340(03) West of Glenview, IL - Broken Rail

04JUL26: Train 1340(03), operating with engines 147/375, 3 coaches, was delayed 2.5 miles west of Glenview, IL, on CPKC C&M subdivision, due to a broken rail being repaired. Once the Rail was repaired, train 1340(03) was able to proceed.

Train 339(03) was also delayed due to the broken rail.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
339(03)	20"	
1340(03)	47"	

Train 712(03) East of Wasco, CA - Third Party Contractor Engine Failure

03JUL26: Train 712(03) operating with CC/8312, 7 cars, E/C2009 and 236 customers onboard, was delayed 2 miles east of Wasco, CA at MP911.4 on the BNSF Bakersfield Subdivision with loading issues on engine E/C2009. Head-end power(H.E.P.) remained active during this event. Crew worked with field management and TASI mechanical in order to troubleshoot the issue. They were briefly able to get the engine loading, and were about to depart when the issue returned. The crew continued to troubleshoot, attempting to restart the engine and reset the breakers which was unsuccessful. The decision was made to utilize Train 714(03) to couple and rescue the train into Bakersfield. An EMS was called to the scene to attend to a customer onboard that was hyperventilating. They were attended to, cleared and remained onboard the train. Once Train 714(03) arrived and coupled to 712(03), the combined train continued into Bakersfield.

Due to this disruption, Train 713(04) was cancelled in entirety with no alternate transportation provided. Misconnecting passengers to train 2/422(03) were provided alternate bus transportation from Bakersfield to Ontario to meet the train and those misconnecting to 794(03) were provided alternate bus transportation from LAX upon arrival. Train 703(03) was delayed departing Bakersfield, turning off the late arriving 714(03) after cutting away from the 712(03) equipment set.

WBS#: B.TR.100150.6852

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(04)	00"	Cancelled
714(03)	36"	
712(03)	2'49"	
703(03)	2'19"	ITD BFD- Equip turn from 714

Train 370(03) East of Hammond-Whiting, IN - Freight Train Interference

03JUL26: Train 370(03) 26-FP-00580 00000008154 "UNCLASSIFIED" 4 coaches, was delayed 13 miles east of Hammond-Whiting, IN, on NS Chicago_76CD subdivision, due to meeting NS4083 and Control Point 515 and then again at Hammond-Whiting, IN meeting 37E at Control Point 506.

Train	Delay	Comment
370(03)	52"	

Severe Weather in Michigan, Illinois, and Indiana

03JUL26: Due to severe weather in Michigan, Illinois, and Indiana, multiple trains were delayed operating through.

Train 355(03), operating with engines 4627/4617, 5 coaches, and 232 customers, was delayed holding at Albion, MI, on Amtrak Michigan Line, due to reported downed power lines east of Battle Creek, MI at milepost 112.97. The power company and maintainers responded to the scene. Once on the scene it was determined that there were no downed power lines. It was actually fiber optic cables that were hanging low over the tracks, approximately 19 feet above the rail. The maintainers on the scene were able to walk train 355(03) through the affected area.

Train 352(03) held east of Battle Creek, MI station, for an open route.

364(03) was delayed east of Chicago due to single tracking, resulting in multiple freight meets at control points 515, 506, 506. 364(03) was also delayed due to dark signals east of Battle Creek, MI. They operated at restricted speed through the affected area.

352(03) was delayed west of New Buffalo due to high winds speed restrictions, east of Battle Creek due to low hanging fiber optic cables, west of Ann Arbor, MI, due to signal issues requiring operation at restricted speed.

306(03) was delayed south of Chicago, IL due to holding at Control Brighton (milepost 5.1) due to high winds.

3(03) was delayed east of Naperville, IL due to highwinds.

40(01) was delayed west of South Bend, IN, due to heavy freight traffic as a result of single tracking due to storm related signal issues.

48/448(03) was delayed east of Chicago a halt of all train traffic due to severe storms and flash floods in the area. Once on the move train 48/448(03) struck a tree west of South Bend, IN which resulted in air hose separation. The crew was able to resolve and get back on the move.

Train	Delay	Comment
355(03)	1'19"	low hanging cables
355(03)	1'07"	high winds
48/448(03)	2'15"	weather related
48/448(03)	30	tree strike
352(03)	3'14"	
364(03)	1'44"	
306(03)	39"	
3(03)	32"	
40(01)	2'39"	
354(03)	1'02"	weather related traffic
354(03)	1'16"	weather related TOLs

Train 579(03) East of Santa Ana, CA - Vehicle on Tracks

03JUL26: At approximately 1:05PM-PT, Train 579(03), operating with CC/6907, 5 cars, E/C2122 and 299 customers onboard, came to a stop at MP175.7, 0.5 miles east of Santa Ana station on the SCRRA Metrolink Orange Subdivision in Orange county, after the engineer placed the train into emergency in order to avoid hitting a vehicle on the tracks. No contact with the vehicle was made, and there were no injuries reported to the passengers or crew. The vehicle appeared to had been in an accident and was disabled blocking both main tracks. Once the vehicle was removed and the tracks were released, Train 579(03) proceeded into Santa Ana, CA station. Train 580(03) was also delayed holding at Anaheim station, due to this.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
580(03)	29"	
579(03)	1'02"	
584(03)	13"	ITD LAX - Turn off 579

Train 714(03) Turlock-Denair, CA - Freight Train Interference

03JUL26: At approximately 3:02PM-PT, Train 714(03), operating with CC/8309-6 cars, E/C2103 was struck by an open freight car door from BNSF train 5215 that was in Denair siding, while operating into Turlock-Denair, CA/ MP 1079.5. The incident occurred on the BNSF Stockton subdivision, just outside of Turlock station in Stanislaus county. The impact resulted in damage to the engineer-side mirror on cab car 8309. There were no injuries reported to the crew or the 129 customers onboard. After the inspection was complete, Train 714(03) departed Turlock operating 16 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(03)	01"	

Train 5(30) East of Reno, NV - Freight Train Interference

03JUL26: Train 5(30) was delayed 7 miles east of Reno, NV on the UPRR Roseville subdivision due to being routed around on slower tracks via the siding, account of freight congestion in the area between MP247 and MP242.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(30)	41"	

Train 20(03) West of Meridian, MS - Freight Train Interference

04JUL26: NS reported that NS 339 had become disabled at MEI and required a power swap before the train could be handed off to CPKC. In addition, once NS 339 was removed from the main track, NS 355 needed to clear in order for a route to be established for trains 19(02) and 20(03). At that time, train 20(03) was estimated to arrive at MEI at 4:26 PM, while train 19(02) was estimated to arrive at 4:59 PM.

As a result of the freight traffic congestion, train 20(03) came to a stop south of MEI with an initial delay of approximately 30 minutes. The conductor reported that the freight train was exiting the yard and would be clear shortly, and authority was granted for 20(03) to proceed once the freight movement had cleared. Meanwhile, train 19(02) was stopped north of MEI and held for the same freight traffic, also accumulating an approximate 30-minute delay.

The delays continued to increase as train 20(03) remained stopped, reaching approximately 1 hour. Train 19(02) also continued to hold, with its delay growing to approximately 1 hour and 30 minutes. Once the freight traffic cleared, train 20(03) resumed movement and departed MEI at 6:00 PM CT, operating 4 hours and 28 minutes behind schedule. At that time, train 19(02) remained stopped and continued to hold for traffic, with an approximate delay of 1 hour and 30 minutes.

Train 21(02) Fort Worth, TX - Freight Train Interference

04JUL26: Train 21(02), 26-FQI-00580, 00000008154 engine UNCLASSIFIED 62/48, 7/7/2026, 164 coaches, and 164 customers, was delayed at Fort Worth, TX, on BNSF Ft. Worth subdivision, due to a UP freight train to clear Tower 55. The UP freight crew was dealing with a medical emergency. Once the freight crew resolved their issues they were able to proceed, clearing a route for train 21(02).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(02)	2'00"	

Train 8/28(02) West of Havre, MT - Freight Train Interference

03JUL26: Train 8/28(02) was delayed at Devon/MP 1046.1, 19 miles west of Havre, MT, on the BNSF Hi Line holding for freight. ONce BN7333 and BN7112 cleared route, Train 8/28(02) proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(02)	38"	

Train 516(03) South of Vancouver, BC - Debris

03JUL26: Train 516(03) was delayed starting at MP 141.1, 15 miles south of Vancouver, BC, on the CN New Westminster Subdivision due to debris on the tracks ahead blocking route. Once debris was cleared, Train 516(03) proceeded north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
516(03)	42"	

Train 2(01) East of Houston, TX - Tree Strike

03JUL26: At 12:50PM-CT, Train 2(01), E/15-E/201-7 Cars, struck a tree 7.8 miles east of Houston, TX (MP362.3), on the UPRR Beaumont Subdivision at MP380.5. There were no injuries reported to the crew or the 144 customers onboard. The crew conducted an inspection and reported no damage to the train. Once the inspection was completed, Train 2(01) resumed eastward movement at 1:03PM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(01)	14"	

Train 6(01) Galesburg, IL - Freight Train Interference

03JUL26: Train 6(01) was delayed into Galesburg, IL (MP162.6), on the BNSF Ottumwa Subdivision, routing via the Graham Cutoff through the Galesburg yard into the station. Additional delay incurred prior to entering the station waiting at A Plant (MP162.7) for BNSF 1416 to be pulled clear by a yard job after it became disabled. Train 4(01) was also delayed trailing Train 6(01) through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(01)	15"	Route through Yard
6(01)	35"	BN 1416
4(01)	30"	

Train 20(03) New Orleans, LA - Initial Terminal Delay

03JUL26: Train 20(03) was delayed starting 10.6 miles east of Pascagoula, MS (MP706.6), on the CSX NO&M Subdivision while following CSX M602-02 from MP696 to Mobile, AL (MP666.7). Additional delay was incurred before entering Mobile as both trains were required to wait for CSX local L685-03 to complete its work and clear the territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(03)	3'17"	

Train 24(03) East of Pascagoula, MS - Freight Train Interference

03JUL26: Train 24(03) was delayed starting 10.6 miles east of Pascagoula, MS (MP706.6), on the CSX NO&M Subdivision while following CSX M602-02 from MP696 to Mobile, AL (MP666.7). Additional delay was incurred before entering Mobile as both trains were required to wait for CSX local L685-03 to complete its work and clear the territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(03)	1'54"	

Train 503(03) Kelso-Longview, WA - Engine Failure

03JUL26: Train 503(03), CC/90251-3 cars- E/WS1407-E/WS1406, was delayed departing Kelso-Longview, WA on the BNSF Seattle Subdivision due to the parking brake being stuck on trail unit E/WS1406. The crew contacted mechanical to troubleshoot. Once crew cut out the parking brake and performed air test, they departed Kelso-Longview.

Train 503(03) was further delayed at MP 126.4 due to actuating a wayside detector at MP 113.5. The crew stopped to inspect to ensure the brakes were completely released on the E/WS1406.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(03)	28"	
503(03)	12"	Inspect equipment

Train 351(03) West of Albion, MI - Medical Emergency

03JUL26: Train 351(03) stopped 20.3 miles west of Albion, MI (MP95.8), on the Michigan DOT Michigan Line while waiting for emergency services to respond to an onboard medical emergency at MP116.1. The customer was removed from the train for further evaluation. Once the response was complete, Train 351(03) resumed westward movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
351(03)	50"	

Train 300(03) Bloomington-Normal, IL - Freight Train Interference

03JUL26: Union Pacific 26-FOI-00580 00000008154-164MQ-03 (UP9614) 7/7/2026 disabled 14 miles north of Bloomington-Normal, IL (MP124.0), on the UPRR Joliet Subdivision at Lexington (MP110). A carman responded to assist the crew and ultimately determined that one of the cars in the consist had to be set out. A local yard job responded to assist with the setout and remove the bad-order car from the main line. Additional delay was incurred while waiting for police to remove a trespasser who was found sleeping in UP9614.

During this time, Train 300(03) held at Bloomington-Normal station and then moved up to Normal (MP121.4) to wait for open track. Train 302(03) held at Bloomington-Normal station, while Train 301(03) held behind UP9614 at MP107.9. Once UP9614 was back together, Train 301(03) followed UP9614 until it was able to get by at Bloomington-Normal. After both southbound trains were cleared, Trains 300(03) and 302(03) were released to continue north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
301(03)	47"	
300(03)	2'58"	
302(03)	36"	

Train 371(03) West of Holland, MI - Tree Strike

03JUL26: At 7:15AM-ET, Train 371(03), ID4628-4 Cars, struck a tree at MP48.2 on the CSX Grand Rapids Subdivision, 22.8 miles west of Holland, MI (MP25.4). The impact caused the lead locomotive to shut down, resulting in an initial loss of Head End Power (HEP). The locomotive was restarted and HEP was restored at 7:35AM-ET; however, the crew continued troubleshooting power-related issues involving car ID4129. Damage from the strike was limited to a bent plow. No injuries were reported to the crew or the 184 customers onboard.

At 8:20AM-ET, Train 371(03) started to move but stopped again at MP48.6 to inspect a possible flat spot on car ID4129. The suspected flat spot was inspected and cleared for movement; however, power could not be restored to car ID4129. At 9:09AM-ET, Train 371(03) resumed movement to Chicago. One bus was secured at St. Joseph, MI (MP87.9) for any customers wishing to detrain and continue to Chicago by bus. No customers opted for this option and remained onboard as the train continued to Chicago.

WBS#: B.TR.100150.6849

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
371(03)	2'04"	

Train 2/422(01) West of San Antonio, TX - Deer Strike

03JUL26: At 4:29AM-CT, Train 2/422(01), E/15-E/201-9 Cars, struck a deer at MP 258.5 on the UPRR Del Rio Subdivision, 49 miles west of San Antonio, TX (MP 209.5). There were no injuries reported to the crew or the 252 customers onboard. The impact caused an air hose to hang low and require attention by the crew. After the issue was corrected, Train 2/422(01) resumed its eastward movement at 4:36AM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(01)	03"	

Train 50(02) South of Lafayette, IN - Freight Train Interference

03JUL26: Train 50(02) was delayed between Lafayette, IN (MP120.1) and Crawfordsville, IN (MP147.5), on the CSX Monon Subdivision, following CSX L413.

Train 6(02) West of Salt Lake City, UT - Passenger Train Interference

03JUL26: Train 6(02) was delayed at MP 85.6, 1.8 miles west of Salt Lake City, UT, on the UPRR Shafter Subdivision due to meet Train 5(01). Once Train 5(01) cleared route, Train 6(02) proceeded east.

Train	Delay	Comment
6(02)	46"	

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated	JAN
58(27JUN-06JUL)	Cancelled	
59(27JUN-06JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on MP 588.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05JUL)	00"	BYPASS PSN
1 (01, 04JUL) / 421 (03JUL)	00"	BYPASS PSN

Maintenance of Way Highlights

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
59 (26)	JAN	62		Gouged wheels

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(12)	STL	1	Carried passenger to ALN to wait for Train 21	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00580

00000008154

"UNCLASSIFIED"

7/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
240 (03)	ALB	Car 82567 shopped due HVAC issues. no impact to customers.	0	0	48192
48 (03)	CHI	CAR 25001 (IN THE 448 SECTION OF THE CONSIST) SHOPPED FOR HVAC. OVERCAPACITY COINDITIONS EXIST. PLEASE NOTIFY PAX	Resolved	0	25001
562 (03)	LAX	Operating with 90215 in consist will not be able to accommodate passengers with bike reservation. Will need to reaccommodate in passengers impacted by this change.	Pax notified	1	90215
580 (03)	LAX	Operating with 90215 in consist will not be able to accommodate passengers with bike reservation. Will need to reaccommodate in passengers impacted by this change.	Pax notified	2	90215
4 (02)	LAX	Operating with sleeper in lieu of the bag coach. Lower Level inventory has been increased.	No impact	0	34101
101 (03)	NYP	Operating with business class in lieu of coach.	No impact	0	81514
291 (03)	NYP	Car 82567 shopped due to HVAC issues. Overcapacity, customer service notified.	0	0	48192
573 (03)	SAN	Operating with 90215 in consist will not be able to accommodate passengers with bike reservation. Will need to reaccommodate in passengers impacted by this change.	Pax notified	1	90215
591 (03)	SAN	Operating with 90215 in consist will not be able to accommodate passengers with bike reservation. No passenger impacted by this change.	No impact	0	90215
194 (03)	WAS	Due to using a biz car in lieu of a coach, we're overcapacity at WIL -12. Please notify those passengers.	0	0	81530
126 (03)	WAS	Reported byd inline due to bad toilets, byd water tanks and needing to be dumped. overcapacity by -6. customer service notified.			81502

Reverse Consists

Train Number	Station	Reason	
		26-FOI-00580	00000008154 "UNCLASSIFIED" 7/7/2026
197 (02)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
195 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front	
87 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front	
109 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front	
153 (03)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
155 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front	
127 (03)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
150 (03)	PHL	Consist reversed Business class seat orientation may have changed At Front	
144 (03)	PHL	Consist reversed Business class seat orientation may have changed At Rear	
103 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front	
128 (04)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 128(04)**	
158 (04)	NFK	Consist reversed Business class seat orientation may have changed At Front	
135 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front	
101 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front	