



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, July 29, 2026

Rules: 4-41



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/28/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	54	83.1%	8,619	1,287	85.1%	89,973	12,408	86.2%
Central Division	86.0%	55	8	85.5%	1,559	158	89.9%	17,250	1,549	91.0%
East Division	82.0%	176	30	83.0%	4,555	735	83.9%	47,151	7,348	84.4%
West Division	86.0%	89	16	82.0%	2,505	394	84.3%	25,572	3,511	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00625 00000008485 UNCLASSIFIED 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	99,683	31,999	68%	3,057,891	1,060,226	65%	30,005,215	7,534,512	75%
Northeast Corridor	81%	43,552	9,370	78%	1,313,773	434,747	67%	13,157,554	3,217,940	76%
Acela	83%	11,292	3,686	67%	290,067	93,324	68%	2,626,832	696,001	74%
Northeast Regional	79%	32,260	5,684	82%	1,023,706	341,423	67%	10,530,722	2,521,939	76%
Richmond / Newport News / Norfolk	77%	8,956	2,645	70%	318,775	136,628	57%	3,269,503	950,249	71%
Springfield Shuttles	89%	694	173	75%	18,573	5,651	70%	186,607	29,865	84%
Roanoke	79%	3,703	508	86%	99,471	38,722	61%	992,531	214,007	78%
On Spine Northeast Regional	80%	18,907	2,358	88%	586,887	160,422	73%	6,082,081	1,327,818	78%
State Supported	80%	44,804	15,311	66%	1,375,091	395,608	71%	13,161,139	2,757,972	79%
Borealis	80%	546	489	10%	16,805	4,268	75%	167,775	34,714	79%
Capitol Corridor	90%	4,045	1,090	73%	104,687	16,326	84%	1,105,906	145,522	87%
Carolinian	70%	426	66	85%	30,925	16,965	45%	340,899	132,871	61%
Cascades	75%	2,529	672	73%	87,453	23,423	73%	775,097	211,983	73%
Downeaster	82%	1,897	182	90%	56,103	9,727	83%	453,601	55,197	88%
Empire	78%	5,909	3,087	48%	175,651	62,266	65%	1,629,656	376,683	77%
Adirondack	72%	378	270	29%	12,471	4,884	61%	98,904	30,368	69%
Ethan Allen Express	70%	532	426	20%	16,585	11,853	29%	167,550	59,460	65%
Maple Leaf	70%	829	398	52%	24,126	9,836	59%	198,945	76,623	61%
New York - Albany	85%	2,786	1,261	55%	78,752	18,740	76%	755,917	122,640	84%
New York - Niagara Falls	75%	1,384	732	47%	39,302	14,536	63%	400,761	84,315	79%
Berkshire Flyer	60%	0	0	-	4,415	2,417	45%	7,579	3,277	57%
Gold Runner	73%	2,330	1,350	42%	74,002	33,227	55%	747,622	265,325	65%
Heartland Flyer	70%	217	121	44%	8,019	4,307	46%	63,724	24,800	61%
Hiawatha	90%	1,535	686	55%	57,224	6,193	89%	514,918	56,741	89%
Illinois	78%	2,242	885	61%	75,294	25,462	66%	737,449	201,506	73%
Carl Sandburg / Illinois Zephyr	85%	449	129	71%	13,775	5,331	61%	123,329	33,137	73%
Illini / Saluki	85%	407	173	57%	23,919	7,540	68%	257,581	61,567	76%
Lincoln Service	70%	1,386	583	58%	37,600	12,591	67%	356,539	106,802	70%
Keystone	92%	8,955	846	91%	210,907	27,733	87%	2,267,984	237,668	90%
Lincoln / Missouri	70%	393	217	45%	21,240	12,880	39%	229,759	116,696	49%
Mardi Gras Service	80%	438	74	83%	10,847	4,362	60%	121,795	26,823	78%
Michigan	70%	2,689	1,314	51%	69,807	25,254	64%	589,554	190,209	68%
Blue Water	70%	840	587	30%	17,421	9,587	45%	137,647	54,921	60%
Pere Marquette	85%	120	0	100%	9,631	1,572	84%	77,203	14,902	81%
Wolverine	70%	1,729	727	58%	42,755	14,095	67%	374,704	120,386	68%
Missouri	80%	0	0	-	5,756	2,553	56%	64,992	15,793	76%
Pacific Surfliner	85%	7,771	3,359	57%	286,834	88,559	69%	2,369,358	415,721	82%
Pennsylvanian	80%	750	411	45%	24,345	8,515	65%	263,055	50,674	81%
Piedmont	80%	721	101	86%	23,540	9,182	61%	336,925	87,736	74%
Vermont	75%	1,411	361	74%	35,652	14,406	60%	381,070	111,310	71%
Long Distance	70%	11,327	7,318	35%	369,027	229,871	38%	3,647,255	1,556,137	57%
Auto Train	70%	813	396	51%	23,089	9,522	59%	231,933	80,350	65%
California Zephyr	70%	386	297	23%	28,957	19,511	33%	289,020	104,808	64%
Cardinal	70%	0	0	-	7,037	4,681	33%	70,711	34,923	51%
City Of New Orleans	75%	651	605	7%	11,657	6,960	40%	189,021	56,577	70%
Coast Starlight	70%	1,199	310	74%	35,900	14,427	60%	340,664	118,879	65%
Crescent	70%	813	95	88%	26,116	13,307	49%	276,609	85,399	69%
Empire Builder	70%	847	835	1%	34,255	22,417	35%	287,316	141,169	51%
Floridian	60%	1,752	1,311	25%	43,635	39,563	9%	473,800	323,206	32%
Lake Shore Ltd	73%	1,180	678	43%	33,829	12,903	62%	285,466	84,513	70%
Palmetto	70%	447	167	63%	25,435	15,115	41%	273,208	81,213	70%
Silver Meteor	70%	906	509	44%	29,768	24,783	17%	302,149	134,935	55%
Southwest Chief	60%	1,038	1,010	3%	28,579	21,730	24%	247,229	160,142	35%
Sunset Ltd	70%	327	327	0%	8,780	5,287	40%	87,165	31,968	63%
Texas Eagle	70%	968	778	20%	31,990	19,665	39%	292,964	118,055	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00025 00000000485 "UNCLASSIFIED" 8/7/2026

Train Index Dates Through July 28, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	200,139	2,984,463	671	1,767,671	31,616,697	559

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	11,621	886,456	131	85,011	9,095,933	93
INFRASTRUCTURE PLANNED	135	15,390	886,456	174	94,290	9,095,933	104
FLEET RELIABILITY	90	29,002	2,984,463	97	282,252	31,616,697	89
TRAIN OPERATIONS	424	144,126	2,984,463	483	1,306,118	31,616,697	413

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/28/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	54	83.1%	8,619	1,287	85.1%	89,973	12,408	86.2%
Central Division	86.0%	55	8	85.5%	1,559	158	89.9%	17,250	1,549	91.0%
East Division	82.0%	176	30	83.0%	4,555	735	83.9%	47,151	7,348	84.4%
West Division	86.0%	89	16	82.0%	2,505	394	84.3%	25,572	3,511	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/28/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	54	83.1%	8,619	1,287	85.1%	89,973	12,408	86.2%
Central Division	86.0%	55	8	85.5%	1,559	158	89.9%	17,250	1,549	91.0%
CDL	95.0%	2	1	50.0%	53	6	88.7%	570	24	95.8%
CHI	86.0%	26	3	88.5%	731	89	87.8%	7,968	952	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	1	0	100.0%	2	0	100.0%	60	3	95.0%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	1	0.0%	28	2	92.9%	324	36	88.9%
GBB	-	-	-	-	13	11	15.4%	13	11	15.4%
GRR	95.5%	-	-	-	26	0	100.0%	285	8	97.2%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	-	-	-	43	3	93.0%	581	43	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	2	66.7%	164	14	91.5%	1,762	111	93.7%
MOE	97.5%	2	0	100.0%	54	1	98.1%	599	9	98.5%
MSP	96.5%	1	1	0.0%	28	1	96.4%	294	6	98.0%
NOL	94.5%	4	0	100.0%	110	7	93.6%	1,260	60	95.2%
OKC	97.0%	1	0	100.0%	28	0	100.0%	295	6	98.0%
PNT	88.0%	3	0	100.0%	75	6	92.0%	778	64	91.8%
PTH	93.0%	1	0	100.0%	28	1	96.4%	289	11	96.2%
QCY	91.0%	2	0	100.0%	40	3	92.5%	571	43	92.5%
SAS	90.5%	1	0	100.0%	29	5	82.8%	298	32	89.3%
STL	89.0%	4	0	100.0%	106	8	92.5%	1,163	98	91.6%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	30	83.0%	4,555	735	83.9%	47,151	7,348	84.4%
ALB	88.5%	8	0	100.0%	216	8	96.3%	2,230	169	92.4%
ATL	-	-	-	-	1	1	0.0%	36	6	83.3%
BON	87.5%	5	1	80.0%	139	17	87.8%	1,451	157	89.2%
BOS	85.5%	18	6	66.7%	471	38	91.9%	5,111	600	88.3%
BRK	92.5%	5	0	100.0%	136	18	86.8%	1,437	102	92.9%
BTN	82.0%	1	0	100.0%	28	1	96.4%	287	40	86.1%
CLT	91.5%	5	0	100.0%	121	18	85.1%	1,462	150	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	56	7	87.5%	587	57	90.3%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	13	1	92.3%	302	41	86.4%	3,325	547	83.5%
HFD	-	2	0	100.0%	38	5	86.8%	185	13	93.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	1	0.0%	28	4	85.7%	297	38	87.2%
MIA	89.5%	2	0	100.0%	55	8	85.5%	594	68	88.6%
MTR	79.0%	1	0	100.0%	28	5	82.1%	284	51	82.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/28/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	54	83.1%	8,619	1,287	85.1%	89,973	12,408	86.2%
East Division	82.0%	176	30	83.0%	4,555	735	83.9%	47,151	7,348	84.4%
NFK	84.5%	2	0	100.0%	56	14	75.0%	677	123	81.8%
NFL	93.5%	2	2	0.0%	56	6	89.3%	606	28	95.4%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	0	100.0%	133	30	77.4%	1,539	253	83.6%
NPN	93.0%	2	0	100.0%	54	6	88.9%	567	41	92.8%
NYP	75.5%	50	13	74.0%	1,283	286	77.7%	12,337	2,747	77.7%
PGH	93.0%	1	0	100.0%	27	3	88.9%	298	22	92.6%
PHL	48.0%	5	1	80.0%	135	56	58.5%	1,535	733	52.2%
PIT	76.0%	-	-	-	8	6	25.0%	14	11	21.4%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	0	100.0%	89	7	92.1%	1,146	48	95.8%
RNK	83.5%	2	0	100.0%	56	9	83.9%	590	86	85.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	25	1	96.0%	284	5	98.2%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	26	0	100.0%	294	10	96.6%
SFA	88.0%	1	0	100.0%	28	4	85.7%	297	41	86.2%
SPG	92.5%	5	0	100.0%	140	12	91.4%	1,792	104	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	27	3	88.9%	286	59	79.4%
WAS	84.0%	31	4	87.1%	784	116	85.2%	7,380	957	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	89	16	82.0%	2,505	394	84.3%	25,572	3,511	86.3%
ARN	92.0%	1	0	100.0%	28	7	75.0%	299	26	91.3%
BFD	79.0%	6	0	100.0%	190	45	76.3%	1,876	386	79.4%
EMY	72.0%	1	0	100.0%	28	9	67.9%	315	94	70.2%
EUG	86.5%	2	0	100.0%	56	3	94.6%	592	55	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	3	2	33.3%	4	3	25.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	84	23	72.6%	900	137	84.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	292	42	85.6%	2,967	318	89.3%
MCD	-	-	-	-	7	6	14.3%	15	13	13.3%
OKJ	74.5%	13	5	61.5%	323	87	73.1%	3,222	823	74.5%
PDX	86.0%	4	0	100.0%	137	12	91.2%	1,474	178	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	3	81.3%	414	49	88.2%	4,219	459	89.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/28/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/28/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	54	83.1%	8,619	1,287	85.1%	89,973	12,408	86.2%
West Division	86.0%	89	16	82.0%	2,505	394	84.3%	25,572	3,511	86.3%
SAN	90.5%	13	2	84.6%	361	46	87.3%	3,605	340	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	7	1	85.7%	220	31	85.9%	2,362	341	85.6%
SJC	89.0%	7	1	85.7%	196	25	87.2%	2,103	207	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	84	4	95.2%	663	64	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	1	0.0%	27	3	88.9%	293	23	92.2%
VAC	97.0%	2	0	100.0%	55	0	100.0%	585	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	137	12	5	58.3%	127	30	76.4%	11	4	63.6%	123	24	80.5%
3	185	28	5	82.1%	299	59	80.3%	28	16	42.9%	297	133	55.2%
4	82	28	4	85.7%	298	46	84.6%	28	18	35.7%	298	197	33.9%
5	61	28	5	82.1%	297	48	83.8%	27	22	18.5%	293	85	71.0%
6	65	28	9	67.9%	296	85	71.3%	29	20	31.0%	297	102	65.7%
7	262	28	6	78.6%	288	41	85.8%	28	12	57.1%	281	73	74.0%
8	290	28	16	42.9%	288	127	55.9%	28	23	17.9%	287	172	40.1%
11		28	5	82.1%	299	55	81.6%	28	6	78.6%	293	60	79.5%
14		28	6	78.6%	300	47	84.3%	28	8	71.4%	298	91	69.5%
19		28	10	64.3%	298	75	74.8%	27	12	55.6%	295	71	75.9%
20		28	5	82.1%	298	23	92.3%	28	11	60.7%	298	58	80.5%
21	35	28	2	92.9%	295	24	91.9%	28	18	35.7%	294	80	72.8%
22	80	28	5	82.1%	296	30	89.9%	28	18	35.7%	294	80	72.8%
23		27	1	96.3%	300	6	98.0%	27	14	48.1%	298	83	72.1%
24		27	2	92.6%	300	16	94.7%	27	12	55.6%	299	55	81.6%
25		27	0	100.0%	299	3	99.0%	27	13	51.9%	297	82	72.4%
26	57	27	0	100.0%	299	5	98.3%	27	7	74.1%	297	59	80.1%
40	137	27	3	88.9%	293	41	86.0%	26	21	19.2%	291	153	47.4%
41	41	26	10	61.5%	292	112	61.6%	26	25	3.8%	290	221	23.8%
42	24	28	4	85.7%	300	24	92.0%	28	9	67.9%	298	51	82.9%
43		28	1	96.4%	299	42	86.0%	27	14	48.1%	298	70	76.5%
48		28	4	85.7%	298	57	80.9%	28	4	85.7%	298	42	85.9%
49	34	28	7	75.0%	298	74	75.2%	28	9	67.9%	298	61	79.5%
52	215	28	4	85.7%	297	41	86.2%	28	11	60.7%	296	72	75.7%
53		28	4	85.7%	297	38	87.2%	28	9	67.9%	296	94	68.2%
55		19	1	94.7%	187	7	96.3%	19	4	78.9%	184	38	79.3%
56		19	1	94.7%	188	23	87.8%	18	7	61.1%	184	33	82.1%
59	73	15	4	73.3%	273	32	88.3%	14	10	28.6%	269	56	79.2%
63	37	28	13	53.6%	301	130	56.8%	26	23	11.5%	295	163	44.7%
64	49	28	4	85.7%	299	67	77.6%	28	18	35.7%	299	109	63.5%
66		28	7	75.0%	298	61	79.5%	26	4	84.6%	294	53	82.0%
67		19	2	89.5%	206	13	93.7%	18	4	77.8%	205	35	82.9%
68	80	28	5	82.1%	301	60	80.1%	28	14	50.0%	301	117	61.1%
69		28	7	75.0%	288	66	77.1%	28	10	64.3%	284	42	85.2%
71		28	0	100.0%	296	3	99.0%	28	14	50.0%	295	80	72.9%
72		24	2	91.7%	292	31	89.4%	24	6	75.0%	291	61	79.0%
73		23	2	91.3%	295	18	93.9%	23	14	39.1%	293	140	52.2%
74		23	3	87.0%	293	33	88.7%	23	13	43.5%	291	107	63.2%
75		19	2	89.5%	289	16	94.5%	18	10	44.4%	283	135	52.3%
76	71	19	3	84.2%	289	29	90.0%	18	11	38.9%	280	115	58.9%
77		22	3	86.4%	291	20	93.1%	22	14	36.4%	289	122	57.8%
78	23	27	5	81.5%	295	25	91.5%	27	13	51.9%	294	63	78.6%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79	92	28	1	96.4%	298	56	81.2%	28	16	42.9%	297	100	66.3%
80		28	5	82.1%	298	33	88.9%	27	13	51.9%	295	62	79.0%
84		16	2	87.5%	178	13	92.7%	16	7	56.3%	176	42	76.1%
85	17	19	0	100.0%	189	16	91.5%	19	9	52.6%	189	70	63.0%
86	125	19	1	94.7%	189	15	92.1%	19	13	31.6%	188	113	39.9%
89		28	6	78.6%	296	64	78.4%	28	15	46.4%	294	85	71.1%
90	52	28	0	100.0%	296	10	96.6%	28	13	53.6%	295	50	83.1%
93	109	19	1	94.7%	188	19	89.9%	19	9	52.6%	187	46	75.4%
94	21	19	5	73.7%	219	55	74.9%	19	13	31.6%	217	82	62.2%
95		19	1	94.7%	188	4	97.9%	19	9	52.6%	188	68	63.8%
97		28	25	10.7%	298	198	33.6%	28	21	25.0%	296	97	67.2%
98	99	28	5	82.1%	298	26	91.3%	28	26	7.1%	296	106	64.2%
110		19	5	73.7%	185	101	45.4%	19	2	89.5%	182	18	90.1%
111		19	3	84.2%	179	35	80.4%	19	1	94.7%	177	21	88.1%
112		19	1	94.7%	179	17	90.5%	19	2	89.5%	178	19	89.3%
113		19	2	89.5%	110	24	78.2%	19	2	89.5%	109	13	88.1%
119		16	2	87.5%	176	45	74.4%	16	2	87.5%	174	22	87.4%
125		19	2	89.5%	189	10	94.7%	19	7	63.2%	189	73	61.4%
129		19	3	84.2%	188	47	75.0%	19	4	78.9%	188	27	85.6%
130		19	2	89.5%	179	18	89.9%	19	1	94.7%	177	16	91.0%
131		19	6	68.4%	181	53	70.7%	19	6	68.4%	181	35	80.7%
134		19	4	78.9%	189	25	86.8%	19	8	57.9%	188	34	81.9%
136		19	4	78.9%	189	24	87.3%	19	7	63.2%	187	24	87.2%
137		19	4	78.9%	186	34	81.7%	19	6	68.4%	186	58	68.8%
138	28	19	4	78.9%	189	39	79.4%	19	7	63.2%	188	34	81.9%
141		19	0	100.0%	188	3	98.4%	19	4	78.9%	187	32	82.9%
148	26	19	2	89.5%	188	19	89.9%	19	6	68.4%	186	36	80.6%
151		28	9	67.9%	297	95	68.0%	28	11	60.7%	296	95	67.9%
170		19	0	100.0%	184	12	93.5%	19	0	100.0%	183	29	84.2%
171		19	0	100.0%	189	10	94.7%	19	13	31.6%	189	74	60.8%
172	203	19	0	100.0%	188	14	92.6%	19	5	73.7%	186	60	67.7%
173		16	1	93.8%	181	24	86.7%	16	4	75.0%	180	77	57.2%
174	82	19	0	100.0%	189	20	89.4%	19	10	47.4%	189	48	74.6%
175	215	19	1	94.7%	189	22	88.4%	19	6	68.4%	189	61	67.7%
176		16	1	93.8%	181	15	91.7%	16	6	62.5%	179	21	88.3%
177	247	19	2	89.5%	189	26	86.2%	19	2	89.5%	189	46	75.7%
178		19	1	94.7%	189	25	86.8%	19	6	68.4%	187	29	84.5%
179	23	19	4	78.9%	189	23	87.8%	19	10	47.4%	188	68	63.8%
181		19	4	78.9%	185	58	68.6%	19	2	89.5%	183	14	92.3%
182		19	2	89.5%	179	30	83.2%	19	5	73.7%	177	21	88.1%
183		19	7	63.2%	188	55	70.7%	18	5	72.2%	185	38	79.5%
184		19	4	78.9%	189	33	82.5%	19	4	78.9%	188	27	85.6%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
185		19	1	94.7%	189	37	80.4%	19	3	84.2%	189	14	92.6%
186	18	19	3	84.2%	188	20	89.4%	19	10	47.4%	187	50	73.3%
190	36	19	5	73.7%	188	67	64.4%	19	5	73.7%	187	42	77.5%
192		19	5	73.7%	186	24	87.1%	19	3	84.2%	186	17	90.9%
193	29	16	5	68.8%	185	76	58.9%	16	7	56.3%	184	87	52.7%
196		16	1	93.8%	185	19	89.7%	16	0	100.0%	184	15	91.8%
197	23	19	7	63.2%	189	75	60.3%	19	13	31.6%	189	66	65.1%
198		19	3	84.2%	121	17	86.0%	19	4	78.9%	120	20	83.3%
230		28	0	100.0%	135	4	97.0%	28	0	100.0%	135	6	95.6%
232		28	0	100.0%	301	11	96.3%	28	2	92.9%	301	19	93.7%
233	29	20	4	80.0%	271	60	77.9%	20	14	30.0%	271	87	67.9%
234		28	1	96.4%	301	20	93.4%	28	0	100.0%	301	24	92.0%
235	57	28	6	78.6%	225	33	85.3%	28	11	60.7%	225	52	76.9%
236		28	2	92.9%	285	9	96.8%	28	3	89.3%	285	39	86.3%
237		28	4	85.7%	299	56	81.3%	28	7	75.0%	297	50	83.2%
238	33	28	0	100.0%	225	19	91.6%	28	4	85.7%	224	18	92.0%
239	19	28	5	82.1%	300	77	74.3%	28	7	75.0%	299	37	87.6%
240	21	28	0	100.0%	300	20	93.3%	28	15	46.4%	298	59	80.2%
241		28	5	82.1%	301	73	75.7%	28	3	89.3%	301	69	77.1%
243	59	28	9	67.9%	237	64	73.0%	28	6	78.6%	236	32	86.4%
244	33	20	2	90.0%	271	12	95.6%	20	10	50.0%	271	48	82.3%
245		28	6	78.6%	182	33	81.9%	28	3	89.3%	181	20	89.0%
280	53	28	3	89.3%	301	14	95.3%	28	9	67.9%	301	59	80.4%
281		28	6	78.6%	301	35	88.4%	28	9	67.9%	301	56	81.4%
283		28	9	67.9%	301	73	75.7%	28	8	71.4%	301	60	80.1%
284		28	3	89.3%	301	13	95.7%	28	12	57.1%	299	54	81.9%
290	18	28	1	96.4%	301	49	83.7%	28	22	21.4%	299	113	62.2%
291		28	16	42.9%	300	91	69.7%	28	15	46.4%	298	73	75.5%
300	25	28	1	96.4%	285	20	93.0%	28	11	60.7%	283	67	76.3%
301		27	1	96.3%	298	10	96.6%	26	5	80.8%	294	55	81.3%
302		22	2	90.9%	280	33	88.2%	22	5	77.3%	276	77	72.1%
305		22	0	100.0%	283	28	90.1%	22	11	50.0%	279	113	59.5%
306	41	27	0	100.0%	296	15	94.9%	27	10	63.0%	295	81	72.5%
307		28	3	89.3%	289	38	86.9%	28	11	60.7%	286	81	71.7%
318		27	5	81.5%	299	31	89.6%	27	18	33.3%	296	142	52.0%
319	21	27	3	88.9%	300	20	93.3%	24	18	25.0%	295	163	44.7%
329	44	20	0	100.0%	212	8	96.2%	20	1	95.0%	212	14	93.4%
330	62	24	0	100.0%	255	4	98.4%	24	2	91.7%	255	15	94.1%
331	50	28	4	85.7%	301	33	89.0%	28	4	85.7%	301	44	85.4%
332		28	3	89.3%	301	17	94.4%	28	4	85.7%	301	43	85.7%
334		28	1	96.4%	301	10	96.7%	28	3	89.3%	300	39	87.0%
335		28	2	92.9%	301	32	89.4%	28	7	75.0%	299	50	83.3%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
336		28	2	92.9%	301	10	96.7%	28	2	92.9%	299	27	91.0%
337		28	1	96.4%	301	18	94.0%	28	3	89.3%	297	36	87.9%
338		28	5	82.1%	301	46	84.7%	28	10	64.3%	299	91	69.6%
339	62	28	4	85.7%	301	50	83.4%	28	5	82.1%	301	53	82.4%
342	47	28	3	89.3%	301	24	92.0%	28	6	78.6%	299	59	80.3%
350	42	24	1	95.8%	278	18	93.5%	22	12	45.5%	271	148	45.4%
351		28	2	92.9%	284	27	90.5%	28	10	64.3%	282	78	72.3%
352		28	1	96.4%	268	21	92.2%	28	9	67.9%	262	80	69.5%
353		24	1	95.8%	239	13	94.6%	24	3	87.5%	233	38	83.7%
354	24	28	7	75.0%	282	35	87.6%	25	11	56.0%	275	100	63.6%
355		24	4	83.3%	291	31	89.3%	24	12	50.0%	284	97	65.8%
364		28	4	85.7%	290	64	77.9%	28	16	42.9%	284	106	62.7%
365	17	28	1	96.4%	289	11	96.2%	28	16	42.9%	287	108	62.4%
370		28	2	92.9%	292	35	88.0%	25	3	88.0%	282	68	75.9%
380		27	3	88.9%	286	27	90.6%	27	12	55.6%	286	61	78.7%
381		26	1	96.2%	299	12	96.0%	26	10	61.5%	298	58	80.5%
382	26	26	11	57.7%	298	27	90.9%	26	14	46.2%	298	98	67.1%
383	18	28	1	96.4%	290	26	91.0%	27	15	44.4%	287	120	58.2%
390	32	28	1	96.4%	283	18	93.6%	28	10	64.3%	282	73	74.1%
391	Cncld	26	3	88.5%	284	11	96.1%	25	10	60.0%	280	75	73.2%
392	Cncld	25	5	80.0%	297	10	96.6%	24	11	54.2%	294	89	69.7%
393		28	1	96.4%	301	17	94.4%	28	13	53.6%	298	90	69.8%
417		19	6	68.4%	199	44	77.9%	19	5	73.7%	190	22	88.4%
425		19	0	100.0%	201	6	97.0%	19	0	100.0%	201	7	96.5%
448	61	28	6	78.6%	231	44	81.0%	28	11	60.7%	229	79	65.5%
449		28	2	92.9%	229	32	86.0%	28	6	78.6%	229	42	81.7%
470		19	3	84.2%	212	37	82.5%	19	1	94.7%	206	24	88.3%
471		19	4	78.9%	202	10	95.0%	19	3	84.2%	202	5	97.5%
473		19	1	94.7%	208	14	93.3%	19	1	94.7%	205	9	95.6%
474	20	22	12	45.5%	206	63	69.4%	19	16	15.8%	191	63	67.0%
475		19	1	94.7%	206	6	97.1%	19	5	73.7%	206	15	92.7%
478		19	5	73.7%	200	32	84.0%	19	7	63.2%	198	27	86.4%
479		19	5	73.7%	207	34	83.6%	19	9	52.6%	205	31	84.9%
486		19	3	84.2%	211	31	85.3%	19	7	63.2%	205	57	72.2%
494		20	6	70.0%	213	41	80.8%	19	13	31.6%	206	57	72.3%
495		18	1	94.4%	196	4	98.0%	18	0	100.0%	194	3	98.5%
500		28	1	96.4%	292	16	94.5%	27	3	88.9%	289	35	87.9%
502		28	3	89.3%	299	18	94.0%	27	1	96.3%	295	57	80.7%
503		28	2	92.9%	297	27	90.9%	27	13	51.9%	290	87	70.0%
504		28	1	96.4%	301	18	94.0%	28	7	75.0%	299	89	70.2%
505		28	3	89.3%	299	39	87.0%	27	9	66.7%	294	82	72.1%
506		28	3	89.3%	296	41	86.1%	27	4	85.2%	290	45	84.5%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507	16	28	2	92.9%	301	36	88.0%	28	11	60.7%	301	99	67.1%
508		28	2	92.9%	296	41	86.1%	27	4	85.2%	292	66	77.4%
509		28	2	92.9%	298	14	95.3%	28	3	89.3%	298	66	77.9%
511	80	28	3	89.3%	293	24	91.8%	28	4	85.7%	292	49	83.2%
516	23	27	1	96.3%	292	28	90.4%	27	9	66.7%	291	132	54.6%
517		28	0	100.0%	301	8	97.3%	28	17	39.3%	297	125	57.9%
518	23	28	1	96.4%	301	36	88.0%	28	21	25.0%	299	204	31.8%
519		27	0	100.0%	292	9	96.9%	27	1	96.3%	290	64	77.9%
520		20	1	95.0%	170	25	85.3%	20	0	100.0%	167	9	94.6%
521		20	0	100.0%	208	7	96.6%	20	4	80.0%	208	27	87.0%
522		20	3	85.0%	208	39	81.3%	20	2	90.0%	205	20	90.2%
523		20	1	95.0%	208	7	96.6%	20	0	100.0%	207	22	89.4%
524		20	4	80.0%	208	15	92.8%	20	3	85.0%	206	23	88.8%
525	25	20	3	85.0%	206	15	92.7%	19	1	94.7%	202	14	93.1%
526	16	20	5	75.0%	182	34	81.3%	20	3	85.0%	179	15	91.6%
527		20	1	95.0%	208	10	95.2%	20	5	75.0%	207	37	82.1%
528		20	2	90.0%	208	17	91.8%	20	1	95.0%	207	30	85.5%
529		20	1	95.0%	208	12	94.2%	20	7	65.0%	207	57	72.5%
530		20	2	90.0%	162	16	90.1%	20	6	70.0%	162	32	80.2%
531		20	1	95.0%	182	13	92.9%	20	2	90.0%	182	13	92.9%
532		20	8	60.0%	208	51	75.5%	20	4	80.0%	207	31	85.0%
534		20	1	95.0%	167	25	85.0%	20	1	95.0%	165	16	90.3%
535	11	20	2	90.0%	195	25	87.2%	20	3	85.0%	190	23	87.9%
536		20	6	70.0%	208	55	73.6%	19	1	94.7%	204	38	81.4%
537		20	4	80.0%	179	22	87.7%	19	4	78.9%	173	20	88.4%
538	134	20	0	100.0%	208	23	88.9%	20	6	70.0%	207	43	79.2%
539		20	3	85.0%	162	23	85.8%	20	7	65.0%	162	71	56.2%
540		19	3	84.2%	207	38	81.6%	18	0	100.0%	199	18	91.0%
541		20	1	95.0%	207	22	89.4%	19	3	84.2%	201	36	82.1%
542	28	20	3	85.0%	207	24	88.4%	19	5	73.7%	204	37	81.9%
543	89	20	4	80.0%	208	23	88.9%	20	13	35.0%	208	63	69.7%
544		20	0	100.0%	206	20	90.3%	20	4	80.0%	203	19	90.6%
545		20	2	90.0%	208	17	91.8%	19	2	89.5%	205	24	88.3%
547	28	20	4	80.0%	208	41	80.3%	20	3	85.0%	208	47	77.4%
548		19	1	94.7%	203	21	89.7%	18	1	94.4%	201	15	92.5%
549		20	1	95.0%	203	26	87.2%	19	1	94.7%	195	17	91.3%
550	32	20	4	80.0%	162	18	88.9%	20	5	75.0%	162	36	77.8%
551		20	3	85.0%	204	22	89.2%	19	2	89.5%	195	19	90.3%
562		27	1	96.3%	292	22	92.5%	27	5	81.5%	289	34	88.2%
564		28	2	92.9%	293	19	93.5%	28	7	75.0%	285	37	87.0%
566	43	28	7	75.0%	291	24	91.8%	28	11	60.7%	288	43	85.1%
567		28	2	92.9%	178	10	94.4%	28	3	89.3%	176	9	94.9%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572	16	28	1	96.4%	288	23	92.0%	27	17	37.0%	282	82	70.9%
573		28	0	100.0%	291	40	86.3%	28	6	78.6%	284	50	82.4%
579	19	28	2	92.9%	178	10	94.4%	28	10	64.3%	173	36	79.2%
580		28	1	96.4%	293	15	94.9%	27	7	74.1%	287	28	90.2%
581		28	6	78.6%	293	49	83.3%	28	8	71.4%	291	62	78.7%
584	40	28	8	71.4%	177	25	85.9%	27	24	11.1%	172	106	38.4%
587	119	27	1	96.3%	287	16	94.4%	27	15	44.4%	278	53	80.9%
588	84	28	6	78.6%	178	18	89.9%	28	10	64.3%	177	32	81.9%
591	149	27	3	88.9%	291	21	92.8%	27	9	66.7%	285	38	86.7%
593	No OS	28	10	64.3%	287	47	83.6%	25	9	64.0%	266	36	86.5%
595	No OS	28	13	53.6%	288	54	81.3%	28	13	53.6%	285	59	79.3%
600		19	0	100.0%	216	9	95.8%	19	4	78.9%	214	19	91.1%
601		19	10	47.4%	199	82	58.8%	19	2	89.5%	196	25	87.2%
605		19	9	52.6%	206	127	38.3%	19	3	84.2%	202	22	89.1%
607		19	5	73.7%	215	29	86.5%	19	3	84.2%	212	25	88.2%
609		19	1	94.7%	206	23	88.8%	19	4	78.9%	205	19	90.7%
622		15	2	86.7%	118	32	72.9%	15	0	100.0%	116	5	95.7%
626		19	4	78.9%	120	16	86.7%	19	3	84.2%	118	18	84.7%
639		18	1	94.4%	186	38	79.6%	18	0	100.0%	185	19	89.7%
640		19	0	100.0%	206	7	96.6%	19	4	78.9%	204	80	60.8%
641		19	4	78.9%	188	38	79.8%	19	1	94.7%	188	26	86.2%
642		19	0	100.0%	204	9	95.6%	19	3	84.2%	203	26	87.2%
643		19	4	78.9%	218	43	80.3%	19	4	78.9%	215	36	83.3%
644		19	1	94.7%	210	28	86.7%	19	3	84.2%	208	51	75.5%
645	23	19	3	84.2%	218	41	81.2%	18	7	61.1%	215	46	78.6%
646	17	19	5	73.7%	207	51	75.4%	19	12	36.8%	205	101	50.7%
647		19	1	94.7%	218	32	85.3%	19	4	78.9%	217	47	78.3%
648		19	5	73.7%	214	55	74.3%	19	3	84.2%	214	34	84.1%
649		19	5	73.7%	219	42	80.8%	19	3	84.2%	216	34	84.3%
650	30	19	2	89.5%	218	41	81.2%	19	6	68.4%	215	36	83.3%
651		19	0	100.0%	218	16	92.7%	19	3	84.2%	216	42	80.6%
652		19	2	89.5%	219	29	86.8%	19	5	73.7%	215	37	82.8%
653		19	3	84.2%	207	33	84.1%	19	4	78.9%	204	38	81.4%
654		19	4	78.9%	208	40	80.8%	18	1	94.4%	204	17	91.7%
655		19	3	84.2%	216	72	66.7%	19	5	73.7%	214	73	65.9%
656	15	19	2	89.5%	218	47	78.4%	19	9	52.6%	217	30	86.2%
657		19	1	94.7%	207	27	87.0%	19	1	94.7%	206	29	85.9%
658		19	1	94.7%	218	35	83.9%	19	2	89.5%	216	32	85.2%
680		20	3	85.0%	213	12	94.4%	20	3	85.0%	212	27	87.3%
681	19	20	3	85.0%	213	17	92.0%	19	12	36.8%	207	84	59.4%
682		20	1	95.0%	212	6	97.2%	20	5	75.0%	212	38	82.1%
683	18	20	2	90.0%	195	17	91.3%	20	15	25.0%	194	66	66.0%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684		20	5	75.0%	194	32	83.5%	20	6	70.0%	194	44	77.3%
685		20	3	85.0%	209	31	85.2%	20	8	60.0%	206	52	74.8%
686		20	4	80.0%	214	37	82.7%	20	9	55.0%	213	45	78.9%
687		20	3	85.0%	213	33	84.5%	20	4	80.0%	212	35	83.5%
688		20	4	80.0%	212	13	93.9%	20	6	70.0%	211	36	82.9%
689		6	2	66.7%	145	20	86.2%	6	1	83.3%	144	21	85.4%
701		28	4	85.7%	233	25	89.3%	28	5	82.1%	230	25	89.1%
702	19	28	1	96.4%	300	32	89.3%	27	9	66.7%	297	69	76.8%
703		28	15	46.4%	301	92	69.4%	27	14	48.1%	299	84	71.9%
704		28	5	82.1%	232	37	84.1%	26	5	80.8%	225	43	80.9%
710		28	8	71.4%	301	77	74.4%	28	7	75.0%	297	80	73.1%
711	18	28	5	82.1%	292	33	88.7%	24	5	79.2%	271	50	81.5%
712		28	8	71.4%	298	79	73.5%	27	10	63.0%	289	97	66.4%
714	21	27	16	40.7%	182	74	59.3%	25	15	40.0%	168	73	56.5%
715	52	28	2	92.9%	300	60	80.0%	24	14	41.7%	277	139	49.8%
716	28	28	13	53.6%	301	120	60.1%	27	13	51.9%	295	115	61.0%
717	30	27	4	85.2%	286	66	76.9%	26	13	50.0%	267	83	68.9%
718	31	28	14	50.0%	301	150	50.2%	28	16	42.9%	299	107	64.2%
719		28	13	53.6%	301	101	66.4%	27	10	63.0%	286	82	71.3%
757		28	1	96.4%	86	4	95.3%	28	4	85.7%	85	8	90.6%
761	26	28	1	96.4%	297	12	96.0%	28	7	75.0%	294	41	86.1%
765		28	0	100.0%	297	24	91.9%	28	4	85.7%	297	40	86.5%
769		28	1	96.4%	297	26	91.2%	28	7	75.0%	291	56	80.8%
770	56	28	0	100.0%	297	21	92.9%	28	13	53.6%	295	87	70.5%
774	33	28	0	100.0%	297	16	94.6%	28	11	60.7%	296	67	77.4%
777		28	3	89.3%	182	12	93.4%	28	7	75.0%	181	41	77.3%
782	38	28	23	17.9%	182	79	56.6%	28	10	64.3%	177	25	85.9%
785		28	4	85.7%	297	21	92.9%	28	6	78.6%	297	52	82.5%
786	95	28	2	92.9%	86	18	79.1%	26	17	34.6%	83	44	47.0%
790	No OS	28	0	100.0%	297	26	91.2%	28	12	57.1%	294	44	85.0%
794	57	28	2	92.9%	297	33	88.9%	27	9	66.7%	293	64	78.2%
821		28	0	100.0%	295	6	98.0%	28	15	46.4%	295	118	60.0%
822	54	28	2	92.9%	297	16	94.6%	28	21	25.0%	295	139	52.9%
1058	36	2	0	100.0%	4	1	75.0%	2	2	0.0%	4	3	25.0%
1333	65	28	4	85.7%	297	32	89.2%	28	10	64.3%	294	98	66.7%
1340	28	28	1	96.4%	296	6	98.0%	28	7	75.0%	296	49	83.4%
2102	26	19	1	94.7%	65	13	80.0%	19	2	89.5%	64	6	90.6%
2103		19	2	89.5%	129	12	90.7%	19	0	100.0%	128	9	93.0%
2104		19	1	94.7%	155	10	93.5%	19	2	89.5%	153	12	92.2%
2107		19	4	78.9%	186	34	81.7%	19	0	100.0%	183	20	89.1%
2108		19	1	94.7%	186	26	86.0%	19	3	84.2%	180	20	88.9%
2109		19	1	94.7%	79	10	87.3%	19	0	100.0%	78	4	94.9%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2026

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2112		19	2	89.5%	26	4	84.6%	18	2	88.9%	24	2	91.7%
2113		19	3	84.2%	65	6	90.8%	19	1	94.7%	65	8	87.7%
2115		19	5	73.7%	65	10	84.6%	19	7	63.2%	64	11	82.8%
2116		19	1	94.7%	26	1	96.2%	19	4	78.9%	26	6	76.9%
2118		19	2	89.5%	26	2	92.3%	19	7	63.2%	26	9	65.4%
2119		19	1	94.7%	26	3	88.5%	19	8	57.9%	26	9	65.4%
2120	48	19	6	68.4%	26	9	65.4%	18	10	44.4%	25	13	48.0%
2123		19	2	89.5%	64	8	87.5%	18	2	88.9%	63	15	76.2%
2124		19	10	47.4%	158	33	79.1%	19	9	52.6%	156	22	85.9%
2127	103	19	7	63.2%	26	8	69.2%	19	7	63.2%	25	7	72.0%
2128		19	3	84.2%	26	3	88.5%	19	2	89.5%	26	2	92.3%
2131		19	5	73.7%	26	5	80.8%	19	2	89.5%	26	2	92.3%
2150	24	19	0	100.0%	179	22	87.7%	19	6	68.4%	176	73	58.5%
2151		19	0	100.0%	128	6	95.3%	19	7	63.2%	126	36	71.4%
2152		16	3	81.3%	84	6	92.9%	16	4	75.0%	83	30	63.9%
2154	187	15	3	80.0%	87	23	73.6%	14	5	64.3%	83	41	50.6%
2155		19	2	89.5%	188	16	91.5%	19	6	68.4%	184	96	47.8%
2158	40	19	2	89.5%	26	4	84.6%	19	12	36.8%	26	12	53.8%
2159		19	2	89.5%	181	13	92.8%	19	11	42.1%	179	59	67.0%
2160	22	19	1	94.7%	26	1	96.2%	18	12	33.3%	25	16	36.0%
2162		19	4	78.9%	187	17	90.9%	19	7	63.2%	181	84	53.6%
2165	45	16	2	87.5%	23	2	91.3%	16	9	43.8%	23	11	52.2%
2167	34	16	2	87.5%	175	20	88.6%	16	2	87.5%	175	38	78.3%
2171	Cncld	19	2	89.5%	115	10	91.3%	18	5	72.2%	111	23	79.3%
2190		16	3	81.3%	184	27	85.3%	16	1	93.8%	182	23	87.4%
2193	102	14	2	85.7%	179	25	86.0%	14	3	78.6%	177	48	72.9%

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2102	NYP	26	CAR	20	CAR	20	WAS-WAS	AM	FDA, 3261 NG NS, TRAIN WAS SHOPPED DUE NO WATER SERVICE IN THE FIRST CLASS CAR SINK WAS BROKEN.
2120	NYP	48	ENG	24	ENG	24	XPV-WIL	AM	Air / Brake, 2124 NG NP, stopped a/c main reservoir opened and pantograph dropped just north of Prince Int.
2127	WAS	103	ENG	72	DMW	20	PHL-XPV	AM	Held for or routed around MW work or equipment, Control Point, Holly, speed restriction 10 MPH on 3 track a/c track defect
2150	BOS	24	ENG	23	ENG	21	XNH-XGX	AM	Radio failure, 2013 LH LP, AM2150 is stopped at MP 91.29 A/C did not hear the audible HBD/DED, needs to inspect train
2154	BOS	187	TRS	141	TRS	141	PVD-PVD	AM	Trespasser strike, Control Point, MP 196.9
2158	BOS	40	TRS	38	TRS	38	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike at Attleboro
2160	BOS	22	DSR	13	DSR	8	STM-NHV	MN	Per bulletin Milepost, 41.7, 42.0, 15, 4
2165	WAS	45	OTH	20	CTI	13	BAL-XNY	AM	Cross over or go around, MARC, 447, Milepost, 112.4, 127, opr 2 trk around 447 on 3 trk
2167	WAS	34	ENG	18	ENG	18	NYP-NYP	AM	Other electrical failure, 2024 LH LP, MECHAINCAL ISSUES IN STATION
2171	WAS	Trn Cancelled	TRS	185	TRS	121	BOS-BOS	AM	Trespasser strike, Control Point, MP196.9, Holding due to trespasser strike in Attleboro
2193	NYP	102	TRS	103	TRS	87	BOS-BOS	AM	Trespasser strike, Milepost, BOS, BOS, Substantial delay due to earlier downline tresp. strike
85	WAS	17	DSR	20	DSR	20	BRP-STM	MN	Per bulletin Milepost, 49.9, 48.8, 30, 3, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2
86	BOS	125	TRS	92	TRS	92	PVD-PVD	AM	Trespasser strike, Milepost, pvd, pvd, holding due to trespasser strike
93	NFK	109	POL	81	POL	81	RVR-PTB	CS	Right of Way police hold
94	BOS	21	SMW	22	PTI	11	PVD-RTE	AM	Follow, 2160, Control Point, X7O, Held at Orms for 2160 to pass (2160 on short time)
138	NYP	28	WTR	18	FTI	14	PTB-RVR	CS	Meet IL 31, Milepost, 3.4, 3.4
148	SPG	26	TRS	44	TRS	44	NYP-XPB	AM	Near-miss, Other, MP.12, HELD AT PELHAM BAY A/C POSSIBLE TRESPASSER STRIKE
172	BOS	203	TRS	208	TRS	208	PVD-RTE	AM	Trespasser strike, Control Point, MP 196.9, trespasser strike in Attleboro

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
174	BOS	82	TRS	76	TRS	76	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike in Attleboro mp169.9, also westbound traffic and speed restrictions	
175	WAS	215	TRS	188	TRS	125	BOS-BOS	AM	Trespasser strike, Milepost, bos, bos, Holding due to trespasser strike in Attleboro	
177	PHL	No OS Rpt	TRS	206	TRS	206	BOS-BOS	AM	Trespasser strike, Other, Attleboro , Late turn from earlier trespasser strike in Attleboro mp169.9	
179	PHL	23	SMW	24	SMW	9	MET-TRE	AM	Scheduled in track usage program, Other, XMW-TRE, SINGLE TRACKING ON NO.4 TRACK A/C 1 & 2 TRACKS O/O/S MIDWAY TO HAM AND 1,2, & 3 TRACKS O/O/S HAM INT. LIMITS.	
186	PHL	18	WTR	42	WTR	25	ASD-FBG	CS	High winds Do not pass Cfp: 54.9 for tornado, Milepost, 47.7, 54.9	
190	BOS	36	CTI	26	CTI	12	NHV-NLC	AM	Meet, CDOT, 1610, Other, gui-osb, followed trains 2150 and ct 1610	
193	WAS	29	CTI	15	CTI	11	BWI-NCR	AM	Follow, MARC, 455, Milepost, 106.3, 127	
197	WAS	23	PTI	20	PTI	9	WIL-XPV	AM	Follow, 193, Milepost, 51, 59.5	
474	SPG	20	CON	10	CON	10	NHV-NHV	AM	Hold for connecting train	
52	LOR	215	FTI	76	ITI	75	SFA-SFA	FR	Service, turn, or wye train 53	
79	CLT	92	TRS	66	TRS	66	HPT-SAL	NS	Vehicle on track ahead Milepost, 313.2, 313.2	
645	HAR	23	WTR	23	WTR	21	DOW-PAR	AM	Storm, Control Point, ., CALN OUT A/C LIGHTNING STRIKE, GIVING 241 TO TRAINS	
646	NYP	17	OTH	12	PTI	5	XHM-TRE	AM	Follow, AM98, Other, XHM-TRE	
650	NYP	30	WTR	40	WTR	40	LNC-DOW	AM	Storm, Control Point, ., CALN OUT A/C LIGHTNING STRIKE, GIVING 241 TO TRAINS	
656	NYP	15	PTI	17	PTI	9	TRE-NWK	AM	Follow, AM136, Other, TRE-NWK	
681	BRK	19	DMW	18	DMW	16	DOV-WEM	CS	Held for or routed around MW work or equipment Control Point, Rollinsford	
683	BRK	18	FTI	15	FTI	15	POR-FRE	CS	Meet FRA inspection car, W9057, Control Point, congress	
63	TWO	37	OTH	4	OTH	4	NYP-XSD	AM	Lost time - N.A.R.	
64	NYP	49	DSR	23	CUI	19	NFL-NFL	CS	U.S. Border Patrol	
68	NYP	80	WTR	47	WTR	47	SLQ-RSP	CN	Heat order Milepost, 42, 2	

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
233	ALB	29	PTI	19	PTI	19	RHI-HUD	AM	Meet 284, Control Point, 114
235	ALB	57	DBS	18	DBS	18	RHI-HUD	AM	Debris strike Hit large tree. Inspect engine do a brake test. Trouble shoot lost HEP, Tree, Milepost, 112, 112
238	NYP	33	CTI	30	CTI	30	POU-CRT	MN	Meet metro north, 829, Control Point, 46
239	ALB	19	DBS	23	DBS	23	RHI-HUD	AM	Debris blocking track (no debris strike) Single tracking from 103-125, Control Point, 103
240	NYP	21	CTI	22	CTI	22	POU-CRT	MN	Meet man, Control Point, 47
243	ALB	59	ENG	69	ENG	69	NYP-NYP	AM	Loading problem, 714 DX DM, LATE RELEASE FROM SSYD BY MECHANICAL A/C UNSPECIFIED MECHANICAL ISSUES.
244	NYP	33	PTI	19	PTI	19	ALB-HUD	AM	Meet Single tracking 124-114. Held at 124 on track 2 for 291, amt291, Control Point, cp124
280	NYP	53	DCS	28	PTI	23	ALB-HUD	AM	Meet 69, Control Point, 141
290	NYP	18	CTI	12	CTI	12	POU-CRT	MN	Follow metro, 870, Milepost, 62, 39
49	CHI	34	FTI	91	FTI	55	SKY-TOL	NS	Blocked from station track 257 assisting 337 in emergency., 257, Control Point, 286
448	BOS	31	PTI	53	PTI	53	XRD-PIT	CS	Meet Amtrak 449, Control Point, cp 171
42	NYP	24	ENG	31	ENG	31	LNC-EXT	AM	Cab signal failure, 125 DX BD, cabs went to restricting from Park to Thorn
76	RGH	71	WTR	70	WTR	45	GRO-DNC	NS	Tornado warning Milepost, 7.7, 25.0
78	RGH	23	WTR	28	WTR	14	CLT-KAN	NS	Tornado warning First train through after expiration of tornado warning. 20mph, Milepost, 352.4, 348.2
90	NYP	52	TRS	61	TRS	61	SSM-WLN	CS	Vehicle strike Milepost w/Letters, A 142.79, A 142.79
98	NYP	99	FTI	83	FTI	40	JSP-SAV	CS	Meet TOOK TK # 1, STOP SIGNAL, Milepost, 540.2, 533.4, M 693/26, I 197/27
40	CHI	137	PTI	112	INJ	45	TPA-LAK	CS	Injured or sick passenger Mr Thomas passenger was experiencing severe seizures and vomiting Train 40 shoved back into Tampa to have Mr Thomas remove and transported to hospital by ambulance
41	MIA	41	RTE	65	FTI	27	XPI-SOB	NS	Follow NS east, Milepost, 479, 453
26	MOE	57	DCS	60	DCS	58	BIX-PAG	CS	CTC system failure Milepost, 722.5, 713.0
5	EMY	57	WTR	111	PTI	33	XBB-XDC	UP	Meet Amtk6, Siding, Range
6	DEN	65	DSR	76	WTR	31	WNN-XW6	UP	Heat order Milepost, 535, 612

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
525	EMY	25	SVS	13	SVS	13	SAC-SAC	UP	Pick up equipment Coupled into dead Goldrunner train set to drag to OMF., Other, SAC
526	SAC	16	ITI	24	ITI	24	OKJ-OKJ	UP	Service, turn, or wye train 525, Late turn after dragging deadhead Goldrunner set into OMF.
535	OKJ	11	DCS	11	DCS	6	MTZ-RIC	UP	Restrictive signal(s) from known wayside signal failure Signal kept dropping from green to red and back to green, Stop, Control Point, RV015
538	ARN	134	TRS	100	TRS	100	OAC-OKJ	UP	Trespasser strike Milepost, 10.4, 10.4
542	SAC	28	TRS	25	TRS	22	OAC-OAC	UP	Vehicle strike Milepost, 10.36, 10.36
543	SJC	89	POL	82	POL	75	OKJ-OKJ	UP	RR blocked by trespasser or vehicle strike by another train
547	SJC	28	TEN	34	TEN	16	SAC-SAC	UP	PTC - On Board Cab Signal or PTC Failure C2010
550	SAC	32	ITI	24	ITI	24	SJC-SJC	UP	Service, turn, or wye train 543
507	EUG	16	DSR	26	DSR	9	ALY-EUG	UP	Per bulletin Milepost, 678.25, 676.25, 30, mt, Milepost, 668.75, 668.70, 30, mt, Milepost, 665.40, 665.25, 15, mt
511	PDX	80	ENG	55	ENG	55	SEA-SEA	BN	PTC - On Board Cab Signal or PTC Failure 90230
516	VAC	23	DSR	17	DMW	14	XF2-X1J	BN	Held for or routed around MW work or equipment Bridge, Fraser River Bridge
518	VAC	23	ENG	17	FTI	9	X8B-XF2	BN	Meet bnsf 9178, Control Point, oliver
59	NOL	73	FTI	106	FTI	46	EFG-CEN	CC	Meet cn3150, Siding, tonti
1058	CHI	36	DSR	46	PTI	23	FTN-CDL	CC	Meet 59, Siding, Anna
7	SPK	262	FTI	244	FTI	120	WTN-WPT	BN	Follow BNSF 6720W, Milepost, 121.0, 192.0
8	CHI	287	FTI	112	CON	87	SPK-SPK	BN	Hold for bus with passengers from train Held for last bus to arrive with passengers
822	OKC	54	DSR	40	FTI	20	FTW-GLE	BN	Meet bn 8042, Siding, vally view
329	MKE	44	DCS	40	DCS	29	XRO-SVT	CP	Restrictive signal(s) from known wayside signal failure Restricted , Control Point, XRO, Control Point, Wadsworth

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
330	CHI	62	DCS	40	DCS	30	SVT-XRO	CP	Restrictive signal(s) from known wayside signal failure Signal issues from storm the previous day. Talked by the stop signal at Wadsworth and Rondout. Restricted speed till next signal. Clear signal 36.5, Stop, Control Point, Wadsworth, Control Point, Rondout
331	MKE	50	ITI	46	ITI	46	CHI-CHI	AM	Service, turn, or wye train 330
339	MKE	62	CTI	69	CTI	60	GLN-XRO	ME	Follow Multiple Metra trains had to be talked past A20, backing traffic up., Metra, 2135, Milepost, 17.8, 28.7
342	CHI	47	ITI	41	ITI	41	MKE-MKE	CP	Service, turn, or wye train 339
350	PNT	42	MBO	52	MBO	52	CHI-XTF	AM	Bridge strike Bridge, 35th st Bridge
354	PNT	24	PTI	45	PTI	45	KAL-XGO	MI	Meet amt355, Other, 140
365	CHI	17	DSR	20	MBO	15	XPI-XH6	NS	For maritime traffic Other, 15
566	SAN	43	CTI	21	WTR	18	SNP-X98	SC	Flood / washout Per engineers request, walked track where sea water was splashing over breakwater onto the tracks. Tracks looked stable but ballast look disturbed. Reported findings to Orange Sub and SD Sub., Milepost, 206.6, 206.8
572	SAN	16	DCS	14	DCS	8	SNP-X98	SC	Flag CP pier Control Point, pier
579	LAX	19	FTI	11	FTI	11	FUL-XRJ	BN	Follow 300 axle, BNSF UNK, Milepost, 165., 144.4
584	SAN	40	DCS	30	DCS	10	SNP-SNP	SC	CTC system failure Red signals account high tide and large waves, Control Point, pier
587	LAX	119	CTI	50	CTI	50	OSD-X98	SC	Meet 6.21.3 and track inspection, Metrolink, 626, Control Point, Songs
588	SAN	84	DSR	47	DSR	32	SNP-X98	SC	Per dispatcher (radio/phone) Waiting on DS to flag us thru CP PIER, Control Point, CP PIER, 0, MT
591	LAX	149	PTI	117	PTI	54	OSD-X98	SC	Meet 786, Control Point, songs
593	LAX	No OS Rpt	PTI	69	PTI	35	OSD-X98	SN	Follow 591, Control Point, CP SONGS
595	LAX	No OS Rpt	DCS	5	DCS	3	SAN-SAN	SN	Restrictive signal(s) from unknown cause Stop, Control Point, ash
761	GTA	26	DCS	41	DCS	30	OSD-X98	SN	CTC system failure Flag CP Songs wait on instructions, Control Point, Songs
770	SAN	56	PTI	37	PTI	18	OSD-SOL	SN	Meet 777, Control Point, Ponto
774	SAN	33	PTI	25	PTI	17	SNC-SNP	SC	Meet 777, Control Point, serra

Amtrak Endpoint OTP Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
782	SAN	38	PTI	21	PTI	17	CPN-VEC	UP	Meet 769, Siding, Seacliff
786	SAN	95	PTI	55	PTI	37	GUA-LPS	UP	Meet 765, 14, Siding, Tangair
790	SAN	No OS Rpt	PTI	148	PTI	79	SNC-SNC	SC	Meet Open door policy at SNC, 591, Control Point, serra
794	SAN	57	PTI	39	PTI	27	SNC-SNC	SC	Meet 595, Other, San Juan Capistrano Station
702	BFD	19	FTI	23	PTI	14	COC-WAC	BN	Meet Amtk715, Control Point, Angiola
711	OKJ	18	TRS	18	TRS	18	MCD-MCD	BN	Vehicle on track ahead Other, 1062.4
714	BFD	21	PTI	22	PTI	16	MOD-TRK	BN	Meet Held at E Empire for 715. BNSF train in Denair siding, 715, Control Point, E Empire
715	OKJ	52	PTI	36	PTI	12	TRK-MOD	BN	Meet Shuffle, amt 714, Control Point, east empire
716	BFD	28	TEN	55	TEN	55	OKJ-OKJ	UP	Bad order railing for locomotive causing delay C2013
717	OKJ	30	PTI	39	PTI	11	COC-HNF	BN	Meet 712, Siding, W. Corcoran
718	BFD	31	FTI	24	FTI	14	HNF-COC	BN	Meet 613, Control Point, Wagner, BNSF
3	LAX	185	FTI	110	FTI	75	FMD-LAP	BN	Meet Milepost, 305, 305, BN 7059, BN 3950
4	CHI	82	FTI	161	FTI	62	FLG-WLO	BN	Meet Met 4 BNSF WESTBOUNDS, BNSF WEST, Other, W DARLING
2	NOL	137	FTI	215	FTI	105	XEA-XRB	UP	Dispatcher Stopped us at SA061. UP1464E hit the back of an 18wheeler trailer. Waited for it to be moved and cleared then followed for a few miles up1464e, Milepost, 61, 50.8
21	SAS	35	FTI	152	FTI	47	WNR-XDZ	UP	Meet UP 6838, Control Point, x226
22	CHI	80	FTI	140	FTI	120	XDZ-WNR	UP	Freight train went in emergency waited for clearance to proceed 0338, Control Point, Tuckerman
300	CHI	25	FTI	34	FTI	20	XUD-SMT	CC	Cross Traffic unknown, Control Point, canal
306	CHI	41	FTI	36	FTI	24	STL-XQT	TR	Meet 6309, 2531, Control Point, NORTH APPROACH
382	CHI	26	FTI	21	FTI	12	QCY-MAC	BN	Cross over or go around Siding, Macomb, 7275, BNSF
383	QCY	18	FTI	15	FTI	15	MAC-QCY	BN	Meet BN unknown E, Control Point, Camp Point
390	CHI	32	FTI	36	FTI	26	CHM-RTL	CC	Meet CN3268, Siding, Leverett

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/28/2026

26-FOI-00625 00000008485 "UNCLASSIFIED" 8/7/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
391	CDL	Trn Cancelled	TRS	191	TRS	191	CHM-MAT	CC	Vehicle strike Hit semi truck trailer, Other, Mp 158.10	
392	CHI	Trn Cancelled								
319	STL	21	DCS	19	FTI	10	XQT-STL	TR	Meet UP 9006, Control Point, North Approach	
1333	MSP	65	ENG	53	ENG	29	MKE-MKE	CP	Set out defective locomotive 147	
1340	CHI	28	DSR	39	DSR	18	MSP-XH8	CP	Per bulletin GTB 13556, Milepost, 422.8, 402.4, 45, main 1 / crossover, Milepost, 422.7, 422.2, 30, main 1 / main 2 / crossover, Milepost, 400.1, 399.5, 10, main 1	

Amtrak Initial Terminal Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/28/2026

Terminal	Train	Date	Late	Delay	Cause
TWO	64	07/28	1		
BON	681	07/28	1	1	Cross Traffic Keolis, Other, BON
BOS	93	07/28	28	28	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard servicing C/82741
BOS	175	07/28	125	125	Trespasser strike, Milepost, bos, bos, Holding due to trespasser strike in Attleboro
BOS	177	07/28	206	206	Trespasser strike, Other, Attleboro , Late turn from earlier trespasser strike in Attleboro mp169.9
BOS	179	07/28	99	99	Trespasser strike, Other, Attleboro, Late turn of 172 a/c earlier trespasser strike
BOS	2171	07/28	121	121	Trespasser strike, Control Point, MP196.9, Holding due to trespasser strike in Attleboro
BOS	2193	07/28	87	87	Trespasser strike, Milepost, BOS, BOS, Substantial delay due to earlier downline tresp. strike
HAR	654	07/28	5	5	Meet, 609, Control Point, .
LOR	53	07/28	67	67	Service, turn, or wye train 52
NFL	280	07/28	1		
NFL	284	07/28	4	4	Inability to contact dispatcher No light at 28 was on hold trying to report switch was lined and locked normal at QDN 26.7, Control Point, 28
NYP	49	07/28	24	24	Removal of passenger by police, DPT NYP LATE ACCT POLICE REMOVING A DISORDERLY PSGR
NYP	69	07/28	3	3	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	07/28	7	7	Hold for connecting train, WAITING FOR PSGRS OFF AM93
NYP	119	07/28	4	4	Door, 00000, UNSPECIFIED DOOR ISSUES
NYP	131	07/28	3	3	Passenger and/or baggage, LOADING
NYP	181	07/28	12	12	Loading problem, 635 EX ES, issue with the load meter on the leading engine.
NYP	235	07/28	15	15	Service, turn, or wye train, 238, LATE TURN OFF AM238
NYP	243	07/28	69	69	Loading problem, 714 DX DM, LATE RELEASE FROM SSYD BY MECHANICAL A/C UNSPECIFIED MECHANICAL ISSUES.
NYP	245	07/28	30	30	Service, turn, or wye train, 68, LATE TURN OF AM68
NYP	291	07/28	9	9	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	643	07/28	2	2	Cross Traffic, NJT, NJ6317, Other, NYP
NYP	649	07/28	4	4	Planned set out / pick out of locomotives, cars or section of train, HELD TO FOLLOW DELAYED AM93 DUE TO LATE SERVICING IN BOSTON
NYP	2127	07/28	13	13	Other electrical failure, 2141 NG NP, MECHANICAL ISSUES IN STATION WITH ATC ISSUES

Amtrak Initial Terminal Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/28/2026

Terminal	Train	Date	Late	Delay	Cause
PHL	190	07/28	1	1	Passenger and/or baggage
WAS	2102	07/28	20	20	FDA, 3261 NG NS, TRAIN WAS SHOPPED DUE NO WATER SERVICE IN THE FIRST CLASS CAR SINK WAS BROKEN.
WAS	2108	07/28	6	6	Air / Brake / Wheel, 3362 NG ND, INBOUND 2103 TURN FOR 2108 SHOPPED FOR LOUD BANG COMING FROM UNDER THE CAR 3362 CAFE.
WAS	2124	07/28	3	3	Delay in Block, CNDR HELD OFF ON BOARDING DUE TO TRTTAIN STILL BEING CLEANED
WAS	2154	07/28	2	2	Malfunction of platform structure at Amtrak station, Control Point, K INTERLOCKING, MOTORIZED CARTS ARE BAND FROM BEING USED ON THE PLATFORMS ON 20 AND 19 AT THIS TIME. THEY HAVE TO USE HAND CARTS TO LOAD THE TRAINS.
CDL	392	07/28	(Trn Cxld)		Trespasser Strike
CHI	3	07/28	2	2	Routine inspections Control Point, chi
CHI	7	07/28	28	28	Water radiator 193
CHI	331	07/28	46	46	Service, turn, or wye train 330
FTW	822	07/28	1		
MKE	336	07/28	1		
MKE	342	07/28	41	41	Service, turn, or wye train 339
MSP	1340	07/28	1	1	Routine inspections Left MSP late due to MDOT inspection and being released late from mechanicals blue flag protection.
GTA	782	07/28	4	4	Wait for station track 14, Control Point, CO 356
LAX	584	07/28	2	2	Meet Train departed on time, amtk581, Control Point, terminal
OKJ	526	07/28	24	24	Service, turn, or wye train 525, Late turn after dragging deadhead Goldrunner set into OMF.
OKJ	532	07/28	1		
OKJ	714	07/28	1	1	Wait for station track 711 arrived OKJ 11:31 turns to yard 530 at 11:51 through to SAC 535 arrived OKJ at 12:01 turns as 534 714 held at OMF behind AMT 535 Quick turn at OKJ Almost made OTD, 711, 530 &. 535, Control Point, OTM Magnolia
OKJ	716	07/28	55	55	Bad order railing for locomotive causing delay C2013
OKJ	718	07/28	40	40	Routine inspections
SAC	525	07/28	13	13	Pick up equipment Coupled into dead Goldrunner train set to drag to OMF., Other, SAC
SAC	547	07/28	16	16	PTC - On Board Cab Signal or PTC Failure C2010

Amtrak Initial Terminal Details

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/28/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	704	07/28	2	1	Key on in key panel at other end; could not trainline doors closed.
SAC	704	07/28	2	1	Mobility Impaired Venture cars, manual lift. Three up.
SAN	581	07/28	14	14	Service, turn, or wye train 770
SAN	595	07/28	3	3	Restrictive signal(s) from unknown cause Stop, Control Point, ash
SEA	511	07/28	55	55	PTC - On Board Cab Signal or PTC Failure 90230
SJC	550	07/28	24	24	Service, turn, or wye train 543
SLO	786	07/28	2	2	FDA 6301, Water stopped working shortly before departure. Attempted to put more water in, but were unsuccessful.
SPK	8	07/27	135	171	Wait for bus 8

Eastern Region

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	98.6	94.8	342	3
CDOT	95.0	95.0	84.9	92.4	20	1
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	96.3	92.5	88.6	350	13
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 245(28) - New York Penn Station, NY - Initial Terminal Delay

29JUL26: Train 245(28) was delayed at its initial terminal at New York Penn Station due to turning off the late arriving 68(28) equipment - which arrived 1'20" late.

Train	Delay	Comment
245 (28)	30"	

Train 79(28) - North of Salisbury, NC - Trespasser Incident

28JUL26: Train 79(28) was delayed on the Norfolk Southern Charlotte District at MP 313.1 due to a vehicle stuck on the tracks ahead.

Train	Delay	Comment
79 (28)	1'06"	

Train 93(28) and 97(28) - South of Richmond, VA - Police Related

28JUL26: Due to a police hold for a suspect search on the right of way, at MP 5.6 on the CSX North End Subdivision, Amtrak Train 93(28) was held north at MP 5.2 and Train 97(28) was held north at MP 0.4 until police were clear of the right of way.

Train	Delay	Comment
93 (28)	1'15"	
97 (28)	49"	

Train 243(28) - New York Penn Station, NY/Sunnyside Yard - Miscellaneous Amtrak Responsible

28JUL26: Train 243(28) was delayed at its initial terminal due to a late mechanical released from Sunnyside Yard. No other reason was cited.

Train	Delay	Comment
243 (28)	1'09"	

Train 2171(28) - New York Penn Station, NY - Expiring Paperwork

28JUL26: Train 2171(28) with E/125 and 7 cars with 240 customers onboard was delayed due to expiring inspection paperwork. The passengers were moved to Train 175(28) for continued travel west and south NYP-WAS.

Train	Delay	Comment
2171(28)	Term NYP	Expiring Paperwork

Train 148(28) - East of New York Penn Station - Trespasser Incident

28JUL26: Train 148(28) was delayed at MP 12.1 on the NYS Hellgate Line due to a near miss involving a trespasser. The crew restored air, inspected the consist, conducted a brake test and continued east.

Train	Delay	Comment
148(28)	44"	

Train 53(28) Lorton, VA - Servicing

28JUL26: Train 53(28) was delayed departing Lorton due to the late arrival of train 52(27) that arrived at 1234P-ET 3 hours and 55 minutes late.

Train	Delay	Comment
53(28)	1'07"	

Train 42(28) East of Lancaster, PA - Engine Failure

28JUL26: Train 42(28) with E/125 and 7 cars with 240 customers onboard was delayed due to E/125 having cab signal failure between Park-Thorn.

Train	Delay	Comment
42(28)	31"	

Train 172(28) East of Providence, RI - Trespasser Incident

28JUL26: At 248P-ET, Train 172(28) with E/668 and 8 cars with 373 customers onboard reported that they struck a trespasser at MP 196.9. The train was able to maintain HEP. No reported injuries to customers or crew. Amtrak Road Foreman's were enroute with the recrew. Attleboro Fire Department placed a hold on all tracks. Several other trains were held while the Fire department hold was in effect. Amtrak Road Foreman arrived on scene at 341P-ET. At 347P-ET, Attleboro Fire Department release the hold to Amtrak Road Foreman. The hold was still in place until the State Police arrived. The recrew arrived at 418P-ET. This was a confirmed fatality. This occurred in Bristol County, MA. At 500P-ET, Amtrak Road Foreman released the hold on track 1 at restricted speed and track 3 at 30 MPH from Thatcher to Holden and all Keolis trains were bypassing.

National Response Center Number: 1469182

Train	Delay	Comment
2171(28)	2'01"	BOS
175(28)	2'05"	BOS
2154(28)	2'25"	PVD
86(28)	1'35"	PVD
2193(28)	1'27"	
172(28)	3'28"	
177(28)	3'26"	TURNING OFF 86(28)
179(28)	1'39"	
2158(28)	38"	
174(28)	1'16"	

Train 650(28) East of Lancaster, PA - Signal

28JUL26: Train 650(28) with E/606 GC/9635 and 4 cars with 108 customers onboard was delayed on the Philadelphia to Harrisburg main line due to a restricted signal from a known wayside signal failure at MP 36.6/Caln. Trains were given Rule 241 to proceed.

Train	Delay	Comment
650(28)	40"	

Train 90(28) North of Selma-Smithfield, NC - Trespasser Incident

28JUL26: At 139P-ET, Train 90(28) with E/331 and 7 cars with 166 customers onboard reported that they struck a vehicle at MP A142.7 on the CSX South End A subdivision. There were no injuries reported to the customers or crew and the vehicle occupant was ok. The train was able to maintain HEP. This did occur at a private crossing DOT # 630036W in Wilson County equipped with 2 crossbuck assemblies. Amtrak Road Foreman was enroute estimated to be 1'15" out. Local Police responded and cleared the scene.

National Response Center Number: 1469173

Train	Delay	Comment
90(28)	1'00"	

Train 48(27) East of Buffalo, NY - Signal

28JUL26: Train 48(27) was delayed on the CSX Buffalo Terminal due to restricted signals from unknown wayside signal failure from MP 410 to MP 406.

Train	Delay	Comment
48(27)	33"	

CSX Heat Orders - Weather

28JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
52(28)	06"	
98(28)	33"	
40(28)	48"	
97(27)	23"	

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00625 00000008485 "UNCLASSIFIED" 8/7/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	
284(26)	25"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008485 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FOI-00625a 00000008485 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No data

Eastern Region

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train 48/448(28) Toledo, OH - PTC Disengaged

29JUL26: Train 48/448(28), with engines 127 and 98, 10 cars, and 183 customers onboard, was delayed departing Toledo, OH/MP288.3 on the NS Toledo Terminal subdivision due to the PTC system on lead engine 127 going disengaged. The crew contacted CNOC and was able to successfully engage the system after correcting an error in the consist. Once PTC was engaged, train 48/448(28) departed Toledo Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448 (28)	43"	

Train 50(28) East of Connersville, IN - Freight Train Interference

29JUL26: Train 50(28), with 89 customers onboard, was delayed between control point BD58.0 and control point Hamilton/BD25.5 beginning 11 miles east of Connersville, IN/BD67.2 on the CSX Indianapolis subdivision following CSX freight 360. Once the freight was clear of the route, train 50(28) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50 (28)	1'12"	

Train 511(28) Seattle, WA - Cab Car PTC Failure

28JUL26: Train 511(28), operating with cab car CC/90230, three cars, and locomotive WS1401, was delayed departing Seattle, WA Station due to Positive Train Control (PTC) issues. The crew worked with Mechanical forces and local management to troubleshoot the problem and determine a recovery plan. To mitigate the issue, the train was routed via the Stacy Wye to reposition the equipment and place locomotive WS1401 in the lead position.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
511 (28)	1'23"	

Train 6(28) East of Winnemucca, NV - Freight Train Interference

28JUL26: Train 6(28), carrying 155 customers onboard, was delayed east of Winnemucca, NV, on the Union Pacific Elko Subdivision due to freight train interference. The train was required to follow UP 2580 from approximately MP 565.0 to Whirlwind (MP 612.1), resulting in reduced speeds through the territory. Train was further delayed meeting UP 7339 at Whirlwind.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(28)	18"	meet at XW6
6(28)	42"	follow WNN-XW6

Train 3(27) West of Gallup, NM - Flash Flood Warnings

28JUL26: Train 3(27) was delayed west of Gallup, NM, on the BNSF Gallup Subdivision due to a flash flood warning affecting the route. The train was required to operate through the warning area between approximately MP 179.0, located about 22 miles west of Gallup, and MP 205.9, approximately 48 miles west of Gallup, under weather-related operating restrictions.

Train 718(28) Oakland, CA - Late Yard Release

28JUL26: Train 718(28) delayed departure from Oakland Jack London Square (OKJ) due to a late release of equipment from the Oakland Maintenance Facility. Prior to entering service, the consist was required to swap locomotives and undergo additional inspections, extending preparation time before departure. Once the locomotive change and required inspections were completed, Train 718(28) departed Oakland Jack London Square with 11 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(28)	40"	

Train 26(28) North of Biloxi, MS - CTC System Failure

28JUL26: Train 26(28), with 75 customers onboard, was delayed between mile post 722.5 and mile post 713.0, beginning 4.5 miles north of Biloxi, MS/MP726.95, on the CSX N.O.&M. subdivision operating through a CTC system outage. Once clear of the affected area, train 26(28) continued north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(28)	58"	

Train 587(28) West of San Diego, CA - Engine Issue

28JUL26: Train 587(28), operating with CC/6908, five cars, locomotive E/192, and 83 customers onboard, was delayed west of San Diego Old Town Station, at MP 262.8 on the NCTD San Diego Subdivision, after the crew observed a smoke condition originating from the brake system. The train was stopped to allow for a thorough inspection. The crew found no defects or abnormalities and successfully performed a brake set-and-release test, which verified normal brake operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
587(28)	42"	

Train 538(28) North of Oakland Coliseum Airport Station - Vehicle Strike

28JUL26: At approximately 4:05 PM PT, Train 538(28), operating with cab car CC/C8302, four cars, locomotive JPBX922, and 75 customers onboard, struck a vehicle approximately 1.6 miles north of Oakland-Coliseum Airport Station at the High Street grade crossing (MP 10.4) on the Union Pacific Niles Subdivision in Alameda, Alameda County, CA.

The crossing (DOT #749712Y) is a public grade crossing located on triple-main-track territory and is equipped with advance warning signs, pavement markings, and fully operational gate arms. There were multiple occupants in the vehicle, and all occupants, train crew members, and onboard customers were reported without injury. Weather conditions at the time were 69°F and sunny, and head-end power remained operational throughout the incident.

Local law enforcement, an Amtrak Road Foreman, and an Amtrak Trainmaster responded to the scene to assist with the investigation. Once the investigation was completed, the scene cleared, and the track was released for service, Train 538(28) continued to Oakland Jack London Square Station, where a relief crew assumed operation of the train.

National Response Center Number: 1469213

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
538(28)	1'40"	
538(28)	29"	OKJ recrew
542(28)	25"	
543(28)	1'22"	

Train 1(27)/421(26) East of El Paso, TX - Heat Orders

28JUL26: Train 1(27)/421(26) with 1480 customers onboard was delayed between mile post 1298.48 and mile post 1227.82, beginning 2.5 miles east of El Paso, TX/MP1296.0, on the UP Lordsburg subdivision following level two heat orders. Once clear of the affected area, train 1(27)/421(26) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(27)/421(26)	50"	

Train 339(28) West of Glenview, IL - Commuter Train Interference

28JUL26: Train 339(28), 255 customers onboard, was delayed between mile post 17.8 and mile post 28.7, beginning 0.5 miles west of Glenview, IL/MP17.32, on the CPKC C&M subdivision operating through Metra commuter train congestion. Rail traffic was being talked past Tower A20/MP20.5 and trains were beginning to queue. Once through the affected area, train 339(28) continued west.

Train 342(28) was delayed departing Milwaukee, WI due to the late turn of train 339(28)'s equipment.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
339(28)	1'00"	
342(28)	41"	Late turn @MKE

Train 20(28) East of Birmingham, AL - Power Switch Failure

28JUL26: Train 20(28), with 99 customers onboard, was delayed at 20th St east of Birmingham, AL/MP143.0, on the NS East End subdivision operating around a power switch failure. Once clear of the switch, train 20(28) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(28)	36"	

Train 4(27) East of Las Vegas, NM - Signal Issues

28JUL26: Train 4(27), carrying 156 customers onboard, was delayed east of Las Vegas, NM, on the BNSF Raton Subdivision due to restrictive signal indications of an unknown cause. The train encountered a series of approach, stop, and restricting signal aspects between approximately MP 744.3 and MP 720.7, requiring reduced-speed operation and compliance with dispatcher instructions through the affected territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(27)	43"	

Train 716(28) Oakland, CA - Third Party Contractor Engine Failure

28JUL26: Train 716(28), operating with CC/C8310, seven cars, and locomotive E/C2013, was delayed departing Oakland Jack London Square Station due to a late release from the Oakland Maintenance Facility. Mechanical technicians were completing repairs to replace a damaged handrail on the locomotive prior to releasing the equipment for service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(28)	55"	

Train 7/27(27) East of Wolf Point, MT - Freight Train Interference

28JUL26: Train 7/27(27) with 26, FOC 00625, 00000008485 customers onboard, was delayed east of Wolf Point, MT, while holding at Blair Siding (MP 180.3) on the BNSF Glasgow Subdivision to meet BNSF 7087.

Train	Delay	Comment
7/27(27)	31"	

Train 5(27) East of Glenwood Springs, CO - Signal Issues

28JUL26: Train 5(27), with 114 customers onboard, was delayed between mile post 351.0 and mile post 358.0, beginning 9 miles east of Glenwood Springs, CO/MP360.1, on the UP Glenwood Springs subdivision operating through a CTC system outage. Once clear of the affected area, train 5(27) continued west.

Train 5(27) was delayed once again for CTC failure east of Green River, UT station with issues between mile post 494.0 and mile post 499.0 on the UP Green River subdivision.

Train	Delay	Comment
5(27)	46"	
5(27)	36"	E/ GRI

Train 7/27(28) West of Chicago, IL - System

28JUL26: Train 7/27(28) with E/193-342, 10 cars, and 259 customers was delayed nine miles west of Chicago at MP 8.7 on the CPKC C&M subdivision due to PTC issues.

Train 7/27(28) was further delayed at Milwaukee, WI/MP85.4 on CPKC Watertown subdivision flat switching the engines due to an unrecoverable PTC reverser wiring fault on engine 342.

Train	Delay	Comment
7/27(28)	34"	Cut out PTC E/GLN
7/27(28)	1'13"	Flat Switch at MKE

Train 786(28) North of Lompoc-Surf, CA - Passenger Train Interference

28JUL26: Train 786(28), carrying 73 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.6) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(28) and 14(28).

Train	Delay	Comment
786(28)	37"	

Train 4(27) East of Lamy, NM - Passenger Train Interference

28JUL26: Train 4(27), carrying 159 customers onboard, was delayed east of Lamy NM, while holding at Fox Siding (MP 820.2) on the BNSF Glorieta Subdivision to meet Amtrak Train 3(27).

Train	Delay	Comment
4(27)	39"	

Train 3(27) West of Las Vegas, NM - Signal

28JUL26: Train 3(27) with 187 customers was delayed 39 miles west of Las Vegas, NM on the BNSF Raton subdivision. The delay was caused by receiving restrictive signals for unknown reasons from MP722.7 to MP735.2

Train	Delay	Comment
3 (27)	32"	

Train 391(28) North of Mattoon, IL - Trespasser Incident

28JUL26: 1137AM-CT, Train 391(28) with E/ID4628, seven cars, and 65 customers struck the flat bed on a tractor trailer on the CN Champaign subdivision 14 miles north of Mattoon at Springfield Road/MP 158.15 (DOT# 289125B) in Arcola, Illinois located in Douglas County. The operator of the tractor trailer operated around the downed crossing gates. There were two reported injuries of the customers onboard, who were taken to Sarah Bush Lincoln Health Center in Mattoon, Illinois. The locomotive engineer was evaluated by EMS. The outside temperature was 83 degrees and partly sunny. After impact, head end power was down for approximately one hour and twenty minutes while the crew worked with CNOC mechanical to restart the engine and restore head end power. Head end power was restored as of 1258PM-CT. During the disruption a community bus arrived on scene, rescued the customers, and delivered them to the Arcola Community Center. An Amtrak customer service representative responded to the Arcola Community Center to assist the customers. Two buses were secured as alternate transportation between the Arcola Community Center and Carbondale, Illinois. The conductor reported plow damage to E/ID4628. The plow was clear of the rail and within specifications with a plate missing on the engineer side. The tractor trailer and flat bed were clear of the tracks, but the truck and back axle of the trailer were fouling the right of way. A wrecker responded to remove the truck and trailer. Local authorities and state police were on the scene for an investigation. PTC was reported inactive on E/ID4628. The crew advanced the equipment into the clear at Mattoon/MP 172.3 and held for a relief crew. Once the relief crew arrived on scene the equipment wye'd at Effingham and was deadhead back to Chicago. As a result, train 392(28) was cancelled entirely with two buses secured as alternate transportation.

WBS#: B.TR.100150.6959

National Response Center Number: 1469166

Train	Delay	Comment
391 (28)	3'11"	

Train 341(28) Chicago, IL - Engine Failure

28JUL26: Train 341(28) with E/50, four cars, and E/514 with 114 customers was cancelled between Chicago and Milwaukee with alternate bus transportation due to E/50 bad ordered for air issues and C/35008 bad ordered for refrigeration. The switching necessary to fill out the train would have delayed customers at least two hours, so the train was cancelled to prevent any inconveniences. Once the equipment was made up, it was deadhead to Milwaukee for service on July 29.

WBS#: B.TR.100150.6958

Train 3(27) West of La Junta, CO - Signal

28JUL26: Train 3(27) with 187 customers was delayed 29 miles west of La Junta, CO on the BNSF Raton subdivision. The delay was caused by receiving restrictive signals for unknown reasons from MP580.3 to MP586.3

Train 2(26) West of Houston, TX - Commuter Train Interference

28JUL26: Train 2(26) was delayed just west of Houston on the UPRR Glidden subdivision due to LHT44-28 striking the rear of a tractor trailer at MP 52.8. Train 2(26) held at Lissie/MP 61.5 for an open route and then followed LHT44-28 to East Bernard/MP 49.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2 (26)	1'45"	

Train 3(26) West of Needles, CA - Engine Failure

28JUL26: Train 3(26), consisting of locomotives E/39 and E/4 and carrying 184 customers, stopped approximately 76 miles west of Needles, CA, on the BNSF Needles Subdivision after the crew received a hot bearing alarm on trailing locomotive E/4.

Following troubleshooting with CNOC Mechanical, it was determined that the bearing temperature did not exceed the established threshold, and the train was authorized to continue operation. After movement resumed, the hot box detector alarm activated again and could not be reset.

As a precaution, the crew was instructed to proceed at a maximum speed of 50 MPH for 10 miles and then conduct a reinspection of the affected locomotive. After reinspection was completed, crew took no exceptions and was authorized to resume operation at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3 (26)	57"	

Train 350(28) East of Chicago, IL - Police Related

28JUL26: Train 350(28) with 185 customers was delayed just south of Chicago due to a bridge strike reported on the NS Chicago district at the 35th Street bridge. Once the bridge was inspected with no exceptions train movement continued.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
350 (28)	52"	

Train 49/449(27) East of Toledo, OH - Freight Train Interference

28JUL26: Train 49/449(27) was delayed on the NS Toledo Terminal two miles east of Toledo at CP 286 due to 337-28 disabled ahead at CP 288 and being assisted into the yard to clear the route. Train 40(26) was delayed for the same reason and held at CP 285.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49/449 (27)	1'20"	
40 (26)	35"	

Texas Eagle Service Walnut Ridge, AR - Freight Train Interference

28JUL26: Trains 22(27), with 139 customers onboard, and 21(27), with 108 customers onboard, were delayed around Walnut Ridge, AR/MP224.9 meeting disabled UP freight UP/8038. The freight was 14,000ft long and a key train, requiring the conductor walk the length of it. Train 21(27) held at Minturn Junction 3.5 miles south of Walnut Ridge for an open route. Once the issue was resolved, train 22(27) followed UP/8038 to Walnut Ridge and operated around the freight there.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21 (27)	47"	
22 (27)	2'34"	

Train 765(28) South of Lompoc-Surf, CA UP Santa Barbara Subdivision - Loss of Shunt

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

28JUL26: Union Pacific Railroad advised that train 765(28) operating with E/C2113, C/34120, C/6803, C/6304, C/C6462, C/6407, and CC/6905 experienced a loss of shunt on July 28th, 2026 at 3:27:43 PM PST. This occurred south of Lompoc-Surf station at Honda/MP 303.4 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 427 seconds. UPRR signal department was notified, and shunt testing will be performed.

East and West of Chicago, IL - Downed Trees

27JUL26: The Hiawatha, Pere Marquette, Floridian, Lake Shore Limited, and Empire Builder Services reported downed trees west of Glenview, IL/MP17.32 on the CPKC C&M subdivision and west of Porter, IN/MP482.2 on the NS Chicago district and CSX Grand Rapids subdivision. Local Maintenance of Way teams were dispatched to their territories to clear the tracks but significant delays were incurred. Train 370(27) terminated at Porter, IN/MP482.2 due to a four-hour estimate to open track on the CSX Grand Rapids subdivision. Four buses were secured: bus one operated express to Holland, MI, Buses two and three operated express to Grand Rapids, MI, and bus four operated St Joseph and Bangor.

28JUL26: Delays continued on the CPKC C&M subdivision due to switch and signal issues west of Glenview. A generator was placed between Rondout/MP 32.3 and Wadsworth/MP 44.3 to restore signals. A separate generator was placed to restore signals between Lake Forest/MP 27.8 and Rondout/MP 32.3. Trains 329(28) and 330(28) were delayed operating through the area prior to the generators being placed. Train 330(28) arrived Chicago at 859AM-CT, 1 hour, and 2 minutes late. As a result, train 331(28) departed Chicago at 911AM-CT, 46 minutes late due to the late turn of this equipment.

WBS#: B.TR.100150.6954

Train	Delay	Comment
370(27)	Terminated XPI	Near Porter, IN
383(27)	19"	LAG
1340(27)	39"	SVT
352(27)	1'16"	XPI
339(27)	1'42"	W/GLN
364(27)	1'13"	XPI
342(27)	1'10"	Late Turn off 339(27)
7/27(27)	2'58"	GLN
341(27)	48"	Late Turn off 1340(27)
41(27)	3'18"	XPI
330(28)	40"	
329(28)	40"	
331(28)	46"	CHI - late turn of equip 330(28)

West of Kirkwood, MO - UP Freight Train Derailment

26JUL26: Due to a UPRR freight derailed at Kirkwood, MO/MP13.49, with 28 coal cars derailed and 900 feet of track damaged, train 316(26) is terminated at Washington, MO. with alternate buses secured. The equipment operated deadhead with BNSF pilots across a detour between Pacific/MP34.7 and St Louis, MO/MP1.5. Missouri River Runner Service is adjusted at follows:

-Train 311(27) was cancelled with alternate buses sourced. Bus One operated between St Louis, Kirkwood, Lee's Summit, and Kansas City. Bus Two operated between St Louis and Kansas City making all stops.

-Train 318(27) originated at St Louis with alternate buses sourced. Bus One operated express between Kansas City and St Louis. Bus Two operated between Kansas City, Lee's Summit, Kirkwood, and St Louis. Bus Three operated between Kansas City and St Louis making all stops.

-Train 316(27) was cancelled in its entirety with an alternate bus secured. Bus One operated between Kansas City and St Louis making all stops.

-Train 319(27) terminated at St Louis, with alternate buses secured. Bus One operated express between St Louis and Kansas City. Bus Two operated between St Louis, Kirkwood, Lee's Summit, and Kansas City. Bus Three operated between St Louis and Kansas City making all stops.

Train 316(26) was further delayed en route to Washington, MO by UP freight UP/5285 at Dow siding. The freight crew was having trouble repairing a broken knuckle.

27JUL26: UPRR advised the tentative track opening was midday on July 28. As a result, trains 311(28) and 316(28) were cancelled entirely with alternate transportation. Train 318(28) originated at St. Louis with alternate transportation and train 319(28) terminated at St. Louis with alternate transportation.

WBS#: B.TR.100150.6946

Train	Delay	Comment
316(26)	Terminated WAH	
316(27)	Cancelled	w/Alternate Bus
311(27)	Cancelled	w/Alternate Bus
318(27)	Originates at St Louis	w/Alternate Buses
319(27)	Terminates St Louis	w/Alternate Buses
311(28)	Cancelled	w/Alternate
316(28)	Cancelled	w/Alternate
318(28)	Originates STL	w/Alternate
319(28)	Terminates STL	w/Alternate
316(26)	2'47"	FTI E/SED

Train 1(25)/421(24) West of San Antonio, TX - Freight Train Interference

26JUL26: Train 1(25)/421(24) 00000008485 175 "UNCLASSIFIED" 8/7/2026 was delayed on the UPRR Del Rio subdivision 25 miles west of San Antonio at Lacoste/MP 235.9 due to east bound ZLBHO-23 stopped ahead at Dunlay/MP 247.4 with their lead locomotive shut down due to a low oil pressure fault and unable to restart. A rescue locomotive from MEWWC-24 at Noonan/MP 242.8 was dispatched to assist and clear the route. After accessing the main line, the rescue locomotive was bad ordered for crankcase pressure, rendering it unusable. A freight crew moved the bad ordered rescue locomotive back to the Noonan siding and delivered a second rescue locomotive long hood forward to continue the rescue effort. Train 2/422(24) with 209 customers held at Medina/MP 254.9 for an open route. Once the route was cleared, train 1(25)/421(24) continued to Hacienda/MP 307.5 to pickup a relief crew. Train 2/422(24) then followed ZLBHO-23 towards San Antonio and to Macdona/MP 225.4. Train 22(26) was delayed departing San Antonio due to holding for the late 422(24) section. Train 22(26)/422(24) departed San Antonio at 125PM-CT, 6 hours, and 37 minutes late.

27JUL26: Train 22(26)/422(24) arrived Marshall at 219AM-CT, 7 hours, and 15 minutes late. As a result, train 21/421(26) was delayed at Marshall due to the crew signing up on rest at 1030AM-CT. Once the crew signed up, briefed, and boarded the train, 21/421(26) departed Marshall at 1055AM-CT, 2 hours, and 33 minutes late.

Train 2(24) arrived New Orleans at 351AM-CT, 6 hours, and 11 minutes late. As a result, train 1(27) was delayed departing New Orleans due to the late turn of this equipment. Once the equipment was turned and serviced, 91 customers were welcomed aboard, and train 1(27) departed New Orleans at 1255PM-CT, 3 hours, and 55 minutes late.

WBS#: B.TR.100150.6944

Train	Delay	Comment
1(25)/421(24)	6'19"	W/SAS - ZLBHO-23
1(25)/421(24)	34"	Hacienda - relief crew
2/422(24)	6'11"	W/SAS - ZLBHO-23
22(26)	6'37"	SAS - held for connecting train 422(24)
1(27)	3'55"	NOL - late turn of equip 2(24)
21/421(26)	2'48"	MHL - crew rest

Pacific Surfliners San Clemente Pier, CA - Ocean Water Affecting Track Indication

25JUL26: Multiple Pacific Surfliner trains experienced delays due to high tide ocean conditions affecting the Metrolink Orange Subdivision east of San Clemente Pier, between approximately MP 206 and MP 207. The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. These restrictions resulted in cascading delays throughout the corridor, including additional train meets, congestion, and late-turn equipment impacts.

At approximately 11:50 PM PT, Metrolink reported a track-blocking event caused by a ballast washout in the same area. Maintenance crews were mobilized to make repairs, and rail service through the location was suspended pending restoration of the track structure.

Due to the overnight outage and the inability to secure bus transportation, the following Pacific Surfliner service adjustments were implemented:

- Train 595(25), carrying 461 customers onboard, was terminated at Oceanside (OSD) and returned toward its origin as a drop-off-only movement.
- Train 794(25), carrying 132 customers onboard, was terminated at Irvine (IRV) and returned toward its origin as a drop-off-only movement.
- Train 562(26) was canceled in its entirety, with customers directed to the next available service.
- Train 761(26) was canceled between San Diego and Los Angeles and instead originated in Los Angeles for service to Goleta (GTA).

Maintenance forces continued repair efforts while rail operators implemented service recovery measures across the corridor.

27JUL26: Track indication issues persist as high tides and oceans water reach the tracks.

28JUL26: Track indication issues persist as high tides and oceans water reach the tracks. There were some brief periods where all traffic was halted for Metrolink track inspectors to assess and restore some ballast that had washed away.

26-FOI-00625 00000008485 "UNCLASSIFIED" 8/7/2026

WBS#: B.TR.100150.6960

Train	Delay	Comment
794 (25)	Term IRV	
562 (26)	Cancel	
761 (26)	Cancel SAN-LAX	
782 (25)	1'14"	
786 (25)	1'58"	
584 (25)	1'55"	
593 (25)	58"	late turn 782
593 (25)	1'05"	
591 (25)	1'41"	
588 (25)	2'09"	
587 (25)	1'19"	
790 (25)	1'14"	
595 (25)	1'21"	late turn 584
595 (25)	1'10"	Term OSD
567 (26)	23"	
564 (26)	1'07"	
769 (26)	1'09"	
566 (26)	58"	
573 (26)	44"	
770 (44)	1'20"	
580 (26)	27"	
581 (26)	47"	late turn 770 (26)
785 (26)	13"	late turn 774 (26)
785 (26)	26"	
782 (26)	1'41"	
587 (26)	1'17"	
584 (26)	1'51'	
786 (26)	1'51"	
591 (26)	12"	late turn 580 (26)
591 (26)	1'05"	
593 (26)	1'10"	late turn 782 (26)
593 (26)	38"	
588 (26)	1'40"	
790 (26)	56"	
595 (26)	1'48"	late turn 584 (26)
794 (26)	15"	
595 (26)	1'45"	
567 (20)	10"	
562 (27)	26"	
769 (27)	33"	
564 (27)	27"	
786 (27)	23"	
588 (27)	1'04"	
584 (27)	25"	
587 (27)	22"	
790 (27)	1'35"	
794 (27)	47"	
593 (27)	56"	
595 (27)	24"	late turn 584 (27)
595 (27)	1'21"	
769 (28)	49"	
566 ((28)	49"	
587 (28)	1'35"	
786 (28)	1'23"	
591 (28)	2'33"	
588 (28)	1'39"	
593 (28)	2'17"	
790 (28)	2'32"	
595 (28)	2'45"	
782 (28)	28"	
770 (28)	1'02"	
581 (28)	24"	
572 (28)	24"	
794 (28)	47"	
584 (28)	30"	

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures in the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

25JUL26: Train 7(23) arrived into Seattle, WA 2'46" late causing late departure of 8(25). Train 27(23) arrived into Portland, OR 3'51" late causing late departure of 28(25).

25JUL26: Temperatures continue to be in excess of 100°F in the Great Plains. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow, Milk River and Hi-Line Subdivision from Stanley, ND and Cutbank, MT. Train 7 / 27(24) and Train 8 / 28(24) were affected by the restrictions and freight interference caused by the restrictions.

Due to late operation of 7/27(24) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(24) from Spokane to Seattle and for 27(24) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(26) Seattle to Spokane and 28(26) Portland to Spokane with Train 8/28(26) originating Spokane, WA.

27JUL26: Due to late operation of 7/27(25) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(25) from Spokane to Seattle and for 27(25) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(27) Seattle to Spokane and 28(27) Portland to Spokane with Train 8/28(27) originating Spokane, WA.

WBS#: B.TR.100150.6937

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	
8/28(24)	2'16"	
7/27(24)	2'20"	Term SPK
28(25)	57"	late turn 27(23)
8(25)	2'00"	late turn 7(23)
7/27(25)	2'26"	Term SPK
8/28(27)		Orig SPK
8/28(25)	1'46"	
8/28(26)	1'16"	Orig SPK
7/27(26)		Term SPK
8/28(28)		Orig SPK
8/28(27)	2'15"	Orig SPK

Maintenance of Way Highlights

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

-Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

-Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has to work scheduled "UNCLASSIFIED" C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No data

Western Region

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(28)	JOL	2	SMT	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00625

00000008485

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
175 (28)	BOS	175(28) will operate with a Business Class car in lieu of a coach.	none	0	81522
2165 (29)	BOS	Operates with Next Gen Acela set instead of Legacy Acela set - have the RSO check the war report.	PASSENGERS NOTIFIED	476	
448 (28)	CHI	Train 448 out of CHI has shopped car 25082(BYD*wheels with no replacement. The train is now over capacity. I have shut down sales on train 48 to help with the reaccommodation of passengers affected.	PASSENGERS MOVED TO 48(28)	32	25082
566 (29)	LAX	no bike space or wifi	NONE	0	90225
584 (29)	LAX	no bike space or wifi	NONE	0	90225
2190 (29)	NYP	Operates with Next Gen Acela set instead of Legacy Acela set - have the RSO check the war report.	PASSENGERS NOTIFIED	175	
579 (29)	SAN	no bike space or wifi	NONE	0	90225
595 (29)	SAN	no bike space or wifi	NONE	0	90225
125 (28)	SPG	125(28) will operate with a club-dinette in lieu of a coach.	none	0	48174
170 (28)	WAS	170(28) will operate with a Business Class car in lieu of a coach.	none	0	81522
2167 (29)	WAS	Operates with Next Gen Acela set instead of Legacy Acela set - have the RSO check the war report.	PASSENGERS NOTIFIED	470	
2128 (29)	WAS	Operates with Next Gen Acela set instead of Legacy Acela set - have the RSO check the war report.	PASSENGERS NOTIFIED	103	

Reverse Consists

Train Number	Station	Reason
138 (28)	NFK	Consist reversed Business class seat orientation may have changed At Front
93 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00625	00000008485 "UNCLASSIFIED" 8/7/2026
178 (28)	RNK	Consist reversed Business class seat orientation may have changed At Front	
171 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
183 (28)	NYP	Consist reversed Business class seat orientation may have changed At Front	
190 (28)	PHL	Consist reversed Business class seat orientation may have changed At Front	
136 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
125 (28)	SPG	Consist reversed Business class seat orientation may have changed At Front	
178 (28)	RNK	Consist reversed Business class seat orientation may have changed At Front	
138 (28)	NFK	Consist reversed Business class seat orientation may have changed At Front	
137 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
174 (28)	WAS	Consist reversed Business class seat orientation may have changed At Front	
67 (28)	BOS	Consist reversed Business class seat orientation may have changed At Front	
178 (29)	RNK	Consist reversed Business class seat orientation may have changed At Front	
125 (29)	SPG	Consist reversed Business class seat orientation may have changed At Front	
179 (29)	BOS	Consist reversed Business class seat orientation may have changed At Front	
86 (29)	NPN	Consist reversed Business class seat orientation may have changed At Front	
138 (29)	NFK	Consist reversed Business class seat orientation may have changed At Front	
173 (28)	BOS	Business class change only Business class seating orientation may have changed At Rear	