



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, April 11, 2026

Rules: 0-19



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	04/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 04/10/2026			ITP April 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	33	89.7%	3,100	370	88.1%	56,340	7,986	85.8%
Central Division	88.0%	69	8	88.4%	669	70	89.5%	12,598	1,368	89.1%
Northeast Division	82.0%	104	10	90.4%	1,008	110	89.1%	17,644	2,913	83.5%
Southeast Division	83.0%	71	6	91.5%	692	81	88.3%	12,982	1,968	84.8%
Southwest Division	86.0%	76	9	88.2%	731	109	85.1%	13,116	1,737	86.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00408 00000006306 UNCL ASSIFIED Endpoint Arrival Dates through 4/10/26 4/30/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	113,472	22,077	81%	1,095,909	221,125	80%	18,332,083	4,232,090	77%
Northeast Corridor	81%	46,776	3,222	93%	469,312	70,225	85%	8,092,528	1,877,449	77%
Acela	83%	9,304	664	93%	87,033	14,925	83%	1,581,891	427,203	73%
Northeast Regional	79%	37,472	2,558	93%	382,279	55,300	86%	6,510,637	1,450,246	78%
Richmond / Newport News / Norfolk	77%	11,058	114	99%	120,309	26,887	78%	2,071,215	518,794	75%
Springfield Shuttles	89%	1,019	35	97%	9,561	547	94%	112,470	14,620	87%
Roanoke	79%	4,328	153	96%	38,910	3,915	90%	613,794	115,477	81%
On Spine Northeast Regional	80%	21,067	2,256	89%	213,499	23,951	89%	3,713,158	801,355	78%
State Supported	80%	53,030	12,344	77%	494,185	94,814	81%	7,942,724	1,549,723	80%
Borealis	60%	625	184	71%	6,120	1,216	80%	103,427	23,365	77%
Capitol Corridor	90%	4,552	65	99%	41,839	3,983	90%	683,316	85,194	88%
Carolinian	60%	2,051	950	54%	13,898	6,207	55%	216,486	67,362	69%
Cascades	63%	2,556	1,260	51%	25,901	9,712	63%	449,306	111,765	75%
Downeaster	82%	1,640	0	100%	15,475	334	98%	271,010	34,485	87%
Empire	78%	6,482	2,521	61%	59,487	10,482	82%	976,268	206,045	79%
Adirondack	72%	332	0	100%	3,832	528	86%	58,602	20,646	65%
Ethan Allen Express	70%	645	301	53%	5,323	873	84%	104,695	27,837	73%
Maple Leaf	70%	928	522	44%	7,731	2,685	65%	107,974	43,831	59%
New York - Albany	85%	3,057	1,179	61%	28,436	4,697	83%	450,981	65,668	85%
New York - Niagara Falls	75%	1,520	519	66%	14,165	1,699	88%	254,016	48,063	81%
Gold Runner	73%	2,955	678	77%	27,313	6,741	75%	464,476	149,603	68%
Heartland Flyer	65%	259	171	34%	1,520	331	78%	36,669	13,705	63%
Hiawatha	90%	1,963	0	100%	19,240	2,366	88%	309,351	36,936	88%
Illinois	78%	3,001	1,125	63%	27,748	7,998	71%	444,694	118,199	73%
Carl Sandburg / Illinois Zephyr	85%	474	113	76%	4,503	1,719	62%	73,354	18,918	74%
Illini / Saluki	85%	1,093	0	100%	9,796	827	92%	160,797	35,987	78%
Lincoln Service	70%	1,434	1,012	29%	13,449	5,452	59%	210,543	63,294	70%
Keystone	92%	8,608	705	92%	86,029	8,151	91%	1,399,687	164,999	88%
Lincoln / Missouri	60%	940	668	29%	8,187	4,559	44%	140,897	68,183	52%
Mardi Gras Service	80%	426	15	96%	4,310	597	86%	77,508	11,228	86%
Michigan	69%	2,528	87	97%	24,327	6,379	74%	348,873	103,206	70%
Blue Water	70%	562	16	97%	5,820	2,627	55%	82,780	27,363	67%
Pere Marquette	85%	410	0	100%	2,903	153	95%	44,932	8,047	82%
Wolverine	65%	1,556	71	95%	15,604	3,599	77%	221,161	67,796	69%
Missouri	80%	283	0	100%	2,282	348	85%	40,620	7,312	82%
Pacific Surfliner	85%	10,196	2,850	72%	93,479	18,210	81%	1,344,249	202,600	85%
Pennsylvanian	72%	949	1	100%	9,402	1,306	86%	167,514	25,906	85%
Piedmont	73%	1,680	982	42%	14,535	4,394	70%	225,709	52,245	77%
Vermont	75%	1,336	82	94%	13,093	1,500	89%	242,664	67,385	72%
Long Distance	56%	13,666	6,511	52%	132,412	56,086	58%	2,257,564	802,455	64%
Auto Train	57%	915	915	0%	9,753	5,868	40%	144,015	40,371	72%
California Zephyr	50%	979	179	82%	10,146	2,912	71%	182,151	54,572	70%
Cardinal	55%	279	194	30%	2,741	1,337	51%	46,003	20,493	55%
City Of New Orleans	75%	814	328	60%	7,184	2,172	70%	125,364	27,017	78%
Coast Starlight	60%	1,223	294	76%	13,434	5,256	61%	206,150	68,102	67%
Crescent	70%	1,263	449	64%	10,745	3,016	72%	170,314	39,106	77%
Empire Builder	55%	1,053	570	46%	10,375	4,869	53%	170,642	69,737	59%
Floridian	40%	1,538	1,292	16%	17,533	13,819	21%	301,645	174,177	42%
Lake Shore Ltd	73%	992	502	49%	9,448	2,582	73%	173,313	46,755	73%
Palmetto	65%	970	566	42%	9,370	3,224	66%	172,633	33,037	81%
Silver Meteor	45%	1,076	614	43%	11,054	3,669	67%	189,994	64,223	66%
Southwest Chief	40%	779	283	64%	7,496	3,148	58%	143,038	84,678	41%
Sunset Ltd	70%	842	43	95%	3,564	1,387	61%	53,320	15,501	71%
Texas Eagle	50%	943	282	70%	9,569	2,827	70%	178,982	64,686	64%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00400 000000000000 "UNCLASSIFIED" 4/00/2020

Train Index Dates Through April 10, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	54,531	1,077,089	506	1,081,895	19,922,446	543

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,899	314,858	92	51,066	5,690,132	90
INFRASTRUCTURE PLANNED	135	3,401	314,858	108	41,447	5,690,132	73
FLEET RELIABILITY	90	6,934	1,077,089	64	186,447	19,922,446	94
TRAIN OPERATIONS	424	41,297	1,077,089	383	802,935	19,922,446	403

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	04/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 04/10/2026			ITP April 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	33	89.7%	3,100	370	88.1%	56,340	7,986	85.8%
Central Division	88.0%	69	8	88.4%	669	70	89.5%	12,598	1,368	89.1%
Northeast Division	82.0%	104	10	90.4%	1,008	110	89.1%	17,644	2,913	83.5%
Southeast Division	83.0%	71	6	91.5%	692	81	88.3%	12,982	1,968	84.8%
Southwest Division	86.0%	76	9	88.2%	731	109	85.1%	13,116	1,737	86.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-004 Initial Terminal Performance By Terminal

Scheduled Departure Date: 04/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 04/10/2026			ITP April 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	33	89.7%	3,100	370	88.1%	56,340	7,986	85.8%
Central Division	88.0%	69	8	88.4%	669	70	89.5%	12,598	1,368	89.1%
CDL	95.0%	2	0	100.0%	20	0	100.0%	353	12	96.6%
CHI	86.0%	28	2	92.9%	272	30	89.0%	5,065	652	87.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	-	-	-	57	2	96.5%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	20	0	100.0%	376	44	88.3%
EVR	-	-	-	-	2	2	0.0%	2	2	0.0%
GRR	95.5%	1	1	0.0%	8	1	87.5%	181	7	96.1%
KCY	92.0%	2	0	100.0%	20	2	90.0%	378	25	93.4%
MHL	-	1	1	0.0%	4	1	75.0%	17	7	58.8%
MKE	92.0%	6	0	100.0%	59	4	93.2%	1,124	76	93.2%
MSP	96.5%	1	0	100.0%	10	0	100.0%	185	4	97.8%
PDX	86.0%	5	1	80.0%	50	6	88.0%	940	118	87.4%
PNT	88.0%	3	0	100.0%	30	1	96.7%	480	48	90.0%
PTH	93.0%	1	0	100.0%	10	0	100.0%	181	10	94.5%
QCY	91.0%	2	0	100.0%	19	1	94.7%	372	29	92.2%
SEA	85.0%	8	1	87.5%	79	16	79.7%	1,495	219	85.4%
SPK	90.0%	1	0	100.0%	10	0	100.0%	185	15	91.9%
STL	89.0%	4	2	50.0%	39	4	89.7%	733	72	90.2%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	17	2	88.2%	369	10	97.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	104	10	90.4%	1,008	110	89.1%	17,644	2,913	83.5%
ALB	88.5%	8	1	87.5%	80	4	95.0%	1,376	137	90.0%
BON	87.5%	5	2	60.0%	50	2	96.0%	929	103	88.9%
BOS	85.5%	18	0	100.0%	177	13	92.7%	3,235	425	86.9%
BRK	92.5%	5	0	100.0%	50	0	100.0%	905	55	93.9%
BTN	82.0%	1	0	100.0%	9	0	100.0%	178	29	83.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	20	0	100.0%	370	36	90.3%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.0%	1	0	100.0%	10	0	100.0%	175	33	81.1%
NFL	93.5%	2	0	100.0%	23	1	95.7%	388	20	94.8%
NFS	-	-	-	-	-	-	-	3	3	0.0%
NHV	78.0%	6	0	100.0%	57	2	96.5%	1,007	196	80.5%
NYP	75.5%	47	7	85.1%	445	85	80.9%	7,429	1,733	76.7%
ROC	-	-	-	-	1	1	0.0%	2	2	0.0%
SAB	98.0%	1	0	100.0%	10	0	100.0%	182	2	98.9%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	1	1	0.0%	2	2	0.0%
SPG	92.5%	7	0	100.0%	69	0	100.0%	1,211	71	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	6	1	83.3%	181	47	74.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 04/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 04/10/2026			ITP April 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	33	89.7%	3,100	370	88.1%	56,340	7,986	85.8%
Northeast Division	82.0%	104	10	90.4%	1,008	110	89.1%	17,644	2,913	83.5%
WEM	-	-	-	-	-	-	-	20	12	40.0%
Southeast Division	83.0%	71	6	91.5%	692	81	88.3%	12,982	1,968	84.8%
ATL	-	-	-	-	-	-	-	34	4	88.2%
CLT	91.5%	5	0	100.0%	50	2	96.0%	940	71	92.4%
GRO	-	-	-	-	-	-	-	9	3	66.7%
HAR	79.5%	13	0	100.0%	118	18	84.7%	2,122	408	80.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	1	0.0%	10	3	70.0%	189	29	84.7%
MIA	89.5%	2	1	50.0%	20	3	85.0%	377	36	90.5%
MOE	97.5%	2	0	100.0%	20	0	100.0%	384	5	98.7%
NFK	84.5%	2	0	100.0%	20	3	85.0%	459	65	85.8%
NOL	94.5%	4	0	100.0%	44	1	97.7%	803	35	95.6%
NPN	93.0%	2	1	50.0%	20	3	85.0%	351	21	94.0%
PGH	93.0%	1	0	100.0%	10	0	100.0%	190	11	94.2%
PHL	48.0%	5	2	60.0%	48	25	47.9%	1,021	523	48.8%
RGH	95.0%	4	0	100.0%	40	2	95.0%	755	28	96.3%
RNK	83.5%	2	0	100.0%	18	0	100.0%	372	54	85.5%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	10	0	100.0%	188	5	97.3%
SFA	88.0%	1	0	100.0%	10	4	60.0%	189	24	87.3%
WAS	84.0%	26	1	96.2%	254	17	93.3%	4,477	629	86.0%
Southwest Division	86.0%	76	9	88.2%	731	109	85.1%	13,116	1,737	86.8%
ARN	92.0%	1	0	100.0%	10	1	90.0%	191	13	93.2%
BFD	79.0%	6	1	83.3%	60	8	86.7%	1,149	230	80.0%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	1	0.0%	10	4	60.0%	206	57	72.3%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	2	1	50.0%	14	5	64.3%	205	22	89.3%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GTA	90.0%	3	1	66.7%	30	2	93.3%	576	52	91.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	1	90.9%	104	17	83.7%	1,830	180	90.2%
MCD	-	-	-	-	-	-	-	6	6	0.0%
OKC	97.0%	1	0	100.0%	9	0	100.0%	186	3	98.4%
OKJ	74.5%	12	2	83.3%	112	30	73.2%	1,967	492	75.0%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	88.5%	16	2	87.5%	152	17	88.8%	2,613	276	89.4%
SAN	90.5%	13	0	100.0%	128	15	88.3%	2,222	197	91.1%
SAS	90.5%	1	0	100.0%	10	0	100.0%	187	14	92.5%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	89.0%	7	0	100.0%	70	8	88.6%	1,341	135	89.9%
SKN	-	-	-	-	-	-	-	6	5	16.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	04/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 04/10/2026			ITP April 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	33	89.7%	3,100	370	88.1%	56,340	7,986	85.8%
Southwest Division	86.0%	76	9	88.2%	731	109	85.1%	13,116	1,737	86.8%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	20	2	90.0%	361	31	91.4%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	2	0	100.0%	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		4	0	100.0%	81	5	93.8%	5	1	80.0%	82	11	86.6%
2		5	2	60.0%	82	16	80.5%	4	1	75.0%	79	11	86.1%
3		10	1	90.0%	191	32	83.2%	10	2	80.0%	190	79	58.4%
4		10	3	70.0%	190	26	86.3%	10	4	60.0%	190	122	35.8%
5		10	0	100.0%	190	34	82.1%	10	2	80.0%	186	41	78.0%
6		10	4	60.0%	189	50	73.5%	10	2	80.0%	189	51	73.0%
7		10	0	100.0%	179	25	86.0%	9	3	66.7%	172	36	79.1%
8	107	10	5	50.0%	179	76	57.5%	10	7	30.0%	178	91	48.9%
11		10	2	80.0%	190	34	82.1%	9	1	88.9%	184	34	81.5%
14		10	3	70.0%	191	25	86.9%	10	3	70.0%	189	50	73.5%
19		10	2	80.0%	189	41	78.3%	10	1	90.0%	189	27	85.7%
20		10	0	100.0%	189	11	94.2%	10	2	80.0%	189	23	87.8%
21		10	1	90.0%	186	19	89.8%	10	2	80.0%	185	38	79.5%
22		10	0	100.0%	187	13	93.0%	10	1	90.0%	187	37	80.2%
23		10	0	100.0%	192	4	97.9%	10	1	90.0%	192	36	81.3%
24		10	0	100.0%	192	12	93.8%	10	0	100.0%	192	19	90.1%
25		10	0	100.0%	192	1	99.5%	10	4	60.0%	191	36	81.2%
26		10	0	100.0%	192	3	98.4%	10	0	100.0%	191	26	86.4%
27		10	4	60.0%	178	12	93.3%	10	4	60.0%	175	49	72.0%
28		10	3	70.0%	175	41	76.6%	10	2	80.0%	175	29	83.4%
40	496	10	2	80.0%	185	24	87.0%	10	7	30.0%	185	69	62.7%
41	100	10	5	50.0%	186	75	59.7%	10	8	20.0%	186	124	33.3%
42		10	0	100.0%	191	12	93.7%	10	1	90.0%	189	30	84.1%
43		10	0	100.0%	190	33	82.6%	10	4	60.0%	190	27	85.8%
48	75	10	2	80.0%	189	38	79.9%	10	3	70.0%	189	29	84.7%
49		10	3	70.0%	189	54	71.4%	10	1	90.0%	189	38	79.9%
50		4	1	75.0%	80	21	73.8%	5	2	60.0%	80	40	50.0%
52	183	10	4	60.0%	189	24	87.3%	10	6	40.0%	189	37	80.4%
53	120	10	3	70.0%	189	29	84.7%	10	5	50.0%	189	46	75.7%
55		8	0	100.0%	113	4	96.5%	8	0	100.0%	111	22	80.2%
56	44	8	0	100.0%	113	16	85.8%	8	1	87.5%	112	19	83.0%
58	42	10	1	90.0%	183	8	95.6%	10	4	60.0%	182	33	81.9%
59		10	0	100.0%	182	18	90.1%	10	1	90.0%	181	20	89.0%
63		10	1	90.0%	192	88	54.2%	9	1	88.9%	189	85	55.0%
64	24	10	2	80.0%	190	52	72.6%	10	5	50.0%	190	50	73.7%
66		10	2	80.0%	189	40	78.8%	10	0	100.0%	189	35	81.5%
67		7	0	100.0%	130	9	93.1%	8	1	87.5%	131	17	87.0%
68		10	0	100.0%	192	42	78.1%	10	0	100.0%	192	89	53.6%
69		10	3	70.0%	179	29	83.8%	10	2	80.0%	176	21	88.1%
71	22	10	0	100.0%	187	2	98.9%	10	3	70.0%	187	46	75.4%
72		10	1	90.0%	187	15	92.0%	10	2	80.0%	187	30	84.0%
73	15	10	1	90.0%	191	9	95.3%	10	6	40.0%	190	94	50.5%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74	18	10	0	100.0%	191	20	89.5%	10	4	60.0%	190	59	68.9%
75	27	10	0	100.0%	190	7	96.3%	10	3	70.0%	187	77	58.8%
76	22	10	0	100.0%	190	12	93.7%	10	6	40.0%	184	70	62.0%
77	41	10	1	90.0%	189	12	93.7%	10	7	30.0%	188	70	62.8%
78		10	0	100.0%	188	10	94.7%	10	3	70.0%	187	26	86.1%
79		10	2	80.0%	189	37	80.4%	10	4	60.0%	188	38	79.8%
80		10	1	90.0%	189	15	92.1%	10	0	100.0%	188	23	87.8%
84		8	1	87.5%	106	10	90.6%	8	1	87.5%	106	21	80.2%
85		8	0	100.0%	114	11	90.4%	8	0	100.0%	114	40	64.9%
86		8	2	75.0%	114	9	92.1%	8	4	50.0%	113	59	47.8%
89	52	9	3	66.7%	187	38	79.7%	9	2	77.8%	186	41	78.0%
90		10	0	100.0%	188	5	97.3%	9	1	88.9%	187	17	90.9%
93		8	1	87.5%	113	15	86.7%	8	1	87.5%	112	19	83.0%
94	187	8	1	87.5%	144	35	75.7%	8	4	50.0%	143	46	67.8%
95		8	0	100.0%	113	2	98.2%	8	3	62.5%	113	32	71.7%
97		10	9	10.0%	190	114	40.0%	10	4	60.0%	190	44	76.8%
98		10	1	90.0%	189	11	94.2%	10	3	70.0%	188	44	76.6%
110		8	8	0.0%	111	62	44.1%	8	1	87.5%	110	11	90.0%
111	73	8	3	62.5%	104	19	81.7%	8	2	75.0%	104	14	86.5%
112		8	0	100.0%	104	10	90.4%	8	1	87.5%	104	15	85.6%
113		8	0	100.0%	35	10	71.4%	8	0	100.0%	35	7	80.0%
119		8	1	87.5%	104	27	74.0%	8	1	87.5%	103	15	85.4%
125		8	0	100.0%	114	5	95.6%	8	3	62.5%	114	39	65.8%
129		8	0	100.0%	113	36	68.1%	8	2	75.0%	113	15	86.7%
130		8	1	87.5%	104	11	89.4%	8	0	100.0%	103	7	93.2%
131		8	3	62.5%	106	32	69.8%	8	0	100.0%	106	16	84.9%
134		8	2	75.0%	114	18	84.2%	8	2	75.0%	113	19	83.2%
136		8	2	75.0%	114	14	87.7%	8	0	100.0%	112	10	91.1%
137		8	1	87.5%	111	21	81.1%	8	1	87.5%	111	31	72.1%
138		8	1	87.5%	114	16	86.0%	8	2	75.0%	113	12	89.4%
141		8	0	100.0%	113	3	97.3%	8	1	87.5%	113	22	80.5%
148		8	2	75.0%	113	15	86.7%	8	2	75.0%	111	23	79.3%
151		10	5	50.0%	188	54	71.3%	10	4	60.0%	187	57	69.5%
170		8	0	100.0%	109	10	90.8%	8	0	100.0%	109	26	76.1%
171		8	0	100.0%	114	8	93.0%	8	2	75.0%	114	31	72.8%
172		8	0	100.0%	113	11	90.3%	8	0	100.0%	111	38	65.8%
173		8	1	87.5%	109	16	85.3%	8	2	75.0%	109	48	56.0%
174		8	0	100.0%	114	14	87.7%	8	1	87.5%	114	20	82.5%
175		8	1	87.5%	114	18	84.2%	8	1	87.5%	114	37	67.5%
176		8	0	100.0%	109	9	91.7%	8	0	100.0%	109	8	92.7%
177		8	1	87.5%	114	18	84.2%	8	1	87.5%	114	36	68.4%
178		8	0	100.0%	114	16	86.0%	7	0	100.0%	113	18	84.1%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179	19	8	0	100.0%	114	10	91.2%	8	4	50.0%	114	31	72.8%
181		8	3	62.5%	110	28	74.5%	8	0	100.0%	109	5	95.4%
182		8	1	87.5%	104	17	83.7%	8	1	87.5%	104	8	92.3%
183	19	8	2	75.0%	113	33	70.8%	8	6	25.0%	112	24	78.6%
184		8	1	87.5%	114	20	82.5%	8	0	100.0%	114	18	84.2%
185	18	8	2	75.0%	114	26	77.2%	8	1	87.5%	114	9	92.1%
186		8	1	87.5%	113	12	89.4%	8	1	87.5%	113	21	81.4%
190		8	1	87.5%	113	47	58.4%	8	2	75.0%	113	27	76.1%
192		8	0	100.0%	111	16	85.6%	8	1	87.5%	111	9	91.9%
193		8	2	75.0%	113	47	58.4%	8	2	75.0%	113	44	61.1%
196		8	0	100.0%	113	8	92.9%	8	0	100.0%	113	11	90.3%
197		8	4	50.0%	114	47	58.8%	8	1	87.5%	114	28	75.4%
198		8	0	100.0%	46	9	80.4%	8	2	75.0%	45	5	88.9%
230		10	2	80.0%	26	2	92.3%	10	1	90.0%	26	3	88.5%
232		10	0	100.0%	192	10	94.8%	10	0	100.0%	192	14	92.7%
233	27	10	1	90.0%	176	40	77.3%	10	4	60.0%	176	34	80.7%
234		10	0	100.0%	192	18	90.6%	10	0	100.0%	192	18	90.6%
235	29	10	0	100.0%	116	17	85.3%	10	2	80.0%	116	21	81.9%
236		10	1	90.0%	176	6	96.6%	10	0	100.0%	176	22	87.5%
237		10	1	90.0%	191	41	78.5%	10	1	90.0%	189	34	82.0%
238		10	0	100.0%	116	12	89.7%	10	0	100.0%	115	8	93.0%
239	22	10	3	70.0%	191	58	69.6%	10	3	70.0%	190	21	88.9%
240	21	10	0	100.0%	192	17	91.1%	10	2	80.0%	191	22	88.5%
241	29	10	5	50.0%	192	49	74.5%	10	4	60.0%	192	46	76.0%
243		10	6	40.0%	128	44	65.6%	10	1	90.0%	129	20	84.5%
244		10	0	100.0%	176	7	96.0%	10	3	70.0%	176	28	84.1%
245		10	0	100.0%	73	16	78.1%	10	1	90.0%	72	8	88.9%
280		10	1	90.0%	192	10	94.8%	10	1	90.0%	192	35	81.8%
281	114	10	1	90.0%	192	22	88.5%	10	2	80.0%	192	32	83.3%
283		10	0	100.0%	192	43	77.6%	10	0	100.0%	192	35	81.8%
284		10	0	100.0%	192	9	95.3%	10	0	100.0%	190	30	84.2%
290		10	1	90.0%	192	38	80.2%	10	1	90.0%	190	55	71.1%
291		10	2	80.0%	191	44	77.0%	9	1	88.9%	189	30	84.1%
300	185	9	2	77.8%	176	15	91.5%	9	4	55.6%	174	42	75.9%
301	19	10	0	100.0%	190	8	95.8%	10	5	50.0%	187	34	81.8%
302	50	10	1	90.0%	177	25	85.9%	10	4	60.0%	174	52	70.1%
305		10	1	90.0%	180	24	86.7%	10	5	50.0%	176	69	60.8%
306	34	10	0	100.0%	188	12	93.6%	10	2	80.0%	187	43	77.0%
307		10	2	80.0%	180	29	83.9%	9	2	77.8%	177	46	74.0%
311		10	1	90.0%	191	19	90.1%	10	3	70.0%	188	31	83.5%
316		10	2	80.0%	188	10	94.7%	10	1	90.0%	187	31	83.4%
318		10	0	100.0%	191	16	91.6%	10	6	40.0%	189	80	57.7%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
319	65	10	1	90.0%	192	13	93.2%	10	5	50.0%	191	96	49.7%
329		8	0	100.0%	135	7	94.8%	8	0	100.0%	135	12	91.1%
330		9	1	88.9%	162	3	98.1%	9	1	88.9%	162	13	92.0%
331		10	3	70.0%	192	24	87.5%	10	3	70.0%	192	29	84.9%
332		10	0	100.0%	192	12	93.8%	10	1	90.0%	192	28	85.4%
334		10	1	90.0%	192	6	96.9%	10	1	90.0%	191	26	86.4%
335		10	1	90.0%	192	23	88.0%	10	1	90.0%	190	31	83.7%
336		10	0	100.0%	192	8	95.8%	10	1	90.0%	190	13	93.2%
337		10	1	90.0%	192	12	93.8%	9	1	88.9%	188	22	88.3%
338		10	1	90.0%	192	33	82.8%	10	3	70.0%	190	60	68.4%
339		10	1	90.0%	192	37	80.7%	10	1	90.0%	192	37	80.7%
341		10	2	80.0%	183	24	86.9%	10	3	70.0%	180	26	85.6%
342		10	1	90.0%	192	14	92.7%	10	2	80.0%	190	37	80.5%
350	25	10	1	90.0%	173	13	92.5%	10	8	20.0%	169	90	46.7%
351		10	0	100.0%	177	19	89.3%	10	1	90.0%	177	56	68.4%
352		10	0	100.0%	176	14	92.0%	10	2	80.0%	171	49	71.3%
353		10	0	100.0%	151	12	92.1%	10	1	90.0%	146	25	82.9%
354		10	1	90.0%	175	16	90.9%	10	2	80.0%	172	55	68.0%
355		10	1	90.0%	187	23	87.7%	10	3	70.0%	181	59	67.4%
364		10	1	90.0%	185	48	74.1%	10	3	70.0%	179	52	70.9%
365		10	0	100.0%	181	10	94.5%	10	5	50.0%	180	58	67.8%
370		8	2	75.0%	184	24	87.0%	8	1	87.5%	180	39	78.3%
371		8	1	87.5%	181	7	96.1%	8	0	100.0%	180	20	88.9%
380		9	1	88.9%	180	22	87.8%	9	2	77.8%	180	37	79.4%
381		10	1	90.0%	192	9	95.3%	10	2	80.0%	192	28	85.4%
382		10	0	100.0%	192	7	96.4%	10	8	20.0%	192	54	71.9%
383		10	1	90.0%	181	22	87.8%	10	5	50.0%	179	72	59.8%
390		10	0	100.0%	175	13	92.6%	10	1	90.0%	174	48	72.4%
391		10	0	100.0%	177	5	97.2%	10	1	90.0%	174	35	79.9%
392		10	0	100.0%	191	4	97.9%	10	1	90.0%	189	43	77.2%
393		10	0	100.0%	192	14	92.7%	10	1	90.0%	191	48	74.9%
417		8	0	100.0%	124	29	76.6%	8	0	100.0%	115	12	89.6%
425		8	0	100.0%	127	6	95.3%	8	0	100.0%	127	6	95.3%
448	132	10	2	80.0%	125	32	74.4%	10	2	80.0%	123	43	65.0%
449		10	1	90.0%	123	14	88.6%	10	1	90.0%	123	20	83.7%
470		8	0	100.0%	136	30	77.9%	8	0	100.0%	131	21	84.0%
471		8	0	100.0%	127	4	96.9%	8	0	100.0%	127	1	99.2%
473		8	0	100.0%	133	12	91.0%	8	0	100.0%	130	8	93.8%
474		8	1	87.5%	126	41	67.5%	8	1	87.5%	117	29	75.2%
475		8	0	100.0%	132	3	97.7%	8	0	100.0%	132	3	97.7%
478		8	0	100.0%	124	23	81.5%	8	0	100.0%	123	15	87.8%
479		8	0	100.0%	132	18	86.4%	8	1	87.5%	130	12	90.8%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
486		8	0	100.0%	135	19	85.9%	8	1	87.5%	130	34	73.8%
490		8	1	87.5%	110	31	71.8%	8	0	100.0%	104	14	86.5%
494	148	9	3	66.7%	136	23	83.1%	8	2	75.0%	131	34	74.0%
495		8	0	100.0%	122	3	97.5%	8	0	100.0%	121	2	98.3%
500		10	1	90.0%	186	12	93.5%	10	0	100.0%	185	22	88.1%
502		10	0	100.0%	190	11	94.2%	10	0	100.0%	188	38	79.8%
503	17	10	0	100.0%	188	18	90.4%	10	7	30.0%	184	50	72.8%
504	54	10	0	100.0%	192	14	92.7%	10	5	50.0%	190	55	71.1%
505		10	3	70.0%	190	28	85.3%	10	3	70.0%	188	47	75.0%
506	No OS	10	2	80.0%	188	25	86.7%	10	3	70.0%	187	29	84.5%
507		10	3	70.0%	192	24	87.5%	10	5	50.0%	192	62	67.7%
508	21	10	0	100.0%	189	34	82.0%	10	5	50.0%	186	39	79.0%
509		10	1	90.0%	189	10	94.7%	10	3	70.0%	189	43	77.2%
511		10	0	100.0%	185	18	90.3%	10	3	70.0%	185	32	82.7%
516	18	9	2	77.8%	185	18	90.3%	8	6	25.0%	184	74	59.8%
517	253	10	2	80.0%	192	5	97.4%	10	7	30.0%	190	62	67.4%
518	54	10	0	100.0%	192	24	87.5%	9	6	33.3%	190	117	38.4%
519		9	2	77.8%	185	8	95.7%	8	2	75.0%	183	41	77.6%
520		8	1	87.5%	94	15	84.0%	8	0	100.0%	92	8	91.3%
521		8	1	87.5%	132	5	96.2%	8	1	87.5%	132	15	88.6%
522	29	8	1	87.5%	132	22	83.3%	8	1	87.5%	129	12	90.7%
523		8	0	100.0%	132	5	96.2%	8	0	100.0%	132	15	88.6%
524		8	0	100.0%	132	8	93.9%	8	1	87.5%	131	14	89.3%
525		8	0	100.0%	130	8	93.8%	8	1	87.5%	128	12	90.6%
526		8	2	75.0%	106	18	83.0%	8	0	100.0%	104	10	90.4%
527		8	0	100.0%	132	5	96.2%	8	0	100.0%	132	18	86.4%
528		8	0	100.0%	132	10	92.4%	8	2	75.0%	132	24	81.8%
529		8	1	87.5%	132	8	93.9%	8	4	50.0%	131	33	74.8%
530		8	1	87.5%	86	9	89.5%	8	1	87.5%	86	11	87.2%
531		8	2	75.0%	106	8	92.5%	8	0	100.0%	106	9	91.5%
532		8	3	62.5%	132	26	80.3%	8	2	75.0%	132	20	84.8%
534		8	0	100.0%	91	15	83.5%	8	0	100.0%	90	7	92.2%
535		8	1	87.5%	119	16	86.6%	8	2	75.0%	116	16	86.2%
536	11	8	5	37.5%	132	32	75.8%	8	4	50.0%	129	21	83.7%
537		8	2	75.0%	103	10	90.3%	7	1	85.7%	98	7	92.9%
538		8	1	87.5%	132	18	86.4%	8	1	87.5%	132	27	79.5%
539		8	2	75.0%	86	10	88.4%	8	3	62.5%	86	40	53.5%
540		8	1	87.5%	132	22	83.3%	8	0	100.0%	126	11	91.3%
541		8	0	100.0%	131	13	90.1%	8	3	62.5%	130	21	83.8%
542		8	2	75.0%	132	17	87.1%	8	1	87.5%	131	25	80.9%
543	15	8	1	87.5%	132	9	93.2%	8	3	62.5%	132	34	74.2%
544		8	1	87.5%	130	16	87.7%	8	1	87.5%	128	11	91.4%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
545		8	1	87.5%	132	11	91.7%	8	1	87.5%	130	16	87.7%
547		8	1	87.5%	132	26	80.3%	8	2	75.0%	132	33	75.0%
548		8	0	100.0%	132	18	86.4%	8	0	100.0%	132	9	93.2%
549		8	0	100.0%	128	18	85.9%	8	1	87.5%	124	12	90.3%
550		8	1	87.5%	86	10	88.4%	8	2	75.0%	86	17	80.2%
551		8	1	87.5%	128	10	92.2%	8	0	100.0%	122	9	92.6%
562		10	1	90.0%	186	18	90.3%	10	1	90.0%	183	23	87.4%
564		10	1	90.0%	186	13	93.0%	10	1	90.0%	180	20	88.9%
566	42	10	0	100.0%	184	9	95.1%	10	2	80.0%	181	24	86.7%
567		10	0	100.0%	71	3	95.8%	10	0	100.0%	71	3	95.8%
572		10	2	80.0%	181	15	91.7%	10	2	80.0%	178	41	77.0%
573		10	1	90.0%	184	28	84.8%	10	1	90.0%	178	29	83.7%
579		10	1	90.0%	71	4	94.4%	9	2	77.8%	68	12	82.4%
580	19	10	1	90.0%	186	8	95.7%	9	1	88.9%	183	16	91.3%
581		10	2	80.0%	186	27	85.5%	10	4	60.0%	186	41	78.0%
584	37	10	1	90.0%	71	8	88.7%	9	4	55.6%	69	34	50.7%
586		9	1	88.9%	184	28	84.8%	9	1	88.9%	175	22	87.4%
587		10	2	80.0%	182	11	94.0%	8	2	75.0%	174	27	84.5%
588	55	10	2	80.0%	71	4	94.4%	10	4	60.0%	71	7	90.1%
591	47	10	1	90.0%	185	9	95.1%	9	2	77.8%	181	18	90.1%
593	67	10	1	90.0%	182	24	86.8%	8	2	75.0%	170	19	88.8%
595	16	10	2	80.0%	185	31	83.2%	10	3	70.0%	184	29	84.2%
600		8	0	100.0%	141	7	95.0%	8	0	100.0%	140	13	90.7%
601		8	3	62.5%	124	65	47.6%	7	1	85.7%	121	22	81.8%
605		8	5	37.5%	131	88	32.8%	8	3	62.5%	128	18	85.9%
607		8	3	62.5%	140	17	87.9%	8	2	75.0%	138	18	87.0%
609		8	0	100.0%	131	21	84.0%	8	1	87.5%	131	11	91.6%
626		8	2	75.0%	45	9	80.0%	8	1	87.5%	44	11	75.0%
639		8	1	87.5%	113	29	74.3%	8	0	100.0%	113	15	86.7%
640	25	8	0	100.0%	131	5	96.2%	8	4	50.0%	130	57	56.2%
641		8	0	100.0%	113	23	79.6%	8	0	100.0%	113	20	82.3%
642		8	0	100.0%	129	4	96.9%	8	1	87.5%	129	20	84.5%
643	31	8	1	87.5%	143	33	76.9%	8	1	87.5%	141	27	80.9%
644		8	1	87.5%	135	24	82.2%	8	1	87.5%	134	38	71.6%
645		8	1	87.5%	143	33	76.9%	8	1	87.5%	141	29	79.4%
646		8	2	75.0%	132	40	69.7%	8	4	50.0%	131	67	48.9%
647		8	1	87.5%	143	27	81.1%	8	2	75.0%	143	34	76.2%
648		8	3	62.5%	140	38	72.9%	8	2	75.0%	140	21	85.0%
649		8	0	100.0%	144	23	84.0%	8	1	87.5%	142	28	80.3%
650		8	1	87.5%	143	35	75.5%	8	1	87.5%	142	23	83.8%
651		8	1	87.5%	143	13	90.9%	8	1	87.5%	142	32	77.5%
652	15	8	0	100.0%	144	24	83.3%	8	1	87.5%	141	26	81.6%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
653		8	0	100.0%	132	23	82.6%	8	2	75.0%	131	25	80.9%
654		8	1	87.5%	133	30	77.4%	8	2	75.0%	132	13	90.2%
655		8	5	37.5%	141	48	66.0%	8	1	87.5%	139	47	66.2%
656		8	2	75.0%	143	33	76.9%	8	2	75.0%	143	18	87.4%
657		8	0	100.0%	132	21	84.1%	8	0	100.0%	130	22	83.1%
658		8	1	87.5%	143	24	83.2%	8	1	87.5%	142	26	81.7%
680		8	0	100.0%	136	5	96.3%	8	0	100.0%	135	19	85.9%
681		8	0	100.0%	136	8	94.1%	8	2	75.0%	133	57	57.1%
682		8	0	100.0%	135	3	97.8%	8	1	87.5%	135	29	78.5%
683		8	0	100.0%	118	10	91.5%	8	0	100.0%	118	36	69.5%
684		8	0	100.0%	117	17	85.5%	8	0	100.0%	117	30	74.4%
685		8	0	100.0%	132	17	87.1%	8	1	87.5%	131	32	75.6%
686	14	8	0	100.0%	137	25	81.8%	8	1	87.5%	137	29	78.8%
687		8	1	87.5%	137	23	83.2%	8	0	100.0%	136	22	83.8%
688		8	0	100.0%	135	4	97.0%	8	0	100.0%	135	26	80.7%
689		3	1	66.7%	109	14	87.2%	3	0	100.0%	107	15	86.0%
701		10	0	100.0%	124	10	91.9%	10	0	100.0%	121	8	93.4%
702		10	2	80.0%	191	23	88.0%	10	0	100.0%	190	38	80.0%
703		10	1	90.0%	192	48	75.0%	10	2	80.0%	191	41	78.5%
704		10	1	90.0%	123	18	85.4%	10	2	80.0%	121	20	83.5%
710		10	1	90.0%	192	57	70.3%	9	0	100.0%	189	50	73.5%
711		10	2	80.0%	183	16	91.3%	10	1	90.0%	172	28	83.7%
712		10	4	60.0%	189	47	75.1%	9	2	77.8%	183	59	67.8%
715		10	0	100.0%	191	43	77.5%	9	2	77.8%	179	83	53.6%
716		10	4	60.0%	192	73	62.0%	10	3	70.0%	189	69	63.5%
717		10	1	90.0%	179	42	76.5%	9	2	77.8%	166	45	72.9%
718	55	10	7	30.0%	192	91	52.6%	10	5	50.0%	190	58	69.5%
719		10	4	60.0%	192	65	66.1%	9	2	77.8%	182	49	73.1%
761		10	1	90.0%	188	9	95.2%	10	1	90.0%	186	29	84.4%
765	41	10	1	90.0%	188	19	89.9%	10	3	70.0%	188	28	85.1%
769		10	0	100.0%	188	20	89.4%	10	1	90.0%	185	37	80.0%
770	23	10	0	100.0%	188	16	91.5%	10	5	50.0%	187	46	75.4%
774	19	10	0	100.0%	188	14	92.6%	10	4	60.0%	187	40	78.6%
777		10	0	100.0%	73	4	94.5%	10	5	50.0%	73	20	72.6%
782		10	0	100.0%	73	4	94.5%	9	0	100.0%	72	5	93.1%
785		10	3	70.0%	188	8	95.7%	10	2	80.0%	188	32	83.0%
790	18	10	2	80.0%	188	18	90.4%	10	2	80.0%	186	18	90.3%
794		10	2	80.0%	188	20	89.4%	10	3	70.0%	187	38	79.7%
821	147	9	0	100.0%	186	3	98.4%	9	1	88.9%	186	74	60.2%
822	15	10	2	80.0%	188	8	95.7%	9	2	77.8%	186	80	57.0%
1021	48	4	3	25.0%	18	14	22.2%	4	2	50.0%	17	3	82.4%
1022		4	1	75.0%	17	7	58.8%	4	0	100.0%	16	3	81.3%

Amtrak On Time Performance

Trains Arriving Through: 4/10/2026

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1333	67	10	1	90.0%	188	22	88.3%	10	3	70.0%	185	67	63.8%
1340		10	0	100.0%	187	4	97.9%	10	2	80.0%	187	34	81.8%
2104		8	0	100.0%	80	8	90.0%	8	0	100.0%	79	8	89.9%
2107		8	0	100.0%	111	20	82.0%	8	0	100.0%	109	15	86.2%
2108		8	0	100.0%	111	20	82.0%	8	1	87.5%	106	14	86.8%
2109		8	1	87.5%	43	5	88.4%	8	0	100.0%	42	2	95.2%
2117		8	1	87.5%	80	19	76.3%	8	2	75.0%	79	13	83.5%
2121		8	1	87.5%	107	19	82.2%	8	1	87.5%	105	16	84.8%
2122		8	0	100.0%	109	13	88.1%	8	0	100.0%	109	9	91.7%
2124		8	1	87.5%	83	11	86.7%	8	1	87.5%	83	8	90.4%
2126		8	0	100.0%	48	13	72.9%	8	0	100.0%	47	12	74.5%
2150	36	8	0	100.0%	104	19	81.7%	8	5	37.5%	102	49	52.0%
2153		8	0	100.0%	108	15	86.1%	8	1	87.5%	106	24	77.4%
2155		8	1	87.5%	113	12	89.4%	7	3	57.1%	110	63	42.7%
2159		8	0	100.0%	106	6	94.3%	8	0	100.0%	105	24	77.1%
2162		8	0	100.0%	113	6	94.7%	8	5	37.5%	110	51	53.6%
2163		8	0	100.0%	113	15	86.7%	8	2	75.0%	109	46	57.8%
2166		8	0	100.0%	109	10	90.8%	8	1	87.5%	107	21	80.4%
2167		8	1	87.5%	103	18	82.5%	8	1	87.5%	103	29	71.8%
2168		8	1	87.5%	105	14	86.7%	8	0	100.0%	104	21	79.8%
2171		8	0	100.0%	40	6	85.0%	8	2	75.0%	37	10	73.0%
2172		8	0	100.0%	85	8	90.6%	8	2	75.0%	85	19	77.6%
2190		8	1	87.5%	112	21	81.3%	8	0	100.0%	110	19	82.7%
2192		8	2	75.0%	38	7	81.6%	8	0	100.0%	38	1	97.4%
2193	25	8	1	87.5%	112	16	85.7%	8	3	62.5%	111	38	65.8%

Amtrak Endpoint OTP Details

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 4/10/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2150	BOS	36	CTI	9	OTH	8	NYP-XSH	AM	Lost time - N.A.R.
2193	NYP	25	POL	31	POL	31	RTE-PVD	AM	Right of Way police hold, AM2193 held at MP 190 a/c of amtrak police hold at MP 189.3
94	BOS	187	DBS	144	DBS	144	NFK-X3V	NS	Debris blocking track (no debris strike) Three down on both tracks, Other, N17
111	WAS	73	ENG	69	ENG	69	NYP-NYP	AM	Air / Brake, 658, LATE F/SSYD SHOPPED ENG.658 A/C PARKING BRAKE ISSUE
179	PHL	19	SMW	22	SMW	17	XHM-PHL	AM	Scheduled in track usage program, Control Point, ., Opr around the Barry a/c 1/4 trks o/o/s
183	WAS	19	CTI	14	CTI	12	BAL-BWI	AM	Follow, MARC, 427, Control Point, .
185	WAS	18	OTH	10	OTH	8	PHL-WIL	AM	Lost time - N.A.R.
494	GFD	148	CON	172	CON	172	NHV-NHV	AM	Hold for connecting train, AM494 departed late due to late connection of late AM94
52	LOR	183	ITI	160	ITI	160	SFA-SFA	FR	Service, turn, or wye train 53
53	SFA	120	FTI	87	FTI	35	XOU-XSA	CS	Meet M492, Control Point, Richland
640	NYP	25	ENG	20	ENG	20	LNC-PAR	AM	Onboard HBD alarm, 641, Hot journal and alarm a/c 0659 fault West of Parkesburg.
643	HAR	31	CAR	32	CAR	21	XHM-PHL	AM	Onboard HBD alarm, C/82522, stopped at Girard a/c hot journal alarm
652	NYP	15	CAR	15	CAR	10	NBK-MET	AM	Onboard HBD alarm, 82522, STOPPED EAST OF EDISION STATION A/C HOT JOURNAL ALARM RINGING OFF
686	BON	14	DCS	9	DCS	9	WOB-BON	MT	Restrictive signal(s) from known wayside signal failure 4 r241's into north station, Stop signals, Control Point, tower a
64	NYP	24	FTI	31	FTI	31	BUF-ROC	CS	Follow Caught an approach at 429 track 2 to a restricted proceed at 427 and came to a stop. Once they were on the move we got an approach were we followed them until CP417, they crossed over to Track 1 and we passed them., X63409, Control Point, 429, Control Point, A427, Control Point, 417
233	ALB	27	CTI	14	CTI	14	CRT-POU	MN	Meet mnrr, 858, Control Point, 39
235	ALB	29	CTI	16	CTI	16	CRT-POU	MN	Follow man, 8835, Control Point, 46
239	ALB	22	CTI	22	CTI	15	CRT-POU	MN	Follow MNRR, 857, Control Point, 39
240	NYP	21	PTI	14	PTI	11	YNY-XSD	MN	Meet 283, Control Point, 12
241	ALB	29	CTI	16	CTI	16	CRT-POU	MN	Follow MN, Milepost w/Letters, cp 39, cp 72

Amtrak Endpoint OTP Details

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 4/10/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
281	NFL	114	FTI	119	FTI	107	SDY-XHF	CS	Hold due to freight derailment Control Point, 169, m382
48	NYP	75	FTI	115	FTI	93	UCA-XHF	CS	Hold due to freight derailment N/A, Control Point, 169
448	BOS		FTI	95	FTI	95	ALB-ALB	AM	Hold due to freight derailment Control Point, 169, M38209
71	CLT	22	INJ	17	INJ	17	DNC-GRO	NS	Injured or sick passenger Pax removed by EMS at BNC
73	CLT	15	FTI	9	PTI	9	RGH-CYN	NS	Meet Amtk 80, Control Point, Fetner
74	RGH	18	PTI	19	PTI	17	SAL-HPT	NS	Meet Amtk75, Control Point, Sharp
75	CLT	27	FTI	13	PTI	11	CYN-DNC	NS	Meet #Am72, Control Point, D & S Jct
76	RGH	22	FTI	18	FTI	18	KAN-GRO	NS	Meet #NS50W, Control Point, Varner
77	CLT	41	TCR	38	TCR	32	CYN-CYN	NS	Fire under HVAC 400002
89	SAV	52	ENG	96	ENG	28	PHL-PHL	AM	HEP, 607 612, ADDED MOTOR 607
56	SAB	44	DCS	50	DCS	34	BLF-CLA	NE	Restrictive signal(s) from unknown cause Approach to stop signal, talk by at north Walpole, unable to lock in signal per dispatcher for switch indicator light issue at CLA south., Approach, Stop, Other, nss walpole
40	CHI	496	ENG	297	ENG	270	DNK-CLB	CS	Air / Brake Brakes wouldn't release. Set out engine, 307
41	MIA	100	FTI	155	FTI	34	HFY-RKV	CS	Follow CSXT M416, Other, East #2
522	SAC	29	TCC	35	TCC	35	OKJ-EMY	UP	Speedometer not functioning mechanical forces onboard C8308
536	SAC	11	PTI	20	PTI	20	DAV-SAC	UP	Wait for station track 547, Control Point, W SAC
543	SJC	15	CTI	25	CTI	25	SCC-SJC	UP	Blocked from station track Stop, Caltrain, 523, Control Point, alameda
503	EUG	17	ADA	17	MBO	10	VAN-PDX	BN	For maritime traffic Bridge, Willamite river
504	SEA	54	TRS	51	TRS	51	ALY-SLM	UP	Trespasser strike Madison street jay mcdermott 67 was walking his bike across tracks saw train tried to hurry and was struck by train. Jay was taken to Corvallis hospital case number #26-01934, Milepost, 691.37, 691.37

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Region: ALL

Service: ALL

Arriving On: 4/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
506	SEA	No OS Rpt	ITI	197	ITI	197	PDX-PDX	BN	Service, turn, or wye train 517, Train had mechanical issues coming in. Drumack "tried" to fix it but nothing besides filling the DEF tank.
508	SEA	21	DSR	26	PTI	7	EUG-ALY	UP	Meet 11, Siding, Swain
516	VAC	18	PTI	21	PTI	21	BEL-X8B	BN	Meet Sat on the main, Amtk 517, Control Point, Swift
517	PDX	253	FTI	135	FTI	130	XF2-X8B	BN	Meet Hold at Annieville due to freight train ahead with broken drawbar. Wait for crew to remove train in two segments., Control Point, Annieville, BNSF
518	VAC	54	MBO	45	MBO	39	XF2-X1J	BN	For maritime traffic Bridge, Fraser
58	CHI	42	SYS	48	SYS	47	JAN-YAZ	CC	Re-crew / job briefing Control Point, Anding
8	CHI	107	FTI	160	OTH	52	SPK-SPT	BN	Delay reported departure of Spokane wrong We departed Spokane at 02:38am pacific time due to extra car switching in Spokane.
821	FTW	147	TRS	111	TRS	107	PVL-PVL	BN	Trespasser strike Held at Paul's Valley for trespasser strike ahead, Other, PVL
822	OKC	15	DSR	21	FTI	13	GLE-ADM	BN	Meet BN3257, BN8541, Siding, Gainesville, Siding, Thackerville
350	PNT	25	PTI	23	PTI	13	DOA-KAL	AM	Meet AMTK351, Siding, DOWAGIAC
566	SAN	42	POL	51	POL	51	XRJ-FUL	BN	RR blocked by trespasser or vehicle strike by another train
580	SAN	19	DSR	11	PTI	7	X98-OSD	SN	Meet A785, Control Point, don
584	SAN	37	PTI	22	PTI	19	SNC-SNP	SC	Meet Amtk 587, Control Point, Serra
588	SAN	55	POL	66	POL	54	OSD-SOL	SN	Per dispatcher held at Poinsettia due to police activity ahead
591	LAX	47	TRS	44	TRS	44	ANA-ANA	SC	Vehicle on track ahead Milepost, 167.9, 167.9
593	LAX	67	TRS	74	TRS	74	SOL-SOL	SN	Trespasser strike PD activity at mile post 237.96 E st. due to strike., Control Point, swami
595	LAX	16	POL	25	POL	25	SOL-SOL	SN	Right of Way police hold Holding at SOL. Police activity at Encinitas station.
765	SLO	41	POL	46	POL	46	FUL-XRJ	BN	Right of Way police hold
770	SAN	23	CTI	20	PTI	8	MPK-MPK	SC	Meet 761, Control Point, Colonia
774	SAN	19	PTI	29	PTI	13	SIM-CWT	SC	Meet amtk, Control Point, santa sue

Amtrak Endpoint OTP Details

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 4/10/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
790	SAN	18	POL	26	POL	16	OSD-OSD	SN	Police activity at Encinitas held by North County Dispatcher at Oceanside	
718	BFD	55	SYS	31	SYS	23	OKJ-OKJ	UP	Re-crew / job briefing Other, OKJ	
1021	SAS	48	CON	65	CON	65	FTW-FTW	UP	Hold for bus with passengers from train Hold for passengers and OBS crew for bus bridge from train 21 of the 8th	
300	CHI	185								
301	STL	19	FTI	42	FTI	24	JOL-BNL	UP	Follow UP 828, Milepost, 55, 85	
302	CHI	50	OTH	67	ENG	12	STL-STL	TR	Waited for map100 for second unit ID4609	
306	CHI	34	FTI	50	FTI	23	SMT-XTF	CC	Cross Traffic unknown, unknown, Control Point, Lemoyne, Control Point, corwith	
319	KCY	65	FTI	51	FTI	47	XRC-KCY	KC	Cross Traffic Freight train yarding train, UP5904, Control Point, Sheffield	
1333	MSP	67	FTI	67	FTI	27	XH8-MSP	CP	Meet CPKC 246, Control Point, Dunn	

Amtrak Initial Terminal Details

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 4/10/2026

Terminal	Train	Date	Late	Delay	Cause
LOR	53	04/10	40	38	DRUMMAC Milepost, 92.1, 92.1
LOR	53	04/10	40	2	Routine inspections Milepost, 92.1, 92.1
MIA	40	04/10	26	26	Set out defective locomotive 366
NPN	86	04/10	1	1	Mobility Impaired Slow moving passengers late
PHL	110	04/10	1		
PHL	605	04/10	2	2	PTC - Stop Bypass Permission Required, Control Point, ., Stop bypass on cc 9646
WAS	136	04/10	10	10	Heat / AC, 82749, HOT CAR 82749. MECH'S UNABLE TO INSPECT HOT CAR DUE TO MULTIPLE LATE TRAINS ARRIVING IN LL TRACKS
ALB	448	04/09	95	95	Hold due to freight derailment Control Point, 169, M38209
BON	687	04/10	1		
BON	689	04/10	1	1	Signal suspension Rule 241 permission to pass stop signal Tower A, Control Point, Tower A
NYP	49	04/10	2	2	Passenger and/or baggage, BOARDING
NYP	97	04/10	31	31	Planned set out / pick out of locomotives, cars or section of train, DELAYED F/SSYD A/C NECESSARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND USE 4 COACH CARS
NYP	111	04/10	69	69	Air / Brake, 658, LATE F/SSYD SHOPPED ENG.658 A/C PARKING BRAKE ISSUE
NYP	183	04/10	4	4	Passenger and/or baggage, LOADING
NYP	241	04/10	5	5	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	281	04/10	8	8	Scheduled in track usage program, Other, NYP, HELD F/AM236 A/C TRACK INSPECTION ON 1 TRK EMPIRE TO INWOOD
NYP	291	04/10	18	18	Service, turn, or wye train, 240, LATE TURN OFF AM240
CHI	41	04/10	101	101	Service, turn, or wye train 0040, Waited for train to be serviced from late arrival of train 40
CHI	307	04/10	30	30	Train line down on engineer side 69
GRR	371	04/10	2	2	Wheelchair Gandhi, Mary #75D6BF w/scooter Required lift to board train showed up at 05:58AM
PDX	506	04/10	197	197	Service, turn, or wye train 517, Train had mechanical issues coming in. Drumack "tried" to fix it but nothing besides filling the DEF tank.
SEA	11	04/10	6	6	Wait for Seattle yard switch crew to finish move. Other, Lead 2
STL	300	04/10	137		
STL	302	04/10	12	12	Waited for map100 for second unit ID4609
BFD	719	04/10	1		

Amtrak Initial Terminal Details

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 4/10/2026

Terminal	Train	Date	Late	Delay	Cause
EMY	6	04/10	64	64	Train was not complete we. Waited for yard job to complete our train Other, Oakland yard
FTW	1021	04/10	1	1	Radio failure 68
GTA	790	04/10	1	1	Door C6352
LAX	14	04/10	10	10	Cross Traffic metrolink, Milepost, 0, 0
MHL	1022	04/10	8	8	Local bus late arriving. 0000
OKJ	520	04/10	1		
OKJ	526	04/10	2	2	Meet 11, Control Point, North Jack London
SAC	531	04/10	4	4	Cross over or go around Dispatcher held us for late inbound AMTK 522 did depart on time with a approach signal followed by a stop signal, amtk 522, Milepost, 88.85, 88.70
SAC	704	04/10	11	11	Re-crew / job briefing 1173 paperwork not completed properly, making sure no rule. Violations per management, Other, SAC

Eastern Region

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	89.7	88.3	90.2	58	8
SEPTA	95.0	95.5	94.0	91.5	221	10
NJT-NED	95.0	97.5	91.1	88.6	367	9
NJT-SED	95.0	100.0	96.8	97.2	22	0

Operating Highlights

Train 66(10) Washington, DC - Engine Failure

11APR26: Train 66(10) with engines 642, 617, 5 cars, and 223 customers onboard was delayed at Washington, DC on the Amtrak Washington Terminal Line due to the loss of H.E.P on the trailing motor. The reason for the loss was unknown. Troubleshooting efforts were successful and H.E.P was restored. The train was able to advance to the next station.

Train	Delay	Comment
66(10)	31"	

Train 40(09) Washington, DC - Engine Failure

11APR26: Train 40(09) with engines 150, 336, 10 cars and 167 customers onboard was delayed at Washington, DC/MP 136.0 on the Amtrak Washington Terminal Line due to engine 150 not having operational ditch lights. It was required that engine 150 and 336 be flat switched. After the diesels were switched and the train was put back together, the train encountered PTC issues. Engine 336 was recycled to clear the PTC fault. Once the train was clear of all faults, train 40(09) departed Washington, DC at 6:57 PM-ET.

Train	Delay	Comment
40(09)	1'42"	

Train 66(10) North of Washington, DC - Deer Strike

10APR26: Train 66(10) with engines 642, 617, 5 cars, and 223 customers onboard was delayed at MP 123.8, 15 miles north of Washington, DC on the Amtrak PW line due to striking three deer. The train was stopped at 10:55 PM-ET due to receiving multiple faults. The crew inspected the train and did not find any damage. The engine was recycled. Once the recycle was completed, the train was back on the move at 11:47 PM-ET.

Train	Delay	Comment
66(10)	57"	

Train 51(10) North of Culpeper, VA - Vehicle on the Tracks

10APR26: Train 51(10) with engines 284, 308, 326, 5 cars and 138 customers onboard was delayed at MP 64.0, 11 miles north of Culpeper, VA on the NS Washington District due to a report of a vehicle on the tracks ahead. Once the vehicle was removed from the tracks, train 51(10) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
51(10)	35"	

Train 52(09) North of Charleston, SC - Freight Train Interference

10APR26: Train 52(09) with engines 358, 357, 50 cars, and 550 customers onboard was delayed at control point Hannahan/MP 383.4, 8 miles north of Charleston, SC on the CSX Charleston subdivision due to meeting freight train CSX31. Once the freight train was cleared, train 52(09) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(09)	44"	

Train 41(08) Savannah, GA - Freight Train Interference

10APR26: Train 41(08) with engines 346, 38, 14 cars, and 174 customers onboard was delayed beginning at Savannah, GA/MP 491.0 on the CSX Savannah subdivision due to following CSX freight train IO31 between MP 194.0 and MP 548.0. Once the freight train was cleared, the train was able to advance to the next station at normal authorized speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(08)	32"	

Train 64(10) East of Buffalo, NY - Freight Train Interference

10APR26: Train 64(10) with engine 113, 5 cars and 202 customers onboard was delayed beginning at MP 429.8, approximately 4 miles east of Buffalo, NY on the CSX Buffalo Terminal subdivision due to following a freight train until MP 417.7. Once the freight train cleared, train 64(10) advanced to the next station at normal authorized speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
64(10)	31"	

Train 2193(10) North of Providence, RI - Police Hold Due to Trespasser

10APR26: Train 2193 with 283 customers onboard was delayed at MP 191, 8 miles north of Providence, RI on the Amtrak New Haven to Boston Line due to the police placing a hold on all tracks at MP 189.3 to pursue a trespasser. Once the police cleared the tracks, the train advanced to the next station. Train 2166(10) was held at Providence until the tracks were released.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2166(10)	5"	
2193(10)	31"	

Train 77(10) Cary, NC - Third Party Contractor Car Failure

10APR26: Train 77(10) with engine 87, 5 cars and 160 customers onboard was delayed at Cary, NC/MP 72.6 on the NS Danville District due to a fire under the HVAC on car 400002. The fire was extinguished and the train departed Cary at 3:59 PM. The train advanced to the next station and continued to monitor the car to ensure that the fire did not reignite.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(10)	38"	

Train 56(10) North of Bellows Falls, VT - Signal

10APR26: Train 56(10) with engine 87, 5 cars and 79 customers onboard was delayed at MP 145.8, approximately 2 miles north of Bellows Falls, VT on the New England Central Railroad Palmer subdivision due to receiving restrictive signals. The train received an approach signal into a stop. The train was talked by the signal at North Walpole. Dispatcher reported to the crew that there was an issue with the switch indicator light that prevented them from being able to display a signal. Once the signals cleared, the train advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
56(10)	34"	

Train 53(10) Lorton, VA Initial Terminal Delay - Servicing

10APR26: Train 53(10) took an initial terminal delay at Lorton due to the late arrival of train 52(10). After the train was serviced, the auto carriers were loaded and added, and the customers were boarded train 53(10) was able to depart Lorton.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(10)	40"	

Train 97(10) New York, NY - Initial Terminal Delay - Servicing

10APR26: Train 97(10), operating with locomotive 617 and a planned consist of 10 cars, experienced a delay at the initial terminal of New York due to equipment availability. Four coaches were required from inbound Train 98(09) in order to fulfill the scheduled consist. Once the inbound equipment arrived, the consist was made up and all required inspections and operational tests were completed in accordance with established procedures. Upon completion, the equipment was moved into New York Station for customer boarding. A total of 187 customers boarded at New York Station and train 97(10) departed New York at 3:01 PM ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(10)	31"	

10APR26: 2:15PM-ET M382-09 train experienced delays due to a derailment involving CSX train M382-09 on the CSX Mohawk Subdivision. One truck of a single railcar derailed at MP 169. At the time of the derailment, the position of the train fully blocked the CP 169 interlocking, preventing any movement between Amtrak-controlled territory and the CSX Mohawk Line. CSX responded by dispatching a local train, which coupled onto the rear of the disabled consist and pulled the intact portion of the train westward, clearing the interlocking. Once CP 169 was confirmed clear and inspected, normal train movements were permitted to resume. Amtrak Train 281(10) was the first train to operate through the affected area at 3:40 PM ET.

Train	Delay	Comment
281(10)	1'56"	
448(09)	1'35"	
48(09)	1'33"	

Train 94(10) West of Norfolk, VA - Tree on Track

10APR26: Train 94(10) operating with locomotive 368, 9 cars and 206 customers onboard was delayed at MP 8.1 on the NS Norfolk Subdivision due to reported trees on tracks ahead. NS Maintenance of Way employees responded to remove the foliage from the track to allow the railroad to reopen. Once the clearing work was completed train 94(10) was able to proceed without and further delay.

Train 94(10), operating with locomotive 368, 9 cars, and 206 customers onboard, experienced a delay at MP 8.1 on the NS Norfolk Terminal Subdivision due to reported trees obstructing the track ahead. NS Maintenance of Way personnel responded to the location and removed the foliage from the track, allowing the line to be safely reopened. Once the clearing work was completed, Train 94(10) proceeded without further delay.

Train	Delay	Comment
94(10)	2'24"	
494(10)	2'52"	ITD waited for connections from 94(10)

Train 640(10) West of Parkesburg, PA - Car Failure

10APR26: Train 640(10), operating with locomotive 641, 5 cars, and 43 customers, experienced a delay at MP 48.3, approximately four miles west of Parkesburg on the Amtrak Philadelphia-Harrisburg Line, due to a hot journal alarm on car 82522. In response, the crew stopped and conducted an on-site inspection, during which no defects or abnormal conditions were found. In accordance with operating rules, Train 640(10) then proceeded 10 miles at a speed not exceeding 50 MPH to Coatesville for a required re-inspection. Upon arrival at Coatesville, the crew performed a second inspection, which again revealed no exceptions. Following this inspection, the train was cleared to resume normal operating conditions.

Train 643(10) operating with a turn of equipment off 640(10) experienced an additional hot journal alarm at MP .1 on the NYP line requiring crew to stop and inspect the equipment with no exceptions taken. Upon arrival into Philadelphia, mechanical personnel responded and found no exceptions releasing the equipment for continued service.

Train 652(10) operated with the same equipment. The train experienced a delay in Philadelphia due to the hot journal alarms as well as a delay east of Edison Station.

Train	Delay	Comment
640(10)	20"	LNC-PAR
640(10)	05"	PAR-DOW
640(10)	05"	PHL-PHN
643(10)	21"	XHM-PHL
643(10)	07"	PHL-PHL
643(10)	04"	PHL-PAO
652(10)	05"	PHL-PHL
652(10)	10"	NBK-MET

Train 111(10) Initial Terminal Delay New York, NY - Engine Failure

10APR26: Train 111(10) with engines 361, 9UNCLASSIFIED, 4/30/2026 as departed New York, NY due to engine failure on engine 658. Engine 658 was shopped for parking brake issues and removed from the consist causing a late release from Sunnyside Yard. Once the train was released from mechanical, the train was positioned in New York Terminal. Train 111(10) departed New York at 5:59AM-ET with 231 customers onboard.

Train	Delay	Comment
111(10)	1'09"	

Train 53(09) South of Yemassee, SC - Freight Train Interference

10APR26: Train 53(09) with engines 364, 322, 50 cars, and 354 customers on board was delayed at MP 459.3, approximately 17 miles south of Yemassee, SC on the CSX Charleston subdivision due to meeting freight train M492. Once the freight train cleared, the train was able to advance.

Train	Delay	Comment
53(09)	35"	

Eastern Region

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
20 (4)	ATL	339		Loading//HEP faults
40 (8)	CLB	307		Air leaks

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
19	LYH	5	DM Jeff Brown will cab them back from GRO	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 7/27(09) - Freight Train Interference

11APR26: Train 7/27(09) was delayed 0.5 miles west of Whitefish, MT at West Whitefish/MP1219.9 on the BNSF Kootenai River Subdivision due to meeting BNSF 4250. Train was further delayed between West Brimstone/MP1253.9 and Riverview following BNSF 4250. Once route was clear, Train 7/27(09) was able to proceed west at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(09)	1'06"	

Train 3(10) West of Topeka, KS - Freight Train Interference

11APR26: Train 3(10), operating with engines 174/176, 10 coaches and 139 customers, was delayed 56.5 miles west of Topeka, KS, on BNSF Topeka subdivision, due to holding behind BNSF8338, who was holding for a recrew. Once the freight was recrewed and on the move, train 3(10) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(10)	1'13"	Wi-Tronix Estimate

Train 794(10) Chatsworth, CA - Freight Train Derailment

11APR26: At approximately 6:15PM-PDT, Metrolink reported UPRR freight train MGMGM-10 derailed coming out of the yard at Gemco/MP456.1 approximately 0.6 miles south of Van Nuys, CA on the Ventura Subdivision of Metrolink SCRRA Railway. The derailment occurred on double main track No.1. Train 794(10) was held at Chatsworth, CA/MP445.46 waiting for open track. Both main tracks were placed on a hold for initial inspection. Once the track department arrived on the scene and verified the derailed car did not foul the opposing main track, Train 794(10) was cleared to operate by at restricted speed on main track No.2.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
794(10)	1'54"	

Train 14(10) North of Martinez, CA - Animal Stirke

11APR26: Train 14(10), operating with engines 313/361, 9 coaches and 251 customers, was delayed 16.5 miles north of Martinez, CA, on UP Martinez subdivision, due to striking a large pig. The strike caused air hoses to separate between car 61063 and car 39037. Once the crew was able to re-attach the hoses and perform their required brake test, train 14(10) was able to proceed. Train was further delayed at Davis, CA reinspecting the lead locomotive.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(10)	18"	ADTL 03" at DAV

Train 518(10) South of Vancouver, BC - Maritime Traffic

11APR26: Train 518(10) was delayed at MP141.1, 13.60 miles south of Vancouver, BC. station on the CN New Westminster subdivision due to the Fraser bridge opening for maritime traffic. Once the traffic cleared and the bridges closed, 518(10) was able to proceed north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518(10)	30"	

11APR26: At Approximately 1:15 PM, 04/26/2026, Metrolink reported that a Metrolink Coaster struck and injured a trespasser at Encinitas Station/MP238, 3 miles north of Solana Beach, CA on the San Diego Subdivision of Metrolink SCRRA Railway. There were no injuries to the passengers or crew on board. Local police arrived for an investigation. While waiting for investigation to be completed, the following Surfliner services were affected: Train 588(20) initially held at Oceanside, then was advanced to Carlsbad-Poinsettia and Train 593(10) Held at Solana Beach for open track.

Train	Delay	Comment
593 (10)	1'14"	
588 (10)	1'06"	

11APR26: Train 591(10), operating with engine 2113, 6 coaches and 169 customers, was delayed at Anaheim, CA, on SCRRA Orange subdivision, due to a vehicle on the tracks ahead at milepost 1686. Local police responded with a tow truck to remove the vehicle. Once the tracks were inspected train 591(10) was able to proceed.

Train	Delay	Comment
591 (10)	44"	

11APR26: Train 58(10), operating with engine 45, 7 coaches, and 145 customers, was delayed 2 miles south of Memphis, TN, on CN Memphis subdivision, due to a signal outage requiring the crew to flag between milepost 393 and milepost 391.9. Once clear of the affected area, train 58(10) was able to proceed at normal speed.

Train	Delay	Comment
58 (10)	32"	

10APR26: Train 319(10), operating with engine4620, 7 coaches and 92 customers, was delayed 5 miles east of Kansas City, MO, on KCT KCT Terminal subdivision, due to holding for UP5904 to clear into the yard. Once the freight was cleared and a route was made available, train 319(10) was able to proceed.

Train	Delay	Comment
319 (10)	47"	

11APR26: Train 8/28(09) operating with engines 353/301, 10 coaches, and 151 customers, was delayed 51 miles west of Williston, ND, on BNSF Glasgow subdivision, due to BNSF5009, BNSF6060, BNSF8320, and an unknown BNSF freight at Macon Siding, Poplar Siding, Brockton Siding, and Culbertson Siding.

Train	Delay	Comment
8/28 (09)	42"	

Train 1333(10) St. Paul-Minneapolis, MN - Freight Train Interference

10APR26: Train 1333(10) was delayed beginning at MP424.0, 9.57 miles east of St. Paul Minneapolis MN station on the BNSF St Paul subdivision meeting BNSF freights XMHSP13, XUEPPCXZ0 and CPKC Freight trains 246, 576. Train 1333(10) was back on the move at 740PM CT after all the freight trains cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(10)	1'05"	

Train 307(10) Chicago, IL - Engine Failure

10APR26: Train 307(10) was delayed departing Chicago IL station on the Amtrak Chicago line due to trainline issues with engine 69. Mechanical was able to troubleshoot the issue and found an equipment room door that was not closed. Door was closed and train 307(10) departed Chicago IL Station at 740PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(10)	30"	

Train 26(10) South of Bay Saint Louis, MS - Freight Train Interference

10APR26: Train 26(10) was delayed at MP793.5, 39 miles south of Bay Saint Louis MS station on the CSX N O and M line meeting Norfolk Southern Freight 601. Train 26(10) was back on the move at 646PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(10)	43"	

Train 19(09) Hattiesburg, MS - Freight Train Interference

10APR26: Train 19(09) was delayed beginning at MP60.3, 20 miles north of Hattiesburg, MI station on the Norfolk Southern meeting NS 2587 at the Shows Field siding. Once the freight cleared, train 19(09) proceeded to the Dragon siding and met NS freight train 131. Train 19(09) was back on the move at 639PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(09)	42"	

Train 1022(09) North of Springfield, IL - Animal Strike

10APR26: At 12:40PM-CT, Train 1022(09), E/62-E/59-7 Cars, reported striking an animal on the tracks 17 miles north of Springfield, IL/MP185.1, on the UPRR Springfield Subdivision, at MP168.1. The strike resulted in the brake pipe uncoupling on car 39024. There were no injuries reported to the crew or 245 customers onboard. There was no damage to the equipment. Once the air hoses were fixed and a success brake test complete, Train 1022(09) was back on the move north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1022(09)	15"	

Train 517(10) South of Vancouver, BC - Disabled Freight

10APR26: AT 4:35A-PT, BNSF 10000006306 disabled at MP 137.2 on the BNSF New Westminster Subdivision with drawbar issues. BNSF arrived on scene 6:45A-PT. Train 517(10) departed Vancouver, BC on time at 7:15a-PT then held at MP 143.5, 12 miles south of Vancouver, BC. At 8:39A-PT, the BNSF gave an estimate for track opening of 10:30A-PT. The crew advanced to MP 139.3, to fully cross over bridge, then held until tracks were cleared. Once mechanical was able to resolve issue, then move equipment to clear tracks, Train 517(10) was able to proceed south at 10:20A-PT. To accommodate passengers traveling between Seattle, WA and Portland, OR three supplemental buses were sourced to operate on time out of Seattle. All three buses dropped off and picked up passengers, and made all station stops. Due to the late operation, service recovery was initiated with snack boxes and bottles watered being provided to all passengers.

Train 517(10) was further delayed at Kelso, WA station holding for a relief crew.

Train 506(10) was delayed departing Portland, OR due to the late turn of equipment from Train 517(10) arriving at 7:48P-PT. Once equipment was wye'd and serviced, the passengers boarded and Train 506(10) was able to depart.

Train 506(10) was further delayed at Tacoma, WA due to needing to complete a calendar day inspection.

WBS#: B.TR.100150.6624

Train	Delay	Comment
517(10)	2'10"	
517(10)	1'05"	Re-crew KEL
506(10)	3'18"	
506(10)	Estimated 90"	TAC - Calendar day inspection

Train 6(10) Emeryville, CA - Late Release from Mechanical

10APR26: Train 6(10), E/25-E/61 and 8 cars, was delayed departing Emeryville, CA on the UPRR Martinez Subdivision due to a late release from mechanical. The equipment was delayed in the Oakland yard for mechanical to replace the vertical shocks on both locomotives, E/25 and E/61. Once the equipment was released, the crew was able to deadhead it to Emeryville, where the passengers were boarded. Once all passengers were boarded and crew performed brake test, Train 6(10) departed Emeryville.

Train	Delay	Comment
6(10)	1'04"	

Train 40(08) West of Sandusky, OH - Freight Train Interference

10APR26: Train 40(08) was delayed starting 17.5 miles west of Sandusky, OH/MP241.5, on the NSRR Toledo Subdivision, following NS 39N from MP259 to MP287.9. Due to the late operation, service recovery was ongoing. All coach customers were offered complimentary coffee, tea, and muffins. All first class customers had breakfast as normal from the diner car.

Train 41(10) was delayed departing Chicago, IL due to a late turn of Train 40(08)'s equipment that arrived at 501PM-CT, 08 hours and 16 minutes late.

Train	Delay	Comment
40(08)	53"	
41(10)	1'42"	ITD

Train 504(10) North of Albany, OR - Trespasser Strike

10APR26: At 8:28A-PT, Train 504(10) E/7083, went into emergency after striking a trespasser at 691.0 on the UPRR Brooklyn Subdivision. There were no reported injuries to the crew or 98 customers on board. The strike was non-fatal. The crew held at location until EMS and local police arrived. Once EMS arrived, they removed trespasser and local law enforcement conducted investigation. After investigation was complete and tracks were cleared, Train 504(10) proceeded north.

NRC # 1459414

OR State # 2026-0797

National Response Center Number: 1459414

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
504(10)	51"	

Train 8/28(09) East of Libby, MT - Freight Train Interference

10APR26: Train 8/28(09) was delayed beginning 22.6 miles east of Libby, MT (MP 1319.6) on the BNSF Kootenai River Subdivision after meeting BNSF 6646 at Fish River (MP 1297.0) and then holding for a Flathead Tunnel flush at MP 1271.6. Once back on the move, Train 8/28(09) followed BNSF 4457 from Brimstone (MP 1251.8) until it was able to get around at Vista (MP 1223.9).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(09)	13"	Meet BNSF 6646
8/28(09)	10"	Flathead Tunnel
8/28(09)	1'06"	Follow BNSF 4457

Trains 566(10) and 765(10) West of Fullerton, CA - Police Related

10APR26: BNSF ROCC requested a police hold on all tracks 11.2 miles west of Fullerton, CA, MP 165.2, on the BNSF San Bernardino Subdivision at MP 154.02 after a deceased trespasser was discovered hanging from a bridge over the tracks. Law enforcement and emergency responders were dispatched to secure the scene, confirm the fatality, and conduct a death investigation, resulting in a full suspension of rail traffic through the area. During the police hold, Train 566(10) was stopped at MP 153.4, and Train 765(10) was stopped at MP 155.5. After authorities completed their investigation and cleared the scene, the police hold was lifted and all train traffic resumed movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
765(10)	46"	
566(10)	51"	

Train 522(10) North of Oakland, CA - Speedometer Issues

10APR26: Train 522(10), CC/8308-4 cars- E/C2001, was delayed at MP 5.8, 1 mile north of Oakland Station, on the UPRR Martinez Subdivision due to speedometer issues on CC/8303. The crew stopped adjacent to the Oakland yard for mechanical to respond. Mechanical was able to secure the speedometer. Once speedometer was secured, Train 522(10) proceeded north. A mechanical rider stayed on the equipment to monitor.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
522(10)	35"	

Train 821(10) Pauls Valley, OK - Freight Trespasser Strike

10APR26: Train 821(10) ~~26-FOI-00408~~ ~~00000006306~~ ~~UNCLASSIFIED~~ at the Pauls Valley, OK, station (MP 495.5) on the BNSF Red Rock Subdivision due to BNSF G-GDNCPA9-08A being involved in a trespasser strike at MP 490.06. All rail traffic in the area was stopped while officials conducted an investigation into the incident, which resulted in one injury and one fatality. Once the tracks were released by authorities, Train 821(10) resumed southbound movement, following G-GDNCPA9-08A until it was able to get around the train at Davis (MP 476.9).

Train	Delay	Comment
821(10)	1'51"	PVL
821(10)	20"	Follow

Train 48/448(09) East of Cleveland, OH - Car Failure

10APR26: Train 48/448(09), E/112-E/89-10 cars, stopped 27.2 miles east of Cleveland, OH, on the CSX Erie West Subdivision to inspect car 25068 after an onboard hot journal alarm was activated en route. The inspection was conducted at MP 154.4, where the crew inspected the car and found no exceptions. Following the inspection, Train 48/448(09) proceeded at a reduced speed not exceeding 50 MPH for 10 miles to MP 144.1 for a reinspection, which again revealed no exceptions. The train was then released to continue east at track speed until stopping again at MP 128.8 as the issue persisted, at which point the crew coordinated with CNOC Mechanical and successfully reset the alarm.

Train	Delay	Comment
48/448(09)	58"	

Train 300(10) St. Louis, MO - Engine Failure

10APR26: Train 300(10) experienced a departure delay at St. Louis, MO, MP 1.5, on the TRRA Merchants Subdivision due to unrecoverable IO43 engine fault on locomotive ID4609. Locomotive ID4609 was unable to operate under its own power. As a result, Train 300(10) was combined with Train 302(10), and the two trains operated as a live superset to Chicago under Train 302(10)'s operating schedule.

Train	Delay	Comment
300(10)	2'17"	ITD STL
302(10)	12"	ITD STL
300/302(10)	1'01"	Heavy Train

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station, located at MP 588.2 on the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
-------	-------	---------

2/422 (09JAN)	Bypass PSN	
2/422 (12JAN)	Bypass PSN	
1 (08FEB) / 421 (07FEB)	Bypass PSN	
1 (10FEB) / 421 (09FEB)	Bypass PSN	
2/422 (14FEB)	Bypass PSN	Bypass PSN
421 (14FEB)	Bypass PSN	
1 (17FEB) / 421 (16FEB)	Bypass PSN	
2/422 (16FEB)	Bypass PSN	
2/422 (19FEB)	By-Pass Palm Springs	
1 (19FEB)	By-Pass Palm Springs	
421 (18FEB)	By-Pass Paim Springs	
2/422 (21FEB)	Bypass PSN	
2/422 (02MAR)	Bypass PSN	
1 (01MAR) / 421 (28FEB)	Bypass PSN	
1 (03MAR) 421 (02MAR)	Bypass Palm Springs	
2/422 (05MAR)	Bypass Palm Springs	
1 (05MAR)	Bypass Palm Springs	
2/422 (07MAR)	Bypass Palm Springs	
421 (04MAR)	Bypass Palm Springs	
2/422 (09MAR)	Bypass PSN	
1 (08MAR) / 421 (07MAR)	Bypass PSN	
1 (12, 15, 17MAR) / 421 (11, 14, 16MAR)	Bypass PSN	
2/422 (12, 14, 16MAR)	Bypass PSN	
2/422 (19MAR)	Bypass PSN	
1 (19MAR) / 421 (18MAR)	Bypass PSN	
2/422 (28, 30MAR)	Bypass PSN	
1 (26, 29MAR) / 421 (25, 28MAR)	Bypass PSN	
2/422 (30MAR, 02APR, 04, 06, 09, 11, 13, 16)	Bypass PSN	
1 (29MAR, 31, 02APR, 05, 07, 09, 12, 14) / 421 (28MAR, 30, 01APR, 04, 06, 08, 11, 13)	Bypass PSN	
1 (14APR) / 421 (15APR)	BYPASS PSN	
2/422 (17APR)	BYPASS PSN	
421 (15, 18, 20, 22, 25, 27, 29 APR)	BYPASS PSN	
1 (16, 19, 21, 23, 26, 28, 30 APR)	BYPASS PSN	
2/422 (18, 20, 23, 25, 27, 30 APR)	BYPASS PSN	
2 (02, 04, 07, 09, 11, 14 MAY)	BYPASS PALM SPRINGS	
1 (03, 05, 07, 10, 12, 14 MAY)	BYPASS PALM SPRINGS	
421 (02, 04, 06, 09, 11, 13 MAY)	BYPASS PALM SPRINGS	
2/422 (16, 18, 21, 23, 25, 28 MAY)	BYPASS PALM SPRINGS	
421 (16, 20, 23, 25, 27 MAY)	BYPASS PALM SPRINGS	
1 (17, 21, 24, 26, 28 MAY)	BYPASS PALM SPRINGS	
2/422 (11, 13 JUN)	BYPASS - Palm Springs	
1 (02, 11 JUN)	BYPASS PSN	
421 (01, 10 JUN)	BYPASS PSN	
2/422 (20, 22, 25JUN)	Bypass PSN	
1 (18, 21, 23JUN) / 421 (17, 20, 23JUN)	Bypass PSN	
1 (21JUL) / 421 (20JUL)	Bypass PSN	
1 (15NOV) / 421 (14NOV)	Bypass PSN	
2/422 (24)	Bypass PSN - Flooding	
1 (23) 421 (23)	Bypass PSN - Flooding	
1 (31DEC) 421 (30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (04JAN)	BYPASS PSN - flooding	
1 (03JAN) / 421 (02JAN)	BYPASS PSN - flooding	
1 (05) / 421 (04)	Bypass PSN - flooded roads	
2/422 (07)	Bypass PSN -	

2/422 (18, 20, 22FEB)

1 (30) /421 (29) (MAR)

2/422 (01APR)

1 (01APR) /421 (31MAR)

2/422 (03APR)

1 (04APR) /421 (03APR)

2/422 (05APR)

1 (06) /421 (05)

26-FOI-00408

00000006306

"UNCLASSIFIED"

Bypass Palm
Springs
Bypass PSN
Bypass PSN
Bypass PSN
Bypass PSN
Bypass PSN
Bypass PSN
Bypass PSN

Flooding

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

- Train 736(01-04) Cancelled - No alternate transportation.
- Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 13MAR26

- TRAIN 714(05JAN-12MAR) Cancelled - No alternate transportation.
- TRAIN 713(06JAN-13MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

12JAN26 - 13JAN26

-Train 520(12-13) Cancelled - No alternate transportation.
-Train 534(12-13) Cancelled - No alternate transportation.
-Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

-Train 520(14) Cancelled - No alternate transportation.
-Train 537(14) Cancelled - No alternate transportation.
-Train 534(14) Cancelled - No alternate transportation.

15JAN26:

-Train 520(15-16) Cancelled - No Alternate Transport offered
-Train 534(15-16) Cancelled - No Alternate Transport offered
-Train 535(16) Cancelled - No Alternate Transport offered
-Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

-Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

21JAN26:

-Train 526(21) Cancelled - No Alternate Transport offered
-Train 534(21) Cancelled - No Alternate Transport offered
-Train 535(21) Cancelled - No Alternate Transport offered

23JAN26:

-Train 520(23) Cancelled - No Alternate Transport offered
-Train 534(23) Cancelled - No Alternate Transport offered
-Train 535(23) Cancelled - No Alternate Transport offered
-Train 736(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 737(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 520(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 526(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 534(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 531(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 537(26JAN-01MAR) Cancelled - No Alternate Transportation.

01FEB26:

-Train 732(01FEB) Cancelled - No Alternate Transportation.
-Train 749(01FEB) Cancelled - No Alternate Transportation.
-Train 712(02FEB-04FEB) Cancelled - No Alternate Transportation.
-Train 717(02FEB-04FEB) Cancelled - No Alternate Transportation.

14MAR26:

-Train 714(14MAR-30APR) Cancelled - No Alternate Transportation.
-Train 713(15MAR-01MAY) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
718(17)	Originate EMY	Pax to 744 OKJ-EMY
718(17)	35"	
536(09)	44"	09apr ITD OKJ

26"FOI-00408" 80000005476 "UNCLASSIFIED" MAR26
UPRR Mineola Subdivision Track Work - Scheduled M/W Work

11MAR26: Union Pacific Railroad has trackwork scheduled on their Mineola Subdivision between Fort Worth, TX and Longview, TX, on numerous dates between Thursday March 12th and Tuesday, April 28th, 2026. To accommodate this infrastructure work, Amtrak's Texas Eagle Service has been adjusted as follows:

-Train 21(12Mar-16Mar, 23Mar-30Mar, 6Apr-12Apr, 20Apr-27Apr), which operates between Chicago and San Antonio, will utilize a bus bridge in lieu of train service between Marshall and Fort Worth. The Fort Worth to San Antonio section will operate as Train 1021(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr) and will operate 80-minutes later between Fort Worth and San Antonio, departing Fort Worth at 3:48pm.

Train 421(13Mar, 15Mar, 24Mar, 27Mar, 29Mar, 7Apr, 10Apr, 12Apr, 21Apr, 24Apr, 26Apr), which normally operates between Chicago and Los Angeles, will originate at Fort Worth and will operate 80-minutes later between Fort Worth and San Antonio, departing Fort Worth at 3:48pm.

-Train 22(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr), which operates between San Antonio and Chicago, will utilize a bus bridge in lieu of train service between Fort Worth and Marshall. The Marshall to Chicago section will operate as Train 1022(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr) and will operate 2-hours later between Marshall and St. Louis (departing MHL at 9:29pm), and 2 hours 15-minutes later between St. Louis and Chicago (departing St. Louis at 10:25am).

-Train 422(11Mar, 13Mar, 15Mar, 22Mar, 25Mar, 27Mar, 29Mar, 5Apr, 8Apr, 10Apr, 19Apr, 22Apr, 24Apr, 26Apr), which normally operates between Los Angeles and Chicago, will terminate at Fort Worth.

ALTERNATE TRANSPORTATION

-Bus 3021 will provide alternate transportation at Marshall, Longview, Mineola, Dallas, and Fort Worth

-Bus 3022 will provide alternate transportation at Fort Worth, Dallas, Mineola, Longview, and Marshall

**Please Note: During trackwork days, Bus 6022 from Houston and Buses 6122 and 6421 from Shreveport will be redirected to Marshall, instead of Longview, and Bus 6021 to Houston and Buses 6121 and 6422 to Shreveport will depart from Marshall.

18MAR26: Train 1022(17), E/69-E/668 & 7 cars, was delayed departing St. Louis, MO, due to issues initializing PTC for UPRR. UPRR reported system issues with train symbol related to the planned track work. Road foreman was on scene assisting crew. After working with UPRR PTC desk numerous times, issues were still unresolved and Train 1022(17) was authorized to operate over the UPRR with PTC cut-out. Train 1022(17) was delayed enroute to Joliet, operating 59MPH Max.

WBS#: B.TR.100150.6297

Train	Delay	Comment
1022(17)	2'49"	STL, PTC issues
1021(26)	41"	FTW
1021(25)	29"	FTW

Western Region

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (17)	DEN	4		Wheels/flats
3 (26)	ABQ	50		Fuel leak

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00408

00000006306

"UNCLASSIFIED"

4/30/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
238 (10)	ALB	IB237(09) 82734 shopped Wheels; no replacement	No impact	0	NOCAR
238 (10)	ALB	SHORT COACH DUE SHOPPED EQUIP / AT CAP	0	0	
656 (10)	HAR	No WIFI available due shopped cab car	0	0	
20 (10)	NOL	view 2 sleeper in lieu of view 1 sleeper. schedule change performed.	0	0	62515
20 (11)	NOL	view 2 in lieu of view 1. for line 2010 please notify passengers	No impact	0	62517
235 (10)	NYP	82734 shopped Wheels; no replacement. Y Over capacity	Over capacity	8	NOCAR
97 (10)	NYP	(9711) Viewliner II in lieu of Viewliner I - run war report	0	0	62524
609 (10)	NYP	No WIFI available	0	0	
235 (10)	NYP	SHORT COACH DUE SHOPPED EQUIP / HAS CLUB DINE SEATING WHICH WILL BE USED TO BRING CAP BACK POSITIVE	0	0	

Reverse Consists

Train Number	Station	Reason
93 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
110 (10)	PHL	Consist reversed Business class seat orientation may have changed At Rear
113 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front
185 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front
179 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
164 (11)	NPN	Consist reversed Business class seat orientation may have changed At Front
174 (10)	WAS	Consist reversed Business class seat orientation may have changed At Front