



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, June 23, 2026

Rules: 2-35



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Amtrak or Commuter: **Amtrak**

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00551 00000007873 "UNCLASSIFIED" 6/23/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	106,470	32,840	69%	2,401,440	735,516	69%	26,043,093	6,223,887	76%
Northeast Corridor	81%	45,618	12,106	73%	1,047,360	288,770	72%	11,456,486	2,692,519	76%
Acela	83%	9,580	1,628	83%	206,745	53,436	74%	2,255,494	590,923	74%
Northeast Regional	79%	36,038	10,478	71%	840,615	235,334	72%	9,200,992	2,101,596	77%
Richmond / Newport News / Norfolk	77%	10,328	3,746	64%	254,989	98,484	61%	2,855,007	776,343	73%
Springfield Shuttles	89%	720	0	100%	16,309	4,306	74%	162,878	23,521	86%
Roanoke	79%	3,158	652	79%	81,127	18,082	78%	863,880	168,105	81%
On Spine Northeast Regional	80%	21,832	6,080	72%	488,190	114,462	77%	5,319,227	1,133,627	79%
State Supported	80%	47,415	14,610	69%	1,067,920	275,787	74%	11,376,948	2,262,905	80%
Borealis	80%	571	219	62%	12,901	2,396	81%	145,894	29,916	79%
Capitol Corridor	90%	4,628	675	85%	88,750	12,478	86%	971,229	124,710	87%
Carolinian	70%	1,371	1,198	13%	24,107	14,848	38%	300,879	110,625	63%
Cascades	75%	3,316	1,727	48%	69,413	27,197	61%	660,865	181,472	73%
Downeaster	82%	1,480	641	57%	34,895	3,134	91%	382,323	43,474	89%
Empire	78%	5,780	1,501	74%	131,521	41,192	69%	1,404,569	293,613	79%
Adirondack	72%	465	14	97%	8,291	2,083	75%	83,099	24,414	71%
Ethan Allen Express	70%	602	272	55%	13,135	7,820	40%	146,126	43,463	70%
Maple Leaf	70%	846	278	67%	18,768	8,789	53%	168,089	63,355	62%
New York - Albany	85%	2,470	927	62%	60,501	13,924	77%	654,747	97,602	85%
New York - Niagara Falls	75%	1,397	10	99%	28,754	7,751	73%	350,436	63,954	82%
Berkshire Flyer	60%	0	0	-	2,072	825	60%	0	825	60%
Gold Runner	73%	2,764	1,983	28%	58,769	26,354	55%	652,619	223,310	66%
Heartland Flyer	70%	269	269	0%	5,787	1,982	66%	53,591	19,929	63%
Hiawatha	90%	1,716	253	85%	44,115	5,246	88%	441,104	48,941	89%
Illinois	78%	2,672	1,024	62%	59,509	20,734	65%	640,577	169,442	74%
Carl Sandburg / Illinois Zephyr	85%	383	17	96%	10,920	3,313	70%	105,711	26,496	75%
Illini / Saluki	85%	874	145	83%	19,092	6,038	68%	226,518	51,002	77%
Lincoln Service	70%	1,415	862	39%	29,497	11,383	61%	308,348	91,944	70%
Keystone	92%	8,784	1,046	88%	184,241	12,783	93%	1,991,801	205,648	90%
Lincoln / Missouri	70%	968	68	93%	19,885	12,525	37%	200,751	98,549	51%
Mardi Gras Service	80%	343	91	73%	8,151	3,647	55%	106,780	20,557	81%
Michigan	70%	1,670	1,125	33%	50,970	21,436	58%	499,993	156,176	69%
Blue Water	70%	319	297	7%	11,632	7,032	40%	115,877	41,375	64%
Pere Marquette	85%	215	0	100%	6,608	1,805	73%	64,882	12,590	81%
Wolverine	70%	1,136	828	27%	32,730	12,599	62%	319,234	102,211	68%
Missouri	80%	218	2	99%	5,595	1,934	65%	57,429	13,008	77%
Pacific Surfliner	85%	7,782	2,316	70%	200,928	40,505	80%	1,994,107	310,959	84%
Pennsylvanian	80%	926	353	62%	19,579	5,640	71%	231,440	40,781	82%
Piedmont	80%	837	119	86%	21,368	8,702	59%	305,362	77,223	75%
Vermontier	75%	1,320	0	100%	27,436	13,054	52%	335,635	94,572	72%
Long Distance	70%	13,437	6,124	54%	286,160	170,959	40%	3,170,392	1,266,000	60%
Auto Train	70%	868	0	100%	17,643	8,019	55%	201,538	68,095	66%
California Zephyr	70%	1,013	874	14%	21,553	11,718	46%	251,586	79,528	68%
Cardinal	70%	635	605	5%	5,488	3,578	35%	61,988	28,917	53%
City Of New Orleans	75%	831	57	93%	13,612	9,492	30%	173,864	47,247	73%
Coast Starlight	70%	1,397	664	52%	27,728	14,084	49%	294,152	101,153	66%
Crescent	70%	1,260	237	81%	21,468	9,408	56%	241,673	68,209	72%
Empire Builder	70%	1,202	711	41%	25,619	17,779	31%	244,395	112,723	54%
Floridian	60%	459	459	0%	34,166	31,001	9%	415,977	270,717	35%
Lake Shore Ltd	73%	1,277	211	83%	23,930	8,457	65%	243,493	68,097	72%
Palmetto	70%	546	396	27%	20,272	10,853	46%	240,131	62,763	74%
Silver Meteor	70%	1,241	810	35%	23,042	14,885	35%	263,996	105,759	60%
Southwest Chief	60%	1,023	720	30%	20,983	16,780	20%	210,131	131,271	38%
Sunset Ltd	70%	388	124	68%	7,153	4,091	43%	75,418	25,570	66%
Texas Eagle	70%	1,297	256	80%	23,503	10,814	54%	252,050	95,951	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

26-FOI-00551 00000007070 "UNCLASSIFIED" 6/20/2026

Train Index Dates Through June 22, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	149,244	2,389,426	625	1,518,419	27,762,812	547

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,237	694,496	104	71,374	7,949,347	90
INFRASTRUCTURE PLANNED	135	11,823	694,496	170	74,091	7,949,347	93
FLEET RELIABILITY	90	17,241	2,389,426	72	244,201	27,762,812	88
TRAIN OPERATIONS	424	112,686	2,389,426	472	1,128,449	27,762,812	406

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak or Commuter: **Amtrak**

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-005 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/22/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	57	81.8%	6,851	954	86.1%	78,816	10,792	86.3%
Central Division	88.0%	67	16	76.1%	1,476	181	87.7%	17,448	1,779	89.8%
CDL	95.0%	2	0	100.0%	47	3	93.6%	501	17	96.6%
CHI	86.0%	26	5	80.8%	598	82	86.3%	7,025	835	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	-	-	-	1	1	0.0%	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	44	2	95.5%	520	52	90.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GRR	95.5%	1	0	100.0%	21	0	100.0%	252	8	96.8%
IND	-	-	-	-	1	0	100.0%	1	0	100.0%
KCY	92.0%	2	0	100.0%	43	3	93.0%	522	39	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	129	10	92.2%	1,551	96	93.8%
MSP	96.5%	1	0	100.0%	22	1	95.5%	258	5	98.1%
PDX	86.0%	5	3	40.0%	109	24	78.0%	1,298	164	87.4%
PNT	88.0%	3	2	33.3%	65	3	95.4%	680	57	91.6%
PTH	93.0%	1	0	100.0%	22	0	100.0%	253	10	96.0%
QCY	91.0%	2	0	100.0%	43	3	93.0%	516	37	92.8%
SEA	85.0%	8	4	50.0%	176	40	77.3%	2,077	302	85.5%
SPK	90.0%	1	-	100.0%	22	2	90.9%	258	19	92.6%
STL	89.0%	4	0	100.0%	88	4	95.5%	1,025	88	91.4%
TOL	-	1	1	0.0%	1	1	0.0%	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	44	2	95.5%	514	14	97.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	101	13	87.1%	2,203	319	85.5%	24,882	3,899	84.3%
ALB	88.5%	8	0	100.0%	172	7	95.9%	1,952	159	91.9%
BON	87.5%	5	0	100.0%	110	8	92.7%	1,273	136	89.3%
BOS	85.5%	17	1	94.1%	384	30	92.2%	4,497	551	87.7%
BRK	92.5%	5	2	60.0%	107	15	86.0%	1,261	81	93.6%
BTN	82.0%	1	0	100.0%	22	1	95.5%	251	38	84.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	43	4	90.7%	515	49	90.5%
HFD	-	2	0	100.0%	32	0	100.0%	135	7	94.8%
MTR	79.0%	1	0	100.0%	22	3	86.4%	248	44	82.3%
NFL	93.5%	2	0	100.0%	44	0	100.0%	534	22	95.9%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	109	5	95.4%	1,366	221	83.8%
NYP	75.5%	46	10	78.3%	992	228	77.0%	10,671	2,391	77.6%
PIT	76.0%	-	-	-	4	3	25.0%	4	3	25.0%
POR	-	-	-	-	3	2	33.3%	8	5	37.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%
SAB	98.0%	1	0	100.0%	21	2	90.5%	252	4	98.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/22/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	57	81.8%	6,851	954	86.1%	78,816	10,792	86.3%
Northeast Division	82.0%	101	13	87.1%	2,203	319	85.5%	24,882	3,899	84.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SPG	92.5%	5	0	100.0%	116	8	93.1%	1,609	88	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	22	3	86.4%	251	55	78.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	71	6	91.5%	1,527	188	87.7%	17,996	2,595	85.6%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	5	0	100.0%	107	17	84.1%	1,301	126	90.3%
GRO	-	-	-	-	8	3	62.5%	25	8	68.0%
HAR	79.5%	13	1	92.3%	250	20	92.0%	2,931	497	83.0%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	22	2	90.9%	261	33	87.4%
MIA	89.5%	2	0	100.0%	44	10	77.3%	523	56	89.3%
MOE	97.5%	2	0	100.0%	44	1	97.7%	529	8	98.5%
NFK	84.5%	2	1	50.0%	44	12	72.7%	605	104	82.8%
NOL	94.5%	5	1	80.0%	95	6	93.7%	1,118	51	95.4%
NPN	93.0%	2	1	50.0%	44	4	90.9%	497	33	93.4%
PGH	93.0%	1	0	100.0%	22	1	95.5%	263	18	93.2%
PHL	48.0%	5	1	80.0%	104	44	57.7%	1,362	662	51.4%
RGH	95.0%	4	0	100.0%	78	4	94.9%	1,029	41	96.0%
RNK	83.5%	2	0	100.0%	44	4	90.9%	518	75	85.5%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	22	2	90.9%	260	10	96.2%
SFA	88.0%	1	0	100.0%	22	5	77.3%	261	35	86.6%
WAS	84.0%	25	1	96.0%	577	53	90.8%	6,356	816	87.2%
Southwest Division	86.0%	75	22	70.7%	1,645	266	83.8%	18,490	2,519	86.4%
ARN	92.0%	1	0	100.0%	21	1	95.2%	263	18	93.2%
BFD	79.0%	6	4	33.3%	146	46	68.5%	1,632	334	79.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	2	1	50.0%	22	8	63.6%	279	82	70.6%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	22	2	90.9%	288	34	88.2%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	-	-	-	1	0	100.0%	1	0	100.0%
GTA	90.0%	3	1	66.7%	66	24	63.6%	792	107	86.5%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	233	25	89.3%	2,591	264	89.8%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	1	0.0%	22	1	95.5%	259	5	98.1%
OKJ	74.5%	11	5	54.5%	257	68	73.5%	2,804	703	74.9%

Information Management

26-FOI-00560 Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/22/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	57	81.8%	6,851	954	86.1%	78,816	10,792	86.3%
Southwest Division	86.0%	75	22	70.7%	1,645	266	83.8%	18,490	2,519	86.4%
RNO	-	-	-	-	1	0	100.0%	2	1	50.0%
SAC	88.5%	16	2	87.5%	328	48	85.4%	3,686	391	89.4%
SAN	90.5%	13	3	76.9%	285	18	93.7%	3,140	282	91.0%
SAS	90.5%	1	0	100.0%	22	4	81.8%	261	27	89.7%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	3	57.1%	154	10	93.5%	1,851	176	90.5%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	65	11	83.1%	556	58	89.6%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		10	1	90.0%	112	8	92.9%	10	7	30.0%	112	23	79.5%
3		22	10	54.5%	263	52	80.2%	21	11	47.6%	261	112	57.1%
4		21	6	71.4%	262	39	85.1%	21	16	23.8%	262	173	34.0%
5	280	22	4	81.8%	262	42	84.0%	22	11	50.0%	258	59	77.1%
6	110	22	7	68.2%	261	74	71.6%	22	11	50.0%	261	76	70.9%
7	107	22	3	86.4%	252	31	87.7%	22	8	63.6%	245	56	77.1%
8		22	13	40.9%	252	106	57.9%	22	19	13.6%	251	141	43.8%
11		22	6	72.7%	263	48	81.7%	22	7	68.2%	257	52	79.8%
14	66	22	2	90.9%	264	40	84.8%	22	17	22.7%	262	81	69.1%
19		22	5	77.3%	262	61	76.7%	21	7	66.7%	260	55	78.8%
20		22	2	90.9%	262	18	93.1%	22	9	59.1%	262	46	82.4%
21		22	0	100.0%	259	22	91.5%	22	4	81.8%	258	61	76.4%
22		22	4	81.8%	260	25	90.4%	22	10	54.5%	258	61	76.4%
23	16	22	0	100.0%	265	5	98.1%	21	11	47.6%	263	65	75.3%
24		22	0	100.0%	265	14	94.7%	22	9	59.1%	264	39	85.2%
25		22	1	95.5%	264	3	98.9%	21	11	47.6%	262	65	75.2%
26		22	1	95.5%	264	4	98.5%	21	10	52.4%	262	48	81.7%
27	135	22	6	72.7%	250	18	92.8%	22	11	50.0%	246	76	69.1%
28		22	12	45.5%	246	58	76.4%	22	14	36.4%	246	50	79.7%
40	827	22	7	68.2%	258	35	86.4%	22	20	9.1%	257	124	51.8%
41	480	22	9	59.1%	258	100	61.2%	22	20	9.1%	256	188	26.6%
42		22	1	95.5%	264	19	92.8%	22	3	86.4%	262	42	84.0%
43	25	22	4	81.8%	263	41	84.4%	22	10	54.5%	263	52	80.2%
48		22	2	90.9%	262	51	80.5%	22	2	90.9%	262	37	85.9%
49		22	4	81.8%	262	65	75.2%	22	5	77.3%	262	51	80.5%
51	79	9	1	88.9%	109	49	55.0%	9	3	66.7%	105	35	66.7%
52		22	5	77.3%	261	35	86.6%	22	7	68.2%	260	59	77.3%
53		22	2	90.9%	261	33	87.4%	22	10	54.5%	260	81	68.8%
55		15	1	93.3%	162	5	96.9%	15	6	60.0%	159	33	79.2%
56		16	2	87.5%	163	22	86.5%	16	5	68.8%	161	26	83.9%
58		22	3	86.4%	254	15	94.1%	22	16	27.3%	253	62	75.5%
59		22	7	68.2%	253	27	89.3%	22	11	50.0%	251	43	82.9%
63		22	8	63.6%	265	115	56.6%	22	18	18.2%	261	133	49.0%
64	26	22	3	86.4%	263	62	76.4%	22	16	27.3%	263	84	68.1%
66		22	2	90.9%	262	53	79.8%	22	3	86.4%	260	46	82.3%
67		16	0	100.0%	181	11	93.9%	16	1	93.8%	181	28	84.5%
68		22	3	86.4%	265	53	80.0%	22	6	72.7%	265	101	61.9%
69		22	8	63.6%	252	54	78.6%	22	5	77.3%	248	28	88.7%
71		22	0	100.0%	260	3	98.8%	22	8	63.6%	259	64	75.3%
72		22	6	72.7%	260	28	89.2%	22	11	50.0%	259	53	79.5%
73		22	5	77.3%	264	16	93.9%	21	11	47.6%	262	126	51.9%
74		20	3	85.0%	262	30	88.5%	20	14	30.0%	260	93	64.2%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		21	2	90.5%	262	12	95.4%	21	12	42.9%	258	122	52.7%
76	13	21	0	100.0%	262	25	90.5%	21	5	76.2%	255	103	59.6%
77	19	21	0	100.0%	261	17	93.5%	21	14	33.3%	259	106	59.1%
78	15	22	4	81.8%	260	18	93.1%	22	7	68.2%	259	47	81.9%
79	99	22	6	72.7%	262	53	79.8%	22	14	36.4%	261	80	69.3%
80	38	22	4	81.8%	262	26	90.1%	21	10	52.4%	260	46	82.3%
84	17	16	0	100.0%	156	11	92.9%	16	5	68.8%	154	31	79.9%
85	24	16	1	93.8%	164	16	90.2%	16	10	37.5%	164	60	63.4%
86		16	2	87.5%	164	13	92.1%	16	14	12.5%	163	97	40.5%
89	86	22	4	81.8%	260	56	78.5%	22	9	59.1%	258	68	73.6%
90	No OS	22	2	90.9%	260	10	96.2%	22	9	59.1%	259	35	86.5%
93	249	16	0	100.0%	163	18	89.0%	16	6	62.5%	162	36	77.8%
94	26	16	6	62.5%	194	48	75.3%	16	5	68.8%	192	66	65.6%
95		16	0	100.0%	163	3	98.2%	16	6	62.5%	163	54	66.9%
97	115	22	16	27.3%	262	166	36.6%	22	13	40.9%	260	73	71.9%
98		22	3	86.4%	262	20	92.4%	22	12	45.5%	260	77	70.4%
110		15	11	26.7%	160	94	41.3%	15	1	93.3%	157	16	89.8%
111		16	3	81.3%	154	31	79.9%	16	1	93.8%	152	19	87.5%
112		16	0	100.0%	154	15	90.3%	16	0	100.0%	153	16	89.5%
113	17	16	6	62.5%	85	21	75.3%	16	2	87.5%	84	10	88.1%
119		16	5	68.8%	154	41	73.4%	16	1	93.8%	152	19	87.5%
125	100	16	0	100.0%	164	8	95.1%	16	10	37.5%	164	64	61.0%
128		6	0	100.0%	101	18	82.2%	7	3	57.1%	101	14	86.1%
129		16	3	81.3%	163	43	73.6%	16	4	75.0%	163	23	85.9%
130		16	2	87.5%	154	16	89.6%	16	2	87.5%	152	14	90.8%
131		16	5	68.8%	156	45	71.2%	16	2	87.5%	156	29	81.4%
134		16	1	93.8%	164	19	88.4%	16	0	100.0%	163	23	85.9%
137	40	16	2	87.5%	161	30	81.4%	16	7	56.3%	161	50	68.9%
138	19	16	5	68.8%	164	34	79.3%	16	7	56.3%	163	25	84.7%
139		3	0	100.0%	33	5	84.8%	4	2	50.0%	33	11	66.7%
141	41	16	0	100.0%	163	3	98.2%	16	2	87.5%	162	28	82.7%
148		16	1	93.8%	163	16	90.2%	16	2	87.5%	161	29	82.0%
151	84	22	8	63.6%	261	83	68.2%	22	7	68.2%	260	81	68.8%
166	58	3	0	100.0%	33	4	87.9%	4	3	25.0%	32	11	65.6%
169		6	1	83.3%	99	12	87.9%	7	1	85.7%	99	21	78.8%
170		16	1	93.8%	159	12	92.5%	16	0	100.0%	158	28	82.3%
171	87	16	0	100.0%	164	10	93.9%	16	10	37.5%	164	58	64.6%
172	40	16	0	100.0%	163	14	91.4%	16	7	56.3%	161	52	67.7%
173	151	16	1	93.8%	159	22	86.2%	16	8	50.0%	158	69	56.3%
174	28	16	3	81.3%	164	20	87.8%	16	6	62.5%	164	33	79.9%
175		16	1	93.8%	164	20	87.8%	16	6	62.5%	164	53	67.7%
176		16	2	87.5%	159	13	91.8%	16	1	93.8%	157	15	90.4%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
177		16	1	93.8%	164	23	86.0%	16	1	93.8%	164	43	73.8%
181		16	9	43.8%	160	53	66.9%	16	2	87.5%	158	11	93.0%
182		16	2	87.5%	154	27	82.5%	16	1	93.8%	152	15	90.1%
183		16	4	75.0%	163	48	70.6%	16	0	100.0%	161	32	80.1%
184	40	16	1	93.8%	164	27	83.5%	16	1	93.8%	163	22	86.5%
185		16	2	87.5%	164	36	78.0%	16	1	93.8%	164	11	93.3%
186	No OS	16	2	87.5%	163	16	90.2%	16	7	56.3%	162	37	77.2%
190		16	5	68.8%	163	59	63.8%	16	3	81.3%	162	37	77.2%
192		16	0	100.0%	161	19	88.2%	16	1	93.8%	161	14	91.3%
193	27	16	8	50.0%	163	68	58.3%	16	12	25.0%	162	77	52.5%
196		16	3	81.3%	163	16	90.2%	16	2	87.5%	162	15	90.7%
197		16	5	68.8%	164	68	58.5%	16	8	50.0%	164	51	68.9%
230		22	0	100.0%	99	4	96.0%	22	0	100.0%	99	5	94.9%
232		22	1	95.5%	265	11	95.8%	22	1	95.5%	265	17	93.6%
233	33	18	5	72.2%	245	54	78.0%	18	15	16.7%	245	68	72.2%
234		22	0	100.0%	265	19	92.8%	22	1	95.5%	265	22	91.7%
235	22	22	5	77.3%	189	26	86.2%	22	6	72.7%	189	36	81.0%
236		22	0	100.0%	249	7	97.2%	22	5	77.3%	249	33	86.7%
237	24	21	2	90.5%	263	51	80.6%	21	4	81.0%	261	43	83.5%
238		22	2	90.9%	189	19	89.9%	22	4	81.8%	188	14	92.6%
239		22	5	77.3%	264	72	72.7%	22	3	86.4%	263	27	89.7%
240	17	22	1	95.5%	264	19	92.8%	21	10	52.4%	262	38	85.5%
241		22	5	77.3%	265	68	74.3%	22	8	63.6%	265	64	75.8%
243		22	4	81.8%	201	55	72.6%	21	2	90.5%	200	26	87.0%
244	30	18	1	94.4%	245	10	95.9%	18	3	83.3%	245	37	84.9%
245		22	5	77.3%	146	26	82.2%	22	3	86.4%	145	16	89.0%
280		22	0	100.0%	265	11	95.8%	22	6	72.7%	265	46	82.6%
281		22	3	86.4%	265	28	89.4%	22	6	72.7%	265	42	84.2%
283		22	10	54.5%	265	62	76.6%	22	4	81.8%	265	47	82.3%
284		22	0	100.0%	265	10	96.2%	22	3	86.4%	263	37	85.9%
290		22	1	95.5%	265	47	82.3%	22	13	40.9%	263	84	68.1%
291	26	22	12	45.5%	264	68	74.2%	22	13	40.9%	262	51	80.5%
300	44	22	0	100.0%	249	18	92.8%	22	7	68.2%	247	56	77.3%
301	17	22	1	95.5%	263	9	96.6%	22	6	72.7%	260	49	81.2%
302		22	2	90.9%	250	30	88.0%	21	5	76.2%	246	68	72.4%
305	39	22	2	90.9%	253	28	88.9%	22	11	50.0%	249	100	59.8%
306		22	2	90.9%	261	15	94.3%	22	11	50.0%	260	69	73.5%
307		22	3	86.4%	253	33	87.0%	22	6	72.7%	250	67	73.2%
311		22	0	100.0%	263	23	91.3%	21	5	76.2%	258	50	80.6%
316		21	0	100.0%	260	16	93.8%	21	9	57.1%	257	61	76.3%
318		22	3	86.4%	264	25	90.5%	22	16	27.3%	261	118	54.8%
319		22	3	86.4%	265	17	93.6%	22	15	31.8%	263	137	47.9%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
329	40	16	1	93.8%	186	8	95.7%	16	1	93.8%	186	13	93.0%
330		19	0	100.0%	224	4	98.2%	19	0	100.0%	224	13	94.2%
331		22	3	86.4%	265	29	89.1%	22	3	86.4%	265	39	85.3%
332	36	22	2	90.9%	265	14	94.7%	22	4	81.8%	265	38	85.7%
334		22	3	86.4%	265	9	96.6%	22	6	72.7%	264	35	86.7%
335		22	2	90.9%	265	29	89.1%	22	2	90.9%	263	41	84.4%
336		22	0	100.0%	265	8	97.0%	22	4	81.8%	263	23	91.3%
337		22	0	100.0%	265	17	93.6%	22	2	90.9%	261	31	88.1%
338		22	3	86.4%	265	40	84.9%	22	7	68.2%	263	77	70.7%
339		22	4	81.8%	265	46	82.6%	22	5	77.3%	265	47	82.3%
341	Cncld	22	3	86.4%	255	34	86.7%	20	3	85.0%	250	34	86.4%
342	15	22	2	90.9%	265	21	92.1%	22	7	68.2%	263	51	80.6%
350	30	22	1	95.5%	246	16	93.5%	22	17	22.7%	241	132	45.2%
351	77	22	2	90.9%	248	24	90.3%	22	5	77.3%	247	67	72.9%
352	Cncld	22	2	90.9%	233	19	91.8%	21	6	71.4%	227	69	69.6%
353		22	0	100.0%	208	12	94.2%	22	5	77.3%	202	35	82.7%
354	286	22	6	72.7%	246	25	89.8%	22	7	68.2%	242	83	65.7%
355	165	21	1	95.2%	259	27	89.6%	20	9	55.0%	252	85	66.3%
364	87	22	6	72.7%	254	56	78.0%	22	13	40.9%	248	83	66.5%
365	18	22	0	100.0%	253	10	96.0%	22	13	40.9%	251	85	66.1%
370	158	22	4	81.8%	256	33	87.1%	20	8	60.0%	250	62	75.2%
371		21	0	100.0%	252	8	96.8%	21	3	85.7%	251	27	89.2%
380		21	0	100.0%	251	23	90.8%	21	4	81.0%	251	46	81.7%
381		22	1	95.5%	265	10	96.2%	22	7	68.2%	265	45	83.0%
382		22	3	86.4%	265	14	94.7%	22	11	50.0%	265	82	69.1%
383		22	2	90.9%	254	25	90.2%	22	13	40.9%	252	100	60.3%
390		22	1	95.5%	247	16	93.5%	22	6	72.7%	246	58	76.4%
391	31	22	2	90.9%	250	8	96.8%	22	13	40.9%	247	59	76.1%
392		22	1	95.5%	264	5	98.1%	22	10	54.5%	262	76	71.0%
393	73	22	0	100.0%	265	15	94.3%	21	9	57.1%	262	73	72.1%
417		16	4	75.0%	174	36	79.3%	16	2	87.5%	165	16	90.3%
425		15	0	100.0%	176	6	96.6%	15	0	100.0%	176	7	96.0%
448		22	3	86.4%	195	37	81.0%	22	7	68.2%	193	65	66.3%
449		22	2	90.9%	193	29	85.0%	22	5	77.3%	193	34	82.4%
470		17	3	82.4%	187	34	81.8%	16	2	87.5%	181	23	87.3%
471		16	0	100.0%	177	5	97.2%	16	0	100.0%	177	2	98.9%
473		16	0	100.0%	183	13	92.9%	16	0	100.0%	180	8	95.6%
474		17	6	64.7%	178	50	71.9%	16	10	37.5%	166	44	73.5%
475		15	2	86.7%	181	5	97.2%	15	4	73.3%	181	10	94.5%
478		16	1	93.8%	175	27	84.6%	16	4	75.0%	173	20	88.4%
479		16	3	81.3%	182	28	84.6%	16	4	75.0%	180	20	88.9%
486		16	3	81.3%	186	28	84.9%	16	8	50.0%	180	50	72.2%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
494		16	3	81.3%	187	34	81.8%	16	3	81.3%	181	44	75.7%
495		16	0	100.0%	172	3	98.3%	16	0	100.0%	170	3	98.2%
500		21	0	100.0%	256	15	94.1%	21	2	90.5%	254	30	88.2%
502	40	22	2	90.9%	263	15	94.3%	22	3	86.4%	260	56	78.5%
503	50	22	5	77.3%	261	25	90.4%	22	10	54.5%	255	69	72.9%
504		22	1	95.5%	265	17	93.6%	22	11	50.0%	263	81	69.2%
505	64	22	5	77.3%	263	35	86.7%	22	10	54.5%	260	72	72.3%
506	49	22	5	77.3%	260	38	85.4%	21	6	71.4%	255	41	83.9%
507	27	22	6	72.7%	265	34	87.2%	22	12	45.5%	265	85	67.9%
508		22	1	95.5%	260	39	85.0%	22	7	68.2%	257	59	77.0%
509		22	1	95.5%	262	12	95.4%	22	9	59.1%	262	63	76.0%
511		22	1	95.5%	257	21	91.8%	22	4	81.8%	256	45	82.4%
516	34	22	3	86.4%	257	27	89.5%	22	15	31.8%	256	118	53.9%
517	145	22	1	95.5%	265	8	97.0%	21	14	33.3%	261	103	60.5%
518	29	22	5	77.3%	265	34	87.2%	22	21	4.5%	263	179	31.9%
519		22	1	95.5%	257	9	96.5%	22	3	86.4%	255	60	76.5%
520		16	4	75.0%	144	22	84.7%	16	0	100.0%	141	8	94.3%
521		16	1	93.8%	182	7	96.2%	16	1	93.8%	182	21	88.5%
522		16	7	56.3%	182	35	80.8%	16	1	93.8%	179	17	90.5%
523		16	0	100.0%	182	6	96.7%	16	2	87.5%	181	22	87.8%
524		16	0	100.0%	182	11	94.0%	15	2	86.7%	180	20	88.9%
525		16	1	93.8%	180	11	93.9%	15	1	93.3%	177	13	92.7%
526		16	5	68.8%	156	28	82.1%	15	1	93.3%	153	12	92.2%
527		16	2	87.5%	182	8	95.6%	15	2	86.7%	181	31	82.9%
528		16	1	93.8%	182	14	92.3%	16	0	100.0%	181	29	84.0%
529	24	16	0	100.0%	182	10	94.5%	16	5	68.8%	181	47	74.0%
530		16	2	87.5%	136	14	89.7%	16	2	87.5%	136	24	82.4%
531		16	1	93.8%	156	11	92.9%	16	1	93.8%	156	11	92.9%
532		16	4	75.0%	182	39	78.6%	16	3	81.3%	182	26	85.7%
534	44	16	4	75.0%	141	23	83.7%	15	2	86.7%	139	13	90.6%
535		16	2	87.5%	169	23	86.4%	16	0	100.0%	164	20	87.8%
536		16	3	81.3%	182	46	74.7%	16	1	93.8%	179	36	79.9%
537		16	3	81.3%	153	16	89.5%	16	3	81.3%	148	14	90.5%
538	12	16	2	87.5%	182	23	87.4%	15	3	80.0%	181	35	80.7%
539		16	7	56.3%	136	19	86.0%	16	8	50.0%	136	60	55.9%
540		16	3	81.3%	182	35	80.8%	16	2	87.5%	175	18	89.7%
541		16	4	75.0%	181	21	88.4%	14	2	85.7%	176	33	81.3%
542		16	0	100.0%	181	20	89.0%	16	2	87.5%	179	31	82.7%
543	26	16	3	81.3%	182	18	90.1%	16	5	68.8%	182	50	72.5%
544		16	1	93.8%	180	20	88.9%	16	1	93.8%	177	15	91.5%
545		16	2	87.5%	182	14	92.3%	16	4	75.0%	180	22	87.8%
547	28	16	3	81.3%	182	36	80.2%	16	4	75.0%	182	44	75.8%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
549	Cncld	16	2	87.5%	177	23	87.0%	13	2	84.6%	170	16	90.6%
550		16	0	100.0%	136	13	90.4%	16	6	62.5%	136	29	78.7%
551	14	16	3	81.3%	178	18	89.9%	16	3	81.3%	170	17	90.0%
562		22	3	86.4%	257	21	91.8%	22	1	95.5%	254	28	89.0%
564		22	3	86.4%	257	16	93.8%	22	4	81.8%	249	30	88.0%
566		22	0	100.0%	255	16	93.7%	22	1	95.5%	252	31	87.7%
567	52	22	2	90.9%	142	8	94.4%	22	1	95.5%	140	6	95.7%
572		22	0	100.0%	252	21	91.7%	22	10	54.5%	247	62	74.9%
573		22	2	90.9%	255	37	85.5%	22	4	81.8%	248	41	83.5%
579		22	0	100.0%	142	8	94.4%	22	4	81.8%	137	25	81.8%
580		22	2	90.9%	257	13	94.9%	22	2	90.9%	253	21	91.7%
581		22	3	86.4%	257	41	84.0%	22	5	77.3%	255	50	80.4%
584	32	22	2	90.9%	141	15	89.4%	22	14	36.4%	138	77	44.2%
587		22	1	95.5%	252	15	94.0%	22	6	72.7%	243	36	85.2%
588		22	2	90.9%	142	11	92.3%	21	3	85.7%	141	20	85.8%
591	26	22	2	90.9%	256	17	93.4%	22	5	77.3%	251	28	88.8%
593		22	2	90.9%	251	35	86.1%	21	2	90.5%	234	26	88.9%
595		22	2	90.9%	253	40	84.2%	21	3	85.7%	250	43	82.8%
600		16	0	100.0%	191	9	95.3%	16	0	100.0%	189	14	92.6%
601		16	1	93.8%	174	71	59.2%	16	0	100.0%	171	23	86.5%
605		16	10	37.5%	181	115	36.5%	16	0	100.0%	177	19	89.3%
607		16	3	81.3%	190	22	88.4%	16	1	93.8%	187	22	88.2%
609		16	0	100.0%	181	22	87.8%	16	0	100.0%	180	14	92.2%
622		13	1	92.3%	98	30	69.4%	12	0	100.0%	96	5	94.8%
626		16	1	93.8%	95	12	87.4%	16	1	93.8%	93	15	83.9%
637		6	0	100.0%	52	6	88.5%	7	0	100.0%	52	4	92.3%
639		16	4	75.0%	162	37	77.2%	16	1	93.8%	161	19	88.2%
640		16	1	93.8%	181	7	96.1%	16	4	75.0%	179	74	58.7%
641		16	4	75.0%	163	32	80.4%	16	2	87.5%	163	24	85.3%
642		16	1	93.8%	179	7	96.1%	16	1	93.8%	178	23	87.1%
643		16	0	100.0%	193	39	79.8%	15	0	100.0%	190	31	83.7%
644		16	1	93.8%	185	27	85.4%	16	3	81.3%	183	47	74.3%
645	22	16	3	81.3%	193	38	80.3%	16	6	62.5%	191	39	79.6%
646	17	16	0	100.0%	182	45	75.3%	16	3	81.3%	180	86	52.2%
647	37	16	0	100.0%	193	31	83.9%	16	4	75.0%	192	43	77.6%
648		16	2	87.5%	189	49	74.1%	16	0	100.0%	189	31	83.6%
649		16	4	75.0%	194	35	82.0%	16	0	100.0%	191	31	83.8%
650		16	1	93.8%	193	39	79.8%	16	3	81.3%	190	29	84.7%
651		16	1	93.8%	193	16	91.7%	16	2	87.5%	191	38	80.1%
652		16	2	87.5%	194	27	86.1%	16	1	93.8%	190	32	83.2%
653		16	2	87.5%	182	30	83.5%	15	2	86.7%	179	33	81.6%
654		16	0	100.0%	183	36	80.3%	16	0	100.0%	180	16	91.1%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
655		16	5	68.8%	191	68	64.4%	16	7	56.3%	189	67	64.6%
656		16	5	68.8%	193	45	76.7%	16	0	100.0%	192	21	89.1%
657	35	16	1	93.8%	182	26	85.7%	16	5	68.8%	181	28	84.5%
658		16	2	87.5%	193	32	83.4%	16	1	93.8%	191	30	84.3%
680		16	2	87.5%	187	9	95.2%	16	1	93.8%	186	23	87.6%
681	35	16	1	93.8%	187	13	93.0%	16	7	56.3%	182	69	62.1%
682	19	16	1	93.8%	186	4	97.8%	16	1	93.8%	186	32	82.8%
683	17	16	0	100.0%	169	15	91.1%	16	6	62.5%	168	48	71.4%
684	54	16	6	62.5%	168	25	85.1%	16	4	75.0%	168	37	78.0%
685		16	2	87.5%	183	27	85.2%	16	3	81.3%	181	43	76.2%
686	31	16	3	81.3%	188	33	82.4%	16	2	87.5%	188	36	80.9%
687		16	0	100.0%	188	29	84.6%	16	2	87.5%	187	29	84.5%
688		16	4	75.0%	186	9	95.2%	15	3	80.0%	185	30	83.8%
699		4	0	100.0%	57	8	86.0%	5	0	100.0%	57	2	96.5%
701		22	5	77.3%	197	20	89.8%	22	6	72.7%	194	19	90.2%
702		22	3	86.4%	264	29	89.0%	21	5	76.2%	262	56	78.6%
703	85	22	14	36.4%	265	76	71.3%	22	11	50.0%	264	69	73.9%
704		22	4	81.8%	196	31	84.2%	21	2	90.5%	191	36	81.2%
710	54	22	3	86.4%	265	67	74.7%	22	10	54.5%	261	70	73.2%
711	68	22	6	72.7%	256	28	89.1%	21	6	71.4%	239	42	82.4%
712	28	22	8	63.6%	262	68	74.0%	22	11	50.0%	254	83	67.3%
714	Cncld	21	9	57.1%	147	53	63.9%	18	12	33.3%	136	54	60.3%
715	237	22	6	72.7%	264	58	78.0%	18	13	27.8%	245	122	50.2%
716	75	22	5	77.3%	265	103	61.1%	22	9	59.1%	260	99	61.9%
717	51	22	8	63.6%	251	60	76.1%	18	7	61.1%	233	65	72.1%
718		22	13	40.9%	265	132	50.2%	22	9	59.1%	263	87	66.9%
719	30	22	7	68.2%	265	86	67.5%	21	6	71.4%	252	70	72.2%
757		22	1	95.5%	50	2	96.0%	22	2	90.9%	50	3	94.0%
761		22	2	90.9%	261	11	95.8%	22	1	95.5%	258	33	87.2%
765		22	0	100.0%	261	24	90.8%	22	1	95.5%	261	36	86.2%
769		22	0	100.0%	261	23	91.2%	22	4	81.8%	255	47	81.6%
770	55	22	1	95.5%	261	21	92.0%	22	9	59.1%	259	71	72.6%
774	34	22	0	100.0%	261	16	93.9%	22	5	77.3%	260	54	79.2%
777		22	0	100.0%	146	9	93.8%	21	3	85.7%	145	33	77.2%
782		22	21	4.5%	146	49	66.4%	22	4	81.8%	141	14	90.1%
785		22	3	86.4%	261	16	93.9%	22	5	77.3%	261	44	83.1%
786		22	9	59.1%	50	14	72.0%	22	11	50.0%	49	23	53.1%
790		22	2	90.9%	261	26	90.0%	21	3	85.7%	258	29	88.8%
794		22	2	90.9%	261	31	88.1%	21	4	81.0%	258	55	78.7%
821	23	22	1	95.5%	259	5	98.1%	22	9	59.1%	259	102	60.6%
822	23	22	2	90.9%	261	14	94.6%	22	9	59.1%	259	113	56.4%
1333	125	22	0	100.0%	261	26	90.0%	22	8	63.6%	258	87	66.3%

Amtrak On Time Performance

Trains Arriving Through: 6/22/2026

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1340		22	1	95.5%	260	5	98.1%	22	2	90.9%	260	41	84.2%
2102		16	4	75.0%	40	12	70.0%	16	1	93.8%	39	3	92.3%
2103		16	1	93.8%	104	10	90.4%	16	3	81.3%	103	9	91.3%
2104		16	0	100.0%	130	9	93.1%	16	0	100.0%	128	9	93.0%
2107		16	3	81.3%	161	29	82.0%	16	1	93.8%	158	19	88.0%
2108		16	2	87.5%	161	25	84.5%	16	1	93.8%	155	17	89.0%
2109		1	1	0.0%	54	8	85.2%	1	0	100.0%	53	3	94.3%
2113		16	1	93.8%	40	3	92.5%	16	2	87.5%	40	6	85.0%
2115		16	1	93.8%	40	3	92.5%	15	1	93.3%	39	4	89.7%
2124	28	16	2	87.5%	133	21	84.2%	16	3	81.3%	132	13	90.2%
2128		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2150		16	0	100.0%	154	22	85.7%	16	3	81.3%	151	67	55.6%
2151		16	2	87.5%	103	6	94.2%	16	6	62.5%	101	29	71.3%
2152		1	0	100.0%	62	3	95.2%	1	0	100.0%	61	26	57.4%
2154	22	1	0	100.0%	66	20	69.7%	1	1	0.0%	63	35	44.4%
2155	37	16	1	93.8%	163	14	91.4%	16	8	50.0%	160	90	43.8%
2159		16	0	100.0%	156	9	94.2%	16	6	62.5%	155	46	70.3%
2162		16	2	87.5%	163	13	92.0%	14	6	57.1%	157	77	51.0%
2167		16	0	100.0%	153	18	88.2%	16	3	81.3%	153	35	77.1%
2171		16	1	93.8%	90	8	91.1%	16	1	93.8%	87	18	79.3%
2190		16	1	93.8%	162	24	85.2%	16	1	93.8%	160	22	86.3%
2193		14	2	85.7%	159	23	85.5%	14	1	92.9%	157	45	71.3%
2228		3	1	66.7%	17	6	64.7%	4	1	75.0%	17	5	70.6%
2274	88	3	0	100.0%	18	3	83.3%	4	4	0.0%	18	11	38.9%
2275		3	0	100.0%	33	8	75.8%	4	1	75.0%	33	20	39.4%

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2124	NYP	28	ITI	26	ITI	26	WAS-WAS	AM	Service, turn, or wye train, 2159, LATE ARRIVAL OF INBOUND AM2159	
2154	BOS	22	SMW	27	SMW	16	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD F/AM171 A/C 2 TRK OOS LEGGETT TO PELHAM BAY	
2155	WAS	37	ENG	26	ENG	20	NYP-NYP	AM	Other electrical failure, 2147, NECESSARY TO REBOOT COMPUTER ON PC2147	
2274	BOS	88	TRS	75	TRS	73	XGX-PVD	AM	Trespasser strike, Milepost, XGX, PVD, No. 2274 is operating 89 minutes late, delayed 72 minutes on account of the trespasser strike	
84	NYP	17	OTH	11	OTH	5	BAL-ABE	AM	Lost time - N.A.R., pure time	
85	WAS	24	DCS	11	DCS	11	BWI-NCR	AM	T.O.L, Control Point, ., Bobbing TOL on 3 Trk MP 107.7 to Grove	
93	NFK	249	WTR	251	WTR	207	QAN-QAN	CS	Trees down Milepost, 78.8, 78.8	
94	BOS	26	OTH	23	PTI	9	OSB-NLC	AM	Cross over or go around, 2160, Milepost w/Letters, XSS, XGX, AM94 held at Shaw's Cove for AM2160 to clear crossover trk 1 - 2, then followed signals of AM2160 on trk 2	
113	WAS	17	SMW	17	SVS	13	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING	
125	NPN	100	FTI	35	FTI	22	ALX-WDB	CS	Follow M415, Milepost, 104.3, 97.3	
137	WAS	40	DCS	34	DCS	34	PVD-KIN	AM	Power switch failure, Milepost w/Letters, PVD, KIN, AM137 held at Davisville due to 12sw B end being out of correspondence. sgl trk btwn Kingston and Davisville on trk 1	
138	NYP	19	WTR	30	DCS	11	ALX-XVG	CS	Restrictive signal(s) from unknown cause Stop signal, Control Point, virginia	
141	WAS	41	TRS	51	TRS	51	SPG-WNL	AM	Vehicle on track ahead, Milepost, SPG, WNL, Windsor PD reports a vehicle on the Single track between Dexters MP 48.1 and Bridge St MP 48.5	
151	RNK	84	ENG	71	ENG	71	WAS-WAS	AM	PTC- IETMS recycle breaker to clear fault, 329, NS HAVING PTC ISSUES UNABLE TO INTIALIZE IN TERMINAL	
166	BOS	58	TRS	63	TRS	48	KIN-KIN	AM	Trespasser strike, Milepost, KIN, KIN, No. 132 located on track No. 2 MP 173 cat pole 62. Trespasser was located at MP 173 cat pole 53. No. 166 will hold at Kingston Station	

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
171	RNK	87	DCS	33	DCS	33	XA1-BCV	NS	Restrictive signal(s) from unknown cause Stop, Control Point, Raven, Control Point, Burke	
172	BOS	40	OTH	21	DSR	18	STM-BRP	MN	Per bulletin Milepost, 38.2, 48.4, 15, 2	
173	WAS	151	SVS	72	SVS	57	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard	
174	BOS	28	HLD	10	SMW	7	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD FOR SINGLE TRACKING PELHAM BAY A/C SCHEDULED MAINTENANCE PELHAM BAY TO LEGGETT	
184	BOS	40	WTR	21	WTR	15	WLY-PVD	AM	Trees down, Milepost w/Letters, WLY, PVD, There is currently an emergency plate in effect btwn Davisville and Mansfield on trk 2. Zone 10 is reporting there is a tree in the catenary at MP 180.12 trk 2. AM184 coming to a stop before Packard	
186	PHL	No OS Rpt	WTR	282	WTR	242	FBG-FBG	CS	Trees down Held for tree down, Other, FBG	
193	WAS	27	HLD	11	PTI	9	ABE-BAL	AM	Follow, .. Control Point, .. HELD AT BUSH FOR 2127 AHEAD THEN FOLLOWED.	
79	CLT	99	WTR	70	WTR	30	FBG-RVR	CS	Heat order Other, FBG	
80	NYP	38	WTR	35	WTR	12	RVR-FBG	CS	Heat order Other, RF&P Subdivision	
645	HAR	22	OTH	10	ADA	7	NWK-NWK	AM	Mobility Impaired	
646	NYP	17	OTH	10	SMW	4	MJY-MJY	AM	Scheduled in track usage program, Control Point, RHEEMS TO CORK, PASSENGERS ON WRONG PLATFORM	
647	HAR	37	ENG	37	ENG	34	NYP-NWK	AM	Cab signal failure, 600 EX IES, HELD AT TENTH AVE TO REVERSE BACK INTO STATION A/C CAB SIGNAL ISSUES	
657	HAR	35	WTR	38	WTR	17	PHL-PHL	AM	Trees down, Milepost, wynnwood, 7.41, HELD FOR DISPOSITION. TREES DOWN AROUND WYNNWOOD	
681	BRK	35	DCS	19	RTE	17	POR-FRE	CS	Dispatcher hold Hold for disabled amt 684, Control Point, Falmouth	
682	BON	19	DCS	18	DCS	8	HHL-WOB	MT	Wayside detector failure including false actuation How to do a roll by for an inspection of the train, Other, Andover	
683	BRK	17	PTI	18	PTI	13	DOV-WEM	CS	Meet 684, Control Point, rollinsford	
684	BON	54	TRS	43	TRS	43	FRE-POR	CS	Debris strike, knocked multiple air hoses loose Control Point, royal	

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
686	BON	31	DCS	22	DCS	9	FRE-POR	CS	Restrictive signal(s) from known wayside signal failure Restricting until the clear at auto 13.6d, Red, Other, from West st to auto 13.6 d
64	NYP	26	CTI	19	CTI	19	POU-CRT	MN	Follow mnrr, local, Control Point, 58
233	ALB	33	CTI	23	CTI	20	CRT-POU	MN	Meet MNRR, 858, Control Point, 39
235	ALB	22	DCS	24	DCS	13	HUD-ALB	AM	Slide fence restriction due to false actuation or out of service Milepost, 125, 128
237	ALB	24	DCS	22	DCS	22	RHI-HUD	AM	Wayside detector failure including false actuation Slide fence detector false accusation, Milepost, 103, 108
240	NYP	17	CTI	16	CTI	16	POU-CRT	MN	Meet metro jorth, Control Point, 46
244	NYP	30	WTR	30	WTR	18	ALB-HUD	AM	Slide fence activation Approach 133, signals didn't pick back up til 128, Milepost, 133, 128
291	BTN	26	DCS	27	DCS	16	HUD-ALB	AM	Slide fence restriction due to false actuation or out of service Milepost, 125, 128
43	PGH	25	WTR	14	SYS	13	PHL-PHL	AM	Re-crew / job briefing, ENGINE 121 ADDED
76	RGH	13	FTI	12	FTI	12	GRO-DNC	NS	Meet #NS51X, Control Point, Haw River
77	CLT	19	FTI	24	FTI	21	DNC-BNC	NS	In siding at haw river 74 meet. P07 was the root cause of time lost., P07. ns, Milepost, 34.1, 31.7
78	RGH	15	DSR	10	WTR	4	SAL-HPT	NS	Trees down Milepost, 301.8, 302.0
89	SAV	86	SYS	64	SYS	39	CHS-YEM	CS	PTC problem or failure (cause unknown) Logged out couldn't log back in. Ran restricted speed
90	NYP	No OS Rpt	WTR	347	WTR	314	XDJ-ALX	CS	Trees down Other, cfp 71.2
97	MIA	115	ENG	124	ENG	79	WAS-WAS	AM	Other electrical failure, 366-350, LATE DSLS FROM PIT DUE TO USING DSLS OFF LATE A41(20) AND A158(21)
40	TOL	827	SYS	330	SYS	314	CAM-HAM	CS	Re-crew / job briefing Waiting on relief cndr from JAX
41	MIA	480	ITI	205	ITI	205	CHI-CHI	AM	Service, turn, or wye train 40, Late inbound train, 40(18)
23	NOL	16	DCS	22	DCS	22	XNO-XEJ	NS	Power switch failure Talked by signal and had signal maintenance working on switch then we were able to go, Control Point, east city

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
5	EMY	280	DMW	300	DMW	300	XFJ-XXP	UP	Hold for defect repair Original crew instructed to shove train back to Denver due to broken rail from Arvada.	
									Stopped @ Arvada: 913am Stopped at Denver Union Station: 1013am, Other, DUS Track 4	
6	CHI	110	DSR	111	SYS	73	SAC-RSV	UP	Engineer off of 6(19) needed to get on 6(20), Meet Late train (5) unloading passengers and a re-crew., Amtrak 6 DHQ, Control Point, East Atkinson	
529	SJC	24	POL	18	POL	16	SUI-SUI	UP	EMS emergency, due to passenger medical situation . EMS removal of passenger at sui	
534	SAC	44	POL	47	POL	47	DAV-DAV	UP	Right of Way police hold Police activity at MP 85.38	
538	ARN	12	PTI	17	DSR	11	SAC-RSV	UP	Per bulletin Milepost, 95.35, 97.70, 15, mt 2	
543	SJC	26	PTI	14	CTI	13	GAC-SCC	UP	Meet ace, 8, Control Point, expressway	
547	SJC	28	ITI	21	ITI	21	SAC-SAC	UP	Service, turn, or wye train 534	
549	OKJ	Trn Cancelled	ENG	32	ENG	32	MTZ-MTZ	UP	Pick up rescue locomotive due to mechanical failure Picked up AMT 714 @ MTZ station, 2009	
551	OKJ	14	MBO	17	MBO	17	SUI-MTZ	UP	For maritime traffic Control Point, benicia	
51	CHI	79	ENG	92	ENG	92	XPV-BAL	AM	Other electrical failure, 604 EX ES, stopped at MP 92 reporting circuit breaker issues on E/604.	
502	SEA	40	CCR	41	CCR	41	PDX-PDX	BN	Bad order Speedometer 90222, Wye train due to badorder speedo on 90222.	
503	EUG	50	SYS	59	SYS	56	PDX-ORC	UP	PTC- PTC enforced braking PTC penalty stop D20. pTC went in failed stay. Cleared fault still could not recover. Had to reset PTC breaker and data radio breaker., Other, MP 770.0	
505	PDX	64	FTI	55	FTI	50	VAN-PDX	BN	Meet Freight blocking our route into station. Dispatcher instructed us to shove back to CP will bridge to clear track for freight movement., up 8031, Control Point, .05	
506	SEA	49	ITI	40	ITI	40	PDX-PDX	BN	Service, turn, or wye train 517	
507	EUG	27	ENG	48	ENG	20	CTL-KEL	BN	HEP WS1408	
516	VAC	34	MBO	24	MBO	24	XF2-X1J	BN	Waited on freight trains and for bridge operator to pull up signal for us to proceed. Bridge, Frasier River Bridge	

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
517	PDX	145	ENG	127	ENG	115	CTL-KEL	BN	Undesired emergency application Mp 54.1 first of six episodes of attempting to depart when engine went into emergency. Called Cnoc west desk and they attempted to fix it with a regular tech to no success. I asked for a talgo tech as soon as he got on the phone he fixed us, 7910
518	VAC	29	PTI	30	PTI	13	EVR-STW	BN	Meet 519, Siding, English
14	SEA	66	DCS	88	CTI	44	XNI-TAC	ST	Meet Disabled sounder 904 rescued by 906 @ Tacoma Dome, Sound Transit, 904, Control Point, Manitou
7	SEA	107	FTI	147	POL	53	HAV-SBY	BN	BNSF 5545 couldn't clear the siding due to a car accident., BNSF 5545, Siding, Dunkirk
27	PDX	-29	FTI	20	FTI	20	VAN-PDX	BN	Cross Traffic UP 8031, Control Point, Willbridge
821	FTW	23	FTI	32	FTI	15	PVL-ADM	BN	Follow bnsf 5183, Other, gene autry - ADM
822	OKC	23	FTI	22	FTI	17	FTW-GLE	BN	Meet BN7923, Siding, Ponder
329	MKE	40	SYS	40	SYS	15	GLN-GLN	ME	PTC problem or failure (cause unknown) Just after we left Glenview, PTC went into a failed state. Advised by Metra PTC desk to cycle breaker. It came back up for Metra, but the issue with CP persists. Proceeded at restricted speed., Milepost, 17.8, 17.8
332	CHI	36	ITI	28	ITI	28	MKE-MKE	CP	Service, turn, or wye train 329, 329 late due to PTC issues
341	MKE	Trn Cancelled							
342	CHI	15	DCS	6	DCS	6	GLN-XWA	ME	Power switch failure Control Point, A6
350	PNT	30	PTI	35	PTI	29	KAL-XGO	MI	Meet STOPPED AT GORD WAITING FOR LATE 351, 351, Other, Gord
351	CHI	77	ITI	86	ITI	86	PNT-PNT	CC	Service, turn, or wye train 354, Crew needed to spin equipment. Had issues getting permission into the Pontiac yard
352	PNT	Trn Cancelled							
354	PNT	286	SVS	198	SVS	196	CHI-CHI	AM	Planned set out / pick out of locomotives, cars or section of train Other, chi
355	CHI	165	TRS	91	TRS	91	XGO-KAL	MI	Trespasser strike 354 trespasser strike. Hold on all tracks.stopped at CP140, Other, 144.90

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
364	PTH	87	SVS	75	SVS	54	CHI-CHI	AM	Planned set out / pick out of locomotives, cars or section of train SET UP ISSUES / CAR MOVE., Other, CUS	
365	CHI	18	DSR	22	FTI	8	PTH-LPE	CC	Meet CN 3080, Siding, Emmett	
370	GRR	158	OTH	157	OTH	153	CHI-CHI	AM	Bad ordered cars 4133 and 4213, dealt code CAR resets to Home Screen and will accept delay code	
567	LAX	52	CAR	26	DCS	15	OSD-X98	SN	PTC- I-ETMS Red Fence/Signal Status Unknown Waiting on clearance to run cut out after authority to pass red signal., Control Point, Songs	
584	SAN	32	PTI	31	PTI	13	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano	
591	LAX	26	PTI	24	PTI	16	OSD-X98	SN	Meet 588, Control Point, songs	
770	SAN	55	TRS	39	TRS	39	SIM-CWT	SC	Vandalism Pax removed emergency window in Car C6462. Crew relocated all pax to other cars and closed off car before proceeding., Milepost, 442.75, 442.75	
774	SAN	34	ENG	25	ENG	25	SIM-CWT	SC	HEP c2116	
703	SAC	No OS Rpt	POL	51	POL	51	WAC-COC	BN	Fire department hold Hold for fire at MP 932.0	
710	BFD	54	PTI	22	TSV	22	OKJ-OKJ	UP	Fuel Equipment came in as 715 yesterday and was not fueled. After loco issues were resolved we were instructed to shove north after #6 departed and go from track 6 to track 2.	
711	OKJ	68	TEN	71	TEN	71	BFD-BFD	BN	Failure of diesel engine (CNOC LEVEL 2 - RE: SS 711(22) BFD- ITD) AS A RESULT OF SET UP ISSUES ON THE DOUBLE SET, 711(22) WILL SWAP EQUIPMENT WITH 701(22). 711(22) WILL OPERATE WITH C2014, C2124	
712	BFD	28	PTI	23	DCS	19	COC-WAC	BN	Flagging the block. Milepost, 949.8, 945	
714	BFD	Trn Cancelled	TEN	107	TEN	60	OKJ-OKJ	UP	PTC - On Board Cab Signal or PTC Failure CDTX2009	
715	EMY	237	TEN	145	TEN	118	ACA-ACA	BN	Undesired emergency application This locomotive applied undesired emergency brake application twice due to this delay our engineer died on the log and we had to wait for a new engineer, 2104	
716	BFD	75	DSR	16	PTI	6	ACA-SKN	BN	Meet 715, Control Point, trull	
717	OKJ	51	PTI	46	INJ	21	WAC-WAC	BN	Injured or sick passenger	

Amtrak Endpoint OTP Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/22/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
719	OKJ	30	CON	23	CON	23	BFD-BFD	BN	Hold for thruway bus
300	CHI	44	FTI	34	FTI	18	XUD-SMT	CC	Cross Traffic cn2999, Control Point, canal
301	STL	17	SYS	25	SYS	25	XTF-XUD	CC	PTC problem or failure (cause unknown) Control Point, 21st Street
305	STL	39	OTH	40	OTH	28	PON-BNL	UP	When I was putting under engine with idtx4631 code it wouldn't go through. So CNOC mechanical had us take the mu cable off from behind the engine had a code of 0657
391	CDL	31	FTI	41	FTI	31	MAT-EFG	CC	Follow Milepost w/Letters, north effingham, effingham, southbound cn
393	CDL	73	DBS	62	DBS	62	EFG-CEN	CC	Debris blocking track (no debris strike) Wait on track inspection, Control Point, tonti
1333	MSP	125	FTI	64	DMW	30	WIN-RDW	CP	Hold for defect repair Milepost, 375.6, 376.2

Amtrak Initial Terminal Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/22/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	626	06/22	1		
NFK	94	06/22	2	2	For maritime traffic Control Point, Harbor park
NOL	1	06/22	4	4	PTC problem or failure (cause unknown)
NPN	186	06/22	36	36	Hold for thruway bus
PHL	605	06/22	1		
WAS	2124	06/22	26	26	Service, turn, or wye train, 2159, LATE ARRIVAL OF INBOUND AM2159
BOS	173	06/22	72	57	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard
BOS	173	06/22	72	15	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard due to mechanical issues
BRK	684	06/22	1		
BRK	686	06/22	13	2	Contacting EIC HOLLAND for permission thru his working limits b/w mp bru 0.8 and mp bru 1.0 Milepost, 0.8, 1.0
BRK	686	06/22	13	4	Issue with automatic road crossing protection Other, Union St mp BRU 0.9
BRK	686	06/22	13	7	Late inbound. Brake test, train clearing, turnover, unloading/loading. 681
NYP	79	06/22	8	8	FDA, 43372, MECHANICAL REPAIRING REFRIGERATOR DOOR IN CAR 43372
NYP	97	06/22	10	10	Planned set out / pick out of locomotives, cars or section of train, DELAYED F/SSYD A/C NECCESARY TO WAIT FOR AM98 TO COMPLETE CONSIST AND SERVICE CARS
NYP	113	06/22	13	13	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	185	06/22	3	3	T.O.L, Other, NYP, TOL ON "U" LADDER "A" INT
NYP	193	06/22	6	6	Service, turn, or wye train, 84, LATE TURN OFF AM84
NYP	197	06/22	2	2	Passenger and/or baggage, BOARDING
NYP	239	06/22	6	6	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	291	06/22	4	4	Service, turn, or wye train, 240, LATE TURN OFF AM2140
NYP	649	06/22	2	2	Passenger and/or baggage, BOARDING
NYP	2109	06/22	21	21	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
CHI	341	06/22	(Trn Cxld)		Engine Issue
CHI	352	06/22	(Trn Cxld)		Equipment Issues
CHI	354	06/22	13	13	Bad ordered AMTK63, switched out to engine 4603 4603
CHI	364	06/22	54	54	Planned set out / pick out of locomotives, cars or section of train SET UP ISSUES / CAR MOVE., Other, CUS

Amtrak Initial Terminal Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/22/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	370	06/22	153	153	Bad ordered cars 4133 and 4213, dealt code CAR resets to Home Screen and will accept delay code
MKE	332	06/22	28	28	Service, turn, or wye train 329, 329 late due to PTC issues
PDX	502	06/22	41	41	Bad order Speedometer 90222, Wye train due to badorder speedo on 90222.
PDX	506	06/22	40	40	Service, turn, or wye train 517
PDX	518	06/22	7	7	Called to board all PAX at around 1340, station brought them out at around 1350. At 1405, they stated gates were closed and then at 1407, they stated that they had ADA to still board. Lost time due to trains 11 and 27 getting in and depot being too busy
PNT	351	06/22	86	86	Service, turn, or wye train 354, Crew needed to spin equipment. Had issues getting permission into the Pontiac yard
PNT	355	06/22	86	6	PTC problem or failure (cause unknown)
PNT	355	06/22	86	80	Other late crew
SEA	8	06/22	104	104	Service, turn, or wye train 7, Late inbound train . A lot freight traffic @ Stacy Wye.
SEA	11	06/22	15	15	PTC- PTC enforced braking D20 fault; System not active; Braking due to fault detected; *flashing* braking in progress
SEA	503	06/22	2	3	PTC problem or failure (cause unknown) Control Point, king street
SEA	507	06/22	2	2	Conductor working alone/crew shortage. Working conductor only, delayed arrival of van to take crew to the train., Other, Sea station
TOL	41	06/22	163	163	Hold for bus with passengers from train 5 express bus and 1 local bus. From CHI. AMT 41 started out of Toledo
BFD	703	06/22	20	20	Hold for thruway bus
BFD	711	06/22	71	71	Failure of diesel engine (CNOC LEVEL 2 -RE: SS 711(22) BFD- ITD) AS A RESULT OF SET UP ISSUES ON THE DOUBLE SET, 711(22) WILL SWAP EQUIPMENT WITH 701(22). 711(22) WILL OPERATE WITH C2014, C2124
BFD	715	06/22	56	56	Pick up equipment
BFD	719	06/22	23	23	Hold for thruway bus
EMY	718	06/22	319	319	Service, turn, or wye train 715, Extremely late arrival of 715
GTA	782	06/22	14	14	Meet 14, Control Point, CP CO 358
LAX	562	06/22	8	8	Trespasser riding on knuckle Other, LAUPT
OKC	821	06/22	6	6	Meet bnsf 6175, Other, okc
OKJ	534	06/22	3	3	Meet We were ready to leave on time but had to wait for Amt 716 to arrive at OKJ then Amt 716 we're having PTC issues in the OMF yard and we had wait for signal to time out in order to depart OKJ, Amt 716, Control Point, N. Jack London

Amtrak Initial Terminal Details

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/22/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	710	06/22	44	22	PTC - On Board Cab Signal or PTC Failure PTC in a strange screen that wouldn't exit because engine was shut down, 2010
OKJ	710	06/22	44	22	Fuel Equipment came in as 715 yesterday and was not fueled. After loco issues were resolved we were instructed to shove north after #6 departed and go from track 6 to track 2.
OKJ	712	06/22	5	5	Air Leak in Cab Car. 8303, Left yard late due equipment swap.
OKJ	714	06/22	60	60	PTC - On Board Cab Signal or PTC Failure CDTX2009
OKJ	716	06/22	(Trn Cxld)		Third Party Cab Car Failure
SAC	539	06/22	1	1	Restrictive signal(s) from unknown cause Red, Control Point, RV988
SAC	547	06/22	21	21	Service, turn, or wye train 534
SAN	581	06/22	18		
SAN	591	06/22	14	14	Air / Brake / Wheel 1, Mechanical Changing brakes on NPCU 9700
SAN	593	06/22	4	4	Red signal Control Point, ash
SJC	528	06/22	4	4	Caltrain train had a trespasser strike right before us leaving SJC. Caltrain, Unknown, Other, North of SCC station
SJC	530	06/22	2	2	Follow Caltrain, 121, Control Point, Alameda
SJC	538	06/22	1		
SLO	786	06/22	2	2	Person pulling emergency cord Two people dropping someone off were still on the train after announcement made by conductor saying last call and to step off if you weren't traveling with us. Two people did not step off until doors were closed and then pulled an emergency door release

Eastern Region

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.8	98.8	94.8	342	4
CDOT	95.0	95.0	91.6	92.4	20	1
MARC	95.0	82.8	83.5	90.2	58	10
SEPTA	95.0	91.4	94.4	91.5	221	19
NJT-NED	95.0	94.9	91.6	88.6	350	18
NJT-SED	95.0	100.0	98.3	97.2	12	0

Operating Highlights

Train 89(22) - South of Selma, NC - Freight Train Interference

23JUN26: Train 89(22) was delayed on the CSX South End Subdivision at MP 175.0 due to CSX Freight Train M491-22 going into emergency ahead at MP 187. After the freight crew resolved the issue and cleared their train, Amtrak 89(22) was able to continue south.

Train	Delay	Comment
89(22)	0'49"	

Train 41(20) - North of Miami, FL - Daily Inspection

23JUN26: Train 41(20) was delayed on the SFRTA Miami Subdivision at MP 1027.4 due to the crew having to complete the mandatory daily inspection on the equipment.

Train	Delay	Comment
41(20)	1'50"	

North of Ashland, VA - Weather/Downed Trees and Commercial Power Lines

22JUN26: CSX reported downed trees on its RF&P Subdivision between Quantico and Ashland. The primary blockages were near MP 75.6. There were numerous secondary impact locations. Once on the scene, CSX MW personnel reported commercial power lines were down in spots in addition to the trees. Crews worked to remove the trees and other debris from the right of way.

Multiple Amtrak trains were delayed.

Train	Delay	Comment
97(22)	2'47"	
93(22)	3'35"	
90(22)	5'07"	
186(22)	4'47"	
151(23)	1'30"	estimated - Turning off 186(22)

Next Gen Train 2120(22) Washington, DC - Servicing

22JUN26: Next Gen Train 2120(22) was delayed departing Washington due to set 24 coming from the S&I.

Train	Delay	Comment
2120(22)	1'15"	

Train 186(22) Newport News, VA - Hold for Connection

22JUN26: Train 186(22) with E/318, E/83 and 10 cars with 126 customers onboard was delayed on the CSX Sanford A subdivision due to meeting CSX Q31 at CP United. Holding for 24 connections off late connecting bus 6186(22).

Train	Delay	Comment
186(22)	0'36"	

Train 98(22) North of Sebring, FL - Freight Train Interference

22JUN26: Train 98(22) with E/318, E/83 and 10 cars with 126 customers onboard was delayed on the CSX Sanford A subdivision due to meeting CSX Q31 at CP United.

Train	Delay	Comment
98(22)	0'40"	

Train 647(22) New York, NY - Engine Failure

22JUN26: Train 647(22) with CC/9646 and E/600 with 4 cars departed New York but stopped at A Interlocking with cab signal issues. The crew was unable to clear the penalty and shoved back into the station where mechanical met the train. They departed again after mechanical was able to rectify the issue.

Train	Delay	Comment
647(22)	0'34"	
2119(22)	0'10"	

Train 41(20) South of Jesup, GA - Passenger Train Interference

22JUN26: Train 41(20) with E/333, E/98 and 10 cars with 199 customers onboard was delayed on the CSX Nahunta subdivision holding for 97(21) to clear the station.

Train	Delay	Comment
41(20)	0'39"	

Train 42(22) East of Lewistown, PA - Freight Train Interference

22JUN26: Train 42(22) with E/125 and 7 cars with 262 customers onboard was delayed on the NS Altoona subdivision due to following NS 269 from MP 125 to MP 119.

Cause: Pending

Train	Delay	Comment
42(22)	0'31"	

Train 684(22) South of Freeport, ME - Debris

22JUN26: Train 684(22) with E/94, E/113 and 5 cars with 48 customers onboard was delayed on the CSX Portland PLD at MP 0.4 due to the train going into emergency. The crew inspected the equipment and reported a debris strike that knocked multiple air hoses loose.

Train	Delay	Comment
684(22)	0'43"	

Train 173(22) Boston, MA - Servicing

22JUN26: Train 173(22) with E/0551 and 8 "UNCLASSIFIED" cars with 186 customers was delayed departing Boston due to the late release of equipment from the yard.

Train	Delay	Comment
173(22)	1'12"	

CSX Heat Orders - Weather

22JUN26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Baltimore Terminal, Capital, North End, Peninsula, RF&P, Richmond Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
186(22)	0'20"	
25(22)	0'06"	
53(22)	0'26"	
40(22)	1'04"	
125(22)	0'18"	
79(22)	1'06"	
90(22)	0'33"	
89(22)	0'39"	
171(22)	0'08"	
95(22)	0'36"	
138(22)	0'24"	
98(22)	0'25"	
94(22)	0'07"	
80(22)	0'30"	
97(21)	0'36"	
41(21)	0'21"	
40(21)	0'28"	
20(21)	0'03"	

Train 2107(22) Washington, DC - Car Failure

22JUN26: Legacy train 2107(22) upon arrival into Washington set 10 was shopped due to LVPS on C/3540. There was no replacement Legacy set of equipment so trains 2112(22) and 2123(22) were cancelled in their entirety and customers were advised to rebook on the next available service.

Train	Delay	Comment
2123(22)	0'00"	cancelled
2112(22)	0'00"	cancelled

Train 151(22) Washington, DC - Engine Failure

22JUN26: Train 151(22) with E/329 and 5 cars with 129 customers was delayed due to having PTC issues. The crew was able to initialize CSX and Amtrak they were instructed to depart and attempt to initialize when they are closure to the NS territory.

Train	Delay	Comment
151(22)	1'11"	

Train 141(22) South of Springfield, MA - Vehicle on Tracks/Trespasser Incident

22JUN26: Train 141(22) with E/120 and 8 cars with 18 customers onboard was delayed on the MRS Springfield Line at MP 54.4 due to vehicle on the tracks ahead at MP 48.1/Dexters and MP 48.5/Bridge St.

Train	Delay	Comment
141(22)	0'51"	

21JUN26: Train 40(20) engine 309, "UNCLASSIFIED" carried 228 customers onboard was stopped at milepost 578.0, 14 miles north of Jacksonville, FL on the CSX Nahunta subdivision due to striking a tree and shattering both windshields of engine 309. There were no reported injuries to the crew or the customers. The train maintained head end power and remained intact on the rails. The weather was rainy and 72 degrees. Engine 309 was no longer able to lead due to the significant damage. The engines were back-to-back so that required the engines to be wye'd to continue. A CSX freight diesel was secured and was able to operate the train into Savannah. Engines 309 and 341 were taken around the wye.

The train was further delayed on the CSX Hamlet subdivision due at MP 273.0 due to holding for the recrew conductor coming from Jacksonville and stuck in traffic.

Due to the late operation of train 40(20) the following service adjustments were put into effect:

- Train 40(20) to terminate at Toledo, OH with three buses secured. Two buses operating express to Chicago, IL and one bus making all scheduled stops.
- Train 41(22) to originate in Toledo, OH with six buses secured. Five buses operating express to Toledo, OH and one bus making all scheduled stops.

Service Recovery was initiated with beef stew and rice and bottled water, First class passengers were served lunch from the menu in the diner.

Additional Service Recovery all coach customers offered complimentary coffee or tea with a choice of a breakfast sandwich, muffin or coffee cake. First class customers were served breakfast from the diner as normal.

AN# L-FY26-1152

WBS#: B.TR.100150.6793

Train	Delay	Comment
40(20)	3'52"	
40(20)	3'13"	SAV
40(20)	5'14"	Recrew
40(20)	0'00"	Term TOL
41(22)	0'00"	Orig TOL

16-FOIA-00554 00000007873 UNCLASSIFIED 6/23/2016
MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday

Work will occur Monday 26 For 00551, 00000007873 - 2 UNCLASSIFIED at W 6/23/2026 Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

Eastern Region

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
291 (4)	CRT	9705		Trail link bolts broken

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
90	WAS	1	NCR	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 5(22) East of Creston, IA - Maintenance Overstay

22JUN26: Train 5(22), with 220 customers onboard, was delayed at mile post 370.6 22.5 miles east of Creston, IA/MP393.1 on the BNSF Ottumwa subdivision due to a Maintenance of Way overstay. Once the maintenance of way crew cleared the route, train 5(22) was able to continue to Creston, IA.

Train	Delay	Comment
5(22)	4'22"	

Train 703(22) West of Wasco, CA - Fire near ROW

22JUN26: Train 703(22), carrying 85 customers onboard, was delayed west of Wasco, CA, at Sandrini (MP 925.4) on the BNSF Bakersfield Subdivision due to a trackside fire near the right-of-way at approximately MP 932. Rail traffic was halted while the fire department responded and secured the area.

Once the fire was contained and the track was released by emergency personnel, Train 703(22) resumed its trip.

Train	Delay	Comment
703(22)	0'51"	

Train 14(21) South of Tacoma, WA - Commuter Train Interference

22JUN26: Train 14(21), with 200 customers onboard, was delayed at Manitou/MP6.9 5 miles south of Tacoma, WA/MP1.9 on the Sound Transit Lakewood subdivision meeting disabled Sounder train 904. Sounder train 906 arrived and coupled to the 904 equipment. After 906 opened a route by moving 904 into the clear, train 14(21) continued north.

Train	Delay	Comment
14(21)	0'44"	

Train 354(22) West of Kalamazoo, MI - Struck Cyclist

22JUN26: At 8:28PM CT, train 354(22), with engine IDTX4603, 5 cars, and 264 customers onboard, struck a cyclist at a highway grade crossing, Inventory #545472D, at mile post 144.90 1.5 miles west of Kalamazoo, MI/MP143.4 on the Amtrak Michigan Line. The strike was fatal. No injuries were reported among the customers or crew. No damage was reported to the equipment. The crew did not request relief. HEP remained active throughout the incident. The highway grade crossing was protected by flashing lights, gate arms, pavement markings, and signs. Weather conditions were mostly cloudy with 6MPH winds. Upon release from the scene, train 354(22) advanced to Kalamazoo and parts east.

Train 355(22) held at mile post 140.00 3.5 miles east of Kalamazoo for an open route through the area. Once local police concluded the investigation at the scene, 355(22) continued west.

National Response Center Number: 1465916

Train	Delay	Comment
354(22)	1'22"	
355(22)	1'31"	

Train 341(22) Chicago, IL - Engine Failures

22JUN26: Train 341(22) with 500 000 000 7873 "UNCLASSIFIED" and 6/23/2026 3 cars, and 123 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision. Inbound train 1340(22) lead engine 519 suffered a shattered windshield due to kids throwing rocks east of Milwaukee, WI. Engine 514 was selected to be added ahead of train 341(22). After the equipment was made up complete, the crew on train 341(22) reported setup issues multiple times. Chicago Mechanical responded each time, but the issues continued. Train 341(22) was ultimately cancelled in its entirety with one alternate bus secured, making all stops. Engines 519 and 514 were held off in Chicago and engine 171 was added to deadhead the equipment to Milwaukee, WI for June 23rd service.

WBS#: B.TR.100150.6797

Train	Delay	Comment
341(22)	0'00"	Cancelled CHI-MKE

Train 393(22) North of Centralia, IL - Debris on the Tracks

22JUN26: Train 393(22) was delayed at Tonti siding/MP238.0 15 miles north of Centralia, IL/MP252.3 on the CN Champaign subdivision due to debris on the tracks ahead. Once the track inspectors arrived on the scene, cleared the debris, and confirmed the rail was in good order, train 393(22) continued south.

Train	Delay	Comment
393(22)	1'02"	

Train 8(22) Seattle, WA - Initial Terminal Delay

22JUN26: Train 8(22) was delayed departing Seattle, WA Station due to a late inbound turn from Train 7(20), with the consist requiring servicing and a wye move prior to entering revenue service. Once the necessary servicing and turning were completed, the train was released and departed Seattle with 105 customers onboard.

Train	Delay	Comment
8(22)	1'44"	

Train 4(21) East of Trinidad, CO - Tornado Warning

22JUN26: Train 4(21), carrying 212 customers onboard, was delayed east of Trinidad, CO, on the BNSF Raton Subdivision due to a tornado warning in the area requiring reduced operating speeds. The train operated at approximately 20 MPH between MP 591 and MP 569, resulting in additional delay through the territory. Once clear of the restricted zone and conditions improved, Train 4(21) resumed its eastbound trip.

Train	Delay	Comment
4(21)	1'02"	

Train 11(22) Salem, OR - Air Brake Issues

22JUN26: Train 11(22), operating with locomotives E/363 and E/345 and nine cars, was delayed at Salem, OR Station while the crew troubleshot air brake issues. The train was able to resume movement; however, a subsequent delay occurred at Eugene, OR Station for continued troubleshooting. Further inspection determined the issue to be bottled air in locomotive E/345. Once the condition was corrected and the brake system restored, Train 11(22) continued its trip with 270 customers onboard.

Train	Delay	Comment
11(22)	0'17"	SLM
11(22)	0'18"	EUC

22JUN26: Train 534(22) was delayed while holding at Davis, CA Station on the Union Pacific Martinez Subdivision due to police activity ahead near MP 85.38. The train remained stopped until authorities secured the area and released the track for movement. Once clearance was received, Train 534(22) resumed its trip without further incident.

Train	Delay	Comment
534(22)	0'47"	
547(22)	0'21"	late turn

Train 1333(22) East of Red Wing, MN - Freight Train Interference

22JUN26: Train 1333(22), with 202 customers onboard, was delayed at Colvill/MP368.0 2.68 miles east of Red Wing, MN/MP370.68 on the CPKC River subdivision meeting CPKC freights 224 and 823. Train 1333(22) held at Colvill while a CPKC maintenance of way crew repaired a thermal rail defect at Duke/MP375.6 5 miles west of Red Wing. Once the track was open, train 1333(22) followed CPKC freights 374 and 116 to Red Wing.

Train	Delay	Comment
1333(22)	0'25"	Meet 224, 823 at Colvill
1333(22)	0'30"	DMW W/RDW
1333(22)	0'20"	Follow 374, 116

Train 3(21) West of Albuquerque, NM to Flagstaff, AZ - Freight Train Interference

22JUN26: Train 3(21) was delayed west of Albuquerque, NM on the BNSF Glorieta Subdivision while meeting BNSF 7531 and BNSF 6942 near Dallies (MP 27.2). The train experienced additional delay while following a freight train between approximately MP 111.2 and Gallup, NM Station (MP 157.6). West of Gallup, further delay was incurred while following a stack train from East Winslow (MP 285.7) to Flagstaff, AZ (MP 344.5) on the BNSF Seligman Subdivision.

Train	Delay	Comment
3(21)	1'22"	WLO-FLG
3(21)	0'45"	ABQ-GLP

Train 8/28(21) Shelby, MT to Williston, ND - Freight Train Interference

22JUN26: Train 8/28(21), carrying 211 customers onboard, was delayed while operating east of Shelby, MT, across the BNSF Hi Line, Milk River, and Glasgow Subdivisions due to multiple freight train meets throughout the territory. The train first encountered delays at Shelby Station meeting BNSF 6849, followed by additional meets at Devon (MP 1046.4) with BNSF 5320, and at Havre West (MP 432.1) with BNSF 6338 and BNSF 9044 on the Milk River Subdivision.

Continuing east onto the Glasgow Subdivision, the train was delayed at East Glasgow Siding (MP 276.1) meeting BNSF 4085, and again at Nashua (MP 262.8) meeting BNSF 3269. Further east, additional meets occurred at Poplar (MP 205.5) with BNSF 5167 and at Bainville (MP 159.3) with BNSF 7727.

Once all freight movements were completed and the route was released, Train 8/28(21) resumed its eastbound trip.

Train	Delay	Comment
8/28(21)	0'22"	WPT-WTN
8/28(21)	0'44"	GGW-WPT
8/28(21)	0'47"	SBY-HAV

Train 714(22) Martinez, CA - Third Party Contractor Engine Failure

22JUN26: Train 714(22) with cab car CC/8306, five cars, locomotive E/C2009, and 65 customers onboard, was delayed while approaching and holding at Martinez, CA (MTZ) on the Union Pacific Martinez Subdivision due to locomotive performance issues, specifically alarms when operating above throttle notch 1. Head end power remained operational throughout the incident. The crew coordinated with TASI Mechanical and Amtrak management, with a Road Foreman (RFE) responding to assist with troubleshooting; however, the issue could not be resolved in the field. This resulted in following service adjustments:

- Train 714(22) was terminated at Martinez, and all customers were transferred to Train 716(22) for continued travel.
- Train 549(22) was assigned to couple onto the consist at Martinez for return to Oakland Mechanical Facility and train was terminated at Emeryville, CA.
- Train 713(23) was canceled in its entirety, with customers directed to utilize next available service options.

Train	Delay	Comment
714(22)	0'00"	TERM MTZ
716(22)	0'04"	MTZ
549(22)	0'32"	TERM EMY
713(23)	0'00"	CANCELED

Train 1(22) East of Houston, TX - Routing

22JUN26: Train 1(22), with 116 customers onboard, was delayed beginning at LF356/MP356.5 6.3 miles east of Houston, TX/MP362.3 on the UP Houston subdivision due to being rerouted by dispatch from the east belt to the west belt. Train 1(22) returned to the normal route at Maury St/MP360.8 and continued into Houston, TX.

Train	Delay	Comment
1(22)	0'33"	

Train 517(22) Centralia, WA - Penalty Issues / Door System

22JUN26: Train 517(22), carrying 245 customers onboard, was delayed at Centralia, WA (CTL) due to air brake issues on the consist, which included cab car CC/7910, 12 cars, and locomotive WS1405. The train experienced penalty brake applications, impacting normal operation. The crew coordinated with the CNOC Mechanical Desk to troubleshoot the issue and successfully rectified the brake condition, reported to be caused by door systems. Once repairs were completed and the train was confirmed safe for operation, Train 517(22) departed Centralia, WA.

Train	Delay	Comment
506(22)	0'40"	late turn 517(22)
517(22)	1'05"	

Train 364(22) Chicago, IL - Late Equipment Release

22JUN26: Train 364(22), with engines IDTX4620 and IDTX4616, 6 cars, and 276 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late release of the equipment by Chicago Mechanical. After a planned addition of the married pair IDTX4308/IDTX4122, mechanical investigated setup issues. Once the equipment was made up complete, train 364(22) shoved into the depot, boarded customers, and departed Chicago.

Train	Delay	Comment
364(22)	0'54"	

Train 505(22) East of Portland, OR - Freight Train Interference

22JUN26: Train 505(22) with 18 customers was delayed east of Portland, OR at MP 1.0 on the BNSF Fallbridge subdivision. The delay was caused from interference from 2 freight trains. UPRR operated F PWVAAB1 in front of F ZLCTM1 21 on Steel bridge which blocked the route for 505(22) at CP 05. Crew was instructed to shove back to Willbridge at MP 4.1 to clear route for the freight train's movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
505(22)	0'50"	

Train 355(22) Pontiac, MI - Initial Terminal Delay

22JUN26: Train 355(22) with 10 customers was delayed departing Pontiac due to a late arriving engineer, who was reported to be stuck in traffic.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(22)	1'20"	

Train 714(22) Oakland, CA - PTC

22JUN26: Train 714 (22), with locomotive C2009 and 131 total downline customers, was delayed departing Oakland, CA on the UP Niles Subdivision due to PTC issues. The train was initially unable to initialize PTC in the yard. After troubleshooting, the crew successfully initialized the system; however, it would disengage as soon as the train began to move. Continued troubleshooting resolved the issue, allowing the train to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(22)	1'00"	

Amtrak Michigan Service - Car Failure

22JUN26: Due to C/ID4114-4313 bad ordered for parking brake on C/ID4313 and C/ID4111-4202 bad ordered for condemnable flat spots. As a result, train 352(22) was cancelled between Chicago and Pontiac with alternate bus transportation. Additionally, train 353(23) was cancelled between Pontiac and Chicago with alternate bus transportation.

Train 370(22) was delayed departing Chicago due to the late makeup of the equipment due high shop counts.

WBS#: B.TR.100150.6796

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
370(22)	2'33"	

Train 503(22) South of Portland, OR - System

22JUN26: Train 503(22), with locomotive WS1404 and 156 customers, was stopped south of Portland, OR at MP 770.3 on the UPRR Brooklyn Subdivision due to PTC issues. With assistance from CNOC Mechanical, the crew cycled the PTC breaker. This was a recurring issue throughout the day caused by a PTC update that generated a software error code, placing the train into immediate penalty. It was determined that the solution was to cycle the PTC and Radio breakers at the same time.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(22)	0'56"	

Train 770(22) East of Simi Valley, CA - Vandalism

22JUN26: Train 770 (22) with 1066 customers "UNCLASSIFIED" delayed east of Simi Valley, CA at MP 442.75 on the SCRRA/Metrolink Ventura Subdivision after a passenger in car C6462 removed an emergency window. The crew stopped the train, relocated all customers to other cars, and secured the affected car before continuing.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
770 (22)	0'39"	

Train 502(22) Portland, OR - Cab Car Failure

22JUN26: Train 502 (22), with 108 customers, was delayed departing Portland, OR on the BNSF Fallbridge Subdivision due to a bad-ordered speedometer on cab car 90222. The train had to be wye'd to address the issue, which resulted in a departure delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
502 (22)	0'41"	

Train 710(22) Oakland, CA - Third Party Contractor Engine Failure

22JUN26: Train 710 (22), with 239 total downline customers, was delayed departing Oakland, CA on the UPRR Niles Subdivision due to a late release from the Oakland mechanical facility. Locomotive C2010 shut down unexpectedly, followed by PTC issues. After troubleshooting resolved these problems, the locomotive required fueling, which further extended the delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
710 (22)	0'44"	

Train 391(22) North of Effingham, IL - Freight Train Interference

22JUN26: Train 391(22) with 61 customers was delayed on the CN Champaign two miles north of Effingham at North Effingham/MP 196.8 meeting unknown CN freight and following to Effingham/MP 203.1.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
391 (22)	0'31"	

Train 19(21) South of Atlanta, GA - Signal

22JUN26: Train 19(21) was delayed on the NS Atlanta North district 13 miles south of Atlanta due to signal issues at Lowe/MP 137.2.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19 (21)	0'35"	

Train 711(22) Bakersfield, CA - Third Party Contractor Engine Failure

22JUN26: Train 711(22), carrying 68 "UNCLASSIFIED" rs 6/23/2026, was delayed departing Bakersfield, CA on the BNSF Mojave Subdivision following the cancellation of Train 713(22) due to a hydrostatic oil leak on locomotive C2124. Per TASI Mechanical guidance, the affected equipment was initially configured into a double-draft arrangement with Train 711(22), placing C2124 in the lead as a control stand. However, after testing, air and head-end power (HEP) issues were identified, and Mechanical determined that C2124 could not function in that configuration. To mitigate the impact, a decision was made to swap equipment with Train 701(22), and the defective consist was reassigned to operate in a double set on the rear of Train 715(22) for movement to maintenance.

Train 715(22), carrying 152 customers onboard, was later delayed after becoming disabled at Antioch-Pittsburg, CA (ACA) due to additional mechanical issues. Crews worked with TASI technicians and Amtrak management, with a Road Foreman and relief engineer responding to assist. After troubleshooting, the train was released and departed ACA at 7:34 PM PT, operating approximately 3 hours and 40 minutes late.

Due to ongoing equipment concerns, Train 715(22) was scheduled to terminate at Emeryville (EMY), after which the consist was routed to the Oakland Maintenance Facility (OMF) to set out the bad-ordered C2124 equipment. The remaining equipment was then used to turn for a late Train 718(22) originating from Emeryville.

Train	Delay	Comment
711(22)	1'11"	
713(22)	0'00"	Canceled
715(22)	0'56"	BFD
715(22)	1'58"	ACA
718(22)	5'19"	Late Turn & ORIG EMY

Train 7/27(20) West of Whitefish, MT - Freight Train Interference

22JUN26: Train 7/27 (20), carrying 173 customers, was delayed west of Whitefish, MT at MP 1251.8 on the BNSF Kootenai River Subdivision due to freight traffic interference. The delay resulted from meets with BNSF 7800 at Brimstone siding, BNSF 5512 at Twin Meadows siding, BNSF 3844 at Tamarack siding, and BNSF 6040 at Fisher River siding.

Train	Delay	Comment
7/27(20)	0'35"	

Train 351(22) Pontiac, MI - Initial Terminal Delay

22JUN26: Train 351(22) with 17 customers was delayed departing Pontiac on the CN Holly subdivision due to the CN Flint yardmaster unresponsive, resulting in a late turn of power. Once the power was turned and added to the consist, 351(22) departed Pontiac at 746MA-ET, 1 hour, and 26 minutes late.

Train	Delay	Comment
351(22)	1'26"	

22JUN26: Train 329(22) with E/ID4605, five cars, E/ID4627, and 254 customers was delayed after departing Chicago due to PTC issues on the CPKC that were related to a back office software upgrade that was not implemented on CSX, NS, or CPKC. The crew was able to establish PTC with Amtrak and Metra, but not CPKC. Train 332(22) was delayed departing Milwaukee due to the late arriving crew from 329(22) and departed Milwaukee at 833AM-CT, 28 minutes late.

Train 350(22) with E/ID4605, five cars, E/ID4627, and 254 customers was delayed after departing Chicago due to being unable to initialize PTC on the NS, requiring the crew to continue at 59mph.

Train 301(22) with E/ID4611, five cars, and 170 customers was delayed after departing Chicago on the Amtrak Chicago subdivision due PTC issues at CP 21st Street/MP 1.64 account PTC error messages showing on E/ID4611.

Train 20(22) with E/152-151-507, eight cars, and 156 customers was delayed on the Amtrak NOUPT just after departing New Orleans due to PTC issues related to the software download. The crew worked with mechanical to rectify the issues.

Train 1(22) with E/11-163, seven cars, and 124 customers departed New Orleans four minutes late due to PTC issues and was stopped again eight miles west of New Orleans due to PTC related fault codes. The crew worked with CNOC mechanical to clear the faults and continued to Schriever.

Train 5(22) with E/135-45, nine cars, and 196 customers departed Chicago and was delayed at Lumber/MP 1.46 due to PTC issues with a penalty brake application on E/135. The crew worked with CNOC mechanical to recycle and continued west.

Train 354(22), with engine IDTX4603, 5 cars, and 269 customers onboard, was delayed at Taylor/MP0.48 0.48 miles south of Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to multiple PTC faults. The crew reported at D20 fault and, after the fault was cleared and PTC initialized, a D13 fault when the engineer tried to pull. After reinitializing PTC, train 354(22) was able to continue south.

Train 503(22) with CC/90251, 3 cars, and E/WS1404 was delayed departed Portland, OR with PTC failure noting fault D20 on the CDU. Crew reset both the PTC breaker and Data Radio Breaker to resolve.

Train 716(22) operating CC/C8310, 7 cars, and E/C2014 was delayed departing the Oakland Yard unable to initialize the PTC system. System troubleshot with local TASI technicians until they were able to activate system. Due to late operation the train originated at Emeryville, CA.

Train	Delay	Comment
329(22)	0'31"	
332(22)	0'28"	MKE - late arriving crew
350(22)	0'27"	
301(22)	0'25"	
20(22)	0'14"	
1(22)	0'27"	
5(22)	0'27"	
354(22)	0'44"	
503(22)	0'56"	PDX
716(22)	1'08"	ORIG EMY

Train 21/421(21) North of Little Rock, AR - Freight Train Interference

22JUN26: Train 21/421(21) was delayed on the UPRR Little Rock subdivision starting 26 miles north of Little Rock between MP 319 and MP 334 due to following UP6926.

Train	Delay	Comment
21/421(21)	0'36"	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1(15NOV)/421(14NOV)	Bypass PSN	
1(18-21FEB)/421(17-20FEB)	BYPASS - Palm Springs	Flooding
2/422(18, 20, 22FEB)	Bypass Palm Springs	Flooding
1(30)/421(29)(MAR)	Bypass PSN	
1(01APR)/421(31MAR)	Bypass PSN	
1(04APR)/421(03APR)	Bypass PSN	
1(23, 31DEC)421(23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422(24DEC)	Bypass PSN - Flooding	
1(03, 05JAN)/421(02, 04JAN)	BYPASS PSN - flooding	
2/422(04, 07JAN)	BYPASS PSN - flooding	
2/422(01, 03, 05APR)	Bypass PSN	
1(06, 13, 18, 20, 23MAY) 421(05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422(13, 15, 20, 24MAY)	Bypass PSN	
1(08, 15, 17JUN)421(07, 14, 16JUN)	Bypass PSN	
2/422(17JUN)	Bypass PSN	
1(20)/421(19)	0'00"	BYPASS PSN
2/422(21)	0'00"	BYPASS PSN

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has tie replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

16MAY26: Metra has t26-FOI-00551rk 00000007873uled "UNCLASSIFIED" C&M 6/23/2026 Division at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

-Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

Western Region

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
3(21)	GLP	1	WLO	

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00551

00000007873

"UNCLASSIFIED"

6/23/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
236 (22)	ALB	business class car used in lieu of coach	NONE	0	81527
244 (22)	ALB	b/c car sed xin lieu of coach	NONE	0	81527
85 (22)	BOS	operating with business class in lieu of coach	none	0	81539
85 (22)	BOS	85(22) operating with a Business Class car in lieu of a coach. Capacity reduced 10 seats, no impact to ridership.	NONE	0	81539
173 (22)	BOS	There will be no Business Class available due to 81502 shopped off 132(21) trespasser strike equipment with no replacement Business Class car in BOS.	passengers notified and downgraded to coach.	56	81502
3 (22)	CHI	Sleeper operating in lieu of dorm. No passengers adversely affected.	none	0	32033
5 (22)	CHI	Non H room dorm operating in lieu of transition sleeper. Please check the war reports and re-accommodate any displaced passengers.	none	0	39006
650 (22)	HAR	650(22) operating with 4 coaches and cafe for Wi-Fi services due to no available cab cars or additional coaches in NYP.	n/a	0	
40 (22)	HIA	c/68010 was shopped for shocks. No other iners are available. Hia will add a seong lounge 28015	none	0	68010
562 (22)	LAX	no bike or wifi service	YES	6	9700
580 (22)	LAX	no bike or wifi service	YES	6	9700
4 (22)	LAX	Snack coach in lieu of standard coach. No passengers adversely affected.	NONE	0	35010
233 (22)	NYP	b/c car used in lieu of coach	NJONE	0	81527
243 (22)	NYP	b/c car used xin lieu of coach	NONE	0	81527
181 (22)	NYP	due to 82559 being shopped off 181(22), train 174(22) will be over capacity by 36 seats. Customer service notified	YES	36	82559
641 (22)	NYP	641(22) operating with 4 coaches and cafe for Wi-Fi services due to no available cab	n/a	0	

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00551 00000007873 "UNCLASSIFIED"			
		cars or additional coaches in NYP.			
653 (22)	NYP	653(22) operating with 4 coaches and cafe for Wi-Fi services due to no available cab cars or additional coaches in NYP.	n/a	0	
591 (22)	SAN	no bike or wifi service	YES	6	9700
573 (22)	SAN	no bike or wifi service	YES	6	9700
198 (22)	WAS	198(22) operating with a Business Class car in lieu of a coach. Capacity reduced 10 seats, no impact to ridership.	NONE	0	81539
174 (22)	WAS	Due to 82559 being shopped off 181(22), train 174(22) will be over capacity by 36 seats. Customer service notified	n/a	0	82559

Reverse Consists

Train Number	Station	Reason
181 (22)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (22)	NYP	Consist reversed Business class seat orientation may have changed At Front
85 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
183 (22)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (22)	PHL	Consist reversed Business class seat orientation may have changed At Front
125 (22)	SPG	Consist reversed Business class seat orientation may have changed At Front
137 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
178 (22)	RNK	Consist reversed Business class seat orientation may have changed At Front
182 (22)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (22)	NYP	Consist reversed Business class seat orientation may have changed At Front
171 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
125 (23)	SPG	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00551	00000007873 "UNCLASSIFIED" 6/23/2026
86 (23)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (23)	BOS	Consist reversed Business class seat orientation may have changed At Front	
178 (23)	RNK	Consist reversed Business class seat orientation may have changed At Front	
198 (22)	WAS	Business class change only Business class seating orientation may have changed At Rear	