



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, September 09, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/08/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/08/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	318	41	87.1%	2,503	370	85.2%	103,025	14,338	86.1%
Central Division	86.0%	58	4	93.1%	466	62	86.7%	19,661	1,837	90.7%
East Division	82.0%	177	24	86.4%	1,343	158	88.2%	54,163	8,292	84.7%
West Division	86.0%	83	13	84.3%	694	150	78.4%	29,201	4,209	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008779 UNCLASSIFIED 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	101,151	23,408	77%	846,300	227,087	73%	34,437,346	8,813,067	74%
Northeast Corridor	81%	48,340	6,996	86%	379,244	67,375	82%	15,094,143	3,654,657	76%
Acela	83%	11,295	1,727	85%	82,032	10,128	88%	3,044,658	769,268	75%
Northeast Regional	79%	37,045	5,269	86%	297,212	57,247	81%	12,049,485	2,885,389	76%
Richmond / Newport News / Norfolk	77%	10,111	2,943	71%	88,894	25,207	72%	3,611,693	1,072,506	70%
Springfield Shuttles	89%	715	0	100%	5,842	926	84%	212,244	34,064	84%
Roanoke	79%	2,952	85	97%	28,829	5,517	81%	1,142,632	255,211	78%
On Spine Northeast Regional	80%	23,267	2,241	90%	173,647	25,597	85%	7,082,916	1,523,608	78%
State Supported	80%	39,474	12,122	69%	369,837	109,952	70%	15,158,431	3,321,226	78%
Borealis	80%	529	0	100%	4,859	158	97%	192,848	40,629	79%
Capitol Corridor	90%	4,112	639	84%	30,924	4,323	86%	1,260,428	168,369	87%
Carolinian	70%	1,213	195	84%	9,185	3,768	59%	386,513	151,918	61%
Cascades	75%	2,176	604	72%	21,563	5,567	74%	872,199	246,221	72%
Downeaster	82%	1,606	0	100%	14,194	12	100%	534,174	61,857	88%
Empire	78%	5,615	784	86%	50,024	12,077	76%	1,891,828	467,039	75%
Adirondack	72%	385	16	96%	3,204	748	77%	117,299	37,701	68%
Ethan Allen Express	70%	491	35	93%	4,525	1,569	65%	191,427	73,845	61%
Maple Leaf	70%	819	385	53%	7,254	2,044	72%	235,566	91,923	61%
New York - Albany	85%	2,666	146	95%	21,113	3,604	83%	870,380	152,093	83%
New York - Niagara Falls	75%	1,254	202	84%	12,771	4,096	68%	463,163	104,605	77%
Berkshire Flyer	60%	0	0	-	1,157	16	99%	13,993	6,872	51%
Gold Runner	73%	1,739	936	46%	21,283	10,891	49%	851,005	319,650	62%
Heartland Flyer	70%	133	63	53%	1,676	594	65%	73,233	30,779	58%
Hiawatha	90%	1,521	154	90%	14,891	1,887	87%	598,668	65,734	89%
Illinois	78%	2,367	370	84%	20,110	10,695	47%	848,467	243,329	71%
Carl Sandburg / Illinois Zephyr	85%	328	38	88%	3,465	1,036	70%	141,211	40,370	71%
Illini / Saluki	85%	711	67	91%	6,962	3,963	43%	292,974	75,440	74%
Lincoln Service	70%	1,328	265	80%	9,683	5,696	41%	414,282	127,519	69%
Keystone	92%	9,328	4,087	56%	64,202	10,461	84%	2,578,093	266,713	90%
Lincoln / Missouri	70%	694	446	36%	5,695	4,680	18%	263,306	140,137	47%
Mardi Gras Service	80%	264	0	100%	2,539	518	80%	136,491	30,503	78%
Michigan	70%	1,674	645	61%	18,013	7,634	58%	691,291	233,184	66%
Blue Water	70%	230	218	5%	4,059	1,585	61%	162,684	66,729	59%
Pere Marquette	85%	286	0	100%	2,580	444	83%	89,061	16,797	81%
Wolverine	70%	1,158	427	63%	11,374	5,605	51%	439,546	149,658	66%
Missouri	80%	176	154	13%	2,010	1,745	13%	75,370	23,010	69%
Pacific Surfliner	85%	3,816	2,400	37%	61,945	27,812	55%	2,788,791	546,385	80%
Pennsylvanian	80%	838	142	83%	7,007	1,691	76%	299,560	57,522	81%
Piedmont	80%	445	0	100%	8,442	1,871	78%	379,370	96,472	75%
Vermont	75%	1,228	503	59%	11,275	3,568	68%	436,796	131,775	70%
Long Distance	70%	13,337	4,290	68%	97,219	49,760	49%	4,145,505	1,834,721	56%
Auto Train	70%	632	330	48%	5,098	2,581	49%	265,169	91,322	66%
California Zephyr	70%	1,071	236	78%	7,639	3,149	59%	328,974	129,328	61%
Cardinal	70%	0	0	-	1,612	1,144	29%	78,628	40,395	49%
City Of New Orleans	75%	844	833	1%	5,397	4,995	7%	215,049	77,460	64%
Coast Starlight	70%	1,268	239	81%	9,910	2,416	76%	387,164	137,058	65%
Crescent	70%	1,132	59	95%	7,257	1,577	78%	312,654	96,047	69%
Empire Builder	70%	1,122	468	58%	8,785	3,589	59%	328,341	164,339	50%
Floridian	60%	1,870	847	55%	11,971	9,337	22%	531,877	369,343	31%
Lake Shore Ltd	73%	1,125	31	97%	8,418	3,014	64%	330,099	100,857	69%
Palmetto	70%	884	0	100%	6,435	2,781	57%	309,616	97,579	68%
Silver Meteor	70%	1,103	0	100%	7,249	4,061	44%	341,659	159,465	53%
Southwest Chief	60%	976	719	26%	7,010	4,371	38%	284,265	187,966	34%
Sunset Ltd	70%	323	168	48%	1,879	956	49%	97,583	39,455	60%
Texas Eagle	70%	987	360	64%	8,559	5,789	32%	334,427	144,107	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000770 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 08, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	52,500	878,642	598	2,052,318	36,152,809	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,411	268,029	90	98,850	10,475,463	94
INFRASTRUCTURE PLANNED	135	4,408	268,029	164	119,954	10,475,463	115
FLEET RELIABILITY	90	8,492	878,642	97	328,037	36,152,809	91
TRAIN OPERATIONS	424	37,189	878,642	423	1,505,477	36,152,809	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/08/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/08/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	318	41	87.1%	2,503	370	85.2%	103,025	14,338	86.1%
Central Division	86.0%	58	4	93.1%	466	62	86.7%	19,661	1,837	90.7%
East Division	82.0%	177	24	86.4%	1,343	158	88.2%	54,163	8,292	84.7%
West Division	86.0%	83	13	84.3%	694	150	78.4%	29,201	4,209	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-00730 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/08/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/08/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	318	41	87.1%	2,503	370	85.2%	103,025	14,338	86.1%
Central Division	86.0%	58	4	93.1%	466	62	86.7%	19,661	1,837	90.7%
CDL	95.0%	2	1	50.0%	16	4	75.0%	652	35	94.6%
CHI	86.0%	27	2	92.6%	218	36	83.5%	9,088	1,136	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	1	1	0.0%	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	8	1	87.5%	366	39	89.3%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	8	0	100.0%	322	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	16	1	93.8%	664	55	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	47	2	95.7%	2,006	128	93.6%
MOE	97.5%	2	0	100.0%	16	1	93.8%	683	10	98.5%
MSP	96.5%	1	0	100.0%	8	0	100.0%	336	7	97.9%
NOL	94.5%	4	0	100.0%	34	1	97.1%	1,444	65	95.5%
OKC	97.0%	1	0	100.0%	7	0	100.0%	336	6	98.2%
PNT	88.0%	2	0	100.0%	20	2	90.0%	896	75	91.6%
PTH	93.0%	1	0	100.0%	8	0	100.0%	331	13	96.1%
QCY	91.0%	2	0	100.0%	16	1	93.8%	647	49	92.4%
SAS	90.5%	1	0	100.0%	8	1	87.5%	340	40	88.2%
STL	89.0%	4	0	100.0%	31	7	77.4%	1,327	113	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	177	24	86.4%	1,343	158	88.2%	54,163	8,292	84.7%
ALB	88.5%	7	2	71.4%	61	7	88.5%	2,545	195	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	40	0	100.0%	1,661	175	89.5%
BOS	85.5%	19	1	94.7%	148	7	95.3%	5,853	647	88.9%
BRK	92.5%	5	0	100.0%	40	1	97.5%	1,635	113	93.1%
BTN	82.0%	1	0	100.0%	8	1	87.5%	327	43	86.9%
CLT	91.5%	4	0	100.0%	36	3	91.7%	1,667	170	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	15	2	86.7%	663	62	90.6%
GRO	-	1	1	0.0%	4	2	50.0%	54	13	75.9%
HAR	79.5%	13	4	69.2%	86	12	86.0%	3,793	606	84.0%
HFD	-	2	0	100.0%	10	0	100.0%	242	19	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	8	1	87.5%	339	41	87.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/08/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	318	41	87.1%	2,503	370	85.2%	103,025	14,338	86.1%
East Division	82.0%	177	24	86.4%	1,343	158	88.2%	54,163	8,292	84.7%
MIA	89.5%	2	0	100.0%	16	4	75.0%	674	80	88.1%
MTR	79.0%	1	0	100.0%	8	1	87.5%	326	59	81.9%
NFK	84.5%	2	0	100.0%	16	2	87.5%	761	138	81.9%
NFL	93.5%	2	0	100.0%	16	1	93.8%	690	32	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	2	60.0%	38	8	78.9%	1,740	295	83.0%
NPN	93.0%	2	0	100.0%	16	1	93.8%	650	52	92.0%
NYP	75.5%	51	11	78.4%	373	65	82.6%	14,302	3,122	78.2%
PGH	93.0%	1	0	100.0%	8	1	87.5%	340	24	92.9%
PHL	48.0%	5	2	60.0%	37	14	62.2%	1,732	813	53.1%
PIT	76.0%	-	-	-	2	2	0.0%	26	21	19.2%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	24	3	87.5%	1,288	57	95.6%
RNK	83.5%	2	0	100.0%	16	1	93.8%	674	94	86.1%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	8	0	100.0%	322	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	8	0	100.0%	336	12	96.4%
SFA	88.0%	1	0	100.0%	8	2	75.0%	339	49	85.5%
SPG	92.5%	5	0	100.0%	43	1	97.7%	2,005	116	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	8	0	100.0%	328	63	80.8%
WAS	84.0%	33	1	97.0%	242	16	93.4%	8,611	1,090	87.3%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	83	13	84.3%	694	150	78.4%	29,201	4,209	85.6%
ARN	92.0%	1	0	100.0%	8	1	87.5%	341	29	91.5%
BFD	79.0%	7	1	85.7%	54	17	68.5%	2,167	465	78.5%
EMY	72.0%	1	0	100.0%	8	3	62.5%	357	103	71.1%
EUG	86.5%	2	0	100.0%	15	2	86.7%	675	61	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	2	33.3%	23	7	69.6%	1,024	179	82.5%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	7	0	100.0%	77	11	85.7%	3,397	380	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	6	53.8%	91	39	57.1%	3,710	992	73.3%
PDX	86.0%	5	0	100.0%	40	7	82.5%	1,645	232	85.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/08/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/08/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	318	41	87.1%	2,503	370	85.2%	103,025	14,338	86.1%
West Division	86.0%	83	13	84.3%	694	150	78.4%	29,201	4,209	85.6%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	1	93.8%	116	19	83.6%	4,835	539	88.9%
SAN	90.5%	5	1	80.0%	89	17	80.9%	4,126	409	90.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	0	100.0%	64	12	81.3%	2,617	392	85.0%
SJC	89.0%	7	2	71.4%	56	10	82.1%	2,396	239	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	24	1	95.8%	789	78	90.1%
SNC	-	2	0	100.0%	2	0	100.0%	33	13	60.6%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	8	1	87.5%	320	30	90.6%
VAC	97.0%	2	0	100.0%	16	1	93.8%	669	15	97.8%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		3	1	66.7%	145	37	74.5%	3	0	100.0%	140	29	79.3%
3		8	2	75.0%	341	68	80.1%	8	1	87.5%	338	158	53.3%
4	108	8	1	87.5%	340	54	84.1%	8	3	62.5%	340	224	34.1%
5		8	1	87.5%	339	58	82.9%	8	2	75.0%	335	113	66.3%
6		8	3	62.5%	338	94	72.2%	8	4	50.0%	338	129	61.8%
7		8	0	100.0%	330	51	84.5%	8	0	100.0%	321	86	73.2%
8	88	8	1	87.5%	330	146	55.8%	8	4	50.0%	329	202	38.6%
11		8	3	62.5%	341	75	78.0%	8	1	87.5%	335	68	79.7%
14		8	4	50.0%	342	58	83.0%	8	0	100.0%	339	105	69.0%
19		8	1	87.5%	340	84	75.3%	8	0	100.0%	337	82	75.7%
20		8	0	100.0%	340	23	93.2%	8	1	87.5%	340	66	80.6%
21	54	8	0	100.0%	337	36	89.3%	8	4	50.0%	336	103	69.3%
22		8	1	87.5%	338	38	88.8%	8	7	12.5%	336	106	68.5%
23		8	1	87.5%	342	7	98.0%	8	4	50.0%	340	94	72.4%
24		8	0	100.0%	342	16	95.3%	8	2	75.0%	341	67	80.4%
25		8	0	100.0%	341	3	99.1%	8	0	100.0%	338	94	72.2%
26		8	1	87.5%	341	6	98.2%	8	1	87.5%	338	67	80.2%
27		8	3	62.5%	307	22	92.8%	8	1	87.5%	301	98	67.4%
28		8	1	87.5%	301	68	77.4%	8	1	87.5%	301	61	79.7%
40		8	2	75.0%	331	49	85.2%	8	5	37.5%	327	177	45.9%
41		8	6	25.0%	331	130	60.7%	8	7	12.5%	328	254	22.6%
42		8	1	87.5%	342	26	92.4%	8	0	100.0%	340	58	82.9%
43		8	0	100.0%	341	45	86.8%	8	4	50.0%	340	80	76.5%
48		8	0	100.0%	340	62	81.8%	8	3	62.5%	339	54	84.1%
49		8	1	87.5%	340	85	75.0%	8	2	75.0%	340	72	78.8%
52		8	2	75.0%	339	49	85.5%	8	4	50.0%	338	81	76.0%
53	42	8	1	87.5%	339	41	87.9%	8	4	50.0%	338	110	67.5%
55		5	0	100.0%	216	9	95.8%	5	0	100.0%	213	46	78.4%
56	39	5	0	100.0%	217	25	88.5%	5	4	20.0%	213	44	79.3%
58	107	8	0	100.0%	315	17	94.6%	8	8	0.0%	313	105	66.5%
59	187	8	3	62.5%	314	54	82.8%	8	7	12.5%	309	88	71.5%
63	39	8	2	75.0%	343	146	57.4%	8	8	0.0%	337	205	39.2%
64	71	8	0	100.0%	341	71	79.2%	8	3	62.5%	340	136	60.0%
66		8	1	87.5%	340	65	80.9%	8	2	75.0%	335	62	81.5%
67		5	0	100.0%	235	14	94.0%	5	0	100.0%	234	40	82.9%
68		8	1	87.5%	343	68	80.2%	8	2	75.0%	342	136	60.2%
69		8	3	62.5%	330	82	75.2%	8	2	75.0%	325	58	82.2%
71		8	0	100.0%	338	3	99.1%	8	1	87.5%	336	87	74.1%
72		8	1	87.5%	334	37	88.9%	8	1	87.5%	332	70	78.9%
75		8	3	62.5%	331	20	94.0%	8	3	62.5%	325	154	52.6%
76		8	0	100.0%	331	31	90.6%	8	3	62.5%	321	133	58.6%
77		8	1	87.5%	333	22	93.4%	8	1	87.5%	330	134	59.4%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79		8	0	100.0%	340	59	82.6%	8	4	50.0%	338	116	65.7%
80		8	1	87.5%	340	38	88.8%	8	2	75.0%	337	73	78.3%
84		5	0	100.0%	207	19	90.8%	5	1	80.0%	203	49	75.9%
85	21	5	0	100.0%	218	18	91.7%	5	3	40.0%	218	77	64.7%
86	31	5	0	100.0%	218	16	92.7%	5	2	60.0%	217	123	43.3%
89		8	1	87.5%	338	79	76.6%	8	4	50.0%	336	101	69.9%
90		8	0	100.0%	338	12	96.4%	8	2	75.0%	337	62	81.6%
93	26	5	0	100.0%	217	21	90.3%	5	4	20.0%	216	59	72.7%
94		5	1	80.0%	248	62	75.0%	5	1	80.0%	246	90	63.4%
95	58	5	1	80.0%	217	7	96.8%	5	4	20.0%	217	86	60.4%
97		8	5	37.5%	340	222	34.7%	8	4	50.0%	338	124	63.3%
98		8	2	75.0%	340	30	91.2%	8	4	50.0%	338	127	62.4%
110		5	0	100.0%	214	110	48.6%	5	0	100.0%	211	22	89.6%
111		5	0	100.0%	208	37	82.2%	5	0	100.0%	206	22	89.3%
112		5	1	80.0%	208	21	89.9%	5	0	100.0%	207	20	90.3%
113		5	0	100.0%	139	33	76.3%	5	0	100.0%	138	16	88.4%
119		5	1	80.0%	205	50	75.6%	5	0	100.0%	203	26	87.2%
125		5	0	100.0%	218	12	94.5%	5	2	60.0%	218	86	60.6%
128		3	0	100.0%	125	20	84.0%	3	0	100.0%	125	26	79.2%
129		5	1	80.0%	217	51	76.5%	5	1	80.0%	217	31	85.7%
130		5	0	100.0%	208	20	90.4%	5	0	100.0%	206	16	92.2%
131		5	0	100.0%	210	57	72.9%	5	1	80.0%	210	40	81.0%
134		5	0	100.0%	218	32	85.3%	5	0	100.0%	217	42	80.6%
137		5	0	100.0%	215	36	83.3%	5	2	60.0%	215	64	70.2%
138		5	1	80.0%	218	44	79.8%	5	1	80.0%	217	39	82.0%
139		1	0	100.0%	44	5	88.6%	1	0	100.0%	44	16	63.6%
141		5	1	80.0%	217	5	97.7%	5	1	80.0%	216	38	82.4%
148		5	2	60.0%	217	24	88.9%	5	0	100.0%	215	40	81.4%
151	26	8	2	75.0%	339	107	68.4%	8	2	75.0%	338	101	70.1%
166	27	1	0	100.0%	44	6	86.4%	1	1	0.0%	43	16	62.8%
169		3	0	100.0%	123	13	89.4%	3	0	100.0%	123	26	78.9%
170		5	0	100.0%	213	12	94.4%	5	0	100.0%	212	30	85.8%
171		5	0	100.0%	218	11	95.0%	5	2	60.0%	218	90	58.7%
172		5	0	100.0%	217	19	91.2%	5	2	60.0%	215	71	67.0%
173		5	0	100.0%	210	25	88.1%	5	0	100.0%	209	84	59.8%
174		5	0	100.0%	218	23	89.4%	5	1	80.0%	218	53	75.7%
175		5	0	100.0%	218	23	89.4%	5	2	60.0%	218	72	67.0%
176		5	0	100.0%	210	17	91.9%	5	0	100.0%	207	26	87.4%
177		5	0	100.0%	218	28	87.2%	5	1	80.0%	218	49	77.5%
181	23	5	2	60.0%	214	66	69.2%	5	2	60.0%	211	19	91.0%
182		5	0	100.0%	208	31	85.1%	5	2	60.0%	206	25	87.9%
183		5	1	80.0%	217	63	71.0%	5	0	100.0%	214	44	79.4%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		5	0	100.0%	218	36	83.5%	5	0	100.0%	217	28	87.1%
185		5	1	80.0%	218	42	80.7%	5	0	100.0%	218	18	91.7%
186		5	1	80.0%	217	30	86.2%	5	2	60.0%	216	63	70.8%
190		5	2	60.0%	217	77	64.5%	5	0	100.0%	216	44	79.6%
192		5	0	100.0%	215	24	88.8%	5	0	100.0%	215	19	91.2%
193		5	2	60.0%	213	85	60.1%	5	2	60.0%	212	92	56.6%
196		5	1	80.0%	214	24	88.8%	5	0	100.0%	212	17	92.0%
197		5	1	80.0%	218	78	64.2%	5	3	40.0%	218	74	66.1%
230		8	0	100.0%	176	4	97.7%	8	1	87.5%	176	10	94.3%
232		8	0	100.0%	342	12	96.5%	8	1	87.5%	342	24	93.0%
233		6	1	83.3%	301	67	77.7%	6	1	83.3%	300	102	66.0%
234		8	0	100.0%	343	23	93.3%	8	0	100.0%	342	29	91.5%
235		8	1	87.5%	267	43	83.9%	8	1	87.5%	266	61	77.1%
236		8	1	87.5%	327	11	96.6%	8	1	87.5%	326	44	86.5%
237		8	2	75.0%	340	63	81.5%	8	3	62.5%	338	62	81.7%
239	26	8	2	75.0%	341	85	75.1%	8	1	87.5%	340	43	87.4%
240		8	2	75.0%	342	25	92.7%	8	1	87.5%	339	70	79.4%
241		8	3	62.5%	342	85	75.1%	7	2	71.4%	341	83	75.7%
243		8	1	87.5%	278	72	74.1%	8	0	100.0%	277	39	85.9%
244		6	2	66.7%	300	14	95.3%	6	3	50.0%	300	68	77.3%
245		8	1	87.5%	223	42	81.2%	8	0	100.0%	222	30	86.5%
280		8	0	100.0%	343	17	95.0%	8	2	75.0%	342	80	76.6%
281	24	8	0	100.0%	343	40	88.3%	8	2	75.0%	343	62	81.9%
283		8	3	62.5%	343	88	74.3%	8	5	37.5%	343	71	79.3%
284		8	1	87.5%	343	14	95.9%	8	3	62.5%	340	64	81.2%
290		8	1	87.5%	343	53	84.5%	8	3	62.5%	340	140	58.8%
291		8	1	87.5%	342	113	67.0%	8	2	75.0%	338	92	72.8%
300		7	3	57.1%	325	25	92.3%	6	1	83.3%	321	74	76.9%
301		8	1	87.5%	340	11	96.8%	8	5	37.5%	336	68	79.8%
302		8	2	75.0%	321	36	88.8%	8	5	37.5%	317	95	70.0%
305		8	3	62.5%	324	34	89.5%	7	5	28.6%	318	127	60.1%
306		8	1	87.5%	338	18	94.7%	8	6	25.0%	336	95	71.7%
307	29	7	2	71.4%	330	46	86.1%	8	5	37.5%	327	103	68.5%
311	32	8	1	87.5%	335	29	91.3%	8	8	0.0%	329	92	72.0%
316	26	8	1	87.5%	331	25	92.4%	8	8	0.0%	325	109	66.5%
318	58	8	0	100.0%	341	35	89.7%	8	7	12.5%	338	173	48.8%
319	57	8	1	87.5%	342	21	93.9%	8	8	0.0%	337	201	40.4%
329		6	1	83.3%	242	13	94.6%	6	1	83.3%	242	20	91.7%
330		7	1	85.7%	291	7	97.6%	7	1	85.7%	291	16	94.5%
331		8	2	75.0%	343	35	89.8%	8	2	75.0%	342	46	86.5%
332		8	1	87.5%	342	20	94.2%	8	2	75.0%	342	48	86.0%
334		8	0	100.0%	343	11	96.8%	8	1	87.5%	341	44	87.1%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		8	0	100.0%	343	35	89.8%	8	0	100.0%	340	55	83.8%
336		8	0	100.0%	342	10	97.1%	8	2	75.0%	340	31	90.9%
337	18	8	0	100.0%	343	21	93.9%	8	3	62.5%	339	50	85.3%
338		8	0	100.0%	343	54	84.3%	8	2	75.0%	340	106	68.8%
339		8	1	87.5%	343	55	84.0%	8	1	87.5%	343	59	82.8%
341		8	1	87.5%	328	52	84.1%	8	1	87.5%	322	54	83.2%
342		8	0	100.0%	343	26	92.4%	8	2	75.0%	341	63	81.5%
350	104	8	1	87.5%	318	21	93.4%	8	5	37.5%	310	179	42.3%
351		8	1	87.5%	325	30	90.8%	8	4	50.0%	323	96	70.3%
352	29	8	0	100.0%	309	24	92.2%	8	7	12.5%	303	100	67.0%
353	144	8	1	87.5%	280	15	94.6%	8	3	62.5%	274	52	81.0%
354		8	1	87.5%	324	38	88.3%	8	4	50.0%	316	120	62.0%
355	108	8	4	50.0%	331	41	87.6%	8	4	50.0%	322	123	61.8%
364	47	8	1	87.5%	332	74	77.7%	8	5	37.5%	326	125	61.7%
365	130	8	0	100.0%	331	13	96.1%	8	3	62.5%	328	127	61.3%
370		8	1	87.5%	329	40	87.8%	8	1	87.5%	316	76	75.9%
371		8	0	100.0%	322	11	96.6%	8	2	75.0%	318	32	89.9%
380		8	0	100.0%	324	30	90.7%	8	1	87.5%	323	73	77.4%
381		8	1	87.5%	339	16	95.3%	8	1	87.5%	336	72	78.6%
382		8	1	87.5%	338	31	90.8%	8	4	50.0%	336	120	64.3%
383		8	3	62.5%	329	30	90.9%	7	2	71.4%	325	140	56.9%
390	Cncld	8	2	75.0%	324	26	92.0%	7	4	42.9%	321	90	72.0%
391		8	0	100.0%	325	14	95.7%	8	6	25.0%	320	94	70.6%
392		8	2	75.0%	338	13	96.2%	7	5	28.6%	332	108	67.5%
393		8	3	62.5%	342	22	93.6%	7	5	28.6%	337	109	67.7%
417		5	0	100.0%	226	47	79.2%	5	0	100.0%	217	25	88.5%
425		4	0	100.0%	228	7	96.9%	4	0	100.0%	227	7	96.9%
448		8	3	62.5%	267	52	80.5%	8	2	75.0%	263	91	65.4%
449		8	0	100.0%	264	34	87.1%	8	0	100.0%	264	45	83.0%
470		5	1	80.0%	241	41	83.0%	5	2	60.0%	235	29	87.7%
471		5	0	100.0%	230	14	93.9%	5	0	100.0%	230	6	97.4%
473		5	0	100.0%	237	15	93.7%	5	0	100.0%	234	10	95.7%
474		5	1	80.0%	233	67	71.2%	5	1	80.0%	218	72	67.0%
475		4	0	100.0%	233	8	96.6%	4	0	100.0%	233	16	93.1%
478		5	1	80.0%	229	37	83.8%	5	1	80.0%	227	29	87.2%
479		5	0	100.0%	236	36	84.7%	5	0	100.0%	234	36	84.6%
486		5	1	80.0%	240	36	85.0%	5	0	100.0%	234	61	73.9%
494		5	1	80.0%	243	48	80.2%	5	3	40.0%	235	67	71.5%
495		5	0	100.0%	224	4	98.2%	5	0	100.0%	222	3	98.6%
500		8	1	87.5%	317	17	94.6%	8	1	87.5%	314	37	88.2%
502	20	8	1	87.5%	325	20	93.8%	8	2	75.0%	321	63	80.4%
503		8	2	75.0%	339	42	87.6%	7	1	85.7%	331	103	68.9%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		8	1	87.5%	343	21	93.9%	8	2	75.0%	341	101	70.4%
505		8	2	75.0%	335	45	86.6%	8	5	37.5%	330	96	70.9%
506	25	8	1	87.5%	338	57	83.1%	7	2	71.4%	329	53	83.9%
507		8	0	100.0%	343	49	85.7%	8	2	75.0%	343	117	65.9%
508		7	1	85.7%	337	44	86.9%	7	1	85.7%	333	82	75.4%
509		8	2	75.0%	324	17	94.8%	8	1	87.5%	324	72	77.8%
511		8	1	87.5%	319	26	91.8%	8	1	87.5%	318	54	83.0%
516	27	8	1	87.5%	334	36	89.2%	8	4	50.0%	333	150	55.0%
517		8	0	100.0%	343	8	97.7%	8	2	75.0%	339	152	55.2%
518	No OS	8	3	62.5%	343	49	85.7%	8	6	25.0%	341	238	30.2%
519	147	8	1	87.5%	334	10	97.0%	8	4	50.0%	332	76	77.1%
520		5	1	80.0%	199	30	84.9%	5	1	80.0%	194	12	93.8%
521		5	1	80.0%	237	8	96.6%	5	1	80.0%	236	32	86.4%
522		5	1	80.0%	237	44	81.4%	5	0	100.0%	234	24	89.7%
523		5	0	100.0%	237	9	96.2%	5	2	60.0%	236	28	88.1%
524		5	1	80.0%	236	18	92.4%	5	1	80.0%	233	28	88.0%
525		5	1	80.0%	234	17	92.7%	4	0	100.0%	229	15	93.4%
526		5	2	60.0%	211	43	79.6%	4	0	100.0%	207	18	91.3%
527		5	0	100.0%	237	10	95.8%	5	0	100.0%	235	40	83.0%
528		5	0	100.0%	237	19	92.0%	5	1	80.0%	236	33	86.0%
529	15	5	0	100.0%	237	13	94.5%	5	1	80.0%	236	66	72.0%
530		5	1	80.0%	191	19	90.1%	4	0	100.0%	190	38	80.0%
531	21	5	2	60.0%	211	16	92.4%	5	2	60.0%	211	15	92.9%
532	17	5	3	40.0%	237	60	74.7%	5	2	60.0%	235	37	84.3%
534		5	2	60.0%	196	30	84.7%	5	0	100.0%	193	17	91.2%
535		5	1	80.0%	223	27	87.9%	5	0	100.0%	218	28	87.2%
536		5	2	60.0%	237	66	72.2%	5	1	80.0%	233	42	82.0%
537		5	2	60.0%	206	26	87.4%	5	0	100.0%	200	25	87.5%
538		5	2	60.0%	237	28	88.2%	5	0	100.0%	236	46	80.5%
539		5	0	100.0%	191	28	85.3%	5	2	60.0%	191	84	56.0%
540		5	1	80.0%	236	45	80.9%	5	1	80.0%	226	22	90.3%
541		5	1	80.0%	236	26	89.0%	5	1	80.0%	229	42	81.7%
542	17	5	1	80.0%	236	26	89.0%	5	2	60.0%	233	43	81.5%
543	45	5	2	60.0%	237	30	87.3%	5	4	20.0%	237	77	67.5%
544		5	0	100.0%	235	22	90.6%	5	0	100.0%	231	22	90.5%
545		5	2	60.0%	237	22	90.7%	5	1	80.0%	234	30	87.2%
547		5	2	60.0%	237	49	79.3%	5	1	80.0%	237	55	76.8%
548	13	4	0	100.0%	228	22	90.4%	4	1	75.0%	225	18	92.0%
549		5	0	100.0%	232	27	88.4%	5	0	100.0%	222	20	91.0%
550	27	5	2	60.0%	191	22	88.5%	5	2	60.0%	191	46	75.9%
551		5	0	100.0%	233	23	90.1%	5	0	100.0%	223	23	89.7%
562	28	8	0	100.0%	334	27	91.9%	8	3	62.5%	329	40	87.8%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		8	0	100.0%	335	19	94.3%	7	2	71.4%	326	45	86.2%
579		8	0	100.0%	220	14	93.6%	8	2	75.0%	213	47	77.9%
580		8	2	75.0%	335	20	94.0%	8	3	62.5%	328	40	87.8%
591	31	8	3	62.5%	332	29	91.3%	7	3	57.1%	324	52	84.0%
595		8	5	37.5%	328	65	80.2%	7	1	85.7%	324	74	77.2%
600	67	5	0	100.0%	245	9	96.3%	5	2	60.0%	243	24	90.1%
601		5	1	80.0%	228	91	60.1%	5	1	80.0%	225	28	87.6%
605		5	5	0.0%	235	144	38.7%	4	1	75.0%	230	24	89.6%
607		5	1	80.0%	244	31	87.3%	5	1	80.0%	241	26	89.2%
609		5	1	80.0%	235	24	89.8%	5	0	100.0%	234	23	90.2%
622	18	4	1	75.0%	141	36	74.5%	4	2	50.0%	138	7	94.9%
626	14	5	0	100.0%	149	20	86.6%	5	1	80.0%	147	19	87.1%
637	11	3	1	66.7%	76	8	89.5%	3	1	66.7%	76	7	90.8%
639	27	5	1	80.0%	215	41	80.9%	5	1	80.0%	213	21	90.1%
640	20	5	1	80.0%	235	8	96.6%	5	2	60.0%	233	86	63.1%
641	42	5	1	80.0%	217	44	79.7%	5	4	20.0%	217	31	85.7%
642	31	5	1	80.0%	233	12	94.8%	5	1	80.0%	232	28	87.9%
643		5	1	80.0%	247	45	81.8%	5	1	80.0%	244	40	83.6%
644	66	5	1	80.0%	239	29	87.9%	5	3	40.0%	237	59	75.1%
645		5	0	100.0%	247	42	83.0%	5	0	100.0%	244	55	77.5%
646	19	5	3	40.0%	236	59	75.0%	5	3	40.0%	234	116	50.4%
647		5	2	60.0%	247	37	85.0%	5	1	80.0%	245	52	78.8%
648		5	1	80.0%	243	60	75.3%	5	1	80.0%	243	36	85.2%
649		5	2	60.0%	248	46	81.5%	5	1	80.0%	244	35	85.7%
650	37	5	1	80.0%	247	46	81.4%	5	2	60.0%	244	41	83.2%
651	100	5	1	80.0%	247	18	92.7%	5	1	80.0%	244	44	82.0%
652		5	0	100.0%	248	31	87.5%	5	2	60.0%	244	43	82.4%
653	45	5	2	60.0%	236	38	83.9%	5	3	40.0%	232	44	81.0%
654	66	5	0	100.0%	237	44	81.4%	5	1	80.0%	233	21	91.0%
655		5	3	40.0%	245	77	68.6%	5	2	60.0%	242	78	67.8%
656	24	5	2	60.0%	247	56	77.3%	5	1	80.0%	245	34	86.1%
657		5	0	100.0%	236	29	87.7%	5	1	80.0%	234	31	86.8%
658		5	0	100.0%	247	37	85.0%	5	0	100.0%	245	35	85.7%
680		6	0	100.0%	243	12	95.1%	6	0	100.0%	241	27	88.8%
681		6	0	100.0%	243	18	92.6%	6	1	83.3%	236	94	60.2%
682		6	1	83.3%	242	10	95.9%	6	0	100.0%	242	42	82.6%
683		6	0	100.0%	225	18	92.0%	6	2	66.7%	224	77	65.6%
684		6	0	100.0%	224	37	83.5%	6	1	83.3%	224	48	78.6%
685		6	0	100.0%	239	33	86.2%	6	0	100.0%	236	55	76.7%
686		6	0	100.0%	244	39	84.0%	6	1	83.3%	243	53	78.2%
687		6	0	100.0%	243	38	84.4%	6	0	100.0%	242	40	83.5%
688		6	0	100.0%	242	15	93.8%	6	0	100.0%	241	41	83.0%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
689		4	0	100.0%	159	21	86.8%	4	0	100.0%	158	23	85.4%
701		8	0	100.0%	275	30	89.1%	8	1	87.5%	272	33	87.9%
702		8	1	87.5%	342	37	89.2%	7	3	57.1%	338	86	74.6%
703		8	4	50.0%	343	116	66.2%	8	3	62.5%	341	103	69.8%
704		8	2	75.0%	274	51	81.4%	8	3	62.5%	266	62	76.7%
710	Cncld	8	1	87.5%	343	80	76.7%	6	3	50.0%	337	91	73.0%
711		8	1	87.5%	334	39	88.3%	8	1	87.5%	311	66	78.8%
712	58	8	4	50.0%	340	95	72.1%	8	4	50.0%	330	118	64.2%
713	Cncld	7	3	57.1%	209	23	89.0%	5	4	20.0%	182	84	53.8%
714	79	8	6	25.0%	224	98	56.3%	7	5	28.6%	207	100	51.7%
715	Cncld	8	2	75.0%	342	65	81.0%	6	4	33.3%	311	159	48.9%
716	38	8	5	37.5%	343	148	56.9%	8	6	25.0%	334	147	56.0%
717	74	7	3	57.1%	327	82	74.9%	7	5	28.6%	302	103	65.9%
718	156	8	7	12.5%	343	185	46.1%	8	6	25.0%	340	135	60.3%
719	Cncld	8	4	50.0%	343	117	65.9%	7	3	57.1%	325	101	68.9%
757		8	0	100.0%	128	7	94.5%	8	1	87.5%	127	15	88.2%
761		8	1	87.5%	339	14	95.9%	8	1	87.5%	336	45	86.6%
765	23	8	2	75.0%	339	27	92.0%	8	3	62.5%	339	49	85.5%
769	48	8	1	87.5%	339	28	91.7%	8	5	37.5%	332	70	78.9%
770	16	8	2	75.0%	339	27	92.0%	8	4	50.0%	336	108	67.9%
774	57	8	0	100.0%	339	17	95.0%	8	5	37.5%	337	85	74.8%
777	34	8	1	87.5%	224	14	93.8%	8	8	0.0%	223	66	70.4%
782		8	5	37.5%	224	110	50.9%	8	3	62.5%	219	39	82.2%
785		8	1	87.5%	339	30	91.2%	8	5	37.5%	339	66	80.5%
786	71	8	1	87.5%	128	24	81.3%	6	4	33.3%	122	70	42.6%
790	24	8	0	100.0%	339	31	90.9%	7	3	57.1%	335	57	83.0%
794	Cncld	8	0	100.0%	339	40	88.2%	8	3	62.5%	335	79	76.4%
794		8	0	100.0%	339	40	88.2%	8	3	62.5%	335	79	76.4%
821		7	0	100.0%	336	6	98.2%	7	2	71.4%	336	142	57.7%
822	31	8	1	87.5%	339	19	94.4%	7	5	28.6%	336	175	47.9%
1333		8	0	100.0%	339	40	88.2%	8	1	87.5%	336	113	66.4%
1340		8	0	100.0%	338	7	97.9%	8	0	100.0%	337	56	83.4%
2102		5	0	100.0%	94	16	83.0%	5	0	100.0%	93	7	92.5%
2103		5	0	100.0%	158	14	91.1%	5	1	80.0%	157	11	93.0%
2104	Cncld	5	0	100.0%	184	10	94.6%	4	0	100.0%	181	13	92.8%
2105		5	0	100.0%	6	1	83.3%	5	0	100.0%	6	0	100.0%
2107		4	0	100.0%	214	35	83.6%	4	0	100.0%	211	21	90.0%
2108		5	0	100.0%	215	28	87.0%	5	0	100.0%	209	27	87.1%
2109		5	1	80.0%	108	14	87.0%	5	0	100.0%	106	6	94.3%
2112		5	0	100.0%	55	6	89.1%	5	0	100.0%	53	2	96.2%
2113	16	5	1	80.0%	94	10	89.4%	5	1	80.0%	94	11	88.3%
2115	Cncld	5	2	60.0%	94	15	84.0%	4	0	100.0%	92	12	87.0%

Amtrak On Time Performance

Trains Arriving Through: 9/8/2026

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2116		5	0	100.0%	55	1	98.2%	5	0	100.0%	55	8	85.5%
2118		5	0	100.0%	55	4	92.7%	5	0	100.0%	55	12	78.2%
2119		5	1	80.0%	55	9	83.6%	5	1	80.0%	54	13	75.9%
2120		5	1	80.0%	55	20	63.6%	5	0	100.0%	53	23	56.6%
2123		5	2	60.0%	93	12	87.1%	5	0	100.0%	92	15	83.7%
2124		5	0	100.0%	186	38	79.6%	5	0	100.0%	184	24	87.0%
2126		5	0	100.0%	103	26	74.8%	5	0	100.0%	102	22	78.4%
2127		5	0	100.0%	55	10	81.8%	5	0	100.0%	54	9	83.3%
2128		5	1	80.0%	55	5	90.9%	5	0	100.0%	55	3	94.5%
2131		5	0	100.0%	55	10	81.8%	5	0	100.0%	55	6	89.1%
2150		5	0	100.0%	208	22	89.4%	5	0	100.0%	205	75	63.4%
2151		5	0	100.0%	157	7	95.5%	5	3	40.0%	155	44	71.6%
2152		5	0	100.0%	113	7	93.8%	5	0	100.0%	112	31	72.3%
2154		5	1	80.0%	116	24	79.3%	4	0	100.0%	111	45	59.5%
2155		5	0	100.0%	217	17	92.2%	5	1	80.0%	213	103	51.6%
2156		5	0	100.0%	6	0	100.0%	5	1	80.0%	6	1	83.3%
2158		5	0	100.0%	54	6	88.9%	5	0	100.0%	54	16	70.4%
2159	28	5	1	80.0%	210	17	91.9%	5	2	60.0%	208	71	65.9%
2160		5	1	80.0%	55	3	94.5%	5	0	100.0%	54	28	48.1%
2162		5	0	100.0%	216	23	89.4%	5	0	100.0%	210	91	56.7%
2163	32	5	0	100.0%	168	17	89.9%	5	3	40.0%	162	72	55.6%
2165		5	0	100.0%	52	4	92.3%	5	1	80.0%	52	22	57.7%
2167		5	1	80.0%	203	21	89.7%	5	1	80.0%	203	42	79.3%
2171		5	0	100.0%	144	10	93.1%	5	1	80.0%	140	24	82.9%
2190		5	0	100.0%	213	29	86.4%	5	0	100.0%	211	24	88.6%
2193		4	0	100.0%	207	26	87.4%	4	0	100.0%	205	50	75.6%
2228		1	0	100.0%	18	6	66.7%	1	0	100.0%	18	5	72.2%
2233		1	0	100.0%	28	6	78.6%	1	0	100.0%	27	4	85.2%
2264		1	0	100.0%	10	1	90.0%	1	0	100.0%	10	7	30.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2104	NYP	Trn Cancelled	PTI	11	PTI	7	XHM-XCY	AM	Follow, AM600, Other, XHM-XFR
2113	WAS	16	ENG	20	ENG	20	NYP-NYP	AM	Unrecoverable penalty (PCS), 2116 NG NP, NECESSARY TO LOOP TRAIN A/C UNABLE TO OPERATE FROM PC2016
2115	WAS	Trn Cancelled							
2159	WAS	28	DET	20	DET	20	BOS-BOS	AM	Catenary failure, Other, LOOP AND BROADWAY, LATE FROM YARD A/C CONGESTION AFTER CATENARY DAMAGE FROM TRAIN 2151
2163	WAS	32	PTI	16	PTI	13	BAL-XNY	AM	Follow, 93, Milepost, 112.4, 134.6
85	WAS	21	CTI	15	PTI	9	PHL-PHL	AM	Follow, 2165, Control Point, ., held for 2165 ahead then followed
86	NYP	31	CAR	25	CAR	25	PHL-PHL	AM	Heat / AC, 82631 AX AS
93	NFK	26	PTI	22	CAR	17	WAS-WAS	AM	Air / Brake / Wheel, XXXXX, EXTENDED BLUE FLAG PROCEDURES
95	NFK	58	CTI	30	ENG	20	PHL-PHL	AM	Undesired emergency application, 636 630
151	RNK	26	FTI	29	FTI	29	LYH-RNK	NS	Follow V70, Control Point, Kinney
166	BOS	27	SMW	15	SMW	12	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING ON NO.2 TRK LEGGETT TO PELHAM BAY DUE TO SCHEDULED MAINTANENCE WORK
181	WAS	23	SVS	15	SVS	15	NYP-NYP	AM	Routine inspections, LATE RELEASE BY MECHANICAL, LATE INSPECTION.
53	SFA	42	FTI	85	FTI	40	XSA-XJG	CS	Cross Traffic M491-07, Control Point, Clark
600	NYP	67	MTI	41	MTI	41	TRE-NWK	AM	Disabled train ahead, Other, XMW-XCY, NECESSARY TO MAKE REVERSE MOVE A/C AM2104 DISABLED AHD AT COUNTY
622	PHL	18	ITI	21	ITI	16	HAR-HAR	AM	Service, turn, or wye train, 653
626	NYP	14	DCS	12	DCS	12	XHM-NWK	AM	T.O.L, Other, XHM-XGY, TOL ON NO.2 TRACK BTWN HOLMES AND GRUNDY
637	PHL	11	ENG	9	ENG	9	NYP-NYP	AM	Loading problem, 620 EX ES, LOSS OF POWER JUST BEORE DEPARTURE. ENGR RECYCLED ENGINE.
639	PHL	27	ITI	30	ITI	30	NYP-NYP	AM	Service, turn, or wye train, 654, LATE TURN OFF AM654

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
640	NYP	20	DET	30	DET	14	ARD-PHL	AM	Catenary failure, Control Point, ZOO TO BRYN MAWR
641	HAR	42	CCR	42	CCR	42	PHL-PAO	AM	Set out defective cab car, NO CAB CAR IN CONSIST, WYE OUTBOUND
642	NYP	31	CCR	26	CCR	26	PHL-XHM	AM	Set out defective cab car, NO CAB CAR IN CONSIST
644	NYP	66	DET	39	DET	39	PAO-PHL	AM	Catenary failure, Control Point, ZOO TO BRYN MAWR
646	NYP	19	HLD	7	DET	7	PAO-PHL	AM	Catenary failure, Control Point, ZOO TO BRYN MAWR
650	NYP	37	SVS	43	SVS	43	PHL-XHM	AM	Unplanned Wye
651	HAR	100	OTH	132	OTH	130	NWK-TRE	AM	Lost time - N.A.R.
653	HAR	45	SVS	38	SVS	38	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, capped engine
654	NYP	66	CTP	60	CTP	58	ARD-PHL	AM	Delay due to mechanical problems on a Commuter train, picked up disabled SE4587 pax at Ardmore
656	NYP	24	CTP	24	CTP	14	ARD-PHL	AM	Delay due to mechanical problems on a Commuter train, SE4587
63	TWO	39	HLD	8	HLD	6	YNY-YNV	MN	Passenger and/or baggage
64	NYP	71	FTI	40	CUI	32	NFL-NFL	CS	U.S. Border Patrol
239	ALB	26	ENG	23	ENG	23	NYP-XSD	AM	HEP, 9705 CB DC, LOST POWER AT EMPIRE
281	NFL	24	ENG	28	ENG	28	ALB-ALB	AM	PTC- IETMS recycle breaker to clear fault Unable to log consist in, 9703
56	SAB	39	MTI	38	MTI	38	TRE-NWK	AM	Disabled train ahead, Other, XCY, PICKING UP TERMINATED AM2104'S PSGRS
529	SJC	15	DCS	10	OTH	10	OKJ-OKJ	UP	Crew change jack london
531	OKJ	21	TEN	31	TEN	31	SAC-SAC	UP	Loading problem C2009
532	SAC	17	TEN	19	TEN	19	OKJ-OKJ	UP	HEP cable frayed, engine removed from consist 2009
542	SAC	17	CTI	9	CTI	9	SJC-SJC	UP	Cross Traffic Cal Train, Cal Train, Control Point, ALAMEDA
543	SJC	45	PTI	28	PTI	18	FMT-GAC	UP	Meet 544, Siding, albrea
548	SAC	13	MBO	26	MBO	26	MTZ-SUI	UP	For maritime traffic Control Point, RV033

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
550	SAC	27	DSR	15	TRS	10	FFV-FFV	UP	Unticketed or fare evading passenger Ran through train. Down to the crew area of cafe car and locked in bathroom. I unlocked it and he claimed he was a minor then later told Greg he was 28. Clearly not a minor. Once he heard we requested police he stepped off. Verbally aggressive fare evader, Other,
502	SEA	20	DMW	34	DMW	30	VAN-KEL	BN	Held for or routed around MW work or equipment Control Point, Kelso South
506	SEA	25	DCS	28	DCS	23	TUK-SEA	BN	Power switch failure Dispatcher gave us authority by cp bailey and then again at cp Spokane street, where we manually lined a switch., Control Point, bailey, Control Point, spokane street
516	VAC	27	SYS	16	SYS	16	X8B-XF2	BN	PTC-caused slow-down or penalty stop Control Point, Annieville
518	VAC	No OS Rpt	MBO	15	MBO	15	X8B-XF2	BN	For maritime traffic Control Point, fraser river
519	SEA	147	PTI	76	PTI	76	STW-EVR	BN	Meet 518, Siding, English
58	CHI	107	DSR	79	FTI	31	YAZ-GWD	CC	Meet CN3228, Siding, Sidon
59	NOL	187	DSR	117	ITI	84	CHI-CHI	AM	Service, turn, or wye train 59, Engine swap
8	CHI	88	FTI	144	ENG	67	HAV-HAV	BN	Pick up rescue locomotive due to mechanical failure Swapped out lead unit Amtk 37 with the trailing Amtrak 337, 337
822	OKC	31	DSR	33	DSR	22	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, m1, Milepost, 350.7, 351.1, 50, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.7, 375.2, 60, m, Milepost, 375.4, 376.6, 60, m, Milepost, 377.5, 378.5, 60, m, Milepost, 378.5, 379.1, 60, m, Milepost,
337	MKE	18	CAR	16	CAR	16	XRO-SVT	CP	Air / Brake / Wheel ID4118, ID4017
350	DET	104	DCS	126	DCS	126	KAL-XGO	MI	Full service disruption. Signals, switches, PTC, crossings. Control Point, 140
352	PNT	29	DSR	30	RTE	11	XT6-X1W	CC	Dispatcher hold Control Point, fed jct
353	CHI	144	RTE	124	RTE	124	DER-ARB	MI	Dispatcher hold Milepost, 21.2, 21.2
355	CHI		PTI	71	PTI	71	DER-ARB	MI	Meet AMT 352, Control Point, 28
364	PTH	47	FTI	50	FTI	40	BTL-LNS	CC	Cross Traffic CN M399 crossing over from main 1 into BTL yard at McAllister, Control Point, mckalister, M399, manifest
365	CHI	130	SYS	110	SYS	110	XGO-KAL	MI	PTC problem or failure (cause unknown) Milepost, 122, 124

Amtrak Endpoint OTP Details

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
562	SAN	28	CON	19	CON	19	OSD-OSD	SN	Hold for bus with passengers from train
591	LAX	31	DCS	17	SYS	10	SNC-IRV	SC	PTC-caused slow-down or penalty stop
765	SLO	23	CON	19	CON	19	IRV-IRV	SC	Hold for bus with passengers from train
769	GTA	48	CON	32	CON	32	IRV-IRV	SC	Hold for bus with passengers from train
770	SAN	16	CON	36	CON	36	OSD-OSD	SN	Hold for thruway bus Hold at OSD for 6 connecting busses
774	SAN	57	CTI	17	CTI	15	SOL-SOL	SN	Meet coaster, Control Point, valley
777	SLO	34	PTI	23	SYS	19	IRV-IRV	SC	WAITED FOR BUSES Other, SAN JUAN STATION
786	SAN	71	PTI	49	PTI	46	GUA-LPS	UP	Meet 765, 14, Siding, Tangair
790	SAN	24	CTI	13	CTI	8	CML-XMR	UP	Meet SCRRA, 127, Control Point, N Camarillo
794	SAN	Trn Cancelled	DCS	13	CON	5	LAX-LAX	SC	Hold for thruway bus Manager held us for 5 mins for connections
710	BFD	Trn Cancelled	TEN	140	TEN	121	MCD-MDR	BN	HEP Lost HEP at W LeGrand. Crew found exposed, frayed power cable connected to HEP. Short looped and taped as temporary solution., C2003
712	BFD	58	FTI	24	FTI	24	MCD-MDR	BN	Meet Extended meet time due to AMTK 710 breaking down blocking single main at west kismet, bnsf 7977 west, Control Point, east kismet
713	OKJ	Trn Cancelled	PTI	20	PTI	14	TRK-MOD	BN	Meet 712, Control Point, WE MODESTO EMPIRE
714	BFD	79	PTI	53	TCC	44	OKJ-OKJ	UP	Task hold to replace horn valve C8303
715	OKJ	Trn Cancelled	PTI	5	PTI	5	WAC-COC	BN	Meet amt 703, Control Point, west allensworth
716	BFD	38	TCC	21	TCC	21	OKJ-OKJ	UP	Brake indicator replaced as well as throttle light replaced at Oakland Mechanical Facility additionally issues with PTC and blower in cab car at square icausing delay C6963
717	OKJ	74	CON	59	CON	51	HNF-HNF	BN	Hold for connecting train Hold for passengers from 715., 712
718	BFD	156	TRS	126	TRS	126	MTZ-MTZ	UP	Vehicle on track ahead Vehicle stuck on the tracks at 1158.8., Other, MTZ Depot
719	OKJ	Trn Cancelled							
4	CHI	108	FTI	215	FTI	73	KNG-FLG	BN	Cross Traffic BNSF, Milepost, 418.4, 344.0

Amtrak Endpoint OTP Details

26-FOI-0073100000008779"UNCLASSIFIED"9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/8/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
21	SAS	54	FTI	109	FTI	34	MCG-TPL	BN	Follow BNSF 8282, Siding, Pendleton, Siding, Temple	
307	STL	29	FTI	32	FTI	18	CRV-ALN	UP	Meet 7622, Control Point, GODFREY	
390	CHI	Trn Cancelled								
311	KCY	32	WTR	31	WTR	11	JEF-SED	UP	Heat order Other, Sedalia sub	
316	STL	26	WTR	25	WTR	10	SED-JEF	UP	Heat order Milepost w/Letters, SED, JEF	
318	CHI	58	FTI	42	FTI	20	SMT-XTF	CC	Cross Traffic unk, Control Point, Corwith	
319	KCY	57	PTI	28	PTI	28	JEF-SED	UP	Meet Siding, dow, amtk 316	

Amtrak Initial Terminal Details

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/8/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	244	09/08	3	3	Heat / AC 43348, Hot cafe. Mechanical came out to fix
ALB	448	09/07	6	6	Water, commissary, toilet/trash dumping Control Point, 142
BOS	2159	09/08	20	20	Catenary failure, Other, LOOP AND BROADWAY, LATE FROM YARD A/C CONGESTION AFTER CATENARY DAMAGE FROM TRAIN 2151
GRO	75	09/08	16		
HAR	622	09/08	21	16	Service, turn, or wye train, 653
HAR	622	09/08	21	5	Service, turn, or wye train, 653
HAR	644	09/08	4	4	Door, ENTIRE CONSIST
HAR	650	09/08	3	3	Set out defective cab car, NO CAB CAR IN CONSIST
HAR	656	09/08	1	1	Passenger and/or baggage
NHV	474	09/08	9	9	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard
NHV	486	09/08	5	5	Blocked from station track, ctial, 4407, Milepost, NHV, NHV, Waiting for the Ctrial
NYP	89	09/08	10	10	Routine inspections, LATE RELEASE BY MECHANICAL, LATE INSPECTION.
NYP	97	09/08	11	11	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASEF/SSYD A/C NECESSARY TO WAIT FOR AM98 TO ADD DINER CAR TO COMPLETE CONSIST
NYP	119	09/08	3	3	Passenger and/or baggage, BOARDING
NYP	181	09/08	15	15	Routine inspections, LATE RELEASE BY MECHANICAL, LATE INSPECTION.
NYP	609	09/08	6	6	Service, turn, or wye train, 644, TURNED OFF AM644
NYP	639	09/08	30	30	Service, turn, or wye train, 654, LATE TURN OFF AM654
NYP	651	09/08	19	19	Other electrical failure, 635 EX ES, LATE RELEASE F/SSYD A/C MECHANICAL ISSUES
NYP	655	09/08	2	2	Passenger and/or baggage, BOARDING
NYP	2109	09/08	5	5	Water, commissary, toilet/trash dumping, LATE COMMISSARY
NYP	2113	09/08	20	20	Unrecoverable penalty (PCS), 2116 NG NP, NECESSARY TO LOOP TRAIN A/C UNABLE TO OPERATE FROM PC2016
NYP	2115	09/08	(Trn Cxld)		Engine Issue
PHL	190	09/08	2	2	Planned set out / pick out of locomotives, cars or section of train, LATE FROM YARD
PHL	605	09/08	1	1	Planned set out / pick out of locomotives, cars or section of train, LATE FROM YARD
WAS	196	09/08	2	2	Passenger and/or baggage, DETRAINING ABOUT 10 PSGRS THAT GOT ON WRONG TRAIN THINKING IT WAS A138(8)

Amtrak Initial Terminal Details

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/8/2026

Terminal	Train	Date	Late	Delay	Cause
CDL	390	09/08	(Trn Cxld)		Car Issue
CHI	41	09/08	74	74	Waited for inbound train 6 engine 383 Late release of equipment, 383
CHI	329	09/08	11	7	Door ID4315, Unable to close doors
CHI	329	09/08	11	4	Trespassers broke the gate in CHI. APD called to remove from train. Other, CHI
DER	355	09/08	50	30	Hold for bus with pax's from PNT, TRM, ROY, and DET. Scheduled departure time out of DER is 6:09pm. EDR is only showing a 30 minute delay. Delay should be 50 minutes.
BFD	719	09/08	(Trn Cxld)		Third Party Engine Failure
GTA	770	09/08	18	18	Routine inspections The class one brake test had to be redone, Other, Goleta layover
GTA	782	09/08	25	25	Wait for station track Held in the siding at Elwood waiting for Amtrak 765 and 14 to pass before we could pull down to the Goleta station. Dispatcher was informed of our departure time and that we were ready to pull down in advance., 765, 14, Control Point, CP CO358
OKJ	526	09/08	1	1	Meet amt 11, Control Point, north jack london
OKJ	532	09/08	19	19	HEP cable frayed, engine removed from consist 2009
OKJ	712	09/08	7	7	Other electrical failure No hi horn. Swapped equipment, C2106
OKJ	714	09/08	44	44	Task hold to replace horn valve C8303
OKJ	716	09/08	21	21	Brake indicator replaced as well as throttle light replaced at Oakland Mechanical Facility additionally issues with PTC and blower in cab car at square icausing delay C6963
OKJ	718	09/08	29	29	Water, commissary, toilet/trash dumping
SAC	531	09/08	31	31	Loading problem C2009
SAN	765	09/08	13	13	PTC- IETMS incorrect consist Equipment swap. Consist was not showing. Reset and called CNOC west., Control Point, ash
SJC	538	09/08	2	2	Door C8010, Closed all doors, all door closed and was not getting door light. Reset doors and still did not get a door light. Cut out doors after double checking all doors closed.
SJC	542	09/08	9	9	Cross Traffic Cal Train, Cal Train, Control Point, ALAMEDA

Eastern Region

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	98.9	94.8	342	0
CDOT	95.0	90.0	91.2	92.4	20	2
MARC	95.0	93.1	92.4	90.2	58	4
SEPTA	95.0	90.9	93.4	91.5	197	18
NJT-NED	95.0	94.9	94.5	88.6	357	18
NJT-SED	95.0	100.0	98.4	97.2	21	0

Operating Highlights

Train 179(08) - Bridgeport, CT - Engine Failure

09SEP26: Train 179(08) stopped at Bridgeport Station/MP 55.4 on the Metro North Railroad due to what the engineer suspected was a condemnable flat spot on the lead engine 616. The train was ordered to shove back to the location of the Metro North Bridgeport yard, to facilitate a MNRR QMP inspecting the train.

An inspection by a Metro North Railroad QMP revealed two 2 inch shelling spots. The train was released to proceed at track speed, as this measurement fell within regular operating tolerances.

Train 179(08) was re-inspected by Amtrak mechanical personnel upon arrival at New York Penn Station. Upon inspection, E/616 was shopped for flat spots.

Train 179(08) continued west to Philadelphia after E/616 was removed and E/663 was ran around to lead.

As a result of Train 179(08)'s late operation, Train 110(09) was cancelled and Train 185(09) originated at Philadelphia.

Train	Delay	Comment
179(08)	2'17"	
110(09)	Cancelled	
185(09)	Orig PHL	
179(08)	1'46"	Inspection at NYP

Train 98(08) - South of Yemassee, SC - Freight Train Interference

08SEP26: Train 98(08) was delayed on the CSX Charleston Subdivision at MP 456.1 due to meeting CSX Train M409-08.

Train	Delay	Comment
98(08)	49"	

Train 2162(08) - New York Penn Station, NY - System/Expiring Paperwork

08SEP26: Service for Acela Train 2162(08) was delayed at New York Penn Station due to a set swap necessitated by expiring paperwork. Passengers were cross platformed to the equipment that came in as Train 2120(08) which represented Trin 2162(08) NYP-BOS.

Train	Delay	Comment
2162(08)	35"	

Train 653(08) - Philadelphia, PA - Cab Car Failure

08SEP26: Train 653(08) with E/633 and 3 cars was delayed upon departure at Philadelphia due to being capped with E/633. The set arrived at PHL with no cab car due to the current high shop count for cab cars.

Train	Delay	Comment
653(08)	38"	

Zoo Interlocking - Philadelphia, PA - Catenary or Wayside Failure

08SEP26: 5:46pm An emergency plate was automatically placed into effect on No. 4 track between Zoo Interlocking/MP 2.3 and Bryn Mawr Interlocking/MP 10.1. TE Personnel were immediately notified. Septa Train 4587 became disabled on No. 4 track at Zoo. Train 654(08) was used as a rescue train - and received all passengers from the Septa train before completing its move through Zoo Interlocking into 30th Street Station. All repairs were completed at 4:45am 09/09/26.

Train	Delay	Comment
654(08)	58"	
656(08)	24"	
651(08)	1'15"	
639(08)	30"	Turn off 654(08)
136(08)	30"	Held for Connections on 654(08)

Train 650(08) Philadelphia, PA -No Cab Car/Wying- Servicing

08SEP26: Train 650(08) with E/649 and 5 cars was delayed upon departure at Philadelphia due to operating without a cab car caused by shopped equipment.

Train	Delay	Comment
650(08)	43"	

Train 64(08) Niagara Falls, NY - Customs and Immigration

08SEP26: Train 64(08) with E/95 and 5 cars was delayed on the CSX Niagara QDN at MP 28.2 Niagara Falls due to US Border for customs. They were further delayed waiting for police to removing an unruly passenger.

Train	Delay	Comment
64(08)	20"	POLICE UNRULY PAX
64(08)	32"	US CUSTOMS

Philadelphia to Harrisburg Main Line - Zoo/Catenary or Wayside Failure

08SEP26: At 653A-ET, CETC reported that the emergency plate was cancelled on track 2 between MP10.1/Bryn Mawr and MP 5.4/Overbrook but there was damage reported to the catenary on track 2 at MP 88.0/Zoo. The Cat Car was needed to make the repairs. Septa westbound service was temporally cancelled and eastbound operated express from Bryn Mawr into Zoo. Several Trains were delayed operating through the area until repairs were complete.

Train	Delay	Comment
648(08)	06"	
646(08)	07"	
643(08)	06"	
644(08)	39"	
600(08)	34"	
642(08)	08"	

Train 2104(08) West of Philadelphia, PA - Engine Failure

08SEP26: At 1020A-ET, 26-PC-00731-100000008779 2104(08) UNCLASSIFIED 14 9/18/2026 PC/2014, PC/2141 was stopped on track 2 at County interlocking on the New York to Philadelphia main line with an unknown penalty. The engineer was trouble shooting with High Speed rail. Train 600(08) was behind them and had to make a reverse move to go around. The train was able to maintain HEP after the attempt of recycling but unable to clear the fault. New York was getting an E/606 ready for a rescue. Passengers were transferred to trains 56(08) and 644(08). Due to 2104(08) being terminated at County train 2115(08) was cancelled in its entirety. Train 2104(08) equipment recovered and was able to proceed east under its own power. The rescue E/606 at Edison changed ends and operated east back to New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2104(08)		TERM COUNTY
2115(08)	CANCELLED	
600(08)	35"	
644(08)	35"	
56(08)	39"	
2154(08)	03"	
NJT3833	07"	
2155(08)	08"	

Train 40(07) North of Camden, SC - Signal

08SEP26: Train 40(07) with E/145, E/199 and 10 cars was delayed on the CSX Hamlet S subdivision due to restricted signals from a known wayside signal failure from CP NE Mc Bee and CP Middendorf.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(07)	34"	

Boston, MA - Catenary or Wayside Failure

08SEP26: 2:08am - The equipment for Acela Train 2151(08) became disabled on its way from Southampton Yard to Boston South Station. The engineer reported an inverted pantograph on the lead power car. The engineer also reported a broken hanger and wires down 3 cars ahead. RFE Mingione and ET personnel responded. Once ET cleared the scene, the knuckle was prepared on the original 2151(08) equipment for the rescue diesel being dispatched from Southampton Yard. The inspection of the OCS on the Dorchester Branch between Loop/MP 227.0 and Broad/MP 227.6 revealed a series of broken hangers to which the inverted pantograph was attributed.

The 2155(08) set was moved up to replace the original 2151(08) equipment.

As a result train 85(08) was delayed.

As of 820A-ET, Dorchester dispatcher reported that the overhead catenary between South Bay and Broad was repaired and was good for normal service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2159(08)	20"	

New York Penn Station, NY/Sunnyside Yard - Catenary or Wayside Failure

07SEP26: 6:01pm The emergency maintenance unit 241(07) was delayed in Sub 2 between Sunnyside Yard and New York Penn Station due to downed catenary. 40 Office reported the catenary fell on top of the E/114. There were no passengers on board at the time of incident.

An emergency plate was placed into effect initially impacting Sunnyside (Sub 2 & 3, eastward engine track, ready tracks, 1-15 body tracks, 1 and 3 leads) to the Hellgate (no. 1 track Gate-Leggett), but was then sectionalized/shortened to Sub 2. ET Personnel responded to the scene.

As a result Train 241(07) was cancelled in its entirety. Passengers ticketed for Train 241(07) were moved to next available Trains 243(07) and 245(07).

As of 709A-ET, All signal indications at Leggett were restored and control of the interlocking was returned to section A dispatcher.

As of 554A-ET, Sunnyside yard Q switching center TOL's were cleared by C&S, Sub 1 and 2 were working as intended.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
241(07)	Cancelled	
238(08)	Cancelled	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
240(29)	29"	
280(29)	18"	
233(29)	54"	
283(29)	64"	
284(29)	39"	
291(29)	36"	
290(29)	47"	
49(29)	49"	
235(29)	49"	
48(28)	31"	
237(29)	36"	
239(29)	1'10"	
69(30)	51"	
240(30)	35"	
1233(30)	18"	
291(30)	45"	LATE TURN OFF 240(30)
284(06)	1'01"	

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77 (03)	50"	
78 (03)	50"	Turn of Late 77 (03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008779 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008779 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
159 (5)	BAL	665		HEP-WAS inspected and planning to move 9/9

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
612	8/29	175 (28)	I/O 41 MVB BUS COUPLER		

Eastern Region

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 90(08) Passenger Removal at Wilson, North Carolina – Improper Conduct

08SEP26, Passenger on PNR EF1C4B, traveling from Kingstree, SC to Philadelphia, PA was reportedly removed by local police due to disruptive behavior and using foul language and disturbing other passenger. Amtrak Police notified.

Delay:

90(08)

01"

Western Region

Operating Highlights

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Train 3(07) West of Kingman, AZ - Passenger Train Interference

09SEP26: Train 3(07), carrying 123 customers onboard, was delayed west of Kingman, AZ, while holding at Topock (MP 560.6) on the BNSF Seligman Subdivision to meet Amtrak Train 4(08).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(07)	36"	

Train 1(07)/421(06) East of Yuma, AZ - Freight Train Interference

09SEP26: Train 1(07)/421(06) was delayed east of Yuma, AZ, while holding at Colfred area (MP 785.5) on the Union Pacific Gila Subdivision due to freight traffic interference. Freight train IG4LB-05, led by UP 7905, stopped to inspect a reported hot bearing condition on its equipment. After the inspection, the freight train was authorized to continue operating at 30 MPH, requiring Train 1(07)/421(06) to follow the movement until Wellton (MP 771), where it was able to proceed around the freight train.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(07)/421(06)	37"	

Train 4(07) West of La Junta, CO - High Wind Warnings

08SEP26: Train 4(07), carrying 120 customers onboard, was delayed west of La Junta, CO, on the BNSF Raton Subdivision due to high wind warnings in effect between MP 574 and MP 557, and from MP 557 to the La Junta Station area. Winds were reported up to 65 MPH, requiring trains to operate at restricted speeds of 20 MPH through the affected territory.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(07)	32"	

Train 518(08) North of Everett, WA - Trespasser Strike

08SEP26: At 7:09 PM PT, Train 518(08), operating with locomotive WS1400, 13 cars, and carrying 171 customers onboard, fatally struck a trespasser north of Everett, WA, at MP 39.5 on the BNSF Bellingham Subdivision. The incident occurred at the Grove Street Crossing (DOT #084646X) in the City of Marysville, Snohomish County, Washington. The crossing consists of single main track and is equipped with advance warning signs, signals, pavement markings, and functioning gate arms. Head-end power remained operational throughout the incident. Local authorities, BNSF management personnel, Amtrak management personnel, detectives, and the County Coroner responded to the scene. The investigation remained in progress while emergency responders conducted on-scene activities. Following completion of the investigation, a relief crew arrived and assumed operation of the train. Train 518(08) was subsequently released and continued its trip.

Train 519(08), carrying 150 customers onboard, was delayed at Stanwood, WA, and later held at North English Siding (MP 46.0) on the BNSF Bellingham Subdivision while awaiting the release of the affected territory.

National Response Center Number: 1473101

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
519(08)	2'18"	
518(08)	2'18"	

Train 305(08) Bloomington-Normal, IL - Freight Train Interference

08SEP26: Train 305(08) with 160 customers onboard, was delayed departing Bloomington - Normal Station, IL/MP124.0 on the UP Joliet subdivision meeting UP freight UP/5465. Once the route was clear, train 305(08) continued south.

Train	Delay	Comment
305(08)	33"	

Train 370(08) West of St. Joseph-Benton Harbor, MI - Animal Strike

08SEP26: Train 370(08), with engine IDTX 4621, 4 cars, and 100 customers onboard, struck an animal at mile post 133.0, 45 miles west of St Joseph, MI/MP87.9, on the CSX Grand Rapids subdivision. There were no reported injuries to the customers or crew. There was no damage reported to the equipment. The crew completed a brake test and continued east.

Train	Delay	Comment
370(08)	04"	

Train 8/28(07) East of Wolf Point, MT - Freight Train Interference

08SEP26: Train 8/28(07) was delayed east of Wolf Point, MT, while holding at East Glasgow (MP 221.0) on the BNSF Glasgow Subdivision to meet BNSF 7544.

Train	Delay	Comment
8/28(07)	34"	

Train 3(08) East of Kansas City, MO - Freight Train Interference

08SEP26: Train 3(08), with 217 customers onboard, was delayed at Hardin/MP396.6, 55 miles east of Kansas City, MO/MP6.85 on the BNSF Marceline subdivision meeting BNSF freight. Once the route was clear, train 3(08) continued west.

Train	Delay	Comment
3(08)	47"	

Train 364(08) East of Battle Creek, MI - Freight Train Interference

08SEP26: Train 364(08), with 162 customers onboard, was delayed at McAllister/MP181.2 5.5 miles east of Battle Creek, MI/MP175.7 on the CN Flint subdivision meeting CN freight M399 while it crossed over from main track one into Battle Creek Yard. Train 364(08) was further delayed handlining the switch at McAllister to continue travel east on main track one.

Train	Delay	Comment
364(08)	40"	FTI CN/M399
364(08)	35"	DCS Handline switch

Train 41(08) Chicago, IL - Engine Failure

08SEP26: Train 41(08), with engines 171 and 45, 10 cars, and 194 customers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late release of the equipment by Chicago Mechanical. The lead engine 171 was held off of the consist for preventative maintenance. The replacement engine 383 came off of inbound train Amtrak 6(06). Once the equipment was made up complete, train 41(08) shoved into the depot, boarded customers, and departed Chicago Union Station.

Train 355(08) East of Ann Arbor, MI - Passenger Train Interference

08SEP26: Train 355(08) with 78 customers onboard was delayed at control point 28/MP28.2, 11 miles east of Ann Arbor, MI/MP37.5, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 352(08). Once the route was clear, train 355(08) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(08)	1'11"	

Train 21(07) North of Temple, TX - Freight Train Interference

08SEP26: Train 21(07), with 98 customers onboard, was delayed between Pendleton/MP221.2 and Temple Station, TX/MP218.2, on the BNSF Ft Worth subdivision following BNSF freight BN/8282. Once the route was clear, train 21(07) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(07)	34"	

Train 713(08) Terminate Emeryville, CA - Third Party Contractor Engine Failure

08SEP26: Train 713(08), operating with Locomotive C2006 and 8 cars, with 21 customers was terminated in Emeryville, CA account crew of having less than 300 gallons of fuel upon departing the Martinez, CA station. The customers were accommodated on the bus to San Francisco, CA made an extra stop and Oakland, CA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(08)		Term EMY

Train 4(06) East of Naperville, IL - Commuter Train Interference

08SEP26: Train 4(06), with 178 customers onboard, was delayed at Lisle/MP25.4, 3 miles east of Naperville, IL/MP28.5, on the BNSF Chicago subdivision following a Metra commuter. Once the route was clear, train 4(06) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(06)	38"	

Train 786(08) North of Lompoc-Surf, CA - Passenger Train Interference

08SEP26: Train 786(08), carrying 52 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.7) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(08) and 14(08).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(08)	46"	

Train 714(08) Oakland, CA - Third Party Contractor Engine Failure

08SEP26: Train 714(08) was delayed departing the Oakland, CA Jack London Station account of late release from the yard. TASI mechanical made repairs to the horn on Locomotive C2106 prior to releasing the equipment.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(08)	44"	

Train 710(08) and Train 715(08) - No Head End Power

08SEP26: 11:56A-PDT, Train 710(08) with 104 customers operating with push-pull with Cab Car C8311, 7 cars and Locomotive C2003, stopped on single main track at MP 1036.8 on the Burlington Northern Santa Fe Stockton Subdivision, 10 miles west of the Madera, CA station, after losing head end power and tractive motive effort from Locomotive C2003. The weather was reported as 90°F and sunny. The crew worked with TASI Mechanical while Amtrak Road Foreman responded to assist.

The crew found and made temporary repairs to a head end power cable with exposed wire. The train continued to MP 1026.6 where the train lost head end power for a second time. Amtrak Road Foreman responded and was able to restore head end power and air issues but the train lost head end power for a third time. The decision was made to continue to the Fresno, CA station where the train was terminated. The customers were transferred to Train 712(08).

12:54P-PDT, Train 715(08), with 102 customers, operating with Locomotive C2124 and 9 cars, stopped at Calwa / MP 994.9 on the Stockton Subdivision, 3 miles east of the Fresno, CA station, account of major loss of oil in Locomotive C2124 causing lose of head end power and tractive motive effort. The weather was reported as 91°F and sunny. The train was terminated at the location and customers were transferred from train to train from Train 715(08) to Train 712(08). Those customers were taken to Hanford, CA where they boarded 717(08) for continued westbound travel.

The crew reported local ambulance and EMS responded account of reports of customers becoming agitated, 2 customers with panic attacks and conditions inside the vehicle was heating up.

Train 719(08) canceled in its entirety. The customers were accommodated on Train 703(08). Two buses were secured for customers scheduled to travel between Stockton, CA and Oakland, CA.

WBS#: B.TR.100150.7159

Train	Delay	Comment
710(08)		Term FNO - Customers to 712(08)
715(08)		Term East of FNO
719(08)		Cancel - Customers to 703(08)
712(08)	39"	West of FNO and FNO - Disabled 710(08)
712(08)	29"	East of FNO
710(08)	19"	MDR to FNO
710(08)	2'01"	West of MDR
717(08)	51"	Hold HNF for customers on 712(08)
717(08)	23"	Hold for FNO track
714(08)	38"	Meet 715/710 at Figarden

Train 4(07) East of Albuquerque, NM - Commuter Train Interference

08SEP26: Train 4(07), carrying 121 customers onboard, was delayed east of Albuquerque, NM, on the NMRX Glorieta Subdivision due to commuter rail traffic interference. The train followed NMRX 1108 to East Herzog (MP 876.1) and subsequently met NMRX 109 and NMRX 105 at East Herzog (MP 876.1) and East Bernalillo (MP 885.25).

Train	Delay	Comment
4(07)	1'01"	

Train 59(07) South of Hammond, LA - Temporary Speed Restrictions

08SEP26: Train 59(07), with 107 customers onboard, was delayed between McComb, MS/MP806.9 and Hammond, LA/MP859.1 on the CN McComb subdivision due to temporary speed restrictions by order of the dispatcher. Once clear of the affected area, train 59(07) continued south.

Train	Delay	Comment
-------	-------	---------

Train 58(08) South of Hammond, LA - Drawbridge Opening

08SEP26: Train 58(08) with 135 passengers was delayed on the CN McComb subdivision 16 miles south of Hammond due to the Manchac Bridge/MP 873.7 stuck open. CN MOW responded to the scene, closed the bridge, and train movement continued.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(08)	1'33"	

Train 5(07) West of Denver, CO - Signal

08SEP26: Train 5(07) was delayed on the UPRR Moffat Tunnel subdivision seven miles west of Denver due to switch issues at Arvada/MP 7.5. The crew took the switches in hand and continued to Winter Park.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(07)	46"	

Train 7/27(07) Williston, ND - M of W Work

08SEP26: Train 7 / 27(07) was delayed departing the Williston, ND station account of BNSF MoW overstay. The Hollander welder was clamped to the rail and crews had issues releasing it from the welder.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(07)	33"	

Train 502(08) South of Kelso-Longview, WA - M of W Work

08SEP26: Train 502(08) was delayed at Kelso South / MP 98.9 on the Burlington Northern Santa Fe Seattle Subdivision, 2 miles south of the Kelso - Longview, WA station, waiting on BNSF MoW to clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
502(08)	34"	

Train 22(08)/422(06) South of Temple, TX - M of W Work

08SEP26: Train 22(08)/422(06) with 168 customers was delayed on the BNSF Galveston subdivision one mile south of Temple at Opal Junction/MP 217.4 due to MOW overstay. Once MOW was clear of the tracks, 22(08)/422(06) continued to Temple.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(08)/422(06)	1'50"	

Train 531(08) Sacramento, CA - Third Party Contractor Engine Failure

08SEP26: Train 531(08), operating with Locomotive C2009, Locomotive C2102 and 5 cars, was delayed departing the Sacramento, CA Valley Station, due to lead Locomotive C2009 shutdown and the train experiencing air issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
531(08)	31"	

Amtrak Michigan Line West of Dearborn, MI - CETC System

08SEP26: Trains were delayed on the Amtrak Michigan Line due to code line failure between Dearborn, Michigan and Kalamazoo, Michigan at CP 9/MP 9.8 through CP 140/MP 139.9. Train 365(08) was stopped three miles west of Battle Creek at CP 124. Train 353(08) was stopped 12 miles west of Dearborn at CP 21. Train 350(08) was stopped three miles east of Kalamazoo at CP 140. Network and IMCS teams made a configuration change just east of Jackson at MP 75.10 and services were restored by manually reloading the services to the OTN nodes. Once train movement was restored, trains continued to be delayed along the route due to crossing malfunctions, making it necessary to stop and protect.

Train	Delay	Comment
353(08)	2'04"	CP 21
365(08)	1'50"	CP 124
350(08)	2'06"	CP 140
353(08)	05"	Stop and Protect
365(08)	08"	Stop and Protect

Train 5(07) West of McCook, NE - Car Failure

08SEP26: Train 5(07) with E/13-203, ten cars, and 177 customers was delayed on the BNSF Akron subdivision due to C/32006 truck hunting with a grinding noise when operating over 50mph. The crew reduced speed to 50mph and continued to Denver, where C/32006 was set out for repair. Customers were accommodated in available sleeper space as well as C/31006.

Train	Delay	Comment
5(07)	37"	W/MCK - reduced speed
5(07)	1'32"	DEN - set out C/32006

Train 390(08) Carbondale, IL - Car Failure

08SEP26: Axle count C/33025 on train 390(08) was reported with a mechanical defect at Carbondale. A GE board was sourced to repair C/33025 from the local coach C/35005 in St Louis. The local coach car was scheduled to be added to train 22(07), but was set out at St. Louis to utilize the necessary parts. This created over capacity conditions on train 22(07). As a result, one supplemental express bus was secured for train 22(07) and operated St Louis to Chicago.

At Carbondale, mechanical replaced the GE board on C/33025. The replacement GE board failed and C/33025 could not operate in revenue service. As a result, train 390(08) was cancelled with four buses sourced as alternate transportation. The equipment deadhead non-revenue to Chicago.

WBS#: B.TR.100150.7157

Midwest Service Adjustments Chicago, IL - Engine Failure

08SEP26: Due to locomotive availability issues, the following trains were cancelled in their entirety with customer service working to source alternate transportation:

Lincoln Service: 307(08), 302(09), 301(10), and 306(10). Three buses were confirmed for 307(08). Four buses were confirmed for 302(09).

Pere Marquette: 370(09), 371(10), 370(11), and 371(12). Two buses were confirmed for 370(09). Two buses were confirmed for 370(11).

Carl Sandburg: 381(09), 382(09), 381(11), and 382(11). One bus was confirmed for 381(09). One bus was confirmed for 381(11).

Wolverine: 350(10) and 355(10). Two buses were confirmed for 350(10).

WBS#: B.TR.100150.7158

Train 777(07) North of Goleta, CA - Loss of Shunt

07SEP26: Union Pacific Railroad advised that train 777(07) operating with E/C2110, C/34981, C/6805, C/C6352, C/6413, C/C6464, and CC/6903 experienced a loss of shunt on September 7th, 2026 at 7:16:24 PM PST. This occurred north of Goleta, CA station at Capitan/ MP 345.66 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 6 seconds. UPRR signal department was notified, and shunt testing will be performed.

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

05SEP26: High tides along the Southern California coast caused track indication issues between San Clemente Pier (MP 204.8) and CP SONGS (MP 209.5) on the Metrolink Orange Subdivision, requiring trains to operate at restricted speed and flag through the affected territory. Metrolink personnel conducted track inspections following each train movement through the area, resulting in significant congestion and delays to Pacific Surfliner service.

The incident resulted in the following service impacts and recovery actions:

- Train 581(05), carrying 244 customers onboard, was delayed at CP SONGS (MP 209.5) while awaiting authorization to proceed through the affected territory under restricted-speed conditions.
- Train 580(05), carrying 373 customers onboard, was delayed at San Clemente Pier Station (MP 204.9) before proceeding through the area under flag protection.
- Train 785(05), carrying 374 customers onboard, was delayed at CP SONGS while awaiting the passage of Train 580(05) before proceeding toward San Clemente Pier.
- Train 587(05), carrying 410 customers onboard, was delayed at CP SONGS while awaiting track inspections and clearance through the affected territory.
- Train 782(05), carrying 411 customers onboard, was delayed at CP Serra (MP 199.7) pending clearance through the affected territory.
- Train 584(05), carrying 167 customers onboard, was delayed at CP Serra after initially holding near Trabuco (MP 195.5).
- Train 588(05), carrying 106 customers onboard, experienced delays approaching the affected territory.
- Train 591(05) experienced delays approaching and departing Oceanside, CA, due to congestion created by the restricted operations.
- Train 786(05) encountered downstream delays while operating south toward the affected territory.

To mitigate customer impacts, the following service adjustments were implemented:

- Train 584(05) was terminated at San Juan Capistrano, CA, with customers accommodated on Train 588(05).

- Train 595(05) operated late after turning from the delayed Train 782(05).
- Equipment from Trains 584(05) and 786(05) was returned to Los Angeles, CA.

Additional service adjustments for Pacific Surfliner for 9/6

26-FOI-00731 00000008779 "UNCLASSIFIED" 9/18/2026

Trains 566(06), 567(06), 572(06), 573(06), 581(06), 584(06), 588(06), 587(06), 593(06) are canceled entirely with customers to next available services.

Train 782(06) is canceled LAX-SAN, customers to next services.

Train 761(06) is canceled SAN-LAX, customers to next services.

Train 794(06) is canceled LAX-SAN with alternate bus 3594 transportation.

Train 564(06) will term IRV.

Train 595(06) will orig IRV.

Train 580(06) will term IRV.

Train 579(06) will orig IRV.

the following trains will operate a bus bridge between Oceanside (OSD) and Irvine (IRV): 765(06), 562(06), 777(06), 774(06), 591(06), 790(06), 769(06), 770(06), 785(06), 786(06).

6 buses were confirmed for bus bridge segment, and 2-buses for 3594 on both Sunday 9/6 and Monday 9/7.

07SEP26: Pacific Surfliner service resumed normal operations on September 7, 2026. All trains returned to the standard operating plan, with the exception of Train 567(07), due to only three trainsets being available in San Diego, CA.

The following service adjustments were implemented:

- Train 567(07) was canceled, with customers accommodated on Train 769(07).
- Equipment from Los Angeles 8th Street Yard was utilized to operate Train 572(07).

07SEP26: Tracks east of San Clemente Pier, CA, were reopened for service on September 8, 2026; however, high tides later caused washout conditions and recurring signal issues between San Clemente Pier and CP SONGS on the Metrolink Orange Subdivision. Metrolink personnel responded to replace ballast and conduct ongoing inspections of the affected track structure. As a result, Pacific Surfliner trains were required to operate at restricted speeds through the area, causing delays and congestion throughout the corridor.

The incident resulted in the following service impacts and recovery actions:

- Train 579(07), carrying 382 customers onboard, was delayed at Oceanside, CA, while maintenance personnel repaired the affected track. After departing Oceanside, the train incurred additional delays while holding at CP SONGS pending authorization to proceed through the affected territory.
- Train 581(07), carrying 364 customers onboard, was delayed at Oceanside, CA, while awaiting the reopening of the route.
- Train 782(07), carrying 405 customers onboard, was the last train authorized through the affected territory before Metrolink suspended train movements due to worsening tide conditions.
- Train 584(07), carrying 128 customers onboard, was held at Irvine, CA.
- Train 786(07), carrying 258 customers onboard, was held at Santa Ana, CA.
- Train 587(07), carrying 434 customers onboard, was held at Oceanside, CA.
- Train 588(07) was held at Los Angeles, CA.
- Train 591(07) was held at San Diego, CA.

To mitigate customer impacts, the following service adjustments were implemented:

- Trains 591(07), 593(07), and 595(07) were canceled.
- Trains 588(07) and 790(07) were canceled between Los Angeles and San Diego.
- Train 794(07) operated between Los Angeles and Irvine, where it terminated.
- Seven buses were secured to transport customers from Train 587(07) from Oceanside to Irvine.
- The same buses were then utilized to transport customers from Trains 584(07) and 786(07) from Irvine to San Diego, making all intermediate station stops.
- The buses were also used to accommodate customers from the canceled Trains 591(07), 593(07), and 595(07).
- Three additional buses were secured for customers requiring transportation south of Irvine from Trains 790(07) and 794(07).

September 9th:

Trains 566, 567, 572, 573, 581, 584, 588, 587, 593 (08, 09) are cancelled entirely.

Customers will need to take next available trains. ~~26-FOI-007311-00000008779~~ UNCLASSIFIED'S. 9/18/2026

Train 782 (08, 09) cancelled Los Angeles, CA -San Diego, CA, Customers to next available services.

Train 761 (08, 09) cancelled San Diego-Los Angeles, CA, Customers to next available services.

Train 794 (08, 09) cancelled Los Angeles, CA -San Diego, CA, with alternate BUS 3594 Transportation and an additional bus.

Train 564 (08, 09), will terminate in San Juan Capistrano, CA.

Train 595 (08, 09), will originate in San Juan Capistrano, CA.

Train 580 (08, 09), will terminate in San Juan Capistrano, CA.

Train 579 (08, 09), will originate in San Juan Capistrano, CA.

Trains 765, 562, 777, 774, 591, 790, 769, 770, 785, 786 (08, 09) will operate a Bus Bridge between Oceanside, CA and Irvine, CA. (**Please note: Trains will operate TO AND SERVICE San Juan Capistrano (SNC) Station- WILL THEN TURN AND MEET BUS BRIDGE AT IRVINE STATION**).

Initially, there were 3 buses providing alternate transportation between Irvine, CA and San Juan Capistrano. Two additional buses were secured account of the high ridership.

WBS#: B.TR.100150.7150

Train	Delay	Comment
-------	-------	---------

584 (05)	Term SNC				
786 (05)	Term IRV				
593 (05)	Canceled				
785 (05)	50"				
587 (05)	2'19"	26-FOI-00731	00000008779	"UNCLASSIFIED"	9/18/2026
584 (05)	52"				
591 (05)	24"			late turn of 580	
591 (05)	2'17"				
782 (05)	3'35"				
588 (05)	2'52"				
790 (05)	2'11"				
595 (05)	2'36"			late turn of 782	
567 (06)	Canceled				
572 (06)	Canceled				
566 (06)	Canceled				
573 (06)	Canceled				
581 (06)	Canceled				
584 (06)	Canceled				
588 (06)	Canceled				
587 (06)	Canceled				
593 (06)	Canceled				
782 (06)	Canceled LAX-SAN				
761 (06)	Canceled SAN--LAX				
794 (06)	Canceled LAX-SAN				
564 (06)	Term IRV				
595 (06)	Orig IRV				
580 (06)	Term IRV				
579 (06)	Orig IRV				
765 (06)	Bus Bridge OSD-IRV				
562 (06)	Bus Bridge OSD-IRV				
777 (06)	Bus Bridge OSD-IRV				
774 (06)	Bus Bridge OSD-IRV				
591 (06)	Bus Bridge OSD-IRV				
790 (06)	Bus Bridge OSD-IRV				
769 (06)	Bus Bridge OSD-IRV				
770 (06)	Bus Bridge OSD-IRV				
785 (06)	Bus Bridge OSD-IRV				
786 (06)	Bus Bridge OSD-IRV				
567 (07)	Canceled				
581 (07)	1'01"				
579 (07)	1'50"				
782 (07)	2'24"				
584 (07)	41"			late turn 579	
584 (07)	Term IRV				
786 (07)	Term IRV				
587 (07)	3'47"			Bus Bridge OSD-IRV	
588 (07)	Canceled				
591 (07)	Canceled				
593 (07)	Canceled				
790 (07)	Term LAX				
595 (07)	Canceled				
794 (07)	Term IRV				
785 (07)	58"				
769 (08)	32"			IRV Bus Connect	
770 (08)	36"			OSD Bus Connect	
765 (08)	19"			IRV Bus Connect	

Train 5(04) West of Denver, CO - Engine Failure

05SEP26: Train 5(04), E/179-E/206-9 Cars, with 232 customers onboard, was delayed 3 miles west of Denver, CO (MP0.0), on the BNSF Front Range Subdivision. The delay occurred at North Yard (MP3.0) while freight locomotive UP5727 was added to the head end after both train locomotives experienced dynamic braking issues en route to Denver. Once UP5727 was added, Train 5(04) proceeded west.

07SEP26: Oakland Mechanical was unable to make repairs to the dynamic brakes. UP5727 was dispatched on Train 6(08) to operate from Emeryville, CA and Chicago, IL. As a result, the train was limited to a maximum freight speed of 70 mph.

Train	Delay	Comment
5(04)	1'24"	Adding FRT engine
6(07)	32"	EMY to GJT - Operate with Freight Locomotive
5(04)	1'10"	GSC to EMY - Operate with Freight Locomotive

Wolverine Service - Pontiac, MI Wye OOS

04SEP26: Canadian National 26-FOI-00731 00000008779 UNCLASSIFIED 9/18/2026, MI wye on the CNRR Holly Subdivision was removed from service due to wide gauge and was expected to remain out of service until Tuesday, September 7. As a result, Train 355(04) departed Pontiac on time but incurred delay en route to Detroit, MI while completing a shove move to Milwaukee Jct (MP4.1) to wye the equipment. After the wye move was completed, Train 355(04) continued toward Chicago operating at track speed.

05SEP26: Train 351(05), with 14 customers onboard, departed Pontiac, MI 2 hours and 31 minutes late due to the late wyeing of the engines at Milwaukee Jct prior to departure. The wye move was delayed by the late arrival of inbound Train 354(04), which arrived at 3:16AM-ET.

Due to the Pontiac, MI wye being out of service and Chicago unable to support a push-pull trainset, Train 350(05-08) was terminated at Detroit, MI, with two alternate buses secured for 350(05), one alternate bus secured for 350(06), two alternate buses secured for 350(07), and one alternate bus secured for 350(08). Train 355(05-08) originated at Dearborn, MI, with two alternate buses secured for 355(05), two alternate buses secured for 355(06), three alternate buses secured for 355(07), and one alternate bus secured for 355(08) between Pontiac, MI, and Dearborn, MI, to accommodate customers.

08SEP26: The wide gauge on the Pontiac wye was reported to be repaired.

WBS#: B.TR.100150.7144

Train	Delay	Comment
355(04)	31"	
351(05)	2'31"	ITD PNT
355(05)	56"	Air Issues @DER
355(06)	15"	DER - late buses
355(07)	07"	DER - late buses
355(05-08)	ORIG DER	
350(05-08)	TERM DET	
355(08)	50"	

Union Pacific Sedalia, Jefferson City, Springfield and Joliet Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph. Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph through 04SEP.

05SEP26: Continued Union Pacific Level 2 heat restrictions on the Springfield, Sedalia and Jefferson City Subdivisions. The Joliet Subdivision was reduced to a Level 1 heat restriction.

06-07SEP26: Level two restrictions continued on the Sedalia subdivision between Lee's Summit and Independence stations.

WBS#: B.TR.100150.7132

Train	Delay	Comment
-------	-------	---------

316 (31)	31"		
319 (31)	32"		
318 (31)	14"		
311 (31)	12"		
301 (01)	12' 50"	JOL to STL	"UNCLASSIFIED" 9/18/2026
302 (01)	1' 04"	LCN to JOL	
311 (01)	51"	HEM to KCY	
305 (01)	1' 05"	JOL-LCN	
22 (31)	1' 02"	ALN-JOL	
307 (01)	20"	JOL-DWT	
21 (01)	1' 58"	JOL-ALN	
306 (01)	1' 04"		
301 (02)	1' 05"		
22 (01) / 422 (30)	1' 58"		
302 (02)	1' 02"		
21 (02)	1' 57"		
319 (02)	1' 53"		
307 (02)	24"		
305 (02)	1' 09"		
306 (02)	1' 01"		
311 (02)	44"		
316 (02)	36"		
318 (02)	2' 16"		
316 (01)	28"		
318 (01)	2' 41"		
319 (01)	2' 28"		
302 (03)	1' 10"		
301 (03)	1' 35"		
311 (03)	52"		
22 (02)	1' 52"		
319 (03)	2' 45"		
318 (03)	3' 11"		
305 (03)	1' 16"		
306 (03)	1' 08"		
307 (03)	26"		
316 (03)	44"		
21 (03)	1' 40"		
311 (04)	33"		
302 (04)	1' 25"		
301 (04)	1' 25"		
307 (04)	45"	Turn 302 (04)	
22 (03)	1' 46"		
305 (04)	20"		
306 (04)	44"		
318 (04)	2' 01"		
316 (04)	42"		
319 (04)	2' 23"		
21 (04)	1' 59"		
300 (05)	09"		
302 (05)	23"		
301 (05)	44"		
22 (04)	45"		
311 (05)	1' 16"		
316 (05)	27"	ITD KCY - Turn of 311 (05)	
316 (05)	23"	Heat Orders	
21 (05)	03"		
319 (05)	1' 37"		
318 (05)	2' 22"		
306 (05)	37"		
311 (06)	27"		
316 (06)	23"		
319 (06)	26"		

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

26-010273

90000076

UNCLASSIFIED

9/18/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 00900008779 UNCLASSIFIED 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

26-FOI-00731 00000008779
Western Region

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
	Thenard, CA	76		Waiting for BN movement

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (7)	EMY	UP5727	Dynamic Brakes on E/179		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00731

00000008779

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
236 (08)	ALB	CAFE 433XX IN PLACE OF SPLIT CLUB 481XX NO BUSINESS CLASS	passengers notified to rebook due to coach sold out as well.	16	43348
244 (08)	ALB	CAFE 433XX IN PLACE OF SPLIT CLUB 481XX NO BUSINESS CLASS	passengers advise of downrade to coach and refund due to no jy seating	14	43348
233 (08)	NYP	CAFE 433XX IN PLACE OF SPLIT CLUB 481XX NO BUSINESS CLASS	passengers advised no jy car downgrade to coach and refund of diff.	10	43348
243 (08)	NYP	CAFE 433XX IN PLACE OF SPLIT CLUB 481XX NO BUSINESS CLASS	passengers advise of downrade to coach and refund due to no jy seating	8	43348
172 (08)	WAS	SPLIT CLUB 48179 IN PLACE OF A CAFE	none	0	48179

Reverse Consists

Train Number	Station	Reason
171 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (08)	PHL	Consist reversed Business class seat orientation may have changed At Front
110 (08)	PHL	Consist reversed Business class seat orientation may have changed At Rear
138 (08)	NFK	Consist reversed Business class seat orientation may have changed At Front
86 (08)	NPN	Consist reversed Business class seat orientation may have changed At Front
183 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
174 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front
137 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
178 (09)	RNK	Consist reversed Business class seat orientation may have changed At Front