



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, September 10, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/09/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/09/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	39	87.7%	2,820	409	85.5%	103,342	14,377	86.1%
Central Division	86.0%	55	3	94.5%	521	65	87.5%	19,716	1,840	90.7%
East Division	82.0%	178	16	91.0%	1,521	174	88.6%	54,341	8,308	84.7%
West Division	86.0%	84	20	76.2%	778	170	78.1%	29,285	4,229	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008780 Endpoint Arrival Dates through 9/9/26 9/18/2026 UNCLASSIFIED

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	85,853	21,552	75%	935,432	249,161	73%	34,526,478	8,835,141	74%
Northeast Corridor	81%	37,183	5,370	86%	418,109	72,711	83%	15,133,008	3,659,993	76%
Acela	83%	10,425	1,237	88%	92,722	11,404	88%	3,055,348	770,544	75%
Northeast Regional	79%	26,758	4,133	85%	325,387	61,307	81%	12,077,660	2,889,449	76%
Richmond / Newport News / Norfolk	77%	8,040	1,530	81%	97,393	26,900	72%	3,620,192	1,074,199	70%
Springfield Shuttles	89%	688	22	97%	6,507	943	86%	212,909	34,081	84%
Roanoke	79%	3,270	0	100%	32,182	5,532	83%	1,145,985	255,226	78%
On Spine Northeast Regional	80%	14,760	2,581	83%	189,305	27,932	85%	7,098,574	1,525,943	79%
State Supported	80%	37,708	10,196	73%	409,029	120,673	70%	15,197,623	3,331,947	78%
Borealis	80%	498	244	51%	5,373	402	93%	193,362	40,873	79%
Capitol Corridor	90%	3,967	691	83%	35,002	5,061	86%	1,264,506	169,107	87%
Carolinian	70%	920	104	89%	10,147	3,880	62%	387,475	152,030	61%
Cascades	75%	2,621	792	70%	24,320	6,371	74%	874,956	247,025	72%
Downeaster	82%	1,762	244	86%	15,995	256	98%	535,975	62,101	88%
Empire	78%	4,648	1,061	77%	54,819	13,168	76%	1,896,623	468,130	75%
Adirondack	72%	243	56	77%	3,459	804	77%	117,554	37,757	68%
Ethan Allen Express	70%	420	243	42%	4,955	1,812	63%	191,857	74,088	61%
Maple Leaf	70%	640	294	54%	7,917	2,354	70%	236,229	92,233	61%
New York - Albany	85%	2,351	412	82%	23,528	4,019	83%	872,795	152,508	83%
New York - Niagara Falls	75%	994	56	94%	13,803	4,163	70%	464,195	104,672	77%
Berkshire Flyer	60%	0	0	-	1,157	16	99%	13,993	6,872	51%
Gold Runner	73%	1,814	1,621	11%	23,257	12,598	46%	852,979	321,357	62%
Heartland Flyer	70%	109	106	3%	1,790	703	61%	73,347	30,888	58%
Hiawatha	90%	1,468	0	100%	16,401	1,890	88%	600,178	65,737	89%
Illinois	78%	1,482	434	71%	21,710	11,158	49%	850,067	243,792	71%
Carl Sandburg / Illinois Zephyr	85%	181	0	100%	3,672	1,042	72%	141,418	40,376	71%
Illini / Saluki	85%	689	434	37%	7,691	4,414	43%	293,703	75,891	74%
Lincoln Service	70%	612	0	100%	10,347	5,702	45%	414,946	127,525	69%
Keystone	92%	9,705	970	90%	74,153	11,577	84%	2,588,044	267,829	90%
Lincoln / Missouri	70%	526	526	0%	6,255	5,235	16%	263,866	140,692	47%
Mardi Gras Service	80%	274	0	100%	2,820	518	82%	136,772	30,503	78%
Michigan	70%	1,949	731	62%	20,006	8,390	58%	693,284	233,940	66%
Blue Water	70%	560	171	69%	4,625	1,761	62%	163,250	66,905	59%
Pere Marquette	85%	125	0	100%	2,719	444	84%	89,200	16,797	81%
Wolverine	70%	1,264	560	56%	12,662	6,185	51%	440,834	150,238	66%
Missouri	80%	145	37	74%	2,166	1,793	17%	75,526	23,058	69%
Pacific Surfliner	85%	3,478	2,191	37%	65,608	30,074	54%	2,792,454	548,647	80%
Pennsylvanian	80%	724	204	72%	7,755	1,899	76%	300,308	57,730	81%
Piedmont	80%	353	83	76%	8,817	1,954	78%	379,745	96,555	75%
Vermont	75%	1,265	157	88%	12,635	3,746	70%	438,156	131,953	70%
Long Distance	70%	10,962	5,986	45%	108,294	55,777	48%	4,156,580	1,840,738	56%
Auto Train	70%	625	341	45%	5,723	2,922	49%	265,794	91,663	66%
California Zephyr	70%	916	600	34%	8,560	3,749	56%	329,895	129,928	61%
Cardinal	70%	224	187	17%	1,836	1,331	28%	78,852	40,582	49%
City Of New Orleans	75%	615	427	31%	6,010	5,420	10%	215,662	77,885	64%
Coast Starlight	70%	1,049	267	75%	10,972	2,683	76%	388,226	137,325	65%
Crescent	70%	741	217	71%	8,009	1,794	78%	313,406	96,264	69%
Empire Builder	70%	1,162	473	59%	9,960	4,074	59%	329,516	164,824	50%
Floridian	60%	1,468	1,055	28%	13,447	10,394	23%	533,353	370,400	31%
Lake Shore Ltd	73%	873	775	11%	9,314	3,794	59%	330,995	101,637	69%
Palmetto	70%	380	155	59%	6,828	2,936	57%	310,009	97,734	68%
Silver Meteor	70%	807	320	60%	8,063	4,381	46%	342,473	159,785	53%
Southwest Chief	60%	853	499	42%	7,866	4,872	38%	285,121	188,467	34%
Sunset Ltd	70%	357	49	86%	2,237	1,005	55%	97,941	39,504	60%
Texas Eagle	70%	892	621	30%	9,469	6,422	32%	335,337	144,740	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000700 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 09, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	58,612	991,622	591	2,058,430	36,265,788	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,649	303,407	87	99,088	10,510,842	94
INFRASTRUCTURE PLANNED	135	5,189	303,407	171	120,735	10,510,842	115
FLEET RELIABILITY	90	8,970	991,622	90	328,515	36,265,788	91
TRAIN OPERATIONS	424	41,804	991,622	422	1,510,092	36,265,788	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/09/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/09/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	39	87.7%	2,820	409	85.5%	103,342	14,377	86.1%
Central Division	86.0%	55	3	94.5%	521	65	87.5%	19,716	1,840	90.7%
East Division	82.0%	178	16	91.0%	1,521	174	88.6%	54,341	8,308	84.7%
West Division	86.0%	84	20	76.2%	778	170	78.1%	29,285	4,229	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/09/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/09/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	39	87.7%	2,820	409	85.5%	103,342	14,377	86.1%
Central Division	86.0%	55	3	94.5%	521	65	87.5%	19,716	1,840	90.7%
CDL	95.0%	2	0	100.0%	18	4	77.8%	654	35	94.6%
CHI	86.0%	25	3	88.0%	243	39	84.0%	9,113	1,139	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	9	1	88.9%	367	39	89.4%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	9	0	100.0%	323	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	18	1	94.4%	666	55	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	53	2	96.2%	2,012	128	93.6%
MOE	97.5%	2	0	100.0%	18	1	94.4%	685	10	98.5%
MSP	96.5%	1	0	100.0%	9	0	100.0%	337	7	97.9%
NOL	94.5%	5	0	100.0%	39	1	97.4%	1,449	65	95.5%
OKC	97.0%	1	0	100.0%	8	0	100.0%	337	6	98.2%
PNT	88.0%	3	0	100.0%	23	2	91.3%	899	75	91.7%
PTH	93.0%	1	0	100.0%	9	0	100.0%	332	13	96.1%
QCY	91.0%	1	0	100.0%	17	1	94.1%	648	49	92.4%
SAS	90.5%	1	0	100.0%	9	1	88.9%	341	40	88.3%
STL	89.0%	3	0	100.0%	34	7	79.4%	1,330	113	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	16	91.0%	1,521	174	88.6%	54,341	8,308	84.7%
ALB	88.5%	8	1	87.5%	69	8	88.4%	2,553	196	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	45	0	100.0%	1,666	175	89.5%
BOS	85.5%	19	6	68.4%	167	13	92.2%	5,872	653	88.9%
BRK	92.5%	5	0	100.0%	45	1	97.8%	1,640	113	93.1%
BTN	82.0%	1	0	100.0%	9	1	88.9%	328	43	86.9%
CLT	91.5%	4	1	75.0%	40	4	90.0%	1,671	171	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	17	2	88.2%	665	62	90.7%
GRO	-	1	0	100.0%	5	2	60.0%	55	13	76.4%
HAR	79.5%	13	2	84.6%	99	14	85.9%	3,806	608	84.0%
HFD	-	2	0	100.0%	12	0	100.0%	244	19	92.2%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	9	1	88.9%	340	41	87.9%

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/09/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/09/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	39	87.7%	2,820	409	85.5%	103,342	14,377	86.1%
East Division	82.0%	178	16	91.0%	1,521	174	88.6%	54,341	8,308	84.7%
MIA	89.5%	2	0	100.0%	18	4	77.8%	676	80	88.2%
MTR	79.0%	1	0	100.0%	9	1	88.9%	327	59	82.0%
NFK	84.5%	2	0	100.0%	18	2	88.9%	763	138	81.9%
NFL	93.5%	2	0	100.0%	18	1	94.4%	692	32	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	43	8	81.4%	1,745	295	83.1%
NPN	93.0%	2	0	100.0%	18	1	94.4%	652	52	92.0%
NYP	75.5%	51	3	94.1%	424	68	84.0%	14,353	3,125	78.2%
PGH	93.0%	1	0	100.0%	9	1	88.9%	341	24	93.0%
PHL	48.0%	5	2	60.0%	42	16	61.9%	1,737	815	53.1%
PIT	76.0%	-	-	-	2	2	0.0%	26	21	19.2%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	26	3	88.5%	1,290	57	95.6%
RNK	83.5%	2	0	100.0%	18	1	94.4%	676	94	86.1%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	9	0	100.0%	323	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	9	0	100.0%	337	12	96.4%
SFA	88.0%	1	0	100.0%	9	2	77.8%	340	49	85.6%
SPG	92.5%	5	0	100.0%	48	1	97.9%	2,010	116	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	9	1	88.9%	329	64	80.5%
WAS	84.0%	33	0	100.0%	275	16	94.2%	8,644	1,090	87.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	84	20	76.2%	778	170	78.1%	29,285	4,229	85.6%
ARN	92.0%	1	0	100.0%	9	1	88.9%	342	29	91.5%
BFD	79.0%	7	2	71.4%	61	19	68.9%	2,174	467	78.5%
EMY	72.0%	1	1	0.0%	9	4	55.6%	358	104	70.9%
EUG	86.5%	2	0	100.0%	17	2	88.2%	677	61	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	26	8	69.2%	1,027	180	82.5%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	8	2	75.0%	85	13	84.7%	3,405	382	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	7	46.2%	104	46	55.8%	3,723	999	73.2%
PDX	86.0%	5	0	100.0%	45	7	84.4%	1,650	232	85.9%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/09/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/09/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	317	39	87.7%	2,820	409	85.5%	103,342	14,377	86.1%
West Division	86.0%	84	20	76.2%	778	170	78.1%	29,285	4,229	85.6%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	2	87.5%	132	21	84.1%	4,851	541	88.8%
SAN	90.5%	5	1	80.0%	94	18	80.9%	4,131	410	90.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	72	14	80.6%	2,625	394	85.0%
SJC	89.0%	7	2	71.4%	63	12	81.0%	2,403	241	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	27	1	96.3%	792	78	90.2%
SNC	-	2	0	100.0%	4	0	100.0%	35	13	62.9%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	9	1	88.9%	321	30	90.7%
VAC	97.0%	2	0	100.0%	18	1	94.4%	671	15	97.8%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		4	1	75.0%	146	13	91.1%	4	1	75.0%	145	42	71.0%
3	41	9	2	77.8%	342	68	80.1%	9	2	77.8%	339	159	53.1%
4	133	9	2	77.8%	341	55	83.9%	9	4	55.6%	341	225	34.0%
5	80	9	1	88.9%	340	58	82.9%	9	3	66.7%	336	114	66.1%
6	178	9	4	55.6%	339	95	72.0%	9	5	44.4%	339	130	61.7%
7		9	0	100.0%	331	51	84.6%	9	0	100.0%	322	86	73.3%
8	59	9	1	88.9%	331	146	55.9%	9	5	44.4%	330	203	38.5%
11		9	3	66.7%	342	75	78.1%	9	1	88.9%	336	68	79.8%
14		9	5	44.4%	343	59	82.8%	9	0	100.0%	340	105	69.1%
19		9	1	88.9%	341	84	75.4%	9	0	100.0%	338	82	75.7%
20		9	0	100.0%	341	23	93.3%	9	1	88.9%	341	66	80.6%
21		9	0	100.0%	338	36	89.3%	9	4	55.6%	337	103	69.4%
22	106	9	1	88.9%	339	38	88.8%	9	8	11.1%	337	107	68.2%
23		9	1	88.9%	343	7	98.0%	9	4	55.6%	341	94	72.4%
24		9	0	100.0%	343	16	95.3%	9	2	77.8%	342	67	80.4%
25		9	0	100.0%	342	3	99.1%	9	0	100.0%	339	94	72.3%
26		9	1	88.9%	342	6	98.2%	9	1	88.9%	339	67	80.2%
27		9	3	66.7%	308	22	92.9%	9	1	88.9%	302	98	67.5%
28		9	1	88.9%	302	68	77.5%	9	1	88.9%	302	61	79.8%
40	223	9	2	77.8%	332	49	85.2%	9	6	33.3%	328	178	45.7%
41	101	9	7	22.2%	332	131	60.5%	9	8	11.1%	329	255	22.5%
42		9	1	88.9%	343	26	92.4%	9	0	100.0%	341	58	83.0%
43	23	9	0	100.0%	342	45	86.8%	9	5	44.4%	341	81	76.2%
48	77	9	0	100.0%	341	62	81.8%	9	4	55.6%	340	55	83.8%
49	95	9	1	88.9%	341	85	75.1%	9	3	66.7%	341	73	78.6%
50	43	4	1	75.0%	139	35	74.8%	4	4	0.0%	137	87	36.5%
52		9	2	77.8%	340	49	85.6%	9	4	55.6%	339	81	76.1%
53	98	9	1	88.9%	340	41	87.9%	9	5	44.4%	339	111	67.3%
55		6	0	100.0%	217	9	95.9%	6	0	100.0%	214	46	78.5%
56		6	0	100.0%	218	25	88.5%	6	4	33.3%	214	44	79.4%
58	165	9	0	100.0%	316	17	94.6%	9	9	0.0%	314	106	66.2%
59	74	9	3	66.7%	315	54	82.9%	9	8	11.1%	310	89	71.3%
63	42	9	2	77.8%	344	146	57.6%	9	9	0.0%	338	206	39.1%
64	22	9	1	88.9%	342	72	78.9%	9	4	55.6%	341	137	59.8%
66		9	1	88.9%	341	65	80.9%	9	2	77.8%	336	62	81.5%
67		6	0	100.0%	236	14	94.1%	6	0	100.0%	235	40	83.0%
68		9	1	88.9%	344	68	80.2%	9	2	77.8%	343	136	60.3%
69	29	9	3	66.7%	331	82	75.2%	9	3	66.7%	326	59	81.9%
71		9	0	100.0%	339	3	99.1%	9	1	88.9%	337	87	74.2%
72		9	1	88.9%	335	37	89.0%	9	1	88.9%	333	70	79.0%
75		9	3	66.7%	332	20	94.0%	9	3	66.7%	326	154	52.8%
76		9	0	100.0%	332	31	90.7%	9	3	66.7%	322	133	58.7%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	43	9	1	88.9%	334	22	93.4%	9	2	77.8%	331	135	59.2%
78		9	2	77.8%	338	31	90.8%	9	2	77.8%	335	77	77.0%
79		9	0	100.0%	341	59	82.7%	9	4	55.6%	339	116	65.8%
80		9	1	88.9%	341	38	88.9%	9	2	77.8%	338	73	78.4%
84		6	0	100.0%	208	19	90.9%	6	1	83.3%	204	49	76.0%
85		6	0	100.0%	219	18	91.8%	6	3	50.0%	219	77	64.8%
86		6	0	100.0%	219	16	92.7%	6	2	66.7%	218	123	43.6%
89		9	1	88.9%	339	79	76.7%	9	4	55.6%	337	101	70.0%
90	98	9	0	100.0%	339	12	96.5%	9	3	66.7%	338	63	81.4%
93		6	0	100.0%	218	21	90.4%	6	4	33.3%	217	59	72.8%
94	43	6	1	83.3%	249	62	75.1%	6	2	66.7%	247	91	63.2%
95		6	1	83.3%	218	7	96.8%	6	4	33.3%	218	86	60.6%
97		9	5	44.4%	341	222	34.9%	9	4	55.6%	339	124	63.4%
98		9	2	77.8%	341	30	91.2%	9	4	55.6%	339	127	62.5%
111		6	0	100.0%	209	37	82.3%	6	0	100.0%	207	22	89.4%
112		6	1	83.3%	209	21	90.0%	6	0	100.0%	208	20	90.4%
113		6	0	100.0%	140	33	76.4%	6	0	100.0%	139	16	88.5%
119		6	1	83.3%	206	50	75.7%	6	0	100.0%	204	26	87.3%
125	32	6	0	100.0%	219	12	94.5%	6	3	50.0%	219	87	60.3%
129		6	1	83.3%	218	51	76.6%	6	1	83.3%	218	31	85.8%
130		6	0	100.0%	209	20	90.4%	6	0	100.0%	207	16	92.3%
131		6	0	100.0%	211	57	73.0%	6	0	100.0%	211	39	81.5%
134		6	0	100.0%	219	32	85.4%	6	0	100.0%	218	42	80.7%
136	18	6	1	83.3%	219	28	87.2%	6	3	50.0%	217	31	85.7%
137	Cncld	6	1	83.3%	216	37	82.9%	5	2	60.0%	215	64	70.2%
138		6	1	83.3%	219	44	79.9%	6	1	83.3%	218	39	82.1%
141		6	1	83.3%	218	5	97.7%	6	1	83.3%	217	38	82.5%
148		6	2	66.7%	218	24	89.0%	6	0	100.0%	216	40	81.5%
151		9	2	77.8%	340	107	68.5%	9	2	77.8%	339	101	70.2%
170		6	0	100.0%	214	12	94.4%	6	0	100.0%	213	30	85.9%
171		6	0	100.0%	219	11	95.0%	6	2	66.7%	219	90	58.9%
172	158	6	0	100.0%	218	19	91.3%	6	3	50.0%	216	72	66.7%
173		6	0	100.0%	211	25	88.2%	6	0	100.0%	210	84	60.0%
174	132	6	0	100.0%	219	23	89.5%	6	2	66.7%	219	54	75.3%
175	No OS	6	1	83.3%	219	24	89.0%	6	3	50.0%	219	73	66.7%
176	20	6	0	100.0%	211	17	91.9%	6	1	83.3%	208	27	87.0%
177	234	6	1	83.3%	219	29	86.8%	6	2	66.7%	219	50	77.2%
178		6	0	100.0%	219	28	87.2%	6	1	83.3%	217	37	82.9%
179	220	6	1	83.3%	219	26	88.1%	6	3	50.0%	218	79	63.8%
181		6	2	66.7%	215	66	69.3%	6	2	66.7%	212	19	91.0%
182	193	6	0	100.0%	209	31	85.2%	6	3	50.0%	207	26	87.4%
183	17	6	1	83.3%	218	63	71.1%	6	1	83.3%	215	45	79.1%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184	56	6	0	100.0%	219	36	83.6%	6	1	83.3%	218	29	86.7%
185		6	2	66.7%	219	43	80.4%	6	0	100.0%	219	18	91.8%
186	45	6	1	83.3%	218	30	86.2%	6	3	50.0%	217	64	70.5%
190		6	3	50.0%	218	78	64.2%	6	0	100.0%	217	44	79.7%
192		6	0	100.0%	216	24	88.9%	6	0	100.0%	216	19	91.2%
193	24	6	2	66.7%	214	85	60.3%	6	3	50.0%	213	93	56.3%
196		6	1	83.3%	215	24	88.8%	6	0	100.0%	213	17	92.0%
197	19	6	1	83.3%	219	78	64.4%	6	4	33.3%	219	75	65.8%
198		6	2	66.7%	151	19	87.4%	6	2	66.7%	150	24	84.0%
230		9	0	100.0%	177	4	97.7%	9	1	88.9%	177	10	94.4%
232		9	1	88.9%	343	13	96.2%	9	1	88.9%	343	24	93.0%
233		7	1	85.7%	302	67	77.8%	7	1	85.7%	301	102	66.1%
234		9	0	100.0%	344	23	93.3%	9	0	100.0%	343	29	91.5%
235		9	1	88.9%	268	43	84.0%	9	1	88.9%	267	61	77.2%
236		9	1	88.9%	328	11	96.6%	9	1	88.9%	327	44	86.5%
237		9	2	77.8%	341	63	81.5%	9	3	66.7%	339	62	81.7%
238		8	1	87.5%	267	24	91.0%	8	1	87.5%	265	23	91.3%
239		9	3	66.7%	342	86	74.9%	9	1	88.9%	341	43	87.4%
240		9	2	77.8%	343	25	92.7%	9	1	88.9%	340	70	79.4%
241	22	9	4	55.6%	343	86	74.9%	8	3	62.5%	342	84	75.4%
243		9	1	88.9%	279	72	74.2%	9	0	100.0%	278	39	86.0%
244	30	7	2	71.4%	301	14	95.3%	7	4	42.9%	301	69	77.1%
245		9	1	88.9%	224	42	81.3%	9	0	100.0%	223	30	86.5%
280		9	0	100.0%	344	17	95.1%	9	2	77.8%	343	80	76.7%
281		9	0	100.0%	344	40	88.4%	9	2	77.8%	344	62	82.0%
283		9	3	66.7%	344	88	74.4%	9	5	44.4%	344	71	79.4%
284		9	1	88.9%	344	14	95.9%	9	3	66.7%	341	64	81.2%
290	17	9	1	88.9%	344	53	84.6%	9	4	55.6%	341	141	58.7%
291		9	1	88.9%	343	113	67.1%	9	2	77.8%	339	92	72.9%
300		8	3	62.5%	326	25	92.3%	7	1	85.7%	322	74	77.0%
301		9	1	88.9%	341	11	96.8%	9	5	44.4%	337	68	79.8%
305		9	3	66.7%	325	34	89.5%	8	5	37.5%	319	127	60.2%
306		9	1	88.9%	339	18	94.7%	9	6	33.3%	337	95	71.8%
311		9	1	88.9%	336	29	91.4%	9	8	11.1%	330	92	72.1%
316	36	9	1	88.9%	332	25	92.5%	9	9	0.0%	326	110	66.3%
318	33	9	0	100.0%	342	35	89.8%	9	8	11.1%	339	174	48.7%
319	107	9	1	88.9%	343	21	93.9%	9	9	0.0%	338	202	40.2%
329		7	1	85.7%	243	13	94.7%	7	1	85.7%	243	20	91.8%
330		8	1	87.5%	292	7	97.6%	8	1	87.5%	292	16	94.5%
331		9	2	77.8%	344	35	89.8%	9	2	77.8%	343	46	86.6%
332		9	1	88.9%	343	20	94.2%	9	2	77.8%	343	48	86.0%
334		9	0	100.0%	344	11	96.8%	9	1	88.9%	342	44	87.1%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		9	0	100.0%	344	35	89.8%	9	0	100.0%	341	55	83.9%
336		9	0	100.0%	343	10	97.1%	9	2	77.8%	341	31	90.9%
337		9	1	88.9%	344	22	93.6%	9	3	66.7%	340	50	85.3%
338		9	0	100.0%	344	54	84.3%	9	2	77.8%	341	106	68.9%
339		9	1	88.9%	344	55	84.0%	9	1	88.9%	344	59	82.8%
341		9	1	88.9%	329	52	84.2%	9	1	88.9%	323	54	83.3%
342		9	0	100.0%	344	26	92.4%	9	2	77.8%	342	63	81.6%
350	28	9	1	88.9%	319	21	93.4%	9	6	33.3%	311	180	42.1%
351		9	1	88.9%	326	30	90.8%	9	4	55.6%	324	96	70.4%
352	25	9	0	100.0%	310	24	92.3%	9	8	11.1%	304	101	66.8%
353		9	1	88.9%	281	15	94.7%	9	3	66.7%	275	52	81.1%
354	71	9	1	88.9%	325	38	88.3%	9	5	44.4%	317	121	61.8%
355		9	4	55.6%	332	41	87.7%	9	4	55.6%	323	123	61.9%
364		9	1	88.9%	333	74	77.8%	9	5	44.4%	327	125	61.8%
365		9	0	100.0%	332	13	96.1%	9	3	66.7%	329	127	61.4%
371		9	0	100.0%	323	11	96.6%	9	2	77.8%	319	32	90.0%
380		9	0	100.0%	325	30	90.8%	9	1	88.9%	324	73	77.5%
383		9	3	66.7%	330	30	90.9%	8	2	75.0%	326	140	57.1%
390	16	9	2	77.8%	325	26	92.0%	8	5	37.5%	322	91	71.7%
391	32	9	0	100.0%	326	14	95.7%	9	7	22.2%	321	95	70.4%
392	21	9	2	77.8%	339	13	96.2%	8	6	25.0%	333	109	67.3%
393	23	9	3	66.7%	343	22	93.6%	8	6	25.0%	338	110	67.5%
417		6	0	100.0%	227	47	79.3%	6	0	100.0%	218	25	88.5%
425		5	0	100.0%	229	7	96.9%	5	0	100.0%	228	7	96.9%
448	65	9	3	66.7%	268	52	80.6%	9	3	66.7%	264	92	65.2%
449	45	9	0	100.0%	265	34	87.2%	9	1	88.9%	265	46	82.6%
470		6	1	83.3%	242	41	83.1%	6	2	66.7%	236	29	87.7%
471		6	0	100.0%	231	14	93.9%	6	0	100.0%	231	6	97.4%
473		6	0	100.0%	238	15	93.7%	6	0	100.0%	235	10	95.7%
474		7	3	57.1%	235	69	70.6%	6	1	83.3%	219	72	67.1%
475		5	0	100.0%	234	8	96.6%	5	0	100.0%	234	16	93.2%
478		6	1	83.3%	230	37	83.9%	6	1	83.3%	228	29	87.3%
479		6	0	100.0%	237	36	84.8%	6	0	100.0%	235	36	84.7%
486		6	1	83.3%	241	36	85.1%	6	0	100.0%	235	61	74.0%
494		6	1	83.3%	244	48	80.3%	6	3	50.0%	236	67	71.6%
495		6	0	100.0%	225	4	98.2%	6	0	100.0%	223	3	98.7%
500		9	1	88.9%	318	17	94.7%	9	1	88.9%	315	37	88.3%
502	30	9	1	88.9%	326	20	93.9%	9	3	66.7%	322	64	80.1%
503	17	9	2	77.8%	340	42	87.6%	8	2	75.0%	332	104	68.7%
504		9	1	88.9%	344	21	93.9%	9	2	77.8%	342	101	70.5%
505		9	2	77.8%	336	45	86.6%	9	5	44.4%	331	96	71.0%
506		9	1	88.9%	339	57	83.2%	8	2	75.0%	330	53	83.9%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507		9	0	100.0%	344	49	85.8%	9	2	77.8%	344	117	66.0%
508		8	1	87.5%	338	44	87.0%	8	1	87.5%	334	82	75.4%
509	18	9	3	66.7%	325	18	94.5%	9	2	77.8%	325	73	77.5%
511		9	1	88.9%	320	26	91.9%	9	1	88.9%	319	54	83.1%
516		9	2	77.8%	335	37	89.0%	9	4	55.6%	334	150	55.1%
517	22	9	0	100.0%	344	8	97.7%	9	3	66.7%	340	153	55.0%
518		9	3	66.7%	344	49	85.8%	9	6	33.3%	342	238	30.4%
519		9	1	88.9%	335	10	97.0%	9	4	55.6%	333	76	77.2%
520		6	1	83.3%	200	30	85.0%	6	1	83.3%	195	12	93.8%
521		6	1	83.3%	238	8	96.6%	6	1	83.3%	237	32	86.5%
522	12	6	2	66.7%	238	45	81.1%	6	1	83.3%	235	25	89.4%
523		6	0	100.0%	238	9	96.2%	6	2	66.7%	237	28	88.2%
524	13	6	1	83.3%	237	18	92.4%	6	2	66.7%	234	29	87.6%
525	11	6	1	83.3%	235	17	92.8%	5	1	80.0%	230	16	93.0%
526		6	2	66.7%	212	43	79.7%	5	0	100.0%	208	18	91.3%
527	11	6	0	100.0%	238	10	95.8%	6	1	83.3%	236	41	82.6%
528		6	0	100.0%	238	19	92.0%	6	1	83.3%	237	33	86.1%
529		6	0	100.0%	238	13	94.5%	6	1	83.3%	237	66	72.2%
530	44	6	2	66.7%	192	20	89.6%	5	1	80.0%	191	39	79.6%
531		6	2	66.7%	212	16	92.5%	6	2	66.7%	212	15	92.9%
532		6	3	50.0%	238	60	74.8%	6	2	66.7%	236	37	84.3%
534	18	6	3	50.0%	197	31	84.3%	6	1	83.3%	194	18	90.7%
535		6	1	83.3%	224	27	87.9%	6	0	100.0%	219	28	87.2%
536		6	3	50.0%	238	67	71.8%	6	1	83.3%	234	42	82.1%
537		6	2	66.7%	207	26	87.4%	6	0	100.0%	201	25	87.6%
538		6	3	50.0%	238	29	87.8%	6	0	100.0%	237	46	80.6%
539		6	0	100.0%	192	28	85.4%	6	2	66.7%	192	84	56.3%
540		6	1	83.3%	237	45	81.0%	6	1	83.3%	227	22	90.3%
541		6	1	83.3%	237	26	89.0%	6	1	83.3%	230	42	81.7%
542		6	1	83.3%	237	26	89.0%	6	2	66.7%	234	43	81.6%
543	50	6	3	50.0%	238	31	87.0%	6	5	16.7%	238	78	67.2%
544		6	0	100.0%	236	22	90.7%	6	0	100.0%	232	22	90.5%
545		6	2	66.7%	238	22	90.8%	6	1	83.3%	235	30	87.2%
547		6	2	66.7%	238	49	79.4%	6	1	83.3%	238	55	76.9%
548		5	0	100.0%	229	22	90.4%	5	1	80.0%	226	18	92.0%
549		6	0	100.0%	233	27	88.4%	6	0	100.0%	223	20	91.0%
550		6	2	66.7%	192	22	88.5%	6	2	66.7%	192	46	76.0%
551		6	0	100.0%	234	23	90.2%	6	0	100.0%	224	23	89.7%
562	37	9	0	100.0%	335	27	91.9%	9	4	55.6%	330	41	87.6%
564		9	0	100.0%	336	19	94.3%	8	2	75.0%	327	45	86.2%
579	17	9	0	100.0%	221	14	93.7%	9	3	66.7%	214	48	77.6%
580	36	9	2	77.8%	336	20	94.0%	9	4	55.6%	329	41	87.5%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591		9	3	66.7%	333	29	91.3%	8	3	62.5%	325	52	84.0%
595		9	5	44.4%	329	65	80.2%	8	1	87.5%	325	74	77.2%
600	14	6	0	100.0%	246	9	96.3%	6	3	50.0%	244	25	89.8%
601		6	1	83.3%	229	91	60.3%	6	1	83.3%	226	28	87.6%
605		6	5	16.7%	236	144	39.0%	5	1	80.0%	231	24	89.6%
607		6	1	83.3%	245	31	87.3%	6	1	83.3%	242	26	89.3%
609		6	1	83.3%	236	24	89.8%	6	0	100.0%	235	23	90.2%
622		5	1	80.0%	142	36	74.6%	5	2	60.0%	139	7	95.0%
626		6	1	83.3%	150	21	86.0%	6	1	83.3%	148	19	87.2%
639		6	1	83.3%	216	41	81.0%	6	1	83.3%	214	21	90.2%
640		6	1	83.3%	236	8	96.6%	6	2	66.7%	234	86	63.2%
641	13	6	1	83.3%	218	44	79.8%	6	5	16.7%	218	32	85.3%
642		6	1	83.3%	234	12	94.9%	6	1	83.3%	233	28	88.0%
643	11	6	1	83.3%	248	45	81.9%	6	2	66.7%	245	41	83.3%
644		6	2	66.7%	240	30	87.5%	6	3	50.0%	238	59	75.2%
645		6	0	100.0%	248	42	83.1%	6	0	100.0%	245	55	77.6%
646	21	6	3	50.0%	237	59	75.1%	6	4	33.3%	235	117	50.2%
647	20	6	2	66.7%	248	37	85.1%	6	2	66.7%	246	53	78.5%
648		6	1	83.3%	244	60	75.4%	6	1	83.3%	244	36	85.2%
649		6	2	66.7%	249	46	81.5%	6	1	83.3%	245	35	85.7%
650	13	6	1	83.3%	248	46	81.5%	6	3	50.0%	245	42	82.9%
651		6	1	83.3%	248	18	92.7%	6	1	83.3%	245	44	82.0%
652		6	0	100.0%	249	31	87.6%	6	2	66.7%	245	43	82.4%
653		6	2	66.7%	237	38	84.0%	6	3	50.0%	233	44	81.1%
654		6	0	100.0%	238	44	81.5%	6	1	83.3%	234	21	91.0%
655		6	3	50.0%	246	77	68.7%	6	2	66.7%	243	78	67.9%
656		6	2	66.7%	248	56	77.4%	6	1	83.3%	246	34	86.2%
657		6	0	100.0%	237	29	87.8%	6	1	83.3%	235	31	86.8%
658		6	0	100.0%	248	37	85.1%	6	0	100.0%	246	35	85.8%
680		7	0	100.0%	244	12	95.1%	7	0	100.0%	242	27	88.8%
681		7	0	100.0%	244	18	92.6%	7	1	85.7%	237	94	60.3%
682		7	1	85.7%	243	10	95.9%	7	0	100.0%	243	42	82.7%
683		7	0	100.0%	226	18	92.0%	7	2	71.4%	225	77	65.8%
684		7	0	100.0%	225	37	83.6%	7	1	85.7%	225	48	78.7%
685	31	7	0	100.0%	240	33	86.3%	7	1	85.7%	237	56	76.4%
686		7	0	100.0%	245	39	84.1%	7	1	85.7%	244	53	78.3%
687		7	0	100.0%	244	38	84.4%	7	0	100.0%	243	40	83.5%
688		7	0	100.0%	243	15	93.8%	7	0	100.0%	242	41	83.1%
701	32	9	1	88.9%	276	31	88.8%	9	2	77.8%	273	34	87.5%
702	18	9	2	77.8%	343	38	88.9%	8	4	50.0%	339	87	74.3%
703	47	9	4	55.6%	344	116	66.3%	9	4	55.6%	342	104	69.6%
704	45	9	2	77.8%	275	51	81.5%	9	4	55.6%	267	63	76.4%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710	62	9	2	77.8%	344	81	76.5%	7	4	42.9%	338	92	72.8%
711	42	9	1	88.9%	335	39	88.4%	9	2	77.8%	312	67	78.5%
712	19	9	4	55.6%	341	95	72.1%	9	5	44.4%	331	119	64.0%
713	45	8	3	62.5%	210	23	89.0%	6	5	16.7%	183	85	53.6%
714	86	9	7	22.2%	225	99	56.0%	8	6	25.0%	208	101	51.4%
715	26	9	2	77.8%	343	65	81.0%	7	5	28.6%	312	160	48.7%
716	77	9	6	33.3%	344	149	56.7%	9	7	22.2%	335	148	55.8%
717		8	3	62.5%	328	82	75.0%	8	5	37.5%	303	103	66.0%
718	31	9	8	11.1%	344	186	45.9%	9	7	22.2%	341	136	60.1%
719	64	9	5	44.4%	344	118	65.7%	8	4	50.0%	326	102	68.7%
757		9	0	100.0%	129	7	94.6%	9	1	88.9%	128	15	88.3%
761		9	1	88.9%	340	14	95.9%	9	1	88.9%	337	45	86.6%
765	16	9	2	77.8%	340	27	92.1%	9	4	55.6%	340	50	85.3%
769	33	9	1	88.9%	340	28	91.8%	9	6	33.3%	333	71	78.7%
770	57	9	2	77.8%	340	27	92.1%	9	5	44.4%	337	109	67.7%
774	55	9	0	100.0%	340	17	95.0%	9	6	33.3%	338	86	74.6%
777	26	9	2	77.8%	225	15	93.3%	9	9	0.0%	224	67	70.1%
782		9	6	33.3%	225	111	50.7%	9	3	66.7%	220	39	82.3%
785	20	9	1	88.9%	340	30	91.2%	9	6	33.3%	340	67	80.3%
786	56	9	1	88.9%	129	24	81.4%	7	5	28.6%	123	71	42.3%
790		9	0	100.0%	340	31	90.9%	8	3	62.5%	336	57	83.0%
794		9	0	100.0%	340	40	88.2%	9	3	66.7%	336	79	76.5%
821	28	8	0	100.0%	337	6	98.2%	8	3	62.5%	337	143	57.6%
822	48	9	1	88.9%	340	19	94.4%	8	6	25.0%	337	176	47.8%
1333	67	9	1	88.9%	340	41	87.9%	9	2	77.8%	337	114	66.2%
1340		9	0	100.0%	339	7	97.9%	9	0	100.0%	338	56	83.4%
1689		4	0	100.0%	115	6	94.8%	4	0	100.0%	114	14	87.7%
2102		6	0	100.0%	95	16	83.2%	6	0	100.0%	94	7	92.6%
2103		6	0	100.0%	159	14	91.2%	6	1	83.3%	158	11	93.0%
2104		6	0	100.0%	185	10	94.6%	5	0	100.0%	182	13	92.9%
2105		6	0	100.0%	7	1	85.7%	6	0	100.0%	7	0	100.0%
2107		5	0	100.0%	215	35	83.7%	5	0	100.0%	212	21	90.1%
2108		6	0	100.0%	216	28	87.0%	6	0	100.0%	210	27	87.1%
2109		6	2	66.7%	109	15	86.2%	6	0	100.0%	107	6	94.4%
2112		6	0	100.0%	56	6	89.3%	6	0	100.0%	54	2	96.3%
2113		6	1	83.3%	95	10	89.5%	6	1	83.3%	95	11	88.4%
2115		6	2	66.7%	95	15	84.2%	5	0	100.0%	93	12	87.1%
2116		6	0	100.0%	56	1	98.2%	6	0	100.0%	56	8	85.7%
2118		6	0	100.0%	56	4	92.9%	6	0	100.0%	56	12	78.6%
2119		6	1	83.3%	56	9	83.9%	6	1	83.3%	55	13	76.4%
2120		6	1	83.3%	56	20	64.3%	6	0	100.0%	54	23	57.4%
2123		6	2	66.7%	94	12	87.2%	6	0	100.0%	93	15	83.9%

Amtrak On Time Performance

Trains Arriving Through: 9/9/2026

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2124		6	0	100.0%	187	38	79.7%	6	0	100.0%	185	24	87.0%
2126		6	0	100.0%	104	26	75.0%	6	0	100.0%	103	22	78.6%
2127		6	0	100.0%	56	10	82.1%	6	0	100.0%	55	9	83.6%
2128		6	1	83.3%	56	5	91.1%	6	0	100.0%	56	3	94.6%
2131		6	0	100.0%	56	10	82.1%	6	0	100.0%	56	6	89.3%
2150		6	0	100.0%	209	22	89.5%	6	0	100.0%	206	75	63.6%
2151		6	0	100.0%	158	7	95.6%	6	3	50.0%	156	44	71.8%
2152		6	0	100.0%	114	7	93.9%	6	0	100.0%	113	31	72.6%
2154	144	6	1	83.3%	117	24	79.5%	5	1	80.0%	112	46	58.9%
2155		6	0	100.0%	218	17	92.2%	6	1	83.3%	214	103	51.9%
2156	168	6	0	100.0%	7	0	100.0%	6	2	66.7%	7	2	71.4%
2158	78	6	0	100.0%	55	6	89.1%	6	1	83.3%	55	17	69.1%
2159		6	1	83.3%	211	17	91.9%	6	2	66.7%	209	71	66.0%
2160	59	6	1	83.3%	56	3	94.6%	6	1	83.3%	55	29	47.3%
2162		6	0	100.0%	217	23	89.4%	6	0	100.0%	211	91	56.9%
2163	22	6	0	100.0%	169	17	89.9%	6	4	33.3%	163	73	55.2%
2165		6	0	100.0%	53	4	92.5%	6	1	83.3%	53	22	58.5%
2167		6	1	83.3%	204	21	89.7%	6	1	83.3%	204	42	79.4%
2171	273	6	1	83.3%	145	11	92.4%	6	2	66.7%	141	25	82.3%
2190		6	0	100.0%	214	29	86.4%	6	0	100.0%	212	24	88.7%
2193	183	5	1	80.0%	208	27	87.0%	5	1	80.0%	206	51	75.2%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2154	BOS	144	TRS	145	TRS	145	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike trk 1 at Sharon Station.
2156	BOS	168	TRS	180	TRS	180	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike trk 1 at Sharon Station.
2158	BOS	78	TRS	80	TRS	39	PVD-RTE	AM	Trespasser strike, Milepost, PVD, RTE, Trespasser strike trk 1 at Sharon Station
2160	BOS	59	TRS	48	TRS	48	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, traffic through the single trk at Sharon a/c trespasser strike at Sharon Sta.
2163	WAS	22	CTI	15	DMW	11	NHV-STM	MN	Waiting for MW clearance Milepost, 54.6, 53.1
2171	WAS	273	TRS	264	TRS	119	BOS-BOS	AM	Trespasser strike, Milepost, bos, bos, Delayed out BOS a/c Trespasser strike trk 1 at Sharon Station.
2193	NYP	183	TRS	152	TRS	107	RTE-RTE	AM	Trespasser strike, Milepost, RTE, RTE, Trespasser strike trk 1 at Sharon Station.
94	BOS	43	TRS	56	TRS	56	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, traffic through the single trk at Sharon a/c trespasser strike at Sharon Sta.
125	NPN	32	CTI	28	CTI	15	ALX-WDB	CS	Follow VRE, 305, Milepost, 104.3, 88.9
136	SPG	18	CON	30	CON	30	NYP-NYP	AM	Hold for connecting train, HELD FOR 10 PSNGRS OFF AM654
137	WAS	Trn Cancelled	SVS	61	SVS	61	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard dropping Geometry cars
172	BOS	158	TRS	146	TRS	146	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike trk 1 at Sharon Station.
174	BOS	132	TRS	123	TRS	77	PVD-PVD	AM	Trespasser strike, Milepost, pvd, pvd, Trespasser strike trk 1 at Sharon Station.
175	WAS	No OS Rpt	TRS	249	TRS	123	RTE-PVD	AM	Trespasser strike, Milepost, rte, pvd, Trespasser strike trk 1 at Sharon Station.
176	BOS	20	SYS	39	SYS	24	NHV-NHV	AM	Re-crew / job briefing, Train stopped to re-crew at Kingston Sta.a/c trespasser strike
177	PHL	234	TRS	142	TRS	113	BBY-RTE	AM	Trespasser strike, Milepost, BBY, RTE, Trespasser strike trk 1 at Sharon Station
179	PHL	220	CCR	136	CCR	136	NHV-BRP	MN	Air / Brake / Wheel 616
182	BOS	193	TRS	194	TRS	165	PVD-RTE	AM	Trespasser strike, Milepost, pvd, rte, Trespasser strike trk 1 at Sharon Station

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/9/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
183	WAS	17	SMW	16	SMW	16	WIL-XPV	AM	Diversions around M/W work, Control Point, Davis - Bacon, Opr No.2 trk a/c No.3 trk o/o/s
184	BOS	56	SYS	63	SYS	59	PVD-RTE	AM	Re-crew / job briefing, Train stopped to re-crew at Kingston Sta.
186	PHL	45	PTI	25	PTI	11	ALX-XVG	CS	Follow 90, Other, alx-xvg
193	WAS	24	SMW	19	SMW	14	WIL-NRK	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Ragan & Davis
197	WAS	19	SMW	16	SMW	16	WIL-XPV	AM	Diversions around M/W work, Milepost, 38.4, 51, opr 1 track a/c 3 track o/s between Ragan & Davis, followed 193
53	SFA	98	FTI	76	ENG	45	XJG-XJX	CS	Undesired emergency application 364
600	NYP	14	DSR	16	SMW	16	PAO-PHL	AM	Scheduled in track usage program, Control Point, ZOO TO JO, 1 TRACK O/S
641	HAR	13	PTI	18	PTI	9	PJC-XHM	AM	Meet, AM183, Other, XH1, AM183 FOULING AT HAM
643	HAR	11	SMW	10	SMW	10	PHL-PAO	AM	Scheduled in track usage program, Control Point, ZOO TO JO, 1 TRACK O/S
646	NYP	21	DMW	11	SMW	11	PAO-PHL	AM	Scheduled in track usage program, Control Point, ZOO TO JO, 1 TRACK O/S
647	HAR	20	CTC	13	CTC	10	XHM-PHL	AM	PTC - Stop Bypass Permission Required, Control Point, PENN, MULTIPLE STOP BYPASS ATTEMPTS NEEDED
650	NYP	13	PTI	14	SMW	11	ARD-PHL	AM	Scheduled in track usage program, Control Point, ZOO TO JO, 1 TRACK O/S
685	BRK	31	DCS	30	DCS	15	WOB-HHL	MT	Restrictive signal(s) from unknown cause 241, Vale, Control Point, vale
63	TWO	42	DSR	11	DSR	7	SYR-XSV	CS	Per bulletin Milepost, 290.8, 296.7, 25, 1
64	NYP	22	FTI	30	FTI	26	SYR-ROM	CS	Follow csx, Milepost, 288, 278
69	MTR	29	CUI	28	CUI	28	XLQ-XLQ	CN	Canada
241	ALB	22	PTI	14	PTI	10	CRT-POU	MN	Follow MNRR, Control Point, 53, Other, POU
244	NYP	30	CTI	24	CTI	18	POU-CRT	MN	Follow mn, Milepost, 55, 35
290	NYP	17	CTI	25	CTI	16	POU-CRT	MN	Follow Followed MN870 all the way to CRT., Metro North, 870, Control Point, CP72
48	NYP	77	DMW	144	DMW	133	ERI-BUF	CS	Hold for defect repair Working on a switch at CP23, Control Point, 23

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/9/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
49	CHI	95	DMW	55	DMW	32	XPI-XH6	NS	Hold for defect repair Bridge problems at CP503. Hick bridge. Dispatcher hold., Bridge, Hick Bridge	
448	BOS	-29	CTI	15	CTI	15	FRA-BBY	MT	Follow Keolis, 580, Control Point, 11, Other, BBY	
449	ALB	45	FTI	17	FTI	17	WOR-WOR	CS	Meet ?, Control Point, 44.4	
43	PGH	23	FTI	21	FTI	21	HAR-HAR	NS	Cross Traffic NS 90T, Control Point, CP-HARRISBURG	
77	CLT	43	DMW	50	DMW	50	DNC-BNC	NS	Held for or routed around MW work or equipment Control Point, mebane	
90	NYP	98	FTI	76	FTI	31	XDJ-ALX	CS	Follow CSX???, Other, CFP77.1	
40	CHI	223	FTI	111	CAR	58	ORL-ORL	FR	Had to have mechanical repair the buffer plate that came off while in route between the dining car and 10 sleeper car 62039	
41	MIA	101	FTI	70	PTI	53	XJG-JAX	CS	Held at Broadhurst Sdg due to P053 going into emergency ahead of us. P053, Siding, Broadhurst	
5	EMY	80	CAR	157	CAR	92	DEN-DEN	RT	Set out defective car 32006, Car in middle of consist, move train to track 5, cut train in half, bring b/o car back to 4 leave deep and go back to track 5 and put train back together.	
6	CHI	178	ENG	130	FTI	41	OSC-OTM	BN	Follow BNSF 5836e, Milepost, 332.0, 316.1, Control Point, Halpin, Control Point, 2888	
522	SAC	12	SVS	16	SVS	16	OKJ-OKJ	UP	Routine inspections Late drop of blue flags in Oakland Mechanical Yard while TASI mechanical finished last minute air test, inspections, etc., Other, Oakland Mechanical Yard	
524	SAC	13	POL	23	POL	23	RIC-MTZ	UP	Fire department hold Mp 14.5	
525	OKJ	11	PTI	15	PTI	15	FFV-SUI	UP	Meet amt 520, Siding, Tolenus	
527	SJC	11	POL	20	POL	20	MTZ-RIC	UP	Fire department hold	
530	SAC	44	DCS	44	DCS	38	SJC-SJC	UP	Restrictive signal(s) from unknown cause Red, Control Point, alameda	
534	SAC	18	TCC	23	TCC	23	OKJ-OKJ	UP	PTC- IETMS recycle breaker to clear fault C8305, PTC screen not showing the depot track selection on the screen. Per UP PTC desk and Amtrak PTC desk they wanted us to reset breaker for PTC	
543	SJC	50	TEN	39	TEN	39	MTZ-RIC	UP	PTC- IETMS recycle breaker to clear fault 965 no com ECU 977 ECU CONVERTER FAULTY, C2102	

Amtrak Endpoint OTP Details

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/9/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
50	NYP	43	FTI	45	FTI	22	ALX-XVG	CS	Meet CSX UNKNOWN, CSX UNKNOWN, Control Point, Slater's Lane, Control Point, Roslyn	
502	SEA	30	POL	20	POL	20	XNI-TAC	ST	RR blocked by trespasser or vehicle strike by another train Instructed to stop short of MP 11.8 Lakewood sub	
503	EUG	17	OTH	16	OTH	12	PDX-ORC	UP	Had to shove north from PDX depot because depot track 3 south was Out of Service and come back into depot 5 to continue south.	
509	PDX	18	PTI	14	PTI	8	OLW-CTL	BN	Meet AMTK 506, Control Point, Wabash	
517	PDX	22	FTI	16	FTI	16	XA4-XTW	BN	Meet BNSF 5971, Control Point, STEWART	
58	CHI	165	DSR	119	MBO	85	XSU-HMD	CC	Drawbridge issues at manchac bridge Bridge, Manchac	
59	NOL	74	DSR	142	DSR	46	MCB-HMD	CC	Per bulletin Milepost, 807.0, 807.1, 40, main, Milepost, 814.3, 814.7, 25, main, Milepost, 839.6, 839.8, 60, main, Milepost, 854.3, 854.5, 10, main, Milepost, 854.4, 856.2, 25, main, Milepost, 823, 849, 40, main	
8	CHI	59	FTI	135	FTI	34	GGW-WPT	BN	Meet BNSF 7544W, Control Point, E Glasgow	
821	FTW	28	DSR	48	DSR	33	GLE-FTW	BN	Per bulletin Milepost, 409.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 404.1, 403.9, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 400.4, 400.2, 60, m, Milepost, 399.8, 399.2, 60, m, Milepost, 397.5, 397.1, 60, m, Milepost, 396.3, 396.2, 30, m, Milepost, 395.5, 395, 60, m, Milepost, 39	
822	OKC	48	DSR	36	DSR	28	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 354.4, 354.5, 10, X Over, Milepost, 355.6, 355.8, 40, 2, Milepost, 357.3, 357.6, 29, 2, Milepost, 361, 361.2, 40, 2, Milepost, 361.4, 361.6, 25, 2, Milepost, 379.5, 380.8, 40, M, Milepost, 382.5, 382.7, 30, M, Milep	
350	PNT	28	PTI	45	PTI	29	XB0-XA5	MI	Meet AMTK353, Control Point, 96 (Albion siding)	
352	PNT	25	DSR	28	PTI	28	ALI-JXN	MI	Meet 355, Control Point, 75	
354	PNT	71	DSR	23	DSR	7	TRM-PNT	CC	Per bulletin Milepost w/Letters, TRM, CP MAL Jct, 30, 1	
562	SAN	37	CTI	15	FTI	11	XRJ-FUL	BN	Meet bnsf 7422, Control Point, santa fe springs	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/9/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
579	LAX	15	CTI	8	CTI	8	FUL-XRJ	BN	Meet mlink, Control Point, soto
580	SNC	36	DCS	26	DCS	26	XFT-ANA	SC	Power switch failure Flagged past signal at CP La Palma and instructed by dispatcher to take switches in hand. Had to wait for Metrolink on other track to pass before it was safe to line our switches., Control Point, La Palma
765	SLO	16	CON	30	CON	30	IRV-IRV	SC	Hold for thruway bus
769	GTA	33	CON	25	CON	25	IRV-IRV	SC	Hold for bus with passengers from train
770	SAN	57	CTI	24	CON	17	OSD-OSD	SN	Hold for thruway bus
774	SAN	55	CTI	31	HLD	10	OSD-OSD	SN	High passenger count Three buses of passengers boarded Amtrak 774.
777	SLO	26	CON	40	CON	40	IRV-IRV	SC	Hold for bus with passengers from train 3 busses from OSD with ADA pax
785	GTA	20	CON	27	CON	27	IRV-IRV	SC	Hold for bus with passengers from train Waiting for buses from OSD to IRV bus bridge.
786	SAN	56	PTI	44	PTI	34	GUA-LPS	UP	Meet 14, Siding, tangaire
701	SAC	32	DCS	37	DCS	37	MDR-MCD	BN	Power switch failure Control Point, CP Planada
702	BFD	18	PTI	22	PTI	12	MOD-TRK	BN	Cross over or go around AMT 711, Siding, Denair
703	SAC	47	FTI	52	FTI	52	SKT-LOD	UP	Blocked from station track Disabled freight train inspecting their train due to hot wheel detector, UP 8601, Control Point, Tomspur
704	BFD	45	FTI	29	DCS	28	WAC-BFD	BN	Power switch failure Line dual control switches for Gomez main 1 to main 1., Control Point, gomez
710	BFD	62	PTI	46	FTI	12	MDR-FNO	BN	Meet BNSF 7291, Siding, Gregg
711	OKJ	42	DCS	45	DCS	26	MDR-MCD	BN	Power switch failure Instructed by dispatcher to take 2 switches into hand, Control Point, planada
712	BFD	19	PTI	28	PTI	18	MOD-TRK	BN	Wait for station track Shuffle with AMT713 E DENAIR., AMT713, Control Point, E DENAIR
713	OKJ	45	FTI	34	FTI	20	HNF-HNF	BN	Meet bnsf 8074, Control Point, mingo

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/9/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
714	BFD	86	TEN	40	TEN	40	TRK-TRK	BN	Failure of diesel engine No load due to Engine Shutdown - Engine Oil Pressure. TASI advised crew to hold train at Turlock/Denair and wait for their technicians to arrive. Crew was able to restore engine by resetting breakers and jack knife switch. Successful Class 2 Brake Test., C2003	
715	OKJ	26	DMW	14	DMW	7	MOD-SKN	BN	15 mph causing delay Milepost, 1098.1, 1098.3	
716	BFD	77	PTI	50	FTI	22	MCD-MDR	BN	Meet Train in ued, bnsf 7670, Control Point, savanna	
718	BFD	31	TSV	29	TSV	29	OKJ-OKJ	UP	Water, commissary, toilet/trash dumping	
719	OKJ	64	PTI	28	DCS	22	ACA-XPR	BN	Power switch failure Control Point, west Pittsburgh	
3	LAX	41	POL	119	POL	119	SNB-SNB	BN	Fire department hold	
4	CHI	133	FTI	131	CTI	49	ABQ-LMY	NM	Meet Nmr, 109 West, NMRX, 105 West, Control Point, E Bernalillo, Control Point, E Herzog	
22	CHI	106	DMW	111	DMW	107	TAY-XOJ	BN	Waiting for MW clearance Milepost, 217.68, 217.98	
390	CHI	16	FTI	14	PTI	6	CHM-RTL	CC	Meet 391, Control Point, lev jct	
391	CDL	32	WTR	25	FTI	16	RTL-CHM	CC	Three way meet Other, champagne yard, U763, P390	
392	CHI	21	WTR	24	FTI	8	CEN-EFG	CC	Cross Traffic east/west bound freight cross in front of of AMTK 392 at kimmundy interlocker. 392 had stop signal to wait for cross traffic to cross., Control Point, kimmundy, Unknown frieght	
393	CDL	23	DSR	29	WTR	9	EFG-CEN	CC	Heat order Milepost, 199.4, 252.2	
316	STL	36	DSR	26	FTI	15	WAR-SED	UP	Meet UP 9592, Siding, Dresden	
318	CHI	33	FTI	42	PTI	21	CRV-SPI	UP	Meet amt 21, Control Point, iles	
319	KCY	107	FTI	86	FTI	56	WAR-LEE	UP	Follow Siding, pleasant hill, 9592	
1333	MSP	67	CAR	58	CAR	58	CHI-CHI	AM	Added a fourth car (34096) because second car (34030) has an HVAC issue. Also, engine 57 was taken off and the train had to be wyed in the yard. 34030	

Amtrak Initial Terminal Details

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/9/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	232	09/09	7	7	Heat / AC 48172, 82997
BOS	137	09/09	61	61	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard dropping Geometry cars
BOS	175	09/09	109	109	Trespasser strike, Milepost, bos, bos, Delayed out BOS a/c Trespasser strike trk 1 at Sharon Station.
BOS	177	09/09	87	87	Service, turn, or wye train, 172, Late turn
BOS	179	09/09	114	114	Service, turn, or wye train, 182, Late turn
BOS	2171	09/09	119	119	Trespasser strike, Milepost, bos, bos, Delayed out BOS a/c Trespasser strike trk 1 at Sharon Station.
BOS	2193	09/09	35	35	Service, turn, or wye train, 2154, Late turn
CLT	78	09/09	12	12	Service, turn, or wye train 77
HAR	626	09/09	2	2	Passenger and/or baggage
HAR	644	09/09	3	3	Passenger and/or baggage, LATE BOARDING PASSENGER
NHV	474	09/09	14	1	Hold for connecting train
NHV	474	09/09	14	13	Hold for connecting train
NHV	474	09/09	14	13	Hold for connecting train
NHV	474	09/09	14	1	Hold for connecting train
NYP	239	09/09	2	2	Passenger and/or baggage, BOARDING
NYP	241	09/09	7	7	Door, 0000, LATE DEPARTURE F/SSYD A/C UNSPECIFIED DOOR ISSUE
NYP	2109	09/09	5	5	HEP, 2130 NG NP, UNSPECIFIED ISSUE WITH PC2130
PHL	185	09/09	15	15	Other late crew, CMS TOLD CREW TO DEADHEAD ON 643
PHL	190	09/09	1	1	Passenger and/or baggage
TWO	64	09/09	1		
CHI	41	09/09	3	3	Service, turn, or wye train 40
CHI	337	09/09	3	3	Re-crew / job briefing New DOB
CHI	1333	09/09	58	58	Added a fourth car (34096) because second car (34030) has an HVAC issue. Also, engine 57 was taken off and the train had to be wyed in the yard. 34030
BFD	701	09/09	1		
BFD	719	09/09	10	10	Water, commissary, toilet/trash dumping Late arrival 710
EMY	6	09/09	8	8	Follow 710 had many passengers and luggage to load., 710, Control Point, Shellmound
GTA	782	09/09	13	6	Meet 765, Control Point, S.Ellwood

Amtrak Initial Terminal Details

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/9/2026

Terminal	Train	Date	Late	Delay	Cause
GTA	782	09/09	13	7	Meet 14, Control Point, S.Ellwood
LAX	4	09/09	33	33	Electrical failure 3447
LAX	14	09/09	2	2	Restrictive signal(s) from unknown cause Track 10, Red , Control Point, terminal
OKJ	522	09/09	16	16	Routine inspections Late drop of blue flags in Oakland Mechanical Yard while TASI mechanical finished last minute air test, inspections, etc., Other, Oakland Mechanical Yard
OKJ	534	09/09	23	23	PTC- IETMS recycle breaker to clear fault C8305, PTC screen not showing the depot track selection on the screen. Per UP PTC desk and Amtrak PTC desk they wanted us to reset breaker for PTC
OKJ	536	09/09	5	5	Fuel
OKJ	710	09/09	6	6	Meet Waited for signal after late arrival of inbound 525, AMTK 525, Control Point, N. Jack London
OKJ	714	09/09	3	3	Restrictive signal(s) from unknown cause Contacted DS 62 for light and lineup., STOP, Control Point, Oakland / Jack London Square Station
OKJ	716	09/09	9	9	Wait for station track amt 534, Other, okj
OKJ	718	09/09	11	11	Service, turn, or wye train 713
SAC	543	09/09	14	14	Service, turn, or wye train 530
SAC	702	09/09	4	4	Air / Brake Error Code: 3586 Automatic Engine Start Improper Setup- Locomotive Brakes are Not Applied (Locomotive brakes were applied without pressure in the cylinder), C2012
SAN	777	09/09	1		
SEA	509	09/09	3	3	Removal of passenger by police Party of 4 decided to spout off racist remarks at another pax (deportation, skin and race) APD officer involved with removal
SEA	516	09/09	5	5	Cross over or go around On TK 206 to leave out lander to get to King Street 5. Held by a Sounder Train coming in. They had difficulty getting into 209. Made it to the station late and had large amounts of bags getting on., Sounder, Other, SEA YARD
SJC	530	09/09	38	38	Restrictive signal(s) from unknown cause Red, Control Point, alameda
SJC	538	09/09	3	3	Mobility Impaired

Eastern Region

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.1	98.7	94.8	342	10
CDOT	95.0	95	91.7	92.4	20	1
MARC	95.0	87.5	91.7	90.2	56	7
SEPTA	95.0	84.4	92.2	91.5	199	31
NJT-NED	95.0	92.2	94.2	88.6	359	28
NJT-SED	95.0	95.8	98.6	97.2	24	1

Operating Highlights

Train 90(09) South of Woodbridge, VA - Freight Train Interference

09SEP26: Train 90(09) operating with engine 61 and 186 customers was delayed south of Woodbridge, VA on the CSX RFP subdivision following CSX freight from milepost 75.7 until milepost 89.1.

Train	Delay	Comment
90 (09)	31"	

Train 77(09) West of Durham, NC - M of W Work

09SEP26: Train 77(09) operating with engines NC1869, NC102, and 64 customers onboard was delayed 23 miles west of Durham, NC on the Norfolk Southern H Line holding at milepost 31.9 for maintenance of way to finish their work ahead before the train could proceed.

Train	Delay	Comment
77 (09)	50"	

Train 97(09) Washington D.C. - Engine Failure

10SEP26: Train 97(09) operating with engines 38, 121, and 186 customers onboard was delayed departing Washington D.C. due to original engine 39 having a broken main res pipe in S&I causing a replacement engine to be needed.

Train	Delay	Comment
97 (09)	41"	

Train 137(09) Boston, MA - Disabled Train Ahead

09SEP26: Train 137(09) operating with locomotive 626, 2 cars and 206 customers was delayed at the initial terminal of Boston due to operating to the yard after train 19(09) arrived Boston to remove 2 geometry cars from the consist. Once the cars were removed the equipment was position back in the station.

Train 137(09) was further delayed due to MBTA MT840 reporting a traction motor fire at Ruggles Station. APD requested a hold on all tracks and ET personnel to respond. ET was able to sectionalize the power and restore track No.3 to service allowing train 137(09) to resume.

Train	Delay	Comment
137(09)	1'01"	

CSX Heat Order - Weather

09SEP26: CSX has imposed heat orders in affect between 1pm and 7pm for the following subdivisions: Peninsula, Richmond Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, North End, Sanford and Tampa Terminal.

Train	Delay	Comment
41(07)	36"	
41(08)	07"	
40(07)	46"	
97(08)	26"	
52(09)	11"	
40(09)	50"	
53(09)	13"	
79(09)	06"	
80(09)	16"	
89(09)	09"	
90(09)	04"	
95(09)	05"	
98(09)	13"	
138(09)	06"	
186(09)	11"	

Train 51(09) Philadelphia, PA - Engine Failure

09SEP26: Train 51(09) operating with locomotive 602, 5 cars and 59 customers was delayed at Philadelphia after reports of ACSES issues with locomotive 602. Philadelphia mechanical met the train and was able to resolve the issue and train 51(09) was able to depart without restrictions.

At Wilmington the crew reported further ACSES issues with locomotive 602. The crew contacted mechanical and were able to resolve the issue and proceed without further delay.

Multiple trains were delayed due to train 51(09) occupying Wilmington station while receiving assistance from mechanical.

Train	Delay	Comment
51(09)	13"	PHL
51(09)	12"	WIL
2107(09)	15"	
183(09)	09"	
79(09)	06"	

Train 53(08) South of Jacksonville, FL - Signal

09SEP26: Train 53(08) operating with locomotives 364-317, 16 passenger cars, 20 auto carriers and 339 customers was delayed 2 miles south of Jacksonville at MP 642 on the CSX Sanford subdivision due to needing to hand line switches at Moncrief. Once the crew was able to line the route train 53(08) was able to resume normal operations.

Additionally, trains 41(07) and 97(08) were delayed at the same location resulting from signal delays and hand lining switches at Moncrief.

Train	Delay	Comment
53(08)	33"	
41(07)	43"	
97(08)	29"	

Train 53(08) South of Jesup, GA - Engine Failure

09SEP26: Train 53(08) operating with locomotives 364-317, 16 passenger cars, 20 auto carriers and 339 customers onboard was delayed 30 miles south of Jessup, GA at MP 578 on the CSX Nahunta subdivision after the train went into an undesired emergency brake application. Once stopped the crew inspected the equipment and found no defects or cause for the brake application, performed a brake test and were able to resume operations. After returning to normal operations the train was further delayed following CSX I031-08.

Additionally, train 41(07) was delayed by train 53(08) as they caught up to and followed from Broadhurst to Sanford.

Train	Delay	Comment
53(08)	45"	
41(07)	53"	PTI

Train 137(09) West of Route 128, MA - Trespasser Incident

09SEP26: Train 137(09) terminated at location 626, 9/18/2028 26-FOI-00731 00000008780 UNCLASSIFIED
struck a trespasser 7 miles west of Route 128 at MP 210 on the Amtrak NHB Line. This incident did result in a fatality and occurred in the town of Sharon, MA in Norfolk County. The weather was 76 degrees and partly cloudy at the time of the strike. There were no reported injuries to crew on customers onboard and no damage to infrastructure or equipment was noted. The crew did request relief from the scene and protect crews were dispatched from Boston to recrew at location. Amtrak management including Superintendent of Transportation and Road Foreman responded to the scene to assist in expediting the release of the train and the incident location.

Trains 172(09), 2154(09) and 182(09) were held west of the location for an open route and trains 175(09) and 2171(09) were held in Boston prior to departure for an open route.

The late operations of trains 172(09) resulted in a late initial terminal of train 177(09), 2154(09) resulted in a late initial terminal to train 2193(09) and 182(09) resulted in a late initial terminal to train 179(09).

Train 137(09) terminated at X-point XJC and was cancelled to Washington D.C. The equipment deadheaded to New York and train 172(10) originated New York.

National Response Center Number: 1473162

Train	Delay	Comment
137(09)		TERM XJC
67(09)	1'55"	
172(09)	2'26"	
175(09)	4'09"	
177(09)	1'53"	
182(09)	3'14"	
2154(09)	2'25"	
2156(09)	3'00"	
2171(09)	4'24"	
2193(09)	2'01"	
2158(09)	1'21"	
174(09)	2'03"	
184(09)	59"	
179(09)	1'54"	
94(09)	56"	
2160(09)	48"	

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

- Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.
- Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.
- Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.
- Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.
- Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.
- Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.
- Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.
- Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.
- Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.
- Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.
- Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.
- Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.
- Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77 (03)	50"	
78 (03)	50"	Turn of Late 77 (03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B00000008780 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 00000008780 in "UNCLASSIFIED" open 9/18/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train 786(09) Lompoc-Surf, CA - Passenger Train Interference

10SEP26: Train 786(09) was delayed at Tangair siding/MP293.6 5.5 miles south of Lompoc-Surf, CA/MP299.2 on the UP Santa Barbara subdivision due to meeting Train 14(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(09)	34"	

Train 703(09) North of Stockton, CA - Freight Train Interference

10SEP26: Train 703(09) was delayed north of Stockton, CA at MP77.1 on the UPRR Fresno Subdivision, due to meeting UP8601 that stopped to inspect their train due to a hot wheel detector. Once train was inspected, and a route was clear, Train 703(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(09)	52"	

Train 6(09) Winnemucca, NV - Passenger Related

10SEP26: Train 6(09) was delayed at Winnemucca, NV holding for a passenger arriving in an Uber, that was left behind at Reno, NV after stepping off the train and missing the all aboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(09)	30"	

Train 40(08) East of Alliance, OH - Flash Flood Warnings

10SEP26: Train 40(08) was delayed beginning at MP10, 80.2 miles east of Alliance OH station on the Norfolk Southern Fort Wayne Pit subdivision operating through flash flood warnings. Train 40(08) operated through the flash flood warnings until MP31.2.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(08)	36"	

Train 6(09) Elko, NV - Freight Train Interference

10SEP26: Train 6(09) was delayed at Elko, NV station/MP557 on the URRR Subdivision due to meeting freight unit UP5706 setting out two engines ahead. Once a route was clear, Train 6(09) was able to depart taking an additional delay following the freight to MP604.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(09)	53"	
6(09)	45"	Following UP5706

Train 319(09) East of Lees Summit, MO - Freight Train Interference

09SEP26: Train 319(09) was delayed departing Lees Summit station/MP259.9 on the UPRR Sedalia meeting and following UPRR freight train 9592. Train 319(09) resumed operating track speed upon departing Lees Summit station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(09)	56"	

Train 25(09) North of Pascagoula, MS - Freight Train Interference

09SEP26: Train 25(09) was delayed holding at MP700.9, 5.75 miles north of Pascagoula MS station on the CSX NO and M subdivision for a meet with CSX freight train M602(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(09)	31"	

Train 21(08) McGregor, TX - Freight Train Interference

09SEP26: Train 21(08) was delayed holding in the Clifton siding/MP270.8, 28.28 north of McGregor TX station on the BNSF Fort Worth subdivision for a meet with Norfolk Southern freight train 4543.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(08)	34"	

Train 4(09) Los Angeles, CA - Car Failure

09SEP26: Train 4(09) was delayed departing Los Angeles, CA due to a late mechanical release from the yard. Car C/3447 was bad ordered for electrical failure and needed to be replaced. Once the cars were swapped out and train made complete, 4(09) was released to the station to load 106 passengers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(09)	33"	

Train 543(09) Martinez, CA - Third Party Contractor Engine Failure

09SEP26: Train 543(09) E/C2102, 4 CARS, CC/C8314, and 75 passengers onboard, was delayed 8.3 miles west of Martinez, CA at MP 23.1 on the UPRR Martinez subdivision account of the engine shutting down with no head-end power (HEP). The weather was a reported 101 degrees and sunny. Crew worked with an Amtrak Road Foreman and mechanical team to troubleshoot the engine faults. The crew was able to recycle the breaker, which cleared the faults and restored HEP. Once all safety checks were complete, Train 543(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
543(09)	39"	

Train 714(09) Turlock-Denair, CA - Third Party Contractor Engine Failure

09SEP26: Train 714(09) 26-FC-00731 00000008780, E/32003 and 4/18/2026 passengers onboard, was delayed at Turlock-Denair, CA station MP1079.5 on the BNSF Stockton Subdivision, account of the engine shutting down with an oil pressure fault and no head-end power (HEP). The weather was a reported 98 degrees and sunny. Crew worked with an Amtrak Road Foreman and mechanical team to troubleshoot the issue. The crew was able to restore the engine by resetting breakers which restored HEP. Once all safety checks were complete, Train 714(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(09)	40"	

Train 8/28(08) East of Havre, MT - Occupied Vehicle Strike

09SEP26: At 2:02 PM-MT, Train 8/28(08) operating with engines 325, 316, 10 cars, and 176 customers fatally struck an occupied vehicle at milepost 388.5, 42 miles east of Havre, MT on the BNSF Milk River subdivision. The strike occurred at DOTX 059431J. The crossing was equipped with crossbucks and signs or signals. The train maintained head end power and was intact on the rails. There were no reported injuries to the crew or customers. The weather was 77 degrees. The vehicle was stuck on the front of the equipment. Emergency services and road foreman responded to the scene. The crew requested relief, then agreed to take the train into Minot, ND. Once the vehicle was removed and investigation complete, the train was released to proceed. Train 7/27(08) was also delayed due to this, held at Dodson/MP359.3.

Upon departure, the crew reported a speedometer issue on engine E/325 from sustained damage from the strike, and were unable to operate with PTC. The crew was able to proceed with permission to operate from the BNSF host railroad, with PTC cut out causing additional delays operating at reduced speed. After discussion with the mechanical team, the decision was made to set out engine E/325 at Minot, ND and source a BNSF freight to add. BNSF 6662 was identified to be added to the train. Once the move was complete, Train 8/28(08) was able to proceed operating at freight speeds.

National Response Center Number: 1473174

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(08)	2'28"	
7/27(08)	1'48"	
8/28(08)	34"	Add Freight MOT
8/28(08)	44"	W/MOT- Operating reduced speeds

Train 11(08) Sacramento, CA - Servicing

09SEP26: Train 11(08) operating with engines 329, 313, 9 cars, and 197 customers onboard was delayed departing Sacramento, CA on the UPRR Martinez subdivision due to being serviced in the station. Once all servicing was completed, Train 11(08) departed Sacramento at 6:48 AM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(08)	30"	

Train 530(09) San Jose, CA - Initial Terminal Delay - Signal

09SEP26: Train 530(09) operating with CDTX, 4 cars, CDTX2102, and 19 customers onboard was delayed departing San Jose, CA on the UPRR Coast subdivision due to restrictive signals due to unknown causes. Once the train received a more favorable signal, Train 530(09) departed the station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

BNSF Stockton Subdivision Power Switch Failure East of Merced, CA - Switch Failure

09SEP26: At 10:43 AM-26-FOI-00734F 00000008780 UNCLASSIFIED 19/18/2026 between the dispatcher and control point Planada, milepost 1047.1, 8 miles east of Merced, CA on the BNSF Stockton subdivision. The failure in communication resulted in power switch failure. Trains operating through the area experienced delayed due to having to hand throw the switches. BNSF signal department responded to the scene and was able to rectify the issue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
711 (09)	26"	
701 (09)	39"	
702 (09)	16"	

Train 1333(09) Chicago, IL - Servicing

09SEP26: Train 1333(09) was delayed departing the Chicago, IL Union Station do to adding car 34096 account shopping car 34030 for HVAC failure. Also, the train needed to operate around the wye account of shopping 57 account of preventive maintenance requirements. There were no replacements.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(09)	58"	

Train 19(08) South of Birmingham, AL - Freight Train Interference

09SEP26: Train 19(08) was delayed between Vance / MP AGS174.8 and Coaling / MP AGS185.3 on the Norfolk Southern AGS South District, starting 31 miles south of the Birmingham, AL station, following 29S-09.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(08)	50"	

Canadian National McComb Subdivision from McComb, MS to Hammond, LA - Temporary Speed Restrictions

09SEP26: Canadian National placed several speed restrictions between McComb, MS / MP 806.9 and Hammond, LA / MP 859.1 on the McComb Subdivision.

Train 59(08) and Train 59(09) were delayed as a result of the speed restrictions

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(08)	46"	
58(09)	31"	

Train 318(09) St. Louis, MO - Engine HVAC Failure

09SEP26: Train 318(09), operating with Locomotive ID4629 and 7 cars, reported no HVAC in Locomotive ID4629. The crew was willing to operate without HVAC between Kansas City and St. Louis, account morning temperatures were comfortable. With temperatures expected to reach above 90°F later in the day, the decision was made to set out lead Locomotive 311 from Train 22(08)/422(06) in St. Louis to add onto the train.

In addition to setting out Locomotive 311, Train 22(08)/422(06) had a previous move of adding the local coach Car 31008 and deadhead Car 35005.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(08)/422(06)	52"	STL
318(09)	11"	STL

Train 3(07) San Bernardino, CA - Police Related

09SEP26: Train 3(07) 26-FOI-00731 00000008780 UNCLASSIFIED 39, 9/18/2026, and 109 customers onboard was delayed departing San Berardino, CA on the BNSF San Bernardino subdivision due to UPRR freight train 8191 reported to be on fire in multiple spots. The fire department responded and extinguished the fire. Once the fire was out and the tracks were released, Train 3(07) advanced to the next station.

Train	Delay	Comment
3(07)	1'59"	

Train 48/448(08) West of Buffalo, NY - M of W Work

09SEP26: Train 48 / 448(08) was delayed at CP37 / MP QD37.1 on the Chessie, Seaboard and X Subdivision, 42 miles west of the Buffalo - Depew, NY station, waiting on CSX MoW to clear after replacing a switch.

Train	Delay	Comment
48/448(08)	2'13"	

Train 6(07) East of Omaha, NE - Weather

09SEP26: Train 6(07) was delayed between the Omaha, NE station / MP 16.7 and MP 3.0 on the Burlington Northern Santa Fe Omaha Subdivision, account of flash flood warnings.

Train	Delay	Comment
6(07)	33"	

Train 765(09) North of Goleta, CA - Loss of Shunt

09SEP26: Union Pacific Railroad advised that train 765(09) operating with E/C2110, C/34981, C/6805, C/C6352, C/6413, C/C6464, and CC/6903 experienced a loss of shunt on September 9th, 2026 at 12:37:24 PM-PST. This occurred north of Goleta, CA station at MP 355.72 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 34 seconds. UPRR signal department was notified, and shunt testing will be performed.

Train 765(08) North of Goleta, CA - Loss of Shunt

09SEP26: Union Pacific Railroad advised that train 765(08) operating with E/C2122, C/34951, C/6807, C/C6301, C/6406, C/C6453, and CC/6907 experienced a loss of shunt on September 8th, 2026 at 2:43:30 PM PST. This occurred north of Goleta, CA station at Ellwood/ MP 355.81 on the Union Pacific Santa Barbara subdivision. This loss of shunt lasted for 893 seconds. UPRR signal department was notified, and shunt testing will be performed.

Midwest Service Adjustments Chicago, IL - Engine Failure

08SEP26: Due to locomotive availability issues, the following trains were cancelled in their entirety with customer service working to source alternate transportation:

Lincoln Service: 307(08), 302(09), 301(10), and 306(10). Three buses were confirmed for 307(08). Four buses were confirmed for 302(09).

Pere Marquette: 370(09), 371(10), 370(11), and 371(12). Two buses were confirmed for 370(09). Two buses were confirmed for 370(11). Two buses were confirmed for 371(10).

Carl Sandburg: 381(09), 382(09), 381(11), and 382(11). One bus was confirmed for 381(09). One bus was confirmed for 381(11). One bus confirmed for 382(09).

Wolverine: 350(10) and 355(10). Two buses were confirmed for 350(10).

WBS#: B.TR.100150.7158

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

05SEP26: High tides along the Southern California coast caused track indication issues between San Clemente Pier (MP 204.8) and CP SONGS (MP 209.5) on the Metrolink Orange Subdivision, requiring trains to operate at restricted speed and flag through the affected territory. Metrolink personnel conducted track inspections following each train movement through the area, resulting in significant congestion and delays to Pacific Surfliner service.

The incident resulted in the following service impacts and recovery actions:

- Train 581(05), carrying 244 customers onboard, was delayed at CP SONGS (MP 209.5) while awaiting authorization to proceed through the affected territory under restricted-speed conditions.

- Train 580(05), carrying 373 customers onboard, was delayed at San Clemente Pier Station (MP 204.9) before proceeding through the area under flag protection.

- Train 785(05), carrying 374 customers onboard, was delayed at CP SONGS while awaiting the passage of Train 580(05) before proceeding toward San Clemente Pier.

- Train 587(05), carrying 410 customers onboard, was delayed at CP SONGS while awaiting track inspections and clearance through the affected territory.

- Train 782(05), carrying 411 customers onboard, was delayed at CP Serra (MP 199.7) pending clearance through the affected territory.

- Train 584(05), carrying 167 customers onboard, was delayed at CP Serra after initially holding near Trabuco (MP 195.5).

- Train 588(05), carrying 106 customers onboard, experienced delays approaching the affected territory.

- Train 591(05) experienced delays approaching and departing Oceanside, CA, due to congestion created by the restricted operations.

- Train 786(05) encountered downstream delays while operating south toward the affected territory.

To mitigate customer impacts, the following service adjustments were implemented:

- Train 584(05) was terminated at San Juan Capistrano, CA, with customers accommodated on Train 588(05).

- Train 786(05) was terminated at Irvine, CA, after customers detrained at Laguna Niguel/Mission Viejo Station and were accommodated on Train 790(05).

- Train 593(05) was canceled, with customers accommodated on Train 595(05).

- Train 595(05) operated late after turning from the delayed Train 782(05).

- Equipment from Trains 584(05) and 786(05) was returned to Los Angeles, CA.

Additional service adjustments for Pacific Surfliner for 9/6

Trains 566(06), 567(06), 572(06), 573(06), 581(06), 584(06), 588(06), 587(06), 593(06) are canceled entirely with customers to next available services.

Train 782(06) is canceled LAX-SAN, customers to next services.

Train 761(06) is canceled SAN-LAX, customers to next services.

Train 794(06) is canceled LAX-SAN with alternate bus 3594 transportation.

Train 579(06) will orig IRV.

the following trains will operate a bus bridge between Oceanside (OSD) and Irvine (IRV): 765(06), 562(06), 777(06), 774(06), 591(06), 790(06), 769(06), 770(06), 785(06), 786(06).

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

6 buses were confirmed for bus bridge segment, and 2-buses for 3594 on both Sunday 9/6 and Monday 9/7.

07SEP26: Pacific Surfliner service resumed normal operations on September 7, 2026. All trains returned to the standard operating plan, with the exception of Train 567(07), due to only three trainsets being available in San Diego, CA.

The following service adjustments were implemented:

- Train 567(07) was canceled, with customers accommodated on Train 769(07).
- Equipment from Los Angeles 8th Street Yard was utilized to operate Train 572(07).

07SEP26: Tracks east of San Clemente Pier, CA, were reopened for service on September 8, 2026; however, high tides later caused washout conditions and recurring signal issues between San Clemente Pier and CP SONGS on the Metrolink Orange Subdivision. Metrolink personnel responded to replace ballast and conduct ongoing inspections of the affected track structure. As a result, Pacific Surfliner trains were required to operate at restricted speeds through the area, causing delays and congestion throughout the corridor.

The incident resulted in the following service impacts and recovery actions:

- Train 579(07), carrying 382 customers onboard, was delayed at Oceanside, CA, while maintenance personnel repaired the affected track. After departing Oceanside, the train incurred additional delays while holding at CP SONGS pending authorization to proceed through the affected territory.
- Train 581(07), carrying 364 customers onboard, was delayed at Oceanside, CA, while awaiting the reopening of the route.
- Train 782(07), carrying 405 customers onboard, was the last train authorized through the affected territory before Metrolink suspended train movements due to worsening tide conditions.
- Train 584(07), carrying 128 customers onboard, was held at Irvine, CA.
- Train 786(07), carrying 258 customers onboard, was held at Santa Ana, CA.
- Train 587(07), carrying 434 customers onboard, was held at Oceanside, CA.
- Train 588(07) was held at Los Angeles, CA.
- Train 591(07) was held at San Diego, CA.

To mitigate customer impacts, the following service adjustments were implemented:

- Trains 591(07), 593(07), and 595(07) were canceled.
- Trains 588(07) and 790(07) were canceled between Los Angeles and San Diego.
- Train 794(07) operated between Los Angeles and Irvine, where it terminated.
- Seven buses were secured to transport customers from Train 587(07) from Oceanside to Irvine.
- The same buses were then utilized to transport customers from Trains 584(07) and 786(07) from Irvine to San Diego, making all intermediate station stops.
- The buses were also used to accommodate customers from the canceled Trains 591(07), 593(07), and 595(07).
- Three additional buses were secured for customers requiring transportation south of Irvine from Trains 790(07) and 794(07).

08SEP2026: Pacific Surfliner Service Adjustments for Tuesday, September 8th and September 9th:

Trains 566, 567, 572, 573, 581, 584, 588, 587, 593(08, 09, 10, 11) are cancelled entirely. Customers will need to book next available services.

Train 782 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, Customers to next available services.

Train 761 (08, 09, 10, 11) cancelled San Diego-Los Angeles, CA, Customers to next available services.

Train 794 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, with alternate BUS

Train 580 (08, 09, 10, 11), will terminate in San Juan Capistrano, CA.
 Train 579 (08, 09, 10, 11), will originate in San Juan Capistrano, CA.
 Trains 765, 562, 777, 774, 591, 790, 769, 770, 785, 786(08, 09, 10, 11) will operate a
 Bus Bridge between Occidental and Irvine Stations. (**Please note: Trains will operate
 TO AND SERVICE San Juan Capistrano (SNC) Station- WILL THEN TURN AND MEET BUS BRIDGE AT
 IRVINE STATION**).

Initially, there were 3 buses providing alternate transportation between Irvine, CA and
 San Juan Capistrano. Two additional buses were secured account of the high ridership.

WBS#: B.TR.100150.7150

Train	Delay	Comment
584(05)	Term SNC	
786(05)	Term IRV	
593(05)	Canceled	
785(05)	50"	
587(05)	2'19"	
584(05)	52"	
591(05)	24"	late turn of 580
591(05)	2'17"	
782(05)	3'35"	
588(05)	2'52"	
790(05)	2'11"	
595(05)	2'36"	late turn of 782
567(06)	Canceled	
572(06)	Canceled	
566(06)	Canceled	
573(06)	Canceled	
581(06)	Canceled	
584(06)	Canceled	
588(06)	Canceled	
587(06)	Canceled	
593(06)	Canceled	
782(06)	Canceled LAX-SAN	
761(06)	Canceled SAN--LAX	
794(06)	Canceled LAX-SAN	
564(06)	Term IRV	
595(06)	Orig IRV	
580(06)	Term IRV	
579(06)	Orig IRV	
765(06)	Bus Bridge OSD-IRV	
562(06)	Bus Bridge OSD-IRV	
777(06)	Bus Bridge OSD-IRV	
774(06)	Bus Bridge OSD-IRV	
591(06)	Bus Bridge OSD-IRV	
790(06)	Bus Bridge OSD-IRV	
769(06)	Bus Bridge OSD-IRV	
770(06)	Bus Bridge OSD-IRV	
785(06)	Bus Bridge OSD-IRV	
786(06)	Bus Bridge OSD-IRV	
567(07)	Canceled	
581(07)	1'01"	
579(07)	1'50"	
782(07)	2'24"	
584(07)	41"	late turn 579
584(07)	Term IRV	
786(07)	Term IRV	
587(07)	3'47"	Bus Bridge OSD-IRV
588(07)	Canceled	
591(07)	Canceled	
593(07)	Canceled	
790(07)	Term LAX	
595(07)	Canceled	
794(07)	Term IRV	
785(07)	58"	
769(08)	32"	IRV Bus Connect
770(08)	36"	OSD Bus Connect
765(08)	19"	IRV Bus Connect
765(09)	30"	IRV for bus connections
769(09)	25"	IRV Bus connects
770(09)	17"	OSD bus connects
777(09)	42"	OSD Bus Connect

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

26-0102731 9/18/2026 UNCLASSIFIED 9/18/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 009000087801"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Delivered to LAX 8 th st yrd 402am ET 9/10/26
8 (8)	MOT	325		Strike DMG//brake pipe//PTC

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (7)	EMY	UP5727	Dynamic brake	CHI	9/9/26
8 (8)	MOT	UP6662	E/325 strike DMG		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 509(09) Passenger Removal at Seattle, Washington –Intoxication

09SEP26, Passenger on PNR D82BC9, traveling from Seattle, WA to Portland, OR was removed from the train by Amtrak Police Sargent. The passengers were intoxicated on the train. The passengers had slurred speech and were loud and using profanity on the train. Amtrak Police notified.

Delay: 509 (09) 03"

Train 517(09) Passenger Removal at Tacoma, Washington –Medical

09SEP26, Passenger on PNR F38A91, traveling from Tukwila, WA to Portland, OR was removed from the train by Tacoma FD. The passenger complained of dizziness. Amtrak Police notified.

Delay: 517 (09) 09"

Consist Deviations

26-FOI-00731

00000008780

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
137 (09)	BOS	Club dinette in lieu of all table car	No impact	0	48179
59 (09)	CHI	Operating with diner in lieu of lounge.			38066
6 (10)	EMY	Operating with standard coach in lieu of baggage coach. Inventory was increased to reflect changes.			34052
646 (09)	HAR	NO CAB CAR NO WIFI	passnengers notified no wifi	0	633
4 (09)	LAX	Operating with standard coach in lieu of baggage coach. Inventory was increased to reflect changes.			34047
655 (09)	NYP	No cab car or cafe car to provide wifi. Extra coach was added for ridership.	No impact	0	633
605 (09)	PHL	NO CAB CAR NO WIFI	passnengers notified no wifi	0	633
190 (09)	PHL	Club dinette in lieu of all table car	No impact	0	48179

Reverse Consists

Train Number	Station	Reason
95 (09)	BOS	Consist reversed Business class seat orientation may have changed At Front
178 (09)	RNK	Consist reversed Business class seat orientation may have changed At Front
138 (09)	NFK	Consist reversed Business class seat orientation may have changed At Front
449 (09)	BOS	bos b/o amii 25082 hvac and replaced with ami 82978
190 (09)	PHL	Consist reversed Business class seat orientation may have changed At Front
136 (09)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (10)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 125(10)**
94 (10)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 94(10)**