

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, March 15, 2026

Rules: 0-19



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 03/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/14/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	274	46	83.2%	4,101	598	85.4%	48,036	7,011	85.4%
Central Division	85.5%	63	7	88.9%	933	83	91.1%	10,802	1,196	88.9%
Northeast Division	80.0%	82	20	75.6%	1,214	197	83.8%	14,949	2,590	82.7%
Southeast Division	72.5%	62	11	82.3%	1,001	184	81.6%	11,131	1,747	84.3%
Southwest Division	77.0%	67	8	88.1%	953	134	85.9%	11,154	1,478	86.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00361 00000006087 UNCLASSIFIED 4/29/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	94,909	23,530	75%	1,284,559	335,644	74%	15,380,497	3,644,500	76%
Northeast Corridor	81%	40,411	10,728	73%	578,182	161,968	72%	6,831,089	1,671,937	76%
Acela	83%	5,117	1,403	73%	88,120	21,852	75%	1,338,579	373,004	72%
Northeast Regional	79%	35,294	9,325	74%	490,062	140,116	71%	5,492,510	1,298,933	76%
Richmond / Newport News / Norfolk	77%	11,690	3,374	71%	162,876	51,179	69%	1,748,249	458,416	74%
Springfield Shuttles	89%	761	175	77%	10,083	1,869	81%	86,146	12,091	86%
Roanoke	79%	2,844	1,217	57%	38,858	13,459	65%	513,779	100,924	80%
On Spine Northeast Regional	80%	19,999	4,559	77%	278,245	73,609	74%	3,144,336	727,502	77%
State Supported	80%	42,099	8,381	80%	542,466	111,985	79%	6,612,166	1,314,536	80%
Borealis	60%	615	502	18%	7,655	1,099	86%	87,484	19,986	77%
Capitol Corridor	90%	2,782	856	69%	51,664	10,101	80%	574,766	70,478	88%
Carolinian	60%	1,345	48	96%	17,726	6,035	66%	181,571	53,889	70%
Cascades	63%	789	301	62%	28,749	5,659	80%	379,723	88,997	77%
Downeaster	82%	1,806	33	98%	22,138	1,184	95%	228,800	31,914	86%
Empire	78%	5,438	748	86%	73,182	11,267	85%	825,280	185,441	78%
Adirondack	72%	107	0	100%	4,289	1,281	70%	50,182	19,510	61%
Ethan Allen Express	70%	572	73	87%	7,467	624	92%	90,221	25,719	71%
Maple Leaf	70%	842	239	72%	9,106	2,745	70%	89,551	39,489	56%
New York - Albany	85%	2,437	207	92%	34,544	2,923	92%	377,732	56,666	85%
New York - Niagara Falls	75%	1,480	229	85%	17,776	3,694	79%	217,594	44,057	80%
Gold Runner	73%	2,689	385	86%	31,528	8,033	75%	388,088	131,007	66%
Heartland Flyer	65%	318	317	0%	2,660	1,095	59%	30,359	11,432	62%
Hiawatha	90%	2,022	28	99%	21,748	2,954	86%	259,910	31,745	88%
Illinois	78%	3,110	602	81%	34,641	8,293	76%	367,495	98,330	73%
Carl Sandburg / Illinois Zephyr	85%	469	10	98%	4,807	1,114	77%	60,787	15,401	75%
Illini / Saluki	85%	1,170	2	100%	13,812	2,874	79%	134,352	31,653	76%
Lincoln Service	70%	1,471	590	60%	16,022	4,305	73%	172,356	51,276	70%
Keystone	92%	4,509	1,894	58%	77,011	12,945	83%	1,177,053	144,934	88%
Lincoln / Missouri	60%	930	359	61%	9,737	4,690	52%	117,711	54,118	54%
Mardi Gras Service	80%	396	125	68%	5,244	813	84%	65,613	8,539	87%
Michigan	69%	2,481	903	64%	25,500	8,980	65%	288,053	89,096	69%
Blue Water	70%	684	470	31%	5,249	2,811	46%	68,420	23,125	66%
Pere Marquette	85%	470	102	78%	3,585	723	80%	38,287	7,231	81%
Wolverine	65%	1,327	331	75%	16,666	5,446	67%	181,346	58,740	68%
Missouri	80%	282	0	100%	2,709	325	88%	33,900	6,279	81%
Pacific Surfliner	85%	8,704	482	94%	82,138	13,149	84%	1,065,906	159,197	85%
Pennsylvanian	72%	898	661	26%	12,070	4,992	59%	143,177	23,651	83%
Piedmont	73%	1,556	116	93%	16,741	4,077	76%	189,892	43,724	77%
Vermont	75%	1,429	21	99%	19,625	6,294	68%	207,385	61,779	70%
Long Distance	56%	11,690	4,421	62%	159,072	60,801	62%	1,905,576	656,870	66%
Auto Train	57%	969	534	45%	12,109	4,507	63%	119,160	28,786	76%
California Zephyr	50%	523	9	98%	12,734	3,650	71%	154,271	44,664	71%
Cardinal	55%	657	307	53%	3,067	1,468	52%	39,159	17,245	56%
City Of New Orleans	75%	878	135	85%	10,187	1,704	83%	105,651	21,179	80%
Coast Starlight	60%	575	59	90%	10,673	2,207	79%	169,952	53,353	69%
Crescent	70%	1,158	429	63%	12,313	2,310	81%	141,347	31,132	78%
Empire Builder	55%	53	0	100%	10,670	4,682	56%	147,631	58,036	61%
Floridian	40%	1,834	929	49%	20,040	12,150	39%	253,783	141,743	44%
Lake Shore Ltd	73%	989	931	6%	12,653	3,468	73%	148,331	41,745	72%
Palmetto	65%	982	9	99%	12,997	4,697	64%	147,343	26,123	82%
Silver Meteor	45%	1,215	331	73%	13,533	6,363	53%	159,884	55,279	65%
Southwest Chief	40%	933	396	58%	9,703	5,789	40%	121,584	71,159	41%
Sunset Ltd	70%	0	0	-	4,566	1,683	63%	45,490	11,832	74%
Texas Eagle	50%	924	352	62%	13,827	6,123	56%	151,990	54,594	64%
Seasonal Trains	%	709	0	100%	4,839	890	82%	31,666	1,157	96%
Winter Park Express	75%	709	0	100%	4,839	890	82%	31,666	1,157	96%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00001 00000000007 "UNCLASSIFIED" 4/20/2020

Train Index Dates Through March 14, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	77,489	1,404,961	552	936,448	17,057,682	549

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	7,305	380,806	192	42,766	4,850,972	88
INFRASTRUCTURE PLANNED	135	5,717	380,806	150	34,749	4,850,972	72
FLEET RELIABILITY	90	12,632	1,404,961	90	165,480	17,057,682	97
TRAIN OPERATIONS	424	51,835	1,404,961	369	693,453	17,057,682	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 03/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/14/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	274	46	83.2%	4,101	598	85.4%	48,036	7,011	85.4%
Central Division	85.5%	63	7	88.9%	933	83	91.1%	10,802	1,196	88.9%
Northeast Division	80.0%	82	20	75.6%	1,214	197	83.8%	14,949	2,590	82.7%
Southeast Division	72.5%	62	11	82.3%	1,001	184	81.6%	11,131	1,747	84.3%
Southwest Division	77.0%	67	8	88.1%	953	134	85.9%	11,154	1,478	86.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-0038

Scheduled Departure Date: 03/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/14/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	274	46	83.2%	4,101	598	85.4%	48,036	7,011	85.4%
Central Division	85.5%	63	7	88.9%	933	83	91.1%	10,802	1,196	88.9%
CDL	90.0%	2	0	100.0%	28	1	96.4%	299	12	96.0%
CHI	85.0%	27	2	92.6%	378	40	89.4%	4,341	572	86.8%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	8	0	100.0%	48	2	95.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	28	5	82.1%	323	40	87.6%
GRR	98.0%	1	0	100.0%	14	0	100.0%	158	6	96.2%
KCY	84.5%	2	0	100.0%	28	2	92.9%	325	23	92.9%
MHL	-	1	1	0.0%	2	2	0.0%	2	2	0.0%
MKE	86.5%	6	0	100.0%	82	5	93.9%	965	68	93.0%
MSP	94.0%	1	0	100.0%	14	0	100.0%	159	3	98.1%
PDX	78.0%	4	2	50.0%	65	6	90.8%	810	101	87.5%
PNT	91.5%	3	0	100.0%	41	2	95.1%	401	43	89.3%
PTH	93.0%	1	0	100.0%	13	0	100.0%	154	10	93.5%
QCY	87.5%	2	0	100.0%	28	0	100.0%	319	26	91.8%
SEA	80.0%	3	2	33.3%	100	15	85.0%	1,292	187	85.5%
SPK	92.0%	-	-	-	12	1	91.7%	163	15	90.8%
STL	88.0%	4	0	100.0%	56	3	94.6%	627	64	89.8%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	95.0%	2	0	100.0%	28	0	100.0%	320	7	97.8%
WIP	-	1	0	100.0%	8	1	87.5%	48	4	91.7%
Northeast Division	80.0%	82	20	75.6%	1,214	197	83.8%	14,949	2,590	82.7%
ALB	91.5%	8	0	100.0%	111	7	93.7%	1,157	129	88.9%
BON	43.5%	5	0	100.0%	70	5	92.9%	794	89	88.8%
BOS	86.5%	14	8	42.9%	195	25	87.2%	2,762	395	85.7%
BRK	88.0%	5	1	80.0%	70	3	95.7%	773	52	93.3%
BTN	48.0%	1	0	100.0%	14	1	92.9%	152	26	82.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	28	0	100.0%	316	36	88.6%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	14	3	78.6%	150	31	79.3%
NFL	96.5%	2	1	50.0%	28	3	89.3%	331	18	94.6%
NHV	75.5%	4	1	75.0%	77	14	81.8%	855	180	78.9%
NYP	77.5%	32	9	71.9%	484	129	73.3%	6,248	1,503	75.9%
SAB	98.0%	1	0	100.0%	14	0	100.0%	155	2	98.7%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	0	100.0%	95	5	94.7%	1,025	67	93.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	84.0%	1	0	100.0%	14	2	85.7%	162	43	73.5%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	62	11	82.3%	1,001	184	81.6%	11,131	1,747	84.3%
ATL	-	-	-	-	4	0	100.0%	34	4	88.2%

Information Management

Initial Terminal Performance By Terminal

26-FOI-0038

Scheduled Departure Date: 03/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/14/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	274	46	83.2%	4,101	598	85.4%	48,036	7,011	85.4%
Southeast Division	72.5%	62	11	82.3%	1,001	184	81.6%	11,131	1,747	84.3%
CLT	92.0%	5	0	100.0%	69	5	92.8%	805	62	92.3%
GRO	-	-	-	-	1	0	100.0%	9	3	66.7%
HAR	62.0%	8	0	100.0%	161	33	79.5%	1,812	356	80.4%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	69.5%	1	0	100.0%	14	1	92.9%	162	24	85.2%
MIA	87.5%	2	0	100.0%	28	3	89.3%	323	31	90.4%
MOE	94.0%	2	0	100.0%	28	1	96.4%	330	5	98.5%
NFK	86.0%	2	2	0.0%	28	8	71.4%	405	59	85.4%
NOL	92.0%	5	0	100.0%	58	2	96.6%	685	28	95.9%
NPN	96.0%	2	0	100.0%	28	1	96.4%	297	19	93.6%
PGH	92.0%	1	1	0.0%	13	3	76.9%	163	10	93.9%
PHL	45.0%	5	4	20.0%	133	74	44.4%	891	454	49.0%
RGH	97.0%	4	0	100.0%	56	2	96.4%	647	22	96.6%
RNK	85.5%	2	1	50.0%	28	7	75.0%	323	52	83.9%
RVM	86.0%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	91.5%	1	0	100.0%	14	1	92.9%	161	5	96.9%
SFA	70.5%	1	0	100.0%	14	2	85.7%	162	17	89.5%
WAS	70.0%	21	3	85.7%	324	41	87.3%	3,800	579	84.8%
Southwest Division	77.0%	67	8	88.1%	953	134	85.9%	11,154	1,478	86.7%
ARN	60.5%	1	0	100.0%	14	1	92.9%	164	11	93.3%
BFD	75.5%	6	1	83.3%	83	15	81.9%	988	204	79.4%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	16	1	93.8%	180	49	72.8%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	2	1	50.0%	16	3	81.3%	163	7	95.7%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GTA	72.5%	3	0	100.0%	36	3	91.7%	495	45	90.9%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	77.5%	10	1	90.0%	127	10	92.1%	1,551	152	90.2%
MCD	-	-	-	-	-	-	-	6	6	0.0%
OKC	96.0%	1	0	100.0%	14	0	100.0%	160	3	98.1%
OKJ	79.0%	8	3	62.5%	149	45	69.8%	1,671	418	75.0%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	12	1	91.7%	206	25	87.9%	2,210	238	89.2%
SAN	77.0%	13	1	92.3%	156	16	89.7%	1,876	164	91.3%
SAS	85.0%	1	0	100.0%	14	4	71.4%	160	12	92.5%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	98	9	90.8%	1,152	115	90.0%
SKN	-	-	-	-	-	-	-	6	5	16.7%
SLO	62.0%	2	0	100.0%	24	2	91.7%	307	27	91.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	20	1	95.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	03/14/2026
Amtrak or Commuter:	Amtrak

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		13	3	76.9%	164	30	81.7%	13	8	38.5%	163	68	58.3%
4		13	2	84.6%	163	22	86.5%	13	10	23.1%	163	103	36.8%
5	No OS	13	3	76.9%	163	31	81.0%	13	4	69.2%	160	34	78.8%
6		13	1	92.3%	162	41	74.7%	13	1	92.3%	162	43	73.5%
11	No OS	13	2	84.6%	163	27	83.4%	13	3	76.9%	158	31	80.4%
14		13	2	84.6%	164	22	86.6%	12	1	91.7%	162	41	74.7%
19	33	14	2	85.7%	162	37	77.2%	14	2	85.7%	162	22	86.4%
20		14	0	100.0%	162	11	93.2%	14	0	100.0%	162	18	88.9%
21	56	14	0	100.0%	159	15	90.6%	14	5	64.3%	158	33	79.1%
22		14	4	71.4%	160	11	93.1%	15	4	73.3%	160	33	79.4%
23	20	14	1	92.9%	165	4	97.6%	14	3	78.6%	165	27	83.6%
24		14	1	92.9%	165	10	93.9%	14	1	92.9%	165	15	90.9%
25		14	0	100.0%	165	1	99.4%	14	5	64.3%	164	28	82.9%
26		14	0	100.0%	165	3	98.2%	14	1	92.9%	164	24	85.4%
40		13	2	84.6%	159	20	87.4%	13	6	53.8%	159	58	63.5%
41		13	6	53.8%	159	64	59.7%	13	8	38.5%	159	104	34.6%
42	143	14	4	71.4%	164	11	93.3%	14	8	42.9%	162	27	83.3%
43	57	14	4	71.4%	163	31	81.0%	14	5	64.3%	163	23	85.9%
48	58	14	1	92.9%	162	35	78.4%	14	1	92.9%	162	26	84.0%
49	156	14	7	50.0%	162	46	71.6%	14	2	85.7%	162	36	77.8%
51		6	4	33.3%	69	37	46.4%	6	2	66.7%	68	21	69.1%
52	40	14	2	85.7%	162	17	89.5%	14	3	78.6%	162	26	84.0%
53		14	1	92.9%	162	24	85.2%	14	5	64.3%	162	36	77.8%
54		14	2	85.7%	68	5	92.6%	14	2	85.7%	68	9	86.8%
57		14	0	100.0%	67	2	97.0%	14	1	92.9%	67	5	92.5%
58		14	0	100.0%	156	4	97.4%	14	2	85.7%	155	24	84.5%
59		14	0	100.0%	155	15	90.3%	14	2	85.7%	155	16	89.7%
63		14	6	57.1%	165	83	49.7%	14	3	78.6%	164	80	51.2%
64		14	2	85.7%	163	44	73.0%	14	2	85.7%	163	39	76.1%
65		4	1	75.0%	52	8	84.6%	4	1	75.0%	51	9	82.4%
66		14	5	64.3%	162	33	79.6%	14	3	78.6%	162	32	80.2%
68	153	14	3	78.6%	165	39	76.4%	14	7	50.0%	165	87	47.3%
69		14	4	71.4%	152	23	84.9%	13	0	100.0%	149	19	87.2%
71		14	0	100.0%	160	2	98.8%	14	2	85.7%	160	39	75.6%
72		14	2	85.7%	160	14	91.3%	14	0	100.0%	160	28	82.5%
73		14	0	100.0%	164	7	95.7%	14	6	57.1%	163	79	51.5%
74		14	3	78.6%	164	17	89.6%	14	6	57.1%	164	51	68.9%
75		14	0	100.0%	163	5	96.9%	14	8	42.9%	160	69	56.9%
76	38	14	0	100.0%	163	10	93.9%	14	4	71.4%	158	58	63.3%
77		14	2	85.7%	162	10	93.8%	14	8	42.9%	161	56	65.2%
78		14	0	100.0%	161	8	95.0%	14	3	78.6%	160	19	88.1%
79		14	3	78.6%	162	33	79.6%	14	6	57.1%	161	29	82.0%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80		14	0	100.0%	162	14	91.4%	14	1	92.9%	161	23	85.7%
82		14	1	92.9%	50	5	90.0%	14	6	57.1%	50	16	68.0%
87	51	14	6	57.1%	71	19	73.2%	14	8	42.9%	71	22	69.0%
88		14	1	92.9%	70	9	87.1%	14	1	92.9%	70	15	78.6%
89		14	6	57.1%	161	32	80.1%	14	5	64.3%	161	35	78.3%
90		14	1	92.9%	161	5	96.9%	14	2	85.7%	161	15	90.7%
94		14	4	71.4%	123	34	72.4%	14	6	57.1%	122	39	68.0%
97		14	12	14.3%	163	96	41.1%	14	4	71.4%	163	36	77.9%
98		14	0	100.0%	162	10	93.8%	13	3	76.9%	161	40	75.2%
99		14	1	92.9%	70	10	85.7%	14	9	35.7%	69	39	43.5%
101		14	3	78.6%	49	6	87.8%	14	6	57.1%	49	10	79.6%
103	114	14	5	64.3%	69	16	76.8%	14	2	85.7%	69	7	89.9%
106	22	14	2	85.7%	67	8	88.1%	14	2	85.7%	67	10	85.1%
107		14	6	57.1%	67	22	67.2%	14	1	92.9%	67	9	86.6%
109		14	2	85.7%	32	4	87.5%	14	1	92.9%	32	4	87.5%
118		14	0	100.0%	70	6	91.4%	14	0	100.0%	70	4	94.3%
124		14	1	92.9%	68	7	89.7%	14	4	71.4%	68	14	79.4%
126		14	3	78.6%	28	5	82.1%	14	2	85.7%	28	6	78.6%
127		14	6	57.1%	28	10	64.3%	14	3	78.6%	28	5	82.1%
128		14	3	78.6%	71	14	80.3%	14	2	85.7%	70	8	88.6%
135	102	14	2	85.7%	70	12	82.9%	14	7	50.0%	70	39	44.3%
140		14	3	78.6%	69	9	87.0%	14	0	100.0%	68	14	79.4%
142		14	0	100.0%	50	5	90.0%	14	1	92.9%	50	4	92.0%
143		14	1	92.9%	68	5	92.6%	14	6	57.1%	68	15	77.9%
144	168	14	13	7.1%	50	38	24.0%	14	4	71.4%	50	9	82.0%
146		14	1	92.9%	68	11	83.8%	14	4	71.4%	68	26	61.8%
147		14	0	100.0%	51	6	88.2%	14	7	50.0%	51	15	70.6%
151	51	14	5	64.3%	161	45	72.0%	14	8	42.9%	160	48	70.0%
152		14	3	78.6%	50	5	90.0%	14	5	64.3%	50	17	66.0%
153		14	2	85.7%	69	7	89.9%	14	2	85.7%	69	9	87.0%
155		14	2	85.7%	71	12	83.1%	14	5	64.3%	71	14	80.3%
156	92	14	2	85.7%	71	9	87.3%	14	10	28.6%	71	20	71.8%
158		14	4	71.4%	70	8	88.6%	14	5	64.3%	70	13	81.4%
159		14	1	92.9%	51	7	86.3%	14	1	92.9%	51	9	82.4%
160		14	1	92.9%	68	3	95.6%	14	6	57.1%	66	19	71.2%
161	135	14	2	85.7%	70	7	90.0%	14	10	28.6%	69	46	33.3%
162		14	0	100.0%	70	4	94.3%	14	11	21.4%	70	41	41.4%
163	90	14	2	85.7%	50	11	78.0%	14	14	0.0%	50	40	20.0%
164	62	14	0	100.0%	71	5	93.0%	14	9	35.7%	71	30	57.7%
165		14	2	85.7%	70	20	71.4%	14	5	64.3%	70	30	57.1%
167		14	3	78.6%	51	12	76.5%	13	3	76.9%	50	16	68.0%
168		14	6	57.1%	49	8	83.7%	14	5	64.3%	49	17	65.3%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
169	158	14	2	85.7%	69	10	85.5%	14	4	71.4%	68	19	72.1%
194	20	14	3	78.6%	50	9	82.0%	14	5	64.3%	49	12	75.5%
195		14	0	100.0%	69	0	100.0%	14	4	71.4%	69	40	42.0%
232		14	0	100.0%	165	9	94.5%	14	0	100.0%	165	13	92.1%
233		14	2	85.7%	149	34	77.2%	14	1	92.9%	149	27	81.9%
234		14	1	92.9%	165	17	89.7%	14	0	100.0%	165	17	89.7%
235		14	2	85.7%	89	13	85.4%	14	1	92.9%	89	16	82.0%
236		14	0	100.0%	149	5	96.6%	14	0	100.0%	149	21	85.9%
237		14	3	78.6%	164	39	76.2%	14	3	78.6%	162	33	79.6%
238		14	0	100.0%	89	12	86.5%	14	1	92.9%	88	8	90.9%
239		14	5	64.3%	164	52	68.3%	14	0	100.0%	163	17	89.6%
240		14	0	100.0%	165	17	89.7%	14	0	100.0%	164	20	87.8%
241	19	14	4	71.4%	165	42	74.5%	14	3	78.6%	165	36	78.2%
244		14	0	100.0%	149	7	95.3%	14	1	92.9%	149	24	83.9%
280		14	0	100.0%	165	7	95.8%	14	0	100.0%	165	31	81.2%
281		14	1	92.9%	165	20	87.9%	14	5	64.3%	165	30	81.8%
283		14	1	92.9%	165	39	76.4%	14	0	100.0%	165	34	79.4%
284		14	3	78.6%	165	10	93.9%	14	3	78.6%	163	28	82.8%
290		14	1	92.9%	165	34	79.4%	14	0	100.0%	163	52	68.1%
291		14	3	78.6%	164	40	75.6%	14	1	92.9%	163	27	83.4%
300		14	1	92.9%	151	13	91.4%	14	3	78.6%	149	36	75.8%
301		14	1	92.9%	163	8	95.1%	14	1	92.9%	160	27	83.1%
302	39	14	2	85.7%	150	20	86.7%	14	5	64.3%	148	45	69.6%
305	70	14	0	100.0%	153	21	86.3%	14	6	57.1%	149	59	60.4%
306	32	14	0	100.0%	161	12	92.5%	14	4	71.4%	160	37	76.9%
307	68	14	2	85.7%	154	23	85.1%	14	5	64.3%	152	38	75.0%
311		14	0	100.0%	164	18	89.0%	14	2	85.7%	162	27	83.3%
316		14	0	100.0%	162	8	95.1%	14	2	85.7%	161	25	84.5%
318		14	2	85.7%	164	16	90.2%	14	3	78.6%	163	64	60.7%
319		14	2	85.7%	165	11	93.3%	14	8	42.9%	164	79	51.8%
330		12	0	100.0%	139	2	98.6%	12	0	100.0%	139	11	92.1%
331		14	0	100.0%	165	20	87.9%	14	1	92.9%	165	25	84.8%
332		14	0	100.0%	165	11	93.3%	14	1	92.9%	165	25	84.8%
334		14	0	100.0%	165	5	97.0%	14	3	78.6%	164	23	86.0%
335		14	2	85.7%	165	20	87.9%	14	2	85.7%	163	29	82.2%
336		14	1	92.9%	165	7	95.8%	14	3	78.6%	165	12	92.7%
337	11	14	2	85.7%	165	9	94.5%	13	1	92.3%	164	20	87.8%
338		14	1	92.9%	165	31	81.2%	14	5	64.3%	163	50	69.3%
339		14	4	71.4%	165	34	79.4%	14	4	71.4%	165	34	79.4%
341		14	0	100.0%	158	21	86.7%	14	2	85.7%	155	22	85.8%
342		14	3	78.6%	165	12	92.7%	14	5	64.3%	163	32	80.4%
343		2	0	100.0%	24	2	91.7%	2	0	100.0%	24	6	75.0%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
350	98	14	0	100.0%	146	12	91.8%	14	5	64.3%	143	76	46.9%
351		14	0	100.0%	150	19	87.3%	14	5	64.3%	150	52	65.3%
352		14	0	100.0%	149	13	91.3%	14	4	71.4%	144	44	69.4%
353		13	2	84.6%	126	10	92.1%	12	3	75.0%	122	22	82.0%
354		13	0	100.0%	150	15	90.0%	13	2	84.6%	147	50	66.0%
355		14	0	100.0%	160	20	87.5%	14	5	64.3%	154	51	66.9%
364		14	7	50.0%	158	44	72.2%	13	7	46.2%	152	46	69.7%
365	30	13	0	100.0%	154	10	93.5%	13	7	46.2%	153	49	68.0%
370		14	1	92.9%	161	18	88.8%	13	4	69.2%	157	34	78.3%
371		14	0	100.0%	158	6	96.2%	14	1	92.9%	157	19	87.9%
380		14	0	100.0%	154	19	87.7%	14	2	85.7%	154	33	78.6%
381		14	0	100.0%	165	8	95.2%	14	1	92.9%	165	23	86.1%
382		14	0	100.0%	165	7	95.8%	14	7	50.0%	165	43	73.9%
383		14	0	100.0%	154	19	87.7%	14	7	50.0%	152	61	59.9%
390		14	1	92.9%	148	13	91.2%	14	4	71.4%	147	44	70.1%
391		14	1	92.9%	150	5	96.7%	14	3	78.6%	147	29	80.3%
392		14	0	100.0%	164	4	97.6%	14	1	92.9%	162	39	75.9%
393		14	2	85.7%	165	14	91.5%	14	4	71.4%	164	41	75.0%
400		4	0	100.0%	50	4	92.0%	4	0	100.0%	48	2	95.8%
405		4	0	100.0%	47	0	100.0%	4	0	100.0%	47	4	91.5%
448	121	14	4	71.4%	98	31	68.4%	14	8	42.9%	96	38	60.4%
449	63	14	3	78.6%	96	12	87.5%	14	5	64.3%	96	18	81.3%
450	33	4	3	25.0%	50	22	56.0%	4	3	25.0%	49	20	59.2%
460		4	0	100.0%	50	21	58.0%	4	0	100.0%	47	15	68.1%
461		4	0	100.0%	51	5	90.2%	4	0	100.0%	50	2	96.0%
463		2	0	100.0%	27	3	88.9%	2	0	100.0%	27	0	100.0%
464	40	4	0	100.0%	49	11	77.6%	4	3	25.0%	48	16	66.7%
467		2	0	100.0%	27	1	96.3%	2	0	100.0%	26	1	96.2%
488		4	0	100.0%	52	12	76.9%	4	0	100.0%	46	8	82.6%
499	39	4	0	100.0%	47	8	83.0%	4	1	75.0%	45	5	88.9%
503		14	0	100.0%	162	16	90.1%	13	2	84.6%	159	38	76.1%
504		14	1	92.9%	165	14	91.5%	13	2	84.6%	163	42	74.2%
507	64	14	3	78.6%	165	19	88.5%	14	1	92.9%	165	50	69.7%
508		14	4	71.4%	163	30	81.6%	13	1	92.3%	162	29	82.1%
516	64	14	2	85.7%	161	14	91.3%	14	4	71.4%	161	65	59.6%
517		14	0	100.0%	165	3	98.2%	13	0	100.0%	163	48	70.6%
518	44	14	2	85.7%	165	23	86.1%	14	9	35.7%	164	100	39.0%
519		14	0	100.0%	161	5	96.9%	14	8	42.9%	161	33	79.5%
562		12	0	100.0%	159	16	89.9%	12	0	100.0%	156	19	87.8%
564		12	1	91.7%	159	12	92.5%	12	0	100.0%	153	18	88.2%
566		12	0	100.0%	157	9	94.3%	12	1	91.7%	154	19	87.7%
567		12	1	91.7%	44	2	95.5%	12	0	100.0%	44	1	97.7%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572		12	0	100.0%	154	12	92.2%	12	3	75.0%	151	34	77.5%
573		12	3	75.0%	157	23	85.4%	12	2	83.3%	152	25	83.6%
579		12	1	91.7%	44	2	95.5%	11	3	72.7%	43	9	79.1%
580		12	1	91.7%	159	6	96.2%	12	0	100.0%	158	14	91.1%
581		12	3	75.0%	159	21	86.8%	12	4	66.7%	159	34	78.6%
584		12	1	91.7%	44	4	90.9%	12	7	41.7%	43	21	51.2%
586		12	2	83.3%	159	25	84.3%	12	1	91.7%	151	20	86.8%
587		12	1	91.7%	155	9	94.2%	11	1	90.9%	149	23	84.6%
588		12	1	91.7%	44	1	97.7%	12	1	91.7%	44	3	93.2%
591		12	1	91.7%	159	7	95.6%	12	1	91.7%	157	15	90.4%
593		12	1	91.7%	155	22	85.8%	12	1	91.7%	145	16	89.0%
595		12	1	91.7%	158	28	82.3%	12	1	91.7%	157	26	83.4%
600		14	1	92.9%	120	6	95.0%	14	1	92.9%	119	12	89.9%
607		14	3	78.6%	119	13	89.1%	13	0	100.0%	117	11	90.6%
624		14	7	50.0%	98	33	66.3%	14	6	57.1%	99	25	74.7%
643	146	14	3	78.6%	122	30	75.4%	14	3	78.6%	121	24	80.2%
644		14	2	85.7%	114	21	81.6%	14	4	71.4%	113	35	69.0%
645	21	13	10	23.1%	122	31	74.6%	12	2	83.3%	120	28	76.7%
647	94	14	9	35.7%	122	24	80.3%	14	4	71.4%	122	30	75.4%
648		13	2	84.6%	119	32	73.1%	13	1	92.3%	119	16	86.6%
649	46	14	1	92.9%	123	23	81.3%	14	6	57.1%	121	26	78.5%
650	232	14	4	71.4%	122	31	74.6%	14	2	85.7%	121	20	83.5%
651	25	14	2	85.7%	122	11	91.0%	14	6	57.1%	121	29	76.0%
652	49	14	2	85.7%	123	21	82.9%	14	2	85.7%	120	23	80.8%
655	98	14	4	71.4%	120	39	67.5%	14	6	57.1%	118	41	65.3%
656		14	1	92.9%	122	29	76.2%	14	1	92.9%	122	14	88.5%
657		10	4	60.0%	112	20	82.1%	10	0	100.0%	111	22	80.2%
658		14	1	92.9%	122	19	84.4%	13	2	84.6%	121	21	82.6%
661	27	14	5	64.3%	69	11	84.1%	14	8	42.9%	68	27	60.3%
690		4	0	100.0%	47	1	97.9%	4	0	100.0%	46	3	93.5%
691	16	4	1	75.0%	47	4	91.5%	4	4	0.0%	46	18	60.9%
692		4	0	100.0%	47	2	95.7%	4	0	100.0%	46	11	76.1%
693		4	1	75.0%	47	7	85.1%	4	1	75.0%	47	16	66.0%
694		4	0	100.0%	47	5	89.4%	4	0	100.0%	47	8	83.0%
695		4	0	100.0%	47	5	89.4%	4	0	100.0%	47	10	78.7%
696		4	1	75.0%	47	6	87.2%	4	1	75.0%	47	12	74.5%
697		4	0	100.0%	47	9	80.9%	4	0	100.0%	47	10	78.7%
698		4	0	100.0%	46	0	100.0%	4	0	100.0%	46	6	87.0%
701		14	1	92.9%	97	10	89.7%	14	1	92.9%	95	7	92.6%
702		14	0	100.0%	164	20	87.8%	14	1	92.9%	163	36	77.9%
703		14	3	78.6%	165	42	74.5%	14	3	78.6%	164	37	77.4%
704		14	5	64.3%	96	13	86.5%	14	3	78.6%	95	18	81.1%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710		14	4	71.4%	165	51	69.1%	14	3	78.6%	164	46	72.0%
711		13	1	92.3%	157	13	91.7%	13	3	76.9%	146	26	82.2%
712		14	7	50.0%	162	40	75.3%	14	4	71.4%	157	53	66.2%
715		14	5	64.3%	164	41	75.0%	13	4	69.2%	154	74	51.9%
716		14	6	57.1%	165	66	60.0%	14	3	78.6%	162	62	61.7%
717		14	4	71.4%	152	39	74.3%	14	1	92.9%	140	40	71.4%
718		14	7	50.0%	165	78	52.7%	13	3	76.9%	163	50	69.3%
719		14	1	92.9%	165	53	67.9%	14	3	78.6%	156	42	73.1%
720		4	0	100.0%	53	4	92.5%	4	0	100.0%	53	2	96.2%
723		4	0	100.0%	53	4	92.5%	4	0	100.0%	53	5	90.6%
724		4	1	75.0%	53	2	96.2%	4	0	100.0%	53	6	88.7%
727		4	0	100.0%	53	5	90.6%	4	0	100.0%	53	8	84.9%
728		4	0	100.0%	53	5	90.6%	4	1	75.0%	53	9	83.0%
729		4	1	75.0%	53	5	90.6%	4	2	50.0%	53	13	75.5%
732	90	4	0	100.0%	51	8	84.3%	4	2	50.0%	50	9	82.0%
733	26	4	0	100.0%	53	8	84.9%	4	4	0.0%	49	18	63.3%
734	33	4	2	50.0%	53	12	77.4%	4	1	75.0%	53	10	81.1%
736		1	0	100.0%	29	1	96.6%	1	0	100.0%	29	4	86.2%
737		1	0	100.0%	30	3	90.0%	1	0	100.0%	30	4	86.7%
738		4	0	100.0%	53	8	84.9%	4	1	75.0%	51	4	92.2%
741	30	4	2	50.0%	53	9	83.0%	4	2	50.0%	53	7	86.8%
742		4	2	50.0%	53	7	86.8%	3	1	66.7%	51	6	88.2%
743		4	2	50.0%	53	8	84.9%	3	1	66.7%	52	4	92.3%
744		4	0	100.0%	53	6	88.7%	4	2	50.0%	53	17	67.9%
745	27	4	1	75.0%	53	5	90.6%	4	3	25.0%	53	11	79.2%
746		4	0	100.0%	53	3	94.3%	4	1	75.0%	53	7	86.8%
747		4	0	100.0%	53	10	81.1%	4	0	100.0%	53	11	79.2%
748		4	0	100.0%	52	8	84.6%	4	2	50.0%	52	9	82.7%
749		4	1	75.0%	50	8	84.0%	3	1	66.7%	43	6	86.0%
751		4	1	75.0%	53	11	79.2%	4	0	100.0%	51	6	88.2%
761		12	0	100.0%	161	6	96.3%	12	2	83.3%	159	26	83.6%
765		12	1	91.7%	161	17	89.4%	12	2	83.3%	161	25	84.5%
769		12	1	91.7%	161	17	89.4%	12	3	75.0%	158	31	80.4%
770		12	1	91.7%	161	15	90.7%	12	4	66.7%	161	35	78.3%
774		12	1	91.7%	161	14	91.3%	12	2	83.3%	160	32	80.0%
777	226	12	1	91.7%	46	4	91.3%	12	4	66.7%	46	11	76.1%
782		12	1	91.7%	46	3	93.5%	12	1	91.7%	46	4	91.3%
785	51	12	1	91.7%	161	5	96.9%	12	2	83.3%	161	26	83.9%
790		12	1	91.7%	161	13	91.9%	12	0	100.0%	159	15	90.6%
794	39	12	1	91.7%	161	16	90.1%	12	4	66.7%	160	34	78.8%
821	48	14	0	100.0%	160	3	98.1%	14	6	57.1%	160	65	59.4%
822	46	14	1	92.9%	161	5	96.9%	14	5	64.3%	160	70	56.3%

Amtrak On Time Performance

Trains Arriving Through: 3/14/2026

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1021		2	2	0.0%	3	2	33.3%	1	0	100.0%	2	0	100.0%
1022		2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
1105		8	0	100.0%	48	2	95.8%	8	1	87.5%	48	3	93.8%
1106		8	1	87.5%	48	4	91.7%	8	2	75.0%	48	3	93.8%
1333	32	14	1	92.9%	161	18	88.8%	14	4	71.4%	158	57	63.9%
1340	24	14	0	100.0%	160	3	98.1%	14	1	92.9%	160	30	81.3%
1689	13	4	1	75.0%	31	2	93.5%	4	2	50.0%	31	3	90.3%
2201		14	3	78.6%	32	7	78.1%	14	0	100.0%	32	2	93.8%
2203	23	14	4	71.4%	49	9	81.6%	14	8	42.9%	49	17	65.3%
2205		14	1	92.9%	68	8	88.2%	14	3	78.6%	68	10	85.3%
2216		14	1	92.9%	51	3	94.1%	14	1	92.9%	51	1	98.0%
2218		14	2	85.7%	48	8	83.3%	14	2	85.7%	48	7	85.4%
2220		14	2	85.7%	29	5	82.8%	14	1	92.9%	28	5	82.1%
2248		14	3	78.6%	65	8	87.7%	14	2	85.7%	65	13	80.0%
2249		14	0	100.0%	48	1	97.9%	14	6	57.1%	48	18	62.5%
2250		14	0	100.0%	68	8	88.2%	14	4	71.4%	68	28	58.8%
2252		14	0	100.0%	67	6	91.0%	14	5	64.3%	65	16	75.4%
2255	45	14	1	92.9%	68	10	85.3%	14	6	57.1%	67	33	50.7%
2271	76	14	1	92.9%	52	7	86.5%	14	8	42.9%	51	30	41.2%

Amtrak Endpoint OTP Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/14/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2203	WAS	23	ENG	20	ENG	20	NYP-NYP	AM	Undesired emergency application, 2145, UNSPECIFIED MECHANICAL PROBLEMS	
2255	WAS	45	DMW	31	DMW	31	BOS-BOS	AM	Hold for defect repair, Milepost, BOS, BOS, late a/c switch damage after train 851 derailed on 3/13 tower 1	
2271	WAS	76	DMW	58	DMW	58	BOS-BOS	AM	Hold for defect repair, Milepost, BOS, BOS, Train 2271 will be delayed departing Boston a/c ongoing repairs in tower 1	
87	NFK	51	DMW	142	DMW	142	BOS-BOS	AM	Hold for defect repair, Milepost, BOS, BOS, Delayed dp a/c track repairs cause by derailment at tower 1 on 3/13	
103	WAS	114	ITI	141	ITI	141	NYP-NYP	AM	Service, turn, or wye train, 144, LATE TURN OFF AM144	
106	NYP	22	ITI	25	ITI	25	WAS-WAS	AM	Service, turn, or wye train, 103, LATE INBOUND TURN OFF AM103	
135	WAS	102	SVS	97	SVS	97	BOS-BOS	AM	Water, commissary, toilet/trash dumping, AM135 departed late due to AM162 eq from 3/13 needing to be deep cleaned	
144	NYP	168	ITI	154	ITI	154	PHL-PHL	AM	Service, turn, or wye train, 169, LATE TURN FROMTRAIN 169	
151	RNK	51	SVS	65	SVS	65	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM THE YARD	
156	NYP	92	PTI	123	PTI	113	RNK-LYH	NS	Meet p19, Milepost, 164.0, 164.0	
161	WAS	135	DMW	93	DMW	93	BOS-BOS	AM	Hold for defect repair, Other, bos, late a/c switch damage after train 851 derailed on 3/13 tower 1.	
163	WAS	90	DMW	93	DMW	93	BOS-BOS	AM	Hold for defect repair, Milepost, bos, bos, late a/c switch damage after train 851 derailed on 3/13 tower 1	
164	BOS	62	HLD	47	HLD	33	KIN-PVD	AM	Passenger and/or baggage, AM164 had to reverse back to PVD, 40 + psngr didn't get off the train	
169	PHL	158	DCS	166	DCS	166	BOS-BOS	AM	Power switch failure, Control Point, BOS, HELD DUE TO DERAILMENT OF KEOLIS MT851, DUE TO A SWITCH FAILURE AT TOWER 1	
194	BOS	20	HLD	16	HLD	6	NYP-NYP	AM	Passenger and/or baggage	
450	SPG	33	ITI	16	ITI	16	NHV-NHV	AM	Service, turn, or wye train, 405, Late turn	
464	SPG	40	CON	20	CON	20	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM164	

Amtrak Endpoint OTP Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
499	SPG	39							
52	LOR	40	DSR	77	DSR	74	XSE-XV7	CS	Per bulletin Milepost w/Letters, a 97.3, a 97.0, 25, main, Milepost w/Letters, a 84.7, a 84.6, 25, main, Milepost w/Letters, a 76.8, a 75.0, 25, main, Milepost w/Letters, a 75.0, a 74.0, 25, main, Milepost w/Letters, a 73.9, a 73.4, 25, 1 track, Milepost w/Letters, a 71.2, a 69.5, 25, 1 track, Milep
643	HAR	146	POL	150	POL	147	PHL-PAO	AM	Fire department hold, HELD FOR DISPOSITON A/C HOLD ON ALL TRKS A/C TREE FIRE AT MP 19.5
645	HAR	21	POL	27	POL	15	PHL-PAO	AM	Fire department hold, HELD FOR DISPOSITON A/C HOLD ON ALL TRKS A/C TREE FIRE AT MP 19.5
647	HAR	94	POL	101	POL	97	PHL-PHL	AM	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
649	HAR	46	POL	48	POL	48	PHL-PHL	AM	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
650	NYP	232	POL	224	POL	183	LNC-DOW	AM	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
651	HAR	25	PTI	36	PTI	17	PHN-PHL	AM	Wait for station track, ., Control Point, ., HELD FOR STATION TRACK.
652	PHL	49	POL	39	POL	39	PAR-DOW	AM	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
655	HAR	98	ITI	124	ITI	124	NYP-NYP	AM	Service, turn, or wye train, 650
661	HAR	27	CTI	16	CTI	6	EXT-DOW	AM	Follow, SEPTA, 8515, Control Point, WHITFORD, SEPTA TAIN 8515 STOPPED AT WHITFORD
19	NOL	33	DCS	80	FTI	42	GNS-ATL	NS	Follow ns 25a, Milepost, 626.3, 633.3
691	BRK	16	PTI	14	PTI	14	POR-FRE	CS	Meet 694, Control Point, Congress
1689	BRK	13	FTI	8	FTI	8	EXR-DHM	CS	Cross over or go around m426, Control Point, rockingham
68	NYP	153	CUI	70	CUI	70	RSP-RSP	DH	U.S. Border Patrol

Amtrak Endpoint OTP Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
241	ALB	19	ENG	14	ENG	14	NYP-NYP	AM	Other electrical failure, 708
48	NYP	58	SYS	126	SYS	126	CHI-CHI	AM	Crew rest 49 arr into Chicago at 303 P.. held for 8 hrs rest, on duty at 1113 P, Other, chi union station
49	CHI	156	SVS	106	SVS	106	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train Trouble with engine 370. Wouldn't communicate with trailing units.
448	BOS	39	CON	68	CON	68	ALB-ALB	AM	Hold for connecting train 448
449	ALB	63	DMW	53	DTR	53	BOS-BOS	AM	Derailment Control Point, Tower 1, BOS, BOS
42	NYP	143	POL	131	POL	118	LNC-EXT	AM	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
43	PGH	57	POL	69	POL	56	PHL-PHL	AM	Fire department hold, HELD FOR DISPOSITON A/C HOLD ON ALL TRKS A/C TREE FIRE AT MP 19.5
76	RGH	38	TEN	27	TEN	27	CLT-KAN	NS	Onboard HBD alarm NC1871
23	NOL	20	FTI	31	FTI	25	BAS-XNO	NS	Cross Traffic 130, Control Point, NO NE Tower
5	EMY	No OS Rpt	ENG	505	ENG	203	PRO-SLC	UP	Failure of diesel engine 23
732	SAC	90	DMW	96	DMW	96	DAV-DAV	UP	Hold for track/bridge inspection Rough track reported by 743 on track 2 around mp 83. UP stopped all traffic until track and bridge could be inspected, Milepost, 82.85, 83
733	SJC	26	PTI	18	PTI	8	GAC-SCC	UP	Cross over or go around 734, Control Point, CO044
734	SAC	33	DMW	25	DMW	14	DAV-DAV	UP	Rough track wait for bridge and track inspector to clear scene Other, DAV station
741	SJC	30	PTI	22	TRS	22	MTZ-RIC	UP	Car on fire near mt 1 Milepost, 13.7, 13.7
745	SJC	27	DMW	27	DMW	27	SAC-SAC	UP	Hold for defect repair Rough track, Milepost, 82.5, 83.0
507	EUG	40	TRS	57	TRS	57	PDX-ORC	UP	Vehicle on track ahead Control Point, 769.62
516	VAC	64	FTI	73	FTI	38	XF2-X1J	BN	Meet CN 5468, Control Point, Still Creek
518	VAC	21	CON	22	CON	22	SEA-SEA	BN	Hold for bus with passengers from train
11	LAX	No OS Rpt	FTI	257	FTI	240	RDD-CIC	UP	Freight with busted drawbar clogging the main track. UP 5517, Control Point, VP212

Amtrak Endpoint OTP Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
821	FTW	48	FTI	40	FTI	25	PVL-ADM	BN	Follow Bnsf 8264, Milepost, 447.1, 450.7
822	OKC	46	FTI	49	FTI	29	GLE-ADM	BN	Meet BNSF 3853, Siding, Gainesville
337	MKE	11	PTI	15	PTI	8	XWA-GLN	ME	Follow 7 / 27, Control Point, grayland
351	CHI	98	SYS	60	SYS	28	DER-ARB	MI	PTC problem or failure (cause unknown) ITcs cut in at cp townline entering the property. When Crossing over at cp 18 we received the c-69000 code screen blank again and suppression. This time lost mode light. Instructed to run the signals to see if it would cut back on.
365	CHI	30	FTI	31	FTI	31	LNS-BTL	CC	Cross over or go around Take Lansing Thoroughfare from CP Cedar to CP Mill handling two hang throw switches. CN freight in emergency on the main., x301 CN 3278, Control Point, Cedar
777	SLO	226	POL	182	POL	182	LAX-LAX	SC	RR blocked by trespasser or vehicle strike by another train
785	GTA	51	DCS	58	DCS	53	OXN-VEC	UP	Power switch failure Milepost, 400, 397
794	SAN	39	CCR	53	CCR	53	FUL-FUL	BN	Air / Brake / Wheel 90215, All rear brakes were sticking; everything cut properly. Seat locked, no brakes set on control stand. Until in trail. After placing train into emergency twice all but one wheels brake would release. Cut out rear truck on AMTK 90215. 85% operative brakes.
21	MHL	56	FTI	100	PTI	27	SPI-CRV	UP	Meet 306, Control Point, X214
302	CHI	39	FTI	23	FTI	13	BNL-PON	UP	Meet Unknown, Siding, Pontiac
305	STL	70	DTR	62	DTR	62	XWR-STL	TR	High line XWR, STL
306	CHI	32	FTI	52	FTI	27	SMT-XTF	CC	Cross Traffic NA, Control Point, Brighton
307	STL	68	FTI	80	FTI	63	XQT-STL	TR	Blocked from station track NA, Milepost w/Letters, Gratiot, Gratiot
1333	MSP	32	FTI	40	FTI	21	WIN-RDW	CP	Meet CP 285, Control Point, Wevor, mixed
1340	CHI	24	DMW	25	DMW	25	RDW-WIN	CP	Held for or routed around MW work or equipment Track inspector, Control Point, Lakeview East

Amtrak Initial Terminal Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 3/14/2026

Terminal	Train	Date	Late	Delay	Cause
NFK	94	03/14	1		
NFK	158	03/14	1		
PGH	42	03/14	4	4	Hold for connecting train 26 transfers, 41
PHL	144	03/14	180	154	Service, turn, or wye train, 169, LATE TURN FROM TRAIN 169
PHL	144	03/14	180	26	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
PHL	151	03/14	65	65	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM THE YARD
PHL	645	03/14	7	7	Fire department hold, HELD FOR DISPOSITION A/C HOLD ON ALL TRKS DUE TO TREE FIRE AT MP 19.5
PHL	647	03/14	97	97	Fire department hold, HELD FOR DISPOSITON. SINGLE TRACKING ON 4TRK BETWEEN MP 19.5 AND PAOLI A/C TREE FIRE AT MP 19.5.
RNK	66	03/14	1		
WAS	106	03/14	25	25	Service, turn, or wye train, 103, LATE INBOUND TURN OFF AM103
WAS	128	03/14	29	29	HEP, 602, MTR LOST HEP, MTR CUT FROM REAR
WAS	194	03/14	4	4	Air / Brake, ALL, DOOR LIGHT STILL SHOWING, NECESSARY TO PUT IN DOOR BYPASS.
ALB	448	03/13	68	68	Hold for connecting train 448
BOS	87	03/14	142	142	Hold for defect repair, Milepost, BOS, BOS, Delayed dp a/c track repairs cause by derailment at tower 1 on 3/13
BOS	99	03/14	25	25	Hold for defect repair, Milepost, BOS, BOS, Train 99 will be delayed departing Boston a/c ongoing repairs in tower 1
BOS	135	03/14	97	97	Water, commissary, toilet/trash dumping, AM135 departed late due to AM162 eq from 3/13 needing to be deep cleaned
BOS	161	03/14	93	93	Hold for defect repair, Other, bos, late a/c switch damage after train 851 derailed on 3/13 tower 1.
BOS	163	03/14	93	93	Hold for defect repair, Milepost, bos, bos, late a/c switch damage after train 851 derailed on 3/13 tower 1
BOS	449	03/14	53	22	Hold for defect repair, Milepost, BOS, BOS, late a/c switch damage after train 851 derailed on 3/13 tower 1
BOS	449	03/14	53	31	Hold for defect repair, Milepost, BOS, BOS, late a/c switch damage after train 851 derailed on 3/13 tower 1
BOS	449	03/14	53	53	Derailment Control Point, Tower 1, BOS, BOS
BOS	2255	03/14	31	31	Hold for defect repair, Milepost, BOS, BOS, late a/c switch damage after train 851 derailed on 3/13 tower 1

Amtrak Initial Terminal Details

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 3/14/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	2271	03/14	58	58	Hold for defect repair, Milepost, BOS, BOS, Train 2271 will be delayed departing Boston a/c ongoing repairs in tower 1
BRK	696	03/14	2	2	Unable to use DTMF code had to tone Dispatcher Control Point, Brunswick Station
NFL	284	03/14	1	1	EDR reported wrong departure time. 284 departed at 6:47.
NHV	450	03/14	16	16	Service, turn, or wye train, 405, Late turn
NYP	19	03/14	5	5	Passenger and/or baggage
NYP	49	03/14	3	3	Other late crew, delayed departing NYS, due to OBS, released at 2:45pm
NYP	97	03/14	59	59	Service, turn, or wye train, 98, 28024 being shopped for batteries. The replacement car is 28000.
NYP	103	03/14	141	141	Service, turn, or wye train, 144, LATE TURN OFF AM144
NYP	155	03/14	3	3	Passenger and/or baggage, LOADING LAST MINUTE PSGR
NYP	241	03/14	14	14	Other electrical failure, 708
NYP	245	03/14	33	33	Other late crew, LATE F/SSYD A/C WAITING FOR CREWS
NYP	655	03/14	124	124	Service, turn, or wye train, 650
NYP	2203	03/14	20	20	Undesired emergency application, 2145, UNSPECIFIED MECHANICAL PROBLEMS
CHI	5	03/14	18	18	Wheelchair Pax Thomas, Mary (PNR 60E4DC) had been downgraded without notification from H room to lower level coach. This was not discovered until just prior to departure. Waited for red cap to provide a ride from 532 car to 510 car. Also needed ramps at both cars.
CHI	319	03/14	9	9	Door ID4126, Stairs would not retract
PDX	11	03/14	78		
PDX	28	03/14	1		
SEA	8	03/14	2	2	Conductor working alone/crew shortage.
SEA	518	03/14	45	22	Hold for bus with passengers from train
BFD	715	03/14	1	1	PTC- IETMS recycle breaker to clear fault C2106
FTW	1021	03/14	24	24	2131/2130 slprs were not made up coaches need to be cleaned up Other, FTW DEPO
LAX	4	03/14	1	1	Late bulletins/paperwork. 20 minutes past on duty time. Milepost, 0.0, 0.0
MHL	1022	03/14	24	24	Planned Switch Control Point, R066
OKJ	712	03/14	2	2	HEP 90218
OKJ	716	03/14	12	6	Wait for station track 534, Control Point, Martin Luther King
OKJ	716	03/14	12	6	PTC - On Board Cab Signal or PTC Failure 8303, Engineer had issue log on PTC

Amtrak Initial Terminal Details

Late Trains For:

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Region: ALL

Division: ALL

Data Through: 3/14/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	718	03/14	5	5	Emap 100 not signed by supervisor could not leave the yard on time pulls from the yard arriving at jack London around 5:35 90278
SAC	745	03/14	27	27	Hold for defect repair Rough track, Milepost, 82.5, 83.0
SAN	581	03/14	5	5	Other late crew Engineer late. CMS and mgmt aware, Other, SAN

Eastern Region

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	97.5	94.8	166	0
CDOT	95.0	100.0	97.7	92.4	16	0
MARC	95.0	82.3	82.6	90.2	62	11
SEPTA	95.0	94.8	95.4	91.5	96	5
NJT-NED	95.0	93.1	77.0	88.6	174	12
NJT-SED	95.0	100.0	99.6	97.2	22	0

Operating Highlights

Train 53(14) Florence, SC - Engine Failure

14MAR26: Train 53(14) operating with E/360, E/352, 16 passengers cars, 30 auto carriers and 406 passengers onboard, was delayed at the Florence, SC Station on CSX Charleston Subdivision due to engine issues. The engineer had stepped off E/360, when he went to step back, both engine were shut down. The engineer was able to get the rear motor, E/352, stated and providing head-end power. Road foreman was enroute to assist. The crew contacted CNOC Mechanical and they were able to get the lead E/360 restarted and they departed Florence.

Train	Delay	Comment
53(14)	26"	

Train 245(14) New York, NY - System

14MAR26: Train 245(14) operating with E/95, 5 cars, E/701 and 170 passengers onboard, was delayed departing New York, NY on Amtrak NYT Subdivision due to a late release from the yard and waiting on crew.

Train	Delay	Comment
245(14)	33"	

Train 53(14) North of Dillon, SC - Injured or Sick Passenger or Employee

14MAR26: Train 53(14) operating with E/360, E/352, 16 passengers cars, 30 auto carriers and 406 passengers onboard, was delayed at MP 242.7 approximately 20 miles north of Dillon, SC on CSX South End Subdivision due to a passenger with a medical emergency. EMS meet the train, examined the passenger and they remained on the train.

Train	Delay	Comment
53(14)	41"	

Train 128(14) Washington, DC - Engine Failure

14MAR26: Train 128(14) operating with E/661, E/602, 84 and 242 passengers onboard, was delayed departing Washington, DC on Amtrak Washington Union Terminal Subdivision due to head-end power (HEP) issues with E/602. E/602 was cut-out and Train 128(14) departed WAS with a single motor, E/661.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
128(14)	29"	

Train 164(14) Providence, RI - Passenger Related

14MAR26: Train 164(14) operating with operating with E/630, 10 cars and 433 passengers onboard, carried by 40 passengers that were scheduled for the Providence, RI Station on Amtrak New Haven to Boston Subdivision. Train 164(14) stopped at MP 186.00 approximately 1 mile east of the Providence Station, reversed back to the station to discharge the passengers. Once discharged, they proceeded to Boston, MA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
164(14)	33"	

Train 20(14) Meridian, MS - Signal

14MAR26: Train 20(14) operating with E/198, E/188, 9 cars and 138 passengers onboard, was delayed at Boligee / MP 242.7 approximately 53 miles north of Meridian, MS on NS AGS South District Subdivision due to a stop signal at Control Point Boligee, they were able to proceed once they received permission from the dispatcher.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(14)	55"	

Train 40(14) East of Tampa, FL - Vehicle on Tracks

14MAR26: Train 40(14) was delayed at MP 879.7, 2 miles east of Tampa, FL, on the CSX Tampa Terminal Subdivision due to a semi-truck on the tracks ahead at MP 881.2. The crew held while local law enforcement responded and tow truck arrived to remove vehicle. Once vehicle was removed, Train 40(14) proceeded.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(14)	1'15"	

Train 68(14) Rouses Point, NY - Customs and Immigration

14MAR26: Train 68(14) was delayed departing Rouses Point, NY on the CN Rouses Subdivision due to extended immigration and customs.

14MAR26: Train 68(14) was delayed meeting on-time Train 69(14) at MP 188.6. Once 69(14) passed, Train 68(14) was able to proceed south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(14)	1'10"	
68(14)	1'04"	PTI/MEET 69(14)
68(14)	02"	PTI/MEET 291(14)

Train 63(14) Buffalo, NY - Trespasser Incident

14MAR26: Train 63(14) 26-FOI-00381 00000006087 UNCLASSIFIED 4/29/2025 delayed departing Buffalo-Exchange Street Station on the CSX Niagara Subdivision due to a fare evading passenger. The crew held in station for local police to arrive and remove passenger, who locked themselves in restroom. Once the local police removed passenger, Train 63(14) departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
63(14)	36"	

Train 97(14) New York, NY - Bad Ordered Cafe

14MAR26: Train 97(14), E/653 and 10 cars, was delayed departing New York, NY due to cafe C/28024 being shopped for bad batteries. Once shopped car was removed from consist and replacement C/28000 was added, the crew took the equipment to the station. Once all passengers were boarded, Train 97(14) departed New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(14)	1'01"	

Train 20(14) East of New Orleans, LA - Freight Train Interference

14MAR26: Train 20(14), E/198-188 and 8 cars, was delayed at MP 7.6, 7 miles north of New Orleans, LA, on the NS No and Ne Subdivision due to NS130 in emergency ahead. Once freight inspected equipment and resolved issues, Train 20(14) was able to proceed east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(14)	45"	

Train 156(14) West of Lynchburg, VA - Freight Train Interference

14MAR26: Train 156(14), E/326 and 8 cars, were delayed at MP 20.0, 5 miles west of Lynchburg, VA, on the NS Blue Ridge Subdivision due to NS-19M building train at Lynchburg. The crew held while freight crew worked to build consist and clear route. Once route was clear, Train 156(14) proceeded east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
156(14)	1'53"	

PH Line East of Paoli, PA - Tree on Fire

14MAR26: At approximately 11:20 AM-ET, ACP notified a hold on all mainline tracks at MP-19.5 on the Amtrak PH-Main Line, approximately one-half mile east of Paoli, PA, due to local fire department personnel reporting tree on fire adjacent to mainline tracks.

Keystone westbound Train 643(14) held in Daylesford Septa Station/MP-18.6, and Keystone eastbound Train 650(14) held in Exton, PA station/MP-27.5, pending disposition. Upon arrival of local division supervision, at approximately 1:30 PM-ET no.4 track was released with speed restrictions for train movement at location. Due to responding IMCS/ET personnel requiring to de-energize no.1 track at location for local fire department response, plate-order was issued between Bryn Mawr and Paoli, and eastbound Keystone and Pennsylvanian frequencies were required to operate against the current of traffic (rule-251 territory), Downs/MP-32.1 to Overbrook/MP-5.4 via no.4 track at reduced speeds. Trains 650(14) and 42(14) had to make reverse moves west to Thorn in order to operate east through on no.4 track. As a result; multiple Keystone and Pennsylvanian frequencies were delayed between 30" to 4'00".

As of 607P-ET, SEPTA service was restored. As of 730P-ET, ET Foreman cleared tracks/catenary, restored power and normal service and operation resumed.

Train	Delay	Comment
652(14)	39"	pol
652(14)	14"	ARD-PHL/PTI
647(14)	1'41"	PHL - PAO
650(14)	4'48"	POL
650(14)	29"	ARD - TRE/PTI
645(14)	27"	POL
645(14)	02"	PTI
643(14)	2'30"	PHL - DOW/POL
643(14)	02"	PTI
42(14)	2'11"	LNC - PAO/POL
43(14)	1'09"	PHL - LNC/POL
161(14)	23"	PHL-Connects off 42
161(14)	08"	PHL - WIL/PTI
655(14)	2'04"	ITD- Equip turn off 650

Train 151(14) Philadelphia, PA - Shopped Coach

14MAR26: Train 151(14) was delayed departing Philadelphia, PA due to a late release from the yard account of shopping coach car C/82559. Once the car was shopped, the train completed its normal mechanical servicing then was released to the station.

Train	Delay	Comment
151(14)	1'05"	

PTC System Wide Outage

14MAR26: Amtrak performed a PTC test, "UNCLASSIFIED" experiencing multiple outages between 145AM-ET/1045PM-PT and 600AM-ET/300AM-PT system wide affecting several trains. Train experienced issues initializing PTC

Train	Delay	Comment
794 (14)	04"	OSD - SOL
14 (14)	01"	SAC -OKJ
777 (14)	30"	OXN - VEC
4 (13)	03"	GCK - DDG
6 (14)	19"	XSN - XNV
40 (13)	04"	PGH
6 (13)	04"	DEN - XID
4 (13)	09"	DDG
98 (14)	11"	RMT - PTB
49 (14)	1'06"	BUF - ERI
97 (14)	52"	FAY - XDI
59 (14)	17"	CDL
20 (14)	03"	ATN - ATL
21 (14)	39"	XKN - WNR
595 (14)	03"	OSD - X98
3 (13)	17"	KNG
5 (13)	15"	XSZ - XNV
7 (14)	49"	SCD - SPL
48 (14)	46"	BYN - TOL
2 (14)	06"	ALP
52 (14)	1'19"	XFL - XSE
11 (14)	05"	KFS - DUN

MBTA851 Derailment in Tower 1 Interlocking - Boston South Station, MA

13MAR26: At 3:35 PM-EDT, MBTA 26-FOI-00361 d 00000006087 in MBTA "UNCLASSIFIED" their 4/29/2026 b-car CC/828 over the no.98 switch in Tower-1 Interlocking while departing off station track no.7 at Boston South Station. No customer or employee injuries were reported. Customers were disembarked at location, and escorted back onto the station platform into Boston South Station for handling. As a result of this derailment, access to station tracks no. 7 through no.10 were blocked, resulting in significant delays arriving and departing Boston South Station, routing around the derailed MBTA equipment. In addition, inbound Train 162(13) equipment, scheduled to turn for outbound Train 167(13), was blocked-in on station track no. 9. As a result, Train 167(13) was cancelled in its entirety.

13MAR26: Due to the derailment, several trains were affect arriving and departing Boston, MA South Station due to track space and single tracking. Trains took significant delays due to having to be towed in/out of the station with a diesel engine. Train 194(13) terminated at the Back Bay Station and it's 225 customers found alternate transportation into Boston South Station.

13MAR26: at approximately 1205 AM-ET, the track supervisor advised that the cars were detached from derailed Keolis Train 851 and were pushed into the station due to a broken knuckle. At approximately 12458 AM-ET, the engine was rerailed and extra 118 took the equipment to the S&I pit. At approximately 128 AM-ET, all equipment was clear of the 98SW at tower 1. The car were set on track 7 where they will remain until the switch is repaired. ET took tracks out of service while they erected repairs.

14MAR26: Multiple trains were delayed departing Boston South Station due to the affected tracks still being out of service through the morning hours. A diesel locomotive towed electric power from the pit to the station. Once electric power was towed to station and coupled to equipment, the diesel cut away and boarding was able to commence. At 8:55AM-ET C&S reported no. 98 switch to have broken internals, thus resulting in further repairs needed and estimate of track restoration was extended. Due to the late operation of Train 168(13) into Philadelphia at 4:23 AM-ET, 2'38" late, Train 144(14) took a delay departing Philadelphia, PA due to servicing. At 12:27P- ET, partial repairs were made, eliminating the need to tow electric power to and from the yard and giving access to all station platforms. Train delays began to subside throughout the afternoon as equipment was able to move more efficiently between the yard and the station. Train 2255(14) was delayed departing due to the availability of yard crews to move equipment. Train 135(14) was delayed departing due to equipment needing to be serviced from being blocked in by derailed equipment. Once derailed equipment was removed and partial repair of the track was made, the crew was able to take equipment from 162(13), which was blocked in by derailed equipment prior day, to the yard to be serviced at 12:04P-ET.

Train 103(14) was delayed departing New York, NY due to the late operation of 144(14) arriving into New York at 10:36A-ET, 2 hours and 48 minutes late. This, also, caused Train 106(14) to be delayed departing Washington, DC with Train 103(14) arriving at 2:10P.

National Response Center Number: 1457132

Train	Delay	Comment
167(13)	CANCELLED	
150(14)	CANCELLED	
194(13)	TERM BBY	AR BBY 1012P, 48" LATE
168(13)	54"	RTE - BBY
2248(13)	34"	RTE - BBY
164(13)	39"	BBY
2252(13)	57"	PVD - BBY
88(13)	2'36"	RTE - BBY
65(13)	3'00"	BOS
169(13)	2'46"	BOS
82(13)	1'30"	PVD - RTE - BBY
194(13)	2'45"	RTE - BBY
2250(13)	10"	
448(12)	1'05"	
KELOIS TRAINS	5" - 1'41"	1 TERM/29 CANCELLED
103(14)	2'21"	Turn of 144(14) NYP
144(14)	3'00"	Turn of 169(13) PHL
106(14)	25"	Turn of 103(14) WAS
2271(14)	58"	ITD BOS
99(14)	25"	ITD BOS
161(14)	1'33"	ITD BOS
87(14)	2'22"	ITD BOS
163(14)	1'33"	ITD BOS
449(14)	53"	ITD BOS
2255(14)	31"	ITD BOS
135(14)	1'37"	ITD BOS
49/449(14)	55"	SVS - LATE 449(14)

Overhead Catenary Structure Failure at Old Portal - Catenary or Wayside Failure

13MAR26: At approximately 2:20 AM-EDT, catenary poles were reported leaning at Old Portal/MP-6.0 on the NYP-Main Line, approximately 6-miles west of New York. Upon arrival of IMC/ET personnel, multiple catenary poles were reported leaning at location due to a failed guy-wire. As a result, no.22 track was removed from service at location, between Old Portal and Old Swift/MP-7.2, and all traffic was held between New York and Newark pending disposition. At approximately 5:25 AM-EDT, no.3 track was placed into service between Hudson/MP-8.3 to Lack/MP-5.1 over North Portal Bridge, with absolute-block restrictions, and Train 66(12) continued eastward from Newark into New York. At approximately 5:45 AM-EDT, westbound hold was released at New York, and train operations resumed. As a result of this disruption, the following Northeast Corridor service adjustments were implemented:

- Train 648(13) cancelled in entirety, Harrisburg, PA to New York

Trains 144(13) and 103(13) were originally scheduled to Terminate and Originate at Newark, however it was decided to allow Train 144(13) to operate through upon arrival into NWK due to light eastbound traffic. Both trains operated normal late.

Due to the disruption, multiple trains were delayed between 15"-25" operating between Newark and New York. All affected Amtrak passengers were notified via Service-360 allowing impacted customers to self-accommodate to other available services, or request a refund. NJT reduced scheduled service down to 30" intervals from the Coast Line, and from Trenton (approximately 50% reduction of scheduled service).

Amtrak IMCS ET and Production staff report that no.22 track between Old Swift and Old Portal is expected to be returned to service by approximately 5:00 AM-EDT on Saturday March 14th. As a result, no further service adjustments are planned, and the current level of service will operate tomorrow, Saturday March 14th, as scheduled.

Train	Delay	Comment
66(12)	58"	
109(13)	05"	ITD NYP 52"
89(13)	25"	ITD NYP 11"
51(13)	29"	ITD NYP 10"
79(13)	12"	ITD NYP 18"
2201(13)	30"	
103(13)	37"	
127(13)	15"	
143(13)	22"	
2203(13)	45"	
2249(13)	21"	
144(13)	40"	
153(13)	49"	
155(13)	28"	
160(13)	37"	
162(13)	31"	
661(13)	33"	
101(13)	47"	ITD NYP 08"
118(13)	09"	
164(13)	10"	
147(13)	05"	
195(13)	28"	
644(13)	21"	
2205(13)	33"	
2223(13)	05"	
2248(13)	17"	
2250(13)	07"	
43(13)	06"	
54(13)	16"	
97(13)	20"	
99(13)	06"	
98(12)	12"	
87(13)	06"	
649(13)	07"	
150(13)	Cancelled	
648(13)	Cancelled	
607(13)	Cancelled	
135(13)	Originated PHL	
650(13)	11"	
2215(13)	09"	
140(13)	08"	
163(13)	09"	

CSX Trackwork effecting Carolinian, Floridian, and Northeast Regional Service - M of W Work

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

23FEB26: Due to CSX Trackwork on the North End subdivision between Petersburg, VA MP A42.0 and Rocky Mount, NC MP A104.0 from Monday February 23 to Monday March 2 and Monday March 9 to Monday March 16. The following service adjustments have been made for the Carolinian, Floridian and Northeast Regional Service.

Carolinian

- Train 80 (23Feb-16Mar) will operate 45-minutes LATER between CLT and RGH, 2-hours LATER between RGH and WAS, 2 hours 10-minutes LATER between WAS and PHL, and 2 hours 20-minutes LATER between PHL and NYP.

Floridian

- Train 40 (22Feb-15Mar) will operate on their normal schedule between MIA and SAV, and then will operate 1 hour 30-minutes LATER between SAV and RGH and 2 hours 45-minutes LATER between RGH and CHI.

Northeast Regional

- Train 94 (23Feb, 24Feb) will operate 3 hours 10-minutes LATER between NFK and WAS.

2/26/26 - Trains 40(25), 90(26), 80(26) and 79(26) were all delayed between Petersburg, NC and Rocky Mount, NC for a 4-way passenger train meet as a result of CSXM807 in penalty at Stony Creek Interlocking in the affected track work location..

3/11/26 - Trains 89(11) and 79(11) were delayed between Petersburg, NC and Rocky Mount, NC as a result of congestion throughout the affected track work location.

3/12/26 - Trains 40(11), 41(11), 80(12), 89(12), 90(12), 79(12), 52(11) and 53(12) were all delayed between Petersburg, NC and Rocky Mount, NC as a result of speed restrictions and congestion throughout the affected track work location.

WBS#: B.TR.100150.6471

Train	Delay	Comment
40(25)	27"	
79(26)	18"	
90(26)	12"	
80(26)	1'52"	PTI 40 / MW
89(11)	48"	
79(11)	25"	
40(11)	25"	
41(11)	20"	
52(11)	21"	
53(12)	39"	
79(12)	21"	
89(12)	17"	
90(12)	30"	
80(12)	44"	

Maintenance of Way Highlights

Long Bridge Replacement Outage - Scheduled M/W Work

26-FCI-00387 0000000608 UNCLASSIFIED 12/28/2026

18DEC25: Starting January 12, 2026 CSX Long Bridge replacement trackwork will commence causing reduced service and schedule changes extended through March 15, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

Several additional minor schedule changes have been made to additional Northeast Regional trains and also long distance Carolinian/Piedmont, Palmetto and Cardinal trains.

06MAR26: UPDATE - Schedule changes to the Carolinian/Piedmont, Palmetto, Cardinal and Northeast regional Train 178 will remain in effect until end of inventory.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 98(13) Passenger Removal at Richmond, Virginia – Improper Conduct

14MAR26, Passenger on PNR A3D333, traveling from Rocky Mount, NC to New York, NY was reportedly found smoking onboard. Amtrak Police notified.

Delay: 98 (13) None

Western Region

Operating Highlights

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Train 306(14) North of Summit, IL - Freight Train Interference

15MAR26: Train 306(14), operating with locomotive E/ID4624, five cars, and 111 customers onboard, was delayed on the CN Joliet Subdivision between Summit Station (MP 11.8) and the 21st Street Interlocking in Chicago due to congestion and freight traffic in the area. The train was required to stop twice—first near the Corwith Crossing area (MP 6.6) and again at Brighton Crossing (MP 5.3)—before being able to proceed. Once traffic conditions improved and the route was clear, Train 306(14) continued toward Chicago without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
306(14)	25"	Corwith
306(14)	27"	Brighton

Train 1022(14) Marshall, TX - Freight Train Interference

15MAR26: Train 1022(14), operating with locomotives E/69 and E/68, 6 cars, and 94 customers onboard, was delayed between Marshall, TX (MP 66.5) and Texarkana, AR (MP 490.3) on the UP Little Rock Subdivision due to freight train congestion in the territory. After meeting and waiting for multiple UP freight movements to clear, the route was eventually opened, and Train 1022(14) continued its trip toward Texarkana without further incident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1022(14)	33"	

Train 507(14) Portland, OR - Police Related

14MAR26: Train 507(14) was delayed upon departure from Portland, OR (PDX) at MP 0.1 on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. Train 507(14) was held by the Union Pacific Railway Dispatcher from crossing the Steel Bridge account a car reported on tracks at MP 769.62 on the Union Pacific Railway Brooklyn Subdivision with no route for train 507(14) to proceed. Once the vehicle was removed and track inspected, train 507(14) was able to resume operation at 7:00 PM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
507(14)	57"	

Train 777(14) Oxnard, CA - Signal

15MAR26: Train 777(14) operating with engine 2112, 6 coaches, and 94 customers, was delayed 5.5 miles west of Oxnard, CA, on UP Santa Barbara subdivision, due to wayside signal outage. This outage also affected a switch, requiring train 777(14) to have to manually operate a switch for their route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
777(14)	30"	
785(14)	53"	

Train 305(14) St. Louis, MO - Freight Train Interference

15MAR26: Train 305(14) was delayed with locomotive E/4607, 5 cars, and 56 customers was delayed 5 miles north of St. Louis, MO, on TRRA Merchants subdivision, due to holding behind work train NS259. Once the work train cleared and route was made available, train 305(14) was able to proceed.

Train	Delay	Comment
305(14)	1'02"	

Train 50(14) North of Rensselaer, IN - Freight Train Interference

14MAR26: Train 50(14), operating with locomotive E/304, 5 cars, and 110 customers onboard, was delayed approximately 4 miles north of Rensselaer, IN, after meeting CSX freight train Q642 at the Surrey Siding (MP 68.2) on the CSX Monon Subdivision. Once the meet was completed and the route was clear, Train 50(14) resumed its southbound movement.

Train	Delay	Comment
50(14)	39"	

Train 6(13) West of Denver, CO - High Wind Warnings

14MAR26: Train 6(13), operating with UP 5833, locomotive E/201, and 9 cars with 152 customers onboard, was delayed on the Union Pacific Moffat Tunnel Subdivision due to a high-wind warning. The train initially came to a stop west of Denver, CO at MP 22.6 when winds in the area exceeded the allowable operating threshold. Once the warning was downgraded from 80 mph to 60 mph, the train was permitted to advance to MP 19.1, where it was required to hold again for a second high-wind restriction in effect between MP 18 and MP 13. After authorization was granted and conditions improved, Train 6(13) continued its movement into Denver, CO without further delay.

Train	Delay	Comment
6(13)	1'25"	

Train 782(14) Burbank, CA - Commuter Train Interference

14MAR26: Train 782(14) was delayed at Burbank-Airport, CA (BUR) on the Southern California Regional Rail Authority Ventura Subdivision. A Metrolink train, 1270, had struck a trespasser between Burbank-Downtown (BBK) and Los Angeles, CA (LAX). Tracks were closed while local authorities responded to and investigated the incident. There was an extended delay waiting for the local Coroners office to arrive on scene and release the tracks. The following recovery plan was enacted account extended delays:

- "On-Time" Section of 782(14) operated from Los Angeles, CA (LAX) to San Diego, CA (SAN) using protect comet equipment.
- 593(14) operated from San Diego, CA (SAN) to Los Angeles, CA (LAX) using protect comet equipment.
- 782(14) advanced to Burbank-Downtown, CA (BBK) where crew expired on Hours of Service. Passengers were accommodated on Metrolink train 1278 from Burbank Downtown, CA (BBK) to Los Angeles, CA (LAX). In LAX through passengers to San Diego, CA (SAN) were accommodated on the next available southbound Surfliner train, 588(14)
- 777(14) held in Los Angeles, CA (LAX) for open track.

Once tracks were released by authorities train traffic was able to resume operations.

SERVICE RECOVERY: Service Recovery of complimentary snack packs and non-alcoholic beverages were provided on all affected trains.

WBS#: B.TR.100150.6544

Train	Delay	Comment
-------	-------	---------

Train 822(14) Gainesville, TX - Freight Train Interference

14MAR26: Train 822(14) was delayed departing with locomotives E/191 and E/204 and three cars, was delayed on the BNSF Fort Worth and Red Rock Subdivisions between Fort Worth, TX, and Ardmore, OK, due to meeting multiple freight trains ahead. The train first met BNSF 6332 at Ponder Siding (MP 376.6), then met Norfolk Southern 7616 at Metro Siding (MP 388.2), and later met BNSF 3853 at Gainesville Siding (MP 413.3). Once freight traffic cleared and the route was available, Train 822(14) continued northward toward Oklahoma City, OK without further delay.

Train	Delay	Comment
822(14)	2"	376.6
822(14)	13"	388.2
822(14)	29"	413.3

Train 732(14) Davis, CA - M of W Work

14MAR26: Train 732(14) was delayed departing Davis, CA (DAV) on the Union Pacific Railway Martinez Subdivision. There was a report of a track defect between Davis, CA (DAV) and Sacramento, CA (SAC) at MP 83.0 on the Yolo Causeway. Train traffic was halted in all directions waiting for a track and bridge inspection. Once the inspection was complete and no defects were found, train traffic was resumed with 732(14) departing DAV at 4:16 PM-PT.

Train	Delay	Comment
734(14)	28"	
745(14)	27"	
732(14)	1'36"	

Train 2(13) East of El Paso, TX - Freight Train Trespasser Strike

14MAR26: Train 2(13), operating with locomotives E/142 and E/175, 7 cars, and 130 customers onboard, was delayed departing El Paso, TX Station and again east of the station at MP 815.5 on the Union Pacific Valentine Subdivision. The delay resulted from UP freight train ZLAAI-13 striking a trespasser ahead at MP 799.2 at approximately 1:33 PM CT. Local authorities responded to the incident, and the Medical Examiner arrived at approximately 6:52 PM CT to complete recovery and scene remediation. The delay was prolonged further due to air issues on the involved freight train. Once the scene was cleared, track inspections were completed, and the territory was deemed safe for movement, Train 2(13) was authorized to continue eastward.

Service recovery was initiated onboard with sleeper meals unaffected. Coffee, Tea, water, and snack packs were provided.

Train	Delay	Comment
2(13)	6'24"	

Train 516(14) Bellingham, WA - Freight Train Interference

14MAR26: Train 516(14) was delayed north of Bellingham, WA (BEL) at MP 141.1 (CP Still Creek) on the Burlington Northern Santa Fe Railway New Westminster Subdivision. Train 516(14) was held for an opposing freight train, CPCK/7484 to clear the single main track ahead. Train 516(14) advanced to MP 153.5 (Fraser River Bridge) on the Canadian National New Westminster Subdivision where the train was again required to wait for a freight train, CN/5468, to clear the single main track ahead. Once the track ahead was clear, train 516(14) was able to proceed north at 1:18 PM-PT.

Train	Delay	Comment
516(14)	38	CP Still Creek
516(14)	35"	Fraser Bridge

Train 351(14) Pontiac, MI - Engine Failure

14MAR26: Train 351(14) was delayed beginning at MP25.9 on the CNRR Holly subdivision operating with ITCS cut out due to a mod light issues. Train 351(14) operated all the way MP240.57 at a reduced speed of 59MPH.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
351 (14)	44"	BTL-CHI
351 (14)	1'03"	PNT-BTL

Train 1(14) West of Lafayette, LA - Trespasser Incident

14MAR26: At 6:30AM, Train 1(14), E/15-E/151-9 Cars, struck a vehicle 5.9 miles west of Lafayette, LA/MP144.5.0, on the BNSF Lafayette Subdivision, at MP150.4. Located in the city of Lafayette, LA in Mecklenburg County. The vehicle was occupied at the time of the strike with 3 passengers. Emergency services and local PD responded to the scene and performed an investigation. Scene was released and train 1(14) was back on the move at 215PM CT.

There were no injuries to the crew or 122 passengers onboard. The crew did not request trauma relief. This incident occurred at a DOT crossing #763060R. The weather was 73 degrees and clear. Train 1(14) was operating 58MPH at the time of the strike. Head end power stayed on for the duration of the investigation. NRC 1457210.

National Response Center Number: 1457210

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1 (14)	1'10"	

Train 4(13) West of Albuquerque, NM - Freight Train Interference

14MAR26: Train 4(13) was delayed holding at MP129.3 , 129.3 miles west of Albuquerque, NM. station on the Amtrak Gallup subdivision due to congestion caused by a broke rail that created single track conditions. Train 4(13) held while 3 westbound freights cleared the single track. Train 4(13) was back on the move at 1059AM MT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4 (13)	52"	

Train 365(13) West of East Lansing, MI - Freight Train Interference

14MAR26: Train 365(13) was delayed beginning at MP223.4, 0.4 miles west of East Lansing, MI station on the CN Flint subdivision routing around disabled CN freight 3278 until MP215.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
365 (13)	31"	

Train 11(13) North of Chico, CA - Freight Train Interference

14MAR26: Train 11(13) was delayed beginning at MP212.3, 22.09 miles north of Chico, CA (CIC). station on the UPRR Valley sub division due to freight MPDRVb-12 stopped with a right end drawbar. Freight crew pulled the train ahead and set out the car in the Anita siding. Once the setout was complete the crew recoupled to the rest out of the consist and shoved back at Gerber/MP214.9. Once the freight cleared north, train 11(12) proceeded out of the siding and was back on the move at 8:10 AM PT. The crew on train 11(13) did not have sufficient hours of service to complete the trip to Sacramento, CA (SAC). A replacement crew was dispatched from SAC to meet train 11(13) at CIC.

UPDATE: Train 11(13) incurred further delay at San Luis Obispo, CA (SLO) on the Union Pacific Railway Santa Barbara Subdivision. The calendar day inspection on the locomotives was set to expire prior to arrival in Los Angeles, CA (LAX). The outbound crew at SLO was required to perform and complete the inspection prior to departing. Once the inspection was complete train 11(13) departed SLO.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(13)	4'00"	
11(13)	29"	CIC - hold for recrew
11(13)	1'30"	SLO - Calendar Day Inspection

Train 48(13) West of Elyria, OH - Freight Train Interference

14MAR26: Train 48(13) was delayed beginning at MP224, 20.6 miles west of Elyria OH station on the Norfolk Southern Cleveland Toledo subdivision following freight N16 until MP206.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48(13)	35"	

Train 370(13) East of Grand Rapids, MI - Utility Company Failure

14MAR26: Train 370(13) operating with engine 4627, 4 coaches and 61 customers was terminated 2 miles west of Grand Rapids, MI, on CSX Grand Rapids Term subdivision, due to power lines being down interfering with the right of way. With no ETA on a track inspector or the power company, the decision was made to source a bus to accommodate customers. The bus arrived approximately 1:20am-et, meanwhile, train 370(13) reversed a few feet to get to a more favorable location to detrain customers. Once in position, train 370(13) customers detrained and boarded the bus to continue to Grand Rapids. 370(13) equipment waited for the power company to clear the downed wires from the tracks.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
370(13)	term XHV	

Train 5(12) West of Helper, UT - Engine Failure

14MAR26: Train 5(12), 26-FOI-00361, 0000000087, UNCLASSIFIED, 4/29/2026, consisted of 6 Engines, 23 and 14, and 142 coaches, and 142 customers, experienced multiple mechanical issues that significantly impacted its operation 21 miles west of Helper, UT, on UP Provo subdivision at milepost 647.8. The initial problem occurred with the lead locomotive, Engine 23, which developed fuel pump issues. As a result, the crew isolated Engine 23 and continued operating with a single locomotive. This mechanical failure caused Train 5(12) to depart approximately 23 minutes late. Union Pacific (UP) was contacted to source a replacement locomotive, and UP identified freight locomotive UP8154, located in Sparks, Nevada, as a unit that would eventually be provided to support Train 5(12).

While operating westbound with Engine 23 isolated, the train encountered further difficulties when the remaining locomotive, Engine 14, began to overheat while ascending a 2 percent grade west of Helper, Utah, near milepost 654. The train was forced to stop multiple times due to repeated overheating faults on Engine 14. The crew was able to stop and reset the fault several times and initially believed the overheating was caused by the sustained grade. They attempted to manage the situation by stopping periodically to allow the locomotive to cool, waiting approximately ten minutes between attempts. Although the crew expected the overheating to subside once the train cleared the grade, the issue persisted.

As Train 5(12) continued to make slow westward progress with repeated cooling stops, a longer-term recovery plan was implemented to stabilize operations. UP identified locomotive UP5833 in Salt Lake City, Utah, and scheduled a crew to report on duty at 2:15 a.m. Mountain Time to move that unit into position. Additionally, when Train 6(13) arrived in Salt Lake City, it was planned that its lead unit, Engine 37, would be cut from the consist, wye'd, and placed on the rear of Train 6(13), while UP5833 would be added to the head end. Train 6(13) was then scheduled to deliver Engine 37 to Train 5(12) en route. In conjunction with this plan, Train 5(12) was still scheduled to receive freight locomotive UP8154 in Sparks, providing the necessary additional power to fully resolve the mechanical challenges and restore reliable operation.

As service recovery, snack packs, water, tea and coffee were provided to customers. Normal dinner service was feld for sleeping car customers.

WBS # B.TR.100150.6542 has been issued.

WBS#: B.TR.100150.6542

Train	Delay	Comment
5(12)	4'07"	HER-PRO
6(13)	1'52	Engine Move
5(12)	1'17"	RNO - CALENDAR DAY INSPECT
14(14)	1'04"	CONNECTIONS

Winter Storm Iona Service Adjustments - Weather

14MAR26: The following service adjustments are in effect due to Winter Storm Iona:
Train 1333(15) will terminate MKE with no alternate transportation.
Train 1340(15) will originate MKE with no alternate transportation
Train 370(15) and 371(16) are cancelled in their entirety with no alternate transportation.

North of Kelso, WA BNSF Mudslide / 48hr Moratorium on Passenger Trains

13MAR26: Beginning 12:20PM-PT, Friday March 13th, 2026 the BNSF Railway imposed a 48-HR Moratorium on passenger conveying services between Portland and Seattle in both directions. This was a result of heavy rainstorms dumping debris and mud with

UPDATE: A third qualifying blocking event was reported at the same location, extending the moratorium thru 5:30PM-PT on 15th March.

Passenger services were suspended until 2:30PM-PT Sunday, 15TH March 2026 with ticket sales suspended.

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

The following amended train plan was instigated:

Train 504(13) returned to Portland shortly after arriving Kelso. Replacement buses were arranged in Portland to take passengers stations Centralia thru Seattle.

Train 517(13) Returned to Seattle from Tacoma Dome. Passengers transferred to replacement buses in Seattle thru to Portland.

Train 507(13) - Originates Portland - Replacement buses available to stations Seattle thru Portland.

Train 507(13) returned to Seattle shortly after departing Tacoma. Replacement buses were not available. Passengers required to wait for replacement buses for 511(13) for stations to Seattle.

Train 14(12-13-14) Terminated Portland - Replacement bus service operated for stations to Seattle. The original plan to operate the train deadhead thru to Seattle was abandoned when trains experienced lengthy delays waiting for a route thru the area of the blocking event. The train operated deadhead back to Portland to be serviced/turned for 11(27) Originating in Portland.

Train 503(14-15) Originates Portland - Replacement bus service operates Seattle to Portland.

Train 505(14-15) Cancelled - Replacement bus service operates Seattle stations to Portland.

Train 517(14-15) Terminates Seattle - Replacement bus service operates Seattle stations thru to Portland.

Train 507(13-14-15) Originates Portland - Replacement bus service operates Seattle to stations thru Portland.

Train 509(13-14) Cancelled - No alternate buses available. Passengers required to utilize replacement buses for 511(13)

Train 511(13-14) Cancelled - Replacement bus service operates Seattle to Portland.

Train 500(14-15) Cancelled - Replacement bus service operates Portland Thru to Seattle.

Train 502(14-15) Cancelled - Replacement bus service operates Portland Thru to Seattle.

Train 504(14-15) Terminates Portland - Replacement bus service operates Portland Thru to Seattle

Train 518(13-14-15) Originates Seattle - Replacement bus service operates Portland Thru to Seattle.

Train 506(13-14) Cancelled - Replacement bus service operates Portland Thru to Seattle.

Train 508(13-14) Terminates Eugene - Replacement bus service operates Portland Thru to Seattle.

Train 518(13-14-15) Originates Seattle- Replacement bus service operates Portland thru to Seattle.

Train 11(14-15) Originates Portland - Replacement bus service operates stations Seattle to Portland for passengers. Train operates deadhead Seattle to Portland.

Train 14(12-13-14) Terminates Portland - Replacement bus service operates to stations to Seattle for passengers. Train operates deadhead Portland Thru to Seattle.

Service Recovery: Passengers delayed on trains 517(13), 504(13) were offered complimentary soft drinks and snack packs.

WBS#: B.TR.100150.6541

Train

Delay

Comment

504(13)	Returned to Portland	Buses Centralia- Seattle
517(13)	Returned to Seattle	Buses Olympia - Portland
509(13-14)	Cancelled	Replacement Buses Operate
511(13-14)	Cancelled	Replacement Buses Operate
503(14-15)	Originates Portland	Replacement Buses Operate
505(14-15)	Cancelled	Replacement Buses Operate
517(14-15)	Terminates Seattle	Replacement Buses Operate
517(14-15)	Terminates Seattle	Replacement Buses Operate
500(14-15)	Cancelled	Replacement Buses Operate
502(14-15)	Cancelled	Replacement Buses Operate
504(14-15)	Terminates Portland	Replacement Buses Operate
504(13)	Returned to Portland	Replacement Buses Centralia - Seattle
506(13-14)	Cancelled	Replacement Buses Operate
508(13-14)	Terminates Portland	Replacement Buses Operate
11(14)	Originates Portland	Replacement Buses Operate
14(12-13)	Terminates Portland	Replacement Buses Operate
507(13-14-15)	Originates Portland	Replacement Buses Operate
518(13-14-15)	Originates Seattle	Replacement Buses Operate

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

05JAN26- 13MAR26

- TRAIN 714 (05JAN-12MAR) Cancelled - No alternate transportation.
- TRAIN 713 (06JAN-13MAR) Cancelled - No alternate transportation.

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

10JAN26 - 11JAN26

- Train 736 (10-11) Cancelled - No alternate transportation.
- Train 737 (10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

- Train 520 (12-13) Cancelled - No alternate transportation.
- Train 534 (12-13) Cancelled - No alternate transportation.
- Train 535 (12-13) Cancelled - No alternate transportation.

14JAN26:

- Train 520 (14) Cancelled - No alternate transportation.
- Train 537 (14) Cancelled - No alternate transportation.
- Train 534 (14) Cancelled - No alternate transportation.

15JAN26:

- Train 520 (15-16) Cancelled - No Alternate Transport offered
- Train 534 (15-16) Cancelled - No Alternate Transport offered
- Train 535 (16) Cancelled - No Alternate Transport offered
- Train 537 (15) Cancelled - No Alternate Transport offered

17JAN26:

- Train 718 (17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744 (17) OKJ-EMY.

21JAN26:

- Train 526 (21) Cancelled - No Alternate Transport offered
- Train 534 (21) Cancelled - No Alternate Transport offered
- Train 535 (21) Cancelled - No Alternate Transport offered

23JAN26:

- Train 520 (23) Cancelled - No Alternate Transport offered
- Train 534 (23) Cancelled - No Alternate Transport offered
- Train 535 (23) Cancelled - No Alternate Transport offered
- Train 736 (23JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 737 (23JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 520 (26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 526 (26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 534 (26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 531 (26JAN-01MAR) Cancelled - No Alternate Transportation.
- Train 537 (26JAN-01MAR) Cancelled - No Alternate Transportation.

01FEB26:

- Train 732 (01FEB) Cancelled - No Alternate Transportation.
- Train 749 (01FEB) Cancelled - No Alternate Transportation.
- Train 712 (02FEB-04FEB) Cancelled - No Alternate Transportation.
- Train 717 (02FEB-04FEB) Cancelled - No Alternate Transportation.

14MAR26:

- Train 714 (14MAR-30APR) Cancelled - No Alternate Transportation.
- Train 713 (15MAR-01MAY) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
-------	-------	---------

715(21)	Terminate	Passengers to bus 6615 EMY-OKJ-SFC
	EMY	
718(21)	Originate	Passengers to 744(21) OKJ-EMY
	EMY	
718(22)	Originate	Passengers to 544(22) OKJ-EMY
	EMY	
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
718(17)	Originate	Pax to 744 OKJ-EMY
	EMY	
718(17)	35"	

Maintenance of Way Highlights

UPRR Mineola Subdivision Track Work - Scheduled M/W Work

11MAR26: Union Pacific Railroad has trackwork scheduled on their Mineola Subdivision between Fort Worth, TX and Longview, TX, on numerous dates between Thursday March 12th and Tuesday, April 28th, 2026. To accommodate this infrastructure work, Amtrak's Texas Eagle Service has been adjusted as follows:

-Train 21(12Mar-16Mar, 23Mar-30Mar, 6Apr-12Apr, 20Apr-27Apr), which operates between Chicago and San Antonio, will utilize a bus bridge in lieu of train service between Marshall and Fort Worth. The Fort Worth to San Antonio section will operate as Train 1021(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr) and will operate 80-minutes later between Fort Worth and San Antonio, departing Fort Worth at 3:48pm.

Train 421(13Mar, 15Mar, 24Mar, 27Mar, 29Mar, 7Apr, 10Apr, 12Apr, 21Apr, 24Apr, 26Apr), which normally operates between Chicago and Los Angeles, will originate at Fort Worth and will operate 80-minutes later between Fort Worth and San Antonio, departing Fort Worth at 3:48pm.

-Train 22(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr), which operates between San Antonio and Chicago, will utilize a bus bridge in lieu of train service between Fort Worth and Marshall. The Marshall to Chicago section will operate as Train 1022(13Mar-17Mar, 24Mar-31Mar, 7Apr-13Apr, 21Apr-28Apr) and will operate 2-hours later between Marshall and St. Louis (departing MHL at 9:29pm), and 2 hours 15-minutes later between St. Louis and Chicago (departing St. Louis at 10:25am).

-Train 422(11Mar, 13Mar, 15Mar, 22Mar, 25Mar, 27Mar, 29Mar, 5Apr, 8Apr, 10Apr, 19Apr, 22Apr, 24Apr, 26Apr), which normally operates between Los Angeles and Chicago, will terminate at Fort Worth.

ALTERNATE TRANSPORTATION

-Bus 3021 will provide alternate transportation at Marshall, Longview, Mineola, Dallas, and Fort Worth

-Bus 3022 will provide alternate transportation at Fort Worth, Dallas, Mineola, Longview, and Marshall

**Please Note: During trackwork days, Bus 6022 from Houston and Buses 6122 and 6421 from Shreveport will be redirected to Marshall, instead of Longview, and Bus 6021 to Houston and Buses 6121 and 6422 to Shreveport will depart from Marshall.

WBS#: B.TR.100150.6297

Western Region

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
1003 (7)	ABQ	44		BRAKE APPARATUS MELTED TO WHEEL

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (12)	RNO	UP8154	E/23 fuel pump//E/14 Overheating	EMY	
6 (13)	SLC	UP5833	E/37 cut for 5 (12)	CHI	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 584(13) Passenger Removal at Fullerton, California – Fare Evader

14MAR26, Unknown Male Passenger traveling without a reservation, attempted to travel from Los Angeles, CA to San Diego, CA was reportedly discovered in the business class car without a ticket and several electronic items plugged into outlets. The traveler was recognized as a repeat fare evader and was told to exit while doing so he became verbally abusive. Amtrak Police notified.

Delay: **584(13)** **05"**

Train 581(14) Passenger Removal at Fullerton, California – Fare Evader

14MAR26, Unknown Passenger traveling without a reservation, attempting to travel from Fullerton, CA to Los Angeles, CA reportedly had no identification and no means to purchase a fare. The traveler was removed from travel. Amtrak Police notified.

Delay: **581(14)** **None**

26-FBI-00361 00000006087 "UNCLASSIFIED" 4/29/2026
Train 782(14) Passenger Removal at Santa Barbara, California – Fare Evader

14MAR26, Unknown Male and Unknown Female Passengers traveling without a reservation were discovered attempting travel from Goleta, CA to Los Angeles, CA reportedly refused to purchase tickets. The travelers were asked to leave and initially refused to exit. However, they finally thought better and left. Amtrak Police notified.

Delay: 782(14) 03"

Train 2(13) Passenger Removal at El Paso, Texas – Medical

14MAR26, Passenger on PNR 777F8D, traveling from Los Angeles, CA to Schriever, LA was reportedly found unresponsive in a lower-level restroom. Paramedics assisted with CPR and transported the traveler to a local hospital for evaluation. Local Police have this incident logged at Police Report# 26-073139. Amtrak Police notified.

Delay: 2(13) None

Consist Deviations

26-FOI-00361

00000006087

"UNCLASSIFIED"

4/29/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
695 (14)	BON	NO CAFE SERVICE	Pax notified	175	
695 (14)	BON	NO BUSINESS CLASS DUE NO POWER (480)	0	0	
163 (14)	BOS	DUE TO SHOPPED EQUIP CLUB DINE WILL OPERATE IN LIEU OF CAFE CAR	0	0	43349
694 (14)	BRK	NO FOOD SERVICE	Pax notified	165	
694 (14)	BRK	NO BUSINESS CLASS DUE NO POWER (480)	0	0	
3 (14)	CHI	Utilizing SLpr in lieu of T-dorm due to 39038 shipped and no replacement on yd. Schedule change has been performed for out bound and return 4(16). Will need to block FS and all DS rooms.	0	0	32098
381 (14)	CHI	49/68-seat married pair used in lieu of venture cafe pair. y inventory increased.	0	0	ID4101, ID4207
790 (14)	GTA	NO BIKE SERVICE	Pax notified	6	90215
580 (14)	LAX	NO BIKE SERVICE	No impact	0	90225
4 (16)	LAX	Utilizing SLpr in lieu of T-dorm due to 39038 shipped and no replacement on yd. Schedule change has been performed. Will need to block FS and all DS rooms.	0	0	32098
782 (14)	LAX	OTP at LAX with comet set. NO BUSINESS CLASS, CAFE, or BIKE SERVICE. lax-san	NO JY LAX-SAN -65 NO BV -1	66	
382 (14)	QCY	49/68-seat married pair used in lieu of venture cafe pair. y inventory increased.	0	0	ID4101, ID4207
769 (14)	SAN	NO BIKE SERVICE	Pax notified	4	90215
567 (14)	SAN	NO BIKE SERVICE	No impact	0	90225
591 (14)	SAN	NO BIKE SERVICE	No impact	0	90225
593 (14)	SAN	NO BUSINESS CLASS, CAFE, or BIKE SERVICE. Operating with Comet set	NO JY -24 / NO BIKE	24	

Reverse Consists

Train Number	Station	Reason
109 (14)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00361	00000006087
153 (14)	NYP	Consist reversed Business class seat orientation may have changed At Front	"UNCLASSIFIED" 4/29/2026
155 (14)	NYP	Consist reversed Business class seat orientation may have changed At Front	
161 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front	
94 (15)	NFK	Consist reversed Business class seat orientation may have changed At Front	
168 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front	
142 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front	
128 (14)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
127 (14)	NYP	Business class seat orientation is reversed on head end	
126 (14)	WAS	Business class seat orientation is reversed on rear end	
146 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front	
147 (15)	SPG	Consist reversed Business class seat orientation may have changed At Front	