



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, December 21, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/20/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	273	49	82.1%	6,096	968	84.1%	24,005	3,158	86.8%
Central Division	85.5%	68	13	80.9%	1,318	229	82.6%	5,340	598	88.8%
Northeast Division	80.0%	81	14	82.7%	1,962	309	84.3%	7,558	1,061	86.0%
Southeast Division	72.5%	58	9	84.5%	1,398	235	83.2%	5,597	752	86.6%
Southwest Division	77.0%	66	13	80.3%	1,418	195	86.2%	5,510	747	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance

26-FOI-00197 00000005537 Endpoint Arrival Dates through 12/20/25 UNCLASSIFIED 12/23/2025

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%			-			-			-
	%			-			-			-

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005507 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 20, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	126,401	2,162,142	585	456,283	8,670,935	526

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	5,902	638,561	92	18,257	2,540,797	72
INFRASTRUCTURE PLANNED	135	3,396	638,561	53	13,977	2,540,797	55
FLEET RELIABILITY	90	23,603	2,162,142	109	71,487	8,670,935	82
TRAIN OPERATIONS	424	93,487	2,162,142	432	352,549	8,670,935	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/20/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	273	49	82.1%	6,096	968	84.1%	24,005	3,158	86.8%
Central Division	85.5%	68	13	80.9%	1,318	229	82.6%	5,340	598	88.8%
Northeast Division	80.0%	81	14	82.7%	1,962	309	84.3%	7,558	1,061	86.0%
Southeast Division	72.5%	58	9	84.5%	1,398	235	83.2%	5,597	752	86.6%
Southwest Division	77.0%	66	13	80.3%	1,418	195	86.2%	5,510	747	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/20/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	273	49	82.1%	6,096	968	84.1%	24,005	3,158	86.8%
Central Division	85.5%	68	13	80.9%	1,318	229	82.6%	5,340	598	88.8%
CDL	90.0%	1	0	100.0%	21	2	90.5%	135	8	94.1%
CHI	85.0%	27	8	70.4%	535	117	78.1%	2,168	254	88.3%
CHM	-	1	0	100.0%	11	4	63.6%	11	4	63.6%
DEN	-	1	1	0.0%	2	1	50.0%	2	1	50.0%
EUG	86.5%	2	0	100.0%	39	5	87.2%	156	20	87.2%
GRR	98.0%	1	0	100.0%	19	2	89.5%	80	2	97.5%
KCY	84.5%	2	0	100.0%	40	3	92.5%	160	14	91.3%
MKE	86.5%	6	1	83.3%	118	14	88.1%	474	44	90.7%
MSP	94.0%	1	0	100.0%	20	0	100.0%	81	3	96.3%
PDX	78.0%	5	0	100.0%	100	11	89.0%	406	57	86.0%
PNT	91.5%	3	0	100.0%	59	12	79.7%	185	17	90.8%
PTH	93.0%	1	0	100.0%	19	4	78.9%	80	6	92.5%
QCY	87.5%	2	1	50.0%	40	4	90.0%	162	16	90.1%
SEA	80.0%	8	1	87.5%	158	26	83.5%	643	100	84.4%
SPK	92.0%	1	0	100.0%	23	5	78.3%	84	6	92.9%
STL	88.0%	3	0	100.0%	77	17	77.9%	319	35	89.0%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	1	50.0%	35	2	94.3%	157	6	96.2%
WIP	-	1	0	100.0%	2	0	100.0%	2	0	100.0%
Northeast Division	80.0%	81	14	82.7%	1,962	309	84.3%	7,558	1,061	86.0%
ALB	91.5%	8	0	100.0%	160	10	93.8%	527	31	94.1%
BON	43.5%	5	0	100.0%	100	6	94.0%	387	38	90.2%
BOS	86.5%	15	2	86.7%	378	51	86.5%	1,476	154	89.6%
BRK	88.0%	5	0	100.0%	100	4	96.0%	367	17	95.4%
BTN	48.0%	1	0	100.0%	20	0	100.0%	80	17	78.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	40	5	87.5%	156	14	91.0%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	20	3	85.0%	81	14	82.7%
NFL	96.5%	2	0	100.0%	40	1	97.5%	162	5	96.9%
NHV	75.5%	4	1	75.0%	112	13	88.4%	419	76	81.9%
NYP	77.5%	30	7	76.7%	815	208	74.5%	3,191	638	80.0%
SAB	98.0%	1	0	100.0%	20	0	100.0%	79	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	3	50.0%	137	5	96.4%	486	21	95.7%
TWO	84.0%	1	0	100.0%	20	3	85.0%	80	19	76.3%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	58	9	84.5%	1,398	235	83.2%	5,597	752	86.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	100	6	94.0%	405	31	92.3%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	7	2	71.4%	230	63	72.6%	910	161	82.3%
LOR	69.5%	1	0	100.0%	20	1	95.0%	81	6	92.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/20/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/20/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	273	49	82.1%	6,096	968	84.1%	24,005	3,158	86.8%
Southeast Division	72.5%	58	9	84.5%	1,398	235	83.2%	5,597	752	86.6%
MIA	87.5%	2	0	100.0%	40	5	87.5%	162	18	88.9%
MOE	94.0%	2	0	100.0%	40	0	100.0%	162	3	98.1%
NFK	86.0%	3	0	100.0%	58	9	84.5%	228	24	89.5%
NOL	92.0%	5	1	80.0%	89	5	94.4%	358	19	94.7%
NPN	96.0%	2	1	50.0%	40	3	92.5%	137	10	92.7%
PGH	92.0%	1	0	100.0%	20	2	90.0%	81	3	96.3%
PHL	45.0%	4	4	0.0%	93	59	36.6%	374	182	51.3%
RGH	97.0%	4	0	100.0%	80	4	95.0%	320	7	97.8%
RNK	85.5%	2	0	100.0%	40	5	87.5%	161	19	88.2%
RVM	86.0%	1	0	100.0%	20	2	90.0%	91	13	85.7%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	20	2	90.0%	81	2	97.5%
SFA	70.5%	1	0	100.0%	20	0	100.0%	81	3	96.3%
WAS	70.0%	17	1	94.1%	488	69	85.9%	1,957	246	87.4%
Southwest Division	77.0%	66	13	80.3%	1,418	195	86.2%	5,510	747	86.4%
ARN	60.5%	1	0	100.0%	20	1	95.0%	81	6	92.6%
BFD	75.5%	7	2	71.4%	132	27	79.5%	479	111	76.8%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	25	14	44.0%	88	31	64.8%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	20	0	100.0%	80	3	96.3%
GTA	72.5%	3	0	100.0%	60	2	96.7%	236	19	91.9%
LAX	77.5%	9	2	77.8%	187	24	87.2%	747	85	88.6%
OKC	96.0%	1	0	100.0%	20	0	100.0%	81	3	96.3%
OKJ	79.0%	9	3	66.7%	228	68	70.2%	888	220	75.2%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	12	1	91.7%	285	32	88.8%	1,073	118	89.0%
SAN	77.0%	12	4	66.7%	232	14	94.0%	925	79	91.5%
SAS	85.0%	1	0	100.0%	20	1	95.0%	81	4	95.1%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	140	9	93.6%	565	49	91.3%
SLO	62.0%	2	1	50.0%	40	2	95.0%	157	13	91.7%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	112	20	5	75.0%	81	9	88.9%	19	10	47.4%	80	33	58.8%
4		19	6	68.4%	80	12	85.0%	19	15	21.1%	80	53	33.8%
5		20	7	65.0%	80	14	82.5%	19	6	68.4%	78	12	84.6%
6		18	7	61.1%	79	24	69.6%	18	5	72.2%	79	26	67.1%
7		20	4	80.0%	81	8	90.1%	16	6	62.5%	77	13	83.1%
8	102	20	13	35.0%	81	33	59.3%	20	11	45.0%	81	38	53.1%
11	68	20	3	85.0%	80	14	82.5%	20	4	80.0%	78	11	85.9%
14		20	1	95.0%	81	10	87.7%	20	1	95.0%	80	19	76.3%
19	58	20	6	70.0%	81	14	82.7%	20	2	90.0%	81	13	84.0%
20		20	0	100.0%	81	6	92.6%	20	1	95.0%	81	7	91.4%
21		20	5	75.0%	80	13	83.8%	20	5	75.0%	80	16	80.0%
22		20	1	95.0%	81	4	95.1%	20	3	85.0%	80	16	80.0%
23		20	0	100.0%	81	3	96.3%	20	1	95.0%	81	11	86.4%
24	21	20	4	80.0%	81	6	92.6%	20	2	90.0%	81	8	90.1%
25	29	20	0	100.0%	81	0	100.0%	20	1	95.0%	81	10	87.7%
26	20	20	0	100.0%	81	2	97.5%	20	1	95.0%	81	12	85.2%
27		20	4	80.0%	81	5	93.8%	19	7	63.2%	80	17	78.8%
28	107	19	4	78.9%	80	17	78.8%	19	2	89.5%	80	10	87.5%
40	131	20	4	80.0%	81	13	84.0%	20	9	55.0%	81	31	61.7%
41		20	11	45.0%	81	29	64.2%	20	13	35.0%	81	52	35.8%
42		20	2	90.0%	81	3	96.3%	20	2	90.0%	81	11	86.4%
43		20	2	90.0%	81	7	91.4%	20	1	95.0%	81	4	95.1%
48	116	20	8	60.0%	81	13	84.0%	20	6	70.0%	81	9	88.9%
49	32	20	2	90.0%	81	12	85.2%	20	7	65.0%	81	12	85.2%
51		8	3	62.5%	35	17	51.4%	8	2	75.0%	34	11	67.6%
52		20	0	100.0%	81	3	96.3%	20	2	90.0%	81	14	82.7%
53		20	1	95.0%	81	6	92.6%	20	4	80.0%	81	12	85.2%
54		5	0	100.0%	24	0	100.0%	5	1	80.0%	24	2	91.7%
57		5	0	100.0%	24	1	95.8%	5	1	80.0%	24	1	95.8%
58		20	1	95.0%	80	3	96.3%	20	4	80.0%	79	11	86.1%
59	88	20	3	85.0%	79	6	92.4%	20	3	85.0%	79	6	92.4%
63	92	20	8	60.0%	81	29	64.2%	20	13	35.0%	81	42	48.1%
64		20	3	85.0%	80	19	76.3%	20	7	65.0%	80	17	78.8%
65	69	6	1	83.3%	25	4	84.0%	5	2	60.0%	24	7	70.8%
66		20	2	90.0%	81	12	85.2%	20	1	95.0%	81	14	82.7%
68		20	3	85.0%	81	14	82.7%	20	13	35.0%	81	38	53.1%
69		20	2	90.0%	81	9	88.9%	20	3	85.0%	81	10	87.7%
71	11	20	1	95.0%	81	1	98.8%	20	6	70.0%	81	22	72.8%
72		20	3	85.0%	81	8	90.1%	20	8	60.0%	81	18	77.8%
73	20	20	2	90.0%	81	3	96.3%	20	7	65.0%	80	40	50.0%
74		20	1	95.0%	81	6	92.6%	20	4	80.0%	81	24	70.4%
75		20	0	100.0%	81	2	97.5%	20	7	65.0%	81	35	56.8%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-EOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		20	0	100.0%	81	4	95.1%	20	4	80.0%	81	34	58.0%
77		20	1	95.0%	81	3	96.3%	20	7	65.0%	81	29	64.2%
78		20	0	100.0%	81	3	96.3%	20	2	90.0%	81	11	86.4%
79		20	6	70.0%	81	17	79.0%	20	3	85.0%	80	14	82.5%
80		20	2	90.0%	81	10	87.7%	20	5	75.0%	80	10	87.5%
82		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
87		5	1	80.0%	24	5	79.2%	5	1	80.0%	24	5	79.2%
88		5	0	100.0%	24	1	95.8%	5	1	80.0%	24	3	87.5%
89		20	5	75.0%	81	17	79.0%	20	7	65.0%	81	13	84.0%
90		20	2	90.0%	81	2	97.5%	20	3	85.0%	81	9	88.9%
97		20	14	30.0%	81	32	60.5%	20	3	85.0%	81	19	76.5%
98	58	20	1	95.0%	81	5	93.8%	20	9	55.0%	81	20	75.3%
99		5	0	100.0%	24	1	95.8%	5	2	60.0%	23	10	56.5%
101		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
103		5	0	100.0%	24	3	87.5%	5	1	80.0%	24	1	95.8%
106		5	1	80.0%	24	2	91.7%	5	1	80.0%	24	3	87.5%
107		5	2	60.0%	24	4	83.3%	5	1	80.0%	24	2	91.7%
118		5	1	80.0%	24	2	91.7%	5	1	80.0%	24	1	95.8%
124		5	0	100.0%	24	2	91.7%	5	0	100.0%	24	4	83.3%
135	31	5	1	80.0%	24	3	87.5%	5	3	40.0%	24	12	50.0%
136		15	2	86.7%	57	5	91.2%	15	1	93.3%	58	4	93.1%
140		5	0	100.0%	24	2	91.7%	5	1	80.0%	24	5	79.2%
142		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
143		5	0	100.0%	24	2	91.7%	5	1	80.0%	24	2	91.7%
144		3	2	33.3%	13	7	46.2%	3	0	100.0%	13	0	100.0%
146		5	2	60.0%	24	4	83.3%	5	1	80.0%	24	6	75.0%
147		3	1	66.7%	12	3	75.0%	3	0	100.0%	12	1	91.7%
150	26	5	5	0.0%	24	18	25.0%	5	4	20.0%	24	16	33.3%
151		20	10	50.0%	81	24	70.4%	20	7	65.0%	80	23	71.3%
152		3	0	100.0%	12	0	100.0%	3	1	66.7%	12	3	75.0%
153		5	0	100.0%	24	1	95.8%	5	2	60.0%	24	2	91.7%
155		5	0	100.0%	24	1	95.8%	5	1	80.0%	24	2	91.7%
156		5	1	80.0%	24	2	91.7%	5	2	60.0%	24	4	83.3%
158		5	0	100.0%	24	0	100.0%	5	1	80.0%	24	1	95.8%
159		3	1	66.7%	12	1	91.7%	3	0	100.0%	12	0	100.0%
160		5	0	100.0%	24	0	100.0%	4	2	50.0%	22	3	86.4%
161	20	5	0	100.0%	24	0	100.0%	5	4	20.0%	24	12	50.0%
162		5	1	80.0%	24	2	91.7%	5	3	40.0%	24	9	62.5%
163	18	3	0	100.0%	12	1	91.7%	3	2	33.3%	12	7	41.7%
164		5	1	80.0%	24	4	83.3%	5	3	40.0%	24	7	70.8%
165		5	3	40.0%	24	6	75.0%	5	2	60.0%	24	6	75.0%
168	59	3	0	100.0%	12	2	83.3%	3	1	66.7%	12	3	75.0%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		15	1	93.3%	57	8	86.0%	15	1	93.3%	58	6	89.7%
179		15	1	93.3%	57	5	91.2%	15	2	86.7%	58	12	79.3%
194		3	1	66.7%	12	3	75.0%	3	0	100.0%	12	1	91.7%
195	20	5	0	100.0%	24	0	100.0%	5	4	20.0%	24	17	29.2%
232		20	0	100.0%	81	1	98.8%	20	0	100.0%	81	6	92.6%
233		20	6	70.0%	81	19	76.5%	20	5	75.0%	81	17	79.0%
234		20	0	100.0%	81	3	96.3%	20	0	100.0%	81	2	97.5%
235		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
236		20	0	100.0%	81	1	98.8%	20	3	85.0%	81	14	82.7%
237		20	2	90.0%	81	12	85.2%	20	2	90.0%	81	6	92.6%
238		20	2	90.0%	20	2	90.0%	20	0	100.0%	20	0	100.0%
239		20	7	65.0%	80	22	72.5%	20	1	95.0%	80	3	96.3%
240		20	1	95.0%	81	7	91.4%	20	4	80.0%	81	11	86.4%
241		20	7	65.0%	81	23	71.6%	20	3	85.0%	81	13	84.0%
244		20	0	100.0%	81	2	97.5%	20	1	95.0%	81	16	80.2%
280		20	1	95.0%	81	4	95.1%	20	5	75.0%	81	15	81.5%
281		20	0	100.0%	81	8	90.1%	20	2	90.0%	81	7	91.4%
283		20	8	60.0%	81	16	80.2%	20	4	80.0%	81	13	84.0%
284		20	0	100.0%	81	1	98.8%	20	2	90.0%	81	7	91.4%
290		20	0	100.0%	81	18	77.8%	20	6	70.0%	80	27	66.3%
291		20	4	80.0%	81	17	79.0%	20	3	85.0%	81	15	81.5%
300		20	6	70.0%	81	8	90.1%	20	9	55.0%	80	23	71.3%
301		19	1	94.7%	79	2	97.5%	19	5	73.7%	78	14	82.1%
305	25	20	6	70.0%	81	11	86.4%	19	13	31.6%	79	33	58.2%
306		19	3	84.2%	79	5	93.7%	19	6	68.4%	78	17	78.2%
307	Cncld	20	5	75.0%	80	10	87.5%	19	9	52.6%	79	20	74.7%
311		20	3	85.0%	80	10	87.5%	20	5	75.0%	80	19	76.3%
316		20	2	90.0%	80	5	93.8%	20	5	75.0%	80	17	78.8%
318		20	1	95.0%	81	10	87.7%	20	8	60.0%	80	33	58.8%
319		20	2	90.0%	81	4	95.1%	20	8	60.0%	81	44	45.7%
330		18	0	100.0%	69	2	97.1%	18	4	77.8%	69	5	92.8%
331	18	20	6	70.0%	81	10	87.7%	20	5	75.0%	81	11	86.4%
332		20	4	80.0%	81	9	88.9%	20	6	70.0%	81	11	86.4%
334		20	1	95.0%	81	2	97.5%	20	7	65.0%	80	11	86.3%
335	44	20	7	65.0%	81	14	82.7%	19	5	73.7%	79	14	82.3%
336		20	3	85.0%	81	4	95.1%	20	1	95.0%	81	5	93.8%
337		20	1	95.0%	81	5	93.8%	20	4	80.0%	81	9	88.9%
338	35	20	4	80.0%	81	19	76.5%	19	7	63.2%	79	19	75.9%
339	16	20	5	75.0%	81	19	76.5%	20	7	65.0%	81	18	77.8%
341		18	4	77.8%	78	13	83.3%	17	4	76.5%	77	12	84.4%
342		20	2	90.0%	81	8	90.1%	20	6	70.0%	80	14	82.5%
343		3	0	100.0%	12	1	91.7%	3	1	66.7%	12	4	66.7%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
350	60	20	1	95.0%	63	3	95.2%	20	14	30.0%	63	36	42.9%
351	29	20	7	65.0%	81	10	87.7%	20	9	55.0%	81	35	56.8%
352		20	2	90.0%	81	6	92.6%	19	6	68.4%	78	20	74.4%
353		20	3	85.0%	60	5	91.7%	20	10	50.0%	60	15	75.0%
354		20	4	80.0%	81	7	91.4%	19	11	42.1%	80	25	68.8%
355		19	2	89.5%	80	7	91.3%	18	8	55.6%	79	21	73.4%
364	29	19	10	47.4%	80	15	81.3%	18	9	50.0%	79	17	78.5%
365		19	4	78.9%	80	6	92.5%	18	10	44.4%	79	26	67.1%
370		20	3	85.0%	81	5	93.8%	20	6	70.0%	81	15	81.5%
371		19	2	89.5%	80	2	97.5%	19	5	73.7%	80	9	88.8%
380	27	20	4	80.0%	81	14	82.7%	20	7	65.0%	81	20	75.3%
381		20	1	95.0%	81	2	97.5%	20	3	85.0%	81	10	87.7%
382		20	0	100.0%	81	2	97.5%	20	6	70.0%	81	21	74.1%
383		20	4	80.0%	81	9	88.9%	19	10	47.4%	79	32	59.5%
390		12	4	66.7%	65	8	87.7%	12	5	58.3%	65	21	67.7%
391		12	1	91.7%	66	1	98.5%	12	2	83.3%	65	14	78.5%
392	34	20	2	90.0%	81	4	95.1%	20	13	35.0%	80	28	65.0%
393	37	20	2	90.0%	81	7	91.4%	20	9	55.0%	80	24	70.0%
400	21	5	1	80.0%	23	2	91.3%	5	1	80.0%	22	1	95.5%
405		5	0	100.0%	20	0	100.0%	5	0	100.0%	20	1	95.0%
448	246	20	9	55.0%	22	10	54.5%	19	9	52.6%	20	9	55.0%
449		19	1	94.7%	19	1	94.7%	19	3	84.2%	19	3	84.2%
450		5	3	40.0%	21	7	66.7%	5	1	80.0%	21	7	66.7%
460		5	2	60.0%	21	9	57.1%	5	1	80.0%	20	5	75.0%
461		5	1	80.0%	23	2	91.3%	5	0	100.0%	23	1	95.7%
463		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	0	100.0%
464		5	1	80.0%	21	3	85.7%	5	3	40.0%	21	7	66.7%
467		3	0	100.0%	11	1	90.9%	3	0	100.0%	10	0	100.0%
488		5	1	80.0%	24	7	70.8%	5	0	100.0%	22	4	81.8%
499		5	0	100.0%	22	3	86.4%	5	0	100.0%	22	2	90.9%
500		20	1	95.0%	81	6	92.6%	20	4	80.0%	80	9	88.8%
502		20	1	95.0%	81	7	91.4%	20	3	85.0%	80	19	76.3%
503		20	3	85.0%	78	11	85.9%	20	7	65.0%	77	22	71.4%
504		20	2	90.0%	81	7	91.4%	20	6	70.0%	81	25	69.1%
505		20	3	85.0%	81	13	84.0%	20	4	80.0%	79	17	78.5%
506		20	4	80.0%	80	13	83.8%	20	3	85.0%	79	12	84.8%
507		20	3	85.0%	81	10	87.7%	20	6	70.0%	81	28	65.4%
508	34	20	4	80.0%	79	15	81.0%	20	8	60.0%	79	21	73.4%
509	67	20	2	90.0%	81	6	92.6%	20	9	55.0%	81	22	72.8%
511		20	2	90.0%	81	6	92.6%	20	4	80.0%	81	16	80.2%
516	23	18	0	100.0%	79	9	88.6%	18	5	72.2%	79	33	58.2%
517		20	1	95.0%	81	2	97.5%	20	8	60.0%	80	30	62.5%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-EOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
518	59	20	0	100.0%	81	13	84.0%	20	11	45.0%	81	47	42.0%
519		18	1	94.4%	79	4	94.9%	18	4	77.8%	79	13	83.5%
562		20	3	85.0%	79	11	86.1%	20	3	85.0%	78	9	88.5%
564		20	1	95.0%	79	7	91.1%	19	2	89.5%	75	12	84.0%
566		20	1	95.0%	79	6	92.4%	20	2	90.0%	76	8	89.5%
572	Cncld	20	2	90.0%	78	8	89.7%	19	0	100.0%	76	14	81.6%
573		20	3	85.0%	79	12	84.8%	19	0	100.0%	77	8	89.6%
577	60	20	2	90.0%	77	7	90.9%	20	5	75.0%	73	7	90.4%
580		20	0	100.0%	79	2	97.5%	20	1	95.0%	79	8	89.9%
581		20	1	95.0%	79	8	89.9%	20	2	90.0%	79	14	82.3%
582		20	2	90.0%	79	6	92.4%	20	2	90.0%	77	6	92.2%
586		20	5	75.0%	79	16	79.7%	19	1	94.7%	75	10	86.7%
587		20	0	100.0%	79	3	96.2%	19	0	100.0%	76	9	88.2%
591		20	0	100.0%	79	1	98.7%	19	1	94.7%	78	7	91.0%
593		20	3	85.0%	79	12	84.8%	18	1	94.4%	71	6	91.5%
595		20	3	85.0%	78	17	78.2%	20	1	95.0%	77	11	85.7%
611		3	3	0.0%	12	9	25.0%	3	0	100.0%	12	1	91.7%
624		15	5	66.7%	57	15	73.7%	15	4	73.3%	58	13	77.6%
660		5	1	80.0%	24	2	91.7%	5	1	80.0%	24	9	62.5%
661		5	0	100.0%	24	3	87.5%	5	1	80.0%	24	6	75.0%
662		3	0	100.0%	14	0	100.0%	3	0	100.0%	14	0	100.0%
663		5	0	100.0%	24	2	91.7%	5	0	100.0%	24	1	95.8%
664		5	1	80.0%	24	5	79.2%	5	0	100.0%	24	1	95.8%
665		5	3	40.0%	24	5	79.2%	5	2	60.0%	24	10	58.3%
666		5	3	40.0%	24	9	62.5%	5	1	80.0%	24	2	91.7%
667	14	5	1	80.0%	24	3	87.5%	5	2	60.0%	24	5	79.2%
669		5	1	80.0%	24	1	95.8%	5	2	60.0%	24	9	62.5%
670	22	5	1	80.0%	24	3	87.5%	5	1	80.0%	24	2	91.7%
671	12	5	0	100.0%	24	1	95.8%	5	3	40.0%	24	4	83.3%
672		5	1	80.0%	24	3	87.5%	5	1	80.0%	24	2	91.7%
674		5	3	40.0%	24	7	70.8%	5	0	100.0%	24	0	100.0%
689		11	1	90.9%	47	5	89.4%	11	1	90.9%	47	4	91.5%
690		5	0	100.0%	23	0	100.0%	5	0	100.0%	23	1	95.7%
691		5	0	100.0%	23	2	91.3%	5	0	100.0%	23	6	73.9%
692		5	0	100.0%	23	1	95.7%	5	0	100.0%	23	5	78.3%
693		5	0	100.0%	23	3	87.0%	5	1	80.0%	23	6	73.9%
694		5	0	100.0%	23	4	82.6%	5	1	80.0%	23	2	91.3%
695		5	0	100.0%	23	2	91.3%	5	0	100.0%	23	5	78.3%
696		5	0	100.0%	23	1	95.7%	5	1	80.0%	23	4	82.6%
697		5	0	100.0%	23	3	87.0%	5	1	80.0%	23	5	78.3%
698		5	0	100.0%	23	0	100.0%	5	1	80.0%	23	3	87.0%
701		13	3	76.9%	13	3	76.9%	13	2	84.6%	13	2	84.6%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
702		20	2	90.0%	81	17	79.0%	20	3	85.0%	80	22	72.5%
703		20	4	80.0%	81	19	76.5%	20	4	80.0%	81	20	75.3%
704		13	3	76.9%	13	3	76.9%	12	3	75.0%	12	3	75.0%
710		20	8	60.0%	81	32	60.5%	20	2	90.0%	81	30	63.0%
711		20	3	85.0%	77	7	90.9%	17	3	82.4%	70	10	85.7%
712	49	20	4	80.0%	81	21	74.1%	20	6	70.0%	80	29	63.8%
713		19	3	84.2%	80	12	85.0%	15	5	66.7%	70	32	54.3%
714	Cncld	20	8	60.0%	75	27	64.0%	19	6	68.4%	69	22	68.1%
715	140	20	5	75.0%	81	27	66.7%	18	10	44.4%	76	39	48.7%
716	201	20	11	45.0%	81	34	58.0%	20	12	40.0%	80	35	56.3%
717	32	20	4	80.0%	72	17	76.4%	20	10	50.0%	67	23	65.7%
718	40	20	13	35.0%	81	35	56.8%	19	9	52.6%	80	25	68.8%
719	36	20	5	75.0%	81	29	64.2%	20	8	60.0%	79	24	69.6%
720		5	0	100.0%	25	2	92.0%	5	0	100.0%	25	1	96.0%
723		5	0	100.0%	25	3	88.0%	5	0	100.0%	25	2	92.0%
724		5	0	100.0%	25	0	100.0%	5	1	80.0%	25	1	96.0%
727		5	0	100.0%	25	3	88.0%	5	0	100.0%	25	6	76.0%
728		5	0	100.0%	25	2	92.0%	5	0	100.0%	25	4	84.0%
729		5	1	80.0%	25	3	88.0%	5	2	60.0%	25	7	72.0%
732		5	0	100.0%	25	3	88.0%	5	0	100.0%	25	4	84.0%
733		5	0	100.0%	25	3	88.0%	4	1	75.0%	21	4	81.0%
734		5	2	60.0%	25	10	60.0%	5	0	100.0%	25	6	76.0%
736		5	0	100.0%	25	1	96.0%	5	0	100.0%	25	4	84.0%
737		5	1	80.0%	25	3	88.0%	5	0	100.0%	25	3	88.0%
738		5	2	60.0%	25	5	80.0%	5	0	100.0%	23	1	95.7%
741		5	2	60.0%	25	5	80.0%	5	0	100.0%	25	4	84.0%
742		5	2	60.0%	25	5	80.0%	5	0	100.0%	24	3	87.5%
743		5	1	80.0%	25	3	88.0%	5	0	100.0%	25	1	96.0%
744	31	5	1	80.0%	25	2	92.0%	5	3	40.0%	25	8	68.0%
745	36	5	0	100.0%	25	2	92.0%	5	2	60.0%	25	4	84.0%
746		5	0	100.0%	25	0	100.0%	5	0	100.0%	25	1	96.0%
747		5	2	60.0%	25	5	80.0%	5	1	80.0%	25	3	88.0%
748		5	0	100.0%	24	5	79.2%	5	1	80.0%	24	2	91.7%
749		5	1	80.0%	25	5	80.0%	5	0	100.0%	21	2	90.5%
751		5	1	80.0%	25	5	80.0%	4	0	100.0%	24	4	83.3%
761		20	0	100.0%	79	3	96.2%	20	1	95.0%	79	10	87.3%
765		20	1	95.0%	79	8	89.9%	20	1	95.0%	79	14	82.3%
769		20	1	95.0%	79	5	93.7%	20	1	95.0%	77	12	84.4%
770	30	20	0	100.0%	79	7	91.1%	20	2	90.0%	79	11	86.1%
774		20	1	95.0%	79	7	91.1%	20	4	80.0%	78	15	80.8%
779		20	0	100.0%	79	4	94.9%	20	2	90.0%	78	11	85.9%
784		20	2	90.0%	79	8	89.9%	20	11	45.0%	78	40	48.7%

Amtrak On Time Performance

Trains Arriving Through: 12/20/2025

28-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
785		20	0	100.0%	79	0	100.0%	20	3	85.0%	79	10	87.3%
790		20	0	100.0%	79	5	93.7%	20	3	85.0%	79	10	87.3%
794		20	1	95.0%	79	6	92.4%	20	4	80.0%	78	14	82.1%
821		20	0	100.0%	81	3	96.3%	20	6	70.0%	81	46	43.2%
822		20	0	100.0%	81	3	96.3%	20	2	90.0%	81	46	43.2%
1105	46	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
1106		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
1333	16	20	5	75.0%	81	9	88.9%	20	9	55.0%	80	35	56.3%
1340		20	0	100.0%	81	3	96.3%	20	7	65.0%	81	20	75.3%
2174		3	0	100.0%	13	2	84.6%	3	0	100.0%	13	2	84.6%
2203		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	0	100.0%
2205		5	0	100.0%	24	3	87.5%	5	1	80.0%	24	2	91.7%
2216		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	0	100.0%
2218		3	0	100.0%	12	1	91.7%	3	0	100.0%	12	0	100.0%
2248		5	2	60.0%	24	4	83.3%	5	2	60.0%	24	5	79.2%
2249		3	0	100.0%	12	0	100.0%	3	0	100.0%	12	3	75.0%
2250		5	0	100.0%	24	3	87.5%	5	2	60.0%	24	10	58.3%
2251		3	0	100.0%	12	0	100.0%	3	1	66.7%	12	4	66.7%
2252		4	1	75.0%	23	2	91.3%	4	0	100.0%	23	2	91.3%
2253	16	3	0	100.0%	22	2	90.9%	3	3	0.0%	22	13	40.9%
2254		5	0	100.0%	24	0	100.0%	5	1	80.0%	24	5	79.2%
2255		5	0	100.0%	24	2	91.7%	5	2	60.0%	24	8	66.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/20/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2253	WAS	16	DSR	8	DSR	6	NHV-STM	MN	Per bulletin Other, cp 243 to co 241, 15, 2
65	NPN	69	SVS	61	SVS	61	WAS-WAS	AM	PTC - Initializing PTC (no failure), SSUE INITIALIZING PTC. CONSIST WOULD NOT DOWNLOAD.
135	WAS	31	DSR	25	DSR	12	BRP-STM	MN	Per bulletin Milepost w/Letters, BRP, STM, 30, 2
150	BOS	26	PTI	10	PTI	10	NHV-NHV	AM	Wait for station track, 405, Milepost, NHV, NHV
161	WAS	20	OTH	14	OTH	6	OSB-NHV	AM	Lost time - N.A.R.
163	WAS	18	DSR	13	DSR	8	BRP-STM	MN	Per bulletin Control Point, 248, 30, 1, Milepost, 42, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 2
168	BOS	59	INJ	46	INJ	46	MYS-MYS	AM	Injured or sick passenger, AM168 Requested EMS at Mystic Station for a passenger who fell while getting off train, EMS has removed and transported the passenger
195	RVM	20	CTI	17	PTI	15	XVG-ALX	CS	Follow AMT 41, Milepost, 112.2, 105.1
400	GFD	21							
667	HAR	14	CCR	8	CCR	6	EXT-DOW	AM	Electrical failure, CC/9644, intermittent power loss
670	NYP	22	POL	17	POL	17	PAR-PAR	AM	Removal of passenger by police, Unruly passenger
671	HAR	12	OTH	5	CTI	5	ARD-PAO	AM	Follow, Septa, 9567, Milepost, 8.5, 19.9
19	NOL	58	INJ	144	INJ	144	GRV-GRV	NS	Injured or sick passenger PNR 261705
63	TWO	92	ADA	24	SVS	13	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train Control Point, 143
48	NYP	116	ENG	225	ENG	225	CHI-CHI	AM	Traction motor Bad order engine .. replacing second unit with engine 142 off train 6 (17) ..., 107
49	CHI	32	FTI	38	DSR	20	ERI-X81	CS	Per dispatcher (radio/phone) Restricted speed thru MP QD (142.2 - 142.6) on TRK (2). Due to possible TRK damage from vehicle being stuck on TRK., Milepost, 142.2, 142.6, 15, 2
448	BOS	79	CON	167	CON	167	ALB-ALB	AM	Hold for connecting train
71	CLT	11	FTI	18	FTI	15	GRO-GRO	NS	Meet We waited at Greensboro station for NS to clear up then held for Amtrak 80. At 8:16am Amtrak 80 arrived on track #2, we departed at 8:17am, Other, Greensboro Station, #NS 28N, #NS 28N

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
73	CLT	20	FTI	12	FTI	9	CYN-DNC	NS	Meet #NS350, Control Point, D&S Jct	
98	NYP	58	FTI	80	FTI	26	RMT-PTB	CS	Meet CSX, Control Point, Bricks	
40	CHI	131	ENG	95	ENG	48	WAS-WAS	AM	Other electrical failure, 341-356, CNOC REQUESTED HEADEND SWAP DUE TO FUELING ISSUES IN PA. & DSL'S LATE COMING DOWN FROM PIT.	
24	MOE	21	FTI	55	FTI	27	PAG-MOE	CS	Follow M520-20, Milepost w/Letters, 000696, Brookley	
25	NOL	29	FTI	51	FTI	51	GUF-BAS	CS	Meet 602, Siding, harbin	
26	MOE	20	FTI	55	FTI	55	XNO-BAS	CS	M602 had a bad order car set out on the N end of the siding at Nicholson causing long delay for both North and South bound Amtrak trains. Had to wait in siding behind bad ordered freight equipment until AMTK 25 was able to pass us at Nicholson Siding, Nicholson, M602	
744	ARN	31	TRS	33	TRS	31	OAC-OKJ	UP	Vehicle on track ahead Held by track inspector for vehicle in tracks at south jack London, Control Point, strong	
745	SJC	36	TRS	45	TRS	45	OKJ-OAC	UP	Vehicle on track ahead Control Point, ni008	
508	SEA	34	TRS	44	TRS	44	XTW-XA4	BN	Vehicle on track ahead Control Point, cp sumner mp 28.75	
509	PDX	67	TRS	62	TRS	62	XA4-XTW	BN	Vehicle on track ahead Car fouling main 2, waited to be allowed by on main 1, Control Point, stewart	
516	VAC	23	DCS	19	PTI	15	STW-MVW	BN	Meet Amtrak 517, Control Point, North Mount Vernon	
518	VAC	59	TRS	59	TRS	59	MVW-BEL	BN	Vehicle strike Milepost, 70.9, 71.9	
59	NOL	88	CAR	158	CAR	158	CHI-CHI	AM	59 CHI xxx car at 604PM, sleeping car/32072 BO'D for freeze damaged and replaced with sleeping C/32070 32070	
11	LAX	68	SVS	122	SVS	122	EMY-OKJ	UP	Pick up equipment Added a loco and 3 coaches to consist. Deadhead to LAX for repairs, Other, OMF	
8	CHI		FTI	138	CON	45	SPK-SPK	BN	Hold for bus with passengers from train	
28	SPK	107	SVS	114	SVS	114	PDX-PDX	BN	Late arrival of train 27. Had to wye equipment and service it	
331	MKE	18	SYS	10	SYS	10	CHI-CHI	AM	PTC- IETMS incorrect consist System-wide PTC issue; consist was incorrect. Spoke with CNOC and worked out a fix.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
335	MKE	44	SYS	27	SYS	27	CHI-CHI	AM	PTC problem or failure (cause unknown) Could not get past clearance screen in PTC, could not even access consist. System-wide issues are present; CNOC did come up with a work around	
338	CHI	35	ITI	34	ITI	34	MKE-MKE	CP	Service, turn, or wye train 335	
339	MKE	16	ITI	15	ITI	15	CHI-CHI	AM	Service, turn, or wye train 338	
350	PNT	60	SYS	66	SYS	62	CHI-XTF	AM	PTC problem or failure (cause unknown) PTC systemwide outage, Control Point, Roosevelt	
351	CHI	29	PTI	38	PTI	19	XH6-XTF	NS	Follow amtk40, amtk49, Milepost, 497, 521	
364	PTH	29	DBS	31	DBS	31	NLS-DOA	AM	Animal strike Hit a deer and engine shut down. Had to reboot engine, Other, 184	
572	SAN	Trn Cancelled	SYS	62	SYS	62	LAX-LAX	SC	PTC problem or failure (cause unknown) Milepost, 0.0, 0.0	
577	LAX	60	CCR	26	CCR	26	SAN-SAN	SN	PTC- IETMS recycle breaker to clear fault 6905, PTC outage had to recycle breaker.	
770	SAN	30	CTI	39	CTI	39	SNC-SNP	SC	Meet Hold per dispatcher. If we're not past Serra at 11:34 they will hold us. For Metrolink 1663. We left SNC at 11:30. Per dispatcher JBL., Metrolink, 1663, Control Point, serra	
712	BFD	49	DCS	33	DCS	30	COC-WAC	BN	CTC system failure CTC signal failure due to power outage, Control Point, allensworth-sandrini	
714	BFD	Trn Cancelled	DBS	192	DBS	192	ACA-SKN	BN	Struck empty vehicle Milepost, 1126, 1126	
715	OKJ	140	POL	143	POL	87	SKN-SKN	BN	RR blocked by trespasser or vehicle strike by another train Amt 714 vehicle at mp 1126	
716	BFD	201	SYS	90	POL	53	ACA-SKN	BN	RR blocked by trespasser or vehicle strike by another train 714 hit a vehicle	
717	OKJ	32	POL	26	POL	26	MOD-SKN	BN	RR blocked by trespasser or vehicle strike by another train	
718	BFD	8	ITI	29	ITI	29	OKJ-OKJ	UP	Service, turn, or wye train 715	
719	OKJ	36	DCS	23	DCS	23	WAC-COC	BN	Restrictive signal(s) from known wayside signal failure Stop, Control Point, sandrini, Control Point, allensworth	
4	CHI	112	FTI	89	FTI	26	WLO-GLP	BN	Follow BNSF unknown, Milepost, 282.7, 273.0, Milepost, 210.2, 167.1	
305	STL	25	FTI	30	FTI	14	BNL-BNL	UP	Meet Freight, Siding, Normal	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/20/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
307	STL	Trn Cancelled	CAR	52	CAR	52	CHI-CHI	AM	Door 4203, Having trouble with door relay Had to cut it out per foreman Tate	
380	CHI	27	SVS	28	SVS	28	QCY-QCY	BN	Routine inspections Late inbound train from previous night, Control Point, west qcy yard	
392	CHI	34	DSR	20	DSR	11	MAT-CHM	CC	Per bulletin Milepost, 170.0, 165.0, 60, main, Milepost, 148.3, 143.4, 25, main	
393	CDL	37	PTI	32	PTI	32	CHM-MAT	CC	Meet 392, Siding, TOLONO	
1105	WIP	46	DCS	39	DCS	23	XFJ-XXP	UP	CTC system failure Power outages causing us to flag and hand operate switches., Control Point, CP DS 013, Control Point, CP DS 016, Control Point, CP DS 019	
1333	MSP	16	PTI	20	PTI	14	POG-WDL	CP	Meet Had to stop on the main to wait for train 8 to take the siding at Lewiston., AMTK 8, Control Point, Lewiston West	

Amtrak Initial Terminal Details

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/20/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	660	12/20	2	2	Door, .., car number not provided by cdr
HAR	674	12/20	2	2	Door, entire train, Cut out doors
NOL	58	12/20	6	6	Ptc outage 192
NPN	194	12/20	16	16	PTC - Initializing PTC (no failure) PTC FAILURE NATIONWIDE PER CNOC
PHL	144	12/20	1		
PHL	150	12/20	9	9	Planned set out / pick out of locomotives, cars or section of train, LATE EQUIPMENT OUT OF THE YARD
PHL	151	12/20	1		
PHL	611	12/20	2	2	Passenger and/or baggage, late travel per dispatcher 7:37am, section C
WAS	128	12/20	2	2	High passenger count, PAX STILL BOARDING. GATE CLOSED ON TIME. 303 TOTAL PAX
ALB	448	12/19	215	167	Hold for connecting train
ALB	448	12/19	215	48	Planned set out / pick out of locomotives, cars or section of train
BOS	135	12/20	4	4	Door, 82560, Door issues
BOS	165	12/20	4	4	Door, 81532, 82999, 82579, AM165 Late departure from Boston due to multiple door issues. 81532 B End, 82999 A End, 82579 A End
GFD	461	12/20	15		
NHV	450	12/20	5	5	Service, turn, or wye train, 405, Late turn
NYP	19	12/20	2	2	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME
NYP	63	12/20	9	9	Passenger and/or baggage, HEAVY TRAVEL
NYP	79	12/20	9	10	Set out defective car, 81503, LATE F/SSYD A/C SHOPPED BUISNESS CLASS CAR 81503
NYP	159	12/20	13	13	Radio failure, 608, late out of the yard due to miscommunication and radio issues with the crew.
NYP	283	12/20	2	2	Cross Traffic, NJT, NJ7245, Other, NYP-NYP
NYP	665	12/20	2	2	Passenger and/or baggage, STILL LOADING AT DEPARTURE TIME
NYP	667	12/20	3	3	High passenger count
SPG	147	12/20	27	27	Air / Brake / Wheel, 82528, Brakes won't release on car
SPG	400	12/20	15		
SPG	463	12/20	2	2	Wheelchair, pgsr assist
CHI	48	12/20	6	6	Hoses not tied Engine access door will not close QMP sign off on door bypass

Amtrak Initial Terminal Details

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/20/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	305	12/20	8	4	Door ID4317, Doors and stairs wouldn't retract/ placed on manual and closed by hand
CHI	305	12/20	8	4	Door ID4203, Doors and stairs wouldn't retract/ placed on manual and closed by hand
CHI	307	12/20	7	7	Door ID4114, Door bypass was not working contacted CNOC and mechanical cut it out .
CHI	331	12/20	10	10	PTC- IETMS incorrect consist System-wide PTC issue; consist was incorrect. Spoke with CNOC and worked out a fix.
CHI	335	12/20	27	27	PTC problem or failure (cause unknown) Could not get past clearance screen in PTC, could not even access consist. System-wide issues are present; CNOC did come up with a work around
CHI	339	12/20	15	15	Service, turn, or wye train 338
CHI	350	12/20	4	4	Door 4204, Train would not load, showed a open door. Had initially performed a load test when we boarded equipment. 4204 door opened by itself, it also opened up by itself again after departure
CHI	1333	12/20	7	5	Service, turn, or wye train 332
CHI	1333	12/20	7	2	Planned Switch
DEN	1105	12/20	14	14	Meet Amtk #5, Other, Union Station
MKE	338	12/20	34	34	Service, turn, or wye train 335
QCY	380	12/20	28	28	Routine inspections Late inbound train from previous night, Control Point, west qcy yard
SEA	507	12/20	4	4	Mobility Impaired
BFD	703	12/20	5	5	Service, turn, or wye train 712
BFD	719	12/20	9	9	Had to inspect flat spots and wheels C2004
LAX	4	12/20	61	61	Set out defective car 34099, Car switched out at 8th St Yard
LAX	572	12/20 (Trn Cxld)		62	PTC Failure
OKJ	710	12/20	2	2	Meet amtk 723, Other, okj station
OKJ	716	12/20	9	9	PTC problem or failure (cause unknown) Engineer states CPU issue initialization not available, Other, Oakland Jack London Station
OKJ	742	12/20	1		
SAC	741	12/20	2	2	Door C8314
SAN	573	12/20	2	2	Passenger and/or baggage Cruise ship! lots of big bags and business class passengers had to accommodate baggage arrow and PTC system down not populating times
SAN	577	12/20	26	26	PTC- IETMS recycle breaker to clear fault 6905, PTC outage had to recycle breaker.

Amtrak Initial Terminal Details

26-FOI-00197 00000005537 "UNCLASSIFIED" 12/23/2025

Late Trains For:
Region: ALL
Division: ALL
Data Through: 12/20/2025

Terminal	Train	Date	Late	Delay	Cause
SAN	581	12/20	3	3	Loading problem C2111
SAN	595	12/20	1		
SLO	774	12/20	2	2	Pax needed help boarding Pax needs help boarding
VAC	517	12/20	9	9	United States CBP requested clear the train after clear the all the crew members

Eastern Region

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	98.5	94.8	165	1
CDOT	95.0	100.0	92.4	92.4	16	0
MARC	95.0	83.3	88.0	90.2	18	3
SEPTA	95.0	92.2	94.6	91.5	102	8
NJT-NED	95.0	90.2	92.1	93.8	193	19
NJT-SED	95.0	100	99.1	97.2	22	0

Operating Highlights

Train 40(20) Savannah, GA - Engine Failure

21DEC25: Train 40(20) operating with engines 120 and 340 was delayed departing Savannah, GA due to original lead engine 120 arriving into Savannah, GA with a cracked windshield on the fireman side. Per AMT-3 and Savannah being a 1500 mile mechanical inspection point, engine 120 was flat switched with engine 340. Once the swap was complete, train 40(20) was able to proceed north.

Train	Delay	Comment
40(20)	3'02"	

Train 168(20) Mystic, CT - Injured or Sick Passenger or Employee

21DEC25: Train 168(20) operating with engine 658 and 10 cars was delayed departing Mystic, CT on the Amtrak NHB line due to a passenger falling when deboarding the train. Local EMS arrived on scene and transported the passenger to the local hospital for evaluation.

Train	Delay	Comment
168(20)	46"	

Train 448(19) Albany, NY - Hold for Connection

21DEC25: Train 448(19) was delayed departing Albany, NY waiting on connecting train 48(19) which arrived into Albany, NY operating 2 hours and 5 minutes late.

Train	Delay	Comment
448(19)	2'47"	

Train 57(20) South of Aberdeen, MD - Trespasser Incident

20DEC25: At approximately 9:20 p.m., Train 57(20), operating with Engine 640 and six cars carrying 258 passengers, struck a deer at milepost 69.0 on Track 4 on the Amtrak PW Line 3.4 miles south of Aberdeen, MD. Following the incident, the pantographs were lowered for approximately five minutes before the crew successfully restored them to operational status. There were no reported injuries to passengers or crew, and no damage to equipment. Train 57(20) resumed movement after a total delay of 10 minutes.

Train	Delay	Comment
-------	-------	---------

Train 25(20) West of Bay Saint Louis, MS - Freight Train Interference

20DEC25: Train 25(20) was delayed 51 minutes at milepost 746.7 of Bay Saint Louis, MS on the CSX NO&M subdivision holding at milepost 746.7 for CSX freight to drop a bad ordered car off at a nearby siding. Train 26(20) was additionally delayed 2 miles east of Bay Saint Louis, MS holding at milepost 756.2 for the freight to finish dropping off the car.

Train	Delay	Comment
26(20)	55"	
25(20)	51"	

Train 19(19) Greenville, SC - Deceased Passenger

20DEC25: At 5:10AM, Train 19(19), with 205 passengers onboard, arrived to the Greenville, SC. station/MP484.1 on the Norfolk Southern Salisbury Greenville subdivision. A passenger onboard alerted the crew to an unresponsive passenger in car 62039 room 3. The crew called emergency responders to respond for the unresponsive passenger. EMS arrived and pronounced the passenger deceased. A Coroner was requested and responded to the location. The Coroner arrived, performed an investigation, and then removed the deceased passenger from the train. At 7:42AM, Train 19(19) was released from officials to continue west.

National Response Center Number: 1450963

Train	Delay	Comment
19(19)	2'24"	

Train 41(18) North of Savannah, GA - Freight Train Interference

20DEC25: Train 41(18) was delayed at MP490.1, 1.5 miles north of Savannah, GA. station on the CSX Columbia subdivision due to meet with a freight train. Once the freight cleared train 40(18) was back on the move south into Savannah, GA. Station.

Train	Delay	Comment
41(18)	36"	

26"FOI 00197 00000005587 UNCLASSIFIED

WBS#: B.TR.100150.5989

Train	Delay	Comment
64 (13)	57"	

Eastern Region

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
79(20)	60	NO	DUE TO SHOPPED EQUIPMENT, 79(20) WILL NOT OFFER BUSINESS CLASS. PASSENGERS WERE NOTIFIED AND DOWNGRADED.

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 26(20) Passenger Removal at Gulfport, Mississippi – Improper Behavior***

20DEC25, Passengers on PNR 0EA4FD, traveling from New Orlean, LA to Biloxi, MS were removed from the train by local Police for causing a disturbance. One of the group members apparently flashed her breast. Amtrak Police notified.

Delay: 26 (20) 13"

Train 99(20) Passenger Removal at Metropark, New Jersey – Improper Behavior

20DEC25, Passengers on PNR 241454, traveling from New York, NY to Philadelphia, PA removed by the Conductor for refusing to put her pet in a carrier. Amtrak Police notified.

Delay: 99 (20) None

Train 19(19) Passenger Removal at Greenville, South Carolina – Deceased

20DEC25, Passenger on PNR 261705, traveling from New York, NY to Birmingham, AL was found unresponsive by traveling companion. EMS was

dispatched and the passenger was confirmed deceased. Amtrak Police notified.

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Delay: 19(19) 144"

Train 168(20) Passenger Removal at Mystic, Connecticut – Medical

20DEC25, Passengers on PNR C723AC, traveling from Philadelphia, PA to New London, CT was removed from the train by EMS after missing initial stop of New London. When trying to alight at Mystic, passenger became weak and could not move. Amtrak Police notified.

Delay: 168(20) 55"

Operating Highlights

Train 518(20) Mount Vernon, WA - Trespasser Incident

20DEC25: At approximately train 518(20) - operating with camera equipped locomotive WDTX/1400 and thirteen cars - struck a vehicle at MP 70.79 on the Burlington Northern Santa Fe Railway Bellingham Subdivision in the City of Burlington, Skagit County, Washington. This incident occurred on the public highway crossing at grade for Pease Road (US DOT 084763T); the crossing is equipped with quad gates, flashing lights and audible warning devices which were observed to be working at the time the incident occurred. Train 518(20) was operating north at an estimated 54 MPH on the main track with a posted track speed of 79 MPH. There were no initial reports of injuries to the 104 passengers or crew, and no significant damage reported to Amtrak equipment. Local police and fire departments responded to the scene and tracks were closed for the duration of an investigation. Once the investigation was complete, train 518(20) was able to resume travel.

Google Maps Location of Incident:

<https://maps.app.goo.gl/Pru77M5psaLKHbMY6>

48.457206, -122.325781

Pease Rd, Burlington, WA 98233

National Response Center: 145-1031

Washington Office of Emergency Services: Pending

National Response Center Number: 145-1031

Train	Delay	Comment
518(20)	59"	

Train 508(20) East of Tacoma, WA - Vehicle on Tracks

21DEC25: Train 508(20) was delayed 9 miles east of Tacoma, WA, at milepost 31.9, on BNSF Seattle subdivision, due to a vehicle on the tracks. Local police responded with a tow truck to remove the vehicle and BNSF supervision responded to inspect the tracks. Once the scene was clear, train 508(20) was able to proceed.

Train	Delay	Comment
508(20)	44"	

Train 8(20) East of Everett, WA - M of W Work

20DEC25: Train 8(20) was delayed east of Everett, WA (EVR) at MP 1731.2 on the Burlington Northern Santa Fe Railway Scenic Subdivision. Train 8(20) was held for a mandatory track inspection following the activation of a "Slump Detector". Once the track inspection was complete, train 8(20) was able to proceed east.

Train	Delay	Comment
8(20)	1'36"	

Train 509(20) South of Tukwila, WA - Trespasser Incident/Vehicle on Tracks

20DEC25: Train 509(20) was delayed south of Tukwila, WA (TUK) at MP 33.5X on the Burlington Northern Santa Fe Railway Seattle Subdivision. There was a report of a vehicle high centered on the track ahead; all train traffic was halted until the vehicle was removed and tracks inspected. Once tracks were clear and inspection complete, train 509(20) was able to proceed south at 7:24 PM-PT.

Train	Delay	Comment
509(20)	1'02"	
14(19)	37"	

Train 4(20) Los Angeles, CA - Car Failure

20DEC25: Train 4(20) was delayed departing the initial terminal of Los Angeles, CA (LAX) on the Southern California Regional Rail Authority (Metrolink) River Subdivision. Train 4(20) was delayed departing the 8th St Maintenance Facility after an electrical fault on car C/34099; the car was switched out and replaced with car C/34105. Train 4(20) departed LAX at 6:20 PM-PT.

Train	Delay	Comment
4(20)	1'01"	

Train 6(20) Esat of Winnemucca, NV - Injured or Sick Passenger or Employee

20DEC25: Train 6(20) was delayed 53 miles east of Winnemucca, NV at Reese Road crossing/milepost 475.9, on BNSF Elko subdivision, due to EMS meeting the train for a crew member having a medical Emergency. The crew member having the medical emergency was taken off the train by ambulance and taken to the local hospital.

Train	Delay	Comment
6(20)	54"	

Train 712(20) East of Corcoran, CA - Signal

20DEC25: Train 712(20) was delayed east of Corcoran, CA (COC) at CP East Allensworth on the Burlington Northern Santa Fe Railway Bakersfield Subdivision. There was a problem with the signal system between CP East Allensworth and CP West Sandrini which required the train crew to obtain verbal authority from the dispatcher and operate at reduced speeds in the area. Once clear of CP West Sandrini, train 712(20) was able to resume operation at maximum authorized track speeds.

Train	Delay	Comment
712(20)	30"	

Train 14(20) North of San Luis Obispo, CA - Passenger Train Interference

20DEC25: Train 14(20) was delayed north of San Luis Obispo, CA (SLO) at CP Templeton on the Union Pacific Railway Coast Subdivision. Train 14(20) was required to hold the siding track at CP Templeton for train 11(19) to clear the single main track ahead. Once the track ahead was clear, train 14(20) was able to proceed north at 4:36 PM-PT.

Train	Delay	Comment
14(20)	45"	

Train 714(20) West of Stockton, CA - Trespasser Incident

20DEC25: At approximately 26-FOI-001975700000008537 train UNCLASSIFIED - 02/23/2025 ing with camera equipped cab car CC/6965, six additional cars and locomotive CDTX/2107 pushing - stuck an unoccupied vehicle at MP 1125.25 on the Burlington Northern Santa Fe (BNSF) Railway Stockton Subdivision in the city of Stockton, San Joaquin County, California. There were 146 passengers on the train at the time the incident occurred. There was one reported passenger injury (chest pains); the passenger was treated by EMS at the scene and elected to continue travel. There were no reports of injuries to crew. Cab Car CC/6965 was reported to have a damaged plow and HEP cables on the engineers side; which resulted in a temporary loss of Head End Power (HEP). The crew was able to short loop the HEP system and restore HEP operation at 3:15 PM-PT. Train 714(20) was operating east at an estimated 79 MPH on the main track with a posted track speed of 79 MPH. California Highway Patrol and local EMS responded to the scene, along with Amtrak Management, Amtrak Police, BNSF Management and TASI Mechanical Contractors. With the damage to the cab car, train 714(20) was unable to continue in revenue service, once the scene was released by authorities train 714(20) advanced to Stockton, CA (SKN) where passengers were discharged and the train terminated with the following recovery plan:

- 714(20) Terminate Stockton, CA (SKN) - passengers accommodated on later train 716(20).
- 714(20) equipment return to Oakland Maintenance Facility for repairs.
- 711(21) Cancelled - Passengers able to self modify tickets for alternative departures.

Duration of HEP loss: 1'17"

Google Maps Location of Incident:
<https://maps.app.goo.gl/NKb1GmYbNqqwHHsp7>
37.934188, -121.363527
San Joaquin County, California 95206

National Response Center: 1451021
California Office of Emergency Services: 25-6444
Amtrak Police Case: C25018065

WBS#: B.TR.100150.6334

National Response Center Number: 1451021

Train	Delay	Comment
714(20)	Terminate SKN	Passengers to 716(20)
711(21)	Cancelled	Pax to self-modify for later departures
715(20)	2'11"	Hold for route
716(20)	53"	
714(20)	3'12"	

Train 744(20) Oakland, CA - Trespasser Incident

20DEC25: Train 744(20) was delayed 1 mile south of Oakland, CA station, at milepost 7.9, on UP Niles subdivision, because of 2 vehicles on the tracks. One vehicle was on the tracks at the station and on vehicle was on the tracks just south of the station at milepost 7.1. Local police responded to the scene with a tow truck to remove the vehicles and a track inspector was dispatched to inspect the tracks for damage. Once the vehicle was removed and the tracks were inspected, both trains were released and able to proceed.

Train	Delay	Comment
744(20)	31"	
745(20)	45"	

Train 716(20) Oakland, CA - Third Party Contractor Cab Car Failure

20DEC25: Train 716(20) ^{20-FOI-00197} ⁰⁰⁰⁰⁰⁰⁰⁶⁵³⁷ ^{UNCLASSIFIED} ^{CA} (G2/23/2025) on the Union Pacific Railway (UPRR) Niles Subdivision. There was a problem with the Positive Train Control System (PTC) on cab car CC/90278. Eventually the crew was able to initialise the PTC system and depart OKJ at 2:27 PM-PT. PTC again failed at MP 20.0 on the Martinez Subdivision; the crew was instructed to cut out the PTC System and operate over the UPRR territory with speeds limited to 59 MPH. The crew again had problems on the Burlington Northern Santa Fe Railway (BNSF), and was initially instructed to attempt to enable PTC by the BNSF dispatcher when entering the BNSF Stockton Subdivision at CP Port Chicago. PTC again failed at CP Pittsburg; the dispatcher instructed the crew to cut out the PTC system on BNSF territory and operate with speeds also reduced to 59 MPH.

Train	Delay	Comment
716(20)	53"	

Train 364(20) West of Dowagiac, MI - Deer Strike

20DEC25: Train 364(20) with E/4626, 7 coaches, and 217 passengers struck a deer 4 miles east of Dowagiac, MI, at milepost 182.8, on Amtrak Michigan Line. The deer strike caused the engine to shut down. The crew was able to reboot the engine and proceed.

Train	Delay	Comment
364(20)	31"	

Train 770(20) San Juan Capistrano, CA - Passenger Train Interference

20DEC25: Train 770(20) was delayed east of San Juan Capistrano, CA (SNC) at CP Serra on the Southern California Regional Rail Authority Orange Subdivision. Train 770(20) was held for two opposing trains to clear the single main track ahead, train 573(20) and Metrolink 1663. Once the track ahead was clear, train 770(20) was able to proceed at 12:15 PM-PT.

Train	Delay	Comment
770(20)	39"	

Train 4(18) East of Mendota, IL - Car Failure

20DEC25: Train 4(18) stopped 13.1 miles east of Mendota, IL/MP82.8, on the BNSF Mendota Subdivision, at MP69.7 to inspect axle 16 on car SC155 after it setoff a wayside hotbox detector. The crew inspected and took no exceptions. Train 4(18) operated 10 miles at 50MPH to reinspect at MP59.9 to which no exceptions were taken. Once the second inspection was complete, Train 4(18) was released to continue to Chicago at track speed.

Train	Delay	Comment
4(18)	1'00"	Wi-tronix est.

Train 3(19) Lamy, NM - Passenger Train Interference

20DEC25: Train 3(19) was delayed at Canyoncito/MP830.5, 4.7 miles east of the Lamy, NM station/MP835.2 on the BNSF Glorieta subdivision, in order to meet Train 4(19).

Train	Delay	Comment
3(19)	33"	

Train 351(20) West of New Buffalo, MI - Passenger Train Interference

20DEC25: Train 351(20) was delayed 32 minutes west of New Buffalo, MI/MP218.9, on the NSRR Chicago Line, between MP497.0 and MP521.0 following Train 40(18) and 49(19).

Train	Delay	Comment
351(20)	32"	

Train 11(19) West of Emeryville, CA - Servicing

20DEC25: Train 11(19) was delayed west of Emeryville, CA (EMY) at Oakland Maintenance Facility (OMF) on the Union Pacific Railway Niles Subdivision. Three cars, C/8021, C/8027 and C/6852 along with locomotive AMTK/371 were added to the train so they could be ferried to Los Angeles, CA for use on trains in Southern California as part of a planned deadhead equipment move. Once the cars and locomotives were attached, train 11(19) was able to depart OMF at 10:48 AM-PT.

Train	Delay	Comment
11(19)	2'02"	

Trains 1105(20) and 5(19) West of Denver, CO - Flagging

20DEC25: Trains 1105(20) and 5(19) were both delayed west of Denver, CO/MP0.0, on the UPRR Moffatt Tunnel Subdivision, from signal issues. Due to power outages in the area, both trains had to flag through the signals starting at Leyden/MP13.4 to Rocky/MP19.0. At Rocky, both trains reporting having to take the switch by hand in order to proceed west. Additional delays to both trains at Crescent/MP31.8 causing them to have to flag through to Cliff/MP36.7.

Train	Delay	Comment
5(19)	37"	Leyden to Rocky
5(19)	10"	Crescent to Cliff
1105(20)	23"	Leyden to Rocky
1105(20)	08"	Leyden to Rocky

Train 7/27(19) West of Devils Lake, ND - M of W Work

20DEC25: Train 7/27(19) was delayed 2.2 miles west of Devils Lake, ND/MP85.1, on the BNSF Devils Lake Subdivision, holding in the West Devils Lake siding/MP87.3. Maintenance of Way was working ahead repairing the switch at Leeds/MP114.2. Once the switch was repaired, Train 7/27(19) was further delayed holding to meet BNSF 610. Once the meeting was complete, Train 7/27(19) was able to proceed west.

Train	Delay	Comment
7/27(19)	1'14"	

Train 51(19) North of Lafayette, IN - Freight Train Interference

20DEC25: Train 51(19) was delayed 2.1 miles north of Lafayette, IN/MP120.1, on the CSX Monon Subdivision, at the Lafayette Yard/MP118.0 meeting CSX Q642.

Train	Delay	Comment
51(19)	45"	

Train 2/422(19) West of Yuma, AZ - Freight Train Interference

20DEC25: Train 2/422(19) was delayed starting 42.6 miles west of Yuma, AZ/MP732.8, on the UPRR Yuma subdivision, at Mortmar/MP634.6 from freight interference. UP6899 was stopped on the single main ahead inspecting their equipment after setting off a dragging equipment detector. UP6899 inspected, took no exceptions, and then moved to clear. Once clear, Train 2/422(19) was back on the move east.

Train	Delay	Comment
2/422(19)	35"	

Train 4(19) East of Kingman, AZ - Freight Train Interference

20DEC25: Train 4(19) was delayed starting 42.6 miles east of Kingman, AZ/MP516.3, on the BNSF Seligman Subdivision, from Cherokee/MP473.7 to West Pica/MP446.8 following a BNSF freight train. Further delay following another BNSF freight train from West Perrin/MP385.6 to Maine/MP362.2. Starting 32.3 miles east of Winslow, AZ/MP285.5, on the BNSF Gallup Subdivision, Train 4(19) followed another BNSF freight train from East Holbrook/MP253.2 to Gallup/MP157.5.

Train	Delay	Comment
4(19)	43"	KNG-FLG
4(19)	54"	WLO-GLP

Amtrak Nationwide PTC Outage

20DEC25: At 8:00AM-ET, Amtrak reported a nationwide PTC outage impacting trains trying to initialize on Amtrak territory. Amtrak's DT Incident team opened a bridge to investigate the matter. During this time, multiple trains were delayed waiting on permission to proceed with PTC cutout. NTAMS and Arrow were also having tracking issues which were tied to the same event. At 3:02PM-ET, all services were restored. Support teams reported finding an incorrect configuration file. The file was replaced and all services were restored.

Train	Delay	Comment
400(20)	15"	ITD SPG
65(19)	1'01"	Holding WAS
331(20)	10"	ITD CHI
194(20)	16"	ITD NPN
350(20)	1'02"	CHI
301(20)	10"	CHI
335(20)	27"	ITD CHI
572(20)	CANCELLED	Pax to 774(20)
577(20)	15'	ITD - SAN
332(20)	03"	MKE
338(20)	34"	ITD MKE - Turn of 335(20)
572(20)	1'02"	LAX - Delay to Passengers

Train 3(19) West of Hutchinson, KS - Signal

20DEC25: Train 3(19) was delayed starting 41.9 miles west of Hutchinson, KS/MP218.10, on the BNSF La Junta Subdivision, due to restrictive signals from MP260 to MP280.

Train	Delay	Comment
3(19)	52"	

Train 365(20) Port Huron, MI - Car Failure

20DEC25: Train 365(20) 26-FOI-00197 200000005537 Passenger UNCLASSIFIED, d 12/23/2025 Port Huron, MI/MP334.3, on the CNRR Strathroy Subdivision, and reported cars ID4014 and ID4132 exit doors were inoperable. As a result, these cars were blocked off to deadhead in line. This resulted in overcapacity conditions downline starting at Kalamazoo (-09) with the highest at New Buffalo (-33). One supplemental express bus was secured to alleviate these conditions at Lansing, MI to Chicago for Chicago-bound passengers only. No delay was incurred to the train.

WBS#: B.TR.100150.6333

Train	Delay	Comment
365(20)	No Delay	

16-501-00187 000000537 UNCLASSIFIED 12/3/2025
Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Western Region

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
364	35	NO	DUE TO SHOPPED EQUIPMENT, 364(20) WILL NOT OFFER BUSINESS CLASS. PASSENGERS WERE NOTIFIED AND DOWNGRADED.
307	11	NO	DUE TO SHOPPED EQUIPMENT, 307(20) WILL NOT OFFER BUSINESS CLASS. PASSENGERS WERE NOTIFIED AND DOWNGRADED.

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 7(20) Passenger Removal at Wisconsin Dells, Wisconsin – Improper Behavior***

20DEC25, Passenger on PNR 306449, traveling from Chicago, IL to Minneapolis, MN was removed from the train by local Police for exhibiting strange and aggressive behavior. Passenger touched a crew member in an inappropriate way. Amtrak Police notified.

Delay: 7 (20) 2"

Train 14(20) Passenger Removal at Paso Robles, California – Improper Behavior

20DEC25, Passenger on PNR 31CB72, traveling from Los Angeles, CA to Tacoma, WA, was removed from the train by local Police for moving seats constantly and other passengers' belongings and taking items. Amtrak Police notified.

Delay: 14 (20) 7"

Train 59(20) Passenger Removal at Homewood, Illinois – Medical

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

20DEC25, Passenger on PNR 1147DA, traveling from Chicago, IL to New Orleans, LA was removed from the train by EMS after falling on the platform at Homewood, IL due to ice. She had a 6-inch gash. Amtrak Police notified.

Delay: 59(20) 5"

Consist Deviations

26-FOI-00197

00000005537

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
449 (20)	BOS	25049 shopped for no 480 power in car; no replacement. NYP will add 25103 to 49(20) to become 449(20) coach out of ALB.	Buses being sourced	53	NOCAR
161 (20)	BOS	OPERATING 1 CAR SHORT DUE TO EQUIPMENT SHORTAGE BOS	NONE	0	
364 (20)	CHI	Due to shopped equipment, 364(20) & 365(21) will NOT offer Biz Class. Customer service notified.	PASSENGERS NOTIFIED AND DOWNGRADED	35	NOCAR
307 (20)	CHI	due to equip swap in CHI, 307(20) & 302(21) will NOT offer biz class. customer service notified.	PASSENGERS NOTIFIED AND DOWNGRADED	11	NOCAR
80 (21)	CLT	No biz class car, coach in lieu of biz class. we're overcapacity. customer service notified.	PASSENGERS NOTIFIED AND DOWNGRADED	60	82779
79 (20)	NYP	81503 shopped; replacement 82779. coach in lieu of business class	No impact.	0	82779
49 (20)	NYP	Consist running in reverse order to add 25103 for the short coach section on 449(19).	No impact	0	25103, 25027, 25045, 25024, 68003, 62041, 62019, 61026
19 (20)	NYP	62010 (1912) VWI sleeper running in lieu of bag dorm. Please block A, B, and H room.	Rooms blocked	0	62010, 61068
79 (20)	NYP	No Biz class car, coach in lieu of biz class. customer service notified.	PASSENGERS DOWNGRADED AND NOTIFIED	60	82779
351 (20)	PNT	deadhead id4215 BYD outer steps in consist. Crew reports car cannot run live. NO BUSINESS CLASS.	PASSENGERS DOWNGRADED AND NOTIFIED	27	ID4215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
365 (21)	PTH	Due to shopped equipment, 365(21) will NOT offer Biz Class. Customer service notified.	PASSENGERS DOWNGRADED AND NOTIFIED	35	NOCAR
302 (21)	STL	due to equip swap in CHI, 302(21) will NOT off biz class. customer service notified.	PASSENGERS NOTIFIED AND DOWNGRADED	27	NOCAR
2248 (20)	WAS	Legacy Acela in lieu of Next Gen Acela.	Seat have changed.	309	

Reverse Consists

Train Number	Station	Reason
87 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front
101 (20)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (20)	NYP	Consist reversed Business class seat orientation may have changed At Front
150 (20)	PHL	Consist reversed Business class seat orientation may have changed At Front
158 (21)	NFK	Consist reversed Business class seat orientation may have changed At Front
87 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front
164 (20)	RVM	Consist reversed Business class seat orientation may have changed At Front
135 (20)	BOS	Consist reversed Business class seat orientation may have changed At Front