

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, June 13, 2026

Rules: 0-33



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 06/12/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/12/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	68	78.8%	3,786	529	86.0%	75,751	10,367	86.3%
Central Division	88.0%	68	11	83.8%	808	91	88.7%	16,780	1,689	89.9%
Northeast Division	82.0%	105	27	74.3%	1,220	196	83.9%	23,899	3,776	84.2%
Southeast Division	83.0%	69	11	84.1%	847	114	86.5%	17,316	2,521	85.4%
Southwest Division	86.0%	79	19	75.9%	911	128	85.9%	17,756	2,381	86.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00532 00000007811 "UNCLASSIFIED" 6/17/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	108,583	42,533	61%	1,261,440	398,130	68%	24,903,093	5,886,501	76%
Northeast Corridor	81%	45,604	11,507	75%	557,258	172,448	69%	10,966,384	2,576,197	77%
Acela	83%	10,679	3,334	69%	117,513	33,867	71%	2,166,262	571,354	74%
Northeast Regional	79%	34,925	8,173	77%	439,745	138,581	68%	8,800,122	2,004,843	77%
Richmond / Newport News / Norfolk	77%	8,364	2,905	65%	129,631	56,393	56%	2,729,649	734,252	73%
Springfield Shuttles	89%	781	322	59%	8,655	2,405	72%	155,224	21,620	86%
Roanoke	79%	2,603	417	84%	41,658	9,470	77%	824,411	159,493	81%
On Spine Northeast Regional	80%	23,177	4,529	80%	259,801	70,313	73%	5,090,838	1,089,478	79%
State Supported	80%	50,694	21,086	58%	555,530	139,687	75%	10,864,558	2,126,805	80%
Borealis	80%	652	75	88%	6,793	1,669	75%	139,786	29,189	79%
Capitol Corridor	90%	4,007	894	78%	46,425	4,337	91%	928,904	116,569	87%
Carolinian	70%	1,158	1,094	6%	11,618	7,245	38%	288,390	103,022	64%
Cascades	75%	3,271	867	73%	33,850	13,933	59%	625,302	168,208	73%
Downeaster	82%	1,564	0	100%	18,299	1,067	94%	365,727	41,407	89%
Empire	78%	6,419	2,606	59%	69,513	22,268	68%	1,342,561	274,689	80%
Adirondack	72%	415	19	95%	4,211	844	80%	79,019	23,175	71%
Ethan Allen Express	70%	646	342	47%	6,935	4,168	40%	139,926	39,811	72%
Maple Leaf	70%	966	420	57%	9,818	4,188	57%	159,139	58,754	63%
New York - Albany	85%	2,449	554	77%	32,945	8,163	75%	627,191	91,841	85%
New York - Niagara Falls	75%	1,551	879	43%	15,212	4,513	70%	336,894	60,716	82%
Berkshire Flyer	60%	392	392	0%	392	392	0%	392	392	0%
Gold Runner	73%	2,447	1,632	33%	30,495	13,146	57%	624,345	210,102	66%
Heartland Flyer	70%	271	0	100%	2,910	964	67%	50,714	18,911	63%
Hiawatha	90%	2,315	0	100%	22,836	2,058	91%	419,825	45,753	89%
Illinois	78%	3,995	2,905	27%	31,501	10,956	65%	612,569	159,664	74%
Carl Sandburg / Illinois Zephyr	85%	648	575	11%	5,827	1,557	73%	100,618	24,740	75%
Illini / Saluki	85%	1,272	757	40%	9,864	2,996	70%	217,290	47,960	78%
Lincoln Service	70%	2,075	1,573	24%	15,810	6,403	60%	294,661	86,964	70%
Keystone	92%	8,606	981	89%	105,910	6,774	94%	1,913,470	199,639	90%
Lincoln / Missouri	70%	1,470	958	35%	9,797	6,011	39%	190,663	92,035	52%
Mardi Gras Service	80%	425	307	28%	4,803	2,249	53%	103,432	19,159	81%
Michigan	70%	2,593	2,086	20%	26,027	11,481	56%	475,050	146,221	69%
Blue Water	70%	634	631	0%	6,014	3,160	47%	110,259	37,503	66%
Pere Marquette	85%	0	0	-	3,239	965	70%	61,513	11,750	81%
Wolverine	70%	1,959	1,455	26%	16,774	7,356	56%	303,278	96,968	68%
Missouri	80%	310	55	82%	2,773	1,029	63%	54,607	12,103	78%
Pacific Surfliner	85%	9,211	5,117	44%	97,788	18,670	81%	1,890,967	289,124	85%
Pennsylvanian	80%	838	681	19%	10,527	3,370	68%	222,388	38,511	83%
Piedmont	80%	567	529	7%	9,913	3,897	61%	293,907	72,418	75%
Vermont	75%	575	299	48%	13,752	8,563	38%	321,951	90,081	72%
Long Distance	70%	12,285	9,940	19%	148,652	85,995	42%	3,032,884	1,181,036	61%
Auto Train	70%	807	807	0%	9,045	3,650	60%	192,940	63,726	67%
California Zephyr	70%	962	706	27%	11,051	4,123	63%	241,084	71,933	70%
Cardinal	70%	0	0	-	2,691	1,255	53%	59,191	26,594	55%
City Of New Orleans	75%	711	708	0%	6,391	4,791	25%	166,643	42,546	74%
Coast Starlight	70%	1,307	625	52%	13,903	6,219	55%	280,327	93,288	67%
Crescent	70%	471	471	0%	10,796	4,212	61%	231,001	63,013	73%
Empire Builder	70%	1,261	1,261	0%	13,332	9,522	29%	232,108	104,466	55%
Floridian	60%	885	885	0%	18,531	15,855	14%	400,342	255,571	36%
Lake Shore Ltd	73%	1,028	1,028	0%	12,506	4,770	62%	232,069	64,410	72%
Palmetto	70%	905	769	15%	10,443	5,973	43%	230,302	57,883	75%
Silver Meteor	70%	1,144	997	13%	11,982	7,333	39%	252,936	98,207	61%
Southwest Chief	60%	1,009	1,006	0%	11,506	8,849	23%	200,654	123,340	39%
Sunset Ltd	70%	742	538	27%	4,172	2,635	37%	72,437	24,114	67%
Texas Eagle	70%	1,053	139	87%	12,303	6,808	45%	240,850	91,945	62%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

26-FOI-00502 00000007011 "UNCLASSIFIED" 0/17/2026

Train Index Dates Through June 12, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	81,332	1,313,669	619	1,450,507	26,687,055	544

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,381	387,336	113	68,518	7,642,323	90
INFRASTRUCTURE PLANNED	135	6,845	387,336	177	69,113	7,642,323	90
FLEET RELIABILITY	90	9,142	1,313,669	70	236,102	26,687,055	88
TRAIN OPERATIONS	424	60,937	1,313,669	464	1,076,700	26,687,055	403

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak or Commuter: **Amtrak**

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/12/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/12/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	68	78.8%	3,786	529	86.0%	75,751	10,367	86.3%
Central Division	88.0%	68	11	83.8%	808	91	88.7%	16,780	1,689	89.9%
CDL	95.0%	2	0	100.0%	27	2	92.6%	481	16	96.7%
CHI	86.0%	28	5	82.1%	329	40	87.8%	6,756	793	88.3%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	1	0.0%	1	1	0.0%	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	24	1	95.8%	500	51	89.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GRR	95.5%	-	-	-	11	0	100.0%	242	8	96.7%
KCY	92.0%	2	0	100.0%	23	1	95.7%	502	37	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	71	5	93.0%	1,493	91	93.9%
MSP	96.5%	1	1	0.0%	12	1	91.7%	248	5	98.0%
PDX	86.0%	5	1	80.0%	59	14	76.3%	1,248	154	87.7%
PNT	88.0%	3	0	100.0%	35	1	97.1%	650	55	91.5%
PTH	93.0%	1	0	100.0%	12	0	100.0%	243	10	95.9%
QCY	91.0%	2	0	100.0%	24	2	91.7%	497	36	92.8%
SEA	85.0%	8	2	75.0%	96	17	82.3%	1,997	279	86.0%
SPK	90.0%	1	-	100.0%	12	1	91.7%	248	18	92.7%
STL	89.0%	4	1	75.0%	48	3	93.8%	985	87	91.2%
TOL	-	-	-	-	-	-	-	2	2	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	24	2	91.7%	494	14	97.2%
WIP	-	-	-	-	-	-	-	57	5	91.2%
Northeast Division	82.0%	105	27	74.3%	1,220	196	83.9%	23,899	3,776	84.2%
ALB	88.5%	7	1	85.7%	95	5	94.7%	1,875	157	91.6%
BON	87.5%	5	0	100.0%	60	5	91.7%	1,223	133	89.1%
BOS	85.5%	18	2	88.9%	213	19	91.1%	4,326	540	87.5%
BRK	92.5%	5	0	100.0%	60	8	86.7%	1,214	74	93.9%
BTN	82.0%	1	0	100.0%	12	1	91.7%	241	38	84.2%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	23	4	82.6%	495	49	90.1%
HFD	-	2	0	100.0%	20	0	100.0%	123	7	94.3%
MTR	79.0%	1	0	100.0%	12	2	83.3%	238	43	81.9%
NFL	93.5%	2	0	100.0%	24	0	100.0%	514	22	95.7%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	1	80.0%	61	3	95.1%	1,318	219	83.4%
NYP	75.5%	49	19	61.2%	556	138	75.2%	10,235	2,301	77.5%
PIT	76.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
POR	-	-	-	-	-	-	-	5	3	40.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
SAB	98.0%	1	0	100.0%	11	2	81.8%	242	4	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/12/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/12/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	68	78.8%	3,786	529	86.0%	75,751	10,367	86.3%
Northeast Division	82.0%	105	27	74.3%	1,220	196	83.9%	23,899	3,776	84.2%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SPG	92.5%	5	2	60.0%	60	6	90.0%	1,553	86	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	12	2	83.3%	241	54	77.6%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
Southeast Division	83.0%	69	11	84.1%	847	114	86.5%	17,316	2,521	85.4%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CLT	91.5%	3	2	33.3%	57	12	78.9%	1,251	121	90.3%
GRO	-	-	-	-	8	3	62.5%	25	8	68.0%
HAR	79.5%	13	1	92.3%	144	10	93.1%	2,825	487	82.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	12	1	91.7%	251	32	87.3%
MIA	89.5%	2	0	100.0%	24	5	79.2%	503	51	89.9%
MOE	97.5%	2	0	100.0%	24	0	100.0%	509	7	98.6%
NFK	84.5%	2	1	50.0%	24	10	58.3%	585	102	82.6%
NOL	94.5%	4	0	100.0%	50	2	96.0%	1,073	47	95.6%
NPN	93.0%	2	1	50.0%	24	1	95.8%	477	30	93.7%
PGH	93.0%	1	1	0.0%	12	1	91.7%	253	18	92.9%
PHL	48.0%	5	2	60.0%	58	29	50.0%	1,316	647	50.8%
RGH	95.0%	2	1	50.0%	38	3	92.1%	989	40	96.0%
RNK	83.5%	2	0	100.0%	24	2	91.7%	498	73	85.3%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	96.0%	1	0	100.0%	12	1	91.7%	250	9	96.4%
SFA	88.0%	1	1	0.0%	12	1	91.7%	251	31	87.6%
WAS	84.0%	28	1	96.4%	324	33	89.8%	6,103	796	87.0%
Southwest Division	86.0%	79	19	75.9%	911	128	85.9%	17,756	2,381	86.6%
ARN	92.0%	1	0	100.0%	11	0	100.0%	253	17	93.3%
BFD	79.0%	6	5	16.7%	81	20	75.3%	1,567	308	80.3%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	72.0%	1	0	100.0%	12	4	66.7%	269	78	71.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	92.5%	1	0	100.0%	12	2	83.3%	278	34	87.8%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GJT	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
GTA	90.0%	3	1	66.7%	36	14	61.1%	762	97	87.3%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	12	1	91.7%	126	9	92.9%	2,484	248	90.0%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKC	97.0%	1	0	100.0%	12	0	100.0%	249	4	98.4%
OKJ	74.5%	13	3	76.9%	148	31	79.1%	2,695	666	75.3%
RNO	-	-	-	-	-	-	-	1	1	0.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 06/12/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 06/12/2026			ITP June 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	68	78.8%	3,786	529	86.0%	75,751	10,367	86.3%
Southwest Division	86.0%	79	19	75.9%	911	128	85.9%	17,756	2,381	86.6%
SAC	88.5%	16	7	56.3%	184	31	83.2%	3,542	374	89.4%
SAN	90.5%	13	1	92.3%	156	9	94.2%	3,011	273	90.9%
SAS	90.5%	1	0	100.0%	12	2	83.3%	251	25	90.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SJC	89.0%	7	0	100.0%	84	2	97.6%	1,781	168	90.6%
SKN	-	-	-	-	-	-	-	7	6	14.3%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	36	4	88.9%	527	51	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	139	5	0	100.0%	107	7	93.5%	6	5	16.7%	108	21	80.6%
2		5	1	80.0%	108	24	77.8%	5	2	60.0%	104	18	82.7%
3	459	12	5	58.3%	253	47	81.4%	12	6	50.0%	252	107	57.5%
4	86	12	4	66.7%	253	37	85.4%	12	9	25.0%	253	166	34.4%
5	77	12	1	91.7%	252	39	84.5%	13	4	69.2%	249	52	79.1%
5	No OS	12	1	91.7%	252	39	84.5%	13	4	69.2%	249	52	79.1%
6	No OS	12	4	66.7%	251	71	71.7%	13	5	61.5%	252	70	72.2%
6	242	12	4	66.7%	251	71	71.7%	13	5	61.5%	252	70	72.2%
7	534	12	0	100.0%	242	28	88.4%	12	6	50.0%	235	54	77.0%
8	66	12	6	50.0%	242	99	59.1%	12	11	8.3%	241	133	44.8%
11		12	3	75.0%	253	45	82.2%	12	4	66.7%	247	49	80.2%
14	42	12	1	91.7%	254	39	84.6%	12	7	41.7%	252	71	71.8%
19	260	12	3	75.0%	252	59	76.6%	12	3	75.0%	251	51	79.7%
20	124	12	1	91.7%	252	17	93.3%	12	4	66.7%	252	41	83.7%
21		12	0	100.0%	249	22	91.2%	12	1	91.7%	248	58	76.6%
22		12	2	83.3%	250	23	90.8%	12	8	33.3%	248	59	76.2%
23	44	12	0	100.0%	255	5	98.0%	12	6	50.0%	254	60	76.4%
24	24	12	0	100.0%	255	14	94.5%	12	4	66.7%	254	34	86.6%
25		12	0	100.0%	254	2	99.2%	12	7	41.7%	253	61	75.9%
26	30	12	0	100.0%	254	3	98.8%	12	7	41.7%	253	45	82.2%
27	201	12	3	75.0%	240	15	93.8%	12	7	41.7%	236	72	69.5%
28	144	12	8	33.3%	236	54	77.1%	12	7	41.7%	236	43	81.8%
40	197	12	3	75.0%	248	31	87.5%	12	10	16.7%	247	114	53.8%
41	437	12	5	58.3%	248	96	61.3%	12	10	16.7%	246	178	27.6%
42	58	12	1	91.7%	254	19	92.5%	12	2	83.3%	252	41	83.7%
43	45	12	1	91.7%	253	38	85.0%	12	5	58.3%	253	47	81.4%
48	317	12	2	83.3%	252	51	79.8%	12	2	83.3%	252	37	85.3%
49	146	12	3	75.0%	252	64	74.6%	12	2	83.3%	252	48	81.0%
50	No OS	5	2	60.0%	103	26	74.8%	5	4	20.0%	103	56	45.6%
52	57	12	1	91.7%	251	31	87.6%	12	3	75.0%	250	55	78.0%
53	90	12	1	91.7%	251	32	87.3%	12	5	58.3%	250	76	69.6%
55	116	9	1	88.9%	156	5	96.8%	9	5	44.4%	153	32	79.1%
56	138	10	1	90.0%	157	21	86.6%	10	5	50.0%	155	26	83.2%
58	129	12	2	83.3%	244	14	94.3%	12	9	25.0%	243	55	77.4%
59	247	12	3	75.0%	243	23	90.5%	12	7	41.7%	241	39	83.8%
63	43	12	5	58.3%	255	112	56.1%	12	11	8.3%	251	126	49.8%
64	26	12	2	83.3%	253	61	75.9%	12	9	25.0%	253	77	69.6%
66		12	2	83.3%	252	53	79.0%	12	1	91.7%	250	44	82.4%
67		9	0	100.0%	174	11	93.7%	10	1	90.0%	175	28	84.0%
68		12	2	83.3%	255	52	79.6%	12	3	75.0%	255	98	61.6%
69		12	5	58.3%	242	51	78.9%	12	2	83.3%	238	25	89.5%
71	51	12	0	100.0%	250	3	98.8%	12	4	66.7%	249	60	75.9%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
72	147	12	3	75.0%	250	25	90.0%	12	5	58.3%	249	47	81.1%
73	80	12	5	58.3%	254	16	93.7%	11	7	36.4%	252	122	51.6%
78	23	12	3	75.0%	250	17	93.2%	12	4	66.7%	249	44	82.3%
79	80	12	4	66.7%	252	51	79.8%	12	8	33.3%	251	74	70.5%
80	174	12	3	75.0%	252	25	90.1%	12	5	58.3%	251	41	83.7%
84		10	0	100.0%	150	11	92.7%	10	2	80.0%	148	28	81.1%
85	33	10	1	90.0%	158	16	89.9%	10	6	40.0%	158	56	64.6%
86	28	10	0	100.0%	158	11	93.0%	10	10	0.0%	157	93	40.8%
89		12	3	75.0%	250	55	78.0%	12	3	75.0%	248	62	75.0%
90	192	12	1	91.7%	250	9	96.4%	12	7	41.7%	249	33	86.7%
93	100	10	0	100.0%	157	18	88.5%	10	4	60.0%	156	34	78.2%
94		10	4	60.0%	188	46	75.5%	10	3	70.0%	186	64	65.6%
95	86	10	0	100.0%	157	3	98.1%	10	5	50.0%	157	53	66.2%
97	116	12	8	33.3%	252	158	37.3%	12	7	41.7%	250	67	73.2%
98	44	12	2	83.3%	252	19	92.5%	12	6	50.0%	250	71	71.6%
110		9	8	11.1%	154	91	40.9%	9	1	88.9%	151	16	89.4%
111		10	1	90.0%	148	29	80.4%	10	0	100.0%	146	18	87.7%
112		10	0	100.0%	148	15	89.9%	10	0	100.0%	147	16	89.1%
113	26	10	4	60.0%	79	19	75.9%	10	1	90.0%	78	9	88.5%
119		10	3	70.0%	148	39	73.6%	10	1	90.0%	146	19	87.0%
125	245	10	0	100.0%	158	8	94.9%	10	6	40.0%	158	60	62.0%
129		10	3	70.0%	157	43	72.6%	10	4	60.0%	157	23	85.4%
130		10	1	90.0%	148	15	89.9%	10	0	100.0%	146	12	91.8%
131		10	3	70.0%	150	43	71.3%	10	2	80.0%	150	29	80.7%
134		10	1	90.0%	158	19	88.0%	10	0	100.0%	157	23	85.4%
136		10	0	100.0%	158	18	88.6%	9	1	88.9%	156	16	89.7%
137	59	10	2	80.0%	155	30	80.6%	10	4	60.0%	155	47	69.7%
138	123	10	5	50.0%	158	34	78.5%	10	4	60.0%	157	22	86.0%
141		10	0	100.0%	157	3	98.1%	10	1	90.0%	156	27	82.7%
148		10	1	90.0%	157	16	89.8%	10	1	90.0%	155	28	81.9%
151	20	12	6	50.0%	251	81	67.7%	12	4	66.7%	250	78	68.8%
170		10	0	100.0%	153	11	92.8%	10	0	100.0%	152	28	81.6%
171	161	10	0	100.0%	158	10	93.7%	10	6	40.0%	158	54	65.8%
172		10	0	100.0%	157	14	91.1%	10	5	50.0%	155	50	67.7%
173		10	0	100.0%	153	21	86.3%	10	5	50.0%	152	66	56.6%
174	37	10	2	80.0%	158	19	88.0%	10	3	70.0%	158	30	81.0%
175	16	10	1	90.0%	158	20	87.3%	10	4	60.0%	158	51	67.7%
176		10	2	80.0%	153	13	91.5%	10	1	90.0%	151	15	90.1%
177		10	1	90.0%	158	23	85.4%	10	1	90.0%	158	43	72.8%
178		10	0	100.0%	158	22	86.1%	9	1	88.9%	156	23	85.3%
179	22	10	2	80.0%	158	16	89.9%	9	7	22.2%	157	55	65.0%
181		10	8	20.0%	154	52	66.2%	10	1	90.0%	152	10	93.4%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		10	2	80.0%	148	27	81.8%	10	0	100.0%	146	14	90.4%
183		10	3	70.0%	157	47	70.1%	10	0	100.0%	155	32	79.4%
184		10	0	100.0%	158	26	83.5%	10	0	100.0%	157	21	86.6%
185		10	1	90.0%	158	35	77.8%	10	0	100.0%	158	10	93.7%
186	177	10	1	90.0%	157	15	90.4%	10	5	50.0%	156	35	77.6%
190	38	10	2	80.0%	157	56	64.3%	10	3	70.0%	156	37	76.3%
192		10	0	100.0%	155	19	87.7%	10	1	90.0%	155	14	91.0%
193		10	7	30.0%	157	67	57.3%	10	7	30.0%	156	72	53.8%
196		10	3	70.0%	157	16	89.8%	10	0	100.0%	156	13	91.7%
197		10	4	60.0%	158	67	57.6%	10	6	40.0%	158	49	69.0%
198		10	2	80.0%	90	13	85.6%	9	2	77.8%	89	14	84.3%
230		12	0	100.0%	89	4	95.5%	12	0	100.0%	89	5	94.4%
232		12	1	91.7%	255	11	95.7%	12	1	91.7%	255	17	93.3%
234		12	0	100.0%	255	19	92.5%	12	0	100.0%	255	21	91.8%
235		12	4	66.7%	179	25	86.0%	12	4	66.7%	179	34	81.0%
236		12	0	100.0%	239	7	97.1%	12	2	83.3%	239	30	87.4%
237		11	2	81.8%	253	51	79.8%	11	3	72.7%	251	42	83.3%
238		12	2	83.3%	179	19	89.4%	12	4	66.7%	178	14	92.1%
239		12	3	75.0%	254	70	72.4%	12	2	83.3%	253	26	89.7%
240	18	12	0	100.0%	254	18	92.9%	11	5	54.5%	252	33	86.9%
241	26	12	3	75.0%	255	66	74.1%	12	6	50.0%	255	62	75.7%
243	Cncld	12	2	83.3%	191	53	72.3%	11	0	100.0%	190	24	87.4%
245		12	2	83.3%	136	23	83.1%	12	0	100.0%	135	13	90.4%
280	69	12	0	100.0%	255	11	95.7%	12	4	66.7%	255	44	82.7%
281		12	1	91.7%	255	26	89.8%	12	4	66.7%	255	40	84.3%
283	40	12	5	58.3%	255	57	77.6%	12	2	83.3%	255	45	82.4%
284		12	0	100.0%	255	10	96.1%	12	2	83.3%	253	36	85.8%
290		12	1	91.7%	255	47	81.6%	12	8	33.3%	253	79	68.8%
291	27	12	6	50.0%	254	62	75.6%	12	8	33.3%	252	46	81.7%
300	35	12	0	100.0%	239	18	92.5%	12	2	83.3%	237	51	78.5%
301	97	12	1	91.7%	253	9	96.4%	12	3	75.0%	250	46	81.6%
302		12	2	83.3%	240	30	87.5%	11	4	63.6%	236	67	71.6%
305		12	2	83.3%	243	28	88.5%	12	6	50.0%	239	95	60.3%
306	56	12	1	91.7%	251	14	94.4%	12	7	41.7%	250	65	74.0%
307	131	12	2	83.3%	243	32	86.8%	12	5	58.3%	240	66	72.5%
311		12	0	100.0%	253	23	90.9%	11	2	81.8%	248	47	81.0%
316		11	0	100.0%	250	16	93.6%	11	5	54.5%	247	57	76.9%
318		12	1	91.7%	254	23	90.9%	12	9	25.0%	251	111	55.8%
319	118	12	2	83.3%	255	16	93.7%	12	8	33.3%	253	130	48.6%
329		10	1	90.0%	180	8	95.6%	10	0	100.0%	180	12	93.3%
330		11	0	100.0%	216	4	98.1%	11	0	100.0%	216	13	94.0%
331		12	2	83.3%	255	28	89.0%	12	1	91.7%	255	37	85.5%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		12	1	91.7%	255	13	94.9%	12	2	83.3%	255	36	85.9%
334		12	1	91.7%	255	7	97.3%	12	3	75.0%	254	32	87.4%
335		12	0	100.0%	255	27	89.4%	12	1	91.7%	253	40	84.2%
336		12	0	100.0%	255	8	96.9%	12	2	83.3%	253	21	91.7%
337		12	0	100.0%	255	17	93.3%	12	1	91.7%	251	30	88.0%
338		12	1	91.7%	255	38	85.1%	12	4	66.7%	253	74	70.8%
339		12	2	83.3%	255	44	82.7%	12	2	83.3%	255	44	82.7%
341		12	2	83.3%	245	33	86.5%	11	2	81.8%	241	33	86.3%
342		12	2	83.3%	255	21	91.8%	12	2	83.3%	253	46	81.8%
350	18	12	0	100.0%	236	15	93.6%	12	10	16.7%	231	125	45.9%
351		12	1	91.7%	238	23	90.3%	12	1	91.7%	237	63	73.4%
352	54	12	0	100.0%	223	17	92.4%	12	4	66.7%	218	67	69.3%
353	25	12	0	100.0%	198	12	93.9%	12	4	66.7%	192	34	82.3%
354	26	12	3	75.0%	236	22	90.7%	12	4	66.7%	232	80	65.5%
355	78	11	0	100.0%	249	26	89.6%	10	5	50.0%	242	81	66.5%
364	148	12	2	83.3%	244	52	78.7%	12	7	41.7%	238	77	67.6%
365	43	12	0	100.0%	243	10	95.9%	12	6	50.0%	241	78	67.6%
370	138	12	2	83.3%	246	31	87.4%	10	4	60.0%	240	58	75.8%
380	16	12	0	100.0%	242	23	90.5%	12	2	83.3%	242	44	81.8%
381		12	1	91.7%	255	10	96.1%	12	3	75.0%	255	41	83.9%
382	32	12	2	83.3%	255	13	94.9%	12	8	33.3%	255	79	69.0%
383	No OS	12	0	100.0%	244	23	90.6%	12	5	58.3%	242	92	62.0%
390		12	0	100.0%	237	15	93.7%	12	3	75.0%	236	55	76.7%
391	39	12	0	100.0%	240	6	97.5%	12	5	58.3%	237	51	78.5%
392	16	12	1	91.7%	254	5	98.0%	12	6	50.0%	252	72	71.4%
393	17	12	0	100.0%	255	15	94.1%	12	5	58.3%	253	69	72.7%
417		10	3	70.0%	168	35	79.2%	10	1	90.0%	159	15	90.6%
425		9	0	100.0%	170	6	96.5%	9	0	100.0%	170	7	95.9%
448	374	12	3	75.0%	185	37	80.0%	12	6	50.0%	183	64	65.0%
449	52	12	2	83.3%	183	29	84.2%	12	4	66.7%	183	33	82.0%
470		11	3	72.7%	181	34	81.2%	10	2	80.0%	175	23	86.9%
471		10	0	100.0%	171	5	97.1%	10	0	100.0%	171	2	98.8%
473		10	0	100.0%	177	13	92.7%	10	0	100.0%	174	8	95.4%
474	51	10	3	70.0%	171	47	72.5%	10	7	30.0%	160	41	74.4%
475	93	9	2	77.8%	175	5	97.1%	9	3	66.7%	175	9	94.9%
478	27	10	1	90.0%	169	27	84.0%	10	3	70.0%	167	19	88.6%
479	69	10	3	70.0%	176	28	84.1%	10	3	70.0%	174	19	89.1%
486	104	10	2	80.0%	180	27	85.0%	10	4	60.0%	174	46	73.6%
494		10	2	80.0%	181	33	81.8%	10	0	100.0%	175	41	76.6%
495		10	0	100.0%	166	3	98.2%	10	0	100.0%	164	3	98.2%
500		11	0	100.0%	246	15	93.9%	11	1	90.9%	244	29	88.1%
502		12	1	91.7%	253	14	94.5%	12	1	91.7%	250	54	78.4%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
503		12	0	100.0%	251	20	92.0%	12	2	83.3%	245	61	75.1%
504		12	0	100.0%	255	16	93.7%	12	5	58.3%	253	75	70.4%
505		12	2	83.3%	253	32	87.4%	12	6	50.0%	250	68	72.8%
506		12	1	91.7%	250	34	86.4%	11	3	72.7%	245	38	84.5%
507	16	12	3	75.0%	255	31	87.8%	12	5	58.3%	255	78	69.4%
508		12	1	91.7%	250	39	84.4%	12	5	58.3%	247	57	76.9%
509		12	1	91.7%	252	12	95.2%	12	6	50.0%	252	60	76.2%
511		12	1	91.7%	247	21	91.5%	12	4	66.7%	246	45	81.7%
516	64	12	1	91.7%	247	25	89.9%	12	9	25.0%	246	112	54.5%
517	19	12	1	91.7%	255	8	96.9%	11	9	18.2%	251	98	61.0%
518	21	12	4	66.7%	255	33	87.1%	12	11	8.3%	253	169	33.2%
519		12	1	91.7%	247	9	96.4%	12	3	75.0%	245	60	75.5%
520		10	3	70.0%	138	21	84.8%	10	0	100.0%	135	8	94.1%
521		10	1	90.0%	176	7	96.0%	10	1	90.0%	176	21	88.1%
522		10	3	70.0%	176	31	82.4%	10	1	90.0%	173	17	90.2%
523		10	0	100.0%	176	6	96.6%	10	2	80.0%	175	22	87.4%
524		10	0	100.0%	176	11	93.8%	9	2	77.8%	174	20	88.5%
525	Cncld	10	0	100.0%	174	10	94.3%	9	1	88.9%	171	13	92.4%
526	Cncld	10	4	60.0%	150	27	82.0%	9	1	88.9%	147	12	91.8%
527	11	10	1	90.0%	176	7	96.0%	10	2	80.0%	176	31	82.4%
528		10	0	100.0%	176	13	92.6%	10	0	100.0%	175	29	83.4%
529	75	10	0	100.0%	176	10	94.3%	10	3	70.0%	175	45	74.3%
530		10	0	100.0%	130	12	90.8%	10	1	90.0%	130	23	82.3%
531		10	1	90.0%	150	11	92.7%	10	1	90.0%	150	11	92.7%
532		10	3	70.0%	176	38	78.4%	10	3	70.0%	176	26	85.2%
534		10	0	100.0%	135	19	85.9%	9	0	100.0%	133	11	91.7%
535		10	2	80.0%	163	23	85.9%	10	0	100.0%	158	20	87.3%
536		10	0	100.0%	176	43	75.6%	10	0	100.0%	173	35	79.8%
537		10	3	70.0%	147	16	89.1%	10	1	90.0%	142	12	91.5%
538		10	0	100.0%	176	21	88.1%	9	1	88.9%	175	33	81.1%
539	36	10	5	50.0%	130	17	86.9%	10	6	40.0%	130	58	55.4%
540		10	3	70.0%	176	35	80.1%	10	1	90.0%	169	17	89.9%
541	Cncld	10	3	70.0%	175	20	88.6%	8	2	75.0%	170	33	80.6%
542		10	0	100.0%	175	20	88.6%	10	2	80.0%	173	31	82.1%
543		10	1	90.0%	176	16	90.9%	10	1	90.0%	176	46	73.9%
544		10	1	90.0%	174	20	88.5%	10	0	100.0%	171	14	91.8%
545	17	10	0	100.0%	176	12	93.2%	10	2	80.0%	174	20	88.5%
547	51	10	2	80.0%	176	35	80.1%	10	3	70.0%	176	43	75.6%
548		10	0	100.0%	176	20	88.6%	10	1	90.0%	175	14	92.0%
549		10	2	80.0%	171	23	86.5%	8	1	87.5%	165	15	90.9%
550		10	0	100.0%	130	13	90.0%	10	3	70.0%	130	26	80.0%
551		10	3	70.0%	172	18	89.5%	10	2	80.0%	164	16	90.2%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		12	0	100.0%	247	18	92.7%	12	0	100.0%	244	27	88.9%
564		12	2	83.3%	247	15	93.9%	12	2	83.3%	239	28	88.3%
566		12	0	100.0%	245	16	93.5%	12	0	100.0%	242	30	87.6%
567		12	1	91.7%	132	7	94.7%	12	0	100.0%	130	5	96.2%
572	60	12	0	100.0%	242	21	91.3%	12	5	58.3%	237	57	75.9%
573	67	12	1	91.7%	245	36	85.3%	12	4	66.7%	238	41	82.8%
579	45	12	0	100.0%	132	8	93.9%	12	2	83.3%	127	23	81.9%
580		12	0	100.0%	247	11	95.5%	12	1	91.7%	243	20	91.8%
581	21	12	2	83.3%	247	40	83.8%	12	2	83.3%	245	47	80.8%
584	33	12	0	100.0%	131	13	90.1%	12	8	33.3%	128	71	44.5%
587	25	12	0	100.0%	242	14	94.2%	12	2	83.3%	233	32	86.3%
588	34	12	0	100.0%	132	9	93.2%	12	2	83.3%	132	19	85.6%
591	25	12	1	91.7%	246	16	93.5%	12	2	83.3%	241	25	89.6%
593		12	0	100.0%	241	33	86.3%	12	0	100.0%	225	24	89.3%
595		12	1	91.7%	243	39	84.0%	12	0	100.0%	241	40	83.4%
600		10	0	100.0%	185	9	95.1%	10	0	100.0%	183	14	92.3%
601		10	0	100.0%	168	70	58.3%	10	0	100.0%	165	23	86.1%
605		10	7	30.0%	175	112	36.0%	10	0	100.0%	171	19	88.9%
607	24	10	3	70.0%	184	22	88.0%	10	1	90.0%	181	22	87.8%
609		10	0	100.0%	175	22	87.4%	10	0	100.0%	174	14	92.0%
626		10	0	100.0%	89	11	87.6%	10	1	90.0%	87	15	82.8%
639		10	3	70.0%	156	36	76.9%	10	0	100.0%	155	18	88.4%
640		10	0	100.0%	175	6	96.6%	10	3	70.0%	173	73	57.8%
641		10	3	70.0%	157	31	80.3%	10	1	90.0%	157	23	85.4%
642		10	1	90.0%	173	7	96.0%	10	0	100.0%	172	22	87.2%
643		10	0	100.0%	187	39	79.1%	10	0	100.0%	185	31	83.2%
644		10	0	100.0%	179	26	85.5%	10	1	90.0%	177	45	74.6%
645		10	2	80.0%	187	37	80.2%	10	3	70.0%	185	36	80.5%
646	14	10	0	100.0%	176	45	74.4%	10	1	90.0%	174	84	51.7%
647	11	10	0	100.0%	187	31	83.4%	10	2	80.0%	186	41	78.0%
648		10	2	80.0%	183	49	73.2%	10	0	100.0%	183	31	83.1%
649		10	1	90.0%	188	32	83.0%	10	0	100.0%	185	31	83.2%
650		10	1	90.0%	187	39	79.1%	10	2	80.0%	184	28	84.8%
651		10	1	90.0%	187	16	91.4%	10	2	80.0%	185	38	79.5%
652		10	1	90.0%	188	26	86.2%	10	1	90.0%	184	32	82.6%
653		10	1	90.0%	176	29	83.5%	10	2	80.0%	174	33	81.0%
654		10	0	100.0%	177	36	79.7%	10	0	100.0%	174	16	90.8%
655	12	10	4	60.0%	185	67	63.8%	10	5	50.0%	183	65	64.5%
656		10	3	70.0%	187	43	77.0%	10	0	100.0%	186	21	88.7%
657		10	0	100.0%	176	25	85.8%	10	2	80.0%	175	25	85.7%
658		10	1	90.0%	187	31	83.4%	10	1	90.0%	185	30	83.8%
680		10	1	90.0%	181	8	95.6%	10	0	100.0%	180	22	87.8%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681		10	0	100.0%	181	12	93.4%	10	4	60.0%	176	66	62.5%
682		10	0	100.0%	180	3	98.3%	10	0	100.0%	180	31	82.8%
683		10	0	100.0%	163	15	90.8%	10	3	70.0%	162	45	72.2%
684		10	3	70.0%	162	22	86.4%	10	2	80.0%	162	35	78.4%
685		10	2	80.0%	177	27	84.7%	10	1	90.0%	175	41	76.6%
686		10	1	90.0%	182	31	83.0%	10	1	90.0%	182	35	80.8%
687		10	0	100.0%	182	29	84.1%	10	2	80.0%	181	29	84.0%
688		10	3	70.0%	180	8	95.6%	10	2	80.0%	180	29	83.9%
701	42	12	2	83.3%	187	17	90.9%	12	3	75.0%	184	16	91.3%
702	146	12	2	83.3%	254	28	89.0%	11	2	81.8%	252	53	79.0%
703	No OS	12	8	33.3%	255	70	72.5%	12	6	50.0%	254	64	74.8%
704	Cncld	12	3	75.0%	186	30	83.9%	11	1	90.9%	181	35	80.7%
710	140	12	1	91.7%	255	65	74.5%	12	6	50.0%	251	66	73.7%
711		12	2	83.3%	246	24	90.2%	12	2	83.3%	230	38	83.5%
712	63	12	3	75.0%	252	63	75.0%	12	6	50.0%	244	78	68.0%
714	61	12	4	66.7%	138	48	65.2%	11	8	27.3%	129	50	61.2%
715	No OS	12	2	83.3%	254	54	78.7%	10	6	40.0%	237	115	51.5%
716	37	12	2	83.3%	255	100	60.8%	12	6	50.0%	250	96	61.6%
717	203	12	4	66.7%	241	56	76.8%	9	4	55.6%	224	62	72.3%
718	133	12	5	58.3%	255	124	51.4%	12	4	66.7%	253	82	67.6%
719	No OS	12	2	83.3%	255	81	68.2%	12	3	75.0%	243	67	72.4%
757		12	1	91.7%	40	2	95.0%	12	1	91.7%	40	2	95.0%
761		12	1	91.7%	251	10	96.0%	12	1	91.7%	248	33	86.7%
765		12	0	100.0%	251	24	90.4%	12	0	100.0%	251	35	86.1%
769	28	12	0	100.0%	251	23	90.8%	12	3	75.0%	245	46	81.2%
770	22	12	1	91.7%	251	21	91.6%	12	4	66.7%	249	66	73.5%
774	56	12	0	100.0%	251	16	93.6%	12	3	75.0%	250	52	79.2%
777	59	12	0	100.0%	136	9	93.4%	12	2	83.3%	136	32	76.5%
782		12	12	0.0%	136	40	70.6%	12	1	91.7%	131	11	91.6%
785	32	12	2	83.3%	251	15	94.0%	12	2	83.3%	251	41	83.7%
786	21	12	3	75.0%	40	8	80.0%	12	5	58.3%	39	17	56.4%
790		12	1	91.7%	251	25	90.0%	12	0	100.0%	249	26	89.6%
794		12	1	91.7%	251	30	88.0%	12	3	75.0%	249	54	78.3%
821		12	0	100.0%	249	4	98.4%	12	5	58.3%	249	98	60.6%
822		12	2	83.3%	251	14	94.4%	12	5	58.3%	249	109	56.2%
1233	165	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
1246	161	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
1333		12	0	100.0%	251	26	89.6%	12	5	58.3%	248	84	66.1%
1340		12	1	91.7%	250	5	98.0%	12	2	83.3%	250	41	83.6%
1689		6	0	100.0%	64	5	92.2%	5	1	80.0%	63	7	88.9%
2102		10	4	60.0%	34	12	64.7%	10	1	90.0%	33	3	90.9%
2103		10	1	90.0%	98	10	89.8%	10	2	80.0%	97	8	91.8%

Amtrak On Time Performance

Trains Arriving Through: 6/12/2026

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2104		10	0	100.0%	124	9	92.7%	10	0	100.0%	122	9	92.6%
2107		10	3	70.0%	155	29	81.3%	10	1	90.0%	152	19	87.5%
2108		10	1	90.0%	155	24	84.5%	10	0	100.0%	149	16	89.3%
2110		10	1	90.0%	34	2	94.1%	10	1	90.0%	34	5	85.3%
2113		10	0	100.0%	34	2	94.1%	10	0	100.0%	34	4	88.2%
2115		10	1	90.0%	34	3	91.2%	10	1	90.0%	34	4	88.2%
2121		10	1	90.0%	151	27	82.1%	10	2	80.0%	149	25	83.2%
2122		10	0	100.0%	153	16	89.5%	10	2	80.0%	153	14	90.8%
2123	18	10	1	90.0%	34	4	88.2%	10	4	60.0%	34	11	67.6%
2124		10	1	90.0%	127	20	84.3%	10	1	90.0%	126	11	91.3%
2126		10	3	70.0%	92	22	76.1%	10	0	100.0%	91	18	80.2%
2150	23	10	0	100.0%	148	22	85.1%	10	2	80.0%	145	66	54.5%
2151		10	2	80.0%	97	6	93.8%	10	3	70.0%	95	26	72.6%
2155	20	10	1	90.0%	157	14	91.1%	10	6	40.0%	154	88	42.9%
2159	24	10	0	100.0%	150	9	94.0%	10	4	60.0%	149	44	70.5%
2162	30	10	1	90.0%	157	12	92.4%	10	5	50.0%	153	76	50.3%
2163	18	10	0	100.0%	157	17	89.2%	10	5	50.0%	151	65	57.0%
2166	22	10	0	100.0%	153	13	91.5%	10	5	50.0%	151	37	75.5%
2167	17	10	0	100.0%	147	18	87.8%	10	3	70.0%	147	35	76.2%
2170	31	10	0	100.0%	127	38	70.1%	10	8	20.0%	123	54	56.1%
2171		10	1	90.0%	84	8	90.5%	10	0	100.0%	81	17	79.0%
2172		10	0	100.0%	129	10	92.2%	10	0	100.0%	128	28	78.1%
2190	35	10	1	90.0%	156	24	84.6%	10	1	90.0%	154	22	85.7%
2192		10	4	60.0%	82	18	78.0%	10	1	90.0%	82	4	95.1%
2193		10	2	80.0%	155	23	85.2%	10	1	90.0%	153	45	70.6%

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2123	WAS	18	OTH	10	OTH	7	PHL-XPV	AM	Lost time - N.A.R., no train ahead
2150	BOS	23	CTI	30	CTI	11	STM-XNH	MN	Follow MN, Milepost, 33, 55
2155	WAS	20	OTH	18	HLD	5	NYP-NYP	AM	Passenger and/or baggage, HEAVY LOADING
2159	WAS	24	OTH	19	WTR	10	XCY-XHM	AM	Heat order, Other, XCY-XHM
2162	BOS	30	CTI	14	DMW	11	STM-NHV	MN	Hold for defect repair Control Point, East Norwalk
2163	WAS	18	DSR	10	DSR	5	NHV-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2
2166	BOS	22	ADA	9	DET	9	XHM-XCY	AM	Catenary maintenance , Other, TRE-XCY, OPR 1 TRK A/C CONGESTION ON 2 TRK A/C DET CATENARY INSPECTION ON 3 TRK XCY TO HAM
2167	WAS	17	SMW	14	SMW	11	XSH-NYP	AM	Scheduled in track usage program, Other, LEGGETT, HELD FOR SINGLE TRACKING PELHAM BAY A/C SCHEDULED MAINTENANCE PELHAM BAY TO LEGGETT
2170	BOS	31	DSR	16	DSR	9	STM-NHV	MN	Per bulletin Milepost, 38.2, 41.7, 30, 4, Milepost, 40.4, 41.7, 30, 2, Milepost, 41.7, 42.0, 15, 2, Milepost, 48.4, 48.6, 30, 2
2190	BOS	35	ENG	31	ENG	31	STM-STM	MN	Battery charge low alert 2035
85	WAS	33	ENG	18	ENG	18	PHL-PHL	AM	Other electrical failure, 622, REQUESTED MECH A/C HOT ENG CABIN
86	BOS	28	CTI	27	CTI	14	WDB-ALX	CS	Follow VRE, 31012, Other, ALL
93	NFK	100	DBS	73	DBS	73	FBG-ASD	CS	Debris blocking track (no debris strike) Stopped at crossroads to wait for trees to be cleared from tracks, Control Point, crossroads
95	NFK	86	DSR	94	DSR	76	X3V-NFK	NS	Per bulletin Account heat restriction, Milepost, 52.0, 3.5, 25, 2
113	WAS	26	SVS	48	SVS	48	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
125	NPN	245	DBS	182	DBS	182	FBG-FBG	CS	Debris blocking track (no debris strike) Held at FBG station due to trees reported blocking tracks around cfp 42. Reported as 4-5 trees needing removal., Milepost, 59.3, 59.3
137	WAS	59	ITI	78	ITI	78	BOS-BOS	AM	Service, turn, or wye train, 190, AM137 will be late dp BOS today due mechanical issues on the eq. Train turned from AM190 which was dealing with the hot journal alarm

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
138	NYP	123	DSR	68	DSR	64	NFK-X3V	NS	Per bulletin Milepost, 3.5, 8.55, 25, both, Milepost, 8.6, 22.2, 25, both, Milepost, 22.2, 52.0, 25, both
151	RNK	20	PTI	24	PTI	14	CVS-LYH	NS	Meet po20, Milepost, 164.2, 164.2
171	RNK	161	RTE	77	RTE	77	CVS-CVS	NS	Dispatcher hold Dispatch holds AMTK 171 at Charlottesville station milepost 112.1 due to tire fire by tracks at milepost 115.1 at 8:09pm. At 9:36pm. Dispatch gives clear signal to leave Charlottesville and fire is clear., Other, 112.1
174	BOS	37	HLD	16	ENG	8	PHL-PHL	AM	Other electrical failure, 625, Mechanical assistance a/c MCB constantly opening.
175	WAS	16	CTI	33	CTI	21	NHV-STM	MN	Follow metto, Other, enroure
179	PHL	22	SMW	18	SMW	9	TRE-XHM	AM	Diversions around M/W work, Other, XGY-XHM, HELD ON NO.3 TRACK BTWN GRUNDY AND HOLMES A/C CETC 6 TRACK WORK WEST OF HOLMES ON NO.3 TRACK.
186	PHL	177	WTR	196	WTR	167	ASD-FBG	CS	Trees down Other, MP CFP 42.6
190	BOS	38	CAR	30	CAR	28	RTE-RTE	AM	Onboard HBD alarm, 81518, INSPECTED AT THE RTE
474	SPG	51	CON	37	CON	37	NHV-NHV	AM	Hold for connecting train
475	NHV	93	WTR	100	WTR	55	SPG-SPG	AM	Trees down, Other, SPG, tree down between Hayden - Field
478	SPG	27	ITI	21	ITI	21	NHV-NHV	AM	Service, turn, or wye train, 479, late turn
479	NHV	69	ITI	75	ITI	75	GFD-GFD	MA	486 late 486
486	GFD	104	WTR	46	WTR	25	WND-WNL	AM	Trees down, Milepost w/Letters, WND, WNL, tree down btwn Hayden - Field
52	LOR	57	FTI	47	SVS	34	XJG-XSA	CS	Water, commissary, toilet/trash dumping Watering car 32114, Other, Savannah Station
53	SFA	90	FTI	102	FTI	35	XSE-XFL	CS	Cross over or go around Milepost w/Letters, a 256.5, a 259.2, io31
79	CLT	80	WTR	49	SVS	34	NYP-NYP	AM	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
80	NYP	174	WTR	131	ENG	51	CLT-CLT	NS	Set out defective locomotive Set engine off and wye train., 355
607	HAR	24	ENG	45	ENG	45	NYP-NYP	AM	Other electrical failure, 630 EX ES, UNSPECIFIED MECHANICAL ISSUE.

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
646	NYP	14	CTI	9	CTI	7	PAO-PHL	AM	Cross over or go around, SEPTA, 9546, Control Point, .	
647	HAR	11	DET	8	DET	8	EWR-TRE	AM	Catenary maintenance , Other, XCY-XHM, OPR NO.2 TRK A/C ET INSPECTION ON 3 TRK	
655	HAR	12	OTH	13	DET	5	NYP-NYP	AM	Catenary failure, Other, NYP, HELD IN STATION A/C POWER ISSUES IN NORTH TUBE	
19	NOL	260	WTR	145	WTR	145	MSS-CLP	NS	Trees down Train in emergency at 51.5 for large tree across both main 1 & 2., Other, 52.0	
20	NYP	124	FTI	150	FTI	68	LAU-MEI	NS	Cross Traffic Stop signal 49th, had to line 27th Ave switch it was against train movement, can to the station north on the south main..., NS346, Milepost, 7.2, 0.4	
63	TWO	43	FTI	18	FTI	11	ROC-BUF	CS	Follow Follow mixed-freight led by locomotive CSXT 3217., Control Point, 388, Control Point, 390, Control Point, 408, Control Point, 410, Control Point, 427, Control Point, 429, 3217, Manifest	
64	NYP	26	PTI	30	PTI	30	AMS-XHF	CS	Meet 283, Control Point, 169	
240	NYP	18	PTI	10	WTR	9	CRT-YNM	MN	Heat order Milepost, 30, 16	
241	ALB	26	MBO	14	MBO	14	NYP-XSD	AM	For maritime traffic, Other, SPUYTENDUYVIL BRIDGE	
243	ALB	Trn Cancelled	ITI	126	ITI	126	NYP-NYP	AM	Service, turn, or wye train, 1246, LATE TURN OFF AM1246	
280	NYP	69	RTE	44	FTI	33	XSV-SYR	CS	- Instructed to bring train to safe stop @ QC 295.7 - Freight train in emergency on track 1 - EC-1 # 85251 issued to pass train in emergency once the crew was clear of inspecting the train M36810, Other, QC 295.7	
283	NFL	40	DCS	50	DCS	50	NYP-NYP	AM	T.O.L, Other, NYP, LATE F/SSYD LATE TURN OFF AM236 A/C TOL IN LINE 1	
291	BTN	27	MBO	21	MBO	21	NYP-XSD	AM	For maritime traffic, Other, SPUTYTENDUYVIL	
1233	PIT	165	DCS	50	FTI	50	XRD-PIT	CS	Meet Dispatcher held us at cp187 for the m427, m427, Control Point, 187	
1246	NYP	161	SYS	160	SYS	160	PIT-PIT	CS	Late turn from amt 1233 into Pittsfield	

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
48	NYP	317	WTR	350	WTR	350	CHI-CHI	AM	Trees down Tornado warnings, flash flood warnings and high winds. Down power line and trees around CD 490. Ordered to wait in shelter at the station by NS. Since nothing was moving due to weather., Other, CHI station
49	CHI	146	ENG	71	ENG	71	NYP-NYP	AM	Other electrical failure, 705, NECESSARY TO SWING IN SSYD A/C OPR WITH DIESEL ENGINE AND MECHANICAL ISSUES IN YARD
448	BOS	43	SVS	340	SVS	340	ALB-ALB	AM	Planned Switch Other, alb
449	ALB	52	WTR	38	CTI	28	FRA-WOR	MT	Blocked from station track keolis, Control Point, 44
42	NYP	58	FTI	39	SYS	38	PGH-PGH	NS	Crew rest Signed up off of rest. Delay includes acquiring mandatory directives, crew briefing, and engineer logging into PTC.
43	PGH	45	FTI	55	FTI	34	TYR-ALT	NS	Follow Milepost, 219.0, 235.7, 25P
71	CLT	51	FTI	25	FTI	18	DNC-GRO	NS	Follow Held w DNC account MS350 mechanical issues, Other, W Durham, #NS351
72	RGH	147	WTR	72	WTR	38	BNC-DNC	NS	Heat order 25 MPH Heat order NC Line, Other, NC Line
73	CLT	80	DSR	52	DSR	27	DNC-BNC	NS	Per bulletin Milepost, 41.2, 41.0, 25, Main, Milepost, 36.8, 36.7, 10, Main, Milepost, 36.2, 36.1, 25, Main, Milepost, 34.2, 34.0, 10, Main, Milepost, 33.0, 32.8, 25, Main, Milepost, 30.3, 30.1, 25, Main, Milepost, 25.8, 25.7, 25, Main
78	RGH	23	DSR	16	DSR	14	BNC-DNC	NS	Per bulletin Milepost w/Letters, 25.7 NC, 25.8 NC, 25, 1, Milepost w/Letters, 30.1 NC, 30.3 NC, 25, 1, Milepost w/Letters, 34.0 NC, 34.2 NC, 25, 1, Milepost w/Letters, 36.1 NC, 36.2 NC, 25, 1, Milepost w/Letters, 36.7 NC, 36.8 NC, 10, 1, Milepost w/Letters, 41.0 NC, 41.2 NC, 25, 1
90	NYP	192	WTR	257	WTR	205	RVR-XDJ	CS	Trees down Other, CFP42.3
97	MIA	116	WTR	73	TRS	55	SAV-JSP	CS	Vehicle strike Milepost w/Letters, A528.0, A528.0
98	NYP	44	FTI	81	WTR	17	JAX-JSP	CS	Heat order Other, Nahunta SUB
55	WAS	116	WTR	118	WTR	77	SPG-WNL	AM	Trees down, Milepost w/Letters, SPG, WNL, tree down btwn Hayden - Field

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
56	SAB	138	WTR	120	WTR	120	WNL-SPG	AM	Trees down, Milepost w/Letters, WNL, SPG, delay due to downed tree btwn Hayden - Field
40	CHI	197	WTR	111	TRS	85	TOL-WTI	NS	Near-miss Other, 342
41	MIA	437	DCS	156	DBS	65	CLE-X86	NS	Debris blocking track (no debris strike) Tree down on tracks RD79.8 Held us at CP86, Control Point, 86
23	NOL	44	PTI	32	PTI	32	BAS-XNO	CS	Meet Work train in siding Watson 24 to make it here and go in the siding behind work train where we could depart, 24, Control Point, south nicholson
24	MOE	24	FTI	34	FTI	16	XNO-BAS	CS	Follow BNSF 5672, Milepost, 803.6, 801.5
26	MOE	30	PTI	26	PTI	26	XNO-BAS	CS	Meet Three way with work train, 25, Siding, nicholson
5	RNO	No OS Rpt	WTR	1088	WTR	552	CRN-OMA	BN	Flood / washout Down trees, downed power lines from CP creston to CP red oak, Control Point, Creston, Control Point, Red Oak
5	DEN	77	FTI	86	FTI	54	OTM-OSC	BN	Cross over or go around Shuffle at maxon, 3344, unknown, Control Point, cp2888, Control Point, maxon
6	CHI	No OS Rpt	SVS	115	SVS	109	DEN-DEN	RT	Complete turnover of train 5 (10) at Denver Control Point, DUS
6	GJT	242	PTI	103	PTI	88	XWC-GJT	UP	Amtrak 5 train set in Depot, waiting for buses, pulled our train beyond the Depot and and turned it around the wye and brought into Grand Junction Depot Station parking behind number five train set. Amtrak 5, Siding, GJT DEPOT
525	OKJ	Trn Cancelled	DSR	4	DSR	2	SAC-DAV	UP	Per bulletin Milepost, 80.2, 80.05, 30, 2
526	SAC	Trn Cancelled							
527	SJC	11	CTI	16	CTI	8	HAY-FMT	UP	Follow ACE, Control Point, FO30
529	SJC	75	TRS	50	TRS	50	OKJ-OKJ	UP	Vehicle on track ahead Remained at OKJ waiting for car to be removed from track ahead, Milepost, 10.86, 10.86
539	SJC	36	ITI	20	ITI	20	SAC-SAC	UP	Service, turn, or wye train 528
541	OKJ	Trn Cancelled							
545	OKJ	17	DCS	21	DCS	21	FFV-SUI	UP	Power switch failure Hand throw., Control Point, RV052

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
547	SJC	51	DCS	35	DCS	31	FFV-SUI	UP	Power switch failure Control Point, RV052
50	NYP	No OS Rpt	WTR	240	WTR	59	DYE-REN	CS	Trees down Milepost w/Letters, DYE, REN
507	EUG	16	DSR	16	SYS	11	SEA-SEA	BN	Re-crew / job briefing No available engineer, used engineer off 504 once he arrived, Other, SEA
516	VAC	64	DMW	58	DMW	58	X8B-XF2	BN	Waiting for MW clearance Scheduled work block at Fraser River Drawbridge. Waited at Brownsville behind one BN freight train., Bridge, Fraser
517	PDX	19	PTI	15	PTI	8	TAC-XNI	ST	Meet AMT 504, Control Point, RILL
518	VAC	21	DSR	14	OTH	12	VAN-VAN	BN	Cab car 90250 roll up door would not close. Had to figure out how to put it into manual operation and use the chain. Unable to use cab car code for delay report; it kept crashing the app.
58	CHI	129	DMW	94	DMW	78	GWD-GWD	CC	Held for or routed around MW work or equipment Held at station per dispatcher for m/w clearance ahead of station. Worked out best for the passengers., Control Point, n greenwood
59	NOL	247	WTR	171	WTR	81	CHM-MAT	CC	Trees down Control Point, south Humboldt
14	SEA	42	CAR	59	CAR	59	SAC-XB7	UP	Air / Brake / Wheel 32044, Glad hand on break pipe hose broke and break pie had to be replaced.
7	SEA	534	FTI	587	FTI	248	WEN-LWA	BN	FRight train caught fire at Winston held at cashmere for route Control Point, cashmere, 4723
8	CHI	66	FTI	97	DCS	34	MSP-XH8	CP	Restrictive signal(s) from unknown cause Restricting from Newport to st Croix, Restricting , Milepost, 422, 410
27	PDX	-27	FTI	27	FTI	27	PSC-WIH	BN	Meet BN 7079, Siding, Berrian
28	SPK	144	SVS	120	SVS	120	PDX-PDX	BN	Late arrival of 27 into PDX. Train had to be wyed cleaned and maintenance. Other, pdx station
350	PNT	18	PTI	29	PTI	22	XB0-XA5	MI	Meet 353, Siding, Albion
352	PNT	54	FTI	41	MBO	27	XH6-XPI	NS	For maritime traffic Milepost, 503, 503
353	CHI	25	FTI	40	FTI	33	HMI-XTF	NS	Cross Traffic 10E, Control Point, 513
354	PNT	26	DSR	18	ITI	16	CHI-CHI	AM	Service, turn, or wye train 353
355	CHI	78	PTI	67	FTI	38	XPI-HMI	NS	Follow ns, Milepost, 482, 497

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
364	PTH	148	FTI	151	FTI	89	XH6-XPI	NS	Follow 264, Milepost, 521, 485	
365	CHI	43	DSR	31	FTI	21	DRD-LNS	CC	Meet Wait for CN Eng 3095, CN 148, Control Point, Bancroft	
370	GRR	138	FTI	146	FTI	68	XTF-XH6	NS	Meet 27G, Control Point, 509	
572	SAN	60	DCS	49	DCS	47	IRV-SNC	SC	Restrictive signal(s) from known wayside signal failure Flag signal and hand throw switch, Red / stop, Control Point, solo	
573	LAX	67	DCS	33	DCS	29	SNC-IRV	SC	Restrictive signal(s) from known wayside signal failure Take switch 21B in hand - flagging., Stop/ Cp Crown , Stop/ Cp Solow, Control Point, Solow	
579	LAX	45	DCS	21	DCS	21	SNC-IRV	SC	Restrictive signal(s) from known wayside signal failure Signal went from green to red then back to green then red. Put train into emergency and had to flag CP Solo per dispatch., Stop, Control Point, solo	
581	LAX	21	SYS	13	CTI	9	SOL-OSD	SN	Meet Stop signal at Swami, coaster, 640, Control Point, swami	
584	SAN	33	PTI	25	PTI	16	SNC-SNP	SC	Meet 587, Control Point, serra	
587	LAX	25	CTI	29	CTI	15	OSD-X98	SC	Meet metrolink, Control Point, songs	
588	SAN	34	PTI	25	PTI	20	SNC-SNP	SC	Meet 591, Control Point, serra	
591	LAX	25	DSR	7	FTI	7	OSD-X98	SN	Meet BNSF 5470, Control Point, songs	
769	GTA	28	RTE	39	RTE	39	SNC-IRV	SC	Line manual or spring switch Flagged by signal, had to line route by hand, main 2 to main 1, Control Point, Solow	
770	SAN	22	DCS	31	DCS	31	IRV-SNC	SC	Power switch failure Flag CP Lettengarver and CP Solow. Line switch 1A MT2-->MT2 fore & aft for out MVT @ Sollw, Control Point, Solow	
774	SAN	56	DCS	40	DCS	32	IRV-SNC	SC	Power switch failure Control Point, Lettengarber	
777	SLO	59	PTI	72	PTI	19	OSD-X98	SN	Meet 572, Control Point, CP Songs	
785	GTA	32	ITI	27	ITI	27	SAN-SAN	SN	Service, turn, or wye train 774	
786	SAN	21	PTI	40	PTI	33	GUA-LPS	UP	Meet 14, Siding, Tangair	
701	SAC	42	FTI	32	OTH	14	BFD-WAC	BN	Hep dropped on loco 2005, unable to submit on ENG.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Region: ALL

Service: ALL

Arriving On: 6/12/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
702	BFD	146	TRS	150	TRS	141	WAC-BFD	BN	Vehicle on track ahead Vehicle stuck on tracks at MP905.1 causing train congestion. After vehicle was removed and track was inspected we were OK'd to proceed over the area at 10mph from MP905.15-901.1 with flaggers present., Milepost, 905.1, 905.1
703	SAC	No OS Rpt	PTI	50	PTI	30	BFD-WAC	BN	Meet STOPPED AT W UNA, THEN PROCEEDED TO SHAFTER SIDING TO MEET AMT 714, AMT714, Control Point, CP WEST UNA, Control Point, CP SHAFTER
704	BFD	Trn Cancelled							
710	BFD	140	TRS	113	TRS	69	COC-COC	BN	Vehicle on track ahead Other, 905.1
712	BFD	63	TRS	50	TRS	48	COC-COC	BN	Vehicle on track ahead Vehicle stuck on the tracks and track repair at 905.1, waiting for a clear route., Siding, W. Corcoran
714	BFD	61	FTI	45	FTI	18	WAC-BFD	BN	Meet CP 8844, Control Point, E. Kitfox
715	EMY	No OS Rpt	TRS	195	TRS	195	BFD-WAC	BN	Vehicle on track ahead Milepost, 905.14, 905.14
716	BFD	37	FTI	51	FTI	26	COC-WAC	BN	Meet BNSF 6881, BNSF 7310, Control Point, East Corcoran
717	OKJ	203	TRS	141	TRS	134	BFD-BFD	BN	Vehicle on track ahead Milepost, 905.1, 905.1
718	BFD	133	SYS	105	SYS	105	WAC-BFD	BN	Blocked by or assisting another, disabled Amtrak train Control Point, una
719	OKJ	No OS Rpt	PTI	140	PTI	106	BFD-BFD	BN	Waited for equipment 710 that turns 719. 710, Other, Bakersfield station
3	LAX	459	WTR	395	WTR	146	FMD-LAP	BN	High winds Milepost, 234.3, 246.0, Milepost, 254.0, 313.2
4	CHI	86	PTI	98	CTI	42	ABQ-LMY	NM	Cross Traffic NMRX, EAST/WEST, Milepost, 902.0, 865.0
1	LAX	139	ENG	173	TRS	127	SCH-NIB	BN	Trespasser strike Baldwin emergency personnel on scene. BNSF Superintendent Cody Richardson on scene. Investigation done by City of Baldwin, Louisiana Police. Amtrak Police Detective H. Stanton notified. CNOC West and RFE G Davis Notified, Milepost, 104.9, 105.1
300	CHI	35	FTI	58	FTI	44	XQT-XWR	UP	Cross Traffic Freight train stopped at WR Tower, Unknown, Control Point, WR Tower

Amtrak Endpoint OTP Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 6/12/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
301	STL	97	SYS	65	SYS	65	XTF-XUD	CC	Re-crew / job briefing Engineer out of hours. Wait for recrew off 300, Other, lemont metra
306	CHI	56	FTI	65	FTI	27	SMT-XTF	CC	Cross Traffic NA, Control Point, Brighton
307	STL	131	ENG	89	ENG	33	PON-BNL	UP	Loading problem PCS Light on. Engine won't load., 57
380	CHI	16	ADA	19	ADA	6	KEE-KEE	BN	Wheelchair Unannounced last minute wheelchair lift
382	CHI	32	FTI	20	FTI	14	QCY-MAC	BN	Cross over or go around bnsf 8269, Siding, macomb
383	QCY	No OS Rpt	HLD	14	HLD	9	NPV-NPV	BN	Minors on train detrained at NPV
391	CDL	39	DSR	42	DSR	11	KKI-GLM	CC	Per bulletin A lot Rule 528's in the orders., Milepost, 68.45, 77.99, 50, main
392	CHI	16	DSR	27	DSR	17	CEN-EFG	CC	Per bulletin Milepost, 244.3, 243.6, 10, main, Milepost, 241.2, 240.7, 30, main, Milepost, 239.1, 238.6, 10, main, Milepost, 229.43, 229.43, 25, main, Milepost, 199.3, 199.3, 10, main
393	CDL	17	DSR	24	PTI	10	CHM-MAT	CC	Meet AMT 392, Control Point, Tuscola
319	KCY	118	PTI	49	CAR	43	CHI-CHI	AM	Air / Brake / Wheel ID4014, Changed out car for brakes

Amtrak Initial Terminal Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/12/2026

Terminal	Train	Date	Late	Delay	Cause
CLT	72	06/12	22	22	Service, turn, or wye train 71
CLT	80	06/12	65	14	PTC problem or failure (cause unknown) Had to reset PTC in order to accept train consist, Milepost, 376.0, 376.0
CLT	80	06/12	65	51	Set out defective locomotive Set engine off and wye train., 355
HAR	648	06/12	1		
NFK	94	06/12	1		
NPN	186	06/12	2	2	Hold for thruway bus Arrived at 3:39.
PGH	42	06/12	38	38	Crew rest Signed up off of rest. Delay includes acquiring mandatory directives, crew briefing, and engineer logging into PTC.
PHL	110	06/12	1		
PHL	190	06/12	5	5	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
RGH	73	06/12	5	5	Meet Stop signal at Southern Junction. P59 working yard., #NSP59, Control Point, Southern Junction
SFA	52	06/12	15	15	Heat / AC 33100, Hot car had to be cutout # 33100
WAS	2102	06/12	8	7	Re-crew / job briefing, NO CONDUCTOR. 130'S CONDUCTOR HAD TO BE PULLED TO TAKE TRN.
ALB	448	06/11	340	340	Planned Switch Other, alb
BOS	137	06/12	78	78	Service, turn, or wye train, 190, AM137 will be late dp BOS today due mechanical issues on the eq. Train turned from AM190 which was dealing with the hot journal alarm
BOS	449	06/12	2	2	Late coming from the yard 449
GFD	479	06/12	75	75	486 late 486
NHV	474	06/12	38	37	Hold for connecting train
NHV	478	06/12	21	21	Service, turn, or wye train, 479, late turn
NYP	63	06/12	2	2	Passenger and/or baggage, LOADING
NYP	69	06/12	2	2	Cross Traffic, NJT, NJ6219, Other, NYP
NYP	79	06/12	34	34	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	97	06/12	114	47	Planned set out / pick out of locomotives, cars or section of train, necessary to wait for inbound train 98 to add a lounge car and one sleeper to complete the consist and service the equipment.
NYP	97	06/12	114	67	Other electrical failure, 641, HELD IN STATION FOR MECHANICAL ISSUES WITH COOLER IN CAFE CAR
NYP	113	06/12	48	48	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL

Amtrak Initial Terminal Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/12/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	131	06/12	13	13	Delay in Block, NECESSARY TO RUN AROUND TRAIN A/C OPERATING WITH ONLY 1 ENGINE
NYP	181	06/12	15	15	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	183	06/12	17	17	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	193	06/12	5	5	Service, turn, or wye train, 84, LATE TURN OFF AM84
NYP	243	06/12	(Trn Cxld)	126	Cab Car Issue
NYP	245	06/12	67	23	On-train police or DEA activity, HELD IN STATION A/C POLICE ACTIVITY ON BOARD
NYP	245	06/12	67	44	Blocked by or assisting another, disabled Amtrak train, HELD IN STATION FOR A POSSIBLE PSNGR TRANSFER FOR DISABLED AM243 MP 1.2.
NYP	283	06/12	50	50	T.O.L, Other, NYP, LATE F/SSYD LATE TURN OFF AM236 A/C TOL IN LINE 1
NYP	291	06/12	11	11	Restrictive signal(s) from unknown cause Stop, Milepost, 0.0, 0.0
NYP	291	06/12	11	11	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	607	06/12	45	45	Other electrical failure, 630 EX ES, UNSPECIFIED MECHANICAL ISSUE.
NYP	641	06/12	12	12	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	655	06/12	5	5	Catenary failure, Other, NYP, HELD IN STATION A/C POWER ISSUES IN NORTH TUBE
NYP	1233	06/12	38	38	T.O.L, Other, NYP, LATE ARRIVAL OPR LINE 3 A/C TOL IN LINE 1
NYP	2190	06/12	16	16	Re-crew / job briefing, LATE CREW
NYP	2192	06/12	2	2	Passenger and/or baggage, LOADING
PIT	1246	06/12	160	160	Late turn from amt 1233 into Pittsfield
SPG	417	06/12	5	5	Meet, CTRAIL, 4476, Other, SPG, AM417 waited for CT4476 to clear single track
SPG	475	06/12	55	55	Trees down, Other, SPG, tree down between Hayden - Field
CHI	41	06/12	7	7	Water, commissary, toilet/trash dumping Commissary, Other, CUS
CHI	59	06/12	12	12	Crew rest Control Point, CHI
CHI	301	06/12	10	10	Air / Brake / Wheel ID4014, Last minute bad ordered. Switched to 319 train set
CHI	319	06/12	43	43	Air / Brake / Wheel ID4014, Changed out car for brakes
CHI	331	06/12	5	5	Routine inspections Mechanical department dropped blue flags at 08:24, departure test, class II, and PTC entered after confirmation with C&M dispatcher, Control Point, Madison 0.20
DEN	1006	06/12	24	17	Hold for thruway bus Waited for bus bridge from Grand Junction
DEN	1006	06/12	24	7	Wait for station track Waited for signal from RTD, Control Point, 8N, RTD
MSP	1340	06/12	1		

Amtrak Initial Terminal Details

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 6/12/2026

Terminal	Train	Date	Late	Delay	Cause
PDX	28	06/12	53	53	Routine inspections Late arrival train 27
SEA	8	06/12	(No OS)		
SEA	507	06/12	11	11	Re-crew / job briefing No available engineer, used engineer off 504 once he arrived, Other, SEA
STL	302	06/12	4	2	PTC problem or failure (cause unknown) PTC wouldn't load for TRRA, Engr had to log out then log back in.
STL	302	06/12	4	2	Mobility Impaired
BFD	701	06/12	2	2	Late delivery of orders due to power outage, shoved from 3 track to 1 track
BFD	703	06/12	30	30	Service, turn, or wye train 712
BFD	715	06/12	26	26	HEP C2012
BFD	717	06/12	134	134	Vehicle on track ahead Milepost, 905.1, 905.1
BFD	719	06/12	106	106	Waited for equipment 710 that turns 719. 710, Other, Bakersfield station
GTA	782	06/12	10	10	Meet 14, Control Point, CP CO 358
LAX	4	06/12	25	25	Service, turn, or wye train 3, This delay code was added because the program would not accept ENG. The delay was caused by the need to cut out engines 181 and 50 and to substitute engines 176 and 204 in their place.
OKJ	526	06/12	(Trn Cxld)		Third Party Engine Failure
OKJ	532	06/12	1	1	Meet 537, Control Point, n jack london
OKJ	718	06/12	396	396	Service, turn, or wye train 715
SAC	537	06/12	1		
SAC	539	06/12	20	20	Service, turn, or wye train 528
SAC	541	06/12	(Trn Cxld)		Third Party Engine Failure
SAC	543	06/12	1		
SAC	549	06/12	1	1	Unruly passenger Control Point, west platform
SAC	702	06/12	1	1	Door C9301, Doors would not trainline, had to walk down the consist to close door locally.
SAC	704	06/12	(Trn Cxld)		Third Party Engine Failure
SAN	785	06/12	27	27	Service, turn, or wye train 774
SLO	786	06/12	3		

Eastern Region

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.0	98.9	94.8	342	10
CDOT	95.0	90.0	93.9	92.4	20	2
MARC	95.0	79.3	81.7	90.2	58	12
SEPTA	95.0	96.9	94.9	91.5	223	7
NJT-NED	95.0	92.3	89.2	88.6	355	27
NJT-SED	95.0	100.0	97.3	97.2	24	0

Operating Highlights

Train 41(11) Washington, DC - Servicing

13JUN26: Train 41(11) with engines 309, 192, 11 cars, and 86 customers onboard was delayed departing Washington, DC on the Amtrak Washington Terminal Line due to the equipment requiring daily inspections due to the late operation of the train. Once the necessary inspections were completed, the train departed Washington at 2:43 AM-ET.

Train	Delay	Comment
41(11)	2'16"	

Train 448(11) West of Worcester, MA - Commuter Train Interference

13JUN26: Train 448(11) with engines 114, 122, 4 cars, and 72 customers onboard was delayed at milepost 44.5, half a mile west of Worcester, MA on the CSX Boston subdivision due to being blocked from the station tracks by Keolis 593. Once the commuter train was cleared, train 448(11) entered the station.

Train	Delay	Comment
448(11)	40"	

Train 89(12) South of Charleston, SC - Freight Train Interference

12JUN26: Train 89(12) with engine 331, 7 cars, and 42 customers onboard was delayed beginning at milepost 392.6, 5 miles south of Charleston, SC on the CSX Charleston subdivision due to following CSX freight train M493 from milepost 392.6 to milepost 403.5. Once the freight train was cleared, train 89(12) was able to advance to the next station.

Train	Delay	Comment
89(12)	31"	

Train 243(12) New York, NY - Cab Car Failure

13JUN26: Train 243(12) with engines 354, 360, 44 cars, and 403 customers onboard was stopped at milepost 1.3, 1 mile north of New York, NY on the Amtrak Hudson Line due to parking brake issues with the cab car. The crew attempted to troubleshoot the issue and was not successful. The train reversed back to New York and the customers were transferred to train 245(12) that was holding in the station. Train 245(12) departed New York at 12:32 AM-ET after receiving the customers. Train 243(12) was cancelled from New York to Albany. The equipment was able to be repaired and was deadheaded to Albany to be in place for service in the morning.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
243(12)	Cancelled	
245(12)	44"	

Train 53(12) South of Fayetteville, NC - Freight Train Interference

13JUN26: Train 53(12) with engines 354, 360, 44 cars, and 403 customers onboard was delayed at milepost 232.9, 24 miles south of Fayetteville, NC on the CSX South End subdivision due to meeting CSX freight train I036. The train was delayed further at control point South Sellers to meet CSX freight train 34411. Once the freight trains cleared, train 53(12) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(12)	31"	

Train 171(12) Charlottesville, VA - Routing

12JUN26: Train 171(12) with engine 336, 9 cars, and 144 customers onboard was delayed at Charlottesville, VA on the NS Washington District due to the dispatcher holding the train at the station for a tie fire near the tracks at milepost 115.1. Once the fire was reported to be extinguished, train 171(12) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
171(12)	1'17"	

Train 90(12) South of Fredericksburg, VA - Trees Down

12JUN26: At 6:13 PM-ET, train 90(12) with engine 44, 7 cars, and 200 customers onboard was stopped at milepost 42.3, 17 miles south of Fredericksburg, VA on the CSX RF&P subdivision due to trees being down across both tracks. The crew reported three to four trees down. CSX was notified and responded to the scene to remove the debris. Once the debris was removed, train 90(12) was on the move at 9:21 PM-ET.

Train 186(12) was stopped at 6:43 PM-ET behind train 90(12). The train was on the move at 9:22 PM-ET.

Train 125(12) was held in Fredericksburg to wait on a clear route. The train was on the move at 9:43 PM-ET.

Train 93(12) was stopped at milepost 53.7. The train was on the move at 9:41 PM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(12)	3'25"	
186(12)	2'47"	
125(12)	3'02"	
93(12)	1'13"	

12JUN26: Train 138 (126-FOI-00532 00000007811 337, "UNCLASSIFIED" and 6/17/2026) and 35 customers onboard was delayed beginning at milepost 25.0, 10 miles north of Ashland, VA on the CSX RF&P subdivision due to following freight train P080 through high wind warnings from milepost 63.3 to milepost 74.0.

Train 19(12) North of Manassas, VA - High Wind Warning

12JUN26: Train 19(12) with engines 37, 98, 8 cars, and 199 customers onboard was delayed beginning at milepost 21.2, 10 miles north of Manassas, VA on the NS Washington District due to operating at a reduced speed through an area with high wind warnings. Once the high wind warnings were lifted, train 19(12) advanced to the next station at normal authorized speed.

CN Heat Orders

12JUN26: CN imposed heat orders on the Rouses Point subdivision causing delays to trains 68 and 69 due to having to operate at a reduced speed.

Train 49/449(12) Albany-Rensselaer, NY - Servicing

12JUN26: Train 49/449(12) with engines 109, 108, 5, 11 cars, and 234 customers was delayed at Albany-Rensselaer, NY on the Amtrak HUD Line due to a planned set out and pick up of locomotives. The consist also had to wait for the late train 449(12) to arrive so that it could be added to the consist. Once the consist was together and all necessary inspections completed, train 49/449(12) advanced to the next station.

Train 125(12) North of Quantico, VA - High Wind Warnings

12JUN26: Train 125 with engine 139, 8 cars, and 363 customers onboard was delayed beginning at milepost 78.9, just north of Quantico on the CSX RF&P subdivision due to operating at a reduced speed through high wind warnings from milepost 78.9 to milepost 59.3.

Train	Delay	Comment
125 (12)	48"	

Train 66(12) North of Charlottesville, VA - Passenger Train Interference

12JUN26: Train 66(12) with engine 339, 5 cars, and 167 customers onboard was delayed beginning at milepost 102.0, 10 miles north of Charlottesville, VA on the NS Washington District due to following a passenger train from milepost 102.0 to milepost 84.7. Once the passenger train cleared, train 66(12) advanced to the next station at normal authorized speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
66(12)	32"	

Train 1246(12) South of Albany-Rensselaer, NY - Passenger Train Interference

12JUN26: Train 1246(12) with engine 706, 5 cars, 9704, and 3 customers onboard was delayed at milepost 141.8, half a mile south of Albany-Rensselaer, NY on the Amtrak HUD Line due to waiting outside the station for a track. Once train 449(12) departed the station, train 1246(12) was able to advance into Albany-Rensselaer.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1246(12)	30"	

Train 64(12) East of Amsterdam, NY - Passenger Train Interference

12JUN26: Train 64(12) with engine 93, 5 cars, and 233 customers onboard was delayed at milepost 169.9, 7 miles east of Amsterdam, NY on the CSX Mohawk subdivision due to meeting train 283(12). Once the passenger train cleared, train 64(12) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
64(12)	30"	

Train 43(12) East of Tyrone, PA - Freight Train Interference

12JUN26: Train 43(12) with engine 124, 7 cars, and 238 customers onboard was delayed beginning at milepost 219.0, 3 miles east of Tyrone on the NS Pittsburgh Line due to following an NS freight train between milepost 219.0 and milepost 235.7. Once the freight train cleared, train 43(12) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
43(12)	34"	

Train 1233(12) East of Albany-Rensselaer, NY - Freight Train Interference

12JUN26: Train 1233(12) with engine 706, 5 cars, 9704, and 29 customers onboard was delayed at milepost 187.5, 21 miles east of Albany-Rensselaer, NY on the CSX Berkshire subdivision due to meeting CSX freight train M427. Once the freight train cleared, train 1233(12) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1233(12)	50"	

Train 80(12) North of Richmond, VA - High Wind Warnings

12JUN26: Train 80(12) with engine 355, 7 cars, and 277 customers onboard was delayed between Richmond, VA and Fredericksburg, VA on the CSX RF&P subdivision due to high wind warnings required the train to operate at a reduced speed. Once the high wind warnings were lifted, train 80(12) advanced to the next station at normal authorized speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 80(12) Charlotte, NC - Engine Failure

12JUN26: Train 80(12) was delayed at Charlotte, NC with engine 355, 8/17/2026, 10:00:00.07811, UNCLASSIFIED, 26-FOI-00532, 00000007811. Train 80(12) was delayed departing Charlotte, NC, on NS Salisbury-Greenville_04 subdivision, due to swapping engines. 80(12) original engine, 101, was replaced by engine 355 off of train 19(11) due to brake issues on engine 101.

Train 20(11) was delayed holding outside of Charlotte, NC for an open track. Once 80(12) cleared and a track was opened, train 20(11) was able to enter the station.

Train	Delay	Comment
19(11)	32"	setting out E/355
80(12)	51"	Eng Swap
80(12)	14"	PTC issues with new LOCO
20(11)	1'27"	

Train 474(12) New Haven, CT - Passenger Train Interference

12JUN26: Train 474(12) was delayed departing New Haven, CT, on MNCW New Haven Line, due to holding for train 174(12). train 174(12) arrived in New Haven, at 4:51pm-et.

Train	Delay	Comment
474(12)	38"	

Train 51(12) West of Charlottesville, VA - Commuter Train Interference

12JUN26: Train 51(12) held 21.9 miles west of Charlottesville, VA (MP182.2), on the Buckingham Branch North Mountain Subdivision, at West Afton (MP204.1) meeting N&W 611.

Train	Delay	Comment
51(12)	42"	

Train 50(11) White Sulphur Springs, WV - Freight Train Interference

12JUN26: Train 50(11) was held at the White Sulphur Springs, WV station (MP 311.8) on the CSX Alleghany Subdivision to meet CSX L209, which was approaching its hours-of-service limit.

Train	Delay	Comment
50(11)	43"	

Train 20(11) North of Washington, DC - Car Failure

12JUN26: Train 20(11), operating with engine 633, 8 coaches, and 151 customers was delayed after departing Washington DC, Union Station, on Amtrak PW Line, due to a main reservoir issue on the train. Washington mechanical responded and was unable to resolve the issue. As a result train 20(11) isolated their main reservoir behind the first 2 coaches, making them the only 2 coaches with operable toilets. The issue was addressed when the train reached its final stop, New York, NY.

Train	Delay	Comment
20(11)	39"	

Train 41(11) Pittsburgh, PA - Fueling Delay

12JUN26: Train 41(11) was delayed departing Pittsburgh, PA (MP353.1) on the NSRR Pittsburgh Line due to waiting on a fuel vendor to complete fueling of the locomotives.

Train	Delay	Comment
41(11)	59"	

NS Heat Restrictions - Weather

12JUN26: Multiple train heat restrictions on the NS Norfolk subdivision. Trains were restricted to 25MPH between mp n3.5 and n52. UNCLASSIFIED//FOR OFFICIAL USE ONLY 6/17/2025

Train	Delay	Comment
138(12)	1'04"	
95(12)	1'16"	

Train 1233(12) East of Albany-Rensselaer, NY - Freight Train Interference

12JUN26: Train 1233(12) operating with engines 9704/706, 5 coaches and 29 customers, was delayed 5 miles east of Albany-Rensselaer, NY, on Amtrak Post Road subdivision due to CSX running a freight ahead of them. The crew reports the dispatcher didn't know they Berkshire Flyer was running despite receiving their orders prior to getting on their territory. Once the freight cleared and a route was made available, train 1233(12) was able to proceed.

1246(12) was delayed departing Pittsfield, MA due to the late arrival of 123(12).

Train	Delay	Comment
1233(12)	50"	
243(12)	2'04"	Late turn of equipment from 1246(12)
1246(12)	2'40"	Late turn of equipment from 1233(12)

Train 56(12) North of Windsor Locks, CT - Tree on Tracks

12JUN26: Train 56(12) operating with engine 115, 6 coaches and 241 customers, was delayed north of Windsor Locks, CT, on Amtrak MSR Line, due to a tree on the tracks obstructing the route. Maintenance of Way (MOW) responded with chainsaws to remove the tree.

Train 55(12), 486(12) and 475(12) all delayed due to the tree on the tracks.

Train	Delay	Comment
56(12)	2'00"	
55(12)	1'17"	
475(12)	1'37"	
486(12)	1'32"	
479(12)	1'15"	Late turn of equipment from 486(12)

Train 97(12) New York, NY - Servicing

12JUN26: Train 97(12), operating with engine 186, 13 coaches, and 198 customers, was delayed departing New York, NY, Penn Station, on Amtrak NYT Line, due to adding lounge car and sleeper car from train 98(10). Train 98(11) arrived in New York at 11:31am, and marked up in the yard for servicing at 12:49pm.

Train 97(12) was additionally held at the station due to electrical issues with the cooler in the cafe car. Mechanical met the train and was able to resolve.

Train	Delay	Comment
97(12)	47"	SSYD delay
97(12)	1'07"	Mech issue NYP

12JUN26:

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

CSX HAS IMPOSED HEAT ORDERS EFFECTIVE BETWEEN 1:00 PM AND 7:00 PM FOR THE FOLLOWING SUBDIVISIONS:

Baltimore Terminal, Berkshire, Boston, Capital, Cumberland, Keystone, Metropolitan, New River, Old Main Line, Peninsula, RF&P, Richmond Terminal, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, Niagara, Old Main Line, Peninsula, RF&P, Richmond Terminal, Rochester, Syracuse Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah, South End, Tampa Terminal

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
186(12)	20"	
53(12)	23"	
79(12)	49"	
138(12)	09"	
98(12)	48"	
97(11)	22"	
40(12)	52"	
40(11)	46"	
449(12)	38"	
89(12)	51"	
95(12)	30"	
52(12)	08"	
1233(12)	26"	
171(12)	02"	
90(12)	29"	
80(12)	29"	
178(12)	02"	

Train 1233(12) New York, NY - Initial Terminal Delay

12JUN26: Train 1233(12), operating with engines 9704/706, 5 coaches, and 297 customers was delayed departing New York, NY, on Amtrak NYP Line, due to a Track Occupied Light on line one from Sunny Side Yard. This required the train to be routed to line 4 instead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1233(12)	38"	

Train 190(12) Route 128, MA - Defect Detector Actuation

12JUN26: Train 190(12), operating with engine 668, 8 coaches, and 414 customers, was delayed departing Route 128, MA, on Amtrak NHB line, due to setting off a hot box detector prior to arriving at the station. Once in the station the crew was required to inspect the equipment which required them to use a temple to stick to check the bearings to be sure they weren't actually hot. Once they finished their inspection and determined it was safe to proceed the then departed the station, operating at a maximum speed of 80MPH as a precaution.

Train 137(12) was delayed as a result of the late arrival of train 190(12) into Boston, MA. 190(12) arrived 38" late into Boston, MA and then went to the yard for mechanical inspection.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
137(12)	1'18"	
190(12)	30"	

12JUN26: Train 97(11) 26-FOI-00532 00000007811 UNCLASSIFIED 3306/17/2026 10 coaches and carrying 263 customers, went into emergency 20 miles north of Jesup Georgia, at milepost 528.1 on the CSX Nahunta Subdivision after striking a vehicle. Head-end power remained active as the crew conducted an inspection of the equipment for damage. No injuries were reported among the crew, customers, or any trespassers. The crew reported that the occupants of the vehicle fled the vehicle before the train struck it. Weather conditions at the time were sunny with a temperature of 81 degrees. Equipment was dispatched to remove the vehicle, which was fouling the single main line, and a track inspector was also en route.

Upon further inspection, the crew reported no significant damage to the train. They successfully recovered their air and performed a brake test. The vehicle was confirmed to be clear of the train, positioned at least one train length behind. Local police were present at the scene, and the initial delay reached approximately 25 minutes. After completing all necessary checks and receiving clearance, Train 97(11) was released and resumed movement.

NRC Number: 1465075

National Response Center Number: 1465075

Train	Delay	Comment
97(11)	55"	

Train 2190(12) Stamford, CT - Engine Failure

12JUN26: Legacy Acela, 2190(12), operating with power cars 2035/2039 6 coaches and 278 customers, was delayed at Stamford, CT, on MNRR New Haven Line, due to engine issues with Power Car 2035. The power car was showing a "battery charge low alert". After working with High Speed Rail and a Road Foreman, they were able to resolve.

Train	Delay	Comment
2190(12)	31"	

Train 607(12) New York, NY - System

12JUN26: Train 607(12), operating with engine 630, 5 coaches and 178 customers, was delayed departing New York, NY Penn Station, due to late release from Sunny Side yard. Mechanical was troubleshooting an electrical issue on engine 630.

Train	Delay	Comment
607(12)	45"	

Piedmont - Heat Restrictions

12JUN26: The following adjustments have been made to piedmont services due to 25 mph speed restrictions being placed by NS for heat orders. Trains 74, 75, 76, and 77(12) will be cancelled in their entirety with alternate transportation secured and confirmed. Trains 71, 72, 73, and 78(12) will operate as normal, delays expected.

Train	Delay	Comment
74(12)	cancelled	
75(12)	cancelled	
76(12)	cancelled	
77(12)	cancelled	
71(12)	23"	
72(12)	1'23"	
73(12)	56"	
78(12)	16"	

SS 7D Late Release Delays - Servicing

12JUN26: Multiple trains delayed at Sunny Side Yard in Queens, NY, due to late release by mechanical.

26-FOI-00532

00000007811

UNCLASSIFIED

6/17/2026

Train	Delay	Comment
79(12)	34"	
113(12)	48"	

NS Trackwork affecting Piedmont and Carolinian Services - 6/8 - 6/11- TW 26-054

11MAY26:

Beginning Monday May18th - Thursday May 21st and again Monday June 8th - Thursday June 11th between the hours of 9:30 AM-ET and 3:30 PM-ET NS will be performing scheduled trackwork on their NC Lines between Charlotte and Raleigh, NC., between MP 0.0 and 34.0 at Elm to Isom.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (18May-21May; 8Jun-11Jun), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (18May-21May; 8Jun-11Jun) will operate 40-minutes Later between CLT and GRO, arrive 45-minutes later at BNC, and operate 50-minutes Later between DNC and RGH.
- Train 76 (18May-21May; 8Jun-11Jun) will operate 12-minutes Later between DNC and RGH.
- Train 78 (18May-21May; 8Jun-11Jun) will depart BNC 10-minutes Later and operate 20-minutes Later between DNC and RGH.
- Train 80 (18May-21May; 8Jun-11Jun) will operate 10-minutes Later between DNC and RGH.

WESTBOUND

- Train 71 (18May-21May; 8Jun-11Jun) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (18May-21May; 8Jun-11Jun), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (18May-21May; 8Jun-11Jun), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (18May-21May; 8Jun-11Jun) will depart BNC 1-minute Later and operate 21-minutes Later between GRO and CLT.
- Train 79 (18May-21May; 8Jun-11Jun) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

EQUIPMENT:

May 18th - 21st and June 8th - 11th:

- Train 71 will operate RGH to CLT with a double trainset. This train set will then operate on Train 72 between CLT and GRO where it will be split up to represent Trains 73 and 75.

WBS#: B.TR.100150.6656

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
77(09)	1'09"	

21MAY26: CSX Albany Division, 26-FOI-00532, 00000007813, UNCLASSIFIED, 6/17/2026
 Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

17Jul, 20Oct-21Oct, 27Oct-31Oct, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) Train "UNCLASSIFIED" operates Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
20 (26)	XN2	174		Brake pads missing
291 (4)	CRT	9705		Trilink Bolt missing

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights***Train 4(11) West of Raton, NM - Weather***

13JUN26: Train 4(11) was delayed beginning at MP733, 75 miles west of Raton NM station on the BNSF Raton subdivision due to flash flood and high wind warnings. Train 4(11) was delayed by the flash flood warnings from MP733 to MP724, operating at a reduced speed of 20 miles per hour and was delayed even further by high wind warnings from MP719 to MP701 operating at a reduced speed of 40 miles per hour.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(11)	20	Wind Warnings
4(11)	36	Flood Warnings

Train 6(12) West of Salt Lake City, UT - Freight Train Interference

13JUN26: Train 6(12) was delayed beginning at MP737, 192 miles west of Salt Lake City UT station on the UPRR Shafter subdivision following UPRR freight train 7688 until MP773.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(12)	43"	

Train 5(10) East of Elko, NV - Freight Train Interference

13JUN26: Train 5(10) was delayed beginning at MP780, 114.70 miles east of Elko NV Station on the UPRR Shafter subdivision following UPRR Freight 5310 until MP773.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(10)	40"	

Train 547(12) East of Suisun-Fairfield, CA - Signal

13JUN26: Train 547(12) was delayed east of Suisun-Fairfield, CA due to a power switch failure at RV052/Tolenas on the UPRR Martinez Subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
547(12)	31"	

Train 4(12) East of San Bernardino, CA - Vehicle on Tracks

13JUN26: Train 4(12) was delayed 27 miles east of San Bernardino, CA at MP54.9 on the BNSF Cajon Subdivision due to a police hold for a vehicle on the tracks at MP54.19. Once the vehicle was removed and tracks inspected, Train 4(12) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(12)	1'10"	Wi-Tronix estimate

Train 704(12) Cancelled at Sacramento, CA - Third Party Contractor Engine Failure

13JUN26: Train 704(12) CC8312, 7 cars, E/C2005, was cancelled in entirety out of Sacramento, CA with no alternate transportation provided, due to HEP failure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
704(12)	Cancelled	

Train 719(12) West of Bakersfield, CA - Freight Train Interference

13JUN26: Train 719(12) 26-FOI-00532 e00000007811 CDTX "UNCLASSIFIED" car 6/17/2026 delayed at milepost 905.1, 18 miles west of Bakersfield, CA on the BNSF Bakersfield subdivision due to meeting BNSF freight train 6884. Once the freight train cleared, train 719(12) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(12)	42"	

Train 19(11) North of Laurel Laurel, MS - Signal

13JUN26: Train 19(11) was delayed beginning at MP9.8, North of Laurel, MS station/MP56.4 on the Norfolk Southern NO and NE subdivision due restrictive signals from an unknown cause. Train 19(11) operated at reduced speed of 20 miles per hour through the signals until MP26.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(11)	48"	

Train 22(12) Marshall, TX - System

12JUN26: Train 22(12) was delayed at Marshall TX station/MP66.5 on the BNSF Little Rock subdivision due to a late arriving bus.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(12)	42"	

Train 8/28(11) East of Wolf Point, MT - Freight Train Interference

13JUN26: Train 8/28(11) with engines 130, 79, 10 cars, and 261 customers onboard was delayed at milepost 205.3, 24 miles east of Wolf Point, MT on the BNSF Glasgow subdivision due to meeting BNSF freight train 8593 and 7601. The train was further delayed at milepost 178.8 due to meeting BNSF freight train 602. Once the freight trains cleared, train 8/28(11) was able to advance to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(11)	30"	

Train 4(11) Lamy, NM - Trespasser Incident

12JUN26: At 3:02PM-MT, Train 4(11), E/I193-E/78-11 Cars, struck an occupied vehicle at a DOT crossing 013710A located at MP 815.6 on the BNSF Glorieta Subdivision, approximately 19.6 miles east of Lamy, NM (MP 835.2), in Pecos, San Miguel County. The crossing was equipped with cross bucks and a yield sign. The occupant of the vehicle was reported as uninjured. At the time of the incident, the train was operating at 57MPH. Weather conditions were approximately 81 degrees and cloudy and head-end power was maintained throughout the duration of the incident. No injuries were reported to the crew or the 179 customers onboard, and no damage was reported to the train equipment. Local police and EMS responded to the scene along with the Albuquerque Road Foreman. The crew did not request trauma relief. Once released by local authorities, Train 4(11) resumed movement east at 514PM-MT. NRC # 1465114

National Response Center Number: 1465114

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(11)	2'18"	

Train 19(11) North of Tuscaloosa, AL - Passenger Train Interference

12JUN26: Train 19(11) was delayed beginning at MP172.3, 50.4 miles north of Tuscaloosa, AL station on the Norfolk Southern AGS South subdivision holding for a meet with Amtrak train 20(12). Train 19(11) was back on the move at 528PM CT once train 20(12) cleared to the north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(11)	51"	

Train 58(12) South of Greenwood, MS - Freight Train Interference

12JUN26: Train 58(12) was delayed beginning at MP172.3, 50.4 miles south of Greenwood MS station on the CN Yazoo subdivision following freight train 301.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(12)	31"	

Train Train 20(12) South of Tuscaloosa, AL - Signal

12JUN26: Train 20(12) was delayed at MP22.1, 23.7 miles south of Tuscaloosa, AL station on the Norfolk Southern AGS South division due to restrictive signals caused by a track light issues. 20(12) operated through the signals at restricted speed until MP214.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(12)	36"	

Train 715(12) West of Bakersfield, CA - Police Related

12JUN26: Train 715(12) was delayed at MP 904.7, 8 miles west of Bakersfield, CA, on the BNSF Bakersfield Subdivision due to a vehicle on the tracks. The crew held while a tow truck and BNSF personnel responded. The tow truck arrived on scene at 12:45P-PT and worked to remove the vehicle. Due to the trailer being hi-centered, the excavator had to be removed in order for the trailer to be removed from tracks. Once vehicle was removed and tracks were inspected, Train 715(12) proceeded west. Train 702(12) was delayed at MP 908.3 holding for tracks to be cleared. Train 710(12) was also delayed at Wasco waiting for repairs to the track to be complete.

Due to this, several trains and equipment turns were affected. Train 715(12) operating as a double-set was terminated at Emeryville with 24 affected passengers transferring to Train 551(12), Train 718(12) was then severely delayed departing Oakland due to needing to split the set upon arrival and Train 713(13) was cancelled in entirety. Train 719(12) was delayed initial terminal and was then terminated at Emeryville with all passengers Ubered to Oakland. Train 14(12) was also delayed holding at Sacramento, CA for late bus connections from 719(12).

WBS#: B.TR.100150.6765

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
713(13)	Cancelled	
712(12)	1'07"	
718(12)	6'35"	ITD- OKJ
702(12)	2'30"	
710(12)	1'53"	
715(12)	3'15"	Terminated EMY
717(12)	2'21"	
719(12)	1'46"	Terminated EMY
14(12)	1'04"	SAC- Held 719/3819 bus connects

Train 715(12) Bakersfield, CA - Third Party Contractor Engine Failure

12JUN26: Train 715(12), 5/62004-7 cars- CC/90278, were delayed departing Bakersfield, CA due to head end power issues. The crew worked with mechanical and Amtrak road foreman to troubleshoot. Once issues were resolved, the customers were boarded and Train 715(12) departed.

Train 715(12) was further delayed at MP 903.2, 6 miles west of Bakersfield, CA, due to locomotive issues. The crew worked with mechanical to further troubleshoot.

Train	Delay	Comment
715(12)	55"	

Train 516(12) North of Bellingham, WA - M of W Work

12JUN26: Train 516(12) held 47.7 miles north of Bellingham, WA (MP93.4), on the BNSF New Westminster Subdivision, at the Fraser River Jct (MP141.1) waiting on Maintenance of Way to finish scheduled work on the Fraser River Bridge (MP143.4). Once the work was complete, Train 516(12) was released to continue north.

Train	Delay	Comment
516(12)	58"	

Train 526(12) Oakland, CA - Third Party Contractor Engine Failure

12JUN26: Train 526(12), CC/C8311-4 cars, E/C2102, was delayed departing Oakland, CA due to late release from mechanical. Once mechanical released equipment, E/C2102 had loading issues which the crew and mechanical began to troubleshoot. Mechanical was unable to resolve the issue. Train 526(12) was cancelled its entirety with customers reaccommodated on the next available service. Due to equipment shortage in Sacramento, CA, Train 541(12) was also cancelled in its entirety with customers reaccommodated on next available. Train 539(12) was delayed departing Sacramento due to the turn of equipment from Train 528(12) arriving at 12:03P-PT.

Train	Delay	Comment
526(12)	Cancelled	
541(12)	Cancelled	
539(12)	20"	ITD SAC

Train 769(12) West of San Juan Capistrano, CA - Signal Issues

12JUN26: Train 769(12) was delayed at MP 192.5, 5 miles west of San Juan Capistrano, on the Metrolink Orange Subdivision due to signal issues. The crew had to stop and hand line from main track two to main track one. Once tracks were lined, the crew operated at restricted speed through the affect area. Multiple other trains were delayed operating through the affected area.

Train	Delay	Comment
769(12)	39"	
770(12)	31"	
573(12)	29"	

Train 7(10) East of Leavenworth, WA - Freight Train Interference

12JUN26: Train 7(10) 26-P01-005322.00000007815 east UNCLASSIFIED Leavenworth, WA (MP1672.0), on the BNSF Scenic Subdivision, at Cashmere (MP1659.3) due to BNSF 5629 with a reported engine fire at Leavenworth. There was no route around due another BNSF freight train sitting in the siding. BNSF 5629 engine was bad ordered and required a setout. Due to this, Train 8(12) was delayed departing Seattle, the train departed 8 hours and 9 minutes late.

Train	Delay	Comment
7(10)	5'55"	
8(12)	8'09"	ITD- Equip turn 7(10)

Train 529(12) Oakland, CA - Vehicle on Tracks

12JUN26: Train 529(12) was delayed departing Oakland, CA/ MP 7.1 on the UPRR Niles Subdivision due to a vehicle on the tracks ahead at MP 10.36. The crew held at the station for tow truck and track inspector to arrive. Once vehicle was removed and the tracks were inspected, Train 529(12) departed Oakland.

Train	Delay	Comment
529(12)	50"	

Train 8/28(10) East of St. Paul-Minneapolis, MN - Signal

12JUN26: Train 8/28(10) was delayed 8.9 miles east of St. Paul, MN (MP 410.3), on the BNSF St. Paul Subdivision, due to a reported stop signal at Newport (MP 422.2). Once permission was granted to proceed east, operating speeds were restricted until a clear signal was reached at St. Croix (MP 410.5).

Train	Delay	Comment
8/28(10)	28"	Newport
8/28(10)	34"	Restricted

Trains 301(12) and 319(12) Chicago, IL - Bad Order Car

12JUN26: Train 301(12) was delayed 10 minutes departing Chicago, Illinois account a late bad order car. While attempting to shove Train 301(12) equipment, the yard crew reported issues releasing the brakes on coach car ID4004. At 6:33AM-CT, the car was bad ordered for brake issues. It was necessary to utilize Train 319(12)'s equipment. Train 301(12) departed at 7:25AM-CT, 10 minutes late. Train 301(12)'s equipment was then switched out and axle count cars were added, made up complete at 8:27AM-CT and set in the station at 1000AM-CT. After loading 238 passengers, Train 319(12) departed at 10:33AM-CT, 43 minutes late.

Train	Delay	Comment
301(12)	10"	ITD CHI
319(12)	43"	ITD CHI

Train 23(12) South of Bay Saint Louis, MS - Passenger Train Interference

12JUN26: Train 23(12) was held 1.9 miles south of Bay Saint Louis, MS (MP 754.5) on the CSX NO&M Subdivision at Nicholson Ave (MP 756.4) to meet Train 24(12). Train 24(12) was delayed through the area following BNSF 5672 from MP803.6 to MP801.5 and then had to meet CSX M605-10 at Lake Catherine (MP780.3).

Train	Delay	Comment
24(12)	16"	Follow BNSF 5672
24(12)	15"	Meet 23(12)
24(12)	15"	Meet CSX M605-10
23(12)	32"	Meet 24(12)

Train 40(10) East of Waterloo, IN - Near Miss

12JUN26: At 8:30AM-ET, Train 40(10), E/375-E/341-10 Cars, went into emergency approximately 20.9 miles east of Waterloo, IN (MP 367.1) on the NSRR Chicago Line, at MP 346.2, in order to avoid striking a vehicle on the tracks ahead. No impact occurred. There were no injuries reported to the crew or the 268 customers onboard, and no damage was sustained to the equipment. The vehicle was fouling Main Track 2 and required a tow response for removal. Train 49(11) was also delayed during the incident, holding at MP 346.2. Once the track was cleared, both Train 40(10) and Train 49(11) resumed movement at approximately 9:35AM-ET.

Train	Delay	Comment
40(10)	1'25"	
49(11)	32"	Hold for track opening
49(11)	16"	Follow 40(10) to CHI

Train 4(11) West of Flagstaff, AZ - Freight Train Interference

12JUN26: Train 4(11) was delayed starting at MP 439.4, 95 miles west of Flagstaff, AZ, on the BNSF Seligman Subdivision due to following BN6242. The crew followed BN6242 from MP 439.4 to MP 389.5 where it was able to operate around. Once route was clear, Train 4(11) proceeded at track speed.

Train	Delay	Comment
4(11)	34"	

Train 5(10) East of Denver, CO - Freight Train Interference

12JUN26: Train 5(10) was delayed 16.2 miles east of Denver, CO (MP0.0), on the BNSF Brush Subdivision, at Barr (MP526.1) meeting BNSF 7746.

Train	Delay	Comment
5(10)	1'03"	

Train 300(12) South of Alton, IL - Freight Train Interference

12JUN26: Train 300(12) held 20.4 miles south of Alton, IL (MP255.1), on the UPRR Springfield Subdivision, at WR Tower (MP275.5) waiting on NS 35N to clear the crossing ahead.

Train	Delay	Comment
300(12)	44"	

Train 7/27(12) Chicago, IL - Yard derailment

12JUN26: At 3:35AM-CT, Train 7/27(12), E/375-E/341-10 Cars, derailed with the rear truck (2 axles) in engine 341 on the ground and the front truck (4 axles) of car 61055 on the ground in the Chicago yard. The equipment derailed while moving through Main 8 at switch E87B and was fouling Main 7. Minimal impact to operations was expected. All departments were on scene, including IMCS, Transportation, and Mechanical. No injuries were reported to the crew. A crane arrived to the location at 8:00AM-CT to re-rail the equipment. At 2:15PM-CT, the equipment was rerailed with no impacts to service.

Train	Delay	Comment
7/27(12)	No Delays to the operation	

12JUN26: Train 59(11) was delayed at Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision, at North Carbondale (MP305.7) meeting Train 58(11). Service recovery was initiated due to lateness consisting of snack packs bottled water to all coach customers. Hot tea and coffee were available in the cafe car. Breakfast was extended for the first-class customers in the dining car.

Train	Delay	Comment
59(11)	32"	

Train 383(12) Galesburg, IL - Engine Failure

13JUN26: Train 383(12) was delayed at Galesburg, IL station/MP162.6 on the BNSF Brookfield subdivision adding BNSF freight engine 5045 due to an oil rifle pressure fault on engine ID4618. Crew was delayed adding the engine to a broken air brake pressure pipe so the engine could not be added to the lead. Crew attempted to add the engine to the rear but could not get the engine to load due to no m/u cables between cars ID4117 and ID4311. Engine 5045 was added to the rear but due to not loading the freight engine needed a rider. Train 383(12) was back on the move at 116AM CT with the rider on board engine 5045. Due to engine mechanical issues with engine ID4618 and no available buses train 380(13) is cancelled with no alternate transportations. The equipment will deadhead to Chicago IL station as train 380(13).

Train	Delay	Comment
383(12)	3'50"	

Severe Weather Central U.S - Weather

09JUN26: A seasonably strong storm system brought scattered storms to much of the Northern Plains and Midwest. Storms forecasted to congeal as they move east and are expected to produce wind gusts to 80MPH, large hail, localized flash flooding and isolated tornadoes. Storms will diminish into the early hours of Wednesday morning. Another round of scattered storms will develop Wednesday afternoon along a corridor through central Minnesota, central Iowa and northwestern Missouri. Disruptions are expected from these storms, including flash floods, downed trees and power lines and possible power outages in affected areas.

Southwest Chief

09JUN26: Train 4(07), E/50-E/181 & 9 cars, with 181 customers, was delayed at MP125.2, 72 miles west of Topeka, KS, on the BNSF Emporia Subdivision, due to a reported washout ahead at MP56.8, on the BNSF Topeka Subdivision and no estimate for open track. As a result, Train 4(07) was rerouted to detour over the BNSF Emporia Subdivision to Kansas City, MO, bypassing the Topeka, KS and Lawrence, KS station stops. Train 4(07) advanced to Emporia/MP112 where BNSF pilots boarded and proceeded onto the detour. Customers (10) scheduled to board at Topeka and Lawrence were notified train was bypassing and advised to rebook travel. The ten customers scheduled to detrain at the bypassed stops were provided alternate transportation from Kansas City back to Lawrence and Topeka. BNSF estimated track would be open at approximately 600PM-CT.

Empire Builder and Borealis

10JUN26, Train 7/27(09), with 254 customers, was delayed west of Staples, MN/MP148.3, on the BNSF Staples Subdivision, due to high wind warnings in effect between MP148 and MP165. Train 7/27(09) was delayed operating reduced speed through the affected area.

10JUN26, Train 8/28(08), E/353-E/301 & 11 cars, with 213 customers, was delayed at MP413, 3 miles west of St. Paul-Minneapolis, MN, on the CPKC Merriam Park Subdivision, due to large tree down ahead at Erie St. Train 8/28(08) held for MW to respond, clear tree and open the route. Train 8/28(08) was further delayed at MP361.1, 9 miles east of Red Wing, MN, due to PTC issues after striking a tree. There were no injuries and no reported damages to equipment. The crew contacted PTC desk however was unable to resolve issues. Train 8/28(08) proceeded east with PTC cut out on E/353.

reported injuries to passengers or crew. Lead E/29 engineer's side air horn light was knocked out. There were no other exceptions to equipment reported.

26-FOI-00532 00000007811 "UNCLASSIFIED" 6/17/2026

10JUN26, Train 1333(10), E/519-3 cars-E/198, was delayed at MP172.3, 6 miles east of Portage, WI, on the CPKC Watertown Subdivision, due to striking a tree and PTC disengaging on E/519. There were no injuries reported and no other exceptions to equipment reported. Crew was unable to resolve PTC issue and Train 1333(10) was authorized to proceed with PTC cut out. Train 1333(10) was delayed enroute operating 59MPH Max.

Lake Shore Limited & Floridian

10JUN26, Trains 49/449(09) with 256 customers, and Train 40(08) with 126 customers, were delayed west of Elyria, OH/MP206.6, on the NS Toledo East Subdivision, operating through flash flood warnings between MP232 and MP240. Trains 48/448(09), with 272 customers, and Train 41(09), with 182 customers, were delayed east of Toledo, OH/MP288.3, on the NS Toledo East Subdivision, operating through flash flood warnings between MP271 and MP233.

Cardinal: 10JUN26, Train 50(09), with 85 customers, was delayed at MP110, 17 miles east of Indianapolis, IN, on the CSX Indianapolis Subdivision, waiting on track inspector to clear ahead after high winds expired.

California Zephyr & Southwest Chief

10JUN26, BNSF issues numerous high wind warnings across the BNSF Mendota and Ottumwa Subdivisions. Trains 3(10) and 5(10) were delayed operating through the affected areas. 5(10) was delayed from MP155 to MP196 east of Burlington IL due to high wind and flash flood warnings. Train 5(10) held at Ottumwa IA station on the BNSF Ottumwa sub due to a washout reported at MP322. Train 5(10) departed the station at 116AM CT to approach the washout and wait for open tracks. Train 3(10) was delayed holding for a re-crew at La Plata MO station on the BNSF Marceline subdivision. Re-crew arrived and after the briefing train 3(10) departed La Plata MO station at 212AM CT.

Texas Eagle: UPRR issued high wind warnings, in excess of 80MPH gusts, on the Joliet Subdivision, between Joliet, IL/MP37 and MP81. Additionally a tornado warning was in effect between MP39 and MP46. Trains 21(10) and 22(09)/422(07) were delayed through the area.

Borealis: Train 1340(10) was delayed holding at MP187.2, 10.10 miles west of Portage WI station on the CPKC Tomah subdivision due to signal issues caused by lightning strikes in the area.

Michigan Line: Train 352(10) was stopped at MP266, west of New Buffalo, MI station on the Amtrak Michigan line due to debris on the track. Train 352(10) was back on the move at 609PM ET. Train 370(10) was delayed beginning at MP136.4 west of St. Joseph MI station on the CSX Grand Rapids subdivision due to high wind warnings until MP5.9.

Illini Service: Train 393(10) was delayed departing Chicago IL station/MP0.0 due to Norfolk Southern holding trains on while tracks ahead were inspected for debris. Train 393(10) received permission from CN to re-route on Cermak and were back on the move at 456PM CT.

Lincoln Service: Train 318(10) was delayed beginning at MP51.6, south of Joliet IL Station on the CN Joliet subdivision operating at restricted speed due to a track light from severe weather.

Carl Sandberg: Train 383(10) was delayed beginning at MP61, west of Mendota, IL station on the BNSF Mendota subdivision due to high wind warnings until MP52.3. 382(10) was delayed beginning at MP191.4 east of Galesburg, IL station due to high wind warnings until MP162.4

11JUN26 Updates:

Southwest Chief Service:

-Train 3(10) was further delayed after departing La Plata, MO (MP312.7), on the BNSF Marceline Subdivision, due to flash flood warnings ending at MP327.0. Operating speeds were restricted through the area. At West Marceline (MP347.3), Train 3(10) stopped to pick-up their recrew before being able to proceed west.

-Train 4(09) was delayed starting 133.2 miles east of Kansas City, MO (MP6.9), on the BNSF Marceline Subdivision, from high wind warnings starting at MP318.0 to MP273.3.

Train 5(10), once released from Ottumwa, IA (MP279.8), operated through flash flood warnings starting at M281.0 to MP347.0. Operating speeds were restricted from Halpin (MP309.8) to MP347.0. 26-FOI-00532 00000007811 "UNCLASSIFIED" 6/17/2026 Severe weather continued west of Creston, IA (MP393.1) resulting extensive delays due to multiple downed trees ahead of 5(10) at MP404.8, MP405, MP418 and also downed power lines at MP421. The crew was able to remove the tree at MP404.8 themselves but required Maintenance of Way and a Hi-rail excavator response for the others and the power lines. Train 5(10) held at MP404.7 with 235 customers onboard for a route to be established. The tracks were reopened at 3:00PM-CT. Re-crew arrived on site for train 5(10) at MP442.6 W/CRN at approximately 520PM CT. Train 5(10) was back on the move west at 538PM CT and was operating approximately 19'37" late. Service recovery was enacted due to the delay and car lounge 33039 with no refrigeration. Sleeper customers meal service was not affected. Snack packs, coffee, tea, juice, and water were offered for all customers. Coach customers received beef stew for lunch and Pizza at Omaha for dinner. Customers waiting at the Omaha station were given Jersey Mikes meal boxes. Train 5(10) was delayed at MP263.9 east of McCook NE station on the BNSF Hastings subdivision holding for a re-crew. Re-crew arrived on site and train 5(10) was back on the move at 150AM CT.

-Train 6(09) was delayed starting 0.8 miles east of Lincoln, NE (MP0.8X), on the BNSF Creston and Omaha Subdivisions, due to high wind warnings starting at Baird (MP58.8) to MP29.0. 60MPH warnings in effect MP58.8 to MP41.1, 70MPH warnings in effect MP41.1 to Ashland (MP35.1), then 80MPH warnings on the Omaha Subdivision from East Wye Ashland (MP46.1) to MP29.0. Train 6(09) was also heavily delayed west of Creston holding at MP429.1 for the power lines and trees to be removed ahead. Train 6(09) held at MP426.5 west of Creston IA station waiting for a re-crew to arrive. Re-crew arrived on site and train 6(09) was back on the move at 503PM CT operating approximately 10'57" late. Service recovery was enacted starting with snack packs, bottled water, coffee, tea, and juice for all customers. Coach customers also received beef stew or vegetarian chili. Sleeper customers meals were not affected for breakfast or lunch but did receive a modified menu for dinner consisting of chicken, salmon, and pasta.

-Due to the extensive delay to Train 5(10) and the upcoming UPRR Moffat Subdivision trackwork starting at 5PM-MDT on 11JUN, Train 5(10) and 6(10) bus bridged between Denver and Grand Junction. Train 6(10) had four buses secured to arrive to Grand Junction at 1:30PM-MDT to bus bridge Grand Junction to Denver. One bus operated Grand Junction, Glenwood Springs, Denver and the other three operated express. Two ADA customers at Glenwood Springs were also provided vans. Train 5(10) had five buses secured between Denver and Grand Junction to be onsite upon train arrival. Bus#1 made stops to Denver, Glenwood Springs, and Grand Junction and the other four buses operated express. Local transportation was provided for customers destined to Winter Park and Granby for both trains. Customers for trains 5(10) and 6(10) set to board at Winter Park and Granby were notified of no alternate and to rebook to the next available.

-Additional service adjustments were made due to the late operations of Train 5(10). Train 5(10) was terminated at Reno, NV with alternate bus transportation provided between Reno and Sacramento; 3 express and 1 local making all intermediate stops, then passengers would take a capitol corridor train between SAC-EMY. Train 6(13) originated at Reno, NV from Train 5(10) equipment. Passengers between EMY-SAC were accommodated on Train 720(13) to SAC then boarded a bus from SAC to RNO; 3 express busses and 1 local bus making all intermediate stops were secured to arrive at Sacramento 13JUN at 9:30AM-PT.

Cardinal

Train 50(11) was delayed due to tornado warnings at MP25.1 north of Dyer, IN station on the CSX Monon subdivision. 50(11) was delayed again between Dyer and Rensselaer due to trees down.

Carl Sandberg:

Train 383(11) was delayed at holding at Mendota IL station/MP82.8 on the BNSF Mendota subdivision due to down tress reported on the tracks ahead. Train 383(11) was back on the move at 824PM CT. Train 382(11) was delayed beginning at MP263.4 north of Quincy IL station on the BNSF Brookfield subdivision due to high wind warnings until MP240.

Lincoln

Train 318(11) was delayed holding at Springfield IL station/MP185.1 due to high wind

318(11) advanced to the Normal siding to meet train 306(11) so that they could couple up and double draft. After coupling up both trains were back on the move at 945PM CT.

26-FOI-00532 00000007811 "UNCLASSIFIED" 6/17/2026

Train 305(11) was delayed holding at MP170 north of Springfield IL station for a track inspector to release the tracks due to debris from the severe weather.

Illini Service:

Train 392(11) was delayed holding at MP101.2 due to downed trees south of Gilman IL station.

City Of New Orleans

Train 59(11) was delayed holding at MP83.2 due to downed trees south of Gilman IL station.

NS Chicago subdivision down power lines :

Trains 41(11), 370(11) and 355(11) were delayed due to downed power lines on the Norfolk Southern Chicago subdivision. Trains 41(10) and 370(11) reversed to Chicago IL station. 370(11) terminated Chicago IL station with alternate bus transportation secure Chicago IL to Grand Rapids MI. Train 41(11) coupled with train 48/448(11) and double drafted to Toledo OH station. 355(11) reversed to Michigan City to meet alternate bus transportation for Hammond IN and Chicago IL station. 371(12) was cancelled in it's entirety with no alternate transportation due to train 370(11) being cancelled. Train 350(12) delayed departing Chicago IL station. Train 48/448(11) and 41(11) double draft departed Chicago IL Station at 321AM CT. Train 355(11) deadhead equipment on the move to Chicago IL station at 241AM CT.

12JUN26:

-Train 301(12) held at Lemont (MP 25.3) on the CNRR Joliet Subdivision, approximately 13.5 miles south of Summit, IL (MP 11.8), while awaiting the engineer recrew deadheading on Train 300(12). The assigned engineer remained within hours of service until 8:22AM-CT, following an adjusted start time due to the overnight weather-related disruption. Once the recrew arrived and boarded the train, Train 301(12) continued south without further delay.

-Train 5(10) arrived at Denver, CO (MP0.0), on the BNSF Front Range Subdivision, at 6:38AM-MT, 22 hours and 42 minutes late. All customers boarded buses to bus bridge to Grand Junction, Train 5(10) departed Grand Junction, CO at 1:39PM-MT, operating 20 hours and 56 minutes late.

-Train 6(11) was unable to officially arrive to Grand Junction and unload customers to buses until after Train 5(10) departed the station track. The 6(11) equipment was wye'd for turn of 5(11), but customers remained onboard as the equipment was positioned behind 5(10). Once Train 5(10) cleared the station track, Train 6(11) arrived at Grand Junction at 1:43PM, 4 hours and 02 minutes late.

-Train 6(10) departed Denver, CO at 9:02AM-MT after successfully completing the bus bridge and turning the inbound equipment. Once on the move, Train 6(10) was operating 14 hours and 03 minutes late.

-Train 5(11) was held 1.1 miles east of Denver, CO, on the BNSF Brush Subdivision at 31st Street (MP 341.2), where it waited for Train 6(10) to clear the station track.

-Trains 41(11) and 48(11) uncoupled their equipment at Toledo, OH and continued to their end points. Train 48(11) departed Toledo, OH operating 6 hours and 08 minutes late. Train 41(11) departed Toledo operating 10 hours and 08 minutes late. Service recovery for 41(11) was initiated with all customers offered bottled water, snack packs, coffee and tea. Coach customers were offered beef stew, rice, and bottled water for lunch. All first-class customers received breakfast and lunch as normal from the diner.

-Train 6(10) was delayed holding at MP196.7 west of Hastings NE station on the BNSF Hastings subdivision waiting for the arrival of a re-crew and BNSF pilots. Crews arrived on site and did their briefing. Train 6(10) was back on the move at 445PM CT.

NS Chicago Subdivision:

Multiple trains were delayed on the Norfolk Southern Chicago subdivision due to freight congestion and signal issues that were caused by the severe weather on June 11 2026. Trains 364(12), 370(12), 355(12), 354(12), 352(12), 41(12) and 48/448(12) all saw significant delays operating on the Norfolk Southern Chicago subdivision due to the congestion and switch issues.

WBS#: B.TR.100150.6762

Train	Delay	Comment
-------	-------	---------

49/449 (09)	15"	W/ELY, flash flood warnings
40 (08)	04"	W/ELY, flash flood warnings
48/448 (09)	28"	E/TOL, flash flood warnings
41 (09)	15"	E/TOL, flash flood warnings
50 (09)	29"	E/IND, high winds/track insp
8/28 (08)	52"	W/MSP, downed tree
8/28 (08)	44"	E/RDW, PTC c/o after tree strike
8/28 (08)	20"	E/RDW, tree strike
22 (09) / 422 (07)		
1333 (10)	28"	E/POG, tree strike
3 (10)	33"	W/NPV, high wind warnings
21 (10)	1'07"	S/JOL, high wind/tornado warning
5 (10)	1'28"	W/NPV, high wind warnings
1340 (10)	50"	
352 (10)	1'29"	W/NBU, downed tree
393 (10)	51"	
318 (10)	32"	
383 (10)	41"	PLO-MDT
382 (10)	1'14"	MAC-GBB
5 (10)	1'45"	GBB-BRL
5 (10)	1'36"	HOLD OTM
3 (10)	1'16"	HOLD LAP RE-CREW
3 (10)	4'51"	FMD-LAP FLOOD WIND
370 (10)	48"	
1333 (10)	49"	W/POG, PTC c/o
3 (10)	35"	W/LAP FF
3 (10)	10"	West Marceline - Recrew
5 (10)	3'13"	OTM - OSC Flash Floods MP281-MP347
6 (09)	55"	LNK-OMA High Winds
4 (09)	1'00"	High Winds/Flash Floods KCY-FMD
6 (09)	9'08"	W/CRN POWERLINES
5 (10)	1'31"	RECREW W/CRN
5 (10)	9'12"	W/CRN POWERLINES
382 (11)	40"	
50 (11)	58"	TORNADO W N/DYE
6 (13)	Originated RNO	
5 (10)	Terminated RNO	
383 (11)	40"	
50 (11)	59"	DYE-REN TREES DOWN
306 (11)	38"	COUPLE 318 (11)
318 (11)	1'20"	COUPLE 306 (11)
318 (11)	32"	High Winds SPI
392 (11)	1'39"	TREES S/GLM
305 (11)	35"	HOLD MP170 TI
5 (10)	1'28"	RECREW E/MCK
370 (11)	Term CHI	
355 (11)	Term NBU	
371 (12)	Cancelled No ALT	
48 (11)	5'50"	CHI - Hold
41 (11)	8'40"	CHI - Hold
59 (11)	3'29"	TREES S/GLM
301 (12)	1'05"	Lemont - Recrew
300 (12)	03"	Lemont - Dropping off Recrew
6 (10)	14'03"	DP DEN after Bus Bridge
5 (11)	38"	31st St - Meet 6 (10)
41 (11)	23"	TOL - Uncouple
6 (11)	4'02"	Held out of GJT
5 (10)	20'56"	DP GJT after Bus Bridge
6 (10)	53"	RE-CREW W/HAS
352 (12)	41"	FTI CHI CUB
364 (12)	2'10"	FTI CHI SUB
354 (12)	21"	FTI CHI SUB
354 (12)	1'24"	PTI CHI SUB
370 (12)	2'26"	FTI CHI SUB
355 (12)	38"	FTI CHI SUB
355 (12)	43"	PTI CHI SUB
41 (12)	2'08"	PTI CHI SUB
41 (12)	33"	FTI CHI SUB
48/448 (12)	36"	FTI CHI SUB
5 (12)	1'45"	LNK CREW REST

UPRR Moffat Tunnel Subdivision - Scheduled M/W Work 26-060

11JUN26: Union Pacific has tunnel rehabilitation scheduled on the Moffat Tunnel Subdivision starting June 11th at 5:00PM through June 12th at 1:00PM. To accommodate the above outlined infrastructure work, Amtrak's California Zephyr Service will be adjusted as follows:

-Train 5(11Jun), which normally operates between CHI and EMY, will operate as Train 5(11Jun) CHI to DEN, as Bus 3005(12Jun) DEN to GJT, and as Train 1005(12Jun) GJT-EMY. Bus 3005(12Jun) will provide alternate transportation at DEN, GSC, and GJT. The bus will not be stopping at WIP or GRA.

-Train 6(11Jun), which normally operates between EMY and CHI, will operate as Train 6(11Jun) EMY to GJT, as Bus 3006(12Jun) GJT to DEN, and as Train 1006(12Jun) DEN-CHI. Bus 3006(12Jun) will provide alternate transportation at GJT, GSC and DEN. The bus will not be stopping at GRA or WIP.

EQUIPMENT

-After arriving at DEN, Train 5(11Jun) will wye and the equipment will represent Train 1006(12Jun) from DEN to CHI.

-Train 6(11Jun) will operate with diesel engines back-to-back and will wye upon arrival in GJT. Should the wye be unavailable, the engines will run around the train. The equipment will represent Train 1005(12Jun) from GJT to EMY.

Update: Due to the continued late operation of Train 5(10) from weather and the previously scheduled UPRR trackwork, the following California Zephyr service adjustments were implemented;

Train 5(10) and Train 6(10) were cancelled between Grand Junction, CO and Denver, CO, with alternate transportation provided via bus-bridge between Grand Junction and Denver.

Train 5(10) equipment, upon arrival at Denver, will turn and represent Train 6(10) Denver to Chicago. Train 6(10) equipment, upon arrival at Grand Junction, will turn and represent Train 5(10) Grand Junction to Emeryville, holding for arrival of customers from delayed Train 5(10) at Denver.

WBS#: B.TR.100150.6655

13APR26: BNSF will perform multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

26APR26: Canadian National has scheduled trackwork on the Yazoo Subdivision between MP94 and MP126 starting on April 27th through May 29th. To accommodate this infrastructure work, Amtrak's City of New Orleans Service has been adjusted as follows:
24MAY26: Track work extended through June 19th, 2026.

-Train 1059 (26Apr) will operate in lieu of Train 59(26Apr), departing Chicago 2-hours Earlier, at 6:05pm, and will operate on an adjusted schedule between Chicago and New Orleans.

-Train 59(27Apr-18JUN) will depart Chicago 2-hours Earlier, at 6:05pm, and operate on an adjusted schedule between Chicago and New Orleans.

-Train 1058(27Apr) will operate in lieu of Train 58(27Apr), departing New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

-Train 58(28Apr-19JUN) will depart New Orleans 2-hours Earlier, at 11:45am, and will operate on an adjusted schedule between New Orleans and Chicago.

WBS#: B.TR.100150.6608

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

09APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

WBS#: B.TR.100150.6620

Western Region

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
380 (13)	QCY	BNSF 5045	Oil pressure faults	Enroute	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(12)	STL	1	Carried passenger to ALN to wait for Train 21	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00532

00000007811

"UNCLASSIFIED"

6/17/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
21 (12)	CHI	Operating with bag coach in lieu of standard coach for local coach. No passenger impacted.	0	0	31043
59 (12)	CHI	Operating with diner in lieu of diner/lounge.	0	0	38067
3 (12)	CHI	Operating w/o baggage car. Passengers baggage will be accommodated in the bag coach.	0	0	31045
562 (12)	LAX	NO BIKE SERVICE	0	0	9700
566 (12)	LAX	NO BIKE SERVICE	0	0	90225
580 (12)	LAX	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	-1	-1	9700
584 (12)	LAX	Operating with 90225 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	0	0	90225
97 (12)	NYP	AM 1 CAFE IN LIEU OF A AM 2 LOUNGE	0	0	43391
97 (12)	NYP	VIEW 1 SLEEPER IN LIEU OF A VIEW 2 SLEEPER	0	0	62026
573 (12)	SAN	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	-2	-2	9700
591 (12)	SAN	Operating with 9700 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	0	0	9700
579 (12)	SAN	Operating with 90225 in consist will not be able to accommodate passenger with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.	0	0	90225
595 (12)	SAN	Operating with 90225 in consist will not be able to accommodate passenger	0	0	90225

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		with BV reservations. Inventory has been updated to reflect changes. CSV please reaccomodate any paxs impacted by this change.			
22 (12)	STL	Operating with bag coach in lieu of standard coach for local coach. No passenger impacted.	0	0	31043
66 (11)	WAS	operating with biz coach in lieu of coach. no impact to customers	0	0	81501

Reverse Consists

Train Number	Station	Reason
95 (12)	BOS	Consist reversed Business class seat orientation may have changed At Front
86 (12)	NPN	Consist reversed Business class seat orientation may have changed At Front
113 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (12)	PHL	Consist reversed Business class seat orientation may have changed At Front
137 (12)	BOS	Consist reversed Business class seat orientation may have changed At Front
136 (12)	WAS	Consist reversed Business class seat orientation may have changed At Front
147 (13)	SPG	Consist reversed Business class seat orientation may have changed At Front.. **Train 147(13)**
164 (13)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **Train 164(13)**
179 (12)	BOS	Consist reversed Business class seat orientation may have changed At Front
158 (13)	NFK	Consist reversed Business class seat orientation may have changed At Front
193 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front
182 (12)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (12)	NYP	Consist reversed Business class seat orientation may have changed At Front