CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, October 07, 2026 Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

27-FOI-00048 Request Received 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/06/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	328	40	87.8%	1,900	258	86.4%	1,900	258	86.4%
Central Division	86.0%	59	2	96.6%	346	13	96.2%	346	13	96.2%
East Division	82.0%	178	21	88.2%	1,022	152	85.1%	1,022	152	85.1%
West Division	86.0%	91	17	81.3%	532	93	82.5%	532	93	82.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/6/26

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**93,091**	**26,470**	**72%**	**656,354**	**196,276**	**70%**	**656,354**	**196,276**	**70%**
Northeast Corridor	***81%***	***42,440***	***9,989***	***76%***	***288,071***	***83,238***	***71%***	***288,071***	***83,238***	***71%***
Acela	83%	11,186	2,125	81%	64,439	16,620	74%	64,439	16,620	74%
Northeast Regional	79%	31,254	7,864	75%	223,632	66,618	70%	223,632	66,618	70%
Richmond / Newport News / Norfolk	77%	8,236	2,000	76%	64,244	20,005	69%	64,244	20,005	69%
Springfield Shuttles	89%	684	31	95%	5,564	1,289	77%	5,564	1,289	77%
Roanoke	79%	3,368	1,188	65%	21,874	7,631	65%	21,874	7,631	65%
On Spine Northeast Regional	80%	18,966	4,645	76%	131,950	37,693	71%	131,950	37,693	71%
State Supported	***80%***	***39,854***	***10,453***	***74%***	***294,906***	***75,337***	***74%***	***294,906***	***75,337***	***74%***
Borealis	80%	545	46	92%	3,865	1,028	73%	3,865	1,028	73%
Capitol Corridor	90%	4,303	388	91%	26,125	7,112	73%	26,125	7,112	73%
Carolinian	70%	960	165	83%	7,461	2,046	73%	7,461	2,046	73%
Cascades	75%	2,118	619	71%	16,985	3,830	77%	16,985	3,830	77%
Downeaster	82%	1,609	367	77%	11,269	3,378	70%	11,269	3,378	70%
Empire	78%	5,143	1,848	64%	36,609	8,130	78%	36,609	8,130	78%
Adirondack	72%	332	21	94%	2,310	327	86%	2,310	327	86%
Ethan Allen Express	70%	441	199	55%	3,412	1,068	69%	3,412	1,068	69%
Maple Leaf	70%	687	212	69%	4,959	1,056	79%	4,959	1,056	79%
New York - Albany	85%	2,576	986	62%	17,533	3,475	80%	17,533	3,475	80%
New York - Niagara Falls	75%	1,107	430	61%	8,395	2,204	74%	8,395	2,204	74%
Gold Runner	73%	1,477	785	47%	16,662	5,272	68%	16,662	5,272	68%
Heartland Flyer	70%	104	62	40%	1,081	1,016	6%	1,081	1,016	6%
Hiawatha	90%	1,470	553	62%	11,355	560	95%	11,355	560	95%
Illinois	78%	1,776	593	67%	16,712	5,498	67%	16,712	5,498	67%
Carl Sandburg / Illinois Zephyr	85%	273	124	55%	2,569	583	77%	2,569	583	77%
Illini / Saluki	85%	536	172	68%	5,486	1,484	73%	5,486	1,484	73%
Lincoln Service	70%	967	297	69%	8,657	3,431	60%	8,657	3,431	60%
Keystone	92%	9,267	1,130	88%	51,779	7,481	86%	51,779	7,481	86%
Lincoln / Missouri	70%	655	301	54%	5,060	2,590	49%	5,060	2,590	49%
Mardi Gras Service	80%	309	170	45%	1,849	374	80%	1,849	374	80%
Michigan	70%	1,581	229	86%	13,672	2,479	82%	13,672	2,479	82%
Blue Water	70%	303	149	51%	3,118	703	77%	3,118	703	77%
Pere Marquette	85%	227	0	100%	1,805	53	97%	1,805	53	97%
Wolverine	70%	1,051	80	92%	8,749	1,723	80%	8,749	1,723	80%
Missouri	80%	202	0	100%	1,702	109	94%	1,702	109	94%
Pacific Surfliner	85%	6,059	2,381	61%	52,479	19,600	63%	52,479	19,600	63%
Pennsylvanian	80%	718	231	68%	5,547	1,095	80%	5,547	1,095	80%
Piedmont	80%	387	119	69%	5,975	707	88%	5,975	707	88%
Vermonter	75%	1,171	466	60%	8,719	3,032	65%	8,719	3,032	65%
Long Distance	***70%***	***10,797***	***6,028***	***44%***	***73,377***	***37,701***	***49%***	***73,377***	***37,701***	***49%***
Auto Train	70%	627	627	0%	4,055	2,822	30%	4,055	2,822	30%
California Zephyr	70%	1,024	415	59%	5,189	2,233	57%	5,189	2,233	57%
Cardinal	70%	0	0	-	1,785	1,306	27%	1,785	1,306	27%
City Of New Orleans	75%	708	412	42%	4,488	2,563	43%	4,488	2,563	43%
Coast Starlight	70%	1,048	533	49%	7,129	4,020	44%	7,129	4,020	44%
Crescent	70%	792	203	74%	5,884	850	86%	5,884	850	86%
Empire Builder	70%	568	487	14%	5,214	3,084	41%	5,214	3,084	41%
Floridian	60%	1,516	1,087	28%	9,207	6,424	30%	9,207	6,424	30%
Lake Shore Ltd	73%	921	672	27%	6,421	2,390	63%	6,421	2,390	63%
Palmetto	70%	770	54	93%	5,151	752	85%	5,151	752	85%
Silver Meteor	70%	774	77	90%	5,460	2,308	58%	5,460	2,308	58%
Southwest Chief	60%	998	788	21%	5,426	3,910	28%	5,426	3,910	28%
Sunset Ltd	70%	307	133	57%	1,691	821	51%	1,691	821	51%
Texas Eagle	70%	744	540	27%	6,277	4,218	33%	6,277	4,218	33%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00048 00000000050 "UNCLASSIFIED" 10/19/2026~~

Train Index Dates Through October 06, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	39,207	655,271	598	39,207	655,271	598

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	3,040	203,244	150	3,040	203,244	150
INFRASTRUCTURE PLANNED	135	4,739	203,244	233	4,739	203,244	233
FLEET RELIABILITY	90	5,364	655,271	82	5,364	655,271	82
TRAIN OPERATIONS	424	26,064	655,271	398	26,064	655,271	398

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

27-FOI-00048 Request Received 10/27/2026

Initial Terminal Performance By Division

Scheduled Departure Date: **10/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/06/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	328	40	87.8%	1,900	258	86.4%	1,900	258	86.4%
Central Division	86.0%	59	2	96.6%	346	13	96.2%	346	13	96.2%
East Division	82.0%	178	21	88.2%	1,022	152	85.1%	1,022	152	85.1%
West Division	86.0%	91	17	81.3%	532	93	82.5%	532	93	82.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/06/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	328	40	87.8%	1,900	258	86.4%	1,900	258	86.4%
Central Division	86.0%	59	2	96.6%	346	13	96.2%	346	13	96.2%
CDL	95.0%	1	0	100.0%	9	0	100.0%	9	0	100.0%
CHI	86.0%	28	1	96.4%	160	8	95.0%	160	8	95.0%
CHM	-	1	0	100.0%	2	0	100.0%	2	0	100.0%
FTW	92.5%	1	0	100.0%	6	0	100.0%	6	0	100.0%
GRR	95.5%	1	0	100.0%	6	0	100.0%	6	0	100.0%
KCY	92.0%	2	0	100.0%	12	0	100.0%	12	0	100.0%
MKE	92.0%	6	1	83.3%	35	1	97.1%	35	1	97.1%
MOE	97.5%	2	0	100.0%	12	0	100.0%	12	0	100.0%
MSP	96.5%	1	0	100.0%	6	0	100.0%	6	0	100.0%
NOL	94.5%	4	0	100.0%	26	1	96.2%	26	1	96.2%
OKC	97.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
PNT	88.0%	3	0	100.0%	18	0	100.0%	18	0	100.0%
PTH	93.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
QCY	91.0%	2	0	100.0%	12	1	91.7%	12	1	91.7%
SAS	90.5%	1	0	100.0%	6	1	83.3%	6	1	83.3%
STL	89.0%	4	0	100.0%	24	1	95.8%	24	1	95.8%
East Division	82.0%	178	21	88.2%	1,022	152	85.1%	1,022	152	85.1%
ALB	88.5%	8	3	62.5%	48	6	87.5%	48	6	87.5%
BON	87.5%	5	0	100.0%	30	2	93.3%	30	2	93.3%
BOS	85.5%	19	0	100.0%	112	4	96.4%	112	4	96.4%
BRK	92.5%	5	0	100.0%	30	2	93.3%	30	2	93.3%
BTN	82.0%	1	1	0.0%	6	1	83.3%	6	1	83.3%
CLT	91.5%	4	1	75.0%	27	4	85.2%	27	4	85.2%
GFD	88.0%	2	0	100.0%	12	2	83.3%	12	2	83.3%
GRO	-	1	0	100.0%	3	0	100.0%	3	0	100.0%
HAR	79.5%	13	1	92.3%	66	10	84.8%	66	10	84.8%
HFD	-	2	0	100.0%	8	0	100.0%	8	0	100.0%
LOR	84.0%	1	0	100.0%	6	3	50.0%	6	3	50.0%
MIA	89.5%	2	0	100.0%	12	2	83.3%	12	2	83.3%
MTR	79.0%	1	1	0.0%	6	3	50.0%	6	3	50.0%
NFK	84.5%	2	0	100.0%	12	3	75.0%	12	3	75.0%
NFL	93.5%	2	1	50.0%	12	3	75.0%	12	3	75.0%
NHV	78.0%	5	1	80.0%	29	8	72.4%	29	8	72.4%
NPN	93.0%	1	0	100.0%	11	1	90.9%	11	1	90.9%
NYP	75.5%	51	7	86.3%	285	58	79.6%	285	58	79.6%
PGH	93.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
PHL	48.0%	5	1	80.0%	28	13	53.6%	28	13	53.6%
RGH	95.0%	2	0	100.0%	18	1	94.4%	18	1	94.4%
RNK	83.5%	2	0	100.0%	12	1	91.7%	12	1	91.7%
SAB	98.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
SAV	96.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
SFA	88.0%	1	0	100.0%	6	2	66.7%	6	2	66.7%
SPG	92.5%	5	1	80.0%	33	4	87.9%	33	4	87.9%

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/06/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/06/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	328	40	87.8%	1,900	258	86.4%	1,900	258	86.4%
East Division	82.0%	178	21	88.2%	1,022	152	85.1%	1,022	152	85.1%
TWO	73.0%	1	0	100.0%	6	1	83.3%	6	1	83.3%
WAS	84.0%	34	3	91.2%	186	18	90.3%	186	18	90.3%
West Division	86.0%	91	17	81.3%	532	93	82.5%	532	93	82.5%
ARN	92.0%	1	0	100.0%	6	0	100.0%	6	0	100.0%
BFD	79.0%	7	1	85.7%	42	10	76.2%	42	10	76.2%
EMY	72.0%	1	1	0.0%	5	3	40.0%	5	3	40.0%
EUG	86.5%	2	0	100.0%	11	0	100.0%	11	0	100.0%
GTA	90.0%	3	1	66.7%	18	6	66.7%	18	6	66.7%
LAX	89.5%	10	0	100.0%	62	6	90.3%	62	6	90.3%
OKJ	74.5%	13	5	61.5%	70	20	71.4%	70	20	71.4%
PDX	86.0%	5	0	100.0%	30	2	93.3%	30	2	93.3%
SAC	88.5%	16	6	62.5%	88	14	84.1%	88	14	84.1%
SAN	90.5%	13	1	92.3%	76	12	84.2%	76	12	84.2%
SEA	85.0%	8	1	87.5%	47	7	85.1%	47	7	85.1%
SJC	89.0%	7	1	85.7%	42	12	71.4%	42	12	71.4%
SLO	90.0%	3	0	100.0%	18	1	94.4%	18	1	94.4%
SPK	90.0%	-	-	-	5	0	100.0%	5	0	100.0%
VAC	97.0%	2	0	100.0%	12	0	100.0%	12	0	100.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		2	0	100.0%	2	0	100.0%	3	1	66.7%	3	1	66.7%
3		6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
4	109	6	0	100.0%	6	0	100.0%	6	5	16.7%	6	5	16.7%
5		5	0	100.0%	5	0	100.0%	6	3	50.0%	6	3	50.0%
6	48	5	3	40.0%	5	3	40.0%	5	3	40.0%	5	3	40.0%
8	150	5	2	60.0%	5	2	60.0%	5	4	20.0%	5	4	20.0%
11		6	1	83.3%	6	1	83.3%	6	4	33.3%	6	4	33.3%
14	126	6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
19		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
20		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
21	20	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
22	67	6	1	83.3%	6	1	83.3%	6	5	16.7%	6	5	16.7%
23	40	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
24	32	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
25		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
26		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
28		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
40	111	6	1	83.3%	6	1	83.3%	6	6	0.0%	6	6	0.0%
41	140	6	2	66.7%	6	2	66.7%	6	3	50.0%	6	3	50.0%
42	18	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
43		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
48	36	6	2	66.7%	6	2	66.7%	6	3	50.0%	6	3	50.0%
49	41	6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
52	36	6	2	66.7%	6	2	66.7%	6	3	50.0%	6	3	50.0%
53	99	6	3	50.0%	6	3	50.0%	6	5	16.7%	6	5	16.7%
55		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
56		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
58	43	6	0	100.0%	6	0	100.0%	6	5	16.7%	6	5	16.7%
59		6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
63	41	6	5	16.7%	6	5	16.7%	6	6	0.0%	6	6	0.0%
64	25	6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
66		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
67	70	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
68		6	3	50.0%	6	3	50.0%	6	1	83.3%	6	1	83.3%
69		6	3	50.0%	6	3	50.0%	6	1	83.3%	6	1	83.3%
71		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
72		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
75		6	0	100.0%	6	0	100.0%	5	0	100.0%	5	0	100.0%
76		6	1	83.3%	6	1	83.3%	5	1	80.0%	5	1	80.0%
77	35	6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
78	82	6	2	66.7%	6	2	66.7%	6	2	66.7%	6	2	66.7%
79		6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%

Amtrak On Time Performance

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
84		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
85		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
86		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
89	17	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
90		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
93	18	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
94		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
95		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
97		6	3	50.0%	6	3	50.0%	6	1	83.3%	6	1	83.3%
98		6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
110		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
111		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
112		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
113		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
119		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
125		4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
129		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
130		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
131	37	4	1	75.0%	4	1	75.0%	4	4	0.0%	4	4	0.0%
134		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
136		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
137		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
138		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
141		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
148		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
151		6	5	16.7%	6	5	16.7%	6	2	66.7%	6	2	66.7%
170	33	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
171	67	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
172		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
173	20	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
174		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
175	52	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
176		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
177	25	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
178	33	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
179		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
181		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
182		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
183		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
184		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
185		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%

Amtrak On Time Performance

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
186		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
190		4	3	25.0%	4	3	25.0%	4	0	100.0%	4	0	100.0%
192	74	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
193	32	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
196		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
197	30	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
198	59	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
230		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
232		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
233	30	6	2	66.7%	6	2	66.7%	6	4	33.3%	6	4	33.3%
234		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
235	19	6	1	83.3%	6	1	83.3%	6	4	33.3%	6	4	33.3%
236	17	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
237		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
238		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
239		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
240	62	6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
241		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
243		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
244	23	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
245		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
280	54	6	3	50.0%	6	3	50.0%	6	3	50.0%	6	3	50.0%
281		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
283		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
284		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
290		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
291	40	6	5	16.7%	6	5	16.7%	6	2	66.7%	6	2	66.7%
300		6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
301		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
302		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
305	30	6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
306	23	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
307		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
311		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
316		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
318		6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
319		6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
329		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
330	28	5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
331	28	6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
332		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
334		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
336		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
337		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
338	16	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
339		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
341		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
342		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
350	20	6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
351		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
352		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
353		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
354		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
355		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
364		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
365	33	6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
370		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
371		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
380		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
381		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
382		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
383	41	6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
390		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
391		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
392	28	6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
393	32	5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
417		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
425		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
448	49	6	4	33.3%	6	4	33.3%	6	2	66.7%	6	2	66.7%
449		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
470		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
471		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
473		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
474		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
475		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
478		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
479	17	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
486		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
494		5	2	60.0%	5	2	60.0%	4	1	75.0%	4	1	75.0%
495		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
500		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
502		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
503	17	6	2	66.7%	6	2	66.7%	6	4	33.3%	6	4	33.3%

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504	84	6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
505		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
506	18	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
507		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
508	16	6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
509		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
511		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
516	82	6	2	66.7%	6	2	66.7%	6	4	33.3%	6	4	33.3%
517		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
518		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
519		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
520		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
521		4	1	75.0%	4	1	75.0%	3	0	100.0%	3	0	100.0%
522		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
523		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
524		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
525	Cncld	4	2	50.0%	4	2	50.0%	3	1	66.7%	3	1	66.7%
526	Cncld	4	2	50.0%	4	2	50.0%	3	0	100.0%	3	0	100.0%
527		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
528		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
529		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
530		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
531		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
532		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
534		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
535		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
536		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
537		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
538		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
539	47	4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
540		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
541		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
542		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
543	46	4	1	75.0%	4	1	75.0%	4	4	0.0%	4	4	0.0%
544		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
545		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
547		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
548		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
549		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
550		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
551		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
562		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%

Amtrak On Time Performance

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564	23	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
566		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
567	19	6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
572		6	2	66.7%	6	2	66.7%	6	3	50.0%	6	3	50.0%
573		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
579	38	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
580		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
581		6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
584	34	6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
587	30	6	2	66.7%	6	2	66.7%	5	2	60.0%	5	2	60.0%
588		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
591		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
593		6	3	50.0%	6	3	50.0%	5	0	100.0%	5	0	100.0%
595		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
600	35	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
601		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
605		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
607		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
609		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
622	16	3	2	33.3%	3	2	33.3%	3	1	66.7%	3	1	66.7%
626		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
639		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
640	18	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
641		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
642		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
643	19	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
644		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
645		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
646		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
647		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
648		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
649		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
650		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
651		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
652		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
653		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
654		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
655		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
656		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
657		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
658		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
680		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681	17	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
682		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
683	19	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
684	23	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
685	29	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
686		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
687		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
688		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
689		1	0	100.0%	1	0	100.0%	2	0	100.0%	2	0	100.0%
701		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
702	46	6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
703		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
704		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
710		6	2	66.7%	6	2	66.7%	6	0	100.0%	6	0	100.0%
711	Cncld	6	1	83.3%	6	1	83.3%	4	0	100.0%	4	0	100.0%
712		6	3	50.0%	6	3	50.0%	6	3	50.0%	6	3	50.0%
713		6	3	50.0%	6	3	50.0%	6	1	83.3%	6	1	83.3%
714	103	6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
715	29	6	2	66.7%	6	2	66.7%	6	2	66.7%	6	2	66.7%
716		6	4	33.3%	6	4	33.3%	6	2	66.7%	6	2	66.7%
717	16	6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
718		6	4	33.3%	6	4	33.3%	6	1	83.3%	6	1	83.3%
719		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
757	18	6	0	100.0%	6	0	100.0%	6	3	50.0%	6	3	50.0%
761		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
765		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
769		6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
770		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
774	18	6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
777		6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
782	41	6	6	0.0%	6	6	0.0%	6	4	33.3%	6	4	33.3%
785		6	1	83.3%	6	1	83.3%	6	2	66.7%	6	2	66.7%
786		6	0	100.0%	6	0	100.0%	5	2	60.0%	5	2	60.0%
790		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
794	46	6	1	83.3%	6	1	83.3%	6	4	33.3%	6	4	33.3%
821		6	0	100.0%	6	0	100.0%	6	5	16.7%	6	5	16.7%
822	29	6	0	100.0%	6	0	100.0%	6	6	0.0%	6	6	0.0%
1333		6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
1340		6	0	100.0%	6	0	100.0%	6	1	83.3%	6	1	83.3%
2102		4	0	100.0%	4	0	100.0%	3	1	66.7%	3	1	66.7%
2103		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2104		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/6/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2105		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2107		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
2108		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2109		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
2112		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2113		4	2	50.0%	4	2	50.0%	3	1	66.7%	3	1	66.7%
2115		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2116		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2118		4	2	50.0%	4	2	50.0%	3	1	66.7%	3	1	66.7%
2119		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
2120		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
2123	18	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
2124		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2126		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2127	18	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
2128		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2131		4	2	50.0%	4	2	50.0%	2	0	100.0%	2	0	100.0%
2150		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2151		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
2152		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2154	18	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
2155		4	0	100.0%	4	0	100.0%	3	1	66.7%	3	1	66.7%
2156	26	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
2158		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2159	32	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
2160		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2162		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
2163	28	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
2165	25	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
2167		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2171		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2190		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2193		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2123	WAS	18	DSR	11	DSR	11	NWK-XCY	AM	Per MW foreman, Other, LINCOLN INT LIMIT, 10, 3, IMPOSED 10MPH S/R ON NO.3 TRK FOR TRACK DEFECT
2127	WAS	18	CAR	9	CAR	9	BWI-BWI	AM	Door, entire train, door problems
2154	BOS	18	CTP	19	CTP	19	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION AHEAD IN THE SOUTH TUBE A/C DUE TO NJ3234 HIT A BENCH WALL IN THE SOUTH TUBE
2156	BOS	26	SMW	18	SMW	15	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING ON NO.2 TRK LEGGETT TO PELHAM BAY A/C 1 TRK OOS MANOR TO LEGGETT
2159	WAS	32	DMW	24	DMW	24	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2163	WAS	28	DMW	20	DMW	20	NHV-STM	MN	Waiting for MW clearance Milepost, 36.0, 34.8
2165	WAS	25	OTH	23	DMW	20	NHV-STM	MN	Waiting for MW clearance Milepost, 36, 34.8
67	NPN	70	DCS	110	DCS	61	ALX-QAN	CS	Restrictive signal(s) from known wayside signal failure Permission passed the stop signal. Also, checking switch points before the Newington Defect detector all while at restricted speed from Beltway to Pohick., Stop signal , Control Point, Beltway
93	NFK	18	CTI	40	CTI	15	BRP-STM	MN	Follow metro north, Control Point, 252
131	WAS	37	ENG	34	ENG	34	NBK-NBK	AM	Air / Brake, 661|EX|ES, LOSS OF AIR ON NO.4 TRACK AT NEW BRUNSWICK
170	BOS	33	DCS	25	DCS	25	XGX-KIN	AM	Power switch failure, Other, liberty, spike and clamp 21sw at liberty
171	RNK	67	DCS	41	DCS	41	MSS-CLP	NS	Power switch failure Control Point, s manassas
173	WAS	20	DSR	22	RTE	11	XNY-WAS	AM	Routed to abnormal station track due to N.A.R., 12, Control Point, K-INTERLOCKING, ROUTED TO 12TRK ON TOP OF MK9448 NEC'Y TO REVERSE EQUIPMENT AND REROUTE TO CLEAR TRK
175	WAS	52	CTI	36	CTI	27	NHV-STM	MN	Follow Metro North, Other, NHV-STM
177	PHL	25	CTI	18	CON	16	NHV-NHV	MN	Hold for connecting train 417

Amtrak Endpoint OTP Details

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
178	BOS	33	SMW	23	SYS	15	NHV-NLC	AM	Unscheduled passenger stop, due to the delayed caused by the 21sw failure ar Guilford CD1652 was cancelled, AM178 made CDOT stops instead
192	NYP	74	SVS	72	SVS	72	WAS-WAS	AM	Planned set out / pick out of locomotives, cars or section of train, LATE REPLACING SHOP MTR DUE TO MISCOMMUNICATION BETWEEN CONTROL CENTER AND K-TOWER.
193	WAS	32	CTI	25	CTI	11	BWI-NCR	AM	Follow, MARC, 455, Milepost, 112.4, 127
197	WAS	30	OTH	16	PTI	12	BAL-XNY	AM	Follow, 193, Milepost, 112.4, 134.6
198	NYP	59	POL	28	POL	28	WAS-WAS	AM	Suspicious bag or bomb threat, LATE WYING EQUIPMENT DUE TO WAITING ON POLICE TO REMOVE UNATTENDED BAG
479	NHV	17	SMW	11	SMW	11	SPG-WNL	AM	Diversions around M/W work, Milepost, SPG, WNL, SHOVE OUT CSX, CHANGE ENDS AT SWEENEY AND BRAKE TEST.
52	LOR	36	FTI	70	FTI	67	XOU-XFL	CS	Follow csx410, Control Point, charleston
53	SFA	99	TSV	65	TSV	63	LOR-LOR	CS	Drumac did not have enough drivers
600	NYP	35	SVS	30	SVS	30	PHL-XHM	AM	Unplanned Wye, Wye'd on the outbound.
622	PHL	16	ENG	13	ENG	13	HAR-HAR	AM	Other electrical failure, 615|EX|ES, mech recycled engine after stop signal penalty
640	NYP	18	CTI	19	CTI	11	NWK-NYP	AM	Follow, NJT, NJ3224, Other, NWK-NYP
643	HAR	19	DCS	23	DCS	13	PHL-PAO	AM	Power switch failure, Control Point, Bryn Mawr, 4w sw fails to normal.
681	BRK	17	DMW	10	SVS	8	POR-POR	CS	Fuel
683	BRK	19	PTI	11	PTI	11	EXR-DHM	CS	Meet 683, Control Point, rockingham
684	BON	23	DCS	13	DCS	13	HHL-WOB	MT	Power switch failure Control Point, FR
685	BRK	29	PTI	14	PTI	12	ORB-POR	CS	Meet 688, Control Point, mountain
63	TWO	41	FTI	11	FTI	9	ROC-BUF	CS	Follow csx, Milepost, 400, 425
64	NYP	25	CTI	37	CTI	17	RHI-XCP	MN	Blocked from station track Stop signal at CP75. Waited for MN 857 and 863 to go into POU first., Metro North, 857, Metro North, 863, Control Point, 75
233	ALB	30	ENG	15	ENG	15	POU-XCP	MN	HEP 708
235	ALB	19	SYS	14	SYS	6	CRT-POU	MN	PTC problem or failure (cause unknown) Acses fault, Milepost, 33.3, 73.6

Amtrak Endpoint OTP Details

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
236	NYP	17	PTI	7	PTI	7	YNY-XSD	AM	Meet 281, Control Point, CP 12
240	NYP	62	ENG	55	ENG	55	ALB-ALB	AM	Delayed delivery of equipment from Mechanical (not due to mechanical failure) 9701
244	NYP	23	CTI	22	CTI	15	POU-CRT	MN	Follow We followed 48 witch followed 890, metro, 880, Milepost, 72, 39
280	NYP	54	SYS	23	SYS	23	NFL-NFL	CS	Swapping ends Running a push-pull set. Had to swap ends, perform class II brake test and running brake test 3 times. Once on the yard, once on the siding and once before departure from NFL.
291	BTN	40	ITI	53	ITI	53	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240
48	NYP	36	FTI	88	ITI	40	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 40, Swapped equipment
49	CHI	41	PTI	90	PTI	54	ELY-SKY	NS	Follow Amtk40, Control Point, 242
448	BOS	39	PTI	45	PTI	45	XRD-PIT	CS	Meet 448, Control Point, 171
42	NYP	18	DSR	29	CTI	12	NWK-NYP	AM	Follow, NJT, NJ3858, Other, NWK-NYP
77	CLT	35	DSR	22	FTI	16	GRO-GRO	NS	Cross over or go around NS 204, Milepost, 0.0, 0.0
78	RGH	82	ITI	94	ITI	94	CLT-CLT	NS	Late departure at initial terminal due to late arrival of inbound equipment 77
89	SAV	17	FTI	45	FTI	23	CHS-YEM	CS	Meet M 410, Control Point, A 388.4
40	CHI	111	FTI	104	DBS	39	ELY-SKY	NS	Debris blocking track (no debris strike) Held at CP 216, waiting for track to open … coal on tracks ahead .., Control Point, 219
41	MIA	140	FTI	130	FTI	45	COV-CUM	CS	Train is disabled and tying up a single track. M225/04, Control Point, Sandpatch
23	NOL	40	FTI	49	FTI	36	MOE-PAG	CS	Meet Take Siding, 606-06, Siding, Brookley
24	MOE	32	FTI	52	FTI	40	XNO-BAS	CS	Meet 5121, Control Point, 780
6	CHI	48	FTI	107	FTI	41	COX-COX	UP	Cross over or go around Up freight stalled on track 2 east of cox we waited for 5 the used the hand throws to cross over and go around, Control Point, w cox, up, up
525	OKJ	Trn Cancelled	TEN	57	TEN	57	SAC-SAC	UP	Other electrical failure Headlights bad ordered. Wyed the train at Haggin., JPBX921

Amtrak Endpoint OTP Details

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
526	SAC	Trn Cancelled							
539	SJC	47	ITI	20	ITI	20	SAC-SAC	UP	Late departure at initial terminal due to late arrival of inbound equipment 539, Wait for 528 arrival.
543	SJC	46	PTI	27	MBO	26	SUI-MTZ	UP	For maritime traffic Bridge, suisun bay
503	EUG	17	FTI	28	FTI	10	PDX-ORC	UP	Follow Manifest, Milepost, 761, 748, UP 6663
504	SEA	84	POL	73	POL	73	VAN-KEL	BN	Right of Way police hold Held at kelso south due to trs north of kelso
506	SEA	18	PTI	19	PTI	12	XNI-TAC	ST	Meet amtrak 511, Control Point, manitou
508	SEA	16	FTI	20	FTI	15	VAN-KEL	BN	Meet 6621, Control Point, richfield south
516	VAC	82	CCR	43	CCR	43	SEA-SEA	BN	Electrical failure 90230, Drop WDTX 1400 due to B/O MU receptacles on front on AMTK 90230. Later found bottled air when trying to pull out of the yard.
58	CHI	43	DSR	99	PTI	18	XSU-HMD	CC	Meet amtrak 59, Siding, N Manchac
14	SEA	126	ITI	69	ITI	69	LAX-LAX	SC	Late departure at initial terminal due to late arrival of inbound equipment 11, Departed at 11:00 as instructed, due to the service disruption text which was set to the pax.
8	CHI	150	FTI	138	SVS	99	SEA-SEA	BN	Routine inspections
822	OKC	29	DSR	57	DSR	37	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, m1, Milepost, 353.7, 354.1, 60, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 369, 370.2, 60, m, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.6, 376.8, 60, m, Milepost, 376.9, 377.1, 25, m, Milepost, 377.5, 378.9, 60, m, Milepost, 3
330	CHI	28	CTI	32	CTI	16	XRO-GLN	ME	Follow Metra, 2118, Milepost, 32.3, 17.4
331	MKE	28	ITI	22	ITI	22	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 330, 8:35 arrived 8:42 all passengers disembarked, only able to utilize two exit doors being car #4204 door is locked out due to mechanical issues. Boarded passengers and class II brake test 8:47 departed after talking wit
338	CHI	16	CTI	29	CTI	28	GLN-XWA	ME	Follow METRA, 2140, Control Point, MORTON GROVE
350	PNT	20	PTI	34	PTI	21	XB0-XA5	MI	Meet Amtrak Wolverine 353, Control Point, CP96

Amtrak Endpoint OTP Details

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	33	MBO	25	MBO	25	XH6-XTF	NS	Repairs Milepost, 508, 509
564	SAN	23	CTI	35	DSR	10	XRJ-FUL	BN	Per bulletin Milepost, 1494, 1495, 10, 2
567	LAX	19	DCS	20	DCS	10	FUL-XRJ	BN	PTC- Planned PTC system maintenance Milepost, 156, 150
579	LAX	38	CTI	24	ENG	21	OLT-SOL	SN	Failure of diesel engine C2110
584	SAN	34	PTI	28	PTI	17	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	30	DSR	17	PTI	12	OSD-X98	SN	Meet 782, Control Point, Songs
757	SLO	18	PTI	29	PTI	29	GTA-X3G	UP	Meet DS held us for late 774 even after we called and asked if we could have a better meet since 774 was late., 774, Siding, Elwood
774	SAN	18	DCS	35	CTI	8	CWT-VNC	SC	Meet 115 is flagging by the red signal into the siding., ml, 115, Control Point, de soto
782	SAN	41	CTI	37	PTI	14	GTA-SBA	UP	Wait for station track Waiting for train 14 to complete station work at Santa Barbara station before entering station per Rule 6.30., 14, Other, Santa Barbara station
794	SAN	46	PTI	71	PTI	25	SLO-GVB	UP	Meet 14, Control Point, CO251
702	BFD	46	PTI	23	PTI	17	MOD-TRK	BN	Meet AMT 711, Control Point, EE EMPIRE
711	OKJ	Trn Cancelled	FTI	31	FTI	21	MCD-TRK	BN	Meet Nothing at Ballico, BNSF 7339, Control Point, W. Fluhr
714	BFD	103	PTI	48	ITI	45	OKJ-OKJ	UP	Late departure at initial terminal due to late arrival of inbound equipment 711
715	OKJ	29	FTI	27	FTI	10	BFD-WAC	BN	Meet BNSF 6776, Control Point, una xover
717	OKJ	16	PTI	26	PTI	11	COC-HNF	BN	Meet 712, Siding, Guernsey
4	CHI	109	FTI	139	FTI	39	FLG-WLO	BN	Cross Traffic BNSF, Milepost, 340.8, 288.4
21	SAS	20	FTI	154	FTI	62	ARK-HOP	UP	Blocked from station track up 5471, Other, emmet
22	CHI	67	DSR	113	DSR	40	TPL-MCG	BN	Per bulletin Milepost, 220.4, 221.0, 25, Main, Milepost, 222.1, 222.4, 25, Main, Milepost, 225.0, 229.3, 25, Main, Milepost, 228.3, 230.6, 15, Main, Milepost, 232.5, 232.7, 60, Main, Milepost, 233.4, 235.2, 25, Main, Milepost, 236.0, 238.5, 30, Main, Milepost, 237.8, 239.5, 15, Main
305	STL	30	PTI	45	PTI	39	BNL-LCN	UP	Meet 306, Siding, McLean
306	CHI	23	FTI	38	FTI	22	SMT-XTF	CC	Cross Traffic UNKNOWN, Control Point, CORWITH

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
383	QCY	41	DCS	32	DCS	28	NPV-PLO	BN	Power switch failure Throw switch at Eola 3a, Control Point, Eola
392	CHI	28	DSR	43	FTI	18	EFG-MAT	CC	Meet M399 / UP4680, Control Point, north neoga
393	CDL	32	DSR	29	PTI	21	CHM-MAT	CC	Meet AM 392, Control Point, S Tuscola

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/6/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	238	10/06	10	10	Engine issues 706
ALB	240	10/06	55	55	Delayed delivery of equipment from Mechanical (not due to mechanical failure) 9701
ALB	448	10/05	19	10	Await arrival of split train equipment
ALB	448	10/05	19	9	Planned set out / pick out of locomotives, cars or section of train Control Point, 142
BTN	290	10/06	4	4	Late bulletins due to Amtrak cause Amtrak neglected to include empire “empire” email in email change over!
CLT	78	10/06	18	18	Late departure at initial terminal due to late arrival of inbound equipment 77
HAR	622	10/06	13	13	Other electrical failure, 615|EX|ES, mech recycled engine after stop signal penalty
MTR	68	10/06	1		
NFL	280	10/06	38	15	PTC - Initializing PTC (no failure) Had to enter PTC manually.
NFL	280	10/06	38	23	Swapping ends Running a push-pull set. Had to swap ends, perform class II brake test and running brake test 3 times. Once on the yard, once on the siding and once before departure from NFL.
NHV	474	10/06	3	3	Wheelchair, 1 PSGR (WHEELCHAIR), 1 PSGR (VISION IMPAIRED), (38/ON-0/OFF)
NYP	63	10/06	3	3	Late departure at initial terminal due to late arrival of inbound equipment, 230, HELD FOR AM230 TO ARRIVE.
NYP	69	10/06	16	16	Undesired emergency application, 105|DX|BD, ENGINE ISSUES
NYP	97	10/06	5	5	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C IT WAS NECCESSARY TO WAIT FOR AM98 FOR SLEEPERS TO COMPLETE CONSIST
NYP	183	10/06	10	10	Routine inspections, RELEASED LATE BY MECHANICAL FROM SSYD
NYP	233	10/06	6	6	Passenger and/or baggage, LOADING AT DEPARTURE TIME
NYP	291	10/06	53	53	Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240
NYP	2123	10/06	10	10	Other electrical failure, 2010|LH|LP, MECHANCIAL ISSUES WITH REAR POWER CAR
PHL	190	10/06	3	3	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE OUT OF THE YARD
SPG	125	10/06	4	4	Hold for connecting train, Late arrival
WAS	136	10/06	3	3	Late departure at initial terminal due to late arrival of inbound equipment, 131
WAS	170	10/06	3	3	Injured or sick passenger, PSGR SICK ON TRAIN
WAS	192	10/06	72	72	Planned set out / pick out of locomotives, cars or section of train, LATE REPLACING SHOP MTR DUE TO MISCOMMUNICATION BETWEEN CONTROL CENTER AND K-TOWER.

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/6/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	331	10/06	22	22	Late departure at initial terminal due to late arrival of inbound equipment 330, 8:35 arrived 8:42 all passengers disembarked, only able to utilize two exit doors being car #4204 door is locked out due to mechanical issues. Boarded passengers and class II brake test 8:47 departed after talking wit
MKE	332	10/06	11	11	Late departure at initial terminal due to late arrival of inbound equipment 329
BFD	717	10/06	4	4	Water, commissary, toilet/trash dumping
EMY	6	10/06	4	4	Meet 527, Control Point, East Emeryville
GTA	782	10/06	3	3	Wait for station track 765, Control Point, CO 358
OKJ	522	10/06	1	1	Loading problem C2014
OKJ	526	10/06	(Trn Cxld)		Third Party Engine Failure
OKJ	714	10/06	45	45	Late departure at initial terminal due to late arrival of inbound equipment 711
OKJ	716	10/06	5	5	Dispatcher 62 had us hold in depot for 539 causing delay 539, Other, OKJ Depot
OKJ	718	10/06	(Trn Cxld)		Third Party Cab Car Failure
SAC	521	10/06	6	6	First equipment assigned had NO headlights. Had to change equipment.
SAC	523	10/06	4	4	Switch equipment in SAC Set over 6E to 5W Fuel 2006
SAC	525	10/06	57	57	Other electrical failure Headlights bad ordered. Wyed the train at Haggin., JPBX921
SAC	539	10/06	20	20	Late departure at initial terminal due to late arrival of inbound equipment 539, Wait for 528 arrival.
SAC	543	10/06	1	1	Loading problem C2004
SAC	547	10/06	6	6	Air / Brake / Wheel C8018, Air leak coming from car, Sacramento mechanical able to fix issue
SAN	593	10/06	5	5	Individual needing possible medical assistance fouling the track. Other, SANTA FE DEPOT
SEA	516	10/06	61	6	Dispatcher hold Other, SEA Yard
SEA	516	10/06	61	12	Meet BNSF 5586, Control Point, South Portal
SEA	516	10/06	61	43	Electrical failure 90230, Drop WDTX 1400 due to B/O MU receptacles on front on AMTK 90230. Later found bottled air when trying to pull out of the yard.
SJC	542	10/06	6	6	Meet CAL Train, 000, Control Point, ALAMEDA

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.4	94.8	342	0
CDOT	95.0	91.7	81.7	92.4	24	2
MARC	95.0	96.6	82.8	90.2	58	2
SEPTA	95.0	95.2	89.9	91.5	230	11
NJT-NED	95.0	92.7	87.6	88.6	357	26
NJT-SED	95.0	100.0	98.6	97.2	24	0

Operating Highlights

Train 49(06) - West of Rochester, NY - Freight Train Interference

07OCT26: Train 49(06) was delayed on the CSX Rochester and Buffalo Terminal Subdivisions beginning at MP 307 due to meeting a CSX High and Wide Train S111-05.

Train	Delay	Comment
49(06)	31"	

Train 171(06) - South of Manassas, VA - Switch Failure

06OCT26: Train 171(06) was delayed on the Norfolk Southern Washington District Line at MP 35.7 due to power switch failure at CP Manassas.

Train	Delay	Comment
171(06)	41"	

Train 192(06) - Washington, DC - Initial Terminal Delay

06OCT26: Train 192(06) was delayed at its initial terminal at Washington Union Terminal due to E/609 being shopped late and replaced with E/616. The engine swap was prolonged due to traffic in and out of the terminal.

Train	Delay	Comment
192(06)	1'12"	

Train 40(05) North of Richmond, VA - Injured or Sick Passenger or Employee

06OCT26: Train 40(05) with E/324, E/320 and 10 cars was delayed on the CSX RF&P subdivision at MP 44.7 due to sick customer requiring EMS assistance.

Train	Delay	Comment
40(05)	43"	

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Train 131(06) South of New Brunswick, NJ - Engine Failure

06OCT26: Train 131(06) with E/661, E/609 and 10 cars was delayed on the New York to Philadelphia main line at MP 31.3 due to an air leak. The engineer cleared the faults on E/609 and after preforming a brake test they were able to proceed south.

Train	Delay	Comment
131(06)	34"	

Train 240(06) - Cab Car Failure

06OCT26: Train 240(06) with E/714, CC/9701 and 5 cars was delayed departing Albany due to having mechanical problems with CC/9701 in the yard. This also caused train 291(06) to be delayed departing New York due to the late turn off 240(06)

Train	Delay	Comment
240(06)	55"	
291(06)	53"	

Train 67(05) South of Alexandria, VA - Signal

06OCT26: Train 67(05), with E/379, E/10, and 5 cars, encountered restrictive signals due to a known wayside signal failure on the CSX Peninsula Subdivision, including a Stop signal at CP Beltway. The crew received permission to pass the Stop signal and checked switch points before reaching the Newington Defect Detector. The train operated at Restricted Speed from Beltway to Pohick.

Train	Delay	Comment
67(05)	1'01"	

Train 600(06) Philadelphia, PA - Engine Failure

06OCT26: Train 600(06) with E/648, CC/9649 and 4 cars was delayed after departing Philadelphia due to wying the equipment caused by E/648 having cab signal issues.

Train	Delay	Comment
600(06)	30"	

Train 97(05) South of Savannah, GA - Freight Train Interference

06OCT26: Train 97(05) with E/369, E/330 and 10 cars was delayed on the CSX Savannah A subdivision at MP A494.3 due to meeting CSX M494-06.

Train	Delay	Comment
97(05)	36"	

27-FOI-00046 0000008953 "UNCLASSIFIED" 10/19/2026

Train 19(05) North of Atlanta, GA - Trespasser Incident

06OCT26: At 805A-ET, Train 19(05) with E/340, E/336, 8 cars, and 128 customers, struck a flatbed truck carrying a forklift at the Amwiler Road crossing, DOT 717880R, in DeKalb County equipped with 2 crossbucks and gate arms, MP 620.97 on the NS Greenville-Iman District, 13 miles north of Atlanta, GA. No injuries were reported to customers, crew, or the driver of the vehicle. The crew reported the forklift was knocked off the flatbed. The train has HEP, and the crew is inspecting the consist. Local authorities are responding to the scene. The conductor reported that the scene was released as of 923A-ET and they were able to proceed north.

National Response Center Number: 1475444

Train	Delay	Comment
19(05)	1'10"	

Train 280(06) - Niagara Falls, NY - Engine Failure

06OCT26: Train 280(06) was delayed at its initial terminal at Niagara Falls, NY due to issues with PTC. The crew consulted the host railroad for assistance.

Train	Delay	Comment
280(06)	38"	

Train 125(05) - Williamsburg, VA - Engine Failure

05OCT26: Train 125(05) stopped at MP 39.3 on the CSX Peninsula Subdivision due to a hydrostatic oil leak and smokey conditions in the engine compartment. The engine shut down. HEP was dropped immediately. Amtrak Mechanical personnel and field management responded to the scene.
The train was terminated at its location. The host railroad sent CSXT 7084 to be used as a rescue motor. Once coupled to the disabled set, the set was pulled into Newport News with no HEP.
Service recovery was initiated with complimentary snacks and beverages.
Due to the status of Engine 371, Train 86(06) was cancelled NPN-WAS. No alternate transportation was provided.

A extra bus was order for Richmond to Washington customers due to high customer counts.

WBS#: B.TR.100150.7246

Train	Delay	Comment
86(06)	Orig WAS	
125(05)	4'18"	

Maintenance of Way Highlights

27-FOU00046 00000098853 "UNCLASSIFIED" 10/19/2026

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None				RNK	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
643 (29)	LNC	1	MJY	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train59(04) Passenger Removal at McComb, Mississippi – Improper Conduct

05OCT26, Passenger on PNR 2B75CC traveling from Champaign IL to New Orleans, LA was removed by local Police due to being rude and disrespectful towards crew and passenger on board. Amtrak Police notified.

Delay: 59(04) NONE 02"

Western Region
Operating Highlights

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Train 7/27(05) West of Whitefish, MT - Freight Train Interference

06OCT26: Train 7/27(05) with 216 customers was delayed on the BNSF Kootenai River subdivision starting 25 miles west of Whitefish due to meeting ZPTLCHC4-06 at Radnor/MP 1244.3 and ZSSECHC2-06 at Twin Meadows/MP 1264.5.

Train	Delay	Comment
7/27(05)	33"	Radnor
7/27(05)	25"	Twin Meadows

Train 3(05) West of Winslow, AZ - Freight Train Interference

06OCT26: Train 3(05) with 206 customers was delayed on the BNSF Seligman subdivision starting 15 miles west of Winslow due to meeting BN 7818 at Dennison/MP 300.3 and an unknown freight at East Darling/MP 326.8.

Train	Delay	Comment
3(05)	35"	

Train 354(06) East of Ann Arbor, MI - Engine Failure

06OCT26: Train 354(06), with engine IDTX4629, 5 cars, and 53 customers onboard, stopped at mile post 34.3, 3 miles east of Ann Arbor, MI/MP37.5, on the Michigan Department of Transportation Michigan Line subdivision due to the engine shutting down. HEP was down. The crew was able to restart the engine, but it shut down immediately upon attempting to move. The crew contacted CNOC Mechanical Desk and reported a low hydrostatic oil fault. Engine IDTX4629 would not restart. Due to the failed engine, train 354(06) was terminated at Ann Arbor, MI. One bus was secured and staged at Ann Arbor. Two Road Foremen and Mechanical personnel from Pontiac, MI responded. Pontiac Mechanical was able to restart the engine by adding additional hydrostatic oil. The equipment shoved back to Ann Arbor Station and the customers boarded the bus to parts east.

The equipment was approved by Pontiac Mechanical to operate deadhead to Pontiac. The equipment was coupled to train 353(07) to operate as a double draft back to Chicago.

Train 351(07) was cancelled in its entirety with four buses secured.

Train	Delay	Comment
354(06)	Terminated	ARB
351(07)	Cancelled	

Train 355(06) West of Kalamazoo, MI - Animal Strike

06OCT26: Train 355(06), with engine IDTX4604, 5 cars, and 135 customers onboard, struck a deer at mile post 154.3, 11 miles west of Kalamazoo, MI/MP143.4, on the Amtrak Michigan Line subdivision. Engine IDTX4604 shut down after impact, dropping HEP. The crew worked with CNOC Mechanical Desk to restart the engine and restore HEP. Once the crew completed a brake test, train 355(06) continued west. Due to PTC issues, the train proceeded at a maximum of 59MPH to mile post 160.8 before engaging PTC.

Train	Delay	Comment
355(06)	29"	

27-FOI-00046 000000008953 UNCLASSIFIED 10/19/2026

Train 718(06) Oakland, CA - Third Party Contractor Cab Car Failure

06OCT26: Train 718(06) with C/90278 as second consist and C/2124 originated at Emeryville due to C/90278 with a cracked windshield on the engineer side and capped with C/2013. It was necessary to wye C/2013 before it was added. All customers were accommodated on train 544(06) between Oakland and Emeryville. Once the equipment was released and set in the station, 718(06) departed Emeryville at 751PM-PT, 1 hour, and 53 minutes late. The crew departed Emeryville with traction and head end power from C/2013 due to C/2124 unable to provide. While enroute to Richmond the crew lost head end power. At Richmond, the crew restarted C/2124 to regain traction and head end power and departed Richmond at 820PM-PT, 2 hours, and 14 minutes late.

Train	Delay	Comment
718(06)	1'53"	
718(06)	17"	RIC

Train 305(06) South of Bloomington-Normal, IL - Passenger Train Interference

06OCT26: Train 305(06), with 209 customers onboard, was delayed at McLean siding/MP141.3, 17 miles south of the Bloomington-Normal Station, IL/MP124.0, on the UP Springfield subdivision meeting Amtrak train 306(06). Once the route was clear, train 305(06) continued south.

Train	Delay	Comment
305(06)	39"	

Train 714(06) - Initial Terminal Delay

06OCT26: Train 714(06) was delayed departing Oakland, CA, due to the late turn of inbound Train 711(06), which was terminated in Emeryville due to its late operation.

Train	Delay	Comment
714(06)	45"	
711(06)	Term EMY	

Train 8/28(05) Shelby, MT - Engine Failure

06OCT26: Train 8/28(05), with 204 customers, was delayed departing Shelby, MT, on the BNSF Hi-Line Subdivision due to loading issues on E/310. The locomotive was reset, and the train resumed operations.

Train	Delay	Comment
8/28(05)	36"	

Train 6(04) East of Naperville, IL - Commuter Train Interference

06OCT26: Train 6(04) was delayed east of Naperville, IL/MP28.5, on the BNSF Chicago Subdivision, following Metra 1262 between Naperville and Downers Grove/MP21.5.

Train 4(04), with 182 customers onboard, was also delayed following Metra trains between Naperville and Downers Grove.

Train	Delay	Comment
6(04)	34"	
4(04)	38"	

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Train 8/28(05) East of East Glacier Park, MT - Freight Train Interference

06OCT26: Train 8/28(05), with 0 customers, was delayed at MP 1136.1 on the BNSF Hi-Line Subdivision due to freight interference. The train was held for meets with BNSF 5249, BNSF 7219, and BNSF 7053 between Control Point Grizzly and Control Point Spotted Robe.

Train	Delay	Comment
8/28(05)	34"	

Train 504(06) South of Kelso-Longview, WA - Trespasser Incident

06OCT26: Train 504(06), with 129 customers, was held at MP 99.2 on the BNSF Seattle Subdivision due to a trespasser on the tracks ahead at MP 95. A BNSF Roadmaster was on site searching for the trespasser. After the all clear was given, train 504(06) resume normal operations.

Train	Delay	Comment
504(06)	1'13"	
11(05)	36"	

Train 14(05) North of Chemult, OR - System

06OCT26: Train 14(05) with E/338-332, nine cars, and 247 customers was delayed on the UPRR Cascade subdivision 54 miles north of Chemult at Fields/MP 556.6 due to PTC issues on E/338. The crew worked with CNOC mechanical and was unable to rectify the issue. The crew continued operating with PTC cut out and as a failed train.

Train	Delay	Comment
14(05)	1'03"	CMO-EUG

Train 24(06) North of New Orleans, LA - Freight Train Interference

06OCT26: Train 24(06), with 77 customers, was delayed at MP780, 34 miles north of New Orleans, LA, on the CSX NO&M Subdivision, meeting CSX 5121.

Train	Delay	Comment
24(06)	40"	

Train 516(06) - Cab Car Failure

06OCT26: Train 516(06), operating with Airo Set #3, WS1404 and cab car 90230, was delayed departing Seattle, WA, on the BNSF Seattle Subdivision due to mechanical issues. Cab car 90230 was initially reported with ditch light issues, with plans to cap the equipment with WDTX 1400 to protect service. However, WDTX 1400 was dropped from the consist due to bad-ordered MU receptacles on the front of 90230. The delay was further extended when bottled air was discovered while the equipment was attempting to pull out of the yard.

Train	Delay	Comment
516(06)	43"	

Train 525(06) Sacramento, CA - Third Party Contractor Engine Failure

27-FOI-00046 00000008953 UNCLASSIFIED 10/19/2026

06OCT26: Train 525(06) originating with JPBX921 was delayed departing Sacramento, CA, on the UPRR Martinez Subdivision due to a mechanical failure. Locomotive JPBX921 was originally assigned to Train 521(06); however, just prior to departure, its headlights were bad ordered. Several equipment swaps were made to allow additional time for repairs, and JPBX921 was ultimately reassigned to Train 525(06).

Repair efforts were unsuccessful, requiring Train 525(06) to be wyed prior to departure. As a result of the late operation, Train 525(06) was terminated at Emeryville, CA, and the equipment was routed to the Oakland Maintenance Facility for repairs before its scheduled turn as Train 526(06). With repairs taking longer than expected, Train 526(06) canceled in its entirety, and the equipment deadheaded to Sacramento for its turn.

Train	Delay	Comment
525(06)	57"	TERM EMY
526(06)	Canceled	

Train 4(04) East of Kansas City, MO - Freight Train Interference

06OCT26: Train 4(04) was delayed at CA Jct/MP418, 35 miles east of Kansas City, MO, on the BNSF Marceline Subdivision, meeting BNSF 7454.

Train	Delay	Comment
4(04)	34"	

Train 6(04) East of Osceola, IA - Freight Train Interference

06OCT26: Train 6(04) was delayed east of Osceola, IA/MP359.9, on the BNSF Ottumwa Subdivision, following BNSF 6189 between MP335 and MP300.8.

Train	Delay	Comment
6(04)	31"	

Train 23(06) South of Mobile, AL - Freight Train Interference

06OCT26: Train 23(06), with 35 customers, was delayed at Brookley/MP671.8, 5 miles south of Mobile, AL, on the CSX NO&M Subdivision, meeting M606-06.

Train	Delay	Comment
23(06)	36"	

Train 330(06) East of Sturtevant, WI - Commuter Train Interference

06OCT26: Train 330(06) was delayed beginning 29 miles east of Sturtevant, WI, on the CPKC C&M Subdivision, following Metra 2118 between Rondout/MP32.3 and MP1.7. Train 330(06) had previously been delayed just east of Milwaukee Airport/MP78.4 due to CPKC MW repairing a broken rail on Main 1 at Lake/MP76.2. Train 329(06) was also delayed being routed around MW at MP76.2. Train 331(06) was delayed departing Chicago, IL, due to late turn of equipment off Train 330(06) which arrived at 835AM, 28 minutes late. Train 332(06) was delayed departing Milwaukee, WI, due to late turn of equipment off Train 329(06) which arrived at 756AM, 7 minutes late.

Train	Delay	Comment
330(06)	08"	E/MKA, broken rail MP76.2
331(06)	22"	CHI, late turn off 330(06)
330(06)	31"	E/SVT, follow M2118
329(06)	11"	E/MKA, broken rail MP76.2
332(06)	11"	MKE, late turn off 329(06)

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Train 8/28(05) West of Whitefish, MT - Trespasser Incident

06OCT26: Train 8/28(05), with 105 customers, was delayed 5 miles west of Whitefish, MT, at MP 1224.04 on the BNSF Kootenai River Subdivision due to police activity. A body was reported on the tracks at the Whitefish station platform, with the strike believed to have involved a freight train. Upon completion of the investigation, Train 8/28(05) was given a signal to resume its journey.

Train	Delay	Comment
8/28(05)	1'06"	

Train 40(04) West of Toledo, OH - Freight Train Interference

06OCT26: Train 40(04) was delayed at MP292, 4 miles west of Toledo, OH, on the NS Toledo Terminal, meeting NS 4249. Train 49/449(05) was delayed following Train 40(04) between MP289 and MP297.

Train	Delay	Comment
40(04)	35"	

Train 6(04) West of Omaha, NE - Freight Train Interference

06OCT26: Train 6(04), with 205 customers, was delayed at South Omaha/MP21.3, 4 miles west of Omaha, NE, on the BNSF Omaha Subdivision, operating through the siding around BNSF 8406.

Train	Delay	Comment
6(04)	41"	

Train 21(05) North of Hope, AR - Freight Train Interference

06OCT26: Train 21(05), with 63 customers, was delayed at Emmet/MP450.3, 7 miles north of Hope, AR, on the UPRR Little Rock Subdivision, due to MRENL-05 (UP 5471) stopped in emergency ahead. Train 21(05) held for UP 5471 to inspect consist, restore air and operate in the clear.

Train	Delay	Comment
21(05)	1'02"	

Train 40(04) West of Elyria, OH - Coal on Tracks

06OCT26: Train 40(04), with 209 customers onboard, was held at Elyria, OH/MP206.6 on the NS Toledo East subdivision due to an NS coal train spilling coal on the tracks between mile post 219.0 and mile post 222.0. NS MW and C&S responded to the scene and were able to okay No 1 track for traffic to resume. Train 40(04) held at Elyria, then advanced to MP216 and met Train 48/448(05) and NS 22M, before proceeding west on No 1 track. Train 49/449(05), with 261 customers, was also delayed as a result and followed Train 40(04) through the area.

Train	Delay	Comment
40(04)	11"	ELY
40(04)	39"	W/ELY, MP216 hold for open route
40(04)	33"	W/ELY, MP216 meet 22M & 48/448(05)
49/449(05)	54"	

27-FOI-00046 00000008553 "UNCLASSIFIED" 10/19/2026

Train 5(06) West of Chicago, IL - Engine Failure

06OCT26: Train 5(06), E/45-E/5 6 cars, with 100 customers, pulled from Chicago, IL, on time and then stopped just west of Chicago due to lead E/45 with a locked axle alarm. Mechanical forces from CUS and the general foreman from the locomotive shop responded to assist. Train 5(06) shoved back on the platform in CUS and engine tech changed out a speed sensor on E/45. Train 5(06) departed Chicago the second time approximately 1 hour and 20 minutes late. Train 5(06) was further delayed at MP10, 10 miles west of Chicago, on the BNSF Chicago Subdivision, due to same issue on lead E/45. The crew contacted road foreman and mechanical for assistance. After cutting out No 3 traction motor on E/45 and performing roll-by inspection, Train 5(06) was back on the move west.

A UP freight unit was sourced to meet train 5(06) at Denver, CO in case the traction motors could not be cut back in.

Train	Delay	Comment
5(06)	1'27"	W/CHI MP1.5
5(06)	40"	W/CHI MP10

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	

Maintenance of Way Highlights

87-FOI-00946 00000908853 "UNCLASSIFIED" 10/19/2026

BNSF Fort Worth Subdivision Track Work - Texas Eagle Service TW 27-007

05OCT26: BNSF will perform tie replacement work on the Fort Worth Subdivision north of Temple, TX/MP218.2, between MP230 and MP245 beginning Monday October 5th through Friday October 9th. The work curfew will be from 630AM until 1230PM on the scheduled work days. To accommodate this infrastructure work, Amtrak's Texas Eagle Service will be adjusted as follows:

- Train 22(05-09) will depart San Antonio, TX, 59 minutes later, depart Fort Worth, TX, 30 minutes later and resume normal schedule upon departure from Dallas, TX.
- Train 422(04, 07) will depart San Antonio, 59 minutes later, depart Fort Worth 30 minutes later and resume normal schedule upon departure from Dallas.

WBS#: B.TR.100150.7225

Train	Delay	Comment
22(06)/422(04)	55"	N/TPL, slow orders

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

27-FOI-00046 000000008953 "UNCLASSIFIED" 10/19/2026

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gang will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

27-FOI-00048 0000000008953 "UNCLASSIFIED" 10/19/2026

16MAY26: Metra has track work scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

	Projected Need		Number Operated			
Train	Cars	Seats	Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

27-FOI-00046 00000008953 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
790 (07)	GTA	NO BIKE SPACE OR WIFI	YES	2	90215
129 (06)	NYP	Consist operating with a stubb set out of NYP due to engine failure on 125(05) equipment being stranded south of WAS. Capacity reduced. Check for any overages and reaccommodate as necessary.	PASSENGERS DOWNGRADED	15	
769 (07)	SAN	NO BIKE SPACE OR WIFI	YES	2	90215
86 (06)	WAS	Consist operating with a stubb set out of WAS due to engine failure on 125(05) equipment being stranded south of WAS. Capacity reduced. Check for any overages and reaccommodate as necessary.	PASSENGERS NOTIFIED	35	

Reverse Consists

Train Number	Station	Reason
110 (06)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
190 (06)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
138 (06)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
94 (06)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
137 (06)	BOS	Consist reversed | Business class seat orientation may have changed | At Front