# CNOC

## (CONSOLIDATED NATIONAL OPERATIONS CENTER)

# Amtrak Status Report

Thursday, October 08, 2026 Rules: 0-0




*This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.*

**Information Management**

27-FOI-00044 [illegible] 10/27/2026

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/07/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 329 | 44 | 86.6% | 2,229 | 301 | 86.5% | 2,229 | 301 | 86.5% |
| Central Division | 86.0% | 58 | 2 | 96.6% | 404 | 15 | 96.3% | 404 | 15 | 96.3% |
| East Division | 82.0% | 178 | 24 | 86.5% | 1,200 | 175 | 85.4% | 1,200 | 175 | 85.4% |
| West Division | 86.0% | 93 | 18 | 80.6% | 625 | 111 | 82.2% | 625 | 111 | 82.2% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

## Information Management

# Customer On Time Performance

Endpoint Arrival Dates through 10/7/26

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

| Service | Target | Day | | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score | Total Customers | Late Customers | Score |
| **Amtrak System** | **80%** | **98,651** | **21,918** | **78%** | **758,481** | **218,941** | **71%** | **758,481** | **218,941** | **71%** |
| ***Northeast Corridor*** | ***81%*** | ***46,948*** | ***6,595*** | ***86%*** | ***336,711*** | ***90,205*** | ***73%*** | ***336,711*** | ***90,205*** | ***73%*** |
| Acela | 83% | 12,215 | 1,949 | 84% | 76,979 | 18,630 | 76% | 76,979 | 18,630 | 76% |
| Northeast Regional | 79% | 34,733 | 4,646 | 87% | 259,732 | 71,575 | 72% | 259,732 | 71,575 | 72% |
| Richmond / Newport News / Norfolk | 77% | 8,669 | 1,406 | 84% | 73,392 | 21,450 | 71% | 73,392 | 21,450 | 71% |
| Springfield Shuttles | 89% | 582 | 221 | 62% | 6,147 | 1,507 | 75% | 6,147 | 1,507 | 75% |
| Roanoke | 79% | 3,331 | 309 | 91% | 25,302 | 8,009 | 68% | 25,302 | 8,009 | 68% |
| On Spine Northeast Regional | 80% | 22,151 | 2,710 | 88% | 154,891 | 40,609 | 74% | 154,891 | 40,609 | 74% |
| ***State Supported*** | ***80%*** | ***41,025*** | ***9,857*** | ***76%*** | ***337,539*** | ***85,503*** | ***75%*** | ***337,539*** | ***85,503*** | ***75%*** |
| Borealis | 80% | 575 | 0 | 100% | 4,459 | 1,028 | 77% | 4,459 | 1,028 | 77% |
| Capitol Corridor | 90% | 3,696 | 1,021 | 72% | 29,932 | 8,134 | 73% | 29,932 | 8,134 | 73% |
| Carolinian | 70% | 969 | 226 | 77% | 8,461 | 2,273 | 73% | 8,461 | 2,273 | 73% |
| Cascades | 75% | 2,068 | 712 | 66% | 19,216 | 4,576 | 76% | 19,216 | 4,576 | 76% |
| Downeaster | 82% | 1,530 | 520 | 66% | 12,837 | 3,908 | 70% | 12,837 | 3,908 | 70% |
| Empire | 78% | 5,755 | 1,615 | 72% | 42,497 | 9,785 | 77% | 42,497 | 9,785 | 77% |
| Adirondack | 72% | 338 | 0 | 100% | 2,656 | 327 | 88% | 2,656 | 327 | 88% |
| Ethan Allen Express | 70% | 547 | 281 | 49% | 3,973 | 1,355 | 66% | 3,973 | 1,355 | 66% |
| Maple Leaf | 70% | 721 | 384 | 47% | 5,724 | 1,446 | 75% | 5,724 | 1,446 | 75% |
| New York - Albany | 85% | 2,926 | 404 | 86% | 20,508 | 3,901 | 81% | 20,508 | 3,901 | 81% |
| New York - Niagara Falls | 75% | 1,223 | 546 | 55% | 9,636 | 2,756 | 71% | 9,636 | 2,756 | 71% |
| Gold Runner | 73% | 1,836 | 1,025 | 44% | 18,651 | 6,373 | 66% | 18,651 | 6,373 | 66% |
| Heartland Flyer | 70% | 93 | 91 | 2% | 1,184 | 1,112 | 6% | 1,184 | 1,112 | 6% |
| Hiawatha | 90% | 1,616 | 0 | 100% | 13,004 | 569 | 96% | 13,004 | 569 | 96% |
| Illinois | 78% | 2,083 | 569 | 73% | 18,881 | 6,102 | 68% | 18,881 | 6,102 | 68% |
| Carl Sandburg / Illinois Zephyr | 85% | 330 | 294 | 11% | 2,906 | 879 | 70% | 2,906 | 879 | 70% |
| Illini / Saluki | 85% | 681 | 186 | 73% | 6,192 | 1,680 | 73% | 6,192 | 1,680 | 73% |
| Lincoln Service | 70% | 1,072 | 89 | 92% | 9,783 | 3,543 | 64% | 9,783 | 3,543 | 64% |
| Keystone | 92% | 9,215 | 712 | 92% | 61,383 | 8,212 | 87% | 61,383 | 8,212 | 87% |
| Lincoln / Missouri | 70% | 630 | 286 | 55% | 5,719 | 2,887 | 50% | 5,719 | 2,887 | 50% |
| Mardi Gras Service | 80% | 376 | 365 | 3% | 2,256 | 766 | 66% | 2,256 | 766 | 66% |
| Michigan | 70% | 1,353 | 318 | 76% | 15,082 | 2,804 | 81% | 15,082 | 2,804 | 81% |
| Blue Water | 70% | 370 | 188 | 49% | 3,499 | 895 | 74% | 3,499 | 895 | 74% |
| Pere Marquette | 85% | 243 | 0 | 100% | 2,064 | 53 | 97% | 2,064 | 53 | 97% |
| Wolverine | 70% | 740 | 130 | 82% | 9,519 | 1,856 | 81% | 9,519 | 1,856 | 81% |
| Missouri | 80% | 186 | 0 | 100% | 1,896 | 109 | 94% | 1,896 | 109 | 94% |
| Pacific Surfliner | 85% | 6,533 | 1,819 | 72% | 59,230 | 21,419 | 64% | 59,230 | 21,419 | 64% |
| Pennsylvanian | 80% | 749 | 351 | 53% | 6,312 | 1,451 | 77% | 6,312 | 1,451 | 77% |
| Piedmont | 80% | 472 | 23 | 95% | 6,460 | 730 | 89% | 6,460 | 730 | 89% |
| Vermonter | 75% | 1,290 | 204 | 84% | 10,079 | 3,265 | 68% | 10,079 | 3,265 | 68% |
| ***Long Distance*** | ***70%*** | ***10,678*** | ***5,466*** | ***49%*** | ***84,231*** | ***43,233*** | ***49%*** | ***84,231*** | ***43,233*** | ***49%*** |
| Auto Train | 70% | 662 | 662 | 0% | 4,717 | 3,484 | 26% | 4,717 | 3,484 | 26% |
| California Zephyr | 70% | 498 | 15 | 97% | 5,712 | 2,250 | 61% | 5,712 | 2,250 | 61% |
| Cardinal | 70% | 243 | 10 | 96% | 2,028 | 1,316 | 35% | 2,028 | 1,316 | 35% |
| City Of New Orleans | 75% | 702 | 347 | 51% | 5,190 | 2,911 | 44% | 5,190 | 2,911 | 44% |
| Coast Starlight | 70% | 961 | 598 | 38% | 8,139 | 4,629 | 43% | 8,139 | 4,629 | 43% |
| Crescent | 70% | 779 | 160 | 79% | 6,675 | 1,012 | 85% | 6,675 | 1,012 | 85% |
| Empire Builder | 70% | 1,025 | 477 | 53% | 6,252 | 3,567 | 43% | 6,252 | 3,567 | 43% |
| Floridian | 60% | 1,416 | 1,026 | 28% | 10,641 | 7,468 | 30% | 10,641 | 7,468 | 30% |
| Lake Shore Ltd | 73% | 960 | 95 | 90% | 7,396 | 2,499 | 66% | 7,396 | 2,499 | 66% |
| Palmetto | 70% | 709 | 256 | 64% | 5,879 | 1,009 | 83% | 5,879 | 1,009 | 83% |
| Silver Meteor | 70% | 731 | 182 | 75% | 6,204 | 2,490 | 60% | 6,204 | 2,490 | 60% |
| Southwest Chief | 60% | 939 | 898 | 4% | 6,365 | 4,808 | 24% | 6,365 | 4,808 | 24% |
| Sunset Ltd | 70% | 314 | 110 | 65% | 2,005 | 931 | 54% | 2,005 | 931 | 54% |
| Texas Eagle | 70% | 739 | 630 | 15% | 7,028 | 4,859 | 31% | 7,028 | 4,859 | 31% |

**Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"**

# Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FGI 00046 00000000052 "UNCLASSIFIED" 10/10/2026~~

## Train Index Dates Through October 07, 2026

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Service** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| Amtrak System | 585 | 44,956 | 769,664 | 584 | 44,956 | 769,664 | 584 |

| | | Month to Date | | | FY to Date | | |
|---|---|---|---|---|---|---|---|
| **Department** | **Target** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** | **ACD Minutes** | **Train Miles** | **ACD per 10K TM** |
| INFRASTRUCTURE UNPLANNED | 107 | 3,296 | 238,642 | 138 | 3,296 | 238,642 | 138 |
| INFRASTRUCTURE PLANNED | 135 | 5,196 | 238,642 | 218 | 5,196 | 238,642 | 218 |
| FLEET RELIABILITY | 90 | 6,179 | 769,664 | 80 | 6,179 | 769,664 | 80 |
| TRAIN OPERATIONS | 424 | 30,285 | 769,664 | 393 | 30,285 | 769,664 | 393 |

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

**Information Management**

27-FOI-00044 [illegible] 10/27/2026

# Initial Terminal Performance By Division

Scheduled Departure Date: **10/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/07/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 329 | 44 | 86.6% | 2,229 | 301 | 86.5% | 2,229 | 301 | 86.5% |
| Central Division | 86.0% | 58 | 2 | 96.6% | 404 | 15 | 96.3% | 404 | 15 | 96.3% |
| East Division | 82.0% | 178 | 24 | 86.5% | 1,200 | 175 | 85.4% | 1,200 | 175 | 85.4% |
| West Division | 86.0% | 93 | 18 | 80.6% | 625 | 111 | 82.2% | 625 | 111 | 82.2% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

**Information Management**

# Initial Terminal Performance By Terminal

27-FOI-00048

Scheduled Departure Date: **10/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/07/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 329 | 44 | 86.6% | 2,229 | 301 | 86.5% | 2,229 | 301 | 86.5% |
| Central Division | 86.0% | 58 | 2 | 96.6% | 404 | 15 | 96.3% | 404 | 15 | 96.3% |
| CDL | 95.0% | 1 | 0 | 100.0% | 10 | 0 | 100.0% | 10 | 0 | 100.0% |
| CHI | 86.0% | 27 | 0 | 100.0% | 187 | 8 | 95.7% | 187 | 8 | 95.7% |
| CHM | - | 1 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| FTW | 92.5% | 1 | 1 | 0.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| GRR | 95.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| KCY | 92.0% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 14 | 0 | 100.0% |
| MKE | 92.0% | 6 | 0 | 100.0% | 41 | 1 | 97.6% | 41 | 1 | 97.6% |
| MOE | 97.5% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 14 | 0 | 100.0% |
| MSP | 96.5% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| NOL | 94.5% | 5 | 0 | 100.0% | 31 | 1 | 96.8% | 31 | 1 | 96.8% |
| OKC | 97.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| PNT | 88.0% | 2 | 1 | 50.0% | 20 | 1 | 95.0% | 20 | 1 | 95.0% |
| PTH | 93.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| QCY | 91.0% | 2 | 0 | 100.0% | 14 | 1 | 92.9% | 14 | 1 | 92.9% |
| SAS | 90.5% | 1 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| STL | 89.0% | 4 | 0 | 100.0% | 28 | 1 | 96.4% | 28 | 1 | 96.4% |
| East Division | 82.0% | 178 | 24 | 86.5% | 1,200 | 175 | 85.4% | 1,200 | 175 | 85.4% |
| ALB | 88.5% | 8 | 1 | 87.5% | 56 | 7 | 87.5% | 56 | 7 | 87.5% |
| BON | 87.5% | 5 | 2 | 60.0% | 35 | 4 | 88.6% | 35 | 4 | 88.6% |
| BOS | 85.5% | 19 | 1 | 94.7% | 131 | 5 | 96.2% | 131 | 5 | 96.2% |
| BRK | 92.5% | 5 | 2 | 60.0% | 35 | 4 | 88.6% | 35 | 4 | 88.6% |
| BTN | 82.0% | 1 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| CLT | 91.5% | 4 | 0 | 100.0% | 31 | 4 | 87.1% | 31 | 4 | 87.1% |
| GFD | 88.0% | 2 | 0 | 100.0% | 14 | 2 | 85.7% | 14 | 2 | 85.7% |
| GRO | - | 1 | 0 | 100.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| HAR | 79.5% | 13 | 2 | 84.6% | 79 | 12 | 84.8% | 79 | 12 | 84.8% |
| HFD | - | 2 | 0 | 100.0% | 10 | 0 | 100.0% | 10 | 0 | 100.0% |
| LOR | 84.0% | 1 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| MIA | 89.5% | 2 | 0 | 100.0% | 14 | 2 | 85.7% | 14 | 2 | 85.7% |
| MTR | 79.0% | 1 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| NFK | 84.5% | 2 | 0 | 100.0% | 14 | 3 | 78.6% | 14 | 3 | 78.6% |
| NFL | 93.5% | 2 | 0 | 100.0% | 14 | 3 | 78.6% | 14 | 3 | 78.6% |
| NHV | 78.0% | 5 | 1 | 80.0% | 34 | 9 | 73.5% | 34 | 9 | 73.5% |
| NPN | 93.0% | 2 | 0 | 100.0% | 13 | 1 | 92.3% | 13 | 1 | 92.3% |
| NYP | 75.5% | 51 | 7 | 86.3% | 336 | 65 | 80.7% | 336 | 65 | 80.7% |
| PGH | 93.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| PHL | 48.0% | 5 | 4 | 20.0% | 33 | 17 | 48.5% | 33 | 17 | 48.5% |
| RGH | 95.0% | 2 | 0 | 100.0% | 20 | 1 | 95.0% | 20 | 1 | 95.0% |
| RNK | 83.5% | 2 | 0 | 100.0% | 14 | 1 | 92.9% | 14 | 1 | 92.9% |
| SAB | 98.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| SAV | 96.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| SFA | 88.0% | 1 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| SPG | 92.5% | 5 | 1 | 80.0% | 38 | 5 | 86.8% | 38 | 5 | 86.8% |

**Information Management**

27-FOI-00044

# Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/07/2026**

Amtrak or Commuter: **Amtrak**

| Location | Target | ITP 10/07/2026 | | | ITP October 2026 To Date | | | ITP Fiscal Year 2027 To Date | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | Operated | Late | ITP | Operated | Late | ITP | Operated | Late | ITP |
| **System** | 84.0% | 329 | 44 | 86.6% | 2,229 | 301 | 86.5% | 2,229 | 301 | 86.5% |
| East Division | 82.0% | 178 | 24 | 86.5% | 1,200 | 175 | 85.4% | 1,200 | 175 | 85.4% |
| TWO | 73.0% | 1 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| WAS | 84.0% | 33 | 3 | 90.9% | 219 | 20 | 90.9% | 219 | 20 | 90.9% |
| West Division | 86.0% | 93 | 18 | 80.6% | 625 | 111 | 82.2% | 625 | 111 | 82.2% |
| ARN | 92.0% | 1 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| BFD | 79.0% | 7 | 3 | 57.1% | 49 | 13 | 73.5% | 49 | 13 | 73.5% |
| EMY | 72.0% | 1 | 0 | 100.0% | 6 | 3 | 50.0% | 6 | 3 | 50.0% |
| EUG | 86.5% | 2 | 0 | 100.0% | 13 | 0 | 100.0% | 13 | 0 | 100.0% |
| GTA | 90.0% | 3 | 1 | 66.7% | 21 | 7 | 66.7% | 21 | 7 | 66.7% |
| LAX | 89.5% | 11 | 1 | 90.9% | 73 | 7 | 90.4% | 73 | 7 | 90.4% |
| OKJ | 74.5% | 13 | 7 | 46.2% | 83 | 27 | 67.5% | 83 | 27 | 67.5% |
| PDX | 86.0% | 5 | 0 | 100.0% | 35 | 2 | 94.3% | 35 | 2 | 94.3% |
| SAC | 88.5% | 16 | 3 | 81.3% | 104 | 17 | 83.7% | 104 | 17 | 83.7% |
| SAN | 90.5% | 13 | 0 | 100.0% | 89 | 12 | 86.5% | 89 | 12 | 86.5% |
| SEA | 85.0% | 8 | 0 | 100.0% | 55 | 7 | 87.3% | 55 | 7 | 87.3% |
| SJC | 89.0% | 7 | 3 | 57.1% | 49 | 15 | 69.4% | 49 | 15 | 69.4% |
| SLO | 90.0% | 3 | 0 | 100.0% | 21 | 1 | 95.2% | 21 | 1 | 95.2% |
| SPK | 90.0% | 1 | - | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| VAC | 97.0% | 2 | 0 | 100.0% | 14 | 0 | 100.0% | 14 | 0 | 100.0% |

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 1 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 1 | 66.7% | 3 | 1 | 66.7% |
| 3 | 32 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 4 | 129 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 6 | 14.3% | 7 | 6 | 14.3% |
| 6 | | 6 | 3 | 50.0% | 6 | 3 | 50.0% | 6 | 3 | 50.0% | 6 | 3 | 50.0% |
| 7 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 8 | 205 | 6 | 2 | 66.7% | 6 | 2 | 66.7% | 6 | 5 | 16.7% | 6 | 5 | 16.7% |
| 11 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 14 | 24 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 19 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 20 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 21 | 53 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 22 | 93 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 6 | 14.3% | 7 | 6 | 14.3% |
| 23 | 30 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 24 | 37 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 25 | 61 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 26 | 70 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 27 | | 6 | 3 | 50.0% | 6 | 3 | 50.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 28 | | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 40 | 49 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 7 | 0.0% | 7 | 7 | 0.0% |
| 41 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 42 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 43 | 27 | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 48 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 49 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 50 | | 3 | 0 | 100.0% | 3 | 0 | 100.0% | 3 | 2 | 33.3% | 3 | 2 | 33.3% |
| 52 | 23 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 53 | 59 | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 6 | 14.3% | 7 | 6 | 14.3% |
| 55 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 56 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 58 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 59 | 228 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 63 | 35 | 7 | 6 | 14.3% | 7 | 6 | 14.3% | 7 | 7 | 0.0% | 7 | 7 | 0.0% |
| 64 | 26 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 66 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 67 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 68 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 69 | | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 71 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 72 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 75 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 76 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 77 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 78 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 79 | 22 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 80 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 84 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 85 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 86 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 89 | 27 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 90 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 93 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 94 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 95 | 49 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 97 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 98 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 110 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 111 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 112 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 113 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 119 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 125 | 27 | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 129 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 130 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 131 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 134 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 136 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 137 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 138 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 141 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 148 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 151 | | 7 | 5 | 28.6% | 7 | 5 | 28.6% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 170 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 171 | 16 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 172 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 173 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 174 | | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 175 | 26 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 176 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 177 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 178 | 17 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 179 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 181 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 182 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 183 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 184 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 185 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 186 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 190 | | 5 | 4 | 20.0% | 5 | 4 | 20.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 192 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 193 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 196 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 197 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 198 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 230 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 232 | 17 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 233 | 21 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 234 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 235 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 236 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 237 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 238 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 239 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 240 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 241 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 243 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 244 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 245 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 280 | 34 | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 281 | 39 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 283 | 17 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 284 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 290 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 291 | 66 | 7 | 6 | 14.3% | 7 | 6 | 14.3% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 300 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 301 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 302 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 305 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 306 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 307 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 311 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 316 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 318 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 319 | 24 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 329 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 330 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 331 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 332 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 334 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 335 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 336 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 337 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 338 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 339 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 341 | | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 342 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 350 | 22 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 352 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 353 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 354 | Cncld | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 6 | 1 | 83.3% | 6 | 1 | 83.3% |
| 355 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 364 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 365 | 39 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 370 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 371 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 380 | 22 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 381 | 18 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 382 | 24 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 383 | 33 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 390 | | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 391 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 392 | 21 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 393 | | 6 | 1 | 83.3% | 6 | 1 | 83.3% | 6 | 3 | 50.0% | 6 | 3 | 50.0% |
| 417 | 84 | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 425 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 448 | | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 449 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 470 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 471 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 473 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 474 | 131 | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 475 | 50 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 478 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 479 | 28 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 486 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 494 | 20 | 6 | 2 | 66.7% | 6 | 2 | 66.7% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 495 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 500 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 502 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 503 | 32 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 504 | 19 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 505 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 506 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 507 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 508 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 509 | 20 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 511 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 516 | 40 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 517 | 53 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 518 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 519 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 520 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 521 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 522 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 523 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 524 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 525 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 526 | 39 | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 527 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 528 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 529 | 24 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 530 | 28 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 531 | 29 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 532 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 534 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 535 | 18 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 536 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 537 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 538 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 539 | 38 | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 540 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 541 | 16 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 542 | 228 | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 543 | 205 | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 5 | 0.0% | 5 | 5 | 0.0% |
| 544 | 186 | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 545 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 547 | 60 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 548 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 549 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 550 | 120 | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 551 | No OS | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 562 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 564 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 566 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 567 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 572 | 57 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 573 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 579 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 580 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 581 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 584 | 34 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 587 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 588 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 591 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 593 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 6 | 0 | 100.0% | 6 | 0 | 100.0% |
| 595 | 16 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 600 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 601 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 605 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 607 | 22 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 609 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 622 | | 4 | 2 | 50.0% | 4 | 2 | 50.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 626 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 639 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 640 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 641 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 642 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 643 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 644 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 645 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 646 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 647 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 648 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 649 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 650 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 651 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 652 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 653 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 654 | 17 | 5 | 3 | 40.0% | 5 | 3 | 40.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 655 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 656 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 657 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 658 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |

# Amtrak On Time Performance

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 680 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 681 | Cncld | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 4 | 3 | 25.0% | 4 | 3 | 25.0% |
| 682 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 683 | 53 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 5 | 0.0% | 5 | 5 | 0.0% |
| 684 | 56 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 4 | 20.0% | 5 | 4 | 20.0% |
| 685 | 27 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 686 | 172 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 687 | 152 | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 688 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 701 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 702 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 703 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 704 | | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 710 | 56 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 711 | 43 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 712 | 24 | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 713 | | 7 | 3 | 57.1% | 7 | 3 | 57.1% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 714 | Cncld | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 715 | 41 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 716 | 53 | 7 | 5 | 28.6% | 7 | 5 | 28.6% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 717 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 718 | 126 | 7 | 4 | 42.9% | 7 | 4 | 42.9% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 719 | 80 | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 757 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 761 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 765 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 769 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 3 | 57.1% | 7 | 3 | 57.1% |
| 770 | 16 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 774 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 777 | 26 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 782 | 31 | 7 | 6 | 14.3% | 7 | 6 | 14.3% | 7 | 5 | 28.6% | 7 | 5 | 28.6% |
| 785 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 786 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 6 | 2 | 66.7% | 6 | 2 | 66.7% |
| 790 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 0 | 100.0% |
| 794 | | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 4 | 42.9% | 7 | 4 | 42.9% |
| 821 | 59 | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 6 | 14.3% | 7 | 6 | 14.3% |
| 822 | 172 | 7 | 1 | 85.7% | 7 | 1 | 85.7% | 7 | 7 | 0.0% | 7 | 7 | 0.0% |
| 1333 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 2 | 71.4% | 7 | 2 | 71.4% |
| 1340 | | 7 | 0 | 100.0% | 7 | 0 | 100.0% | 7 | 1 | 85.7% | 7 | 1 | 85.7% |
| 1689 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2102 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2103 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

# Amtrak On Time Performance

Trains Arriving Through: 10/7/2026

| | | Initial Terminal | | | | | | Endpoint | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Month to Date | | | Year to Date | | | Month to Date | | | Year to Date | | |
| Train | Late | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score | Opr | Late | Score |
| 2104 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2105 | 81 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2107 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2108 | Cncld | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 4 | 0 | 100.0% | 4 | 0 | 100.0% |
| 2109 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2112 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2113 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2115 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2116 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2118 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2120 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2123 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2124 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2126 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2127 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 2128 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2131 | | 5 | 2 | 60.0% | 5 | 2 | 60.0% | 3 | 0 | 100.0% | 3 | 0 | 100.0% |
| 2150 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2151 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 2152 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2154 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 2155 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 4 | 1 | 75.0% | 4 | 1 | 75.0% |
| 2156 | 35 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 2158 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2159 | 18 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 5 | 0.0% | 5 | 5 | 0.0% |
| 2160 | 19 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 2 | 60.0% | 5 | 2 | 60.0% |
| 2162 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2163 | 25 | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 5 | 0.0% | 5 | 5 | 0.0% |
| 2165 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 3 | 40.0% | 5 | 3 | 40.0% |
| 2167 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |
| 2171 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2190 | | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% | 5 | 0 | 100.0% |
| 2193 | | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% | 5 | 1 | 80.0% |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 2105 | WAS | 81 | SVS | 76 | SVS | 76 | XHM-PHL | AM | Unplanned Wye, WYE A/C PC/2147 THROTTLE AND BRAKE ISSUES |
| 2108 | NYP | Trn Cancelled | | | | | | | |
| 2156 | BOS | 35 | CAR | 36 | CAR | 33 | XGX-PVD | AM | Air / Brake / Wheel, 3375\|NG\|ND, Multiple brake faults on cafe car 3375, necessary to truck #8 |
| 2159 | WAS | 18 | DMW | 21 | DMW | 21 | NHV-STM | MN | Hold for defect repair Control Point, Unknown |
| 2160 | BOS | 19 | CTI | 25 | ENG | 20 | XHM-XCY | AM | Other electrical failure, 2145\|NG\|NP, STOPPED AT MORRIS WITH MULTIPLE FAULTS SHOWING ON THE POWER CAR |
| 2163 | WAS | 25 | PTI | 23 | DMW | 17 | NHV-STM | MN | Waiting for MW clearance Milepost, 36.0, 34.8 |
| 95 | NFK | 49 | PTI | 84 | PTI | 30 | FBG-RVR | CS | Wait for station track Amt-186, Milepost, 5.5, 5.5 |
| 125 | NPN | 27 | FTI | 41 | FTI | 41 | ASD-RVR | CS | Follow Follow 41507, 41507, Milepost, 13.0, 5.0 |
| 171 | RNK | 16 | RTE | 19 | RTE | 19 | LYH-RNK | NS | Line manual or spring switch Per Dispatcher signal off of line at mp km0.9. Directed to take switch off of motor, throw it , throw it back; line it for our move and restore to motor., Milepost, .0.3, 16.6 |
| 175 | WAS | 26 | DCS | 24 | DCS | 20 | NHV-STM | MN | Restrictive signal(s) from unknown cause Stop Signal, Control Point, 266 |
| 178 | BOS | 17 | OTH | 22 | FTI | 14 | RNK-LYH | NS | Cross over or go around 203, Milepost, 173.3, 174.6 |
| 417 | NHV | 84 | ITI | 75 | ITI | 75 | SPG-SPG | AM | Crew rest, 474, LATE TURNOF AM474 |
| 474 | SPG | 131 | ENG | 123 | ENG | 62 | NHV-NHV | AM | PTC - On Board Cab Signal or PTC Failure, 9635\|CB\|CC, DP NHV 123 MIN LATE A/C OF IETMS ISSUES |
| 475 | NHV | 50 | CCR | 51 | CCR | 33 | SPG-WNL | AM | Electrical failure, 9638, STOPPED AT MP 61, MULTIPLE ALARMS IN LOCOMOTIVE E/110 |
| 479 | NHV | 28 | CTI | 19 | CTI | 19 | SPG-WNL | AM | Meet, CTRAIL, 4466, Milepost, SPG, WNL, WAITED FOR CT4466 TO CLEAR FIELD |
| 494 | GFD | 20 | CTI | 17 | CTI | 17 | WND-WNL | AM | Meet, AM479, 479, Milepost, WND, WNL, MEET AM479 AT HAYDEN |
| 52 | LOR | 23 | FTI | 81 | FTI | 33 | XFL-XSE | CS | L24306 was building their train on the main at wn we had to wait for them to clear up l24306/7478, Control Point, wn |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 53 | SFA | 59 | FTI | 76 | FTI | 32 | XOU-XSA | CS | Follow csx31, Control Point, kress |
| 79 | CLT | 22 | FTI | 52 | FTI | 23 | PTB-RMT | CS | Follow CSX I031, Control Point, Stateline |
| 607 | HAR | 22 | DET | 24 | DET | 24 | PHL-ARD | AM | Catenary failure, Siding, ., Single tracking at Zoo a/c power loss 4 trk, Zoo-Bryn Mawr. |
| 654 | NYP | 17 | SVS | 19 | SVS | 19 | HAR-HAR | AM | Unplanned Wye, WYE AT STATE A/C BAD CAB CAR SPEEDOMETER; C/C 9632 |
| 681 | BRK | Trn Cancelled | PTI | 7 | PTI | 7 | WOB-HHL | MT | Meet 682, Control Point, LJ |
| 683 | BRK | 53 | PTI | 57 | PTI | 47 | POR-FRE | CS | Meet 686, Control Point, ROYAL |
| 684 | BON | 56 | CTI | 9 | CTI | 9 | HHL-WOB | MT | Blocked from station track Keolis, 357, Control Point, wilmington |
| 685 | BRK | 27 | PTI | 18 | PTI | 18 | ORB-POR | CS | Wait for station track 688, Control Point, mountain |
| 686 | BON | 172 | ENG | 125 | ENG | 125 | BRK-BRK | CS | Air / Brake 684 engine compressor failed. Waited for rescue engine., 92 |
| 687 | BRK | 152 | ITI | 141 | ITI | 141 | BON-BON | MT | Late departure at initial terminal due to late arrival of inbound equipment 686 |
| 63 | TWO | 35 | SYS | 20 | SYS | 17 | ROC-BUF | CS | Copy authority / restriction Ec1 98203, Milepost, 382, 382 |
| 64 | NYP | 26 | CTI | 30 | CUI | 27 | NFL-NFL | CS | United States |
| 232 | NYP | 17 | CTI | 7 | ENG | 5 | ALB-ALB | AM | Air / Brake Air compressor fault before leaving, mechanical department assessed and was able to rectify issue, 98 |
| 233 | ALB | 21 | CTI | 10 | DMW | 10 | YNY-CRT | MN | Waiting for MW clearance Normal procedure for working limits stop sign on metro north. Also given a 30mph speed restriction through the limits, Milepost, 30.0, 31.9 |
| 280 | NYP | 34 | ENG | 29 | ENG | 24 | NFL-BFX | CS | Axle slip on read engine 713 Stopping in interlocking had to receive permission from ng dispatcher to proceed, 713 |
| 281 | NFL | 39 | FTI | 53 | PTI | 16 | ROM-SYR | CS | Meet 64, Control Point, 278 |
| 283 | NFL | 17 | FTI | 52 | FTI | 40 | ROC-BUF | CS | Follow - Follow Freight from CP 402 to CP 429<br>- Crossover 1 to 2 @ CP 429, CSX (multiple), Milepost w/Letters, CP 402, CP 429 |
| 291 | BTN | 66 | ENG | 78 | ENG | 78 | ALB-ALB | AM | Issue's with cab car 9708 |
| 43 | PGH | 27 | ENG | 29 | ENG | 29 | NYP-NYP | AM | HEP, 620, LATE F/SSYD SHOPPED ENG.620 FOR UNSPECIFIED REASON SUBBED ENG.604 |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 89 | SAV | 27 | FTI | 75 | FTI | 29 | DIL-FLO | CS | Meet CSX138, Control Point, Mars Bluff |
| 40 | CHI | 49 | CAR | 63 | CAR | 57 | TPA-TPA | CS | Legitimate wayside HBD or DED actuation 324, Bad HBD sponsor. Had to inspect entire train for hot bearings. |
| 23 | NOL | 30 | FTI | 45 | FTI | 26 | BAS-XNO | NS | Meet csx 60607, Milepost, 780.3, 781.8 |
| 24 | MOE | 37 | FTI | 48 | FTI | 29 | XNO-BAS | CS | Meet CSX M80107, Siding, Claiborne |
| 25 | NOL | 61 | FTI | 63 | FTI | 63 | GUF-BAS | CS | Meet x606, Control Point, 745 |
| 26 | MOE | 70 | PTI | 42 | PTI | 42 | XNO-BAS | CS | Meet am 25, Milepost, 768.1, 766.3 |
| 526 | SAC | 39 | DCS | 43 | DCS | 43 | RIC-MTZ | UP | Restrictive signal(s) from known wayside signal failure Flagged from Hercules to Ozol., Stop, Control Point, Costa |
| 529 | SJC | 24 | DCS | 28 | DCS | 19 | MTZ-RIC | UP | CTC system failure Flagging past red signals at Howard and Costa, Control Point, RV030 |
| 530 | SAC | 28 | MBO | 23 | MBO | 23 | MTZ-SUI | UP | For maritime traffic Control Point, Vista |
| 531 | OKJ | 29 | DMW | 18 | DMW | 18 | SUI-MTZ | UP | Waiting for MW clearance Milepost, 44.25, 43.5 |
| 535 | OKJ | 18 | PTI | 10 | PTI | 7 | MTZ-RIC | UP | Follow Followed 711 from Ozol to Richmond, AMT 711, Control Point, Ozol |
| 539 | SJC | 38 | PTI | 27 | PTI | 22 | FMT-GAC | UP | Meet Amt 538, Siding, S.Albrae |
| 541 | OKJ | 16 | MBO | 11 | MBO | 11 | SUI-MTZ | UP | For maritime traffic Control Point, CP RV035 BENICIA |
| 542 | SAC | 228 | CTI | 189 | CTI | 189 | GAC-GAC | UP | ACE trespasser strike 37.9 MP. ACE, ACE, Milepost, 37.9, 37.9 |
| 543 | SJC | 205 | DTR | 213 | DTR | 213 | FMT-SCC | UP | Ace fatality FMT, SCC |
| 544 | SAC | 186 | POL | 157 | POL | 157 | SJC-SJC | UP | RR blocked by trespasser or vehicle strike by another train |
| 547 | SJC | 60 | POL | 65 | POL | 54 | FMT-GAC | UP | Right of Way police hold ACE trespasser strike delays |
| 550 | SAC | 120 | ITI | 139 | ITI | 139 | SJC-SJC | UP | Late departure at initial terminal due to late arrival of inbound equipment 543 |
| 551 | OKJ | No OS Rpt | | | | | | | |
| 503 | EUG | 32 | CTI | 30 | CTI | 30 | XA4-XTW | BN | Meet Issues with switch at Stewart, sound transit, sdrx 303/327, Control Point, sumner |
| 504 | SEA | 19 | PTI | 11 | PTI | 11 | VAN-KEL | BN | Meet Amtk 505, Control Point, Toteff |
| 509 | PDX | 20 | PTI | 24 | PTI | 13 | TAC-XNI | ST | Meet amtk 14, Control Point, rill |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 516 | VAC | 40 | MBO | 55 | MBO | 55 | X8B-XF2 | BN | Bridge had a broken rail they had to check Control Point, fraiser river bridge |
| 517 | PDX | 53 | DCS | 39 | DCS | 39 | CTL-KEL | BN | Power switch failure Control Point, Centralia South |
| 59 | NOL | 228 | FTI | 227 | FTI | 109 | YAZ-JAN | CC | Hold do to disabled freight train CN 3906, Siding, s. valley |
| 14 | SEA | 24 | FTI | 78 | FTI | 42 | CIC-RDD | UP | Meet UP 5793, Control Point, Culp |
| 8 | CHI | 205 | FTI | 189 | TRS | 64 | LIB-WFH | BN | Trespasser strike BNSF hit trespasser, Other, whf platform |
| 821 | FTW | 59 | DSR | 63 | DSR | 35 | GLE-FTW | BN | Per bulletin Milepost, 409.5, 409, 60, m, Milepost, 408.5, 403.7, 60, m, Milepost, 407.9, 407.1, 30, m, Milepost, 405.9, 405, 60, m, Milepost, 404.2, 403.8, 60, m, Milepost, 403.2, 402.7, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.5, 400.1, 60, m, Milepost, 399.9, 399.2, 60, m, Milepost, 39 |
| 822 | OKC | 172 | FTI | 175 | FTI | 120 | FTW-GLE | BN | Meet Control Point, N Alliance, Control Point, Harriet, BN 5032, BN 4213, BN7823 |
| 350 | PNT | 22 | PTI | 39 | PTI | 25 | KAL-XGO | MI | Meet AMTK 365, Control Point, 140 |
| 354 | PNT | Trn Cancelled | OTH | 4 | OTH | 3 | XH6-XPI | NS | Normal signal progression |
| 365 | CHI | 39 | FTI | 28 | FTI | 23 | LNS-BTL | CC | Follow unknown, Control Point, mcallister and Emmett |
| 572 | SAN | 57 | DCS | 37 | DCS | 37 | XRJ-FUL | BN | Restrictive signal(s) from unknown cause Red / stop, Control Point, buena park |
| 584 | SAN | 34 | CTI | 24 | PTI | 15 | SNC-SNP | SC | Meet Amtk 587, Siding, Capistrano |
| 595 | LAX | 16 | DMW | 24 | DMW | 24 | FUL-XRJ | BN | Waiting for MW clearance Milepost, 152, 145 |
| 770 | SAN | 16 | FTI | 17 | FTI | 17 | XRJ-FUL | BN | Follow 4231, Other, XRJ to FUL, BNSF |
| 777 | SLO | 26 | DCS | 35 | DCS | 16 | CPN-SBA | UP | Power switch failure Signal dropped at 372. Restricted proceed to South SBA, Control Point, CO369 |
| 782 | SAN | 31 | CTI | 49 | CTI | 29 | SIM-SIM | SC | Blocked from station track Holding at SIM platform., MTK, 123, Milepost, 438.1, 438.1 |
| 710 | BFD | 56 | DCS | 51 | DCS | 36 | RIC-MTZ | UP | CTC system failure Restricting at CP Pinole Came to stop at CP Hercules Flagged from CP Hercules to CPCosta, Control Point, Hercules |
| 711 | OKJ | 43 | PTI | 31 | PTI | 16 | SKN-ACA | BN | Meet AMTK 710, Control Point, W Sando |
| 712 | BFD | 24 | PTI | 22 | PTI | 12 | SKN-MOD | BN | Meet amtrak 713, Siding, riverbank |

# Amtrak Endpoint OTP Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/7/2026

| | | | Max Type | | Max Single Delay Item | | | | |
|---|---|---|---|---|---|---|---|---|---|
| Train | Terminal | Late | Type | Mins | Type | Mins | Between | Host | Delay Reason |
| 714 | BFD | Trn Cancelled | | | | | | | |
| 715 | OKJ | 41 | PTI | 52 | PTI | 34 | SKN-ACA | BN | Meet 716, Control Point, Sando |
| 716 | BFD | 53 | TEN | 32 | TEN | 32 | OKJ-OKJ | UP | Air / Brake C2123 |
| 718 | BFD | 126 | DSR | 17 | TCR | 17 | RIC-RIC | UP | HEP C2124, Lost hep |
| 719 | OKJ | 80 | PTI | 46 | POL | 35 | BFD-BFD | BN | Removal of passenger by police A passenger came in on 710, was really intoxicated and couldn't walk couldn't stand up so police came on board to get him off with wheelchair and wheelchair lift. I'm assuming they are taking him to jail. It was Bakersfield police |
| 3 | LAX | 32 | FTI | 163 | FTI | 35 | WLO-FLG | BN | Meet Also met eastbound at E Darling., BNSF 7818 East, Control Point, Dennison |
| 4 | CHI | 129 | TRS | 110 | TRS | 110 | GBB-GBB | BN | Trespasser strike Control Point, GBB depot |
| 21 | SAS | 53 | FTI | 126 | SVS | 63 | FTW-FTW | UP | Fuel Re spot train for fuel on account incorrect hose, Other, FTW DEPO |
| 22 | CHI | 93 | DSR | 138 | DSR | 20 | TPL-MCG | BN | Per bulletin Milepost, 236.0, 239.5, 15, MT |
| 380 | CHI | 22 | DSR | 16 | FTI | 10 | MAC-GBB | BN | Follow bnsf 7028, Control Point, east mac |
| 381 | QCY | 18 | FTI | 24 | FTI | 24 | GBB-MAC | BN | Meet Freight into yard, Control Point, Saluda, 5870, BNSF |
| 382 | CHI | 24 | DSR | 19 | DMW | 15 | MAC-GBB | BN | Unannounced yellow red flag @ MP 167.8- restricted speed for 4 miles beyond yellow red. Other, 167.8 |
| 383 | QCY | 33 | HLD | 2 | HLD | 2 | LAG-LAG | BN | Passenger and/or baggage |
| 392 | CHI | 21 | DSR | 29 | FTI | 12 | MAT-CHM | CC | Meet CN8854, Control Point, S Humbolt |
| 319 | KCY | 24 | DSR | 28 | PTI | 8 | JEF-SED | UP | Meet 316, Siding, shell |

# Amtrak Initial Terminal Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/7/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| ALB | 232 | 10/07 | 5 | 5 | Air / Brake Air compressor fault before leaving, mechanical department assessed and was able to rectify issue, 98 |
| BON | 685 | 10/07 | 6 | 6 | Late departure at initial terminal due to late arrival of inbound equipment 684 |
| BON | 687 | 10/07 | 141 | 141 | Late departure at initial terminal due to late arrival of inbound equipment 686 |
| BOS | 2165 | 10/07 | 8 | 8 | Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM THE YARD |
| BRK | 684 | 10/07 | (Trn Cxld) | | Engine Issue |
| BRK | 686 | 10/07 | 125 | 125 | Air / Brake 684 engine compressor failed. Waited for rescue engine., 92 |
| HAR | 654 | 10/07 | 19 | 19 | Unplanned Wye, WYE AT STATE A/C BAD CAB CAR SPEEDOMETER; C/C 9632 |
| HAR | 656 | 10/07 | 1 | 1 | Passenger and/or baggage |
| NHV | 474 | 10/07 | 123 | 62 | PTC - On Board Cab Signal or PTC Failure, 9635\|CB\|CC, DP NHV 123 MIN LATE A/C OF IETMS ISSUES |
| NHV | 474 | 10/07 | 123 | 61 | PTC - On Board Cab Signal or PTC Failure, 110\|DX\|BD, DP NHV 123 MIN LATE A/C OF IETMS ISSUES |
| NYP | 43 | 10/07 | 29 | 29 | HEP, 620, LATE F/SSYD SHOPPED ENG.620 FOR UNSPECIFIED REASON SUBBED ENG.604 |
| NYP | 51 | 10/07 | 23 | 23 | Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING |
| NYP | 63 | 10/07 | 3 | 3 | Meet, AM230, Other, NYP, HELD F/INBOUND AM230 |
| NYP | 69 | 10/07 | 2 | 2 | Passenger and/or baggage, BOARDING |
| NYP | 181 | 10/07 | 4 | 4 | Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL |
| NYP | 291 | 10/07 | 7 | 7 | Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240 |
| NYP | 2109 | 10/07 | 13 | 13 | Air / Brake / Wheel, 3372, WATER ISSUES IN CAR 3372 |
| PHL | 110 | 10/07 | 4 | 4 | Other electrical failure, 632\|EX\|ES, Main circuit breaker wouldn't close. Fixed the issue and train on the move. |
| PHL | 190 | 10/07 | 6 | 2 | High passenger count |
| PHL | 190 | 10/07 | 6 | 4 | PTC - Stop Bypass Permission Required, Control Point, ., HAD TO PRESS STOP BY PASS TWICE. |
| PHL | 601 | 10/07 | 2 | 2 | Per MW foreman, Milepost, 31.0, 32.0, 15, 4, received TSRB addition. |
| PHL | 605 | 10/07 | 1 | 1 | Passenger and/or baggage |
| SPG | 417 | 10/07 | 75 | 75 | Crew rest, 474, LATE TURNOF AM474 |
| WAS | 112 | 10/07 | 5 | 5 | Dispatcher hold, Control Point, WAS, BSP REMOVED IN 7 S&I AT 518A. BLOCK WASN'T REMOVED UNTIL 623A |

# Amtrak Initial Terminal Details

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/7/2026

| Terminal | Train | Date | Late | Delay | Cause |
|---|---|---|---|---|---|
| WAS | 174 | 10/07 | 4 | 4 | Door, 43392\|AX\|MF, DOOR WOULDN'T STAY SHUT AT DP TIME MECH CALLED CUTOUT BUT STILL NEC'Y TO PUT IN BYPASS |
| WAS | 2108 | 10/07 | (Trn Cxld) | | Engine Issue |
| FTW | 822 | 10/07 | 13 | 13 | Loading problem 203 |
| PNT | 353 | 10/07 | 8 | 8 | Late departure at initial terminal due to late arrival of inbound equipment 354 |
| BFD | 701 | 10/07 | 6 | 6 | Improper signal & switch/lineup at departure time. Control Point, AMTRAK LEAD |
| BFD | 711 | 10/07 | 3 | 3 | Door C9021, C9303, No door light between 9303 & 9021 upon departure. Had door closed light and engineer preformed a successful load test prior to departure |
| BFD | 719 | 10/07 | 35 | 35 | Removal of passenger by police A passenger came in on 710, was really intoxicated and couldn't walk couldn't stand up so police came on board to get him off with wheelchair and wheelchair lift. I'm assuming they are taking him to jail. It was Bakersfield police |
| GTA | 770 | 10/07 | 4 | 4 | Waiting for MW clearance Control Point, S. Elleood |
| LAX | 14 | 10/07 | 18 | 18 | Passenger and/or baggage Awaiting the "all clear" while baggage is being loaded and red caps are enroute. |
| OKJ | 526 | 10/07 | 3 | 3 | Meet 6, Control Point, North Jack London |
| OKJ | 532 | 10/07 | 8 | 8 | PTC - On Board Cab Signal or PTC Failure JPBX921 |
| OKJ | 534 | 10/07 | 9 | 9 | Meet Dispatch had us wait for 539 to arrive, AMT 539, Other, Jack London Station |
| OKJ | 536 | 10/07 | 10 | 2 | Meet Amtk 541, Control Point, NI007 |
| OKJ | 536 | 10/07 | 10 | 5 | Meet Wait for amtk716 who was having mechanical issues at OKJ, amtk716, Control Point, NI005 |
| OKJ | 536 | 10/07 | 10 | 3 | Unable to contact dispatcher / MW foreman Unable to get a hold of dispatcher to depart yard, Control Point, NI005 |
| OKJ | 712 | 10/07 | 3 | 3 | Tasie had door issues, and air test issues C8301 |
| OKJ | 714 | 10/07 | (Trn Cxld) | | Third Party Car Failure |
| OKJ | 716 | 10/07 | 32 | 32 | Air / Brake C2123 |
| SAC | 539 | 10/07 | 5 | 5 | Meet Amt 6, Milepost, 88.5, 88.5 |
| SAC | 543 | 10/07 | 1 | 1 | Sac station hold for a ada cart that having issues in the tunnel. |
| SAC | 551 | 10/07 | 152 | | |
| SJC | 542 | 10/07 | 20 | 20 | PTC system failure Engineer could not log into PTC, Control Point, ALAMEDA |
| SJC | 544 | 10/07 | 157 | 157 | RR blocked by trespasser or vehicle strike by another train |
| SJC | 550 | 10/07 | 139 | 139 | Late departure at initial terminal due to late arrival of inbound equipment 543 |
| SPK | 27 | 10/05 | 1 | 1 | Late arrival of 7 into SPK |

# Eastern Region



## Commuter Services

| Service Type | OTP Goal | OTP Day | OTP MTD | OTP Prior Month | Trains Operated | Trains Late |
|---|---|---|---|---|---|---|
| MBTA | 95.0 | 99.7 | 99.4 | 94.8 | 342 | 1 |
| CDOT | 95.0 | 100 | 84.7 | 92.4 | 24 | 0 |
| MARC | 95.0 | 92.9 | 84.5 | 90.2 | 56 | 4 |
| SEPTA | 95.0 | 93.5 | 90.4 | 91.5 | 215 | 14 |
| NJT-NED | 95.0 | 95.7 | 88.9 | 88.6 | 351 | 15 |
| NJT-SED | 95.0 | 100.0 | 97.6 | 97.2 | 24 | 0 |

## Operating Highlights

### *Train 41(06) South of Columbia, SC - Freight Train Interference*

08OCT26: Train 41(06) operating with engines 366, 333, and 190 customers onboard was delayed 6 miles south of Columbia, SC on the CSX Columbia subdivision holding at Dixiana siding milepost 366.4 waiting for CSX U657-07 to cut cars off at Nassau siding due to the freight's inability to traverse the hill between Nassau and Richland. After the freight set the cars off and put their train back together, train 41(06) was met and able to proceed south.

| Train | Delay | Comment |
|---|---|---|
| 41(06) | 2'00" | |

### *Train 52(07) South of Charleston, SC - Freight Train Interference*

08OCT26: Train 52(07) operating with engines 354, 364, and 269 customers onboard was delayed 13 miles south of Charleston, SC on the CSX Charleston subdivision following CSX M410-07 from milepost 394 until Charleston Station milepost 387.

| Train | Delay | Comment |
|---|---|---|
| 52(07) | 30" | |

### *Train 283(07) West of Rochester, NY - Freight Train Interference*

07OCT26: Train 283(07) operating with engine 98 and 42 customers onboard was delayed west of Rochester, NY on the CSX Buffalo Terminal subdivision following freight traffic from milepost 402 until milepost 429.

| Train | Delay | Comment |
|---|---|---|
| 283(07) | 40" | |

### *Train 2171(07) West of Metro Park, NJ - Signal*

07OCT26: Acela 2171(07) operating with power cars 2017, 2036, and 186 customers onboard was delayed west fo Metro Park, NJ on the Amtrak NYP Line operating through a power switch failure at Iselin Interlocking milepost 24.5. Acela 2171(07) had to reverse to operate through a different route.

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## Train 2156(07) East of Providence, RI - Car Failure

07OCT26: Acela 2156(07) operating with power 2137, 2138, and 318 customers onboard was delayed east of Providence, RI on the Amtrak NHB Line due to a faulty brake alarm on cafe car 3375 causing the crew to cut out the 8th truck.

| Train | Delay | Comment |
|---|---|---|
| 2156(07) | 33" | |

## Train 95(07) Richmond Staples Mill, VA - Passenger Train Interference

07OCT26: Train 95(07) operating with engine 379 and 215 customers onboard was delayed 2 miles north of Richmond, VA on the CSX RFP subdivision holding at milepost 6.0 for open station track in the station due to congestion. Train 53(07) was affected following 95(07) causing delay.

| Train | Delay | Comment |
|---|---|---|
| 95(07) | 30" | |
| 53(07) | 54" | |

## Train 291(07) Albany, NY - Engine Failure

07OCT26: Train 291(07) operating with cab car 9708, engine 708, and 119 customers onboard was delayed departing Albany, NY due to the brake controller on cab car 9708 being replaced due to mechanical failure.

| Train | Delay | Comment |
|---|---|---|
| 291(07) | 1'18" | |

## Train 474(07) New Haven, CT - Cab Car Failure

07OCT26: Train 474(07) operating with locomotive 120, 1 car, cab car 9635 and 28 customers was delayed at the initial terminal of New Haven due to cab signal failure on cab car 9635 requiring the equipment to be capped with locomotive 93. After adding locomotive 93 mechanical continued to have PTC troubles within the consist and contacted CNOC Mechanical for assistance. Due to issue not being resolved, train 475(07) short turned for 474(07). Additional IETMS issues were ongoing with 475(07) equipment but was able to be resolved.

| Train | Delay | Comment |
|---|---|---|
| 474(07) | 2'03" | |
| 417(07) | 1'15" | |

## Train 654(07) Harrisburg, PA - Cab Car Failure

07OCT26: Train 654(07) operating with locomotive 613, 4 cars, cab car 9632 and 55 customers onboard was delayed 2 miles east of Harrisburg Station at MP 103 on the Amtrak PH Line due to speedometer failure on cab car 9632. It was necessary for the crew to reverse back to Harrisburg and wye the equipment to operate with the motor in lead. The train was further delayed due to needing to be capped in Philadelphia.

| Train | Delay | Comment |
|---|---|---|
| 654(07) | 19" | Reverse and WYE train |
| 654(07) | 12" | PHL |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## Train 475(07) South of Springfield, MA - Cab Car Failure

07OCT26: Train 475(07) operating with locomotive 110, 1 car, cab car 9638 and 18 customers onboard was delayed 1 mile south of Springfield at MP 61 on the Amtrak MRS line due to multiple faults on cab car 9638. There were alarms in locomotive 110 additionally. The crew, with the help of CNOC Mechanical was able to clear all faults and allow the train to proceed.

Train 475(07) was further delayed after setting off the Windsor HBD for a hot journal. The crew stopped at MP 36 and inspected the equipment and took no exceptions and continued toward New Haven.

| Train | Delay | Comment |
|---|---|---|
| 475(07) | 33" | Cab car faults |
| 475(07) | 20" | Hot journal activation |

## Train 684(07) Brunswick, ME - Engine Failure

07OCT26: Train 684(07) operating with locomotive 92-90224, 4 coaches and 39 customers became disabled .02 miles West of Brunswick, ME at MP 1 on the CSX Portland subdivision due to air compressor failure on locomotive 92. The crew worked with Amtrak mechanical technicians and were unable to resolve the air compressor failure due to contactor failure. HEP was able to remain functional throughout the delay.

As a result of the engine failure, train 681(07) was terminated at Portland and 1 bus provided alternate transportation for the customers to Freeport and Brunswick. Train 684(07) originated Portland with the equipment from train 681(07) and the customers at Brunswick and Freeport were transferred to train 686(07). Rescue equipment was dispatched from Portland to be added to the disabled set and push the trainset back into Brunswick where it became train 686(07) for operation Brunswick to Boston.

Due to the late operations of both trains 684(07) and 686(07) the equipment turns to 685(07) and 687(07) resulted in initial terminal delays to both trains.

Additionally, train 683(07) was delayed between Portland and Freeport holding meeting train 686(07) at CPF 185.

**WBS#: B.TR.100150.7248**

| Train | Delay | Comment |
|---|---|---|
| 681(07) | Terminated POR | |
| 684(07) | 46" | Originate POR |
| 686(07) | 2'05" | Initial terminal delay |
| 683(07) | 46" | Meet 686(07) |
| 685(07) | 06" | Initial terminal delay |
| 687(07) | 2'21" | Initial terminal delay |

## Train 2105(07) Philadelphia, PA - Engine Failure

07OCT26: Next Gen Acela 2105(07) operating with TS-26 was delayed at Philadelphia after the engineer requested mechanical and Road Foreman assistance due to an unresponsive brake and throttle on power car 2147. An Amtrak Road Foreman responded and determined it would be unsafe to continue with power car 2147 in lead and would need to wye the train to have power car 2147 in trail for operation to Washington. After the train completed the move around the wye train 2105(07) was able to proceed.

As a result of the late operation of train 2105(07) trains 2108(07) and 2119(07) were cancelled in their entirety.

| Train | Delay | Comment |
|---|---|---|
| 2105(07) | 1'14" | |
| 2108(07) | cancelled | |
| 2119(07) | cancelled | |

# *Train 97(06) South of Savannah, GA - Freight Train Interference*

27-FOI-00046 00000008952 UNCLASSIFIED 10/19/2026,

07OCT26: Train 97(06) operating with locomotives 8302, 10 cars and 207 customers onboard was delayed 31 miles south of Savannah, GA at MP 522 on the CSX Nahunta subdivision due to freight train interference with CSX S431-04 performing local work between Mc Intosh and North Ludowici. Once the freight cleared the main line train 97(06) was able to proceed without further delay.

| Train | Delay | Comment |
|---|---|---|
| 97(06) | 30" | |

# Maintenance of Way Highlights

27-FOU00046 00000098853 "UNCLASSIFIED" 10/19/2026

## *NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095*

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will

**WBS#: B.TR.100150.7085**

| Train | Delay | Comment |
|---|---|---|
| 77(03) | 50" | |
| 78(03) | 50" | Turn of Late 77(03) |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## *CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work*

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

**WBS#: B.TR.100150.6692**

# Eastern Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| None | | | | |
| | | | | |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Eastern Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| Train | Projected Need Cars | Projected Need Seats | Number Operated Cars | Number Operated Seats | Standees | Location |
|---|---|---|---|---|---|---|
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| | | | | |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

# Western Region
# Operating Highlights

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## *Train 8/28(06) West of Glasgow, MT - Freight Train Interference*

08OCT26: Train 8/28(06) was delayed at Tampico / MP 288.0, on the Burlington Northern Santa Fe Milk River Subdivision, 11 miles west of the Glasgow, MT station, meeting BNSF 7245.

| Train | Delay | Comment |
|---|---|---|
| 8/28(06) | 41" | |

## *Train 715(07) East of Antioch-Pittsburg, CA - Passenger Train Interference*

08OCT26: Train 715(07) was delayed at W. Sando/ MP1150.8 on the BNSF Stockton Subdivision, 1.2 miles east of Antioch, CA station, meeting Train 716(07)

| Train | Delay | Comment |
|---|---|---|
| 715(07) | 34" | |

## *Train 8(07) West of Ephrata, WA - Set Out Coach Car*

08OCT26: Train 8(07) was delayed at Adrian/ MP1589.8 on the BNSF Columbia River Subdivision, 9.3 miles west of Ephrata, WA station, due to the crew reporting flat spots on coach car C/34094. The crew contacted CNOC Mechanical, and it was determined that the car needed to be set out. Once the affected car was set out at Adrian siding, Train 8(07) continued east.

| Train | Delay | Comment |
|---|---|---|
| 8(07) | 2'11" | |

## *Train 3(06) West of Winslow, AZ - Freight Train Interference*

08OCT26: Train 3(06) was delayed at W. Winslow/ MP288.0 on the BNSF Seligman Subdivision, 2.5 miles west of Winslow, AZ station, due to meeting BNSF 7649. The train was further delayed following BNSF 7408 between MP290.8 and MP340.6, then met BNSF 5837 at E. Flagstaff/ MP340.8.

| Train | Delay | Comment |
|---|---|---|
| 3(06) | 1'23" | |

## *Train 26(07) South of Mobile, AL - Signal*

08OCT26: Train 26(07) was delayed at MP667, .41 miles south of Mobile, AL station on the CSX NO and M subdivision due to power switch failure. Train 26(07) arrived to Mobile AL Station at 1024PM CT after proceeding through the switch at reduced speed.

| Train | Delay | Comment |
|---|---|---|
| 26(07) | 36" | |

27-FOIA-00046 00000008952 UNCLASSIFIED 10/19/2026

## Train 822(07) South of Ardmore, OK - Freight Train Interference

08OCT26: Train 822(07) was delayed beginning at MP410.30, 30.86 miles south of Ardmore, OK station on the BNSF Red Rock subdivision following BNSF freight train 7071. Train 822(07) followed the freight until MP450.

| Train | Delay | Comment |
|---|---|---|
| 822(07) | 41" | |

## Train 6(06) Denver, CO - System

08OCT26: Train 6(06) was delayed departing Denver, CO station/MP0.0 on the BNSF Front Range subdivision due to the engineers signing up on rest at 821PM MT. Train 6(06) departed Denver CO station at 839PM MT operating 1 hour and 40 minutes late.

| Train | Delay | Comment |
|---|---|---|
| 6(06) | 1'54" | |

## Train 822(07) South of Gainesville, TX - Freight Train Interference

07OCT26: Train 822(07) was delayed beginning at MP364.6, 46.2 miles south of Gainesville, TX station on the BNSF Fort Worth subdivision meeting BNSF Freight trains 5032, 4213, and 7823. Train 822(07) was back on the move at 742PM CT once all the freight trains cleared the route.

| Train | Delay | Comment |
|---|---|---|
| 822(07) | 2'00" | |

## Train 26(07) South of Bay Saint Louis, MS - Passenger Train Interference

07OCT26: Train 26(07) was delayed beginning at MP768.1, 12.07 miles south of Bay Saint Louis, MS station on the CSX NO and M subdivision meeting Amtrak train 25(07). Train 26(07) was back on the move at 740PM CT after 25(07) cleared to the south.

| Train | Delay | Comment |
|---|---|---|
| 26(07) | 42" | |

## Train 25(07) North of Bay Saint Louis, MS - Freight Train Interference

07OCT26: Train 25(07) was delayed holding at MP745, 9.59 miles north of Bay Saint Louis, MS station on the CSX NO and M subdivision for a meet with CSX freight train 606. Train 25(07) was back on the move at 712PM CT after the freight cleared to the north.

| Train | Delay | Comment |
|---|---|---|
| 25(07) | 1'03" | |

## Train 719(07) Bakersfield, CA - Police Related

07OCT26: Train 719(07) was delayed departing Bakersfield, CA due to waiting for police to arrive and remove an intoxicated customer, who was unable to stand or walk.

| Train | Delay | Comment |
|---|---|---|
| 719(07) | 35" | |

27-FOI-00046 00000008952 UNCLASSIFIED 10/19/2026

## Train 5(07) East of Mount Pleasant, IA - Signal

07OCT26: Train 5(07) was delayed beginning at MP213, 21 miles east of Mount Pleasant IA station on the BNSF Ottumwa subdivision due to wayside signal failure. Train 5(07) was delayed operating through the failure until MP227.

| Train | Delay | Comment |
|---|---|---|
| 5(07) | 40" | |

## Train 24(07) West of Bay Saint Louis, MS - Freight Train Interference

07OCT26: Train 24(07), operating with engines 154/365 three coaches, and 112 customers, was delayed 12 miles west of Bay Saint Louis, MS, on CSX NO&M meeting NS131 at milepost 6.8 and CSX M80107 at milepost 766.5.

| Train | Delay | Comment |
|---|---|---|
| 24(07) | 19" | milepost 6.8 |
| 24(07) | 29" | milepost 766.5 |

## Train 542(07) Santa Clara, CA - A.C.E. Trespasser Incident

07OCT26: Train 542(07) was delayed at Santa Clara- Great America, CA station. This was due to the investigation of fatal trespasser incident involving Altamont Corridor Express (A.C.E.) train #6. The incident occurred at MP 37.4 on the Coast Subdivision of the Union Pacific Railroad, 3.5 miles north of the station. The local Police and Union Pacific Police closed the tracks while investigating the incident. The following train plan was instigated for the duration: Train 542(07) was held at Great America, Train 542(07) was reversed back to Fremont and 544(07) was held at San Jose. The Uber Voucher program was initiated for passengers onboard these trains at the affected stations. Due to the anticipated lengthy delay, one bus was sourced to provide a bus bridge for passengers on trains 542 and 543, between Fremont and Great America stations. Once the scene was released and track re-opened, Train 542 equipment turned as 543(07) at Great America, and 543 equipment was turned as 542(07) at Fremont. Due to this, Train 547(07) was also delayed, held at Albrae/ MP34.9 for 544 and Ace 8 to pass, and trains 550(07) and 551(07) were delayed initial terminal due to late inbound trains 542(07) and 547(07).

| Train | Delay | Comment |
|---|---|---|
| 542(07) | 3'29" | |
| 544(07) | 2'37" | |
| 543(07) | 3'33" | |
| 550(07) | 2'19" | |
| 551(07) | 2'32" | |
| 547(07) | 1'05" | |

## Train 21(06) Fort Worth, TX - System

07OCT26: Train 21(06) with engine 63, 9 coaches and 76 customers was delayed departing Fort Worth, TX, on BSNF Ft. Worth Subdivision, due to dropping off extra coaches to be added to 822(07) for big game day trains. They were also delayed due to respotting the train for refueling. The vendor didn't have a long enough hose to accommodate fueling at normal location.

| Train | Delay | Comment |
|---|---|---|
| 21(06) | 1'03" | |

27-FOI-00046 0000008952 "UNCLASSIFIED" 10/19/2026

## Train 58(07) Jackson, MS - System

07OCT26: Train 58(07) originating with engine 30, seventeen coaches and 148 customers was delayed departing Jackson, MS, on CN Mccomb subdivision, due to holding for a relief engineer to arrive from Yazoo City, MS. The engineer on train 59(06) was supposed to get off at Jackson, MS and then operate train 58(07) to meet the relief engineer between Yazoo City and Jackson, MS

| Train | Delay | Comment |
|---|---|---|
| 58(07) | 1'24" | |

## Train 713(07) East of Antioch-Pittsburg, CA - Trespasser Incident

07OCT26: At 1:52P-PT, Train 713(07), operating with Locomotive C2103, 6 cars and 67 customers, had a near miss with a tractor-trailer at a private crossing (MP 1139.8, DOT 029645U) on the Burlington Northern Santa Fe Stockton Subdivision, 12 miles east of the Antioch-Pittsburg, CA station. No injuries to the crew or customers and no equipment damage were reported. The crew was inspecting the train before resuming operation.

| Train | Delay | Comment |
|---|---|---|
| 713(07) | 05" | |

## Suisun Bay Bridge East of Martinez, CA - Drawbridge Opening for Maritime Traffic

07OCT26: The Suisun Bay Bridge (MP 33.2) on the Union Pacific Martinez Subdivision, 2 miles east of the Martinez, CA station, opened for maritime traffic.

Train 530(07) and Train 539(07) were delayed awaiting the bridge closure.

| Train | Delay | Comment |
|---|---|---|
| 530(07) | 23" | |
| 539(07) | 14" | |

## Train 516(07) South of Vancouver, BC - Drawbridge Opening

07OCT26: Train 516(07) was delayed at Fraser River Bridge (MP 141.3) on the Burlington Northern Santa Fe New Westminster Subdivision, 14 miles south of Vancouver, BC Pacific Central Station, awaiting bridge closure following maritime traffic.

| Train | Delay | Comment |
|---|---|---|
| 516(07) | 55" | |

## Train 714(07) Canceled - Third Party Contractor Car Failure

07OCT26: Due to ongoing wheel truing and additional servicing for C9001, Train 714(07) was canceled in its entirety. The following service adjustments were implemented:

The 70 customers from Train 714(07) were accommodated on Train 716(07).
Train 711(07) turned for Train 716(07).
Train 713(07) turned for Train 718(07).

Following completion of the wheel truing, the equipment was deadheaded to the Bakersfield, CA station for an equipment turn.

| Train | Delay | Comment |
|---|---|---|
| 716(07) | 32" | ITD OKJ - Equip off 711 |

## Train 572(07) Fullerton, CA - Temporary Speed Restrictions

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

07OCT26: Train 572(07) was delayed at Burton Park (MP 160.3) on the Burlington Northern Santa Fe San Bernardino Subdivision, 5 miles west of the Fullerton, CA station, while following commuter (METROLINK) due to several 10 mph speed restrictions.

| Train | Delay | Comment |
|---|---|---|
| 572(07) | 37" | |

## Train 22(07) South of McGregor, TX - Freight Train Interference

07OCT26: Train 22(07), operating with engine 311, six coaches, and 128 customers, was delayed 10 miles south of McGregor, TX, on BNSF Ft. Worth subdivision, due to meeting BNSF6047 at Control Point Moody. Once the freight cleared and a route was made available, train 22(07) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 22(07) | 45" | |

## Train 20(07) West of Meridian, MS - Freight Train Interference

07OCT26: Train 20(07), operating with engines 336/204, was delayed 2 miles west of Meridian, MS, on NS NO&NE subdivision, due to meeting multiple freight trains due to congestion in the area. The congestion was caused by a disabled freight with a broken knuckle.

| Train | Delay | Comment |
|---|---|---|
| 20(07) | 44" | |

## Train 4(05) Galesburg, IL - Trespasser Incident

07OCT26: At approximately 12:15 p.m. CT, Train 4(05), operating with engines 192/48, nine coaches, and 227 customers, went into emergency at Milepost 177.4 on the BNSF Chillicothe Subdivision upon departing Galesburg Station, Galesburg, Illinois, after striking a trespasser. Head-end power remained active but was temporarily secured while EMS personnel and law enforcement conducted their on-scene response. No injuries were reported to the crew or customers, and no damage to the equipment was identified. Weather conditions at the time were approximately 76 degrees and mostly sunny. The train remained at the station while the investigation was conducted, and two Amtrak Road Foremen responded to the scene with an estimated arrival time of 3:30 p.m. CT.

To facilitate access for EMS and first responders, the crew reversed the train to the location of the incident. The trespasser was pronounced deceased at the scene, resulting in a confirmed fatality. The crew did not request relief and advised they were willing to continue operating the train once released, although a potential Hours of Service conflict was anticipated. Following completion of the police and coroner's investigation, Train 4(05) was released and departed Galesburg Station, Galesburg, Illinois, at 2:08 p.m. CT. A relief conductor from Train 3(07) met the train en route to protect Train 4(05) into Chicago, Illinois.

NRC # 1475602

**WBS#:** B.TR.100150.7252

**National Response Center Number:** 1475602

| Train | Delay | Comment |
|---|---|---|
| 4(05) | 1'50" | |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## *Train 59(06) Yazoo City, MS - Freight Train Interference*

07OCT26: Train 59(06) operating with engines 3602, 7 cars and 157 customers, was delayed departing Yazoo City, MS, on CN Yazoo subdivision due to holding for a stalled CN freight to clear. The CN freight received a helper engine and was able to get back on the move. Trian 59(06) then followed them for 15 miles.

| Train | Delay | Comment |
|---|---|---|
| 59(06) | 1'05" | HOLDING YAZ |
| 59(06) | 1'49" | FOLLOWING STALLED FRT |

## *Union Pacific Martinez Subdivision, West of Martinez, CA - Signal*

07OCT26: There was a signal outage that had occurred at Costa (MP 27.5) on the Union Pacific Martinez Subdivision, 4 miles west of the Martinez, CA station. A Union Pacific Signal Maintainer made repairs at 10:35A-PT

Train 710(07), Train 529(07), Train 526(07), Train 531(07) and Train 6(07) were delayed flagging between Hercules (MP 30.1) and Hercules (MP 20.8).

Train 528(07), Train 535(07), Train 711(07) and Train 712(07) were delayed account of residual train interference.

| Train | Delay | Comment |
|---|---|---|
| 710(07) | 51" | |
| 526(07) | 46" | |
| 529(07) | 19" | |
| 531(07) | 30" | |
| 6(07) | 1'39" | |
| 528(07) | 13" | |
| 535(07) | 08" | |
| 711(07) | 06" | |
| 712(07) | 06" | |

## *Train 5(06) East of Denver, CO - Trespasser Incident*

07OCT26: Train 5(06), operating with engines 45/5, eight coaches and 191 customers, was delayed 40 miles east of Denver Colorodo, on BNSF Brush subdivision, due to a milk truck over turning on the tracks, following a car crash. Local police arrived on the scene with wreck equipment and tow trucks to remove the vehicle from the tracks. Due to the weight of the overturned truck, Milk had to be siphoned out of the truck before it could be removed. UPRR personnel also responded to the scene, including management and track inspector. Once the vehicle was removed and the tracks were inspected, train 5(06) was able to proceed.

Due to Hours of Service constraints the outbound crew from Denver, CO, was dispatched to meet train 5(06) enroute to relieve them.

| Train | Delay | Comment |
|---|---|---|
| 5(06) | 3'16" | |

## *Train 503(07) North of Tacoma, WA - Signal / Switch Failure*

07OCT26: Train 503(07) was delayed at Sumner (MP 29.7X) on the Burlington Northern Santa Fe Seattle Subdivision, 10 miles north of the Tacoma, WA station, meeting commuter Sound Transit 303/327. The delay was a result of a switch failure at Stewart (MP 34.0X).

| Train | Delay | Comment |
|---|---|---|
| 503(07) | 30" | |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

## Train 14(06) South of Redding, CA - Freight Train Interference

07OCT26: Train 14(06) with 21 customers was delayed at Culp (MP 244.9) on the Union Pacific Valley Subdivision, 13 miles south of RDD, while meeting freight MHKRV-05 (UP 5793).

| Train | Delay | Comment |
|---|---|---|
| 14(06) | 42" | |

## Train 1(05)/421(04) West of Palm Springs, CA - Freight Train Interference

07OCT26: Train 1(05)/421(04) was delayed between West Palm Springs (MP 581.7) and Ordway (MP 548.1) on the Union Pacific Yuma Subdivision, beginning 7 miles west of the Palm Springs, CA station, while following freight train ZG2LC-04 (UP 7713).

| Train | Delay | Comment |
|---|---|---|
| 1(05)/421(04) | 39" | |

## Train 21(06) North of Hope, AR - Freight Train Interference

07OCT26: Train 21(06) operating with engine 63, nine coaches and 127 customers, was delayed 16 miles north of Hope Texas, on UPRR Little Rock subdivision, due to holding at Prescott siding due to UP8188 train setting out a car for a hot bearing. Once the car was set up and the freight cleared, train 21(06) was able to proceed.

| Train | Delay | Comment |
|---|---|---|
| 21(06) | 41" | |

## Train 4(06) West of Kingman, AZ - Passenger Train Interference

07OCT26: Train 4(06) with 194 customers was delayed on the BNSF Seligman subdivision 11 miles west of Kingman due to meeting train 3(05) at East Griffith/MP 526.9.

| Train | Delay | Comment |
|---|---|---|
| 4(06) | 47" | |

## Train 6(06) East of Elko, NV - Injured or Sick Passenger or Employee

07OCT26: Train 6(06) with 129 customers was delayed on the UPRR Shafter subdivision 61 miles east of Elko at Wells/MP 719.3 due to meeting EMS for a customer medical emergency.

| Train | Delay | Comment |
|---|---|---|
| 6(06) | 36" | |

## *Tropical Storm Isaias- Weather*



07OCT26: Tropical Storm Isaias formed in the southern Gulf and was forecast to strengthen into a hurricane before making landfall near Mobile Bay. Damaging winds, flooding rain, storm surge, and tornadoes were expected across portions of the U.S. Gulf Coast, particularly Alabama, eastern Mississippi, eastern Louisiana, and the western Florida Panhandle. Due to the anticipated storm impacts, Crescent and Mardi Gras service will be modified.
Crescent
Train 19(07) will terminate at the Atlanta, GA station. Alternate transportation will be provided by 3 buses.
Trains 19(08-10) will terminate at the Atlanta, GA station. No alternate transportation will be provided.
Train 20(08) will originate at the Atlanta, GA station. Alternate transportation will be provided by 3 buses.
Trains 20(09-11) will originate at the Atlanta, GA station. No alternate transportation will be provided.
Train 19(11) is expected to operate through to the New Orleans, LA Union Passenger Terminal.
Train 20(12) is expected to originate at the New Orleans, LA Union Passenger Terminal.
Mardi Gras
Train 23(08) will operate as scheduled from the Mobile, AL station to the New Orleans, LA Union Passenger Terminal.
Trains 23(09-11) will be canceled. No alternate transportation will be provided.
Train 24(08) will be canceled. Alternate transportation will be provided by 2 buses.
Trains 24(09-11) will be canceled. No alternate transportation will be provided.
Trains 25(08-11) and 26(08-10) will be canceled. No alternate transportation will be provided.
Train 26(11) is expected to operate from the New Orleans, LA Union Passenger Terminal to the Mobile, AL station, restoring full service on October 12, 2026.

WBS Number: 1 B.TR.100150.7249 has been issued for all service adjustments related to Tropical Storm Isaias.

**WBS#: B.TR.100150.7249**

## *Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions*

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

| Train | Delay | Comment |
|---|---|---|
| 822(29) | 32" | |
| 821(29) | 27" | |
| 821(30) | 34" | |
| 822(30) | 30" | |
| 822(01) | 30" | |
| 821(02) | 34" | |
| 822(02) | 29" | |
| 822(03) | 33" | |
| 821(03) | 25" | |
| 821(04) | 35" | |
| 822(04) | 32" | |
| 821(05) | 35" | |
| 822(05) | 26" | |
| 821(06) | 26" | |
| 822(06) | 37" | |

# Maintenance of Way Highlights

27-FOI-00946 00000908852 "UNCLASSIFIED" 10/19/2026

## *BNSF Fort Worth Subdivision Track Work - Texas Eagle Service TW 27-007*

05OCT26: BNSF will perform tie replacement work on the Fort Worth Subdivision north of Temple, TX/MP218.2, between MP230 and MP245 beginning Monday October 5th through Friday October 9th. The work curfew will be from 630AM until 1230PM on the scheduled work days. To accommodate this infrastructure work, Amtrak's Texas Eagle Service will be adjusted as follows:

- Train 22(05-09) will depart San Antonio, TX, 59 minutes later, depart Fort Worth, TX, 30 minutes later and resume normal schedule upon departure from Dallas, TX.
- Train 422(04, 07) will depart San Antonio, 59 minutes later, depart Fort Worth 30 minutes later and resume normal schedule upon departure from Dallas.

**WBS#: B.TR.100150.7225**

| Train | Delay | Comment |
|---|---|---|
| 22(06)/422(04) | 55" | N/TPL, slow orders |
| 22(07) | 35" | |

## *CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006*

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

**WBS#: B.TR.100150.7220**

## *Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082*

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

27-FOI-00046 000000089852 "UNCLASSIFIED" 10/19/2026

## *CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075*

26JUL26: CN rail production gang will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

**WBS#: B.TR.100150.6867**

| Train | Delay | Comment |
|---|---|---|
| 59(21) | Terminated MEM | |

## *BNSF Southwest Chief Service - Scheduled M/W Work 26-049*

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

**WBS#: B.TR.100150.6626**

## *Metra C&M Subdivision - Scheduled M/W Work 26-055*

27-FOI-00048 0000000008952 "UNCLASSIFIED" 10/19/2026

16MAY26: Metra has track work scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

**WBS#: B.TR.100150.6663**

# Western Region

## Equipment Set Out & Damage Disposition

| Train | Location | Eng | Car | Reason/Disposition |
|---|---|---|---|---|
| 8(7) | EPH | | 34094 | Flat spots |

## Leased Freight Locomotives

| Train | Location | Eng | Purpose | Location Returned | Date Returned |
|---|---|---|---|---|---|
| None | | | | | |

## Pair Only Locomotives

| Loco | Date Failed | Train Failed | Failure | Date OK'd as single | OK'd as single by: |
|---|---|---|---|---|---|
| None | | | | | |

# Western Region

## Displaced Guests

| Train | Number of Guests | Planned (Yes/No) | Details |
|---|---|---|---|
| None | | | |

## Physical Distancing

| Train | Number of Passengers Re-accommodated | Seating Option Provided (café, dining car, other) | Segment Customer Occupied Temporary Space (stations) |
|---|---|---|---|
| None | | | |

## Standees

| | Projected Need | | Number Operated | | | |
|---|---|---|---|---|---|---|
| Train | Cars | Seats | Cars | Seats | Standees | Location |
| None | | | | | | |

## Misconnects

| Station | From Train | To Train | Passengers | Rooms | Cost |
|---|---|---|---|---|---|
| None | | | | | |

## Carry-By

| Train | Location | Passengers | Disposition | Cost |
|---|---|---|---|---|
| | | | | N/A |

## Station Service Recovery

| Train/Bus | Station | # of Psgr's | Type of Service Recovery | Cost |
|---|---|---|---|---|
| None | | | | |

## Passenger Removals and/or Isolations

### *Train 318(07) Passenger Removal at Bloomington-Normal, Illinois – Medical*

07OCT26, Passenger on PNR 0E04DE, traveling from St. louis, MO to Bloomington-Normal, IL was removed from the train by Normal Illinois Police and EMS. The passenger missed their stop and after being told the train couldn't make a stop the passenger had a panic attack to make the train stop. Amtrak Police notified.

**Delay: 318(07) 10"**

## Consist Deviations

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2026

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 27 (07) | CHI | DUE TO NO GOOD BAG COACH OPERATING WITH STANDARD COACH AND BAGGAGE CAR TO ACCOMMODATE PASSENGER BAGGAGE. INVENTORY HAS BEEN ADJUSTED TO REFLECT THE CHANGE. | No impact | 0 | 34065 61064 |
| 3 (08) | CHI | Operating with T-Dorm without H room. Schedule change has been performed. CSV will need reaccommodate any passengers impacted by this. | no impact | 0 | 39002 |
| 5 (08) | CHI | Operating with sleeper in lieu of T-Dorm. Schedule change has been performed. CSV will need reaccommodate any passengers impacted by this. | ni impact | 0 | 32002 |
| 6 (11) | EMY | Operating with sleeper in lieu of T-Dorm. Schedule change has been performed. CSV will need reaccommodate any passengers impacted by this. | no impact | 0 | 32002 |
| 562 (07) | LAX | Due to equipment swap operating with only one buisness class short on car. Inventory has been updated to reflect the changes. | NA | 0 | NOCAR |
| 580 (07) | LAX | Due to equipment swap operating with only one buisness class short on car. Inventory has been updated to reflect the changes. | n/a | 0 | NOCAR |
| 4 (10) | LAX | Operating with T-Dorm without H room. Schedule change has been performed. CSV will need reaccommodate any passengers impacted by this. | no impact | 0 | 39002 |
| 572 (08) | LAX | TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 IN ITS CONSIST. PLEASE NOTIFY ALL EFFECTED PAX. | 6 pax notified | 6 | 90215 |
| 43 (07) | NYP | AMI IN PLACE OF AMII | NONE | 0 | 82590 |
| 28 (09) | PDX | DUE TO NO GOOD BAG COACH OPERATING WITH STANDARD COACH AND BAGGAGE CAR TO ACCOMMODATE PASSENGER BAGGAGE. INVENTORY HAS BEEN ADJUSTED TO REFLECT THE CHANGE. | No impact | 0 | 34065 61064 |

| Train Number | Station | Reason | Customer Impact | Affected Psgr | Unit Number(s) |
|---|---|---|---|---|---|
| 42 (08) | PGH | AMI IN PLACE F AMII | NONE | 0 | 82590 |
| 573 (07) | SAN | Due to equipment swap operating with only one buisness class short on car. Inventory has been updated to reflect the changes. | NA | 0 | NOCAR |
| 591 (07) | SAN | Due to equipment swap operating with only one buisness class short on car. Inventory has been updated to reflect the changes. | N/A | 0 | NOCAR |
| 567 (08) | SAN | TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 IN ITS CONSIST. PLEASE NOTIFY ALL EFFECTED PAX. | 6 pax notified | 6 | 90215 |
| 587 (08) | SAN | TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 IN ITS CONSIST. PLEASE NOTIFY ALL EFFECTED PAX. | 6 pax notified | 6 | 90215 |
| 22 (07) | SAS | COACH IN PLACE OF A CREW DORM | THIS WAS UPDATE | 0 | 32057 |
| 22 (07) | SAS | SLEEPER IN PLACE OF CREW DORM | YES | 7 | 32057 |

27-FOI-00046 00000008952 "UNCLASSIFIED" 10/19/2023

**Reverse Consists**

| Train Number | Station | Reason |
|---|---|---|
| 93 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 95 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 190 (07) | PHL | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 110 (07) | PHL | Consist reversed \| Business class seat orientation may have changed \| At Rear |
| 2165 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Rear |
| 193 (07) | NYP | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 137 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |
| 179 (07) | BOS | Consist reversed \| Business class seat orientation may have changed \| At Front |