



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, January 04, 2026

Rules: 0-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-002Initial Terminal Performance By Division

Scheduled Departure Date: 01/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/03/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	272	43	84.2%	853	138	83.8%	28,159	3,813	86.5%
Central Division	85.5%	69	10	85.5%	205	23	88.8%	6,287	690	89.0%
Northeast Division	80.0%	81	16	80.2%	267	47	82.4%	8,883	1,328	85.1%
Southeast Division	72.5%	58	6	89.7%	188	33	82.4%	6,535	913	86.0%
Southwest Division	77.0%	64	11	82.8%	193	35	81.9%	6,454	882	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00217 00000005555 "UNCLASSIFIED" 1/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	92,485	20,050	78%	276,051	64,256	77%	9,600,967	2,103,840	78%
Northeast Corridor	81%	37,933	9,346	75%	117,470	30,885	74%	4,285,392	910,500	79%
Acela	83%	5,678	2,507	56%	19,795	6,938	65%	903,584	217,985	76%
Northeast Regional	79%	32,255	6,839	79%	97,675	23,947	75%	3,381,808	692,515	80%
Richmond / Newport News / Norfolk	77%	10,224	2,006	80%	31,341	6,662	79%	1,033,593	239,750	77%
Springfield Shuttles	89%	624	90	86%	1,941	311	84%	61,651	6,998	89%
Roanoke	79%	2,468	125	95%	7,657	1,067	86%	261,008	43,912	83%
On Spine Northeast Regional	80%	18,939	4,618	76%	56,736	15,907	72%	2,025,556	401,855	80%
State Supported	80%	40,297	6,787	83%	118,341	21,828	82%	4,102,828	787,275	81%
Borealis	60%	434	0	100%	1,202	19	98%	55,159	13,912	75%
Capitol Corridor	90%	3,025	12	100%	7,812	904	88%	328,908	34,819	89%
Carolinian	60%	996	301	70%	3,012	390	87%	110,242	30,739	72%
Cascades	63%	2,617	320	88%	7,909	1,081	86%	228,582	53,449	77%
Downeaster	82%	1,108	0	100%	3,519	127	96%	138,391	17,709	87%
Empire	78%	5,749	638	89%	17,307	4,276	75%	512,787	108,340	79%
Adirondack	72%	521	37	93%	1,507	589	61%	32,607	12,116	63%
Ethan Allen Express	70%	559	22	96%	1,714	457	73%	56,252	16,663	70%
Maple Leaf	70%	815	491	40%	2,371	1,661	30%	60,756	26,936	56%
New York - Albany	85%	2,512	0	100%	7,612	847	89%	232,744	31,053	87%
New York - Niagara Falls	75%	1,342	88	93%	4,103	722	82%	130,428	21,572	83%
Gold Runner	73%	3,035	1,175	61%	7,313	2,867	61%	240,694	88,000	63%
Heartland Flyer	65%	262	138	47%	718	138	81%	20,219	8,431	58%
Hiawatha	90%	1,517	125	92%	4,118	270	93%	163,746	19,872	88%
Illinois	78%	2,127	382	82%	6,730	1,088	84%	230,969	66,201	71%
Carl Sandburg / Illinois Zephyr	85%	485	54	89%	1,424	54	96%	40,435	10,319	74%
Illini / Saluki	85%	772	328	58%	2,314	542	77%	80,309	21,764	73%
Lincoln Service	70%	870	0	100%	2,992	492	84%	110,225	34,118	69%
Keystone	92%	5,133	0	100%	17,343	538	97%	767,788	75,106	90%
Lincoln / Missouri	60%	858	178	79%	2,601	283	89%	75,176	35,551	53%
Mardi Gras Service	80%	420	66	84%	1,360	66	95%	41,002	4,745	88%
Michigan	69%	1,957	829	58%	5,648	2,454	57%	187,067	57,834	69%
Blue Water	70%	205	205	0%	1,033	674	35%	45,549	14,318	69%
Pere Marquette	85%	144	0	100%	660	152	77%	25,141	4,471	82%
Wolverine	65%	1,608	624	61%	3,955	1,628	59%	116,377	39,045	66%
Missouri	80%	274	0	100%	822	152	82%	23,149	5,187	78%
Pacific Surfliner	85%	7,474	2,299	69%	20,970	5,944	72%	640,485	95,024	85%
Pennsylvanian	72%	983	60	94%	2,854	60	98%	88,660	9,280	90%
Piedmont	73%	1,128	235	79%	3,416	328	90%	122,119	28,016	77%
Vermont	75%	1,200	29	98%	3,687	843	77%	127,685	35,060	73%
Long Distance	56%	13,731	3,917	71%	39,089	11,543	70%	1,208,156	405,798	66%
Auto Train	57%	1,107	0	100%	3,085	0	100%	66,952	10,771	84%
California Zephyr	50%	1,164	342	71%	3,462	633	82%	90,107	25,375	72%
Cardinal	55%	316	4	99%	869	272	69%	26,440	11,598	56%
City Of New Orleans	75%	789	0	100%	2,067	73	96%	67,786	14,482	79%
Coast Starlight	60%	722	172	76%	2,960	1,631	45%	112,479	36,421	68%
Crescent	70%	1,041	105	90%	2,738	163	94%	92,843	21,148	77%
Empire Builder	55%	1,231	930	24%	3,545	2,205	38%	98,383	38,649	61%
Floridian	40%	1,981	1,294	35%	5,301	3,224	39%	164,753	90,680	45%
Lake Shore Ltd	73%	1,135	42	96%	2,953	669	77%	93,601	20,096	79%
Palmetto	65%	974	0	100%	2,660	16	99%	92,174	15,233	83%
Silver Meteor	45%	1,118	226	80%	3,043	639	79%	99,663	31,580	68%
Southwest Chief	40%	851	578	32%	2,403	1,116	54%	79,248	47,418	40%
Sunset Ltd	70%	0	0	-	761	118	84%	27,532	6,282	77%
Texas Eagle	50%	1,302	224	83%	3,242	784	76%	96,195	36,065	63%
Seasonal Trains	%	524	0	100%	1,151	0	100%	4,591	267	94%
Winter Park Express	75%	524	0	100%	1,151	0	100%	4,591	267	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00217 00000005555 "UNCLASSIFIED" 1/5/2020

Train Index Dates Through January 03, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	15,898	313,320	507	544,477	10,173,711	535

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	558	84,832	66	21,291	2,966,809	72
INFRASTRUCTURE PLANNED	135	250	84,832	29	15,625	2,966,809	53
FLEET RELIABILITY	90	3,858	313,320	123	86,908	10,173,711	85
TRAIN OPERATIONS	424	11,232	313,320	358	420,653	10,173,711	413

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 01/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/03/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	272	43	84.2%	853	138	83.8%	28,159	3,813	86.5%
Central Division	85.5%	69	10	85.5%	205	23	88.8%	6,287	690	89.0%
Northeast Division	80.0%	81	16	80.2%	267	47	82.4%	8,883	1,328	85.1%
Southeast Division	72.5%	58	6	89.7%	188	33	82.4%	6,535	913	86.0%
Southwest Division	77.0%	64	11	82.8%	193	35	81.9%	6,454	882	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/03/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	272	43	84.2%	853	138	83.8%	28,159	3,813	86.5%
Central Division	85.5%	69	10	85.5%	205	23	88.8%	6,287	690	89.0%
CDL	90.0%	2	0	100.0%	6	0	100.0%	161	8	95.0%
CHI	85.0%	27	6	77.8%	82	10	87.8%	2,548	289	88.7%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	2	0	100.0%	8	2	75.0%
EUG	86.5%	2	1	50.0%	6	1	83.3%	184	27	85.3%
GRR	98.0%	1	0	100.0%	3	0	100.0%	94	3	96.8%
KCY	84.5%	2	0	100.0%	6	1	83.3%	187	16	91.4%
MKE	86.5%	7	0	100.0%	18	0	100.0%	555	46	91.7%
MSP	94.0%	-	-	-	2	0	100.0%	94	3	96.8%
PDX	78.0%	5	0	100.0%	15	2	86.7%	476	63	86.8%
PNT	91.5%	3	0	100.0%	9	1	88.9%	227	23	89.9%
PTH	93.0%	1	0	100.0%	3	1	66.7%	94	8	91.5%
QCY	87.5%	2	0	100.0%	6	0	100.0%	190	17	91.1%
SEA	80.0%	8	1	87.5%	24	5	79.2%	755	124	83.6%
SPK	92.0%	1	1	0.0%	3	1	66.7%	98	6	93.9%
STL	88.0%	4	0	100.0%	12	0	100.0%	375	38	89.9%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	6	0	100.0%	185	6	96.8%
WIP	-	1	1	0.0%	2	1	50.0%	8	1	87.5%
Northeast Division	80.0%	81	16	80.2%	267	47	82.4%	8,883	1,328	85.1%
ALB	91.5%	8	1	87.5%	24	3	87.5%	639	49	92.3%
BON	43.5%	5	0	100.0%	15	0	100.0%	456	44	90.4%
BOS	86.5%	15	5	66.7%	50	14	72.0%	1,730	223	87.1%
BRK	88.0%	5	0	100.0%	15	2	86.7%	436	22	95.0%
BTN	48.0%	1	0	100.0%	3	0	100.0%	94	18	80.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	6	1	83.3%	182	16	91.2%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	3	1	66.7%	95	18	81.1%
NFL	96.5%	2	1	50.0%	6	1	83.3%	191	9	95.3%
NHV	75.5%	4	2	50.0%	14	4	71.4%	493	85	82.8%
NYP	77.5%	30	6	80.0%	106	20	81.1%	3,734	783	79.0%
SAB	98.0%	1	0	100.0%	3	0	100.0%	93	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	6	0	100.0%	19	0	100.0%	580	24	95.9%
TWO	84.0%	1	0	100.0%	3	1	66.7%	93	20	78.5%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	58	6	89.7%	188	33	82.4%	6,535	913	86.0%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	15	0	100.0%	475	37	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	7	2	71.4%	27	12	55.6%	1,056	202	80.9%
LOR	69.5%	1	0	100.0%	3	0	100.0%	95	9	90.5%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 01/03/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 01/03/2026			ITP January 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	272	43	84.2%	853	138	83.8%	28,159	3,813	86.5%
Southeast Division	72.5%	58	6	89.7%	188	33	82.4%	6,535	913	86.0%
MIA	87.5%	2	0	100.0%	6	0	100.0%	190	19	90.0%
MOE	94.0%	2	0	100.0%	6	0	100.0%	190	3	98.4%
NFK	86.0%	3	2	33.3%	8	2	75.0%	266	30	88.7%
NOL	92.0%	5	0	100.0%	13	0	100.0%	420	20	95.2%
NPN	96.0%	2	0	100.0%	6	0	100.0%	165	10	93.9%
PGH	92.0%	1	0	100.0%	3	0	100.0%	95	3	96.8%
PHL	45.0%	4	2	50.0%	13	8	38.5%	436	225	48.4%
RGH	97.0%	4	0	100.0%	12	0	100.0%	376	9	97.6%
RNK	85.5%	2	0	100.0%	6	2	66.7%	189	23	87.8%
RVM	86.0%	1	0	100.0%	3	0	100.0%	105	13	87.6%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	3	0	100.0%	95	2	97.9%
SFA	70.5%	1	0	100.0%	3	1	66.7%	95	4	95.8%
WAS	70.0%	17	0	100.0%	61	8	86.9%	2,279	299	86.9%
Southwest Division	77.0%	64	11	82.8%	193	35	81.9%	6,454	882	86.3%
ARN	60.5%	1	0	100.0%	3	0	100.0%	95	7	92.6%
BFD	75.5%	7	1	85.7%	21	3	85.7%	573	138	75.9%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	3	1	66.7%	102	37	63.7%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	3	0	100.0%	94	3	96.8%
GTA	72.5%	3	1	66.7%	9	1	88.9%	278	26	90.6%
LAX	77.5%	9	1	88.9%	28	3	89.3%	880	95	89.2%
OKC	96.0%	1	0	100.0%	3	0	100.0%	95	3	96.8%
OKJ	79.0%	8	3	62.5%	24	9	62.5%	1,023	251	75.5%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	11	1	90.9%	33	3	90.9%	1,250	132	89.4%
SAN	77.0%	12	1	91.7%	36	8	77.8%	1,093	99	90.9%
SAS	85.0%	1	0	100.0%	3	0	100.0%	95	4	95.8%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	21	6	71.4%	663	65	90.2%
SLO	62.0%	2	1	50.0%	6	1	83.3%	184	16	91.3%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		3	0	100.0%	95	12	87.4%	3	0	100.0%	94	36	61.7%
4	33	3	0	100.0%	94	14	85.1%	3	2	33.3%	94	61	35.1%
5		3	0	100.0%	94	15	84.0%	3	0	100.0%	92	13	85.9%
6	68	3	1	66.7%	93	30	67.7%	3	1	66.7%	93	28	69.9%
7	152	3	0	100.0%	95	10	89.5%	3	1	66.7%	91	16	82.4%
8	102	3	2	33.3%	95	41	56.8%	3	2	33.3%	95	47	50.5%
11	221	3	1	66.7%	94	19	79.8%	3	1	66.7%	92	16	82.6%
14		3	0	100.0%	95	10	89.5%	3	2	33.3%	94	23	75.5%
19		3	1	66.7%	95	19	80.0%	3	0	100.0%	95	13	86.3%
20		3	0	100.0%	95	6	93.7%	3	0	100.0%	95	8	91.6%
21		3	0	100.0%	94	13	86.2%	3	0	100.0%	94	18	80.9%
22		3	0	100.0%	95	4	95.8%	3	1	66.7%	94	20	78.7%
23		3	0	100.0%	95	3	96.8%	3	0	100.0%	95	13	86.3%
24		3	0	100.0%	95	7	92.6%	3	0	100.0%	95	9	90.5%
25	19	3	0	100.0%	95	0	100.0%	3	1	66.7%	95	11	88.4%
26		3	0	100.0%	95	2	97.9%	3	0	100.0%	95	14	85.3%
27	63	3	3	0.0%	95	5	94.7%	3	1	66.7%	94	21	77.7%
28	152	3	1	66.7%	94	21	77.7%	3	1	66.7%	94	13	86.2%
40		3	0	100.0%	95	14	85.3%	3	1	66.7%	95	35	63.2%
41	36	3	1	66.7%	95	34	64.2%	3	3	0.0%	95	61	35.8%
42		3	0	100.0%	95	3	96.8%	3	0	100.0%	95	12	87.4%
43		3	0	100.0%	95	8	91.6%	3	0	100.0%	95	4	95.8%
48		3	1	66.7%	95	14	85.3%	3	0	100.0%	95	10	89.5%
49		3	1	66.7%	95	15	84.2%	3	1	66.7%	95	14	85.3%
51		1	0	100.0%	41	18	56.1%	2	0	100.0%	40	12	70.0%
52		3	1	66.7%	95	4	95.8%	3	0	100.0%	95	14	85.3%
53		3	0	100.0%	95	9	90.5%	3	0	100.0%	95	13	86.3%
54		2	0	100.0%	30	0	100.0%	2	0	100.0%	30	4	86.7%
57		2	0	100.0%	30	1	96.7%	2	0	100.0%	30	1	96.7%
58		3	0	100.0%	94	3	96.8%	3	0	100.0%	93	14	84.9%
59		3	0	100.0%	93	7	92.5%	3	0	100.0%	93	9	90.3%
63	62	3	2	33.3%	95	41	56.8%	3	2	33.3%	94	50	46.8%
64		3	1	66.7%	94	21	77.7%	3	0	100.0%	94	21	77.7%
65		2	0	100.0%	31	5	83.9%	2	0	100.0%	30	7	76.7%
66		3	2	33.3%	95	15	84.2%	3	1	66.7%	95	20	78.9%
68		3	1	66.7%	95	18	81.1%	3	2	33.3%	95	48	49.5%
69		3	1	66.7%	95	12	87.4%	3	0	100.0%	95	13	86.3%
71		3	0	100.0%	95	1	98.9%	3	0	100.0%	95	24	74.7%
72		3	0	100.0%	95	10	89.5%	3	0	100.0%	95	23	75.8%
73	24	3	0	100.0%	95	3	96.8%	3	2	33.3%	94	46	51.1%
74		3	0	100.0%	95	7	92.6%	3	1	66.7%	95	26	72.6%
75		3	0	100.0%	95	3	96.8%	3	0	100.0%	95	39	58.9%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		3	0	100.0%	95	4	95.8%	3	1	66.7%	95	36	62.1%
77		3	0	100.0%	95	4	95.8%	3	0	100.0%	95	31	67.4%
78		3	0	100.0%	95	5	94.7%	3	0	100.0%	95	12	87.4%
79		3	0	100.0%	95	21	77.9%	3	0	100.0%	94	15	84.0%
80		3	0	100.0%	95	11	88.4%	3	0	100.0%	94	10	89.4%
82		2	1	50.0%	16	1	93.8%	2	0	100.0%	16	1	93.8%
87		2	1	50.0%	30	7	76.7%	2	0	100.0%	30	5	83.3%
88		2	1	50.0%	30	2	93.3%	2	0	100.0%	30	4	86.7%
89		3	0	100.0%	95	18	81.1%	3	0	100.0%	95	15	84.2%
90		3	0	100.0%	95	2	97.9%	3	0	100.0%	95	9	90.5%
97		3	2	33.3%	95	43	54.7%	3	1	66.7%	95	20	78.9%
98		3	0	100.0%	95	5	94.7%	3	0	100.0%	95	24	74.7%
99	41	2	1	50.0%	30	3	90.0%	2	1	50.0%	29	13	55.2%
101		2	0	100.0%	16	1	93.8%	2	0	100.0%	16	0	100.0%
103		2	1	50.0%	30	4	86.7%	2	1	50.0%	30	2	93.3%
106		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	3	90.0%
107		2	1	50.0%	30	7	76.7%	2	0	100.0%	30	2	93.3%
118		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	2	93.3%
124		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	4	86.7%
135	26	2	1	50.0%	30	6	80.0%	2	2	0.0%	30	16	46.7%
136		1	0	100.0%	65	7	89.2%	2	0	100.0%	66	5	92.4%
140		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	6	80.0%
142		2	0	100.0%	16	0	100.0%	2	0	100.0%	16	0	100.0%
143		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	3	90.0%
144		2	2	0.0%	17	10	41.2%	2	1	50.0%	17	1	94.1%
146		2	0	100.0%	30	5	83.3%	2	1	50.0%	30	10	66.7%
147		2	0	100.0%	16	3	81.3%	2	0	100.0%	16	2	87.5%
150	19	2	0	100.0%	30	22	26.7%	2	2	0.0%	30	21	30.0%
151		3	0	100.0%	95	30	68.4%	3	0	100.0%	94	25	73.4%
152		2	0	100.0%	16	0	100.0%	2	0	100.0%	16	4	75.0%
153		2	0	100.0%	30	2	93.3%	2	0	100.0%	30	3	90.0%
155		2	0	100.0%	30	3	90.0%	2	0	100.0%	30	4	86.7%
156		2	0	100.0%	30	3	90.0%	2	0	100.0%	30	5	83.3%
158		2	0	100.0%	30	0	100.0%	2	0	100.0%	30	1	96.7%
159	19	2	1	50.0%	16	2	87.5%	2	1	50.0%	16	1	93.8%
160		2	0	100.0%	30	0	100.0%	2	1	50.0%	28	5	82.1%
161	38	2	0	100.0%	30	1	96.7%	2	2	0.0%	30	17	43.3%
162		2	0	100.0%	30	2	93.3%	2	1	50.0%	30	12	60.0%
163	109	2	1	50.0%	16	3	81.3%	2	2	0.0%	16	10	37.5%
164		2	0	100.0%	30	4	86.7%	2	0	100.0%	30	9	70.0%
165		2	1	50.0%	30	9	70.0%	2	1	50.0%	30	9	70.0%
168	25	2	0	100.0%	16	2	87.5%	2	2	0.0%	16	6	62.5%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		1	0	100.0%	65	10	84.6%	2	0	100.0%	66	9	86.4%
179		1	0	100.0%	65	6	90.8%	2	0	100.0%	66	14	78.8%
194		2	0	100.0%	16	3	81.3%	2	0	100.0%	16	2	87.5%
195		2	0	100.0%	30	0	100.0%	2	1	50.0%	30	20	33.3%
232		3	0	100.0%	95	2	97.9%	3	0	100.0%	95	6	93.7%
233		3	1	66.7%	95	25	73.7%	3	2	33.3%	95	22	76.8%
234		3	0	100.0%	95	4	95.8%	3	0	100.0%	95	3	96.8%
235		3	0	100.0%	34	5	85.3%	3	0	100.0%	34	6	82.4%
236		3	0	100.0%	95	1	98.9%	3	0	100.0%	95	16	83.2%
237		3	0	100.0%	94	15	84.0%	3	1	66.7%	93	8	91.4%
238		3	1	66.7%	34	7	79.4%	3	0	100.0%	34	3	91.2%
239		3	0	100.0%	94	24	74.5%	3	0	100.0%	94	4	95.7%
240		3	0	100.0%	95	9	90.5%	3	0	100.0%	95	12	87.4%
241		3	0	100.0%	95	24	74.7%	3	0	100.0%	95	14	85.3%
244		3	0	100.0%	95	5	94.7%	3	0	100.0%	95	18	81.1%
280		3	0	100.0%	95	4	95.8%	3	0	100.0%	95	17	82.1%
281		3	0	100.0%	95	9	90.5%	3	1	66.7%	95	11	88.4%
283		3	0	100.0%	95	20	78.9%	3	0	100.0%	95	15	84.2%
284		3	1	66.7%	95	4	95.8%	3	0	100.0%	94	7	92.6%
290		3	0	100.0%	95	19	80.0%	3	1	66.7%	94	32	66.0%
291		3	0	100.0%	95	18	81.1%	3	0	100.0%	95	15	84.2%
300		3	0	100.0%	95	10	89.5%	3	0	100.0%	94	25	73.4%
301		3	0	100.0%	93	2	97.8%	3	0	100.0%	92	16	82.6%
302		3	0	100.0%	92	11	88.0%	3	0	100.0%	90	27	70.0%
305		3	1	66.7%	95	13	86.3%	3	1	66.7%	93	36	61.3%
306	No OS	3	0	100.0%	93	6	93.5%	3	1	66.7%	92	21	77.2%
307		3	1	66.7%	94	12	87.2%	3	1	66.7%	93	21	77.4%
311		3	0	100.0%	94	10	89.4%	3	1	66.7%	93	21	77.4%
316		3	0	100.0%	93	5	94.6%	3	0	100.0%	93	18	80.6%
318		3	1	66.7%	95	12	87.4%	3	0	100.0%	94	37	60.6%
319		3	0	100.0%	95	4	95.8%	3	0	100.0%	95	48	49.5%
330		2	0	100.0%	79	2	97.5%	2	0	100.0%	79	5	93.7%
331		3	0	100.0%	95	11	88.4%	3	0	100.0%	95	14	85.3%
332		3	0	100.0%	95	9	90.5%	3	0	100.0%	95	16	83.2%
334	15	3	0	100.0%	95	2	97.9%	3	1	66.7%	94	13	86.2%
335		3	0	100.0%	95	14	85.3%	3	0	100.0%	93	17	81.7%
336		3	0	100.0%	95	4	95.8%	3	0	100.0%	95	5	94.7%
337		3	0	100.0%	95	5	94.7%	3	0	100.0%	95	12	87.4%
338		3	0	100.0%	95	21	77.9%	3	0	100.0%	93	22	76.3%
339	162	3	1	66.7%	95	21	77.9%	3	2	33.3%	95	21	77.9%
341		3	0	100.0%	92	16	82.6%	2	0	100.0%	90	14	84.4%
342		3	0	100.0%	95	8	91.6%	2	0	100.0%	93	16	82.8%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
343	88	1	1	0.0%	14	2	85.7%	1	1	0.0%	14	5	64.3%
350	20	3	1	66.7%	77	4	94.8%	3	3	0.0%	77	44	42.9%
351		3	1	66.7%	95	14	85.3%	3	0	100.0%	95	38	60.0%
352	143	3	0	100.0%	95	7	92.6%	3	2	33.3%	92	28	69.6%
353		3	0	100.0%	74	5	93.2%	3	0	100.0%	74	16	78.4%
354	143	3	1	66.7%	95	9	90.5%	3	3	0.0%	93	31	66.7%
355		3	0	100.0%	94	9	90.4%	3	2	33.3%	93	27	71.0%
364	83	3	1	66.7%	94	18	80.9%	3	1	66.7%	93	21	77.4%
365	35	3	1	66.7%	94	8	91.5%	3	3	0.0%	93	31	66.7%
370	53	3	1	66.7%	95	6	93.7%	3	2	33.3%	95	18	81.1%
371		3	0	100.0%	94	3	96.8%	3	0	100.0%	94	11	88.3%
380		3	0	100.0%	95	15	84.2%	3	0	100.0%	95	21	77.9%
381		3	0	100.0%	95	2	97.9%	3	0	100.0%	95	11	88.4%
382	No OS	3	0	100.0%	95	2	97.9%	3	1	66.7%	95	24	74.7%
383		3	0	100.0%	95	9	90.5%	3	0	100.0%	93	36	61.3%
390		3	0	100.0%	79	9	88.6%	3	1	66.7%	78	26	66.7%
391		3	0	100.0%	80	2	97.5%	3	0	100.0%	78	15	80.8%
392	20	3	0	100.0%	95	4	95.8%	3	1	66.7%	94	29	69.1%
393	35	3	0	100.0%	95	7	92.6%	3	1	66.7%	94	26	72.3%
400		2	0	100.0%	28	2	92.9%	2	0	100.0%	27	1	96.3%
405		2	0	100.0%	26	0	100.0%	2	0	100.0%	26	2	92.3%
448		3	1	66.7%	36	14	61.1%	3	1	66.7%	34	13	61.8%
449		3	0	100.0%	33	1	97.0%	3	0	100.0%	33	5	84.8%
450		2	1	50.0%	27	9	66.7%	2	0	100.0%	27	8	70.4%
460	57	3	3	0.0%	29	15	48.3%	2	2	0.0%	26	9	65.4%
461		2	0	100.0%	29	3	89.7%	2	0	100.0%	29	1	96.6%
463		2	0	100.0%	15	1	93.3%	2	0	100.0%	15	0	100.0%
464		2	0	100.0%	27	4	85.2%	2	0	100.0%	27	8	70.4%
467		2	0	100.0%	15	1	93.3%	2	0	100.0%	14	0	100.0%
488		2	1	50.0%	30	8	73.3%	1	0	100.0%	26	4	84.6%
499		2	1	50.0%	27	4	85.2%	1	0	100.0%	26	2	92.3%
500		3	0	100.0%	95	6	93.7%	3	0	100.0%	94	10	89.4%
502		3	1	66.7%	95	8	91.6%	2	0	100.0%	93	21	77.4%
503		3	0	100.0%	92	11	88.0%	3	0	100.0%	91	22	75.8%
504		3	1	66.7%	95	9	90.5%	3	1	66.7%	94	26	72.3%
505		3	1	66.7%	95	17	82.1%	3	1	66.7%	93	18	80.6%
506		3	0	100.0%	94	14	85.1%	3	0	100.0%	93	13	86.0%
507	16	3	1	66.7%	95	12	87.4%	3	1	66.7%	95	33	65.3%
508		3	0	100.0%	93	20	78.5%	3	0	100.0%	93	22	76.3%
509		3	0	100.0%	95	7	92.6%	3	0	100.0%	95	25	73.7%
511		3	0	100.0%	95	10	89.5%	3	0	100.0%	95	17	82.1%
516	24	3	0	100.0%	93	9	90.3%	3	1	66.7%	93	39	58.1%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
517		3	0	100.0%	95	2	97.9%	3	0	100.0%	94	31	67.0%
518		3	0	100.0%	95	13	86.3%	3	2	33.3%	95	56	41.1%
519		3	0	100.0%	93	4	95.7%	3	1	66.7%	93	15	83.9%
562		3	0	100.0%	93	11	88.2%	2	0	100.0%	91	9	90.1%
564		3	0	100.0%	93	9	90.3%	2	0	100.0%	88	12	86.4%
566		3	0	100.0%	93	6	93.5%	3	1	66.7%	90	9	90.0%
572		3	1	66.7%	92	8	91.3%	2	0	100.0%	89	18	79.8%
573		3	2	33.3%	93	14	84.9%	3	1	66.7%	91	11	87.9%
577		3	1	66.7%	91	8	91.2%	2	0	100.0%	86	8	90.7%
580		3	1	66.7%	93	3	96.8%	3	0	100.0%	93	9	90.3%
581		3	2	33.3%	93	12	87.1%	3	1	66.7%	93	17	81.7%
582		3	1	66.7%	93	7	92.5%	3	0	100.0%	91	7	92.3%
586	16	3	0	100.0%	93	19	79.6%	3	1	66.7%	88	12	86.4%
587		3	0	100.0%	93	5	94.6%	3	1	66.7%	89	12	86.5%
591		3	0	100.0%	93	2	97.8%	3	0	100.0%	92	8	91.3%
593		3	1	66.7%	93	15	83.9%	3	0	100.0%	85	9	89.4%
595		3	0	100.0%	92	19	79.3%	3	0	100.0%	91	14	84.6%
611		2	2	0.0%	16	13	18.8%	2	1	50.0%	16	2	87.5%
624		1	1	0.0%	65	20	69.2%	2	0	100.0%	66	14	78.8%
660		2	1	50.0%	30	3	90.0%	2	1	50.0%	30	12	60.0%
661		2	0	100.0%	30	3	90.0%	2	0	100.0%	30	6	80.0%
662		2	0	100.0%	18	0	100.0%	2	0	100.0%	18	0	100.0%
663		2	0	100.0%	30	3	90.0%	2	0	100.0%	30	1	96.7%
664		2	1	50.0%	30	6	80.0%	2	0	100.0%	30	1	96.7%
665		2	0	100.0%	30	6	80.0%	2	0	100.0%	30	11	63.3%
666		2	2	0.0%	30	12	60.0%	2	0	100.0%	30	3	90.0%
667		2	0	100.0%	30	3	90.0%	2	0	100.0%	30	6	80.0%
669		2	1	50.0%	30	3	90.0%	2	0	100.0%	30	10	66.7%
670		2	1	50.0%	30	5	83.3%	2	0	100.0%	30	2	93.3%
671		2	1	50.0%	30	2	93.3%	2	0	100.0%	30	4	86.7%
672		2	1	50.0%	30	4	86.7%	2	0	100.0%	30	2	93.3%
674		2	1	50.0%	30	9	70.0%	2	0	100.0%	30	0	100.0%
690		1	0	100.0%	27	0	100.0%	1	0	100.0%	27	1	96.3%
691		1	0	100.0%	27	2	92.6%	1	0	100.0%	27	6	77.8%
692		1	0	100.0%	27	1	96.3%	1	0	100.0%	27	7	74.1%
693		1	0	100.0%	27	3	88.9%	1	0	100.0%	27	7	74.1%
694		1	0	100.0%	27	4	85.2%	1	0	100.0%	27	3	88.9%
695		1	0	100.0%	27	3	88.9%	1	0	100.0%	27	5	81.5%
696		1	0	100.0%	27	1	96.3%	1	0	100.0%	27	5	81.5%
697		1	0	100.0%	27	3	88.9%	1	0	100.0%	27	5	81.5%
698		1	0	100.0%	27	0	100.0%	1	0	100.0%	27	3	88.9%
701		3	0	100.0%	27	6	77.8%	3	0	100.0%	27	2	92.6%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
702		3	0	100.0%	95	17	82.1%	3	0	100.0%	94	24	74.5%
703		3	0	100.0%	95	24	74.7%	3	2	33.3%	95	26	72.6%
704		3	0	100.0%	27	3	88.9%	3	0	100.0%	26	5	80.8%
710		3	3	0.0%	95	38	60.0%	3	1	66.7%	95	35	63.2%
711		3	0	100.0%	89	8	91.0%	2	0	100.0%	81	12	85.2%
712	19	3	1	66.7%	95	23	75.8%	3	2	33.3%	93	35	62.4%
713		3	0	100.0%	92	12	87.0%	2	0	100.0%	80	33	58.8%
714		3	2	33.3%	89	32	64.0%	3	1	66.7%	82	26	68.3%
715	21	3	0	100.0%	95	30	68.4%	3	3	0.0%	88	46	47.7%
716		3	2	33.3%	95	42	55.8%	3	1	66.7%	93	42	54.8%
717		3	1	66.7%	86	24	72.1%	2	0	100.0%	78	28	64.1%
718	19	3	1	66.7%	95	40	57.9%	3	1	66.7%	94	30	68.1%
719		3	2	33.3%	95	37	61.1%	3	0	100.0%	93	32	65.6%
720		3	0	100.0%	33	2	93.9%	3	0	100.0%	33	1	97.0%
723		3	0	100.0%	33	3	90.9%	3	0	100.0%	33	3	90.9%
724		3	1	66.7%	33	1	97.0%	3	2	33.3%	33	4	87.9%
727		3	0	100.0%	33	3	90.9%	3	1	66.7%	33	7	78.8%
728		3	1	66.7%	33	3	90.9%	3	0	100.0%	33	5	84.8%
729		3	0	100.0%	33	3	90.9%	3	0	100.0%	33	7	78.8%
732		3	0	100.0%	33	5	84.8%	3	0	100.0%	33	4	87.9%
733		3	0	100.0%	33	3	90.9%	3	1	66.7%	29	8	72.4%
734		3	0	100.0%	33	9	72.7%	3	0	100.0%	33	6	81.8%
738		3	2	33.3%	33	7	78.8%	3	0	100.0%	31	2	93.5%
741		3	0	100.0%	33	7	78.8%	3	0	100.0%	33	4	87.9%
742		3	0	100.0%	33	4	87.9%	3	0	100.0%	32	3	90.6%
743		3	2	33.3%	33	6	81.8%	3	0	100.0%	33	2	93.9%
744		3	0	100.0%	33	3	90.9%	3	0	100.0%	33	11	66.7%
745		3	0	100.0%	33	3	90.9%	3	0	100.0%	33	7	78.8%
746		3	1	66.7%	33	1	97.0%	3	1	66.7%	33	3	90.9%
747		3	0	100.0%	33	7	78.8%	3	1	66.7%	33	7	78.8%
749		3	0	100.0%	32	5	84.4%	3	0	100.0%	28	2	92.9%
751		3	1	66.7%	33	8	75.8%	3	0	100.0%	32	5	84.4%
761	Cncld	3	0	100.0%	93	4	95.7%	2	1	50.0%	92	15	83.7%
765	72	3	0	100.0%	93	8	91.4%	3	1	66.7%	93	18	80.6%
769	32	3	1	66.7%	93	8	91.4%	3	1	66.7%	91	19	79.1%
770	33	3	0	100.0%	93	10	89.2%	3	3	0.0%	93	17	81.7%
774		3	0	100.0%	93	7	92.5%	3	2	33.3%	92	21	77.2%
779	82	3	1	66.7%	93	5	94.6%	3	2	33.3%	92	20	78.3%
784	35	3	1	66.7%	93	11	88.2%	3	1	66.7%	92	48	47.8%
785	26	3	0	100.0%	93	0	100.0%	3	1	66.7%	93	15	83.9%
790		3	0	100.0%	93	6	93.5%	3	0	100.0%	93	11	88.2%
794	49	3	1	66.7%	93	9	90.3%	3	1	66.7%	92	17	81.5%

Amtrak On Time Performance

Trains Arriving Through: 1/3/2026

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
821		3	0	100.0%	95	3	96.8%	3	0	100.0%	95	46	51.6%
822	66	3	0	100.0%	95	3	96.8%	3	1	66.7%	95	48	49.5%
1105		2	0	100.0%	8	2	75.0%	2	0	100.0%	8	1	87.5%
1106		2	1	50.0%	8	1	87.5%	2	1	50.0%	8	1	87.5%
1333		3	0	100.0%	95	10	89.5%	2	0	100.0%	93	36	61.3%
1340		3	0	100.0%	95	3	96.8%	3	0	100.0%	95	22	76.8%
1689		2	0	100.0%	19	1	94.7%	2	1	50.0%	19	1	94.7%
2174		1	0	100.0%	16	3	81.3%	2	1	50.0%	16	4	75.0%
2203		2	0	100.0%	16	0	100.0%	2	0	100.0%	16	0	100.0%
2205		2	1	50.0%	30	4	86.7%	2	0	100.0%	30	2	93.3%
2216		2	0	100.0%	16	1	93.8%	2	0	100.0%	16	0	100.0%
2218	46	2	1	50.0%	16	3	81.3%	2	2	0.0%	16	3	81.3%
2248		1	0	100.0%	28	4	85.7%	1	0	100.0%	28	7	75.0%
2249	35	2	1	50.0%	16	1	93.8%	2	2	0.0%	16	6	62.5%
2250	16	2	0	100.0%	30	3	90.0%	2	1	50.0%	30	12	60.0%
2251	30	2	2	0.0%	16	2	87.5%	2	2	0.0%	16	7	56.3%
2252		2	0	100.0%	29	3	89.7%	2	0	100.0%	29	4	86.2%
2253		2	0	100.0%	28	3	89.3%	2	0	100.0%	27	14	48.1%
2254		2	0	100.0%	30	0	100.0%	2	0	100.0%	30	7	76.7%
2255	43	2	0	100.0%	30	4	86.7%	2	1	50.0%	30	11	63.3%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/3/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2218	NYP	46	ENG	38	ENG	9	XPV-WIL	AM	Traction motor, PC/2104, opr 79 MPH a/c transponder not read
2249	WAS	35	CCR	22	CCR	22	NHV-STM	MN	Paragraph lost power eng 2141, 2141
2250	BOS	16	CAR	35	CAR	13	MET-MET	AM	Door, 3655, 3658, GAP FILLER ISSUES ON CAR 3655 AND 3658
2251	WAS	30	ENG	25	ENG	25	BOS-BOS	AM	Other electrical failure, 2125, Due to mechanical issues in the yard equipment is currently being looped due to a DNL on E/2125.
2255	WAS	43	DBS	18	DBS	18	PVD-XGX	AM	Animal strike, Milepost w/Letters, PVD, XGX, AM2255 stopped at trk 1 at MP 151 Cp 23 a/c Deer Strike
99	NPN	41	CAR	43	CAR	36	BOS-BOS	AM	Door, ALL, due to door issues on the whole consist on the old eq.99 now running with E/619(10
135	WAS	26	PTI	18	PTI	15	NLC-NHV	AM	Meet, 82, Other, XBC, AM135 was held for AM82 to run around CD3645 shoving
150	BOS	19	ENG	15	ENG	15	NLC-NLC	AM	HEP, 614, ENG losing HEP.
159	WAS	19	ITI	16	ITI	16	NYP-NYP	AM	Service, turn, or wye train, 9798, DELAYED SSYD A/C AM97 PRIORITY SERVICING
161	WAS	38	PTI	13	PTI	9	BAL-BAL	AM	Cross over or go around, 2253, Milepost, 95.7, ., opr 6 trk for 2253 on 7 trk
163	WAS	109	SVS	78	SVS	78	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, delayed departing the yard due to shopped coach
168	BOS	25	DET	26	DET	26	NYP-XSH	AM	Catenary failure, Other, LOST OVER HEAD POWER LINE , POWER WAS RESTORED ON TEH MOVE
460	SPG	57	SVS	43	SVS	37	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
63	TWO	62	WTR	57	WTR	57	NYP-NYP	AM	Ice / snow on or under equipment, Other, NYP-NYP, LATE F/SSYD A/C UNSPECIFIED WEATHER RELATED PROBLEMS
73	CLT	24	TEN	18	PTI	5	RGH-CYN	NS	Meet #Amt80, Control Point, Fetner
41	MIA	36	SVS	68	SVS	65	PGH-PGH	NS	Fuel Milepost, 353.0, 353.0
25	NOL	19	FTI	60	FTI	31	BAS-XNO	CS	Meet Bridge, industrial canal, x60103

Amtrak Endpoint OTP Details

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 1/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
6	CHI	68	FTI	172	FTI	58	XFJ-DEN	BN	Hold due to freight derailment Derailment in 31st yard, train was blocking all ways of access to Denver Union Station, H DENAMS1 02A, Other, 31st Yard
507	EUG	16	PTI	14	PTI	14	PDX-ORC	UP	Meet AMTK 508, Siding, Clackamas
516	VAC	24	DCS	18	DCS	15	X8B-XF2	BN	PTC system failure (wayside) Lost wayside signal status. PTC signal dropped while in the control point at Annieville and went into penalty., Control Point, 135.4, Control Point, Townsend, Control Point, Annieville
11	LAX	No OS Rpt	PTI	103	WTR	79	SJC-SJC	UP	Landslide / rockslide Waited at San Jose for clearance due to high tide and land slide past San Luis Obispo, Control Point, San jose
7	SEA	152	SYS	224	SYS	223	SPK-SPK	BN	Blocked by or assisting another, disabled Amtrak train Put two cars from train #8 on the rear of train #7. The two cars are as follows 830 sleeper #32016 and the baggage car#61037... Returning to Seattle for repair.
8	CHI	102	FTI	111	FTI	45	GGW-WPT	BN	Meet Duck and tuck behind the bn7120, bn7985, bn8403, Siding, oswego
27	PDX	63	SYS	63	SYS	55	SPK-SPK	BN	Held for train 8 Other, spokane station
28	SPK	152	ENG	175	ENG	125	PDX-PDX	BN	Air / Brake Compressed air leak, 164
822	OKC	66	POL	71	POL	71	FTW-GLE	BN	Right of Way police hold
334	CHI	15	CTI	5	CTI	4	X9L-CHI	AM	Cross Traffic Stopped at Lake, train exiting CUS, Metra, Control Point, Lake
339	MKE	162	ENG	161	ENG	161	CHI-CHI	AM	DEF fuel exhausted on IDTX4608. Replaced with IDTX4613 ID4608
343	MKE	88	CAR	73	CAR	73	CHI-CHI	AM	Set out defective car 4103
350	PNT	20	PTI	36	PTI	13	XB0-XA5	MI	Meet 353, Siding, albion
352	PNT	143	ENG	163	ENG	163	CHI-XTF	AM	Train 352 stopped at Lumber due to PTC failure. The failure was caused by a disconnected speed sensor. 352 forced to shove back into Chicago Union Station so mechanical could fix sensor. After issue was fixed, train 352 left Chicago union station at approximately 4:50pm, ID4606
354	PNT	143	PTI	164	PTI	164	KAL-KAL	MI	Meet Amtrak 355 had a trespasser strike. Held at Kalamazoo for the all clear., Amtrak 355, Control Point, 143
364	PTH	83	SYS	68	SYS	68	CHI-XTF	AM	PTC problem or failure (cause unknown)

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Region: ALL

Service: ALL

Arriving On: 1/3/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	35	ENG	39	ENG	37	PTH-LPE	CC	Air / Brake Engine 4628 got a fault code of 0158 saying that the parking brake was set on the engine 57. Released the MU cable did a class two inside and outside and made sure all the wheels are rolling freely all with permission from CNOC Mechanical., 57, ID4628
370	GRR	53	FTI	35	FTI	35	XH6-XPI	NS	Follow 22M, Control Point, 507
586	SAN	16	DBS	23	DBS	23	XRJ-FUL	BN	Debris strike Engineer thought by the sound there may have been a trespasser. I walked back and found cases of frozen pigs feet. No trespassers., Frozen pigs feet, Milepost, 157, 157
761	SLO	Trn Cancelled	DBS	178	DBS	178	GTA-GTA	UP	Debris blocking track (no debris strike) Other, goleta
765	GTA	72	WTR	64	WTR	49	OXN-OXN	UP	Flood / washout Dispatcher hold due to mudslides north of VEC., Other, OXN
769	GTA	32	PTI	41	PTI	29	SBA-GTA	UP	Meet 784, Control Point, co 365
770	SAN	33	CTI	36	CTI	22	SNC-SNP	SC	Meet Metrolink, 1663, Control Point, serra
779	SLO	82	DCS	52	PTI	25	VEC-CPN	UP	Meet Due to the signal issues, weather and lateness of 794 the meet was changed., 794, Siding, seacliff
784	SAN	35	WTR	52	WTR	46	GTA-GTA	UP	Landslide / rockslide Other, goleta
785	GTA	26	DCS	35	DCS	29	VEC-CPN	UP	Restrictive signal(s) from known wayside signal failure Red, Milepost, 385, 377
794	SAN	49	RTE	60	RTE	60	GUA-LPS	UP	Dispatcher hold Control Point, tangair
712	BFD	19	FTI	33	FTI	11	SKN-MOD	BN	Meet Amtk 713, Siding, E.Riverbank
715	OKJ	21	FTI	33	FTI	18	BFD-WAC	BN	Switching crew bnsf, Control Point, shafter
718	BFD	19	PTI	31	PTI	17	XPR-ACA	BN	Meet Shuffle, 717, Control Point, west pittsburg
4	CHI	33	FTI	75	PTI	32	HUT-NEW	BN	Meet amtk, Siding, halstead
306	CHI	No OS Rpt	PTI	26	PTI	19	XWR-XW1	UP	Meet Amt 21, Control Point, Wann
382	CHI	No OS Rpt	FTI	3	FTI	3	LAG-XUA	BN	Follow bnsf 3796, Control Point, Lagrange
392	CHI	20	PTI	18	DCS	15	HMW-XCS	CT	Restrictive signal(s) from unknown cause Signal would not come in Had to back out to Wildwood main 2 to main 1, Red, Control Point, Kensington
393	CDL	35	PTI	35	PTI	35	X9R-XCS	CT	Wait for station track 364, Control Point, ROOSEVELT

Amtrak Initial Terminal Details

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/3/2026

Terminal	Train	Date	Late	Delay	Cause
HAR	666	01/03	2	2	Door, 82588, 82735, door bypass
HAR	674	01/03	1		
NFK	82	01/03	21	21	Routine inspections Norfolk mechanical still servicing train
NFK	88	01/03	56	56	Everything. Mechanical was short staffed and unable to service train during the night. 82 was delayed by this as well. Mechanical accidentally serviced our train first forcing an equipment change as 82 took our equipment. We had to wait on class 1.
PHL	144	01/03	4	3	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
PHL	611	01/03	1		
ALB	69	01/03	14		
BOS	87	01/03	5	5	Door, 82813, Door issue
BOS	99	01/03	36	36	Door, ALL, due to door issues on the whole consist on the old eq.99 now running with E/619(10
BOS	163	01/03	78	78	Planned set out / pick out of locomotives, cars or section of train, delayed departing the yard due to shopped coach
BOS	2249	01/03	13	13	Door, 3669, Engine alarm for a door issue. Cndr reports cut out the door on coach car 3669, engineer side
BOS	2251	01/03	25	25	Other electrical failure, 2125, Due to mechanical issues in the yard equipment is currently being looped due to a DNL on E/2125.
MTR	68	01/03	7	7	Meet via, 15, Milepost w/Letters, MTR, mtr
NFL	284	01/03	1	1	EDR reported wrong departure time. 284 departed at 6:47.
NHV	450	01/03	9	9	Service, turn, or wye train, 405, Late turn
NHV	460	01/03	42	37	Planned set out / pick out of locomotives, cars or section of train, Late release from yard
NHV	460	01/03	42	6	Planned set out / pick out of locomotives, cars or section of train, late release from yard
NYP	49	01/03	9	9	Wheelchair
NYP	63	01/03	57	57	Ice / snow on or under equipment, Other, NYP-NYP, LATE F/SSYD A/C UNSPECIFIED WEATHER RELATED PROBLEMS
NYP	97	01/03	50	53	Other electrical failure, 640, delayed out SSYD due to E-640 being shopped for multiple faults. E-605 off of inbound AM98 will be the replacement.
NYP	107	01/03	3	3	Passenger and/or baggage
NYP	159	01/03	14	16	Service, turn, or wye train, 9798, DELAYED SSYD A/C AM97 PRIORITY SERVICING
NYP	245	01/03	12	12	Other late crew

Amtrak Initial Terminal Details

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 1/3/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	01/03	2	2	Hold for connecting train 8
CHI	48	01/03	5	5	Removal of passenger by police Passenger who didn't have a ticket at all refused to leave the platform and police escorted her out. Also passenger who had a ticket but was refused due to excessive bag count, an animal that was not a service animal, and previous improper conduct. 365CB1
CHI	339	01/03	161	161	DEF fuel exhausted on IDTX4608. Replaced with IDTX4613 ID4608
CHI	354	01/03	3	3	PTC- IETMS recycle breaker to clear fault Per CNOC/PTC mechanical. Recycled breaker. This caused IETMS to get stuck in self test mode. Chicago Mechanical responded., ID4601
CHI	364	01/03	7	7	Heat / AC ID4002, ID4309, ID4201, ID4124
CHI	370	01/03	29	29	Daily inspection was not performed, had to wait for a daily to be performed ID4632
EUG	504	01/03	1	1	Passenger and/or baggage Boarding last minute passenger. Confusion with platform work at Eugene
SEA	8	01/03	89	89	Service, turn, or wye train 7, Late arrival, turn
SPK	27	01/01	55	55	Held for train 8 Other, spokane station
WIP	1106	01/03	11	11	Wait for station track Amtk #6, Other, Fraser
BFD	719	01/03	9	9	Hold for thruway bus
EMY	6	01/03	1		
GTA	784	01/03	46	46	Landslide / rockslide Other, goleta
LAX	582	01/03	1		
OKJ	710	01/03	41	6	Door 8308, 9303, 9021, 9810, 9004, 9807, 9025, 9007, Trainset has faulty door lights. Said there was a door light forward but found 2 open. Said there wasn't one in the cab car but they were closed with no red light indicator.
OKJ	710	01/03	41	35	Failure of diesel engine Multiple issues with both locos that were written up last night and not fixed. Had to swap equipment with 714, C2006, C2004
OKJ	714	01/03	1		
OKJ	716	01/03	1	1	Passenger and/or baggage Multiple passengers getting on last minute informed Nick Oakland Operations
SAC	743	01/03	1	1	Restrictive signal(s) from known wayside signal failure Resting , Control Point, Rv989
SAN	581	01/03	1		
SJC	748	01/03	3	3	Follow cal train, Control Point, alameda
SLO	794	01/03	(Trn Cxld)		Severe Storm

Eastern Region

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	99.8	94.8	165	0
CDOT	95.0	81.3	92.3	92.4	16	3
MARC	95.0	94.4	88.2	90.2	18	1
SEPTA	95.0	97.2	97.0	91.5	107	3
NJT-NED	95.0	97.9	95.6	93.8	194	4
NJT-SED	95.0	100	100	97.2	24	0

Operating Highlights

Train 98/52(03) Charleston, SC - Police Related

03JAN26: Train 98(03) operating with engines 142, 330, and 11 cars was delayed holding at Charleston station on the CSX Charleston subdivision due to a vehicle stuck on the tracks ahead at Hannahan milepost 383.6. The original tow truck that arrived on scene was unable to remove the vehicle and a second tow truck was dispatched to remove the vehicle. Once the tracks were inspected, train 98(03) and 52(03) proceeded north.

Train	Delay	Comment
52(03)	20"	
98(03)	1'37"	

Train 25(03) East of New Orleans, LA - Freight Train Interference

03JAN26: Train 25(03) operating with engine 180, 3 cars, and engine 187 was delayed 8 miles east of New Orleans, LA on the CSX NO&M subdivision following CSX Y205-03 from Arabi milepost 801.2 into New Orleans, LA.

Train	Delay	Comment
25(03)	31"	

Acela Train 2247(04) Cancelled - Equipment Availability

03JAN26: Due to equipment availability, Acela Train 2247(04) was cancelled in entirety, with no alternate transportation. There were 455 passengers affected.

Train	Delay	Comment
2247(04)	Cancelled	

Train 2218(03) North of Washington, DC - ACSES /Engine Failure

03JAN26: Next Gen Acela Train 2218(03) with power car 2104 leading experienced ACSES issues just north of Washington DC at CP Avenue/MP134.6 on the Amtrak Washington Terminal Line. The Engineer reporting "No Valid TSR" fault. This enroute failure restricted the train's speed to 79MPH. Prior to reaching Wilmington, the ACSES picked back up on its own and the train was able to continue at track speed.

Train	Delay	Comment
2218(03)	32"	

Train 2255(03) West of Kingston, RI - Deer Strike

03JAN26: Train 2255(03) 26-FDB-00217 00000006555 PC2-0008 UNCLASSIFIED"uck 2/5/2026 r and stopped 7 miles west of Kingston, RI at MP151 on the Amtrak NJB Line Subdivision to inspect. There were 279 passengers onboard and head end power remained active. Crew initially reported a possible air leak, and after inspection, took no exceptions with no reported damage to equipment. After crew inspected, Train 2255(03) was able to proceed.

Train	Delay	Comment
2255(03)	18"	

Train 97(03) New York, NY - Shopped Engine

03JAN26: Train 97(03) E/640, 10 cars, was delayed departing New York, NY due to engine E/640 being shopped for multiple faults and replaced with engine E/605 that arrived on Train 98(02).

Train	Delay	Comment
97(03)	52"	

Train 460(03) New Haven, CT - Late Yard /Servicing

03JAN26: Train 460(03) E/112, 2 cars, was delayed departing New Haven, CT due to a late yard release for normal servicing.

Train	Delay	Comment
460(03)	37"	

Train 163(03) Boston, MA - Shopped Car

03JAN26: Train 163(03) was delayed departing Boston, MA due to a late yard release account of a shopped coach car C/82994 for bad J-16 valve. Once car was cut out, and train made complete, the train was released to the station. Train was then further delayed when departing the yard, for E/661 losing head end power(HEP). Mechanical was able to restore HEP and the train proceeded towards the station. Due to no replacement coach car, 163(03) was over capacity by 21 at EWR.

Train	Delay	Comment
163(03)	1'18"	

Train 99(03) Boston, MA - Door Issues/ Car Failure

03JAN26: Train 99(03) E/633, 10 cars, was delayed departing Boston due to reporting issues on entire consist. The crew troubleshooted and were unable to resolve. In order prevent an extended delay, the trainsets were swapped with equipment slated for 161(03) E/619, 10 cars. Once passengers boarded new equipment, Train 99(02) operating with E/619 was able to depart.

Train	Delay	Comment
99(03)	36"	

Train 63/69(03) New York, NY - Servicing SSYD

03JAN26: Train 63/69(03) E/89, 10 cars, E/715 was delayed departing New York, NY due to a late yard release account of frozen hydrants in SSYD coupled with a replacement of shopped car C/43367.

Train	Delay	Comment
63/69(03)	57"	

Train 82(03) Norfolk, VA - Servicing

03JAN26: Train 82(03) at 0000000555 with 4 and 7 cars was delayed departing Norfolk, VA due to late release off storage track from contracted Rail Plan mechanical who was under hours of service constraints. Train 88(03) was also late due to this. Both trains needed to have their mechanical work-ups completed prior to departure.

Train	Delay	Comment
82(03)	21"	
88(03)	56"	

10OCT25: To accommodate the above outlined infrastructure work, Amtrak's Crescent Service will be adjusted as follows:

- Train 19 (5Jan-7Jan, 11Jan-14Jan, 18Jan-21Jan, 25Jan-28Jan, 1Feb-4Feb, 8Feb-11Feb, 16Feb-18Feb, 22Feb-25Feb, 1Mar-4Mar), which normally operates between NYP and NOL, will terminate at ATL.
- Train 20 (6Jan-8Jan, 12Jan-15Jan, 19Jan-22Jan, 26Jan-29Jan, 2Feb-5Feb, 9Feb-12Feb, 17Feb-19Feb, 23Feb-26Feb, 2Mar-5Mar), which normally operates between NOL and NYP, will originate at ATL.

ALTERNATE TRANSPORTATION:

- Local Bus 3119 will provide alternate transportation between ATL and NOL, making all scheduled station stops.
- Express Bus 3019 will provide alternate transportation from ATL to NOL only.
- Local Bus 3120 will provide alternate transportation between NOL and ATL, making all scheduled station stops.
- Express Bus 3020 will provide alternate transportation from NOL to ATL only.

Weekly Friday through Sunday (This INCLUDES Monday February 16th) - No Track Work Scheduled:

- Trains 19 & 20 will operate normal schedule and route between Atlanta and New Orleans.
- Trains may incur delays of 20-30 minutes operating through the track work area, due to residual slow orders and congestion.

WBS#: B.TR.100150.6165

Eastern Region

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Operating Highlights

Train 8(02) West of Wolf Point, MT - Track Indication

04JAN26: Train 8(02) was delayed holding at Oswego siding, milepost 239.9, on BNSF glasgow subdivision, due to meeting BNSF6610. This meet was caused by a track indication that created congestion. The Track indication was reported as a passable broken rail. BSNF maintenance of Way crew was on scene to walk train 8(02) over the broken rail. Once the freight cleared, train 8(02) then had to flag through the affected area. Once clear of the affected area. Train 8(02) was able to proceed east at normal speed.

Train	Delay	Comment
8(02)	19"	Meet BNSF6610
8(02)	27"	Track Indication

Train 50 Chicago, IL - Engine Failure

03JAN26: Train 50(03) with E/518/312 and 8 coaches, experienced PTC a speed sensor failure on E/518. Mechanical responded and was unable to repair. As background train 50(03) was operating with deadhead equipment set that was destined for, Indianapolis, IN, Beech Grove shops. This section of the train experienced the fault. As a result, train 50(03) reversed back to Chicago, IL station and the deadhead section was removed. the consist that was removed consisted of E/518, C/32103, C/33014, C/34048. Once the deadhead equipment was removed, train 50(03) was able to depart Chicago, IL for a second time at 7:43pm-ct, 1 hour 50 minute delay.

Train	Delay	Comment
50	1'50"	

Train 370(03) Chicago, IL - Servicing

03JAN26: train 370(03) was delayed departing Chicago, IL, on Amtrak Chicago Terminal subdivision, due to the daily inspection being performed on E/ID4632. Chicago Mechanical Department was notified and responded to perform the task. Once the daily inspection was complete, train 370(03) was able to depart Chicago, IL.

Train	Delay	Comment
370(03)	29"	

Train 822(03) North Fort Worth, TX - Police Related

03JAN26: Train 822(03) was delayed .5 miles north of Fort Worth, TX, on BNSF FT. Worth subdivision, at milepost 346.4, because of a police hold on the tracks. Local police were in foot pursuit of a suspect which required them to foul the main line. The police pursuit resulted in a vehicle being stuck on the tracks which required a tow truck to remove. Once the vehicle was removed and the tracks were inspected, train 822(03) was able to proceed.

Train	Delay	Comment
822(03)	1'11"	

04JAN26: Train 339(03) FOI-00217 00000005555 departed Chicago 1/5/2026 to E/ID4608 running out of DEF. At 506PM, after being boarded and ready to depart, Mechanical reported E/ID4608 had no DEF in it. With no DEF vendor available in the yard, it was decided the engine would need to be pulled and replaced. Engine ID4613 was worked up in the yard at released at 546PM. Crew YC5 departed the diesel pit for CUS at 650PM and the engine swap was completed with Train 339(03) made up complete at 705PM. Mechanical cleared at 730PM, but the train crew reported a brake issue at 735PM requesting mechanical to return. The air brake issues was resolved and Train 339(03) departed Chicago at 749PM, 2'41" late.

Train	Delay	Comment
339(03)	2'41"	

Train 761(03) Goleta, CA - Weather

03JAN26: At 10:08 AM-PT Union Pacific Railway received a report of a mudslide north of Goleta, CA (GTA) at MP 354.0 from the California Highway Patrol. Train traffic was halted pending a track inspection. Train 761(03) held at GTA pending the track inspection. Once the track inspector arrived on-scene it was determined that track were not passable and an extensive cleanup would be required. at 10:30 AM-PT a second slide was reported north of Oxnard, CAA (OXN) at MP 388.0 and train traffic was again halted pending a track inspection. Trains 765(03), 14(03) and 769(03) were delayed pending inspection. Once inspection at MP 388.0 was complete train traffic was able to proceed through the area at reduced speeds. The following recovery plan was enacted between Santa Barbara, CA (SBA) and San Luis Obispo, CA (SLO) account the extended closure at MP 354.0:

- 761(03) Terminate GTA - Passengers to rescue bus service GTA to SLO**.
- 794(03) Originate GTA - Passengers to replacement bus service SLO-SBA**.
- 11(02) hold at SLO for open track.
- 14(03) hold at SBA for open track.
- **replacement buses were not able to serve Lompoc-Surf, CA (LPS).**

WBS#: B.TR.100150.6369

Train	Delay	Comment
761(03)	2'58"	GTA - Holding for inspection
761(03)	Term SBA	Pax to 14(03) once track open
761(03)	5'58"	Delay to passengers
14(03)	1'24"	OXN - Hold for route
765(03)	49"	OXN - Hold for route
784(03)	46"	GTA - Late inbound 765 equipt
769(03)	29"	Blocked by 784(03) at SBA
790(03)	24"	Reduced Speed, Flash Flood Warning
794(03)	Originate	replacement bus SLO-SBA
	GTA	
11(02)	1'03"	SLO - Hold for route
794(03)	42"	SBA - Hold for replacement bus with through passengers
794(03)	31"	CP C0369 - Bad meet with 779(03) RE: Switch Failure from severe weather
14(03)	4'17"	SBA - hold for route
779(03)	42"	Seacliff - Mudslides, switch failure, changed meet with 794(03) all from severe weather

Train 11(02) San Jose, CA - Weather

03JAN26: Train 11(02) was delayed at SJC on the Union Pacific Railway Coast Subdivision. Train 11(02) was held at SJC account high tides with water over the rail at CP Moss Landing. Once the tide receded, train 11(02) departed SJC at 12:14 PM-PT.

Train	Delay	Comment
11(02)	1'38"	

Train 352(03) Chicago, IL - Speed Sensor

03JAN26: Train 352(03) 26-FBI-002196-00000005555 dep UNCLASSIFIED Chicago 1/5/2026 L on time and then stopped on the Amtrak Chicago Line at CP Lumber/MP1.34 with PTC issues. The crew reported PTC was not allowing them to select a track and worked with the PTC desk to troubleshoot. All efforts were unsuccessful and Chicago Mechanical responded to the train. After inspection, mechanical found a the speed sensor was broken. As a result, Train 352(03) shoved back to the station for mechanical to repair the defect. At 4:45PM-CT, Train 352(03) departed Chicago a second time operating 2 hours and 43 minutes late.

Train	Delay	Comment
352(03)	2'43"	

Train 5(03) West of Naperville, IL - Car Failure

03JAN26: At 2:47PM-CT, Train 5(03), E/61-E/158-7 Cars, went into an undesired emergency 3.5 miles west of Naperville, IL/MP28.5, on the BNSF Chicago Subdivision, at MP32.0. The Conductor walked the train and found a cracked gladhand on the brake pipe between trail engine 158 and crew dorm car 39012. Head end power was intermittent while the crew worked to replace the hose with 177 passengers onboard. Weather in the area was 28 degrees and cloudy. At 3:30PM-CT, Train 5(03) was back on the move west.

Train	Delay	Comment
5(03)	46"	

Train 1(03) West of Lake Charles, LA - Air Hose Separation

03JAN26: At 2:31PM-CT, Train 1(03), E/136-E/77-8 Cars, went into an undesired emergency 2.4 miles west of Lake Charles, LA/MP218.9, on the UPRR Lafayette Subdivision, at MP221.3. The Conductor walked the train and found a brake pipe separation between cars 61046 and 39031. The crew was able to repair the hose and restore air to the trainset. Additional delay was incurred initializing PTC. Once initialized, Train 1(03) was back on the move west at 3:05PM-CT.

Train	Delay	Comment
1(03)	22"	

Train 11(02) Emeryville, CA - Servicing

03JAN26: Train 11(02) was delayed east of Emeryville, CA (EMY) at Oakland Maintenance Facility (OMF) on the Union Pacific Railway Niles Subdivision. Train 11(02) was routed into OMF to add four cars, C/33041, C/5008, C/5009 and C/5011 as part of a ferry move to Los Angeles 8th St Yard. Once the cars were added, train 11(02) was able to proceed at 9:29 AM-PT.

Train	Delay	Comment
11(02)	43"	

Train 6(01) East of Osceola, IA - Freight Train Interference

03JAN26: Train 6(01) held 50.1 miles east of Osceola, IA/MP359.9, on the BNSF Ottumwa Subdivision, on Main Track 2 at Halpin/MP309.8. The 2B switch ahead at Maxon/MP300.8 was out of service so Train 6(01) had to wait for westbound BNSF H-GALLIN to clear on Main Track 1. Once a route was established, Train 6(01) crossed over to Main Track 1 and proceeded east.

Train	Delay	Comment
6(01)	30"	

Train 710(03) Oakland, CA - Mechanical

03JAN26: Train 710(03) ^{26-FOM-00217} ⁰⁰⁰⁰⁰⁰⁰⁵⁵⁵⁵ departed ^{UNCLASSIFIED} Oakland ^{11/5/2026} CA/MP7.1, on the UPRR Niles Subdivision, for mechanical reasons. Mechanical was still working on the equipment writeups so to allow time, Train 714(03)'s equipment was moved up to represent 710(03). At 8:33AM, Train 710(03) departed the station operating 38 minutes late.

Train	Delay	Comment
710(03)	38"	

Train 4(02) West of Gallup, NM - Freight Train Interference

03JAN26: Train 4(02) held 32.5 miles west of Gallup, NM/MP157.5, on the BNSF Gallup Subdivision, at East Houck/MP190.0 meeting BNSF 4756.

Train	Delay	Comment
4(02)	30"	

Train 3(01) East of Victorville, CA - Freight Train Interference

03JAN26: BNSF reported at 1:54AM-PT, BNSF U-VVCVRNO-01 derailed 1 car two miles east of Victorville, CA/MP36.7, on the BNSF Cajon Subdivision, on Main Track 2 at East Victorville/MP34.7. There was a route for all traffic around the derailment on Main Track 1. As a result, Train 3(01) was delayed through the area starting at MP23.0 from congestion built up from single tracking. At Lugo/MP50.1, Train 3(01) was able to cross back over to Main Track 2 to get around the congestion and continue at track speed to Los Angeles with no further delay.

Train	Delay	Comment
3(01)	1'09"	

Train 4(01) West of Newton, KS - Passenger Train Interference

03JAN26: Train 4(01) held 10.3 miles west of Newton, KS/MP185.1, on the BNSF La Junta Subdivision, at Halstead/MP195.4 meeting Train 3(02).

Train	Delay	Comment
4(01)	32"	

Train 5(01) West of Salt Lake City, UT - Freight Train Interference

03JAN26: Train 5(01) was delayed west of Salt Lake City, UT/MP745.0, on the UPRR Shafter Subdivision, between Wendover/MP806.0 and Silverzone/MP771.8 following an unspecified UPRR freight train.

Train	Delay	Comment
5(01)	1'00"	

Train 49(02) West of Sandusky, OH - Power Switch Failure

03JAN26: Train 49(02) was delayed 25.6 miles west of Sandusky, OH/MP241.5, on the NSRR Chicago Line, due to power switch failure at CP-267/MP267.1. The Conductor reporting having to manually line the switch in order to proceed west.

Train	Delay	Comment
49(02)	39"	

Train 365(03) West of Port Huron, MI - Engine Failure

03JAN26: Train 365(03), E/303-E/307-E/336-11 Cars, was delayed at Port Huron, MI/MP334.3, on the CNRR Flint Subdivision, at MP329.6 from engine issues. The Conductor reported receiving fault code 0158 stating the parking brake on rear engine 57 was set. The multiple unit (M/U) cable was pulled after contacting and troubleshooting with CNOC Mechanical. Head end power was on for the duration. A class II was completed to confirm that all the wheels were rolling freely. There was a rider placed in engine 57 through to Chicago. Once the successful brake test was complete, Train 365(03) was back on the move west.

Train	Delay	Comment
365(03)	37"	

Train 8/28(01) Minot, ND - Servicing

03JAN26: Train 8/28(01), E/303-E/307-E/336-11 Cars, was delayed at Minot, ND/MP203.3X, on the BNSF KO Subdivision, for mechanical to complete their routine inspection of the equipment.

Train	Delay	Comment
8/28(01)	30"	

Train 8(02) East of Ephrata, WA - Boulder Strike

02JAN26: At 11:08PM-PT 26-FBI-00217 80000005555 oper UNCLASSIFIED E/45/2026/327-6 Cars and 66 passengers onboard, went into emergency 12.8 miles east of Ephrata, WA/MP1599.1, on the BNSF Columbia River Subdivision, at MP1586.3 after striking an 80-100lb boulder. There were no injuries to the crew or 66 passengers onboard. The crew walked the equipment and originally found a broken main reservoir hose. Upon further inspection of the equipment, extensive damage was found on three cars in the consist, C/61037, C/32016, C/38017. Multiple trucks on these cars needed to be cut out, reducing braking effort. Train 8(02) was back on the move at 12:58AM-PT operating not exceeding 40MPH to Spokane per rule. The Conductor reported that head end power was off to the trainset after they were back on the move and it continued with no HEP through to Spokane arriving at 3:47AM-PT, 3 hours and 10 minutes late. The outdoor temperature at the time was 34 degrees with the temperature onboard reported comfortable with emergency blankets handed out if needed.

Upon arrival to Spokane, mechanical was onsite to complete an assessment of the equipment. It was found that the damaged baggage car 61037 and sleeper car 32016 had to be setout. Repairs were made to dining car 38017. Train 7(01) was held at Spokane for the assessment and then took a delay adding the two setout cars to the rear end of the train so that the cars could deadhead to Seattle for repair. Once the two cars were added, Train 7(01) was released to depart Spokane at 6:22AM, operating 3 hours and 03 minutes late. The 27(01) section was originally held and released at 4:44AM, operating 55 minutes late to Portland.

Train 8/28(02) departed Spokane at 7:11AM, operating 5 hours and 56 minutes late. 42 Sleeper car passengers were impacted after setting out sleeper car 32016. 39 of the 42 impacted customers were able to be reaccommodated into the open rooms in the other two sleeping cars. 3 of the 42 affected passengers were notified and downgraded to coach seating. Service recovery was enacted for train 8(02) which consisted of the Lounge car offering coffee, tea, and juice discounted and comping meals as needed. Snack packs and water was available for all guests. The sleeper passengers meals were not affected and received normal meals off the menu.

After departing Spokane, WA, Train 8/28(02) reported experiencing intermittent head end power issues anytime the train would come to a stop. Loss of head end power happened for small periods of time and quickly would come back up as soon as the train was on the move. BNSF mechanical met the train upon arrival to the Whitefish, MT station to troubleshoot the issue with the crew. Upon inspection, two loose cables between the locomotives were found and secured. Head end power was brought up on lead engine 39 and Train 8/28(02) departed Whitefish at 2:26PM-MST, operating 7 hours late.

Due to the late operation of 8(02), three supplemental on-time buses were secured between St. Paul, MN and Chicago, IL for Sunday. Two buses will operate express from St. Paul to Chicago. The third bus will make all stops from St. Paul to Milwaukee and then all passengers destined east of Milwaukee will board the next available Hiawatha.

Due to the late arrival of train 7(01) into Seattle, WA, train 8(03) was delayed departing Seattle, WA due to normal servicing. Train 8(03) departed Seattle at 6:24pm-pt, 1'29" late.

WBS#: B.TR.100150.6368

Train	Delay	Comment
8(02)	25"	EPH-SPK Speed Restriction
8(02)	2'08"	E/EPH - Boulder Strike
8(02)	2'46"	SPK
28(02)	3'24"	SPK - Holding for 8(02)
7(01)	3'03"	SPK
27(01)	55"	SPK
8/28(02)	45"	WFH - Troubleshoot

03JAN26: Train 703(02) 26-FOI-00217 41000P0005555 Passenger UNCLASSIFIED delay 1/5/2026 miles north of Lodi, CA, at milepost 52.1, on UP Fresno subdivision, due to a disabled freight (UP8104) with a broken knuckle. The freight crew had trouble replacing the knuckle and UP management and car department responded to assist. Due to the extensive delay to the train, 703(02) was advanced to Elk Road BLVD crossing to allow passengers, who secured their own transportation, to detrain. A total of 33 passengers detrained leaving 8 passengers on board. Once the knuckle was replaced the freight train was able to proceed, clearing a route for train 703(02).

Train	Delay	Comment
703(02)	3'20"	

Gold Runner/ Capitol Corridor Service - Third Party Contractor Engine Failure - High Shop Counts

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated form Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

- Train 736(01-04) Cancelled - No alternate transportation.
- Train 737(01-04) Cancelled - No alternate transportation.

Cause: Pending

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

WBS#: B.TR.100150.6340

Train	Delay	Comment
715 (21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718 (21)	Originate EMY	Passengers to 744 (21) OKJ-EMY
718 (22)	Originate EMY	Passengers to 544 (22) OKJ-EMY
714 (22)	1'07"	ITD - OKJ - Late change of equipment
718 (21)	37"	ITD - EMY
716 (22)	20"	
718 (22)	3'10"	ITD - EMY
714 (23)	.	CANCELLED
713 (24)	.	CANCELLED
535 (24)	Cancelled	
520 (24)	Cancelled	
534 (24)	Cancelled	
736 (25-28)	Cancelled	
737 (25-28)	Cancelled	
749 (28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751 (28)
551 (29-30)	Cancelled	Replacement Bus SAC-OKJ
520 (29-31)	Cancelled	No alternate transportation.
534 (29-31)	Cancelled	No alternate transportation.
736 (01JAN-04JAN))	Cancelled	No alternate transportation
737 (01JAN-04JAN)	Cancelled	No alternate transportation
535 (29)	Cancelled	No alternate transportation.
537 (30-31)	Cancelled	No Alternate Transportation
713 (06JAN-07MAR)	CANCELLED	No Alternate Transport Offered
714 (05JAN-06MAR)	CANCELLED	No Alternate Transport Offered

Western Region

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 49(02) Passenger Incident at Waterloo, Indiana – Baggage

03JAN26, Passengers on PNR 4013A2, traveling from Waterloo, IN to Chicago, IL were forced to repack luggage due to carryon being over the weight limit per baggage policy. Amtrak Police notified.

Delay: 49 (02) 04"

Train 1(03) Passenger Removal at Lafayette, Louisiana – Improper Conduct

03JAN26, Passenger on PNR 41B78F, traveling from New Orleans, LA to Tucson, AZ was removed from the train by Lafayette Police OFC. Trajan. The passenger stole from the diner car and began yelling and trying to fight other passengers. Amtrak Police notified.

Delay: 1 (03) 04"

Train 11(01) Passenger Incident at Paso Robles, California – Improper Conduct

03JAN26, Passenger on PNR 221684, traveling from Seattle, WA to Los Angeles, CA fell in the restroom but did decline medical attention. Amtrak Police notified.

Delay: 11 (01) 13"

Train 770(03) Passenger Removal at Santa Ana, California – Fare Evader

03JAN26, Passenger on PNR Unknown, traveling from Los Angeles, CA to San Diego, CA was removed from the train after trying to ride the train without purchasing a ticket. Amtrak Police notified.

Delay: 770(03) 1"

Train 761(03) Passenger Removal at Solana Beach, California – Fare Evader

03JAN26, Passenger on PNR Unknown, traveling from Los Angeles, CA to San Diego, CA was removed from the train after trying to ride the train without purchasing a ticket. Amtrak Police notified.

Delay: 761(03) 1"

Train 28(02) Passenger Removal at Pasco, Washington – Medical

03JAN26, Passenger on PNR 43AF83, traveling from Portland, OR to Whitefish, MT detrained early due to complaints of stomach pain. The passenger declined waiting for medical attention. Amtrak Police notified.

Delay: 28(02) None

Consist Deviations

26-FOI-00217

00000005555

"UNCLASSIFIED"

1/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2249 (03)	BOS	NEXT GEN ACELA in lieu of LEGACY ACELA	No Impact	0	
449 (03)	BOS	no sleeper car- short equipment	Passengers downgraded.	16	NOCAR
163 (03)	BOS	82994 SHOPPED BOS WITH NO REPLACEMENT. CAP REDUCED TO 504 AND OVER CAP BY 21 PASSENGERS	0	0	82994
2253 (04)	BOS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
2257 (04)	BOS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
2275 (04)	BOS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
155 (03)	NYP	Business class car in lieu of coach car- short equipment	0	0	81518
97 (03)	NYP	Using a viewliner 2 in lieu of a viewliner 1 sleeper. schedule change was performed. customer service notified.	0	0	62519
103 (03)	NYP	BUSINESS CLASS IS ON THE HEAD END BUT IS POINTED CORRECTLY (A LEADING) NO SCHEDULE CHANGE NEEDED	0	0	81522
107 (03)	NYP	BUSINESS CLASS IS ON THE HEAD END BUT IS POINTED CORRECTLY (A LEADING) NO SCHEDULE CHANGE NEEDED	0	0	81522
2205 (04)	NYP	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
2292 (04)	NYP	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
144 (03)	PHL	cafe car running 4 cars away from business class car and the consist calls for the cafe to be placed business class-coach(quiet car)-cafe. Cafe car is out of place.	0	0	43388
8 (02)	SPK	32016 (0830 car) and 61037 set out @ SPK due to boulder strike.	0	0	32016, 61037

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		both cars added to 7(01) to SEA for repairs.			
106 (03)	WAS	BUSINESS CLASS IS ON THE REAR END BUT IS POINTED CORRECTLY (B LEADING) NO SCHEDULE CHANGE NEEDED	0	0	81522
2226 (04)	WAS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
2250 (04)	WAS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			
2262 (04)	WAS	WILL OPERATE NEXT GEN EQUIPMENT, SCHEDULE CHANGE COMPLETED.			

Reverse Consists

Train Number	Station	Reason
87 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
150 (03)	PHL	Consist reversed Business class seat orientation may have changed At Front
144 (03)	PHL	Consist reversed Business class seat orientation may have changed At Rear
155 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
2251 (03)	BOS	Acela consist reversed First class at Front
2251 (03)	BOS	Acela consist reversed First class at Rear
135 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
99 (03)	BOS	EQUIPMENT SWAPPED CONSIST NOW REVERSED Business class seat orientation may have changed At Front
96 (04)	NPN	Consist reversed Business class seat orientation may have changed At Front
2255 (03)	BOS	Acela consist reversed First class at Rear