

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, August 28, 2026

Rules: 3-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/27/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	51	84.4%	8,343	1,259	84.9%	99,287	13,811	86.1%
Central Division	86.0%	59	7	88.1%	1,534	183	88.1%	18,962	1,757	90.7%
East Division	82.0%	176	16	90.9%	4,498	646	85.6%	52,168	8,064	84.5%
West Division	86.0%	91	28	69.2%	2,311	430	81.4%	28,157	3,990	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00703 00000008731 "UNCLASSIFIED" 9/2/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	94,538	22,870	76%	2,839,085	826,370	71%	33,172,083	8,467,720	74%
Northeast Corridor	81%	43,869	6,911	84%	1,236,879	297,168	76%	14,538,392	3,553,196	76%
Acela	83%	11,278	909	92%	263,188	50,597	81%	2,923,612	752,148	74%
Northeast Regional	79%	32,591	6,002	82%	973,691	246,571	75%	11,614,780	2,801,048	76%
Richmond / Newport News / Norfolk	77%	9,171	3,303	64%	300,265	101,072	66%	3,600,241	1,062,533	70%
Springfield Shuttles	89%	684	185	73%	16,870	3,032	82%	204,597	32,900	84%
Roanoke	79%	3,331	710	79%	96,343	26,888	72%	1,101,627	245,544	78%
On Spine Northeast Regional	80%	19,405	1,804	91%	560,213	115,579	79%	6,708,315	1,460,071	78%
State Supported	80%	40,767	11,280	72%	1,281,891	346,581	73%	14,591,510	3,152,506	78%
Borealis	80%	578	0	100%	16,014	4,130	74%	185,640	39,762	79%
Capitol Corridor	90%	4,020	812	80%	101,274	15,528	85%	1,216,993	161,277	87%
Carolinian	70%	417	5	99%	28,546	11,384	60%	373,428	146,383	61%
Cascades	75%	2,669	1,227	54%	56,597	23,280	59%	839,847	238,316	72%
Downeaster	82%	1,592	0	100%	52,820	5,792	89%	513,133	61,747	88%
Empire	78%	6,336	2,231	65%	172,450	59,812	65%	1,816,163	443,271	76%
Adirondack	72%	443	0	100%	12,385	5,536	55%	112,348	36,381	68%
Ethan Allen Express	70%	241	232	4%	15,748	10,276	35%	184,656	70,625	62%
Maple Leaf	70%	951	419	56%	24,749	11,768	52%	225,098	88,611	61%
New York - Albany	85%	3,114	789	75%	76,852	19,114	75%	839,200	145,041	83%
New York - Niagara Falls	75%	1,587	791	50%	39,166	10,820	72%	443,198	96,501	78%
Berkshire Flyer	60%	0	0	-	3,550	2,298	35%	11,663	6,112	48%
Gold Runner	73%	1,911	1,326	31%	64,374	32,484	50%	819,940	302,937	63%
Heartland Flyer	70%	165	88	47%	5,962	4,046	32%	70,645	29,468	58%
Hiawatha	90%	2,151	8	100%	54,884	5,058	91%	575,803	62,755	89%
Illinois	78%	2,620	1,040	60%	70,407	26,112	63%	816,631	230,667	72%
Carl Sandburg / Illinois Zephyr	85%	319	213	33%	11,082	4,906	56%	135,882	39,064	71%
Illini / Saluki	85%	818	263	68%	22,123	8,341	62%	282,010	70,241	75%
Lincoln Service	70%	1,483	564	62%	37,202	12,865	65%	398,739	121,362	70%
Keystone	92%	8,507	302	96%	213,748	17,024	92%	2,495,867	256,570	90%
Lincoln / Missouri	70%	613	502	18%	22,041	15,578	29%	254,532	133,886	47%
Mardi Gras Service	80%	219	33	85%	8,148	1,932	76%	131,869	29,547	78%
Michigan	70%	1,966	722	63%	65,518	30,011	54%	662,943	222,432	66%
Blue Water	70%	365	364	0%	16,336	8,947	45%	155,994	64,775	58%
Pere Marquette	85%	350	0	100%	6,742	1,234	82%	85,176	16,358	81%
Wolverine	70%	1,251	358	71%	42,440	19,830	53%	421,773	141,299	66%
Missouri	80%	148	137	7%	6,689	4,023	40%	72,525	20,459	72%
Pacific Surfliner	85%	4,129	2,202	47%	257,949	67,572	74%	2,670,121	497,279	81%
Pennsylvanian	80%	777	29	96%	23,395	4,148	82%	289,197	55,225	81%
Piedmont	80%	688	36	95%	26,189	4,970	81%	366,463	93,622	74%
Vermont	75%	1,261	580	54%	34,886	13,697	61%	419,770	126,903	70%
Long Distance	70%	9,902	4,679	53%	320,315	182,621	43%	4,002,914	1,759,555	56%
Auto Train	70%	700	362	48%	22,853	6,091	73%	257,262	86,880	66%
California Zephyr	70%	796	502	37%	26,069	17,714	32%	317,663	124,371	61%
Cardinal	70%	294	128	56%	4,771	3,144	34%	76,252	38,687	49%
City Of New Orleans	75%	497	372	25%	15,581	12,540	20%	206,805	70,719	66%
Coast Starlight	70%	993	214	78%	27,715	12,114	56%	372,392	132,576	64%
Crescent	70%	713	397	44%	21,648	7,019	68%	301,301	93,002	69%
Empire Builder	70%	1,097	553	50%	28,410	16,504	42%	316,777	158,709	50%
Floridian	60%	1,297	785	39%	37,023	30,513	18%	514,789	357,555	31%
Lake Shore Ltd	73%	1,107	94	92%	30,990	11,216	64%	318,227	96,322	70%
Palmetto	70%	296	177	40%	23,298	10,827	54%	299,401	93,436	69%
Silver Meteor	70%	685	371	46%	25,729	15,877	38%	330,929	153,228	54%
Southwest Chief	60%	710	402	43%	23,797	18,808	21%	274,263	181,401	34%
Sunset Ltd	70%	0	0	-	6,356	4,698	26%	94,722	37,466	60%
Texas Eagle	70%	717	322	55%	26,075	15,556	40%	322,131	135,203	58%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00700 00000000701 "UNCLASSIFIED" 8/2/2020

Train Index Dates Through August 27, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	182,081	2,890,859	630	1,972,160	34,838,797	566

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	9,555	882,285	108	95,467	10,079,288	95
INFRASTRUCTURE PLANNED	135	17,502	882,285	198	113,557	10,079,288	113
FLEET RELIABILITY	90	28,971	2,890,859	100	315,111	34,838,797	90
TRAIN OPERATIONS	424	126,053	2,890,859	436	1,448,025	34,838,797	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/27/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	51	84.4%	8,343	1,259	84.9%	99,287	13,811	86.1%
Central Division	86.0%	59	7	88.1%	1,534	183	88.1%	18,962	1,757	90.7%
East Division	82.0%	176	16	90.9%	4,498	646	85.6%	52,168	8,064	84.5%
West Division	86.0%	91	28	69.2%	2,311	430	81.4%	28,157	3,990	85.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/27/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	51	84.4%	8,343	1,259	84.9%	99,287	13,811	86.1%
Central Division	86.0%	59	7	88.1%	1,534	183	88.1%	18,962	1,757	90.7%
CDL	95.0%	2	0	100.0%	52	6	88.5%	628	31	95.1%
CHI	86.0%	28	4	85.7%	712	122	82.9%	8,762	1,089	87.6%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	27	2	92.6%	354	38	89.3%
GBB	-	-	-	-	2	1	50.0%	15	12	20.0%
GRR	95.5%	1	0	100.0%	22	3	86.4%	310	11	96.5%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	53	8	84.9%	640	52	91.9%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	156	11	92.9%	1,936	125	93.5%
MOE	97.5%	2	0	100.0%	54	0	100.0%	659	9	98.6%
MSP	96.5%	1	0	100.0%	27	1	96.3%	324	7	97.8%
NOL	94.5%	4	0	100.0%	119	3	97.5%	1,392	63	95.5%
OKC	97.0%	1	0	100.0%	27	0	100.0%	325	6	98.2%
PNT	88.0%	3	1	66.7%	77	8	89.6%	864	72	91.7%
PTH	93.0%	1	0	100.0%	27	2	92.6%	319	13	95.9%
QCY	91.0%	2	1	50.0%	46	5	89.1%	623	48	92.3%
SAS	90.5%	1	0	100.0%	27	4	85.2%	328	37	88.7%
STL	89.0%	4	1	75.0%	105	6	94.3%	1,280	106	91.7%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	16	90.9%	4,498	646	85.6%	52,168	8,064	84.5%
ALB	88.5%	8	0	100.0%	204	10	95.1%	2,454	185	92.5%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	135	15	88.9%	1,601	173	89.2%
BOS	85.5%	18	1	94.4%	471	32	93.2%	5,634	636	88.7%
BRK	92.5%	5	0	100.0%	123	10	91.9%	1,575	112	92.9%
BTN	82.0%	1	0	100.0%	26	1	96.2%	316	42	86.7%
CLT	91.5%	5	1	80.0%	135	15	88.9%	1,612	165	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	47	3	93.6%	640	60	90.6%
GRO	-	2	0	100.0%	16	0	100.0%	49	10	79.6%
HAR	79.5%	13	4	69.2%	303	44	85.5%	3,667	592	83.9%
HFD	-	2	0	100.0%	37	4	89.2%	228	19	91.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	27	1	96.3%	327	39	88.1%
MIA	89.5%	2	0	100.0%	50	8	84.0%	650	76	88.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/27/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	51	84.4%	8,343	1,259	84.9%	99,287	13,811	86.1%
East Division	82.0%	176	16	90.9%	4,498	646	85.6%	52,168	8,064	84.5%
MTR	79.0%	1	0	100.0%	27	6	77.8%	314	58	81.5%
NFK	84.5%	2	1	50.0%	54	10	81.5%	737	133	82.0%
NFL	93.5%	2	0	100.0%	54	2	96.3%	666	31	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	130	31	76.2%	1,684	284	83.1%
NPN	93.0%	2	0	100.0%	54	9	83.3%	626	50	92.0%
NYP	75.5%	50	5	90.0%	1,265	256	79.8%	13,749	3,034	77.9%
PGH	93.0%	1	0	100.0%	27	1	96.3%	328	23	93.0%
PHL	48.0%	5	1	80.0%	127	52	59.1%	1,677	792	52.8%
PIT	76.0%	-	-	-	7	6	14.3%	22	18	18.2%
POR	-	-	-	-	12	7	41.7%	23	15	34.8%
RGH	95.0%	2	0	100.0%	92	5	94.6%	1,250	54	95.7%
RNK	83.5%	2	0	100.0%	54	4	92.6%	650	91	86.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	23	0	100.0%	310	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	1	0.0%	27	2	92.6%	324	12	96.3%
SFA	88.0%	1	1	0.0%	27	4	85.2%	327	45	86.2%
SPG	92.5%	5	0	100.0%	133	8	94.0%	1,940	113	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	27	3	88.9%	316	63	80.1%
WAS	84.0%	31	1	96.8%	784	97	87.6%	8,256	1,064	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	91	28	69.2%	2,311	430	81.4%	28,157	3,990	85.8%
ARN	92.0%	1	0	100.0%	27	2	92.6%	329	28	91.5%
BFD	79.0%	7	2	71.4%	188	47	75.0%	2,085	440	78.9%
EMY	72.0%	1	0	100.0%	27	5	81.5%	345	99	71.3%
EUG	86.5%	2	0	100.0%	54	3	94.4%	652	59	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	0	100.0%	6	3	50.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	3	0.0%	81	25	69.1%	990	168	83.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	3	70.0%	278	36	87.1%	3,277	362	89.0%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	6	53.8%	316	109	65.5%	3,577	937	73.8%
PDX	86.0%	5	1	80.0%	90	34	62.2%	1,578	215	86.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/27/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/27/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	51	84.4%	8,343	1,259	84.9%	99,287	13,811	86.1%
West Division	86.0%	91	28	69.2%	2,311	430	81.4%	28,157	3,990	85.8%
SAC	88.5%	16	4	75.0%	397	49	87.7%	4,663	511	89.0%
SAN	90.5%	12	5	58.3%	344	33	90.4%	3,985	377	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	144	38	73.6%	2,529	385	84.8%
SJC	89.0%	7	0	100.0%	188	18	90.4%	2,312	227	90.2%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	3	0.0%	81	11	86.4%	753	76	89.9%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	13	4	69.2%	311	30	90.4%
VAC	97.0%	2	0	100.0%	54	0	100.0%	645	14	97.8%
VAN	-	-	-	-	27	16	40.7%	27	16	40.7%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	471	27	7	74.1%	329	66	79.9%	26	19	26.9%	326	155	52.5%
4		27	5	81.5%	328	51	84.5%	27	19	29.6%	328	218	33.5%
5		27	6	77.8%	327	56	82.9%	27	21	22.2%	323	109	66.3%
6	69	27	5	81.5%	326	90	72.4%	27	20	25.9%	326	123	62.3%
7		27	8	70.4%	318	50	84.3%	26	10	61.5%	309	84	72.8%
8	45	27	15	44.4%	318	144	54.7%	27	20	25.9%	317	195	38.5%
11		27	15	44.4%	329	72	78.1%	27	7	74.1%	323	67	79.3%
14		27	5	81.5%	330	54	83.6%	26	12	53.8%	327	104	68.2%
19	69	27	6	77.8%	328	83	74.7%	27	9	66.7%	325	80	75.4%
20		27	0	100.0%	328	23	93.0%	27	7	74.1%	328	65	80.2%
21	222	27	10	63.0%	325	35	89.2%	27	14	48.1%	324	96	70.4%
22		27	4	85.2%	326	35	89.3%	27	15	44.4%	324	96	70.4%
23		27	0	100.0%	330	6	98.2%	27	5	81.5%	328	90	72.6%
24		27	0	100.0%	330	16	95.2%	27	8	70.4%	329	64	80.5%
25		27	0	100.0%	329	3	99.1%	26	11	57.7%	326	94	71.2%
26	25	27	0	100.0%	329	5	98.5%	26	4	84.6%	326	64	80.4%
27		13	6	53.8%	298	22	92.6%	10	5	50.0%	291	98	66.3%
28	75	9	3	66.7%	290	67	76.9%	9	4	55.6%	290	60	79.3%
40		23	6	73.9%	319	47	85.3%	22	16	27.3%	315	171	45.7%
41	328	24	10	58.3%	319	124	61.1%	24	21	12.5%	317	245	22.7%
42		27	1	96.3%	330	25	92.4%	27	5	81.5%	328	57	82.6%
43		27	3	88.9%	329	45	86.3%	27	5	81.5%	328	75	77.1%
48		27	5	81.5%	328	62	81.1%	27	8	70.4%	327	50	84.7%
49		27	9	66.7%	328	84	74.4%	27	6	77.8%	328	68	79.3%
51		8	3	62.5%	134	58	56.7%	9	6	33.3%	130	50	61.5%
52		27	4	85.2%	327	45	86.2%	27	2	92.6%	326	74	77.3%
53	183	27	1	96.3%	327	39	88.1%	27	9	66.7%	326	104	68.1%
55		19	2	89.5%	209	9	95.7%	19	8	57.9%	206	46	77.7%
56		19	2	89.5%	210	25	88.1%	19	6	68.4%	206	40	80.6%
58		26	1	96.2%	303	17	94.4%	25	22	12.0%	301	95	68.4%
59	32	27	17	37.0%	302	50	83.4%	26	22	15.4%	297	79	73.4%
63	77	27	9	66.7%	331	141	57.4%	27	27	0.0%	325	193	40.6%
64	22	27	3	88.9%	329	71	78.4%	27	22	18.5%	328	131	60.1%
66		27	2	92.6%	328	63	80.8%	27	6	77.8%	324	60	81.5%
67		20	1	95.0%	228	14	93.9%	19	4	78.9%	227	40	82.4%
68		27	6	77.8%	331	67	79.8%	27	14	48.1%	330	132	60.0%
69		27	11	59.3%	318	79	75.2%	27	12	55.6%	313	55	82.4%
71		27	0	100.0%	326	3	99.1%	26	4	84.6%	324	85	73.8%
72		27	4	85.2%	322	35	89.1%	26	7	73.1%	320	68	78.8%
73		27	4	85.2%	325	23	92.9%	27	5	81.5%	323	147	54.5%
74		27	2	92.6%	323	35	89.2%	27	9	66.7%	321	117	63.6%
75		27	0	100.0%	319	16	95.0%	27	11	59.3%	313	148	52.7%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		27	2	92.6%	319	31	90.3%	27	12	55.6%	310	129	58.4%
77		27	1	96.3%	321	21	93.5%	27	9	66.7%	319	132	58.6%
78		27	3	88.9%	325	28	91.4%	27	12	55.6%	324	75	76.9%
79	85	27	3	88.9%	328	59	82.0%	27	10	63.0%	327	111	66.1%
80		27	4	85.2%	328	37	88.7%	27	8	70.4%	325	71	78.2%
84		19	5	73.7%	200	19	90.5%	17	5	70.6%	196	48	75.5%
85		19	2	89.5%	211	18	91.5%	19	4	78.9%	211	74	64.9%
86	26	19	1	94.7%	211	16	92.4%	19	6	68.4%	210	121	42.4%
89		27	13	51.9%	326	78	76.1%	27	10	63.0%	324	95	70.7%
90	61	27	2	92.6%	326	12	96.3%	27	9	66.7%	325	60	81.5%
93	18	19	2	89.5%	210	21	90.0%	19	8	57.9%	209	55	73.7%
94	80	19	5	73.7%	241	60	75.1%	19	6	68.4%	239	89	62.8%
95		19	2	89.5%	210	6	97.1%	19	12	36.8%	210	81	61.4%
97	156	27	19	29.6%	328	217	33.8%	27	18	33.3%	326	118	63.8%
98		27	2	92.6%	328	28	91.5%	27	14	48.1%	326	122	62.6%
110		19	8	57.9%	207	110	46.9%	19	3	84.2%	204	22	89.2%
111		19	1	94.7%	201	36	82.1%	19	1	94.7%	199	22	88.9%
112		19	1	94.7%	201	19	90.5%	19	1	94.7%	200	20	90.0%
113		19	8	57.9%	132	33	75.0%	19	2	89.5%	131	16	87.8%
119		19	4	78.9%	198	49	75.3%	19	4	78.9%	196	26	86.7%
125		19	1	94.7%	211	12	94.3%	19	8	57.9%	211	82	61.1%
129		19	3	84.2%	210	50	76.2%	19	2	89.5%	210	30	85.7%
130		19	2	89.5%	201	20	90.0%	19	0	100.0%	199	16	92.0%
131		19	4	78.9%	203	57	71.9%	19	3	84.2%	203	38	81.3%
134		19	5	73.7%	211	32	84.8%	19	6	68.4%	210	42	80.0%
136		19	3	84.2%	211	27	87.2%	19	3	84.2%	209	28	86.6%
137		19	1	94.7%	208	36	82.7%	19	4	78.9%	208	62	70.2%
138		19	3	84.2%	211	42	80.1%	19	4	78.9%	210	38	81.9%
141		19	1	94.7%	210	4	98.1%	19	3	84.2%	209	36	82.8%
148		19	2	89.5%	210	22	89.5%	19	5	73.7%	208	41	80.3%
151		27	8	70.4%	327	103	68.5%	27	3	88.9%	326	98	69.9%
170		19	0	100.0%	206	12	94.2%	19	1	94.7%	205	30	85.4%
171	36	19	0	100.0%	211	11	94.8%	19	11	42.1%	211	86	59.2%
172		19	4	78.9%	210	19	91.0%	19	7	63.2%	208	69	66.8%
173		19	1	94.7%	203	25	87.7%	19	5	73.7%	202	83	58.9%
174		19	3	84.2%	211	23	89.1%	19	4	78.9%	211	52	75.4%
175	24	19	1	94.7%	211	23	89.1%	19	8	57.9%	211	70	66.8%
176		19	2	89.5%	203	17	91.6%	19	2	89.5%	201	26	87.1%
177		19	1	94.7%	211	28	86.7%	19	1	94.7%	211	47	77.7%
178		19	1	94.7%	211	27	87.2%	19	4	78.9%	209	35	83.3%
179		19	2	89.5%	211	25	88.2%	19	5	73.7%	210	75	64.3%
181		19	5	73.7%	207	64	69.1%	18	2	88.9%	204	17	91.7%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		19	1	94.7%	201	31	84.6%	19	1	94.7%	199	22	88.9%
183		19	6	68.4%	210	62	70.5%	19	5	73.7%	207	43	79.2%
184		19	3	84.2%	211	36	82.9%	19	1	94.7%	210	28	86.7%
185	18	19	4	78.9%	211	41	80.6%	19	4	78.9%	211	18	91.5%
186		19	8	57.9%	210	29	86.2%	19	8	57.9%	209	61	70.8%
190		19	6	68.4%	210	75	64.3%	19	1	94.7%	209	44	78.9%
192		19	0	100.0%	208	24	88.5%	19	2	89.5%	208	19	90.9%
193		18	5	72.2%	206	83	59.7%	18	2	88.9%	205	90	56.1%
196		19	3	84.2%	207	23	88.9%	18	2	88.9%	205	17	91.7%
197		19	1	94.7%	211	76	64.0%	19	4	78.9%	211	71	66.4%
198		19	0	100.0%	143	17	88.1%	19	1	94.7%	142	22	84.5%
230		27	0	100.0%	164	4	97.6%	27	1	96.3%	164	8	95.1%
232		27	1	96.3%	330	12	96.4%	27	2	92.6%	330	23	93.0%
233		20	5	75.0%	293	66	77.5%	20	11	45.0%	292	99	66.1%
234		27	0	100.0%	331	22	93.4%	27	3	88.9%	330	28	91.5%
235		27	7	74.1%	255	41	83.9%	27	6	77.8%	254	58	77.2%
236		27	0	100.0%	315	10	96.8%	27	4	85.2%	314	43	86.3%
237	49	27	3	88.9%	328	59	82.0%	27	7	74.1%	326	58	82.2%
238		27	3	88.9%	255	23	91.0%	27	3	88.9%	253	21	91.7%
239		27	3	88.9%	329	82	75.1%	27	3	88.9%	328	41	87.5%
240		27	2	92.6%	330	23	93.0%	27	7	74.1%	327	67	79.5%
241	25	27	8	70.4%	330	82	75.2%	27	8	70.4%	330	79	76.1%
243		27	5	81.5%	266	70	73.7%	27	5	81.5%	265	38	85.7%
244	32	20	0	100.0%	292	12	95.9%	20	14	30.0%	292	63	78.4%
245		27	6	77.8%	211	39	81.5%	27	7	74.1%	210	29	86.2%
280	48	27	2	92.6%	331	17	94.9%	27	14	48.1%	330	75	77.3%
281		27	3	88.9%	331	40	87.9%	27	2	92.6%	331	59	82.2%
283		27	10	63.0%	331	84	74.6%	27	4	85.2%	331	65	80.4%
284	52	27	0	100.0%	331	13	96.1%	27	4	85.2%	328	58	82.3%
290	28	27	1	96.3%	331	51	84.6%	27	20	25.9%	328	134	59.1%
291	Cncld	27	16	40.7%	330	109	67.0%	25	12	52.0%	326	88	73.0%
300		26	2	92.3%	314	22	93.0%	25	5	80.0%	311	73	76.5%
301		27	0	100.0%	328	10	97.0%	27	7	74.1%	324	62	80.9%
302	17	26	1	96.2%	309	34	89.0%	26	12	53.8%	305	90	70.5%
305		26	3	88.5%	312	31	90.1%	25	7	72.0%	307	122	60.3%
306		27	1	96.3%	326	17	94.8%	26	7	73.1%	324	89	72.5%
307	18	27	6	77.8%	319	44	86.2%	26	15	42.3%	315	97	69.2%
311	52	26	2	92.3%	323	28	91.3%	26	17	34.6%	317	80	74.8%
316	27	26	4	84.6%	319	22	93.1%	25	19	24.0%	313	97	69.0%
318	145	27	4	85.2%	329	35	89.4%	27	20	25.9%	326	164	49.7%
319	23	27	0	100.0%	330	20	93.9%	27	25	7.4%	325	190	41.5%
329	14	19	3	84.2%	234	12	94.9%	19	4	78.9%	234	19	91.9%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
330		23	0	100.0%	281	6	97.9%	23	0	100.0%	281	15	94.7%
331		27	0	100.0%	331	33	90.0%	26	0	100.0%	330	44	86.7%
332		26	2	92.3%	330	19	94.2%	26	3	88.5%	330	46	86.1%
334		27	1	96.3%	331	11	96.7%	26	3	88.5%	329	43	86.9%
335		27	1	96.3%	331	35	89.4%	26	4	84.6%	328	55	83.2%
336		26	0	100.0%	330	10	97.0%	26	1	96.2%	328	29	91.2%
337		27	2	92.6%	331	20	94.0%	27	8	70.4%	327	44	86.5%
338		27	6	77.8%	331	53	84.0%	26	8	69.2%	328	102	68.9%
339		27	3	88.9%	331	53	84.0%	27	3	88.9%	331	56	83.1%
341		24	5	79.2%	316	49	84.5%	24	10	58.3%	310	51	83.5%
342		27	2	92.6%	331	26	92.1%	27	1	96.3%	329	61	81.5%
350	256	25	1	96.0%	306	19	93.8%	24	19	20.8%	298	170	43.0%
351		26	2	92.3%	313	29	90.7%	26	12	53.8%	311	90	71.1%
352	36	26	3	88.5%	297	24	91.9%	26	11	57.7%	291	92	68.4%
353	336	26	0	100.0%	268	13	95.1%	26	10	61.5%	262	48	81.7%
354		27	2	92.6%	312	37	88.1%	26	14	46.2%	304	115	62.2%
355	191	25	6	76.0%	319	37	88.4%	23	19	17.4%	310	118	61.9%
364	34	27	7	74.1%	320	72	77.5%	27	13	51.9%	314	120	61.8%
365	40	27	2	92.6%	319	13	95.9%	26	15	42.3%	316	124	60.8%
370		22	4	81.8%	317	39	87.7%	19	6	68.4%	304	75	75.3%
371		22	3	86.4%	310	11	96.5%	19	1	94.7%	306	30	90.2%
380	52	23	3	87.0%	312	30	90.4%	22	9	59.1%	311	72	76.8%
381	22	25	3	88.0%	327	15	95.4%	23	10	56.5%	324	70	78.4%
382	16	25	3	88.0%	326	30	90.8%	23	16	30.4%	324	116	64.2%
383		24	1	95.8%	317	27	91.5%	24	13	45.8%	314	136	56.7%
390		26	5	80.8%	312	24	92.3%	25	12	52.0%	310	85	72.6%
391		26	3	88.5%	313	14	95.5%	25	11	56.0%	308	87	71.8%
392	37	26	1	96.2%	326	11	96.6%	24	10	58.3%	321	100	68.8%
393		26	1	96.2%	330	19	94.2%	25	11	56.0%	326	102	68.7%
417		18	3	83.3%	220	47	78.6%	18	3	83.3%	211	25	88.2%
425		18	1	94.4%	222	7	96.8%	17	0	100.0%	221	7	96.8%
448		21	5	76.2%	255	48	81.2%	20	8	60.0%	251	88	64.9%
449		21	2	90.5%	252	34	86.5%	21	2	90.5%	252	44	82.5%
470		19	2	89.5%	234	39	83.3%	19	3	84.2%	228	27	88.2%
471		18	3	83.3%	223	14	93.7%	18	1	94.4%	223	6	97.3%
473		19	0	100.0%	230	15	93.5%	19	0	100.0%	227	10	95.6%
474	20	18	3	83.3%	227	66	70.9%	18	7	61.1%	212	70	67.0%
475		18	2	88.9%	227	8	96.5%	18	1	94.4%	227	16	93.0%
478		19	4	78.9%	222	36	83.8%	19	1	94.7%	220	28	87.3%
479		19	2	89.5%	229	36	84.3%	19	5	73.7%	227	36	84.1%
486		19	4	78.9%	233	35	85.0%	19	3	84.2%	227	61	73.1%
494	36	20	6	70.0%	236	47	80.1%	19	7	63.2%	228	64	71.9%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
495		18	0	100.0%	217	4	98.2%	18	0	100.0%	215	3	98.6%
500	38	10	0	100.0%	305	16	94.8%	10	1	90.0%	302	36	88.1%
502		11	1	90.9%	313	19	93.9%	11	3	72.7%	309	61	80.3%
503	19	27	13	51.9%	327	40	87.8%	27	15	44.4%	320	102	68.1%
504	33	27	1	96.3%	331	20	94.0%	27	8	70.4%	329	98	70.2%
505	50	21	1	95.2%	323	42	87.0%	21	6	71.4%	318	90	71.7%
506	24	27	13	51.9%	326	55	83.1%	25	4	84.0%	318	50	84.3%
507	25	27	12	55.6%	331	48	85.5%	27	15	44.4%	331	115	65.3%
508		27	2	92.6%	326	43	86.8%	27	11	59.3%	322	79	75.5%
509		11	1	90.9%	312	15	95.2%	11	4	63.6%	312	70	77.6%
511		11	1	90.9%	307	25	91.9%	11	2	81.8%	306	52	83.0%
516	51	27	6	77.8%	322	35	89.1%	27	12	55.6%	321	146	54.5%
517		27	0	100.0%	331	8	97.6%	27	22	18.5%	327	149	54.4%
518		27	8	70.4%	331	45	86.4%	27	23	14.8%	329	230	30.1%
519		27	0	100.0%	322	9	97.2%	27	6	77.8%	320	72	77.5%
520		19	4	78.9%	192	29	84.9%	17	1	94.1%	187	10	94.7%
521		19	0	100.0%	230	7	97.0%	18	3	83.3%	229	30	86.9%
522	14	19	3	84.2%	230	42	81.7%	19	3	84.2%	227	23	89.9%
523		19	2	89.5%	230	9	96.1%	19	4	78.9%	229	26	88.6%
524		18	1	94.4%	229	17	92.6%	18	4	77.8%	226	27	88.1%
525		18	0	100.0%	227	16	93.0%	18	1	94.4%	223	15	93.3%
526		19	7	63.2%	204	41	79.9%	19	3	84.2%	201	18	91.0%
527		19	0	100.0%	230	10	95.7%	19	3	84.2%	229	40	82.5%
528		19	2	89.5%	230	19	91.7%	19	2	89.5%	229	32	86.0%
529		19	1	94.7%	230	13	94.3%	19	6	68.4%	229	64	72.1%
530		19	2	89.5%	184	18	90.2%	19	5	73.7%	184	37	79.9%
531		19	1	94.7%	204	14	93.1%	19	0	100.0%	204	13	93.6%
532		19	6	68.4%	230	57	75.2%	18	4	77.8%	228	35	84.6%
534	95	19	3	84.2%	189	28	85.2%	18	1	94.4%	186	17	90.9%
535	11	18	1	94.4%	216	26	88.0%	18	4	77.8%	211	27	87.2%
536	57	19	8	57.9%	230	63	72.6%	19	3	84.2%	226	41	81.9%
537		18	2	88.9%	199	24	87.9%	18	4	77.8%	193	24	87.6%
538		19	2	89.5%	230	26	88.7%	19	3	84.2%	229	46	79.9%
539	11	19	4	78.9%	184	28	84.8%	19	9	52.6%	184	80	56.5%
540	16	19	6	68.4%	229	44	80.8%	17	3	82.4%	219	21	90.4%
541	101	19	3	84.2%	229	25	89.1%	18	5	72.2%	222	41	81.5%
542		19	1	94.7%	229	25	89.1%	19	3	84.2%	226	40	82.3%
543	42	19	3	84.2%	230	27	88.3%	19	9	52.6%	230	72	68.7%
544		19	1	94.7%	228	21	90.8%	18	2	88.9%	224	22	90.2%
545		19	2	89.5%	230	19	91.7%	19	4	78.9%	227	28	87.7%
547	53	19	6	68.4%	230	47	79.6%	19	7	63.2%	230	54	76.5%
548		17	1	94.1%	223	22	90.1%	16	2	87.5%	220	17	92.3%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
549		19	1	94.7%	225	27	88.0%	17	3	82.4%	215	20	90.7%
550		19	2	89.5%	184	20	89.1%	19	8	57.9%	184	44	76.1%
551		19	1	94.7%	226	23	89.8%	19	3	84.2%	216	23	89.4%
562		27	4	85.2%	322	27	91.6%	27	1	96.3%	318	36	88.7%
564		27	0	100.0%	323	19	94.1%	27	3	88.9%	315	41	87.0%
566		27	4	85.2%	321	29	91.0%	27	7	74.1%	318	52	83.6%
567	339	27	1	96.3%	208	11	94.7%	27	4	85.2%	206	13	93.7%
572	Cncld	27	3	88.9%	318	27	91.5%	26	10	61.5%	310	93	70.0%
573	248	27	3	88.9%	320	43	86.6%	27	5	81.5%	313	56	82.1%
579	126	27	2	92.6%	208	13	93.8%	25	6	76.0%	201	43	78.6%
580	117	27	2	92.6%	323	18	94.4%	27	6	77.8%	316	34	89.2%
581	Cncld	27	6	77.8%	323	56	82.7%	26	9	65.4%	320	73	77.2%
584	195	27	5	81.5%	207	30	85.5%	26	22	15.4%	201	130	35.3%
588	100	25	2	92.0%	206	20	90.3%	25	9	64.0%	205	42	79.5%
591	175	27	3	88.9%	320	24	92.5%	26	8	69.2%	313	47	85.0%
593	No OS	23	3	87.0%	313	50	84.0%	23	3	87.0%	292	40	86.3%
595	No OS	25	6	76.0%	316	59	81.3%	25	10	60.0%	313	70	77.6%
600		19	0	100.0%	238	9	96.2%	19	3	84.2%	236	22	90.7%
601		19	7	63.2%	221	90	59.3%	19	2	89.5%	218	27	87.6%
605		19	7	63.2%	228	137	39.9%	19	1	94.7%	224	23	89.7%
607		19	0	100.0%	237	30	87.3%	19	0	100.0%	234	25	89.3%
609		19	0	100.0%	228	23	89.9%	19	4	78.9%	227	23	89.9%
622		16	3	81.3%	136	35	74.3%	15	0	100.0%	133	5	96.2%
626		19	4	78.9%	142	20	85.9%	19	0	100.0%	140	18	87.1%
639		19	2	89.5%	208	40	80.8%	18	1	94.4%	206	20	90.3%
640		19	0	100.0%	228	7	96.9%	19	4	78.9%	226	84	62.8%
641		19	5	73.7%	210	43	79.5%	19	1	94.7%	210	27	87.1%
642		19	2	89.5%	226	11	95.1%	19	1	94.7%	225	27	88.0%
643		19	0	100.0%	240	44	81.7%	19	3	84.2%	237	39	83.5%
644		19	0	100.0%	232	28	87.9%	19	3	84.2%	230	55	76.1%
645		19	1	94.7%	240	42	82.5%	19	9	52.6%	237	55	76.8%
646	43	19	5	73.7%	229	56	75.5%	19	11	42.1%	227	112	50.7%
647		19	3	84.2%	240	35	85.4%	18	1	94.4%	238	50	79.0%
648		19	3	84.2%	236	59	75.0%	19	1	94.7%	236	35	85.2%
649		19	2	89.5%	241	44	81.7%	18	0	100.0%	237	34	85.7%
650		19	4	78.9%	240	45	81.3%	19	3	84.2%	237	39	83.5%
651		19	1	94.7%	240	17	92.9%	18	1	94.4%	237	43	81.9%
652		19	2	89.5%	241	31	87.1%	19	4	78.9%	237	41	82.7%
653		19	3	84.2%	229	36	84.3%	18	2	88.9%	225	41	81.8%
654		19	4	78.9%	230	44	80.9%	19	2	89.5%	226	20	91.2%
655		19	2	89.5%	238	74	68.9%	18	3	83.3%	235	76	67.7%
656		19	7	63.2%	240	54	77.5%	18	3	83.3%	238	33	86.1%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
657		19	2	89.5%	229	29	87.3%	18	1	94.4%	227	30	86.8%
658		19	2	89.5%	240	37	84.6%	19	2	89.5%	238	35	85.3%
680		19	0	100.0%	235	12	94.9%	18	0	100.0%	233	27	88.4%
681		19	1	94.7%	235	18	92.3%	18	7	61.1%	228	93	59.2%
682		19	3	84.2%	234	9	96.2%	19	3	84.2%	234	41	82.5%
683		19	1	94.7%	217	18	91.7%	19	8	57.9%	216	75	65.3%
684		19	5	73.7%	216	37	82.9%	19	2	89.5%	216	47	78.2%
685		19	2	89.5%	231	33	85.7%	19	2	89.5%	228	55	75.9%
686		19	2	89.5%	236	39	83.5%	19	5	73.7%	235	52	77.9%
687		19	4	78.9%	235	38	83.8%	19	3	84.2%	234	39	83.3%
688		19	2	89.5%	234	15	93.6%	19	4	78.9%	233	40	82.8%
689		10	1	90.0%	155	21	86.5%	9	2	77.8%	153	23	85.0%
701	21	27	3	88.9%	263	28	89.4%	27	6	77.8%	260	31	88.1%
702	65	27	2	92.6%	330	34	89.7%	27	12	55.6%	327	82	74.9%
703	No OS	27	18	33.3%	331	111	66.5%	27	13	51.9%	329	98	70.2%
704		27	10	63.0%	262	47	82.1%	26	10	61.5%	254	56	78.0%
710		27	1	96.3%	331	78	76.4%	27	6	77.8%	327	87	73.4%
711	19	27	4	85.2%	322	38	88.2%	25	12	52.0%	299	64	78.6%
712		27	10	63.0%	328	90	72.6%	26	12	53.8%	318	110	65.4%
713	176	26	2	92.3%	198	18	90.9%	20	12	40.0%	176	79	55.1%
714	49	27	15	44.4%	212	90	57.5%	25	17	32.0%	196	93	52.6%
715	28	27	2	92.6%	330	63	80.9%	23	13	43.5%	303	154	49.2%
716	119	27	19	29.6%	331	139	58.0%	25	20	20.0%	323	138	57.3%
717	30	27	8	70.4%	316	76	75.9%	21	10	52.4%	291	96	67.0%
718	20	27	21	22.2%	331	174	47.4%	26	16	38.5%	328	125	61.9%
719		27	10	63.0%	331	113	65.9%	26	12	53.8%	314	96	69.4%
757		27	2	92.6%	116	7	94.0%	27	3	88.9%	115	11	90.4%
761		27	1	96.3%	327	13	96.0%	27	2	92.6%	324	43	86.7%
765	84	27	0	100.0%	327	25	92.4%	27	4	85.2%	327	46	85.9%
769	Cncld	27	0	100.0%	327	27	91.7%	26	6	76.9%	320	63	80.3%
770	Cncld	27	3	88.9%	327	25	92.4%	26	13	50.0%	324	102	68.5%
774	Cncld	27	1	96.3%	327	17	94.8%	26	8	69.2%	325	77	76.3%
777	172	27	0	100.0%	212	12	94.3%	27	12	55.6%	211	54	74.4%
782	68	27	20	25.9%	212	102	51.9%	27	9	66.7%	207	34	83.6%
785		27	5	81.5%	327	27	91.7%	27	6	77.8%	327	59	82.0%
786	145	27	3	88.9%	116	22	81.0%	26	16	38.5%	112	63	43.8%
790	49	27	2	92.6%	327	30	90.8%	27	7	74.1%	324	53	83.6%
794		27	7	74.1%	327	40	87.8%	27	7	74.1%	323	73	77.4%
821		27	0	100.0%	325	6	98.2%	27	16	40.7%	325	137	57.8%
822	29	27	2	92.6%	327	18	94.5%	27	25	7.4%	325	167	48.6%
1333		27	8	70.4%	327	40	87.8%	27	11	59.3%	324	110	66.0%
1340		27	1	96.3%	326	7	97.9%	26	4	84.6%	325	55	83.1%

Amtrak On Time Performance

Trains Arriving Through: 8/27/2026

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2102		19	3	84.2%	87	16	81.6%	19	1	94.7%	86	7	91.9%
2103		19	2	89.5%	151	14	90.7%	19	1	94.7%	150	10	93.3%
2104		19	0	100.0%	177	10	94.4%	19	1	94.7%	175	13	92.6%
2107		19	1	94.7%	208	35	83.2%	19	1	94.7%	205	21	89.8%
2108		19	2	89.5%	208	28	86.5%	19	7	63.2%	202	27	86.6%
2109		19	1	94.7%	101	12	88.1%	19	1	94.7%	99	5	94.9%
2112		19	2	89.5%	48	6	87.5%	19	0	100.0%	46	2	95.7%
2113		19	1	94.7%	87	9	89.7%	19	0	100.0%	87	10	88.5%
2115		19	2	89.5%	87	13	85.1%	19	1	94.7%	86	11	87.2%
2116		19	0	100.0%	48	1	97.9%	19	1	94.7%	48	8	83.3%
2118		19	2	89.5%	48	4	91.7%	19	3	84.2%	48	12	75.0%
2119		19	4	78.9%	48	8	83.3%	18	2	88.9%	47	12	74.5%
2120		19	10	47.4%	48	19	60.4%	18	9	50.0%	46	22	52.2%
2123		19	2	89.5%	86	10	88.4%	19	0	100.0%	85	15	82.4%
2124		18	4	77.8%	179	38	78.8%	18	2	88.9%	177	24	86.4%
2127		19	3	84.2%	48	10	79.2%	19	2	89.5%	47	9	80.9%
2128		19	1	94.7%	48	4	91.7%	19	1	94.7%	48	3	93.8%
2131		19	4	78.9%	48	10	79.2%	19	3	84.2%	48	6	87.5%
2150		19	0	100.0%	201	22	89.1%	19	1	94.7%	198	74	62.6%
2151		19	1	94.7%	150	7	95.3%	19	4	78.9%	148	41	72.3%
2152		19	1	94.7%	106	7	93.4%	19	1	94.7%	105	31	70.5%
2154		19	0	100.0%	109	23	78.9%	19	3	84.2%	105	45	57.1%
2155		19	1	94.7%	210	17	91.9%	19	4	78.9%	206	100	51.5%
2158		19	1	94.7%	47	5	89.4%	19	3	84.2%	47	15	68.1%
2159		19	2	89.5%	203	16	92.1%	19	10	47.4%	201	69	65.7%
2160	39	19	0	100.0%	48	2	95.8%	19	10	47.4%	47	28	40.4%
2162		19	4	78.9%	209	22	89.5%	19	5	73.7%	203	90	55.7%
2165		19	2	89.5%	45	4	91.1%	19	8	57.9%	45	21	53.3%
2167		19	0	100.0%	196	20	89.8%	19	1	94.7%	196	40	79.6%
2171		19	0	100.0%	137	10	92.7%	19	0	100.0%	133	23	82.7%
2190		19	2	89.5%	206	29	85.9%	19	1	94.7%	204	24	88.2%
2193		19	1	94.7%	201	26	87.1%	19	1	94.7%	199	50	74.9%

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2160	BOS	39	DCS	35	DCS	35	NHV-XGX	AM	T.O.L, Control Point, XNA, Control Point, XSS, Restricting cabs mp118.0 to Shaws Cove, also with a xing failure at Miners Lane mp120.2	
86	NYP	26	ENG	39	ENG	35	NPN-WBG	CS	Traction motor Eng 33 with loading problems call mechanical CNOC for assistance. Cut out #. 3. Traction motors., 33	
93	NFK	18	CTI	27	DCS	11	ASD-RVR	CS	Issue with automatic road crossing protection Per EC 1, activation failure at Myrtle St, Other, CFP 14.6	
94	BOS	80	DCS	69	DCS	47	NFK-X3V	NS	Power switch failure Milepost, 77.6, 77.6	
171	RNK	36	FTI	19	FTI	19	CVS-LYH	NS	Meet 27A, Control Point, teal	
175	WAS	24	CTI	35	CTI	27	NHV-STM	MN	Follow metro, Other, enroute	
185	WAS	18	PTI	10	PTI	10	PHL-WIL	AM	Cross over or go around, 2113, Control Point, PHIL TO BALDWIN, OPERATE 4 TRACK	
474	SPG	20	CON	10	CON	10	NHV-NHV	AM	Hold for connecting train	
494	GFD	36	CON	38	CON	38	NHV-NHV	AM	Hold for connecting train, held for late connection of AM94	
53	SFA	183	TRS	167	TRS	167	XJG-XJX	CS	Trespasser strike Stopped behind po91 due to trespasser strike. Routed around incident., Milepost, 632.0, 643.0	
79	CLT	85	PTI	42	WTR	25	PTB-RMT	CS	Heat order Other, PTB	
646	NYP	43	ENG	39	ENG	39	HAR-HAR	AM	Undesired emergency application, 9646 CB CC, SWAPPED EQUIPMENT WITH 648	
19	NOL	69	TRS	115	TRS	115	SAL-CLT	NS	Trespasser strike Milepost, 352.9, 352.9	
63	TWO	77	DMW	6	SYS	4	SYR-XSV	CS	Unscheduled passenger stop	
64	NYP	22	CTI	24	CTI	17	POU-CRT	MN	Follow metro north, 890, Milepost w/Letters, mp 65.0, cp 35	
237	ALB	49	CTI	22	CTI	22	CRT-POU	MN	Meet mn, Control Point, 39	
241	ALB	25	OTH	4	HLD	4	NYP-NYP	AM	Passenger and/or baggage, HELD FOR TRAVEL OFF AM20	
244	NYP	32	CTI	41	CTI	17	CRT-YNV	MN	Follow metro, 780, Milepost, 33, 15	
280	NYP	48	DSR	41	DMW	19	SYR-ROM	CS	Unable to contact dispatcher / MW foreman Wait for M.O.W. Foreman Burdick to answer to receive permission through working limits. Further delayed approaching next crossing ensuring gates were functioning before resuming track speed, Milepost, 260.0, 256.0	

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
284	NYP	52	DSR	30	CTI	19	POU-CRT	MN	Follow mn, Control Point, 61
290	NYP	28	RTE	19	RTE	19	ALB-HUD	AM	Dispatcher hold Held at 141 for 233 to come north and 284 to head south then followed them out while single tracking between 141 and 124, Control Point, 141
291	BTN	Trn Cancelled	SVS	11	SVS	11	ALB-ALB	AM	Brake shoe needed repair on the 9702 Other, alb
90	NYP	61	DMW	54	POL	42	RMT-PTB	CS	Fire department hold
97	MIA	156	PTI	144	PTI	136	JSP-JAX	CS	Wait for station track P041, Control Point, Dinsmore
41	MIA	328	TRS	328	TRS	328	XJG-JAX	CS	Vehicle strike Vehicle strike at Moncrief, Milepost, 636.0, 636.0
26	MOE	25	FTI	39	FTI	34	PAG-MOE	CS	Follow CSX M606028, Milepost, 693.6, 671.8
6	CHI	69	DSR	87	PTI	29	XNV-XSZ	UP	Meet Take the siding, AMT 5, Siding, Timpie
522	SAC	14	TEN	27	TEN	27	OKJ-OKJ	UP	Air / Brake Air issues on JPBX 921. Brake cylinder not fully developing on setting brakes. TASI mechanical diagnosed issue as a sticky brake gauge, and gave us permission to depart., JPBX921
534	SAC	95	POL	105	POL	105	BKY-RIC	UP	Gas leak near mp 10.6
535	OKJ	11	PTI	11	PTI	11	EMY-OKJ	UP	Meet Amt 530, Control Point, King St.
536	SAC	57	DMW	42	DMW	35	BKY-BKY	UP	Held at BKJ per dispatcher instructions. Gas leak at mt10.6 on main line. Other, BKJ
539	SJC	11	PTI	10	PTI	10	GAC-SCC	UP	Meet Amt538, Control Point, Co044
540	SAC	16	ITI	17	ITI	17	OKJ-OKJ	UP	Late arriving inbound train 541 541
541	OKJ	101	POL	83	POL	83	RIC-RIC	UP	Gas leak at mp 10.60 MTZ sub.
543	SJC	42	POL	39	POL	39	MTZ-MTZ	UP	RMCC shutdown for gas leak at at 10.6 on the Martinez sub. Held at MTZ
547	SJC	53	ITI	48	ITI	48	SAC-SAC	UP	Service, turn, or wye train 534
500	SEA	38	POL	30	POL	30	PDX-VAN	BN	Dispatcher hold Fire near tracks. Dispatcher told us to hold., Milepost, 1.5, 1.5
503	EUG	19	DSR	18	PTI	8	CTL-KEL	BN	Meet Including routing us to M2 Vader in Advance of Meet at Ostrander, 502, Control Point, Ostrander
504	SEA	33	FTI	21	PTI	21	OLW-XNI	BN	Meet Amtk 517, Control Point, Nisqually
505	PDX	50	POL	31	POL	31	KEL-VAN	BN	Removal of passenger by police Passenger removal at control point toteff

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
506	SEA	24	PTI	30	PTI	17	PDX-VAN	BN	Meet amtrak 507, Control Point, 0.5
507	EUG	25	FTI	27	FTI	20	VAN-PDX	BN	Meet After van station stop backed up to van center to wait for freight to pass. Crossed over from M1 - M2 after freight passed, BNSF 4415, Control Point, van center
516	VAC	51	FTI	32	FTI	32	XF2-X1J	BN	Follow Control Point, Piper - CN Jct, 5432
59	NOL	32	DSR	92	DSR	17	NBN-MEM	CC	Per bulletin Milepost, 310.6, 311.0, 30, 1, Milepost, 327.9, 328.6, 30, main, Milepost, 336.6, 337.0, 60, main, Milepost, 338.4, 338.8, 39, main, Milepost, 351.2, 351.2, 70, main, Milepost, 389.6, 390.0, 10, main, Milepost, 390.6, 390.99, 10, main
8	CHI	45	FTI	136	FTI	47	MAL-GGW	BN	Meet Duck and Tuck, Siding, Saco, BN 8076, BN 3809
28	SPK	75	POL	51	POL	45	BNG-BNG	BN	Fire department hold Dispatcher hold at Bingen Depot
822	OKC	29	DSR	28	DSR	14	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, m1, Milepost, 358.7, 351.1, 50, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 374, 374.1, 60, m, Milepost, 375.4, 376.6, 60, m, Milepost, 375.9, 376.1, 60, m, Milepost, 377.5, 378.3, 75, m, Milepost, 378.7, 378.9, 60, m, Milepost, 379.5, 380.7, 60, m, Milepost,
329	MKE	14	SYS	18	SYS	16	CHI-CHI	AM	Late bulletins due to Amtrak cause
350	PNT	256	TRS	183	TRS	116	DER-DER	MI	Holding at Dearborn station due to 353 trespasser strike on Conrail territory Other, dearborn station
352	PNT	36	ADA	30	ADA	13	DET-DET	CC	Wheelchair Very large and Heavy wheel chair. Struggled to get the wheelchair onto lift also conductor working alone
353	CHI	336	TRS	290	TRS	290	X1W-XT6	CR	Trespasser strike Milepost, 5.75, 5.75
355	CHI	191	ITI	177	ITI	177	PNT-PNT	CC	Service, turn, or wye train 350, Late inbound AMT 350 which arrive in PNT at 6:37pm. Train needed wyed after arrival.
364	PTH	34	FTI	39	FTI	23	XH6-XPI	NS	Cross over or go around 264, ns3647, Milepost, 504, 501, Milepost, 497, 490

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
365	CHI	40	DSR	53	DSR	20	LNS-BTL	CC	Per bulletin Milepost, 210.40, 210.40, 30, MAIN TWO, Milepost, 202.45, 202.25, 25, MAIN, Milepost, 196.82, 196.82, 25, MAIN TWO, Milepost, 185.66, 184.79, 30, MAIN TWO, Milepost, 182.85, 181.99, 30, MAIN TWO, Milepost, 181.34, 180.91, 30, MAIN TWO, Milepost, 179.15, 179.15, 25, MAIN TWO, Milepost, 1
567	LAX	339	TRS	206	TRS	206	FUL-FUL	BN	Trespasser strike 765 trespasser strike at 155.0 waiting for tracks to open, Milepost, 155.0, 155.0
572	SAN	Trn Cancelled							
573	LAX	248	POL	209	POL	149	SNA-SNA	SC	RR blocked by trespasser or vehicle strike by another train 765 trespasser strike. Open door policy per DS at SNA
579	LAX	126	POL	131	POL	53	IRV-IRV	SC	RR blocked by trespasser or vehicle strike by another train Holding at IRV due to train congestion caused by an earlier trespasser strike at Norwalk by 765.
580	SAN	117	ITI	59	ITI	59	LAX-LAX	SC	Service, turn, or wye train 567, Waiting for late arriving equipment off of train 567.
581	LAX	Trn Cancelled							
584	SAN	195	POL	88	POL	78	OSD-SOL	SN	Right of Way police hold DS STOPPED US AT CP FAR DUE TO POLICE ACTIVITY
588	SAN	100	POL	50	POL	30	OSD-SOL	SN	Right of Way police hold
591	LAX	175	ITI	88	ITI	88	SAN-SAN	SN	Service, turn, or wye train 580
593	LAX	No OS Rpt	POL	54	ITI	46	SAN-SAN	SN	Service, turn, or wye train 782, Late arriving inbound equipment from train 782.
595	LAX	No OS Rpt	ITI	163	ITI	163	SAN-SAN	SN	Service, turn, or wye train 584
765	SLO	84	TRS	417	TRS	417	FUL-XRJ	BN	Trespasser strike Other, lakeland road xing
769	GTA	Trn Cancelled	POL	225	POL	199	ANA-XFT	SC	RR blocked by trespasser or vehicle strike by another train
770	SAN	Trn Cancelled	POL	138	POL	138	LAX-LAX	SC	RR blocked by trespasser or vehicle strike by another train 765 TRS strike
774	SAN	Trn Cancelled	POL	25	POL	25	LAX-LAX	SC	RR blocked by trespasser or vehicle strike by another train A765 trespasser strike on BNSF
777	SLO	172	POL	105	DCS	70	FUL-XRJ	BN	CTC system failure Control Point, eastern

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
782	SAN	68	POL	46	POL	46	XRJ-FUL	BN	RR blocked by trespasser or vehicle strike by another train
786	SAN	145	POL	65	POL	65	OSD-SOL	SN	Right of Way police hold Hold at Carlsbad Village.
790	SAN	49	FTI	22	FTI	12	XRJ-FUL	BN	Meet 8269, Control Point, Santa Fe Springs, BNSF
701	SAC	21	TEN	36	TEN	36	MCD-TRK	BN	Loading problem Ground relay fault Fault code 1893: "Feedback inconsistent with engine RPM", C2005
702	BFD	65	FTI	80	FTI	39	MCD-MDR	BN	Held due to disabled freight train ahead. Control Point, EE SHARON, BNSF 8075
703	SAC	No OS Rpt	CON	87	CON	87	BFD-BFD	BN	Hold for thruway bus
711	OKJ	19	FTI	26	FTI	16	WAC-COC	BN	Meet BNSF 7102, Control Point, W. Allensworth
713	OKJ	176	POL	34	POL	34	MTZ-RIC	UP	Fire department hold UP Dispatcher 62 notified AMTK 713 of railroad traffic closure at MP 10.60 due to a gas leak.
714	BFD	49	PTI	31	TCC	21	MCD-MDR	BN	Door C6961, Had to stop in Sharon sighting due to door issues
715	OKJ	28	FTI	16	FTI	13	COC-HNF	BN	Meet bnsf 8075, Siding, guernsey
716	BFD	119	RTE	97	RTE	93	EMY-RIC	UP	Dispatcher hold Gas Leak, Milepost, 10.60, 10.60
717	OKJ	30	PTI	34	ITI	17	BFD-BFD	BN	Service, turn, or wye train 702
718	BFD	20	DSR	20	DMW	7	WAC-BFD	BN	Waiting for MW clearance Forman Garcia 711, Milepost, 902.3, 896.8
3	LAX	471	CAR	264	CAR	264	NDL-BAR	BN	Legitimate wayside HBD or DED actuation 32039, Axle 27 set off HBD. Crew inspected, warmer slightly than surrounding axles; DS instructed us to wait for Responder but since he was 90 minutes away, the bearings would have cooled down making the readings inconclusive. Moved PAX, set out car on spur
21	SAS	222	ENG	155	ENG	140	MVN-ARK	UP	Other electrical failure 325
302	CHI	17	FTI	21	PTI	17	JOL-JOL	UP	Meet 319, Other, jol station
307	STL	18	FTI	37	FTI	24	PON-BNL	UP	Meet UP6496, Other, BALARD
380	CHI	52	POL	44	POL	44	QCY-QCY	BN	Blocked from station track due to BNSF 5427 trespasser strike at MP 257.9, Control Point, west Quincy

Amtrak Endpoint OTP Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/27/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
381	QCY	22	FTI	16	FTI	16	GBB-GBB	BN	Follow Galesburg yard job 108, bnsf675, Control Point, A-plant	
382	CHI	16	DMW	17	DMW	17	NPV-LAG	BN	Held for or routed around MW work or equipment Control Point, Downers Grove	
392	CHI	37	CTI	17	DCS	17	CEN-EFG	CC	Restrictive signal(s) from known wayside signal failure Stop, Control Point, Edgewood	
311	KCY	52	FTI	46	FTI	28	WAR-LEE	UP	Follow UP 7493, Other, WAR, Other, LEE	
316	STL	27	DSR	39	DSR	14	WAH-KWD	UP	Per bulletin Milepost, 30.25, 29.75, 30, MT 2, Milepost, 27.5, 27.0, 30, MT 2, Milepost, 26.0, 25.25, 40, MT 2, Milepost, 23.0, 21.0, 15, MT 2	
318	CHI	145	FTI	98	FTI	88	LEE-WAR	UP	Meet Met three freight trains, 7493, 1128, ?, Siding, centerview	
319	KCY	23	DSR	36	PTI	13	PON-BNL	UP	Meet Train 319 held in Siding, Amtrak Train 22, Siding, Pontiac	

Amtrak Initial Terminal Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/27/2026

Terminal	Train	Date	Late	Delay	Cause
BOS	2193	08/27	15	15	Other electrical failure, 2015 LH LP, HSR Mech rpts need to reset AM2193 e/2015
CLT	74	08/27	11	11	Late / wrong track bulletins from host railroad CSX, Other, CLT Station
HAR	622	08/27	1	1	Passenger and/or baggage
HAR	646	08/27	39	39	Undesired emergency application, 9646 CB CC, SWAPPED EQUIPMENT WITH 648
HAR	648	08/27	11	11	HEP, 9646 CB CC, LOSING POWER, NO POWER BRAKE ALERT, WYE EQUIPMENT
HAR	656	08/27	2	2	Wet / slippery rail, Control Point, .
NFK	94	08/27	1		
NYP	19	08/27	4	4	Water, commissary, toilet/trash dumping, NECESSARY TO RELOAD COMMISSARY
NYP	49	08/27	11	11	Other electrical failure, 703, 710, TEMPORARILY LOST DC POWER
NYP	233	08/27	4	4	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	237	08/27	20	20	Service, turn, or wye train, 284, LATE TURN OFF AM284
NYP	241	08/27	4	4	Passenger and/or baggage, HELD FOR TRAVEL OFF AM20
PHL	110	08/27	3	3	PTC - Stop Bypass Permission Required, Control Point, PHL
SAV	90	08/27	2	2	Wheelchair Two Wheelchair lifts
SFA	52	08/27	51	51	Service, turn, or wye train 53
WAS	134	08/27	8	8	Other electrical failure, 652, DOOR LIGHT STILL SHOWING, NECESASSARY TO PUT IN DOOR BYPASS.
CHI	3	08/27	95	30	Over speed alarm 19
CHI	3	08/27	95	25	Engine ats bare needed to adjust and wires hanging 19
CHI	3	08/27	95	40	Water, commissary, toilet/trash dumping Control Point, CHI terminal
CHI	59	08/27	41	41	Switch car for no reason given 37013
CHI	307	08/27	165	165	Service, turn, or wye train 353
CHI	329	08/27	16	16	Late bulletins due to Amtrak cause
PNT	355	08/27	177	177	Service, turn, or wye train 350, Late inbound AMT 350 which arrive in PNT at 6:37pm. Train needed wyed after arrival.
QCY	380	08/27	44	44	Blocked from station track due to BNSF 5427 trespasser strike at MP 257.9, Control Point, west Quincy
STL	302	08/27	3	3	Water, commissary, toilet/trash dumping
BFD	703	08/27	87	87	Hold for thruway bus
BFD	717	08/27	17	17	Service, turn, or wye train 702

Amtrak Initial Terminal Details

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/27/2026

Terminal	Train	Date	Late	Delay	Cause
GTA	770	08/27	(Trn Cxld)		Signal Outage
GTA	782	08/27	11	11	Meet 14, Control Point, CO 358
GTA	790	08/27	(Trn Cxld)		Signal Outage
LAX	572	08/27	(Trn Cxld)		Trespasser Strike
LAX	580	08/27	59	59	Service, turn, or wye train 567, Waiting for late arriving equipment off of train 567.
LAX	584	08/27	52	52	Waiting on 770 to shove back into union station. Trespasser strike caused crew to DOL. waiting for 770 pax to come into union station to transfer over to 584 Milepost, 0.0, 0.0
OKJ	522	08/27	27	27	Air / Brake Air issues on JPBX 921. Brake cylinder not fully developing on setting brakes. TASI mechanical diagnosed issue as a sticky brake gauge, and gave us permission to depart., JPBX921
OKJ	536	08/27	18	18	Door C8805, Door #'s 4&5 would not close. Defective key station. Departed Oakland maintenance yard late.
OKJ	540	08/27	17	17	Late arriving inbound train 541 541
OKJ	714	08/27	4	4	PTC - On Board Cab Signal or PTC Failure C6961
OKJ	716	08/27	3	3	Issues with pcs during air test Also left yard late 1355 then all Red at King waited for 534 C8308
OKJ	718	08/27	30	30	Water, commissary, toilet/trash dumping
PDX	502	08/27	2	2	PTC- IETMS incorrect consist After getting consist corrected had to do a departure test., Other, PDX
SAC	531	08/27	6	6	Meet UP 4317, Control Point, W. SAC
SAC	537	08/27	11	11	PTC problem or failure (cause unknown) After already having been logged in to PTC, PTC experienced a "reverser wiring to TMC" failure requiring reset of the PTC breaker, logging back in, and departure test. SAC RFE Kyle Barton assisted in rebooting PTC system., Other, SAC Depot
SAC	547	08/27	48	48	Service, turn, or wye train 534
SAC	704	08/27	2	2	Door C9307, All doors we're closed before departure except one. Upon inspection the door where baggage is loaded through was closed but once keyed and pressed the close button again, we got a door light.
SAN	581	08/27	(Trn Cxld)		Signal Outage
SAN	591	08/27	88	88	Service, turn, or wye train 580
SAN	593	08/27	46	46	Service, turn, or wye train 782, Late arriving inbound equipment from train 782.
SAN	595	08/27	163	163	Service, turn, or wye train 584
SAN	785	08/27	(Trn Cxld)		Signal Outage
SEA	8	08/27	55	30	Routine inspections Including late wyeing of train.

Amtrak Initial Terminal Details

26-FOI-00703 00000008731 "UNCLASSIFIED" 9/2/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 8/27/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	8	08/27	55	25	Electrical failure 32095
SLO	774	08/27	(Trn Cxld)		Signal Outage
SLO	786	08/27	1		
SLO	794	08/27	22	22	Fuel Other, SLO Spur track

Eastern Region

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	99.4	94.8	342	0
CDOT	95.0	80.0	88.4	92.4	20	1
MARC	95.0	91.4	84.4	90.2	58	5
SEPTA	95.0	96.4	95.3	91.5	195	7
NJT-NED	95.0	97.9	91.7	88.6	349	7
NJT-SED	95.0	94.7	98.8	97.2	19	1

Operating Highlights

Train 53(27) North of Fayetteville, NC - Trespasser Incident

28AUG26: Train 53(27) operating with engines 354, 380, and 352 customers onboard was delayed 1 miles north of Fayetteville, NC on the CSX South End subdivision holding at milepost 208.9 for an unoccupied vehicle that was struck on track 2 by CSX M582-27 at milepost 209.8. The vehicle became lodged in the cow catcher of the freight and once the scene was clear to allow rail traffic to resume on track 1 at restricted speed, 53(27) was able to proceed.

Train	Delay	Comment
53(27)	2'43"	
98(27)	1'07"	Congestion
97(27)	41"	

Train 52(27) North of Jesup, GA - Vehicle on Tracks

28AUG26: Train 52(27) operating with engines 317, 352, and 336 customers was delayed 4 miles north of Jesup, GA on the CSX Nahunta subdivision holding at milepost 544.2 for an unoccupied vehicle that was struck by CSX M492-27 at milepost 537.0. Train 52(27) operated on track 1 at restricted speed upon release from dispatch.

Train	Delay	Comment
52(27)	1'37"	

Train 2160(27) West of New London, CT - Signal

27AUG26: Acela 2160 operating with power cars 2127, 2131, and 341 customers onboard was delayed west of New London, CT on the Amtrak NHB Line operating through track occupancy lights from milepost 118 to milepost 122.5 within Shaws Cove interlocking.

Train	Delay	Comment
2160(27)	35"	

Train 494(27) New Haven, CT - Hold for Connection

27AUG26: Train 494(27) operating with cab car 9643, 1 car, and engine 129 was delayed departing New Haven, CT due to waiting on 15 inbound connections from 94(27).

Train 448(26) Springfield, CT - Freight Train Interference

27AUG26: Train 448(26) operating with engines 160, 106, and 79 customers onboard was delayed after departing Springfield, CT on the CSX Berkshire subdivision following CSX 526-27 from Springfield to Worcester.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
448(26)	31"	

Train 98(27) North of Jacksonville, FL - Freight Train Interference

27AUG26: Train 98(27) operating with engines 160, 383, and 223 customers onboard was delayed 30 miles north of Jacksonville, FL on the CSX Nahunta subdivision operating through approaches and restricting signals following CSX I026-27 to milepost 609.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98(27)	30"	

Train 40(26) West of Martinsburg, WV - Weather

27AUG26: Train 40(26) operating with engines 140, 341, and 134 customers onboard was delayed 5 miles west of Martinsburg, WV holding at milepost 104.9 while the crew hand lined the switch at milepost 105 due to weather causing the switches to fall out of correspondence. Once the switches in the interlocking were hand lined, train 40(26) proceeded west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(26)	45"	

Train 90(27) North of Rocky Mount, NC - Police Related

27AUG26: Train 90(27) operating with engine 127, 8 cars, and 182 customers onboard was delayed at milepost 84.9, 37 miles north of Rocky Mount, NC on the CSX North End subdivision due to a police hold on all tracks for a fire in the area. Once the police hold was lifted, Train 90(27) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
90(27)	43"	

Train 68(27) Train 68(18) North of St-Lambert, QC -CN Heat Orders/ Weather

27AUG26: Train 68(27) was delayed on the CN Rouses Point subdivision due to Heat Orders from MP 40 to MP 15.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(27)	44"	

CSX Heat Orders - Weather

27AUG26: Trains were delayed on the following CSX subdivisions due to heat orders in effect between 100PM-ET through 700PM-ET: North End, Peninsula, Richmond Terminal, Auburndale, Carters, and Lakeland.

Train	Delay	Comment
97 (26)	17"	
40 (27)	55"	
53 (27)	27"	
79 (27)	33"	
89 (27)	23"	
80 (27)	02"	
90 (27)	21"	
95 (27)	04"	
138 (27)	03"	
186 (27)	14"	

Train 94(27) South of Petersburg, VA - Power Switch Failure

27AUG26: Train 94(27) operating with engine 132, 9 cars, and 142 customers onboard was delayed at milepost 77.6, 7 miles south of Petersburg, VA on the NS Norfolk District due to power switch failure. The train had to wait for maintainers to provide a clear route. Once the route was provided, Train 94(27) advanced to the next station.

Train	Delay	Comment
94 (27)	47"	

Train 646(27) Harrisburg, PA - Engine Failure

27AUG26: Train 646(27) operating with cab car 9646, 4 cars, engine 626, and 33 customers onboard was delayed departing Harrisburg, PA on the Amtrak PH Line due to power loss on cab car 9646 after departing the station. It was reported that the crew could not take power due to no brake power. The crew was instructed to cut out ACSES and that was unsuccessful in fixing the problem. The crew changed ends and reversed back to Harrisburg station. The crew and customers transferred equipment and departed the station at 9:39 AM-ET.

Train	Delay	Comment
646 (27)	39"	

Train 41(25) North of Jacksonville, FL - Fatal Vehicle Strike - Trespasser Incident

27AUG26: Train 41(25) operating with engines 256, 326, 10 cars, and 156 customers onboard struck an occupied vehicle at milepost 637.4, 2 miles north of Jacksonville, FL on the CSX Jacksonville Terminal subdivision. The strike was fatal and occurred at DOTX 620753S. The crossing was equipped with signs and signals, crossing symbols, and stop lines. The weather was 74 degrees and clear. The train maintained headend power and was intact on the rails. There were no reported injuries to the crew or the customers. Local management and emergency services responded to the scene. The crew requested relief and a crew was sent from Jacksonville to the scene to recreate the train.

Train 53(26) was stopped at milepost 633.6 to wait for a clear route through the area. Pilots were secured from CSX and the train was detoured around Train 41(25). Train 52(27) was late departing Sanford due to late turn of equipment from Train 53(26).

Train 97(26) was stopped waiting on a clear route through the area. Once the scene was cleared and the tracks opened, train 97(26) was able to advance to the next station.

National Response Center Number: 1471991

Train	Delay	Comment
53(26)	2'47"	
97(26)	1'22"	
41(25)	5'22"	
52(27)	51"	Turn of late equipment

Train 97(26) North of Charleston, SC - Freight Train Interference

27AUG26: Train 97(26) operating with engines 199, 326, 10 cars, and 165 customers onboard was delayed at milepost 376.6, 14 miles north of Charleston, SC on the CSX Charleston subdivision due to meeting CSX freight train 410. Once the freight train cleared, Train 97(26) advanced to the next station.

Train	Delay	Comment
97(26)	47"	

Train 86(27) North of Newport News, VA - Engine Failure

27AUG26: Train 86(27) operating with engine 33, 8 cars, and 58 customers onboard was stopped 7 miles north of Newport News on the CSX Peninsula subdivision at milepost 29.0 with no head end power and no tractive effort from multiple fault codes. The crew worked with CNOC mechanical and Washington mechanical to resolve the issue by resetting the unit and cutting out tractive motor 3.

Train	Delay	Comment
86(27)	35"	

Train 291(27) East of Saratoga Springs, NY - Weather

27AUG26: Train 291(27) operating with engine 9702, 708, and 105 customers onboard was delayed holding at Saratoga Springs, NY on the CPKC Canadian subdivision for tornado warnings that expired at 7:00 p.m. A track patrol unit operated ahead of 291(27) and found a large tree that would have required a grapple truck at milepost 45.0. Due to this, train 291(27) terminated Saratoga Springs and train 290(28) originated Saratoga Springs with 2 buses confirmed for each train to operate full service from Saratoga Springs to Burlington for 291(27) and Burlington to Saratoga Springs for 290(28). The equipment remained tied down in Saratoga Springs and Albany mechanical met the train to update the paperwork.

WBS#: B.TR.100150.7101

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
43	LEW	1	HGD	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Train - Police Related

28AUG26:

Due to police activity between Oceanside (OSD) and Solana Beach (SOL), several trains were held while awaiting the reopening of the route. Trains 588(27), 786(27), 584(27), 891(27), and 593(27) were impacted by the service disruption. The delay was caused by a trespasser on the tracks, and local law enforcement responded to the scene to remove the individual and ensure the area was safe for train operations. Once police cleared the incident and the route was reopened, all affected trains resumed movement.

Train	Delay	Comment
588 (27)	1'28"	
584 (27)	1'35"	
786 (27)	1'17"	
591 (27)	1'20"	
593 (27)	1'17"	

Train 3(27) East of Lawrence, KS - Freight Train Interference

28AUG26: Train 3(27) was delayed holding at MP3.5, 36.9 miles east of Lawrence KS station on the BNSF Emporia subdivision meeting BNSF freight train Z LACWSP1 26. Train 3(27) was back on the move at 1202AM CT after the freight cleared.

Train	Delay	Comment
3 (27)	41"	

Train 7/27(26) Spokane, WA - Engine Failure

28AUG26: Train 7/27(26), operating with engine 377/368, 10 coaches, 202 customers will terminate its 27(26) section at Spokane, WA, due to a fault code indicating a bad fuel pump on trailing loco 368. A BNSF freight was sourced (BNSF6572) to assist out of Spokane. The entire consist of 7/27(26) will travel to Seattle where loco 368 can be repaired. Buses were sourced for customers traveling Spokane to Portland and for customers traveling Portland to Spokane on train 28(28).

WBS#: B.TR.100150.7102

Train 14(27) West of Martinez, CA - Fire Near Tracks

28AUG26: Train 14(27), operating with engines 318/350, 9 coaches, and 147 customers, was delayed 4.5 miles west of Martinez, CA, on UP Martinez subdivision, due to a fire reported on or near the tracks. Train 14(27) held until the fire was extinguished and the tracks were inspected.

Train	Delay	Comment
14 (27)	1'01"	

Train 26(27) South of Mobile, AL - Freight Train Interference

27AUG26: Train 26(27) was delayed beginning at MP693.6, 3.05 miles south of Mobile, AL station on the CSX NO and M subdivision following CSX freight train M606028. Train 226(27) was able to get around the freight train at MP671.8 and resumed operating at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(27)	34"	

Train 703(27) Wasco, CA - Freight Train Interference

27AUG26: Train 703(27), operating with engine 2013, 8 coaches and 47 customers was delayed departing Wasco, CA, on BNSF Bakersfield subdivision due to a disabled freight ahead of them. The freight was having air issues that required the crew to inspect the equipment. Once the crew recovered the freight got back on the move, creating a route for train 703(27).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(27)	34"	

Train 21(26) Fort Worth, TX - Servicing

27AUG26: Train 21(26) was delayed departing Fort Worth, TX /MP346.2 station on the BNSF Fort Worth subdivision due to a late arriving fuel truck. The fuel truck arrived on site at approximately 612PM CT and began fueling train 21(26). Train 21(26) departed Fort Worth TX station at 650PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(26)	1'04"	

Train 1(26)/421(25) East of El Paso, TX - Freight Train Interference

27AUG26: Train 1(26)/421(25) was delayed beginning at MP794.9, 36.9 miles east of El Paso TX station on the UPRR Valentine subdivision meeting and following UPRR freight trains 7417 and 2335.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(26)/421(25)	32"	

Train 14(26) South of Eugene, OR - Freight Train Interference

27AUG26: Train 14(26) was delayed holding at MP647.1, .5 miles south of Eugene OR station on the UPRR Brooklyn subdivision due to UP Freight 4302 stopped ahead with a broken knuckle in front of the station. The freight crew was able to repair the broken knuckle and moved to clear a route for 14(26). Train 14(26) was back on the move at 1255PM PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(26)	35"	

Gas Leak South of Richmond, CA - Police Related

28AUG26:

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

A reported gas leak south of Richmond (RIC) at Milepost 10.60 caused significant delays to train operations. Initially, Trains 541(27), 534(27), and 716(27) were delayed while emergency responders assessed the situation. Union Pacific (UP) reported that excavators were needed to access the area and shut off the gas source, with an estimated arrival time of 1 hour and 30 minutes. In addition, a hazardous materials (HazMat) team was dispatched to monitor gas levels in the vicinity and was estimated to arrive within 1 hour and 45 minutes.

At approximately 3:55 PM PT, the RMCC HazMat team arrived on scene and evaluated conditions in the affected area. After conducting gas level readings, the team determined that concentrations were low enough to safely resume normal train operations. As a result, Trains 541(27), 534(27), and 716(27) were authorized to proceed and returned to service. The incident also resulted in delays to Trains 536(27) and 713(27), which were affected while the response and safety assessments were underway. Normal operations resumed after the HazMat team confirmed that the area was safe for rail traffic.

Train	Delay	Comment
534(27)	1'45"	
716(27)	1'33"	
541(27)	1'23"	
536(27)	35"	
713(27)	34"	

Train South of Los Angeles, CA - BNSF Signal Outage

27AUG26:

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

BNSF reported a signal outage north of Fullerton (FUL) at Milepost (MP) 147.3, which impacted multiple train operations. Train 3(25) was stopped north of Fullerton at MP 150, and a relief crew was already on board. Train 765S(27) was also stopped north of Fullerton at MP 148.7 due to the signal issue. Additionally, Train 770(27) expired under Hours of Service south of Los Angeles (LAX) at MP 143.9. As a result, Train 774(27) was assigned to couple to Train 770(27) and return to Los Angeles. BNSF advised that a signal maintainer was en route with an estimated arrival time of 5:00 PM PT.

As the incident continued, Train 765S(27) remained stopped north of Fullerton because the signal failure at MP 147.3 required a signal reset. BNSF personnel responded to the location and worked to restore normal operations.

Due to delays resulting from the BNSF signal outage, extensive service adjustments were implemented. Train 769N(27) was canceled at Los Angeles, with passengers accommodated on Train 777(27). Train 790N(27) was canceled between GTA and Los Angeles, and affected passengers were re-accommodated on Train 794(27). Train 770S(27) was canceled, with passengers directed to Trains 580(27) or 782(27). Train 581(27) was canceled, and passengers were accommodated on Train 591(27). Train 774S(27) was also canceled, with passengers re-accommodated on Train 580(27). Train 785S(27) was canceled between San Diego (SAN) and Los Angeles, and passengers were directed to Train 591(27). To maintain equipment balance, Train 785N(27) originated from Los Angeles using Train 774N(27) equipment, while Train 790S(27) originated from Los Angeles using Train 769S(27) equipment.

Later in the evening, Train 703(27) was held for a connecting bus that had been delayed while accommodating customers from trains affected by the BNSF signal outage north of Fullerton.

Train	Delay	Comment
769(27)	1'30"	
567(27)	1'50"	
777(27)	1'10"	
580(27)	59"	
786(27)	39"	
703(27)	1'27"	
547(27)	48"	
580(27)	30"	
591(27)	1'28"	
593(27)	46"	
3(25)	2'12"	

Train 505(27) South of Kelso-Longview, WA - Police Related

27AUG26: Train 505(27) was delayed at MP 109.4, 12 miles south of Kelso, WA, on the BNSF Seattle Subdivision holding for police for an unruly customer. Once local police responded to scene and removed the unruly customer, Train 505(27) proceeded south.

Train	Delay	Comment
505(27)	31"	

Train 516(27) South of Vancouver, WA - Freight Train Interference

27AUG26: Train 516(27) was delayed at MP 153.5, 3 miles south of Vancouver, BC, on the CNRR New Westminster Subdivision holding for CN5432 to clear into the yard. Once the freight cleared, Train 516(27) was able to proceed north.

Train	Delay	Comment
516(27)	32"	

Train 3(27) Chicago, IL - Car Failure

27AUG26: Train 3(27) was delayed departing initial terminal of Chicago IL station/MP0.0 due to diner car 37005 being used for train 3(27) because car 38032 was bad ordered. Car 38032 was repaired by yard mechanical and was used to replace car 37005. Train 59(27) was released from the yard at 550PM CT and set in the station at 603PM CT. Train 59(27) departed Chicago IL station at 646PM CT 41 minutes late.

26-FOI-00703 00000008731 UNCLASSIFIED 9/2/2026

27AUG26: Train 3(27) was delayed departing initial terminal of Chicago IL station/MP0.0 due to multiple car and engine issues. At 6:00AM-CT, it was determined that rip and back car 38032 would not be completed in time for service. As a result, replacement car 37005 was identified from inbound Train 58(26), which arrived at 7:31AM-CT, 16 minutes late. The train was wyeed to the yard at 8:18AM-CT. Train 3(27) was made up complete at 12:11PM-CT and released by Mechanical at 1:10PM-CT. Commissary released the train at 1:25PM-CT. At 1:31PM-CT, Mechanical flagged the equipment back into service due to an inoperative microwave on car 37005 that required replacement. Mechanical released the train again at 1:49PM-CT; however, at 2:10PM-CT, engine 19 experienced an overspeed alarm. Mechanical responded and replaced the speed sensor. Train 3(27) departed Chicago Union Station at 3:05PM-CT, 1 hour and 35 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(27)	1'35"	
59(27)	41"	

Train 8/28(26) East of West Glacier, MT - Freight Train Interference

27AUG26: Train 8/28(26) held 1.2 miles east of West Glacier, MT (MP1196.2), on the BNSF Hi Line Subdivision, at Belton (MP1195.0) meeting BNSF 4180.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(26)	42"	

Train 702(27) West of Madera, CA - Freight Train Interference

27AUG26: Train 702(27) was delayed at MP 1030.1, 6 miles west of Madera, CA, on the BNSF Stockton Subdivision due to BN8075 ahead in emergency at MP 1027. The crew held while the freight resolved issues and cleared route. Once route was clear, Train 702(27) proceeded east being further delayed following BN8075 until Hanford, CA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
702(27)	39"	Hold for BN8075
702(27)	10"	Follow BN8075 MDR-FNO
702(27)	15"	Follow BN8075 FNO-HNF

Train 701(27) West of Merced, CA - Third Party Contractor Engine Failure

27AUG26: Train 701(27) was delayed at MP 1062.3, 4 miles west of Merced, CA, on the BNSF Stockton Subdivision due to loading issues with E/C2005. The crew contact mechanical to troubleshoot. Amtrak roadforeman responded from Merced. Once the loading issues were resolved, Train 701(27) advanced to MP 1072.3 where they held for meet with Train 710(27).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
701(27)	36"	Loco Issues
701(27)	10"	Hold for 710(27)

Train 21(26) West of Longview, TX - Heat orders

27AUG26: Train 21(26) was delayed starting 6.8 miles west of Longview, TX (MP89.5), on the UPRR Mineola Subdivision, due to heat orders in effect from Greggton (MP95.7) to Terrell (MP182.4).

Train	Delay	Comment
21(26)	30"	

Train 3(25) East of Victorville, CA - Freight Train Interference

27AUG26: Train 3(25) was delayed starting at Lenwood/MP 6.8, 30 miles east of Victorville, CA, on the BNSF Cajon Subdivision due to freight interference. The crew held at MP 6.8 for two eastbound BNSF freights and one eastbound UPRR freights to clear. Once freight was clear, the crew advanced to Hodge/MP 13.6 where they stopped then followed a BNSF freight.

Train	Delay	Comment
3(25)	30"	Hold Lenwood
3(25)	20"	Hold Hodge

Train 500(27) North of Portland, OR - Fire Near Tracks

27AUG26: Train 500(27) was delayed at MP 0.2, a quarter mile north of Portland, OR, on the BNSF Fallbridge Subdivision due to the hold placed on all tracks due to a possible trackside fire at MP 1.5. An Amtrak roadforeman responded to location. Once on site, the roadforeman was able to verify the tracks were clear. The crew held until the BNSF released the tracks then they proceeded north.

Train	Delay	Comment
500(27)	30"	

Train 765(27) West of Fullerton, CA - Trespasser Incident

27AUG26: At 8:39A-PT, ~~26-FOI-00703~~ ~~00000008731~~ CC/6904-5-~~UNCLASSIFIED~~ s- E/02113, went into emergency after fatally striking a trespasser at MP 155.0 on the BNSF San Bernardino Subdivision. The incident occurred at the Lakeland Road crossing (DOT# 027653E) in Los Angeles County. There were no reported injuries to the crew or the 280 customers on board. There was no damage reported to the equipment and head end power(HEP) remained on and active. The crew held while local police and an Amtrak roadforeman responded to scene. Train 567(27) arrived into Fullerton, CA at 9:21A-PT and Train 769(27) arrived on into Anaheim, CA at 10:15A-PT to hold for open track. An Amtrak roadforeman arrived on scene at 10:20A-PT. Train 765(25) held at scene while the local police conducted their investigation. Due to the length of the delay, several service adjustments were made to the Pacific Surfliner service to alleviate further delays. The equipment from Train 770(27) Goleta to Los Angeles was turned in Los Angeles to operate as Train 765(27) from Los Angeles to San Luis Obispo. Once the equipment was in station and all customer detrained Train 770(25) and customers traveling on Train 765(27) between Los Angeles and San Luis Obispo boarded, Train 765(274) Los Angles to San Luis Obispo section was able to depart. Train 572(27) was cancelled in its entirety with customers reaccommodated on Train 774(27). Train 587(27) was cancelled in its entirety with customers reaccommodated on Train 591(27). The protect comet set was serviced from yard to operate as Train 770(27) Los Angeles to San Diego.

Service recovery was initiated on Train 765(27) SAN-LAX, Train 769(27) and Train 567(27) with complimentary water and snacks available from the cafe.

NRC # 1472022

CA # 26-4377

WBS#: B.TR.100150.7100

National Response Center Number: 1472022

Train	Delay	Comment
765 (27)	6'57"	
769 (27)	3'19"	
573 (27)	3'29"	
777 (27)	1'43"	
770 (27)	2'18"	
579 (27)	53"	
584 (27)	52"	

Train 318(27) West of Warrensburg, MO - Freight Train Interference

27AUG26: Train 318(27) 26-FD000703 00000008731 "UNCLASSIFIED" 19/2/2026 disabled 7 miles west of Warrensburg, MO (MP218.5) on the UPRR Sedalia Subdivision due to freight interference. UP 7493 had stalled on the hill at MP223 and required assistance from UP 1128 to be pushed up the grade. After the shove was completed, additional delay was incurred while a motor was added ahead of UP 7493 to continue west. Once UP 7493, UP 1128, and UP 8891 were moving and able to clear the route, Train 318(27) shoved out of the siding at Centerview (MP225.5) and proceeded east.

After Train 318(27) cleared the area, UP 7493 experienced an undesired emergency at MP237 and was found to have a broken knuckle. As a result, Train 311(27) was delayed holding at Warrensburg while UP 7493 recovered and resumed movement. Once the train was on the move, Train 311(27) followed UP 1128 to Strasburg (MP243.8), UP 8891 to Pleasant Hill (MP249.8), and UP 7493 to Independence Jct (MP271.2).

Train	Delay	Comment
318(27)	1'28"	Disabled Freight
318(27)	03"	Meet 311(27) at Dresden
311(27)	10"	Meet 318(27) at Dresden
311(27)	16"	WAR - Hold
311(27)	30"	Follow

Train 3(25) East of Barstow, CA - Car Failure

27AUG26: At 3:32A-PT, Train 3(25), E/22-E/181-E/78-9 cars, was delayed at West Amboy/ MP 661.6, 84 miles east of Barstow, CA, on the BNSF Needles Subdivision after actuating a hot axle detector. The crew stopped at MP 661.6 to inspect sleeper C/32039 axle R27 and contact mechanical. Amtrak mechanical confirmed with BNSF mechanical that the car needed to be set out. The crew worked to move all 15 affected customers from the defective car to other sleeper car accommodations. At approximately 6:20A-PT, and once all customers were removed, the crew began to set out the defective car at the North Amboy spur track 6629. There were 105 customers on board with the head end power (HEP) intermittent while the crew worked to remove C/32039. The ambient outside temperature was in the 80's and mostly cloudy. At 7:32A-PT, the consist was back together and HEP was restored. Once the crew completed all testing, Train 3(25) proceeded west at 7:40A-PT

Due to the late operation of Train 3(25), service recovery was initiated as follows. All coach customers were provided a snack pack with complimentary water, tea and coffee from the lounge car. All sleeper car customers were provided regular breakfast service and an abbreviated lunch service.

WBS#: B.TR.100150.7098

Train	Delay	Comment
3(25)	4'24"	

Train 353(27) East of Dearborn, MI - Trespasser Strike

27AUG26: At 10:06AM-ET, Train 353(27), "UNCLASSIFIED" E/ID4626 with five cars, struck a trespasser on the Conrail Michigan Line at MP5.75, four miles east of Dearborn, MI (MP9.7), in Wayne County. The incident was determined to be a fatality and did not occur at a crossing. The impact caused a main reservoir and brake pipe hose separation between engine ID4626 and car ID4013, which was repaired after the remains were removed from the train. The crew requested trauma relief at the scene. A recrew went on duty in Pontiac at 11:45AM-ET and arrived at the train at 1:00PM-ET. Head end power remained online throughout the incident. No injuries were reported to the four crewmembers or the 126 customers onboard, and no equipment damage was reported. Local police, fire, EMS, and Amtrak's Toledo Road Foreman responded to the location. Train 353(27) was operating at 60MPH at the time of the incident. A lengthy delay was incurred while awaiting completion of the police investigation and the arrival of the coroner at 2:05PM-ET. Three downline buses were secured but later canceled as the train was expected to be released. Following release of the scene by local authorities and the boarding of the recrew, Train 353(27) resumed westward movement at 2:44PM-ET.

Train 350(27), carrying 122 customers, was held at Dearborn while Train 353(27) cleared the main track. At 2:57PM-ET, Train 350(27) departed Dearborn and proceeded to MP7.6, where it was held pending completion of an environmental cleanup and track inspection at the strike location. Upon completion of the cleanup and inspection activities, Train 350(27) resumed movement to Detroit where it held at the station for the recrew to arrive due to the current crew expiring on their hours of service at 4:43PM-ET. Once the recrew arrived, Train 350(27) continued to Pontiac.

Train 355(27) was delayed departing Pontiac, MI (MP25.9), on the CNRR Holly Subdivision, due to a late turn of Train 350(27)'s equipment that arrived at 637PM-ET, 4 hours and 16 minutes late.

Train 307(27) was delayed departing Chicago, IL due to a late turn of Train 353(27)'s equipment that arrived at 748PM-CT, 5 hours and 36 minutes late.

WBS#:

B.TR.100150.7099

National Response Center Number: 1472014

Train	Delay	Comment
350(27)	1'56"	DER - Hold
350(27)	1'07"	MP7.6 - Hold for Cleanup
350(27)	52"	DET - Recrew
355(27)	2'57"	ITD PNT
307(27)	2'45"	ITD CHI
353(27)	4'50"	

Train 380(27) Quincy, IL - Freight Train Interference

27AUG26: Train 380(27) was delayed departing Quincy, IL (MP258.6), on the BNSF Brookfield Subdivision due to BNSF 5427 striking an unoccupied vehicle at MP257.9. After the scene was released, BNSF 5427 was required to clear westward. Once a route was established, Train 380(27) was released to proceed from the yard to the station, load the 35 customers, and depart.

Train	Delay	Comment
380(27)	44"	

Train 21(26) South of Malvern, AR - Engine Failure

27AUG26: At 5:06AM-CT, 26-FR-00703 26-0000008731 UNCLASSIFIED 8/2/2026 operating southbound with engines 57 and 325 and six cars, stopped 4.7 miles north of Arkadelphia, AR (MP410.9) on the UPRR Little Rock Subdivision at Witherspoon (MP406.2) due to a reported battery fault on trailing engine 325. The crew contacted CNOC Mechanical to troubleshoot the issue while head end power remained intermittent. Additional trainline issues were encountered, and a LAX mechanical technician worked with the crew to resolve the problem. Weather conditions were clear with a temperature of 70 degrees, and 97 customers were onboard. Following troubleshooting efforts, engine 325 was isolated, allowing Train 21(26) to resume southbound movement at 7:17AM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(26)	2'20"	

Train 1(26)/421(25) San Antonio, TX - Car Failure

27AUG26: Train 1(26)/421(25) was delayed departing San Antonio TX/MP209.5 on the UPRR Del Rio subdivision due to a stuck knuckle on car 32082 off train 21(25). San Antonio mechanical were able to get the knuckle released and car 32082 was added to train 1(26)/421(25). Train 1(26)/421(25) departed San Antonio TX station at 350AM CT operating 1 hour and 5 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(26)/421(25)	42"	

Train 6(25) East of Grand Junction, CO - Engine Failure

27AUG26: Train 6(25), E/45-E/193-9 cars, had E/193 isolated after departing Grand Junction, CO (MP 449.5) on the UPRR Glenwood Springs Subdivision due to reported flames coming from the locomotive. Drummac Mechanical was unable to resolve the issue at Denver. As a result, the train continued to Chicago with engine 45 providing propulsion. Engine 193 remained online supplying HEP and was only utilized for propulsion assistance as necessary on ascending grades. Engine 45 carried sufficient fuel to operate the train to Chicago Union Station, with the crew monitoring fuel levels en route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(25)	48"	GJT-CHI

Train 28(26) Bingen-White Salmon, WA - Right of Way Fire

27AUG26: Train 28(26), carrying 71 customers, experienced a delay at Bingen, WA, on the BNSF Fallbridge Subdivision due to reports of a fire within the railroad right-of-way near MP 102.5.

Upon notification of the fire, local authorities responded to the scene and halted all rail traffic in the affected area as a precaution to ensure the safety of train operations, emergency responders, and railroad infrastructure. Train 28(26) remained held at Bingen while the incident was evaluated and emergency personnel addressed the situation.

A track inspector was dispatched to inspect the affected territory and determine whether any damage had occurred to the track structure or surrounding railroad property. After completing the inspection, the track inspector provided an all-clear, confirming that train operations could safely resume.

Train 27(25) was delayed departing Pasco, WA holding for crew rest. Once the engineer arrived on duty at 7:00A-PT, the crew performed their job briefing and tests then were able to depart.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(26)	45"	

Maintenance of Way Highlights

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Aug) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Aug) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has task scheduled on C&M Subdivision at Western Avenue -
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In
order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be
adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (7/20)	ABQ	76		Picked up by BNSF // mu issues
22 (18)	XNT	315		I/O 47 faults

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
Yard	SEA	BNSF6688	E/506 waiting on parts		
7 (26)	SPK	BNSF6572	E/386 fuel injector faults		
22 (28)	SAS	UP5068	E/325 Battery faults		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 318(27) Passenger Removal at Alton, Illinois – Medical

27AUG26, Passenger on PNR ABB879, traveling from Kansas City, MO to Chicago, IL was removed from the train by Alton EMS & Fire. The passenger was feeling numbness on right side of face and dizziness. Amtrak Police notified.

Delay: 318 (27) 07"

Train 505(27) Passenger Removal at Kelso-Longview, Washington – Improper Conduct

27AUG26, Passenger on PNR DE0C51, traveling from Seattle, WA to Vancouver, WA was removed from the train by Cowlitz County Sheriff Office. The passenger was using profanity and loudly screaming on the train. The passengers became irate with conductor after being asked to calm down. Amtrak Police notified.

Delay: 505 (27) 35"

Consist Deviations

26-FOI-00703

00000008731

"UNCLASSIFIED"

9/2/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
448 (27)	CHI	no 4820 sleeper for 448(27) from CHI-ALB only. ALB will add the 62507 to fill out the ALB-BOS section. sleeper sales inhibited. please reaccom affected pax.	13 PAX DG	0	62XXX
448 (27)	CHI	all table lounge in lieu of AMII lounge. no customer impact.	NA	0	43391
448 (27)	CHI	AMI coach in lieu of AMII.	NO CAPACITY IMPACT	0	82535
41 (28)	CHI	VI sleeper in lieu of VII. two extra rooms. schedule change performed to open space.	SVWR41/28AUG NO WAR DATA THIS TRAIN/DATE	0	62013
3 (27)	CHI	OPERATING WITH DINER/LOUNGE IN LIEU OF DINER A/C 38032 NOT OKM BEFORE DEPARTURE TIME.	NA	0	37005
508 (27)	EUG	OPERATING W/O CAB CAR A/C SHOPPED IN SEA. WILL NOT BE ABLE TO ACCOMMODATE PASSENGER WITH BV RESERVATION OR CHECKED BAGGAGE. CNOC CSV PLEASE CONTACT ANY PASSENGERS IMPACTED BY THIS CHANGE.	NA	0	NOCAR
757 (27)	LAX	DUE TO EQUIPMENT SWAP OPERATING WITH 90225 IN CONSIST UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO RE-ACCOMMODATE PASSENGER IMPACTED BY THIS CHANGE.	PASSENGERS NOTIFIED	2	90225
770 (27)	LAX	EQUIPMENT SWAP LAX-SAN OPERATING WITH COMET SET WILL NOT BE ABLE TO ACCOMODATE PASSENGERS BV RESERVATION OR BUSINESS CLASS WILL NEED TO REACCOMODATE	115 JY 3 BV	118	C5004 C5007 C5001 C5002 C5005 9700

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00703 00000008731 "UNCLASSIFIED" 9/2/2026			
		PASSENGER IMPACTED BY THIS CHANGE			
40 (27)	MIA	VIEWLINER II IN LIEU OF A VIEWLINER I. TWO LESS ES ROOMS VS PLAN.	all pax protected	0	62514
97 (27)	NYP	schedule changes performed for 9710 and 9711 car. check war report. crew to be in 9710 car. no additional crew room holdouts required.	NA	0	62517
581 (27)	SAN	OPERATING WITH COMET SET WILL NOT BE ABLE TO ACCOMMODATE PASSENGER WITH BV RESERVATION OR BUSINESS. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGER IMPACTED BY THIS CHANGE.	35 - JY 0 - BV	35	C5004 C5007 C5001 C5002 C5005 9700
503 (27)	SEA	CAB CAR/BAGGAGE CAR REMOVE FOR BAD OUTER SPRING. BAGGAGE/CHECKED WILL NOT BE AVAILABLE.	n/a	0	90230
786 (27)	SLO	DUE TO EQUIPMENT SWAP OPERATING WITH 90225 IN CONSIST UNABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS. CNOC CSV WILL NEED TO RE-ACCOMMODATE PASSENGER IMPACTED BY THIS CHANGE.	PASSENGERS NOTIFIED	2	90225

Reverse Consists

Train Number	Station	Reason
2127 (26)	NYP	Acela consist reversed First class at Rear
95 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
113 (27)	NYP	Consist reversed Business class seat orientation may have changed At Rear
190 (27)	PHL	Consist reversed Business class seat orientation may have changed At Front
174 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front
84 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front
136 (27)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (28)	SPG	Consist reversed Business class seat orientation may have changed At Front
129 (28)	NYP	Consist reversed Business class seat orientation may have changed At Front
86 (28)	NPN	Consist reversed Business class seat orientation may have changed At Front
137 (27)	BOS	Consist reversed Business class seat orientation may have changed At Front
178 (28)	RNK	Consist reversed Business class seat orientation may have changed At Front