



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, July 09, 2026

Rules: 0-36



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-005Initial Terminal Performance By Division

Scheduled Departure Date: 07/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/08/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	299	46	84.6%	2,205	369	83.3%	82,631	11,409	86.2%
Central Division	86.0%	63	8	87.3%	509	56	89.0%	20,262	1,856	90.8%
East Division	82.0%	160	22	86.3%	1,106	212	80.8%	43,022	6,755	84.3%
West Division	86.0%	76	16	78.9%	590	101	82.9%	19,347	2,798	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00590 00000008303 UNCLASSIFIED 7/15/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	93,182	24,392	74%	781,078	309,505	60%	26,346,562	6,528,279	75%
Northeast Corridor	81%	43,608	8,255	81%	346,751	148,969	57%	12,190,532	2,932,162	76%
Acela	83%	10,454	1,477	86%	74,708	29,687	60%	2,411,473	632,364	74%
Northeast Regional	79%	33,154	6,778	80%	272,043	119,282	56%	9,779,059	2,299,798	76%
Richmond / Newport News / Norfolk	77%	8,952	3,286	63%	83,699	44,389	47%	3,034,427	858,010	72%
Springfield Shuttles	89%	670	240	64%	5,780	2,075	64%	173,814	26,289	85%
Roanoke	79%	3,369	953	72%	25,171	13,813	45%	918,231	189,098	79%
On Spine Northeast Regional	80%	20,163	2,299	89%	157,393	59,005	63%	5,652,587	1,226,401	78%
State Supported	80%	39,754	9,784	75%	333,792	97,063	71%	10,738,000	2,203,915	79%
Borealis	80%	561	204	64%	4,613	1,338	71%	155,583	31,784	80%
Capitol Corridor	90%	3,928	325	92%	30,428	4,927	84%	1,031,647	134,123	87%
Carolinian	70%	1,665	1,092	34%	8,863	5,904	33%	318,837	121,810	62%
Cascades	75%	2,905	688	76%	25,823	7,192	72%	713,467	195,752	73%
Downeaster	82%	2,218	61	97%	14,376	3,960	72%	411,874	49,430	88%
Empire	78%	1,632	745	54%	15,904	8,636	46%	431,285	149,374	65%
Adirondack	72%	362	37	90%	3,571	1,691	53%	90,004	27,175	70%
Ethan Allen Express	70%	511	507	1%	4,443	2,905	35%	155,408	50,512	67%
Maple Leaf	70%	759	201	74%	6,915	3,249	53%	181,734	70,036	61%
Berkshire Flyer	60%	0	0	-	975	791	19%	4,139	1,651	60%
Gold Runner	73%	1,786	1,102	38%	21,476	8,663	60%	695,096	240,761	65%
Heartland Flyer	70%	211	204	3%	2,174	1,210	44%	57,879	21,703	63%
Hiawatha	90%	1,731	103	94%	15,107	959	94%	472,801	51,507	89%
Illinois	78%	940	55	94%	10,567	5,026	52%	329,506	99,237	70%
Lincoln Service	70%	940	55	94%	10,567	5,026	52%	329,506	99,237	70%
Keystone	92%	8,853	1,154	87%	52,915	10,982	79%	2,109,992	220,917	90%
Lincoln / Missouri	70%	856	849	1%	5,568	3,265	41%	214,087	107,081	50%
Mardi Gras Service	80%	449	446	1%	3,378	1,510	55%	114,326	23,971	79%
Michigan	70%	1,748	57	97%	19,029	9,716	49%	538,776	174,671	68%
Blue Water	70%	489	0	100%	4,555	3,291	28%	124,781	48,625	61%
Pere Marquette	85%	317	37	88%	2,387	528	78%	69,959	13,858	80%
Wolverine	70%	942	20	98%	12,087	5,897	51%	344,036	112,188	67%
Missouri	80%	217	129	41%	1,261	318	75%	60,497	13,558	78%
Pacific Surfliner	85%	7,378	1,599	78%	81,117	13,569	83%	2,163,641	340,731	84%
Pennsylvanian	80%	745	581	22%	7,132	3,631	49%	245,842	45,790	81%
Piedmont	80%	723	286	60%	3,649	1,858	49%	317,034	80,412	75%
Vermont	75%	1,208	104	91%	10,412	4,399	58%	355,830	101,303	72%
Long Distance	70%	9,820	6,353	35%	100,535	63,473	37%	3,378,763	1,389,739	59%
Auto Train	70%	805	805	0%	6,636	1,615	76%	215,480	72,443	66%
California Zephyr	70%	443	0	100%	7,688	4,202	45%	267,751	89,499	67%
Cardinal	70%	0	0	-	1,729	1,451	16%	65,403	31,693	52%
City Of New Orleans	75%	368	171	54%	368	171	54%	177,732	49,788	72%
Coast Starlight	70%	1,144	551	52%	10,058	2,383	76%	314,822	106,835	66%
Crescent	70%	776	484	38%	7,603	6,010	21%	258,096	78,102	70%
Empire Builder	70%	1,318	764	42%	10,096	5,602	45%	263,157	124,354	53%
Floridian	60%	0	0	-	10,920	10,873	0%	441,085	294,516	33%
Lake Shore Ltd	73%	1,012	930	8%	9,324	4,722	49%	260,961	76,332	71%
Palmetto	70%	442	178	60%	6,853	5,259	23%	254,626	71,357	72%
Silver Meteor	70%	980	911	7%	8,942	7,720	14%	281,323	117,872	58%
Southwest Chief	60%	1,018	641	37%	8,242	5,831	29%	226,892	144,243	36%
Sunset Ltd	70%	407	148	64%	2,766	1,387	50%	81,151	28,068	65%
Texas Eagle	70%	1,107	770	30%	9,310	6,247	33%	270,284	104,637	61%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 000000000000 "UNCLASSIFIED" 7/15/2020

Train Index Dates Through July 08, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	61,069	830,648	735	1,628,002	29,467,690	552

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,155	241,364	131	76,495	8,455,968	90
INFRASTRUCTURE PLANNED	135	3,656	241,364	151	82,528	8,455,968	98
FLEET RELIABILITY	90	11,465	830,648	138	264,454	29,467,690	90
TRAIN OPERATIONS	424	42,793	830,648	515	1,204,525	29,467,690	409

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/08/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	299	46	84.6%	2,205	369	83.3%	82,631	11,409	86.2%
Central Division	86.0%	63	8	87.3%	509	56	89.0%	20,262	1,856	90.8%
East Division	82.0%	160	22	86.3%	1,106	212	80.8%	43,022	6,755	84.3%
West Division	86.0%	76	16	78.9%	590	101	82.9%	19,347	2,798	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/08/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	299	46	84.6%	2,205	369	83.3%	82,631	11,409	86.2%
Central Division	86.0%	63	8	87.3%	509	56	89.0%	20,262	1,856	90.8%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	-	-	-	-	-	-	445	14	96.9%
CHI	86.0%	20	4	80.0%	176	23	86.9%	7,271	880	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	-	-	-	1	1	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	16	0	100.0%	552	52	90.6%
FTW	92.5%	1	0	100.0%	8	1	87.5%	304	35	88.5%
GRR	95.5%	1	0	100.0%	7	0	100.0%	266	8	97.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	12	2	83.3%	550	42	92.4%
LAX	89.5%	1	1	0.0%	8	2	75.0%	270	42	84.4%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	1	83.3%	47	4	91.5%	1,645	101	93.9%
MOE	97.5%	2	0	100.0%	16	1	93.8%	561	9	98.4%
MSP	96.5%	1	0	100.0%	8	0	100.0%	274	5	98.2%
NOL	94.5%	5	1	80.0%	29	6	79.3%	1,179	59	95.0%
OKC	97.0%	1	0	100.0%	8	0	100.0%	275	6	97.8%
PDX	86.0%	4	0	100.0%	32	3	90.6%	1,114	110	90.1%
PNT	88.0%	2	0	100.0%	22	3	86.4%	725	61	91.6%
PTH	93.0%	1	0	100.0%	8	1	87.5%	269	11	95.9%
QCY	91.0%	-	-	-	-	-	-	461	33	92.8%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	8	0	100.0%	277	27	90.3%
SEA	85.0%	7	0	100.0%	56	6	89.3%	1,946	213	89.1%
STL	89.0%	4	1	75.0%	32	4	87.5%	1,089	94	91.4%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	16	0	100.0%	546	14	97.4%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	160	22	86.3%	1,106	212	80.8%	43,022	6,755	84.3%
ALB	88.5%	1	-	100.0%	8	1	87.5%	1,776	155	91.3%
BON	87.5%	5	0	100.0%	39	7	82.1%	1,351	147	89.1%
BOS	85.5%	18	2	88.9%	129	11	91.5%	4,765	572	88.0%
BRK	92.5%	5	1	80.0%	39	8	79.5%	1,340	92	93.1%
BTN	82.0%	1	0	100.0%	8	0	100.0%	267	39	85.4%
CLT	91.5%	5	1	80.0%	26	5	80.8%	1,367	137	90.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	16	2	87.5%	547	52	90.5%
GRO	-	-	-	-	-	-	-	29	10	65.5%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/08/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	299	46	84.6%	2,205	369	83.3%	82,631	11,409	86.2%
East Division	82.0%	160	22	86.3%	1,106	212	80.8%	43,022	6,755	84.3%
HAR	79.5%	13	0	100.0%	80	8	90.0%	3,103	514	83.4%
HFD	-	2	1	50.0%	10	2	80.0%	157	10	93.6%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	8	0	100.0%	277	34	87.7%
MIA	89.5%	2	0	100.0%	15	3	80.0%	554	63	88.6%
MTR	79.0%	1	0	100.0%	8	2	75.0%	264	48	81.8%
NFK	84.5%	2	1	50.0%	16	7	56.3%	637	116	81.8%
NFL	93.5%	-	-	-	-	-	-	478	22	95.4%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	1	80.0%	38	4	89.5%	1,444	227	84.3%
NPN	93.0%	2	1	50.0%	14	3	78.6%	527	38	92.8%
NYP	75.5%	42	9	78.6%	280	81	71.1%	11,014	2,485	77.4%
PGH	93.0%	1	0	100.0%	8	2	75.0%	279	21	92.5%
PHL	48.0%	5	1	80.0%	38	16	57.9%	1,438	693	51.8%
PIT	76.0%	-	-	-	2	2	0.0%	8	7	12.5%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	4	0	100.0%	18	1	94.4%	1,075	42	96.1%
RNK	83.5%	2	0	100.0%	16	4	75.0%	550	81	85.3%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	8	0	100.0%	267	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	6	0	100.0%	274	10	96.4%
SFA	88.0%	1	0	100.0%	8	0	100.0%	277	37	86.6%
SPG	92.5%	5	1	80.0%	44	2	95.5%	1,696	94	94.5%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	8	0	100.0%	267	56	79.0%
WAS	84.0%	32	3	90.6%	215	40	81.4%	6,808	881	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	76	16	78.9%	590	101	82.9%	19,347	2,798	85.5%
ARN	92.0%	1	0	100.0%	8	2	75.0%	279	21	92.5%
BFD	79.0%	6	3	50.0%	52	18	65.4%	1,738	359	79.3%
EMY	72.0%	1	1	0.0%	8	4	50.0%	285	89	68.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	2	1	50.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	0	100.0%	24	5	79.2%	840	119	85.8%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	76	7	90.8%	2,490	243	90.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/08/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	299	46	84.6%	2,205	369	83.3%	82,631	11,409	86.2%
West Division	86.0%	76	16	78.9%	590	101	82.9%	19,347	2,798	85.5%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	3	76.9%	93	31	66.7%	2,992	767	74.4%
PDX	86.0%	1	0	100.0%	8	0	100.0%	263	59	77.6%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	4	75.0%	120	16	86.7%	3,924	426	89.1%
SAN	90.5%	13	1	92.3%	104	8	92.3%	3,348	302	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	1	0.0%	8	3	62.5%	260	106	59.2%
SJC	89.0%	7	0	100.0%	56	5	91.1%	1,963	187	90.5%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	24	2	91.7%	603	62	89.7%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	8	0	100.0%	274	20	92.7%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		4	0	100.0%	119	8	93.3%	4	1	75.0%	119	24	79.8%
3	185	8	0	100.0%	279	54	80.6%	8	2	75.0%	277	119	57.0%
4		8	0	100.0%	278	42	84.9%	8	4	50.0%	278	183	34.2%
5	No OS	8	1	87.5%	277	44	84.1%	7	4	42.9%	273	67	75.5%
6		8	4	50.0%	276	81	70.7%	8	5	37.5%	276	87	68.5%
7	225	8	1	87.5%	268	36	86.6%	8	2	75.0%	261	63	75.9%
8	61	8	3	62.5%	268	114	57.5%	8	5	37.5%	267	154	42.3%
11	92	8	2	75.0%	279	52	81.4%	8	1	87.5%	273	55	79.9%
14		8	2	75.0%	280	43	84.6%	8	0	100.0%	278	83	70.1%
19		8	5	37.5%	278	70	74.8%	8	7	12.5%	276	66	76.1%
20	96	8	4	50.0%	278	22	92.1%	8	7	12.5%	278	54	80.6%
21		8	0	100.0%	275	22	92.0%	8	5	37.5%	274	67	75.5%
22	76	8	0	100.0%	276	25	90.9%	8	5	37.5%	274	67	75.5%
23	113	8	1	87.5%	281	6	97.9%	8	5	37.5%	279	74	73.5%
24	131	8	2	75.0%	281	16	94.3%	8	4	50.0%	280	47	83.2%
25	19	8	0	100.0%	280	3	98.9%	8	3	62.5%	278	72	74.1%
26	82	8	0	100.0%	280	5	98.2%	8	3	62.5%	278	55	80.2%
27		8	2	75.0%	266	16	94.0%	8	2	75.0%	262	83	68.3%
28		8	0	100.0%	262	59	77.5%	8	1	87.5%	262	52	80.2%
41	408	7	5	28.6%	273	107	60.8%	7	7	0.0%	271	203	25.1%
42	32	8	2	75.0%	280	22	92.1%	8	4	50.0%	278	46	83.5%
43		8	0	100.0%	279	41	85.3%	8	5	37.5%	279	61	78.1%
48	31	8	3	62.5%	278	56	79.9%	8	3	62.5%	278	41	85.3%
49	50	8	3	62.5%	278	70	74.8%	8	3	62.5%	278	55	80.2%
50	No OS	3	1	66.7%	114	27	76.3%	4	4	0.0%	114	67	41.2%
52	143	8	0	100.0%	277	37	86.6%	8	1	87.5%	276	62	77.5%
53		8	0	100.0%	277	34	87.7%	8	2	75.0%	276	87	68.5%
55		5	0	100.0%	173	6	96.5%	5	2	60.0%	170	36	78.8%
56		5	0	100.0%	174	22	87.4%	5	3	40.0%	171	29	83.0%
59	117	1	0	100.0%	259	28	89.2%	1	1	0.0%	256	47	81.6%
63	75	8	4	50.0%	281	121	56.9%	8	7	12.5%	277	147	46.9%
64		8	0	100.0%	279	63	77.4%	8	4	50.0%	279	95	65.9%
66	25	8	3	62.5%	278	57	79.5%	6	2	66.7%	274	51	81.4%
67		5	1	80.0%	192	12	93.8%	5	1	80.0%	192	32	83.3%
68		8	2	75.0%	281	57	79.7%	8	4	50.0%	281	107	61.9%
69		8	3	62.5%	268	62	76.9%	8	5	37.5%	264	37	86.0%
71	26	8	0	100.0%	276	3	98.9%	8	7	12.5%	275	73	73.5%
72	12	4	0	100.0%	272	29	89.3%	4	1	75.0%	271	56	79.3%
73	67	3	0	100.0%	275	16	94.2%	3	2	33.3%	273	128	53.1%
74	122	3	1	66.7%	273	31	88.6%	3	2	33.3%	271	96	64.6%
75	44	3	0	100.0%	273	14	94.9%	3	2	33.3%	268	127	52.6%
76		3	0	100.0%	273	26	90.5%	3	2	33.3%	265	106	60.0%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	14	3	1	66.7%	272	18	93.4%	3	2	33.3%	270	110	59.3%
78		8	2	75.0%	276	22	92.0%	8	6	25.0%	275	56	79.6%
79	39	8	0	100.0%	278	55	80.2%	8	7	12.5%	277	91	67.1%
80		8	2	75.0%	278	30	89.2%	7	4	42.9%	275	53	80.7%
84	25	4	0	100.0%	166	11	93.4%	4	2	50.0%	164	37	77.4%
85		5	0	100.0%	175	16	90.9%	5	2	60.0%	175	63	64.0%
86	181	5	1	80.0%	175	15	91.4%	5	5	0.0%	174	105	39.7%
89	81	8	4	50.0%	276	62	77.5%	8	5	37.5%	274	75	72.6%
90	37	8	0	100.0%	276	10	96.4%	8	6	25.0%	275	43	84.4%
93		5	0	100.0%	174	18	89.7%	5	3	40.0%	173	40	76.9%
94	28	5	3	40.0%	205	53	74.1%	5	4	20.0%	203	73	64.0%
95		5	0	100.0%	174	3	98.3%	5	3	40.0%	174	62	64.4%
97	111	8	8	0.0%	278	181	34.9%	8	7	12.5%	276	83	69.9%
98		8	1	87.5%	278	22	92.1%	8	7	12.5%	276	87	68.5%
110		5	3	40.0%	171	99	42.1%	5	1	80.0%	168	17	89.9%
111		5	0	100.0%	165	32	80.6%	5	0	100.0%	163	20	87.7%
112	24	5	0	100.0%	165	16	90.3%	5	1	80.0%	164	18	89.0%
113		5	1	80.0%	96	23	76.0%	5	0	100.0%	95	11	88.4%
119		4	1	75.0%	164	44	73.2%	4	2	50.0%	162	22	86.4%
125		5	0	100.0%	175	8	95.4%	5	3	40.0%	175	69	60.6%
129		5	0	100.0%	174	44	74.7%	5	2	60.0%	174	25	85.6%
130		5	1	80.0%	165	17	89.7%	5	1	80.0%	163	16	90.2%
131	73	5	2	60.0%	167	49	70.7%	5	4	20.0%	167	33	80.2%
134		5	1	80.0%	175	22	87.4%	5	2	60.0%	174	28	83.9%
136		5	2	60.0%	175	22	87.4%	5	2	60.0%	173	19	89.0%
137		5	2	60.0%	172	32	81.4%	5	2	60.0%	172	54	68.6%
138		5	2	60.0%	175	37	78.9%	5	3	40.0%	174	30	82.8%
141	28	5	0	100.0%	174	3	98.3%	5	2	60.0%	173	30	82.7%
148		5	0	100.0%	174	17	90.2%	5	1	80.0%	172	31	82.0%
151		8	2	75.0%	277	88	68.2%	8	6	25.0%	276	90	67.4%
170		5	0	100.0%	170	12	92.9%	5	0	100.0%	169	29	82.8%
171	49	5	0	100.0%	175	10	94.3%	5	4	20.0%	175	65	62.9%
172		5	0	100.0%	174	14	92.0%	5	3	40.0%	172	58	66.3%
173		4	1	75.0%	169	24	85.8%	4	3	25.0%	168	76	54.8%
174	29	5	0	100.0%	175	20	88.6%	5	3	40.0%	175	41	76.6%
175		5	0	100.0%	175	21	88.0%	5	2	60.0%	175	57	67.4%
176		4	1	75.0%	169	15	91.1%	4	2	50.0%	167	17	89.8%
177		5	1	80.0%	175	25	85.7%	5	0	100.0%	175	44	74.9%
178		5	0	100.0%	175	24	86.3%	5	3	40.0%	173	26	85.0%
179		5	2	60.0%	175	21	88.0%	5	3	40.0%	174	61	64.9%
181		5	1	80.0%	171	55	67.8%	5	2	60.0%	169	14	91.7%
182		5	1	80.0%	165	29	82.4%	5	1	80.0%	163	17	89.6%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		5	3	40.0%	174	51	70.7%	5	2	60.0%	172	35	79.7%
184		5	2	60.0%	175	31	82.3%	5	3	40.0%	174	26	85.1%
185		5	0	100.0%	175	36	79.4%	5	0	100.0%	175	11	93.7%
186		5	1	80.0%	174	18	89.7%	5	2	60.0%	173	42	75.7%
190		5	2	60.0%	174	64	63.2%	5	2	60.0%	173	39	77.5%
192		5	2	60.0%	172	21	87.8%	5	1	80.0%	172	15	91.3%
193		4	2	50.0%	173	73	57.8%	4	3	25.0%	172	83	51.7%
196		4	0	100.0%	173	18	89.6%	4	0	100.0%	172	15	91.3%
197		5	1	80.0%	175	69	60.6%	5	4	20.0%	175	57	67.4%
198		5	3	40.0%	107	17	84.1%	5	1	80.0%	106	17	84.0%
230		8	0	100.0%	115	4	96.5%	8	0	100.0%	115	6	94.8%
232		8	0	100.0%	281	11	96.1%	8	0	100.0%	281	17	94.0%
233	128	6	2	66.7%	257	58	77.4%	6	3	50.0%	257	76	70.4%
234		8	1	87.5%	281	20	92.9%	8	0	100.0%	281	24	91.5%
235		8	0	100.0%	205	27	86.8%	8	3	62.5%	205	44	78.5%
236		8	0	100.0%	265	7	97.4%	8	2	75.0%	265	38	85.7%
237		8	0	100.0%	279	52	81.4%	8	3	62.5%	277	46	83.4%
238		8	0	100.0%	205	19	90.7%	8	0	100.0%	204	14	93.1%
239		8	2	75.0%	280	74	73.6%	8	3	62.5%	279	33	88.2%
240		8	0	100.0%	280	20	92.9%	8	3	62.5%	278	47	83.1%
241		8	2	75.0%	281	70	75.1%	8	2	75.0%	281	68	75.8%
243		8	5	37.5%	217	60	72.4%	8	3	62.5%	216	29	86.6%
244	28	6	1	83.3%	257	11	95.7%	6	4	33.3%	257	42	83.7%
245		8	2	75.0%	162	29	82.1%	8	1	87.5%	161	18	88.8%
280		8	1	87.5%	281	12	95.7%	8	0	100.0%	281	50	82.2%
281	27	8	2	75.0%	281	31	89.0%	8	4	50.0%	281	51	81.9%
283	18	8	3	62.5%	281	67	76.2%	8	4	50.0%	281	56	80.1%
284	28	8	0	100.0%	281	10	96.4%	8	4	50.0%	279	46	83.5%
290	27	8	0	100.0%	281	48	82.9%	8	6	25.0%	279	97	65.2%
291	41	8	4	50.0%	280	79	71.8%	8	4	50.0%	278	62	77.7%
300		8	0	100.0%	265	19	92.8%	8	5	37.5%	263	61	76.8%
301		8	0	100.0%	279	9	96.8%	8	3	62.5%	276	53	80.8%
302		8	1	87.5%	266	32	88.0%	8	2	75.0%	262	74	71.8%
306		8	0	100.0%	277	15	94.6%	8	4	50.0%	276	75	72.8%
307	16	8	1	87.5%	269	36	86.6%	8	3	62.5%	266	73	72.6%
311	103	6	1	83.3%	277	24	91.3%	6	2	66.7%	272	52	80.9%
316		6	1	83.3%	274	17	93.8%	5	2	60.0%	270	66	75.6%
318	82	8	3	62.5%	280	29	89.6%	8	6	25.0%	277	130	53.1%
329		6	0	100.0%	198	8	96.0%	6	0	100.0%	198	13	93.4%
330		7	0	100.0%	238	4	98.3%	7	1	85.7%	238	14	94.1%
331		8	0	100.0%	281	29	89.7%	8	0	100.0%	281	40	85.8%
332		8	1	87.5%	281	15	94.7%	8	2	75.0%	281	41	85.4%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334	15	8	0	100.0%	281	9	96.8%	8	1	87.5%	280	37	86.8%
335		8	0	100.0%	281	30	89.3%	8	2	75.0%	279	45	83.9%
336	19	8	1	87.5%	281	9	96.8%	8	1	87.5%	279	26	90.7%
337		8	1	87.5%	281	18	93.6%	8	1	87.5%	277	34	87.7%
338		8	2	75.0%	281	43	84.7%	8	2	75.0%	279	83	70.3%
339		8	1	87.5%	281	47	83.3%	8	1	87.5%	281	49	82.6%
341		8	1	87.5%	270	36	86.7%	8	1	87.5%	265	36	86.4%
342		8	0	100.0%	281	21	92.5%	8	0	100.0%	279	53	81.0%
350		8	0	100.0%	262	17	93.5%	7	4	42.9%	256	140	45.3%
351		8	1	87.5%	264	26	90.2%	8	3	62.5%	262	71	72.9%
352		8	0	100.0%	248	20	91.9%	8	4	50.0%	242	75	69.0%
354	Cncld	8	4	50.0%	262	32	87.8%	7	6	14.3%	257	95	63.0%
355		8	1	87.5%	275	28	89.8%	8	6	25.0%	268	91	66.0%
364		8	1	87.5%	270	61	77.4%	8	5	37.5%	264	95	64.0%
365		8	1	87.5%	269	11	95.9%	8	6	25.0%	267	98	63.3%
370		8	1	87.5%	272	34	87.5%	7	1	85.7%	264	66	75.0%
371		7	0	100.0%	266	8	97.0%	7	1	85.7%	265	28	89.4%
380	27	7	0	100.0%	266	24	91.0%	7	4	42.9%	266	53	80.1%
381		8	0	100.0%	281	11	96.1%	8	2	75.0%	280	50	82.1%
382	36	8	3	62.5%	280	19	93.2%	8	5	37.5%	280	89	68.2%
383		8	1	87.5%	270	26	90.4%	7	3	57.1%	267	108	59.6%
390		8	0	100.0%	263	17	93.5%	8	3	62.5%	262	66	74.8%
391		8	1	87.5%	266	9	96.6%	8	3	62.5%	263	68	74.1%
392		8	0	100.0%	280	5	98.2%	8	6	25.0%	278	84	69.8%
393	18	8	0	100.0%	281	16	94.3%	8	5	37.5%	278	82	70.5%
417		5	2	60.0%	185	40	78.4%	5	1	80.0%	176	18	89.8%
425		5	0	100.0%	187	6	96.8%	5	0	100.0%	187	7	96.3%
448	61	8	2	75.0%	211	40	81.0%	8	4	50.0%	209	72	65.6%
449		8	1	87.5%	209	31	85.2%	8	4	50.0%	209	40	80.9%
470		5	1	80.0%	198	35	82.3%	5	0	100.0%	192	23	88.0%
471	18	5	2	60.0%	188	8	95.7%	5	2	60.0%	188	4	97.9%
473		5	0	100.0%	194	13	93.3%	5	0	100.0%	191	8	95.8%
474	48	6	3	50.0%	190	54	71.6%	5	5	0.0%	177	52	70.6%
475		5	0	100.0%	192	5	97.4%	5	2	60.0%	192	12	93.8%
478	19	5	2	60.0%	186	29	84.4%	5	1	80.0%	184	21	88.6%
479	37	5	2	60.0%	193	31	83.9%	5	4	20.0%	191	26	86.4%
486		5	1	80.0%	197	29	85.3%	5	2	60.0%	191	52	72.8%
494	25	5	0	100.0%	198	35	82.3%	5	4	20.0%	192	48	75.0%
495		5	0	100.0%	183	3	98.4%	5	0	100.0%	181	3	98.3%
500		8	1	87.5%	272	16	94.1%	7	0	100.0%	269	32	88.1%
502		8	1	87.5%	279	16	94.3%	7	0	100.0%	275	56	79.6%
503	19	8	1	87.5%	277	26	90.6%	8	5	37.5%	271	79	70.8%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		8	0	100.0%	281	17	94.0%	8	2	75.0%	279	84	69.9%
505		8	1	87.5%	279	37	86.7%	7	4	42.9%	274	77	71.9%
506		8	1	87.5%	276	39	85.9%	8	2	75.0%	271	43	84.1%
507		8	1	87.5%	281	35	87.5%	8	2	75.0%	281	90	68.0%
508		8	0	100.0%	276	39	85.9%	8	0	100.0%	273	62	77.3%
509		8	0	100.0%	278	12	95.7%	8	0	100.0%	278	63	77.3%
511		8	0	100.0%	273	21	92.3%	8	0	100.0%	272	45	83.5%
516		8	1	87.5%	273	28	89.7%	8	2	75.0%	272	125	54.0%
517	20	8	0	100.0%	281	8	97.2%	8	6	25.0%	277	114	58.8%
518	20	8	0	100.0%	281	35	87.5%	8	6	25.0%	279	189	32.3%
519		8	0	100.0%	273	9	96.7%	8	1	87.5%	271	64	76.4%
520		6	0	100.0%	156	24	84.6%	6	0	100.0%	153	9	94.1%
521		6	0	100.0%	194	7	96.4%	6	2	66.7%	194	25	87.1%
522		6	0	100.0%	194	36	81.4%	6	0	100.0%	191	18	90.6%
523		6	0	100.0%	194	6	96.9%	6	0	100.0%	193	22	88.6%
524		6	1	83.3%	194	12	93.8%	6	0	100.0%	192	20	89.6%
525	Cncld	6	2	66.7%	192	14	92.7%	5	0	100.0%	188	13	93.1%
526	35	6	2	66.7%	168	31	81.5%	6	2	66.7%	165	14	91.5%
527	11	6	1	83.3%	194	10	94.8%	6	1	83.3%	193	33	82.9%
528		6	0	100.0%	194	15	92.3%	6	0	100.0%	193	29	85.0%
529		6	0	100.0%	194	11	94.3%	6	0	100.0%	193	50	74.1%
530		6	0	100.0%	148	14	90.5%	6	1	83.3%	148	27	81.8%
531		6	0	100.0%	168	12	92.9%	6	1	83.3%	168	12	92.9%
532		6	4	33.3%	194	47	75.8%	6	2	66.7%	193	29	85.0%
534		6	0	100.0%	153	24	84.3%	6	0	100.0%	151	15	90.1%
535		6	1	83.3%	181	24	86.7%	6	0	100.0%	176	20	88.6%
536		6	1	83.3%	194	50	74.2%	6	0	100.0%	191	37	80.6%
537	15	6	1	83.3%	165	19	88.5%	6	1	83.3%	160	17	89.4%
538		6	0	100.0%	194	23	88.1%	6	2	66.7%	193	39	79.8%
539		6	1	83.3%	148	21	85.8%	6	1	83.3%	148	65	56.1%
540		5	2	60.0%	193	37	80.8%	5	0	100.0%	186	18	90.3%
541		6	0	100.0%	193	21	89.1%	6	1	83.3%	188	34	81.9%
542	32	6	0	100.0%	193	21	89.1%	6	3	50.0%	191	35	81.7%
543		6	1	83.3%	194	20	89.7%	6	4	33.3%	194	54	72.2%
544		6	0	100.0%	192	20	89.6%	6	1	83.3%	189	16	91.5%
545		6	1	83.3%	194	16	91.8%	6	0	100.0%	192	22	88.5%
547		6	0	100.0%	194	37	80.9%	6	0	100.0%	194	44	77.3%
548		5	0	100.0%	189	20	89.4%	5	0	100.0%	188	14	92.6%
549		6	0	100.0%	189	25	86.8%	6	0	100.0%	182	16	91.2%
550		6	1	83.3%	148	15	89.9%	6	1	83.3%	148	32	78.4%
551		6	0	100.0%	190	19	90.0%	6	0	100.0%	182	17	90.7%
562		8	1	87.5%	273	22	91.9%	8	0	100.0%	270	29	89.3%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		8	0	100.0%	273	17	93.8%	8	1	87.5%	265	31	88.3%
566	43	8	1	87.5%	271	18	93.4%	8	2	75.0%	268	34	87.3%
567		8	0	100.0%	158	8	94.9%	8	0	100.0%	156	6	96.2%
572	32	8	0	100.0%	268	22	91.8%	8	4	50.0%	263	69	73.8%
573		8	0	100.0%	271	40	85.2%	8	0	100.0%	264	44	83.3%
579		8	0	100.0%	158	8	94.9%	8	2	75.0%	153	28	81.7%
580		8	0	100.0%	273	14	94.9%	8	0	100.0%	268	21	92.2%
581	19	8	2	75.0%	273	45	83.5%	8	2	75.0%	271	56	79.3%
584	30	8	2	75.0%	157	19	87.9%	8	7	12.5%	153	89	41.8%
587	26	8	0	100.0%	268	15	94.4%	8	3	62.5%	259	41	84.2%
588		8	1	87.5%	158	13	91.8%	8	0	100.0%	157	22	86.0%
591		8	0	100.0%	272	18	93.4%	8	0	100.0%	266	29	89.1%
593		8	2	75.0%	267	39	85.4%	8	1	87.5%	249	28	88.8%
595		8	1	87.5%	268	42	84.3%	8	1	87.5%	265	47	82.3%
600		5	0	100.0%	202	9	95.5%	5	1	80.0%	200	16	92.0%
601		5	2	60.0%	185	74	60.0%	5	0	100.0%	182	23	87.4%
605		5	2	60.0%	192	120	37.5%	5	0	100.0%	188	19	89.9%
607		5	2	60.0%	201	26	87.1%	5	2	60.0%	198	24	87.9%
609	22	5	1	80.0%	192	23	88.0%	5	2	60.0%	191	17	91.1%
622		4	0	100.0%	107	30	72.0%	4	0	100.0%	105	5	95.2%
626		5	0	100.0%	106	12	88.7%	5	1	80.0%	104	16	84.6%
639		4	0	100.0%	172	37	78.5%	4	0	100.0%	171	19	88.9%
640		5	0	100.0%	192	7	96.4%	5	1	80.0%	190	77	59.5%
641		5	1	80.0%	174	35	79.9%	5	0	100.0%	174	25	85.6%
642	45	5	0	100.0%	190	9	95.3%	5	1	80.0%	189	24	87.3%
643		5	0	100.0%	204	39	80.9%	5	0	100.0%	201	32	84.1%
644		5	0	100.0%	196	27	86.2%	5	3	40.0%	194	51	73.7%
645		5	2	60.0%	204	40	80.4%	4	2	50.0%	201	41	79.6%
646		5	1	80.0%	193	47	75.6%	5	2	60.0%	191	91	52.4%
647		5	0	100.0%	204	31	84.8%	5	2	60.0%	203	45	77.8%
648		5	1	80.0%	200	51	74.5%	5	1	80.0%	200	32	84.0%
649		5	3	40.0%	205	40	80.5%	5	1	80.0%	202	32	84.2%
650		5	0	100.0%	204	39	80.9%	5	2	60.0%	201	32	84.1%
651		5	0	100.0%	204	16	92.2%	5	2	60.0%	202	41	79.7%
652		5	0	100.0%	205	27	86.8%	5	2	60.0%	201	34	83.1%
653		5	1	80.0%	193	31	83.9%	5	2	60.0%	190	36	81.1%
654		5	2	60.0%	194	38	80.4%	4	0	100.0%	190	16	91.6%
655		5	1	80.0%	202	70	65.3%	5	2	60.0%	200	70	65.0%
656	19	5	0	100.0%	204	45	77.9%	5	3	40.0%	203	24	88.2%
657		5	1	80.0%	193	27	86.0%	5	1	80.0%	192	29	84.9%
658		5	0	100.0%	204	34	83.3%	5	0	100.0%	202	30	85.1%
680		6	2	66.7%	199	11	94.5%	6	0	100.0%	198	24	87.9%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681	11	6	0	100.0%	199	14	93.0%	6	3	50.0%	194	75	61.3%
682		6	0	100.0%	198	5	97.5%	6	1	83.3%	198	34	82.8%
683		6	0	100.0%	181	15	91.7%	6	5	16.7%	180	56	68.9%
684		6	2	66.7%	180	29	83.9%	6	1	83.3%	180	39	78.3%
685		6	2	66.7%	195	30	84.6%	6	4	33.3%	192	48	75.0%
686		6	1	83.3%	200	34	83.0%	6	4	33.3%	199	40	79.9%
687		6	2	66.7%	199	32	83.9%	6	3	50.0%	198	34	82.8%
688	49	6	3	50.0%	198	12	93.9%	6	4	33.3%	197	34	82.7%
701		8	2	75.0%	213	23	89.2%	8	0	100.0%	210	20	90.5%
702	Cncld	8	1	87.5%	280	32	88.6%	7	2	71.4%	277	62	77.6%
703	No OS	8	5	37.5%	281	82	70.8%	7	5	28.6%	279	75	73.1%
704		8	1	87.5%	212	33	84.4%	7	1	85.7%	206	39	81.1%
710	16	8	2	75.0%	281	71	74.7%	8	4	50.0%	277	77	72.2%
711	Cncld	8	2	75.0%	272	30	89.0%	6	1	83.3%	253	46	81.8%
712	Cncld	8	3	62.5%	278	74	73.4%	7	1	85.7%	269	88	67.3%
713		5	1	80.0%	151	15	90.1%	5	2	60.0%	138	58	58.0%
714	16	7	5	28.6%	162	63	61.1%	7	5	28.6%	150	63	58.0%
715	46	8	2	75.0%	280	60	78.6%	6	2	66.7%	259	127	51.0%
716	118	8	3	62.5%	281	110	60.9%	8	3	62.5%	276	105	62.0%
718	30	8	6	25.0%	281	142	49.5%	8	7	12.5%	279	98	64.9%
719		8	5	37.5%	281	93	66.9%	8	4	50.0%	267	76	71.5%
757		8	0	100.0%	66	3	95.5%	8	0	100.0%	65	4	93.8%
761		8	1	87.5%	277	12	95.7%	8	1	87.5%	274	35	87.2%
765		8	0	100.0%	277	24	91.3%	8	0	100.0%	277	36	87.0%
769	26	8	0	100.0%	277	25	91.0%	8	1	87.5%	271	50	81.5%
770		8	0	100.0%	277	21	92.4%	8	4	50.0%	275	78	71.6%
774		8	0	100.0%	277	16	94.2%	8	2	75.0%	276	58	79.0%
777		8	1	87.5%	162	10	93.8%	8	0	100.0%	161	34	78.9%
782		8	5	37.5%	162	61	62.3%	8	1	87.5%	157	16	89.8%
785	29	8	1	87.5%	277	18	93.5%	8	1	87.5%	277	47	83.0%
786		8	1	87.5%	66	17	74.2%	8	1	87.5%	65	28	56.9%
790		8	0	100.0%	277	26	90.6%	8	1	87.5%	274	33	88.0%
794		8	1	87.5%	277	32	88.4%	8	1	87.5%	274	56	79.6%
821	21	8	0	100.0%	275	6	97.8%	8	4	50.0%	275	107	61.1%
822	37	8	1	87.5%	277	15	94.6%	8	6	25.0%	275	124	54.9%
1333	37	8	2	75.0%	277	30	89.2%	8	3	62.5%	274	91	66.8%
1340		8	0	100.0%	276	5	98.2%	8	2	75.0%	276	44	84.1%
1689		3	0	100.0%	77	5	93.5%	3	0	100.0%	76	8	89.5%
2102		5	0	100.0%	51	12	76.5%	5	0	100.0%	50	4	92.0%
2103		5	1	80.0%	115	11	90.4%	5	0	100.0%	114	9	92.1%
2104		5	0	100.0%	141	9	93.6%	5	0	100.0%	139	10	92.8%
2107		5	2	60.0%	172	32	81.4%	5	0	100.0%	169	20	88.2%

Amtrak On Time Performance

Trains Arriving Through: 7/8/2026

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2108		5	0	100.0%	172	25	85.5%	5	1	80.0%	166	18	89.2%
2109		5	0	100.0%	65	9	86.2%	5	0	100.0%	64	4	93.8%
2112		5	1	80.0%	12	3	75.0%	4	1	75.0%	10	1	90.0%
2113		5	2	60.0%	51	5	90.2%	5	0	100.0%	51	7	86.3%
2115		5	1	80.0%	51	6	88.2%	5	2	60.0%	50	6	88.0%
2116		5	0	100.0%	12	0	100.0%	5	2	60.0%	12	4	66.7%
2118		5	2	60.0%	12	2	83.3%	5	3	40.0%	12	5	58.3%
2119		5	0	100.0%	12	2	83.3%	5	3	40.0%	12	4	66.7%
2120		5	3	40.0%	12	6	50.0%	4	2	50.0%	11	5	54.5%
2123		5	1	80.0%	50	7	86.0%	4	1	75.0%	49	14	71.4%
2124	28	5	4	20.0%	144	27	81.3%	5	4	20.0%	142	17	88.0%
2127		5	2	60.0%	12	3	75.0%	5	2	60.0%	11	2	81.8%
2128		5	1	80.0%	12	1	91.7%	5	1	80.0%	12	1	91.7%
2131		5	3	40.0%	12	3	75.0%	5	1	80.0%	12	1	91.7%
2150		5	0	100.0%	165	22	86.7%	5	2	60.0%	162	69	57.4%
2151		5	0	100.0%	114	6	94.7%	5	1	80.0%	112	30	73.2%
2152	32	4	1	75.0%	72	4	94.4%	4	2	50.0%	71	28	60.6%
2154	20	4	0	100.0%	76	20	73.7%	4	2	50.0%	73	38	47.9%
2155		5	1	80.0%	174	15	91.4%	5	2	60.0%	170	92	45.9%
2158		5	0	100.0%	12	2	83.3%	5	2	60.0%	12	2	83.3%
2159		5	1	80.0%	167	12	92.8%	5	4	20.0%	165	52	68.5%
2160	21	5	0	100.0%	12	0	100.0%	4	3	25.0%	11	7	36.4%
2162		5	0	100.0%	173	13	92.5%	5	2	60.0%	167	79	52.7%
2165		4	1	75.0%	11	1	90.9%	4	2	50.0%	11	4	63.6%
2167		4	0	100.0%	163	18	89.0%	4	0	100.0%	163	36	77.9%
2171		5	0	100.0%	101	8	92.1%	5	3	40.0%	98	21	78.6%
2190		4	1	75.0%	172	25	85.5%	4	1	75.0%	170	23	86.5%
2193		4	0	100.0%	169	23	86.4%	4	1	75.0%	167	46	72.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2124	NYP	28	SVS	19	SVS	19	WAS-WAS	AM	Unplanned Wye, TRN HAD TO WYE DUE TO A CRACKED WINDSHEILD
2152	BOS	32	DSR	25	DCS	19	XHM-XCY	AM	Power switch failure, Other, XH1-XMW, NECESSARY TO MAKE REVERSE MOVE A/C 23 SWITCH OUT OF CORRESPONDENCE AT MIDWAY
2154	BOS	20	SMW	21	SMW	9	NYP-NYP	AM	Scheduled in track usage program, Other, NYP, HELD F/WESTBOUND TRAFFIC IN LINE 1 A/C THERMAL TRAIN IN LINE 4
2160	BOS	21	SMW	24	SMW	12	NYP-XSH	AM	Scheduled in track usage program, Other, LEGGETT, HELD A/C SINGLE TRACKING LEGGETT TO PELHAM BAY FOR SCHEDULED MAINTENANCE
66	BOS	25	DCS	45	DCS	28	RNK-LYH	NS	PTC system failure (wayside) Other, 0.8 KM
84	NYP	25	PTI	11	OTH	6	WIL-PHL	AM	Lost time - N.A.R., pure run time
86	BOS	181	CAR	87	CAR	83	MET-MET	AM	Onboard HBD alarm, 82618, HOT JOURNAL ALARM ON CAR 82618
94	BOS	28	ENG	22	ENG	22	NWK-NYP	AM	Other electrical failure, 652 EX ES, STOPPED AT TENTH AVE A/C STOP BYPASS
112	NYP	24	PTI	23	PTI	8	BWI-BAL	AM	Follow, 98, Milepost, 98.2, 95.7
131	WAS	73	ENG	64	ENG	64	NYP-NYP	AM	HEP, 635 EX ES, NECESSARY TO LOOP TRAIN A/C UNKNOWN PROBLEM W/ENG.635
141	WAS	28	SMW	18	SMW	14	PHL-WIL	AM	Diversions around M/W work, Control Point, .. Held for Acela 2151 ahead on No.3 trk at Holly Opr No.4 trk a/c No.2 trk O/O/S Phil - Baldwin
171	RNK	49	DSR	18	PTI	17	CLP-CVS	NS	Cross over or go around 66, Milepost, 102.0, 109.9
174	BOS	29	MTI	27	MTI	22	PJC-NBK	AM	Disabled train ahead, Other, XCY, HELD F/DISPOSITION A/C AM86 W/HOT JOURNAL ALARM AT METROPARK
471	NHV	18	ITI	18	ITI	18	HFD-HFD	AM	Service, turn, or wye train, 426, Late turn of AM426
474	SPG	48	PTI	23	CON	23	NHV-NHV	AM	Hold for connecting train
478	SPG	19	SMW	7	SMW	7	WNL-SPG	AM	Scheduled in track usage program, Milepost, wnl, spg
479	NHV	37	CTI	13	CTI	13	WND-HFD	AM	Meet, CTRAIL, 4466, Milepost w/Letters, WND, WFD, AM479 waited for CT4466 to clear

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
494	GFD	25	CON	22	CON	22	NHV-NHV	AM	Hold for connecting train	
52	LOR	143	FTI	185	FTI	173	XFL-XSE	CS	Follow Pulled into 1 track behind M410 at A248.8 waited on I031 to pass. M410 having Engine Problems. M410 gonna set off last 5 cars in 1 track and we give conductor ride to headend of his train, M410, Milepost w/Letters, A262.8, A248.0	
79	CLT	39	ADA	37	ADA	9	GRO-GRO	NS	Mobility Impaired Two lifts , different doors.	
609	HAR	22	SVS	27	SVS	27	PHL-PAO	AM	Unplanned Wye, WYE ON THE OUTBOUND FROM PENN	
642	NYP	45	ENG	40	ENG	40	PHL-XHM	AM	Other electrical failure, 630 EX ES, E/630 unable to proceed as lead motor, necessary to WYE	
656	NYP	19	SVS	28	SVS	28	PHL-XHM	AM	Unplanned Wye, WYE ON THE OUTBOUND. NEEDED THE BUTTON NUMEROUS TIMES; CUT OUT KEY PAD	
20	NYP	96	SYS	260	SYS	200	NOL-NOL	AM	Late turn over of equipment from Amtk 19	
681	BRK	11	PTI	12	PTI	11	POR-FRE	CS	Meet 684, Control Point, Congress	
688	BON	49	DCS	41	DCS	15	HHL-WOB	MT	Power switch failure Control Point, FR	
63	TWO	75	DCS	46	DCS	46	BFX-BFX	CS	Power switch failure Control Point, 8	
233	ALB	128	ENG	119	ENG	119	NYP-NYP	AM	HEP, 9701, NECESSARY TO LOOP TRAIN A/C MECHANICAL ISSUES ON ENG.9701	
244	NYP	28	PTI	30	PTI	21	POU-CRT	MN	Follow Caught up to them around Bank street and followed them all the way to Croton, 880, Control Point, 61, Control Point, 34	
281	NFL	27	CTI	28	CTI	25	CRT-POU	MN	Cross over or go around man, local, Control Point, 39	
283	NFL	18	CTI	24	CTI	24	CRT-POU	MN	Cross Traffic metro north, 866, Control Point, 39	
284	NYP	28	CTI	42	CTI	35	POU-CRT	MN	Cross over or go around metro north, 853, Control Point, 46	
290	NYP	27	DMW	20	DMW	20	POU-CRT	MN	Waiting for MW clearance Milepost, 43.4, 41.9	
291	BTN	41	CTI	41	CTI	41	CRT-POU	MN	Follow 2 south bounds and one northbound local, metro north, Control Point, 39	
48	NYP	31	RTE	62	RTE	47	POU-CRT	MN	Dispatcher hold Control Point, 46	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
49	CHI	50	CAR	47	INJ	26	TOL-TOL	NS	Injured or sick passenger Passenger had a seizure and fell. Hit head, bit tongue and looked like a cut under his chin.
448	BOS	39	CTI	39	FTI	30	SPG-WOR	CS	Meet N43098, Control Point, 57
42	NYP	32	PTI	43	PTI	43	LEW-XNN	NS	Meet Dispatcher hold for the UP 4014 BIG BOY, 061, Milepost, 162.0, 162.0
71	CLT	26	FTI	20	FTI	20	GRO-SAL	NS	Cross over or go around NS 053, Control Point, Pomona
72	RGH	12	DCS	13	DCS	13	DNC-CYN	NS	Power switch failure Control Point, D&S Junction
73	CLT	67	DCS	28	PTI	21	RGH-CYN	NS	Meet #Amt80, Control Point, Fetner
74	RGH	122	ITI	120	ITI	120	CLT-CLT	NS	Service, turn, or wye train 73, After late arrival into CLT, had to wye the equipment.
75	CLT	44	PTI	25	PTI	25	CYN-DNC	NS	Meet AMTK 72 had to get talked past D&S by signal maintainer; restricted speed from D&S to Sullivan, AMTK 72, Control Point, Nelson
77	CLT	14	DSR	6	DSR	4	DNC-BNC	NS	Per bulletin Milepost, 46.7, 46.6, 25, MT
89	SAV	81	FTI	84	FTI	30	FLO-KTR	CS	Cross over or go around 408, Milepost, 306.1, 306.1
90	NYP	37	PTI	53	FTI	19	CHS-KTR	CS	Meet unknown, Other, chs sub
97	MIA	111	ITI	156	ITI	131	NYP-NYP	AM	Service, turn, or wye train, 98, LATE F/SSYD A/C LACK OF EQUIPMENT AVAILABLE AND TO MINIMIZE THE DRILLING OF EQUIPMENT, WE TURN INBOUND TRAIN 98 ENTIRE CONSIST FOR AM97.
41	MIA	408	WTR	234	WTR	146	PGH-PGH	NS	Landslide / rockslide Rock slide conditions ahead. Held at Pittsburgh station until further notice., Milepost, 353.0, 270.4
23	NOL	113	TRS	82	TRS	82	BAS-XNO	CS	Vehicle on track ahead Milepost, 760.2, 760.2
24	MOE	131	TRS	80	TRS	80	XNO-BAS	CS	Vehicle on track ahead Milepost, 761.0, 761.0
25	NOL	19	FTI	41	FTI	41	GUF-BAS	CS	Meet m602, Control Point, 746
26	MOE	82	FTI	51	FTI	51	XNO-BAS	CS	Meet CSX M601, Siding, Nicholson Ave
5	EMY	No OS Rpt	TRS	325	TRS	325	PRO-SLC	UP	Trespasser strike UP Train struck trespasser., Other, 731.3
525	OKJ	Trn Cancelled							

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
526	SAC	35	SVS	49	SVS	49	OKJ-OKJ	UP	Planned set out / pick out of locomotives, cars or section of train Deadheaded from SAC with 702 consist to drop off in yard., Other, OAK
527	SJC	11	DCS	11	DCS	11	OKJ-OAC	UP	Flagging Flag cpni011 to pack, Control Point, cpni011
537	OKJ	15	MBO	19	MBO	19	SUI-MTZ	UP	For maritime traffic Control Point, Benicia
542	SAC	32	POL	34	POL	34	BKY-BKY	UP	Fire department hold
50	NYP	No OS Rpt	ENG	275	ENG	80	CIN-CIN	CS	Failure of diesel engine Fault code 0954, 366
503	EUG	19	PTI	22	PTI	22	CTL-KEL	BN	Meet amtk 502, Control Point, cp 85
517	PDX	20	DCS	27	DCS	21	VAN-VAN	BN	Power switch failure Hold for signal maintainer to fix the switch, Control Point, Columbia Bridge
518	VAC	20	DSR	24	DSR	11	XF2-X1J	BN	Per bulletin Time table speed reduction 60>40, Bridge, Fraser, 40, Main
59	NOL	117	DCS	123	DCS	100	JAN-HAZ	CC	Restrictive signal(s) from unknown cause Stop signal, Milepost, 736.0, 736.0
11	LAX	92	FTI	128	FTI	110	CIC-XB7	UP	Freight train broke down at F140 Sacramento Subdivision BNSF 6927, Control Point, F180
7	SEA	225	FTI	309	FTI	243	SPK-XOD	BN	Mechanical problem broken freight Bnsf 8208 bnsf 8208, Siding, Espanola
8	CHI	61	FTI	191	FTI	45	MAL-GGW	BN	Meet bnsf 7542E, Siding, Hindsdale
821	FTW	21	DSR	27	DSR	19	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.2, 15, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5, 385.3, 30, m, Milepost, 383.6, 383.4, 60, m, Milepost, 380, 379.5, 60, m, Milepost, 378.
822	OKC	37	FTI	41	FTI	26	FTW-GLE	BN	Meet Bnsf 7930, Siding, N.Valley View
334	CHI	15	CTI	8	CTI	8	GLN-XWA	ME	Follow Metra, 2132, Milepost, 10.4, 3.1
336	CHI	19	ENG	12	ENG	12	XRO-GLN	ME	Air / Brake 139
354	PNT	Trn Cancelled	PTI	11	PTI	11	KAL-XGO	MI	Meet amt355, Other, 140
566	SAN	43	ENG	25	ENG	25	LAX-LAX	SC	Set out defective locomotive Late arrival from yard on A566Q on account of engine swap. CDTX 2116 for AMTK 140. Released from S&I 1 @ 0800., C2116

Amtrak Endpoint OTP Details

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
572	SAN	32	CTI	26	CTI	14	SOL-OLT	SN	Per Schedule NCTD, 637, Control Point, skripps	
581	LAX	19	CTI	13	CTI	13	SOL-OSD	SN	Meet Stop signal at Swami, coaster, 640, Control Point, swami	
584	SAN	30	CTI	26	PTI	12	XRJ-FUL	BN	Wait for station track Amtk 4, Other, Station FUL	
587	LAX	26	CTI	34	CTI	19	OSD-X98	SC	Meet Metrolink, 624, Control Point, SONGS	
769	GTA	26	PTI	30	PTI	19	ANA-XFT	BN	Wait for station track Amtk 3, Control Point, Fullerton Jct.	
785	GTA	29	PTI	44	PTI	44	MPK-XMR	UP	Meet Had to wait for Amtrak 794 they had to flag from Camarillo to Las Posas., 794, Control Point, Los Posas	
702	BFD	Trn Cancelled								
703	SAC	No OS Rpt	ITI	114	ITI	114	BFD-BFD	BN	Service, turn, or wye train 712, Changed to 714 after 712 broke down. Then bad paperwork on 714, so changed back to 712.	
710	BFD	16	FTI	26	FTI	26	MDR-FNO	BN	Meet BNSF 8386, BNSF 6677, Control Point, E. Madera, Siding, Gregg	
711	OKJ	Trn Cancelled	DCS	14	DCS	12	COC-HNF	BN	PTC- I-ETMS Red Fence/Signal Status Unknown Per engineer, PTC message signal status unknown. Signal @ E. Guernsey showing clear in the field. Per BNSF PTC, pressed acknowledged button. PTC enforced restricted speed. Advanced approach @ W. Guernsey, Control Point, E. Guernsey	
712	BFD	Trn Cancelled	TEN	112	TEN	112	OKJ-EMY	UP	Failure of diesel engine C2104	
714	BFD	16	PTI	28	PTI	8	FNO-HNF	BN	Wait for station track Held at Mingo for AMTK 719. Train worked normal station track., AMTK 719, Control Point, Mingo	
715	OKJ	46	PTI	22	FTI	10	COC-HNF	BN	Meet BNSF 6865, Control Point, East Corcoran	
716	BFD	118	SVS	130	SVS	130	EMY-EMY	UP	Planned Switch	
718	BFD	30	PTI	40	PTI	24	SKN-MOD	BN	Meet 719, Control Point, lake	
3	LAX	185	FTI	220	FTI	95	NDL-BAR	BN	Hold due to freight derailment BNSF 5379, Control Point, Cadiz	
22	CHI	76	DCS	49	DCS	45	MHL-TXA	UP	Cad system failure Control Point, Sulfur	
307	STL	16	DCS	24	DCS	24	BNL-LCN	UP	Power switch failure Siding, McLean	

Amtrak Endpoint OTP Details

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
380	CHI	27	DSR	12	FTI	7	GBB-KEE	BN	Follow bnsf 7895, Control Point, west kee
382	CHI	36	CON	33	CON	33	GBB-GBB	BN	Hold for thruway bus
393	CDL	18	FTI	17	FTI	17	CHM-MAT	CC	Follow Follow into M1 North Tuscola, 399, Milepost, 129.8, 148.3
311	KCY	103	FTI	82	FTI	54	JEF-JEF	UP	Held at Jeff city per up dispatcher due to broke down freight train between Jeff city and Sedalia unkown, Other, jefferson city platform
318	CHI	82	FTI	116	FTI	70	SED-SED	UP	Stop at Sedalia up 8038, Siding, smithton
1333	MSP	37	FTI	48	FTI	48	WIN-RDW	CP	Meet CPKC was pulling into siding and a knuckle broke, CPKC, Siding, Midland

Amtrak Initial Terminal Details

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/8/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	24	07/08	31	31	Air / Brake 365
ALB	244	07/08	9	9	Meet Waited for 283 to 142 so that we could progress east/south., 283, Control Point, 142
BOS	137	07/08	16	16	Service, turn, or wye train, 190, removed geometry cars from consist
BOS	179	07/08	66	66	Service, turn, or wye train, 86, late turn of AM86
BRK	686	07/08	3	3	Waiting for MW clearance Waiting for 2 track cars to clear up., Control Point, brunswick west
CLT	74	07/08	120	120	Service, turn, or wye train 73, After late arrival into CLT, had to wye the equipment.
HFD	471	07/08	18	18	Service, turn, or wye train, 426, Late turn of AM426
NFK	138	07/08	1		
NHV	474	07/08	46	23	Follow, 86, Control Point, NHV, AM474 held for late AM86
NHV	474	07/08	46	23	Hold for connecting train
NPN	186	07/08	2	2	Hold for thruway bus
NYP	51	07/08	11	11	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	69	07/08	4	4	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	89	07/08	20	20	Routine inspections, LATE RELEASE BY MECHANICAL FROM SSYD
NYP	97	07/08	59	60	Planned set out / pick out of locomotives, cars or section of train, DELAYED F/SSYD A/C LACK OF AVAILABLE EQUIPMENT, IT IS NECESSARY TO WAIT FOR INBOUND TRAIN 98 TO TURN ENTIRE CONSIST AND SERVICE EQUIPMENT
NYP	131	07/08	64	64	HEP, 635 EX ES, NECESSARY TO LOOP TRAIN A/C UNKNOWN PROBLEM W/ENG.635
NYP	183	07/08	11	11	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	233	07/08	119	119	HEP, 9701, NECESSARY TO LOOP TRAIN A/C MECHANICAL ISSUES ON ENG.9701
NYP	243	07/08	5	5	Service, turn, or wye train, 244, LATE TURN OFF AM244
NYP	281	07/08	4	4	Passenger and/or baggage, BOARDING
NYP	283	07/08	3	3	Passenger and/or baggage, LOADING
NYP	291	07/08	26	26	Hold for connecting train, HELD TO WAIT FOR CONNECTING PSNGRS OFF AM86
NYP	2103	07/08	8	8	Passenger and/or baggage, LOADING
NYP	2131	07/08	3	3	Door, 3647 NG NB, DOOR ISSUES
PHL	190	07/08	6	6	Set out defective car, ..., HAD TO DO A BRAKE TEST AND INSPECT CARS 10005, 10002 PER CREW AT 6:06AM

Amtrak Initial Terminal Details

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/8/2026

Terminal	Train	Date	Late	Delay	Cause
SPG	417	07/08	8	8	Service, turn, or wye train, 474, late turn of AM474
WAS	136	07/08	2	2	Wait for station track, 131, Control Point, K INTERLOCKING, ARRIVING 131
WAS	198	07/08	42	42	Hold for connecting train, TRN HLD FOR 59 TRANSFERS OFF OF LATE IB TRN 40
WAS	2124	07/08	19	19	Unplanned Wye, TRN HAD TO WYE DUE TO A CRACKED WINDSHEILD
CHI	41	07/08	7	7	Late release 198, 339
CHI	48	07/08	55	55	Power switch failure Was told their was a switch failure that slowed the switching of cars in the yard, Other, CHI Yard
CHI	307	07/08	35	35	Had issues with door bypass on car 4303 Control Point, Chicago CUS
CHI	354	07/08	(Trn Cxld)		Equipment Issues
GBB	382	07/08	33	33	Hold for thruway bus
MKE	332	07/08	5	5	PTC problem or failure (cause unknown) CPKC was having a system failure- took multiple calls to get PTC up and running.
STL	311	07/08	1		
BFD	703	07/08	114	114	Service, turn, or wye train 712, Changed to 714 after 712 broke down. Then bad paperwork on 714, so changed back to 712.
BFD	711	07/08	2	2	Door C8308, C9004, C9007, C9021, C9025, C9303, C9807, C9810, No door light when door close was pressed. All door were physically closed
BFD	715	07/08	3	3	Traction motor No load, 2006
EMY	6	07/08	5	5	Meet amtk 527, Control Point, east emeryville
LAX	2	07/08	57	57	Hold for connecting train HOLD FOR 11, 26 TRANSFER PAX, 11
LAX	14	07/08	6	6	Routed to abnormal station track due to N.A.R. A last minute track change with no warning caused sheer pandemonium as the station staff scrambled to move over two hundred pax from track 10's platform to track 13's, with the OBS staff struggling to sort the sudden crowd rushing towards them., Other,
LAX	566	07/08	39	7	Meet SCAX, M705, Control Point, Olympic
LAX	566	07/08	39	7	Meet SCAX, M605, Control Point, Olympic
LAX	566	07/08	39	25	Set out defective locomotive Late arrival from yard on A566Q on account of engine swap. CDTX 2116 for AMTK 140. Released from S&I 1 @ 0800., C2116
OKJ	526	07/08	49	49	Planned set out / pick out of locomotives, cars or section of train Deadheaded from SAC with 702 consist to drop off in yard., Other, OAK
OKJ	532	07/08	12	12	Original equipment used to rescue AMT712, took over AMT537's equipment 537
OKJ	716	07/08	(Trn Cxld)		Third Party Engine Failure
SAC	525	07/08	(Trn Cxld)		Third Party Engine Failure
SAC	527	07/08	2	2	525 blocking track Other, sac depot, 525

Amtrak Initial Terminal Details

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/8/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	543	07/08	1		
SAC	702	07/08	(Trn Cxld)		Third Party Engine Failure
SAN	593	07/08	2	2	Electrical failure 6802, 6304, 6407, C6462, 34120, 6905, Briefing with mechanical and management after troubleshooting major electrical issues including loss of HEP, door control, PA system, and lighting.
SEA	8	07/08	155	155	Service, turn, or wye train 7
SLO	786	07/08	1		

Eastern Region

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	98.1	94.8	342	1
CDOT	95.0	70.0	83.5	92.4	20	6
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	93.0	90.0	88.6	357	25
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(08) North of Charleston, SC - Freight Train Interference

09JUL26: Train 53(08) with engines 322, 354, 38 cars, and 421 customers onboard was delayed beginning at milepost 351.0, 38 miles north of Charleston, NC on the CSX Charleston subdivision due to following CSX freight train I031 from milepost 351.0 to milepost 393.3. Once the freight train cleared, train 53(08) was able to advance.

Train	Delay	Comment
53(08)	47"	

Train 89(08) North of Charleston, SC - Trespasser Incident

09JUL26: Train 89(08) with engine 206, 7 cars, and 44 customers onboard was delayed at milepost 383.2, 4 miles north of Charleston, NC on the CSX Charleston subdivision due to a vehicle reported on the tracks ahead at milepost 384.3. Once the vehicle was removed from the tracks, train 89(08) was able to advance to the next station.

Train	Delay	Comment
89(08)	31"	

Train 98(08) North of Kingstree, SC - Freight Train Interference

09JUL26: Train 98(08) with engines 83, 37, 10 cars, and 229 customers onboard was delayed beginning at milepost 321.0, 12 miles north of Kingstree, SC on the CSX Charleston subdivision due to following CSX freight I138-08 from milepost 321.0 to milepost 292.2. Once the freight train cleared, train 98(08) advanced to the next station.

Train	Delay	Comment
98(08)	46"	

Train 198(08) Washington, DC - Hold for Connection

08JUL26: Train 198(08) with engine 629, 9 cars, and 329 customers onboard was delayed departing Washington, DC on the Amtrak WT Line due to waiting for connections from late train 40(07). Once the passengers were boarded, train 198(08) departed the station at 9:56 PM-ET.

Train 448(07) West of Worcester, MA - Freight Train Interference

08JUL26: Train 448(07) with E/108 and 5 cars with 127 customers onboard was delayed at milepost 57.9, 13 miles west of Worcester, MA on the CSX Boston subdivision due to meeting CSX freight train N4309-8. Once the freight train cleared, train 448(07) advanced to the next station.

Train	Delay	Comment
448(07)	30"	

CN Heat Order - Weather

08JUL26: CN imposed heat orders between Rouses Point, NY and St. Lambert, QC of 25 mph created delays for trains 68 and 69.

Train	Delay	Comment
69(08)	42"	
68(08)	40"	

Train 474(08) New Haven, CT - Hold for Connection

08JUL26: Train 474(08) was delayed in New Haven due to holding for connections off late 174(08).

Train	Delay	Comment
474(08)	44"	

Train 63(08) Buffalo, NY - Switch/ Failure Signal

08JUL26: Train 63(08) with E/93 and 5 cars with 127 customers onboard was delayed at Buffalo Exchange St station on the CSX Niagara QDN subdivision due to switch failure at CP 8. CSX maintainer was estimated to be on scene by 505P-ET.

Train	Delay	Comment
63(08)	48"	

Train 97(09) New York, NY - Servicing

08JUL26: Train 97(09) was delayed departing New York due to turning off 98(07).

Train	Delay	Comment
97(09)	59"	

Train 74(08) Charlotte, NC - Servicing

08JUL26: Train 74(08) was delayed departing Charlotte due to the late turn off 73(08). They were further delayed due to having power issues on E/NC103. The power issue with NC103 caused them to have to wye the equipment in Charlotte.

Train	Delay	Comment
74(08)	2'00"	

Train 68(08) South of St-Lambert, QC -Heat Orders/Weather

08JUL26: Train 68(08) with E/112 and 5 cars was delayed on the CN Rouses Point subdivision due to heat orders from MP 43.0 to MP 0.0.

Train 86(08) Metropark, NJ - Car Failure

08JUL26: Train 86(08) 25-F01-00590 / 66000008303 8 C UNCLASSIFIED 383 7/15/2026 383 customers onboard was stopped at Metropark on the New York to Philadelphia main line inspecting C/82618 for a hot journal alarm. After inspecting the crew was able to extinguish the yellow light and proceed to New York. New York mechanical inspected car upon arrival. New York Mechanical found a bad sensor on C/82618 and replaced the sensor.

UPDATE: As soon as they attempted to pull the light came back on. The conductor was given protection again on track 2 and will manually test the hot journal with the Amtrak Road Foreman.

Train 291(08) was delayed departing New York due to train 86(08) having 12 connections.

This also caused train 179(08) to be delayed departing Boston due to the late arrival of 86(08) equipment.

Train	Delay	Comment
86(08)	1'23"	
291(08)	26"	held for 12 connections
86(08)	24"	NYP
179(08)	1'06"	turning off late 86(08)

Train 42(08) East of Lewistown, PA - Passenger Train Interference

08JUL26: Train 42(08) with E/121 and 7 cars with 231 customers onboard was delayed on the NS Altoona subdivision at MP 162.0 due to meeting NS 061 UP4014 Big Boy.

Train	Delay	Comment
42(08)	35"	

Train 131(08) New York, NY - Engine Failure

08JUL26: Train 131(08) was delayed departing New York due to looping equipment due to mechanical problem with E/635.

Train	Delay	Comment
131(08)	1'04"	

Train 233(08) New York, NY - Engine Failure

08JUL26: Train 233(08) was delayed departing New York due to having mechanical issues with 9701 which made it necessary to turn the equipment in New York prior to departing.

Train	Delay	Comment
233(08)	1'59"	

CSX Heat Orders - Weather

08JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Kanawha, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
40(07)	11"	
40(08)	57"	
52(08)	51"	
79(08)	05"	
89(08)	12"	
90(08)	17"	

Train 642(08) Philadelphia, PA - Engine Failure

08JUL26: Train 642(08) with E/630 and E/630C/9630 identified Philadelphia and had to wye after departing due to electrical failure on E/630.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
642(08)	40"	

Train 53(07) South of Jacksonville, FL - Temporary Speed Restrictions

08JUL26: Train 53(07) with E/364, E/380 and 40 cars was delayed on the CSX Sanford A subdivision due to speed restrictions from MP 657.0 to MP 667.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(07)	33"	

Train 41(07) South of Pittsburgh, PA - Freight Train Interference

08JUL26: Train 41(07) with E/106, E/343 and 10 cars with 151 customers onboard was delayed on the CSX Pittsburgh BF subdivision at MP 272.6 due to holding for CSX I135-07 to finish work at Connellsville.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(07)	1'22"	

Train 53(07) South of Palatka, FL - Struck an Animal/ Debris

08JUL26: Train 53(07) with E/364, E/380 and 40 cars went into emergency on the CSX Sanford A subdivision at MP 722.9 due to striking a dog. The crew inspected the equipment and found a loose hose. They secured the hose and were able to proceed south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(07)	40"	

Train 86(08) North of Richmond, VA - M of W Work

08JUL26: Train 86(08) with E/355 and 8 cars with 84 customers onboard was delayed on the CSX RF&P subdivision at MP 80.7 due to holding for M/W to clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
86(08)	43"	

Train 40(07) Savannah, GA - Engine Failure

08JUL26: Train 40(07) was delayed on the CSX Savannah A subdivision at Savannah station due to having traction motor fault on E/333.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(07)	34"	

Train 52(07) - North of Florence, SC - Freight Train Interference

08JUL26: Train 52(07) ~~26-FBI-00590-00000008303~~ delayed the CSX North End Subdivision at MP 247.9 due to CSX Train M410-07 being disabled ahead of it. CSX Mechanical was dispatched to the scene with an initial estimated arrival time of plus 90". CSX suggested Train 52(07) shove back to the previous CP to be routed around, but that was ruled out because the Conductor would have to hang from the last auto-carrier car to ride the point.

Train	Delay	Comment
52(07)	2'45"	Estimated

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, 26-FCI-00390, 00000008303, UNCLASSIFIED, 7/16/2028 Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM – 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
50 (8)	CIN	CSXT5240	E/366 fuel delivery issues	CIN	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 19(08) Passenger Removal at Charlottesville, Virginia – Improper Conduct***

08JUL26, Passenger on PNR 8352C5, traveling from New York, NY to New Orleans, LA was removed from the train by local Police for exhibiting paranoid behavior by randomly yelling obscenities at other passengers. Amtrak Police notified.

Delay: 19(08) 11"

Western Region

Operating Highlights

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train 794(08) South of Camarillo, CA - Temporary Speed Restrictions

09JUL26: Train 794(08) was delayed south of Camarillo, CA between MP415 and MP423 on the UPRR Santa Barbara Subdivision due to temporary speed restrictions in place by the host railroad. Train 785(08) was also delayed due to single track, held at Los Posas/MP423.1 waiting for 794(08) to pass.

Train	Delay	Comment
794 (08)	33"	
785 (08)	44"	Meeting 794(08)

Train 14(08) Oakland, CA(Coliseum) - Trespasser Incident

09JUL26: Train 14(08) was delayed at Oakland, CA Coliseum/MP12.0 on the UPRR Niles Subdivision, due to a vehicle reported on the track ahead at MP10.37. Once the track inspector arrived and cleared the tracks for service, Train 14(08) proceeded north.

Train	Delay	Comment
14 (08)	1'13"	

Train 542(08) Berkeley, CA - Police Related

09JUL26: Train 542(08) was delayed at Berkeley, CA due to a hold on the tracks ahead account of a reported trackside fire at MP10.59 on the UPRR Martinez Subdivision. Once the tracks were inspected and hold released, Train 542(08) departed Berkeley. Train 718(08) was also delayed during this time, holding at Emeryville.

Train	Delay	Comment
542 (08)	34"	BKY
718 (08)	16"	EMY

Train 8/28(07) East of Wolf Point, MT - Freight Train Interference

09JUL26: Train 8/28(07) was delayed at Macon/MP220.9 on the BNSF Glasgow Subdivision, 7 miles east of Wolf Point, MT meeting BNSF 3850 and BNSF 4687. Once a route was clear, Train 7/27(07) proceeded east at track speed.

Train	Delay	Comment
8/28(07)	36"	

Train 7/27(07) West of Whitefish, MT - Freight Train Interference

09JUL26: Train 7/27(07) was delayed beginning at Twin Meadows/MP1262.5 on the BNSF Kootenai River Subdivision, 43.2 miles west of Whitefish, MT meeting BNSF 3268. Once a route was clear, Train 7/27(07) proceeded west at track speed.

Train	Delay	Comment
7/27(07)	38"	

Train 48/448(08) Chicago, IL - Signal

09JUL26: Train 48/448(08) departed Chicago IL Station due to a late make up in the yard. Original engine 374 was swapped out for engine 179 off inbound train 6(06). Flags were dropped for 48(08) at 455PM CT to swap diner car 68023 for 68021, flat switch 25087 & 25114 and add engine 179. Switching was delayed due to failure of switches 59 and 60 in the yard. Maintainers arrived and were able to repair the switches. Train 48/448(08) was made up and flagged back in at 805PM CT. Mechanical released the train at 934PM CT and set at the station at 945PM CT to board 301 passengers. Train 48/448(08) departed Chicago IL Station at 1025PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448(08)	55"	

Train 7/27(07) East Glacier Park, MT - Sick Passenger

09JUL26: Train 7/27(07) was delayed at East Glacier Park, MT, due to waiting for a local EMS to assist a passenger with a severe nose bleed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(07)	34"	

Train 7/27(07) East of Havre, MT - Freight Train Interference

09JUL26: Train 7/27(07) was delayed beginning at Havre Center/MP429.3 on the BNSF Milk River Subdivision, 1 mile west of Havre, MT meeting BNSF7510. Train was further delayed following this freight to Gildford/MP988.9 on the BNSF Hi-Line. Once a route was clear, Train 7/27(07) proceeded at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(07)	37"	

Train 4(07) Lamy, NM - Police Removal of Fare Evader

09JUL26: Train 4(7) was delayed departing Lamy, NM due to waiting for police to remove a fare evading passenger, that reportedly assaulted the crew after refusing to purchase a ticket.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(07)	42"	

08JUL26: Train 354(08) was cancelled and no alternate cars were ordered and no available replacement cars in Chicago, IL. C/ID4107 and ID4315 were shopped for air brake issues. Passengers were provided alternate transportation between Chicago, IL and Detroit MI. . Due to the cancellation of Train 354(08), Train 35309) was also cancelled, with alternate transportation between Pontiac and Chicago.

Train 353(09) alternate transportation: Two busses operated out of Detroit, MI one express to Chicago, IL and the second made stops at Dearborn, MI, New Buffalo, MI and Chicago IL. One bus operated out of Ann Arbor, MI express to Chicago IL. One bus operated out of Troy, MI and made stops at Royal Oak, MI, Jackson, MI, and Chicago IL. One bus operated out of Pontiac MI making all schedules stops. One shuttle operated out of Kalamazoo, MI and stopped at Chicago, IL. station.

Train	Delay	Comment
354 (08)	Cancelled	
353 (09)	Cancelled	

08JUL26: Train 307(08) was delayed departing initial terminal of Chicago IL station/MP0.0 due to door issues on car ID4303. Mechanical arrived from the yard to assist the crew and was able to resolve the issues with the door issues on car ID4303.

Train 58(08) South of Brookhaven, MS - Freight Train Interference

08JUL26: Train 58(08) was delayed holding at MP802, 19.5 miles south of Brookhaven, MS station on the CN McComb subdivision meeting UP freight train 6595.

Train 382(08) Galesburg, IL - Hold for Connection

08JUL26: Train 382(08) was delayed departing Galesburg, IL station on the BNSF Brookfield subdivision due to a late arriving bus.

Train 26(08) South of Bay Saint Louis, MS - Freight Train Interference

08JUL26: Train 26(08) was delayed at MP754.9, .74 miles south of Bay Saint Louis, MS station on the CSX NO and M subdivision meeting CSX Freight train M601. Train 26(08) was back on the move at 739PM CT after the freight cleared to the south.

Train	Delay	Comment
26(08)	51"	

Train 25(08) North of Bay Saint Louis, MS - Freight Train Interference

08JUL26: Train 25(08) was delayed at MP746.7, 13 miles north of Bay Saint Louis, MS station on the CSX NO and M subdivision meeting CSX Freight train M602. Train 25(08) was back on the move at 701PM CT after the freight cleared to the north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(08)	41"	

Train 59(07) North of Hammond, LA - Injured or Sick Passenger or Employee

08JUL26: Train 59(07) was delayed holding at MP823.8, 39.1 miles north of Hammond, LA station on the CN McComb subdivision due to passenger medical emergency. Local EMS responded to the scene and the passenger was transported by EMS to the local hospital.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(08)	40"	
59(07)	24"	

Train 1333(08) Red Wing, MN - Freight Train Interference

08JUL26: Train 1333(08) was delayed holding at MP339.6, 33.38 miles east of Red Wing, MN station on the CPKC River subdivision due to CPKC train 280 stopped ahead in emergency. Freight crew inspected the consist and found a broken knuckle. Mechanical arrived on scene and were able to assist the crew with repairing the broken knuckle. Train 1333(08) was back on the move at 612PM CT after the freight cleared into the siding.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(08)	48"	

Train 21(07) Fort Worth, TX - Servicing

08JUL26: Train 21(07) was delayed departing Fort Worth, TX station/MP611.29 due to fueling engine 69.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(07)	37"	

Train 716(08) Oakland, CA - Third Party Contractor Engine Failure

08JUL26: Train 716(08) was delayed departing the Oakland, CA Jack London Station account of a late release of equipment. TASI mechanical had been waiting on Locomotive C2014 from preventive maintenance. Due to the anticipated delay, the train would originate at Emeryville, CA. The train took a further mechanical delay in the yard and then the decision was made to utilize equipment from inbound Train 713(08). Once this equipment was serviced, the train departed toward Emeryville, CA to load 36 customers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(08)	2'10"	

Train 59(07) South of Jackson, MS - M of W Overstay

08JUL26: Train 59(07), with 181 customers, was delayed at MP735.8, 7 miles south of Jackson, MS, on the CN McComb Subdivision, due to CN MW overstay ahead. MW curfew was scheduled to clear at 200PM-CT however a disabled ballast regulator resulted in the overstay. Train 59(07) and deadhead equipment 967(08) were delayed holding for open route ahead.

Train 1(08) East of Lafayette, LA - BNSF Freight Derailment

08JUL26: Train 1(08) was delayed at MP139.0 east of Lafayette, LA, on the BNSF Lafayette Subdivision, due to BNSF local LDRR 1708 derailed in the siding at MP141.17 with close clearance by location. Train 1(08) was delayed walked by location at restricted speed between MP139 and MP142.

Train	Delay	Comment
1(08)	48"	

Train 4(07) Lamy, NM - Police Related

08JUL26: Train 4(07), with 128 customers, was delayed departing the Lamy, NM station, waiting on local police to remove a fare evader.

Train	Delay	Comment
4(07)	42"	

Train 21/421(07) West of Longview, TX - Freight Train Interference

08JUL26: Train 21/421(07) was delayed west of Longview, TX/MP89.6, on the UPRR Mineola Subdivision, following UP 3026 between Longview and Mineola/MP136.1.

Train	Delay	Comment
21/421(07)	41"	

Train 318(08) Sedalia, MO - Freight Train Interference

08JUL26: Train 318(08), with 136 customers, was delayed at Sedalia, MO/MP188.9, on the UPRR Sedalia Subdivision, due to MASHN-07 (UP 8038), with a 15,000' long consist, stopped in emergency ahead at MP180. UPRR crew inspected consist and found a bad order knuckle. UPRR carman and manager responded to the scene to assist. Train 311(08), with 63 customers, held at Jefferson City, MO/MP125.5, on the UPRR Jefferson City Subdivision, for dispo of the route ahead. Once repairs were completed on UP 8038, Train 311(08) was advanced west from Jefferson City and Train 318(08) advanced from Sedalia. Train 318(08) was further delayed at MP181.2 meeting UP 8038. Train 311(08) was further delayed at MP166 meeting Train 318(08) and at MP183 shuffling around UP 8038.

Train	Delay	Comment
318(08)	1'10"	SED
311(08)	54"	JEF
311(08)	17"	W/JEF
318(08)	27"	E/SED

Trains 23(08) and 24(08) South of Bay Saint Louis, MS - Vehicle on Track Ahead

08JUL26: Train 23(08), with 110 customers, and Train 24(08), with 94 customers, were delayed south of Bay Saint Louis, MS/MP754.48, on the CSX NO&M Subdivision, due to a vehicle on the track ahead at MP760.2. Trains 23(08) and 24(08) were delayed holding for vehicle removal and track inspection ahead. Train 24(08) was further delayed just south of Pascagoula, MS/MP706.6 due to drawbridge opening ahead for maritime traffic.

Train	Delay	Comment
23(08)	1'22"	
24(08)	1'20"	S/BAS
24(08)	34"	S/PAG

Train 712(08) West of Emeryville, CA - Third Party Contractor Engine Failure

08JUL26: 10:52A-PDT, 28-FCI-00590712(08)0000008303 with UNCLASSIFIED customers operating with Cab Car C8310, 7 cars and Locomotive C2104, stopped in emergency at MP 2.6 on the Union Pacific Niles Subdivision. The crew reported the locomotive had shutdown. The train did not have head end power. The weather was reported as 58°F and cloudy. The customers on the train were comfortable.

The decision was made to have the equipment from Train 531 which had just terminated in Oakland to rescue the train. Once coupled, the train set shoved to the Emeryville, CA station to allow passengers to be accommodated on Train 714(08).

Train 711(08) was terminated in Emeryville, CA. The 20 customers scheduled to Oakland were accommodated on Train 535(08). The decision to made to allow fueling of the equipment on Train 711 so it could turn as Train 712(08) operating late between Emeryville and Bakersfield, CA.

As a result of late servicing, Train 712(08) was terminated in Emeryville, CA. As mention, the customers ere accommodated on Train 714(08). The equipment deadhead to Bakersfield for service tomorrow.

Also as a result of late servicing, it was necessary to turn inbound Train 714(08) at Bakersfield for Train 703(08). Train 703(08) was to be delayed account the scheduled arrival time for Train 714(08) is 28 minutes after the scheduled departure time of Train 703(08). This plan was later changed to utilize Train 712's deadhead equipment instead to turn for 703, account of Train 714(08) paperwork only good until midnight.

WBS#: B.TR.100150.6873

Train	Delay	Comment
712(08)		Term EMY
711(08)		Term EMY
714(08)	07"	EMY - Assist 712(08)'s customers
703(08)	1'54"	BFD - Turn 712 DH equipment

Train 3(07) West of Raton, NM - Signal

08JUL26: Train 3(07), with 157 customers, was delayed between Schomberg / MP 678.7 and MP 701.0 on the Burlington Northern Santa Fe Raton Subdivision, starting 19 miles west of the Raton, NM station, account of a signal outage. The crew was flagged through the area.

Train	Delay	Comment
3(07)	1'11"	

Train 566(08) Los Angeles, CA - Engine Failure

08JUL26: Train 566(08) was delayed departing the Los Angeles, CA Union Station account of air brake issues on Locomotive C2116. It was necessary to swap equipment. Train was further delayed meeting two commuter trains prior to departure.

Train	Delay	Comment
566(08)	14"	Meeting M705/M605
566(08)	25"	

Train 23(08) South of Mobile, AL - Freight Train Interference

08JUL26: Train 23(08) was delayed at Brookley/MP670, 3 miles south of Mobile, AL, on the CSX NO&M Subdivision, meeting CSX M62007.

Train	Delay	Comment
23(08)	38"	

Train 24(08) Late Departure New Orleans, LA - Engine

08JUL26: Train 24(08) 26-FOI-00590-3 00000008303/365 UNCLASSIFIED 4 7/15/2026 s, was delayed departing New Orleans, LA, due to sticking brakes on lead locomotive, E/369. Mechanical forces responded and resolved issue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(08)	31"	

Train 319(08) Cancelled - Car Failure

08JUL26: Train 319(08) was cancelled entirely, due to bad orders and no available replacement cars in Chicago, IL. C/ID4317 was shopped for flat spots, married pair with C/ID4127, and C/ID4007 was shopped for B-end coupler carrier bolts. Passengers were provided alternate transportation between Chicago, IL and Kansas City, MO. Due to the cancellation of Train 319(08), Train 318(09) was also cancelled, with alternate transportation between Kansas City and Chicago.

Train 319(08) alternate transportation: Two busses operated out of Chicago, IL, one express to St. Louis, MO and the second made all scheduled stops between Chicago and St. Louis. Three busses operated out of St. Louis. Bus 1 operated St. Louis-Kirkwood-Kansas City and Bus 2 operated St. Louis to Kansas City, making all scheduled stops. Bus 1 and Bus 2 departed St. Louis on time. Bus 3 held for connecting bus enroute from Chicago and operated St. Louis to Kansas City making scheduled stops as needed for drop off.

Train 318(09) alternate transportation: Bus 1: Kansas City to St. Louis Express. Bus 2: Kansas City-Independence-Lee's Summit-Warrensburg-Sedalia-Jefferson City-Hermann-Washington-Kirkwood-St. Louis. Bus 3: Lee's Summit-Sedalia-Jefferson City-Hermann-Washington-Kirkwood-St. Louis. Bus 4: Jefferson City-Hermann-Washington-Kirkwood-St. Louis. Bus 5: St. Louis to Chicago Express. Bus 6: St. Louis-Alton-Carlinville-Springfield-Lincoln-Bloomington Normal-Dwight-Joliet-Summit-Chicago. Bus 7: St. Louis-Chicago Express (departs STL upon arrival of connecting Kansas City busses). Bus 8: St. Louis-Alton-Carlinville-Springfield-Lincoln-Bloomington Normal-Dwight-Joliet-Summit-Chicago (departs STL upon arrival of connecting Kansas City busses). Bus 9: Springfield-Lincoln-Bloomington Normal-Dwight-Joliet-Summit-Chicago.

WBS#: B.TR.100150.6868

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(08)	Cancelled	
318(09)	Cancelled	

Train 702(08) Canceled - Third Party Contractor Engine Failure

08JUL26: Train 702(08) was canceled with Canceled 6965, 7/15/2025. UNCLASSIFIED 00000008303
26-FOI-00390-00000008303
was canceled in its entirety account of a compressor failure on Locomotive C2013.

173 customer affected. Customers traveling between Modesto, CA and Bakersfield, CA were accommodate on Train 710(08). Customers traveling between Sacramento, CA and Stockton, CA Ace Station were provided buses to the Stockton, CA Amtrak Station before boarding Train 710(08).

The equipment was added to Train 525(08) to return to the Oakland Maintenance Facility. The train terminated in Emeryville, CA to minimize the delay to the equipment turn. The 7 customers were provided alternate transportation to Oakland, CA Jack London Station.

Train 546(08) was delayed departing the Oakland, CA Jack London Station account turning late inbound equipment from Train 525(08).

WBS#: B.TR.100150.6869

Train	Delay	Comment
702(08)		Cancel
717(08)		Cancel
525(08)		Cancel
526(08)	49"	OKJ

Train 3(07) La Junta to Trinidad, CO - Temporary Speed Restrictions

08JUL26: Train 3(07) was delayed between the La Junta, CO station / MP 554.9 and the Trinidad, CO station / MP 636.7 on the Burlington Northern Santa Fe account of several speed restrictions.

Train	Delay	Comment
3(07)	30"	

Train 318(07) North of Summit, IL - Freight Train Interference

08JUL26: Train 318(07) was delayed at Corwith/MP6.6, 5 miles north of Summit, IL, on the CN Joliet Subdivision, holding for CN cross-traffic to clear ahead.

Train	Delay	Comment
318(07)	56"	

Train 48/448(07) East of Toledo, OH - Freight Train Interference

08JUL26: Train 48/448(07) was delayed east of Toledo, OH/MP288, on the NS Toledo East Subdivision, following NS 29G between MP282 and MP264.

Train	Delay	Comment
48/448(07)	31"	

Train 8/28(06) West of Fargo, ND - Freight Train Interference

08JUL26: Train 8/28(06) was delayed at Bison/MP27.4, 4 miles west of Fargo, ND, on the BNSF Hillsboro Subdivision, due to BNSF 7305 ahead setting out a bad order car at MP24.2.

Train	Delay	Comment
8/28(06)	43"	

Train 11(07) South of Chico, CA - Freight Train Interference

08JUL26: Train 11(07) with 228 customers was delayed at Berg / MP 146.1 on the Union Pacific Valley Subdivision, 40 miles south of Chico, CA station, account of 2QKDBCJ-06 (BNSF 6927) disabled blocking single main track. The crew experienced locomotive issues but was able to clear on their own power.

Due to late operations of Train 11(07), Trains 2/422(08) and 794(08) were delayed departing Los Angeles holding for connecting passengers.

Train	Delay	Comment
11(07)	1'50"	
2/422(08)	57"	ITD LAX - Held for Connections
794(08)	21"	LAX - Held for Connections

Train 7(06) West of Spokane, WA - Freight Train Interference

08JUL26: Train 7(06), with 125 customers, was delayed at Española / MP 1500.1 on the Burlington Northern Santa Fe Columbia River Subdivision, 20 miles west of the Spokane, WA station, account of VTACLP1-07 (BNSF 8208) repairing a broken knuckle. Once repaired, the freight crew had issues linking the locomotives. BNSF Trainmaster responded to assist. After several attempts, the train was able to clear on its own power.

As a result of late inbound Train 7(06) arriving in Seattle at 3:14 PM-PT, 3hours and 45 minutes late, Train 8(08) was delayed departing Seattle, WA for servicing.

Train	Delay	Comment
7(06)	4'02"	
8(08)	2'35"	SEA

Train 3(06) Needles, CA - Freight Train Interference

08JUL26: Train 3(06), with 199 customers, was delayed at Danby / MP 636.9 on the Burlington Northern Santa Fe Seligman Subdivision, 59 miles west of the Needles, CA station, meeting 4 freight trains. The delay was a result of SLHWLPC1-03 (BNSF 5379) derailling one car at West Cadiz / MP 649.0 and VTACLP1-07 (BNSF 8208).

Train	Delay	Comment
3(06)	1'39"	

Train 50(07) Cincinnati, OH - Engine Failure

08JUL26: Train 50(07) with E/366, five cars, and 82 customers was delayed on the CSX Cincinnati Terminal subdivision due to E/366 with a fuel supply low pressure fault and a clogged fuel filter. As a result, a freight unit was requested through CSX and south facing CSX 5240 was delivered by a CSX yard crew, who assisted the Amtrak crew in tying on the locomotive to the lead of 50(07). CSX advised Amtrak to deliver the 5240 back to Cincinnati.

WBS#: B.TR.100150.6876

Train	Delay	Comment
50(07)	1'20"	
50(07)	17"	CIN-HUN, op with freight loco

Train 5(06) East of Salt Lake City, UT - Freight Trespasser Strike

08JUL26: Train 5(06), 26-FC-09590 00000008303 UNCLASSIFIED, 7/15/2026, delayed approximately 16 miles east of Salt Lake City, UT Station, while holding at Riverton (MP 727.9) on the Union Pacific Provo Subdivision due to a fatal trespasser strike involving RTU 310, led by Utah 2000, ahead on the route. Rail traffic was halted while Union Pacific management, local authorities, and contracted recovery personnel responded to the scene and conducted the required investigation and cleanup activities. Once the investigation was completed, the scene cleared, and the track released for service, Train 5(06) resumed its westbound trip into Salt Lake City.

Due to the lengthy delay, Train 5(06) was delayed at Sacramento, CA to complete a calendar day inspection.

WBS#: B.TR.100150.6875

Train	Delay	Comment
6(07)	1'58"	
5(06)	5'25"	
5(06)	48"	SAC- Calendar Day

Heat Dome affect Entire Network - Weather

08JUL26: A heat dome evolving in the west will be bringing high temps in excess of 100° throughout the country. It will begin to expand as the week goes along and shift to the east affecting the entire nation. The first few days will be focused from the southwest through the Rockies to the Great Plains. It will then shift east affecting the Upper Midwest through the Northeast. Trains will be restricted to high temperature restriction. The high temperatures, there will be increase of severe thunderstorms and high winds.

The heat dome is expected to persist until the remainder of July.

Train	Delay	Comment
6(08)	32"	Heat Orders WNN-ELK
5(06)	31"	Heat orders - ELK to WNN
6(08)	49"	Heat orders- GRI to GJT

Midwest State Supported Service Adjustments - Equipment

08JUL26: The following Midwest State Supported service adjustments are in effect due to equipment availability issues in Chicago, IL:

Lincoln Service:

- Trains 305(08-10) cancelled entirely, with alternate transportation for customers between Chicago, IL and St. Louis, MO.
- Trains 302(09-10) cancelled entirely, with alternate transportation for customers between St. Louis and Chicago.

Carl Sandburg Service:

- Trains 381(09-10) cancelled entirely, with alternate transportation for customers between Chicago and Quincy, IL.
- Trains 382(09-10) cancelled entirely, with alternate transportation for customers between Quincy and Chicago.

WBS#: B.TR.100150.6872

Train	Delay	Comment
305(08-10)	Cancelled	
302(09-10)	Cancelled	
381(09-10)	Cancelled	
382(09-10)	Cancelled	

forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. CN performed track inspection between Carbondale and New Orleans and no track defects were identified. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

29JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 30JUN.

30JUN26: Due to the ongoing equipment availability issue, the service adjustments were extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

06JUL26: City of New Orleans service adjustments were updated as follows:

- Train 59(07) operated normal, Chicago, IL to New Orleans, LA.
- Train 58(07) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(08) cancelled entirely, no alternate transportation between Chicago and New Orleans.

WBS#: B.TR.100150.6822

Train	Delay	Comment
59(26)	Terminated JAN	
58(27JUN-07JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station is located on the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2 / 422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2 / 422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2 / 422 (04, 07JAN)	BYPASS PSN - flooding	
2 / 422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2 / 422 (13, 15, 20, 24MAY)	Bypass PSN	
2 / 422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2 / 422 (01, 03, 05JUL, 07JUL, 10JUL)	00"	BYPASS PSN
1 (01, 04, 08JUL) / 421 (03, 07JUL)		BYPASS PSN

Maintenance of Way Highlights

BNSF Track Work West of Macomb, IL - Carl Sandburg Service

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th. To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL) and Train 382(13JUL-17JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL) and Train 381(13JUL-17JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has replaced the replacement scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

- Train 59(21Jun-29Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (30Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-30Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(31Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Amtrak/MDOT Michigan Line Track Work 26-044

20APR26: Amtrak/MDOT will perform track rehabilitation work on the Michigan Line east of Jackson, MI/MP75.5 between MP75 and MP28 beginning 900PM-ET Monday April 20th through Thursday July 30th. To accommodate this infrastructure work, Wolverine service has been adjusted as follows:

04JUN26: Amtrak/MDOT trackwork will be concluding earlier with a new end date of Thursday, July 9th. Normal operations will resume to all Wolverine service trains on Friday, July 10th. The changes are reflected below:

- Train 1354(20APR) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 354(21APR-09JUL) operates 1-hour earlier departing Chicago, IL at 450PM-CT.
- Train 351(20APR-09JUL) operates 37 minutes later, departing Pontiac, MI at 620AM-ET.
- Train 355(20APR-09JUL) operates 1-hour earlier, departing Pontiac, MI at 4PM-ET.
- Train 350(20APR-09JUL) will have two locomotives and will be configured as push pull consist to turn for Train 355(20APR-30JUL) at Pontiac.

WBS#: B.TR.100150.6614

Western Region

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
40 (7)	ALC	NS9871	E/333 not loading		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standeers

Train	Projected Need		Number Operated		Standeers	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Train 8(06) Passenger Removal at Detroit Lakes, Minnesota – Improper Conduct

08JUL26, Passenger on PNR 7BB9C2, traveling from Grand Forks, ND to Saint Cloud, MN was removed from the train by local Police after exposing himself in front of a 16-year-old passenger. Passenger may be unfit to travel. Amtrak Police notified.

Delay: 8 (06) 9"

Consist Deviations

26-FOI-00590

00000008303

"UNCLASSIFIED"

7/15/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
245 (08)	ALB	245(08) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48172
685 (08)	BON	685(08) will operate with a club-dinette in lieu of a coach for additonal seating.	NONE	0	48189
171 (08)	BOS	81518 WILL BE USED AS COACH	n/a	0	81518
171 (08)	BOS	amii used to replace ami	n/a	0	25085
173 (08)	BOS	173(08) operating with 8 cars due to lack of available equipment in BOS.	none	0	
684 (08)	BRK	684(08) will operate with a club-dinette in lieu of a coach for additonal seating.	NONE	0	48189
7 (08)	CHI	Cross-country Diner/Lounge operating in lieu of a standard diner.	NONE	0	37010
383 (08)	CHI	383(8) will operate with no cafe car	NONE	0	NOCAR
6 (08)	EMY	39015 deadhead only due to no hot water. Re-accommodate passengers.	YES WAS MOVED TO RMH 632 CAR PNR 849727	1	39015
644 (08)	HAR	NO CAB CAR	n/a	0	43389
626 (08)	HAR	NO CAB CAR	n/a	0	43389
600 (08)	HAR	600(08) is operating with 3 coaches and a cab car. There is no customer impact.	none	0	
644 (08)	HAR	644(08) will operate with 4 coaches and cafe for Wi-Fi. Capacity reduced to 288, with no customer impact.	none	0	43389
654 (08)	HAR	654(08) will operate with 4 coaches and cafe for Wi-Fi. Capacity reduced to 288, with no customer impact.	none	0	43389
640 (08)	HAR	640(08) will operate with 5 coaches and cafe for Wi-Fi. There is no impact on passenger capacity.	none	0	43379
652 (08)	HAR	652(08) will operate with 5 coaches and cafe for Wi-Fi. There is no impact on passenger capacity.	No impact	0	43379

Train Number	Station	Reason 26-FOI-00590 00000008303	Customer Impact "UNCLASSIFIED" 7/15/2026	Affected Psgr	Unit Number(s)
656 (08)	HAR	656(08) will operate with 5 coaches and no cab car. Wi-Fi services are not available.	none	0	82764
564 (08)	LAX	Cab 90215. No bike space, no Wifi. Notify passengers.	NONE	0	90215
68 (08)	MTR	68(08) will operate with a club-dinette in lieu of a cafe car.	NONE	0	48172
181 (08)	NYP	split club in place of a cafe	n/a	0	48174
181 (08)	NYP	business class used as a coach	n/a	0	81511
649 (08)	NYP	NO CAB CAR	n/a	0	43389
609 (08)	NYP	NO CAB CAR/NO WIFI	No impact	0	NOCAR
651 (08)	NYP	651(08) is operating with 3 coaches and a cab car. There is no customer impact.	none	0	
645 (08)	NYP	645(08) will operate with 4 coaches and cafe for Wi-Fi. Capacity reduced to 288, with no customer impact.	NONE	0	43389
639 (08)	NYP	639(08) will operate with 4 coaches and cafe for Wi-Fi. Capacity reduced to 288, with no customer impact.	NONE	0	43389
643 (08)	NYP	643(08) will operate with 5 coaches and cafe for Wi-Fi. There is no impact on passenger capacity.	none	0	43379
657 (08)	NYP	657(08) will operate with 5 coaches and cafe for Wi-Fi. There is no impact on passenger capacity.	No impact	0	43379
49 (08)	NYP	(4912) Viewliner II in lieu of Viewliner I. Please accomodate all passengers effected.	No impact.	0	62517
601 (08)	PHL	NO CAB CAR	n/a	0	43389
380 (09)	QCY	train 380(9) will operate with no cafe car	NONE	0	NOCAR
777 (08)	SAN	Cab car 90215 - no bike space no Wifi. Notify passengers.	none	0	90215
785 (09)	SAN	NO BIKE SERVICE- over capacity. NO WIFI SERVICE.	Passengers notified 5 bike spaces	614	90215
774 (09)	SLO	NO BIKE SERVICE- over capacity. NO WIFI SERVICE.	Passengers notified 4 bike	287	90215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00590 00000008303 "UNCLASSIFIED" 7/15/2026	spaces		
174 (08)	WAS	174(08) will operate with a Business Class car in lieu of a coach and a club-dinette in lieu of a cafe car.	NONE	0	81511

Reverse Consists

Train Number	Station	Reason
181 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
110 (08)	PHL	Consist reversed Business class seat orientation may have changed At Rear
190 (08)	PHL	Consist reversed Business class seat orientation may have changed At Front
137 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
185 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
131 (08)	NYP	Consist reversed Business class seat orientation may have changed At Rear
196 (08)	WAS	Business class change only Business class seating orientation may have changed At Rear
148 (08)	WAS	Business class change only Business class seating orientation may have changed At Rear
171 (08)	BOS	Business class change only Business class seating orientation may have changed At Rear
178 (09)	RNK	Business class change only Business class seating orientation may have changed At Rear
148 (09)	WAS	Business class change only Business class seating orientation may have changed At Rear
141 (09)	SPG	Business class change only Business class seating orientation may have changed At Rear