



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, July 11, 2026

Rules: 0-36



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-005Initial Terminal Performance By Division

Scheduled Departure Date: 07/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/10/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	42	86.9%	3,048	478	84.3%	84,395	11,600	86.3%
Central Division	86.0%	68	6	91.2%	708	73	89.7%	20,747	1,891	90.9%
East Division	82.0%	177	22	87.6%	1,599	277	82.7%	44,150	6,884	84.4%
West Division	86.0%	76	14	81.6%	741	128	82.7%	19,498	2,825	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00590

Endpoint Arrival Dates through 7/10/26

UNCLASSIFIED

7/15/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	113,585	35,645	69%	1,048,263	394,471	62%	27,995,587	6,868,757	75%
Northeast Corridor	81%	49,921	12,629	75%	445,479	171,091	62%	12,289,260	2,954,284	76%
Acela	83%	12,121	2,330	81%	98,541	34,211	65%	2,435,306	636,888	74%
Northeast Regional	79%	37,800	10,299	73%	346,938	136,880	61%	9,853,954	2,317,396	76%
Richmond / Newport News / Norfolk	77%	12,132	3,994	67%	106,977	50,116	53%	3,057,705	863,737	72%
Springfield Shuttles	89%	894	96	89%	7,434	2,537	66%	175,468	26,751	85%
Roanoke	79%	4,193	309	93%	33,147	15,852	52%	926,207	191,137	79%
On Spine Northeast Regional	80%	20,581	5,900	71%	199,380	68,375	66%	5,694,574	1,235,771	78%
State Supported	80%	50,118	12,652	75%	474,556	139,337	71%	12,260,604	2,501,701	80%
Borealis	80%	613	192	69%	5,899	1,530	74%	156,869	31,976	80%
Capitol Corridor	90%	3,543	760	79%	38,010	6,446	83%	1,039,229	135,642	87%
Carolinian	70%	1,671	1,249	25%	11,086	7,575	32%	321,060	123,481	62%
Cascades	75%	3,087	1,195	61%	32,210	9,598	70%	719,854	198,158	72%
Downeaster	82%	1,940	207	89%	18,360	5,283	71%	415,858	50,753	88%
Empire	78%	6,457	1,963	70%	60,592	23,148	62%	1,514,597	337,565	78%
Adirondack	72%	381	196	49%	4,394	2,149	51%	90,827	27,633	70%
Ethan Allen Express	70%	654	494	24%	5,753	4,049	30%	156,718	51,656	67%
Maple Leaf	70%	912	281	69%	8,746	3,947	55%	183,565	70,734	61%
New York - Albany	85%	2,482	1	100%	26,743	6,576	75%	703,908	110,476	84%
New York - Niagara Falls	75%	1,519	653	57%	13,472	5,298	61%	374,931	75,077	80%
Berkshire Flyer	60%	509	338	34%	1,484	1,129	24%	4,648	1,989	57%
Gold Runner	73%	3,029	1,397	54%	26,418	11,402	57%	700,038	243,500	65%
Heartland Flyer	70%	335	225	33%	2,817	1,574	44%	58,522	22,067	62%
Hiawatha	90%	2,078	29	99%	19,149	989	95%	476,843	51,537	89%
Illinois	78%	2,249	347	85%	26,790	10,297	62%	688,945	186,341	73%
Carl Sandburg / Illinois Zephyr	85%	329	11	97%	4,675	1,516	68%	114,229	29,322	74%
Illini / Saluki	85%	931	336	64%	9,574	3,199	67%	243,236	57,226	76%
Lincoln Service	70%	989	0	100%	12,541	5,582	55%	331,480	99,793	70%
Keystone	92%	8,170	1,143	86%	70,353	13,659	81%	2,127,430	223,594	89%
Lincoln / Missouri	70%	530	314	41%	6,360	3,797	40%	214,879	107,613	50%
Mardi Gras Service	80%	384	176	54%	4,143	1,863	55%	115,091	24,324	79%
Michigan	70%	2,978	1,022	66%	23,299	11,163	52%	543,046	176,118	68%
Blue Water	70%	553	458	17%	5,409	4,033	25%	125,635	49,367	61%
Pere Marquette	85%	362	51	86%	3,087	717	77%	70,659	14,047	80%
Wolverine	70%	2,063	513	75%	14,803	6,413	57%	346,752	112,704	67%
Missouri	80%	0	0	-	1,266	319	75%	60,502	13,559	78%
Pacific Surfliner	85%	9,936	1,473	85%	100,325	18,583	81%	2,182,849	345,745	84%
Pennsylvanian	80%	964	282	71%	9,007	4,086	55%	247,717	46,245	81%
Piedmont	80%	929	470	49%	5,487	2,553	53%	318,872	81,107	75%
Vermont	75%	1,225	208	83%	12,985	5,472	58%	358,403	102,376	71%
Long Distance	70%	13,546	10,364	23%	128,228	84,043	34%	3,406,456	1,410,309	59%
Auto Train	70%	853	853	0%	8,304	2,885	65%	217,148	73,713	66%
California Zephyr	70%	1,044	858	18%	10,165	6,226	39%	270,228	91,523	66%
Cardinal	70%	252	107	58%	2,498	1,846	26%	66,172	32,088	52%
City Of New Orleans	75%	355	351	1%	849	648	24%	178,213	50,265	72%
Coast Starlight	70%	1,277	800	37%	12,526	3,862	69%	317,290	108,314	66%
Crescent	70%	1,098	430	61%	9,482	6,549	31%	259,975	78,641	70%
Empire Builder	70%	1,296	644	50%	12,749	7,460	41%	265,810	126,212	53%
Floridian	60%	1,844	1,844	0%	15,296	15,202	1%	445,461	298,845	33%
Lake Shore Ltd	73%	1,243	911	27%	11,733	6,466	45%	263,370	78,076	70%
Palmetto	70%	424	349	18%	8,517	6,694	21%	256,290	72,792	72%
Silver Meteor	70%	967	922	5%	10,853	9,527	12%	283,234	119,679	58%
Southwest Chief	60%	1,007	949	6%	10,219	7,595	26%	228,869	146,007	36%
Sunset Ltd	70%	906	650	28%	3,670	2,037	44%	82,055	28,718	65%
Texas Eagle	70%	980	696	29%	11,367	7,046	38%	272,341	105,436	61%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00500 00000000001 "UNCLASSIFIED" 7/15/2020

Train Index Dates Through July 10, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	74,523	1,047,318	712	1,641,456	29,684,360	553

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,162	310,336	134	77,502	8,524,940	91
INFRASTRUCTURE PLANNED	135	4,847	310,336	156	83,719	8,524,940	98
FLEET RELIABILITY	90	12,163	1,047,318	116	265,152	29,684,360	89
TRAIN OPERATIONS	424	53,351	1,047,318	509	1,215,083	29,684,360	409

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/10/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	42	86.9%	3,048	478	84.3%	84,395	11,600	86.3%
Central Division	86.0%	68	6	91.2%	708	73	89.7%	20,747	1,891	90.9%
East Division	82.0%	177	22	87.6%	1,599	277	82.7%	44,150	6,884	84.4%
West Division	86.0%	76	14	81.6%	741	128	82.7%	19,498	2,825	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/10/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	42	86.9%	3,048	478	84.3%	84,395	11,600	86.3%
Central Division	86.0%	68	6	91.2%	708	73	89.7%	20,747	1,891	90.9%
ATL	-	-	-	-	-	-	-	35	5	85.7%
CDL	95.0%	2	1	50.0%	20	1	95.0%	537	19	96.5%
CHI	86.0%	25	1	96.0%	258	29	88.8%	7,497	893	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
EMY	72.0%	-	-	-	-	-	-	10	1	90.0%
EUG	86.5%	2	0	100.0%	20	0	100.0%	556	52	90.6%
FTW	92.5%	1	0	100.0%	10	1	90.0%	306	35	88.6%
GBB	-	-	-	-	3	3	0.0%	3	3	0.0%
GRR	95.5%	1	0	100.0%	9	0	100.0%	268	8	97.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	-	-	-	12	2	83.3%	550	42	92.4%
LAX	89.5%	1	0	100.0%	10	2	80.0%	272	42	84.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	59	4	93.2%	1,657	101	93.9%
MOE	97.5%	2	0	100.0%	20	1	95.0%	565	9	98.4%
MSP	96.5%	1	0	100.0%	10	0	100.0%	276	5	98.2%
NOL	94.5%	4	0	100.0%	37	6	83.8%	1,187	59	95.0%
OKC	97.0%	1	0	100.0%	10	0	100.0%	277	6	97.8%
PDX	86.0%	4	0	100.0%	40	3	92.5%	1,122	110	90.2%
PNT	88.0%	3	1	66.7%	26	4	84.6%	729	62	91.5%
PTH	93.0%	1	0	100.0%	10	1	90.0%	271	11	95.9%
QCY	91.0%	1	1	0.0%	14	2	85.7%	545	42	92.3%
SAC	88.5%	-	-	-	-	-	-	1	0	100.0%
SAS	90.5%	1	0	100.0%	10	0	100.0%	279	27	90.3%
SEA	85.0%	7	0	100.0%	70	6	91.4%	1,960	213	89.1%
STL	89.0%	3	2	33.3%	39	7	82.1%	1,096	97	91.1%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	97.0%	2	0	100.0%	20	0	100.0%	550	14	97.5%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	177	22	87.6%	1,599	277	82.7%	44,150	6,884	84.4%
ALB	88.5%	7	0	100.0%	77	3	96.1%	2,091	164	92.2%
BON	87.5%	5	2	60.0%	49	9	81.6%	1,361	149	89.1%
BOS	85.5%	18	0	100.0%	165	11	93.3%	4,801	572	88.1%
BRK	92.5%	5	1	80.0%	49	10	79.6%	1,350	94	93.0%
BTN	82.0%	1	0	100.0%	10	0	100.0%	269	39	85.5%
CLT	91.5%	5	3	40.0%	36	9	75.0%	1,377	141	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	20	2	90.0%	551	52	90.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/10/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	42	86.9%	3,048	478	84.3%	84,395	11,600	86.3%
East Division	82.0%	177	22	87.6%	1,599	277	82.7%	44,150	6,884	84.4%
GRO	-	-	-	-	-	-	-	29	10	65.5%
HAR	79.5%	13	3	76.9%	106	13	87.7%	3,129	519	83.4%
HFD	-	2	0	100.0%	14	2	85.7%	161	10	93.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	1	0.0%	10	1	90.0%	279	35	87.5%
MIA	89.5%	2	0	100.0%	19	3	84.2%	558	63	88.7%
MTR	79.0%	1	0	100.0%	10	2	80.0%	266	48	82.0%
NFK	84.5%	2	0	100.0%	20	7	65.0%	641	116	81.9%
NFL	93.5%	2	0	100.0%	20	2	90.0%	570	24	95.8%
NFS	-	-	-	-	-	-	-	6	5	16.7%
NHV	78.0%	5	0	100.0%	48	4	91.7%	1,454	227	84.4%
NPN	93.0%	2	0	100.0%	18	3	83.3%	531	38	92.8%
NYP	75.5%	51	8	84.3%	451	118	73.8%	11,502	2,579	77.6%
PGH	93.0%	1	0	100.0%	10	2	80.0%	281	21	92.5%
PHL	48.0%	5	2	60.0%	48	19	60.4%	1,448	696	51.9%
PIT	76.0%	1	1	0.0%	3	3	0.0%	9	8	11.1%
POR	-	-	-	-	-	-	-	8	5	37.5%
RGH	95.0%	4	0	100.0%	26	2	92.3%	1,083	43	96.0%
RNK	83.5%	2	0	100.0%	20	4	80.0%	554	81	85.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	10	0	100.0%	269	4	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	8	0	100.0%	276	10	96.4%
SFA	88.0%	1	0	100.0%	10	0	100.0%	279	37	86.7%
SPG	92.5%	5	0	100.0%	54	3	94.4%	1,706	95	94.4%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	10	1	90.0%	269	57	78.8%
WAS	84.0%	31	1	96.8%	277	43	84.5%	6,870	884	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	76	14	81.6%	741	128	82.7%	19,498	2,825	85.5%
ARN	92.0%	1	0	100.0%	10	2	80.0%	281	21	92.5%
BFD	79.0%	6	2	66.7%	65	21	67.7%	1,751	362	79.3%
EMY	72.0%	1	1	0.0%	10	6	40.0%	287	91	68.3%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	0	100.0%	2	1	50.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	30	7	76.7%	846	121	85.7%
IRV	-	-	-	-	-	-	-	4	2	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/10/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/10/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	321	42	86.9%	3,048	478	84.3%	84,395	11,600	86.3%
West Division	86.0%	76	14	81.6%	741	128	82.7%	19,498	2,825	85.5%
LAX	89.5%	10	3	70.0%	95	10	89.5%	2,509	246	90.2%
MCD	-	-	-	-	-	-	-	8	7	12.5%
OKJ	74.5%	13	1	92.3%	119	37	68.9%	3,018	773	74.4%
PDX	86.0%	1	1	0.0%	10	1	90.0%	265	60	77.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	2	87.5%	152	21	86.2%	3,956	431	89.1%
SAN	90.5%	13	1	92.3%	129	9	93.0%	3,373	303	91.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	1	1	0.0%	10	4	60.0%	262	107	59.2%
SJC	89.0%	7	1	85.7%	70	8	88.6%	1,977	190	90.4%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	30	2	93.3%	609	62	89.8%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	10	0	100.0%	276	20	92.8%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	134	4	0	100.0%	119	8	93.3%	5	2	60.0%	120	25	79.2%
2		5	2	60.0%	120	27	77.5%	4	1	75.0%	116	21	81.9%
3	63	10	0	100.0%	281	54	80.8%	10	4	60.0%	279	121	56.6%
4	145	10	0	100.0%	280	42	85.0%	10	6	40.0%	280	185	33.9%
5	53	10	1	90.0%	279	44	84.2%	9	6	33.3%	275	69	74.9%
6	50	10	6	40.0%	278	83	70.1%	10	7	30.0%	278	89	68.0%
7		10	1	90.0%	270	36	86.7%	10	3	70.0%	263	64	75.7%
8	204	10	4	60.0%	270	115	57.4%	10	7	30.0%	269	156	42.0%
11		10	2	80.0%	281	52	81.5%	10	1	90.0%	275	55	80.0%
14	113	10	2	80.0%	282	43	84.8%	10	2	80.0%	280	85	69.6%
19	56	10	6	40.0%	280	71	74.6%	10	8	20.0%	278	67	75.9%
20		10	4	60.0%	280	22	92.1%	10	7	30.0%	280	54	80.7%
21	36	10	0	100.0%	277	22	92.1%	10	6	40.0%	276	68	75.4%
22	303	10	0	100.0%	278	25	91.0%	10	6	40.0%	276	68	75.4%
23		10	1	90.0%	283	6	97.9%	10	6	40.0%	281	75	73.3%
24		10	2	80.0%	283	16	94.3%	10	4	60.0%	282	47	83.3%
25	82	10	0	100.0%	282	3	98.9%	10	5	50.0%	280	74	73.6%
26	44	10	0	100.0%	282	5	98.2%	10	4	60.0%	280	56	80.0%
27		10	2	80.0%	268	16	94.0%	10	2	80.0%	264	83	68.6%
28		10	1	90.0%	264	60	77.3%	10	1	90.0%	264	52	80.3%
40	161	9	2	77.8%	275	40	85.5%	9	9	0.0%	274	141	48.5%
41	102	9	6	33.3%	275	108	60.7%	9	9	0.0%	273	205	24.9%
42		10	2	80.0%	282	22	92.2%	10	4	60.0%	280	46	83.6%
43	22	10	0	100.0%	281	41	85.4%	10	6	40.0%	281	62	77.9%
48		10	3	70.0%	280	56	80.0%	10	3	70.0%	280	41	85.4%
49	60	10	3	70.0%	280	70	75.0%	10	5	50.0%	280	57	79.6%
50		4	1	75.0%	115	27	76.5%	5	4	20.0%	115	67	41.7%
52	157	10	0	100.0%	279	37	86.7%	10	2	80.0%	278	63	77.3%
53		10	1	90.0%	279	35	87.5%	10	2	80.0%	278	87	68.7%
55		7	0	100.0%	175	6	96.6%	7	2	71.4%	172	36	79.1%
56		7	0	100.0%	176	22	87.5%	7	4	42.9%	173	30	82.7%
58	325	3	0	100.0%	262	16	93.9%	2	2	0.0%	260	67	74.2%
63		10	5	50.0%	283	122	56.9%	10	8	20.0%	279	148	47.0%
64	24	10	1	90.0%	281	64	77.2%	10	6	40.0%	281	97	65.5%
66		10	3	70.0%	280	57	79.6%	8	2	75.0%	276	51	81.5%
67	95	6	1	83.3%	193	12	93.8%	7	2	71.4%	194	33	83.0%
68	75	10	2	80.0%	283	57	79.9%	10	6	40.0%	283	109	61.5%
69		10	3	70.0%	270	62	77.0%	10	5	50.0%	266	37	86.1%
71		10	0	100.0%	278	3	98.9%	10	7	30.0%	277	73	73.6%
72	15	6	0	100.0%	274	29	89.4%	6	2	66.7%	273	57	79.1%
73		5	0	100.0%	277	16	94.2%	5	3	40.0%	275	129	53.1%
74	18	5	1	80.0%	275	31	88.7%	5	4	20.0%	273	98	64.1%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	Cncld	5	0	100.0%	275	14	94.9%	4	3	25.0%	269	128	52.4%
76	Cncld	5	1	80.0%	275	27	90.2%	4	3	25.0%	266	107	59.8%
77	101	5	2	60.0%	274	19	93.1%	5	4	20.0%	272	112	58.8%
78	42	10	3	70.0%	278	23	91.7%	10	7	30.0%	277	57	79.4%
79	51	10	0	100.0%	280	55	80.4%	10	9	10.0%	279	93	66.7%
80		10	4	60.0%	280	32	88.6%	9	4	55.6%	277	53	80.9%
84		6	1	83.3%	168	12	92.9%	6	3	50.0%	166	38	77.1%
85	16	7	0	100.0%	177	16	91.0%	7	3	57.1%	177	64	63.8%
86	28	7	1	85.7%	177	15	91.5%	7	6	14.3%	176	106	39.8%
89	80	10	4	60.0%	278	62	77.7%	10	7	30.0%	276	77	72.1%
90	213	10	0	100.0%	278	10	96.4%	10	8	20.0%	277	45	83.8%
93		7	0	100.0%	176	18	89.8%	7	4	42.9%	175	41	76.6%
94		7	3	57.1%	207	53	74.4%	7	4	42.9%	205	73	64.4%
95		7	0	100.0%	176	3	98.3%	7	3	57.1%	176	62	64.8%
97	115	10	10	0.0%	280	183	34.6%	10	9	10.0%	278	85	69.4%
98	71	10	1	90.0%	280	22	92.1%	10	9	10.0%	278	89	68.0%
110	17	7	3	57.1%	173	99	42.8%	7	2	71.4%	170	18	89.4%
111	19	7	0	100.0%	167	32	80.8%	7	1	85.7%	165	21	87.3%
112		7	0	100.0%	167	16	90.4%	7	2	71.4%	166	19	88.6%
113		7	1	85.7%	98	23	76.5%	7	0	100.0%	97	11	88.7%
119		6	1	83.3%	166	44	73.5%	6	2	66.7%	164	22	86.6%
125		7	0	100.0%	177	8	95.5%	7	3	57.1%	177	69	61.0%
129		7	0	100.0%	176	44	75.0%	7	2	71.4%	176	25	85.8%
130		7	1	85.7%	167	17	89.8%	7	1	85.7%	165	16	90.3%
131		7	3	57.1%	169	50	70.4%	7	4	42.9%	169	33	80.5%
134		7	2	71.4%	177	23	87.0%	7	3	57.1%	176	29	83.5%
136	35	7	2	71.4%	177	22	87.6%	8	4	50.0%	176	21	88.1%
136		7	2	71.4%	177	22	87.6%	8	4	50.0%	176	21	88.1%
137		7	2	71.4%	174	32	81.6%	7	2	71.4%	174	54	69.0%
138		7	2	71.4%	177	37	79.1%	7	3	57.1%	176	30	83.0%
141		7	0	100.0%	176	3	98.3%	7	2	71.4%	175	30	82.9%
148	130	7	0	100.0%	176	17	90.3%	7	2	71.4%	174	32	81.6%
151		10	2	80.0%	279	88	68.5%	10	7	30.0%	278	91	67.3%
170		7	0	100.0%	172	12	93.0%	7	0	100.0%	171	29	83.0%
171	16	7	0	100.0%	177	10	94.4%	7	6	14.3%	177	67	62.1%
172	26	7	0	100.0%	176	14	92.0%	7	4	42.9%	174	59	66.1%
173		6	1	83.3%	171	24	86.0%	6	3	50.0%	170	76	55.3%
174	29	7	0	100.0%	177	20	88.7%	7	4	42.9%	177	42	76.3%
175		7	0	100.0%	177	21	88.1%	7	2	71.4%	177	57	67.8%
176	68	6	1	83.3%	171	15	91.2%	6	3	50.0%	169	18	89.3%
177		7	1	85.7%	177	25	85.9%	7	0	100.0%	177	44	75.1%
178		7	0	100.0%	177	24	86.4%	7	3	57.1%	175	26	85.1%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		7	2	71.4%	177	21	88.1%	7	4	42.9%	176	62	64.8%
181		7	1	85.7%	173	55	68.2%	7	2	71.4%	171	14	91.8%
182		7	1	85.7%	167	29	82.6%	7	1	85.7%	165	17	89.7%
183		7	3	57.1%	176	51	71.0%	7	2	71.4%	174	35	79.9%
184		7	2	71.4%	177	31	82.5%	7	3	57.1%	176	26	85.2%
185		7	0	100.0%	177	36	79.7%	7	0	100.0%	177	11	93.8%
186		7	1	85.7%	176	18	89.8%	7	2	71.4%	175	42	76.0%
190		7	2	71.4%	176	64	63.6%	7	2	71.4%	175	39	77.7%
192		7	2	71.4%	174	21	87.9%	7	1	85.7%	174	15	91.4%
193		6	3	50.0%	175	74	57.7%	6	4	33.3%	174	84	51.7%
196		6	0	100.0%	175	18	89.7%	6	0	100.0%	174	15	91.4%
197		7	2	71.4%	177	70	60.5%	7	4	42.9%	177	57	67.8%
198		7	3	57.1%	109	17	84.4%	7	2	71.4%	108	18	83.3%
230		10	0	100.0%	117	4	96.6%	10	0	100.0%	117	6	94.9%
232		10	0	100.0%	283	11	96.1%	10	0	100.0%	283	17	94.0%
234		10	1	90.0%	283	20	92.9%	10	0	100.0%	283	24	91.5%
235		10	0	100.0%	207	27	87.0%	10	4	60.0%	207	45	78.3%
236		10	0	100.0%	267	7	97.4%	10	2	80.0%	267	38	85.8%
237		10	0	100.0%	281	52	81.5%	10	3	70.0%	279	46	83.5%
238		10	0	100.0%	207	19	90.8%	10	0	100.0%	206	14	93.2%
239		10	2	80.0%	282	74	73.8%	10	3	70.0%	281	33	88.3%
240		10	0	100.0%	282	20	92.9%	10	4	60.0%	280	48	82.9%
241		10	2	80.0%	283	70	75.3%	10	2	80.0%	283	68	76.0%
243		10	5	50.0%	219	60	72.6%	10	3	70.0%	218	29	86.7%
245		10	3	70.0%	164	30	81.7%	10	1	90.0%	163	18	89.0%
280		10	2	80.0%	283	13	95.4%	10	1	90.0%	283	51	82.0%
281		10	3	70.0%	283	32	88.7%	10	5	50.0%	283	52	81.6%
283		10	4	60.0%	283	68	76.0%	10	5	50.0%	283	57	79.9%
284	18	10	0	100.0%	283	10	96.5%	10	5	50.0%	281	47	83.3%
290	73	10	0	100.0%	283	48	83.0%	10	8	20.0%	281	99	64.8%
291		10	5	50.0%	282	80	71.6%	10	5	50.0%	280	63	77.5%
300		10	1	90.0%	267	20	92.5%	10	6	40.0%	265	62	76.6%
301		10	0	100.0%	281	9	96.8%	10	3	70.0%	278	53	80.9%
306		10	0	100.0%	279	15	94.6%	10	4	60.0%	278	75	73.0%
307		10	2	80.0%	271	37	86.3%	10	4	60.0%	268	74	72.4%
318	83	10	4	60.0%	282	30	89.4%	10	8	20.0%	279	132	52.7%
319		9	0	100.0%	282	17	94.0%	6	3	50.0%	277	148	46.6%
329		8	0	100.0%	200	8	96.0%	8	0	100.0%	200	13	93.5%
330		9	0	100.0%	240	4	98.3%	9	1	88.9%	240	14	94.2%
331		10	1	90.0%	283	30	89.4%	10	0	100.0%	283	40	85.9%
332		10	1	90.0%	283	15	94.7%	10	2	80.0%	283	41	85.5%
334		10	0	100.0%	283	9	96.8%	10	1	90.0%	282	37	86.9%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335	13	10	0	100.0%	283	30	89.4%	10	3	70.0%	281	46	83.6%
336		10	1	90.0%	283	9	96.8%	10	1	90.0%	281	26	90.7%
337		10	1	90.0%	283	18	93.6%	10	1	90.0%	279	34	87.8%
338		10	2	80.0%	283	43	84.8%	10	2	80.0%	281	83	70.5%
339		10	1	90.0%	283	47	83.4%	10	1	90.0%	283	49	82.7%
341		10	1	90.0%	272	36	86.8%	10	1	90.0%	267	36	86.5%
342		10	0	100.0%	283	21	92.6%	10	1	90.0%	281	54	80.8%
350		10	1	90.0%	264	18	93.2%	8	4	50.0%	257	140	45.5%
351		10	2	80.0%	266	27	89.8%	10	3	70.0%	264	71	73.1%
352		10	0	100.0%	250	20	92.0%	10	4	60.0%	244	75	69.3%
353		7	1	85.7%	222	13	94.1%	7	1	85.7%	216	36	83.3%
354	84	10	4	60.0%	264	32	87.9%	8	7	12.5%	258	96	62.8%
355		10	2	80.0%	277	29	89.5%	10	7	30.0%	270	92	65.9%
364	103	10	1	90.0%	272	61	77.6%	10	7	30.0%	266	97	63.5%
365	24	10	1	90.0%	271	11	95.9%	10	8	20.0%	269	100	62.8%
370		10	1	90.0%	274	34	87.6%	9	1	88.9%	266	66	75.2%
371		9	0	100.0%	268	8	97.0%	9	2	77.8%	267	29	89.1%
380		9	2	77.8%	268	26	90.3%	9	4	55.6%	268	53	80.2%
383		10	1	90.0%	272	26	90.4%	9	4	55.6%	269	109	59.5%
390		10	0	100.0%	265	17	93.6%	10	3	70.0%	264	66	75.0%
391	186	10	1	90.0%	268	9	96.6%	10	4	60.0%	265	69	74.0%
392	120	10	1	90.0%	282	6	97.9%	10	7	30.0%	280	85	69.6%
393	87	10	0	100.0%	283	16	94.3%	10	6	40.0%	280	83	70.4%
417		7	3	57.1%	187	41	78.1%	7	2	71.4%	178	19	89.3%
425		7	0	100.0%	189	6	96.8%	7	0	100.0%	189	7	96.3%
448	51	10	2	80.0%	213	40	81.2%	10	6	40.0%	211	74	64.9%
449		10	1	90.0%	211	31	85.3%	10	4	60.0%	211	40	81.0%
470		7	1	85.7%	200	35	82.5%	7	0	100.0%	194	23	88.1%
471		7	2	71.4%	190	8	95.8%	7	2	71.4%	190	4	97.9%
473		7	0	100.0%	196	13	93.4%	7	0	100.0%	193	8	95.9%
474		8	3	62.5%	192	54	71.9%	7	5	28.6%	179	52	70.9%
475		7	0	100.0%	194	5	97.4%	7	3	57.1%	194	13	93.3%
478		7	2	71.4%	188	29	84.6%	7	1	85.7%	186	21	88.7%
479		7	2	71.4%	195	31	84.1%	7	5	28.6%	193	27	86.0%
486		7	1	85.7%	199	29	85.4%	7	3	57.1%	193	53	72.5%
494	36	7	1	85.7%	200	36	82.0%	7	6	14.3%	194	50	74.2%
495		7	0	100.0%	185	3	98.4%	7	0	100.0%	183	3	98.4%
500		10	1	90.0%	274	16	94.2%	9	1	88.9%	271	33	87.8%
502		10	1	90.0%	281	16	94.3%	9	1	88.9%	277	57	79.4%
503		10	1	90.0%	279	26	90.7%	10	6	40.0%	273	80	70.7%
504	27	10	0	100.0%	283	17	94.0%	10	3	70.0%	281	85	69.8%
505	24	10	1	90.0%	281	37	86.8%	9	6	33.3%	276	79	71.4%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506		10	1	90.0%	278	39	86.0%	10	2	80.0%	273	43	84.2%
507	112	10	1	90.0%	283	35	87.6%	10	3	70.0%	283	91	67.8%
508	57	10	0	100.0%	278	39	86.0%	10	1	90.0%	275	63	77.1%
509	22	10	0	100.0%	280	12	95.7%	10	1	90.0%	280	64	77.1%
511		10	0	100.0%	275	21	92.4%	10	0	100.0%	274	45	83.6%
516		10	1	90.0%	275	28	89.8%	10	2	80.0%	274	125	54.4%
517	20	10	0	100.0%	283	8	97.2%	10	8	20.0%	279	116	58.4%
518	22	10	0	100.0%	283	35	87.6%	10	8	20.0%	281	191	32.0%
519		10	0	100.0%	275	9	96.7%	10	1	90.0%	273	64	76.6%
520		8	0	100.0%	158	24	84.8%	8	0	100.0%	155	9	94.2%
521		8	0	100.0%	196	7	96.4%	8	2	75.0%	196	25	87.2%
522		8	0	100.0%	196	36	81.6%	8	0	100.0%	193	18	90.7%
523		8	0	100.0%	196	6	96.9%	8	0	100.0%	195	22	88.7%
524		8	2	75.0%	196	13	93.4%	8	1	87.5%	194	21	89.2%
525		8	2	75.0%	194	14	92.8%	7	0	100.0%	190	13	93.2%
526		8	3	62.5%	170	32	81.2%	8	2	75.0%	167	14	91.6%
527	44	8	1	87.5%	196	10	94.9%	8	3	62.5%	195	35	82.1%
528	11	8	1	87.5%	196	16	91.8%	8	1	87.5%	195	30	84.6%
529		8	0	100.0%	196	11	94.4%	8	1	87.5%	195	51	73.8%
530	52	8	1	87.5%	150	15	90.0%	8	3	62.5%	150	29	80.7%
531		8	0	100.0%	170	12	92.9%	8	1	87.5%	170	12	92.9%
532		8	4	50.0%	196	47	76.0%	8	2	75.0%	195	29	85.1%
534		8	0	100.0%	155	24	84.5%	8	0	100.0%	153	15	90.2%
535	42	8	1	87.5%	183	24	86.9%	8	1	87.5%	178	21	88.2%
536		8	2	75.0%	196	51	74.0%	7	0	100.0%	192	37	80.7%
537		8	2	75.0%	167	20	88.0%	8	2	75.0%	162	18	88.9%
538		8	0	100.0%	196	23	88.3%	8	2	75.0%	195	39	80.0%
539	No OS	8	1	87.5%	150	21	86.0%	8	2	75.0%	150	66	56.0%
540		7	2	71.4%	195	37	81.0%	7	0	100.0%	188	18	90.4%
541		8	0	100.0%	195	21	89.2%	8	1	87.5%	190	34	82.1%
542		8	0	100.0%	195	21	89.2%	8	3	62.5%	193	35	81.9%
543	44	8	2	75.0%	196	21	89.3%	8	6	25.0%	196	56	71.4%
544	12	8	0	100.0%	194	20	89.7%	8	2	75.0%	191	17	91.1%
545		8	1	87.5%	196	16	91.8%	8	1	87.5%	194	23	88.1%
547	52	8	1	87.5%	196	38	80.6%	8	1	87.5%	196	45	77.0%
548		7	0	100.0%	191	20	89.5%	7	0	100.0%	190	14	92.6%
549		8	1	87.5%	191	26	86.4%	7	0	100.0%	183	16	91.3%
550		8	1	87.5%	150	15	90.0%	8	1	87.5%	150	32	78.7%
551		8	1	87.5%	192	20	89.6%	8	0	100.0%	184	17	90.8%
562		10	1	90.0%	275	22	92.0%	10	0	100.0%	272	29	89.3%
564		10	0	100.0%	275	17	93.8%	10	1	90.0%	267	31	88.4%
566		10	1	90.0%	273	18	93.4%	10	2	80.0%	270	34	87.4%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
567		10	0	100.0%	160	8	95.0%	10	0	100.0%	158	6	96.2%
572		10	0	100.0%	270	22	91.9%	9	4	55.6%	264	69	73.9%
573		10	0	100.0%	273	40	85.3%	10	1	90.0%	266	45	83.1%
579		10	0	100.0%	160	8	95.0%	10	2	80.0%	155	28	81.9%
580		10	0	100.0%	275	14	94.9%	10	1	90.0%	270	22	91.9%
581		10	2	80.0%	275	45	83.6%	10	3	70.0%	273	57	79.1%
584	33	10	3	70.0%	159	20	87.4%	10	8	20.0%	155	90	41.9%
587		9	0	100.0%	269	15	94.4%	9	3	66.7%	260	41	84.2%
588		10	2	80.0%	160	14	91.3%	10	0	100.0%	159	22	86.2%
591		10	0	100.0%	274	18	93.4%	10	0	100.0%	268	29	89.2%
593		10	2	80.0%	269	39	85.5%	10	1	90.0%	251	28	88.8%
595		10	2	80.0%	270	43	84.1%	10	1	90.0%	267	47	82.4%
600		7	0	100.0%	204	9	95.6%	7	1	85.7%	202	16	92.1%
601	26	7	3	57.1%	187	75	59.9%	7	1	85.7%	184	24	87.0%
605	34	7	4	42.9%	194	122	37.1%	7	2	71.4%	190	21	88.9%
607		7	3	57.1%	203	27	86.7%	7	3	57.1%	200	25	87.5%
609	18	7	1	85.7%	194	23	88.1%	7	3	57.1%	193	18	90.7%
626		7	1	85.7%	108	13	88.0%	7	1	85.7%	106	16	84.9%
639		6	1	83.3%	174	38	78.2%	6	0	100.0%	173	19	89.0%
640	15	7	0	100.0%	194	7	96.4%	7	2	71.4%	192	78	59.4%
641	12	7	3	57.1%	176	37	79.0%	7	1	85.7%	176	26	85.2%
642		7	0	100.0%	192	9	95.3%	7	2	71.4%	191	25	86.9%
643		7	0	100.0%	206	39	81.1%	7	0	100.0%	203	32	84.2%
644		7	0	100.0%	198	27	86.4%	7	3	57.1%	196	51	74.0%
645		7	2	71.4%	206	40	80.6%	6	3	50.0%	203	42	79.3%
646	63	7	3	57.1%	195	49	74.9%	7	4	42.9%	193	93	51.8%
647		7	0	100.0%	206	31	85.0%	7	3	57.1%	205	46	77.6%
648		7	2	71.4%	202	52	74.3%	7	2	71.4%	202	33	83.7%
649		7	3	57.1%	207	40	80.7%	7	1	85.7%	204	32	84.3%
650		7	0	100.0%	206	39	81.1%	7	2	71.4%	203	32	84.2%
651		7	0	100.0%	206	16	92.2%	7	3	57.1%	204	42	79.4%
652		7	0	100.0%	207	27	87.0%	7	2	71.4%	203	34	83.3%
653		7	2	71.4%	195	32	83.6%	7	2	71.4%	192	36	81.3%
654		7	2	71.4%	196	38	80.6%	6	0	100.0%	192	16	91.7%
655		7	1	85.7%	204	70	65.7%	7	2	71.4%	202	70	65.3%
656	30	7	0	100.0%	206	45	78.2%	7	4	42.9%	205	25	87.8%
657		7	1	85.7%	195	27	86.2%	7	1	85.7%	194	29	85.1%
658	12	7	0	100.0%	206	34	83.5%	7	1	85.7%	204	31	84.8%
680		8	2	75.0%	201	11	94.5%	8	1	87.5%	200	25	87.5%
681		8	1	87.5%	201	15	92.5%	8	4	50.0%	196	76	61.2%
682		8	0	100.0%	200	5	97.5%	8	2	75.0%	200	35	82.5%
683		8	0	100.0%	183	15	91.8%	8	6	25.0%	182	57	68.7%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684	37	8	3	62.5%	182	30	83.5%	8	2	75.0%	182	40	78.0%
685		8	3	62.5%	197	31	84.3%	8	5	37.5%	194	49	74.7%
686		8	2	75.0%	202	35	82.7%	8	4	50.0%	201	40	80.1%
687		8	2	75.0%	201	32	84.1%	8	3	62.5%	200	34	83.0%
688		8	3	62.5%	200	12	94.0%	8	5	37.5%	199	35	82.4%
689		4	1	75.0%	143	19	86.7%	4	1	75.0%	142	21	85.2%
701		10	2	80.0%	215	23	89.3%	10	1	90.0%	212	21	90.1%
702		10	1	90.0%	282	32	88.7%	9	3	66.7%	279	63	77.4%
703	58	10	7	30.0%	283	84	70.3%	9	7	22.2%	281	77	72.6%
704		10	1	90.0%	214	33	84.6%	9	1	88.9%	208	39	81.3%
710		10	3	70.0%	283	72	74.6%	10	4	60.0%	279	77	72.4%
711		10	2	80.0%	274	30	89.1%	7	1	85.7%	254	46	81.9%
712		10	3	70.0%	280	74	73.6%	9	2	77.8%	271	89	67.2%
714	52	9	7	22.2%	164	65	60.4%	9	7	22.2%	152	65	57.2%
715	47	10	2	80.0%	282	60	78.7%	8	3	62.5%	261	128	51.0%
716		10	4	60.0%	283	111	60.8%	9	3	66.7%	277	105	62.1%
717	41	9	2	77.8%	268	64	76.1%	8	3	62.5%	249	73	70.7%
718		10	6	40.0%	283	142	49.8%	10	8	20.0%	281	99	64.8%
719		10	5	50.0%	283	93	67.1%	9	4	55.6%	268	76	71.6%
757	57	10	1	90.0%	68	4	94.1%	10	1	90.0%	67	5	92.5%
761		10	1	90.0%	279	12	95.7%	10	1	90.0%	276	35	87.3%
765		10	0	100.0%	279	24	91.4%	10	0	100.0%	279	36	87.1%
769		10	0	100.0%	279	25	91.0%	10	1	90.0%	273	50	81.7%
770		10	0	100.0%	279	21	92.5%	10	4	60.0%	277	78	71.8%
774	19	10	0	100.0%	279	16	94.3%	10	4	60.0%	278	60	78.4%
777		10	1	90.0%	164	10	93.9%	10	0	100.0%	163	34	79.1%
782		10	7	30.0%	164	63	61.6%	10	1	90.0%	159	16	89.9%
785		10	1	90.0%	279	18	93.5%	10	1	90.0%	279	47	83.2%
786	24	10	1	90.0%	68	17	75.0%	10	2	80.0%	67	29	56.7%
790		10	0	100.0%	279	26	90.7%	10	2	80.0%	276	34	87.7%
794		10	1	90.0%	279	32	88.5%	10	2	80.0%	276	57	79.3%
821	38	10	0	100.0%	277	6	97.8%	10	5	50.0%	277	108	61.0%
822	12	10	1	90.0%	279	15	94.6%	10	8	20.0%	277	126	54.5%
1233		3	1	66.7%	9	3	66.7%	3	2	33.3%	9	5	44.4%
1246	18	3	3	0.0%	9	8	11.1%	3	3	0.0%	9	4	55.6%
1333	17	10	2	80.0%	279	30	89.2%	10	4	60.0%	276	92	66.7%
1340		10	0	100.0%	278	5	98.2%	10	2	80.0%	278	44	84.2%
2102	20	7	0	100.0%	53	12	77.4%	7	1	85.7%	52	5	90.4%
2103		7	1	85.7%	117	11	90.6%	7	0	100.0%	116	9	92.2%
2104		7	0	100.0%	143	9	93.7%	7	1	85.7%	141	11	92.2%
2107		7	2	71.4%	174	32	81.6%	7	0	100.0%	171	20	88.3%
2108		7	0	100.0%	174	25	85.6%	7	1	85.7%	168	18	89.3%

Amtrak On Time Performance

Trains Arriving Through: 7/10/2026

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2109		7	0	100.0%	67	9	86.6%	7	0	100.0%	66	4	93.9%
2112		7	1	85.7%	14	3	78.6%	6	1	83.3%	12	1	91.7%
2113		7	2	71.4%	53	5	90.6%	7	0	100.0%	53	7	86.8%
2115		7	2	71.4%	53	7	86.8%	7	2	71.4%	52	6	88.5%
2116		7	0	100.0%	14	0	100.0%	7	2	71.4%	14	4	71.4%
2118	47	7	2	71.4%	14	2	85.7%	7	4	42.9%	14	6	57.1%
2119		7	0	100.0%	14	2	85.7%	7	4	42.9%	14	5	64.3%
2120	17	7	3	57.1%	14	6	57.1%	6	3	50.0%	13	6	53.8%
2123		7	1	85.7%	52	7	86.5%	6	1	83.3%	51	14	72.5%
2124		7	5	28.6%	146	28	80.8%	7	5	28.6%	144	18	87.5%
2127		7	2	71.4%	14	3	78.6%	7	2	71.4%	13	2	84.6%
2128		7	1	85.7%	14	1	92.9%	7	1	85.7%	14	1	92.9%
2131		7	4	42.9%	14	4	71.4%	7	1	85.7%	14	1	92.9%
2150	29	7	0	100.0%	167	22	86.8%	7	3	57.1%	164	70	57.3%
2151		7	0	100.0%	116	6	94.8%	7	1	85.7%	114	30	73.7%
2152		6	1	83.3%	74	4	94.6%	6	2	66.7%	73	28	61.6%
2154	28	6	0	100.0%	78	20	74.4%	6	3	50.0%	75	39	48.0%
2155		7	1	85.7%	176	15	91.5%	7	2	71.4%	172	92	46.5%
2158		7	0	100.0%	14	2	85.7%	7	3	57.1%	14	3	78.6%
2159		7	1	85.7%	169	12	92.9%	7	4	42.9%	167	52	68.9%
2160	42	7	0	100.0%	14	0	100.0%	6	5	16.7%	13	9	30.8%
2162	61	7	0	100.0%	175	13	92.6%	7	3	57.1%	169	80	52.7%
2165		6	1	83.3%	13	1	92.3%	6	3	50.0%	13	5	61.5%
2167		6	0	100.0%	165	18	89.1%	6	0	100.0%	165	36	78.2%
2171		7	0	100.0%	103	8	92.2%	7	3	57.1%	100	21	79.0%
2190		6	2	66.7%	174	26	85.1%	6	1	83.3%	172	23	86.6%
2193		6	0	100.0%	171	23	86.5%	6	1	83.3%	169	46	72.8%

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2102	NYP	20	OTH	15	POL	14	NWK-NYP	AM	Right of Way police hold, CONGESTION A/C POLICE HOLD NEWARK STATION DUE TO SUSPECT ON TRACKS	
2118	NYP	47	ENG	44	ENG	44	WIL-WIL	AM	Other electrical failure, 2140 NG NP, CONTACTED ROAD FOREMAN A/C MCB ISSUES; PANTOGRAPHS WOULD NOT STAY RAISED	
2120	NYP	17	SMW	12	SMW	7	BAL-XPV	AM	Diversions around M/W work, Milepost, 90.7, 79.3, opr 1 track a/c 2 track o/s between River & Gunpow	
2150	BOS	29	CTI	18	SMW	7	BAL-XPV	AM	Diversions around M/W work, Control Point, POINT, OPR AROUND NO 2 O/S RIVER TO GUNPOW	
2154	BOS	28	DSR	20	SMW	9	XPV-PHL	AM	Scheduled in track usage program, Control Point, Phl-Baldwin, 2 trk o/s	
2160	BOS	42	CAR	20	CAR	16	PHL-PHL	AM	Door, ENTIRE CONSIST, MET WITH MECHANICAL A/C DOORS NOT CLOSING THROUGHOUT ENTIRE TRAIN	
2162	BOS	61	ENG	28	ENG	28	NYP-NYP	AM	Other electrical failure, 2115 NG NP, DEKAYED AT DEPARTURE A/C EXPIRING PAPERWORK .IT IS NECESSARY TO USE AM2120'S EQUIPMENT TO REPRESENT AM2162	
67	NPN	95	ENG	58	ENG	58	PHL-PHL	AM	Air / Brake, 633 EX ES, MECHANICAL REQUESTED . UNABLE TO RELEASE BRAKS ON THE 2ND ENGINE (E/633)	
85	WAS	16	ADA	15	ADA	8	WIL-WIL	AM	Mobility Impaired, WAITED FOR AN ADA PASSENGER OFF OF AM148	
86	BOS	28	CTI	39	DSR	17	STM-BRP	MN	Per bulletin Milepost, 34.0, 40.0, 30, 1/2	
110	NYP	17	CTI	16	PTI	7	PHL-XHM	AM	Follow, 2150, Control Point, ,	
111	WAS	19	SMW	10	SMW	10	PHL-WIL	AM	Scheduled in track usage program, Control Point, PHL-BALDWIN, Waited for 2150 Northbound a/c 2 trk o/s Phl-Baldwin	
136	NHV	35	DCS	26	DCS	26	XHM-TRE	AM	Power switch failure, Other, MORRIS, HELD AT MORRIS A/C 32 SWITCH FAILING TO NORMAL	
148	NHV	130	MTI	84	ENG	52	NYP-NYP	AM	HEP, 636 EX ES, LOOSE HEP ISSUE IN STATION	
171	RNK	16	PTI	12	SYS	10	CVS-LYH	NS	PTC problem or failure (cause unknown) PTC failure was giving us a yellow fence had to run restricted speed to the favorable target, Milepost, 145.7, 148.0	

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
172	BOS	26	HLD	16	ENG	8	BAL-XPV	AM	Other electrical failure, 646 EX ES, PENALTY AT RIVER. OPERATING 79MPH.	
174	BOS	29	CTI	28	CTI	8	PHL-XHM	AM	Follow, SEPTA, 9735 , Control Point, ,, FOLLOWED 9735 1 TRK TO LEHIGH THEN OPR 2 TRK AROUND.	
176	BOS	68	DBB	23	DBB	23	OSB-OSB	AM	Stuck open bridges, Bridge, Nan, The Nan bridge opr rpts the "Raise/ Low" handle has broke and is unable to get Nan to close, AM176 will hold at OSB due to the bridge issue at Nan	
494	GFD	36	CON	39	CON	39	NHV-NHV	AM	Hold for connecting train, late connection of AM2160	
52	LOR	157	TRS	127	TRS	127	XV7-XRV	CS	Human body found on tracks all train traffic stopped Milepost, 5.0, 3.0	
79	CLT	51	WTR	49	POL	24	NYP-NWK	AM	Right of Way police hold, POLICE HOLD NEWARK STATION A/C SUSPECT ON TRACKS	
601	HAR	26	DCS	28	DCS	23	PAO-PAO	AM	Cab signal or ATS failure (wayside), Control Point, PAO, FRAZER BOARD NOT DISPLAYING PROPERLY. UNABLE TO THROW SWITCHES. SINGLE TRACKING PAOLI TO THORN. 601 HELD FOR 640	
605	HAR	34	SVS	41	SVS	41	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, Late out the yd a/c equipment	
609	HAR	18	SVS	18	SVS	18	PHL-PAO	AM	Unplanned Wye, WY ON THE OUTBOUND	
640	NYP	15	POL	21	POL	21	NWK-NYP	AM	Right of Way police hold, CONGESTION A/C POLICE HOLD NEWARK STATION DUE TO SUSPECT ON TRACKS	
641	HAR	12	POL	14	POL	14	NYP-NWK	AM	Right of Way police hold, POLICE HOLD NEWARK STATION A/C SUSPECT ON TRACKS	
646	NYP	63	CCR	48	CCR	41	PHL-XHM	AM	Electrical failure, NONE, Wye'd on the outbound a/c no cab car.	
656	NYP	30	SVS	22	SVS	22	PHL-XHM	AM	Unplanned Wye, WYE ON THE OUTBOUND	
658	NYP	12	SYS	13	SYS	13	XHM-TRE	AM	Delay in Block, HELD A/C AM138 AHD WITH COMMUNICATION ISSUES WITH CONDUCTOR AND ENGINEER AT TRENTON	
19	NOL	56	FTI	86	FTI	39	HBG-PIC	NS	Meet Stopped and lined switch at Richburg waiting on NS8170 to clear the main..., NS8170/344, Milepost, 90.8, 95.9	

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
684	BON	37	CAR	18	CAR	18	BRK-BRK	CS	Air / Brake / Wheel 82696, Couldn't get air on 90224. Trouble shooting led to a car (82696) that was recently added into consist but was not cut in.
64	NYP	24	CTI	21	POL	20	HUD-HUD	AM	Removal of passenger by police Passenger with infant was removed at Hudson by police for unruly and disruptive behavior. Posed a security risk towards the passengers around him
68	NYP	75	WTR	42	WTR	42	SLQ-RSP	CN	Heat order Milepost, 43, 0
284	NYP	18	CTI	27	CTI	27	POU-CRT	MN	Cross Traffic metro north, 833, Control Point, 46
290	NYP	73	DCS	70	DCS	70	SAR-XSY	DH	Restrictive signal(s) from unknown cause Track light cpc 36-35, Stop, Control Point, 36
1246	NYP	18	CTI	17	CTI	17	POU-CRT	MN	Cross Traffic Single tracking cp61 to 53. Held at 62 then ran behind a MNRR local, MNRR, Control Point, cp61
49	CHI	60	FTI	88	SVS	30	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train
448	BOS	24	FTI	50	FTI	50	XRD-PIT	CS	Meet M427, Control Point, 171
43	PGH	22	WTR	17	FTI	9	TYR-ALT	NS	Meet NS 20H, Control Point, CP-ANTIS
72	RGH	15	TEN	14	TEN	9	SAL-HPT	NS	Loading problem Stopped MP328 issues loading. Isolated and running with only one power unit., NC1810
74	RGH	18	PTI	21	PTI	18	BNC-DNC	NS	Meet Amtk 77, Control Point, Haw River
75	CLT	Trn Cancelled	PTI	12	PTI	12	CYN-DNC	NS	Meet #Am72, Control Point, D&S Jct
76	RGH	Trn Cancelled							
77	CLT	101	TRS	71	TRS	71	BNC-GRO	NS	Trespasser strike Milepost, 20.1, 20.1
78	RGH	42	ITI	33	ITI	33	CLT-CLT	NS	Service, turn, or wye train 77
89	SAV	80	FTI	92	FTI	32	ALX-XDJ	CS	Follow CSX???, Control Point, Beltway
90	NYP	213	DCS	69	DCS	56	NWK-NYP	AM	Power switch failure, Other, XPT-XBH, 62 SWITCH AT ERIE FAILED TO REVERSE
97	MIA	115	WTR	87	SVS	45	NYP-NYP	AM	Planned set out / pick out of locomotives, cars or section of train, DELAYED F/SSYD A/C NECESSARY TO WAIT FOR INBOUND TRAIN 98 TO TURN THE ENTIRE CONSIST AND SERVICE EQUIPMENT

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
98	NYP	71	WTR	52	DMW	36	PAK-JAX	CS	Track Inspector Stopped signals NE Pecan, NE West Toco, Restricted Proceed Durock-Green Cove Springs, Stop signal St John's, following Track Inspector Gano out ahead, Control Point, NE Pecan, Control Point, NE West Toco, Control Point, Durock, Control Point, St John's
40	CHI	161	WTR	119	DCS	32	CLB-CAM	CS	CTC system failure PERMISSION BY STOP SIGNAL, THEN RESTRICTED SPEED TO THE NEXT CLEAR SIGNAL, Milepost, 359.3, 349.4
41	MIA	102	FTI	149	FTI	32	CLE-X86	NS	Meet 29G, Control Point, 107
25	NOL	82	FTI	61	DCS	33	BAS-XNO	NS	CTC system failure Control Point, NOT Junction
26	MOE	44	FTI	40	FTI	20	XNO-BAS	CS	Meet 521, Siding, Nicholson, CSX
5	EMY	53	WTR	128	DBS	34	XBB-XDC	UP	Hold for defect repair Rocks on or near right-of-way, Siding, Range
6	CHI	50	WTR	95	WTR	32	WNN-XW6	UP	Heat order Level 2, Milepost, 535.70, 612
527	SJC	44	TRS	41	TRS	41	OKJ-OKJ	UP	Vehicle on track ahead Milepost, 10.97, 10.97
528	SAC	11	MBO	19	MBO	19	MTZ-SUI	UP	For maritime traffic Control Point, RV033
530	SAC	52	TCR	38	TCR	38	OKJ-OKJ	UP	Wheelchair lift would not stow away after use. Mechanical forces came OKJ to stow the lift. C8016, By doors 3&4. B/O bearings.
535	OKJ	42	MBO	28	MBO	28	SUI-MTZ	UP	For maritime traffic Control Point, Benicia
539	SJC	No OS Rpt							
543	SJC	44	ITI	20	ITI	20	SAC-SAC	UP	Service, turn, or wye train 530
544	SAC	12	MBO	18	MBO	18	MTZ-SUI	UP	For maritime traffic Control Point, Rv033
547	SJC	52	TEN	53	TEN	49	BKY-BKY	UP	HEP C2012, JPBX922
504	SEA	27	FTI	27	FTI	18	ORC-ORC	UP	Hold due to freight derailment Held at ORC due to earlier freight derailment ahead, waited for route to be cleared, unknown, Other, ORC
505	PDX	24	DMW	20	DMW	20	VAN-PDX	BN	Waiting for MW clearance Bridge, columbia river
507	EUG	112	POL	96	POL	96	PDX-PDX	UP	Right of Way police hold Held at Portland, CPS 000 due to reports of trespassers going through standing train (UP 2547) in East Portland. Wait for police to inspect and clear the tracks.

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
508	SEA	57	POL	64	POL	64	ORC-PDX	UP	RR blocked by trespasser or vehicle strike by another train
509	PDX	22	PTI	15	PTI	9	CTL-KEL	BN	Meet Amtrak 14, Control Point, Chehalis Jct.
517	PDX	20	PTI	16	PTI	16	TAC-XNI	ST	Meet amt504, Control Point, Rill
518	VAC	22	DSR	17	DSR	11	XF2-X1J	BN	Per bulletin Time table speed reduction 60>40, Bridge, Fraser, 40, Main
58	CHI	325	DMW	171	DMW	171	FTN-FTN	CC	Waiting for MW clearance Held at Fulton while a partial washout at MP 348.7, Other, FTN
14	SEA	113	PTI	84	HLD	47	CMO-CMO	UP	EMS responding to passenger having mini strokes. Fain, Mary Ann PNR - 880806
8	CHI	204	ITI	155	ITI	155	SEA-SEA	BN	Service, turn, or wye train 7
821	FTW	38	FTI	31	DSR	19	GLE-FTW	BN	Per bulletin Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 396.3, 396.2, 30, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.7, 389, 25, m, Milepost, 385.5, 385.3, 30, m, Milepost, 383.6, 383.4, 60, m, Milepost, 380, 379.5, 60, m, Milepost, 378.3, 377.5, 75, m, Milepost, 374.
822	OKC	12	DSR	22	DSR	16	FTW-GLE	BN	Per bulletin Milepost, 353.8, 354.0, 60, main 2, Milepost, 354.0, 354.1, 70, main 2, Milepost, 355.4, 355.5, 60, main 2, Milepost, 356.5, 356.7, 30, main 2, Milepost, 360.6, 361.1, 30, main 1, Milepost, 364.4, 364.8, 60, main 2, Milepost, 364.5, 364.7, 60, main 2, Milepost, 370.2, 370.9, 30, main, M
335	MKE	13	CTI	10	CTI	8	GLN-XRO	CP	Follow Followed late-running 2117 until it went 1-2 at Lake Forest, Metra, 2117, Milepost, 17.8, 28.7
354	PNT	84	ITI	76	ITI	76	KAL-KAL	MI	355 takes over 354 at BTL, held out at KAL for a late 355 train. 355
364	PTH	103	FTI	87	FTI	60	BTL-LNS	CC	Meet Stop, CN eng 8908, Control Point, Walton
365	CHI	24	DSR	43	DSR	24	LNS-BTL	CC	Per bulletin Milepost, 223.53, 223.53, 25, 2, Milepost, 221.42, 221.42, 30, main, Milepost, 219.15, 218.5, 25, main, Control Point, Mill, 25, main-1, Milepost, 214.93, 214.93, 25, 1, Milepost, 202.45, 195.32, 25, main-2, Milepost, 195.32, 193.3, 30, 1, Milepost, 191.62, 191.45, 10, 1

Amtrak Endpoint OTP Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
584	SAN	33	CTI	35	ENG	13	LAX-LAX	SC	Air / Brake Independent actuating feature was not functioning at all and independent brake cylinder pressure was only building to 50-60 psi fully applied. LAX mechanical had to evaluate and put train into emergency twice to resolve issue., 140
757	SLO	57	HLD	47	HLD	47	LAX-LAX	SC	Up trespasser strike
774	SAN	19	PTI	30	PTI	10	X98-OSD	SN	Meet 579, Control Point, Eastbrook
786	SAN	24	PTI	58	PTI	33	GUA-LPS	UP	Meet 14, Siding, ellwood
703	SAC	58	CON	47	CON	47	BFD-BFD	BN	Hold for thruway bus
714	BFD	52	PTI	41	PTI	16	MDR-FNO	BN	Meet 717, Siding, Gregg
715	OKJ	47	PTI	39	PTI	15	WAC-COC	BN	Meet 702, Milepost, 942, 942
717	OKJ	41	SVS	37	SVS	37	BFD-BFD	BN	Unplanned Wye
3	LAX	63	FTI	180	FTI	30	FLG-KNG	BN	Meet BNSF 6694, Control Point, BNSF 6694
4	CHI	145	FTI	117	FTI	32	KNG-FLG	BN	Follow BNSF 6403, Milepost, 402, 344
1	LAX	134	FTI	245	FTI	68	XZS-YUM	UP	Cross over or go around PER DISPATCHER 244 HEAVY RAIL CONGESTION IN THE AREA, UP FRIEGHT WEST, Milepost, 753, 732
21	SAS	36	FTI	244	FTI	60	LRK-MVN	UP	Meet UP 7084, Control Point, saline
22	CHI	303	DTR	353	DTR	284	XGA-STL	TR	Flood / washout XGA, STL
391	CDL	186	TRS	177	TRS	177	DQN-CDL	CC	Trespasser strike Trespasser fatality crossing 304.5, Other, 304.5
392	CHI	120	ITI	63	ITI	63	CDL-CDL	CC	Trespasser strike 391
393	CDL	87	WTR	91	WTR	91	DQN-CDL	CC	Trees down Cleaning crew and maintenance clearing up trees down south of mp290.3, Control Point, Schafer Jct
318	CHI	19	CON	36	CON	36	STL-STL	TR	Holding for buses arriving from KCY-KWD due to derailment on West Side
1333	MSP	17	MBO	19	MBO	19	LSE-WIN	CP	For maritime traffic Other, bridge switch

Amtrak Initial Terminal Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/10/2026

Terminal	Train	Date	Late	Delay	Cause
BON	681	07/10	4	4	Cross Traffic Keolis, Other, BON
BON	685	07/10	1		
BRK	684	07/10	18	18	Air / Brake / Wheel 82696, Couldn't get air on 90224. Trouble shooting led to a car (82696) that was recently added into consist but was not cut in.
CLT	76	07/10	(Trn Cxld)		Debris Strike
CLT	78	07/10	33	33	Service, turn, or wye train 77
CLT	80	07/10	1		
HAR	624	07/10	3	3	Copy authority / restriction, COPYING FORM D/MAKING SURE THEY HAVE ALL THEIR PAPERWORK
HAR	626	07/10	1		
HAR	646	07/10	2	2	Service, turn, or wye train, 605
LOR	53	07/10	71	71	Service, turn, or wye train 52
NHV	494	07/10	40	39	Hold for connecting train, late connection of AM2160
NYP	63	07/10	5	5	RTU Failure, Other, NYP, "A" TOWER CONSOLE FROZE
NYP	97	07/10	142	142	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C LACK OF AVAILABLE EQUIPMENT IT IS NECESSARY TO WAIT FOR INBOUND TRAIN AM98 TO ADD 4 COACHES AND SERVICE EQUIPMENT
NYP	245	07/10	44	44	Service, turn, or wye train, 68, LATE TURN OFF AM68
NYP	283	07/10	27	27	Routine inspections, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	641	07/10	3	3	RTU Failure, Other, NYP, "A" TOWER CONSOLE FROZE
NYP	653	07/10	2	2	Passenger and/or baggage, BOARDING
NYP	2115	07/10	5	5	Passenger and/or baggage, LOADING
NYP	2131	07/10	2	2	Passenger and/or baggage, BOARDING
PHL	601	07/10	1		
PHL	605	07/10	41	41	Planned set out / pick out of locomotives, cars or section of train, Late out the yd a/c equipment
PIT	1246	07/10	11	11	Switch ends for return to Albany
WAS	84	07/10	2	2	Electrical failure, ,, BLUE FLAG STILL UP AT DEPARTURE TIME.
CDL	392	07/10	63	63	Trespasser strike 391
CHI	307	07/10	6	6	Loading problem Engine was about to be swapped with IDTX 4621 . They decided not to so we still have the IDTX4608, ID4608
PNT	351	07/10	3	3	Fuel They came to fuel. Not aware of departure time.

Amtrak Initial Terminal Details

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/10/2026

Terminal	Train	Date	Late	Delay	Cause
QCY	380	07/10	1	1	Mobility Impaired Passenger required lift, nothing in the reservation stating mobility impaired or lift required, PNR 839D28.
STL	300	07/10	2	2	Wheelchair PNR 572684 pax own power chair came down last.
STL	318	07/10	100	36	Holding for buses arriving from KCY-KWD due to derailment on West Side
BFD	703	07/10	47	47	Hold for thruway bus
BFD	717	07/10	37	37	Unplanned Wye
EMY	6	07/10	1		
GTA	782	07/10	11	11	Meet 14, Control Point, CO 358
LAX	584	07/10	13	13	Air / Brake Independent actuating feature was not functioning at all and independent brake cylinder pressure was only building to 50-60 psi fully applied. LAX mechanical had to evaluate and put train into emergency twice to resolve issue., 140
LAX	588	07/10	1		
LAX	757	07/10	47	47	Up trespasser strike
OKJ	714	07/10	5	5	Disabled Capitol 530 developed a mechanical issue during station stop. Wheelchair lift would not stow. Waited for signal on track 2 to time out, 530, Control Point, North Jack London
PDX	28	07/10	35	35	Hold for connecting train Hold for 30+ connections off 14, 14
SAC	543	07/10	29	20	Service, turn, or wye train 530
SAC	543	07/10	29	9	Unticketed or fare evading passenger Amtrak PD removed known fare evader, Other, Sacramento
SAC	551	07/10	1	1	Door C8019
SAN	595	07/10	7	7	PTC- IETMS recycle breaker to clear fault 6900, PTC was timing out when trying to initialize. Called CNOC PTC desk and was instructed to power cycle PTC Data Radio breaker.
SEA	8	07/10	85	85	Service, turn, or wye train 7, Un able to wye train do to freight interference.
SJC	530	07/10	17	17	Service, turn, or wye train 527, Late arrival on 527.

Eastern Region

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	82.8	75.1	90.2	58	10
SEPTA	95.0	96.6	95.0	91.5	206	7
NJT-NED	95.0	No Data	No Data	88.6	No Data	No Data
NJT-SED	95.0	95.5	95.1	97.2	22	1

Operating Highlights

Train 41(09) South of Petersburg, VA - High Wind Warnings

11JUL26: Train 41(09) with engines 50, 14, 10 cars, and 201 customers onboard was delayed beginning at milepost 56.0, 34 miles south of Petersburg, VA on the CSX North End subdivision due to operating at a reduced speed through high wind warnings from milepost 56.0 to milepost 119.5.

Train	Delay	Comment
41(09)	52"	

Train 98(10) North of Florence, SC - Freight Train Interference

11JUL26: Train 98(10) with engines 307, 328, 10 cars, and 250 customers onboard was delayed at milepost 282.8, 10 miles north of Florence, SC on the CSX South End subdivision due to meeting CSX freight train IO31. The train also met train 53(10). Train 98(10) advanced to milepost 267.3 where it met CSX freight train IO38. Once the freight traffic was cleared, train 98(10) advanced to the next station.

Train	Delay	Comment
98(10)	25"	IO31
98(10)	20"	IO38
98(10)	13"	53(10)

NYP Line Erie Switch Failure - Power Switch Failure

11JUL26: At 12:51 AM-ET, it was reported that the number 62 switch at Erie Interlocking failed to reverse. Maintainers were notified and responded to the switch. Scheduled track work had created a single-track condition through the area. Train 198(10) with 305 customers onboard was held at milepost 4.8. Train 179(10) with 251 customers onboard was held at milepost 3.4. Train 90(10) with 83 customers onboard was held at milepost 8.5. Once the switch was able to be locked in reverse, traffic was able to resume.

Train	Delay	Comment
198(10)	1'52"	
179(10)	1'00"	
90(10)	56"	

Train 89(10) Charleston, SC - Passenger Train Interference

11JUL26: Train 89(10) with engine 30000008304, 7 UNCLASSIFIED 46 7/15/2026 customers onboard was delayed at Charleston, SC on the CSX Charleston subdivision due to meeting train 52(10). Once the passenger train cleared, train 89(10) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
89(10)	42"	

Train 245(10) New York, NY - Initial Terminal Delay

11JUL26: Train 245(10) with engine 710, 5 cars, engine 103, and 70 customers was delayed departing New York, NY on the Amtrak New York Terminal Line due to late turn of equipment from train 68(10). Once the train arrived in the station and was boarded, train 245(10) departed the station at 12:09 AM-ET.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
245(10)	44"	

Train 53(10) Rocky Mount, NC - Freight Train Interference

10JUL26: Train 53(10) with engines 322, 317, 511, 37 cars, and 449 customers onboard was delayed beginning at milepost 91.3, 28 miles north of Rocky Mount, NC on the CSX North End subdivision due to following CSX freight train 1031 from milepost 91.3 to milepost 135.0. Once the freight train cleared, train 53(10) was able to advance.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(10)	40"	

New Haven to Boston Line - Drawbridge Opening

10JUL26: At 9:28 PM-ET, it was reported that the raise/lower handle was broken on the Nan Drawbridge at milepost 116.7, 6 miles south of New London, CT on the Amtrak New Haven to Boston Line. Train 179(10) with 383 customers onboard were held at milepost 116.9. Train 176(10) with 485 customers onboard and train 178(10) with 308 customers onboard were held at Old Saybrooke, CT. At 10:32 PM-ET, it was reported that the bridge was closed and locked. All traffic resumed through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
176(10)	24"	
178(10)	13"	
179(10)	1'08"	

Train 148(10) New York, NY - Engine Failure

10JUL26: Train 148(10) with engine 636, 8 cars, and 221 customers onboard was delayed departing New York, NY on the Amtrak New York Terminal Line due to the train losing head end power while in the station. Mechanical responded to the train and was able to rectify the issue. There were loose head end power cables on the front of the engine. Once head end power was restored, train 148(10) departed the station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
148(10)	52"	

CN Heat Orders - Weather

10JUL26: CN imposed 25-FOL-00590 between Point Stuyvesant, NY and St. Lambert, QC which created delays for trains 68 and 69.

Train	Delay	Comment
68(10)	42"	
69(10)	50"	

Train 494(10) New Haven, CT - Hold for Connection

10JUL26: Train 494(10) with engine 90, 1 car, cab car 9647, and 68 customers onboard was delayed departing New Haven, CT on the Metro North New Haven Line due to waiting on connections from late train 2160(10).

Train	Delay	Comment
494(10)	39"	

Train 68(10) South of Saratoga Springs, NY - Power Switch Failure

10JUL26: Train 68(10) with engine 103, 5 cars, and 118 customers onboard was delayed at milepost 36.7, 1 mile south of Saratoga Springs, NY on the Canadian Pacific Canadian subdivision due to a power switch failure at control point 36. Once the route was lined correctly, train 68(10) was able to advance to the next station.

Train	Delay	Comment
68(10)	33"	

Train 448(09) West of Pittsfield, MA - Freight Train Interference

10JUL26: Train 448(09) with engines 96, 127, 4 cars, and 106 customers onboard was delayed at milepost 171.8, 21 miles west of Pittsfield, MA on the CSX Berkshire subdivision due to meeting CSX freight train M427. Once the freight train cleared, train 448(09) advanced to the next station.

Train	Delay	Comment
448(09)	50"	

Train 77(10) South of Burlington, NC - Trespasser Strike

10JUL26: Train 77(10) with engine NC1810, 5 CARS, NC1984, and 153 customers onboard went into emergency at milepost 20.9, 1 mile south of Burlington, NC on the NS Danville District due to striking a trespasser. The strike was non-fatal and did not occur at a crossing. The train maintained head end power and remained intact on the rails. There were no injuries to the crew or customers reported. There was no damage to the equipment. Local authorities arrived at the scene and completed their investigation. The train was released by the authorities and then NS released the train as well. The train was on the move at 6:00 PM-ET.

National Response Center Number: 1467519

Train	Delay	Comment
77(10)	1'11"	
78(10)	33"	Late turn of equipment

Train 2118(10) Wilmington, DE - Engine Failure

10JUL26: Train 2118 (26-FOI-00590-00000008301 2140 UNCLASSIFIED 15 07/15/2026) was delayed at Wilmington, DE on the Amtrak PW Line due to the MCB opening and the pantographs would not stay raised. the crew contacted the road foreman and mechanical to troubleshoot the issue. The issue was able to be rectified. Train 2118(10) was able to advance to the next station at 5:39 PM-ET.

Train	Delay	Comment
2118(10)	44"	
148(10)	1'10"	

Train 75(10) West of Kannapolis, NC - Tree Strike

10JUL26: Train 75(10) operating with locomotive NC1755, 4 cars and 129 customers onboard was delayed 9 miles west of Kannapolis at MP 358 on the NS Montview-Salisbury subdivision after striking a tree causing a loss of HEP from locomotive NC1755. There were no reported injuries to the crew or customers. The weather was 86 degrees. The train was terminated at 358.3. The train was able to shove back to Kannapolis under its own power with no head end power. Buses were secured to transport the customers to Charlotte. There was one unaccompanied minor onboard that was met at Kannapolis by the parents.

Train 76(10) was cancelled in its entirety with alternate transportation secured. The buses that had been used for train 75(10) were utilized to transport the customers between Charlotte and Raleigh.

The equipment from train 75(10) was deadheaded back to Raleigh.

WBS#: B.TR.100150.6882

Train	Delay	Comment
75(10)	Term KAN	
76(10)	Cancelled	

Train 290(10) Saratoga Springs, NY - Signal

10JUL26: Train 290(10) operating with locomotive 705, 5 cars and 146 customers was delayed at Saratoga Station due to signal issues at CPC 36 requiring a CPKC signal maintainer to respond and repair. After the maintainer arrived on scene, they were able to restore the signal system and clear the track occupancy light allowing train 290(10) to proceed on signal indication.

Train	Delay	Comment
290(10)	1'10"	

Train 97(10) New York, NY - Initial terminal Delay - Car Failure

10JUL26: Train 97(10) operating with locomotive 614, 10 cars and 165 customers was delayed at the initial terminal of New York due to needing cars off inbound train 98(09) to fulfill the consist as a result of the lack of available fleet assets to meet service requirements. Train 97(10) has a scheduled departure time from New York at 2:30 pm-et. Train 98(09) arrived New York at 12:01 pm-et operating 1'11" late and arrived the yard at 1:00 pm-et to begin servicing and inspection. Upon inspection, car 25121 was found to have defective wheels requiring the car to be replaced with an Amfleet II coach to meet capacity needs. After the train was properly made up, inspections were completed and mechanical documentations were finalized train 97(10) was positioned in the station. At the station 165 customers were boarded and train 97(10) departed New York.

Train 41(09) North of Connellsville, PA - Freight Train Interference

10JUL26: Train 41(09) operating with locomotives 501-502, 10 cars and 159 customers onboard was delayed 2 miles north of Connellsville at MP 272 on the CSX Pittsburg subdivision holding for freight train interference. Train 41(09) was held at Broadford interlocking waiting for CSX I135-09 to pass. After CSX I135-09 passed an open route was established and train 41(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(09)	45"	

Train 53(09) North of Sanford, FL - Emergency Brake Application

10JUL26: Train 53(09) operating with locomotives 364-380, 16 passenger cars, 23 auto carriers and 451 customers onboard was delayed 10 miles north of Sanford at MP 756 on the CFRC Orlando subdivision due to the Engineer placing the train into an emergency brake application resulting from aggressive braking. Once stopped the Conductor and Assistant Conductor walked the train to inspect taking no objections. A Class II brake test was performed and train 53(09) was able to resume without further delays.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
53(09)	41"	

Train 52(09) South of Petersburg, VA - Engine Failure

10JUL26: Train 52(09) operating with locomotives 317-322, 16 passenger cars, 21 auto carriers and 411 customers onboard was delayed 30 miles south of Petersburg at MP 54.9 on the CSX North End subdivision due to locomotive failure of unit 317. The crew reported the engine stopped loading and lost the ability to produce tractive effort. With the assistance of CNOC Mechanical the crew was able to isolate the locomotive and have locomotive 322 provide all tractive effort. After isolating locomotive 317 train 52(09) was able to resume operations and proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(09)	35"	

Train 52(09) North of Petersburg, VA - Police Related

10JUL26: Train 52(09) operating with locomotives 317-322, 16 passenger cars, 21 auto carriers and 411 customers onboard was delayed 15 miles north of Petersburg on the CSX North End subdivision for a police hold on all tracks. CSX notified Amtrak that a deceased individual was found on the No.1 track at MP 3.1 on the CSX North End subdivision resulting in local authorities and CSX holding all traffic for an investigation. CSX Police responded and worked with Richmond Police to conduct the investigation and reported the deceased individual was likely a trespasser who fell from CSX I135-10 which operated last through the location. A route was established to allow train 52(09) to cross over and pass the location at walking speed while the investigation was continuing. After passing the scene train 52(09) was able to continue without further delay.

Service recovery was initiated for the impacted customers by extending breakfast service for both Coach Customers and First-Class Customers.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
52(09)	2'07"	
53(10)	1'11"	Late turn of equipment

Train 605(10) Philadelphia, PA - Initial Terminal Delay - Cab Car Failure

10JUL26: Train 605(10) ~~26-FOI-00590100000008301~~ ^{UNCLASSIFIED} ~~7/15/2026~~ left the initial terminal of Philadelphia due to cab car 9646 shopping out during inspection and being replaced with an all-table car to provide Wi-Fi for the customers. Train 605(10) operated without a cab car or 2nd motor requiring the train to be wye'd at all locations. After the equipment was released by mechanical the train was positioned in the station for customer boarding and was able to depart Philadelphia.

The equipment from 605(10) turned for 646(10) in Harrisburg and required the wye'ing of the set for the subsequent turns for the remainder of the day.

Train	Delay	Comment
605(10)	41"	
646(10)	41"	PHL

Maintenance of Way Highlights

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	

Amtrak/MRS Main Line Trackwork - Scheduled M/W Work July 11-13TH

18MAY26: Due to Amtrak/MRS Main Line trackwork for Windsor Locks Station Improvements from Friday May 29th at 11P-ET until Monday June 1st at 6A-ET effecting trains operating between Washington, DC and St Albans, VT the following service adjustments have been made:

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line, Valley Flyer, Northeast Regional, and Vermonter Services will be adjusted as follows:

SOUTH:

Hartford Line

- Train 405 (30May, 31May, 11JUL, 12JUL), which normally operates between SPG and NHV, will be replaced in entirety by bus.
- Train 463 (30May, 11JUL), which normally operates between SPG and NHV, will be replaced in entirety by bus.

replaced in entirety by bus.

- Train 465 (31May, 11JUL), which normally operates between SPG and NHV, will be replaced in entirety by bus.

- Train 497 (31May, 11JUL), which normally operates between SPG and NHV, will be replaced in entirety by bus.

Valley Flyer

- Train 461 (30May, 31May, 11JUL, 12JUL), which normally operates between GFD and NHV, will terminate at SPG.

Northeast Regional

- Train 143 (30May, 31May, 11JUL, 12JUL), which normally operates between SPG and WAS, will originate at NHV.

- Train 147 (30May, 11JUL), which normally operates between SPG and RNK, will originate at NHV.

- Train 157 (31May, 12JUL), which normally operates between SPG and WAS, will originate at NHV.

- Train 141 (1Jun, 13JUL), which normally operates between SPG and WAS, will originate at NHV.

- Train 125 (1Jun, 13JUL), which normally operates between SPG and NPN, will originate at NHV.

Vermonter

- Train 57 (30May, 31May, 11JUL, 12JUL), which normally operates between SAB and WAS, will originate at NHV.

NORTH

Hartford Line

- Train 450 (30May, 31May, 11JUL, 12JUL), which normally operates between NHV and SPG, will be replaced in entirety by bus

- Train 460 (30May, 31May, 11JUL, 12JUL), which normally operates between NHV and SPG, will be replaced in entirety by bus

- Train 464 (30May, 31May, 11JUL, 12JUL), which normally operates between NHV and SPG, will be replaced in entirety by bus

- Train 416 (31May, 12JUL), which normally operates between NHV and SPG, will be replaced in entirety by bus

Valley Flyer

- Train 488 (30May, 31May, 11JUL, 12JUL), which normally operates between NHV and GFD, will originate at SPG.

Northeast Regional

- Train 136 (29May, 10JUL), which normally operates between WAS and SPG, will terminate at NHV.

- Train 148 (29May, 10JUL), which normally operates between WAS and SPG, will terminate at NHV.

- Train 140 (30May, 31May, 11JUL, 12JUL), which normally operates between WAS and SPG, will terminate at NHV.

- Train 146 (30May, 31May, 11JUL, 12JUL), which normally operates between WAS and SPG, will terminate at NHV.

Vermonter

- Train 54 (30May, 31May, 11JUL, 12JUL), which normally operates between WAS and SAB, will terminate at NHV.

ALTERNATE TRANSPORTATION

Hartford Line

- Buses 3405, 3463, 3467, 3409, 3465, and 3497 will provide alternate transportation between SPG and NHV

- Buses 3150, 3460, 3464, and 3416 will provide alternate transportation between NHV and SPG

Valley Flyer

- Bus 3461 will provide alternate transportation between SPG and NHV

between SPG and NHV

- Buses 3136, 3148, 3140, and 3146 will provide alternate transportation between NHV and SPG

Vermont

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

- Bus 3057 will provide alternate transportation between SAB and NHV for all stops except RPH, WNM, CLA, HLK, and MDN.
- Bus 3054 will provide alternate transportation between NHV and SAB for all stops except MDN, HLK, CLA, WNM, and RPH.

WBS#: B.TR.100151.0823

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)

Friday, July 3 (Independence Day)

Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops.
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train 4(10) West of Needles, CA - Freight Train Interference

11JUL26: Train 4(10) was delayed at E. Danby/MP634.8 on the BNSF Needles Subdivision, 56.8 miles west of Needles, CA station, due to a meet and follow with BNSF freights BN6836 and BN5956.

Train	Delay	Comment
4(10)	58"	

Train 7/27(09) West of Whitefish, MT - Freight Train Interference

11JUL26: Train 7/27(09) was delayed beginning 6 miles west of Whitefish, MT on the BNSF Kootenai River Subdivision between MP1225 and MP1306, due to following BNSF 6253.

Train	Delay	Comment
7/27(09)	40"	

Train 5(10) East of Omaha, NE - Freight Train Interference

11JUL26: Train 5(10) was delayed at MP8.3, 20.2 miles east of Omaha, NE station on the BNSF Creston subdivision meeting BNSF Freight train 6557. Train 5(10) was back on the move at 108AM CT after BNSF freight 6557 cleared to the east.

Train	Delay	Comment
5(10)	1'15"	

Train 393(10) North of Carbondale, IL - Weather

11JUL26: Train 393(10) was delayed holding at MP290.4, 18.74 miles north of Carbondale IL station on the CN Centralia subdivision due to trees down on the tracks ahead. Maintainers were on scene when train 393(10) arrived to Schafer Junction. Train 393(10) was back on the move at 1037PM CT after the maintainers removed all the trees from the tracks.

Train	Delay	Comment
393(10)	1'31"	

Train 5(10) West of Osceola, IA - Engine Failure

11JUL26: Train 5(10) E/45, E/135, 8 cars, with 221 customers onboard, was delayed at MP317.5, 45.53 miles west of Osceola, IA station on the BNSF Ottumwa subdivision due to engine 45 shutting down and losing HEP with overspeed faults. Crew worked with CNOC to isolate the engine and switch HEP to engine 135. Train 5(10) was back on the move at 845PM CT with engine 45 shut down and isolated. Train 5(10) arrived to Osceola, IA and was able to reset the breaker on engine 45 to get the engine loading again with overspeed cutout.

Train	Delay	Comment
5(10)	41"	
5(10)	15"	OSC reset breaker

Train 21(10) St. Louis, MO - Weather

11JUL26: Train 21(10) was delayed beginning at MP1.6, 7.15 miles south of St. Louis, MO station on the TRRA Merchants subdivision due to high wind warnings on the Macarthur Bridge. The high wind warnings expired at 939PM CT and train 21(10) was back on the move at 941PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(10)	1'18"	

Train 21(09) North of San Antonio, TX - Freight Train Interference

10JUL26: Train 21(09) was stopped at MP237.6, 24.23 miles north of San Antonio TX station on the UPRR Austin subdivision due to UPRR Freight train 2761 stopped ahead with air issues. Freight crew walked the consist and found a separated air house. Train 21(09) was back on the move at 1022PM CT after the freight re-attached the air hose and cleared a route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	39"	

Train 8/28(09) East of Wolf Point, MT - Freight Train Interference

11JUL26: Train 8/28(09) was delayed west of Wolf Point, MT at Nashua/MP278.2 and Glasgow /MP278.2 on the BNSF Glasgow Subdivision, due to meeting two BNSF freights (7985/ 7378) Train 8/28(09) was further delayed east of Wolf Point, MT station, at Poplar/MP205.3, Blair/ MP180.5 and Bainville/MP160.7 meeting multiple BNSF freights (7252/ 7703/ 6708/ 3927).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(09)	26"	W/WPT
8/28(09)	52"	E/WPT

Train 25(10) North of New Orleans, LA - Signal

10JUL26: Train 25(10) was delayed beginning at MP7.2, 8.05 miles north of New Orleans, LA station on the Norfolk Southern New Orleans Terminal subdivision due to CTC system failure at NOT Junction. Train 25(10) proceeded through NOT Junction at restricted speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
25(10)	33"	

Train 22(10) South of Texarkana, AR - Freight Train Interference

10JUL26: Train 22(10) was delayed beginning at MP60, 52.06 miles south of Texarkana, AR station on the UPRR Little rock subdivision following UP freight 5761 until MP10.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(10)	31"	

Train 364(10) West of East Lansing, MI - Temporary Speed Restrictions

10JUL26: Train 364(10) was delayed beginning at MP177.1, 46.84 miles west of East Lansing MI station on the CN Flint subdivision operating through temporary speed restrictions until MP223.5.

Train 364(10) West of East Lansing, MI - Freight Train Interference

10JUL26: Train 364(10) was delayed beginning at MP97.0, 71.8685 miles west of East Lansing MI. station on the CN Flint subdivision meeting CN Freight train 8908. Train 364(10) was back on the move at 952PM ET once the freight cleared to the west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(10)	1'00"	

Train 19(09) North of Picayune, MS - Freight Train Interference

10JUL26: Train 19(09) was delayed beginning at MP90.8, 58.8 miles north of Picayune, MS station on the Norfolk Southern NO and NE subdivision following Norfolk Southern freight 8170. Freight train 8170 had to stop and line the switch at Richburg/MP94.5. Once freight 8170 cleared the switch train 19(09) was able to get around and resumed operating at track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(09)	39"	

Train 508(10) North of Eugene, OR - Freight Train Interference

10JUL26: Train 508(10) was delayed 12 miles north of Eugene, OR between Swain/MP659.1 and Hallawell/MP688.8 on the UPRR Brooklyn Subdivision, due to following freight unit UP5990. Once route was clear, Train 508(10) was able to resume track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
508(10)	31"	

Train 14(09) Portland, OR - Passenger Train Interference

10JUL26: Train 14(09) was delayed at Portland, OR due to meeting Trains 507(10) and 506(10). Once 506(10) was clear, Train 14(09) departed behind them.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(09)	37"	

Train 28(10) Portland, OR - Hold for Connection

10JUL26: Train 28(10) was delayed departing Portland, OR/MP0.0 on the BNSF Fallbridge Subdivision, due to holding for connections from Train 14(09), that arrived 5:09PM-PT, 1 hour and 29 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
28(10)	35"	

Train 703(10) Bakersfield, CA - Hold for Connection

10JUL26: Train 703(10) was delayed departing Bakersfield, CA/ MP886.9 on the BNSF Bakersfield Subdivision, due to holding for 40 passenger connections off delayed bus 5703. This bus was delayed arriving account of being held in traffic for a highway accident.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(10)	47"	

Train 58(10) South of Brookhaven, MS - Freight Train Interference

10JUL26: Train 58(10) 28-FCI-00390 delay 00000008301 MP80.6 UNCLASSIFIED 7/15/2026 south of Brookhaven MS station on the CN McComb subdivision meeting freight train CN2978. Train 58(10) was back on the move at 610PM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(10)	31"	

Train 547(10) Berkeley, CA - Third Party Contractor Engine Failure

10JUL26: Train 547(10) E/C2012, E/JPX922, 5 cars, with 145 customers onboard, was delayed at Berkeley, CA. The crew reported that the engine shutdown while arriving into the station, showing a coolant pressure alarm. The train did have head-end power (HEP) during this event. The crew worked with TASO mechanical in order to troubleshoot, attempting to recycle the engine but unable to resolve. A TASI technician was dispatched to the scene to further troubleshoot. Once issue was resolved, Train 547(10) departed Berkeley operating 55 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
547(10)	49"	

Train 507(10) Portland, OR - Police Related

10JUL26: Train 507(10) was delayed at Portland, OR, due to a police hold on the tracks due to reported trespassers on the rails ahead. Once the hold was released, Train 507(10) was able to proceed. Train 508(10) was also delayed due to this, holding at MP766.4 on the UPRR Brooklyn Subdivision until 507(10) cleared.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
507(10)	1'36"	
508(10)	1'04"	Held MP766.4

Train 11(10) South of Eugene, OR - M of W Work

10JUL26: At approximately 6:00PM-PT Union Pacific reported a partial tunnel collapse at Cruzatte/MP545.4, with a 4 hour estimate given to make necessary repairs. Train 11(10) already departed Eugene, OR and it was decided to hold them at Oakridge /MP 581.6 on the Union Pacific Brooklyn Subdivision, 43 miles south of the Eugene, OR station. This location allowed the 202 passengers onboard an opportunity to step off the train and stretch during the anticipated lengthy delay. As the repairs being made were closer to completion, Train 11(10) was advanced to MP556.4 for open track. At 10:33PM-PT all necessary repairs were made, and inspected and then Train 11(10) proceeded south to Chemult.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(10)	3'03"	

Train 6(10) East of Colfax, CA - Passenger Train Interference

10JUL26: Train 6(10) with 221 customers was delayed at Switch 9/MP171.3 on the UPRR Roseville Subdivision, 29.4 miles east of Colfax, CA meeting Train 5(09).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(10)	32"	

Train 8(10) Seattle, WA - Initial Terminal Delay/ Freight Train Interference

10JUL26: Train 8(10) was delayed departing Martin, WA to the wye into the station being blocked by a freight train. Once the route was clear and wye became available, the train completed the wye and proceeded to the station to load 115 customers.

Train	Delay	Comment
8(10)	1'25"	

Train 25(10) Pascagoula, MS - Freight Train Interference

10JUL26: Train 25(10) was delayed beginning at MP685.6, 21.43 miles north of Pascagoula, MS station on the CSX NO and M subdivision meeting freight trains M60610 and W082.

Train	Delay	Comment
25(10)	30"	

Train 786(10) Lompoc-Surf, CA - Passenger Train Interference

10JUL26: Train 786(10) was delayed at Tangair siding/MP293.6 5.5 miles south of Lompoc-Surf, CA/MP299.2 on the UP Santa Barbara subdivision meeting Amtrak train 14(10). Once the route was clear, train 786(10) continued south.

Train	Delay	Comment
786(10)	33"	

Train 702(10) East of Sacramento, CA - Third Party Contractor Cab Car Failure

10JUL26: Train 702(10), E/C2006-7 cars-CC/C6961, was delayed at East Sacramento/MP 89.2, a half mile East of Sacramento, CA, on the UPRR Martinez Subdivision due to PTC issues on Cab Car 6961. The equipment needed to be wye'd due to the ongoing PTC issues. Once equipment was wye'd, Train 702(10) proceeded east.

Train 717(10) was delayed departing Bakersfield, CA due to the ongoing PTC issues from CC/C6961. Once equipment arrived into Bakersfield, the crew worked to wye equipment. After equipment was wye'd and customers were boarded, Train 717(10) departed.

Train	Delay	Comment
702(10)	14"	
717(10)	37"	Turn of equipment BFD

Train 3(10) West of Naperville, IL - Freight Train Interference

10JUL26: Train 3(10) was delayed 11.7 miles west of Naperville, IL (MP28.5), on the BNSF Chicago Subdivision, at Montgomery (MP40.2), while meeting eastbound BNSF Train 8524. The freight train was prioritized through the area due to hours-of-service concerns. During this time, Train 5(10) was also delayed while holding at MP37.9. Once the eastbound freight cleared the area, Trains 3(10) and 5(10) were released to continue west.

Train	Delay	Comment
3(10)	48"	
5(10)	25"	

Train 22(10) Fort Worth, TX - Car Failure

10JUL26: Train 22(10) 26-FBI-00590 E/ID4613-8 Cars, UNCLASSIFIED, delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, due to toilet issues in coach car 34047. Mechanical personnel responded and were able to dump the holding tank, resolving the issue. Once repairs were completed, Train 22(10) continued east.

Train	Delay	Comment
22(10)	47"	

Train 391(10) North of Carbondale, IL - Trespasser Incident

10JUL26: At 1:50PM-CT, Train 391(10), E/ID4613-7 Cars, struck a trespasser 3.7 miles north of Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision, at MP304.65. The strike occurred at a private road crossing (DOT#295087H) equipped with only an ENS sign in Carbondale, IL, located in Jackson County. There were no injuries reported to the crew or the 47 customers onboard, and there was no damage to the equipment. Head End Power remained on for the duration of the investigation.

The Conductor walked the train and found the trespasser deceased. Amtrak's Carbondale Road Foreman responded to the scene along with CN personnel, police, EMS, fire personnel, and the coroner. The strike occurred on a single main track, which was closed for the duration of the investigation. Train 391(10) was operating at 78MPH at the time of the incident, with a maximum timetable speed of 79MPH through the crossing. The weather was 84.2 degrees and partly sunny. The crew did request relief. The Road Foreman transported the outbound crew for Train 392(10) to the location to provide relief for the crew of Train 391(10). Once the investigation concluded, Train 391(10) was released to proceed south at 443PM CT. Train 392(10) departed Carbondale IL station at 518PM CT 1'03" late due to late turn off train 391(10). Train 392(10) needed to be wye'd after departing Carbondale.

National Response Center Number: 1467503

Train	Delay	Comment
391(10)	2'57"	
392(10)	1'03"	Late Turn
392(10)	39"	Wye

Train 530(10) Oakland, CA - Third Party Contractor Car Failure

10JUL26: Train 530(10), CC/C8301-4 cars-E/C2101, was delayed departing Oakland, CA due to issues with the wheelchair lift. The crew was unable to stow wheelchair lift away on C/C8016 after use. Train 530(10) held for mechanical to respond and resolve issue. Once mechanical resolved issue, Train 530(10) departed Oakland.

Train 543(10) was delayed departing Sacramento, CA due to the late turn of equipment from Train 530(10).

Train	Delay	Comment
530(10)	38"	
543(10)	29"	ITD - Turn off 530

Train 14(09) Chemult, OR - Injured or Sick Passenger

10JUL26: Train 14(09) was delayed departing Chemult, OR on the UPRR Cascade Subdivision holding for EMS to arrive to assist a customer on board. The train held for EMS to arrive and attend to the customer in need. Once EMS was finished, Train 14(09) proceeded north.

Train	Delay	Comment
-------	-------	---------

Train 535(10) West of Suisun-Fairfield, CA - Drawbridge Opening

10JUL26: Train 535(10) was held 11.8 miles west of Suisun-Fairfield, CA, on the UPRR Martinez Subdivision as a result of the Suisun Drawbridge being raised for maritime traffic to pass. Train 528(10) held at MP 32.8 for the bridge opening. Once the tanker Green Eternity passed and the bridge was lowered, train movement was resumed.

Train	Delay	Comment
535(10)	28"	
528(10)	19"	

Train 527(10) Oakland, CA - Vehicle on Tracks

10JUL26: Train 527(10) was delayed departing Oakland, CA on the UPRR Niles Subdivision due to a vehicle on the tracks. The crew held until tow truck arrived and removed vehicle. Once tracks were cleared, Train 527(10) departed Oakland.

Train 530(10) was delayed departing San Jose, CA due to the late arrival of equipment from Train 527(10). The equipment arrived at 10:38A-PT, 44 minutes late.

Train	Delay	Comment
527(10)	41"	
530(10)	17"	Late turn of equip- SJC

Train 20(10) South of Slidell, LA - B&B Work Due to Defect

10JUL26: Train 20(10) was held 11.8 miles south of Slidell, LA (MP 167.3), on the NSRR NO&NE Subdivision at MP 179.1 due to a reported failure of the North Drawbridge at MP 173.4. Maintenance of Way personnel responded to the location and performed the necessary repairs to restore proper bridge operation. Upon completion of repairs, the drawbridge was successfully seated and locked in position. Train 20(10) was then released and continued north without further delay.

Train	Delay	Comment
20(10)	51"	

Train 4(09) East of Needles, CA - Freight Train Interference

10JUL26: Train 4(09) was delayed at MP 527.2, 50 miles east of Needles, CA, on the BNSF Seligman Subdivision due to meet with Train 3(09). Once Train 3(09) cleared route, Train 4(09) proceeded east.

Train	Delay	Comment
4(09)	41"	

Train 3(08) West of Flagstaff, AZ - Freight Train Interference

10JUL26: Train 3(08) was delayed starting at MP 436, 92 miles west of Flagstaff, AZ, on the BNSF Seligman Subdivision due to freight interference. The crew followed BN6694 from MP 436 to MP 459 where they were able to operate around.

Train	Delay	Comment
3(08)	30"	

Metrolink Ventura Subdivision - Freight Trespasser Strike

10JUL26: At 3:20A-PT, 26-FOI-00590 1-00000008301 UNCLASSIFIED 7/15/2026 k a trespasser at MP 7.7, 2 miles west of Glendale, CA, on the Metrolink Ventura Subdivision fouling both main tracks. The strike was a fatality with initial reports unclear of an E.T.A for the coroner and freight recrew, EMS and local police were on scene. The coroner arrived on scene at 4:10A-PT. Once investigation was completed, the tracks were released by local law enforcement. Train 757(10) was held in Los Angeles Union Station for a better estimate of track opening still awaiting arrival of freight recrew. Once freight recrew arrived and moved train from scene, the track inspector on site was able to inspect tracks and hazmat cleanup began on main track one. Train 757(10) departed Los Angeles with single tracking through area due to hazmat clean-up still on going. At 7:45A-PT, the clean up efforts on main track one were complete and all tracks were in service.

Train	Delay	Comment
757(10)	47"	Hold LAX

Train 1(08)/421(07) East of Yuma, AZ - Freight Train Interference

10JUL26: Train 1(08)/421(07) was delayed starting at Stoval/ MP 801.9, 65 miles east of Yuma, AZ, on the UPRR Gila Subdivision due to freight interference. The crew held at Stoval for meet with UP8249 then further delayed between MP 753 to MP 732 due to following and meeting multiple additional freights.

Train	Delay	Comment
1(08)/421(07)	1'22"	

Train 58(09) Fulton, KY - Washout

10JUL26: Train 58(09) was held at Fulton, KY (MP 404.6) on the CNRR Cairo Subdivision after a reported washout was identified 56 miles north of the station at MP 348.6. Maintenance of Way personnel responded to the location and determined that approximately 200 feet of track structure had been undercut beneath the ballast and ties. An estimated track opening time of 9:00AM-CT was established. Train 58(09) remained at Fulton until it was authorized to proceed to Cairo to meet a recrew from Carbondale, as the operating crew reached their Hours of Service limit at 9:00AM-CT. While the train awaited the recrew, the affected track was repaired and returned to service. After the recrew boarded in Cairo, Train 58(09) was released and proceeded northward without further delay.

Service recovery measures were implemented for all customers. Coach customers received snack packs and bottled water, with complimentary hot tea and coffee were made available in the café car. For lunch, coach customers were provided sandwiches, chips, dessert, and a beverage. First Class customers received an extended breakfast service followed by the regularly scheduled lunch service in the dining car.

WBS#: B.TR.100150.6880

Train	Delay	Comment
58(09)	2'51"	Hold FTN
58(09)	1'49"	Hold for Recrew

Train 21(09) South of Little Rock, AR - Freight Train Interference

10JUL26: Train 21(09) held 24.6 miles south of Little Rock, AR (MP345.7), on the UPRR Little Rock Subdivision, at Saline Jct (MP370.3) in order to meet UP 7084. Additional delay was incurred at Traskwood (MP378.5) in order to meet UP 7406.

Train	Delay	Comment
21(09)	1'00"	Saline Jct

Train 41(09) Chicago, IL - Initial Terminal Delay

09JUL26: Train 41(09) ~~26-FCI-00890~~ ~~000000008301~~ UNCLASSIFIED 7/15/2026 to IL Station/MP0.0 due to a late turn off train 40(07) that arrived to Chicago IL at 456PM CT. Train 41(09) equipment was set in the yard at 616PM CT to remove engine 333 for traction motor faults and replace it with engine 50. Train 41(09) was made up completed at 636PM and released by yard mechanical at 844PM CT. At 856PM CT the yard crew discovered no trainline on the fireman's side. Mechanical responded and found the HEP selector switch was not fully seated in the run position. Train 41(09) arrived to Chicago IL station at 916PM CT and began boarding 237 passengers. Train 41(09) departed Chicago at 950PM CT.

Due to train 41(09) operation 5'13" late out of Pittsburg the following service recovery has been implemented, coach customers were served beef stew, mashed potatoes and bottled water. First class customers were served normal lunch service in the diner.

Train	Delay	Comment
41(09)	3'10"	

UPRR Brooklyn Subdivision - Freight Derailment South of Portland, OR

10JUL26: At 3:13A-PT, The UPRR reported a derailment at MP 0.4, a half mile south of Portland, OR, on the UPRR Brooklyn Subdivision with 9 cars derailed, one impacting the Steel Bridge on main track one. The cars were empty with no hazmat reported. Main track two appeared unaffected but would need to be inspected by a bridge inspector with an ETA of 9:00A-PT. Buses were sourced as a precaution due to the uncertainty of open track for trains operating through the area. Three buses were secured with an ETA of 10:30A in Oregon City, OR. At 9:53A-PT, the UPRR reported main track two had been inspected and Train 504(10) would have an open route shortly. Train 504(10) arrived into Oregon City at 9:47A-PT and held for open tracks. Once tracks were open, Train 504(10) departed Oregon City at 10:06A-PT.

WBS#: B.TR.100150.6881

Train	Delay	Comment
504(10)	18"	

UPRR Desoto Subdivision Washout - North of Poplar Bluff, MO

10JUL26: At 3:30AM-CT, Union Pacific reported a washout on the UPRR DeSoto Subdivision at Annapolis (MP108), located 57.6 miles north of Poplar Bluff, MO (MP165.6). As a result, Train 22(09) arrived at the Poplar Bluff station at 4:04AM-CT with 144 customers onboard and held for disposition.

A Union Pacific Manager of Track Maintenance responded to the washout location at 4:20AM-CT and provided a preliminary estimated track restoration time of 2:00PM-CT. A detour route was available via the Chester Subdivision between Poplar Bluff and St. Louis, bypassing Arcadia. No customer impact occurred at Arcadia, as no customers were scheduled to board or detrain at that location. Union Pacific pilot crews went on duty at 6:10AM-CT and responded to the train, arriving at 7:00AM-CT. Upon the pilots' arrival, Train 22(09) departed Poplar Bluff at 7:21AM-CT and proceeded over the detour route via the Chester Subdivision.

At 12:00PM-CT, Union Pacific reported that floodwaters were not expected to begin receding until Saturday, July 11. Following the water's recession, a track inspection would be required before rail operations could resume through the area. As a result:

-Train 21/421(10) detoured via the Chester Subdivision with 6 on / 0 off at Arcadia. The affected six customers were notified and advised to rebook on the next available departure.

-Train 22(10)/422(08) detoured via the Chester Subdivision with 0 on / 5 off at Arcadia. XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX. A sprinter van transported passengers from Saint Louis, MO back to Arcadia, MO.

Heat Dome affect Entire Network - Weather

08JUL26: A heat dome ~~28-FOI-005901 0000008301~~ west ~~UNCLASSIFIED~~ bringing high temps in excess of 100° throughout the country. It will begin to expand as the week goes along and shift to the east affecting the entire nation. The first few days will be focused from the southwest through the Rockies to the Great Plains. It will then shift east affecting the Upper Midwest through the Northeast. Trains will be restricted to high temperature restriction. The high temperatures, there will be increase of severe thunderstorms and high winds.

The heat dome is expected to persist until the remainder of July.

Train	Delay	Comment
6(08)	32"	Heat Orders WNN-ELK
5(06)	31"	Heat orders - ELK to WNN
6(08)	49"	Heat orders- GRI to GJT
5(08)	28"	Heat Orders GRA-GJT
5(08)	43"	Heat Orders GJT-HER
6(08)	17"	Heat Orders MTZ-RSV
3(08)	45"	High Winds RAT - GLP
6(10)	1'25"	Heat Orders RNO - ELK

City of New Orleans Service Disruption

27JUN26: Trains 58(27) and 59(28) were cancelled in their entirety after Mechanical forces in New Orleans identified multiple wheel defects during inspection of Train 59(25)'s inbound equipment, requiring 18 wheel set replacements. The defects were traced to a suspected rail issue narrowed to down between Carbondale, IL and Yazoo City, MS. CN performed track inspections between Carbondale and New Orleans and no track defects were identified. Chicago inspected Train 390(27)'s inbound equipment to which no defects were found which helped to narrow down the location. CN track inspectors were deployed to conduct a full inspection with a consensus of the rail conditions expected later that evening. As a precaution, sales for Trains 59(27) and 58(28) were shut down.

Train 59(26) was stopped at Yazoo City, MS for inspection, where multiple wheel defects were identified on the Fireman side of cars 31025, 34028, 34014, and 33026. The same side as the defects found on Train 59(25)'s inbound equipment. The train was subsequently terminated at Jackson, MS after CN Mechanical responded and deemed the equipment not fit to proceed to New Orleans. Efforts were underway to secure alternate transportation for the 210 affected customers, while no alternate transportation was being provided for downline customers. Service recovery measures were enacted, including the distribution of snack packs and water, and customers remained in good spirits at the time. Amtrak's New Orleans Trainmaster and New Orleans Mechanical responded to Jackson, as well as CN Mechanical. The train 59(26) equipment was declared unsafe to move and was tied down on main track one at Jackson Station.

The following service adjustments were put into effect:

- Train 58(27-28) was cancelled in its entirety with no alternate transportation.
- Train 59(27-28) was cancelled in its entirety with no alternate transportation.

28JUN26: Due to lack of available equipment, the City of New Orleans service adjustments were extended through 29JUN as follows:

- Train 58(29) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(29) cancelled entirely, no alternate transportation between Chicago and New Orleans.

There were 26 enroute connecting passengers at Chicago impacted by the ongoing City of New Orleans service adjustments. These passengers were reaccommodated on Train 21/421(28) Chicago to Longview, TX, and then on thruway bus 6021(29) to Houston. As a result of accommodating these passengers, Train 21/421(28) was over capacity in coach by 26 seats between Chicago and St. Louis, MO. One supplemental bus was secured and operated Chicago to St. Louis express to alleviate the over capacity condition.

extended through 01JUL.

01JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 03JUL.

02JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 04JUL.

03JUL26: Due to the ongoing equipment availability issue, the service adjustments were extended through 06JUL.

04JUL26: The current plan is to resume service with Trains 58(07) and 59(07). Due to equipment availability, an additional cancellation was implemented. Trains 58(08) and 59(09) were cancelled and no alternate transportation was provided.

06JUL26: City of New Orleans service adjustments were updated as follows:

- Train 59(07) operated normal, Chicago, IL to New Orleans, LA.
- Train 58(07) cancelled entirely, no alternate transportation between New Orleans and Chicago.
- Train 59(08) cancelled entirely, no alternate transportation between Chicago and New Orleans.

09JUL26: Due to wheel defects found on 3 cars from inbound Train 59(07) in New Orleans, additional service adjustments are now enacted through 12JUL:

- Train 59(09-12) cancelled entirely, no alternate transportation between Chicago and New Orleans.
- Train 58(09-10) operated normal, New Orleans, LA to Chicago, IL.
- Train 58(11-12) cancelled entirely, no alternate transportation between New Orleans and Chicago.

WBS#: B.TR.100150.6822

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(26)	Terminated	JAN
59(27JUN-06JUL, 08-12JUL)	Cancelled	
58(27JUN-07JUL, 11-12JUL)	Cancelled	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station is located on the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2 / 422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2 / 422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2 / 422 (04, 07JAN)	BYPASS PSN - flooding	
2 / 422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2 / 422 (13, 15, 20, 24MAY)	Bypass PSN	
2 / 422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2 / 422 (01, 03, 05, 07, 10JUL)	BYPASS PSN	
1 (01, 04, 08JUL) / 421 (03, 07JUL)	BYPASS PSN	

Maintenance of Way Highlights

BNSF Track Work West of Macomb, IL - Carl Sandburg Service TWA 26-073

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th. To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL) and Train 382(13JUL-17JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL) and Train 381(13JUL-17JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

WBS#: B.TR.100150.6826

CPKC Watertown Subdivision - Scheduled M/W Work 26-047

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie replacement and surfacing scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.

- Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.

WBS Element B.TR.100150.6620 has been issued.

CNRR McComb Subdivision - Scheduled M/W Work 26-066

04JUN26: Canadian National Railroad has announced a planned maintenance outage scheduled on the McComb Subdivision between MP736 and MP756.2 starting Monday, June 22nd through Friday, July 31st. To accommodate the infrastructure work, Amtrak's City of New Orleans Service will be adjusted as follows:

09JUL26: This outage was originally scheduled to conclude on Friday July 31st, but will now conclude 2-weeks Earlier on Friday July 17th. The following adjustments are now in place.

- Train 59(21Jun-15Jul) will depart Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 1059 (16Jul) will operate in lieu of Train 59(30Jul), departing Chicago 2-hours Later, at 10:05pm, and will operate 2-hours Later between Chicago and New Orleans.
- Train 58(22Jun-16Jul) will depart New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.
- Train 1058(17Jul) will operate in lieu of Train 58(31Jul), departing New Orleans 2-hours Later, at 3:45pm, and will operate 2-hours Later between New Orleans and Chicago.

WBS#: B.TR.100150.6732

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
 - Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
 - Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00590 k 00900008301 iled "UNCLASSIFIED" C&M Subdivision at Western Avenue -
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In
order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be
adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
318(12)	STL	1	Carried passenger to ALN to wait for Train 21	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00590

00000008301

"UNCLASSIFIED"

7/15/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
173 (10)	BOS	AMII coach in lieu of AMI coach. Business Class in lieu of Coach. Cafe car is located in the middle of the consist.			25085, 81518
449 (10)	BOS	28007 removed in BOS to send to HIA for repair, only substitution is AMF-I All Table Lounge 43395	N/A	0	28007
48 (10)	CHI	BYD HVAC will deadhead inline; no replacement. Please accomodate all passengers affected.	Most pax moved to other rooms. Three downgraded down line.	3	62001
80 (10)	CLT	25071 BYD HVAC- CLT unable to repair; no replacement. Inventories reduced to reflect. over capacity Y and XY.	Notified passengers.	51	25071
770 (10)	GTA	NO BIKE SPACE- over capacity. NO WIFI SERVICE.	Passengers notified	251	90215
770 (10)	GTA	No bikes, reduced Y capacity	no bv	1	90215
646 (10)	HAR	No cab car, cafe car added for wifi. No impact to ridership			43389
642 (10)	HAR	No cab car or cafe car to provide wifi. Please notify pax of no wifi. No impact to inventory.			82728
626 (10)	HAR	No cab car or cafe car to provide wifi. Please notify pax of no wifi. No impact to inventory.			82728
98 (10)	HIA	Viewliner II in Lieu of Viewliner I Sleeper, 1 less ES roomette vs plan.			62519
588 (10)	LAX	NO BIKE SPACE. NO WIFI SERVICE.	Passengers notified	58	90215
572 (10)	LAX	EQUIPMENT CHANGE. 572 WILL HAVE NO BIKES AND REDUCED Y-INVENTORY.	no bv	4	90215
98 (10)	MIA	(9811) Viewliner II in lieu of Viewliner I sleeper. Please			62519

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		accomodate all passengers impacted.			
609 (10)	NYP	push/pull with 2 locomotives; no cab car in consist. 5 AMII coaches and one cafe for WIFI service only.	No impact	0	43379, 600
655 (10)	NYP	No cab car, cafe car added for wifi. No impact to ridership			43389
649 (10)	NYP	No cab car or cafe car to provide wifi. Please notify pax of no wifi. No impact to inventory.			82728
43 (10)	NYP	AM2 replaced with AM1 coach due to no OKM AM2 in NYP - no customer impact.			82697
97 (10)	NYP	Train operates with an AMF-I coach in lieu of planned AMF-II coach	SVWR97/10JUL NO WAR DATA THIS TRAIN/DATE	0	25121
42 (11)	PGH	AM2 replaced with AM1 coach due to no OKM AM2 in NYP - no customer impact.			82697
605 (10)	PHL	605(10) will be push/ push with one locomotive. 4 AMII coaches and cafe for WIFI service.	No impact	0	43389
380 (10)	QCY	Venture Business Class shopped for non functioning toilets; only replacemenet is AMF-I Club Dinette which has 18 less JY seats and 14 less Y seats.	no pax impact	0	ID4202
581 (10)	SAN	NO BIKE SPACE- over capacity. NO WIFI SERVICE.	Passengers notified	138	90215
587 (10)	SAN	EQUIPMENT CHANGE. 587 WILL NAVE NO BV AND REDUCED Y.	no bv	2	90215

Reverse Consists

Train Number	Station	Reason
130 (10)	WAS	Business class change only Business class seating orientation may have changed At Rear

Train Number	Station	Reason	
		26-FOI-00590 00000008301	"UNCLASSIFIED" 7/15/2026
111 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front	
110 (10)	PHL	Consist reversed Business class seat orientation may have changed At Rear	
181 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front	
183 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front	
185 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front	
182 (10)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
129 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front	
141 (10)	SPG	Business class change only Business class seating orientation may have changed At Rear. B-end leading.	
148 (10)	WAS	Business class change only Business class seating orientation may have changed At Rear. B-end leading	
143 (11)	NHV	Business class change only Business class seating orientation may have changed At Rear. B-end leading. **Train 143(11)**	
119 (10)	NYP	Business class change only Business class seating orientation may have changed At Front. B-end leading	
196 (10)	WAS	Business class change only Business class seating orientation may have changed At Rear. B-end leading	