



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, December 06, 2025

Rules: 0-7



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/05/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	52	83.3%	1,550	236	84.8%	19,459	2,426	87.5%
Central Division	85.5%	65	14	78.5%	329	56	83.0%	4,351	425	90.2%
Northeast Division	80.0%	101	23	77.2%	502	72	85.7%	6,098	824	86.5%
Southeast Division	72.5%	74	10	86.5%	368	57	84.5%	4,567	574	87.4%
Southwest Division	77.0%	71	5	93.0%	351	51	85.5%	4,443	603	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00167 00000005498 UNCLASSIFIED Endpoint Arrival Dates through 12/5/25 12/17/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	98,973	26,894	73%	498,096	119,913	76%	6,781,119	1,380,634	80%
Northeast Corridor	81%	43,112	12,028	72%	227,413	49,060	78%	3,049,963	571,367	81%
Acela	83%	10,463	3,584	66%	54,324	14,601	73%	648,616	132,537	80%
Northeast Regional	79%	32,649	8,444	74%	173,089	34,459	80%	2,401,347	438,830	82%
Richmond / Newport News / Norfolk	77%	10,667	1,656	84%	52,343	12,701	76%	729,417	158,277	78%
Springfield Shuttles	89%	945	131	86%	4,352	470	89%	45,316	5,144	89%
Roanoke	79%	2,357	1,067	55%	13,438	2,637	80%	183,954	29,789	84%
On Spine Northeast Regional	80%	18,680	5,590	70%	102,956	18,651	82%	1,442,660	245,620	83%
State Supported	80%	43,786	9,329	79%	203,885	42,057	79%	2,901,924	531,483	82%
Borealis	60%	598	179	70%	2,681	921	66%	39,159	10,555	73%
Capitol Corridor	90%	3,727	107	97%	18,174	2,560	86%	250,264	27,466	89%
Carolinian	60%	1,203	869	28%	5,601	2,323	59%	79,235	23,260	71%
Cascades	63%	2,179	202	91%	9,460	2,723	71%	156,564	38,147	76%
Downeaster	82%	1,605	749	53%	6,341	1,019	84%	100,390	12,836	87%
Empire	78%	5,426	1,352	75%	24,554	6,644	73%	347,846	70,058	80%
Adirondack	72%	271	35	87%	1,290	381	70%	22,291	6,970	69%
Ethan Allen Express	70%	593	310	48%	2,584	697	73%	39,862	12,362	69%
Maple Leaf	70%	600	265	56%	3,171	1,649	48%	43,369	14,884	66%
New York - Albany	85%	2,640	139	95%	11,209	1,043	91%	151,255	20,353	87%
New York - Niagara Falls	75%	1,322	603	54%	6,300	2,874	54%	91,069	15,489	83%
Gold Runner	73%	2,305	603	74%	11,213	3,144	72%	167,153	59,362	64%
Heartland Flyer	65%	194	3	98%	752	108	86%	13,314	7,679	42%
Hiawatha	90%	1,878	356	81%	8,270	2,262	73%	116,281	13,272	89%
Illinois	78%	2,057	789	62%	10,888	3,884	64%	161,333	43,355	73%
Carl Sandburg / Illinois Zephyr	85%	563	19	97%	2,055	533	74%	27,386	7,121	74%
Illini / Saluki	85%	538	518	4%	2,887	995	66%	57,949	14,511	75%
Lincoln Service	70%	956	252	74%	5,946	2,356	60%	75,998	21,723	71%
Keystone	92%	9,393	1,699	82%	46,003	5,670	88%	556,572	47,627	91%
Lincoln / Missouri	60%	818	42	95%	3,492	1,400	60%	52,058	26,207	50%
Mardi Gras Service	80%	450	131	71%	1,413	151	89%	28,289	3,873	86%
Michigan	69%	1,789	1,168	35%	9,597	4,270	56%	129,489	34,257	74%
Blue Water	70%	260	260	0%	2,124	1,106	48%	33,027	8,425	74%
Pere Marquette	85%	298	0	100%	1,311	0	100%	17,290	1,932	89%
Wolverine	65%	1,231	908	26%	6,162	3,164	49%	79,172	23,900	70%
Missouri	80%	239	8	97%	919	336	63%	15,419	3,849	75%
Pacific Surfliner	85%	6,593	338	95%	29,197	1,795	94%	448,624	60,706	86%
Pennsylvanian	72%	975	189	81%	4,322	830	81%	61,494	6,779	89%
Piedmont	73%	1,026	166	84%	4,750	433	91%	89,595	22,333	75%
Vermont	75%	1,331	379	72%	6,258	1,584	75%	88,845	19,862	78%
Long Distance	56%	12,075	5,537	54%	66,798	28,796	57%	829,232	277,784	67%
Auto Train	57%	632	434	31%	3,751	1,365	64%	43,769	8,616	80%
California Zephyr	50%	779	15	98%	4,633	1,776	62%	61,710	17,497	72%
Cardinal	55%	285	150	47%	1,365	614	55%	18,746	8,928	52%
City Of New Orleans	75%	728	307	58%	3,567	473	87%	47,002	10,239	78%
Coast Starlight	60%	1,018	105	90%	6,375	2,098	67%	77,254	24,614	68%
Crescent	70%	881	22	98%	4,582	306	93%	63,698	16,111	75%
Empire Builder	55%	1,029	641	38%	5,759	3,253	44%	68,402	24,089	65%
Floridian	40%	1,451	1,250	14%	9,356	6,217	34%	113,703	60,792	47%
Lake Shore Ltd	73%	1,114	625	44%	5,569	2,824	49%	61,700	11,131	82%
Palmetto	65%	898	227	75%	4,765	1,454	69%	64,837	9,906	85%
Silver Meteor	45%	977	591	40%	5,250	2,250	57%	68,355	20,658	70%
Southwest Chief	40%	768	706	8%	4,464	3,492	22%	56,439	34,017	40%
Sunset Ltd	70%	641	299	53%	1,761	392	78%	18,611	4,765	74%
Texas Eagle	50%	874	165	81%	5,601	2,282	59%	65,006	26,421	59%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00107 00000005400 "UNCLASSIFIED" 12/17/2025

Train Index Dates Through December 05, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	30,770	550,062	559	360,618	7,058,855	511

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,349	167,813	80	13,704	2,070,049	66
INFRASTRUCTURE PLANNED	135	567	167,813	34	11,148	2,070,049	54
FLEET RELIABILITY	90	5,381	550,062	98	53,255	7,058,855	75
TRAIN OPERATIONS	424	23,473	550,062	427	282,511	7,058,855	400

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/05/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	52	83.3%	1,550	236	84.8%	19,459	2,426	87.5%
Central Division	85.5%	65	14	78.5%	329	56	83.0%	4,351	425	90.2%
Northeast Division	80.0%	101	23	77.2%	502	72	85.7%	6,098	824	86.5%
Southeast Division	72.5%	74	10	86.5%	368	57	84.5%	4,567	574	87.4%
Southwest Division	77.0%	71	5	93.0%	351	51	85.5%	4,443	603	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/05/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	52	83.3%	1,550	236	84.8%	19,459	2,426	87.5%
Central Division	85.5%	65	14	78.5%	329	56	83.0%	4,351	425	90.2%
CDL	90.0%	1	0	100.0%	6	0	100.0%	120	6	95.0%
CHI	85.0%	27	7	74.1%	134	30	77.6%	1,767	167	90.5%
EUG	86.5%	2	0	100.0%	10	2	80.0%	127	17	86.6%
GRR	98.0%	1	0	100.0%	5	0	100.0%	66	0	100.0%
KCY	84.5%	2	1	50.0%	10	2	80.0%	130	13	90.0%
MKE	86.5%	6	1	83.3%	30	4	86.7%	386	34	91.2%
MSP	94.0%	1	0	100.0%	5	0	100.0%	66	3	95.5%
PDX	78.0%	5	0	100.0%	25	3	88.0%	331	49	85.2%
PNT	91.5%	3	1	66.7%	15	2	86.7%	141	7	95.0%
PTH	93.0%	1	0	100.0%	5	0	100.0%	66	2	97.0%
QCY	87.5%	2	1	50.0%	10	1	90.0%	132	13	90.2%
SEA	80.0%	8	2	75.0%	40	8	80.0%	525	82	84.4%
SPK	92.0%	1	0	100.0%	5	0	100.0%	66	1	98.5%
STL	88.0%	3	1	66.7%	19	4	78.9%	261	22	91.6%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	10	0	100.0%	132	4	97.0%
Northeast Division	80.0%	101	23	77.2%	502	72	85.7%	6,098	824	86.5%
ALB	91.5%	7	0	100.0%	35	3	91.4%	402	24	94.0%
BON	43.5%	5	1	80.0%	25	2	92.0%	312	34	89.1%
BOS	86.5%	19	5	73.7%	99	11	88.9%	1,197	114	90.5%
BRK	88.0%	5	1	80.0%	25	1	96.0%	292	14	95.2%
BTN	48.0%	1	0	100.0%	5	0	100.0%	65	17	73.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	10	1	90.0%	126	10	92.1%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	5	0	100.0%	66	11	83.3%
NFL	96.5%	2	0	100.0%	10	0	100.0%	132	4	97.0%
NHV	75.5%	6	0	100.0%	30	2	93.3%	337	65	80.7%
NYP	77.5%	44	15	65.9%	213	50	76.5%	2,589	480	81.5%
SAB	98.0%	1	0	100.0%	5	0	100.0%	64	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	1	85.7%	35	1	97.1%	384	17	95.6%
TWO	84.0%	1	0	100.0%	5	1	80.0%	65	17	73.8%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	10	86.5%	368	57	84.5%	4,567	574	87.4%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	25	1	96.0%	330	26	92.1%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	3	76.9%	65	19	70.8%	745	117	84.3%
LOR	69.5%	1	0	100.0%	5	1	80.0%	66	6	90.9%
MIA	87.5%	2	0	100.0%	10	1	90.0%	132	14	89.4%
MOE	94.0%	2	0	100.0%	10	0	100.0%	132	3	97.7%
NFK	86.0%	3	0	100.0%	15	1	93.3%	185	16	91.4%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/05/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/05/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	52	83.3%	1,550	236	84.8%	19,459	2,426	87.5%
Southeast Division	72.5%	74	10	86.5%	368	57	84.5%	4,567	574	87.4%
NOL	92.0%	4	0	100.0%	22	0	100.0%	291	14	95.2%
NPN	96.0%	2	0	100.0%	10	0	100.0%	107	7	93.5%
PGH	92.0%	1	0	100.0%	5	0	100.0%	66	1	98.5%
PHL	45.0%	5	3	40.0%	25	15	40.0%	306	138	54.9%
RGH	97.0%	4	1	75.0%	20	2	90.0%	260	5	98.1%
RNK	85.5%	2	1	50.0%	10	1	90.0%	131	15	88.5%
RVM	86.0%	1	0	100.0%	5	1	80.0%	76	12	84.2%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	5	1	80.0%	66	1	98.5%
SFA	70.5%	1	0	100.0%	5	0	100.0%	66	3	95.5%
WAS	70.0%	27	2	92.6%	131	14	89.3%	1,600	191	88.1%
Southwest Division	77.0%	71	5	93.0%	351	51	85.5%	4,443	603	86.4%
ARN	60.5%	1	0	100.0%	5	2	60.0%	66	7	89.4%
BFD	75.5%	6	2	66.7%	30	3	90.0%	377	87	76.9%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	5	1	80.0%	68	18	73.5%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	5	0	100.0%	65	3	95.4%
GTA	72.5%	3	0	100.0%	15	1	93.3%	191	18	90.6%
LAX	77.5%	10	0	100.0%	47	10	78.7%	607	71	88.3%
OKC	96.0%	1	0	100.0%	5	0	100.0%	66	3	95.5%
OKJ	79.0%	12	3	75.0%	60	20	66.7%	720	172	76.1%
SAC	73.5%	14	0	100.0%	69	10	85.5%	857	96	88.8%
SAN	77.0%	12	0	100.0%	60	2	96.7%	753	67	91.1%
SAS	85.0%	1	0	100.0%	5	0	100.0%	66	3	95.5%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	35	1	97.1%	460	41	91.1%
SLO	62.0%	2	0	100.0%	10	1	90.0%	127	12	90.6%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	10	1	90.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		2	0	100.0%	28	1	96.4%	3	0	100.0%	29	1	96.6%
2		2	0	100.0%	29	4	86.2%	2	0	100.0%	28	4	85.7%
3	49	5	2	60.0%	66	6	90.9%	5	4	20.0%	66	27	59.1%
4	166	5	2	60.0%	66	8	87.9%	5	5	0.0%	66	43	34.8%
5		5	1	80.0%	65	8	87.7%	5	2	60.0%	64	8	87.5%
6		5	1	80.0%	66	18	72.7%	5	2	60.0%	66	23	65.2%
7		5	1	80.0%	66	5	92.4%	5	1	80.0%	66	8	87.9%
8	52	5	2	60.0%	66	22	66.7%	5	4	20.0%	66	31	53.0%
11		5	1	80.0%	65	12	81.5%	5	0	100.0%	63	7	88.9%
14		5	1	80.0%	66	10	84.8%	5	0	100.0%	65	18	72.3%
19		5	2	60.0%	66	10	84.8%	5	0	100.0%	66	11	83.3%
20		5	0	100.0%	66	6	90.9%	5	0	100.0%	66	6	90.9%
21		5	2	60.0%	65	10	84.6%	5	2	60.0%	65	13	80.0%
22		5	0	100.0%	66	3	95.5%	5	1	80.0%	65	14	78.5%
23	42	5	0	100.0%	66	3	95.5%	5	1	80.0%	66	11	83.3%
24		5	0	100.0%	66	2	97.0%	5	1	80.0%	66	7	89.4%
25		5	0	100.0%	66	0	100.0%	5	0	100.0%	66	9	86.4%
26		5	0	100.0%	66	2	97.0%	5	0	100.0%	66	11	83.3%
27		5	2	60.0%	66	3	95.5%	5	1	80.0%	66	11	83.3%
28		5	1	80.0%	66	14	78.8%	5	1	80.0%	66	9	86.4%
40	102	5	1	80.0%	66	10	84.8%	5	2	60.0%	66	24	63.6%
41	73	5	3	40.0%	66	21	68.2%	5	5	0.0%	66	44	33.3%
42		5	0	100.0%	66	1	98.5%	5	0	100.0%	66	9	86.4%
43		5	0	100.0%	66	5	92.4%	5	1	80.0%	66	4	93.9%
48	45	5	1	80.0%	66	6	90.9%	5	3	40.0%	66	6	90.9%
49		5	0	100.0%	66	10	84.8%	5	2	60.0%	66	7	89.4%
50	92	2	1	50.0%	28	5	82.1%	2	2	0.0%	29	15	48.3%
52		5	0	100.0%	66	3	95.5%	5	0	100.0%	66	12	81.8%
53		5	1	80.0%	66	6	90.9%	5	1	80.0%	66	9	86.4%
55	61	5	0	100.0%	47	0	100.0%	5	1	80.0%	47	7	85.1%
56		5	1	80.0%	47	8	83.0%	5	2	60.0%	47	8	83.0%
58	47	5	0	100.0%	65	2	96.9%	5	1	80.0%	64	8	87.5%
59		5	0	100.0%	64	3	95.3%	5	0	100.0%	64	3	95.3%
63		5	2	60.0%	66	23	65.2%	5	1	80.0%	66	30	54.5%
64		5	1	80.0%	65	17	73.8%	5	2	60.0%	65	12	81.5%
66	41	5	0	100.0%	66	10	84.8%	5	1	80.0%	66	14	78.8%
67		4	0	100.0%	46	2	95.7%	5	0	100.0%	47	7	85.1%
68		5	0	100.0%	66	11	83.3%	5	3	40.0%	66	28	57.6%
69		5	0	100.0%	66	7	89.4%	5	0	100.0%	66	7	89.4%
71		5	1	80.0%	66	1	98.5%	5	1	80.0%	66	17	74.2%
72	11	5	1	80.0%	66	6	90.9%	5	2	60.0%	66	12	81.8%
73	15	5	1	80.0%	66	2	97.0%	5	1	80.0%	65	34	47.7%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
74		5	0	100.0%	66	5	92.4%	5	0	100.0%	66	20	69.7%
75		5	0	100.0%	66	2	97.0%	5	1	80.0%	66	29	56.1%
76	12	5	0	100.0%	66	4	93.9%	5	1	80.0%	66	31	53.0%
77	11	5	0	100.0%	66	2	97.0%	5	1	80.0%	66	23	65.2%
78		5	0	100.0%	66	3	95.5%	5	1	80.0%	66	10	84.8%
79		5	1	80.0%	66	12	81.8%	5	0	100.0%	65	11	83.1%
80		5	0	100.0%	66	8	87.9%	5	2	60.0%	65	7	89.2%
84		5	0	100.0%	47	3	93.6%	5	1	80.0%	47	6	87.2%
85	18	5	0	100.0%	47	1	97.9%	5	2	60.0%	47	17	63.8%
86		5	1	80.0%	47	5	89.4%	5	3	40.0%	47	22	53.2%
89		5	1	80.0%	66	13	80.3%	5	1	80.0%	66	7	89.4%
90		5	1	80.0%	66	1	98.5%	5	0	100.0%	66	6	90.9%
93		5	0	100.0%	47	6	87.2%	5	0	100.0%	46	10	78.3%
94		5	1	80.0%	47	7	85.1%	4	2	50.0%	46	14	69.6%
95		5	0	100.0%	47	1	97.9%	5	2	60.0%	47	13	72.3%
97		5	4	20.0%	66	22	66.7%	5	1	80.0%	66	17	74.2%
98	86	5	0	100.0%	66	4	93.9%	5	2	60.0%	66	13	80.3%
110		5	2	60.0%	47	21	55.3%	5	0	100.0%	47	3	93.6%
111		5	0	100.0%	47	4	91.5%	5	1	80.0%	47	4	91.5%
112		5	0	100.0%	47	4	91.5%	5	0	100.0%	47	5	89.4%
114		5	1	80.0%	47	9	80.9%	4	0	100.0%	46	0	100.0%
119		5	0	100.0%	47	9	80.9%	5	1	80.0%	47	4	91.5%
125		5	0	100.0%	47	2	95.7%	5	4	20.0%	47	10	78.7%
129		5	2	60.0%	47	15	68.1%	5	0	100.0%	47	6	87.2%
130		5	0	100.0%	47	4	91.5%	5	0	100.0%	47	4	91.5%
131		5	0	100.0%	47	4	91.5%	5	1	80.0%	47	1	97.9%
133		5	0	100.0%	47	19	59.6%	5	1	80.0%	47	21	55.3%
134	149	5	1	80.0%	47	5	89.4%	5	3	40.0%	47	11	76.6%
136		5	1	80.0%	47	4	91.5%	4	0	100.0%	47	3	93.6%
137	54	5	1	80.0%	45	9	80.0%	5	1	80.0%	45	11	75.6%
138		5	0	100.0%	47	6	87.2%	5	0	100.0%	47	2	95.7%
141	21	5	0	100.0%	47	3	93.6%	5	2	60.0%	47	10	78.7%
148		5	1	80.0%	47	5	89.4%	5	0	100.0%	46	9	80.4%
151		5	3	40.0%	66	17	74.2%	5	1	80.0%	65	17	73.8%
170	16	5	1	80.0%	44	4	90.9%	5	2	60.0%	44	11	75.0%
171	22	5	0	100.0%	47	3	93.6%	5	2	60.0%	47	7	85.1%
172		5	0	100.0%	47	4	91.5%	5	2	60.0%	47	17	63.8%
173	96	5	2	60.0%	47	4	91.5%	5	3	40.0%	47	18	61.7%
174		5	0	100.0%	47	3	93.6%	5	1	80.0%	47	9	80.9%
175	37	5	1	80.0%	47	3	93.6%	5	3	40.0%	47	11	76.6%
176		5	0	100.0%	47	3	93.6%	5	0	100.0%	47	3	93.6%
177	25	5	0	100.0%	47	8	83.0%	5	1	80.0%	47	21	55.3%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		5	0	100.0%	47	7	85.1%	4	0	100.0%	47	5	89.4%
179		5	0	100.0%	47	4	91.5%	4	1	75.0%	47	11	76.6%
181		5	2	60.0%	47	8	83.0%	4	0	100.0%	46	1	97.8%
182		5	1	80.0%	47	10	78.7%	5	0	100.0%	47	3	93.6%
183	33	5	1	80.0%	47	12	74.5%	5	2	60.0%	47	8	83.0%
184	42	5	0	100.0%	47	8	83.0%	5	1	80.0%	47	6	87.2%
185		5	0	100.0%	47	8	83.0%	5	0	100.0%	47	1	97.9%
186		5	0	100.0%	47	7	85.1%	5	1	80.0%	47	13	72.3%
190	32	5	1	80.0%	47	17	63.8%	5	2	60.0%	47	12	74.5%
192		5	0	100.0%	45	6	86.7%	5	0	100.0%	45	1	97.8%
193	35	5	1	80.0%	47	14	70.2%	5	2	60.0%	47	16	66.0%
196		5	0	100.0%	47	0	100.0%	5	0	100.0%	47	2	95.7%
197	104	5	4	20.0%	47	19	59.6%	5	3	40.0%	47	9	80.9%
232		5	0	100.0%	66	1	98.5%	5	0	100.0%	66	6	90.9%
233		5	1	80.0%	66	14	78.8%	5	2	60.0%	66	14	78.8%
234		5	0	100.0%	66	3	95.5%	5	0	100.0%	66	2	97.0%
236		5	0	100.0%	66	1	98.5%	5	0	100.0%	66	11	83.3%
237	20	5	0	100.0%	66	10	84.8%	5	1	80.0%	66	5	92.4%
239		5	2	60.0%	65	17	73.8%	5	0	100.0%	65	2	96.9%
240		5	1	80.0%	66	7	89.4%	5	1	80.0%	66	8	87.9%
241		5	4	20.0%	66	20	69.7%	5	1	80.0%	66	11	83.3%
243		5	1	80.0%	47	17	63.8%	5	0	100.0%	48	8	83.3%
244		5	0	100.0%	66	2	97.0%	5	0	100.0%	66	15	77.3%
280	48	5	0	100.0%	66	3	95.5%	5	3	40.0%	66	13	80.3%
281	30	5	0	100.0%	66	8	87.9%	5	2	60.0%	66	7	89.4%
283		5	2	60.0%	66	10	84.8%	5	0	100.0%	66	9	86.4%
284		5	0	100.0%	66	1	98.5%	5	2	60.0%	66	7	89.4%
290	19	5	0	100.0%	66	18	72.7%	5	1	80.0%	65	22	66.2%
291		5	1	80.0%	66	14	78.8%	5	2	60.0%	66	14	78.8%
300		5	1	80.0%	66	3	95.5%	5	1	80.0%	65	15	76.9%
301		5	0	100.0%	65	1	98.5%	5	0	100.0%	64	9	85.9%
305		5	2	60.0%	66	7	89.4%	4	1	75.0%	64	21	67.2%
306	183	5	1	80.0%	65	3	95.4%	5	4	20.0%	64	15	76.6%
307	112	5	1	80.0%	65	6	90.8%	5	3	40.0%	65	14	78.5%
311		5	2	60.0%	65	9	86.2%	5	3	40.0%	65	17	73.8%
316		5	1	80.0%	65	4	93.8%	5	1	80.0%	65	13	80.0%
318		5	1	80.0%	66	10	84.8%	5	3	40.0%	65	28	56.9%
319		5	0	100.0%	66	2	97.0%	5	0	100.0%	66	36	45.5%
329		5	0	100.0%	47	1	97.9%	5	1	80.0%	47	3	93.6%
330		5	0	100.0%	56	2	96.4%	5	2	60.0%	56	3	94.6%
331		5	3	40.0%	66	7	89.4%	5	2	60.0%	66	8	87.9%
332		5	1	80.0%	66	6	90.9%	5	2	60.0%	66	7	89.4%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334	14	5	1	80.0%	66	2	97.0%	5	4	20.0%	65	8	87.7%
335		5	3	40.0%	66	10	84.8%	4	0	100.0%	64	9	85.9%
336		5	0	100.0%	66	1	98.5%	5	1	80.0%	66	5	92.4%
337		5	0	100.0%	66	4	93.9%	5	1	80.0%	66	6	90.9%
338		5	1	80.0%	66	16	75.8%	4	2	50.0%	64	14	78.1%
339	47	5	2	60.0%	66	16	75.8%	5	2	60.0%	66	13	80.3%
341	130	5	1	80.0%	65	10	84.6%	5	2	60.0%	65	10	84.6%
342	38	5	1	80.0%	66	7	89.4%	5	2	60.0%	65	10	84.6%
350	29	5	0	100.0%	48	2	95.8%	5	2	60.0%	48	24	50.0%
351	48	5	1	80.0%	66	4	93.9%	5	2	60.0%	66	28	57.6%
352	51	5	0	100.0%	66	4	93.9%	5	2	60.0%	64	16	75.0%
353	156	5	0	100.0%	45	2	95.6%	5	4	20.0%	45	9	80.0%
354	84	5	1	80.0%	66	4	93.9%	5	5	0.0%	66	19	71.2%
355		5	1	80.0%	66	6	90.9%	5	0	100.0%	66	13	80.3%
364	63	5	2	60.0%	66	7	89.4%	5	3	40.0%	66	11	83.3%
365	166	5	0	100.0%	66	2	97.0%	5	3	40.0%	66	19	71.2%
370		5	0	100.0%	66	2	97.0%	5	0	100.0%	66	9	86.4%
371		5	0	100.0%	66	0	100.0%	5	0	100.0%	66	4	93.9%
380		5	1	80.0%	66	11	83.3%	5	0	100.0%	66	13	80.3%
381		5	1	80.0%	66	2	97.0%	5	2	60.0%	66	9	86.4%
382		5	0	100.0%	66	2	97.0%	5	1	80.0%	66	16	75.8%
383		5	0	100.0%	66	5	92.4%	5	4	20.0%	65	26	60.0%
392	62	5	0	100.0%	66	2	97.0%	5	4	20.0%	65	19	70.8%
393	60	5	0	100.0%	66	5	92.4%	5	1	80.0%	65	16	75.4%
417		5	0	100.0%	44	8	81.8%	5	0	100.0%	42	1	97.6%
425		5	0	100.0%	44	1	97.7%	5	0	100.0%	44	1	97.7%
448	62	5	4	20.0%	7	5	28.6%	5	4	20.0%	6	4	33.3%
449	44	5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
470		5	1	80.0%	47	6	87.2%	5	0	100.0%	47	7	85.1%
471		5	1	80.0%	44	1	97.7%	5	0	100.0%	44	0	100.0%
473		5	0	100.0%	47	3	93.6%	5	0	100.0%	47	1	97.9%
474	24	5	2	60.0%	45	15	66.7%	5	2	60.0%	42	13	69.0%
475		5	0	100.0%	47	0	100.0%	5	0	100.0%	47	1	97.9%
478		5	0	100.0%	45	10	77.8%	5	0	100.0%	45	6	86.7%
479		5	1	80.0%	47	5	89.4%	5	0	100.0%	47	1	97.9%
486		5	0	100.0%	48	7	85.4%	5	1	80.0%	47	7	85.1%
490		5	1	80.0%	24	6	75.0%	5	0	100.0%	24	2	91.7%
494		5	0	100.0%	49	9	81.6%	5	2	60.0%	46	9	80.4%
495		5	0	100.0%	47	2	95.7%	5	0	100.0%	47	1	97.9%
500		5	1	80.0%	66	6	90.9%	5	1	80.0%	65	6	90.8%
502		5	0	100.0%	66	6	90.9%	5	1	80.0%	65	17	73.8%
503		5	0	100.0%	63	8	87.3%	5	1	80.0%	62	16	74.2%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		5	1	80.0%	66	6	90.9%	5	2	60.0%	66	21	68.2%
505		5	2	60.0%	66	12	81.8%	5	1	80.0%	64	14	78.1%
506		5	1	80.0%	65	10	84.6%	5	0	100.0%	64	9	85.9%
507		5	1	80.0%	66	8	87.9%	5	1	80.0%	66	23	65.2%
508		5	1	80.0%	64	12	81.3%	5	2	60.0%	64	15	76.6%
509	17	5	1	80.0%	66	5	92.4%	5	2	60.0%	66	15	77.3%
511	68	5	1	80.0%	66	5	92.4%	5	1	80.0%	66	13	80.3%
516		5	0	100.0%	66	9	86.4%	5	2	60.0%	66	30	54.5%
517		5	0	100.0%	66	1	98.5%	5	2	60.0%	65	24	63.1%
518	28	5	0	100.0%	66	13	80.3%	5	4	20.0%	66	40	39.4%
519		5	0	100.0%	66	3	95.5%	5	1	80.0%	66	10	84.8%
520		5	1	80.0%	43	4	90.7%	4	0	100.0%	42	2	95.2%
521		5	0	100.0%	46	0	100.0%	5	1	80.0%	46	4	91.3%
522		5	3	40.0%	46	7	84.8%	4	1	75.0%	45	5	88.9%
523	13	5	0	100.0%	46	0	100.0%	5	3	40.0%	46	7	84.8%
524		5	0	100.0%	46	2	95.7%	5	1	80.0%	46	4	91.3%
525		5	0	100.0%	46	1	97.8%	4	1	75.0%	45	6	86.7%
526		5	3	40.0%	46	9	80.4%	4	1	75.0%	45	5	88.9%
527		5	0	100.0%	46	1	97.8%	5	1	80.0%	46	3	93.5%
528		5	1	80.0%	46	6	87.0%	5	2	60.0%	46	12	73.9%
529		5	2	60.0%	46	5	89.1%	5	1	80.0%	46	8	82.6%
531		5	0	100.0%	46	1	97.8%	5	2	60.0%	46	5	89.1%
532		5	0	100.0%	46	1	97.8%	5	0	100.0%	46	7	84.8%
534		5	1	80.0%	43	6	86.0%	5	1	80.0%	43	4	90.7%
535		4	2	50.0%	42	3	92.9%	3	0	100.0%	41	1	97.6%
536		5	0	100.0%	46	4	91.3%	4	0	100.0%	45	1	97.8%
537		5	1	80.0%	46	4	91.3%	4	1	75.0%	45	2	95.6%
538		5	0	100.0%	46	6	87.0%	5	2	60.0%	46	7	84.8%
540		5	2	60.0%	46	6	87.0%	5	1	80.0%	44	2	95.5%
541	16	5	1	80.0%	46	6	87.0%	5	2	60.0%	46	13	71.7%
542		5	0	100.0%	46	3	93.5%	5	1	80.0%	45	11	75.6%
543		5	0	100.0%	46	6	87.0%	5	0	100.0%	46	12	73.9%
544		5	0	100.0%	45	2	95.6%	5	2	60.0%	45	6	86.7%
545		5	0	100.0%	46	4	91.3%	5	1	80.0%	45	5	88.9%
546		5	0	100.0%	46	6	87.0%	5	2	60.0%	46	7	84.8%
547		5	0	100.0%	46	4	91.3%	5	2	60.0%	46	9	80.4%
548		5	1	80.0%	46	9	80.4%	5	1	80.0%	46	6	87.0%
549		5	2	60.0%	43	12	72.1%	4	0	100.0%	41	6	85.4%
551		5	2	60.0%	46	8	82.6%	5	1	80.0%	44	7	84.1%
562		5	2	60.0%	64	10	84.4%	5	1	80.0%	63	7	88.9%
564		5	1	80.0%	64	7	89.1%	5	1	80.0%	61	11	82.0%
566		5	0	100.0%	64	5	92.2%	5	0	100.0%	61	6	90.2%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572		5	0	100.0%	63	6	90.5%	5	0	100.0%	62	14	77.4%
573		5	0	100.0%	64	9	85.9%	5	0	100.0%	63	8	87.3%
577		5	0	100.0%	62	5	91.9%	5	1	80.0%	58	3	94.8%
580		5	0	100.0%	64	2	96.9%	5	0	100.0%	64	7	89.1%
581		5	0	100.0%	64	7	89.1%	5	1	80.0%	64	13	79.7%
582		5	1	80.0%	64	5	92.2%	5	0	100.0%	62	4	93.5%
586		5	3	40.0%	64	14	78.1%	5	0	100.0%	61	9	85.2%
587		5	0	100.0%	64	3	95.3%	5	0	100.0%	62	9	85.5%
591		5	0	100.0%	64	1	98.4%	5	0	100.0%	64	6	90.6%
593		5	0	100.0%	64	9	85.9%	5	0	100.0%	58	5	91.4%
595		5	1	80.0%	63	15	76.2%	5	0	100.0%	62	10	83.9%
600		5	0	100.0%	47	1	97.9%	5	0	100.0%	47	4	91.5%
601		5	4	20.0%	47	23	51.1%	5	0	100.0%	47	13	72.3%
605		5	5	0.0%	47	26	44.7%	5	1	80.0%	46	3	93.5%
607		5	0	100.0%	47	3	93.6%	5	1	80.0%	46	2	95.7%
609		5	0	100.0%	46	1	97.8%	5	0	100.0%	46	3	93.5%
620		5	3	40.0%	46	12	73.9%	5	0	100.0%	44	2	95.5%
624		5	1	80.0%	47	11	76.6%	4	1	75.0%	47	10	78.7%
639		5	3	40.0%	47	13	72.3%	5	0	100.0%	47	4	91.5%
640	20	5	1	80.0%	47	3	93.6%	5	5	0.0%	47	23	51.1%
641	21	5	4	20.0%	47	9	80.9%	5	1	80.0%	47	8	83.0%
642		5	1	80.0%	46	3	93.5%	5	1	80.0%	46	5	89.1%
643	14	5	1	80.0%	47	8	83.0%	5	2	60.0%	46	5	89.1%
644		5	0	100.0%	47	5	89.4%	5	1	80.0%	47	6	87.2%
645		5	0	100.0%	47	3	93.6%	5	2	60.0%	47	8	83.0%
646	15	5	1	80.0%	47	8	83.0%	5	4	20.0%	46	24	47.8%
647		5	0	100.0%	47	2	95.7%	5	0	100.0%	47	12	74.5%
648		5	3	40.0%	47	9	80.9%	5	1	80.0%	47	5	89.4%
649		5	2	60.0%	47	8	83.0%	5	0	100.0%	46	7	84.8%
650	14	5	1	80.0%	47	10	78.7%	5	3	40.0%	47	10	78.7%
651	13	5	0	100.0%	47	5	89.4%	5	2	60.0%	47	15	68.1%
652	25	5	1	80.0%	47	9	80.9%	5	2	60.0%	46	10	78.3%
653		5	1	80.0%	47	9	80.9%	5	0	100.0%	47	14	70.2%
654		5	3	40.0%	47	8	83.0%	5	1	80.0%	47	3	93.6%
655	78	5	3	40.0%	45	15	66.7%	5	2	60.0%	44	10	77.3%
656		5	3	40.0%	47	10	78.7%	5	0	100.0%	47	5	89.4%
657		5	0	100.0%	47	3	93.6%	5	0	100.0%	47	9	80.9%
658	13	5	1	80.0%	47	8	83.0%	5	1	80.0%	47	7	85.1%
680	13	5	0	100.0%	48	2	95.8%	5	1	80.0%	48	4	91.7%
681	34	5	0	100.0%	48	2	95.8%	5	1	80.0%	48	14	70.8%
682	40	5	0	100.0%	48	0	100.0%	5	1	80.0%	48	11	77.1%
683	11	5	0	100.0%	31	3	90.3%	5	1	80.0%	31	10	67.7%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

25-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684		5	0	100.0%	30	4	86.7%	5	0	100.0%	30	8	73.3%
685		5	1	80.0%	47	5	89.4%	5	0	100.0%	47	13	72.3%
686	42	5	1	80.0%	48	14	70.8%	5	2	60.0%	48	12	75.0%
687	53	5	1	80.0%	48	7	85.4%	5	2	60.0%	48	8	83.3%
688	24	5	0	100.0%	48	1	97.9%	5	1	80.0%	48	13	72.9%
689		3	0	100.0%	39	4	89.7%	2	0	100.0%	38	3	92.1%
702		5	2	60.0%	66	17	74.2%	5	2	60.0%	65	21	67.7%
703		5	0	100.0%	66	15	77.3%	5	1	80.0%	66	17	74.2%
710		5	3	40.0%	66	27	59.1%	5	0	100.0%	66	28	57.6%
711		5	0	100.0%	62	4	93.5%	5	2	60.0%	58	9	84.5%
712		5	1	80.0%	66	18	72.7%	5	1	80.0%	65	24	63.1%
713		5	0	100.0%	66	9	86.4%	5	1	80.0%	60	28	53.3%
714		5	1	80.0%	60	20	66.7%	5	0	100.0%	55	16	70.9%
715	37	5	1	80.0%	66	23	65.2%	4	3	25.0%	62	32	48.4%
716		5	1	80.0%	66	24	63.6%	5	2	60.0%	65	25	61.5%
717		5	1	80.0%	57	14	75.4%	5	2	60.0%	52	15	71.2%
718		5	3	40.0%	66	25	62.1%	5	1	80.0%	66	17	74.2%
719	22	5	1	80.0%	66	25	62.1%	5	1	80.0%	64	17	73.4%
761		5	0	100.0%	64	3	95.3%	5	0	100.0%	64	9	85.9%
765		5	1	80.0%	64	8	87.5%	5	0	100.0%	64	13	79.7%
769		5	0	100.0%	64	4	93.8%	5	0	100.0%	62	11	82.3%
770		5	0	100.0%	64	7	89.1%	5	0	100.0%	64	9	85.9%
774		5	0	100.0%	64	6	90.6%	5	0	100.0%	63	11	82.5%
779		5	0	100.0%	64	4	93.8%	5	0	100.0%	63	9	85.7%
784	32	5	1	80.0%	64	7	89.1%	5	4	20.0%	63	33	47.6%
785		5	0	100.0%	64	0	100.0%	5	0	100.0%	64	7	89.1%
790	No OS	5	0	100.0%	64	5	92.2%	5	1	80.0%	64	8	87.5%
794		5	1	80.0%	64	6	90.6%	5	0	100.0%	63	10	84.1%
821		5	0	100.0%	66	3	95.5%	5	2	60.0%	66	42	36.4%
822		5	0	100.0%	66	3	95.5%	5	1	80.0%	66	45	31.8%
1333		5	3	40.0%	66	7	89.4%	5	3	40.0%	65	29	55.4%
1340	16	5	0	100.0%	66	3	95.5%	5	2	60.0%	66	15	77.3%
2103		5	0	100.0%	46	3	93.5%	5	0	100.0%	46	1	97.8%
2104		5	1	80.0%	17	3	82.4%	5	1	80.0%	17	3	82.4%
2107		5	0	100.0%	47	7	85.1%	5	1	80.0%	45	1	97.8%
2108	29	5	0	100.0%	47	2	95.7%	5	1	80.0%	45	1	97.8%
2117		5	2	60.0%	17	5	70.6%	5	2	60.0%	17	3	82.4%
2121		5	1	80.0%	45	4	91.1%	5	0	100.0%	45	3	93.3%
2122		5	0	100.0%	47	6	87.2%	5	0	100.0%	47	3	93.6%
2130		1	0	100.0%	11	0	100.0%	1	0	100.0%	11	2	81.8%
2150		5	0	100.0%	47	9	80.9%	5	0	100.0%	47	9	80.9%
2151		5	0	100.0%	47	0	100.0%	5	1	80.0%	46	7	84.8%

Amtrak On Time Performance

Trains Arriving Through: 12/5/2025

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2152	86	5	1	80.0%	43	3	93.0%	5	3	40.0%	42	12	71.4%
2153		5	0	100.0%	47	6	87.2%	5	1	80.0%	47	10	78.7%
2154	25	5	2	60.0%	47	16	66.0%	5	4	20.0%	45	25	44.4%
2155	44	5	1	80.0%	47	3	93.6%	5	3	40.0%	45	12	73.3%
2159	24	5	0	100.0%	46	1	97.8%	5	3	40.0%	46	10	78.3%
2162		5	0	100.0%	47	2	95.7%	5	2	60.0%	46	11	76.1%
2163		5	0	100.0%	47	4	91.5%	5	1	80.0%	47	11	76.6%
2166		5	0	100.0%	47	5	89.4%	5	0	100.0%	45	6	86.7%
2167	25	5	0	100.0%	47	5	89.4%	5	1	80.0%	47	9	80.9%
2168		5	0	100.0%	47	2	95.7%	5	0	100.0%	47	6	87.2%
2169	109	5	3	40.0%	43	13	69.8%	5	3	40.0%	43	18	58.1%
2170		5	3	40.0%	47	10	78.7%	5	2	60.0%	47	11	76.6%
2172	19	5	0	100.0%	47	6	87.2%	5	2	60.0%	47	9	80.9%
2173		5	2	60.0%	46	9	80.4%	5	0	100.0%	46	18	60.9%
2190	Cncld	5	1	80.0%	47	6	87.2%	4	0	100.0%	46	4	91.3%
2193		5	0	100.0%	46	1	97.8%	5	1	80.0%	46	10	78.3%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/5/2025

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2108	NYP	29	ENG	33	ENG	33	BAL-BAL	AM	Other electrical failure, 2016, STOPPED ON 6 STATION TRACK WITH LOW MAIN RESERVOIR FAULT.	
2152	BOS	86	CAR	54	CAR	33	WIL-WIL	AM	Door, 3361, door issues. gap filler.	
2154	BOS	25	DCS	26	DCS	26	NHV-XGX	AM	T.O.L, Control Point, Shoreline JCT-Branford, TOL reappeared on trk 2 Shoreline JCT to Branford	
2155	WAS	44	DBB	24	DBB	22	XGX-NHV	AM	Stuck open bridges, Bridge, Shaw's Cove, Bridge Malfunction	
2159	WAS	24	PTI	10	PTI	5	BAL-BWI	AM	Follow, 171, Milepost, 95.7, 106.3	
2167	WAS	25	DCS	18	DSR	9	NHV-STM	MN	Per bulletin Other, cat 533-535, 15, 2	
2169	WAS	109	ITI	72	ITI	72	BOS-BOS	AM	Service, turn, or wye train, 2154, AM2169 departed BOS late due to late turn of AM2154	
2172	BOS	19	CTP	29	CTP	29	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN	
2190	BOS	Trn Cancelled								
66	BOS	41	DCS	22	DCS	22	NYP-XSH	AM	Power switch failure, Other, XGG-XPB, SPLIT TRAFFIC A/C CSXLO17 AT HANDSWITCH AT MP 12.2, C&S ON SCENE.	
85	RVM	18	FTI	24	FTI	24	RVR-RVM	CS	Cross over or go around Route blocked AY to South AY. Routed to West AY and reversed into RVM, ???, Control Point, AY	
134	NYP	149	DCS	127	DCS	62	RNK-LYH	NS	Power switch failure Frozen switch, Control Point, Monview	
137	WAS	54	CTP	52	CTP	23	XSH-NYP	AM	Delay due to mechanical problems on a Commuter train, HAROLD HELD NO TRACK SPACE A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN	
141	NFK	21	FTI	20	CAR	12	PHL-PHL	AM	Toilet, 43390, clogged toilet.	
170	BOS	16	DCS	18	DCS	18	NHV-NLC	AM	T.O.L, Other, SLJ-BNF	
171	RNK	22	SVS	16	SVS	16	WAS-WAS	AM	Planned Switch, DSL LATE COMING FROM PIT DUE TO HIGH DSL SHOP COUNT	
173	WAS	96	ENG	42	ENG	42	NYP-NYP	AM	HEP, 650, MULTIPLE MECHANICAL ISSUES	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
175	WAS	37	DSR	19	CTP	18	NYP-NWK	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN
177	PHL	25	CTI	15	POL	10	NRO-NRO	MN	Removal of passenger by police
183	WAS	33	WTR	28	WTR	23	NYP-NYP	AM	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C FROZEN PIPES
184	BOS	42	OTH	25	SYS	17	MYS-WLY	AM	Copy authority / restriction, Stop and Protect WALKERS DOCK & FREEMANS ISLAND
190	BOS	32	DBB	19	DBB	19	XGX-MYS	AM	Stuck open bridges, Bridge, Thames River , Bridge Malfuction
193	WAS	35	PTI	9	PTI	9	XPV-ABE	AM	Follow, 173, Milepost, 62.9, 65.5
197	WAS	104	ITI	97	ITI	97	NYP-NYP	AM	Service, turn, or wye train, 134, LATE F/SSYD LATE TURN OFF AM134
474	SPG	24	CON	16	CON	16	NHV-NHV	AM	Hold for connecting train, AM474 departed late due to late connection of AM174 NHV
640	NYP	20	MTI	16	MTI	16	NWK-NYP	AM	Disabled train ahead, Other, NWK-NYP, CONGESTION A/C AM170 WITH ACSES PENALTY IN "A" INT
641	HAR	21	WTR	30	WTR	27	NYP-NYP	AM	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C FROZEN PIPES
643	HAR	14	PTI	13	PTI	9	NWK-TRE	AM	Follow, AM185, Other, MENLO-TRE
646	NYP	15	WTR	9	WTR	5	PAO-PHL	AM	Wet / slippery rail, Control Point, .
650	NYP	14	BSP	18	BSP	18	PJC-NWK	AM	Bridge strike, Other, PENNINGTON ST
651	HAR	13	CTI	7	POL	7	NWK-NWK	AM	Removal of passenger by police, POLICE ACTION F/UNRULY PSGR
652	NYP	25	CTP	32	CTP	32	NWK-NYP	AM	Delay due to mechanical problems on a Commuter train, CONGESTION NO TRACK SPACE A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN
655	HAR	78	CTP	68	CTP	57	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, LATE ARRIVAL NO TRACK SPACE A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN
658	NYP	13	PTI	7	RTE	6	TRE-NWK	AM	Routed to abnormal station track due to N.A.R., N/A, Other, MENLO-X94, OPR 1 TRK
680	BON	13	CCR	11	CCR	9	XP0-HHL	MT	Cab signal failure 90224, Cutting out cab signals

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
681	BRK	34	DCS	45	DCS	19	WOB-HHL	MT	Restrictive signal(s) from unknown cause Rule 241, cab signals remained restricting until River, Control Point, FR
682	BON	40	SYS	18	SYS	8	POR-POR	CS	Copy authority / restriction
683	BRK	11	PTI	9	PTI	5	EXR-DHM	CS	Meet 684, Control Point, Rockingham
686	BON	42	SVS	17	SVS	12	FRE-POR	CS	Unplanned Wye Had to wye train due to ACSES failure, Control Point, mountain
687	BRK	53	ITI	59	ITI	59	BON-BON	MT	Service, turn, or wye train 686, Had to wait for commuter traffic to wye train in Boston
688	BON	24	PTI	24	PTI	21	WEM-DOV	CS	Meet 687, Control Point, Dover East
237	ALB	20	PTI	18	PTI	18	HUD-ALB	AM	Wait for station track 449, Other, alb station
280	NYP	48	CTI	23	CTI	16	POU-CRT	MN	Follow mn, Control Point, 72
281	NFL	30	FTI	29	SYS	24	ALB-ALB	AM	PTC problem or failure (cause unknown) Unable to initialize I-Etrms due to csx system outage., Other, alb
290	NYP	19	CTI	24	CTI	21	POU-CRT	MN	Follow metro, 874, Milepost, 72, 39
48	NYP	45	FTI	60	PTI	16	UCA-XHF	AM	Meet 281, Control Point, 169
448	BOS	44	SVS	35	SVS	35	ALB-ALB	AM	Switch out engine Other, ALB
449	ALB	44	PTI	30	PTI	30	SPG-PIT	CS	Meet 448, Control Point, 148
72	RGH	11	PTI	15	PTI	15	HPT-GRO	NS	Meet Account M of W equipment on trk one, #amt73, Control Point, Cox
73	CLT	15	RTE	9	RTE	9	RGH-RGH	NS	Dispatcher hold Waited on signal at Boylan. #AMTK40 to arrive at station., Milepost, 81.1, 81.1
76	RGH	12	PTI	22	PTI	22	GRO-DNC	NS	Meet #Am79, Control Point, Isom
77	CLT	11	DBS	17	DBS	17	BNC-GRO	NS	Animal strike Hit a dog. Hose separation (main res and brake pipe) between cafe car and first coach., Milepost w/Letters, 19.2 NC, 19.2 NC
98	NYP	86	PTI	64	INJ	39	RMT-PTB	CS	Injured or sick passenger EMS called and met at A71.9
55	WAS	61	CTP	45	CTP	19	NYP-NWK	AM	Delay due to mechanical problems on a Commuter train
40	CHI	102	CAR	85	CAR	85	MIA-MIA	FL	Set out defective car 28023
41	MIA	73	PTI	65	PTI	52	DNK-SAV	CS	Meet 40, 692, Siding, Stillwell
23	NOL	42	FTI	93	FTI	50	BAS-XNO	CS	Follow 521, Milepost w/Letters, bas, michoud

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/5/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
523	SJC	13	DCS	12	DCS	12	OKJ-OAC	UP	Power switch failure Control Point, NI010
541	SJC	16	PTI	14	PTI	14	GAC-SCC	UP	Meet Expressway shuffle with Amtrak 538 despite plenty of time to clear Coast before their departure from SCC., Amtrak 538, Control Point, CO044
50	NYP	92	FTI	63	FTI	32	STA-CVS	BB	Meet E 895, Siding, Afton
509	PDX	17	CTI	11	CTI	11	TAC-XNI	ST	Cross Traffic sound transit, Control Point, prairie jct
511	PDX	68	ENG	26	ENG	26	SEA-SEA	BN	Cab Car 90251 Had no MAP 100. Waited for mechanical to give us the paperwork. 90251
518	VAC	28	FTI	24	FTI	24	BEL-BEL	BN	Cross Traffic They had to add another engine, BN7771, Control Point, BEL
58	CHI	47	FTI	39	PTI	27	FTN-CDL	CC	Meet 59, Siding, Anna
8	CHI	52	FTI	93	CAR	47	MOT-RUG	BN	Adding a car just east of MOT station 39019
334	CHI	14	CTI	13	CTI	10	GLN-XWA	ME	Follow Metra, 2132, Milepost, 13.1, 6.4
339	MKE	47	CTI	33	ENG	21	CHI-CHI	AM	Air / Brake During mechanical inspection, it was discovered that a pin fell out of the brake cylinder assembly. It took some time to repair it and complete daily tests., 514
341	MKE	130	CAR	126	CAR	126	CHI-CHI	AM	Add car 34094
342	CHI	38	DBS	28	DBS	28	XRO-GLN	ME	Debris blocking track (no debris strike) Car on tracks, Other, SHERMER RD
350	PNT	29	FTI	23	FTI	23	DET-DET	CC	Meet up6399, Control Point, BEAUBIEN
351	CHI	48	SYS	48	SYS	48	PNT-PNT	CC	Other late crew Late call to extra board engineer
352	PNT	51	SYS	62	SYS	37	BTL-BTL	CC	Crew rest
353	CHI	156	ENG	130	ENG	102	DET-X1W	CC	Air / Brake Brake caliper on axle three stuck on wheel causing hot wheel and also hot journal alarm. Instructed to cut out bb truck and release pressure from caliper assembly., ID4613
354	PNT	84	ENG	57	ENG	57	CHI-CHI	AM	Loading problem ID4601
364	PTH	63	SVS	42	SVS	42	CHI-XTF	AM	Fuel Fueling rear engine 4632, Other, Lumber St

Amtrak Endpoint OTP Details

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/5/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
365	CHI	166	DBS	102	DBS	102	DRD-LNS	CC	Debris strike Fireman side plow dropped 4-5 inches after hitting road. All three bolts loosened. Tried to tighten with pipe wrench needed socket on back side. CN mechanical in rout. Engine 4632, Road Crossing, Milepost, 238.73, 237.26	
784	SAN	32	CTI	42	PTI	16	SNC-SNP	SC	Meet Amtk 587, Control Point, Serra	
790	SAN	No OS Rpt	CTI	11	CTI	8	CML-XMR	UP	Meet ml, 127, Control Point, co 415	
715	OKJ	37	PTI	38	PTI	12	WAC-COC	BN	Meet 710, Milepost, 931, 931	
719	OKJ	22	PTI	22	DCS	12	MCD-TRK	BN	Restrictive signal(s) from unknown cause Stop, Control Point, w mcd	
3	LAX	49	DCS	82	DCS	58	PCT-GBB	BN	PTC- I-ETMS Red Fence/Signal Status Unknown Control Point, Buda	
4	CHI	166	FTI	134	PTI	45	LMY-LSV	BN	Meet AMTK # 3, Siding, FOX	
306	CHI	183	POL	210	POL	210	STL-STL	TR	Right of Way police hold	
307	STL	112	SYS	142	SYS	142	JOL-DWT	UP	Blocked by or assisting another, disabled Amtrak train Control Point, X045	
392	CHI	62	PTI	64	PTI	39	MAT-CHM	CC	Meet amtrak 393, Control Point, tolono	
393	CDL	60	DCS	62	DCS	47	RTL-CHM	CC	Restrictive signal(s) from unknown cause Flag s rtl Clr leverette jct, Milepost, 115.8, 124.1	
1340	CHI	16	CTI	11	CTI	11	GLN-XWA	ME	Follow Metra, 2150, Control Point, XWA	

Amtrak Initial Terminal Details

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/5/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	648	12/05	4	4	Other electrical failure, 642, received penalty in station, had to hit the button
HAR	650	12/05	1		
HAR	658	12/05	2	2	PTC - Stop Bypass Permission Required, Control Point, ., E/642
PHL	110	12/05	1		
PHL	601	12/05	1		
PHL	605	12/05	3	3	PTC - Stop Bypass Permission Required, Control Point, PENN, STOP BY PASS TWICE
RGH	73	12/05	9	9	Dispatcher hold Waited on signal at Boylan. #AMTK40 to arrive at station., Milepost, 81.1, 81.1
RNK	134	12/05	34	34	Power switch failure Switch frozen., Control Point, Randolph
WAS	170	12/05	2	2	HEP, 635, Headlight malfunction; mechanical technician corrected the problem
WAS	2152	12/05	6	6	Door, 3361, 3656, faults preventing HEP
ALB	448	12/04	53	18	Late train
ALB	448	12/04	53	35	Switch out engine Other, ALB
BON	687	12/05	22	59	Service, turn, or wye train 686, Had to wait for commuter traffic to wye train in Boston
BOS	65	12/05	8	8	Other electrical failure, 626, AM65 dp BOS 6" late a/c TL issues on e/626 & e/96
BOS	137	12/05	3	3	Service, turn, or wye train, 190, Late turn
BOS	173	12/05	22	22	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard
BOS	2169	12/05	72	72	Service, turn, or wye train, 2154, AM2169 departed BOS late due to late turn of AM2154
BOS	2173	12/05	1		
BRK	686	12/05	8	8	Service, turn, or wye train 681
NYP	51	12/05	23	23	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C FROZEN PIPES
NYP	63	12/05	5	5	Passenger and/or baggage, LOADING
NYP	79	12/05	4	4	Passenger and/or baggage, TRAVEL
NYP	97	12/05	14	14	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY CATERING
NYP	129	12/05	6	6	Service, turn, or wye train, 114, LATE F/SSYD LATE TURN OFF AM114
NYP	183	12/05	23	23	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C FROZEN PIPES
NYP	193	12/05	5	5	Service, turn, or wye train, 84, LATE F/SSYD LATE TURN OFF AM84

Amtrak Initial Terminal Details

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/5/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	197	12/05	97	97	Service, turn, or wye train, 134, LATE F/SSYD LATE TURN OFF AM134
NYP	239	12/05	5	5	Passenger and/or baggage, LOADING
NYP	639	12/05	4	4	Passenger and/or baggage, LOADING
NYP	641	12/05	27	27	Ice / snow on or under equipment, Other, NYP, LATE F/SSYD A/C FROZEN PIPES
NYP	643	12/05	2	2	Passenger and/or baggage, LOADING
NYP	655	12/05	57	57	Delay due to mechanical problems on a Commuter train, LATE ARRIVAL NO TRACK SPACE A/C NJ3267 W/PANTOGRAPH DAMAGE AT BERGEN
NYP	2121	12/05	11	11	Service, turn, or wye train, 2108, LATE TURN OFF AM2108
NYP	2190	12/05	(Trn Cxld)		Engine Issue
SPG	471	12/05	5	5	Mobility Impaired, Late psgr boarding
CHI	21	12/05	3	3	Other late crew
CHI	48	12/05	322		
CHI	305	12/05	8	8	Air / Brake ID4607
CHI	307	12/05	84	84	Service, turn, or wye train 353
CHI	331	12/05	6	6	Routine inspections Engine inspections being done by mechanical department, blue flag protection down, departure test and class II brake test preformed, Milepost, 0.29, 0.29
CHI	339	12/05	21	21	Air / Brake During mechanical inspection, it was discovered that a pin fell out of the brake cylinder assembly. It took some time to repair it and complete daily tests., 514
CHI	341	12/05	126	126	Add car 34094
KCY	316	12/05	1	1	Loading problem 63
MKE	342	12/05	8	8	Service, turn, or wye train 339
PNT	351	12/05	48	48	Other late crew Late call to extra board engineer
QCY	380	12/05	10	10	Waited to see what BNSF, Chicago Division GO 41, from 12/4/25, was. It came out after we left yesterday. Tried calling BNSF, Amtrak's GB office and then Road Forman Control Point, WCY
SEA	505	12/05	1		
SEA	511	12/05	52	26	Cab Car 90251 Had no MAP 100. Waited for mechanical to give us the paperwork. 90251
SEA	511	12/05	52	26	Crew rest Train was delayed due to not having an engineer to shove back to the station. Crew waited for engineers who was signing off on his rest @7:45. Crew was able to shove train to depot., Other, Holgate Yard
STL	306	12/05	210	210	Right of Way police hold

Amtrak Initial Terminal Details

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/5/2025

Terminal	Train	Date	Late	Delay	Cause
BFD	715	12/05	4	4	Door C9801, Couldn't get a door light on this car at the start of the trip.
BFD	717	12/05	1	1	Meet Ready for on time departure 14:12. Waiting for 710, 710, Control Point, Amtrak Lead
OKJ	522	12/05	7	7	Loading problem No door lights, C2124
OKJ	540	12/05	2	2	Late leaving yard due to last minute adding oil C2012
OKJ	710	12/05	6	6	Meet AMTK 524, Control Point, Magnolia

Eastern Region

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No data	No data	94.8	No data	No data
CDOT	95.0	No data	No data	92.4	No data	No data
MARC	95.0	87.9	90.3	90.2	58	7
SEPTA	95.0	94.5	99.5	91.5	218	12
NJT-NED	95.0	84.6	90.1	93.8	370	57
NJT-SED	95.0	100	100	97.2	24	0

Operating Highlights

Train 19(05) Lynchburg, VA - Police Related

06DEC25: Train 19(05) operating with engines 376, 198, and 8 cars was delayed departing Lynchburg, VA on the Norfolk Southern Washington District due to police removing an unruly passenger on the train.

Train	Delay	Comment
19(05)	57"	

Train 51(05) West of Hinton, WV - Engine Failure

05DEC25: At approximately 6:45 p.m. ET, Train 51(05), carrying 128 passengers, experienced a loss of Head-End Power 11 miles west of Hinton, WV at milepost 366.3 on the CSX New River subdivision due to wire damage between cars 62502 and 28024. All passengers were reported comfortable and the ambient temperature outside was 31 degrees. The train proceeded without lighting to Princeton, WV in an attempt to perform a short loop to restore HEP; however, the crew reported a high-voltage engine fault on Locomotive 190. HEP was subsequently placed in standby mode with intermittent functionality, and the train continued toward Charleston, WV. Train 51(05) terminated in Charleston, where 84 passengers were housed in local hotels and bussed the following day, drop off service only to Chicago. The equipment from Train 51(05) deadheaded to Chicago under traction power. Service recovery was initiated and consisted of snack packs, water, coffee, and tea.

Train	Delay	Comment
51(05)	TERM CHW	

Multiple Trains New York, NY - Commuter Train Problems

05DEC25: Multiple trains were delayed and entered into the New York, NY area on the Amtrak NYP Line due to single tracking after NJ3267 inverted a pantograph due to low hanging catenary.

Train	Delay	Comment
136 (05)	20"	
197 (05)	12"	
175 (05)	18"	
2169 (05)	25"	
655 (05)	11"	
178 (05)	33"	
48 (04)	12"	
55 (05)	19"	
137 (05)	16"	
244 (05)	25"	
652 (05)	32"	
176 (05)	35"	
2172 (05)	29"	
20 (04)	22"	
148 (05)	19"	
2170 (05)	16"	
179 (05)	06"	
2130 (05)	05"	
90 (05)	30"	
192 (05)	13"	
50 (04)	30"	

Train 280(05) West of Poughkeepsie, NY - No TSR Data

05DEC25: Train 280(05) E/103, 6 cars, reported entering MNRR territory at MP75.8 with no TSR Fault on E/103. Engineer attempted to reset at Poughkeepsie, NY, which was unsuccessful. The train accumulated delays operating into New York, NY account of being held to a max 59mph speed restriction due to operating without TSR data.

Train	Delay	Comment
280 (05)	40"	

Initial Terminal Delays New York, NY - Frozen Equipment

05DEC25: Several trains were delayed initial terminal at New York, NY account of weather related frozen pipes reported from SSYD. Train 51(05) delayed 23 minutes, Train 641(05) delayed 27 minutes and Train 183(05) delayed 23 minutes.

Train	Delay	Comment
183(05)	23"	
51(05)	23"	
641(05)	27"	

CSX PTC Unplanned Outage

05DEC25: Trains were delayed due to an unplanned CSX PTC outage. Crews at their initial terminals were unable to synchronize with CSX PTC where required. These trains were held at their locations until the CSX PTC outage concluded and the crews were able to synchronize with CSX PTC.

Train	Delay	Comment
41(03)	20"	
281(05)	27"	
63(05)	37"	

Train 2108(05) Baltimore, MD - Engine Failure

05DEC25: Train 2108(05) E/116, 8 cars, PC2016, was delayed at Baltimore, MD station due to a main reservoir fault on E/2016. Crew worked with an Amtrak Road Foreman to troubleshoot issue. Crew was able to clear the fault, and Train 2108(05) departed north.

Train	Delay	Comment
2108(05)	33"	

Train 23(05) West of Mobile, AL - Freight Train Interference

05DEC25: Train 23(05) was delayed beginning 21 miles west of Mobile, AL between SE St. Elmo/MP687.4 and Michoud/MP793.2 on the CSX NO&M Subdivision, due to following freight unit 521.

Train	Delay	Comment
23(05)	1'33"	

NHB Line - Mystic River Bridge Malfunction

05DEC25: at 10:39A-ET, the New London dispatcher reported Mystic River bridge MP 131.9 on the New Haven to Boston main line would not close after opening for marine traffic. Bridge maintainer was dispatched to the scene. At 1052A-ET, the bridge was able to close on it's own, and rail traffic resumed.

Train	Delay	Comment
93(05)	10"	
190(05)	19"	

NHB Line - Shaws Cove Bridge Malfunction

05DEC25: At 658A-ET the New London dispatcher reported that Shaws Cove bridge MP 122.5 on the New Haven to Boston main line would not close or open. B&B personnel were on scene attempting to make repairs. As of 727A-ET The bridge was locked and rail traffic was able to proceed.

Train	Delay	Comment
2155(05)	24"	
66(04)	19"	
2153(05)	07"	

Train 125(05) North of Hartford, CT - Engine Failure

05DEC25: Train 125(05) E/115, 8 cars, was delayed 1 miles north of Hartford, CT at MP37.1 on the Amtrak MRS Line, due to being unable to provide tractive power. Crew troubleshooted with an Amtrak Road Foreman, cleared an ASC fault, then train 125(05) was able to proceed.

Train	Delay	Comment
125(05)	39"	

Train 2152(05) Wilmington, DE - Door Issue

05DEC25: Next Gen Acc 26-FOI-00167-00000005498 (05) "UNCLASSIFIED" 12/17/2025 PC2124, 9 cars, PC2133, was delayed departing Wilmington, DE due to door issues on car C/3361. Crew was able to troubleshoot in order to proceed. Train also encountered minimal delays at Philadelphia and Baltimore for door issues, in the same car.

Train	Delay	Comment
2152(05)	33"	WIL
2152(05)	06"	BAL
2152(05)	09"	PHL

Train 134(05) Roanoke, VA -Frozen Switch

05DEC25: Train 134(05) was delayed departing Roanoke, VA/MP240 on the NSRR Roanoke Terminal Subdivision, due to a frozen switch at Randolph/MP257.4. Once maintainer arrived on scene to resolve and line the switch, Train 134(05) was able to depart. Train was further delayed at Montview/MP174.6, and Rivermont/MP170.8 account of frozen switches at those locations.

Train	Delay	Comment
134(05)	1'56"	
197(05)	1'37"	ITD -Equip Turn off 134

Train 2190(05) New York, NY - Engine Failure

05DEC25: Train 2190(05) TS14, PC2010, 6 cars, PC2015, experienced a loss of head end power (HEP) on PC2010 while still in the origination station, prior to departing New York, NY. An Amtrak Trainmaster and mechanical forces were on scene to troubleshoot the issue. Unable to rectify the issue, the decision was made to cancel 2190(05) in entirety. Due to no available replacement equipment, Train 2163(05) was also canceled between BOS-NYP.

Train	Delay	Comment
2190(05)	Canceled	
2163(05)	Canceled	BOS-NYP

25FOI-00197 00000005488 UNCLASSIFIED
VIA Oakville Subdivision Oakville, ON - Scheduled M/W Work

UPDATE 03OCT25: To accommodate infrastructure maintenance on the VIA Oakville subdivision at Oakville/MP 21.4. As a result, train 63/7098(18OCT, 02-03NOV, 06DEC-07DEC, 13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay. Train 64/7097(13SEP-14SEP, 27SEP-28SEP, 04OCT-05OCT, 18-19OCT, 02-03NOV, 06DEC-07DEC, 13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay.

WBS#: B.TR.100150.5989

Train	Delay	Comment
64(13)	1'39"	

Eastern Region

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
650		7				phl

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 90(5) Passenger Removal at Richmond, Virginia – Other***

05DEC25, Passenger on PNR 1C117F, traveling from Wilson, NC to Baltimore, MD was removed from the train by the conductor. The passenger was told his attire was inappropriate. Amtrak Police notified.

Delay: 90 (5) None

Train 686(5) Passenger Removal at Freeport, Maine – Other

05DEC25, Passenger on PNR Unknown, traveling from Brunswick, ME to Boston North, MA, was removed from the train by the conductor. The passenger was told by Volunteers of Brunswick that she and child could get on the train and ride for free. Amtrak Police notified.

Delay: 686 (5) None

Train 148(5) Passenger Removal at New Rochelle, New York –Improper Conduct

05DEC25, Passenger on PNR 0BE75D, traveling from New York, NY to Windsor Locks, CT, was self-removed from the train. The passenger was asked to remove belongings from the empty seat, and the passenger became aggressive physically and verbally with the conductor. Amtrak Police notified.

Delay:

148 (5)

09"

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Operating Highlights

Train 48/448(05) - Car Failure

06DEC25: Train 48/448(05) was delayed departing initial terminal of Chicago IL. station on the Amtrak chicago subdivision due to frozen lines on cars 62507, 62042 and 25121. Train 48/448(05) offloaded all passengers at 1010PM CT and equipment was sent back to the yard to thaw the lines. 48/448(05) arrived back to the yard at 1111PM CT and began using heaters to thaw the frozen lines. Mechanical was able to thaw out all of the frozen lines in the yard at 147AM CT. Train 48/448(05) was released from the yard at 218AM and proceeded to the station. 48/448(05) arrived back to Chicago, IL station at 232AM CT. Train 48/448(05) departed Chicago IL station at 252AM CT.

Train	Delay	Comment
48/448(05)	5' '22"	

Train 306(05) St. Louis, MO - Police Related

05DEC25: Train 306(05) was delayed holding at MP1.5 St. Louis, MO. station on the TRRA Merchants subdivision due to a police hold on the tracks at MP274. Train 21(05) was delayed holding at Alton, IL station waiting for police to release tracks. Police released the tracks at 855PM CT. Train 306(05) departed St. Louis MO Station at 910PM CT. Train 21(05) departed Alton, IL station at 857PM CT. A bus was secured for 306(05) passengers from Bloomington IL stations to Chicago IL station.

Train	Delay	Comment
21(05)	2' '22"	
306(05)	3' '30"	

Train 6(04) Denver, CO - M of W Work

05DEC25: Train 6(04) was delayed at MP0.0 Denver, CO. Stations on the BNSF Front Range subdivision due to a switch issue. Maintainers arrived and spiked the switch. Train 6(04) departed Denver 757PM MT.

Train	Delay	Comment
6(04)	55"	

Train 22(05) Texarkana, AR - Freight Train Interference

05DEC25:Train 22(05) was delayed beginning at MP38.2, 38.50 miles south of Texarkana, AR. stations on the UPRR Little Rock subdivision meeting multiple freight trains. Once all the freight trains cleared 22(05) was able to get back up to track speed.

Train	Delay	Comment
22(05)	49"	

Train 392(05) South of Champaign-Urbana, IL - Passenger Train Interference

05DEC25:Train 392(05) was delayed at MP137.5, 9.3 miles south of Champaign IL station on the CN Champaign subdivision due to a meet with train 393(05). Once train 393(05) proceeded south, 392(05) was on the move north into Champaign station.

Train	Delay	Comment
392(05)	39"	

Train 393(05) North of Champaign-Urbana, IL - Signal

05DEC25: Train 393(05) was delayed at MP115.05 miles north of Champaign IL station on the CN Chicago subdivision due to signal issues restricted operating speed to 10MPH. Signal issues persisted until MP124.1, once through the affected area train 393(05) was able to get back up to track speed.

Train	Delay	Comment
393(05)	47"	

Train 3(04) Albuquerque, NM - Engine Failure

05DEC25: Train 3(04) was delayed at MP902.45 Albuquerque, NM station on the BNSF Albuquerque subdivision due to air issues with E/146. Mechanical was on site and was able to repair the air leak on E/146. 3(04) departed Albuquerque station at 507PM MT.

Train	Delay	Comment
3(04)	34"	

Train 4(03) East of Kansas City, MO - Freight Train Interference

05DEC25: Train 4(03) was delayed starting 62.4 miles east of Kansas City, MO/MP6.9, on the BNSF Marceline Subdivision, between Norborne/MP388.8 and the West La Plata siding/MP313.2 following BNSF 7566. Additional delay holding in the La Plata siding to meet westbound BNSF 8107 before the train could proceed into the La Plata station at MP312.7. Train 4(03) received more freight delays starting 60.7 miles east of La Plata, MO/MP312.7 following BNSF 7566 from MP252.0 to MP237.1. At East Fort Madison/MP234.2, located 1.3 miles east of the Fort Madison station/MP232.9, Train 4(03) had to meet BNSF 7460 and BNSF 7247.

Train	Delay	Comment
4(03)	31"	Follow BN7566 MP388.8-MP313.2
4(03)	13"	Meet BN8107
4(03)	20"	Meet BN7460 and BN77247 at E. Fort Madison
4(03)	18"	Follow BN7566 MP252.0-237.1

Train 6(05) East of Colfax, CA - Freight Train Interference

05DEC25: Train 6(05) experienced delays while trailing Union Pacific freight trains UPRR/6356E and UPRR/7745E between MP 141.0 (Colfax) and MP 178.2 (Shed 10) on the Roseville Subdivision. The passenger train resumed normal speed once the freight trains cleared to an alternate track at Shed 10.

Train	Delay	Comment
6(05)	56"	

Train 353(05) South of Detroit, MI - Engine Failure

05DEC25: At 9:50AM-ET, 26-FOI-00167 353(05) E/ID4613-5 Cars-E/ID4601, stopped 2 miles south of Detroit, MI/MP53.8, on the CNRR Shore Line Subdivision, at MP51.8. The crew reported sticking brakes on engine ID4613 and phoned in to CNOC Mechanical to troubleshoot. Amtrak's Toledo Trainmaster responded to the train to help the crew troubleshoot the issue. Head end power was on for the duration. The R-End truck on E/ID4613 was ultimately cutout in order to get the brakes to release. This resulted in I-ETMS switched to freight speed account 87.5% operative braking. At 11:30AM-ET, Train 353(05) was back on the move west not exceeding 59MPH until the entry of the Amtrak Michigan Line at Townline/MP7.4. Train 353(05), operating with ITCS on the Michigan Line, was able to operate track speed. Upon arrival to the Norfolk Southern Chicago Line at Porter/MP482.2, operating speeds were reduced again to not exceed 59MPH to Chicago.

Train 352(05) was delayed at Battle Creek, MI/MP175.7, on the CNRR South Bend Subdivision, for crew rest. The crew signed up on their 4 hour cut at 6:34PM-ET from Train 353(05) that arrived at 2:24PM-ET, 2 hours and 29 minutes late.

Train	Delay	Comment
353(05)	1'50"	Troubleshoot Sticking Brakes
352(05)	37"	BTL - Crew Rest
353(05)	32"	Operating 59MPH
307(05)	1'24"	Turn off 353(05)

Train 365(05) East of East Lansing, MI - Plow

05DEC25: At 9:37AM-ET, Train 365(05), E/ID4632-6 Cars-E/ID4621, stopped 13.9 miles east of East Lansing, MI/MP223.8, on the CNRR Flint Subdivision, at MP237.7. The crew reported the fireman side plow on engine ID4632 was hanging very low after operating over multiple crossings. The Conductor notated the Bath Road Street crossing DOT#283678C at MP238.73 and the Beardslee Road crossing DOT#283675G at MP237.26. Three bolts loosened which caused the Fireman side plow to drop 4-5 inches and required mechanical assistance to respond. CN Mechanical arrived to the train at 11:00AM-ET and was able to secure the plow. Head end power was on for the duration. At 11:18AM-ET, Train 365(05) was released to continue west.

Train 364(05) was delayed departing Battle Creek, MI/MP175.7, on the CNRR South Bend Subdivision, for crew rest. The crew signed up fully rested at 8:53PM-ET off of inbound Train 365(05) that arrived at 12:43PM, 2 hours and 48 minutes late.

Train	Delay	Comment
365(05)	1'12"	
364(05)	10"	BTL - Crew Rest

Train 365(05) West of Port Huron, MI - Broken Rail

05DEC25: Train 365(05) was delayed starting 18 miles west of Port Huron, MI/MP334.3, on the CNRR Flint Subdivision, at Emmett/MP316.3 due to a reported broken rail at MP297.26. Maintenance of Way was on scene repairing the defect. Once repaired, Train 365(05) was released to operate restricted speeds from Imlay City/MP304.5 to MP295. After MP295, track speed resumed.

Train	Delay	Comment
365(05)	1'14"	

Train 1340(05) St. Paul-Minneapolis, MN - Car Failure

05DEC25: Train 1340(05) was delayed at St. Paul, MN/MP410.3, on the CPRR Merriam Park Subdivision, with no available replacement due to a bad brake cylinder. Two supplemental buses were secured to alleviate these conditions. Bus#1 picked up the 49 passengers at Tomah, WI to travel express to Chicago. Bus#2 made station stops to Red Wing, Winona, Lacrosse, Portage, and Chicago. No delay was incurred.

Train 341(05) was cancelled in its entirety and replaced with two alternate buses. Bus#1 operated express from Chicago to Milwaukee. Bus#2 made all station stops from Chicago to Milwaukee. This was a result of Train 1340(05) setting out car 34057 and requiring car 34094 be added to the consist upon arrival to Chicago. Once the car was added to the consist, Train 341(05)'s equipment deadheaded late to Milwaukee for its equipment turn of 330(06).

WBS#: B.TR.100150.6288

Train	Delay	Comment
1340(05)	No Delay	
341(05)	Cancelled With Alternate	

Train 21(04) North of Malvern, AR - Broken Rail

05DEC25: Train 21(04) was delayed holding 5.6 miles north of Malvern, AR/MP389.0, on the UPRR Little Rock Subdivision, at Gifford/MP383.4 meeting UP6960. Delays were extensive due to UP6960 slow moving through the area flagging through a track indication at ABCO/MP391.2 left behind from an earlier freight train. After UP6960 cleared, Maintenance of Way responded and found a broken rail at MP389.22. Once the defect was barred, Maintenance of Way released Train 21(04) to flag through the area. Once through, track speed resumed and Train 21(04) continued south.

Train	Delay	Comment
21(04)	29"	Meet UP6960
21(04)	44"	MOW - Broken Rail

Train 351(05) Pontiac, MI - Crew

05DEC25: Train 351(05) was delayed departing Pontiac, MI/MP25.9, on the CNRR Holly Subdivision, waiting on an ASAP extra board Engineer to arrive to the train.

Train	Delay	Comment
351(05)	48"	

Train 4(04) West of Kingman, AZ - Passenger Train Interference

05DEC25: Train 4(04) held 10.6 miles west of Kingman, AZ/MP516.3, on the BNSF Seligman Subdivision, at East Griffith/MP526.9 meeting Train 3(03).

Train	Delay	Comment
4(04)	36"	

16 FCB 08167 00100005498 "UNCLASSIFIED" 11/17/2015
Canadian National Chicago Subdivision - Scheduled M/W Work - Tie Replacement

12NOV25: Canadian National will be performing tie replacement project on the Chicago Subdivision between MP 34 and MP 60 between Homewood, IL and Gilman, IL. To accommodate the work, the following Saluki Service will be replaced with bus service:

05DEC25: Canadian National reported that the trackwork will now be pushed through and including 09DEC. As a result, the service has been adjusted to reflect the update.

- Train 390 (12NOV-18NOV) & 390 (02DEC-09DEC) has been canceled in its entirety. Bus 3390 will be utilized for alternate transportation.
- Train 391 (12NOV-18NOV) & 391 (02DEC-09DEC) has been canceled in its entirety. Bus 3391 (12NOV-18NOV) and Bus 3091 (02DEC-09DEC) will be utilized for alternate transportation.

WBS#: B.TR.100150.6160

Western Region

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (22)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
Yard service	SEA	BN1529	Used for SEA yard service while E/506 PM is performed.		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
49(4)	CHI	1	TOL- BYN	N/A
1(3)	ONA	2	PSN- ONA	N/A
769	VNC	1	FUL-VNC-CWT	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 11(4) Passenger Removal at Sacramento, California – Other

05DEC25, Passenger on PNR 1A5DF7, traveling from Klamath Falls, OR to Oakland, CA was removed at Sacramento, CA. Passenger traveling with a large dog, stated it was a service animal after showing aggressive behavior towards another service animal. Passenger was self-removed. Amtrak Police notified.

Delay: 11(4) 3"

Train 779(5) Passenger Removal at Fullerton, California – Fare Evader

05DEC25, Passenger on PNR Unknown, traveling from Fullerton, CA to Los Angeles, CA was removed from train by APD. Trespasser boarded the train without a ticket and when asked for ticket passenger showed the conductor a chase envelope stating he's going to purchase a car and showed an Metrolink ticket. Amtrak Police notified.

Delay: 779(5) 06"

Train 3(4) Passenger Removal at Flagstaff, Arizona – Intoxication

26-FOI-00167 00000065498 UNCLASSIFIED 12/17/2025

05DEC25, Passenger on PNR 1DE965, traveling from Gallup, NM to Los Angeles, CA was removed from train by Flagstaff PD. The passenger was threatening passenger due to being heavily intoxicated Amtrak Police notified.

Delay: 3 (4) 16"

Train 790(5) Passenger Removal at Los Angeles, California – Fare Evader

05DEC25, Passenger on PNR 182D73, traveling from Van Nuys, CA to Santa Ana, CA, was removed from train by APD. The trespasser is a habitual fare evader boarding the train with invalid tickets. The trespasser was asked for a valid ticket, and she became aggressive when she couldn't produce a valid ticket. Amtrak Police notified.

Delay: 790 (5) None

Consist Deviations

26-FOI-00167

00000005498

"UNCLASSIFIED"

12/17/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
350 (05)	CHI	Consist deviation per consist plan. No impact to ridership.	no in pact	0	61063
350 (05)	CHI	Reported cold car, dhd inline. No impact to customers.	pax moved out of c/4109 sales reduced no pax impact	0	ID4109
6 (05)	EMY	31025 byd brake. no Bag coach in consist. All bags will have to be put on the headend.	0	0	NOCAR
564 (05)	LAX	No Bikes. No Business class	0	0	90225
582 (05)	LAX	NO JY/BV/I-FI/FOOD	2 jy	2	COMET
1340 (05)	MSP	Setout coach in MSP, buses being sourced.	SUPP BUS	71	34078
355 (05)	PNT	Consist deviation per consist plan. No impact to ridership.	update to hvac b/o c/4109	0	61063
355 (05)	PNT	Reported cold car, overcapacity starting at ARB for the rest of the trip. email sent	exp supp bus arb- chi conf	50	ID4109
577 (05)	SAN	NO JY/BV/I-FI/FOOD	n/a	0	COMET
593 (05)	SAN	NO JY/BV/I-FI/FOOD	n/a	0	COMET
56 (05)	WAS	Club Dine is backwards on rear but does not effect the diagram, passengers can be informed they will ride facing backwards.			

Reverse Consists

Train Number	Station	Reason
110 (05)	PHL	Consist reversed Business class seat orientation may have changed At Rear
190 (05)	PHL	Consist reversed Business class seat orientation may have changed At Front
111 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front
93 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front
2155 (05)	BOS	Acela consist reversed First class at Rear
2152 (05)	WAS	Acela consist reversed First class at Rear

Train Number	Station	Reason	
		26-FOI-00167 00000005498	"UNCLASSIFIED" 12/17/2025
88 (06)	NFK	Consist reversed Business class seat orientation may have changed At Front	
185 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front	
176 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
137 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front	
182 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
133 (05)	NYP	Consist reversed Business class seat orientation may have changed At Front	
192 (05)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
2173 (05)	BOS	Acela consist reversed First class at Rear	