



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, September 15, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/14/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	45	86.2%	4,294	628	85.4%	104,816	14,592	86.1%
Central Division	86.0%	57	4	93.0%	797	96	88.0%	19,992	1,871	90.6%
East Division	82.0%	178	22	87.6%	2,346	291	87.6%	55,166	8,421	84.7%
West Division	86.0%	91	19	79.1%	1,151	241	79.1%	29,658	4,300	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00757 00000008818 UNCL ASSIFIED Endpoint Arrival Dates through 9/14/26 9/29/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	96,998	28,808	70%	1,410,314	369,447	74%	35,001,360	8,955,427	74%
Northeast Corridor	81%	44,541	8,226	82%	630,873	113,729	82%	15,345,772	3,701,011	76%
Acela	83%	12,925	1,771	86%	143,139	17,143	88%	3,105,765	776,283	75%
Northeast Regional	79%	31,616	6,455	80%	487,734	96,586	80%	12,240,007	2,924,728	76%
Richmond / Newport News / Norfolk	77%	9,840	3,440	65%	145,256	40,967	72%	3,668,055	1,088,266	70%
Flag_Subroute	%	0	0	-	630	496	21%	630	496	21%
Springfield Shuttles	89%	756	187	75%	9,711	1,833	81%	216,113	34,971	84%
Roanoke	79%	2,568	161	94%	49,936	7,628	85%	1,163,739	257,320	78%
On Spine Northeast Regional	80%	18,452	2,667	86%	282,201	45,664	84%	7,191,470	1,543,675	79%
State Supported	80%	39,755	13,366	66%	612,345	170,117	72%	15,400,939	3,381,391	78%
Borealis	80%	533	0	100%	8,275	1,020	88%	196,264	41,491	79%
Capitol Corridor	90%	3,687	796	78%	52,892	7,632	86%	1,282,396	171,678	87%
Carolinian	70%	433	427	1%	15,593	5,162	67%	392,921	153,312	61%
Cascades	75%	2,320	694	70%	38,297	9,736	75%	888,933	250,390	72%
Downeaster	82%	1,589	226	86%	25,171	488	98%	545,151	62,333	89%
Empire	78%	5,290	893	83%	83,627	21,337	74%	1,925,431	476,299	75%
Adirondack	72%	279	14	95%	5,032	1,026	80%	119,127	37,979	68%
Ethan Allen Express	70%	454	8	98%	7,710	3,023	61%	194,612	75,299	61%
Maple Leaf	70%	746	567	24%	11,862	4,081	66%	240,174	93,960	61%
New York - Albany	85%	2,624	206	92%	36,262	6,577	82%	885,529	155,066	82%
New York - Niagara Falls	75%	1,187	98	92%	20,510	5,834	72%	470,902	106,343	77%
Berkshire Flyer	60%	0	0	-	2,251	796	65%	15,087	7,652	49%
Gold Runner	73%	1,911	1,301	32%	36,478	20,801	43%	866,200	329,560	62%
Heartland Flyer	70%	111	111	0%	2,852	1,490	48%	74,409	31,675	57%
Hiawatha	90%	1,472	0	100%	25,375	2,589	90%	609,152	66,436	89%
Illinois	78%	2,339	1,022	56%	35,328	14,863	58%	863,685	247,497	71%
Carl Sandburg / Illinois Zephyr	85%	304	138	55%	5,692	1,649	71%	143,438	40,983	71%
Illini / Saluki	85%	777	273	65%	12,827	5,892	54%	298,839	77,369	74%
Lincoln Service	70%	1,258	611	51%	16,809	7,322	56%	421,408	129,145	69%
Keystone	92%	9,025	606	93%	117,391	14,382	88%	2,631,282	270,634	90%
Lincoln / Missouri	70%	663	357	46%	10,426	7,387	29%	268,037	142,844	47%
Mardi Gras Service	80%	161	63	61%	4,529	701	85%	138,481	30,686	78%
Michigan	70%	1,269	779	39%	30,076	12,062	60%	703,354	237,612	66%
Blue Water	70%	250	0	100%	7,008	2,294	67%	165,633	67,438	59%
Pere Marquette	85%	151	0	100%	3,658	604	83%	90,139	16,957	81%
Wolverine	70%	868	779	10%	19,410	9,164	53%	447,582	153,217	66%
Missouri	80%	142	36	75%	3,432	2,410	30%	76,792	23,675	69%
Pacific Surfliner	85%	6,410	5,004	22%	79,434	38,108	52%	2,806,280	556,681	80%
Pennsylvanian	80%	851	275	68%	12,401	2,673	78%	304,954	58,504	81%
Piedmont	80%	281	129	54%	13,994	2,874	79%	384,922	97,475	75%
Vermont	75%	1,268	647	49%	16,774	4,402	74%	442,295	132,609	70%
Long Distance	70%	12,702	7,216	43%	167,096	85,601	49%	4,215,382	1,870,562	56%
Auto Train	70%	594	242	59%	8,871	3,893	56%	268,942	92,634	66%
California Zephyr	70%	965	878	9%	13,281	5,570	58%	334,616	131,749	61%
Cardinal	70%	312	17	95%	3,137	1,818	42%	80,153	41,069	49%
City Of New Orleans	75%	753	665	12%	9,223	8,259	10%	218,875	80,724	63%
Coast Starlight	70%	879	284	68%	15,794	4,393	72%	393,048	139,035	65%
Crescent	70%	963	106	89%	12,526	2,733	78%	317,923	97,203	69%
Empire Builder	70%	1,127	845	25%	15,570	7,981	49%	335,126	168,731	50%
Floridian	60%	1,490	1,122	25%	20,620	16,020	22%	540,526	376,026	30%
Lake Shore Ltd	73%	1,148	625	46%	14,482	5,650	61%	336,163	103,493	69%
Palmetto	70%	758	130	83%	11,186	3,920	65%	314,367	98,718	69%
Silver Meteor	70%	988	697	29%	12,716	7,324	42%	347,126	162,728	53%
Southwest Chief	60%	761	632	17%	11,933	7,020	41%	289,188	190,615	34%
Sunset Ltd	70%	326	89	73%	3,530	1,462	59%	99,234	39,961	60%
Texas Eagle	70%	1,638	884	46%	14,227	9,558	33%	340,095	147,876	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00757 00000000010 "UNCLASSIFIED" 0/20/2020

Train Index Dates Through September 14, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	90,953	1,504,492	605	2,090,771	36,778,658	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,041	454,136	89	100,480	10,661,570	94
INFRASTRUCTURE PLANNED	135	7,955	454,136	175	123,501	10,661,570	116
FLEET RELIABILITY	90	15,527	1,504,492	103	335,072	36,778,658	91
TRAIN OPERATIONS	424	63,430	1,504,492	422	1,531,718	36,778,658	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/14/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	45	86.2%	4,294	628	85.4%	104,816	14,592	86.1%
Central Division	86.0%	57	4	93.0%	797	96	88.0%	19,992	1,871	90.6%
East Division	82.0%	178	22	87.6%	2,346	291	87.6%	55,166	8,421	84.7%
West Division	86.0%	91	19	79.1%	1,151	241	79.1%	29,658	4,300	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/14/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/14/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	45	86.2%	4,294	628	85.4%	104,816	14,592	86.1%
Central Division	86.0%	57	4	93.0%	797	96	88.0%	19,992	1,871	90.6%
CDL	95.0%	2	0	100.0%	28	4	85.7%	664	35	94.7%
CHI	86.0%	26	4	84.6%	372	65	82.5%	9,242	1,165	87.4%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	14	1	92.9%	372	39	89.5%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	12	0	100.0%	326	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	28	1	96.4%	676	55	91.9%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	82	3	96.3%	2,041	129	93.7%
MOE	97.5%	2	0	100.0%	28	1	96.4%	695	10	98.6%
MSP	96.5%	1	0	100.0%	14	0	100.0%	342	7	98.0%
NOL	94.5%	5	0	100.0%	61	2	96.7%	1,471	66	95.5%
OKC	97.0%	1	0	100.0%	13	0	100.0%	342	6	98.2%
PNT	88.0%	2	0	100.0%	35	2	94.3%	911	75	91.8%
PTH	93.0%	1	0	100.0%	14	1	92.9%	337	14	95.8%
QCY	91.0%	2	0	100.0%	25	1	96.0%	656	49	92.5%
SAS	90.5%	1	0	100.0%	14	2	85.7%	346	41	88.2%
STL	89.0%	4	0	100.0%	52	8	84.6%	1,348	114	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	22	87.6%	2,346	291	87.6%	55,166	8,421	84.7%
ALB	88.5%	9	1	88.9%	108	12	88.9%	2,592	200	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	70	2	97.1%	1,691	177	89.5%
BOS	85.5%	19	1	94.7%	241	23	90.5%	5,946	663	88.8%
BRK	92.5%	5	0	100.0%	70	2	97.1%	1,665	114	93.2%
BTN	82.0%	1	0	100.0%	14	2	85.7%	333	44	86.8%
CLT	91.5%	4	2	50.0%	63	7	88.9%	1,694	174	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	1	50.0%	26	3	88.5%	674	63	90.7%
GRO	-	1	1	0.0%	7	3	57.1%	57	14	75.4%
HAR	79.5%	13	0	100.0%	152	18	88.2%	3,859	612	84.1%
HFD	-	2	0	100.0%	18	1	94.4%	250	18	92.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	14	1	92.9%	345	41	88.1%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/14/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/14/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	45	86.2%	4,294	628	85.4%	104,816	14,592	86.1%
East Division	82.0%	178	22	87.6%	2,346	291	87.6%	55,166	8,421	84.7%
MIA	89.5%	2	0	100.0%	28	7	75.0%	686	83	87.9%
MTR	79.0%	-	-	-	13	2	84.6%	331	60	81.9%
NFK	84.5%	2	0	100.0%	28	3	89.3%	773	139	82.0%
NFL	93.5%	2	0	100.0%	28	1	96.4%	702	32	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	6	1	83.3%	72	19	73.6%	1,774	306	82.8%
NPN	93.0%	2	1	50.0%	28	2	92.9%	662	53	92.0%
NYP	75.5%	52	6	88.5%	672	106	84.2%	14,601	3,163	78.3%
PGH	93.0%	1	0	100.0%	14	1	92.9%	346	24	93.1%
PHL	48.0%	6	2	66.7%	66	28	57.6%	1,761	827	53.0%
PIT	76.0%	-	-	-	4	3	25.0%	28	22	21.4%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	1	50.0%	42	5	88.1%	1,306	59	95.5%
RNK	83.5%	2	0	100.0%	28	1	96.4%	686	94	86.3%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	-	-	-	11	0	100.0%	325	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	14	0	100.0%	342	12	96.5%
SFA	88.0%	1	0	100.0%	14	2	85.7%	345	49	85.8%
SPG	92.5%	4	2	50.0%	73	7	90.4%	2,035	120	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	14	2	85.7%	334	65	80.5%
WAS	84.0%	32	2	93.8%	414	28	93.2%	8,783	1,102	87.5%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	91	19	79.1%	1,151	241	79.1%	29,658	4,300	85.5%
ARN	92.0%	1	1	0.0%	14	2	85.7%	347	30	91.4%
BFD	79.0%	7	3	57.1%	96	31	67.7%	2,209	479	78.3%
EMY	72.0%	1	0	100.0%	16	6	62.5%	365	106	71.0%
EUG	86.5%	2	0	100.0%	27	3	88.9%	687	62	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	2	33.3%	35	12	65.7%	1,036	184	82.2%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	10	1	90.0%	113	17	85.0%	3,433	386	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	4	69.2%	161	67	58.4%	3,780	1,020	73.0%
PDX	86.0%	5	0	100.0%	70	8	88.6%	1,675	233	86.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/14/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/14/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	326	45	86.2%	4,294	628	85.4%	104,816	14,592	86.1%
West Division	86.0%	91	19	79.1%	1,151	241	79.1%	29,658	4,300	85.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	0	100.0%	204	27	86.8%	4,923	547	88.9%
SAN	90.5%	12	5	58.3%	116	23	80.2%	4,153	415	90.0%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	112	21	81.3%	2,665	401	85.0%
SJC	89.0%	7	1	85.7%	98	16	83.7%	2,438	245	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	36	2	94.4%	801	79	90.1%
SNA	-	-	-	-	1	0	100.0%	1	0	100.0%
SNC	-	-	-	-	7	1	85.7%	38	14	63.2%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	14	1	92.9%	326	30	90.8%
VAC	97.0%	2	0	100.0%	28	2	92.9%	681	16	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		6	1	83.3%	148	13	91.2%	6	1	83.3%	147	42	71.4%
3	808	14	6	57.1%	347	72	79.3%	14	4	71.4%	344	161	53.2%
4	114	14	4	71.4%	346	57	83.5%	14	5	64.3%	346	226	34.7%
5	169	14	3	78.6%	345	60	82.6%	14	4	71.4%	341	115	66.3%
6	72	14	5	64.3%	344	96	72.1%	14	7	50.0%	344	132	61.6%
7		14	1	92.9%	336	52	84.5%	14	2	85.7%	327	88	73.1%
8	63	14	4	71.4%	336	149	55.7%	14	8	42.9%	335	206	38.5%
11		14	4	71.4%	347	76	78.1%	14	1	92.9%	341	68	80.1%
14		14	8	42.9%	348	62	82.2%	14	1	92.9%	345	106	69.3%
19	76	14	1	92.9%	346	84	75.7%	14	3	78.6%	343	85	75.2%
20		14	0	100.0%	346	23	93.4%	14	1	92.9%	346	66	80.9%
21		14	1	92.9%	343	37	89.2%	14	7	50.0%	342	106	69.0%
22		14	2	85.7%	344	39	88.7%	14	12	14.3%	342	111	67.5%
23		14	1	92.9%	348	7	98.0%	14	4	71.4%	346	94	72.8%
24		14	0	100.0%	348	16	95.4%	14	3	78.6%	347	68	80.4%
25	145	14	0	100.0%	347	3	99.1%	14	1	92.9%	344	95	72.4%
26	29	14	1	92.9%	347	6	98.3%	14	2	85.7%	344	68	80.2%
27		14	3	78.6%	313	22	93.0%	14	3	78.6%	307	100	67.4%
28	130	14	1	92.9%	307	68	77.9%	14	2	85.7%	307	62	79.8%
40	433	14	5	64.3%	337	52	84.6%	14	8	42.9%	333	180	45.9%
41	48	14	11	21.4%	337	135	59.9%	14	13	7.1%	334	260	22.2%
42		14	1	92.9%	348	26	92.5%	14	2	85.7%	346	60	82.7%
43		14	1	92.9%	347	46	86.7%	14	5	64.3%	346	81	76.6%
48		14	1	92.9%	346	63	81.8%	14	5	64.3%	345	56	83.8%
49	45	14	4	71.4%	346	88	74.6%	14	5	64.3%	346	75	78.3%
51		6	1	83.3%	142	59	58.5%	6	2	66.7%	138	54	60.9%
52		14	2	85.7%	345	49	85.8%	14	4	71.4%	344	81	76.5%
53		14	1	92.9%	345	41	88.1%	14	7	50.0%	344	113	67.2%
55		9	1	88.9%	220	10	95.5%	9	0	100.0%	217	46	78.8%
56	72	9	0	100.0%	221	25	88.7%	9	5	44.4%	217	45	79.3%
58	72	14	1	92.9%	321	18	94.4%	14	14	0.0%	319	111	65.2%
59	149	14	6	57.1%	320	57	82.2%	14	13	7.1%	315	94	70.2%
63	78	14	4	71.4%	349	148	57.6%	14	14	0.0%	343	211	38.5%
64	25	14	2	85.7%	347	73	79.0%	14	7	50.0%	346	140	59.5%
66		14	1	92.9%	346	65	81.2%	14	2	85.7%	341	62	81.8%
67		9	2	77.8%	239	16	93.3%	9	2	77.8%	238	42	82.4%
68		14	2	85.7%	349	69	80.2%	14	3	78.6%	348	137	60.6%
69		14	5	64.3%	336	84	75.0%	13	3	76.9%	330	59	82.1%
71	Cncld	14	1	92.9%	344	4	98.8%	13	1	92.3%	341	87	74.5%
72	Cncld	14	2	85.7%	340	38	88.8%	13	1	92.3%	337	70	79.2%
75		14	4	71.4%	337	21	93.8%	14	5	64.3%	331	156	52.9%
76		14	0	100.0%	337	31	90.8%	14	5	64.3%	327	135	58.7%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	58	14	2	85.7%	339	23	93.2%	14	4	71.4%	336	137	59.2%
79	48	14	0	100.0%	346	59	82.9%	14	6	57.1%	344	118	65.7%
80	48	14	1	92.9%	346	38	89.0%	14	3	78.6%	343	74	78.4%
84	17	9	0	100.0%	211	19	91.0%	9	2	77.8%	207	50	75.8%
85	21	9	0	100.0%	222	18	91.9%	9	4	55.6%	222	78	64.9%
86		9	0	100.0%	222	16	92.8%	9	4	55.6%	221	125	43.4%
89		14	2	85.7%	344	80	76.7%	14	5	64.3%	342	102	70.2%
90		14	0	100.0%	344	12	96.5%	14	3	78.6%	343	63	81.6%
93		9	0	100.0%	221	21	90.5%	9	5	44.4%	220	60	72.7%
94		9	1	88.9%	252	62	75.4%	9	4	55.6%	250	93	62.8%
95	38	9	1	88.9%	221	7	96.8%	9	5	44.4%	221	87	60.6%
97		14	10	28.6%	346	227	34.4%	14	7	50.0%	344	127	63.1%
98		14	2	85.7%	346	30	91.3%	14	5	64.3%	344	128	62.8%
110		8	1	87.5%	217	111	48.8%	7	0	100.0%	213	22	89.7%
111		9	0	100.0%	212	37	82.5%	9	1	88.9%	210	23	89.0%
112		9	1	88.9%	212	21	90.1%	9	0	100.0%	211	20	90.5%
113		9	0	100.0%	143	33	76.9%	9	0	100.0%	142	16	88.7%
119		9	1	88.9%	209	50	76.1%	9	1	88.9%	207	27	87.0%
125		9	0	100.0%	222	12	94.6%	9	5	44.4%	222	89	59.9%
128		5	1	80.0%	127	21	83.5%	5	0	100.0%	127	26	79.5%
129		9	1	88.9%	221	51	76.9%	9	1	88.9%	221	31	86.0%
130		9	0	100.0%	212	20	90.6%	9	0	100.0%	210	16	92.4%
131		9	1	88.9%	214	58	72.9%	9	0	100.0%	214	39	81.8%
134		9	1	88.9%	222	33	85.1%	9	0	100.0%	221	42	81.0%
137		9	2	77.8%	219	38	82.6%	8	3	62.5%	218	65	70.2%
138		9	1	88.9%	222	44	80.2%	9	1	88.9%	221	39	82.4%
139		2	1	50.0%	45	6	86.7%	2	0	100.0%	45	16	64.4%
141	41	9	2	77.8%	221	6	97.3%	9	2	77.8%	220	39	82.3%
148		9	2	77.8%	221	24	89.1%	9	2	77.8%	219	42	80.8%
151		14	4	71.4%	345	109	68.4%	14	3	78.6%	344	102	70.3%
166	Cncld	2	0	100.0%	45	6	86.7%	1	1	0.0%	43	16	62.8%
169		5	1	80.0%	125	14	88.8%	5	0	100.0%	125	26	79.2%
170		9	0	100.0%	217	12	94.5%	9	1	88.9%	216	31	85.6%
171		9	0	100.0%	222	11	95.0%	9	3	66.7%	222	91	59.0%
172	26	9	1	88.9%	221	20	91.0%	9	5	44.4%	219	74	66.2%
173		9	1	88.9%	214	26	87.9%	9	1	88.9%	213	85	60.1%
174		9	0	100.0%	222	23	89.6%	9	2	77.8%	222	54	75.7%
175		9	1	88.9%	222	24	89.2%	9	3	66.7%	222	73	67.1%
177	22	9	1	88.9%	222	29	86.9%	9	3	66.7%	222	51	77.0%
181		9	2	77.8%	218	66	69.7%	9	2	77.8%	215	19	91.2%
182		9	1	88.9%	212	32	84.9%	9	3	66.7%	210	26	87.6%
183		9	1	88.9%	221	63	71.5%	9	1	88.9%	218	45	79.4%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		9	0	100.0%	222	36	83.8%	9	1	88.9%	221	29	86.9%
185		9	4	55.6%	222	45	79.7%	9	0	100.0%	222	18	91.9%
186		9	2	77.8%	221	31	86.0%	9	3	66.7%	220	64	70.9%
190		9	5	44.4%	221	80	63.8%	9	1	88.9%	220	45	79.5%
192		9	0	100.0%	219	24	89.0%	9	0	100.0%	219	19	91.3%
193	34	9	2	77.8%	217	85	60.8%	9	4	55.6%	216	94	56.5%
196		9	2	77.8%	218	25	88.5%	9	0	100.0%	216	17	92.1%
197		9	1	88.9%	222	78	64.9%	9	5	44.4%	222	76	65.8%
230		14	0	100.0%	182	4	97.8%	14	1	92.9%	182	10	94.5%
232		14	1	92.9%	348	13	96.3%	13	1	92.3%	347	24	93.1%
233	19	10	1	90.0%	305	67	78.0%	10	4	60.0%	304	105	65.5%
234		14	1	92.9%	349	24	93.1%	14	0	100.0%	348	29	91.7%
235		14	1	92.9%	273	43	84.2%	14	3	78.6%	272	63	76.8%
236		14	2	85.7%	333	12	96.4%	14	1	92.9%	332	44	86.7%
237		14	5	64.3%	346	66	80.9%	14	6	57.1%	344	65	81.1%
238		13	1	92.3%	272	24	91.2%	13	1	92.3%	270	23	91.5%
239		14	3	78.6%	347	86	75.2%	14	1	92.9%	346	43	87.6%
240		14	2	85.7%	348	25	92.8%	14	2	85.7%	345	71	79.4%
241		14	4	71.4%	348	86	75.3%	13	4	69.2%	347	85	75.5%
243		14	1	92.9%	284	72	74.6%	14	0	100.0%	283	39	86.2%
244		10	3	70.0%	304	15	95.1%	10	6	40.0%	304	71	76.6%
245		14	2	85.7%	229	43	81.2%	14	0	100.0%	228	30	86.8%
280		14	0	100.0%	349	17	95.1%	14	2	85.7%	348	80	77.0%
281		14	0	100.0%	349	40	88.5%	14	4	71.4%	349	64	81.7%
283		14	3	78.6%	349	88	74.8%	14	6	57.1%	349	72	79.4%
284		14	1	92.9%	349	14	96.0%	14	5	64.3%	346	66	80.9%
290		14	2	85.7%	349	54	84.5%	14	6	57.1%	346	143	58.7%
291		14	4	71.4%	348	116	66.7%	14	3	78.6%	344	93	73.0%
300	34	12	3	75.0%	330	25	92.4%	11	3	72.7%	326	76	76.7%
301		13	1	92.3%	345	11	96.8%	13	5	61.5%	341	68	80.1%
302		13	2	84.6%	326	36	89.0%	13	6	53.8%	322	96	70.2%
305		13	3	76.9%	329	34	89.7%	12	6	50.0%	323	128	60.4%
306		13	1	92.3%	343	18	94.8%	13	6	53.8%	341	95	72.1%
307	32	13	2	84.6%	336	46	86.3%	13	6	53.8%	332	104	68.7%
311		14	2	85.7%	341	30	91.2%	14	10	28.6%	335	94	71.9%
316		14	1	92.9%	337	25	92.6%	14	11	21.4%	331	112	66.2%
318	30	14	0	100.0%	347	35	89.9%	14	11	21.4%	344	177	48.5%
319	17	14	1	92.9%	348	21	94.0%	14	12	14.3%	343	205	40.2%
329		10	1	90.0%	246	13	94.7%	10	1	90.0%	246	20	91.9%
330		12	1	91.7%	296	7	97.6%	12	1	91.7%	296	16	94.6%
331		14	2	85.7%	349	35	90.0%	14	2	85.7%	348	46	86.8%
332		14	1	92.9%	348	20	94.3%	14	3	78.6%	348	49	85.9%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		14	0	100.0%	349	11	96.8%	14	1	92.9%	347	44	87.3%
335		14	0	100.0%	349	35	90.0%	14	0	100.0%	346	55	84.1%
336	12	14	0	100.0%	348	10	97.1%	14	4	71.4%	346	33	90.5%
337		14	1	92.9%	349	22	93.7%	14	3	78.6%	345	50	85.5%
338		14	1	92.9%	349	55	84.2%	14	3	78.6%	346	107	69.1%
339		14	2	85.7%	349	56	84.0%	14	1	92.9%	349	59	83.1%
341		14	3	78.6%	334	54	83.8%	14	3	78.6%	328	56	82.9%
342		14	0	100.0%	349	26	92.6%	14	2	85.7%	347	63	81.8%
351	45	13	1	92.3%	330	30	90.9%	13	6	53.8%	328	98	70.1%
352	24	14	0	100.0%	315	24	92.4%	14	11	21.4%	309	104	66.3%
354	78	14	2	85.7%	330	39	88.2%	14	6	57.1%	322	122	62.1%
355	130	13	4	69.2%	336	41	87.8%	13	6	53.8%	327	125	61.8%
364	74	14	1	92.9%	338	74	78.1%	14	6	57.1%	332	126	62.0%
365		14	1	92.9%	337	14	95.8%	14	4	71.4%	334	128	61.7%
370	27	12	2	83.3%	333	41	87.7%	12	3	75.0%	320	78	75.6%
371		12	0	100.0%	326	11	96.6%	12	2	83.3%	322	32	90.1%
380		14	0	100.0%	330	30	90.9%	14	1	92.9%	329	73	77.8%
381	23	11	2	81.8%	342	17	95.0%	11	3	72.7%	339	74	78.2%
382		11	1	90.9%	341	31	90.9%	11	5	54.5%	339	121	64.3%
383	17	14	3	78.6%	335	30	91.0%	13	6	53.8%	331	144	56.5%
390		14	2	85.7%	330	26	92.1%	13	7	46.2%	327	93	71.6%
391	20	14	1	92.9%	331	15	95.5%	14	9	35.7%	326	97	70.2%
392	17	14	2	85.7%	344	13	96.2%	13	9	30.8%	338	112	66.9%
393	26	14	3	78.6%	348	22	93.7%	13	7	46.2%	343	111	67.6%
417	23	9	1	88.9%	230	48	79.1%	9	2	77.8%	221	27	87.8%
425	Cncld	8	1	87.5%	232	8	96.6%	7	0	100.0%	230	7	97.0%
448		14	5	64.3%	273	54	80.2%	14	3	78.6%	269	92	65.8%
449		14	0	100.0%	270	34	87.4%	14	1	92.9%	270	46	83.0%
470		9	2	77.8%	245	42	82.9%	9	3	66.7%	239	30	87.4%
471		9	0	100.0%	234	14	94.0%	9	0	100.0%	234	6	97.4%
473		9	1	88.9%	241	16	93.4%	9	0	100.0%	238	10	95.8%
474	19	10	3	70.0%	238	69	71.0%	9	2	77.8%	222	73	67.1%
475		8	0	100.0%	237	8	96.6%	8	0	100.0%	237	16	93.2%
478		9	1	88.9%	233	37	84.1%	9	1	88.9%	231	29	87.4%
479		9	0	100.0%	240	36	85.0%	9	1	88.9%	238	37	84.5%
486		9	1	88.9%	244	36	85.2%	9	0	100.0%	238	61	74.4%
494		9	1	88.9%	247	48	80.6%	9	4	55.6%	239	68	71.5%
495		9	0	100.0%	228	4	98.2%	9	0	100.0%	226	3	98.7%
500		14	2	85.7%	323	18	94.4%	14	1	92.9%	320	37	88.4%
502		14	1	92.9%	331	20	94.0%	14	4	71.4%	327	65	80.1%
503	24	14	3	78.6%	345	43	87.5%	13	5	61.5%	337	107	68.2%
504		14	2	85.7%	349	22	93.7%	14	4	71.4%	347	103	70.3%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		14	3	78.6%	341	46	86.5%	14	7	50.0%	336	98	70.8%
506		14	1	92.9%	344	57	83.4%	13	2	84.6%	335	53	84.2%
507	24	14	1	92.9%	349	50	85.7%	14	4	71.4%	349	119	65.9%
508	18	13	1	92.3%	343	44	87.2%	13	3	76.9%	339	84	75.2%
509		14	3	78.6%	330	18	94.5%	14	3	78.6%	330	74	77.6%
511		14	1	92.9%	325	26	92.0%	14	1	92.9%	324	54	83.3%
516		14	2	85.7%	340	37	89.1%	14	6	57.1%	339	152	55.2%
517	26	14	0	100.0%	349	8	97.7%	14	6	57.1%	345	156	54.8%
518	21	14	3	78.6%	349	49	86.0%	14	8	42.9%	347	240	30.8%
519		14	2	85.7%	340	11	96.8%	13	4	69.2%	337	76	77.4%
520		9	1	88.9%	203	30	85.2%	9	1	88.9%	198	12	93.9%
521		9	1	88.9%	241	8	96.7%	9	1	88.9%	240	32	86.7%
522		9	2	77.8%	241	45	81.3%	9	1	88.9%	238	25	89.5%
523		9	0	100.0%	241	9	96.3%	9	2	77.8%	240	28	88.3%
524		9	1	88.9%	240	18	92.5%	9	2	77.8%	237	29	87.8%
525		9	1	88.9%	238	17	92.9%	8	1	87.5%	233	16	93.1%
526		9	4	55.6%	215	45	79.1%	8	1	87.5%	211	19	91.0%
527		9	0	100.0%	241	10	95.9%	9	1	88.9%	239	41	82.8%
528		9	0	100.0%	241	19	92.1%	9	2	77.8%	240	34	85.8%
529		9	1	88.9%	241	14	94.2%	9	2	77.8%	240	67	72.1%
530	13	9	3	66.7%	195	21	89.2%	8	2	75.0%	194	40	79.4%
531		9	2	77.8%	215	16	92.6%	9	2	77.8%	215	15	93.0%
532		9	3	66.7%	241	60	75.1%	9	2	77.8%	239	37	84.5%
534		9	4	55.6%	200	32	84.0%	9	1	88.9%	197	18	90.9%
535	21	9	1	88.9%	227	27	88.1%	9	1	88.9%	222	29	86.9%
536		9	5	44.4%	241	69	71.4%	9	2	77.8%	237	43	81.9%
537		9	2	77.8%	210	26	87.6%	9	0	100.0%	204	25	87.7%
538		9	3	66.7%	241	29	88.0%	9	1	88.9%	240	47	80.4%
539		9	1	88.9%	195	29	85.1%	9	3	66.7%	195	85	56.4%
540		9	2	77.8%	240	46	80.8%	9	2	77.8%	230	23	90.0%
541		9	1	88.9%	240	26	89.2%	9	1	88.9%	233	42	82.0%
542	11	9	1	88.9%	240	26	89.2%	9	3	66.7%	237	44	81.4%
543	44	9	3	66.7%	241	31	87.1%	9	7	22.2%	241	80	66.8%
544	81	9	0	100.0%	239	22	90.8%	9	1	88.9%	235	23	90.2%
545		9	2	77.8%	241	22	90.9%	9	1	88.9%	238	30	87.4%
547	21	9	3	66.7%	241	50	79.3%	9	4	55.6%	241	58	75.9%
548		8	0	100.0%	232	22	90.5%	8	1	87.5%	229	18	92.1%
549		9	0	100.0%	236	27	88.6%	9	0	100.0%	226	20	91.2%
550	61	9	3	66.7%	195	23	88.2%	9	3	66.7%	195	47	75.9%
551		9	0	100.0%	237	23	90.3%	9	0	100.0%	227	23	89.9%
562	49	12	0	100.0%	338	27	92.0%	12	7	41.7%	333	44	86.8%
564	47	12	0	100.0%	339	19	94.4%	11	3	72.7%	330	46	86.1%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
566	20	7	1	85.7%	332	30	91.0%	7	3	57.1%	329	57	82.7%
572	61	7	0	100.0%	329	27	91.8%	7	4	42.9%	321	99	69.2%
573	30	7	1	85.7%	331	45	86.4%	7	2	71.4%	323	60	81.4%
579	38	12	0	100.0%	224	14	93.8%	12	4	66.7%	217	49	77.4%
580		12	2	83.3%	339	20	94.1%	12	4	66.7%	332	41	87.7%
581	32	7	1	85.7%	334	59	82.3%	7	5	28.6%	331	80	75.8%
584	37	7	1	85.7%	218	33	84.9%	5	4	20.0%	209	136	34.9%
587	56	7	1	85.7%	326	22	93.3%	7	4	42.9%	317	69	78.2%
588		7	1	85.7%	217	24	88.9%	6	1	83.3%	214	44	79.4%
591		12	3	75.0%	336	29	91.4%	11	4	63.6%	328	53	83.8%
593		8	3	62.5%	325	56	82.8%	6	2	66.7%	300	43	85.7%
595	18	11	6	45.5%	331	66	80.1%	10	3	70.0%	327	76	76.8%
600		9	0	100.0%	249	9	96.4%	9	3	66.7%	247	25	89.9%
601		9	2	77.8%	232	92	60.3%	9	1	88.9%	229	28	87.8%
605		9	6	33.3%	239	145	39.3%	8	1	87.5%	234	24	89.7%
607		9	1	88.9%	248	31	87.5%	9	1	88.9%	245	26	89.4%
609		9	1	88.9%	239	24	90.0%	9	1	88.9%	238	24	89.9%
622		7	1	85.7%	144	36	75.0%	7	2	71.4%	141	7	95.0%
626		9	1	88.9%	153	21	86.3%	9	1	88.9%	151	19	87.4%
637		5	1	80.0%	78	8	89.7%	5	1	80.0%	78	7	91.0%
639		9	1	88.9%	219	41	81.3%	9	1	88.9%	217	21	90.3%
640		9	1	88.9%	239	8	96.7%	9	2	77.8%	237	86	63.7%
641		9	1	88.9%	221	44	80.1%	9	5	44.4%	221	32	85.5%
642		9	1	88.9%	237	12	94.9%	9	1	88.9%	236	28	88.1%
643		9	1	88.9%	251	45	82.1%	9	2	77.8%	248	41	83.5%
644		9	2	77.8%	243	30	87.7%	9	5	44.4%	241	61	74.7%
645		9	0	100.0%	251	42	83.3%	9	0	100.0%	248	55	77.8%
646		9	4	55.6%	240	60	75.0%	9	4	55.6%	238	117	50.8%
647	18	9	3	66.7%	251	38	84.9%	9	3	66.7%	249	54	78.3%
648		9	2	77.8%	247	61	75.3%	9	1	88.9%	247	36	85.4%
649		9	3	66.7%	252	47	81.3%	9	2	77.8%	248	36	85.5%
650		9	1	88.9%	251	46	81.7%	9	4	55.6%	248	43	82.7%
651	12	9	1	88.9%	251	18	92.8%	9	2	77.8%	248	45	81.9%
652		9	0	100.0%	252	31	87.7%	9	2	77.8%	248	43	82.7%
653		9	2	77.8%	240	38	84.2%	9	3	66.7%	236	44	81.4%
654		9	0	100.0%	241	44	81.7%	9	1	88.9%	237	21	91.1%
655		9	3	66.7%	249	77	69.1%	9	2	77.8%	246	78	68.3%
656		9	2	77.8%	251	56	77.7%	9	2	77.8%	249	35	85.9%
657		9	0	100.0%	240	29	87.9%	9	1	88.9%	238	31	87.0%
658		9	1	88.9%	251	38	84.9%	8	0	100.0%	248	35	85.9%
680		10	1	90.0%	247	13	94.7%	10	0	100.0%	245	27	89.0%
681		10	0	100.0%	247	18	92.7%	10	2	80.0%	240	95	60.4%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
682		10	1	90.0%	246	10	95.9%	10	0	100.0%	246	42	82.9%
683		10	1	90.0%	229	19	91.7%	10	2	80.0%	228	77	66.2%
684		10	0	100.0%	228	37	83.8%	10	1	90.0%	228	48	78.9%
685		10	0	100.0%	243	33	86.4%	10	1	90.0%	240	56	76.7%
686	26	10	0	100.0%	248	39	84.3%	10	3	70.0%	247	55	77.7%
687		10	0	100.0%	247	38	84.6%	10	0	100.0%	246	40	83.7%
688		10	0	100.0%	246	15	93.9%	10	0	100.0%	245	41	83.3%
699		2	1	50.0%	69	9	87.0%	2	0	100.0%	69	3	95.7%
701		14	4	71.4%	281	34	87.9%	14	3	78.6%	278	35	87.4%
702	147	14	2	85.7%	348	38	89.1%	13	6	53.8%	344	89	74.1%
703		14	6	57.1%	349	118	66.2%	14	6	57.1%	347	106	69.5%
704	36	14	5	64.3%	280	54	80.7%	14	7	50.0%	272	66	75.7%
710	38	14	3	78.6%	349	82	76.5%	12	8	33.3%	343	96	72.0%
711		14	3	78.6%	340	41	87.9%	14	4	71.4%	317	69	78.2%
712		14	5	64.3%	346	96	72.3%	14	8	42.9%	336	122	63.7%
713	Cncld	13	4	69.2%	215	24	88.8%	9	7	22.2%	186	87	53.2%
714	19	14	9	35.7%	230	101	56.1%	13	10	23.1%	213	105	50.7%
715	30	14	2	85.7%	348	65	81.3%	12	9	25.0%	317	164	48.3%
716	222	14	11	21.4%	349	154	55.9%	13	11	15.4%	339	152	55.2%
717	145	13	5	61.5%	333	84	74.8%	13	9	30.8%	308	107	65.3%
718		14	12	14.3%	349	190	45.6%	14	9	35.7%	346	138	60.1%
719	51	14	7	50.0%	349	120	65.6%	13	6	53.8%	331	104	68.6%
757	63	12	0	100.0%	132	7	94.7%	12	2	83.3%	131	16	87.8%
761	26	12	1	91.7%	343	14	95.9%	12	2	83.3%	340	46	86.5%
765	73	12	3	75.0%	343	28	91.8%	12	7	41.7%	343	53	84.5%
769	132	12	2	83.3%	343	29	91.5%	12	8	33.3%	336	73	78.3%
770	67	12	3	75.0%	343	28	91.8%	12	7	41.7%	340	111	67.4%
774	131	12	0	100.0%	343	17	95.0%	12	8	33.3%	341	88	74.2%
777	43	12	2	83.3%	228	15	93.4%	12	11	8.3%	227	69	69.6%
782	31	12	8	33.3%	228	113	50.4%	12	5	58.3%	223	41	81.6%
785		12	1	91.7%	343	30	91.3%	12	8	33.3%	343	69	79.9%
786	55	12	1	91.7%	132	24	81.8%	10	7	30.0%	126	73	42.1%
790	33	12	1	91.7%	343	32	90.7%	11	6	45.5%	339	60	82.3%
821	46	13	0	100.0%	342	6	98.2%	13	7	46.2%	342	147	57.0%
822	32	14	1	92.9%	345	19	94.5%	13	11	15.4%	342	181	47.1%
1333		14	3	78.6%	345	43	87.5%	14	4	71.4%	342	116	66.1%
1340		14	0	100.0%	344	7	98.0%	14	0	100.0%	343	56	83.7%
2102		9	0	100.0%	98	16	83.7%	9	0	100.0%	97	7	92.8%
2103		9	0	100.0%	162	14	91.4%	9	2	77.8%	161	12	92.5%
2104		9	0	100.0%	188	10	94.7%	8	0	100.0%	185	13	93.0%
2105		9	0	100.0%	10	1	90.0%	9	0	100.0%	10	0	100.0%
2107		8	1	87.5%	218	36	83.5%	8	0	100.0%	215	21	90.2%

Amtrak On Time Performance

Trains Arriving Through: 9/14/2026

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2108		9	3	66.7%	219	31	85.8%	8	0	100.0%	212	27	87.3%
2109		9	2	77.8%	112	15	86.6%	9	0	100.0%	110	6	94.5%
2112		9	0	100.0%	59	6	89.8%	9	0	100.0%	57	2	96.5%
2113		9	1	88.9%	98	10	89.8%	9	1	88.9%	98	11	88.8%
2115		9	2	77.8%	98	15	84.7%	8	0	100.0%	96	12	87.5%
2116		9	0	100.0%	59	1	98.3%	9	0	100.0%	59	8	86.4%
2118		9	0	100.0%	59	4	93.2%	9	0	100.0%	59	12	79.7%
2119		8	1	87.5%	58	9	84.5%	8	1	87.5%	57	13	77.2%
2120		9	1	88.9%	59	20	66.1%	9	0	100.0%	57	23	59.6%
2123	16	9	3	66.7%	97	13	86.6%	9	1	88.9%	96	16	83.3%
2124		9	0	100.0%	190	38	80.0%	9	0	100.0%	188	24	87.2%
2126		9	1	88.9%	107	27	74.8%	9	0	100.0%	106	22	79.2%
2127		9	0	100.0%	59	10	83.1%	9	0	100.0%	58	9	84.5%
2128		9	1	88.9%	59	5	91.5%	9	0	100.0%	59	3	94.9%
2131		9	0	100.0%	59	10	83.1%	9	0	100.0%	59	6	89.8%
2150		9	1	88.9%	212	23	89.2%	9	0	100.0%	209	75	64.1%
2151		9	1	88.9%	161	8	95.0%	9	4	55.6%	159	45	71.7%
2152		9	0	100.0%	117	7	94.0%	9	0	100.0%	116	31	73.3%
2154		9	1	88.9%	120	24	80.0%	8	1	87.5%	115	46	60.0%
2155		9	0	100.0%	221	17	92.3%	9	1	88.9%	217	103	52.5%
2156		9	0	100.0%	10	0	100.0%	9	2	77.8%	10	2	80.0%
2158	22	9	0	100.0%	58	6	89.7%	9	2	77.8%	58	18	69.0%
2159		9	1	88.9%	214	17	92.1%	9	3	66.7%	212	72	66.0%
2160		9	1	88.9%	59	3	94.9%	9	2	77.8%	58	30	48.3%
2162		9	0	100.0%	220	23	89.5%	9	0	100.0%	214	91	57.5%
2163	36	9	0	100.0%	172	17	90.1%	9	6	33.3%	166	75	54.8%
2165	29	9	0	100.0%	56	4	92.9%	9	2	77.8%	56	23	58.9%
2167		9	1	88.9%	207	21	89.9%	9	2	77.8%	207	43	79.2%
2171		9	1	88.9%	148	11	92.6%	9	3	66.7%	144	26	81.9%
2190		9	1	88.9%	217	30	86.2%	9	0	100.0%	215	24	88.8%
2193		8	1	87.5%	211	27	87.2%	8	1	87.5%	209	51	75.6%
2228		2	0	100.0%	19	6	68.4%	2	0	100.0%	19	5	73.7%
2233		2	0	100.0%	29	6	79.3%	2	0	100.0%	28	4	85.7%
2264	Cncld	2	0	100.0%	11	1	90.9%	1	0	100.0%	10	7	30.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2123	WAS	16	CAR	9	MTI	9	XCY-XHM	AM	Disabled train ahead, Other, HAM INT LIMIT, CONGESTION AHD AT HAM A/C AM97 WITH MECHANICAL ISSUES AT TRENTON
2158	BOS	22	DBB	32	DBB	32	NHV-XGX	AM	Stuck open bridges, Bridge, Conn River, Conn Bridge Issue, unable to close
2163	WAS	36	DET	26	DET	26	XGX-NHV	AM	Catenary failure, Other, WESTBROOK WEST
2165	WAS	29	CTI	19	CTI	15	NHV-STM	MN	Follow mn, Milepost, 72, 33
2264	BOS	Trn Cancelled	OTH	3	OTH	3	XCY-MET	AM	Lost time - N.A.R.
84	NYP	17	ENG	18	ENG	18	NWK-NYP	AM	Other electrical failure, 625 EX ES, STOPPED AT TENTH AVE WITH STOP BYPASS
85	WAS	21	DET	22	DET	22	OSB-NHV	AM	Catenary failure, Other, SHORELINE JCT, STOPPED BEHIND 2163
95	NFK	38	FTI	30	FTI	30	ALX-WDB	CS	Meet M410, Milepost, 99.8, 99.8
141	WAS	41	SYS	31	SYS	31	SPG-SPG	AM	Other late crew, no crew allocated for the trip. The crew of Dead Head 5552 which turns for No. 425 out of GFD has been moved to No. 141. No. 425 has been cancelled
166	BOS	Trn Cancelled	HLD	1	HLD	1	BWI-BWI	AM	Passenger and/or baggage
172	BOS	26	SMW	12	SMW	9	NWK-NYP	AM	Scheduled in track usage program, Other, NWK-NYP
177	PHL	22	DCS	35	DCS	35	NHV-BRP	MN	PTC system failure Control Point, 261
193	WAS	34	CTI	22	CTI	16	BWI-NCR	AM	Follow, marc, 455, Control Point, ., Follow MK455 on 3. 198 on 2, MK548 on 1. No other options available.
417	NHV	23	RTE	16	RTE	16	SPG-SPG	AM	Routed to abnormal station track due to N.A.R., SPG track 2A, Other, CSX, AM417 delayed off of trk 2A on account of waiting for CSX to burn down the signal
425	SPG	Trn Cancelled							
474	SPG	19	CON	16	CON	16	NHV-NHV	AM	Hold for connecting train, late connection of AM174
79	CLT	48	PTI	58	DCS	30	DNC-BNC	NS	Restrictive signal(s) from known wayside signal failure Wayside signal & PTC issues., STOP, Control Point, HAW RIVER

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
80	NYP	48	POL	133	POL	133	HPT-GRO	NS	RR blocked by trespasser or vehicle strike by another train Hold @ CP ELM. Train AM 71 trespasser strike.
647	HAR	18	PTI	11	PTI	11	EWR-TRE	AM	Follow, AM93, Other, EWR-TRE
651	HAR	12	MTI	12	MTI	12	NWK-TRE	AM	Disabled train ahead, Other, HAM INT LIMIT, CONGESTION AHD AT HAM A/C AM97 WITH MECHANICAL ISSUES AT TRENTON
19	NOL	76	POL	91	POL	91	ATL-ATN	NS	RR blocked by trespasser or vehicle strike by another train Stopped at Sewell
686	BON	26	INJ	24	INJ	24	EXR-EXR	CS	Injured or sick passenger William Mahood PNR 8915D7 fell during station stop. Head injury. Taken off by ambulance for further treatment. His wife, Denise, detrained with him.
63	TWO	78	INJ	26	INJ	26	HUD-HUD	AM	Injured or sick passenger EMS met the train at HUD for a passenger who fell on the train. EMS cleared the passenger to stay on the train.
64	NYP	25	CTI	40	CTI	22	RHI-XCP	MN	Blocked from station track Metro North, 857, Metro North, 863, Control Point, 75
233	ALB	19	CTI	11	CTI	11	CRT-POU	MN	Meet mn, 858, Control Point, 39
49	CHI	45	ENG	50	ENG	50	ALB-ALB	AM	Needed oil 132
71	CLT	Trn Cancelled	DMW	6	DMW	6	DNC-GRO	NS	Waiting for MW clearance Other, 22.61 NC
72	GRO	Trn Cancelled							
77	CLT	58	DMW	50	DMW	50	DNC-BNC	NS	Waiting for MW clearance This includes signal delays from inside of the form Y and speed restrictions., Milepost, 22.5, 21.6
56	SAB	72	SYS	69	SYS	69	SPG-SPG	AM	Other late crew Waiting for engineer off of Amtrak bus 3055, Other, SPG Sta
40	CHI	433	TRS	166	TRS	166	CUM-COV	CS	Trespasser strike Milepost, 178.5, 178.5
41	MIA	48	FTI	61	FTI	17	XFI-COV	CS	Follow Followed 116 12 for nearly the entire Pitt Sub despite us being on time. NG made clear we would have to wait until Keystone to get around. 2 track was unoccupied entire time until Broadford., 116 12, Control Point, Riverton, Control Point, Soderm
25	NOL	145	FTI	197	FTI	142	BIX-GUF	CS	Blocked from station track unknown, Control Point, KCS interlock
26	MOE	29	FTI	50	FTI	47	BAS-GUF	CS	Cross Traffic Control Point, KCS, 648

Amtrak Endpoint OTP Details

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
5	EMY	169	PTI	250	PTI	162	PCT-GBB	BN	Engine failure. Shoved back about 14 miles to crossover at Zearing to Main 1. Then meet train 3 to give them lead Engine AMTK 115. 3, Control Point, Buda
6	CHI	72	SYS	121	SYS	98	DEN-DEN	RT	Crew rest Lone Conductor not rested until 2028, Other, D.U.S
530	SAC	13	DMW	11	DMW	11	OAC-OKJ	UP	Waiting for MW clearance Control Point, NI010
535	OKJ	21	MBO	16	MBO	16	SUI-MTZ	UP	For maritime traffic Control Point, Benicia
542	SAC	11	PTI	7	DMW	5	HAY-OAC	UP	Held for or routed around MW work or equipment Control Point, elmhurst
543	SJC	44	PTI	36	PTI	11	BKY-EMY	UP	Follow 713, Control Point, rv007
544	SAC	81	RTE	41	RTE	41	HAY-OAC	UP	Rerouted from HAY-OAC via Coast/Mulford sub after changing operating ends due to suicidal trespasser between MP 18.23 and MP 18.15 Milepost, 21.00, 35.00, Milepost, 30.60, 13.50
547	SJC	21	POL	32	POL	32	OAC-OAC	UP	Right of Way police hold
550	SAC	61	DTR	28	DTR	28	GAC-OAC	UP	Reroute due to a fatality GAC, OAC
503	EUG	24	CCR	35	CCR	18	SEA-SEA	BN	Broken spedo no tag, wait for proper non compliant tags 90252
507	EUG	24	PTI	27	PTI	27	PDX-ORC	UP	Meet 508, Siding, clackamas
508	SEA	18	PTI	16	PTI	13	EUG-ALY	UP	Meet 14, Control Point, Alford
517	PDX	26	DCS	12	PTI	8	TAC-XNI	ST	Meet AMTK 504, Control Point, Rill
518	VAC	21	RTE	31	RTE	31	XF2-X1J	BN	Inability to contact dispatcher Stop Piper no reason why had to copy rule 43, Control Point, Piper
58	CHI	72	WTR	72	WTR	28	HMD-MCB	CC	Heat order Milepost, 849, 823
59	NOL	149	ENG	102	ENG	102	CHI-CHI	AM	Set out defective locomotive 339
8	CHI	63	FTI	193	FTI	36	LIB-WFH	BN	Meet Siding, Brimstone, Brimstone To Vista, BNSF 6642, BNSF 6019, BNSF 9308
28	SPK	130	ENG	105	ENG	98	WIH-PSC	BN	Air / Brake Air compressor quit working unable to get restarted, 198

Amtrak Endpoint OTP Details

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
821	FTW	46	DSR	45	DSR	30	GLE-FTW	BN	Per bulletin Milepost, 409.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 405.9, 405, 60, m, Milepost, 404.1, 403.9, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401.7, 481.3, 60, m, Milepost, 400.4, 400.2, 60, m, Milepost, 399.8, 399.2, 60, m, Milepost, 397.8, 397.1, 60, m, Milepost, 39	
822	OKC	32	DSR	32	DSR	22	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, 1, Milepost, 350.7, 351.1, 50, 1, Milepost, 355.5, 355.9, 50, 1, Milepost, 379.5, 380.8, 40, M, Milepost, 382.2, 382.8, 40, M, Milepost, 382.5, 382.7, 30, M, Milepost, 383.2, 383.3, 25, M, Milepost, 383.4, 384, 25, M, Milepost, 385.3, 385.5, 30, M, Milepost,	
336	CHI	12	CTI	9	FTI	7	SVT-XRO	CP	Cross over or go around CP 8123 sitting on Main 2 at Rondout, waiting for 335 to pass so we can crossover to Main 1, CP 8123, Control Point, Wadsworth	
351	CHI	45	DCS	42	DCS	42	ROY-DET	CC	Power switch failure Switch issues at BEAUBIEN. Reverse move back to D&M and back west on track 2, Control Point, beaubian	
352	PNT	24	DSR	29	PTI	23	ALI-JXN	MI	Meet am355, Control Point, 75	
354	PNT	78	ENG	54	ENG	54	CHI-CHI	AM	Replaced bad order 4633 with 4605 ID4605	
355	CHI	130	FTI	39	FTI	39	XMC-XPI	NS	Cross Traffic multiple, Control Point, 482	
364	PTH	74	ENG	42	ENG	24	BTL-LNS	CC	Other electrical failure Notified by CNOC mechanical that batteries on rear engine were not charging. Engine was not running and batteries not charging. Stopped to troubleshoot the issue and was able to resolve., ID4630	
370	GRR	27	FTI	43	FTI	23	XH6-XPI	NS	Follow 10R, Control Point, 507	
562	SAN	49	CTI	40	CTI	26	OSD-SOL	SN	Follow coaster, Milepost, 225, 241	
564	SAN	47	PTI	29	PTI	15	OSD-OSD	SN	Meet 769, Control Point, pacific	
566	SAN	20	FTI	24	CTI	11	LAX-XRJ	SC	Cross Traffic METROLINK, 605, Control Point, SOTO	
572	SAN	61	CTI	39	CTI	15	OSD-SOL	SN	Follow Coaster, 638, Control Point, Ponto	
573	LAX	30	CTI	14	CTI	14	SOL-OSD	SN	Meet coaster, Control Point, swami	
579	LAX	38	TRS	21	TRS	21	OSD-OSD	SN	Unticketed or fare evading passenger Unticketed unruly and disruptive female removed by SAN DIEGO COUNTY SHERIFF, Other, OSD STATION	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
581	LAX	32	ITI	26	ITI	26	SAN-SAN	SN	Service, turn, or wye train 770
584	SAN	37	CTI	28	CTI	12	OSD-SOL	SN	Follow Coaster, 648, Control Point, Longboard
587	LAX	56	CON	31	CON	31	SAN-SAN	SN	Hold for connecting train 774
595	LAX	18	PTI	26	PTI	12	OSD-X98	SN	Meet 790, Control Point, song
757	SLO	63	DCS	58	DCS	40	X3G-LPS	UP	Restricted speed til signal co 325 due to power outage and after being flagged past cp co 366 south gaviota. Control Point, north gaviota, Control Point, co325
761	GTA	26	DSR	35	DSR	8	SIM-MPK	SC	Per bulletin Milepost, 432.4, 431.5, 10, mt
765	SLO	73	ENG	38	ENG	38	SAN-SAN	SN	Other electrical failure 480 not loading, switch consists to 6901/2118, 2109
769	GTA	132	PTI	38	PTI	15	MPK-XMR	SC	Meet 782, Control Point, Las Posas
770	SAN	67	DCS	30	CCR	23	GTA-GTA	UP	PTC- IETMS recycle breaker to clear fault 6907, PTC not engaging, showing horn fault, troubleshooting with GTA mechanical., breaker was reset.
774	SAN	131	DCS	117	DCS	46	LPS-X3G	UP	Restrictive signal(s) from unknown cause Flag due to signals not working correctly. Power outage. S. Conception to Gaviota., Stop, Control Point, S. conception
777	SLO	43	CTI	30	FTI	13	OLT-SOL	SN	Meet 779, Control Point, scripps, bnsf
782	SAN	31	PTI	46	PTI	24	SBA-CPN	UP	Meet 765, Other, 369
786	SAN	55	PTI	78	PTI	33	LPS-X3G	UP	Meet Meet 14 and 765 at Sudden. Perfect meet with 14 and then we held for 765 which was late, 14, 765, Control Point, S. Sudden
790	SAN	33	CTI	26	PTI	18	VEC-OXN	UP	Meet 777, Control Point, North Oxnard
702	BFD	147	FTI	100	DMW	40	MCD-MDR	BN	Hold for defect repair Stop signal at West Le Grand for change of route/signal in time, then advanced to Le Grand siding and subsequently East Sharon to hold for temporary repair of broken rail at MP 1021.6 with resulting freight congestion., Control Point, West Le Grand, Siding, Le Grand, Control P
704	BFD	36	PTI	31	PTI	20	MCD-MDR	BN	Meet amt 703, Siding, Kismet
710	BFD	38	DMW	43	DMW	34	MCD-MDR	BN	Hold for defect repair Train congestion due to broken rail at 1021.7-1021.6 resulting in holding for BNSF 5740 and AMTK 713 to pass, Control Point, E. Le Grand, Siding, Kismet

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/14/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
713	OKJ	Trn Cancelled	DMW	66	DMW	64	FNO-MDR	BN	Hold for defect repair Broken rail Held at W Madera behind BNSF. 6739 and Amtrak 702, Milepost, 1021.6, 1021.7
714	BFD	19	DSR	23	DMW	13	MCD-MDR	BN	Waiting for MW clearance Per Stockton Sub DS, AMTK 714 held at East Kismet waiting for MW to clear out at MP 1021.6 due to earlier broken rail., Milepost, 1021.6, 1021.5
715	OKJ	30	DSR	25	PTI	13	EMY-OKJ	UP	Meet amtrak 542, Control Point, king St
716	BFD	222	ITI	207	ITI	207	OKJ-OKJ	UP	Had to wait for train 713 to arrive and use that equipment. Our original set was not compliant. 713
717	OKJ	145	ITI	101	ITI	101	BFD-BFD	BN	Service, turn, or wye train 702
719	OKJ	51	PTI	25	CON	23	BFD-BFD	BN	Hold for thruway bus Set Hold foe 3 Busses.
3	LAX	808	ENG	879	ENG	269	PCT-GBB	BN	Failure of diesel engine 15, 78
4	CHI	114	FTI	196	FTI	104	XC7-LAP	BN	Follow BNSF, Control Point, Sibley, Control Point, CA Junction, Control Point, ethel
300	CHI	34	FTI	44	FTI	21	DWT-JOL	UP	Cross Traffic Unknown, Control Point, UD Tower
307	STL	32	FTI	33	FTI	14	XTF-SMT	CC	Cross Traffic NA, Other, CORWITH
381	QCY	23	FTI	11	ENG	10	CHI-CHI	AM	Paperwork boxes not checked Map100. No mechanical in the station. ID4629
383	QCY	17	FTI	16	FTI	16	PLO-MDT	BN	Meet BNSF 6539, Control Point, Electrics
391	CDL	20	DSR	20	DMW	10	CHM-MAT	CC	Waiting for MW clearance Control Point, south humboldt
392	CHI	17	DSR	25	DSR	8	MAT-CHM	CC	Per bulletin Milepost, 170.9, 170.3, 30, all track, Milepost, 163.5, 156, 60, all track, Milepost, 153.8, 153.6, 60, main, Milepost, 136.1, 135.2, 60, main, Milepost, 149.8, 149.8, 25, main two
393	CDL	26	DSR	27	FTI	12	GLM-RTL	CC	Meet Control Point, Paxton, CN3883
318	CHI	30	FTI	51	DCS	21	LCN-BNL	UP	Power switch failure Switch not locking. Instructed to take off power and hand line. Talked past stop signal at CP X127. Restricted speed until CP X124., Control Point, CP X127
319	KCY	17	DSR	28	FTI	15	XRC-KCY	KC	Cross Traffic cp7043, Control Point, KCS interlocking

Amtrak Initial Terminal Details

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/14/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	09/13	6	6	PTC- IETMS incorrect consist Other, ALB
BOS	67	09/14	74	74	Planned set out / pick out of locomotives, cars or section of train, Mechanical rptd there was a fault on E/637 that had to be cleared on AM67 and paper work issues
CLT	72	09/14	(Trn Cxld)		Trespasser Strike
CLT	78	09/14	44	44	Service, turn, or wye train 77
GFD	425	09/14	(Trn Cxld)		Crew Shortage
GRO	75	09/14	2		
NHV	55	09/14	29	29	Hold for bus with passengers from train
NPN	186	09/14	5	5	Hold for thruway bus Late bus arrival, passengers on platform
NYP	43	09/14	2	2	Passenger and/or baggage, LOADING
NYP	69	09/14	11	11	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	09/14	67	67	Air / Brake / Wheel, 0000, LATE RELEASE F/SSYD A/C HOT BEARING FAULT
NYP	185	09/14	7	7	Passenger and/or baggage, LOADING
NYP	237	09/14	2	2	Passenger and/or baggage, BOARDING
NYP	2123	09/14	2	2	Passenger and/or baggage, BOARDING
PHL	67	09/13	2	2	PTC - Stop Bypass Permission Required, Control Point, S PENN
PHL	190	09/14	3	3	Planned set out / pick out of locomotives, cars or section of train, LATE OUT OF THE YARD
RGH	77	09/14	17	17	Held for L620 at east side of bolyan Milepost, 81.1, 81.1
SPG	141	09/14	31	31	Other late crew, no crew allocated for the trip. The crew of Dead Head 5552 which turns for No. 425 out of GFD has been moved to No. 141. No. 425 has been cancelled
SPG	417	09/14	16	16	Routed to abnormal station track due to N.A.R., SPG track 2A, Other, CSX, AM417 delayed off of trk 2A on account of waiting for CSX to burn down the signal
TWO	64	09/14	3		
WAS	2108	09/14	2	2	Electrical failure, ALL, THE TRAIN HAD WATER ISSUSE THROUGHOUT THE TRAIN. MECH HAD TO RES THE COMPUTER.
WAS	2150	09/14	13	13	Delay in Block, ENGR REPORTED THAT THE MAP 100 WAS EXPIRED, MECH. CONFIRMED PAPERWORK HAD A GOOD DATE.
CHI	3	09/14	98	98	Set out defective locomotive 118
CHI	41	09/14	136	136	Service, turn, or wye train 40
CHI	59	09/14	177	177	Pick up rescue locomotive due to mechanical failure 153
CHI	381	09/14	19	10	Paperwork boxes not checked Map100. No mechanical in the station. ID4629

Amtrak Initial Terminal Details

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/14/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	381	09/14	19	9	Door ID4121, All doors registered working with no lights flashing. 4121 ended up being the problem with door on the B-End of car. Couldn't locate the problem because no lights were flashing regular. Have to reopen and close all doors to find the problem.
ARN	529	09/14	16	16	PTC- IETMS hard cutout Could not initialize : instructed to recycle breaker by PTC mechanical help desk., C2001
BFD	701	09/14	1		
BFD	717	09/14	101	101	Service, turn, or wye train 702
BFD	719	09/14	23	23	Hold for thruway bus Set Hold for 3 Busses.
GTA	770	09/14	23	23	PTC- IETMS recycle breaker to clear fault 6907, PTC not engaging, showing horn fault, troubleshooting with GTA mechanical., breaker was reset.
GTA	790	09/14	14	14	Service, turn, or wye train 769, Late 769 due to speed restrictions Freight train interference, commuter train interference and PASSENGER train interference.
LAX	14	09/14	7	7	Hold for connecting train 765
OKJ	526	09/14	6	6	Signal in time Late Train 11 originally had the lineup into OKJ., Control Point, North Jack London
OKJ	536	09/14	1		
OKJ	716	09/14	207	207	Had to wait for train 713 to arrive and use that equipment. Our original set was not compliant. 713
OKJ	718	09/14	80	80	Service, turn, or wye train 715
SAN	573	09/14	6	6	Service, turn, or wye train 562
SAN	581	09/14	26	26	Service, turn, or wye train 770
SAN	587	09/14	31	31	Hold for connecting train 774
SAN	765	09/14	38	38	Other electrical failure 480 not loading, switch consists to 6901/2118, 2109
SAN	769	09/14	15	5	Copy authority / restriction
SAN	769	09/14	15	10	PTC - On Board Cab Signal or PTC Failure 90225
SEA	503	09/14	18	18	Broken speedo no tag, wait for proper non compliant tags 90252
SEA	507	09/14	10	10	Last minute switch of equipment to the 90250 and the 72
SJC	550	09/14	23	23	Re-crew / job briefing Wait for engineer for reroute on Mulford., Other, SJC

Eastern Region

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	98.9	94.8	342	2
CDOT	95.0	90.0	89.2	92.4	20	2
MARC	95.0	93.1	91.1	90.2	58	4
SEPTA	95.0	85.3	90.8	91.5	204	30
NJT-NED	95.0	92.4	93.5	88.6	357	27
NJT-SED	95.0	95.8	98.5	97.2	24	1

Operating Highlights

Southeast Region - CSX Heat Orders

15SEP26: Due to excessive heat, CSX imposed speed restrictions on the following subdivisions in its territories: Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal

Train	Delay	Comment
52 (14)	08"	
40 (14)	1'01"	
98 (14)	47"	
97 (13)	27"	

Train 40(14) - North of Lakeland, FL - Switch Failure

14SEP26: Train 40(14) was delayed at MP 814.1 on the CSX Carters Subdivision due to switch failure ahead at MP 813.5. CSX dispatched a maintainer to resolve the issue.

Train	Delay	Comment
40 (14)	1'21"	

Train 98(14) - Savannah Station, GA - System

14SEP26: Train 98(14) was delayed at Savannah Station/MP 490.9 on the CSX Savannah Subdivision due to a CSX internal system failure. The outbound crew was unable to receive updated bulletins due to a CSX system failure. The crew had to have orders/bulletins delivered from the yard by hand.

Train	Delay	Comment
98 (14)	47"	

Train 49(14) - Albany-Rensselaer Station, NY - Engine Failure

14SEP26: Train 49(14) was delayed at Albany-Rensselaer Station, NY due to the late release of engines from the shop.

Train	Delay	Comment
49 (14)	50"	

Train 53(14) - South of Selma, NC - Car Failure

14SEP26: Train 53(14) was delayed on the CSX South End Subdivision at MP 187.2. The cause was a loose/defective hose on the last passenger car.

Train	Delay	Comment
53(14)	35"	

Train 53(14) - South of Petersburg, VA - Car Failure

14SEP26: Train 53(14) was delayed on the CSX North End Subdivision at MP 52.4 due to a cut in the air hose on the EOT Device, which paced the train into an undesired emergency. The crew used the spare hose on the last coach as a replacement.

Train	Delay	Comment
53(14)	53"	

Train 97(14) - Trenton, NJ - Engine Failure

14SEP26: Train 97(14), after a substantial initial terminal delay, was delayed again at Trenton Station/MP 56.7 on the Amtrak NYP Line due to faults with the trail engine 151. The crew observed smoking conditions on E/151. The crew was instructed to cut both trucks out at Trenton and continue west. Upon arrival at 30th Street Station/MP 1.4 on the PW Line, mechanical personnel met the train and the decision was made to shop the E/151. Crews removed the engine and stowed it in Penn Coach Yard at Philadelphia. The Mechanical Supt. at Penn Coach Yard reported the problem was due to improper set up at the initial terminal/Sunnyside Yard.

Train	Delay	Comment
97(14)	1'24"	Trenton
97(14)	2'17"	30th Street/Philadelphia

Train 56(14) Springfield, MA - System

14SEP26: Train 56(14) with 135 customers was delayed departing Springfield due to holding for the late arriving engineer off the alternate bus transportation from train 55(14). Once the engineer arrived, briefed, and boarded the train, 56(14) departed Springfield at 430PM-ET, 1 hour, and 15 minutes late.

Train	Delay	Comment
56(14)	1'09"	

Train 97(14) New York, NY - Initial Terminal Delay

14SEP26: Train 97(14) with 134 customers was delayed departing New York due to E/632 shopped for a hot bearing fault at 1140AM-ET and replaced with E/643. This caused late train make up and release. Once the train was released and set in the station, the customers were welcomed aboard, and 97(14) departed New York at 337PM-ET, 1 hour, and 7 minutes late.

Train	Delay	Comment
97(14)	1'07"	

Amtrak NHB Line East of New Haven, CT - Catenary or Wayside Failure

14SEP26: The power line reported a bridge failure of C&D east of New Haven between Mill River/MP 73.6 and Westbrook/MP 101.2. Train 2163(14) was delayed due to it being necessary to deprepare. Train 85(14) was delayed operating around train 2163(14).

Train	Delay	Comment
2163(14)	26"	
85(14)	22"	

Train 90(14) North of Charleston, SC - Signal

14SEP26: Train 90(14) was delayed on the CSX Charleston subdivision starting at Charleston station. The crew held at Charleston due to an inoperable fax machine and waiting to receive new orders. Further delay was accumulated north of Charleston between MP 387.2 and MP 378.0 due to issues with road crossings and operating at reduced speed. There were 17 false partials and one activation failure reported.

Train	Delay	Comment
90(14)	41"	N/CHS
90(14)	17"	CHS

Train 71(14) South of Greensboro, NC - Trespasser Incident

14SEP26: Train 71(14) with NC/103, four cars, NC/1755, and 90 customers was delayed on the NS Danville district just south of Greensboro, North Carolina in Guilford County due to fatally striking a trespasser on main track one, who was laying in the gauge at MP 284.6 in the crossover at CP Elm. There were no reported injuries to the customers or the crew. Greensboro Police and Fire responded to the scene as well as a Crime Scene Investigator. Amtrak Assistant Superintendent responded to the scene. Both tracks at the scene were affected and train 80(14) was held just south of the location at MP 284.8. The crew requested and was granted relief.

Once the scene was released, train 71(14) shoved back to Greensboro station, was terminated, and the equipment held at Greensboro to become train 75(14). One bus was secured as alternate transportation for all customers on train 71(14) traveling between Greensboro and Charlotte. Train 72(14) was cancelled entirely with one bus secured as alternate transportation, making all stops between Charlotte and Greensboro. Once train 71(14) was clear of the crossover at CP Elm, train 80(14) continued to Greensboro.

National Response Center Number: 1473522

Train	Delay	Comment
71(14)	Term GRO	
80(14)	2'13"	
72(14)	Canc CLT-GRO	

Train 141(14) Springfield, MA - Crew

14SEP26: Train 141(14) was delayed at the initial terminal of Springfield, MA due to a crew issues with no crew assigned to work train. The regularly assigned crew was scheduled to operate train 146(13) New Haven to Springfield and as a result of the termination of train 146(13) at New York, the crew was not in position to operate train 141(14) at Springfield. The decision was made to cancel deadhead move 5552(14) and train 425(14) to reassign the crew to work 141(14). Once the crew was notified and occupied train 141(14) equipment, they were able to depart Springfield. The 4 customers on train 425(14) were provided alternate transportation by Uber to Springfield.

Train	Delay	Comment
141(14)	31"	

Train 40(12) Pittsburgh, PA - Servicing

14SEP26: Train 40(12) 28-FCI-0075708 00000008818 UNCLASSIFIED 9/29/2026
arriving fuel truck. Once the locomotives were fueled, 40(12) departed Pittsburgh at
510AM-ET, 5 hours, and 11 minutes late.

Train	Delay	Comment
40(12)	36"	

Maintenance of Way Highlights

NS Danville District 26-FOT-00757 00000008916 "UNCLASSIFIED" 9/28/2021 East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	26-FOI-00757 00000008818 "UNCLASSIFIED" 9/29/2026
78(03)	50"	Turn of Late 77(03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Train 518(14) South of Vancouver, BC - Routing

15SEP26: Train 518(14) was delayed south of Vancouver, BC, at Piper (MP 147.39) on the CN New Westminster Subdivision after the crew was unable to establish communication with the dispatcher. The train remained stopped pending communication with the dispatcher and authorization to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518 (14)	31"	

Train 718(14) West of Stockton, CA - Passenger Train Interference

14SEP26: Train 718(14), carrying 97 customers onboard, was delayed west of Stockton, CA, at Holt (MP 1129.5) on the BNSF Stockton Subdivision while meeting Amtrak Trains 717(14) and 719(14).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718 (14)	43"	

Train 48/448(14) South of Chicago, IL - Freight Train Interference

14SEP26: Train 48/448(14), with 207 customers onboard, was delayed between control point 506/MP506.5 and Porter, IN/MP482.2, beginning 16 miles south of Chicago, IL/MP0.0, on the NS Chicago Terminal subdivision following multiple NS freights. Once the route was clear, train 48/448(14) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448 (14)	33"	

Train 6(13) East of Fort Morgan, CO - Temporary Speed Restrictions

14SEP26: Train 6(13), 170 customers onboard, was delayed between mile post 426.1 and mile post 296.4, beginning 38 miles east of Fort Morgan, CO/MP464.2, on the BNSF Akron subdivision following temporary speed restrictions. Once clear of the affected area, train 6(13) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6 (13)	30"	

Train 5(14) West of Creston, IA - High Wind Warnings

14SEP26: Train 5(14), with 171 customers onboard, was delayed between mile post 393.5 and mile post 441.0, beginning 0.4 miles west of Creston, IA/MP393.1, on the BNSF Creston subdivision following high wind warnings of up to 70MPH and critical flash flood warnings. Once clear of the affected area, train 5(14) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5 (14)	2'13"	

Train 355(14) West of New Buffalo, MI - Freight Train Interference

14SEP26: Train 355(14), with 100 customers onboard, was delayed at Porter, IN/MP482.2, 21.7 miles west of New Buffalo, MI/MP218.9, on the Michigan Department of Transportation Michigan Line subdivision meeting multiple freights in cross traffic. Once the route was clear, train 355(14) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(14)	39"	

Train 3(14) West of Fort Madison, IA - Freight Train Interference

14SEP26: 3(14), with 241 customers onboard, was delayed at the West Fort Madison control point/MP236.2, 4.7 miles west of Fort Madison, IA/MP232.9, on the BNSF Marcelline subdivision meeting BNSF freight BN/5795. Once the route was clear, train 3(14) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(14)	1'08"	

Train 8/28(13) West of Malta, MT - Passenger Train Interference

14SEP26: Train 8/28(13) was delayed west of Malta, MT, while holding at Wagner (MP 352.3) on the BNSF Milk River Subdivision to meet Amtrak 7/27(13) as well as BNSF Train Z-CHCSSE8-13, led by BNSF 2026.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(13)	56"	Amtrak
8/28(13)	05"	BNSF 2026

Train 26(14) South of Gulfport, MS - Freight Train Interference

14SEP26: Train 26(14), with 40 customers onboard, was delayed at Gulfport, MS/MP739.38, on the CSX N.O.&M. subdivision meeting CSX freight 648 at KCS Interlocking/MP739.4. Freight 648 was holding for a recrew. Train 25(14) was delayed as well south of the KCS Interlocking. Once the freight recrew was complete, the freight continued south with train 26(14) following. Once the route north was clear, train 25(14) continued north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
26(14)	47"	
25(14)	2'22"	

Train 41(14) Chicago, IL - Initial Terminal Delay

14SEP26: Train 41(14), with 210 customers to board, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late turn of the equipment off inbound 40(12) and the late sign up of the road crew. The equipment was serviced, the engines flat switched, and train 41(14) was made up complete at 7:23PM-CT. Mechanical released the equipment and train 41(14) shoved into the depot. The crew signed up rested at 8:08PM-CT. Once the customers boarded, train 41(14) departed Chicago Union Station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(14)	2'16"	

Train 354(14) East of Chicago, IL - Freight Train Interference

14SEP26: Train 354 (26-FCI-00757) with 00000008838 customers onboard was delayed between 21st Street/MP521.1 and control point 507/MP507.2, meeting multiple freights. Once the route was clear, train 354(14) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(14)	39"	

Train 538(14) South of Fremont, CA - Police Related

14SEP26: Train 538(14) with 49 customers onboard was delayed south of Fremont, CA, after stopping at Newark (MP 31.4) on the Union Pacific Coast Subdivision due to police activity that resulted in the closure of the Union Pacific Niles Subdivision north of Fremont near MP 30.74. To maintain service, a decision was made to detour the train via the Coast Subdivision, bypassing the Fremont, CA, and Hayward, CA, station stops.

The following customer accommodations were implemented:

-BART mutual aid was requested and granted between Oakland Coliseum Airport Station and San Jose, CA, to assist affected customers.

-Uber vouchers were provided to customers impacted by the station bypasses and service disruption.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
538(14)	17"	Bypass FMT & HAY

Train 544(14) Hayward, CA - Police Related

14SEP26: At approximately 6:15 PM PT, Train 544(14), carrying 32 customers onboard, was delayed at Hayward, CA, Station (MP 20.1) on the Union Pacific Niles Subdivision after train movements were suspended due to a reported trespasser incident ahead around MP 18.2. The incident was subsequently determined to be a fatality unrelated to train operations; however, the tracks remained closed while local authorities conducted their investigation.

The incident resulted in the following service impacts and recovery actions:

-Train 544(14) made a reverse movement to Newark (MP 31.4 Coast Subdivision) and was rerouted via the Union Pacific Coast Subdivision to Oakland Coliseum Airport Station.

-Train 547(14) operated via the Coast Subdivision, bypassing Hayward, CA, and Fremont, CA, station stops.

-Train 550(14) was delayed departing San Jose, CA, while awaiting a detour-qualified engineer and subsequently operated via the Coast Subdivision, bypassing Fremont and Hayward station stops.

-BART mutual aid was requested and granted between Oakland Coliseum Airport Station and San Jose, CA, to assist affected customers.

-Uber vouchers were provided to customers impacted by the station bypasses and service disruption.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
544(14)	1'29"	
547(14)	32"	Bypass HAY & FMT
550(14)	51"	Bypass FMT & HAY

Train 716(14) Oakland, CA - Third Party Contractor Engine Failure

14SEP26: Train 716(14) delayed due to equipment reassignment involving its planned consist of locomotive C2004 and eight cars. Locomotive C2004 was bad ordered after an inoperative wiper motor was identified. An initial plan was developed to operate the train using the cab car to shove to Oakland Jack London square and then wye the equipment once in Bakersfield, CA; however, the operating plan was later revised. Inbound Train 713(14) equipment with E/C2123 and 8 cars was utilized for Train 716(14). As part of this plan, Train 713(14) was terminated at Emeryville, CA, with customers using 543(14) for travel to Jack London and the equipment was sent directly to the yard for servicing. Once servicing was completed, the equipment was released and used to operate Train 716(14).

The reassignment of Train 713(14) equipment also impacted Train 718(14), as the equipment was scheduled to make that turn. To maintain service, a decision was made to utilize inbound Train 715(14) equipment, consisting of locomotive C2012 and six cars, to operate Train 718(14). The equipment first returned to the Oakland Maintenance Facility for servicing and fueling before being released for service. Once prepared and released, Train 718(14) operated to Oakland Jack London Square and departed with 19 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(14)	3'27"	
713(14)	Term EMY	
718(14)	1'20"	

Train 786(14) South of Lompoc-Surf, CA - Passenger Train Interference

14SEP26: Train 786(14), carrying 102 customers onboard, was delayed approximately 15 miles south of Lompoc-Surf Station, while holding at Sudden Siding (MP 314.1) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(14) and 14(14). Train 786(14) was further delayed holding at Santa Barbara Station platform to meet late operating 769(14) and then met them at South Santa Barbara (MP 367.9).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
786(14)	33"	
786(14)	31"	

Train 20(14) North of Tuscaloosa, AL - Back Up Hose Issue

14SEP26: Train 20(14), with 124 customers onboard, stopped at mile post 176.4 and again at mile post 146.0, beginning 22 miles north of Tuscaloosa, AL/MP198.4 on the NS AGS South subdivision due to a sudden loss of air brake pressure. Both times the crew inspected and found the back up hose had come apart. The crew attached the back up hose, rebuilt air brake pressure, and continued north after completing a brake test.

Train 20(14) was further delayed at control point Bryant/MP197.5, 1.1 miles north of Tuscaloosa, meeting Amtrak train 19(13).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
20(14)	50"	Back Up Hose
20(14)	30"	PTI 19(13)

Train 59(14) Late Departure Chicago, IL - Servicing

14SEP26: Train 59(14), E/181 & 7 cars, with 180 customers, was delayed departing Chicago, IL, due to turning E/153 off Train 6(12) and C/39003 and C/34052 off Train 22(13)/422(11). E/181 was a replacement for E/196 which was utilized on Train 5(14). C/39003 was a replacement for C/39005 which was shopped for a bad order bolster spring and C/34052 was a replacement for C/34037 which was utilized on Train 21(14).

Train 7/27(13) West of Williston, ND - Freight Train Interference

14SEP26: Train 7/27(13) was delayed west of Williston, ND, while holding at Bainville (MP 160.5) on the BNSF Glasgow Subdivision to meet BNSF 6864 and BNSF 254.

Train	Delay	Comment
7/27(13)	43"	

Train 7/27(13) East and West of Wolf Point, MT - High Wind Warnings

14SEP26: Train 7/27(13) was delayed between Williston, ND, and Wolf Point, MT, on the BNSF Glasgow Subdivision due to high wind warnings in effect between MP 148.0 and Wolf Point Station (MP 227.3). The train was required to operate at reduced speeds through the affected territory in accordance with operating restrictions associated with the high wind conditions. The train incurred additional delays west of Wolf Point, MT, while operating under further high wind restrictions between Wolf Point and MP 277.5 on the BNSF Glasgow Subdivision.

Train	Delay	Comment
7/27(13)	32"	WPT-GGW
7/27(13)	43"	WTN-WPT

Train 4(13) Albuquerque, NM - Commuter Train Interference

14SEP26: Train 4(13), carrying 117 customers onboard, was delayed east of Albuquerque, NM, on the NMRX Glorieta Subdivision while meeting NMRX train traffic at East Bernalillo (MP 885.6) and East Domingo (MP 865.2).

Train	Delay	Comment
4(13)	31"	

Train 22(14) Fort Worth, TX - Fueling

14SEP26: Train 22(14), with 69 and 150, 7 cars, and 98 customers onboard, was delayed departing Ft Worth Central Station, TX/MP346.2 on the BNSF Fort Worth subdivision due to additional time required to fuel the engines. Once fueling was complete, train 22(14) departed Ft Worth Central Station.

Train	Delay	Comment
22(14)	33"	

Train 40(12) West of Toledo, OH - Freight Train Interference

14SEP26: Train 40(12) was delayed west of Toledo, OH/MP288, on the NS Toledo Terminal Subdivision, following NS 17N between MP288 and MP317.

Train	Delay	Comment
40(12)	30"	

Train 3(14) Late Departure Chicago, IL - Engine

14SEP26: Train 3(14), E/19-E/118 & 9 cars, with 236 customers, was delayed departing Chicago, IL, due to the intended trail engine, E/61 shopped at 1140AM-CT for loading issues. It was necessary to turn E/118 off Train 49/449(13) as the replacement trail unit on Train 3(14).

Train	Delay	Comment
3(14)	1:00"	

Train 702(14) Madera, CA - Broken Rail

14SEP26: Train 702(14) was delayed west of Madera, CA, on the BNSF Stockton Subdivision due to a broken rail at MP 1021.6 encountered by a freight train operating ahead. As a precaution, Train 702(14) was routed into the Le Grand siding at MP 1040 to await assessment of the affected track. Following inspection, the track was determined to be passable, and trains were authorized to proceed over the affected location at a restricted speed of 9 mph.

Train 702(14) was also delayed prior to the broken rail by multiple freight train meets as well as some after with cumulative route delays totaling two hours and twenty-seven minutes late into Bakersfield, CA. Train 717(14) was delayed departing from this late inbound equipment.

WBS#: B.TR.100150.7176

Train	Delay	Comment
702(14)	1'36"	
713(14)	1'04"	
710(14)	34"	
717(14)	1'41"	late turn of 702(14)

Train 774(14) South of Lompoc-Surf, CA - Power Outage

14SEP26: Train 774(14) was delayed south of Lompoc/Surf, CA, on the UPRR Santa Barbara Subdivision due to a commercial power outage. The outage was believed to be a precautionary shutoff by the power company between MP 335 and MP 320 due to elevated fire conditions and wildfire risk. Following an inspection of the affected area and fire conditions, commercial power was restored, allowing operations to resume.

Train	Delay	Comment
757(14)	1'02"	
774(14)	46"	
587(14)	31"	late turn 774(14) equip

Train 765(14) San Diego, CA - System

14SEP26: Train 765(14), operating with C2109 and C2119, was delayed departing San Diego, CA, on the SCRRA/Metrolink Subdivision due to trainline issues. The trainset experienced an electrical failure with the 480V system not loading. To mitigate the delay and minimize the impact to customers, the consist was switched to operate with C2118, allowing the train to continue service.

Train	Delay	Comment
765(14)	38"	

Train 49/449(13) West of South Bend, IN - Debris Strike

14SEP26: Train 49/449(13), E/118-E/132 & 11 cars, with 294 customers, reported striking a vulture at MP470, 32 miles west of South Bend, IN, on the NS Elkhart West Subdivision. E/118 engineer side mirror was broken as a result of the bird strike. There were no other exceptions to the equipment report and no delay.

Train 19(13) West of Atlanta, GA - Police Related

14SEP26: Train 19(13), with 66 customers onboard, was delayed at MP682.5, 49 miles west of Atlanta, GA, on the NS East End District, due to a body on the tracks ahead. Local Police and NS responded to the scene. Train 19(13) was delayed holding for completion of the investigation and for open route ahead.

Train	Delay	Comment
19(13)	1'31"	

Train 40(12) West of Pittsburgh, PA - Engine

14SEP26: Train 40(12), E/39-E/346 & 11 cars, with 108 customers, was delayed at MP57.4, 57 miles west of Pittsburgh, PA, on the NS Conway West Subdivision, due to cab signal failure on E/39. Train 40(12) cut out cab signals on E/39 and continued west. Train 40(12) was further delayed beginning 6 miles west of Alliance, OH, on the NS Cleveland Terminal Subdivision, due to E/39 PTC held train at restricting between MP73 and MP86 and between MP94 and MP102.

Train	Delay	Comment
40(12)	22"	W/PGH, MP57.4
40(12)	35"	W/ALC, MP73-MP86
40(12)	40"	W/ALC, MP94-MP102

Train 3(13) West of La Plata, MO - Freight Train Interference

14SEP26: Train 3(13), with 257 customers, was delayed beginning 94 miles west of La Plata, MO, on the BNSF Marceline Subdivision, following BNSF 8064 between CA Junction/MP418.0 and West Sibley/MP426.4.

Train	Delay	Comment
3(13)	30"	

Train 351(14) North of Detroit, MI - Switch Failure

14SEP26: Train 351(14), with 54 customers, was delayed at Beaubien/MP54.0, 1 mile north of Detroit, MI, on the CN Shore Line, due to power switch failure. Train 351(14) reversed back approximately 1 mile to D&M/MP4.4, on the CN Holly Subdivision, and then crossed over to proceed west on No 2 track.

Train	Delay	Comment
351(14)	42"	

Train 41(13) East of Alliance, OH - Freight Train Interference

14SEP26: Train 41(13) was delayed at MP34.0, 49 miles east of Alliance, OH, on the NS Conway West Subdivision, meeting NS27G.

Train	Delay	Comment
41(13)	35"	

Train 19(13) North of Laurel, MS - Freight Train Interference

14SEP26: Train 19(13), with 71 customers onboard, was delayed between Barnett/MP30.0 and Laurel, MS/MP56.4, beginning 26 miles north of Laurel following NS freight NS355. Once the route was clear, train 19(13) continued south.

Train	Delay	Comment
-------	-------	---------

Train 5(14) West of Ottumwa, IA - Engine Failure

15SEP26: Train 5(14), 26-FBI-00757, 00000008818, UNCLASSIFIED, 9/29/2026, 186 customers onboard, was delayed west of Ottumwa, IA/MP279.8 on the BNSF Ottumwa subdivision inspecting an engine fault for a blown fuse on the engine 196. The crew was unable to address the issue en route. Engine 196 was shut down and BNSF freight BN/8785 was secured and added in Lincoln, NE/MP0.8.

Train	Delay	Comment
5(14)	26"	Engine inspection
5(14)	37"	Adding freight in LNK

Train 11(14) North of Eugene, OR - Debris Strike

14SEP26: Train 11(14), operating with locomotives E/349 and E/345, nine cars, and carrying 206 customers onboard, was delayed north of Eugene, OR, at MP 667.9 on the Union Pacific Brooklyn Subdivision due to a Positive Train Control (PTC) system failure. The PTC system degraded to a disengaged state, prompting the crew to perform a system power cycle; however, the issue was not resolved. Further inspection determined the train had previously struck a broken crossing gate arm, damaging the axle 2 speed sensor and causing the PTC system failure. Following coordination with the host railroad and operating authorities, the train was authorized to continue operating with the affected system under a maximum authorized speed of 59 MPH.

Train	Delay	Comment
11(14)	38"	Reboot N/ EUG
11(14)	35"	Troubleshoot at EUG
11(14)	11"	EUG-KFS 59mph

City of New Orleans Service Adjustments - Engine Availability

14SEP26: Due to engine availability, the following City of New Orleans service adjustments are in effect:

- On Tuesday, September 15th, Train 59(15) is cancelled entirely. No alternate transportation between Chicago, IL and New Orleans, LA.
- On Thursday, September 17th, Train 58(17) is cancelled entirely. No alternate transportation between New Orleans, LA and Chicago, IL.

Train	Delay	Comment
59(15)	Cancelled	
58(17)	Cancelled	

Train 4(12) East of Kansas City, MO - Freight Train Interference

14SEP26: Train 4(12) was delayed beginning 30 miles east of Kansas City, MO, on the BNSF Marceline Subdivision, following freight traffic between Sibley/MP424.9 and CA Junction/MP418. Train 4(12) was further delayed at MP336, 23 miles west of La Plata, MO, due to a track indication on Main 1 between E. Ethel/MP329.3 and La Plata/MP312.7 and single tracking through the area. Train 4(12) continued to follow eastbound freight traffic through the area to Fort Madison/MP232.9.

Train	Delay	Comment
4(12)	2'08"	

Train 28(13) West of Pasco, WA - Engine Failure

14SEP26: Train 28(13) E/198 400000008818 with UNCLASSIFIED 9/29/2026 as delayed at MP146.4 on the BNSF Lakeside Subdivision , 0.5 miles west of Pasco, WA due to the main compressor stopped on E/198. The crew worked with CNOC mechanical to troubleshoot the issue. The train maintained head-end power during this event. After several attempts to resolve were unsuccessful, a freight unit was sourced from BNSF. Once BNSF 3922 arrived and was added ahead of E/198, the train was able to proceed west towards Pasco.

Train	Delay	Comment
28(13)	1'38"	
8(13)	1'39"	Hold for 28(13)
8/28(13)	34"	Routine inspection with Frt unit

CN Heat Orders - Weather

CN reports as of 11SEP, there are heat restrictions across the Yazoo and McComb subdivisions between 11:00am CT and 10:00pm CT daily until further notice.

Trains 58 and 59 affected.

Train	Delay	Comment
58(12)	24"	NOL-MEM
58(13)	1'12"	HMD-MEM
59(12)	02"	
58(14)	1'06"	HMD-MCB

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

9/29/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
11 (22AUG)	32"	
14 (22AUG)	23"	
11 (12SEP)	29"	
14 (12SEP)	58"	Detour/ FTI

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00757 00000008818 UNCLASSIFIED 9/29/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
3 (12)	LAJ	BN8170	BN5809 released at LAJ due to a bad horn. Previously added at XAR due to both E/15-78 failing enroute		
28 (13)	PSC	BN3922	E/198 failed air compressor		
5 (14)	LNK	BN8785	E/196 blown rad fan		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of PGR's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train6(13) Passenger Removal at Elko, Nevada – Improper Conduct

13SEP26, Passenger on PNR 03488C, traveling from Elko, NA to Salt Lake City, UT reportedly Passenger had altercation with another passenger Passengers and was removed at MP:806 by Wendover Police. Amtrack Police were notified.

Delay: 06(13) 21"

Consist Deviations

26-FOI-00757

00000008818

"UNCLASSIFIED"

9/29/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
572 (15)	LAX	NO BIKE SPACE OR WIFI	Passengers notification email sent no wifi no bike space.	0	90225
765 (15)	SAN	no bike space or wifi	pax notified no bike space no wifi	2	90225
765 (14)	SAN	no bike space or wifi	pax notified no bike space no wifi	2	90225
567 (15)	SAN	NO BIKE SPACE OR WIFI	Passengers notification email sent no wifi no bike space.	1	90225
587 (15)	SAN	NO BIKE SPACE OR WIFI	Passengers notification email sent no wifi no bike space.	3	90225
794 (14)	SLO	no bike space or wifi	pax notified no bike space no wifi	1	90225

Reverse Consists

Train Number	Station	Reason
171 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front
190 (14)	PHL	Consist reversed Business class seat orientation may have changed At Front
95 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front
111 (14)	NYP	Business class change only Business class seating orientation may have changed At Rear
182 (14)	WAS	Business class change only Business class seating orientation may have changed At Front
179 (14)	BOS	Business class change only Business class seating orientation may have changed At Rear
137 (14)	BOS	Consist reversed Business class seat orientation may have changed At Front
198 (14)	WAS	Consist reversed Business class seat orientation may have changed At Rear
136 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front
184 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
174 (14)	WAS	Consist reversed Business class seat orientation may have changed At Front