



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, September 17, 2026

Rules: 0-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/16/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	43	86.8%	4,946	714	85.6%	105,468	14,678	86.1%
Central Division	86.0%	55	3	94.5%	908	102	88.8%	20,103	1,877	90.7%
East Division	82.0%	178	17	90.4%	2,703	330	87.8%	55,523	8,460	84.8%
West Division	86.0%	92	23	75.0%	1,335	282	78.9%	29,842	4,341	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00757 00000008820 UNCL ASSIFIED 9/29/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	92,114	21,669	76%	1,600,381	414,200	74%	35,191,427	9,000,180	74%
Northeast Corridor	81%	44,404	6,896	84%	721,578	127,121	82%	15,436,477	3,714,403	76%
Acela	83%	12,029	1,700	86%	167,554	20,845	88%	3,130,180	779,985	75%
Northeast Regional	79%	32,375	5,196	84%	554,024	106,276	81%	12,306,297	2,934,418	76%
Richmond / Newport News / Norfolk	77%	8,282	1,908	77%	161,866	43,887	73%	3,684,665	1,091,186	70%
Springfield Shuttles	89%	736	113	85%	11,071	1,977	82%	217,473	35,115	84%
Roanoke	79%	3,251	497	85%	56,498	8,396	85%	1,170,301	258,090	78%
On Spine Northeast Regional	80%	20,106	2,678	87%	324,589	52,016	84%	7,233,858	1,550,027	79%
State Supported	80%	37,675	9,251	75%	691,225	189,553	73%	15,479,819	3,400,827	78%
Borealis	80%	410	197	52%	9,196	1,359	85%	197,185	41,830	79%
Capitol Corridor	90%	3,871	311	92%	61,046	8,132	87%	1,290,550	172,178	87%
Carolinian	70%	1,001	192	81%	18,135	5,600	69%	395,463	153,750	61%
Cascades	75%	1,844	669	64%	42,410	10,922	74%	893,046	251,576	72%
Downeaster	82%	1,337	149	89%	28,199	802	97%	548,179	62,647	89%
Empire	78%	4,925	1,153	77%	93,694	23,225	75%	1,935,498	478,187	75%
Adirondack	72%	251	2	99%	5,542	1,028	81%	119,637	37,981	68%
Ethan Allen Express	70%	459	208	55%	8,658	3,250	62%	195,560	75,526	61%
Maple Leaf	70%	709	327	54%	13,274	4,748	64%	241,586	94,627	61%
New York - Albany	85%	2,411	307	87%	41,303	7,063	83%	890,570	155,552	83%
New York - Niagara Falls	75%	1,095	309	72%	22,666	6,340	72%	473,058	106,849	77%
Berkshire Flyer	60%	0	0	-	2,251	796	65%	15,087	7,652	49%
Gold Runner	73%	987	739	25%	39,080	22,896	41%	868,802	331,655	62%
Heartland Flyer	70%	100	97	3%	3,096	1,722	44%	74,653	31,907	57%
Hiawatha	90%	1,670	7	100%	28,771	2,673	91%	612,548	66,520	89%
Illinois	78%	1,812	1,018	44%	38,934	16,407	58%	867,291	249,041	71%
Carl Sandburg / Illinois Zephyr	85%	302	120	60%	6,263	1,841	71%	144,009	41,175	71%
Illini / Saluki	85%	591	203	66%	14,042	6,314	55%	300,054	77,791	74%
Lincoln Service	70%	919	695	24%	18,629	8,252	56%	423,228	130,075	69%
Keystone	92%	9,124	880	90%	135,913	15,882	88%	2,649,804	272,134	90%
Lincoln / Missouri	70%	549	545	-1%	11,510	8,447	27%	269,121	143,904	47%
Mardi Gras Service	80%	268	62	77%	5,082	768	85%	139,034	30,753	78%
Michigan	70%	1,327	209	84%	33,342	13,164	61%	706,620	238,714	66%
Blue Water	70%	423	206	51%	7,966	2,701	66%	166,591	67,845	59%
Pere Marquette	85%	224	0	100%	4,222	726	83%	90,703	17,079	81%
Wolverine	70%	680	3	100%	21,154	9,737	54%	449,326	153,790	66%
Missouri	80%	132	38	71%	3,718	2,585	30%	77,078	23,850	69%
Pacific Surfliner	85%	6,168	2,438	60%	91,525	43,732	52%	2,818,371	562,305	80%
Pennsylvanian	80%	768	51	93%	13,936	2,909	79%	306,489	58,740	81%
Piedmont	80%	289	0	100%	14,653	2,920	80%	385,581	97,521	75%
Vermont	75%	1,093	496	55%	18,985	5,408	72%	444,506	133,615	70%
Long Distance	70%	10,035	5,522	45%	187,578	97,526	48%	4,235,864	1,882,487	56%
Auto Train	70%	594	245	59%	10,051	4,506	55%	270,122	93,247	65%
California Zephyr	70%	707	324	54%	14,976	6,421	57%	336,311	132,600	61%
Cardinal	70%	215	109	49%	3,352	1,927	43%	80,368	41,178	49%
City Of New Orleans	75%	215	213	1%	10,040	9,074	10%	219,692	81,539	63%
Coast Starlight	70%	965	260	73%	17,719	5,311	70%	394,973	139,953	65%
Crescent	70%	707	72	90%	13,958	2,960	79%	319,355	97,430	69%
Empire Builder	70%	1,469	1,072	27%	17,671	9,652	45%	337,227	170,402	49%
Floridian	60%	1,070	1,070	0%	23,316	18,195	22%	543,222	378,201	30%
Lake Shore Ltd	73%	880	455	48%	16,233	6,540	60%	337,914	104,383	69%
Palmetto	70%	712	166	77%	12,705	4,212	67%	315,886	99,010	69%
Silver Meteor	70%	745	332	55%	14,212	8,319	41%	348,622	163,723	53%
Southwest Chief	60%	807	708	12%	13,617	8,510	38%	290,872	192,105	34%
Sunset Ltd	70%	320	0	100%	4,115	1,530	63%	99,819	40,029	60%
Texas Eagle	70%	629	496	21%	15,613	10,369	34%	341,481	148,687	56%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00757 000000000000 "UNCLASSIFIED" 0/20/2020

Train Index Dates Through September 16, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	104,778	1,728,931	606	2,104,596	37,003,097	569

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,399	524,889	84	100,838	10,732,323	94
INFRASTRUCTURE PLANNED	135	9,097	524,889	173	124,643	10,732,323	116
FLEET RELIABILITY	90	18,588	1,728,931	108	338,133	37,003,097	91
TRAIN OPERATIONS	424	72,694	1,728,931	420	1,540,982	37,003,097	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 09/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/16/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	43	86.8%	4,946	714	85.6%	105,468	14,678	86.1%
Central Division	86.0%	55	3	94.5%	908	102	88.8%	20,103	1,877	90.7%
East Division	82.0%	178	17	90.4%	2,703	330	87.8%	55,523	8,460	84.8%
West Division	86.0%	92	23	75.0%	1,335	282	78.9%	29,842	4,341	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/16/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	43	86.8%	4,946	714	85.6%	105,468	14,678	86.1%
Central Division	86.0%	55	3	94.5%	908	102	88.8%	20,103	1,877	90.7%
CDL	95.0%	2	0	100.0%	32	4	87.5%	668	35	94.8%
CHI	86.0%	25	2	92.0%	423	69	83.7%	9,293	1,169	87.4%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	16	1	93.8%	374	39	89.6%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	14	0	100.0%	328	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	32	1	96.9%	680	55	91.9%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	94	3	96.8%	2,053	129	93.7%
MOE	97.5%	2	0	100.0%	32	1	96.9%	699	10	98.6%
MSP	96.5%	1	1	0.0%	16	1	93.8%	344	8	97.7%
NOL	94.5%	5	0	100.0%	70	2	97.1%	1,480	66	95.5%
OKC	97.0%	1	0	100.0%	15	0	100.0%	344	6	98.3%
PNT	88.0%	1	0	100.0%	38	2	94.7%	914	75	91.8%
PTH	93.0%	1	0	100.0%	16	1	93.8%	339	14	95.9%
QCY	91.0%	2	0	100.0%	29	1	96.6%	660	49	92.6%
SAS	90.5%	1	0	100.0%	16	3	81.3%	348	42	87.9%
STL	89.0%	4	0	100.0%	60	8	86.7%	1,356	114	91.6%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	17	90.4%	2,703	330	87.8%	55,523	8,460	84.8%
ALB	88.5%	8	1	87.5%	124	14	88.7%	2,608	202	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	80	2	97.5%	1,701	177	89.6%
BOS	85.5%	19	0	100.0%	279	26	90.7%	5,984	666	88.9%
BRK	92.5%	5	0	100.0%	80	3	96.3%	1,675	115	93.1%
BTN	82.0%	1	0	100.0%	16	3	81.3%	335	45	86.6%
CLT	91.5%	4	0	100.0%	71	7	90.1%	1,702	174	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	30	3	90.0%	678	63	90.7%
GRO	-	1	0	100.0%	9	3	66.7%	59	14	76.3%
HAR	79.5%	13	1	92.3%	178	19	89.3%	3,885	613	84.2%
HFD	-	2	0	100.0%	22	1	95.5%	254	18	92.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	16	1	93.8%	347	41	88.2%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/16/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/16/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	43	86.8%	4,946	714	85.6%	105,468	14,678	86.1%
East Division	82.0%	178	17	90.4%	2,703	330	87.8%	55,523	8,460	84.8%
MIA	89.5%	2	0	100.0%	32	7	78.1%	690	83	88.0%
MTR	79.0%	1	0	100.0%	15	2	86.7%	333	60	82.0%
NFK	84.5%	2	0	100.0%	32	4	87.5%	777	140	82.0%
NFL	93.5%	2	0	100.0%	32	1	96.9%	706	32	95.5%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	82	20	75.6%	1,784	307	82.8%
NPN	93.0%	2	0	100.0%	32	2	93.8%	666	53	92.0%
NYP	75.5%	51	6	88.2%	774	120	84.5%	14,703	3,177	78.4%
PGH	93.0%	1	0	100.0%	16	1	93.8%	348	24	93.1%
PHL	48.0%	5	1	80.0%	76	31	59.2%	1,771	830	53.1%
PIT	76.0%	-	-	-	4	3	25.0%	28	22	21.4%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	46	5	89.1%	1,310	59	95.5%
RNK	83.5%	2	0	100.0%	32	1	96.9%	690	94	86.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	13	0	100.0%	327	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	16	0	100.0%	344	12	96.5%
SFA	88.0%	1	0	100.0%	16	3	81.3%	347	50	85.6%
SPG	92.5%	5	1	80.0%	83	8	90.4%	2,045	121	94.1%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	16	4	75.0%	336	67	80.1%
WAS	84.0%	33	5	84.8%	481	36	92.5%	8,850	1,110	87.5%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	92	23	75.0%	1,335	282	78.9%	29,842	4,341	85.5%
ARN	92.0%	1	0	100.0%	16	2	87.5%	349	30	91.4%
BFD	79.0%	7	5	28.6%	110	38	65.5%	2,223	486	78.1%
EMY	72.0%	1	0	100.0%	18	7	61.1%	367	107	70.8%
EUG	86.5%	2	0	100.0%	31	3	90.3%	691	62	91.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	41	15	63.4%	1,042	187	82.1%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	11	3	72.7%	134	22	83.6%	3,454	391	88.7%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	5	61.5%	187	75	59.9%	3,806	1,028	73.0%
PDX	86.0%	5	0	100.0%	80	9	88.8%	1,685	234	86.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/16/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/16/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	325	43	86.8%	4,946	714	85.6%	105,468	14,678	86.1%
West Division	86.0%	92	23	75.0%	1,335	282	78.9%	29,842	4,341	85.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	15	3	80.0%	235	30	87.2%	4,954	550	88.9%
SAN	90.5%	13	3	76.9%	142	29	79.6%	4,179	421	89.9%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	3	62.5%	128	27	78.9%	2,681	407	84.8%
SJC	89.0%	7	0	100.0%	112	17	84.8%	2,452	246	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	42	2	95.2%	807	79	90.2%
SNA	-	-	-	-	1	0	100.0%	1	0	100.0%
SNC	-	-	-	-	7	1	85.7%	38	14	63.2%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	16	1	93.8%	328	30	90.9%
VAC	97.0%	2	0	100.0%	32	2	93.8%	685	16	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		7	1	85.7%	149	13	91.3%	7	1	85.7%	148	42	71.6%
3	179	16	6	62.5%	349	72	79.4%	16	5	68.8%	346	162	53.2%
4		16	6	62.5%	348	59	83.0%	16	6	62.5%	348	227	34.8%
5	406	16	4	75.0%	347	61	82.4%	16	5	68.8%	343	116	66.2%
6		16	6	62.5%	346	97	72.0%	16	8	50.0%	346	133	61.6%
7		16	1	93.8%	338	52	84.6%	16	3	81.3%	329	89	72.9%
8	59	16	6	62.5%	338	151	55.3%	16	10	37.5%	337	208	38.3%
11		16	4	75.0%	349	76	78.2%	16	2	87.5%	343	69	79.9%
14		16	8	50.0%	350	62	82.3%	16	1	93.8%	347	106	69.5%
19	70	16	1	93.8%	348	84	75.9%	16	4	75.0%	345	86	75.1%
20		16	0	100.0%	348	23	93.4%	16	1	93.8%	348	66	81.0%
21		16	1	93.8%	345	37	89.3%	16	7	56.3%	344	106	69.2%
22	409	16	3	81.3%	346	40	88.4%	16	13	18.8%	344	112	67.4%
23		16	1	93.8%	350	7	98.0%	16	4	75.0%	348	94	73.0%
24		16	0	100.0%	350	16	95.4%	16	3	81.3%	349	68	80.5%
25	36	16	0	100.0%	349	3	99.1%	16	2	87.5%	346	96	72.3%
26		16	1	93.8%	349	6	98.3%	16	2	87.5%	346	68	80.3%
27		16	3	81.3%	315	22	93.0%	16	4	75.0%	309	101	67.3%
28	65	16	2	87.5%	309	69	77.7%	16	3	81.3%	309	63	79.6%
40	204	16	5	68.8%	339	52	84.7%	16	9	43.8%	335	181	46.0%
41	345	16	13	18.8%	339	137	59.6%	16	15	6.3%	336	262	22.0%
42		16	1	93.8%	350	26	92.6%	16	2	87.5%	348	60	82.8%
43		16	1	93.8%	349	46	86.8%	16	5	68.8%	348	81	76.7%
48		16	1	93.8%	348	63	81.9%	16	6	62.5%	347	57	83.6%
49		16	5	68.8%	348	89	74.4%	16	5	68.8%	348	75	78.4%
50		7	2	71.4%	142	36	74.6%	7	6	14.3%	140	89	36.4%
52	59	16	3	81.3%	347	50	85.6%	16	5	68.8%	346	82	76.3%
53		16	1	93.8%	347	41	88.2%	16	8	50.0%	346	114	67.1%
55	43	11	1	90.9%	222	10	95.5%	11	1	90.9%	219	47	78.5%
56		11	0	100.0%	223	25	88.8%	11	5	54.5%	219	45	79.5%
58	37	16	1	93.8%	323	18	94.4%	16	16	0.0%	321	113	64.8%
63	35	16	4	75.0%	351	148	57.8%	16	16	0.0%	345	213	38.3%
64	27	16	4	75.0%	349	75	78.5%	16	9	43.8%	348	142	59.2%
66		16	1	93.8%	348	65	81.3%	16	2	87.5%	343	62	81.9%
67		11	3	72.7%	241	17	92.9%	11	2	81.8%	240	42	82.5%
68		16	2	87.5%	351	69	80.3%	16	3	81.3%	350	137	60.9%
69		16	5	68.8%	338	84	75.1%	15	3	80.0%	332	59	82.2%
71		16	1	93.8%	346	4	98.8%	15	1	93.3%	343	87	74.6%
72		16	2	87.5%	342	38	88.9%	15	1	93.3%	339	70	79.4%
75		16	4	75.0%	339	21	93.8%	16	5	68.8%	333	156	53.2%
76	Cncld	16	0	100.0%	339	31	90.9%	15	5	66.7%	328	135	58.8%
77		16	2	87.5%	341	23	93.3%	16	4	75.0%	338	137	59.5%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		16	4	75.0%	345	33	90.4%	16	4	75.0%	342	79	76.9%
79		16	1	93.8%	348	60	82.8%	16	6	62.5%	346	118	65.9%
80		16	1	93.8%	348	38	89.1%	16	3	81.3%	345	74	78.6%
84		11	1	90.9%	213	20	90.6%	11	2	81.8%	209	50	76.1%
85		11	0	100.0%	224	18	92.0%	11	4	63.6%	224	78	65.2%
86		11	0	100.0%	224	16	92.9%	11	4	63.6%	223	125	43.9%
89		16	2	87.5%	346	80	76.9%	16	5	68.8%	344	102	70.3%
90		16	0	100.0%	346	12	96.5%	16	3	81.3%	345	63	81.7%
93	20	11	0	100.0%	223	21	90.6%	11	7	36.4%	222	62	72.1%
94		11	2	81.8%	254	63	75.2%	11	4	63.6%	252	93	63.1%
95		11	1	90.9%	223	7	96.9%	11	5	54.5%	223	87	61.0%
97		16	11	31.3%	348	228	34.5%	16	8	50.0%	346	128	63.0%
98	56	16	2	87.5%	348	30	91.4%	16	6	62.5%	346	129	62.7%
110		10	1	90.0%	219	111	49.3%	9	0	100.0%	215	22	89.8%
111		11	0	100.0%	214	37	82.7%	11	1	90.9%	212	23	89.2%
112		11	2	81.8%	214	22	89.7%	11	0	100.0%	213	20	90.6%
113		11	0	100.0%	145	33	77.2%	11	0	100.0%	144	16	88.9%
119		11	1	90.9%	211	50	76.3%	11	1	90.9%	209	27	87.1%
125	20	11	0	100.0%	224	12	94.6%	11	6	45.5%	224	90	59.8%
129		11	1	90.9%	223	51	77.1%	11	1	90.9%	223	31	86.1%
130		11	0	100.0%	214	20	90.7%	11	0	100.0%	212	16	92.5%
131		11	1	90.9%	216	58	73.1%	11	0	100.0%	216	39	81.9%
134		11	1	90.9%	224	33	85.3%	11	0	100.0%	223	42	81.2%
136		11	1	90.9%	224	28	87.5%	11	3	72.7%	222	31	86.0%
137		11	2	81.8%	221	38	82.8%	10	3	70.0%	220	65	70.5%
138		11	1	90.9%	224	44	80.4%	11	1	90.9%	223	39	82.5%
141		11	2	81.8%	223	6	97.3%	11	2	81.8%	222	39	82.4%
148		11	2	81.8%	223	24	89.2%	11	2	81.8%	221	42	81.0%
151		16	4	75.0%	347	109	68.6%	16	3	81.3%	346	102	70.5%
170		11	0	100.0%	219	12	94.5%	11	1	90.9%	218	31	85.8%
171	32	11	0	100.0%	224	11	95.1%	11	4	63.6%	224	92	58.9%
172		11	1	90.9%	223	20	91.0%	11	5	54.5%	221	74	66.5%
173		11	2	81.8%	216	27	87.5%	11	2	81.8%	215	86	60.0%
174		11	0	100.0%	224	23	89.7%	11	2	81.8%	224	54	75.9%
175		11	1	90.9%	224	24	89.3%	11	3	72.7%	224	73	67.4%
176		10	0	100.0%	215	17	92.1%	10	2	80.0%	212	28	86.8%
177		11	1	90.9%	224	29	87.1%	11	3	72.7%	224	51	77.2%
178		11	0	100.0%	224	28	87.5%	11	1	90.9%	222	37	83.3%
179		11	1	90.9%	224	26	88.4%	11	6	45.5%	223	82	63.2%
181		11	2	81.8%	220	66	70.0%	11	2	81.8%	217	19	91.2%
182		11	1	90.9%	214	32	85.0%	11	3	72.7%	212	26	87.7%
183		11	2	81.8%	223	64	71.3%	11	1	90.9%	220	45	79.5%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		11	0	100.0%	224	36	83.9%	11	1	90.9%	223	29	87.0%
185		11	4	63.6%	224	45	79.9%	11	0	100.0%	224	18	92.0%
186		11	2	81.8%	223	31	86.1%	11	3	72.7%	222	64	71.2%
190		11	7	36.4%	223	82	63.2%	11	1	90.9%	222	45	79.7%
192		11	1	90.9%	221	25	88.7%	11	0	100.0%	221	19	91.4%
193	26	11	2	81.8%	219	85	61.2%	11	6	45.5%	218	96	56.0%
196		11	2	81.8%	220	25	88.6%	11	0	100.0%	218	17	92.2%
197	63	11	2	81.8%	224	79	64.7%	11	6	45.5%	224	77	65.6%
198		11	2	81.8%	156	19	87.8%	11	3	72.7%	155	25	83.9%
230		16	0	100.0%	184	4	97.8%	16	1	93.8%	184	10	94.6%
232		16	1	93.8%	350	13	96.3%	15	1	93.3%	349	24	93.1%
233	277	12	2	83.3%	307	68	77.9%	12	5	58.3%	306	106	65.4%
234		16	1	93.8%	351	24	93.2%	16	0	100.0%	350	29	91.7%
235		16	2	87.5%	275	44	84.0%	16	3	81.3%	274	63	77.0%
236		16	2	87.5%	335	12	96.4%	16	1	93.8%	334	44	86.8%
237		16	5	68.8%	348	66	81.0%	16	6	62.5%	346	65	81.2%
238		15	1	93.3%	274	24	91.2%	15	1	93.3%	272	23	91.5%
239		16	3	81.3%	349	86	75.4%	16	1	93.8%	348	43	87.6%
240		16	2	87.5%	350	25	92.9%	16	2	87.5%	347	71	79.5%
241		16	5	68.8%	350	87	75.1%	15	5	66.7%	349	86	75.4%
243	38	16	2	87.5%	286	73	74.5%	16	1	93.8%	285	40	86.0%
244	149	12	4	66.7%	306	16	94.8%	12	7	41.7%	306	72	76.5%
245		16	2	87.5%	231	43	81.4%	16	0	100.0%	230	30	87.0%
280		16	0	100.0%	351	17	95.2%	16	2	87.5%	350	80	77.1%
281		16	0	100.0%	351	40	88.6%	16	5	68.8%	351	65	81.5%
283	33	16	4	75.0%	351	89	74.6%	16	7	56.3%	351	73	79.2%
284		16	1	93.8%	351	14	96.0%	16	5	68.8%	348	66	81.0%
290		16	3	81.3%	351	55	84.3%	16	6	62.5%	348	143	58.9%
291	24	16	5	68.8%	350	117	66.6%	16	4	75.0%	346	94	72.8%
300	23	14	3	78.6%	332	25	92.5%	13	4	69.2%	328	77	76.5%
301	41	15	1	93.3%	347	11	96.8%	15	6	60.0%	343	69	79.9%
302	38	15	2	86.7%	328	36	89.0%	15	7	53.3%	324	97	70.1%
305	23	15	3	80.0%	331	34	89.7%	14	8	42.9%	325	130	60.0%
306		15	1	93.3%	345	18	94.8%	15	7	53.3%	343	96	72.0%
307		15	2	86.7%	338	46	86.4%	15	6	60.0%	334	104	68.9%
311		16	2	87.5%	343	30	91.3%	16	11	31.3%	337	95	71.8%
316	20	16	1	93.8%	339	25	92.6%	16	13	18.8%	333	114	65.8%
318	41	16	0	100.0%	349	35	90.0%	16	13	18.8%	346	179	48.3%
319	47	16	1	93.8%	350	21	94.0%	16	14	12.5%	345	207	40.0%
329		12	1	91.7%	248	13	94.8%	12	1	91.7%	248	20	91.9%
330		14	1	92.9%	298	7	97.7%	14	1	92.9%	298	16	94.6%
331		16	2	87.5%	351	35	90.0%	16	2	87.5%	350	46	86.9%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332	14	16	1	93.8%	350	20	94.3%	16	4	75.0%	350	50	85.7%
334		16	0	100.0%	351	11	96.9%	16	1	93.8%	349	44	87.4%
335		16	0	100.0%	351	35	90.0%	16	0	100.0%	348	55	84.2%
336		16	0	100.0%	350	10	97.1%	16	5	68.8%	348	34	90.2%
337		16	1	93.8%	351	22	93.7%	16	3	81.3%	347	50	85.6%
338		16	1	93.8%	351	55	84.3%	16	3	81.3%	348	107	69.3%
339		16	2	87.5%	351	56	84.0%	16	1	93.8%	351	59	83.2%
342		16	0	100.0%	351	26	92.6%	16	2	87.5%	349	63	81.9%
351		15	1	93.3%	332	30	91.0%	15	6	60.0%	330	98	70.3%
352		16	0	100.0%	317	24	92.4%	16	12	25.0%	311	105	66.2%
354		16	2	87.5%	332	39	88.3%	16	7	56.3%	324	123	62.0%
364		16	1	93.8%	340	74	78.2%	16	6	62.5%	334	126	62.3%
365	32	16	1	93.8%	339	14	95.9%	16	5	68.8%	336	129	61.6%
370		14	2	85.7%	335	41	87.8%	14	3	78.6%	322	78	75.8%
371		14	0	100.0%	328	11	96.6%	14	2	85.7%	324	32	90.1%
380	56	16	0	100.0%	332	30	91.0%	16	2	87.5%	331	74	77.6%
381		13	2	84.6%	344	17	95.1%	13	4	69.2%	341	75	78.0%
382		13	1	92.3%	343	31	91.0%	13	5	61.5%	341	121	64.5%
383		16	3	81.3%	337	30	91.1%	15	6	60.0%	333	144	56.8%
390		16	2	87.5%	332	26	92.2%	15	7	53.3%	329	93	71.7%
391	26	16	1	93.8%	333	15	95.5%	16	10	37.5%	328	98	70.1%
392	20	16	2	87.5%	346	13	96.2%	15	11	26.7%	340	114	66.5%
393	27	16	3	81.3%	350	22	93.7%	15	9	40.0%	345	113	67.2%
417		11	2	81.8%	232	49	78.9%	11	2	81.8%	223	27	87.9%
425		10	1	90.0%	234	8	96.6%	9	0	100.0%	232	7	97.0%
448		16	6	62.5%	275	55	80.0%	16	4	75.0%	271	93	65.7%
449		16	0	100.0%	272	34	87.5%	16	1	93.8%	272	46	83.1%
470		11	2	81.8%	247	42	83.0%	11	3	72.7%	241	30	87.6%
471		11	0	100.0%	236	14	94.1%	11	0	100.0%	236	6	97.5%
473		11	1	90.9%	243	16	93.4%	11	0	100.0%	240	10	95.8%
474		12	3	75.0%	240	69	71.3%	11	2	81.8%	224	73	67.4%
475		10	0	100.0%	239	8	96.7%	10	0	100.0%	239	16	93.3%
478		11	1	90.9%	235	37	84.3%	11	1	90.9%	233	29	87.6%
479	20	11	0	100.0%	242	36	85.1%	11	3	72.7%	240	39	83.8%
486		11	1	90.9%	246	36	85.4%	11	0	100.0%	240	61	74.6%
494		11	2	81.8%	249	49	80.3%	11	4	63.6%	241	68	71.8%
495		11	0	100.0%	230	4	98.3%	11	0	100.0%	228	3	98.7%
500		16	2	87.5%	325	18	94.5%	16	1	93.8%	322	37	88.5%
502		16	1	93.8%	333	20	94.0%	16	4	75.0%	329	65	80.2%
503	63	16	3	81.3%	347	43	87.6%	15	6	60.0%	339	108	68.1%
504		16	2	87.5%	351	22	93.7%	16	4	75.0%	349	103	70.5%
505		16	5	68.8%	343	48	86.0%	16	8	50.0%	338	99	70.7%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506		16	1	93.8%	346	57	83.5%	15	2	86.7%	337	53	84.3%
507		16	2	87.5%	351	51	85.5%	16	4	75.0%	351	119	66.1%
508		15	1	93.3%	345	44	87.2%	15	3	80.0%	341	84	75.4%
509		16	3	81.3%	332	18	94.6%	16	3	81.3%	332	74	77.7%
511		16	1	93.8%	327	26	92.0%	16	1	93.8%	326	54	83.4%
516	67	16	3	81.3%	342	38	88.9%	16	8	50.0%	341	154	54.8%
517	74	16	0	100.0%	351	8	97.7%	16	7	56.3%	347	157	54.8%
518	121	16	3	81.3%	351	49	86.0%	16	10	37.5%	349	242	30.7%
519		16	2	87.5%	342	11	96.8%	15	4	73.3%	339	76	77.6%
520	21	11	2	81.8%	205	31	84.9%	11	2	81.8%	200	13	93.5%
521		11	1	90.9%	243	8	96.7%	11	1	90.9%	242	32	86.8%
522	Cncld	11	3	72.7%	243	46	81.1%	10	1	90.0%	239	25	89.5%
523		11	1	90.9%	243	10	95.9%	11	2	81.8%	242	28	88.4%
524		11	1	90.9%	242	18	92.6%	11	2	81.8%	239	29	87.9%
525		11	1	90.9%	240	17	92.9%	10	1	90.0%	235	16	93.2%
526		11	4	63.6%	217	45	79.3%	10	1	90.0%	213	19	91.1%
527		11	0	100.0%	243	10	95.9%	11	1	90.9%	241	41	83.0%
528		11	0	100.0%	243	19	92.2%	11	2	81.8%	242	34	86.0%
529	24	11	1	90.9%	243	14	94.2%	11	3	72.7%	242	68	71.9%
530		11	3	72.7%	197	21	89.3%	10	2	80.0%	196	40	79.6%
531		11	2	81.8%	217	16	92.6%	11	2	81.8%	217	15	93.1%
532		11	3	72.7%	243	60	75.3%	11	2	81.8%	241	37	84.6%
534		11	4	63.6%	202	32	84.2%	11	1	90.9%	199	18	91.0%
535		11	1	90.9%	229	27	88.2%	11	1	90.9%	224	29	87.1%
536		11	4	63.6%	243	68	72.0%	11	2	81.8%	239	43	82.0%
538		11	4	63.6%	243	30	87.7%	11	1	90.9%	242	47	80.6%
539		11	1	90.9%	197	29	85.3%	11	4	63.6%	197	86	56.3%
540		11	2	81.8%	242	46	81.0%	11	2	81.8%	232	23	90.1%
541		11	1	90.9%	242	26	89.3%	11	1	90.9%	235	42	82.1%
542		11	1	90.9%	242	26	89.3%	11	3	72.7%	239	44	81.6%
543		11	3	72.7%	243	31	87.2%	11	8	27.3%	243	81	66.7%
544		11	0	100.0%	241	22	90.9%	11	1	90.9%	237	23	90.3%
545		11	2	81.8%	243	22	90.9%	11	1	90.9%	240	30	87.5%
547		11	3	72.7%	243	50	79.4%	11	4	63.6%	243	58	76.1%
548		10	0	100.0%	234	22	90.6%	10	1	90.0%	231	18	92.2%
549		11	0	100.0%	238	27	88.7%	11	0	100.0%	228	20	91.2%
550		11	3	72.7%	197	23	88.3%	11	3	72.7%	197	47	76.1%
551		11	0	100.0%	239	23	90.4%	11	0	100.0%	229	23	90.0%
562		14	0	100.0%	340	27	92.1%	14	8	42.9%	335	45	86.6%
564		14	0	100.0%	341	19	94.4%	13	3	76.9%	332	46	86.1%
566		9	1	88.9%	334	30	91.0%	9	3	66.7%	331	57	82.8%
567		8	1	87.5%	220	12	94.5%	7	0	100.0%	217	14	93.5%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572	56	9	1	88.9%	331	28	91.5%	9	6	33.3%	323	101	68.7%
573		9	1	88.9%	333	45	86.5%	9	2	77.8%	325	60	81.5%
579		14	0	100.0%	226	14	93.8%	14	4	71.4%	219	49	77.6%
580		14	2	85.7%	341	20	94.1%	14	4	71.4%	334	41	87.7%
581		9	2	77.8%	336	60	82.1%	9	6	33.3%	333	81	75.7%
584	40	9	3	66.7%	220	35	84.1%	7	6	14.3%	211	138	34.6%
587	23	9	1	88.9%	328	22	93.3%	9	5	44.4%	319	70	78.1%
588	21	9	1	88.9%	219	24	89.0%	8	2	75.0%	216	45	79.2%
591		14	3	78.6%	338	29	91.4%	13	4	69.2%	330	53	83.9%
593	74	10	4	60.0%	327	57	82.6%	8	3	62.5%	302	44	85.4%
595	24	13	8	38.5%	333	68	79.6%	12	5	58.3%	329	78	76.3%
600		11	0	100.0%	251	9	96.4%	11	3	72.7%	249	25	90.0%
601		11	3	72.7%	234	93	60.3%	11	1	90.9%	231	28	87.9%
605		11	6	45.5%	241	145	39.8%	10	1	90.0%	236	24	89.8%
607		11	1	90.9%	250	31	87.6%	11	1	90.9%	247	26	89.5%
609		11	1	90.9%	241	24	90.0%	11	1	90.9%	240	24	90.0%
622		9	1	88.9%	146	36	75.3%	9	2	77.8%	143	7	95.1%
626		11	1	90.9%	155	21	86.5%	11	1	90.9%	153	19	87.6%
639		11	2	81.8%	221	42	81.0%	11	1	90.9%	219	21	90.4%
640	15	11	1	90.9%	241	8	96.7%	11	3	72.7%	239	87	63.6%
641		11	1	90.9%	223	44	80.3%	11	5	54.5%	223	32	85.7%
642		11	1	90.9%	239	12	95.0%	11	1	90.9%	238	28	88.2%
643		11	1	90.9%	253	45	82.2%	11	2	81.8%	250	41	83.6%
644		11	2	81.8%	245	30	87.8%	11	6	45.5%	243	62	74.5%
645		11	0	100.0%	253	42	83.4%	11	0	100.0%	250	55	78.0%
646	18	11	4	63.6%	242	60	75.2%	11	6	45.5%	240	119	50.4%
647		11	3	72.7%	253	38	85.0%	11	3	72.7%	251	54	78.5%
648		11	2	81.8%	249	61	75.5%	11	1	90.9%	249	36	85.5%
649		11	3	72.7%	254	47	81.5%	11	2	81.8%	250	36	85.6%
650		11	1	90.9%	253	46	81.8%	11	4	63.6%	250	43	82.8%
651		11	1	90.9%	253	18	92.9%	11	2	81.8%	250	45	82.0%
652		11	0	100.0%	254	31	87.8%	11	2	81.8%	250	43	82.8%
653	Cncld	11	2	81.8%	242	38	84.3%	10	3	70.0%	237	44	81.4%
654	12	11	0	100.0%	243	44	81.9%	11	2	81.8%	239	22	90.8%
655	37	11	4	63.6%	251	78	68.9%	11	4	63.6%	248	80	67.7%
656		11	2	81.8%	253	56	77.9%	11	2	81.8%	251	35	86.1%
657		11	0	100.0%	242	29	88.0%	11	1	90.9%	240	31	87.1%
658		11	2	81.8%	253	39	84.6%	10	0	100.0%	250	35	86.0%
680		12	1	91.7%	249	13	94.8%	12	0	100.0%	247	27	89.1%
681		12	0	100.0%	249	18	92.8%	12	3	75.0%	242	96	60.3%
682	21	12	1	91.7%	248	10	96.0%	12	1	91.7%	248	43	82.7%
683		12	1	91.7%	231	19	91.8%	12	2	83.3%	230	77	66.5%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684		12	1	91.7%	230	38	83.5%	12	1	91.7%	230	48	79.1%
685		12	0	100.0%	245	33	86.5%	12	2	83.3%	242	57	76.4%
686		12	0	100.0%	250	39	84.4%	12	3	75.0%	249	55	77.9%
687		12	0	100.0%	249	38	84.7%	12	0	100.0%	248	40	83.9%
688		12	0	100.0%	248	15	94.0%	12	0	100.0%	247	41	83.4%
689		7	0	100.0%	162	21	87.0%	6	0	100.0%	160	23	85.6%
701	34	16	4	75.0%	283	34	88.0%	16	5	68.8%	280	37	86.8%
702	Cncld	16	3	81.3%	350	39	88.9%	14	7	50.0%	345	90	73.9%
703	No OS	16	7	56.3%	351	119	66.1%	16	7	56.3%	349	107	69.3%
704	72	16	6	62.5%	282	55	80.5%	16	9	43.8%	274	68	75.2%
710	249	16	3	81.3%	351	82	76.6%	14	10	28.6%	345	98	71.6%
711		16	4	75.0%	342	42	87.7%	16	5	68.8%	319	70	78.1%
712	136	16	7	56.3%	348	98	71.8%	16	10	37.5%	338	124	63.3%
713	Cncld	15	5	66.7%	217	25	88.5%	10	8	20.0%	187	88	52.9%
714	93	16	10	37.5%	232	102	56.0%	15	12	20.0%	215	107	50.2%
715	332	16	2	87.5%	350	65	81.4%	13	10	23.1%	318	165	48.1%
716	103	16	13	18.8%	351	156	55.6%	15	13	13.3%	341	154	54.8%
717	No OS	15	7	53.3%	335	86	74.3%	14	10	28.6%	309	108	65.0%
718	Cncld	16	14	12.5%	351	192	45.3%	15	10	33.3%	347	139	59.9%
719	No OS	16	9	43.8%	351	122	65.2%	15	8	46.7%	333	106	68.2%
757		14	0	100.0%	134	7	94.8%	14	2	85.7%	133	16	88.0%
761	35	14	2	85.7%	345	15	95.7%	14	4	71.4%	342	48	86.0%
765	52	14	3	78.6%	345	28	91.9%	14	9	35.7%	345	55	84.1%
769	31	14	2	85.7%	345	29	91.6%	14	10	28.6%	338	75	77.8%
770	16	14	3	78.6%	345	28	91.9%	14	9	35.7%	342	113	67.0%
774	55	14	0	100.0%	345	17	95.1%	14	9	35.7%	343	89	74.1%
777	34	14	2	85.7%	230	15	93.5%	14	13	7.1%	229	71	69.0%
782	94	14	10	28.6%	230	115	50.0%	14	6	57.1%	225	42	81.3%
785		14	2	85.7%	345	31	91.0%	14	9	35.7%	345	70	79.7%
786		14	1	92.9%	134	24	82.1%	12	7	41.7%	128	73	43.0%
790		14	2	85.7%	345	33	90.4%	13	6	53.8%	341	60	82.4%
794	52	14	1	92.9%	345	41	88.1%	13	4	69.2%	340	80	76.5%
821	50	15	0	100.0%	344	6	98.3%	15	9	40.0%	344	149	56.7%
822	33	16	1	93.8%	347	19	94.5%	15	13	13.3%	344	183	46.8%
1333		16	3	81.3%	347	43	87.6%	16	5	68.8%	344	117	66.0%
1340	50	16	1	93.8%	346	8	97.7%	16	1	93.8%	345	57	83.5%
2102		11	0	100.0%	100	16	84.0%	11	0	100.0%	99	7	92.9%
2103		11	0	100.0%	164	14	91.5%	11	2	81.8%	163	12	92.6%
2104		11	0	100.0%	190	10	94.7%	10	0	100.0%	187	13	93.0%
2105		11	0	100.0%	12	1	91.7%	11	0	100.0%	12	0	100.0%
2107		10	1	90.0%	220	36	83.6%	10	0	100.0%	217	21	90.3%
2108		11	3	72.7%	221	31	86.0%	10	0	100.0%	214	27	87.4%

Amtrak On Time Performance

Trains Arriving Through: 9/16/2026

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2109		11	2	81.8%	114	15	86.8%	11	0	100.0%	112	6	94.6%
2112	24	11	1	90.9%	61	7	88.5%	11	1	90.9%	59	3	94.9%
2113		11	1	90.9%	100	10	90.0%	11	1	90.9%	100	11	89.0%
2115		11	2	81.8%	100	15	85.0%	10	0	100.0%	98	12	87.8%
2116		11	1	90.9%	61	2	96.7%	11	0	100.0%	61	8	86.9%
2118	Cncld	11	1	90.9%	61	5	91.8%	10	0	100.0%	60	12	80.0%
2119		10	1	90.0%	60	9	85.0%	10	1	90.0%	59	13	78.0%
2120		11	1	90.9%	61	20	67.2%	11	0	100.0%	59	23	61.0%
2123	23	11	4	63.6%	99	14	85.9%	11	2	81.8%	98	17	82.7%
2124		11	0	100.0%	192	38	80.2%	11	0	100.0%	190	24	87.4%
2126		11	1	90.9%	109	27	75.2%	11	0	100.0%	108	22	79.6%
2127	74	11	0	100.0%	61	10	83.6%	11	1	90.9%	60	10	83.3%
2128		11	1	90.9%	61	5	91.8%	11	0	100.0%	61	3	95.1%
2150		11	1	90.9%	214	23	89.3%	11	0	100.0%	211	75	64.5%
2151		11	1	90.9%	163	8	95.1%	11	4	63.6%	161	45	72.0%
2152		11	0	100.0%	119	7	94.1%	11	0	100.0%	118	31	73.7%
2154	78	11	3	72.7%	122	26	78.7%	10	3	70.0%	117	48	59.0%
2155	Cncld	11	0	100.0%	223	17	92.4%	10	1	90.0%	218	103	52.8%
2156		11	0	100.0%	12	0	100.0%	11	2	81.8%	12	2	83.3%
2158		11	0	100.0%	60	6	90.0%	11	2	81.8%	60	18	70.0%
2159		11	1	90.9%	216	17	92.1%	11	4	63.6%	214	73	65.9%
2160		11	1	90.9%	61	3	95.1%	11	2	81.8%	60	30	50.0%
2162		11	0	100.0%	222	23	89.6%	11	0	100.0%	216	91	57.9%
2163	22	11	1	90.9%	174	18	89.7%	11	8	27.3%	168	77	54.2%
2165		11	0	100.0%	58	4	93.1%	11	3	72.7%	58	24	58.6%
2167		11	1	90.9%	209	21	90.0%	11	2	81.8%	209	43	79.4%
2171		11	1	90.9%	150	11	92.7%	11	3	72.7%	146	26	82.2%
2190		11	1	90.9%	219	30	86.3%	11	0	100.0%	217	24	88.9%
2193		10	1	90.0%	213	27	87.3%	10	1	90.0%	211	51	75.8%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2112	NYP	24	ENG	35	ENG	35	WAS-WAS	AM	Other electrical failure, 2036 LH LP, WYE'D DUE TO NON FUNCTIONAL HEADLIGHTS	
2118	NYP	Trn Cancelled								
2123	WAS	23	ENG	29	ENG	29	NYP-NYP	AM	Undesired emergency application, 2036 LH LP, PC2036 DNL FOR HIGHLIGHTS.	
2127	WAS	74	MTI	58	MTI	54	XCY-XHM	AM	Disabled train ahead, Other, XCY-XMW, PSGR TRANSFER AT MP38.5 FROM DISABLED AM653 ON NO.3 TRK	
2154	BOS	78	ENG	64	ENG	40	WAS-WAS	AM	HEP, 2123 NG NP, prior to release pantograph required to be replaced	
2155	WAS	Trn Cancelled	ENG	163	ENG	143	XPV-BAL	AM	Air / Brake, 2149 NG NP, brake issues at MP 93, terminated in Baltimore	
2163	WAS	22	DSR	14	DSR	7	NHV-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2	
93	NFK	20	OTH	21	CTC	13	BAL-BAL	AM	PTC - Stop Bypass Permission Required, Milepost, 95.7, .	
125	NPN	20	CTI	31	CTI	13	ALX-WDB	CS	Follow crew, 307, Milepost, 104.3, 88.9	
171	RNK	32	CTI	24	MTI	16	XPV-BAL	AM	Disabled train ahead, Milepost, 94.3, 95.7, opr 2 trk around 2155 with mechanical issues	
193	WAS	26	MTI	18	MTI	18	EWR-TRE	AM	Disabled train ahead, Other, XCY-XMW, PSGR TRANSFER FROM DISABLED AM653 MP38.5	
197	WAS	63	MTI	40	MTI	40	MET-XHM	AM	Disabled train ahead, Other, XCY-XMW, AM653 DISABLED ON NO.3 TRK MP38.5	
479	NHV	20	SMW	15	SMW	15	SPG-WNL	AM	Scheduled in track usage program, Milepost, SPG, SPG, Single track operation at Sweeney due to ongoing track work. Delayed off of trk 2A onto CSX property, shove move off trk2A to trk10, change ends back on Amtrak property	
52	LOR	59	FTI	77	ITI	43	SFA-SFA	FR	Service, turn, or wye train 53	
640	NYP	15	CTI	19	CTI	12	CWH-TRE	AM	Follow, SE, SE783, Other, CWH-TRE	
646	NYP	18	BSP	9	BSP	6	PAO-PHL	AM	Bridge strike, Milepost, 13.8, 13.8	
653	HAR	Trn Cancelled	CTI	5	CTI	5	NYP-NWK	AM	Follow, NJT, NJ3725, Other, NYP-NWK, FOLLOWED NJ3725	
654	NYP	12	POL	13	POL	13	PHL-PHL	AM	Removal of passenger by police, PSGR BLOCKING OTHERS FROM GETTING OFF THE TRAIN; REMOVED BY APD	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
655	HAR	37	MTI	32	MTI	32	NWK-TRE	AM	Disabled train ahead, Other, XCY-TRE, CONGESTION A/C AM653 DISABLED NO.3 TRK MP38.5	
19	NOL	70	FTI	68	FTI	40	MEI-LAU	NS	Follow NS/355, Milepost w/Letters, NO/33, Hawks	
682	BON	21	DMW	11	SYS	10	HHL-WOB	MT	PTC-caused slow-down or penalty stop	
63	TWO	35	FTI	36	FTI	16	AMS-UCA	CS	Follow I01916, Milepost w/Letters, 190, 205, Milepost, 215, 231	
64	NYP	27	CTI	36	CTI	15	RHI-XCP	AM	Blocked from station track 244 held to wait for Metro 890, we held for 244, Amtrak, 244, Control Point, 75	
233	ALB	277	ENG	273	ENG	273	NYP-XSD	AM	HEP, 711 DX DM, REVERSE MOVE BACK TO NYP A/C NO HEP AND TRACTION POWER ON ENG.711	
243	ALB	38	ITI	41	ITI	41	NYP-NYP	AM	Service, turn, or wye train, 244	
244	NYP	149	SVS	119	SVS	119	ALB-ALB	AM	Amtrak 233 failed in route. Crew had to wait for 235s equipment and have it inspected. Control Point, 142	
283	NFL	33	FTI	32	MTI	31	NYP-NYP	AM	Disabled train ahead, Other, NYP, HELD SINGLE TRACKING A/C AM233 DISABLED AT INWOOD	
291	BTN	24	MTI	40	MTI	40	NYP-NYP	AM	Disabled train ahead, Other, NYP-NYP, HELD A/C SINGLE TRACKING ON THE HUDSON LINE DUE TO AM233 DISABLED	
76	RGH	Trn Cancelled	TCR	17	TCR	17	KAN-GRO	NS	Air / Brake / Wheel 400001	
98	NYP	56	FTI	82	CTI	42	XDJ-ALX	CS	Follow vre, Milepost, 61.0, 105.2	
55	WAS	43	DSR	37	PTI	16	PHL-WIL	AM	Follow, 197, Control Point, HOLLY, BEHIND 197 HOLDING FOR 2127 AND 2171	
40	CHI	204	DCS	85	DCS	81	LAK-XP8	CS	Power switch failure Switch was stuck had to wait for signal maintainer, Control Point, pinciana hold	
41	MIA	345	FTI	152	ITI	136	CHI-CHI	AM	Service, turn, or wye train 40	
25	NOL	36	FTI	72	FTI	56	BAS-XNO	CS	Follow 601, Control Point, 801.5	
5	EMY	406	ENG	332	WTR	123	CRN-OMA	BN	High winds The first 2 were high wind warnings spreads up to 70mph The last one was flash flood critical, Milepost, 393.5, 423.0, Milepost, 430.0, 441.0, Milepost, 422.0, 435.0	

Amtrak Endpoint OTP Details

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
520	SAC	21	TEN	16	TEN	16	OKJ-OKJ	UP	Loading problem C2102	
522	SAC	Trn Cancelled								
529	SJC	24	PTI	31	PTI	21	FMT-GAC	UP	Meet Amtk530north, Control Point, N Albrae	
503	EUG	63	CAR	69	CAR	69	SEA-TUK	BN	Air / Brake / Wheel 48193, Locked bearing return to sea to change equipment	
516	VAC	67	FTI	69	FTI	69	EVR-STW	BN	BNSF Freight train hit a car ahead. Waited at Bridge 37.8. Train hit car at 39.85 80th St. in Marysville Wa. Milepost w/Letters, 39.85, 80th St., BNSF 7927	
517	PDX	74	RTE	44	RTE	39	STW-EVR	BN	Dispatcher hold DS instructed 517 back into south Stanwood siding to meet 516, Siding, south stanwood	
518	VAC	121	DCS	34	DCS	34	STW-MVW	BN	Restrictive signal(s) from unknown cause Approach medium, Approach , Restricting , Restricting , Restricting , Control Point, S STW, Control Point, S MVW	
58	CHI	37	DSR	75	WTR	26	HMD-MCB	CC	Heat order Milepost, 849, 823	
8	CHI	59	FTI	150	FTI	49	MAL-GGW	BN	Meet BNSF 7285W, BNSF 8010W, Siding, Tampico	
28	SPK	65	ITI	91	ITI	91	PDX-PDX	BN	Service, turn, or wye train 27, Late arrival of equipment	
821	FTW	50	DSR	47	DSR	32	GLE-FTW	BN	Per bulletin Milepost, 406.5, 409, 60, m, Milepost, 408.5, 406.7, 60, m, Milepost, 405.9, 405, 60, m, Milepost, 40472, 403.8, 60, m, Milepost, 401.7, 401.3, 60, m, Milepost, 400.4, 400.2, 60, m, Milepost, 399.9, 39972, 60, m, Milepost, 397.8, 397.1, 60, m, Milepost, 396.4, 396.2, 30, m, Milepost, 39	
822	OKC	33	DSR	28	FTI	23	FTW-GLE	BN	Meet BN 8352, Siding, Valleyview	
332	CHI	14	CAR	14	CAR	14	XRO-GLN	ME	Air / Brake / Wheel 34111, Went over Rondout on #2 main, popped an air hose. Laced up, did brake tests and inspection and proceeded at restricted speed to next signal (PTC disengaged)	
365	CHI	32	DCS	19	FTI	10	PTH-LPE	CC	Meet CN 2870, Siding, lmlay	
572	SAN	56	CTI	30	CCR	20	LAX-LAX	SC	Door 6903, Took over equipment from 770 and had damaged doors from debris strike Mechanical switched doors around and had to lock off cart	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
584	SAN	40	PTI	49	ENG	16	LAX-LAX	SC	PTC - On Board Cab Signal or PTC Failure 338
587	LAX	23	CTI	34	CTI	11	OSD-X98	SN	Meet metrolink, Control Point, songs
588	SAN	21	PTI	18	PTI	18	SOL-OLT	SN	Meet 593, 595, Control Point, Sorrento
593	LAX	74	ITI	51	ITI	51	SAN-SAN	SN	Service, turn, or wye train 782, Late arriving equipment from inbound train 782.
595	LAX	24	FTI	23	ITI	14	SAN-SAN	SN	Service, turn, or wye train 782, Waiting on 593 still at OLT engine down
761	GTA	35	CTI	17	PTI	14	CML-OXN	UP	Meet 770, Control Point, CO413
765	SLO	52	PTI	60	PTI	24	X3G-LPS	UP	Meet AMTK 786, Control Point, N SUDDEN
769	GTA	31	PTI	34	PTI	25	VEC-CPN	UP	Meet 782, Control Point, Seacliff
770	SAN	16	DBS	69	DBS	69	GTA-SBA	UP	Debris strike Tree, Milepost, 360.35, 360.4
774	SAN	55	PTI	68	PTI	47	CPN-VEC	UP	Meet amtk, Siding, seaclif
777	SLO	34	PTI	41	PTI	15	X3G-LPS	UP	Meet 794, Control Point, Gaviota
782	SAN	94	PTI	75	PTI	40	GTA-GTA	UP	Meet 765/14, Control Point, S. Ellwood
794	SAN	52	DCS	26	PTI	8	X3G-GTA	UP	Meet A777, Control Point, South Ellwood
701	SAC	34	FTI	28	FTI	23	HNF-FNO	BN	Meet BNSF 7533, Control Point, CP Fresno
702	BFD	Trn Cancelled	FTI	230	FTI	122	COC-COC	BN	Disabled freight blocking route ahead Held at COC account disabled freight that suffered a TM fire blocking route ahead., Other, COC, BNSF 7533, Intermodal
703	SAC	No OS Rpt	ITI	85	ITI	85	BFD-BFD	BN	Service, turn, or wye train 712
704	BFD	72	FTI	54	FTI	23	HNF-COC	BN	Follow BNSF 5339, Control Point, West Corcoran
710	BFD	249	FTI	243	FTI	129	COC-WAC	BN	Freight traction motor fire MP 931 causing massive train congestion Followed AMTK 702 Met CP 9377, BNSF 5837, AMTK 715 Went around BNSF, BNSF 7533, Control Point, E. Corcoran, Control Point, W. Allensworth, Siding, Sandrini
712	BFD	136	RTE	107	RTE	67	HNF-COC	BN	Dispatcher hold Held in siding due to train congestion from earlier freight train issue., Siding, GUERNSEY
713	OKJ	Trn Cancelled							

Amtrak Endpoint OTP Details

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
714	BFD	93	TEN	57	TEN	57	TRK-MCD	BN	Failure of diesel engine Engine shutdown due to high engine coolant issue. Loading issue on CDTX 8311. No alarms ever went off to alert engineer of engine shutdown or high engine coolant issue., C2003
715	OKJ	332	FTI	288	FTI	213	WAC-WAC	BN	Hold wasco due to BNSF train with traction motor fire at allensworth bnsf, Other, wasco station
716	BFD	103	ITI	77	ITI	77	OKJ-OKJ	UP	Service, turn, or wye train 711, Had to repair dynamic brake in cab car 8312, broken window in car 8014, replace 2 relays in to loco for ditch lights and repair the doors in car 8814.
717	OKJ	No OS Rpt	FTI	212	FTI	212	WAC-WAC	BN	Blocked from station track BNSF, Milepost, 913.0, 913.0
718	BFD	Trn Cancelled							
719	OKJ	No OS Rpt	ITI	194	ITI	194	BFD-BFD	BN	Service, turn, or wye train 710
3	LAX	179	FTI	140	ENG	98	CHI-CHI	AM	Set out defective locomotive 118
22	CHI	409	FTI	391	FTI	192	MIN-LVW	UP	Meet UP 5855 wrong end draw bar at MP 103. Had to wait for them pass us and then we shuffled out of R117 and headed to LVW., UP 5855, Control Point, R117
300	CHI	23	FTI	39	FTI	33	SPI-LCN	UP	Meet Control Point, Braidwood, Z-Train, UP 8823
301	STL	41	TRS	51	TRS	51	XTF-XUD	CC	Vehicle strike Semi truck carrying load of lumber had end of lumber load sticking out across the tracks. Locomotive clipped the end of the lumber. Damage to locomotive, fireman side ladder, bent drawbar, and other damages to the front end. Lockport police responded., Milepost, 32.59, 32.59
302	CHI	38	FTI	46	FTI	29	PON-DWT	UP	Meet up2618, Siding, odell
305	STL	23	PTI	35	PTI	30	JOL-DWT	UP	Meet 22, 318, Control Point, X063
380	CHI	56	DMW	47	DMW	47	QCY-MAC	BN	Hold for defect repair Restricting EUBANKS to AUGUSTA, Control Point, Eubanks
391	CDL	26	WTR	31	PTI	11	RTL-CHM	CC	Meet 390, Other, champagne yard
392	CHI	20	WTR	23	WTR	7	CEN-EFG	CC	Heat order High Temp Speed Restriction, Other, CEN to EFG

Amtrak Endpoint OTP Details

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/16/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
393	CDL	27	WTR	29	DSR	9	CHM-MAT	CC	Per bulletin Milepost, 135.2, 136.1, 60, MT, Milepost, 153.6, 153.8, 60, MT, Milepost, 156.0, 163.5, 60, all, Milepost, 171.7, 172.7, 10, M2
316	STL	20	FTI	19	PTI	18	SED-JEF	UP	Meet Amtk 319, Siding, Shell
318	CHI	41	DSR	47	PTI	16	STL-STL	TR	Meet amtrak 319, Control Point, STL
319	KCY	47	DSR	33	RTE	29	XQT-STL	TR	Line manual or spring switch Had to line 11a and 11b crossover., Control Point, gratiot
1340	CHI	50	ENG	69	ENG	69	MSP-MSP	CP	Set out defective locomotive Hand break would not release on 519 had to set it out on spud 3, 519

Amtrak Initial Terminal Details

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/16/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	244	09/16	119	119	Amtrak 233 failed in route. Crew had to wait for 235s equipment and have it inspected. Control Point, 142
HAR	658	09/16	1	1	Passenger and/or baggage
NHV	494	09/16	22	22	Other electrical failure, 9643 CB CC, Mechanical issues
NYP	49	09/16	3	3	Passenger and/or baggage, BOARDING
NYP	243	09/16	41	41	Service, turn, or wye train, 244
NYP	283	09/16	31	31	Disabled train ahead, Other, NYP, HELD SINGLE TRACKING A/C AM233 DISABLED AT INWOOD
NYP	291	09/16	40	40	Disabled train ahead, Other, NYP-NYP, HELD A/C SINGLE TRACKING ON THE HUDSON LINE DUE TO AM233 DISABLED
NYP	639	09/16	2	2	Passenger and/or baggage, BOARDING
NYP	2123	09/16	29	29	Undesired emergency application, 2036 LH LP, PC2036 DNL FOR HIGHLIGHTS.
PHL	190	09/16	1	1	Passenger and/or baggage
SPG	417	09/16	5	5	Cross Traffic, CSX Freight M439, Other, SPG sta trk2A, WAIT FOR CSX M439 TO CLEAR CP98
TWO	64	09/16	1		
WAS	84	09/16	5	5	Dispatcher hold, Control Point, K INTERLOCKING, AWAITING SIGNAL BLUE FLAG CALLED DOWN AT 10:58AM, BUT BLUE FLAG CAME DOWN AT 11:04AM,
WAS	112	09/16	3	3	Other late crew, CREW IDENTIFIED AND RESOLVED DOOR ISSUE
WAS	2112	09/16	35	35	Other electrical failure, 2036 LH LP, WYE'D DUE TO NON FUNCTIONAL HEADLIGHTS
WAS	2118	09/16	(Trn Cxld)		Engine Issue
WAS	2154	09/16	40	40	HEP, 2123 NG NP, prior to release pantograph required to be replaced
CHI	41	09/16	8	8	Water, commissary, toilet/trash dumping Milepost w/Letters, CUS, CUS
CHI	59	09/16	188	94	Set out defective locomotive 31028
CHI	59	09/16	188	94	Set out defective car 33038
MSP	1340	09/16	69	69	Set out defective locomotive Hand break would not release on 519 had to set it out on spud 3, 519
BFD	703	09/16	85	85	Service, turn, or wye train 712
BFD	711	09/16	2	2	Door C8814, Engineer reported no door light. No door light from cafe car. Per Drumac, previous known issue and written up
BFD	713	09/16	(Trn Cxld)		Third Party Car Failure
BFD	717	09/16	(Trn Cxld)		Disabled Freight Train

Amtrak Initial Terminal Details

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/16/2026

Terminal	Train	Date	Late	Delay	Cause
BFD	719	09/16	194	194	Service, turn, or wye train 710
GTA	782	09/16	40	40	Meet 765/14, Control Point, S. Ellwood
LAX	4	09/16	4	2	Mobility Impaired Last minute arrivals- needed extra care
LAX	4	09/16	4	2	Homeless woman went between two cars and stood on knuckle. Police had been following her and she came off knuckle as I was calling engineer to drop HEP. HEP stayed on and we left
LAX	572	09/16	20	20	Door 6903, Took over equipment from 770 and had damaged doors from debris strike Mechanical switched doors around and had to lock off cart
LAX	584	09/16	16	16	PTC - On Board Cab Signal or PTC Failure 338
OKJ	520	09/16	16	16	Loading problem C2102
OKJ	522	09/16	(Trn Cxld)		Third Party Car Failure
OKJ	712	09/16	7	7	SPEEDO ISSUE AT OMF. Blue flag dropped at 1005a. C2004
OKJ	716	09/16	77	77	Service, turn, or wye train 711, Had to repair dynamic brake in cab car 8312, broken window in car 8014, replace 2 relays in to loco for ditch lights and repair the doors in car 8814.
OKJ	718	09/16	15	15	Water, commissary, toilet/trash dumping
SAC	523	09/16	1	1	Door C8009, Door #2 already locked out. On departure door was open ajar
SAC	702	09/16	114	114	Fuel Low fuel level (<500 gals) in locomotive account failure of fuel system at SAC. Await diagnosis of cause and temporary repair so that fuel could be added after failed attempts to source alternate fueling enroute.
SAC	704	09/16	9	9	Door C9805, No door light. Attempted to recycle with no change. Door override engaged.
SAN	593	09/16	51	51	Service, turn, or wye train 782, Late arriving equipment from inbound train 782.
SAN	595	09/16	14	14	Service, turn, or wye train 782, Waiting on 593 still at OLT engine down
SAN	785	09/16	13	13	Service, turn, or wye train 774
SEA	8	09/16	8	8	Routine inspections Waited for Mechanical to come get orange RWP Protection lock from Lead Engine
SEA	505	09/16	1		
SEA	507	09/16	1	1	Cross Traffic SDRX, ?, Control Point, King St

Eastern Region

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.1	94.8	342	1
CDOT	95.0	85.0	89.0	92.4	20	3
MARC	95.0	91.1	91.2	90.2	56	5
SEPTA	95.0	86.3	90.0	91.5	211	29
NJT-NED	95.0	94.9	93.9	88.6	356	18
NJT-SED	95.0	100	98.7	97.2	22	0

Operating Highlights

Train 19(16) South of High Point, NC - Debris

17SEP26: Train 19(26) operating with engines 33, 33, and 128 customers onboard was delayed 19 miles south of High Point, NC on the Norfolk Southern Danville District short looping behind car 25012 after striking debris which caused damage to the 480 cable sheath causing a loss of head end power. The ambient temperature outside was 65 degrees and clear. The first five cars consisting of 25078, 25099, 25012, 28012, and 68021 were impacted by the strike causing air hoses to separate and issues with main res.

Train	Delay	Comment
19(16)	1'11"	

Train 98(16) North of Charleston, SC - Injured or Sick Passenger or Employee

16SEP26: Train 98(16) operating with engines 369, 125, and 189 customers onboard was delayed 4 miles north of Charleston, SC on the CSX Charleston subdivision meeting local EMS at milepost 383.7 near Stokes Avenue to remove a customer having a medical emergency onboard and take them to the local hospital.

Train	Delay	Comment
98(16)	30"	

Train 76(16) East of Greensboro, NC - Car Failure

16SEP26: Train 76(16) operating with engines NC1755, NC103, and 88 customers onboard was delayed 8 miles east of Greensboro, NC on the Norfolk Southern H Line stopped at milepost 8.5 with main res issue on car 400001, the first car behind engine RNCX1755. Upon inspection the crew found damage to the main res tank and had to cut out the brakes causing the train to operate at freight speed into Raleigh. Train 78(16) took all of 76(!6) customers at Burlington, NC causing train 76(16) to terminate and deadhead the rest of the way to Raleigh.

Train	Delay	Comment
78(16)	19"	
76(16)		TERM BNC

Train 653(16) West of Newark, NJ - Catenary or Wayside Failure

16SEP26: At 5:55 p.m. ~~FOI-00757~~ 653(16) operated with engine 613, cab car 9647, and 345 customers onboard was affected by an inverted pan at milepost 38.5 between Midway and Adams interlocking. The crew reconfigured the pans to provide head end power. The ambient temperature was 78 degrees and partly cloudy. Customers transferred to trains 193, 197, 2127(16) on track 2. ET travelled from Morrisville Yard to inspect the scene and Amtrak Management was on scene well assisting customers with the transfers. Once all transfers were complete, train 653(16) terminated XMW. All customers destined Philadelphia to Harrisburg were accommodated on 655(16). Train 653(16) equipment deadheaded to Harrisburg with a locomotive change performed in Philadelphia prior to departure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
653(16)		TERM XMW
655(16)	32"	PHL-HAR customers
197(16)	40"	Hold Delco
193(16)	18"	Customers transferred
2127(16)	54"	Customers transferred

Train 89(16) Richmond, VA - Engine Failure

16SEP26: Train 89(16) with E/366, seven cars, and 135 customers was delayed on the CSX Richmond Terminal subdivision at Richmond station/MP 4.6 due to E/366 with air brake issues and necessary to cut out ACSES. The crew worked with the Amtrak road foreman and once the issues were resolved train 89(16) departed Richmond at 400PM-ET, 59 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
89(16)	50"	

Train 2155(16) North of Baltimore, MD - Engine Failure

16SEP26: Train 2155(16) with NG 25, PC/2149-2152, and 242 customers was delayed two miles north of Baltimore on the Amtrak Philadelphia to Washington line at MP 93.0 due to PC/2149 with brake issues. The crew de-prepared and re-prepared in an attempt to clear the alarm and continue. The alarm cleared on PC/2149 and appeared on C/3274, C/3924, and C/3720 with air issues. The crew was able to limp into Baltimore station where train 2155(16) was terminated with all customers accommodated on MARC 679 to Washington. Due to equipment issues, trains 2118(16) and 2131(16) were canceled entirely with customers fare protected for the next available services.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2155(16)		TERM BAL
2118(16)		CANCELLED
2131(16)		CANCELLED

Train 41(14) Orlando, FL - Engine Failure

16SEP26: Train 41(14) with E/346-39, ten cars, and 88 customers was delayed on the CFRC Orlando subdivision at Orlando station/MP 791.3 due to E/346 with a false fire alarm and TCU issue. The crew worked with CNOC mechanical to isolate the lead locomotive, source head end power and tractive effort from trail E/39, and continued operating south using E/346 as a control stand. Train 41(14) departed Orlando at 236PM-ET, 4 hours, and 17 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(14)	46"	

CSX Heat Orders - Weather

16SEP26: Trains were delayed due to weather conditions implemented between 100PM-ET and 700PM-ET on the following CSX subdivisions: Kanawha, Keystone, and Nahunta.

Train	Delay	Comment
98 (16)	32"	

Train 2112(16) Washington, DC - Engine Failure

16SEP26: Train 2112(16) with Legacy set 11, PC/2017-2036, and 151 customers was delayed departing Washington due to PC/2036 do not lead for bad ordered highlighs. As a result, the equipment operated around the wye, customers were welcomed aboard, and 2112(16) departed Washington at 1225PM-ET, 35 minutes late. Train 2123(16) was delayed departing New York due to looping the equipment for the same reason. Train 2123(16) departed New York at 441PM-ET, 28 minutes late.

Train	Delay	Comment
2112 (16)	35"	
2123 (16)	28"	

Train 2165(16) West of Route 128, MA - System

16SEP26: Train 2165(16) with NG 12, PC/2133-2124, was delayed on the Amtrak New Haven to Boston line and Metro North New Haven line due to operating without ACSES. The crew was restricted to 79mph on Amtrak territory and 59mph on Metro North territory. High speed rail met the train at New York to troubleshoot. Train 2165(16) departed New York at 345PM-ET, 29 minutes late with ACSES issues resolved.

Train	Delay	Comment
2165 (16)	40"	

Train 233(16) North of New York, NY - Engine Failure

16SEP26: Train 233(16) with CC/9704, five cars, E/711, and 166 customers was delayed on the Amtrak Hudson line 10 miles north of New York at MP 9.6 due to E/711 with inverter faults and inoperable face modules one and five, which created a loss of head end power with no tractive effort. The crew worked with Albany mechanical and were unable to rectify the issue. The weather was 72 degrees and sunny. The train was without head end power for three hours and three minutes. New York utilized rescue E/700 and pulled the train back to Penn Station where customers alighted to a fresh set of equipment for service to Albany. The customers were welcomed a board the fresh set of equipment through a cross platform and departed New York for a second time at 350PM-ET, 4 hours, and 30 minutes late. Extended delays at New York were attributed to rescue E/700 with communication issues, paperwork issues on the fresh set of equipment E/116, and receiving a relief crew prior to departing New York for a second time.

Train	Delay	Comment
283 (16)	31"	NYP
291 (16)	40"	NYP
233 (16)	4'30"	
49 (16)	03"	NYP
244 (16)	1'59"	ALB - late turn of equip 235(16)
243 (16)	41"	

Train 2154(16) Washington, DC - Initial Terminal Delay

16SEP26: Train 2154(16) with 180 customers was delayed departing Washington due to a late release from S&I. The late release was attributed to work on PC/2121 that had a broken pantograph the day prior. Once the train was released and set in the station, the customers were welcomed aboard, and 2154(16) departed Washington at 910AM-ET, 40 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2154(16)	40"	

Amtrak NYP Line West of Metropark, NJ - Catenary or Wayside Failure

16SEP26: There was an overhead power loss reported on the Amtrak New York to Philadelphia line starting 18 miles west of Metro Park between Midway/MP 41.3 and Morris/MP 58.3 on NO.4 track. Trains 113(16) and NJ3815 were stopped in the area without power. SE9712 was on NO.5 track at Trenton with power. Train 51(16) was stopped east of Fair/MP 56.4 on NO.3 track with power. SE9712 reported no power on NO.5 track at Trenton/MP 56.7. Overhead power was restored and train movement continued. NJ3817, NJ3926, and 2105(16) inspected the catenary and reported no exceptions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
SE783	06"	
SE9712	27"	
SE9716	03"	
SE9714	15"	
NJ3815	20"	
51(16)	22"	
2105(16)	06"	
640(16)	12"	
113(16)	23"	

Train 98(15) South of Alexandria, VA - Commuter Train Interference

16SEP26: Train 98(15) with 200 customers was delayed on the CSX RF&P subdivision starting 44 miles south of Alexandria between Dahlgren Jct./MP 61.0 and Alexandria/MP 105.2 due to following VRE.

Train 40(15) North of Columbia, SC - Trespasser Incident

16SEP26: Train 40(15) with E/305-140, ten cars, and 119 customers was delayed on the CSX Hamlet subdivision ten miles north of Columbia in Dentsville, SC located in Richland County due to fatally striking a female trespasser at MP 350.3, who was crossing the tracks ahead of the train. The incident did not occur at a crossing. There were no injuries reported to the customers or crew and no damages reported to the equipment. The train maintained head end power throughout the disruption. Richland County Sheriff and local EMS responded to the scene for an investigation. The body was reported to be behind and clear of the equipment. The crew did not request relief. Customer service recovery was initiated with complimentary coffee and tea with snacks packs and bottled water. The local authorities released the train for movement and the crew continued to Camden.

National Response Center Number: 1473700

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(15)	1'20"	

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an

WBS#: B.TR.100150.7085

Train	Delay	Comment			
77(03)	50"	26-FOI-00757 00000008820	"UNCLASSIFIED"	9/29/2026	
78(03)	50"	Turn of Late 77(03)			

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
43(16)	HAR	1	LEW	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 98(16) Passenger Removal at Charleston, South Carolina – Medical***

16SEP26, Passenger on PNR D8A269, traveling from Miami, FL to Kingstree, SC was removed from the train by EMS after being unconscious and experiencing labored breathing. Passenger may have been experiencing a diabetic episode. Amtrak Police notified.

Delay: 98 (16) 31"

Western Region

Operating Highlights

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Train 7/27(15) West of Havre, MT - Freight Train Interference

17SEP26: Train 7/27(15) was delayed at Havre Center/MP429.3 on the BNSF Milk River Subdivision, 1 mile west of Havre, MT, due to meeting Train BN6283.

Train	Delay	Comment
7/27(15)	40"	

Train 8/28(15) West of Glasgow, MT - Freight Train Interference

17SEP26: Train 8/28(15) was delayed at Hinsdale / MP 304.9, on the Burlington Northern Santa Fe Milk River Subdivision, 27 miles west of the Glasgow, MT station, due to meeting BN6752

Train	Delay	Comment
8/28(15)	46"	

Train 782(16) West of Chatsworth, CA - Commuter Train Interference

17SEP26: Train 782(16) was delayed at Topanga/ MP444.4 on the SCRRA-Metrolink Ventura Subdivision, 1 mile west of Chatsworth, CA station, due to meeting Metrolink Train 120 and 121. The turn of equipment, Train 593(16) was also delayed departing initial terminal San Diego.

Train	Delay	Comment
782(16)	34"	
593(16)	51"	

Train 22(16) North of Arkadelphia, AR - Freight Train Interference

17SEP26: Train 22(16), with 83 customers onboard, was delayed at Abco/MP393.1 on the UP Little Rock subdivision meeting UP freight UP/8019 that was setting out multiple engines. Once the route was clear, train 22(16) continued north.

Train	Delay	Comment
22(16)	43"	

Train 4(16) East of Barstow, CA - Freight Train Interference

16SEP26: Train 4(16), with 135 customers onboard, was delayed between mile post 712.8 and mile post 605.1, beginning 34 miles east of Barstow, CA/MP0.4, on the BNSF Needles subdivision follow BNSF freight. Once the route was clear, train 4(16) continued east.

Train	Delay	Comment
4(16)	1'23"	

Train 794(16) South of Lompoc-Surf, CA - Rocket Launch

16SEP26: Train 794(16) 26-FOI-00757 in 00000008820 UNCLASSIFIED at Tangair siding/MP293.6 5.5 miles south of Lompoc, CA/MP299.2 on the UP Santa Barbara subdivision, due to a Vandenberg Space Force Base rocket launch requiring a temporary rail safety exclusion zone. All rail traffic was held until the launch activity was completed. Once the launch concluded and the exclusion zone was lifted, the track was released for movement, and Train 794(02) resumed its southbound trip. 777(16) was also delayed due to this, meeting 794(16) at Gaviota/MP336.3.

Train	Delay	Comment
794(16)	57"	
777(16)	27"	Meeting 794(16)

Train 716(16) Oakland, CA - Third Party Contractor Car Failure

16SEP26: Train 716(16) CC/C8312, 5 cars, E/C2012, was delayed departing Oakland, CA due to a late release from the yard, account of TASI needing to repair the dynamic brakes in cab car 8312, broken window in car 8014, replace 2 relays in the locomotive for ditch lights and also repair the doors in car 8814. Once repairs were made, the train was released and proceeded to Oakland station to load passengers.

Train	Delay	Comment
716(16)	1'17"	

Train 6(15) East of Fort Morgan, CO - Temporary Speed Restrictions

16SEP26: Train 6(15), with 201 customers onboard, was delayed between mile post 432.4 and mile post 314.4, beginning 32 miles east of Fort Morgan, CO/MP464.2 on the BNSF Akron subdivision following temporary speed restrictions. Once clear of the affected area, train 6(15) continued east.

Train	Delay	Comment
6(15)	32"	

Train 5(16) West of Ottumwa, IA - Freight Train Interference

16SEP26: Train 5(16), with 165 customers onboard, was delayed between Maxon/MP300.8 and control point 3569/MP356.0, beginning 20 miles west of Ottumwa, IA/MP279.8, on the BNSF Ottumwa subdivision following BNSF freight BN/7626. Once the route was clear, train 5(16) continued west.

Train	Delay	Comment
5(16)	41"	

Train 25(16) North of New Orleans, LA - Freight Train Interference

16SEP26: Train 25(16), 95 customers onboard, was delayed at mile post 801.5, 10 miles north of New Orleans, LA/MP0.0 on the CSX N.O.&M. subdivision meeting CSX freight 601. Once the route was clear, train 25(16) continued south.

Train	Delay	Comment
25(16)	56"	

Train 305(16) North of Dwight, IL - Passenger Train Interference

16SEP26: Train 305(16), with engine 136, 7 cars, and 151 customers to board, was delayed at Mazonia/MP62.6, 11 miles north of Dwight, IL/MP73.8, on the UP Joliet subdivision meeting multiple Amtrak trains. Once Amtrak trains 22(15) and 318(16) were clear of the route, train 305(16) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
305(16)	30"	

Train 59(16) Chicago, IL - Late Train Make Up

16SEP26: 59(16), with engine 136, 7 cars, and 151 customers to board, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to equipment changes by Chicago Mechanical. The original engine 152 was held off and replaced with engine 136. Car 34208 was shopped for HVAC issues and replaced with 34079. Diner/Lounge car 37014 was held off fill a shopped car on train 21(16) and replaced with car 37007. Once the equipment was made up complete and released, train 59(16) shoved into the depot, boarded customers, and departed Chicago Union Station.

Train 59(16) was further delayed between Lumber St/MP1.4 and 21st St/MP2.7, beginning 1.4 miles south of Chicago Union Station meeting Amtrak trains 41 and 391. Once the route was clear, train 59(16) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(16)	3'08"	
59(16)	30"	PTI

Train 3(16) West of Fort Madison, IA - Freight Train Interference

16SEP26: Train 3(16), with 225 customers onboard, was delayed at West Fort Madison/MP236.2 3.3 miles west of Fort Madison, IA/MP232.9, on the BNSF Marceline subdivision meeting BNSF freight BN/5837. Once the route was clear, train 3(16) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(16)	1'00"	

Train 19(15) North of Laurel, MS - Freight Train Interference

16SEP26: Train 19(15), with 62 customers onboard, was delayed between mile post 33.0 and Hawks/MP50.8, beginning 23 miles north of Laurel, MS, on the NS N.O&N.E. subdivision following NS freight NS/355. Once the route was clear, train 19(15) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
19(15)	40"	

Train 22(16) Dallas, TX - Freight Train Interference

16SEP26: Train 22(16), with 88 customers onboard, was delayed departing Dallas, TX/MP214.4 on the UP Dallas subdivision due to UP freight UP/9083 striking an occupied vehicle at mile post 212.8. An UP track inspector and mechanical personnel arrived on the scene to assist. Once the RMCC cleared the scene, train 22(16) pulled up to await the opening of the tracks by the track inspector. Once the tracks were opened, train 22(16) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(16)	53"	Holding at DAL
22(16)	50"	DMW Holding for open track

Train 22(16) Fort Worth, TX - Servicing

16SEP26: Train 22(16) 26-FOI-00757-E/62-00000006820 car "UNCLASSIFIED" delayed at Fort Worth, TX/MP346.2, on the BNSF Fort Worth Subdivision, waiting on fuel vendor to complete fueling Train 21/421(15) ahead.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(16)	59"	

Train 11(16) North of Tacoma, WA - Freight Train Interference

16SEP26: Train 11(16), carrying 143 customers, was delayed 8 miles north of Tacoma, WA, on the BNSF Seattle Subdivision after BNSF 8461 went into undesired emergency on Main Track 1. An MOW work window on Main Track 2 prevented the train from being routed around the disabled equipment. Once a route was available, Train 11(16) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(16)	55"	

Train 58(16) North of New Orleans, LA - Switch Failure

16SEP26: Train 58(16) was delayed at East Bridge Jct/MP906.9, 7 miles north of New Orleans, LA, on the CN McComb Subdivision, due to power switch failure. Train 58(16) was delayed holding for C&S to arrive on scene and okay switch for movement.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(16)	33"	

Train 715(16) Wasco, CA - Freight Train Interference

16SEP26: Train 715(16) was delayed at Wasco, CA, on the BNSF Bakersfield Subdivision after BNSF 7533 experienced a traction motor fire at MP 931, approximately 16 miles west of Wasco. BNSF Mechanical arrived and applied a Level 1 kit, allowing the locomotive to be moved for setout. Train 715(16) was held at Wasco because there was no available route around the incident. Train 702(16) was held at Corcoran, and 710(16) at Hanford. Due to the prolonged delay, 2 busses were secured to allow for a bus bridge between Wasco and Bakersfield, with 702(16) terminating, and 717(16) originating at Wasco. Once the freight was able to set out the engine and clear the route, all trains were able to proceed with train congestion delays in the area. This caused multiple Amtrak trains and their equipment turns to be delayed, including Train 14(16) that was held at Sacramento for connecting bus passengers from late 719(16).

WBS#: B.TR.100150.7185

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
717(16)	3'44"	Originated WAC
702(16)	3'50"	Terminated WAC
710(16)	3'57"	
719(16)	3'14"	ITD- Turn off 710
715(16)	4'54"	
712(16)	1'47"	
718(16)	45"	Meeting 717
703(16)	1'25"	ITD- Turn off 712
714(16)	10"	
14(16)	55"	SAC- Bus connections 3817

Train 774(16) Ventura, CA - Passenger Train Interference

16SEP26: Train 774(16) was delayed 47 seconds north of Ventura, CA on the UPRR Santa Barbara subdivision due to meeting passenger train at Seacliff siding at MP 386.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
774(16)	47"	

Train 522(16) Oakland, CA - Canceled

16SEP26: Trains 522/537(16) were canceled due to mechanical contractor not maintaining equipment to required cleanliness standards.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
537(16)	Canceled	
522(16)	Canceled	

Train 516(16) North of Everett, WA - Freight Train Vehicle Strike

16SEP26: Train 516(16), with 160 customers onboard, was delayed north of Everett, WA, on the BNSF Bellingham Subdivision due to a freight train striking a vehicle at a crossing approximately 14 miles north of Everett at MP 39.852. The trespasser was able to drive the vehicle away from the scene. The freight train subsequently moved into the clear at English Siding, opening the route for Train 516(16) to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
516(16)	1'09"	
517(16)	30"	hold at STW
517(16)	39"	Meet 516(16)

Train 1340(16) Late Departure St. Paul-Minneapolis, MN - Engine Failure

16SEP26: Train 1340(16), E/44-4 cars-E/519, with 97 customers, was delayed departing St. Paul-Minneapolis, MN, due to parking brake issues on trail engine, E/519. Mechanical was on site and determined it was necessary to setout E/519. E/519 was set out on SPUD 3 track and Train 1340(16) operated with single engine, E/44 and 4 cars to Chicago.

Due to the late operation of Train 1340(16) and the anticipated late departure from Chicago of the equipment turn, Train 341(16), the following Hiawatha service adjustment was in effect:

Train 341(16) was cancelled with on time alternate transportation. Two busses were secured, with one operating express Chicago, IL to Milwaukee, WI and one making all scheduled stops. A replacement engine was added to consist in Chicago and Train 341(16)'s equipment deadheaded to Milwaukee to be in position for AM service on 17SEP.

WBS#: B.TR.100150.7184

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
341(16)	Cancelled	
1340(16)	1'09"	

Train 702(16) Sacramento, CA - Servicing

16SEP26: Train 702(16) with 63 passengers was delayed departing Sacramento, CA, due to the locomotive having less than 500 gallons of fuel. It was reported that the fuel pump in Sacramento was inoperable. Alternate vendors were contacted for fuel delivery; however, fuel could not be sourced downline. A technician eventually arrived in Sacramento and completed temporary repairs to the fuel pump. Train 702(16) was subsequently fueled and released.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
702(16)	1'54"	

Train 503(16) Seattle, WA - Car Failure

16SEP26: Train 50(16), with 64 customers onboard, was delayed on the BNSF Seattle Subdivision after departing Seattle on time and subsequently experiencing a wheel bearing issue. The train shoved back to Seattle, where customers were cross-platformed to 511(16) equipment. This allowed 503(16) customers to continue their travel while providing Mechanical additional time to troubleshoot the wheel bearing issue.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
503(16)	1'09"	

Train 714(16) East of Turlock-Denair, CA - Third Party Contractor Cab Car Failure

16SEP26: Train 714(16) CC/C8311, 7 cars, E/C2003, with 54 passengers onboard, was delayed at Ballico/ MP1070.8 on the BNSF Stockton Subdivision, 8.7 miles east of Turlock-Denair, CA station due to the engine E/C2003 shutting down account of a high engine coolant issue. HEP remained active during this event. The crew worked to troubleshoot, recycled the engine and was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(16)	57"	

Train 770(16) Goleta, CA - Trespasser Incident

16SEP26: Train 770(16), with 14 customers onboard, struck a tree at MP 340 north of Goleta, CA, on the Santa Barbara Subdivision. No injuries were reported, HEP remained active, and the train remained upright and on the rails. The tree was lodged beneath the cab car. Following debris removal, customers were moved from Car 6, which was locked out of service due to a broken window. The train was released to resume normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
770(16)	1'09"	

Train 301(16) North of Joliet, IL - Trespasser Incident

16SEP26: 7:58AM-CT, Train 301(16) with 84 customers, struck lumber hanging off the rear of a lumber truck at Lockport/MP32.63, 5 miles north of Joliet, IL, in Will County, on the CN Joliet Subdivision. There were no reported injuries to passengers or crew. The lumber truck initially left the scene and then stopped in the vicinity. Train 301(16) maintained HEP. EIDTX4626 was reported with some damage to the hand rails, nose cone and drawbar. There were no other exceptions to the equipment reported. The crew did not request relief. Train 301(16) was delayed holding for completion of the investigation by local authorities.

WBS B.TR.100150.7181

National Response Center: 1473715

WBS#: B.TR.100150.7181

National Response Center Number: 1473715

Train	Delay	Comment
301(16)	51"	

Train 5(15) West of Hastings, NE - Freight Train Interference

16SEP26: Train 5(15) was delayed at Axtell/MP196.6, 40 miles west of Hastings, NE, on the BNSF Hastings Subdivision, meeting BNSF 5347.

Train	Delay	Comment
5(15)	49"	

Train 380(16) East of Quincy, IL - Track Indication

16SEP26: Train 380(16) was delayed at E. Ewbanks/MP253.9, 5 miles east of Quincy, IL, on the BNSF Brookfield Subdivision, due to a track indication. Train 380(16) was delayed flagging between E. Ewbanks/MP253.9 and Camp Point/MP242.5. Train 380(16) was further delayed flagging through a track indication at East Augusta/MP224.4.

Train	Delay	Comment
380(16)	47"	

Train 300(16) North of Springfield, IL - Freight Train Interference

16SEP26: Train 300(16), with 72 customers, was delayed at MP162.0, 23 miles north of Springfield, IL, on the UPRR Springfield Subdivision, meeting UP8823 which was delayed southbound flagging through signal issues ahead.

Train	Delay	Comment
300(16)	33"	

City of New Orleans Service Adjustments - Engine Availability

14SEP26: Due to engine availability, the following City of New Orleans service adjustments are in effect:

- On Tuesday, September 15th, Train 59(15) is cancelled entirely. No alternate transportation between Chicago, IL and New Orleans, LA.
- On Thursday, September 17th, Train 58(17) is cancelled entirely. No alternate transportation between New Orleans, LA and Chicago, IL.

Train	Delay	Comment
-------	-------	---------

CN Heat Orders - Weather

CN reports as of 11:58 PM the heat restriction cross the Yazoo and McComb subdivisions between 11:00am CT and 10:00pm CT daily until further notice.

Trains 58 and 59 affected.

Train	Delay	Comment
58 (12)	24"	NOL-MEM
58 (13)	1'12"	HMD-MEM
59 (12)	02"	
58 (14)	1'06"	HMD-MCB
59 (14)	33"	MCB-HMD
58 (15)	41"	

Maintenance of Way Highlights

Conrail Track Work North of Detroit, MI TWA 26-100 - Wolverine Service Adjustment

16SEP26: Conrail will perform switch work at CP-Beaubien/MP5.9, 1 mile north of Detroit, MI, on the Conrail North Yard Branch, on Wednesday September 16th between 800AM-ET and 800PM-ET. To accommodate this infrastructure work, Wolverine service adjusted as follows:

- Train 355(16) cancelled entirely, with Bus 3355 as alternate transportation between Pontiac, MI and Chicago, IL. Equipment will deadhead Pontiac to Chicago once the curfew has concluded.

WBS#: B.TR.100150.7174

Train	Delay	Comment
355(16)	Cancelled	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-06Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-07Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00757 0000008820 UNCLASSIFIED 9/29/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (17)	EMY	BNSF8785	Blown Rad fan E/196		
5 (14)	DEN	UPRR6751	E/196 blown Rad fan		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 702(16) Passenger Denied Travel at Fresno, California – Other

16SEP26, Passenger on PNR 0B9F0C, traveling from Fresno, CA to Anaheim, CA was reportedly denied travel due to her power wheelchair having shred up tires unable to gain traction on lift. It was deemed unsafe for travel. Amtrak Police notified.

Delay: 702 (16) 08"

Consist Deviations

26-FOI-00757

00000008820

"UNCLASSIFIED"

9/29/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
244 (16)	ALB	Operating with Cafe in lieu of Club-Dinette. Please downgrade business class passengers to coach.	yes	15	
2193 (16)	BOS	LEGACY REPLACED WITH NG	email sent for review of war reports and passenger notification.	0	3277
562 (17)	LAX	90225 C8021 C6463 6302 6802 34953 C2109	Passengers notified.	1	90225
580 (17)	LAX	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90225 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	Passengers notified.	1	90225
566 (17)	LAX	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	No impact	0	90215
131 (16)	NYP	SHORT 1 COACH WITH NO SPACE ISSUES	none	0	NOCAR
243 (16)	NYP	Operating with Cafe in lieu of Club-Dinette. Please downgrade business class passengers to coach.	YES	13	
573 (17)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90225 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	Passengers notified.	1	90225
591 (17)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90225 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	Passengers notified.	1	90225
579 (17)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	No impact	0	90215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
584 (17)	SAN	26-FOI-00757 00000008820 TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	Passengers notified.	2	90215
595 (17)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO HAVING CAR 90215 AS PART OF THE CONSIST. PLEASE NOTIFY ALL EFFECTED PASSENGERS.	No impact	0	90215
2154 (16)	WAS	LEGACY REPLACED WITH NG	email sent for review of war reports and passenger notification.	0	3277
112 (16)	WAS	SHORT 1 COACH WITH NO SPACE ISSUES	none	0	NOCAR
192 (16)	WAS	SHORT 1 COACH WITH NO SPACE ISSUES	none	0	NOCAR

Reverse Consists

Train Number	Station	Reason
171 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
95 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
125 (16)	SPG	Consist reversed Business class seat orientation may have changed At Front
94 (16)	NFK	Consist reversed Business class seat orientation may have changed At Front
86 (16)	NPN	Consist reversed Business class seat orientation may have changed At Front
190 (16)	PHL	Consist reversed Business class seat orientation may have changed At Front
2118 (16)	WAS	Acela consist reversed First class at Front
174 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front