CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, October 18, 2026 Rules: 2-2



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

27-FOI-00058 [illegible] 10/27/2026

Scheduled Departure Date: **10/17/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/17/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	293	51	82.6%	5,184	727	86.0%	5,184	727	86.0%
Central Division	86.0%	59	3	94.9%	973	68	93.0%	973	68	93.0%
East Division	82.0%	150	33	78.0%	2,764	404	85.4%	2,764	404	85.4%
West Division	86.0%	84	15	82.1%	1,447	255	82.4%	1,447	255	82.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/17/26

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**89,346**	**24,414**	**73%**	**1,803,516**	**527,767**	**71%**	**1,803,516**	**527,767**	**71%**
Northeast Corridor	***81%***	***34,979***	***5,200***	***85%***	***790,002***	***201,992***	***74%***	***790,002***	***201,992***	***74%***
Acela	83%	3,274	502	85%	152,050	32,396	79%	152,050	32,396	79%
Northeast Regional	79%	31,705	4,698	85%	637,952	169,596	73%	637,952	169,596	73%
Richmond / Newport News / Norfolk	77%	8,463	971	89%	166,461	48,269	71%	166,461	48,269	71%
Springfield Shuttles	89%	450	0	100%	13,638	3,365	75%	13,638	3,365	75%
Roanoke	79%	1,902	1,089	43%	58,817	16,708	72%	58,817	16,708	72%
On Spine Northeast Regional	80%	20,890	2,638	87%	399,036	101,254	75%	399,036	101,254	75%
State Supported	***80%***	***41,086***	***12,815***	***69%***	***799,361***	***221,449***	***72%***	***799,361***	***221,449***	***72%***
Borealis	80%	682	262	62%	12,403	2,564	79%	12,403	2,564	79%
Capitol Corridor	90%	2,828	54	98%	71,775	13,163	82%	71,775	13,163	82%
Carolinian	70%	975	423	57%	23,185	7,164	69%	23,185	7,164	69%
Cascades	75%	3,063	568	81%	47,286	13,790	71%	47,286	13,790	71%
Downeaster	82%	1,839	7	100%	33,494	9,109	73%	33,494	9,109	73%
Empire	78%	5,888	1,353	77%	113,955	25,642	77%	113,955	25,642	77%
Adirondack	72%	410	28	93%	7,782	1,198	85%	7,782	1,198	85%
Ethan Allen Express	70%	546	295	46%	10,742	4,305	60%	10,742	4,305	60%
Maple Leaf	70%	774	380	51%	15,170	4,110	73%	15,170	4,110	73%
New York - Albany	85%	2,829	290	90%	55,080	9,221	83%	55,080	9,221	83%
New York - Niagara Falls	75%	1,329	360	73%	25,181	6,808	73%	25,181	6,808	73%
Gold Runner	73%	1,603	1,193	26%	45,384	17,494	61%	45,384	17,494	61%
Heartland Flyer	70%	247	125	49%	3,896	3,356	14%	3,896	3,356	14%
Hiawatha	90%	1,979	0	100%	32,069	2,995	91%	32,069	2,995	91%
Illinois	78%	2,485	505	80%	47,231	15,542	67%	47,231	15,542	67%
Carl Sandburg / Illinois Zephyr	85%	413	265	36%	7,566	2,032	73%	7,566	2,032	73%
Illini / Saluki	85%	758	232	69%	15,563	6,451	59%	15,563	6,451	59%
Lincoln Service	70%	1,314	8	99%	24,102	7,059	71%	24,102	7,059	71%
Keystone	92%	4,629	678	85%	129,192	13,815	89%	129,192	13,815	89%
Lincoln / Missouri	70%	427	56	87%	14,485	7,289	50%	14,485	7,289	50%
Mardi Gras Service	80%	364	100	73%	4,614	1,692	63%	4,614	1,692	63%
Michigan	70%	2,488	239	90%	39,073	8,676	78%	39,073	8,676	78%
Blue Water	70%	326	0	100%	8,934	2,251	75%	8,934	2,251	75%
Pere Marquette	85%	372	0	100%	5,287	271	95%	5,287	271	95%
Wolverine	70%	1,790	239	87%	24,852	6,154	75%	24,852	6,154	75%
Missouri	80%	424	37	91%	5,092	1,009	80%	5,092	1,009	80%
Pacific Surfliner	85%	7,180	6,168	14%	113,628	59,799	47%	113,628	59,799	47%
Pennsylvanian	80%	978	233	76%	16,447	5,327	68%	16,447	5,327	68%
Piedmont	80%	1,580	797	50%	19,824	4,755	76%	19,824	4,755	76%
Vermonter	75%	1,427	17	99%	26,328	8,268	69%	26,328	8,268	69%
Long Distance	***70%***	***13,281***	***6,399***	***52%***	***214,153***	***104,326***	***51%***	***214,153***	***104,326***	***51%***
Auto Train	70%	761	0	100%	11,482	7,874	31%	11,482	7,874	31%
California Zephyr	70%	1,052	403	62%	16,100	5,490	66%	16,100	5,490	66%
Cardinal	70%	489	169	65%	5,098	2,461	52%	5,098	2,461	52%
City Of New Orleans	75%	735	620	16%	12,918	9,341	28%	12,918	9,341	28%
Coast Starlight	70%	1,110	691	38%	19,565	9,341	52%	19,565	9,341	52%
Crescent	70%	883	70	92%	15,886	2,564	84%	15,886	2,564	84%
Empire Builder	70%	1,176	698	41%	17,652	7,958	55%	17,652	7,958	55%
Floridian	60%	2,443	1,515	38%	28,351	18,576	34%	28,351	18,576	34%
Lake Shore Ltd	73%	1,000	182	82%	18,915	5,274	72%	18,915	5,274	72%
Palmetto	70%	535	0	100%	14,421	3,334	77%	14,421	3,334	77%
Silver Meteor	70%	1,226	226	82%	16,782	6,110	64%	16,782	6,110	64%
Southwest Chief	60%	975	975	0%	15,855	12,818	19%	15,855	12,818	19%
Sunset Ltd	70%	374	374	0%	4,956	2,363	52%	4,956	2,363	52%
Texas Eagle	70%	522	476	9%	16,172	10,822	33%	16,172	10,822	33%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FGI 00056 00000000007 "UNCLASSIFIED" 10/18/2026~~

Train Index Dates Through October 17, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	107,654	1,765,058	610	107,654	1,765,058	610

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	5,612	512,759	109	5,612	512,759	109
INFRASTRUCTURE PLANNED	135	11,379	512,759	222	11,379	512,759	222
FLEET RELIABILITY	90	13,378	1,765,058	76	13,378	1,765,058	76
TRAIN OPERATIONS	424	77,285	1,765,058	438	77,285	1,765,058	438

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

27-FOI-00058 [illegible] 10/27/2026

Scheduled Departure Date: **10/17/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/17/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	293	51	82.6%	5,184	727	86.0%	5,184	727	86.0%
Central Division	86.0%	59	3	94.9%	973	68	93.0%	973	68	93.0%
East Division	82.0%	150	33	78.0%	2,764	404	85.4%	2,764	404	85.4%
West Division	86.0%	84	15	82.1%	1,447	255	82.4%	1,447	255	82.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

27-FOI-00054 2000 0000000 [illegible] 10/17/2026

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/17/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/17/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	293	51	82.6%	5,184	727	86.0%	5,184	727	86.0%
Central Division	86.0%	59	3	94.9%	973	68	93.0%	973	68	93.0%
CDL	95.0%	2	0	100.0%	23	2	91.3%	23	2	91.3%
CHI	86.0%	27	1	96.3%	461	37	92.0%	461	37	92.0%
CHM	-	-	-	-	10	2	80.0%	10	2	80.0%
DAL	-	-	-	-	2	0	100.0%	2	0	100.0%
FTW	92.5%	1	1	0.0%	15	2	86.7%	15	2	86.7%
GRR	95.5%	1	0	100.0%	17	0	100.0%	17	0	100.0%
KCY	92.0%	2	0	100.0%	34	0	100.0%	34	0	100.0%
MKE	92.0%	6	0	100.0%	100	7	93.0%	100	7	93.0%
MOE	97.5%	2	0	100.0%	27	0	100.0%	27	0	100.0%
MSP	96.5%	1	0	100.0%	17	0	100.0%	17	0	100.0%
NOL	94.5%	5	1	80.0%	64	4	93.8%	64	4	93.8%
OKC	97.0%	1	0	100.0%	17	1	94.1%	17	1	94.1%
PNT	88.0%	3	0	100.0%	50	6	88.0%	50	6	88.0%
PTH	93.0%	1	0	100.0%	17	0	100.0%	17	0	100.0%
QCY	91.0%	2	0	100.0%	34	2	94.1%	34	2	94.1%
SAS	90.5%	1	0	100.0%	17	4	76.5%	17	4	76.5%
STL	89.0%	4	0	100.0%	68	1	98.5%	68	1	98.5%
East Division	82.0%	150	33	78.0%	2,764	404	85.4%	2,764	404	85.4%
ALB	88.5%	7	0	100.0%	134	11	91.8%	134	11	91.8%
ALX	-	3	2	33.3%	3	2	33.3%	3	2	33.3%
ATL	-	1	0	100.0%	5	1	80.0%	5	1	80.0%
BON	87.5%	5	0	100.0%	85	9	89.4%	85	9	89.4%
BOS	85.5%	6	0	100.0%	249	6	97.6%	249	6	97.6%
BRK	92.5%	5	0	100.0%	85	6	92.9%	85	6	92.9%
BTN	82.0%	1	1	0.0%	17	3	82.4%	17	3	82.4%
CLT	91.5%	5	1	80.0%	79	10	87.3%	79	10	87.3%
GFD	88.0%	2	0	100.0%	34	3	91.2%	34	3	91.2%
GRO	-	-	-	-	5	0	100.0%	5	0	100.0%
HAR	79.5%	8	1	87.5%	192	23	88.0%	192	23	88.0%
HFD	-	-	-	-	24	6	75.0%	24	6	75.0%
JAX	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
LOR	84.0%	1	1	0.0%	16	6	62.5%	16	6	62.5%
MET	-	1	1	0.0%	1	1	0.0%	1	1	0.0%
MIA	89.5%	2	1	50.0%	33	7	78.8%	33	7	78.8%
MTR	79.0%	1	0	100.0%	17	4	76.5%	17	4	76.5%
NFK	84.5%	1	0	100.0%	33	4	87.9%	33	4	87.9%
NFL	93.5%	2	0	100.0%	34	3	91.2%	34	3	91.2%
NHV	78.0%	5	1	80.0%	85	19	77.6%	85	19	77.6%
NPN	93.0%	-	-	-	30	4	86.7%	30	4	86.7%
NYP	75.5%	40	9	77.5%	746	130	82.6%	746	130	82.6%
PGH	93.0%	2	0	100.0%	18	3	83.3%	18	3	83.3%
PHL	48.0%	6	4	33.3%	114	59	48.2%	114	59	48.2%
RGH	95.0%	6	4	33.3%	60	9	85.0%	60	9	85.0%

Information Management

27-FOI-00054

Initial Terminal Performance By Terminal

10/17/2026

Scheduled Departure Date: **10/17/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/17/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	293	51	82.6%	5,184	727	86.0%	5,184	727	86.0%
East Division	82.0%	150	33	78.0%	2,764	404	85.4%	2,764	404	85.4%
RNK	83.5%	1	0	100.0%	32	3	90.6%	32	3	90.6%
SAB	98.0%	1	0	100.0%	17	0	100.0%	17	0	100.0%
SAV	96.0%	-	-	-	15	0	100.0%	15	0	100.0%
SFA	88.0%	1	0	100.0%	16	3	81.3%	16	3	81.3%
SPG	92.5%	6	0	100.0%	92	8	91.3%	92	8	91.3%
TWO	73.0%	1	0	100.0%	17	5	70.6%	17	5	70.6%
WAS	84.0%	29	7	75.9%	475	56	88.2%	475	56	88.2%
West Division	86.0%	84	15	82.1%	1,447	255	82.4%	1,447	255	82.4%
ARN	92.0%	1	1	0.0%	17	1	94.1%	17	1	94.1%
BFD	79.0%	7	1	85.7%	118	27	77.1%	118	27	77.1%
EMY	72.0%	1	1	0.0%	18	9	50.0%	18	9	50.0%
EUG	86.5%	2	0	100.0%	32	1	96.9%	32	1	96.9%
GAC	-	-	-	-	2	1	50.0%	2	1	50.0%
GTA	90.0%	6	2	66.7%	48	16	66.7%	48	16	66.7%
IRV	-	-	-	-	1	0	100.0%	1	0	100.0%
LAX	89.5%	12	1	91.7%	155	19	87.7%	155	19	87.7%
OKJ	74.5%	9	0	100.0%	199	67	66.3%	199	67	66.3%
PDX	86.0%	5	0	100.0%	85	6	92.9%	85	6	92.9%
SAC	88.5%	12	2	83.3%	251	23	90.8%	251	23	90.8%
SAN	90.5%	11	5	54.5%	180	37	79.4%	180	37	79.4%
SEA	85.0%	8	0	100.0%	135	18	86.7%	135	18	86.7%
SJC	89.0%	7	0	100.0%	118	19	83.9%	118	19	83.9%
SLO	90.0%	-	-	-	42	8	81.0%	42	8	81.0%
SPK	90.0%	1	1	0.0%	16	1	93.8%	16	1	93.8%
VAC	97.0%	2	1	50.0%	30	2	93.3%	30	2	93.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	267	17	4	76.5%	17	4	76.5%	17	12	29.4%	17	12	29.4%
4	82	17	1	94.1%	17	1	94.1%	17	15	11.8%	17	15	11.8%
5		16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
6	34	16	9	43.8%	16	9	43.8%	16	6	62.5%	16	6	62.5%
7		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
8	163	16	6	62.5%	16	6	62.5%	16	11	31.3%	16	11	31.3%
11	101	17	3	82.4%	17	3	82.4%	17	7	58.8%	17	7	58.8%
14	115	17	4	76.5%	17	4	76.5%	17	8	52.9%	17	8	52.9%
19		17	2	88.2%	17	2	88.2%	16	3	81.3%	16	3	81.3%
20		17	2	88.2%	17	2	88.2%	18	2	88.9%	18	2	88.9%
21	25	17	1	94.1%	17	1	94.1%	17	10	41.2%	17	10	41.2%
22	628	17	4	76.5%	17	4	76.5%	17	13	23.5%	17	13	23.5%
23		14	0	100.0%	14	0	100.0%	14	4	71.4%	14	4	71.4%
24		13	0	100.0%	13	0	100.0%	13	5	61.5%	13	5	61.5%
25	29	13	0	100.0%	13	0	100.0%	13	4	69.2%	13	4	69.2%
26		14	0	100.0%	14	0	100.0%	14	5	64.3%	14	5	64.3%
27	45	16	4	75.0%	16	4	75.0%	16	3	81.3%	16	3	81.3%
28		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
40		17	4	76.5%	17	4	76.5%	17	9	47.1%	17	9	47.1%
41		17	3	82.4%	17	3	82.4%	18	12	33.3%	18	12	33.3%
41		17	3	82.4%	17	3	82.4%	18	12	33.3%	18	12	33.3%
42		17	3	82.4%	17	3	82.4%	17	7	58.8%	17	7	58.8%
43	56	17	5	70.6%	17	5	70.6%	17	6	64.7%	17	6	64.7%
48		17	4	76.5%	17	4	76.5%	17	6	64.7%	17	6	64.7%
49		17	3	82.4%	17	3	82.4%	17	1	94.1%	17	1	94.1%
50		8	0	100.0%	8	0	100.0%	8	4	50.0%	8	4	50.0%
51		7	3	57.1%	7	3	57.1%	8	3	62.5%	8	3	62.5%
52		16	3	81.3%	16	3	81.3%	16	8	50.0%	16	8	50.0%
53		16	6	62.5%	16	6	62.5%	16	13	18.8%	16	13	18.8%
54		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
57		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
58	293	17	1	94.1%	17	1	94.1%	17	15	11.8%	17	15	11.8%
59	62	17	1	94.1%	17	1	94.1%	17	13	23.5%	17	13	23.5%
63	108	17	8	52.9%	17	8	52.9%	17	17	0.0%	17	17	0.0%
64	97	17	5	70.6%	17	5	70.6%	17	8	52.9%	17	8	52.9%
65		6	0	100.0%	6	0	100.0%	5	1	80.0%	5	1	80.0%
68		17	4	76.5%	17	4	76.5%	17	3	82.4%	17	3	82.4%
69		17	7	58.8%	17	7	58.8%	17	2	88.2%	17	2	88.2%
71	118	17	1	94.1%	17	1	94.1%	17	2	88.2%	17	2	88.2%
72	87	17	3	82.4%	17	3	82.4%	17	2	88.2%	17	2	88.2%
73	32	12	1	91.7%	12	1	91.7%	12	3	75.0%	12	3	75.0%
74	16	12	2	83.3%	12	2	83.3%	12	6	50.0%	12	6	50.0%

Amtrak On Time Performance

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		17	2	88.2%	17	2	88.2%	15	2	86.7%	15	2	86.7%
76		16	2	87.5%	16	2	87.5%	15	4	73.3%	15	4	73.3%
77		17	3	82.4%	17	3	82.4%	17	6	64.7%	17	6	64.7%
78		17	3	82.4%	17	3	82.4%	18	4	77.8%	18	4	77.8%
79		17	2	88.2%	17	2	88.2%	17	7	58.8%	17	7	58.8%
80	19	17	0	100.0%	17	0	100.0%	17	4	76.5%	17	4	76.5%
82		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
87	94	5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
88		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
97		17	8	52.9%	17	8	52.9%	17	4	76.5%	17	4	76.5%
98		17	3	82.4%	17	3	82.4%	18	7	61.1%	18	7	61.1%
99		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
101		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
103		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
106		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
107		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
109		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
118		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
124	32	5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
126		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
127		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
135		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
140		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
142		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
143		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
144		4	3	25.0%	4	3	25.0%	4	0	100.0%	4	0	100.0%
146		5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
147	20	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
150		5	4	20.0%	5	4	20.0%	5	2	60.0%	5	2	60.0%
151	53	12	9	25.0%	12	9	25.0%	12	3	75.0%	12	3	75.0%
152		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
153		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
155		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
156		5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
158		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
159		4	3	25.0%	4	3	25.0%	4	2	50.0%	4	2	50.0%
160		5	3	40.0%	5	3	40.0%	5	2	60.0%	5	2	60.0%
161		5	2	60.0%	5	2	60.0%	5	3	40.0%	5	3	40.0%
162		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
163		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
164		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
165		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
167		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
168		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
194		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
195		5	0	100.0%	5	0	100.0%	5	3	40.0%	5	3	40.0%
230		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
232		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
233		17	7	58.8%	17	7	58.8%	17	8	52.9%	17	8	52.9%
234		17	0	100.0%	17	0	100.0%	17	0	100.0%	17	0	100.0%
235		17	1	94.1%	17	1	94.1%	17	4	76.5%	17	4	76.5%
236		17	0	100.0%	17	0	100.0%	17	3	82.4%	17	3	82.4%
237	53	17	3	82.4%	17	3	82.4%	17	5	70.6%	17	5	70.6%
238		17	1	94.1%	17	1	94.1%	17	0	100.0%	17	0	100.0%
239		17	3	82.4%	17	3	82.4%	17	1	94.1%	17	1	94.1%
240		17	3	82.4%	17	3	82.4%	17	2	88.2%	17	2	88.2%
241		17	4	76.5%	17	4	76.5%	17	4	76.5%	17	4	76.5%
243		17	2	88.2%	17	2	88.2%	17	0	100.0%	17	0	100.0%
244		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
245		17	1	94.1%	17	1	94.1%	17	2	88.2%	17	2	88.2%
280		17	3	82.4%	17	3	82.4%	17	7	58.8%	17	7	58.8%
281		17	2	88.2%	17	2	88.2%	17	3	82.4%	17	3	82.4%
283		17	0	100.0%	17	0	100.0%	17	3	82.4%	17	3	82.4%
284	58	17	0	100.0%	17	0	100.0%	17	2	88.2%	17	2	88.2%
290	27	17	3	82.4%	17	3	82.4%	17	7	58.8%	17	7	58.8%
291		17	12	29.4%	17	12	29.4%	17	5	70.6%	17	5	70.6%
300		17	0	100.0%	17	0	100.0%	17	4	76.5%	17	4	76.5%
301		17	0	100.0%	17	0	100.0%	17	3	82.4%	17	3	82.4%
302		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
305		17	0	100.0%	17	0	100.0%	17	6	64.7%	17	6	64.7%
306		17	0	100.0%	17	0	100.0%	17	6	64.7%	17	6	64.7%
307		17	1	94.1%	17	1	94.1%	17	7	58.8%	17	7	58.8%
311		17	1	94.1%	17	1	94.1%	17	3	82.4%	17	3	82.4%
316		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
318		17	0	100.0%	17	0	100.0%	17	7	58.8%	17	7	58.8%
319	Cncld	17	0	100.0%	17	0	100.0%	16	13	18.8%	16	13	18.8%
330		15	0	100.0%	15	0	100.0%	15	1	93.3%	15	1	93.3%
331		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
332		17	2	88.2%	17	2	88.2%	17	0	100.0%	17	0	100.0%
334		17	0	100.0%	17	0	100.0%	17	0	100.0%	17	0	100.0%
335		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
336		17	0	100.0%	17	0	100.0%	17	1	94.1%	17	1	94.1%
337		17	1	94.1%	17	1	94.1%	17	1	94.1%	17	1	94.1%
338		17	2	88.2%	17	2	88.2%	17	5	70.6%	17	5	70.6%

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
339		17	4	76.5%	17	4	76.5%	17	3	82.4%	17	3	82.4%
341		16	4	75.0%	16	4	75.0%	16	1	93.8%	16	1	93.8%
342		17	3	82.4%	17	3	82.4%	17	1	94.1%	17	1	94.1%
343		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
350		17	1	94.1%	17	1	94.1%	17	10	41.2%	17	10	41.2%
351		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
352		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
353		17	2	88.2%	17	2	88.2%	17	2	88.2%	17	2	88.2%
354		17	3	82.4%	17	3	82.4%	16	5	68.8%	16	5	68.8%
355		17	2	88.2%	17	2	88.2%	16	4	75.0%	16	4	75.0%
364	59	17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
365		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
370		17	0	100.0%	17	0	100.0%	17	1	94.1%	17	1	94.1%
371		17	0	100.0%	17	0	100.0%	17	0	100.0%	17	0	100.0%
380	42	17	0	100.0%	17	0	100.0%	17	4	76.5%	17	4	76.5%
381		17	0	100.0%	17	0	100.0%	17	5	70.6%	17	5	70.6%
382		17	2	88.2%	17	2	88.2%	17	5	70.6%	17	5	70.6%
383	25	17	0	100.0%	17	0	100.0%	17	8	52.9%	17	8	52.9%
390	80	16	3	81.3%	16	3	81.3%	16	4	75.0%	16	4	75.0%
391		17	1	94.1%	17	1	94.1%	17	2	88.2%	17	2	88.2%
392		17	1	94.1%	17	1	94.1%	17	14	17.6%	17	14	17.6%
393	31	16	4	75.0%	16	4	75.0%	16	9	43.8%	16	9	43.8%
400		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
405		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
450		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
460		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
461		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
463		3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
464		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
467		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
488		5	3	40.0%	5	3	40.0%	5	2	60.0%	5	2	60.0%
499		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
500		17	1	94.1%	17	1	94.1%	17	4	76.5%	17	4	76.5%
502		17	1	94.1%	17	1	94.1%	17	2	88.2%	17	2	88.2%
503		17	3	82.4%	17	3	82.4%	17	8	52.9%	17	8	52.9%
504		16	1	93.8%	16	1	93.8%	16	7	56.3%	16	7	56.3%
505		17	1	94.1%	17	1	94.1%	17	3	82.4%	17	3	82.4%
506		17	1	94.1%	17	1	94.1%	16	4	75.0%	16	4	75.0%
507		17	0	100.0%	17	0	100.0%	16	5	68.8%	16	5	68.8%
508		17	1	94.1%	17	1	94.1%	17	5	70.6%	17	5	70.6%
509		17	0	100.0%	17	0	100.0%	17	6	64.7%	17	6	64.7%
511		17	1	94.1%	17	1	94.1%	17	2	88.2%	17	2	88.2%

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
516	18	15	3	80.0%	15	3	80.0%	14	10	28.6%	14	10	28.6%
517	82	17	2	88.2%	17	2	88.2%	17	8	52.9%	17	8	52.9%
518		17	1	94.1%	17	1	94.1%	16	8	50.0%	16	8	50.0%
519		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
562		15	1	93.3%	15	1	93.3%	15	8	46.7%	15	8	46.7%
564		15	0	100.0%	15	0	100.0%	15	7	53.3%	15	7	53.3%
566		15	1	93.3%	15	1	93.3%	13	5	61.5%	13	5	61.5%
567		15	2	86.7%	15	2	86.7%	14	3	78.6%	14	3	78.6%
572	60	12	4	66.7%	12	4	66.7%	11	8	27.3%	11	8	27.3%
573	51	15	1	93.3%	15	1	93.3%	15	8	46.7%	15	8	46.7%
579	48	12	1	91.7%	12	1	91.7%	11	6	45.5%	11	6	45.5%
580	56	15	2	86.7%	15	2	86.7%	14	7	50.0%	14	7	50.0%
581	201	15	7	53.3%	15	7	53.3%	13	9	30.8%	13	9	30.8%
584	117	15	2	86.7%	15	2	86.7%	13	11	15.4%	13	11	15.4%
587	183	15	5	66.7%	15	5	66.7%	13	8	38.5%	13	8	38.5%
588	116	12	3	75.0%	12	3	75.0%	11	4	63.6%	11	4	63.6%
591	87	15	3	80.0%	15	3	80.0%	15	9	40.0%	15	9	40.0%
593	Cncld	10	5	50.0%	10	5	50.0%	8	2	75.0%	8	2	75.0%
595	No OS	11	5	54.5%	11	5	54.5%	11	8	27.3%	11	8	27.3%
600		15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
607		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
626		15	4	73.3%	15	4	73.3%	15	3	80.0%	15	3	80.0%
643		15	5	66.7%	15	5	66.7%	15	3	80.0%	15	3	80.0%
645	18	15	5	66.7%	15	5	66.7%	15	3	80.0%	15	3	80.0%
647		14	2	85.7%	14	2	85.7%	14	0	100.0%	14	0	100.0%
649		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
650		15	3	80.0%	15	3	80.0%	15	1	93.3%	15	1	93.3%
652		15	1	93.3%	15	1	93.3%	15	0	100.0%	15	0	100.0%
655		15	2	86.7%	15	2	86.7%	15	1	93.3%	15	1	93.3%
656	41	15	3	80.0%	15	3	80.0%	15	4	73.3%	15	4	73.3%
658		14	0	100.0%	14	0	100.0%	14	0	100.0%	14	0	100.0%
661		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
662		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
664		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
667		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
689	26	5	0	100.0%	5	0	100.0%	6	2	66.7%	6	2	66.7%
690		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
691		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
692		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
693		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
694		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
695		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
696		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
697		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
698		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
701	19	17	2	88.2%	17	2	88.2%	17	4	76.5%	17	4	76.5%
702	94	17	1	94.1%	17	1	94.1%	17	6	64.7%	17	6	64.7%
703		17	3	82.4%	17	3	82.4%	17	3	82.4%	17	3	82.4%
704		17	3	82.4%	17	3	82.4%	17	2	88.2%	17	2	88.2%
710	53	17	4	76.5%	17	4	76.5%	17	4	76.5%	17	4	76.5%
711	Cncld	17	3	82.4%	17	3	82.4%	13	2	84.6%	13	2	84.6%
712	42	17	6	64.7%	17	6	64.7%	17	6	64.7%	17	6	64.7%
713	Cncld	16	5	68.8%	16	5	68.8%	14	4	71.4%	14	4	71.4%
714	48	17	8	52.9%	17	8	52.9%	16	10	37.5%	16	10	37.5%
715	76	17	2	88.2%	17	2	88.2%	17	9	47.1%	17	9	47.1%
716		17	11	35.3%	17	11	35.3%	16	5	68.8%	16	5	68.8%
717	38	17	8	52.9%	17	8	52.9%	15	7	53.3%	15	7	53.3%
718		17	12	29.4%	17	12	29.4%	17	7	58.8%	17	7	58.8%
719		17	4	76.5%	17	4	76.5%	17	5	70.6%	17	5	70.6%
720		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
723		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
724		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
727		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
728		5	1	80.0%	5	1	80.0%	5	3	40.0%	5	3	40.0%
729		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
732		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
733		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
734		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
736		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
737		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
738		5	0	100.0%	5	0	100.0%	5	2	60.0%	5	2	60.0%
741		5	0	100.0%	5	0	100.0%	4	1	75.0%	4	1	75.0%
742		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
743		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
744		5	2	60.0%	5	2	60.0%	5	2	60.0%	5	2	60.0%
745		5	0	100.0%	5	0	100.0%	5	1	80.0%	5	1	80.0%
746		4	1	75.0%	4	1	75.0%	3	1	66.7%	3	1	66.7%
747		5	1	80.0%	5	1	80.0%	5	2	60.0%	5	2	60.0%
748		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
749		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
751		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
757	45	15	0	100.0%	15	0	100.0%	15	9	40.0%	15	9	40.0%
761	98	15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
765	58	15	0	100.0%	15	0	100.0%	15	9	40.0%	15	9	40.0%

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/17/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
769	62	15	1	93.3%	15	1	93.3%	15	9	40.0%	15	9	40.0%
770	108	15	1	93.3%	15	1	93.3%	14	9	35.7%	14	9	35.7%
774	132	15	1	93.3%	15	1	93.3%	14	11	21.4%	14	11	21.4%
777	103	15	1	93.3%	15	1	93.3%	14	11	21.4%	14	11	21.4%
782	201	15	12	20.0%	15	12	20.0%	14	10	28.6%	14	10	28.6%
785	85	15	6	60.0%	15	6	60.0%	15	9	40.0%	15	9	40.0%
786	Cncld	15	3	80.0%	15	3	80.0%	12	8	33.3%	12	8	33.3%
790	63	15	1	93.3%	15	1	93.3%	15	8	46.7%	15	8	46.7%
821		17	1	94.1%	17	1	94.1%	17	13	23.5%	17	13	23.5%
822	39	17	2	88.2%	17	2	88.2%	17	17	0.0%	17	17	0.0%
1019		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1020		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1040		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1071	24	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
1078		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1079		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1080		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1090		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1094		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1095		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1097	24	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
1098		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1128		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%
1169		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
1179		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
1180	40	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
1333	32	17	1	94.1%	17	1	94.1%	17	4	76.5%	17	4	76.5%
1340		17	0	100.0%	17	0	100.0%	17	3	82.4%	17	3	82.4%
2201		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2203		5	0	100.0%	5	0	100.0%	5	0	100.0%	5	0	100.0%
2205		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2216	17	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2218		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2220		3	0	100.0%	3	0	100.0%	3	2	33.3%	3	2	33.3%
2248		3	0	100.0%	3	0	100.0%	3	0	100.0%	3	0	100.0%
2249		2	0	100.0%	2	0	100.0%	2	0	100.0%	2	0	100.0%
2250		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2251	17	3	1	66.7%	3	1	66.7%	3	1	66.7%	3	1	66.7%
2252		5	1	80.0%	5	1	80.0%	5	0	100.0%	5	0	100.0%
2255		5	1	80.0%	5	1	80.0%	5	1	80.0%	5	1	80.0%

Amtrak Endpoint OTP Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2216	NYP	17	CAR	26	CAR	26	PHL-PHL	AM	Door, ENTIRE CONSIST, COULD NOT GET DOORS TO OPEN; HAD TO PREFORM DEPREPARE
2251	WAS	17	OTH	3	OTH	3	XCY-XHM	AM	Lost time - N.A.R.
87	WAS	2	ENG	69	ENG	69	NYP-NYP	AM	Other electrical failure, 619|EX|ES
124	PHL								
147	WAS	20	CTI	21	CTI	10	BRP-STM	MN	Follow metro, Other, enroute
151	WAS	53	SVS	36	SVS	36	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD
1071	RNK	24	SYS	15	SYS	15	ALX-ALX	CS	Other late crew
80	RGH	19	PTI	10	PTI	10	BNC-DNC	NS	Meet AM 71, Control Point, Haw River
1180	ALX	40	SYS	34	ENG	28	RGH-SSM	NS	PTC - On Board Cab Signal or PTC Failure System was showing breaking enforcement for a speed restriction that we had already cleared. Recycled and was able to proceed east., 37
645	HAR	18	SYS	14	SYS	14	EXT-EXT	AM	Unscheduled passenger stop, WAITING TO PICK UP PSGRS FROM AM42 WHO FORGOT TO GET OFF THE TRAIN
656	NYP	41	SVS	47	SVS	47	PHL-XHM	AM	Unplanned Wye, WYE ON THE OUTBOUND
689	BRK	26	DSR	7	DSR	7	ORB-POR	CS	Per bulletin Milepost w/Letters, pld 16.4, pld 16.3, 25, main, Milepost w/Letters, pld 14.7, pld 14.3, 25, main
63	TWO	108	PTI	15	PTI	15	ROC-BUF	CS	Meet 64, Control Point, 427
64	NYP	97	PTI	21	PTI	21	AMS-XHF	AM	Meet 49, Control Point, CP169
237	ALB	53	ITI	29	ITI	29	NYP-NYP	AM	Late departure at initial terminal due to late arrival of inbound equipment, 284
284	NYP	58	FTI	37	ENG	17	HUD-RHI	AM	HEP HEP still down. Stopped South of CP 114 to inspect equipment. Short looped 480 cable between rear car and Eng 92 on the left side of consist. Train line complete after short looping., 92
290	NYP	27	CTI	16	CTI	13	POU-CRT	MN	Follow metro north, Milepost, 73.6, 33.3
43	PGH	56	FTI	60	FTI	29	TYR-ALT	NS	Follow 29 G, Milepost, 222.1, 236.1
71	CLT	118	TCC	62	TCC	62	RGH-RGH	NS	Windshield wipers broken NC103
72	RGH	87	ITI	94	ITI	94	CLT-CLT	NS	Late departure at initial terminal due to late arrival of inbound equipment 71

Amtrak Endpoint OTP Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
73	CLT	32	WTR	16	PTI	14	HPT-SAL	NS	Meet #Amt72, Control Point, Duke
74	RGH	16	PTI	18	PTI	18	BNC-DNC	NS	Meet #amt77, Siding, Isom
1097	WAS	24	ENG	27	ENG	22	WIL-XPV	AM	HEP, 608|EX|ES, stopped at MP 33 a/c multiple faults and no HEP
25	NOL	29	FTI	29	FTI	29	GUF-BAS	CS	Meet CSX5369, Siding, Harbin
6	CHI	34	DSR	68	DMW	66	GJT-XAC	UP	Waiting for MW clearance Siding, clifton
516	VAC	18	MBO	21	MBO	21	XF2-X1J	BN	For maritime traffic Bridge, Fraser river br
517	PDX	82	FTI	71	FTI	53	X1J-XF2	BN	Cross Traffic Held while 7 o'clock TTR crew put their train away. Tried to convince dispatcher to let us out first, but no go. Three sections to put away., CN 3362, Control Point, CN Jct
58	CHI	293	FTI	105	DMW	69	CEN-EFG	CC	Hold for defect repair Broken rail mp 230.55, Control Point, s tonti
59	NOL	62	DSR	95	PTI	34	MCB-HMD	CC	Meet 58, Siding, s arcola
11	LAX	101	DCS	181	DCS	111	SLO-SBA	UP	Restrictive signal(s) from known wayside signal failure Flagging, Red, Milepost, 295, 356
14	SEA	115	DCS	231	DCS	119	SBA-SLO	UP	Proceeded under Track and Time from CO356 to CO295. Had to wait for AMT765 ahead to do the same. Various Stop and Restricting signals. Control Point, N Ellwood
8	CHI	163	FTI	157	ENG	97	SEA-SEA	BN	Other electrical failure Over speed not working as intended., AMTK 57
27	PDX	11	FTI	51	FTI	33	PSC-WIH	BN	Follow Also waiting for BNSF 3864 to clear at Roosevelt yard, BNSF 3773, Control Point, McCredie, Control Point, Bates
822	OKC	39	DSR	44	DSR	25	FTW-GLE	BN	Per bulletin Milepost, 345.7, 346.3, 25, 1, Milepost, 346.3, 349.8, 25, 1, Milepost, 350.7, 351.1, 50, m, Milepost, 353.7, 354.1, 60, 1, Milepost, 355.5, 355.9, 50, 1, Milepost, 369, 370.2, 60, m, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.6, 376.8, 60, m, Milepost, 355.
364	PTH	59	ENG	93	ENG	93	XPI-XMC	AM	Air / Brake ID4630
572	SAN	60	PTI	25	CTI	14	IRV-SNC	SC	Meet metrolink, 1663, Control Point, trabuco
573	LAX	51	CTI	50	CTI	50	OSD-X98	SN	Meet Metrolink, 1859, Control Point, pulgas
579	LAX	48	DCS	55	DCS	51	OSD-X98	SN	FLAGGING SONGS Had to flag songs due to high tides, Control Point, CP SONGS

Amtrak Endpoint OTP Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
580	SAN	56	CTI	42	CTI	36	SNC-SNP	SC	Follow metrolink, 1664, Control Point, capistrano
581	LAX	201	CTI	82	ITI	74	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 770
584	SAN	117	CTI	83	CTI	38	SNC-SNP	SC	Meet Metrolink, 1667, Control Point, Songs
587	LAX	183	PTI	79	PTI	79	OSD-X98	SC	Meet 782, Control Point, Songs
588	SAN	116	ITI	79	ITI	79	LAX-LAX	SC	Late departure at initial terminal due to late arrival of inbound equipment 581
591	LAX	87	PTI	35	PTI	35	OSD-X98	SN	Meet 584/782, Control Point, Pulgas
593	LAX	Trn Cancelled							
595	LAX	No OS Rpt	ITI	97	ITI	97	SAN-SAN	SN	Late departure at initial terminal due to late arrival of inbound equipment 782
757	GTA	45	DCS	44	PTI	18	VEC-CPN	UP	Meet 770, Siding, Seacliff
761	GTA	98	DCS	82	DCS	49	VEC-CPN	UP	Flagging seacliff to CPN at restricted speed Control Point, seacliff
765	GTA		DCS	47	DCS	26	VEC-CPN	UP	Restrictive signal(s) from known wayside signal failure Flagging by N. Seacliff., Stop, Control Point, co 385
769	GTA	62	PTI	31	CTI	21	OSD-X98	SN	Meet Metrolink, 1857, Control Point, Pulgas
770	SAN	108	DCS	75	DCS	26	CPN-VEC	UP	Restrictive signal(s) from known wayside signal failure Proceed at restricted proceed the intermediate signals 373 to 383 due to signal issues on the up SBA sub, 373, 377, 379, 381, 383, Milepost, 373, 383
774	SAN	132	DCS	65	ITI	53	GTA-GTA	UP	Late departure at initial terminal due to late arrival of inbound equipment 757
777	GTA	103	DCS	60	PTI	25	OSD-X98	SN	Meet Amtk 770, Amtk 572, Control Point, Don
782	SAN	201	DCS	103	CTI	58	SNC-SNP	SC	Meet Metrolink, 1667, Metrolink, 1860, Control Point, Serra
785	GTA	85	DCS	101	DCS	52	OSD-X98	SC	CTC system failure Control Point, songs
786	SAN	Trn Cancelled	DCS	46	DCS	25	CPN-VEC	UP	Restrictive signal(s) from known wayside signal failure Flagging through Seacliff, plus hand lining the south end., Stop, Control Point, CO 385
790	SAN	63	DCS	74	DCS	24	IRV-SNC	SC	CTC system failure Held at LNG station to allow 2 west bound trains go by. After that we continue to our next stop of SNC. High tides causing signal issues, Control Point, pier

Amtrak Endpoint OTP Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/17/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
701	SAC	19	PTI	33	DMW	22	WAC-COC	BN	Hold for defect repair Broken rail, Control Point, east elmo
702	BFD	94	ENG	76	ENG	16	XEC-LOD	UP	PTC - On Board Cab Signal or PTC Failure PTC speedometer and cab car 90218 speedometer unsunchronized. Intermittent PTC dropping out. UP PTC desk and CNOC notified. Advised to run with PTC disengaged and comply with Rule 1.39., 90218
710	BFD	53	TRS	57	TRS	57	TRK-MCD	BN	Trespasser strike Milepost, 1055, 1055
711	OKJ	Trn Cancelled	PTI	57	FTI	46	BFD-WAC	BN	Blocked from station track BNSF 7967, Control Point, West Wasco, Manifest
712	BFD	42	POL	41	POL	40	MOD-MOD	BN	Fire department hold Held at MOD platform (west of west empire) for Fire at mp 1087.65
713	OKJ	Trn Cancelled	DMW	22	DMW	22	WAC-COC	BN	Broken rail at e Elmo. Signal maintainer walked train across. Siding, elmo
714	BFD	48	PTI	34	PTI	17	COC-WAC	BN	Meet 703, Siding, elmo
715	OKJ	76	PTI	36	FTI	23	BFD-WAC	BN	Meet bnsf 7489, Control Point, lopez
717	OKJ	38	ITI	36	ITI	36	BFD-BFD	BN	Late departure at initial terminal due to late arrival of inbound equipment 702
3	LAX	267	FTI	353	FTI	178	KNG-NDL	BN	Follow Milepost w/Letters, KNG, NDL, BNSF 6603, Z Train
4	CHI	82	FTI	146	FTI	40	KNG-FLG	BN	Meet BNSF Unknown, Milepost, 453.8, 430.0
21	SAS	25	FTI	155	SYS	29	CHI-XTF	AM	PTC- IETMS Software Download PTC not initializing, Control Point, Roosevelt
22	CHI	628	CON	460	CON	460	SAS-SAS	UP	Hold for connecting train 2
380	CHI	42	CTI	15	CTI	15	NPV-LAG	BN	Follow metra 2010, 2010, Milepost, 31, 13
383	QCY	25	FTI	21	FTI	12	PCT-KEE	BN	Follow Milepost, 112, 116, BN 8794
390	CHI	80	SYS	40	SYS	40	MAT-CHM	CC	Re-crew / job briefing Wait for 391 then crew swap, Siding, Tuscola
393	CDL	31	DSR	35	RTE	17	X9R-XCS	CT	Dispatcher hold Control Point, 16th
319	KCY	Trn Cancelled	ADA	20	FTI	15	XTF-SMT	CC	Cross Traffic na, Control Point, Corwith
1333	MSP	32	FTI	52	FTI	52	XH8-MSP	CP	Follow cp 261, bnsf 7039, Control Point, cp 3988, Control Point, Newport

Amtrak Initial Terminal Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/17/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	1	10/17	288	195	Late departure at initial terminal due to late arrival of inbound equipment 2
NOL	1	10/17	288	93	PTC - On Board Cab Signal or PTC Failure Replaced Engine 19 with Engine 79, 19
ALX	1071	10/17	25	5	Passenger and/or baggage
ALX	1071	10/17	25	15	Other late crew
ALX	1071	10/17	25	5	Mobility Impaired
ALX	1179	10/17	6	6	Air / Brake Checking brakes were stuck, 111
BTN	290	10/17	1		
CLT	72	10/17	94	94	Late departure at initial terminal due to late arrival of inbound equipment 71
HAR	626	10/17	2	2	Wheelchair, LATE ADA PSGR WITH WHELCHAIR; 757P
LOR	53	10/17	56	56	DRUMMAC did not have enough drivers, took awhile to load cars.
MIA	1040	10/17	1		
NHV	160	10/17	14		
NYP	87	10/17	69	69	Other electrical failure, 619|EX|ES
NYP	153	10/17	3	3	Passenger and/or baggage, BOARDING
NYP	159	10/17	3	3	Passenger and/or baggage
NYP	161	10/17	2	2	Passenger and/or baggage
NYP	237	10/17	29	29	Late departure at initial terminal due to late arrival of inbound equipment, 284
NYP	239	10/17	2	2	Passenger and/or baggage
NYP	291	10/17	1	1	Wait for scheduled departure time, LEFT ON TIME
NYP	607	10/17	27	27	Late departure at initial terminal due to late arrival of inbound equipment, 607, LATE OUT OF SSYD A/C LATE RELEASE
NYP	1097	10/17	21	21	Late departure at initial terminal due to late arrival of inbound equipment, 1098, PLUS ADD MOTOR
PHL	144	10/17	19	1	Passenger and/or baggage, BAGGAGE ASISTANCE AND TRAVEL
PHL	144	10/17	19	18	Planned set out / pick out of locomotives, cars or section of train, late release from yard
PHL	150	10/17	2	2	Planned set out / pick out of locomotives, cars or section of train, late out of the yard
PHL	151	10/17	36	36	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM YARD
PHL	645	10/17	1	1	Passenger and/or baggage
RGH	71	10/17	62	62	Windshield wipers broken NC103

Amtrak Initial Terminal Details

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/17/2026

Terminal	Train	Date	Late	Delay	Cause
RGH	77	10/17	9	9	Late departure at initial terminal due to late arrival of inbound equipment 72
RGH	79	10/17	8	8	PTC SLOW LOGGING
RGH	1180	10/17	24	24	PTC problem or failure (cause unknown)
WAS	54	10/17	5	3	Other late crew, CNDR HELD OFF BOARDING DUE TO NO HEP
WAS	54	10/17	5	2	HEP, 661|EX|ES, HEP FAULT.
WAS	124	10/17	29		
WAS	128	10/17	3	3	Planned set out / pick out of locomotives, cars or section of train
WAS	142	10/17	10	10	HEP, 618|EX|ES, FLAG UP 7" AFTER SPOTTING IN 13 TRK. 53" TOTAL BSP WORKING UP MOTOR
WAS	158	10/17	20		
WAS	168	10/17	6	6	Wheelchair, ADA RESPOT FOR BUISNESS CLASS
WAS	1090	10/17	4	4	Delay in Block
XIS	2255	10/17	1		
CHI	59	10/17	42	42	Late departure at initial terminal due to late arrival of inbound equipment 58, Late Arrival Of 58 Of Oct 16 2026
FTW	822	10/17	2	2	Toilet 34034
ARN	729	10/17	1		
BFD	717	10/17	36	36	Late departure at initial terminal due to late arrival of inbound equipment 702
EMY	6	10/17	10	10	Fuel Left yard late because of fueling for train, Other, yard
GTA	774	10/17	53	53	Late departure at initial terminal due to late arrival of inbound equipment 757
GTA	794	10/17	98		
LAX	588	10/17	79	79	Late departure at initial terminal due to late arrival of inbound equipment 581
SAC	747	10/17	1		
SAC	749	10/17	1	1	Injured or sick passenger Pax Angel Bazan PRN 376074 appeared to be ill. Bazan has had 2 seizures on prior trips on train 749 while conductors Wilson and Koger were assigned. Bazan refused any medical treatment
SAN	581	10/17	74	74	Late departure at initial terminal due to late arrival of inbound equipment 770
SAN	587	10/17	37	37	Late departure at initial terminal due to late arrival of inbound equipment 774
SAN	591	10/17	27	10	Follow coaster, 687, Control Point, Ash
SAN	591	10/17	27	17	Late departure at initial terminal due to late arrival of inbound equipment 580
SAN	593	10/17	(Trn Cxld)		Track Washout
SAN	595	10/17	97	97	Late departure at initial terminal due to late arrival of inbound equipment 782

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/17/2026

Terminal	Train	Date	Late	Delay	Cause
SPK	27	10/15	8	8	Late departure at initial terminal due to late arrival of inbound equipment 7, Late train 7
VAC	519	10/17	60		

Eastern Region

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.3	94.8	166	0
CDOT	95.0	87.5	88.8	92.4	16	2
MARC	95.0	77.8	86.2	90.2	18	4
SEPTA	95.0	85.6	89.9	91.5	111	16
NJT-NED	95.0	97.1	90.3	88.6	171	5
NJT-SED	95.0	100.0	98.8	97.2	22	0

Operating Highlights

Train 53(17) - South of Fredericksburg, VA - Car Failure

17OCT26: Train 53(17) was delayed on the CSX RF&P Subdivision at MP 51.6 after stopping again due to the smell of smoke and a suspected sticking brake. Upon inspection of the consist, the crew discovered the brakes stuck on the second passenger car, (32116). An Amtrak Road foreman and Train master responded to the scene to assist the crew with correction efforts. After troubleshooting and discovering the source of the air issue, the team was able to rectify, after which, train 53(17) continued south.

Train	Delay	Comment
53(17)	2'09"	

Train 656(17) - Philadelphia, PA - Cab Car Failure

17OCT26: Train 656(17) was delayed departing 30th Street Station in Philadelphia due to having to wye the train on the outbound. The delay was prolonged due to the brakes applying and not releasing as it moved on the wye.

Train	Delay	Comment
656(17)	45"	

Train 53(17) - South of Fredericksburg, VA - Car Failure

17OCT26: Train 53(17) was delayed on the CSX RF&P Subdivision at MP 57.7 after experiencing an undesired emergency stop. The crew discovered a hose separation between the EOT and the last car. After correcting this issue, the brakes on the train would not release. The crew consulted with CNOC Mechanical and the Trainmaster on duty. The issue was rectified and the train continued south.

Train	Delay	Comment
53(17)	1'35"	

27-FOI-00056 0000008937 UNCLASSIFIED 10/19/2026

Train 53(17) - South of Lorton, VA - Car Failure

17OCT26: Train 53(17) was delayed on the CSX RF&P subdivision at MP 74.2 due to a suspected brake issue. after stopping, and upon inspection, the crew discovered a tangled brake chain on one of the cars. The issues was corrected and Train 53(17) was able to get back on the move south.

Train	Delay	Comment
53(17)	42"	

Train 53(17) - Lorton, VA - Initial Terminal Delay

17OCT26: Train 53(17) was delayed at its initial terminal in Lorton, VA due to late automobile loading. The last vehicles were reportedly loaded at 3:54pm

Train	Delay	Comment
53(17)	56"	

Train 87(17) New York, NY - Initial Terminal Delay - Engine Failure

17OCT26: Train 87(17) was delayed at the initial terminal of New York due to the equipment going to the yard off train 82(17) and coming late to the station. An equipment swap was made in Sunny Side Yard Train due to train 118(17) locomotive arriving the yard first. Upon inspection locomotive 665 was shopped out for carbon damage and re3quired replacement. Once the delay for the motor swap became extensive the equipment swaps reverted back to their programed frequencies and the equipment departed the yard for the station.

Train	Delay	Comment
87(17)	1'09"	

Train 71(17) Raleigh, NC - Cab Car Failure

17OCT26: Train 71(17) operating with NC103, 5 coaches and NC1984 in trail was delayed at the initial terminal of Raleigh, NC due to a defective windshield wiper on NC1984. The Raleigh mechanical contractors attempted to make repairs and were unsuccessful requiring the crew to switch sets in the yard. Once the original set was returned to the yard the crew operated the replacement set to the station and boarded 100 customers and departed Raleigh.

As a result of the late operation of train 71(17), train 72(17) resulted in an initial terminal delay off the turn of equipment in Charlotte..

Train	Delay	Comment
71(17)	1'02"	
72(17)	1'36"	

Train 607(17) New York, NY - Initial Terminal Delay - Servicing

17OCT26: Train 607(17) operating with locomotives 657-607, 5 cars and 220 customers onboard was delayed departing the initial terminal of New York due to a late release of equipment from the yard. Once released the train was moved into the station and spotted for customer boarding and departed New York.

Train	Delay	Comment
607(17)	27"	

27-FOI-00056 0000008937 "UNCLASSIFIED" 10/19/2026

Train 151(17) Philadelphia, PA - Initial Terminal Delay - Servicing

17OCT26: Train 151(17) operating with engine 646/642, 5 coaches, and 225 customers, was delayed departing Philadelphia, PA, on Amtrak PW Line, due to late release of the equipment by the yard. Once all the necessary servicing was complete, the train was released by mechanical and spotted in the station to board.

Train	Delay	Comment
151(17)	36"	

Washington Terminal 'A' Interlocking - Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, Northeast Regional Services - M of W Work

05OCT26: Due to Diamond Replacement at Washington Terminal 'A' interlocking from Friday, October 16, 2026 to Monday, October 26,2026. There will be several service adjustments made to the following services Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services will be adjusted as follows:

PALMETTO
Northbound
- Train 90 (16Oct-26Oct) is canceled in its entirety.
- Train 1090 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between SAV and WAS.

Southbound
- Train 89 (15Oct-25Oct) is canceled in its entirety.
- Train 1089 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and SAV.

CARDINAL
Eastbound
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct), which normally operates between CHI and NYP, will terminate at IND.

Westbound
- Train 51 (18Oct, 21Oct, 23Oct, 25Oct), which normally operates between NYP and CHI, will originate at IND.

EQUIPMENT
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct) will turn for Train 51 (18Oct, 21Oct, 23Oct, 25Oct) at IND.
  - (Note: Train 51's departure days from IND are 19Oct, 22Oct, 24Oct, and 26Oct)

CRESCENT
Northbound
- Train 20 (16Oct-25Oct), which normally operates between NOL and NYP, will terminate at ATL.
- Train 1020 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between ATL and WAS.

Southbound
- Train 19 (16Oct-25Oct), which normally operates between NYP and NOL, will originate at ATL.
- Train 1019 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and ATL.

EQUIPMENT
- Train 20 (16Oct-25Oct) will turn for Train 19 (16Oct-25Oct) at ATL.
  - (Note: Train 19's departure days from ATL are 17Oct-26Oct)

SILVER METEOR
Northbound
- Train 98 (16Oct-25Oct), which normally operates between MIA and NYP, will terminate

Southbound
• Train 97 (16Oct-25Oct), which normally operates between NYP and MIX, will originate at JAX.
• Train 1097 (17Oct-25Oct) will operate and provide service between NYP and WAS.
27-FOI-00056 0000000089?7 "UNCLASSIFIED" 10/19/2026
• There will be no service between WAS and JAX.
EQUIPMENT
• Train 98 (16Oct-25Oct) will turn for Train 97 (16Oct-25Oct) at JAX.
o (Note: Train 97's departure days from JAX are 17Oct-26Oct)

FLORIDIAN
Northbound
• Train 40 (16Oct-24Oct), which normally operates between MIA and CHI, will originate at PGH.
• Train 1040 (17Oct-24Oct) will operate and provide service between MIA and JAX.
• There will be no service between JAX and PGH.
Southbound
• Train 41 (16Oct-24Oct), which normally operates between CHI and MIA, will terminate at PGH.
• Train 1041 (18Oct-25Oct) will operate and provide service between JAX and MIA.
• There will be no service between PGH and JAX.
EQUIPMENT
• Train 41 (16Oct-24Oct) will turn for Train 40 (16Oct-24Oct) at PGH
o (Note: Train 40's departure days from PGH are 17Oct-25Oct)

• Train 1040 (17Oct-24Oct) will turn for Train 1041 (18Oct-25Oct) at JAX

CAROLINIAN
Northbound
• Train 80 (17Oct-25Oct), which normally operates between CLT and NYP, will terminate at RGH.
• Train 1180 (17Oct-25Oct) is a new train that will operate between RGH and ALX, departing RGH at 11:00am.
• Train 1080 (17Oct-25Oct) is a new train that will operate between WAS and NYP, departing WAS at 5:15pm.
Southbound
• Train 79 (17Oct-25Oct), which normally operates between NYP and CLT, will originate at RGH.
• Train 1079 (17Oct-25Oct) is a new train that will operate between NYP and WAS, departing NYP at 7:05am.
• Train 1179 (17Oct-25Oct) is a new train that will operate between ALX and RGH, departing ALX at 1:00pm.
ALTERNATE TRANSPORTATION
• Train 1180 (17Oct-25Oct) will connect to Bus 1480 (17Oct-25Oct) at ALX
• Train 1079 (17Oct-25Oct) will connect to Bus 1479 (17Oct-25Oct) at WAS
EQUIPMENT
• Equipment for Train 1180 will deadhead on the rear of Train 79(16Oct) and will be cut in RGH
• Train 1179 (17Oct-24Oct) will turn at RGH for Train 1180 (18Oct-25Oct)
• Train 1179 (25Oct) will turn at RGH for Deadhead Train 80 to operate to WAS
• Northeast Regional Train 1094 (17Oct-25Oct) will make a same day turn at ALX for Train 1179 (17Oct-25Oct)
• Train 80 (17Oct-25Oct) will make a same day turn at RGH for Train 79 (17Oct-25Oct)

NORTHEAST REGIONAL
Norfolk
• Train 1094 (17Oct-25Oct) will operate between NFK and ALX
• Train 1095 (17Oct-25Oct) will operate between ALX and NFK

Roanoke
• Train 1071 (17Oct-25Oct) will operate between ALX and RNK
• Train 1078 (17Oct-25Oct) will operate between RNK and ALX
Newport News
• Train 65 (16OCt), which normally operates between BOS and NPN, will terminate at PHL.
• Train 65 (17Oct, 23OCt-24Oct), which normally operates between BOS and NPN, will

entirety with no alternate transportation.

ALTERNATE TRANSPORTATION

- Bus 1495 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1095 (17Oct-25Oct) at ALX

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

- Train 1094 (17Oct-25Oct) will connect to Bus 1494 (17Oct-25Oct) at ALX
- Bus 1471 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1071 (17Oct-25Oct) at ALX
- Train 1078 (17Oct-25Oct) will connect to Bus 1478 (17Oct-25Oct) at ALX
- Bus 1454 (17-Oct- 25Oct) will operate RNK - LYH - WAS.
- Bus 1455 (17-Oct- 25Oct) will operate WAS - LYH - RNK.
- Bus 1456 (17-Oct- 25Oct) will operate CVS - WAS
- Bus 1457 (17-Oct- 25Oct) will operate WAS - CVS

ALX-WAS Buses will unload in front of Union Station utilizing the middle lane of Columbus Circle, with WAS-ALX buses boarding up on the Union Station bus deck

EQUIPMENT

- Carolinian Train 1180 (17Oct-25Oct) will make a same day turn at ALX for Train 1071 (17Oct-25Oct)
- Train 1071 (17Oct-24Oct) will turn for Train 1078 (18Oct-25Oct) at RNK
- Train 1071 (25Oct) will turn for Train 156(26Oct) at RNK
- Train 1078 (17Oct-25Oct) will make a same day turn at ALX for Train 1095 (17Oct-25Oct)
- Train 1095 (17Oct-24Oct) will turn for Train 1094 (18Oct-25Oct) at NFK
- Train 1095 (25Oct) will turn for Train 94 (26Oct) at NFK

WBS#: B.TR.100151.0856

Maintenance of Way Highlights

37 FOI 00066 - 00000008937 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train 6(17) East of Elko, NV - Freight Train Interference

18OCT26: Train 6(17), carrying 104 customers onboard, was delayed east of Elko, NV, while holding at East Shafter Siding (MP 768.5) on the Union Pacific Shafter Subdivision due to disabled freight train CBTNO-15, led by UP 2749, near Silver Zone (MP 773.1). The freight train experienced a knuckle failure, requiring its crew to apply 50 hand brakes before completing repairs. Following replacement of the knuckle, the freight train moved into the siding and cleared the route.

Train	Delay	Comment
6(17)	1'17"	

Train 3(16) East of Flagstaff, AZ - Broken Rails & Freight Train Interference

17OCT26: Train 3(16) with 146 customers was delayed east of Flagstaff, AZ, while holding at East Darling (MP 326.6) on the BNSF Seligman Subdivision due to broken rails on Main Track 1 near MP 327.1 and MP 348, along with freight train interference in the area. The train remained behind three freight trains while eastbound movements crossed over at East Flagstaff before following the freight trains into Flagstaff Station. The broken rail near MP 348 was repaired by the time train arrived into Flagstaff, allowing the train to continue with favorable signal indications toward East Williams.

Train	Delay	Comment
3(16)	2'59"	

Train 4(17) San Bernardino, CA - Car Failure

17OCT26: Train 4(17), operating with locomotives E/164 and E/192, nine cars, and carrying 145 customers onboard, was delayed at San Bernardino, CA, after sleeper car 32039 experienced an electrical and battery failure. The crew worked with Los Angeles mechanical personnel to manually open the car's stuck end doors and restore access through the car. With the electrical issue unresolved, 37 customers assigned to sleeper car 32039 were moved or downgraded and accommodated in available coach seating. The equipment was released for service, with sleeper car 32039 scheduled for further inspection in Albuquerque, NM.

Train	Delay	Comment
4(17)	57"	

Train 6(17) East of Winnemucca, NV - Freight Train Interference

17OCT26: Train 6(17), carrying 110 customers onboard, was delayed east of Winnemucca, NV, at MP 418.2 on the Union Pacific Nevada Subdivision while meeting UP 6160.

Train	Delay	Comment
6(17)	54"	

Train 14(17) North of San Luis Obispo, CA - Signal

17OCT26: Train 14(17), carrying 168 customers onboard, was delayed north of San Luis Obispo, CA, while flagging through Chorro (MP 243.8) on the Union Pacific Coast Subdivision due to signal issues caused by a power outage.

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train 59(17) Chicago, IL - Initial Terminal Delay

17OCT26: Train 59(17), with 236 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late turn of equipment of late inbound train 58(16). Once the equipment was released by Chicago Mechanical, train 59(17) shoved into the depot, boarded customers and departed.

Train	Delay	Comment
59(17)	42"	

Train 7/27(16) West of Cut Bank, MT - High Wind Warnings

17OCT26: Train 7/27(16) was delayed west of Cut Bank, MT, on the BNSF Hi Line Subdivision due to high wind warnings. The train was restricted to a maximum speed of 20 MPH between MP 1105.1 and Browning Station (MP 1124.0), followed by a maximum speed of 30 MPH between Browning and Essex Station (MP 1168.8).

Train	Delay	Comment
7/27(16)	34"	CUT-BRO
7/27(16)	23"	BRO-ESM

Train 1(17) New Orleans, LA - Engine Failure

17OCT26: Train 1(17), with engines 79 and 29, 9 cars, and 89 customers onboard, was delayed departing New Orleans, LA/MP0.0 on the Amtrak New Orleans Terminal subdivision due to MU faults on engine 29 and the late arrival of train 2(14). In order to correct the issue, the lead engine was replaced with engine 79. Train 1(17) departed New Orleans Union Passenger Terminal.

Train 1(17) was further delayed at mile post 223.4, 4.5 miles west of Lake Charles, LA/MP218.9, on the UP Lafayette subdivision due to additional MU faults. The crew inspected with CNOC Mechanical by phone. and determined that the trail engine 29 may be the cause. The MU cables were pulled between the engines and a crew member was assigned to sit in the cab of engine 29. Train 1(17) was then able to initialize PTC and continue west.

Train	Delay	Comment
1(17)	3'15"	Late 2
1(17)	57"	LCH
1(17)	1'33"	Engine swap NOL

Train 8/28(16) East of Wolf Point, MT - Freight Train Interference

17OCT26: Train 8/28(16) was delayed east of Wolf Point, MT, while holding at Macon Siding (MP 221.0) on the BNSF Glasgow Subdivision to meet BNSF 3998.

Train	Delay	Comment
8/28(16)	33"	

Train 352(17) East of Jackson, MI - Passenger Train Interference

17OCT26: Train 352(17), with 146 customers onboard, was delayed at control point 75/MP75.7, 0.2 miles east of Jackson, MI/MP75.5, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(17). Once the route was clear, train 352(17) continued east.

Train	Delay	Comment
352(17)	32"	

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train 1333(17) East of St. Paul-Minneapolis, MN - Freight Train Interference

17OCT26: Train 1333(17) with 271 customers onboard, was delayed at Newport/MP402.5, 7.8 miles east of St Paul - Minneapolis Union Depot, MN/MP410.3, on the CPKC/BNSF River subdivision meeting freights CP 261, BNSF 7039, and CP 3988. Once the route was clear, train 1333(17) continued west.

Train	Delay	Comment
1333(17)	52"	

Train 364(17) West of New Buffalo, MI - Engine Failure

17OCT26: Train 364(17), with engines IDTX 4617 and IDTX 4630, 7 cars, and 199 customers onboard, stopped at mile post 236.1, 17 miles west of New Buffalo, MI/MP218.9 on the Amtrak Michigan Line subdivision due to an issue with their brake pipe pressure. The crew worked with CNOC Mechanical Desk and an air technician over the phone. The crew had to cut out the 21 pipe on the IDTX 4630. Once air pressure was restored, train 364(17) continued east.

Train	Delay	Comment
364(17)	1'33"	

Train 8/28(15) East of Tomah, WI - Passenger Train Interference

17OCT26: Train 8/28(15) held 3.1 miles east of Tomah, WI (MP240.1), on the CPRR Tomah Subdivision, at Monroe (MP237.0) meeting Train 1333(17) and letting Train 1340(17) operate ahead.

Train	Delay	Comment
8/28(15)	31"	

Train 59(16) North of Hammond, LA - Passenger Train Interference

17OCT26: Train 59(16) held 19.1 miles north of Hammond, LA (MP859.1), on the CNRR McComb Subdivision, at Arcola (MP840.0) in order to meet Train 58(17).

Train	Delay	Comment
59(16)	34"	

Train 712(17) Modesto, CA - Police Related

17OCT26: Train 712(17) was delayed departing Modesto, CA/ MP 1091.6 on the BNSF Stockton Subdivision due to a police hold ahead at MP 1087.65 for a vegetation fire. The crew held at the station for the local fire department to extinguish the vegetation fire and clear all equipment from the tracks. Once the tracks were clear, Train 712(17) proceeded east.

Train	Delay	Comment
712(17)	41"	

Train 22(17) Fort Worth, TX - Servicing

17OCT26: Train 22(17), E/203-E/311-E/53-6 Cars, was delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision, while completing routine fueling and required locomotive inspections prior to departure.

Train	Delay	Comment

27-FOI-00056 0000008937 "UNCLASSIFIED" 10/19/2026

Train 27(15) East of Wishram, WA - Freight Train Interference

17OCT26: Train 27(15) was delayed on a standing at McCrandie/MP 158.4, 52 miles east of Wishram, WA, on the BNSF Fallbridge subdivision due to freight interference. The crew began following BN3773 at MP 158.4 then held for BN3864 to clear freight into yard at Roosevelt/MP 147.1. Once freight cleared, the crew continued to follow BN3773 until Bates/MP 135.2 where they were able to operate around.

Train	Delay	Comment
27(15)	33"	

Train 3(16) West of Lamy, NM - Commuter Train Interference

17OCT26: Train 3(16), carrying 131 customers onboard, was delayed west of Lamy, NM, at Madrid (MP 864.9) on the NMRX Glorieta Subdivision while meeting an NMRX commuter train.

Train	Delay	Comment
3(16)	33"	

Train 782(17) Santa Barbara, CA - Passenger Train Interference

17OCT26: Train 782(17), carrying 136 customers onboard, was delayed at Santa Barbara, CA, Station (MP 367.4) on the Union Pacific Santa Barbara Subdivision while meeting Amtrak Train 14(17).

Train	Delay	Comment
782(17)	34"	

BNSF Chicago Subdivision West of Chicago, IL - Single Track

17OCT26: The BNSF Chicago Subdivision had a Maintenance of Way work window west of Chicago, IL on Main Track 1 and Main Track 2 between Congress Park/MP12.6 and Highlands/MP16.6 until 10:00PM-CT that evening. As a result, multiple Amtrak trains were delayed while operating through the territory on Main Track 3 around the work limits, resulting in freight and passenger train interference and extended transit times.

Train	Delay	Comment
5(17)	23"	
3(17)	39"	
6(15)	50"	

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train 710(17) West of Merced, CA - Trespasser Incident

17OCT26: At 11:17A-PT, Train 710(17), CC/C8308-7 cars-E/C2124, went into emergency after fatally striking a trespasser at MP 1056.2, a mile west of Merced, CA, on the BNSF Stockton Subdivision. There were no reported injuries to the crew or 157 customers on board. The crew held for local law enforcement and EMS to arrive. Upon inspecting the equipment, the crew found no noticeable damage and head end power(HEP) remained up and active. An Amtrak Road Foreman arrive on scene by 11:24A-PT to assist. Once the train was released from the scene, the crew advanced Train 710(17) into Merced before taking relief, arriving at 12:15P-PT. The coroner arrived on scene at 12:18P-PT, where the tracks were shut down again for investigation. Train 713(17) held in Merced until they received permission to operate through the affected area at restricted speed. The tracks were reopened once the investigation was complete at 1:18P-PT for normal operation.

NRC # 1476438

CA # 26-5394

National Response Center Number: 1476438

Train	Delay	Comment
710(17)	1'00"	
713(17)	29"	

Train 59(16) North of Hazlehurst, MS - Freight Train Interference

17OCT26: Train 59(16) held 9 miles north of Hazlehurst, MS (MP762.5), on the CNRR McComb Subdivision, at Crystal Springs (MP753.5) meeting CN 3257.

Train	Delay	Comment
59(16)	32"	

Train 702(17) North of Lodi, CA - Third Party Contractor Cab Car Failure

17OCT26: Train 702(17), CC/90218-5 cars-E/C2012, was delayed starting at MP 64.1, 7 miles north of Lodi, CA, on the UPRR Fresno Subdivision due to PTC issues on CC/90218 from speedometer causing PTC to disengage. The crew contacted the UPRR and CNOC PTC desk to troubleshoot. The crew was unable to resolve the issue therefore PTC was disengaged. Train 702(17) was further delayed operating at reduced speed from PTC being disengaged. The crew tried to reinitialize multiple time and PTC remained intermittent from Lodi, CA to Bakersfield, CA.

Train	Delay	Comment
702(17)	1'26"	LOD-COC
717(17)	36"	late turn 702(17)

27-FOI-00056 000000089937 "UNCLASSIFIED" 10/19/2026

Train 711(17) West of Wasco, CA - M of W Work

17OCT26: Train 711(17) was delayed starting at West Wasco/MP 912.3, 1 miles west of Wasco, CA station, on the BNSF Bakersfield Subdivision due to a broken rail between Elmo/MP 918.3 and Wasco. The crew held at West Wasco for BN7967 to be walked through the affected area. Once freight was through and route was cleared, Train 711(17) was able to proceed operating at restricted speed through the area. Multiple other trains were affected operating through the area. Train 715(17) was delayed holding at Wasco for maintenance of way crews to repair the broken rail.

Trains 711(17) and 713(17) were terminated in Emeryville, CA with customers accommodated onto bus for travel to Oakland Jack London station.

Train	Delay	Comment
711(17)	1'07"	
701(17)	22"	
713(17)	22"	
715(17)	45"	
711(17)	Term EMY	
713(11)	Term EMY	

Train 517(17) South of Vancouver, BC - Freight Train Interference

17OCT26: Train 517(17) was delayed starting at MP 155.4, 1 miles south of Vancouver, BC, on the CNRR New Westminster Subdivision due to freight interference. The crew held at MP 155.4 for the crew on CN3362 to put their train away into yard. Once freight crew finished work and cleared route, Train 517(17) was able to proceed south. The crew was further delayed at Spruce/ MP 144.5 for CP3420 to clear.

Train	Delay	Comment
517(17)	53"	CN3362
517(17)	18"	CP3420

Train 58(16) South of Champaign-Urbana, IL - Passenger Train Interference

17OCT26: Train 58(16) was held 9.2 miles south of Champaign, IL (MP127.9) on the CNRR Champaign Subdivision while meeting Train 391(17) at Tolono (MP137.1). Train 390(17) was also delayed while holding behind Train 58(16) to meet Train 391(17) and complete a crew swap.

Train	Delay	Comment
58(16)	44"	
390(17)	40"	

Train 5(16) Denver, CO - Engine Failure

17OCT26: Train 5(16), E/38-E/126-E/163-E/81-9 Cars, was delayed at Denver, CO (MP0.0), on the BNSF Front Range Subdivision due to E/38 and E/163 being noncompliant as a result of bad order air compressors. As a result, the locomotives were flat switched prior to departure. Once the switching was completed, Train 5(16) was able to proceed west.

Train	Delay	Comment
5(16)	1'53"	

27-FOI-00056 09000008937 UNCLASSIFIED 10/19/2026

Train 22(16) South of Little Rock, AR - Freight Train Interference

17OCT26: Train 22(16) was delayed 18.5 miles south of Little Rock, AR (MP345.7) on the UPRR Little Rock Subdivision at Bauxite Jct (MP364.2) due to freight interference. High/wide freight train UP 8161 was operating at a reduced speed ahead on Main Track 2, while UP 8168 was stopped behind it with an EOT issue. After UP 8161 cleared the main line and UP 8168 received its EOT, Train 22(16) was required to follow UP 8168 into Little Rock, resulting in additional delay.

Train	Delay	Comment
22(16)	1'44"	

Train 19(16) South of Atlanta, GA - Freight Train Interference

17OCT26: Train 19(16) was delayed south of Atlanta, GA (MP633.3) on the NSRR Atlanta North Subdivision due to freight interference on the main line. To avoid the obstruction, the train routed through Inman Yard (MP148.0). Once clear of the yard limits, the train resumed operation at track speed.

Train	Delay	Comment
19(16)	32"	

Train 2/422(16) East of Maricopa, AZ - Engine Failure

17OCT26: Train 2/422(16), E/316-E/48-9 Cars, stopped 25.7 miles east of Maricopa, AZ (MP897.7), on the UPRR Gila Subdivision at MP923.4 due to main reservoir issues. Upon inspection, it was determined that a main reservoir air hose had separated between sleeper cars 39036 and 32094. Head end power was intermittent while the crew worked between the cars to restore the connection. Once the air hose was secured and main reservoir air was restored, Train 2/422(16) resumed its eastward movement.

Train	Delay	Comment
2/422(16)	33"	

Train 58(16) North of Centralia, IL - Broken Rail

17OCT26: Train 58(16) was held 17.4 miles north of Centralia, IL (MP252.3), on the CNRR Champaign Subdivision at Tonti (MP238.0) due to an impassable broken rail ahead at MP230.54. Maintenance of Way personnel responded and installed a temporary bar across the defect. Once the track was released for movement, Train 58(16) resumed northward operation. Service recovery measures were enacted and included snack packs, bottled water, coffee, and tea for customers. Breakfast service was also extended for First Class customers.

Train 390(17) was also delayed during this time holding at the Centralia, IL station for the defect to be barred before being released to continue north.

Train	Delay	Comment
58(16)	1'09"	
390(17)	12"	

27-FOI-00056 000000008937 "UNCLASSIFIED" 10/19/2026

Train 7/27(15) West of Sandpoint, ID - Freight Train Interference

17OCT26: Train 7/27(15) held 0.5 miles west of Sandpoint, ID (MP3.1), on the BNSF Kootenai River Subdivision, at CP Jones (MP3.6) meeting BNSF 5775 and BNSF 6848. Additional delay was incurred following BNSF 6359 from Reasor (MP14.3) to Silver (MP34.9).

Train 8/28(16) held 42.5 miles west of Sandpoint, ID (MP3.1), on the BNSF Spokane Subdivision, at East Hauser (MP45.6) meeting BNSF 6359, BNSF 8142 and Train 7/27(15).

Train	Delay	Comment
7/27(15)	41"	Meet BN5775 and BN6848
8/28(16)	29"	Meet BN6359 & BN8142
7(15)	25"	Follow BN6359
8/28(16)	03"	Meet 7/27(15)

Train 49/449(16) West of Erie, PA - Freight Train Interference

17OCT26: Train 49/449(16) was delayed beginning 41.2 miles west of Erie, PA (MP86.9) on the CSX Erie West Subdivision while following UKCSX from MP128.1 to MP148. All rail traffic was slow moving through the area due to a malfunction of the automatic road crossing protection at Maple St (MP147.5), which required trains to stop and flag through the crossing.

Train	Delay	Comment
49/449(16)	06"	Automatic Crossing Protection
49/449(16)	33"	Follow

Train 319(17) East of Warrensburg, MO - Engine Failure

17OCT26: Train 319(17), with engine IDTX4606, 7 cars, and 119 customers onboard, stopped at mile post 208.6, 10 miles east of Warrensburg, MO/MP218.5, on the UP Sedalia subdivision due to the failure of engine IDTX4606. The crew reported repeating engine temperature faults. A UP freight was sourced out of Sedalia to take the equipment to Warrensburg. Train 319(17) terminated at Warrensburg. Two buses were sourced to Warrensburg to take the customers to their destinations west. The UP freight then brought the 319(17) deadhead equipment to Kansas City, MO.

In order to protect train 318(18), the lead engine 39 off train 4(16) was cut off in Kansas City. BNSF freight 7063 was sourced out of Argentine to meet 4(16) at Kansas City and couple up at the head of the equipment.

WBS#: B.TR.100150.7281

Train	Delay	Comment
319(17)	Terminated	WAR

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

27-FOI-00056 00000008987 UNCLASSIFIED 10/19/2026

17OCT26: Pacific Surfliner service experienced delays due to high-tide conditions affecting the NCTD San Diego Subdivision starting at Don/MP 216.38, 12 miles east of San Clemente Pier, to Serra/MP 199.9, 5 miles west. The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. Single-track operations between MP 216.8 and MP 199.9 contributed to additional train meets and cascading delays throughout the corridor.

Due to late Pacific Surfliner operations, the following additional service adjustments were implemented:

-Train 786(17) was terminated at Los Angeles, CA, with customers accommodated on the next available services, including Trains 588(17) and 790(17).
-Train 593(17) was canceled, with customers accommodated on Train 595(17).

Train	Delay	Comment
573(17)	1'01"	
774(17)	1'03"	
777(17)	1'38"	
579(17)	59"	
581(17)	1'14"	late turn 770(17)
581(17)	2'07"	
580(17)	1'05"	
785(17)	1'34"	
584(17)	1'59"	
593(17)	Canceled	
782(17)	2'25"	
786(17)	Term LAX	
790(17)	21"	late turn 785(17)
790(17)	54"	
588(17)	1'19"	late turn 581(17)
588(17)	1'52"	
587(17)	37"	late turn 774(17)
587(17)	2'32"	
595(17)	1'37"	late turn 782(17)
595(17)	47"	
794(17)	18"	

UPRR Santa Barbara Subdivision North of Goleta, CA- Track and Time Authority

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

16OCT26: The UPRR placed general orders in effect beginning October 16th at 7:00A-PT instituting track and time authority on approximately 61 miles of territory on the Santa Barbara Subdivision between CO295, 4 miles north of Lompoc-Surf Station, and CO356, 2 miles north of Goleta, CA. Multiple trains were delayed operating through the affected area due to signal issues where crews operated at restricted speed and stopped to flag crossings.

17OCT26: In order to minimize customer delays due to this, the following Service Adjustments were implemented:

Train 761(17) and 765(17) were originated at Los Angeles, CA, no alternate transportation provided.
Trains 757/ 765/ 777(17-20) Terminated Goleta, CA with alternate bus transportation provided to San Luis Obispo, CA.
Trains 774/ 786/ 794(17-20) Originated Goleta, CA with alternate bus transportation provided from San Luis Obispo, CA.
Three busses were secured to operate each route, and did not make the Lompoc-Surf, CA station stop.

WBS#: B.TR.100150.7278

Train	Delay	Comment
774(16)	1'39"	
757(16)	1'34"	
786(16)	1'35"	ITD SLO- Turn of 757(16)
786(16)	1'35"	ITD SLO- Equip off 757
765(16)	1'22"	
794(16)	38"	ITD SLO- Equip off 765
794(16)	2'08"	
14(16)	2'21"	
786(16)	2'57"	
11(15)	1'23"	
14(17)	1'13"	
11(16)	1'51"	

UPRR Santa Barbara Subdivision North of Moorpark, CA - Signal Issues

27-FOI-00056 0000000008937 "UNCLASSIFIED" 10/19/2026

16OCT26: At 8:30A-PT, the UPRR reported signal issues starting at MP 422.59, 5 miles north of Moorpark, CA, through MP 378, a half mile north of Carpinteria, CA on the Santa Barbara Subdivision. Multiple trains were delayed as crew stopped to flag through crossings and operated at restricted speed through the affected area. Due to the length of delays, additional delays were incurred holding while trains operated through the area. UPRR personnel worked throughout the day to resolve issues.

17OCT26: Signal issues between Seacliff/CO385, MP 385.3, and South Santa Barbara/CO369, MP 368.6, continued delaying multiple trains as they operated at restricted speed and flagged crossings through affected area. Trains were held while while crews worked through the affected area.

Train	Delay	Comment
757(16)	1'27"	
770(16)	49"	
761(16)	2'13"	
774(16)	1'43"	
782(16)	20"	ITD GTA- Turn of 761(16)
765(16)	1'07"	
790(16)	1'13"	
786(16)	1'04"	
782(16)	48"	
794(16)	31"	
785(16)	53"	
757(17)	1'04"	
761(17)	1'52"	
774(17)	53"	ITD GTA- Turn of 757(17)
774(17)	51"	
770(17)	1'10"	
14(17)	1'20"	
782(17)	1'27"	
786(17)	46"	
790(17)	38"	
794(17)	22"	
765(17)	47"	
777(17)	22"	
769(17)	26"	
785(17)	21"	
11(16)	19"	

BNSF Track Work South of Oklahoma City, OK - Heartland Flyer Service TWA 27-010

18OCT26: BNSF will perform bridge replacement and slow order removal work on the Red Rock Subdivision south of Oklahoma City, OK/MP384.0 between MP380.771 and MP387.384. The curfew will begin 0400am Sunday October 18th through 0200am Monday October 19th. To accommodate this infrastructure work, Amtrak's Heartland Flyer Service will be adjusted as follows:

· Train 821(18) canceled entirely, with Bus 3821 as alternate transportation between Oklahoma City, OK and Fort Worth, TX.
· Train 822(18), canceled entirely, with Bus 3822 as alternate transportation between Fort Worth, TX and Oklahoma City, OK.

WBS#: B.TR.100150.7234

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

29SEP26: Train 821(29) was delayed beginning the 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting to delays to the Heartland Flyer Service operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	
821(13)	22"	
822(13)	36"	
821(14)	35"	
822(14)	17"	
821(15)	26"	
821(16)	41"	
822(15)	34"	
822(16)	19"	
821(17)	24"	

Maintenance of Way Highlights

27-FOF-00056 000000098937 "UNCLASSIFIED" 10/19/2026

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
319(17)	SED	UP1100/1369	ID4606 multiple issues	KCY	10/18/26
4(16)	KCY	BN7063	Cut leader for 318(18)		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
656 (17)	HAR	656 WILL OPERATE SHORT A COACH AND CAB CAR. INV HAS BEEN ADJUSTED WITH OVERCAPACITY CONDITIONS. PLS REACCOMODATE AFFECTED PAX.	over cap phl-nyp -74 / fare protect	74	82597 9632
562 (17)	LAX	Operating with 90215 in consist unable to accommodate passenger with BV reservations. Please reaccommodate any passenger impacted by this. Inventory has been adjusted to reflect the change.	NO BV	3	90215
580 (17)	LAX	Operating with 90215 in consist unable to accommodate passenger with BV reservations. Please reaccommodate any passenger impacted by this. Inventory has been adjusted to reflect the change.	NO BV	1	90215
573 (17)	SAN	Operating with 90215 in consist unable to accommodate passenger with BV reservations. Please reaccommodate any passenger impacted by this. Inventory has been adjusted to reflect the change.	NO BV	2	90215
591 (17)	SAN	Operating with 90215 in consist unable to accommodate passenger with BV reservations. Please reaccommodate any passenger impacted by this. Inventory has been adjusted to reflect the change.	NO BV	2	90215

Reverse Consists

Train Number	Station	Reason
163 (17)	BOS	Consist reversed | Business class seat orientation may have changed At Front
150 (17)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
99 (17)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1094 (17)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
1095 (17)	ALX	Consist reversed | Business class seat orientation may have changed | At Rear

27-FOI-00056 00000008937 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason
1094 (18)	NFK	Consist reversed | Business class seat orientation may have changed | At Front