



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, November 09, 2025

Rules: 0-3



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-00103Initial Terminal Performance By Division

Scheduled Departure Date: 11/08/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/08/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	263	32	87.8%	2,330	293	87.4%	11,403	1,343	88.2%
Central Division	85.5%	67	3	95.5%	536	35	93.5%	2,572	238	90.7%
Northeast Division	80.0%	74	9	87.8%	714	106	85.2%	3,558	474	86.7%
Southeast Division	72.5%	58	8	86.2%	540	72	86.7%	2,675	279	89.6%
Southwest Division	77.0%	64	12	81.3%	540	80	85.2%	2,598	352	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00103 00000005196 UNCLASSIFIED Endpoint Arrival Dates through 11/8/25 11/14/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	99,614	25,930	74%	804,129	141,436	82%	3,901,626	725,436	81%
Northeast Corridor	81%	42,857	13,180	69%	360,962	61,928	83%	1,763,907	280,557	84%
Acela	83%	6,012	2,534	58%	75,428	13,546	82%	370,577	61,729	83%
Northeast Regional	79%	36,845	10,646	71%	285,534	48,382	83%	1,393,330	218,828	84%
Richmond / Newport News / Norfolk	77%	10,564	3,970	62%	84,678	18,100	79%	422,365	78,990	81%
Springfield Shuttles	89%	434	68	84%	5,679	939	83%	22,133	2,292	90%
Roanoke	79%	3,185	725	77%	22,701	3,667	84%	105,893	16,744	84%
On Spine Northeast Regional	80%	22,662	5,883	74%	172,476	25,676	85%	842,939	120,802	86%
State Supported	80%	43,634	7,503	83%	348,220	52,895	85%	1,663,528	290,294	83%
Borealis	60%	555	0	100%	4,661	362	92%	23,623	5,984	75%
Capitol Corridor	90%	2,995	898	70%	31,214	3,598	88%	130,609	11,732	91%
Carolinian	60%	1,228	557	55%	9,738	2,120	78%	48,607	14,669	70%
Cascades	63%	2,767	340	88%	17,748	3,381	81%	89,996	22,911	75%
Downeaster	82%	1,551	0	100%	11,370	569	95%	56,303	9,703	83%
Empire	78%	4,893	948	81%	39,214	6,344	84%	203,242	38,585	81%
Adirondack	72%	235	0	100%	2,248	243	89%	13,583	4,051	70%
Ethan Allen Express	70%	841	364	57%	4,305	904	79%	23,640	6,100	74%
Maple Leaf	70%	660	0	100%	5,282	1,466	72%	23,655	7,843	67%
New York - Albany	85%	1,917	534	72%	17,015	2,677	84%	89,135	13,087	85%
New York - Niagara Falls	75%	1,240	50	96%	10,364	1,054	90%	53,229	7,504	86%
Gold Runner	73%	2,740	634	77%	18,316	6,733	63%	91,480	30,112	67%
Heartland Flyer	65%	192	105	45%	1,457	706	52%	7,837	5,433	31%
Hiawatha	90%	1,859	8	100%	13,984	743	95%	67,792	7,726	89%
Illinois	78%	2,675	289	89%	19,397	2,625	86%	98,465	20,086	80%
Carl Sandburg / Illinois Zephyr	85%	435	23	95%	3,036	234	92%	15,448	3,312	79%
Illini / Saluki	85%	932	28	97%	7,334	623	92%	37,148	5,508	85%
Lincoln Service	70%	1,308	238	82%	9,027	1,768	80%	45,869	11,266	75%
Keystone	92%	6,150	783	87%	65,700	6,262	90%	317,943	24,557	92%
Lincoln / Missouri	60%	723	277	62%	5,972	2,896	52%	31,017	16,145	48%
Mardi Gras Service	80%	522	0	100%	3,490	187	95%	18,417	2,664	86%
Michigan	69%	1,943	257	87%	15,054	3,563	76%	73,805	15,912	78%
Blue Water	70%	452	0	100%	3,666	610	83%	19,795	4,779	76%
Pere Marquette	85%	157	0	100%	1,851	48	97%	10,027	1,112	89%
Wolverine	65%	1,334	257	81%	9,537	2,905	70%	43,983	10,021	77%
Missouri	80%	380	0	100%	1,899	277	85%	9,183	2,090	77%
Pacific Surfliner	85%	8,895	1,524	83%	61,634	9,846	84%	251,219	30,538	88%
Pennsylvanian	72%	918	0	100%	7,282	34	100%	36,604	3,975	89%
Piedmont	73%	1,422	461	68%	9,480	1,810	81%	53,241	16,439	69%
Vermont	75%	1,226	422	66%	10,610	839	92%	54,145	11,033	80%
Long Distance	56%	13,123	5,247	60%	94,947	26,613	72%	474,191	154,585	67%
Auto Train	57%	704	272	61%	5,567	2,041	63%	24,756	4,903	80%
California Zephyr	50%	927	100	89%	6,416	1,176	82%	36,017	11,360	68%
Cardinal	55%	655	428	35%	2,258	1,083	52%	11,518	6,070	47%
City Of New Orleans	75%	391	66	83%	4,982	897	82%	27,256	5,974	78%
Coast Starlight	60%	1,380	673	51%	9,153	4,297	53%	43,176	14,618	66%
Crescent	70%	894	377	58%	7,419	2,259	70%	36,832	11,683	68%
Empire Builder	55%	1,403	869	38%	7,187	3,159	56%	37,922	12,712	66%
Floridian	40%	1,823	1,130	38%	13,352	4,673	65%	65,324	31,494	52%
Lake Shore Ltd	73%	978	56	94%	7,036	602	91%	35,218	4,028	89%
Palmetto	65%	1,023	64	94%	7,733	103	99%	37,521	5,077	86%
Silver Meteor	45%	1,237	268	78%	8,254	1,860	77%	37,994	9,158	76%
Southwest Chief	40%	786	767	2%	6,255	2,565	59%	32,937	19,690	40%
Sunset Ltd	70%	0	0	-	1,763	229	87%	10,326	2,543	75%
Texas Eagle	50%	922	177	81%	7,572	1,669	78%	37,394	15,275	59%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00100 00000005100 "UNCLASSIFIED" 11/14/2025

Train Index Dates Through November 08, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	38,836	848,314	458	202,970	4,152,701	489

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	1,711	244,633	70	7,895	1,208,734	65
INFRASTRUCTURE PLANNED	130	1,418	244,633	58	7,075	1,208,734	59
FLEET RELIABILITY	90	5,075	848,314	60	28,789	4,152,701	69
TRAIN OPERATIONS	427	30,632	848,314	361	159,211	4,152,701	383

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 11/08/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/08/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	263	32	87.8%	2,330	293	87.4%	11,403	1,343	88.2%
Central Division	85.5%	67	3	95.5%	536	35	93.5%	2,572	238	90.7%
Northeast Division	80.0%	74	9	87.8%	714	106	85.2%	3,558	474	86.7%
Southeast Division	72.5%	58	8	86.2%	540	72	86.7%	2,675	279	89.6%
Southwest Division	77.0%	64	12	81.3%	540	80	85.2%	2,598	352	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/08/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/08/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	263	32	87.8%	2,330	293	87.4%	11,403	1,343	88.2%
Central Division	85.5%	67	3	95.5%	536	35	93.5%	2,572	238	90.7%
CDL	90.0%	2	0	100.0%	16	0	100.0%	78	5	93.6%
CHI	85.0%	27	2	92.6%	218	12	94.5%	1,046	83	92.1%
EUG	86.5%	2	0	100.0%	16	2	87.5%	73	7	90.4%
GRR	98.0%	1	0	100.0%	8	0	100.0%	39	0	100.0%
KCY	84.5%	2	0	100.0%	16	0	100.0%	76	6	92.1%
MKE	86.5%	6	0	100.0%	47	2	95.7%	229	23	90.0%
MSP	94.0%	1	0	100.0%	8	0	100.0%	39	0	100.0%
PDX	78.0%	5	0	100.0%	40	9	77.5%	196	33	83.2%
PNT	91.5%	3	0	100.0%	23	2	91.3%	62	4	93.5%
PTH	93.0%	1	0	100.0%	8	0	100.0%	39	2	94.9%
QCY	87.5%	2	0	100.0%	16	1	93.8%	78	9	88.5%
SEA	80.0%	8	1	87.5%	64	6	90.6%	309	48	84.5%
SPK	92.0%	1	0	100.0%	8	0	100.0%	39	1	97.4%
STL	88.0%	4	0	100.0%	32	1	96.9%	156	9	94.2%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	16	0	100.0%	78	3	96.2%
Northeast Division	80.0%	74	9	87.8%	714	106	85.2%	3,558	474	86.7%
ALB	91.5%	6	0	100.0%	48	3	93.8%	234	8	96.6%
BON	43.5%	5	1	80.0%	37	3	91.9%	178	24	86.5%
BOS	86.5%	14	2	85.7%	142	15	89.4%	697	64	90.8%
BRK	88.0%	5	0	100.0%	34	3	91.2%	161	9	94.4%
BTN	48.0%	1	0	100.0%	8	2	75.0%	39	12	69.2%
DOV	-	-	-	-	3	2	33.3%	3	2	33.3%
GFD	86.0%	1	0	100.0%	13	3	76.9%	75	6	92.0%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	8	1	87.5%	39	6	84.6%
NFL	96.5%	2	0	100.0%	16	0	100.0%	78	4	94.9%
NHV	75.5%	3	3	0.0%	40	17	57.5%	192	42	78.1%
NYP	77.5%	29	3	89.7%	299	51	82.9%	1,509	267	82.3%
SAB	98.0%	1	0	100.0%	8	0	100.0%	39	0	100.0%
SPG	88.0%	5	0	100.0%	50	4	92.0%	216	11	94.9%
TWO	84.0%	1	0	100.0%	8	2	75.0%	38	6	84.2%
WEM	-	-	-	-	-	-	-	14	10	28.6%
Southeast Division	72.5%	58	8	86.2%	540	72	86.7%	2,675	279	89.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	1	80.0%	40	2	95.0%	195	18	90.8%
GRO	-	-	-	-	4	2	50.0%	4	2	50.0%
HAR	62.0%	7	1	85.7%	86	15	82.6%	440	42	90.5%
LOR	69.5%	1	0	100.0%	8	3	62.5%	39	5	87.2%
MIA	87.5%	2	0	100.0%	16	1	93.8%	78	7	91.0%
MOE	94.0%	2	0	100.0%	16	0	100.0%	78	3	96.2%
NFK	86.0%	3	0	100.0%	21	1	95.2%	110	10	90.9%
NOL	92.0%	5	0	100.0%	36	4	88.9%	172	10	94.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 11/08/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 11/08/2025			ITP November 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	263	32	87.8%	2,330	293	87.4%	11,403	1,343	88.2%
Southeast Division	72.5%	58	8	86.2%	540	72	86.7%	2,675	279	89.6%
NPN	96.0%	2	0	100.0%	4	1	75.0%	54	5	90.7%
PGH	92.0%	1	0	100.0%	8	0	100.0%	39	1	97.4%
PHL	45.0%	4	2	50.0%	36	20	44.4%	179	53	70.4%
RGH	97.0%	4	0	100.0%	28	0	100.0%	152	3	98.0%
RNK	85.5%	2	0	100.0%	15	1	93.3%	77	10	87.0%
RVM	86.0%	1	0	100.0%	13	1	92.3%	48	7	85.4%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	8	0	100.0%	39	0	100.0%
SFA	70.5%	1	0	100.0%	8	1	87.5%	39	2	94.9%
WAS	70.0%	17	4	76.5%	193	20	89.6%	928	98	89.4%
Southwest Division	77.0%	64	12	81.3%	540	80	85.2%	2,598	352	86.5%
ARN	60.5%	1	0	100.0%	8	1	87.5%	39	4	89.7%
BFD	75.5%	6	2	66.7%	39	12	69.2%	216	54	75.0%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	8	2	75.0%	41	12	70.7%
FNO	-	-	-	-	5	3	40.0%	6	3	50.0%
FTW	89.5%	1	0	100.0%	8	0	100.0%	38	3	92.1%
GTA	72.5%	3	0	100.0%	24	2	91.7%	111	9	91.9%
LAX	77.5%	9	0	100.0%	75	8	89.3%	352	37	89.5%
OKC	96.0%	1	0	100.0%	8	0	100.0%	39	2	94.9%
OKJ	79.0%	9	4	55.6%	86	23	73.3%	423	94	77.8%
SAC	73.5%	11	2	81.8%	103	10	90.3%	507	60	88.2%
SAN	77.0%	12	2	83.3%	96	10	89.6%	431	37	91.4%
SAS	85.0%	1	0	100.0%	8	0	100.0%	39	3	92.3%
SJC	87.5%	7	1	85.7%	56	5	91.1%	272	22	91.9%
SLO	62.0%	2	1	50.0%	16	4	75.0%	73	11	84.9%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	8	1	87.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	184	8	0	100.0%	39	2	94.9%	8	2	75.0%	39	14	64.1%
4	107	8	0	100.0%	39	2	94.9%	8	3	62.5%	39	25	35.9%
5		8	0	100.0%	38	4	89.5%	8	0	100.0%	37	5	86.5%
6		8	2	75.0%	39	12	69.2%	8	2	75.0%	39	13	66.7%
7		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	4	89.7%
8	98	8	2	75.0%	39	15	61.5%	8	6	25.0%	39	18	53.8%
11		8	1	87.5%	38	7	81.6%	8	1	87.5%	36	5	86.1%
14	31	8	1	87.5%	39	6	84.6%	8	5	37.5%	38	11	71.1%
19		8	2	75.0%	39	6	84.6%	8	2	75.0%	39	11	71.8%
20	34	8	1	87.5%	39	4	89.7%	8	3	62.5%	39	4	89.7%
21		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	7	82.1%
22		8	0	100.0%	39	3	92.3%	8	0	100.0%	39	6	84.6%
23		8	0	100.0%	39	3	92.3%	8	0	100.0%	39	8	79.5%
24		8	1	87.5%	39	1	97.4%	8	0	100.0%	39	5	87.2%
25		8	0	100.0%	39	0	100.0%	8	1	87.5%	39	5	87.2%
26		8	1	87.5%	39	1	97.4%	8	2	75.0%	39	6	84.6%
27		8	2	75.0%	39	3	92.3%	8	0	100.0%	39	6	84.6%
28		8	1	87.5%	39	8	79.5%	8	0	100.0%	39	4	89.7%
40	348	8	1	87.5%	39	5	87.2%	8	1	87.5%	39	10	74.4%
41	44	8	1	87.5%	39	12	69.2%	8	3	62.5%	39	24	38.5%
42		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	5	87.2%
43		8	1	87.5%	39	2	94.9%	8	0	100.0%	39	2	94.9%
48		8	0	100.0%	39	2	94.9%	8	0	100.0%	39	2	94.9%
49		8	2	75.0%	39	6	84.6%	8	0	100.0%	39	1	97.4%
51	61	3	2	33.3%	17	10	41.2%	4	2	50.0%	17	7	58.8%
52	94	8	1	87.5%	39	2	94.9%	8	5	37.5%	39	8	79.5%
53		8	3	62.5%	39	5	87.2%	8	2	75.0%	39	5	87.2%
54	35	3	0	100.0%	11	0	100.0%	3	1	66.7%	11	1	90.9%
57		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
58		8	1	87.5%	38	2	94.7%	8	1	87.5%	37	6	83.8%
59	No OS	8	0	100.0%	37	3	91.9%	8	1	87.5%	37	4	89.2%
63		8	1	87.5%	39	15	61.5%	8	4	50.0%	39	21	46.2%
64		8	2	75.0%	38	6	84.2%	8	1	87.5%	38	9	76.3%
65	35	3	0	100.0%	12	1	91.7%	3	2	33.3%	11	4	63.6%
66	42	8	2	75.0%	39	9	76.9%	8	1	87.5%	39	8	79.5%
68		8	1	87.5%	39	6	84.6%	8	1	87.5%	39	16	59.0%
69		8	2	75.0%	39	4	89.7%	8	0	100.0%	39	5	87.2%
71	32	8	0	100.0%	39	0	100.0%	8	2	75.0%	39	13	66.7%
72		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	7	82.1%
73	17	8	0	100.0%	39	1	97.4%	8	5	37.5%	38	24	36.8%
74		8	0	100.0%	39	3	92.3%	8	4	50.0%	39	14	64.1%
75		8	2	75.0%	39	2	94.9%	8	2	75.0%	39	21	46.2%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		8	0	100.0%	39	3	92.3%	8	2	75.0%	39	23	41.0%
77		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	17	56.4%
78		8	0	100.0%	39	3	92.3%	8	0	100.0%	39	7	82.1%
79	36	8	0	100.0%	39	7	82.1%	8	2	75.0%	39	9	76.9%
80		8	1	87.5%	39	5	87.2%	8	0	100.0%	39	3	92.3%
82		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
87	23	3	1	66.7%	11	2	81.8%	3	2	33.3%	11	2	81.8%
88		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	0	100.0%
89		8	1	87.5%	39	7	82.1%	8	0	100.0%	39	5	87.2%
90		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	4	89.7%
97		8	5	37.5%	39	13	66.7%	8	0	100.0%	39	9	76.9%
98		8	0	100.0%	39	2	94.9%	8	2	75.0%	39	4	89.7%
99	64	3	1	66.7%	11	1	90.9%	3	2	33.3%	10	2	80.0%
101		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
103		3	0	100.0%	11	3	72.7%	3	0	100.0%	11	0	100.0%
106		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
107		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	0	100.0%
118		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	0	100.0%
124		3	1	66.7%	11	3	72.7%	3	0	100.0%	11	2	81.8%
135	38	3	1	66.7%	11	1	90.9%	3	1	66.7%	11	4	63.6%
136	20	5	0	100.0%	28	2	92.9%	6	2	66.7%	29	3	89.7%
140		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	1	90.9%
142		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
143		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
144		2	0	100.0%	6	2	66.7%	2	0	100.0%	6	0	100.0%
146		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	2	81.8%
147		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	1	83.3%
150	84	3	2	33.3%	11	6	45.5%	3	2	33.3%	11	5	54.5%
151	25	8	3	62.5%	39	10	74.4%	7	3	57.1%	38	13	65.8%
152	21	2	0	100.0%	6	0	100.0%	2	1	50.0%	6	2	66.7%
153		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
155		3	1	66.7%	11	1	90.9%	3	1	66.7%	11	1	90.9%
156		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
158		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
159		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
160		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
161	34	3	0	100.0%	11	0	100.0%	3	1	66.7%	11	3	72.7%
162		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	2	81.8%
163	16	2	0	100.0%	6	1	83.3%	2	2	0.0%	6	4	33.3%
164		3	0	100.0%	11	0	100.0%	3	1	66.7%	11	1	90.9%
165		3	0	100.0%	11	1	90.9%	3	1	66.7%	11	1	90.9%
168		2	0	100.0%	6	1	83.3%	2	0	100.0%	6	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
178		5	2	60.0%	28	4	85.7%	6	1	83.3%	29	4	86.2%
179		5	0	100.0%	28	3	89.3%	6	1	83.3%	29	8	72.4%
194		2	0	100.0%	6	1	83.3%	2	1	50.0%	6	1	83.3%
195	120	3	0	100.0%	11	0	100.0%	3	2	33.3%	11	6	45.5%
232		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	4	89.7%
233	17	8	3	62.5%	39	9	76.9%	8	4	50.0%	39	10	74.4%
234		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	0	100.0%
236	32	8	0	100.0%	39	0	100.0%	8	3	62.5%	39	8	79.5%
237		8	1	87.5%	39	7	82.1%	8	1	87.5%	39	4	89.7%
239		7	1	85.7%	38	10	73.7%	7	0	100.0%	38	1	97.4%
240		8	1	87.5%	39	1	97.4%	8	0	100.0%	39	1	97.4%
241		8	3	62.5%	39	10	74.4%	8	1	87.5%	39	9	76.9%
244		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	13	66.7%
280		8	0	100.0%	39	3	92.3%	8	1	87.5%	39	5	87.2%
281		8	2	75.0%	39	7	82.1%	8	1	87.5%	39	3	92.3%
283		8	0	100.0%	39	2	94.9%	8	0	100.0%	39	5	87.2%
284		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	4	89.7%
290		8	2	75.0%	39	12	69.2%	7	1	85.7%	38	11	71.1%
291		8	1	87.5%	39	6	84.6%	8	3	62.5%	39	9	76.9%
300		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	7	82.1%
301		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	5	87.2%
302		8	1	87.5%	39	4	89.7%	7	1	85.7%	38	11	71.1%
305		8	0	100.0%	39	1	97.4%	8	0	100.0%	38	9	76.3%
306		8	0	100.0%	39	1	97.4%	8	1	87.5%	38	6	84.2%
307	31	8	1	87.5%	39	3	92.3%	8	3	62.5%	39	5	87.2%
311		8	0	100.0%	38	2	94.7%	8	1	87.5%	38	9	76.3%
316		8	0	100.0%	38	1	97.4%	8	0	100.0%	38	6	84.2%
318		8	0	100.0%	39	6	84.6%	8	2	75.0%	38	16	57.9%
319	19	8	1	87.5%	39	2	94.9%	8	4	50.0%	39	24	38.5%
330		7	0	100.0%	34	2	94.1%	7	0	100.0%	34	1	97.1%
331		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	4	89.7%
332		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	3	92.3%
334		8	0	100.0%	39	1	97.4%	8	0	100.0%	38	3	92.1%
335		8	0	100.0%	39	6	84.6%	8	0	100.0%	38	7	81.6%
336		8	0	100.0%	39	1	97.4%	8	0	100.0%	39	4	89.7%
337		8	0	100.0%	39	4	89.7%	8	0	100.0%	39	4	89.7%
338		8	0	100.0%	39	11	71.8%	8	1	87.5%	38	10	73.7%
339		8	1	87.5%	39	10	74.4%	8	1	87.5%	39	8	79.5%
341		8	1	87.5%	39	4	89.7%	8	1	87.5%	39	5	87.2%
342		8	1	87.5%	39	4	89.7%	8	1	87.5%	38	4	89.5%
343		1	0	100.0%	6	0	100.0%	2	0	100.0%	6	2	66.7%
350		8	1	87.5%	21	2	90.5%	8	3	62.5%	21	6	71.4%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
351		8	1	87.5%	39	2	94.9%	8	5	37.5%	39	14	64.1%
352		8	1	87.5%	39	3	92.3%	8	1	87.5%	38	5	86.8%
353		7	0	100.0%	19	2	89.5%	7	1	85.7%	19	3	84.2%
354	91	8	0	100.0%	39	1	97.4%	8	1	87.5%	39	8	79.5%
355		8	1	87.5%	39	5	87.2%	8	3	62.5%	39	7	82.1%
364		8	0	100.0%	39	2	94.9%	8	0	100.0%	39	6	84.6%
365		8	0	100.0%	39	2	94.9%	8	2	75.0%	39	11	71.8%
370	27	8	0	100.0%	39	1	97.4%	8	1	87.5%	39	6	84.6%
371		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	2	94.9%
380		8	1	87.5%	39	8	79.5%	8	0	100.0%	39	7	82.1%
381		8	1	87.5%	39	1	97.4%	8	0	100.0%	39	5	87.2%
382		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	6	84.6%
383		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	12	69.2%
390		8	0	100.0%	39	3	92.3%	8	2	75.0%	39	7	82.1%
391		8	0	100.0%	39	0	100.0%	8	1	87.5%	38	6	84.2%
392		8	0	100.0%	39	2	94.9%	8	0	100.0%	38	4	89.5%
393	23	8	1	87.5%	39	4	89.7%	8	1	87.5%	38	8	78.9%
400		3	1	66.7%	11	1	90.9%	2	0	100.0%	10	0	100.0%
450	68	3	2	33.3%	11	2	81.8%	3	2	33.3%	11	3	72.7%
461		3	1	66.7%	11	1	90.9%	3	0	100.0%	11	1	90.9%
463		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
464		3	1	66.7%	11	1	90.9%	3	1	66.7%	11	3	72.7%
467		2	1	50.0%	6	1	83.3%	1	0	100.0%	5	0	100.0%
488	Cncld	3	3	0.0%	11	3	72.7%	1	1	0.0%	9	1	88.9%
500		8	2	75.0%	39	4	89.7%	7	0	100.0%	38	4	89.5%
502		8	1	87.5%	39	6	84.6%	7	2	71.4%	38	11	71.1%
503		8	1	87.5%	36	7	80.6%	8	3	62.5%	35	11	68.6%
504		8	1	87.5%	39	2	94.9%	8	4	50.0%	39	15	61.5%
505		8	1	87.5%	39	7	82.1%	7	0	100.0%	37	7	81.1%
506		8	3	62.5%	38	7	81.6%	8	2	75.0%	37	7	81.1%
507		8	0	100.0%	39	3	92.3%	8	1	87.5%	39	16	59.0%
508		8	1	87.5%	37	6	83.8%	8	0	100.0%	37	5	86.5%
509		8	0	100.0%	39	1	97.4%	8	1	87.5%	39	8	79.5%
511	29	8	1	87.5%	39	3	92.3%	8	1	87.5%	39	7	82.1%
516		8	0	100.0%	39	4	89.7%	8	2	75.0%	39	18	53.8%
517	17	8	0	100.0%	39	1	97.4%	8	4	50.0%	38	16	57.9%
518		8	2	75.0%	39	8	79.5%	8	3	62.5%	39	25	35.9%
519		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	7	82.1%
562		8	2	75.0%	37	5	86.5%	8	1	87.5%	36	4	88.9%
564		8	0	100.0%	37	2	94.6%	8	0	100.0%	36	5	86.1%
566		8	0	100.0%	37	2	94.6%	7	0	100.0%	36	2	94.4%
572		8	1	87.5%	36	4	88.9%	8	4	50.0%	36	9	75.0%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		8	1	87.5%	37	7	81.1%	8	1	87.5%	36	5	86.1%
577		8	1	87.5%	35	1	97.1%	7	0	100.0%	34	1	97.1%
580		8	0	100.0%	37	2	94.6%	8	0	100.0%	37	3	91.9%
581		8	1	87.5%	37	1	97.3%	8	2	75.0%	37	8	78.4%
582		8	1	87.5%	37	4	89.2%	8	1	87.5%	37	3	91.9%
586		8	3	62.5%	37	8	78.4%	8	2	75.0%	35	4	88.6%
587		8	1	87.5%	37	3	91.9%	8	0	100.0%	35	3	91.4%
591		8	0	100.0%	37	1	97.3%	8	0	100.0%	37	2	94.6%
593		8	1	87.5%	37	5	86.5%	8	0	100.0%	34	3	91.2%
595		8	2	75.0%	36	6	83.3%	8	0	100.0%	35	6	82.9%
611	23	2	2	0.0%	6	3	50.0%	2	1	50.0%	6	1	83.3%
624	84	5	2	60.0%	28	5	82.1%	6	3	50.0%	29	8	72.4%
660	20	3	0	100.0%	11	0	100.0%	3	2	33.3%	11	5	54.5%
661		3	1	66.7%	11	2	81.8%	3	0	100.0%	11	2	81.8%
662		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
663		3	1	66.7%	11	2	81.8%	3	1	66.7%	11	1	90.9%
664		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	1	90.9%
665		3	0	100.0%	11	0	100.0%	3	1	66.7%	11	3	72.7%
666		3	1	66.7%	11	4	63.6%	3	0	100.0%	11	0	100.0%
667		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	3	72.7%
669		3	0	100.0%	11	0	100.0%	3	2	33.3%	11	3	72.7%
670		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
671		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
672		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
674		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	0	100.0%
689		4	1	75.0%	23	4	82.6%	5	1	80.0%	23	3	87.0%
690		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
691		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	4	63.6%
692	14	3	0	100.0%	11	0	100.0%	3	1	66.7%	11	5	54.5%
693		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	4	63.6%
694		3	1	66.7%	11	2	81.8%	3	0	100.0%	11	1	90.9%
695		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	4	63.6%
696		3	0	100.0%	11	1	90.9%	3	1	66.7%	11	3	72.7%
697		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	3	72.7%
698		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	2	81.8%
702		8	2	75.0%	39	9	76.9%	8	3	62.5%	38	12	68.4%
703		8	3	62.5%	39	10	74.4%	8	1	87.5%	39	8	79.5%
710	16	8	3	62.5%	39	15	61.5%	8	4	50.0%	39	17	56.4%
711		7	0	100.0%	36	2	94.4%	6	2	66.7%	34	4	88.2%
712		8	3	62.5%	39	10	74.4%	8	2	75.0%	39	14	64.1%
713	34	8	2	75.0%	39	7	82.1%	7	4	42.9%	36	17	52.8%
714		7	4	42.9%	33	10	69.7%	4	1	75.0%	28	8	71.4%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

25-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
715		8	3	62.5%	39	15	61.5%	8	4	50.0%	37	19	48.6%
716		8	7	12.5%	39	18	53.8%	8	5	37.5%	38	12	68.4%
717		5	3	40.0%	30	6	80.0%	4	0	100.0%	26	5	80.8%
718		8	2	75.0%	39	13	66.7%	8	2	75.0%	39	12	69.2%
719		8	4	50.0%	39	17	56.4%	8	1	87.5%	38	11	71.1%
720		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	1	90.9%
723	19	3	0	100.0%	11	2	81.8%	3	1	66.7%	11	1	90.9%
724		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
727	52	3	0	100.0%	11	2	81.8%	3	2	33.3%	11	3	72.7%
728	22	3	0	100.0%	11	2	81.8%	3	1	66.7%	11	1	90.9%
729	38	3	1	66.7%	11	1	90.9%	3	2	33.3%	11	2	81.8%
732	11	3	1	66.7%	11	1	90.9%	3	1	66.7%	11	1	90.9%
733		3	0	100.0%	11	1	90.9%	3	0	100.0%	8	1	87.5%
734		3	2	33.3%	11	5	54.5%	3	1	66.7%	11	2	81.8%
736	15	3	1	66.7%	11	1	90.9%	3	1	66.7%	11	2	81.8%
737		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	0	100.0%
738		3	1	66.7%	11	3	72.7%	3	0	100.0%	10	0	100.0%
741	53	3	2	33.3%	11	3	72.7%	3	1	66.7%	11	2	81.8%
742		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	3	72.7%
743		3	2	33.3%	11	2	81.8%	3	0	100.0%	11	1	90.9%
744		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	3	72.7%
745		3	0	100.0%	11	2	81.8%	3	0	100.0%	11	0	100.0%
746		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	1	90.9%
747		3	1	66.7%	11	2	81.8%	3	0	100.0%	11	1	90.9%
748		3	1	66.7%	10	3	70.0%	3	0	100.0%	10	0	100.0%
749		3	0	100.0%	11	2	81.8%	3	0	100.0%	10	2	80.0%
751		3	0	100.0%	11	4	63.6%	3	0	100.0%	11	2	81.8%
761		8	1	87.5%	37	3	91.9%	8	2	75.0%	37	6	83.8%
765		8	1	87.5%	37	6	83.8%	8	2	75.0%	37	8	78.4%
769	52	8	1	87.5%	37	3	91.9%	8	2	75.0%	37	7	81.1%
770		8	0	100.0%	37	3	91.9%	8	2	75.0%	37	4	89.2%
774		8	2	75.0%	37	6	83.8%	8	2	75.0%	36	5	86.1%
779	18	8	0	100.0%	37	2	94.6%	8	1	87.5%	36	2	94.4%
784	31	8	1	87.5%	37	4	89.2%	8	4	50.0%	36	15	58.3%
785		8	0	100.0%	37	0	100.0%	8	0	100.0%	37	4	89.2%
790		8	1	87.5%	37	2	94.6%	8	1	87.5%	37	3	91.9%
794		8	2	75.0%	37	5	86.5%	8	2	75.0%	37	9	75.7%
821	16	8	0	100.0%	39	2	94.9%	8	5	37.5%	39	27	30.8%
822		8	0	100.0%	39	3	92.3%	8	4	50.0%	39	30	23.1%
1333		8	0	100.0%	39	2	94.9%	8	1	87.5%	39	17	56.4%
1340		8	0	100.0%	39	0	100.0%	8	0	100.0%	39	8	79.5%
2174		1	0	100.0%	6	1	83.3%	2	0	100.0%	6	1	83.3%

Amtrak On Time Performance

Trains Arriving Through: 11/8/2025

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2203		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
2205		3	2	33.3%	11	2	81.8%	3	0	100.0%	11	0	100.0%
2216		2	0	100.0%	6	0	100.0%	2	0	100.0%	6	0	100.0%
2218		2	1	50.0%	6	1	83.3%	2	0	100.0%	6	0	100.0%
2248		3	1	66.7%	11	2	81.8%	3	0	100.0%	11	1	90.9%
2249	33	2	0	100.0%	6	0	100.0%	2	1	50.0%	6	1	83.3%
2250	103	3	0	100.0%	11	1	90.9%	3	2	33.3%	11	4	63.6%
2251	32	2	0	100.0%	6	0	100.0%	2	1	50.0%	6	2	66.7%
2252		3	0	100.0%	11	1	90.9%	3	0	100.0%	11	1	90.9%
2253	26	3	0	100.0%	11	1	90.9%	3	1	66.7%	11	4	63.6%
2254		3	0	100.0%	11	0	100.0%	3	0	100.0%	11	0	100.0%
2255	25	3	0	100.0%	11	2	81.8%	3	2	33.3%	11	4	63.6%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Region: ALL

Service: ALL

Arriving On: 11/8/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2249	WAS	33	WTR	22	WTR	13	XGX-NHV	AM	Wet / slippery rail, Milepost, xgx, nhv, 80 MPH S/R/ EXCESSIVE WHEELSLIP PER ENGR
2250	BOS	103	ENG	52	ENG	52	NYP-NYP	AM	Undesired emergency application, 2140, MULTIPLE FAULTS ON PC2140
2251	WAS	32	WTR	40	WTR	20	XGX-NHV	AM	Wet / slippery rail, Milepost, xgx, nhv, Excessive wheelslip 80 MPH S/R
2253	WAS	26	WTR	13	WTR	13	XGX-NHV	AM	Wet / slippery rail, Milepost, XGX, NHV, Wheelslip a/c track outage X74 -NHV
2255	WAS	25	PTI	16	PTI	14	XGX-NHV	AM	Meet, 164, Milepost w/Letters, XGX, NHV, AM2255 was held at Brandford for AM164
65	NPN	35	PTI	58	PTI	56	RVM-WBG	CS	Meet p194, Milepost, 76.0, 76.0
66	BOS	42	WTR	19	ENG	17	WLY-WLY	AM	Traction motor, 348, had to make a reverse move in order to regain traction to head east stop to check Eng.
87	NFK	23	CTI	19	CTI	11	BAL-BWI	AM	Follow, MARC, 495, Milepost, 95.7, 106.3
99	NPN	64	WTR	39	DSR	19	RVM-WBG	CS	Per bulletin Milepost, 66.0, 65.0, 10, Main, Milepost, 41.6, 41.4, 25, Main, Milepost, 39.8, 39.3, 25, Main, Milepost, 37.9, 37.3, 25, Main
135	WAS	38	HLD	20	ITI	12	BOS-BOS	AM	Service, turn, or wye train, 150, Late turn
136	SPG	20	OTH	18	OTH	10	WNL-SPG	AM	Lost time - N.A.R., PURE RUN TIME DELAY. MADE UP 1 MIN.
150	BOS	84	WTR	73	WTR	61	NHV-NHV	AM	Wet / slippery rail, Milepost, nhv, nhv, Unable to clear Mill River a/c excessive wheelslip, make a reverse move west back to division post and then continue east on trk 4
151	RNK	25	FTI	17	FTI	17	LYH-RNK	NS	Follow 19M, Milepost w/Letters, Woodall, Liberty
152	BOS	21	MTI	15	HLD	13	NYP-NYP	AM	Passenger and/or baggage, LATE LOADING
161	WAS	34	WTR	32	WTR	15	PVD-KIN	AM	Wet / slippery rail, Milepost, pvd, kin, excessive wheelslip
163	WAS	16	HLD	15	DSR	8	BRP-STM	MN	Per bulletin As per todays DTOBO section E restricted speed limits on track 2, Control Point, 248, 30, 1, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.6, 30, 2, Control Point, 255, 30, 3
195	RVM	120	WTR	58	WTR	42	OSB-NHV	AM	Wet / slippery rail, Milepost, osb, nhv, excessive wheelslip

Amtrak Endpoint OTP Details

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 11/8/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
450	SPG	68	SVS	50	SVS	50	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard	
488	GFD	Trn Cancelled								
52	LOR	94	ENG	138	ENG	70	XSA-XOU	CS	Air / Brake Drawbar on car carrier disconnected EOT device, 354	
79	CLT	36	ENG	65	ENG	21	PTB-RMT	CS	Loading problem Loading fail when the load drops the engine sands on its own., 150	
611	HAR	23	CAR	13	CAR	13	PHL-PHL	AM	Air / Brake / Wheel, C/82670, met mech for hot bearing alarm on 2nd car	
624	NYP	84	MTI	46	MTI	46	LNC-PAR	AM	Disabled train ahead, Milepost, 55.0, ,, TRAIN 620, E/640 STOPPED AT MP 55 WITH TRACTION ISSUES. UNABLE TO PROCEED. PSGR TRANSFER TO 624	
660	NYP	20	DCS	11	DCS	11	NWK-NYP	AM		
20	NYP	34	FTI	47	WTR	36	HPT-HPT	NS	Trees down Dispatcher Hold on all tracks! Due to tree at 296.2., Milepost, 296.2, 296.2	
692	BON	14	DCS	11	DCS	8	HHL-WOB	MT	Restrictive signal(s) from unknown cause Run down time, Stop, Control Point, clark	
233	ALB	17	ITI	14	ITI	14	NYP-NYP	AM	Service, turn, or wye train, 236	
236	NYP	32	CTI	34	CTI	20	POU-CRT	MN	Meet man, ?, Control Point, 72	
71	CLT	32	TEN	28	TEN	22	CYN-DNC	NS	Onboard HBD alarm Wheel slip.. Unable to make trk speed. Reset locked axel fault on both locomotives and rolling inspecting at W cary, NC1871	
73	CLT	17	HLD	18	PTI	8	RGH-CYN	NS		
54	SAB	35	SVS	45	SVS	45	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Engine swap at NHV	
40	CHI	348	SYS	394	SYS	331	XFI-XBL	CS	PTC problem or failure (cause unknown)	
41	MIA	44	FTI	129	FTI	77	ALC-PGH	NS	36 N broke down ahead of us. Shove back from mp76 back through cpAlliance all on Restricted Speed 36 N, Other, 76	
723	SJC	19	TRS	10	TRS	10	OKJ-OKJ	UP	Vehicle strike Waited at OKJ for clearing from track inspector Tovar., Other, NI912	
727	SJC	52	TRS	29	TRS	29	OKJ-OAC	UP	Vehicle on track ahead Control Point, 66th ave	

Amtrak Endpoint OTP Details

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 11/8/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
728	SAC	22	PTI	12	CTI	11	SJC-SCC	UP	Meet Caltrain, 224, Control Point, Alameda
729	SJC	38	CTI	22	CTI	22	GAC-SCC	UP	Meet Caltrain, caltrain 623, Control Point, coast
732	SAC	11	CTI	11	CTI	11	SJC-SJC	UP	Meet Hold on depot TRK 2 for caltrain618 to come Into station moved depot 2 to MT2 through, caltrainCaltrain, 618, Control Point, alameda
736	ARN	15	PTI	19	PTI	16	FMT-HAY	UP	Meet 741, Control Point, shinn
741	SJC	53	TEN	31	POL	21	RIC-RIC	UP	Right of Way police hold Rail traffic stopped at MP 7.06 Martinez Sub account police foot pursuit on or near the tracks.
51	CHI	61	FTI	112	FTI	60	CRF-LAF	CS	Meet 64107, Control Point, switzer
511	PDX	29	SVS	37	SVS	37	SEA-SEA	BN	Late Yard Release 511(8) not listed as required moves for SEA yard moves; late yard release and spot to depot
517	PDX	17	FTI	19	FTI	13	X8B-BEL	BN	Meet BNSF 155, Control Point, Ferndale
59	NOL	No OS Rpt	FTI	41	FTI	20	KKI-CHM	CC	Follow G888, Milepost, 87.3, 98.3
14	SEA	31	ENG	59	ENG	45	ALY-SLM	UP	Stop and inspect for hot barring Temp 147* Amtrak mechanical 10 miles not to exceed 50 mph 92* at SLM, 158
8	CHI	98	FTI	93	RTE	81	EVR-XEN	BN	Dispatcher hold Multiple cars on the tracks..., Milepost, 1768.78, 1768.78
821	FTW	16	DSR	31	DSR	23	GLE-FTW	BN	Per bulletin Milepost, 410.8, 410.5, 60, m, Milepost, 409.9, 409.5, 60, m, Milepost, 409.1, 409.0, 30, m, Milepost, 401.6, 401.5, 30, m, Milepost, 399.9, 399.8, 40, m, Milepost, 394.1, 393.8, 30, m, Milepost, 393.0, 392.9, 60, m, Milepost, 389.7, 389.5, 40, m, Milepost, 385.5, 385.3, 60, m, Milepost
354	PNT	91	ENG	54	ENG	22	NBU-NBU	AM	Onboard HBD alarm Hot journal alarm. #3 left journal B. Inspected all axles and wheels on engine. Then talked to CNOC and reviewed rules and restrictions., ID4606
370	GRR	27	WTR	31	WTR	31	HOM-XP9	CS	Dispatcher hold, fire ahead Milepost, 151.7, 151.7
769	GTA	52	TRS	64	TRS	60	SAN-SAN	SN	Unticketed or fare evading passenger Other, SAN station
779	SLO	18	PTI	43	PTI	41	VEC-CPN	UP	Meet 11, Siding, seacliff
784	SAN	31	PTI	34	PTI	20	SNC-SNP	SC	Meet 587, Control Point, Serra

Amtrak Endpoint OTP Details

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 11/8/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
710	BFD	16	RTE	17	ITI	10	OKJ-OKJ	UP	Crew problem 719, Assigned engineer involved in traffic accident and unable to report to work. Replacement engineer called asap.	
713	OKJ	34	POL	30	POL	30	RIC-EMY	UP	Right of Way police hold	
3	LAX	184	FTI	205	FTI	78	BAR-VRV	BN	BNSF 7656 dead on hours of service. Follow BNSF 7154 W. BNSF 7656 UP 7154, Control Point, East Oro Grande	
4	CHI	107	FTI	148	FTI	40	KNG-FLG	BN	Follow bnsf unknown, Milepost, 484.1, 473.9, Milepost, 459.4, 420.6	
307	STL	31	FTI	49	FTI	19	DWT-PON	UP	Meet unknown, Siding, odell	
393	CDL	23	FTI	29	FTI	12	DQN-CDL	CC	Meet 8088, Siding, schaefer	
319	KCY	19	DCS	19	DCS	15	XTF-SMT	CC	Restrictive signal(s) from unknown cause Stop, Milepost, 7.7, 8.2	

Amtrak Initial Terminal Details

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/8/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	11/08	5	5	Service, turn, or wye train 71
HAR	666	11/08	2	2	Other electrical failure, E/638, door bypass
PHL	150	11/08	14	14	PTC - Stop Bypass Permission Required, Control Point, PHL, RECIEVED STOP BY-PASS TWICE ATTEMPTING TO COME OUT OF THE YARD
PHL	611	11/08	20	13	Air / Brake / Wheel, C/82670, met mech for hot bearing alarm on 2nd car
PHL	611	11/08	20	8	PTC - Stop Bypass Permission Required, Control Point, ., stop bypass and code needed
WAS	118	11/08	1		
WAS	146	11/08	1		
WAS	2218	11/08	7	7	Service, turn, or wye train, 2249, Late arriving equipment 34" min
WAS	2248	11/08	3	3	HEP, 2036, MISSING SEAL ON PC
BON	1689	11/08	1		
BOS	99	11/08	5	5	Wheelchair, PSGR ASSIST WITH POWER WHEELCHAIR EXTRA SIZE
BOS	135	11/08	12	12	Service, turn, or wye train, 150, Late turn
NHV	450	11/08	50	50	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard
NHV	464	11/08	3	3	Dispatcher hold, Other, NHV, Waited for signal from G Metro North side
NHV	488	11/08	(Trn Cxld)		Lack of equipment
NYP	49	11/08	10	10	Mobility Impaired
NYP	233	11/08	14	14	Service, turn, or wye train, 236
NYP	661	11/08	2	2	Passenger and/or baggage, STILL BOARDING AT DEPARTURE TIME
CHI	41	11/08	3	3	Hold for connecting train 8
CHI	307	11/08	6	6	Person boarded train in Chicago then got off the train. Asked APD to walk the train with dog as a precaution. See something, say something.
SEA	511	11/08	37	37	Late Yard Release 511(8) not listed as required moves for SEA yard moves; late yard release and spot to depot
BFD	703	11/08	5	5	Door C6963, Cab car doors were closed but said they were open
BFD	717	11/08	2	2	Meet 710, Control Point, amtrak lead
OKJ	710	11/08	10	10	Crew problem 719, Assigned engineer involved in traffic accident and unable to report to work. Replacement engineer called asap.
OKJ	716	11/08	2	2	PTC - Initializing PTC (no failure) Due to late release in the yard, we logged into PTC and departed
OKJ	734	11/08	14	14	Right of Way police hold Mp 7.05 Martinez sub

Amtrak Initial Terminal Details

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 11/8/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	738	11/08	1		
SAC	741	11/08	1	1	Group Staggered group of 16 school students boarding just prior to departure time.
SAC	747	11/08	1	1	Loading problem Doors were closed. Engineer said couldn't get load, C2102
SAN	573	11/08	1	1	Door 6411, Door closed no door light had to lock out 5
SAN	769	11/08	60	60	Unticketed or fare evading passenger Other, SAN station
SJC	732	11/08	11	11	Meet Hold on depot TRK 2 for caltrain618 to come Into station moved depot 2 to MT2 through, caltrainCaltrain, 618, Control Point, alameda
SLO	794	11/08	1		

Eastern Region

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	97.2	94.8	165	0
CDOT	95.0	62.5	89.9	92.4	16	6
MARC	95.0	94.4	91.6	90.2	18	1
SEPTA	95.0	87.6	91.9	91.5	97	12
NJT-NED	95.0	90.7	93.2	93.8	194	18
NJT-SED	95.0	95.8	98.9	97.2	24	1

Operating Highlights

Train 52(08) Kingstree, SC - Freight Train Interference

09NOV25: Train 52(08) operating with engines 360 and 364, 45 cars and 165 passengers onboard, was delayed south of Kingstree, SC at MP 338.4 approximately 7 miles south of Kingstree Station after the train went into emergency. The crew walked the train, found lose air hose. After reconnecting, they had to hold for Train 53(08) to pass before proceeding north.

Train	Delay	Comment
52(08)	37"	

Train 52(08) South of Florence, SC - Engine Failure

09NOV25: Train 52(08) operating with engines 360 and 364, 45 cars and 165 passengers onboard, was delayed south of Florence, SC MP 307 on CSX Charleston subdivision due to an undesired emergency application end of train device. The crew walked the train, found a loose hose, reattached and continued north.

Train	Delay	Comment
52(08)	45"	

Train Paoli, PA - Catenary or Wayside Failure

09NOV25: AT 12:15A-ET, Paoli Tower reported that the sub station west of the tower exploded and is on fire. Amtrak Police notified, road foreman and ET were notified. At approximately 102A-ET, the Paoli Tower operator reported that the fire was out, just lingering smoke. The fire department was clearing the area. Emergency plates were put into effect on all tracks. 349A-ET, power was restored and tracks ok'd for scheduled speed and service.

Train 66(08) New Carrollton, MD - Engine Failure

09NOV25: Train 66(08) operating with engine 653, 611/14/2025 and 183 passengers onboard, reported issue with engine 653 as it was passing New Carrollton, MD Station on Amtrak PW subdivision. The engineer reported that the horn was not working requiring them to operate maximum speed of 30 mph. Baltimore mechanical was unable to repair. KP716 was operating in the area and meet Train 66(08) at Edgewood, MD, coupled up to it and proceeded north to Philadelphia, PA at 65 mph where engine 653 was swapped out for engine 603(09) Philadelphia, PA to Boston, MA.

Train	Delay	Comment
66(08)	38"	XNY - BAL
66(08)	16"	BAL
66(008)	12"	WIL - PHL
66(08)	18"	KP716

Train 161(08) South of Aberdeen, MD - Deer Strike

08NOV25: Train 161(08) operating with engine 609 and 10 cars was delayed 17 miles south of Aberdeen, MD on the Amtrak PW line after striking a deer at milepost 92.5. The crew inspected, reported no damage, and took no exceptions.

Train	Delay	Comment
161(08)	07"	

Train 54(08) New Haven, CT - Servicing

08NOV25: Train 54(08) operating with engine 86 and 6 cars was delayed departing New Haven, CT on the Amtrak NHB Line due to a delay in swapping power and taking off the local coach.

Train	Delay	Comment
54(08)	45"	

Train 57(08) Brattleboro, VT - Temporary Speed Restrictions

08NOV25: Train 57(08) operating with engine 125 and 5 cars was delayed departing Brattleboro, VT on the NECR Palmer subdivision due to a damaged rail 8 miles south at milepost 113.0 which needed to be inspected for OK speed and service by NECR track inspector.

Train	Delay	Comment
57(08)	30"	

Train 2250(08) New York, NY - Car Failure

08NOV25: Next Gen Acela 2250(08) operating with power car 2140, 9 cars, and power car 2139 was delayed departing New York, NY due to onboard door alarms that needed to be turned off upon arrival into Penn Station. Amtrak management and mechanical met the train on the platform to reset the alarms and resolve the issue.

Train	Delay	Comment
2250(08)	52"	

NHB Line Slippery Rails - East of New Haven, CT

08NOV25: Eastbound 226-FOI-00303 00000005196 train "UNCLASSIFIED" was affected east of New Haven, CT through the area of Groton interlocking milepost 124.2 through Davisville interlocking milepost 168.0 due to excessive wheel slipping on equipment.

Train	Delay	Comment
143(08)	06"	
2249(08)	13"	
147(08)	11"	
66(07)	17"	
2251(08)	20"	
195(08)	47"	
161(08)	15"	
150(08)	07"	
461(08)	02"	
162(08)	07"	
150(08)	02"	
99(08)	23"	
2253(08)	13"	
87(08)	03"	
2250(08)	11"	
2252	06"	

Train 150(08) East of New Haven, CT - Weather

08NOV25: Train 150(08) operating with engine 623 and 10 cars was delayed 1.4 miles east of New Haven, CT on the Amtrak NHB Line due to wheel slipping at milepost 73.8. Train 150(08) performed a reverse move back approximately 0.7 miles to then proceed east on track 4 to avoid the affected rails.

Train	Delay	Comment
150(08)	1'01"	

Train 155(08) Princeton Junction, NJ - Deer Strike

08NOV25: Train 155(08) operating with engine 602 and 10 cars reportedly struck a deer less than 1 mile east of Princeton Junction, NJ on the Amtrak NYP Line at milepost 46.0. No damage to the equipment or injuries were reported by the crew and no exceptions were taken.

Train	Delay	Comment
155(08)	08"	

Train 450(08) New Haven, CT - Initial Terminal Delay

08NOV25: Train 450(08) was delayed departing New Haven, CT due to lack of available power equipment and needing to pull an engine off inbound train 143(08). Once the engine was added and mechanical inspections were performed, train 450(08) departed New Haven.

Train	Delay	Comment
450(08)	50"	

Train 20(07) High Point, NC - Tree Down

08NOV25: Train 20(07) operating with engines 20, 148, and 8 cars was delayed departing High Point, NC station on the Norfolk Southern Montview District waiting for maintenance of way to clear a tree 3 miles north at milepost 296.0.

Train	Delay	Comment
20(07)	36"	

Train 40(07) South of Hamlet, NC - Wheel Slip

08NOV25: Train 40(07) 26-F01-00103 in 00000005196 engine "UNCLASSIFIED" 371 11/14/2025 11 cars was delayed 21 miles south of Hamlet, SC on the CSX Hamlet subdivision at milepost 275.2 after entering emergency from excessive wheel slip due to slick rails. The crew worked with CNOC mechanical and Siemens to resolve the suppression issue on the engine and cut out traction motor 4 on lead unit 335 to disable monitoring on the axle.

Train	Delay	Comment
40(07)	55"	

26 JUL 03 10:00 AM 10005790 UNCLASSIFIED 11/14/02
Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-28Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

23OCT25: Train 448(29NOV) and Train 449(01DEC) will be the first trains operating normal when service resumes on 30NOV.

WBS#: B.TR.100150.5746

Eastern Region

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 69(08) Passenger Removal at Rouses Point, New York – Customs

08OCT25, Passenger on PNR B766DB, traveling from New York to Montreal, Quebec was removed from the train by Canadian Customs. Amtrak Police notified.

Delay: 69(08) 15"

Operating Highlights

Train 41(08) East of Sandusky, OH - NS System Maintenance

09NOV25: Train 41(08) was delayed at mile post 241.1 0.5 miles east of Sandusky, OH/MP241.5 on the NS Cleveland-Toledo subdivision due to NS scheduled system maintenance running over the allotted time. NS was unable to remotely control switch operation. Once the system was restored and traffic resumed, train 41(08) continued east. Train 48(08) was also delayed at mile post 398.2.

Train	Delay	Comment
41(08)	46"	
48(08)	1'06"	Stopped behind NS 16N

Train 370(08) West of Grand Rapids, MI - Trackside Fire

09NOV25: Train 370(08) was delayed at Pleasant St/MP151.7 950 feet from Grand Rapids, MI/MP0.0 on the CSX Grand Rapids Terminal subdivision due to a trackside fire. Local authorities placed a hold on all rail traffic while the fire was contained. Once the route was clear, train 370(08) continued into Grand Rapids, MI.

Train	Delay	Comment
370(08)	31"	

Train 4(08) West of Barstow, CA - Freight Train Interference

09NOV25: Train 4(08) was delayed at Hodge/MP13.6 13.2 miles west of Barstow, CA/MP0.4 on the BNSF Cajon subdivision meeting BNSF freights 5330W and 7623W. Once the route was clear, train 4(08) continued east.

Train	Delay	Comment
4(08)	33"	

Train 779(08) South of Carpinteria, CA - Passenger Train Interference

09NOV25: Train 779(08) was delayed at Seacliff siding/MP385.3 8 miles south of Carpinteria, CA/MP377.6 on the UP Santa Barbara subdivision meeting Amtrak train 11(07). Once the route was clear, train 779(08) continued into Carpinteria, CA.

Train	Delay	Comment
779(08)	41"	

Train 511(08) Seattle, WA - Servicing

08NOV25: Train 511(08) was delayed departing Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. The equipment had not arrived at SEA from King St Maintenance Facility by departure time. Once the equipment arrived, the crew boarded passengers and train 511(08) departed SEA at 8:27 PM-PT.

Train	Delay	Comment
511(08)	37"	

Train 14(08) San Luis Obispo, CA - Passenger Train Interference

08NOV25: Train 14(08) was delayed north of Serrano, CA (SLO) at CP Serrano on the Union Pacific Railway Coast Subdivision. Train 14(08) was held in the siding track to meet opposing train 11(07). Once train 11(07) was clear of the single main track ahead, train 14(08) was able to proceed north.

Train	Delay	Comment
14(08)	33"	

Train 3(07) East of Gallup, NM - Freight Train Interference

08NOV25: Train 3(07) was delayed in Thoreau, NM/MP135.2 22 miles east of Gallup, NM/MP157.5 on the BNSF Gallup subdivision meeting multiple BNSF freights. Once the route was clear, train 3(07) proceeded into Gallup, NM.

Train	Delay	Comment
3(07)	1'07"	

Train 741(08) Hayward, CA - Third Party Contractor Engine Failure

08NOV25: Train 741(08) was delayed at Hayward, CA (HY) on the Union Pacific Railway Niles Subdivision. The crew discovered the mount for the vertical struck on locomotive CDTX/2010 had been sheared off. After consulting with division management and the state of California mechanical contractor, train 741(08) was authorized to proceed at maximum authorized track speeds.

Train	Delay	Comment
741(08)	31"	

Train 14(07) North of Albany, OR - Engine Failure

08NOV25: Train 14(078) was delayed north of Albany, OR (ALY) at MP 714.4 on the Union Pacific Railway Brooklyn Subdivision. A wayside train defect detector indicated a warm wheel bearing on trail locomotive AMTK/158. The crew inspected and found the bearing the measure 147 degrees, which was considered to be high. After a discussion with Union Pacific Railway Dispatchers and CNOC Mechanical desk it was agreed that train 14(07) would proceed for ten miles not exceeding 50 MPH and the crew would inspect again. Upon further inspection the crew measured the bearing to be 120 degrees; train 14(08) was authorized to resume travel at maximum authorized track speeds.

Train	Delay	Comment
14(07)	59"	

Train 22(08) West of Mineola, TX - Freight Train Interference

08NOV25: Train 22(08) was delayed at Elmo/MP175.3 39 miles west of Mineola, TX/MP136.1 on the UP Mineola subdivision meeting UP freights UP/7692 and UP/5390. UP freight UP/5390 went into emergency and would not recover. While UP freight crews inspected the engine, train 22(08) was given a route around the UP/7692. Once UP/5390 was clear of the route, train 22(08) continued to Mineola, TX.

Train	Delay	Comment
22(08)	1'14"	

Train 6(08) Colfax, CA - Freight Train Interference

08NOV25: Train 6(08) was delayed west of Colfax, CA (COL) at MP 156.0 on the Union Pacific Railway Roseville Subdivision. Train 6(08) was required to follow a freight train, UP/6804, from MP 156.0 to MP 178.0. Once at MP 178.0 train 6(08) was able to overtake the freight train and resume operation at maximum authorized track speeds.

Train 11(07) San Jose, CA - Weather

08NOV25: Train 11(07) was delayed south of San Jose, CA (SJC) at CP Elkhorn Slough on the Union Pacific Railway Coast Subdivision. There were high tide conditions at Elkhorn Slough (MP 97.1) with water that had exceeded the height of the rail by over three inches. In compliance with operating instructions, the train crew was required to wait for tidal conditions to change and water to recede. Once the water had receded train 11(07) was able to proceed at reduced speeds through the affected area.

Train	Delay	Comment
11(07)	1'09"	

Train 713(08) Richmond, CA - Police Related

08NOV25: Train 713(08) was delayed west of Richmond, CA (RIC) at MP 7.5 on the Union Pacific Railway Martinez Subdivision. The local police and request all train traffic halted while searching for a suspect in the area. Once the police released the tracks train 713(08) was able to proceed west at 2:45 PM-PT.

Train	Delay	Comment
713(08)	30"	
732(08)	04"	
734(08)	14"	Held at OMF for 741 to clear main track before able to depart
741(08)	21"	

Train 22(08) - Car Failure

08NOV25: Train 22(08) was delayed departing the Fort Worth, TX Central Station due to mechanical servicing the train and attempted to repair the HVAC system in Dining Car 37011.

Train	Delay	Comment
22(08)	40"	

Train 22(08) North of Taylor, TX - Signal

08NOV25: Train 22(08) was delayed between MP 912.8 and Granger / MP 907.3 on the Union Pacific Waco Subdivision, starting 7 miles north of the Taylor, TX station, due to signal issues.

Train 769(08) San Diego, CA - Police Related

08NOV25: Train 769(08) departed SAN at 09:00 AM-PT. The train was delayed at SAN (SAN) on the North County Transit District (Coaster) San Diego Subdivision. There was an aggressive passenger causing a disturbance on the train and the crew requested local authorities to facilitate the removal. After an extended delay authorities had not arrived on scene and train 769(08) departs SAN at 9:01 AM-PT. The passenger was removed at Oceanside, CA (OSD) where police were waiting for the train to arrive.

Train	Delay	Comment
769(08)	1'00"	SAN
769(-08)	04"	OSD

Train 723(08) Oakland, CA - Freight Train Interference

08NOV25: Train 723(08) was delayed south of Oakland, CA (OKJ) at MP 5.0 on the Union Pacific Railway Niles Subdivision. A freight train had struck a vehicle on the crossing at CP NI011 and track one was out of service pending a police investigation, vehicle removal, and track inspection. Single track operation was in affect at that location with trains able to pass the scene on track two at reduced speeds. Once the scene was cleared normal operation was resumed later in the afternoon.

Train	Delay	Comment
723(08)	10"	
727(08)	29"	
729(08)	07"	
733(08)	Terminate OKJ	Avoid congested area ahead, 2 oax pax provided uber OKJ-OAC
728(08)	09"	
724(08)	19"	
11(007)	29"	

Train 21/421(07) West of Longview, TX - Freight Train Interference

08NOV25: Train 21 / 421(07) was delayed at Glade Water / MP 105.5 on the Union Pacific Mineola Subdivision, 16 miles west of the Longview, TX station, meeting ILBMN-05 (UPRR 3049).

Train	Delay	Comment
21/421(07)	33"	

Train 3(06) West of Barstow, CA - Freight Train Interference

08NOV25: Train 3(06) was delayed between West D Yard / MP 2.7 and Summit / MP 55.9 on the Burlington Northern Santa Fe Cajon Subdivision, starting 2 miles west of the Barstow, CA station, following FMNPWC01-04 (UPRR 7154).

Train	Delay	Comment
3(06)	1'35"	

Train 51(07) South of Lafayette, IN - Freight Train Interference

08NOV25: Train 51(07) was delayed at Switzer / MP 00Q127.5 on the Chessie, Seaboard and X Monon Subdivision, 7 miles south of the Lafayette, IN station, account a non-fitting M641-07 tied down ahead because of two freight trains blocking its route. it was necessary to move the two freight trains and wait or a relief crew for the M641-07.

Train	Delay	Comment
51(07)	1'00"	

Train 5(06) East of Elko, NV - Freight Train Interference

08NOV25: Train 5(06) with E/63/307, 10 coaches and 154 passengers onboard, was delayed 5 miles east of Elko, NV, at milepost 561.3 and 559 WWS / MP 558.9 on the Union Pacific Lake Side Subdivision, starting 4 miles east of the Elko, NV station, operating through the yard to operate around a INPOA-06 (UPRR 8359) that was tied down on the main track.

Train	Delay	Comment
5(06)	35"	

Train 40(06) East of Pittsburgh, PA - Engine Failure

08NOV25: Train 40(06) with E/63/307, 10 coaches and 154 passengers onboard, was delayed 5 miles east of Pittsburgh, PA, at milepost 325.8, on CSX P And W_BF subdivision, due to E/63 having a bad BMS contactor which caused the unit to shut down and stop providing tractive effort. The crew worked with CNOC mechanical to resolve and was unsuccessful. Pittsburgh mechanical was dispatched to the scene to assist and arrived approximately 12:50AM-ET. Pittsburgh mechanical was unable to resolve the issue and as a result the following plan was put into action.

The crew on 40(06) will get driven to Pittsburgh to retrieve E/112 from train 42(08) and use that motor to bring 40(06) into the station. Pittsburgh mechanical went with the crew and E/112 to 40(06) to assist with adding the motor to the consist. Once the motor was added, train 40(06) proceeded to Pittsburgh station. They then then cut away with E/112 and continue west with E/63 in the lead as a control stand also providing Head End Power, and E/307 will provide traction effort.

Train 41(07) was delayed west of Pittsburgh, PA on NS Fort Wayne-Pit_72PC subdivision, due to holding out side the station for train 40(06). The outbound conductor for train 41(07) was operating train 40(06) into Pittsburgh.

Train	Delay	Comment
40(06)	6'11"	Holding E/PGH waiting for rescue E/112
41(07)	1'50"	

Train 6(07) East of Winnemucca NV - Trackside Detector Activation

07NOV25: Train 6(07) was stopped 83 miles east of Winnemucca near Whirlwind, NV (MP 615.38, Elko Subdivision, Union Pacific Railroad) after a trackside detector indicated elevated bearing journal temperatures. Upon inspection, the crew identified a loose parking brake air hose, which was tightened to release the brakes. The train was authorized to proceed at a restricted speed of 30 MPH to the next detector at MP 639.1.

Train 6(07) stopped again in Friend, NE/MP99.3 57 miles east of Hastings, NE/MP156.0 on the BNSF Hastings subdivision with another level one wayside bearing heat detection alarm. After inspecting the loose air hose to the parking brake on engine 378, train 6(07) was on the move east at track speed.

Train 6(07) stopped again in Dorchester, NE/MP84.0 after another alarm at the Dorchester detector. The crew tightened the air hose and continued east. A BNSF carman in Lincoln, NE will inspect the hose as well.

Train	Delay	Comment
6(07)	1'16"	
6(07)	36"	East of Hastings, NE
6(07)	30"	Dorchester, NE

Western Region

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 58(7) Passenger Needing Extra Boarding Assistance at Effingham, Illinois – ADA***

08NOV25, Passenger on PNR AF788C, traveling from Effingham, IL to Chicago, IL was dropped off and left at unstaffed station. Passenger confined to wheelchair with limited mobility. The manual wheelchair was oversized and would not be able to fit through the sleeper roomette door. Passenger was accommodated into wheelchair space in coach with extra boarding assistance. Amtrak Police notified.

Delay: 58 (7) 28"

Train 769(8) Passenger Incident at San Diego, California – Fare Evader

08NOV25, Unknown Passenger without a ticket for Amtrak boarded train at San Diego, CA refused to see ticket clerk and get proper ticket for Amtrak. Conductor attempted to resolve the ticketing issue, however, was meet with aggression and verbally dismissed. Passenger was requested to exit the train by crew and became disruptive with another guest. Amtrak Police was notified, further attempts will be made for police to remove passenger downline.

Delay: 769 (8) 1'

Train 14(7) Passenger Removal at Eugene, Oregon – Improper Conduct

08NOV25, Passenger on PNR E07674, traveling from Emeryville, CA to Seattle, WA was removed at Eugene, OR for verbal threatening behavior. Passenger appeared to be under the influence. This disrupted and upset surrounding guest. (Passenger Mary on PNR E09D7F has voice recording) Amtrak Police notified.
Delay: 14(7) 2"

Train 11(8) Passenger Removal at Portland, Oregon – Improper Conduct

08NOV25, Passenger on PNR E6E5B6, traveling from Seattle, WA to Los Angeles, CA was removed from the train by the Conductor for having a non-service that lunged at another passenger. Amtrak Police notified.
Delay: 11(8) 9"

Train 14(7) Passenger Removal at Eugene, Oregon – Improper Conduct

08NOV25, Passenger on PNR E07674, traveling from Emeryville, CA to Seattle, WA was removed from the train by local Police for harassing another passenger about her baby. Amtrak Police notified.
Delay: 14(7) 2"

Consist Deviations

26-FOI-00103

00000005196

"UNCLASSIFIED"

11/14/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
508 (09)	EUG	LOCO USED IN LIEU OF NPCU. NO BV/FW/FX/FY OR CHECKED BAGGAGE SALES.	no bag	0	18
566 (08)	LAX	No bike space.	Pax must re-book	5	90215
580 (08)	LAX	CAB CAR OPERATING IN LIEU OF COACH. U CAPS CHANGED TO 310.	U CAPS CHANGED TO 310	0	6904
562 (08)	LAX	CAB CAR OPERATING IN LIEU OF COACH. U CAPS CHANGED TO 310.	U CAPS CHANGED TO 310	0	6904
582 (08)	LAX	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	0	NOCAR
564 (08)	LAX	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	0	NOCAR
194 (08)	NPN	OPERATING 4 COACH AND A CLUB DINE SPLIT BUSINESS NPN-WAS / WILL SWAP TO FULL SET IN WAS 6 COACH, CAFE, AND BUSINESS	downgrade JY	14	
779 (08)	SAN	No bike space.	No impact	0	90215
573 (08)	SAN	CAB CAR OPERATING IN LIEU OF COACH. U CAPS CHANGED TO 310.	U CAPS CHANGED TO 310	0	6904
591 (08)	SAN	CAB CAR OPERATING IN LIEU OF COACH. U CAPS CHANGED TO 310.	U CAPS CHANGED TO 310	0	6904
577 (08)	SAN	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	0	NOCAR
593 (08)	SAN	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	OPERATING 1-COACH SHORT. U/XY/WY CAPS REDUCED.	0	NOCAR
503 (09)	SEA	LOCO USED IN LIEU OF NPCU. NO BV/FW/FX/FY OR CHECKED BAGGAGE SALES.	no bag svc	0	18

Reverse Consists

Train Number	Station	Reason
195 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
87 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front
150 (08)	PHL	Consist reversed Business class seat orientation may have changed At Front
151 (08)	PHL	Consist reversed Business class seat orientation may have changed At Front
155 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
153 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
101 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
66 (08)	RNK	Consist reversed Business Class at Front
164 (09)	RVM	Consist reversed Business class seat orientation may have changed At Front
158 (09)	NFK	Consist reversed Business class seat orientation may have changed At Front
88 (09)	NFK	Consist reversed Business class seat orientation may have changed At Front
164 (08)	RVM	Consist reversed Business class seat orientation may have changed At Front
135 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front