



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, March 09, 2026

Rules: 0-19



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 03/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/08/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	253	48	81.0%	2,311	306	86.8%	46,246	6,719	85.5%
Central Division	85.5%	67	8	88.1%	543	41	92.4%	10,412	1,154	88.9%
Northeast Division	80.0%	85	15	82.4%	693	96	86.1%	14,428	2,489	82.7%
Southeast Division	72.5%	62	13	79.0%	562	94	83.3%	10,692	1,657	84.5%
Southwest Division	77.0%	39	12	69.2%	513	75	85.4%	10,714	1,419	86.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00361 00000006081 Endpoint Arrival Dates through 3/8/26 "UNCLASSIFIED" 4/29/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	91,331	22,749	75%	728,022	174,534	76%	14,823,960	3,483,390	77%
Northeast Corridor	81%	42,652	8,994	79%	331,261	84,400	75%	6,584,168	1,594,369	76%
Acela	83%	4,942	1,105	78%	47,901	9,619	80%	1,298,360	360,771	72%
Northeast Regional	79%	37,710	7,889	79%	283,360	74,781	74%	5,285,808	1,233,598	77%
Richmond / Newport News / Norfolk	77%	12,862	3,343	74%	94,119	27,003	71%	1,679,492	434,240	74%
Springfield Shuttles	89%	677	155	77%	5,697	1,154	80%	81,760	11,376	86%
Roanoke	79%	3,122	66	98%	22,123	6,091	72%	497,044	93,556	81%
On Spine Northeast Regional	80%	21,049	4,325	79%	161,421	40,533	75%	3,027,512	694,426	77%
State Supported	80%	34,920	7,980	77%	304,428	58,394	81%	6,374,128	1,260,945	80%
Borealis	60%	616	0	100%	4,264	341	92%	84,093	19,228	77%
Capitol Corridor	90%	2,596	923	64%	28,640	5,844	80%	551,742	66,221	88%
Carolinian	60%	1,207	461	62%	9,840	2,458	75%	173,685	50,312	71%
Cascades	63%	2,956	419	86%	19,046	3,215	83%	370,020	86,553	77%
Downeaster	82%	1,397	32	98%	12,483	1,021	92%	219,145	31,751	86%
Empire	78%	6,307	1,175	81%	41,334	5,139	88%	793,432	179,313	77%
Adirondack	72%	531	26	95%	2,694	436	84%	48,587	18,665	62%
Ethan Allen Express	70%	819	213	74%	4,215	299	93%	86,969	25,394	71%
Maple Leaf	70%	701	56	92%	5,033	772	85%	85,478	37,516	56%
New York - Albany	85%	2,800	173	94%	19,190	1,605	92%	362,378	55,348	85%
New York - Niagara Falls	75%	1,456	707	51%	10,202	2,027	80%	210,020	42,390	80%
Gold Runner	73%	2,781	472	83%	18,222	5,084	72%	374,782	128,058	66%
Heartland Flyer	65%	184	27	85%	1,353	354	74%	29,052	10,691	63%
Hiawatha	90%	1,644	0	100%	12,230	1,129	91%	250,392	29,920	88%
Illinois	78%	3,150	484	85%	19,529	4,615	76%	352,383	94,652	73%
Carl Sandburg / Illinois Zephyr	85%	444	124	72%	2,581	496	81%	58,561	14,783	75%
Illini / Saluki	85%	1,250	0	100%	7,898	1,462	81%	128,438	30,241	76%
Lincoln Service	70%	1,456	360	75%	9,050	2,657	71%	165,384	49,628	70%
Keystone	92%	4,702	1,778	62%	43,946	5,050	89%	1,143,988	137,039	88%
Lincoln / Missouri	60%	819	60	93%	5,600	2,473	56%	113,574	51,901	54%
Mardi Gras Service	80%	469	108	77%	3,047	444	85%	63,416	8,170	87%
Michigan	69%	2,008	932	54%	14,511	4,245	71%	277,064	84,361	70%
Blue Water	70%	174	0	100%	2,703	1,263	53%	65,874	21,577	67%
Pere Marquette	85%	292	57	80%	2,051	185	91%	36,753	6,693	82%
Wolverine	65%	1,542	875	43%	9,757	2,797	71%	174,437	56,091	68%
Missouri	80%	229	5	98%	1,454	265	82%	32,645	6,219	81%
Pacific Surfliner	85%	0	0	-	40,718	7,849	81%	1,024,486	153,897	85%
Pennsylvanian	72%	777	777	0%	6,854	2,963	57%	137,961	21,622	84%
Piedmont	73%	1,553	0	100%	9,921	2,592	74%	183,072	42,239	77%
Vermont	75%	1,525	327	79%	11,436	3,313	71%	199,196	58,798	70%
Long Distance	56%	12,996	5,775	56%	89,535	30,850	66%	1,836,039	626,919	66%
Auto Train	57%	915	0	100%	7,256	2,122	71%	114,307	26,401	77%
California Zephyr	50%	968	653	33%	7,518	2,387	68%	149,055	43,401	71%
Cardinal	55%	0	0	-	1,567	762	51%	37,659	16,539	56%
City Of New Orleans	75%	734	324	56%	5,278	1,206	77%	100,742	20,681	79%
Coast Starlight	60%	640	32	95%	5,851	727	88%	165,130	51,873	69%
Crescent	70%	971	4	100%	6,037	721	88%	135,071	29,543	78%
Empire Builder	55%	1,050	756	28%	7,066	2,644	63%	144,027	55,998	61%
Floridian	40%	1,607	1,144	29%	11,579	6,252	46%	245,322	135,845	45%
Lake Shore Ltd	73%	932	80	91%	6,934	1,643	76%	142,612	39,920	72%
Palmetto	65%	1,458	481	67%	7,435	2,274	69%	141,781	23,700	83%
Silver Meteor	45%	934	396	58%	7,547	3,035	60%	153,898	51,951	66%
Southwest Chief	40%	723	696	4%	5,379	3,532	34%	117,260	68,902	41%
Sunset Ltd	70%	469	201	57%	2,547	689	73%	43,471	10,838	75%
Texas Eagle	50%	1,595	1,008	37%	7,541	2,856	62%	145,704	51,327	65%
Seasonal Trains	%	763	0	100%	2,798	890	68%	29,625	1,157	96%
Winter Park Express	75%	763	0	100%	2,798	890	68%	29,625	1,157	96%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00001 00000000001 "UNCLASSIFIED" 4/20/2026

Train Index Dates Through March 08, 2026

Service	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	42,025	804,345	522	900,984	16,457,107	547

Department	Month to Date				FY to Date		
	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,167	216,529	100	37,628	4,686,694	80
INFRASTRUCTURE PLANNED	135	3,640	216,529	168	32,672	4,686,694	70
FLEET RELIABILITY	90	7,303	804,345	91	160,151	16,457,107	97
TRAIN OPERATIONS	424	28,915	804,345	359	670,533	16,457,107	407

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 03/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/08/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	253	48	81.0%	2,311	306	86.8%	46,246	6,719	85.5%
Central Division	85.5%	67	8	88.1%	543	41	92.4%	10,412	1,154	88.9%
Northeast Division	80.0%	85	15	82.4%	693	96	86.1%	14,428	2,489	82.7%
Southeast Division	72.5%	62	13	79.0%	562	94	83.3%	10,692	1,657	84.5%
Southwest Division	77.0%	39	12	69.2%	513	75	85.4%	10,714	1,419	86.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-0038

Scheduled Departure Date: 03/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/08/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	253	48	81.0%	2,311	306	86.8%	46,246	6,719	85.5%
Central Division	85.5%	67	8	88.1%	543	41	92.4%	10,412	1,154	88.9%
CDL	90.0%	2	0	100.0%	16	1	93.8%	287	12	95.8%
CHI	85.0%	26	2	92.3%	217	21	90.3%	4,180	553	86.8%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DEN	-	1	0	100.0%	5	0	100.0%	45	2	95.6%
DER	-	-	-	-	-	-	-	1	1	0.0%
EUG	86.5%	2	0	100.0%	16	2	87.5%	311	37	88.1%
GRR	98.0%	1	0	100.0%	8	0	100.0%	152	6	96.1%
KCY	84.5%	2	1	50.0%	16	2	87.5%	313	23	92.7%
MKE	86.5%	5	0	100.0%	46	1	97.8%	929	64	93.1%
MSP	94.0%	1	0	100.0%	8	0	100.0%	153	3	98.0%
PDX	78.0%	5	0	100.0%	40	2	95.0%	785	97	87.6%
PNT	91.5%	3	0	100.0%	24	0	100.0%	384	41	89.3%
PTH	93.0%	1	0	100.0%	8	0	100.0%	149	10	93.3%
QCY	87.5%	2	0	100.0%	16	0	100.0%	307	26	91.5%
SEA	80.0%	8	3	62.5%	62	7	88.7%	1,254	179	85.7%
SPK	92.0%	1	1	0.0%	8	1	87.5%	159	15	90.6%
STL	88.0%	4	1	75.0%	32	3	90.6%	603	64	89.4%
TRM	-	-	-	-	-	-	-	34	5	85.3%
VAC	95.0%	2	0	100.0%	16	0	100.0%	308	7	97.7%
WIP	-	1	0	100.0%	5	1	80.0%	45	4	91.1%
Northeast Division	80.0%	85	15	82.4%	693	96	86.1%	14,428	2,489	82.7%
ALB	91.5%	8	2	75.0%	63	6	90.5%	1,109	128	88.5%
BON	43.5%	5	2	60.0%	40	4	90.0%	764	88	88.5%
BOS	86.5%	14	0	100.0%	112	9	92.0%	2,679	379	85.9%
BRK	88.0%	5	0	100.0%	40	1	97.5%	743	50	93.3%
BTN	48.0%	1	1	0.0%	8	1	87.5%	146	26	82.2%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	16	0	100.0%	304	36	88.2%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	8	2	75.0%	144	30	79.2%
NFL	96.5%	2	0	100.0%	16	2	87.5%	319	17	94.7%
NHV	75.5%	5	0	100.0%	44	10	77.3%	822	176	78.6%
NYP	77.5%	33	9	72.7%	275	57	79.3%	6,039	1,431	76.3%
SAB	98.0%	1	0	100.0%	8	0	100.0%	149	2	98.7%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	55	4	92.7%	985	66	93.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	84.0%	1	0	100.0%	8	0	100.0%	156	41	73.7%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	62	13	79.0%	562	94	83.3%	10,692	1,657	84.5%
ATL	-	-	-	-	4	0	100.0%	34	4	88.2%
CLT	92.0%	5	1	80.0%	39	3	92.3%	775	60	92.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 03/08/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 03/08/2026			ITP March 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	253	48	81.0%	2,311	306	86.8%	46,246	6,719	85.5%
Southeast Division	72.5%	62	13	79.0%	562	94	83.3%	10,692	1,657	84.5%
GRO	-	-	-	-	1	0	100.0%	9	3	66.7%
HAR	62.0%	8	2	75.0%	89	20	77.5%	1,740	343	80.3%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	69.5%	1	0	100.0%	8	1	87.5%	156	24	84.6%
MIA	87.5%	2	0	100.0%	16	1	93.8%	311	29	90.7%
MOE	94.0%	2	0	100.0%	16	0	100.0%	318	4	98.7%
NFK	86.0%	2	0	100.0%	16	7	56.3%	393	58	85.2%
NOL	92.0%	4	0	100.0%	31	1	96.8%	658	27	95.9%
NPN	96.0%	2	0	100.0%	16	0	100.0%	285	18	93.7%
PGH	92.0%	1	1	0.0%	7	1	85.7%	157	8	94.9%
PHL	45.0%	6	3	50.0%	72	33	54.2%	830	413	50.2%
RGH	97.0%	4	0	100.0%	32	1	96.9%	623	21	96.6%
RNK	85.5%	2	1	50.0%	16	5	68.8%	311	50	83.9%
RVM	86.0%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	5	3	40.0%
SAV	91.5%	1	0	100.0%	8	1	87.5%	155	5	96.8%
SFA	70.5%	1	0	100.0%	8	1	87.5%	156	16	89.7%
WAS	70.0%	21	5	76.2%	183	19	89.6%	3,659	557	84.8%
Southwest Division	77.0%	39	12	69.2%	513	75	85.4%	10,714	1,419	86.8%
ARN	60.5%	1	0	100.0%	8	1	87.5%	158	11	93.0%
BFD	75.5%	6	2	66.7%	47	7	85.1%	952	196	79.4%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	2	0	100.0%	10	1	90.0%	174	49	71.8%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	1	0.0%	8	1	87.5%	155	5	96.8%
GAC	-	-	-	-	-	-	-	1	1	0.0%
GTA	72.5%	-	-	-	18	1	94.4%	477	43	91.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	77.5%	2	0	100.0%	65	2	96.9%	1,489	144	90.3%
MCD	-	-	-	-	-	-	-	6	6	0.0%
OKC	96.0%	1	0	100.0%	8	0	100.0%	154	3	98.1%
OKJ	79.0%	7	2	71.4%	81	26	67.9%	1,603	399	75.1%
RNO	-	-	-	-	-	-	-	1	1	0.0%
SAC	73.5%	11	4	63.6%	114	16	86.0%	2,118	229	89.2%
SAN	77.0%	-	-	-	78	10	87.2%	1,798	158	91.2%
SAS	85.0%	1	1	0.0%	8	2	75.0%	154	10	93.5%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	2	71.4%	56	7	87.5%	1,110	113	89.8%
SKN	-	-	-	-	-	-	-	6	5	16.7%
SLO	62.0%	-	-	-	12	1	91.7%	295	26	91.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	20	1	95.0%

Initial terminal tolerance = 0 minutes.

Information Management

Initial Terminal Performance By Terminal

26-FOI-003

42

Scheduled Departure Date:	03/08/2026
Amtrak or Commuter:	Amtrak

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		4	0	100.0%	69	13	81.2%	4	0	100.0%	67	8	88.1%
3	88	7	1	85.7%	158	28	82.3%	8	5	37.5%	158	65	58.9%
4	77	7	1	85.7%	157	21	86.6%	8	7	12.5%	158	100	36.7%
5	328	7	2	71.4%	157	30	80.9%	8	3	62.5%	155	33	78.7%
6		7	1	85.7%	156	41	73.7%	8	1	87.5%	157	43	72.6%
7	64	7	1	85.7%	153	24	84.3%	8	2	75.0%	148	29	80.4%
8		7	3	57.1%	153	63	58.8%	8	3	62.5%	153	73	52.3%
11		7	1	85.7%	157	26	83.4%	7	1	85.7%	152	29	80.9%
14		7	0	100.0%	158	20	87.3%	7	0	100.0%	157	40	74.5%
19		8	0	100.0%	156	35	77.6%	8	1	87.5%	156	21	86.5%
20		8	0	100.0%	156	11	92.9%	8	1	87.5%	156	19	87.8%
21		8	0	100.0%	153	15	90.2%	8	2	75.0%	152	30	80.3%
22	129	8	2	75.0%	154	9	94.2%	8	2	75.0%	153	31	79.7%
23	24	8	0	100.0%	159	3	98.1%	8	1	87.5%	159	25	84.3%
24		8	0	100.0%	159	9	94.3%	8	1	87.5%	159	15	90.6%
25		8	0	100.0%	159	1	99.4%	8	4	50.0%	158	27	82.9%
26		8	0	100.0%	159	3	98.1%	8	0	100.0%	158	23	85.4%
27	39	7	2	71.4%	152	9	94.1%	8	4	50.0%	150	37	75.3%
40		7	0	100.0%	153	18	88.2%	8	3	62.5%	154	55	64.3%
41	270	7	2	71.4%	153	60	60.8%	8	5	37.5%	154	101	34.4%
42	259	8	2	75.0%	158	9	94.3%	8	5	37.5%	156	24	84.6%
43	103	8	2	75.0%	157	29	81.5%	8	2	75.0%	157	20	87.3%
48		8	0	100.0%	156	34	78.2%	8	0	100.0%	156	25	84.0%
49		8	3	62.5%	156	42	73.1%	8	0	100.0%	156	34	78.2%
50	Cncld	3	0	100.0%	66	16	75.8%	3	3	0.0%	66	32	51.5%
52		8	1	87.5%	156	16	89.7%	8	1	87.5%	156	24	84.6%
53		8	1	87.5%	156	24	84.6%	8	4	50.0%	156	35	77.6%
54		8	2	75.0%	62	5	91.9%	8	0	100.0%	62	7	88.7%
57		8	0	100.0%	61	2	96.7%	8	0	100.0%	61	4	93.4%
58	42	8	0	100.0%	150	4	97.3%	8	2	75.0%	149	24	83.9%
59		8	0	100.0%	149	15	89.9%	8	2	75.0%	149	16	89.3%
63		8	3	62.5%	159	80	49.7%	8	1	87.5%	158	78	50.6%
64		8	0	100.0%	157	42	73.2%	8	1	87.5%	157	38	75.8%
65		2	0	100.0%	50	7	86.0%	3	1	66.7%	50	9	82.0%
66		8	3	62.5%	156	31	80.1%	8	2	75.0%	156	31	80.1%
68		8	2	75.0%	159	38	76.1%	8	2	75.0%	159	82	48.4%
69		8	3	62.5%	146	22	84.9%	7	0	100.0%	143	19	86.7%
71		8	0	100.0%	154	2	98.7%	8	0	100.0%	154	37	76.0%
72		8	1	87.5%	154	13	91.6%	8	0	100.0%	154	28	81.8%
73		8	0	100.0%	158	7	95.6%	8	3	62.5%	157	76	51.6%
74		8	2	75.0%	158	16	89.9%	8	4	50.0%	158	49	69.0%
75		8	0	100.0%	157	5	96.8%	8	6	25.0%	154	67	56.5%

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		8	0	100.0%	157	10	93.6%	8	3	62.5%	152	57	62.5%
77		8	1	87.5%	156	9	94.2%	8	5	37.5%	155	53	65.8%
78		8	0	100.0%	155	8	94.8%	8	1	87.5%	154	17	89.0%
79		8	2	75.0%	156	32	79.5%	8	3	62.5%	155	26	83.2%
80	37	8	0	100.0%	156	14	91.0%	8	1	87.5%	155	23	85.2%
82		8	0	100.0%	44	4	90.9%	8	3	62.5%	44	13	70.5%
87		8	3	62.5%	65	16	75.4%	8	4	50.0%	65	18	72.3%
88		8	1	87.5%	64	9	85.9%	8	0	100.0%	64	14	78.1%
89		8	1	87.5%	155	27	82.6%	8	2	75.0%	155	32	79.4%
90		8	1	87.5%	155	5	96.8%	8	1	87.5%	155	14	91.0%
94		8	4	50.0%	117	34	70.9%	8	3	62.5%	116	36	69.0%
97		8	7	12.5%	157	91	42.0%	8	1	87.5%	157	33	79.0%
98		8	0	100.0%	156	10	93.6%	7	0	100.0%	155	37	76.1%
99	113	8	0	100.0%	64	9	85.9%	8	6	25.0%	63	36	42.9%
101		8	1	87.5%	43	4	90.7%	8	3	62.5%	43	7	83.7%
103		8	2	75.0%	63	13	79.4%	8	0	100.0%	63	5	92.1%
106	42	8	0	100.0%	61	6	90.2%	8	1	87.5%	61	9	85.2%
107		8	2	75.0%	61	18	70.5%	8	1	87.5%	61	9	85.2%
109		8	0	100.0%	26	2	92.3%	8	0	100.0%	26	3	88.5%
118		8	0	100.0%	64	6	90.6%	8	0	100.0%	64	4	93.8%
124	16	8	0	100.0%	62	6	90.3%	8	2	75.0%	62	12	80.6%
126		8	1	87.5%	22	3	86.4%	8	1	87.5%	22	5	77.3%
127		8	3	62.5%	22	7	68.2%	8	2	75.0%	22	4	81.8%
128		8	0	100.0%	65	11	83.1%	8	2	75.0%	64	8	87.5%
135	44	8	0	100.0%	64	10	84.4%	8	5	37.5%	64	37	42.2%
140		8	2	75.0%	63	8	87.3%	8	0	100.0%	62	14	77.4%
142		8	0	100.0%	44	5	88.6%	8	1	87.5%	44	4	90.9%
143		8	1	87.5%	62	5	91.9%	8	3	62.5%	62	12	80.6%
144		8	7	12.5%	44	32	27.3%	8	1	87.5%	44	6	86.4%
146		8	0	100.0%	62	10	83.9%	8	2	75.0%	62	24	61.3%
147		8	0	100.0%	45	6	86.7%	8	4	50.0%	45	12	73.3%
150		8	3	62.5%	63	37	41.3%	8	5	37.5%	62	39	37.1%
151	18	8	3	62.5%	155	43	72.3%	8	4	50.0%	154	44	71.4%
152		8	1	87.5%	44	3	93.2%	8	3	62.5%	44	15	65.9%
153		8	0	100.0%	63	5	92.1%	8	1	87.5%	63	8	87.3%
155	39	8	1	87.5%	65	11	83.1%	8	2	75.0%	65	11	83.1%
156		8	2	75.0%	65	9	86.2%	8	4	50.0%	65	14	78.5%
158		8	3	62.5%	64	7	89.1%	8	2	75.0%	64	10	84.4%
159		8	0	100.0%	45	6	86.7%	8	0	100.0%	45	8	82.2%
160		8	0	100.0%	62	2	96.8%	8	4	50.0%	60	17	71.7%
161	19	8	1	87.5%	64	6	90.6%	8	5	37.5%	63	41	34.9%
162	21	8	0	100.0%	64	4	93.8%	8	6	25.0%	64	36	43.8%

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
163	42	8	1	87.5%	44	10	77.3%	8	8	0.0%	44	34	22.7%
164	27	8	0	100.0%	65	5	92.3%	8	5	37.5%	65	26	60.0%
165		8	1	87.5%	64	19	70.3%	8	3	62.5%	64	28	56.3%
167		8	1	87.5%	45	10	77.8%	8	1	87.5%	45	14	68.9%
168	28	8	3	62.5%	43	5	88.4%	8	2	75.0%	43	14	67.4%
169		8	1	87.5%	63	9	85.7%	8	2	75.0%	62	17	72.6%
194		8	2	75.0%	44	8	81.8%	8	3	62.5%	43	10	76.7%
195		8	0	100.0%	63	0	100.0%	8	2	75.0%	63	38	39.7%
232		8	0	100.0%	159	9	94.3%	8	0	100.0%	159	13	91.8%
233		8	1	87.5%	143	33	76.9%	8	0	100.0%	143	26	81.8%
234		8	1	87.5%	159	17	89.3%	8	0	100.0%	159	17	89.3%
235		8	1	87.5%	83	12	85.5%	8	1	87.5%	83	16	80.7%
236		8	0	100.0%	143	5	96.5%	8	0	100.0%	143	21	85.3%
237		8	3	62.5%	158	39	75.3%	8	2	75.0%	156	32	79.5%
238		8	0	100.0%	83	12	85.5%	8	1	87.5%	82	8	90.2%
239		8	2	75.0%	158	49	69.0%	8	0	100.0%	157	17	89.2%
240		8	0	100.0%	159	17	89.3%	8	0	100.0%	158	20	87.3%
241		8	3	62.5%	159	41	74.2%	8	1	87.5%	159	34	78.6%
244		8	0	100.0%	143	7	95.1%	8	0	100.0%	143	23	83.9%
245	30	3	2	33.3%	45	14	68.9%	3	1	66.7%	44	5	88.6%
280		8	0	100.0%	159	7	95.6%	8	0	100.0%	159	31	80.5%
281		8	1	87.5%	159	20	87.4%	8	3	62.5%	159	28	82.4%
283		8	0	100.0%	159	38	76.1%	8	0	100.0%	159	34	78.6%
284	19	8	2	75.0%	159	9	94.3%	8	2	75.0%	157	27	82.8%
290		8	1	87.5%	159	34	78.6%	8	0	100.0%	157	52	66.9%
291		8	1	87.5%	158	38	75.9%	8	1	87.5%	157	27	82.8%
300	31	8	1	87.5%	145	13	91.0%	8	3	62.5%	143	36	74.8%
301		8	1	87.5%	157	8	94.9%	8	1	87.5%	154	27	82.5%
302		8	2	75.0%	144	20	86.1%	8	2	75.0%	142	42	70.4%
305		8	0	100.0%	147	21	85.7%	8	2	75.0%	143	55	61.5%
306		8	0	100.0%	155	12	92.3%	8	2	75.0%	154	35	77.3%
307	176	8	1	87.5%	148	22	85.1%	8	3	62.5%	146	36	75.3%
311		8	0	100.0%	158	18	88.6%	8	1	87.5%	156	26	83.3%
316		8	0	100.0%	156	8	94.9%	8	2	75.0%	155	25	83.9%
318		8	2	75.0%	158	16	89.9%	8	2	75.0%	157	63	59.9%
319		8	1	87.5%	159	10	93.7%	8	4	50.0%	158	75	52.5%
331		8	0	100.0%	159	20	87.4%	8	0	100.0%	159	24	84.9%
332		8	0	100.0%	159	11	93.1%	8	0	100.0%	159	24	84.9%
334		8	0	100.0%	159	5	96.9%	8	3	62.5%	158	23	85.4%
335		8	1	87.5%	159	19	88.1%	8	1	87.5%	157	28	82.2%
336		8	0	100.0%	159	6	96.2%	8	1	87.5%	159	10	93.7%
337		8	1	87.5%	159	8	95.0%	8	0	100.0%	159	19	88.1%

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
338		8	0	100.0%	159	30	81.1%	8	3	62.5%	157	48	69.4%
339		8	2	75.0%	159	32	79.9%	8	2	75.0%	159	32	79.9%
341		8	0	100.0%	152	21	86.2%	8	0	100.0%	149	20	86.6%
342		8	1	87.5%	159	10	93.7%	8	3	62.5%	157	30	80.9%
350	17	8	0	100.0%	140	12	91.4%	8	3	62.5%	137	74	46.0%
351		8	0	100.0%	144	19	86.8%	8	2	75.0%	144	49	66.0%
352		8	0	100.0%	143	13	90.9%	8	2	75.0%	138	42	69.6%
353	85	8	0	100.0%	121	8	93.4%	8	1	87.5%	118	20	83.1%
354	24	8	0	100.0%	145	15	89.7%	8	2	75.0%	142	50	64.8%
355	25	8	0	100.0%	154	20	87.0%	8	3	62.5%	148	49	66.9%
364	236	8	4	50.0%	152	41	73.0%	8	5	37.5%	147	44	70.1%
365		8	0	100.0%	149	10	93.3%	8	4	50.0%	148	46	68.9%
370		8	0	100.0%	155	17	89.0%	8	1	87.5%	152	31	79.6%
371		8	0	100.0%	152	6	96.1%	8	0	100.0%	151	18	88.1%
380		8	0	100.0%	148	19	87.2%	8	0	100.0%	148	31	79.1%
381		8	0	100.0%	159	8	95.0%	8	0	100.0%	159	22	86.2%
382	63	8	0	100.0%	159	7	95.6%	8	5	37.5%	159	41	74.2%
383	17	8	0	100.0%	148	19	87.2%	8	4	50.0%	146	58	60.3%
390		8	1	87.5%	142	13	90.8%	8	1	87.5%	141	41	70.9%
391		8	1	87.5%	144	5	96.5%	8	2	75.0%	141	28	80.1%
392		8	0	100.0%	158	4	97.5%	8	1	87.5%	156	39	75.0%
393		8	1	87.5%	159	13	91.8%	8	2	75.0%	158	39	75.3%
400		3	0	100.0%	49	4	91.8%	3	0	100.0%	47	2	95.7%
405		3	0	100.0%	46	0	100.0%	3	0	100.0%	46	4	91.3%
409		2	0	100.0%	22	1	95.5%	2	0	100.0%	22	2	90.9%
416		2	0	100.0%	18	2	88.9%	2	0	100.0%	18	1	94.4%
448		8	3	62.5%	92	30	67.4%	8	4	50.0%	90	34	62.2%
449		8	1	87.5%	90	10	88.9%	8	1	87.5%	90	14	84.4%
450		3	2	33.3%	49	21	57.1%	3	2	33.3%	48	19	60.4%
460		3	0	100.0%	49	21	57.1%	3	0	100.0%	46	15	67.4%
461		3	0	100.0%	50	5	90.0%	3	0	100.0%	49	2	95.9%
464	25	3	0	100.0%	48	11	77.1%	3	2	33.3%	47	15	68.1%
465		2	0	100.0%	22	0	100.0%	2	0	100.0%	22	0	100.0%
488		3	0	100.0%	51	12	76.5%	3	0	100.0%	45	8	82.2%
497	19	2	0	100.0%	19	0	100.0%	2	1	50.0%	19	2	89.5%
499		3	0	100.0%	46	8	82.6%	3	0	100.0%	44	4	90.9%
500		8	0	100.0%	155	11	92.9%	8	1	87.5%	154	20	87.0%
502		8	0	100.0%	159	11	93.1%	8	1	87.5%	157	34	78.3%
503	22	8	0	100.0%	156	16	89.7%	8	2	75.0%	154	38	75.3%
504		8	1	87.5%	159	14	91.2%	8	1	87.5%	158	41	74.1%
505		8	0	100.0%	159	24	84.9%	8	2	75.0%	157	38	75.8%
506		8	1	87.5%	158	19	88.0%	8	0	100.0%	157	20	87.3%

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507		8	0	100.0%	159	16	89.9%	8	0	100.0%	159	49	69.2%
508		8	1	87.5%	157	27	82.8%	8	0	100.0%	157	28	82.2%
509		8	1	87.5%	159	9	94.3%	8	0	100.0%	159	37	76.7%
511		8	0	100.0%	155	15	90.3%	8	0	100.0%	155	24	84.5%
516		8	2	75.0%	155	14	91.0%	8	3	62.5%	155	64	58.7%
517		8	0	100.0%	159	3	98.1%	8	0	100.0%	158	48	69.6%
518	35	8	0	100.0%	159	21	86.8%	8	3	62.5%	158	94	40.5%
519	65	8	0	100.0%	155	5	96.8%	8	4	50.0%	155	29	81.3%
600		8	1	87.5%	114	6	94.7%	8	0	100.0%	113	11	90.3%
607		8	2	75.0%	113	12	89.4%	8	0	100.0%	112	11	90.2%
624	19	8	4	50.0%	92	30	67.4%	8	4	50.0%	93	23	75.3%
643	31	8	1	87.5%	116	28	75.9%	8	2	75.0%	115	23	80.0%
644		8	2	75.0%	108	21	80.6%	8	1	87.5%	107	32	70.1%
645	Cncld	7	5	28.6%	116	26	77.6%	6	0	100.0%	114	26	77.2%
647	45	8	6	25.0%	116	21	81.9%	8	2	75.0%	116	28	75.9%
648		8	1	87.5%	114	31	72.8%	8	0	100.0%	114	15	86.8%
649	16	8	0	100.0%	117	22	81.2%	8	1	87.5%	115	21	81.7%
650		8	2	75.0%	116	29	75.0%	8	0	100.0%	115	18	84.3%
651		8	0	100.0%	116	9	92.2%	8	2	75.0%	115	25	78.3%
652		8	0	100.0%	117	19	83.8%	8	0	100.0%	114	21	81.6%
655	36	8	0	100.0%	114	35	69.3%	8	3	62.5%	112	38	66.1%
656	35	8	1	87.5%	116	29	75.0%	8	1	87.5%	116	14	87.9%
658	Cncld	8	1	87.5%	116	19	83.6%	7	0	100.0%	115	19	83.5%
661		8	3	62.5%	63	9	85.7%	8	4	50.0%	62	23	62.9%
690		3	0	100.0%	46	1	97.8%	3	0	100.0%	45	3	93.3%
691	19	3	1	66.7%	46	4	91.3%	3	3	0.0%	45	17	62.2%
692		3	0	100.0%	46	2	95.7%	3	0	100.0%	45	11	75.6%
693		3	2	33.3%	46	8	82.6%	3	1	66.7%	46	16	65.2%
694		3	0	100.0%	46	5	89.1%	3	0	100.0%	46	8	82.6%
695		3	0	100.0%	46	5	89.1%	3	0	100.0%	46	10	78.3%
696		3	0	100.0%	46	5	89.1%	3	1	66.7%	46	12	73.9%
697		3	0	100.0%	46	9	80.4%	3	0	100.0%	46	10	78.3%
698		3	0	100.0%	45	0	100.0%	3	0	100.0%	45	6	86.7%
699		2	1	50.0%	35	3	91.4%	2	0	100.0%	34	1	97.1%
701		8	0	100.0%	91	9	90.1%	8	1	87.5%	89	7	92.1%
702		8	0	100.0%	158	20	87.3%	8	0	100.0%	157	35	77.7%
703	No OS	8	2	75.0%	159	41	74.2%	8	3	62.5%	158	37	76.6%
704		8	3	62.5%	90	11	87.8%	8	2	75.0%	89	17	80.9%
710		8	2	75.0%	159	49	69.2%	8	1	87.5%	158	44	72.2%
711		7	1	85.7%	151	13	91.4%	7	2	71.4%	140	25	82.1%
712	73	8	4	50.0%	156	37	76.3%	8	3	62.5%	151	52	65.6%
715		8	1	87.5%	158	37	76.6%	7	3	57.1%	148	73	50.7%

Amtrak On Time Performance

Trains Arriving Through: 3/8/2026

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
716		8	3	62.5%	159	63	60.4%	8	2	75.0%	156	61	60.9%
717		8	3	62.5%	146	38	74.0%	8	1	87.5%	134	40	70.1%
718		8	4	50.0%	159	75	52.8%	7	3	57.1%	157	50	68.2%
719		8	0	100.0%	159	52	67.3%	8	2	75.0%	150	41	72.7%
720		3	0	100.0%	52	4	92.3%	3	0	100.0%	52	2	96.2%
723		3	0	100.0%	52	4	92.3%	3	0	100.0%	52	5	90.4%
724		3	1	66.7%	52	2	96.2%	3	0	100.0%	52	6	88.5%
727		3	0	100.0%	52	5	90.4%	3	0	100.0%	52	8	84.6%
728		3	0	100.0%	52	5	90.4%	3	1	66.7%	52	9	82.7%
729	22	3	1	66.7%	52	5	90.4%	3	2	33.3%	52	13	75.0%
732		3	0	100.0%	50	8	84.0%	3	1	66.7%	49	8	83.7%
733	14	3	0	100.0%	52	8	84.6%	3	3	0.0%	48	17	64.6%
734		3	2	33.3%	52	12	76.9%	3	0	100.0%	52	9	82.7%
738		3	0	100.0%	52	8	84.6%	3	1	66.7%	50	4	92.0%
741		3	2	33.3%	52	9	82.7%	3	1	66.7%	52	6	88.5%
742	148	3	2	33.3%	52	7	86.5%	2	1	50.0%	50	6	88.0%
743	203	3	2	33.3%	52	8	84.6%	2	1	50.0%	51	4	92.2%
744	23	3	0	100.0%	52	6	88.5%	3	2	33.3%	52	17	67.3%
745	25	3	0	100.0%	52	4	92.3%	3	2	33.3%	52	10	80.8%
746	15	3	0	100.0%	52	3	94.2%	3	1	66.7%	52	7	86.5%
747		3	0	100.0%	52	10	80.8%	3	0	100.0%	52	11	78.8%
748	77	3	0	100.0%	51	8	84.3%	3	2	33.3%	51	9	82.4%
749	Cncld	3	1	66.7%	49	8	83.7%	2	1	50.0%	42	6	85.7%
751		3	1	66.7%	52	11	78.8%	3	0	100.0%	50	6	88.0%
821		8	0	100.0%	154	3	98.1%	8	3	62.5%	154	62	59.7%
822		8	1	87.5%	155	5	96.8%	8	2	75.0%	154	67	56.5%
1028	46	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1105		5	0	100.0%	45	2	95.6%	5	1	80.0%	45	3	93.3%
1106		5	1	80.0%	45	4	91.1%	5	2	60.0%	45	3	93.3%
1333		8	1	87.5%	155	18	88.4%	8	2	75.0%	152	55	63.8%
1340		8	0	100.0%	154	3	98.1%	8	0	100.0%	154	29	81.2%
2201		8	1	87.5%	26	5	80.8%	8	0	100.0%	26	2	92.3%
2203		8	1	87.5%	43	6	86.0%	8	4	50.0%	43	13	69.8%
2205	128	8	1	87.5%	62	8	87.1%	8	2	75.0%	62	9	85.5%
2216		8	1	87.5%	45	3	93.3%	8	0	100.0%	45	0	100.0%
2218	27	8	1	87.5%	42	7	83.3%	8	1	87.5%	42	6	85.7%
2220		8	1	87.5%	23	4	82.6%	8	0	100.0%	22	4	81.8%
2248		8	1	87.5%	59	6	89.8%	8	0	100.0%	59	11	81.4%
2249		8	0	100.0%	42	1	97.6%	8	3	62.5%	42	15	64.3%
2250		8	0	100.0%	62	8	87.1%	8	2	75.0%	62	26	58.1%
2252		8	0	100.0%	61	6	90.2%	8	1	87.5%	59	12	79.7%
2255	73	8	0	100.0%	62	9	85.5%	8	4	50.0%	61	31	49.2%

Amtrak On Time Performance Trains Arriving Through: 3/8/2026 26-FOI-00361 00000006081 "UNCLASSIFIED" 4/29/2026													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2271		8	0	100.0%	46	6	87.0%	8	4	50.0%	45	26	42.2%

Amtrak Endpoint OTP Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2205	WAS	128	ENG	129	ENG	129	NYP-NYP	AM	Set out defective locomotive, 2104, LATE FROM SSYD A/C MISSING DOOR HANDLE ON WESTEND POWER CAR PC2104
2218	NYP	27	SVS	19	SVS	19	WAS-WAS	AM	Planned set out / pick out of locomotives, cars or section of train, LATE INBOUND TURN OFF AM2205
2255	WAS	73	DDA	37	DDA	37	MET-XCY	AM	HBD - no exceptions, Other, MP29.7 NO.3 TRACK , CREW INSPECTING EQUIPMENT
99	NPN	113	DCS	102	DCS	90	RVM-RVM	CS	Power switch failure Other, ca 84.5
106	NYP	42	RTE	26	RTE	26	XHM-EWR	AM	Routed to abnormal station track due to N.A.R., 2 TRACK REVERSE BACK TO MAKE EWR STOP ON NO.1 TRACK, Other, EWR
124	PHL	16	FTI	29	FTI	25	RVR-ASD	CS	Meet 409, Control Point, Lakeside
135	WAS	44	PTI	35	PTI	32	MET-TRE	AM	Cross over or go around, AM655, Other, MP29.7 AM655 STOPPED WITH HOT BOX ALARM
151	RNK	18	PTI	18	PTI	18	CVS-LYH	NS	Meet 156, Control Point, Hamner
155	NFK	39	FTI	45	FTI	45	FBG-ASD	CS	Follow 419, Milepost, 35.0, 4.4
161	WAS	19	SMW	20	SMW	12	WIL-XPV	AM	Diversions around M/W work, Control Point, .. PERRY TO GRACE, SINGLE TRACKING 2 TRACK A/C 3 TRACK O/S
162	BOS	21	SMW	14	DSR	6	STM-BRP	MN	Per bulletin Milepost, 40.4, 48.4, 30, 2
163	WAS	42	SMW	23	SMW	13	XSH-NYP	AM	Scheduled in track usage program, Other, XSH NYP
164	BOS	27	SMW	17	SMW	17	NYP-XSH	AM	Diversions around M/W work, Other, XGG-XPB, SINGLE TRACKING LEGGETT TO PELHAM BAY
168	BOS	28	SMW	23	POL	19	WAS-WAS	AM	Removal of passenger by police, CNDR REQUESTED FOR APD TO INVESTIGATE A PASSENGER RELATED ISSUE
464	SPG	25	CON	22	CON	22	NHV-NHV	AM	Hold for connecting train, late departure due to late connection of AM164
497	NHV	19	PTI	21	PTI	21	SPG-WNL	AM	Meet, 140, Milepost w/Letters, SPG, WNL, AM497 waited for AM140 to clear the single track Hayden - Field
80	NYP	37	FTI	41	FTI	24	RVR-FBG	CS	Meet 419, Other, Elmont (cfp 11.4), csx

Amtrak Endpoint OTP Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/8/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
624	NYP	19	SMW	14	SMW	14	NWK-NYP	AM	Scheduled in track usage program, Other, XHU-XBH, SINGLE TRACKING ON NO.2 TRACK A/C 3 TRACK O/O/S FROM HUDSON TO ERIE	
643	HAR	31	ENG	24	ENG	12	PAO-EXT	AM	HEP, 9645, LOST HEP AT MP 27.3. DRIFTED TO EXTON	
645	HAR	Trn Cancelled	ENG	79	ENG	79	PHL-PHL	AM	Set out defective locomotive, E/659, had to swap equipment a/c engine problems	
647	HAR	45	MTI	30	MTI	30	PHL-PHL	AM	Disabled train ahead, Milepost, 1.5, ., held for 645 to arrive in Philadelphia then received transfer from 645, 645 terminated	
649	HAR	16	DDA	24	DDA	24	EWB-TRE	AM	HBD - no exceptions, Other, MP29.7 SET OFF HOT BOX DETECTOR HOT AXEL ALARM NO.3 TRACK	
655	HAR	36	DDA	28	DDA	28	NWK-TRE	AM	HBD - no exceptions, Other, NO.3 TRACK MP29.7	
656	NYP	35	CCR	38	CCR	31	PHL-XHM	AM	Cab signal failure, CC/9645, had to wye leaving Philadelphia	
658	PHL	Trn Cancelled								
691	BRK	19	PTI	15	PTI	15	POR-FRE	CS	Meet 694, Control Point, Congress	
245	ALB	30	SYS	38	SYS	38	NYP-NYP	AM	Other late crew	
284	NYP	19	FTI	30	PTI	16	ALB-HUD	AM	Meet 233, Control Point, 115	
42	NYP	259	ENG	156	ENG	156	PGH-PGH	NS	Access not working, added NS engine 4109 after we had to y the freight Had to y 4109 and could not get initialized, also dispatch did not give us a C light, had to run restricted speed, XNS4109	
43	PGH	103	ENG	80	ENG	80	NYP-NYP	AM	Set out defective locomotive, 613, UNSPECIFIED MECAHNICAL ISSUE	
41	MIA	270	ENG	179	ENG	171	TPA-LKL	CS	HEP Stopped @ A872.8 due to complete HEP failure. Lead Eng#346 quit providing traction. Contacted CNOC mech to diagnose issue w/ multiple short looping & Eng setup scenarios performed., 346, 350	
23	NOL	24	FTI	40	FTI	40	BAS-XNO	CS	Cross over or go around Siding, Michoud, M80508	
5	EMY	328	ENG	227	CAR	175	SLC-SLC	UP	HEP 61069, HEP shorted out throwing flames from under the car. Rotated car to the rear of train.	
729	SJC	22	DSR	17	DSR	12	DAV-FFV	UP	Per bulletin Milepost, 68.50, 65.40, 15, one	

Amtrak Endpoint OTP Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/8/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
733	SJC	14	PTI	9	PTI	9	GAC-SCC	UP	Meet Shuffle at Expressway, 734, Control Point, Expressway
742	SAC	148	ITI	148	ITI	148	OKJ-OKJ	UP	Late due to 743 being late dropping off dead set at OMF. 743
743	OKJ	203	SVS	106	SVS	106	SAC-SAC	UP	Planned Switch Taking deadhead equipment to the OMF. Delayed for breaks not releasing on the dead loco and calendar day inspection., Other, SAC
744	ARN	23	DSR	12	PTI	9	OKJ-EMY	UP	Wait for station track 743/745, Other, EMY STA
745	SJC	25	MBO	26	MBO	26	SUI-MTZ	UP	For maritime traffic Control Point, rv035
746	SAC	15	FTI	21	FTI	21	RIC-MTZ	UP	Meet MT1. Forced to work single main. We were on MT2, Milepost, 23.5, 23.5, UP1472, local
748	SAC	77	TRS	52	TRS	52	HAY-OAC	UP	Trespasser strike Milepost, 12.7, 12.7
749	OKJ	Trn Cancelled							
50	CVS	Trn Cancelled	DBS	96	DBS	96	CIN-MAY	CS	Debris strike Both windshields shattered but in place, Tree, Milepost w/Letters, ca603.4, ca603.4
503	EUG	22	FTI	24	FTI	19	PDX-ORC	UP	Follow PNWR 2314, Milepost, 0.0, 765.2
518	VAC	35	FTI	37	FTI	27	X8B-XF2	BN	Cross over or go around CN6416, Siding, Oliver
519	SEA	65	DCS	39	DCS	39	X1J-XF2	BN	Power switch failure Hand line switch on br, Bridge, Fraser river br
58	CHI	42	WTR	102	WTR	70	JAN-JAN	CC	Trees down Other, 218.6
7	SEA	64	FTI	211	FTI	36	WFH-LIB	BN	Follow bn5792, Control Point, e Radner, Control Point, e riverview
27	PDX	-51	SYS	66	SYS	59	SPK-SPK	BN	Other late crew Late arrival of train 7 coupled with daylight savings
1028	SPK	46	FTI	86	FTI	70	WIH-PSC	BN	Meet BNSF 9190, BNSF 8290, Siding, Bates
350	PNT	17	PTI	20	PTI	19	ALI-JXN	MI	Meet 353, Control Point, 75
353	CHI	85	SYS	56	SYS	33	DER-ARB	MI	PTC problem or failure (cause unknown) Milepost, 9, 37
354	PNT	24	FTI	18	FTI	12	X1W-DET	CC	Cross Traffic CN 5779, Control Point, Avery
355	CHI	25	PTI	19	FTI	14	XPI-HMI	NS	Follow 27g, Milepost, 501, 506
364	PTH	236	ENG	125	ENG	118	CHI-CHI	AM	Marker light out ID4603

Amtrak Endpoint OTP Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 3/8/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
703	SAC	No OS Rpt	TRS	131	TRS	131	MDR-MCD	BN	Vehicle strike Milepost, 1045.5, 1045.5
712	BFD	73	TEN	89	TEN	31	HNF-COC	BN	HEP Lost HEP (Round 2)coasted to a stop at GUERNSEY. Reset HEP motor and then waited on a W bound Z train at GUERNSEY., C2006
3	LAX	88	FTI	106	FTI	39	NPV-MDT	BN	Follow Follow from CP Bristol to CP Earlville, BNSF, Control Point, Bristol
4	CHI	77	FTI	111	FTI	84	BAR-NDL	BN	Meet BNSF, Control Point, East Cadiz, Control Point, Homer
22	CHI	129	TRS	134	TRS	134	DAL-MIN	UP	Vandalism Dispatcher stoped all traffic for a trespasser vandalizing a freight train, Control Point, T-214
300	CHI	31	FTI	14	FTI	14	SPI-LCN	UP	Meet up 9021, Control Point, broadwell
307	STL	176	CAR	108	CAR	40	SPI-CRV	UP	Cut out axel on 4101 only able to go 40mph ID4101
382	CHI	63	FTI	75	FTI	30	MAC-GBB	BN	Follow 6793, Milepost, 200.5, 168.0, BNSF
383	QCY	17	ADA	9	FTI	8	PCT-KEE	BN	Follow BNSF 8195, Milepost, 111, 114

Amtrak Initial Terminal Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 3/8/2026

Terminal	Train	Date	Late	Delay	Cause
CLT	74	03/08	1		
HAR	624	03/08	2	2	High passenger count
HAR	658	03/08 (Trn Cxld)			Engine Issue
PGH	42	03/08	156	156	Access not working, added NS engine 4109 after we had to y the freight Had to y 4109 and could not get initialized, also dispatch did not give us a C light, had to run restricted speed, XNS4109
PHL	144	03/08	3	3	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE FROM THE YARD
PHL	645	03/08 (Trn Cxld)		79	Engine Issue
PHL	647	03/08	30	30	Disabled train ahead, Milepost, 1.5, ., held for 645 to arrive in Philadelphia then received transfer from 645, 645 terminated
RNK	156	03/08	4	4	Meet 289-07, Other, RNK station
WAS	54	03/08	5	5	Delay in Block, CREW DIDN'T WALK TRAIN, STUCK CHOCK BEHIND MOTOR.
WAS	88	03/08	7	7	Air / Brake / Wheel, 82365, SPLIT CAR AWAY FROM THE TRAIL CAR FOR BAD WHEEL FLANGE
WAS	168	03/08	19	19	Removal of passenger by police, CNDR REQUESTED FOR APD TO INVESTIGATE A PASSENGER RELATED ISSUE
WAS	2218	03/08	19	19	Planned set out / pick out of locomotives, cars or section of train, LATE INBOUND TURN OFF AM2205
ALB	69	03/08	35	23	Loading problem 124
ALB	448	03/07	5	5	Planned set out / pick out of locomotives, cars or section of train Control Point, 142
BON	693	03/08	1		
BON	699	03/08	1		
BTN	290	03/08	24	24	Crew rest
MTR	68	03/08	2	2	Mobility Impaired Mobility issues. Party of 3. PNR 961422.
NYP	43	03/08	80	80	Set out defective locomotive, 613, UNSPECIFIED MECAHNICAL ISSUE
NYP	51	03/08	25		
NYP	63	03/08	7	7	Passenger and/or baggage, BOARDING
NYP	79	03/08	18	18	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C LATE RELEASE FROM CATERING
NYP	89	03/08	4	4	Diversions around M/W work, Other, NYP, LATE RETURN OF O/O/S LIMITS DURING 85/89 SW REPLACEMET PROJECT
NYP	97	03/08	30	30	Service, turn, or wye train, 98, REQUIRED MOTOR FROM 98(07)
NYP	107	03/08	2	3	High passenger count

Amtrak Initial Terminal Details

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 3/8/2026

Terminal	Train	Date	Late	Delay	Cause
NYP	245	03/08	53	53	Planned set out / pick out of locomotives, cars or section of train, DELAYED A/C REMOVED B/O CAR FROM CONSIST AT SSYD
NYP	2205	03/08	129	129	Set out defective locomotive, 2104, LATE FROM SSYD A/C MISSING DOOR HANDLE ON WESTEND POWER CAR PC2104
CHI	364	03/08	118	118	Marker light out ID4603
CHI	1333	03/08	4	4	Missing cable from South end of added car 34094, Bad load test, missing cable from added car
KCY	318	03/08	2	2	Loco showing a door not closed on train. All doors were closed and cut out device indicating door open ID4630
SEA	8	03/08	116	116	Service, turn, or wye train 007
SEA	509	03/08	1	1	Meet Ready to depart on time - held for 518 arrival, 518, Control Point, SEA
SEA	516	03/08	21	21	Loading problem Engine would not load due to multiple faults. Mechanical came and reset locomotive., 186
SPK	27	03/06	59	59	Other late crew Late arrival of train 7 coupled with daylight savings
STL	300	03/08	4	4	Wait for station track 307 coming in from the wye, Amtrak 307, Control Point, gratiot
BFD	703	03/08	28	28	Service, turn, or wye train 712
BFD	717	03/08	1		
FTW	822	03/08	4	4	Wait for station track AMTK 22, Other, FTW
OKJ	712	03/08	12	12	Air / Brake Problems with Air Brakes and M/R causing late yard release at 1013., C2006
OKJ	742	03/08	148	148	Late due to 743 being late dropping off dead set at OMF. 743
SAC	704	03/08	11	11	Meet Freight blocking is from leaving SAC station rv990, up, Control Point, rv 990
SAC	741	03/08	2	2	I St Bridge Stop, Control Point, RV989
SAC	743	03/08	106	106	Planned Switch Taking deadhead equipment to the OMF. Delayed for breaks not releasing on the dead loco and calendar day inspection., Other, SAC
SAC	749	03/08	(Trn Cxld)		Engine Issue
SAS	22	03/08	4	4	Hold for connecting train Hold for transfer cars off train 2/422, 2
SJC	724	03/08	1	1	Door C8016, Door 6 in car 8016 was stuck open - had to pull it from pocket to close.
SJC	734	03/08	1		

Eastern Region

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	96.4	98.0	94.8	166	6
CDOT	95.0	100.0	97.3	92.4	16	0
MARC	95.0	100.0	86.4	90.2	12	0
SEPTA	95.0	94.5	95.7	91.5	109	6
NJT-NED	95.0	90.9	85.7	88.6	132	12
NJT-SED	95.0	100.0	100.0	97.2	18	0

Operating Highlights

Train 245(08) - New York Penn Station - Car Failure

08MAR26: Train 245(08) was delayed at its initial terminal at New York Penn Station due to a bad ordered car (48160) being removed at Sunnyside Yard.

Train	Delay	Comment
245 (08)	53"	

Train 99(08) - Richmond, VA - Switch Failure

08MAR26: Train 99(08) was held at Richmond Main Street Station/MP 0.1 due to an issue involving TOL's on the CSX Peninsula Subdivision at MP 84.5. CSX Maintainers were dispatched to troubleshoot and resolve the issue.

Train	Delay	Comment
99 (08)	1'38"	

Train 97(08) New York, NY - Initial Terminal Delay

08MAR26: Train 97(08) was delayed departing initial terminal of New York Penn Station, NY/MP 0.0 due to needing E/645 from inbound Train 98(07). Once Train 98(07) arrived at 12:08P-ET, lead E/645 was removed. Once engine was worked up, E/645 was added to Train 97(08) and departed New York City.

Train	Delay	Comment
97 (08)	30"	

Train 2255(08) - East of Trenton, NJ - Defect Detector Actuation

08MAR26: Train 2255(08) was delayed on the Amtrak New York to Philadelphia Line at MP 29.7 due to actuating the Hot Box Detector. The crew inspected the consist and took no exceptions.

Train	Delay	Comment
2255 (08)	37"	

Train 41(06) North of Tampa, FL - Engine Failure, HEP Loss

08MAR26: Train 41(06) ~~26-FOI-00361~~ ~~00000006081~~ ~~UNCLASSIFIED~~ ~~4/29/2026~~ operating with CC/346 and E/350 and 9 cars, experienced a loss of head-end power (HEP) at approximately 3:00 PM ET, 9 miles east of Tampa, FL, at MP 872.8 on the CSX Lakeland Subdivision. The train had 173 customers onboard, and the outside temperature was reported as 86°F and sunny. The crew worked in coordination with CNOC Mechanical in an attempt to restore HEP. At 4:50 PM ET, HEP was successfully restored on the trail locomotive (E/350). The crew then continued troubleshooting with Mechanical forces to properly configure both locomotives and assess their reliability for continued service toward Miami. Once the required setup and assessments were completed, Train 41(06) was able to resume its trip under its own power.

Service recovery was initiated onboard with customers being provided snack packs, bottled water, and cups of ice.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(08)	52"	
41(06)	2'51"	

Train 645(08) Philadelphia, PA - Engine Failure

08MAR26: Train 645(08), operating with CC/9651, 4 cars, and locomotive E/614, experienced a delay departing Philadelphia due to mechanical issues with E/614. The locomotive was subsequently removed and replaced with E/659. Once the consist was reassembled and all required work was completed, Train 645(08) departed with 175 customers onboard. Shortly after departure, approximately 5 miles west of Philadelphia, Train 645(08) encountered additional mechanical difficulties when locomotive E/659 experienced pantograph failures and lost head-end power. Due to these ongoing issues, it became necessary to cancel Train 645(08). Customers were reaccommodated onto Train 647(08). Additionally, Train 658(08) was cancelled, and its customers were directed to the next available service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
645(08)	1'19"	PHL
647(08)	30"	

South of New York, NY - Catenary or Wayside Failure

08MAR26: At approximately 12:13 PM ET, overhead catenary power was lost on the Amtrak NYP Line across two track segments:

Track 1: From Elmora (MP 14.7) to A-Tower (MP 0.2)

Track 2: From Old Swift (MP 7.2) to A-Tower (MP 0.2)

At approximately 12:39 PM ET, the Power Director successfully restored and stabilized power. The disruption was attributed to a blown insulator on a feeder cable at Substation 41.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
164(08)	14"	
43(08)	18"	

Train 23(08) North of New Orleans, LA - Freight Train Interference

08MAR26: Train 23(08), operating with locomotives E/187 and E/180, 3 cars, and 109 customers onboard, experienced a delay at Michoud/MP 793.1 on the CSX New Orleans & Mobile Subdivision. The delay occurred while the train was following CSX freight train M805-08 in the New Orleans area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
--------------	--------------	----------------

Train 69(08) Albany-Rensselaer, NY - Loco Swap

08MAR26: Train 69(08) scheduled to operate with locomotive E/121 and 5 cars, experienced a delay departing Albany, NY due to a required locomotive equipment swap. Locomotive E/121 was bad-ordered for ACSES-related issues and subsequently removed from the combined Train 63/69 consist.

To ensure continued service to Montreal, QC, locomotive E/145 was added to replace E/121. Following completion of the switching operations, Train 69(08) departed Albany with 225 customers onboard.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
69(08)	35"	

Train 43(08) New York, NY - ITD Car Failure

08MAR26: Train 43(08), scheduled to operate with locomotive E/613 and 7 cars, experienced a delay departing New York Sunnyside Yard due to the need to shop car C/25060, which had been bad-ordered for an inoperative HVAC blower. To maintain consist integrity, car C/25124 was added in its place. After the equipment substitution was completed, the trainset was transported to New York Penn Station, where 239 customers were boarded.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
43(08)	1'20"	

Train 2205(08) New York, NY - Engine Issue, Late Yard Release

08MAR26: Train 2205(08), operating with Next Generation Trainset 14 (PC/2124-9 cars-PC/2104), experienced a delay departing New York Sunnyside Yard due to a missing door handle on the west power car PC/2104. High-Speed Mechanical personnel responded, inspected the issue, and subsequently cleared the train for movement. Trainset 14 was then transported to New York Penn Station, where 174 customers were boarded. This delay also resulted in a late turn for Train 2218(08) in Washington, DC.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2205(08)	2'09"	
2218(08)	19"	LATE TURN

Train 42(08) Pittsburgh, PA - Engine Failure / Train Control

08MAR26: Train 42(08), scheduled to operate with locomotive E/85 and 6 cars, experienced a delay departing Pittsburgh, PA after E/85 was bad-ordered due to train control system issues. To facilitate movement, it became necessary to secure a freight locomotive to lead the consist between Pittsburgh and Harrisburg. Norfolk Southern delivered locomotive NS 4109; however, the unit arrived facing west, requiring crews to wye the locomotive before coupling it to the Amtrak consist. After the locomotive was correctly positioned, crews recoupled the equipment, completed all required air tests, and Train 42(08) subsequently departed Pittsburgh with 219 customers onboard.

Train 42(08) experienced further delay at Harrisburg, PA removing the NS freight unit and adding E/606.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
42(08)	2'36"	
42(08)	55"	HAR
42(08)	23"	Add Engine 613 at PHL

CSX Trackwork effecting Carolinian, Floridian, and Northeast Regional Service - M of W Work

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

23FEB26: Due to CSX Trackwork on the North End subdivision between Petersburg, VA MP A42.0 and Rocky Mount, NC MP A104.0 from Monday February 23 to Monday March 2 and Monday March 9 to Monday March 16. The following service adjustments have been made for the Carolinian, Floridian and Northeast Regional Service.

Carolinian

- Train 80 (23Feb-16Mar) will operate 45-minutes LATER between CLT and RGH, 2-hours LATER between RGH and WAS, 2 hours 10-minutes LATER between WAS and PHL, and 2 hours 20-minutes LATER between PHL and NYP.

Floridian

- Train 40 (22Feb-15Mar) will operate on their normal schedule between MIA and SAV, and then will operate 1 hour 30-minutes LATER between SAV and RGH and 2 hours 45-minutes LATER between RGH and CHI.

Northeast Regional

- Train 94 (23Feb, 24Feb) will operate 3 hours 10-minutes LATER between NFK and WAS.

2/26/26 - Trains 40(25), 90(26), 80(26) and 79(26) were all delayed between Petersburg, NC and Rocky Mount, NC for a 4-way passenger train meet as a result of CSXM807 in penalty at Stony Creek Interlocking in the affected track work location..

WBS#: B.TR.100150.6471

Train	Delay	Comment
40(25)	27"	
79(26)	18"	
90(26)	12"	
80(26)	1'52"	PTI 40 / MW

Maintenance of Way Highlights

Long Bridge Replacement Outage - Scheduled M/W Work

18DEC25: Starting January 12, 2026 CSX Long Bridge replacement trackwork will commence causing reduced service and schedule changes extended through March 13, 2026 as follows:

January 11th will commence transition plan with 195 terminating New York and 153 terminating Washington D.C.

Monday through Friday: 114 cancelled, 133 cancelled, 141 terminates Washington D.C., 85 terminates Washington D.C., 176 originates Washington D.C., 174 originates Washington D.C., 84 originates Washington D.C., 134 originates Washington D.C., 86 originates Newport News, VA, 178 originates Roanoke, VA.

New trains operating Monday through Friday : 113 originating New York, NY and 198 originating Washington D.C.

Saturday: 167 terminates Philadelphia, PA, 153 terminates Washington D.C., 195 terminates Washington D.C., 155 operates through to Norfolk, VA, 164 originates Newport News, VA, 194 originates Washington D.C., 128 originates Norfolk, VA, 88 originates Washington D.C., 82 originates Washington D.C.

New train operating Saturday: 109 originates New York, NY

Sunday: 106 cancelled, 107 cancelled, 157 terminates Washington D.C., 155 operates through to Norfolk, VA, 195 terminates Washington D.C., 128 originates Norfolk, VA, 96 originates Washington D.C., 88 originates Washington D.C.

New trains operating Sunday: 117 originates Philadelphia, PA, 100 originates Washington D.C.

WBS#: B.TR.100150.6327

Eastern Region

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
50 (7)	MAY	CSX965	E/373 tree strike	WAS	3/9/26

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Train 6(08) West of Elko, NV - Manually Line Switches

09MAR26: Train 6(08) with engines 25,4 and 8 cars with 132 customers on board was delayed at MP 534.5, 24 miles west of Elko, NV on the UPRR Elko subdivision due to improper routing. The switch had to be manually operated. The train encountered another improperly lined switch at MP 557 that had to be manually thrown. After throwing the switch, the train advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(08)	39"	

Train 703(08) East of Merced, CA - Trespasser Incident

08MAR26: 939PM-PT, Train 703(08) with E/C2006 and eight cars was delayed 10 miles east of Merced on the BNSF Stockton subdivision due to striking a gray vehicle with a single occupant at Mission Ave/MP 1045.505 (DOT#028645R) in Planada, California located in Merced County. There was 102 customers on board and no reported injuries to the passengers or the crew. Local authorities responded to the scene for an investigation. HEP remained live throughout the disruption. The weather was 59 degrees and clear. The crew requested and was granted relief. Once the vehicle was cleared of the tracks and the tracks were inspected, the crew advanced the train to Merced to meet an Amtrak Road Foreman with a relief crew. Once the relief crew was onboard and briefed, train 703(08) departed Merced at 111AM-PT, 4 hours late.

National Response Center Number: 1456715

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(08)	2'11"	
703(08)	1'06"	MCD - relief crew

Train 22(08)/422(06) South of Texarkana, AR - Signal

08MAR26: Train 22(08)/422(06) was delayed three miles south of Texarkana on the UPRR Little Rock subdivision due to signal issues at MP 2.4, which required the crew to work the signal box.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(08)/422(06)	34"	

Train 519(08) Vancouver, BC - Signal

08MAR26: Train 518(09) was delayed south of Vancouver, BC at the Fraser River Bridge on the Canadian National New Westminster Subdivision. There were signal and switch issues which required the train crew to manually operate the dual-control main track switches on verbal instruction from the train dispatcher. Once the switches were properly lined, train 519(08) was required to operate at reduced speeds until clear of the affected area, afterwhich the crew was able to resume operation at maximum authorised track speeds.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
519(08)	39"	

Train 748(08) South of Oakland, CA - Trespasser Incident

08MAR26: Train 748(08) with engines CDTW 8311 and 52 with 52 passengers on board struck a trespasser at MP 12.74, half a mile south of Oakland Coliseum in San Leandro, CA located in Alameda County on the UPRR Niles subdivision. There were no reported injuries to the passengers or crew. The trespasser was found to be alive and not bleeding. Local authorities responded to the scene for an investigation. The trespasser was transported to the hospital. The train maintained HEP throughout the disruption. Once the investigation was complete and the train was released, the crew advanced the train to Oakland, CA and were granted relief. Train 748(08) departed Oakland at 1030PM-PT, 1 hour, and 19 minutes late. As a result, train 14(08) was delayed at Sacramento holding for connections.

National Response Center Number: 1456717

Train	Delay	Comment
748(08)	52"	
748(08)	25"	OKJ - Relief crew
14(08)	1'02"	SAC - held for connections

Train 1008/1028(07) West of Glasgow, MT - Freight Train Interference

08MAR26: Train 1008/1028(07) with engines 343,353 and 10 cars with 119 customers on board was delayed at MP 288.1, 4.5 miles west of Glasgow, MT on the BNSF Milk River subdivision due to meeting two freight trains. Train 1008/1028(07) met BNSF 7497 and BNSF 3676 before advancing to the next station.

Train	Delay	Comment
1008/1028(07)	24"	BNSF 7497
1008/1028(07)	19"	BNSF 3676

Train 8(08) Seattle, WA - Car Failure

08MAR26: Train 8(08) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. There was a problem with a bathroom on an unknown coach car which required correction prior to departing the initial terminal. Once repairs were complete, train 8(08) departed SEA at 6:51 PM-PT.

Train	Delay	Comment
8(08)	1'56"	

Train 743(08) Suisun-Fairfield, CA - Drawbridge Opening

08MAR26: Train 743(08) was delayed east of Suisun - Fairfield, CA (SUI) at CP RV035 on the Union Pacific Railway Martinez Subdivision. The movable lift-span of the Suisun Bay Bridge was raised to allow the safe passage of maritime traffic. Once the maritime traffic was clear, train 743(08) was able to resume operation at 5:03 PM-PT.

Train	Delay	Comment
743(08)	31"	
738(08)	10"	
745(08)	26"	

Train 1007/1027(07) West of Shelby, MT - Freight Train Interference

08MAR26: Train 1007/1027(07) was delayed three miles west of Shelby on the BNSF Hi Line subdivision at Teton/MP 1068.2, meeting BNSF 6223, 6972, and 6329.

Train	Delay	Comment
-------	-------	---------

Train 364(08) East of Battle Creek, MI - Police Related

08MAR26: Train 364(08) was delayed 13 minutes east of Battle Creek on the CN Flint subdivision at Sands Road/MP 188.45 (DOT#283569Y) due to meeting the Battle Creek Police Department to remove an unruly passenger. The passenger became physical with the conductors while waiting for the police to arrive. The conductors were evaluated by EMS and completed paperwork with the local police.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(08)	1'42"	

Train 382(08) East of Macomb, IL - Freight Train Interference

08MAR26: Train 382(08) was delayed two miles east of Macomb on the BNSF Brookfield subdivision, following BNSF 6793 between MP 200.5 and MP 189.0 as well as meeting BNSF 5517 at East Bushnell/MP 189.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
382(08)	30"	Follow BN 6793
382(08)	23"	Meet BN 5517

Train 712(08) Madera, CA - Third Party Contractor Engine Failure

08MAR26: Train 712(08) was delayed east of Madera, CA (MDR) at MP 1011.8 on the Burlington Northern Santa Fe Railway Stockton Subdivision. Locomotive CDTX/2006 failed to provide Head End Power (HEP).; forcing the crew to bring the train to a safe stop and inspect as HEP is required to operate cab car first. Inspection found the HEP Auxiliary Motor to have shut down with a over temperature fault. The crew was able to reset the fault and restart the HEP motor. Train 712(08) was able to resume operation at 2:47 PM-PT.

This same fault occurred multiple times throughout the trip, each time the crew was able to resolve the issue and train was able to resume operation.

Duration of HEP Loss:

- 25" at MP 1011.8
- 20" at CP Guernsey
- 10" at Wasco, CA (WAC)

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(08)	29"	MP 1011
712(08)	31"	CP Guernsey
712(08)	17"	WAC
703(08)	28"	BFD - Equipment turn from inbound 712(08)

Train 1003(07) Albuquerque, NM - Engine Failure

08MAR26: Train 1003(07) with E/44-194 and eight cars was delayed departing Albuquerque/MP 902.45 on the NMRX Albuquerque subdivision due to setting out E/44 for brake apparatus melted to the wheel. E/44 was set out on the 314 track for repair. Once the set out was complete, train 1003(07) departed Albuquerque at 623PM-MT, 1 hour, and 49 minutes late. Further delay was accumulated on the BNSF Gallup subdivision at Gallup/MP 157.6 due to adding BNSF 4135. The crew reported BNSF 4135 with air issues and unable to get past 90 PSI with a rapid responder on scene assisting. The air issues were rectified and followed by PTC issues. Inevitably, BNSF 4135 was bad ordered for PTC issues and set out at Gallup. Train 1003(07) departed Gallup at 226AM-MT, 7 hours, and 12 minutes late. An Amtrak relief crew was enroute from Kingman towards Winslow with BNSF pilots.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1003(07)	1'29"	

Train 364(08) Initial Terminal Delay at Chicago, IL - Equipment Failure

08MAR26: Train 364(08) arrived E/58 and 9 UNCLASSIFIED 4/29/2026 customers on board was delayed departing Chicago, IL/MP 0.0 on the Amtrak Chicago South subdivision due to the marker light on the back of the equipment not working. Mechanical forces responded to the train. They attempted to fix the marker light. It was found that a wire in the nose of the device was bad. Mechanical added on an end of train device and tagged the locomotive as non-compliant. Train 364(08) departed Chicago at 5:58 PM-CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
364(08)	1'58"	

Train 22(08)/422(06) South of Fort Worth, TX - Passenger Train Interference

08MAR26: Train 22(08)/422(06) was delayed 12 miles south of Fort Worth on the BNSF Fort Worth subdivision at Crowley/MP 334.2 due to meeting train 21(07).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(08)/422(06)	30"	

Train 1(07)/421(06) East of El Paso, TX - Freight Train Interference

08MAR26: Train 1(07)/421(06) was delayed at McNary/MP771, 61 miles east of El Paso, TX, on the UPRR Valentine Subdivision, in behind UP5467 meeting UP5480, and then following UP 5467 to Iser/MP784.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(07)/421(06)	35"	

Train 2(06) West of Beaumont, TX - Signal

08MAR26: Train 2(06) with 157 passengers was delayed 24 miles west of Beaumont, TX at MP 429 on the UPRR Beaumont subdivision due to a communication issue causing a switch failure. Train 2(06) shoved out of Houston, TX station to Chaney Junction and then was flagged through Beaumont subdivision.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(06)	40"	

Train 58(08) North of Hammond, LA - Passenger Train Interference

08MAR26: Train 58(08) was delayed three miles north of Hammond on the CN McComb subdivision due to meeting train 59(07) at Natalbany/MP 856.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(08)	37"	

Train 7(07) West of Spokane, WA - Freight Train Interference

08MAR26: Train 7(07) was delayed at Edwall/MP1509.9, 29 miles west of Spokane, WA, on the BNSF Columbia River Subdivision, meeting BNSF 4094.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(07)	36"	

Train 1006(07) East of Helper, UT - Signal

08MAR26: Train 1006(07) delayed 30 minutes at 25 miles east of Helper, UT at MP 602.0 on the UPRR Green River subdivision. The train received restrictive signals for unknown reasons, which required flagging from MP 602 to MP 594.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1006(07)	30"	

Train 22(08)/422(06) South of Temple, TX - Freight Derailment

08MAR26: Train 22(08)/422(06), with 209 passengers, was delayed at MP880.8, 1 mile south of Temple, TX, on the UPRR Waco Subdivision, due to BNSF yard job derailed ahead at Temple and came into contact with a BNSF freight on the Main. Train 22(08)/422(06) was delayed holding for the freight on the Main consist to be split and pulled in the clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(08)/422(06)	1'37"	

Train 1008/1028(07) East of Whitefish, MT - High Wind Warnings

08MAR26: Train 1008/1028(07) was delayed east of Whitefish, MT/MP1219.3, on the BNSF Hi Line and Milk River Subdivisions, due to high wind warnings in effect across both subdivisions. Train 1008/1028(07) was delayed operating reduced speed through the affected areas between Whitefish, MT and Glasgow, MT. Train 1007/1027(07) was delayed west of Williston, ND/MP 121.1, on the BNSF Glasgow and Milk River subdivisions, operating through high wind warnings between MP 215.0 and MP 427.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1008/1028(07)	2'22"	E/WFH
1007/1027(07)	2'15"	W/WTN

Train 1008/1028(07) East of Libby, MT - Freight Train Interference

08MAR26: Train 1008/1028(07) was delayed at River View/MP1305, 14 miles east of Libby, MT, on the BNSF Kootenai River Subdivision, meeting BNSF 6972 and BNSF 7246. Train 1008/1028(07) was further delayed at Brimstone/MP1251.8, meeting BNSF 7520 and at Vista/MP1228 meeting BNSF 6558.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1008/1028(07)	28"	MP1305
1008/1028(07)	52"	MP1251.8
1008/1028(07)	39"	MP1228

Train 353(08) Dearborn, MI - Engine Failure

08MAR26: Train 353(08) with IDTX4611 and 139 passengers onboard was delayed departing Dearborn, MI station at MP 9.7 on the MDOT Michigan line. The crew reported experiencing multiple issues with ITCS. Troubleshooting with CNOC mechanical and the road foreman could not rectify the issue. They were instructed to cut out ITCS and proceed under rule 595, operating not exceeding 59mph for the remainder of their run.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
353(08)	33"	
353(08)	1'08"	Residual delay for operating at reduced speed

Train 318(08) - Car Failure

08MAR26: Train 318(08) with E/111, 10 cars and 100 passengers was over capacity at St. Louis, MO due to car 4018 having no power. A supplemental bus was secured to run from St. Louis, MO to Chicago, IL, making one stop in Joliet, IL.

WBS#: B.TR.100150.6529

Train 58(07) North of Jackson, MS - Weather

08MAR26: Train 58(07) with E/192, 7cars and 134 passengers was delayed 1.4 miles north of Jackson, MS at MP 218.6 on the CN McComb subdivision due to downed trees. There was an additional delay 10 miles south of Yazoo City, MS at MP 185 on the CN Yazoo subdivision due to downed power lines.

Train	Delay	Comment
58(07)	1'42"	

Train 50(07) Terminated Maysville, KY - Debris

08MAR26: Train 50(07) with E/373, 6 cars and 60 passengers struck a tree 1 mile west of Maysville, KY at MP 603.4 on the CSX Cincinnati subdivision at 635AM-ET. The strike disabled the train on account of E/373 suffering a shattered windshield resulting in minimal visibility. No injuries were report to passengers or crew. The train had a temporary loss of head end power of approximately 15 minutes. The crew was able to restore head end power after troubleshooting with CNOC mechanical. At 815AM-ET, CSX was able to guide the train, at restricted speed, into Maysville station, to allow passengers to detrain comfortably. A caretaker was onsite to assist. A CSX freight locomotive, CSX-965, was secured out of Russell, KY, 70 miles away from Maysville, KY. Two buses were also secured to transport passengers through to Washington, DC, making all stops except Thurmond, WV. The buses arrived at 330PM-ET and loaded all passengers before departing at 345PM-ET. As a result, train 50(07) was terminated at Maysville. Once the CSX freight arrived on scene and was added to the consist, the equipment deadhead to Washington, DC.

WBS#: B.TR.100150.6527

Train	Delay	Comment
50(07)	Terminated MAY	
50(07)	7'33"	Delay to psgrs at MAY

Major Multi Agency Trackwork - Surfliner & Coast Starlight

07MAR26: Commencing 26-FBI-00368 00000008081 UNCLASSIFIED 4/29/2026 07th and 8th March 2026. Metrolink Railroad will conduct work to upgrade tracks at various locations on the Ventura and Orange Subdivision. This work will coincide with planned track outages by the Union Pacific Santa Barbara Subdivision and North County Transit San Diego Subdivision . For the duration of the project, all Surfliner trains will be cancelled with no alternate transportation offered. Coast Starlight services will Originate and Terminate in Emeryville. Below is a summary of changes:

Coast Starlight

Saturday March 7th and Sunday March 8th.

Train 11(06-07). Will terminate in Emeryville. Passengers for missed stops Emeryville (EMY) thru San Jose (SJC) may use Capitol Corridor Services where connections to Salinas, Paso Robles and San Luis Obispo and stations to Los Angeles may also be made. There is no alternative transport to Simi Valley (SIM). Other connecting services may be utilized via 710(07-08) - connecting in Martinez- using thruway connections from Bakersfield.

Train 14(07-08), Will Originate in Emeryville. Passengers Boarding in Los Angeles may utilized services via 5815/5915(07-08) and 715(07-08) using thruway connections from Bakersfield to connect with 14 via Stockton at Sacramento.

There are no alternate transport from Glendale(GDL) or Burbank(BUR) along the coast..

Passengers travelling to Chico and Redding may use combinations 5713/713/3713/3763(07-08).

Passengers boarding in Burbank (BUR) may utilize travel options to Sacramento and Bay Area via 5717/717/3717(07-08).

Thruway 4765(07-08) from Santa Barbara will serve stations thru San Luis Obispo, Paso Robles, Salinas, and San Jose, and San Francisco transferring to 748(07-08) for stations between San Jose to Emeryville and Sacramento. There are no possible connections beyond Redding for the duration of the project.

Pacific Surfliner

Saturday March 11th and Sunday March 12th

Services between San Diego and Goleta/San Luis Obispo, also services San Diego to Los Angeles are suspended. No specific alternate transportation will be offered.

WBS#: B.TR.100150.6492

Train	Delay	Comment
14(07-08)	Originates	Emeryville
11(06-07)	Terminates	Emeryville
562(07-08)	Cancelled	
564(07-08)	Cancelled	
566(07-08)	Cancelled	
572(07-08)	Cancelled	
580(07-08)	Cancelled	
584(07-08)	Cancelled	
586(07-08)	Cancelled	
588(07-08)	Cancelled	
770(07-08)	Cancelled	
782(07-08)	Cancelled	
774(07-08)	Cancelled	
790(07-08)	Cancelled	
794(07-08)	Cancelled	
567(07-08)	Cancelled	
573(07-08)	Cancelled	
579(07-08)	Cancelled	
581(07-08)	Cancelled	
587(07-08)	Cancelled	
591(07-08)	Cancelled	
593(07-08)	Cancelled	
595(07-08)	Cancelled	
761(07-08)	Cancelled	
765(07-08)	Cancelled	
769(07-08)	Cancelled	
777(07-08)	Cancelled	
785(07-08)	Cancelled	

21DEC25: As a result of high shop counts for state supported services at Oakland Maintenance Facility; to maintain service levels the following modifications were made to Gold Runner/ Capitol Corridor Service trains:

26-FOI-00361 00000006081 "UNCLASSIFIED" 4/29/2026

21DEC25

- 715(21) Terminate Emeryville, CA (EMY) with passengers accommodated to Oakland, CA (OKJ) on bus 6615, operating EMY-OKJ-SFC.
- 718(21) Originate Emeryville, CA (EMY) with passengers accommodated from Oakland, CA (OKJ) on train 744(21) OKJ-EMY.

22DEC25

- 714(22) Locomotive Failure at Oakland Maintenance Facility (OMF), last minute equipment change.
- 718(22) Held at Oakland Maintenance Facility (OMF) for serviceable equipment. Train originate Emeryville, CA (EMY) with passengers accommodated on train 544(22) OKJ-EMY.
- 716(22) Modified Equipment Turn at OMF from 711(21) after repairs completed.

23DEC25

- 714(23) Cancelled. Locomotive Failure CDTX2004 at Oakland Maintenance Facility (OMF).
- 713(24) Cancelled. Turn of equipment from cancelled train 714(23).

24DEC25

- 520(24) Cancelled . Locomotive Failure CDTX2004/CDTX 2107 at Oakland Maintenance Facility (OMF).
- 535(24) Cancelled. Turn of equipment from cancelled train 520(24).
- 534(24) Cancelled. Locomotive Failure CDTX 2107 at Oakland Maintenance Facility (OMF).

25DEC25 - 28DEC25

- Train 736(25-28) Cancelled - No alternate transportation.
- Train 737(25-28) Cancelled - No alternate transportation.
- Train 749(28) Cancelled - No alternate transportation - balance fleet for morning service.

29DEC25 - 30DEC25

- Train 520(29-30) Cancelled - No alternate transportation.
- Train 534(29-30) Cancelled - No alternate transportation.
- Train 535(29) Cancelled - No alternate transportation.
- Train 537(30) Cancelled - No alternate transportation.
- Train 551(29-30) Cancelled - Replacement bus Sacramento, CA to Oakland, CA.

31DCE25

- Train 520(31) Cancelled - No alternate transportation.
- Train 534(31) Cancelled - No alternate transportation.
- Train 537(31) Cancelled - No alternate transportation.

01JAN26 - 04JAN26

- Train 736(01-04) Cancelled - No alternate transportation.
- Train 737(01-04) Cancelled - No alternate transportation.

05JAN26- 13MAR26

- TRAIN 714(05JAN-12MAR) Cancelled - No alternate transportation.
- TRAIN 713(06JAN-13MAR) Cancelled - No alternate transportation.

10JAN26 - 11JAN26

- Train 736(10-11) Cancelled - No alternate transportation.
- Train 737(10-11) Cancelled - No alternate transportation.

12JAN26 - 13JAN26

- Train 520(12-13) Cancelled - No alternate transportation.
- Train 534(12-13) Cancelled - No alternate transportation.
- Train 535(12-13) Cancelled - No alternate transportation.

14JAN26:

- Train 520(14) Cancelled - No alternate transportation.
- Train 537(14) Cancelled - No alternate transportation.
- Train 534(14) Cancelled - No alternate transportation.

-Train 535(16) Cancelled - No Alternate Transport offered
-Train 537(15) Cancelled - No Alternate Transport offered

17JAN26:

-Train 718(17) Delayed at Oakland Maintenance Facility while crews worked to repair locomotive CDTX/2101. Train originated from Emeryville, CA (EMY) with passengers accommodated on train 744(17) OKJ-EMY.

21JAN26:

-Train 526(21) Cancelled - No Alternate Transport offered
-Train 534(21) Cancelled - No Alternate Transport offered
-Train 535(21) Cancelled - No Alternate Transport offered

23JAN26:

-Train 520(23) Cancelled - No Alternate Transport offered
-Train 534(23) Cancelled - No Alternate Transport offered
-Train 535(23) Cancelled - No Alternate Transport offered
-Train 736(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 737(23JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 520(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 526(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 534(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 531(26JAN-01MAR) Cancelled - No Alternate Transportation.
-Train 537(26JAN-01MAR) Cancelled - No Alternate Transportation.

01FEB26:

-Train 732(01FEB) Cancelled - No Alternate Transportation.
-Train 749(01FEB) Cancelled - No Alternate Transportation.
-Train 712(02FEB-04FEB) Cancelled - No Alternate Transportation.
-Train 717(02FEB-04FEB) Cancelled - No Alternate Transportation.

Cause: Pending

WBS#: B.TR.100150.6340

Train	Delay	Comment
715(21)	Terminate EMY	Passengers to bus 6615 EMY-OKJ-SFC
718(21)	Originate EMY	Passengers to 744(21) OKJ-EMY
718(22)	Originate EMY	Passengers to 544(22) OKJ-EMY
714(22)	1'07"	ITD - OKJ - Late change of equipment
718(21)	37"	ITD - EMY
716(22)	20"	
718(22)	3'10"	ITD - EMY
749(28)	Cancelled	Balance Fleet to Protect Morning Service - Passengers to 751(28)
718(17)	Originate EMY	Pax to 744 OKJ-EMY
718(17)	35"	

Maintenance of Way Highlights

Western Region

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
1003 (7)	ABQ	44		Brakes

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
1003 (7)	GLP	BNSF4135	E/44 S/O in ABQ due to brakes		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Thruway 4010(08) Passenger Removal at Paso Robles, California – Medical

08MAR26, Passenger on PNR A160C7, traveling from Hanford, CA to Atascadero, CA was reportedly removed by EMS due to a medical issue and taken to a local hospital. Amtrak Police notified.

Delay: 4010 (08) None

Consist Deviations

26-FOI-00361

00000006081

"UNCLASSIFIED"

4/29/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
236 (09)	ALB	ALB will shop 48160 due B/O trucks with no replacement. As a result, 16 Business Class passengers will be downgraded.	YES	16	48160
244 (09)	ALB	ALB will shop 48160 due B/O trucks with no replacement. As a result, 16 Business Class passengers will be downgraded.	YES	16	48160
244 (08)	ALB	ALB shopped 48160 due B/O trucks off 244(08), 12 Business Class passengers have been displaced.	YES	12	48160
233 (09)	NYP	ALB will shop 48160 due B/O trucks with no replacement. As a result, 16 Business Class passengers will be downgraded.	YES	16	48160
243 (09)	NYP	ALB will shop 48160 due B/O trucks with no replacement. As a result, 5 Business Class passengers will be downgraded.	YES	5	48160
245 (08)	NYP	ALB shopped 48160 off 244(08) due B/O trucks with no replacement. 4 Business Class passengers have been downgraded.	YES	4	48160
127 (08)	NYP	A-end of Business Class car 81529 not against consist.	NONE	0	81529
126 (08)	WAS	A-end of Business Class car 81529 not against consist.	NONE	0	81529

Reverse Consists

Train Number	Station	Reason
158 (08)	NFK	Consist reversed Business class seat orientation may have changed At Front
109 (08)	NYP	Consist reversed Business class seat orientation may have changed At Front
127 (08)	NYP	Consist reversed Business class seat orientation may have changed At Rear
126 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front
128 (08)	WAS	Consist reversed Business class seat orientation may have changed At Rear
163 (08)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00361	00000006081 "UNCLASSIFIED" 4/29/2026
101 (08)	NYP	Business class change only Business class seating orientation may have changed At Rear	
194 (08)	WAS	Business class change only Business class seating orientation may have changed At Rear	
127 (08)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
126 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front	
140 (08)	WAS	Consist reversed Business class seat orientation may have changed At Front	
143 (09)	SPG	Consist reversed Business class seat orientation may have changed At Front	