



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, December 03, 2025

Rules: 0-6



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/02/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	309	47	84.8%	620	96	84.5%	18,533	2,287	87.7%
Central Division	85.5%	66	10	84.8%	133	24	82.0%	4,157	393	90.5%
Northeast Division	80.0%	100	15	85.0%	200	26	87.0%	5,797	778	86.6%
Southeast Division	72.5%	73	9	87.7%	147	21	85.7%	4,347	539	87.6%
Southwest Division	77.0%	70	13	81.4%	140	25	82.1%	4,232	577	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00167 00000005501 UNCLASSIFIED 12/17/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	88,343	22,798	74%	213,407	51,384	76%	6,471,233	1,306,549	80%
Northeast Corridor	81%	39,320	10,516	73%	97,036	22,804	76%	2,919,602	545,620	81%
Acela	83%	10,612	3,749	65%	21,390	5,701	73%	615,682	123,637	80%
Northeast Regional	79%	28,708	6,767	76%	75,646	17,103	77%	2,303,920	421,983	82%
Richmond / Newport News / Norfolk	77%	9,447	2,848	70%	23,339	7,798	67%	701,052	153,374	78%
Springfield Shuttles	89%	711	110	85%	1,831	287	84%	42,169	4,963	88%
Roanoke	79%	2,576	559	78%	6,323	615	90%	176,840	27,768	84%
On Spine Northeast Regional	80%	15,974	3,250	80%	44,153	8,403	81%	1,383,859	235,878	83%
State Supported	80%	35,262	7,530	79%	84,379	16,340	81%	2,757,205	499,701	82%
Borealis	60%	464	142	69%	1,096	142	87%	37,574	9,776	74%
Capitol Corridor	90%	3,975	408	90%	7,989	586	93%	240,080	25,493	89%
Carolinian	60%	1,095	373	66%	2,334	393	83%	75,968	21,330	72%
Cascades	63%	1,475	267	82%	4,142	1,445	65%	151,246	36,869	76%
Downeaster	82%	887	0	100%	2,238	93	96%	96,287	11,910	88%
Empire	78%	3,868	654	83%	10,299	2,299	78%	333,591	65,713	80%
Adirondack	72%	219	133	39%	645	133	79%	21,646	6,722	69%
Ethan Allen Express	70%	382	26	93%	1,043	26	98%	38,321	11,691	69%
Maple Leaf	70%	570	325	43%	1,542	477	69%	41,740	13,712	67%
New York - Albany	85%	1,636	149	91%	4,325	457	89%	144,371	19,767	86%
New York - Niagara Falls	75%	1,061	21	98%	2,744	1,206	56%	87,513	13,821	84%
Gold Runner	73%	1,912	977	49%	5,508	1,402	75%	161,448	57,620	64%
Heartland Flyer	65%	104	60	42%	324	60	81%	12,886	7,631	41%
Hiawatha	90%	1,389	473	66%	3,080	1,134	63%	111,091	12,144	89%
Illinois	78%	1,901	655	66%	5,542	1,883	66%	155,987	41,354	73%
Carl Sandburg / Illinois Zephyr	85%	387	219	43%	770	348	55%	26,101	6,936	73%
Illini / Saluki	85%	396	99	75%	1,440	122	92%	56,502	13,638	76%
Lincoln Service	70%	1,118	337	70%	3,332	1,413	58%	73,384	20,780	72%
Keystone	92%	7,504	1,616	78%	16,801	2,322	86%	527,370	44,279	92%
Lincoln / Missouri	60%	697	384	45%	1,516	721	52%	50,082	25,528	49%
Mardi Gras Service	80%	269	0	100%	400	0	100%	27,276	3,722	86%
Michigan	69%	1,856	893	52%	3,700	1,846	50%	98,377	25,766	74%
Blue Water	70%	785	580	26%	1,194	580	51%	32,097	7,899	75%
Pere Marquette	85%	233	0	100%	542	0	100%	16,521	1,932	88%
Wolverine	65%	838	313	63%	1,964	1,266	36%	49,759	15,935	68%
Missouri	80%	164	100	39%	410	167	59%	14,910	3,680	75%
Pacific Surfliner	85%	5,003	382	92%	12,569	1,032	92%	431,997	59,944	86%
Pennsylvanian	72%	845	64	92%	1,763	135	92%	58,935	6,084	90%
Piedmont	73%	732	77	89%	2,244	77	97%	87,089	21,977	75%
Vermont	75%	1,122	5	100%	2,424	603	75%	85,011	18,881	78%
Long Distance	56%	13,761	4,752	65%	31,992	12,240	62%	794,426	261,228	67%
Auto Train	57%	754	0	100%	1,620	471	71%	41,638	7,722	81%
California Zephyr	50%	947	283	70%	2,208	1,139	48%	59,285	16,860	72%
Cardinal	55%	0	0	-	408	0	100%	17,789	8,314	53%
City Of New Orleans	75%	680	1	100%	1,568	153	90%	45,003	9,919	78%
Coast Starlight	60%	1,032	175	83%	3,478	1,275	63%	74,357	23,791	68%
Crescent	70%	891	54	94%	2,222	119	95%	61,338	15,924	74%
Empire Builder	55%	1,331	193	85%	2,734	1,521	44%	65,377	22,357	66%
Floridian	40%	2,078	771	63%	4,650	2,357	49%	108,997	56,932	48%
Lake Shore Ltd	73%	1,138	613	46%	2,535	1,219	52%	58,666	9,526	84%
Palmetto	65%	992	595	40%	2,062	994	52%	62,134	9,446	85%
Silver Meteor	45%	1,053	263	75%	2,529	507	80%	65,634	18,915	71%
Southwest Chief	40%	959	851	11%	2,136	1,264	41%	54,111	31,789	41%
Sunset Ltd	70%	335	25	93%	786	27	97%	17,636	4,400	75%
Texas Eagle	50%	1,571	928	41%	3,056	1,194	61%	62,461	25,333	59%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00107 00000005501 "UNCLASSIFIED" 12/17/2025

Train Index Dates Through December 02, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	12,081	218,627	553	343,205	6,727,482	510

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	371	66,705	56	12,695	1,968,941	64
INFRASTRUCTURE PLANNED	135	196	66,705	29	10,777	1,968,941	55
FLEET RELIABILITY	90	1,891	218,627	86	49,557	6,727,482	74
TRAIN OPERATIONS	424	9,623	218,627	440	270,176	6,727,482	402

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/02/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	309	47	84.8%	620	96	84.5%	18,533	2,287	87.7%
Central Division	85.5%	66	10	84.8%	133	24	82.0%	4,157	393	90.5%
Northeast Division	80.0%	100	15	85.0%	200	26	87.0%	5,797	778	86.6%
Southeast Division	72.5%	73	9	87.7%	147	21	85.7%	4,347	539	87.6%
Southwest Division	77.0%	70	13	81.4%	140	25	82.1%	4,232	577	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-001

12/02/2025

1000000

12/02/2025

1000000

12/02/2025

1000000

12/02/2025

1000000

12/02/2025

1000000

12/02/2025

Scheduled Departure Date: 12/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/02/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	309	47	84.8%	620	96	84.5%	18,533	2,287	87.7%
Central Division	85.5%	66	10	84.8%	133	24	82.0%	4,157	393	90.5%
CDL	90.0%	1	0	100.0%	3	0	100.0%	117	6	94.9%
CHI	85.0%	27	5	81.5%	54	11	79.6%	1,688	148	91.2%
EUG	86.5%	2	1	50.0%	4	3	25.0%	121	18	85.1%
GRR	98.0%	1	0	100.0%	2	0	100.0%	63	0	100.0%
KCY	84.5%	2	1	50.0%	4	1	75.0%	124	12	90.3%
MKE	86.5%	6	2	66.7%	12	3	75.0%	368	33	91.0%
MSP	94.0%	1	0	100.0%	2	0	100.0%	63	3	95.2%
PDX	78.0%	5	0	100.0%	10	1	90.0%	316	47	85.1%
PNT	91.5%	3	0	100.0%	6	0	100.0%	133	5	96.2%
PTH	93.0%	1	0	100.0%	2	0	100.0%	63	2	96.8%
QCY	87.5%	2	0	100.0%	4	0	100.0%	126	12	90.5%
SEA	80.0%	8	1	87.5%	16	4	75.0%	501	78	84.4%
SPK	92.0%	1	0	100.0%	2	0	100.0%	63	1	98.4%
STL	88.0%	4	0	100.0%	8	1	87.5%	250	19	92.4%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	4	0	100.0%	126	4	96.8%
Northeast Division	80.0%	100	15	85.0%	200	26	87.0%	5,797	778	86.6%
ALB	91.5%	7	2	71.4%	14	2	85.7%	381	23	94.0%
BON	43.5%	5	0	100.0%	10	0	100.0%	297	32	89.2%
BOS	86.5%	20	3	85.0%	40	4	90.0%	1,138	107	90.6%
BRK	88.0%	5	0	100.0%	10	0	100.0%	277	13	95.3%
BTN	48.0%	1	0	100.0%	2	0	100.0%	62	17	72.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	4	1	75.0%	120	10	91.7%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	2	0	100.0%	63	11	82.5%
NFL	96.5%	2	0	100.0%	4	0	100.0%	126	4	96.8%
NHV	75.5%	6	0	100.0%	12	0	100.0%	319	63	80.3%
NYP	77.5%	42	9	78.6%	84	19	77.4%	2,461	449	81.8%
SAB	98.0%	1	0	100.0%	2	0	100.0%	61	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	14	0	100.0%	363	16	95.6%
TWO	84.0%	1	0	100.0%	2	0	100.0%	62	16	74.2%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	73	9	87.7%	147	21	85.7%	4,347	539	87.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	10	0	100.0%	315	25	92.1%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	3	76.9%	26	9	65.4%	706	107	84.8%
LOR	69.5%	1	0	100.0%	2	1	50.0%	63	6	90.5%
MIA	87.5%	2	0	100.0%	4	0	100.0%	126	13	89.7%
MOE	94.0%	2	0	100.0%	4	0	100.0%	126	3	97.6%
NFK	86.0%	3	0	100.0%	6	1	83.3%	176	16	90.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/02/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/02/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	309	47	84.8%	620	96	84.5%	18,533	2,287	87.7%
Southeast Division	72.5%	73	9	87.7%	147	21	85.7%	4,347	539	87.6%
NOL	92.0%	4	0	100.0%	9	0	100.0%	278	14	95.0%
NPN	96.0%	2	0	100.0%	4	0	100.0%	102	8	92.2%
PGH	92.0%	1	0	100.0%	2	0	100.0%	63	1	98.4%
PHL	45.0%	5	3	40.0%	10	6	40.0%	292	129	55.8%
RGH	97.0%	4	0	100.0%	8	0	100.0%	248	3	98.8%
RNK	85.5%	2	0	100.0%	4	0	100.0%	125	14	88.8%
RVM	86.0%	1	0	100.0%	2	0	100.0%	72	11	84.7%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	2	0	100.0%	63	0	100.0%
SFA	70.5%	1	0	100.0%	2	0	100.0%	63	3	95.2%
WAS	70.0%	26	3	88.5%	52	4	92.3%	1,521	181	88.1%
Southwest Division	77.0%	70	13	81.4%	140	25	82.1%	4,232	577	86.4%
ARN	60.5%	1	1	0.0%	2	1	50.0%	63	6	90.5%
BFD	75.5%	6	1	83.3%	12	1	91.7%	359	85	76.3%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	2	1	50.0%	65	18	72.3%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	2	0	100.0%	62	3	95.2%
GTA	72.5%	3	0	100.0%	6	1	83.3%	182	18	90.1%
LAX	77.5%	9	2	77.8%	18	5	72.2%	578	66	88.6%
OKC	96.0%	1	0	100.0%	2	0	100.0%	63	3	95.2%
OKJ	79.0%	12	4	66.7%	24	7	70.8%	684	159	76.8%
SAC	73.5%	14	4	71.4%	28	6	78.6%	816	92	88.7%
SAN	77.0%	12	0	100.0%	24	1	95.8%	717	66	90.8%
SAS	85.0%	1	0	100.0%	2	0	100.0%	63	3	95.2%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	14	1	92.9%	439	41	90.7%
SLO	62.0%	2	0	100.0%	4	1	75.0%	121	12	90.1%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	10	1	90.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2	762	0	0	0.0%	27	4	85.2%	1	0	100.0%	27	4	85.2%
3		2	2	0.0%	63	6	90.5%	2	1	50.0%	63	24	61.9%
4		38	2	1	50.0%	63	7	88.9%	2	2	0.0%	63	40
5		2	1	50.0%	62	8	87.1%	2	1	50.0%	61	7	88.5%
6	52	2	1	50.0%	63	18	71.4%	2	2	0.0%	63	23	63.5%
7		2	0	100.0%	63	4	93.7%	2	1	50.0%	63	8	87.3%
8		2	1	50.0%	63	21	66.7%	2	1	50.0%	63	28	55.6%
11		2	1	50.0%	62	12	80.6%	2	0	100.0%	60	7	88.3%
14		2	0	100.0%	63	9	85.7%	2	0	100.0%	62	18	71.0%
19		2	1	50.0%	63	9	85.7%	2	0	100.0%	63	11	82.5%
20		2	0	100.0%	63	6	90.5%	2	0	100.0%	63	6	90.5%
21		2	1	50.0%	62	9	85.5%	2	1	50.0%	62	12	80.6%
22		2	0	100.0%	63	3	95.2%	2	0	100.0%	62	13	79.0%
23		2	0	100.0%	63	3	95.2%	2	0	100.0%	63	10	84.1%
24		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	6	90.5%
25		2	0	100.0%	63	0	100.0%	2	0	100.0%	63	9	85.7%
26		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	11	82.5%
27		2	2	0.0%	63	3	95.2%	2	1	50.0%	63	11	82.5%
28	73	2	1	50.0%	63	14	77.8%	2	1	50.0%	63	9	85.7%
40		2	0	100.0%	63	9	85.7%	2	0	100.0%	63	22	65.1%
41	92	2	1	50.0%	63	19	69.8%	2	2	0.0%	63	41	34.9%
42		2	0	100.0%	63	1	98.4%	2	0	100.0%	63	9	85.7%
43		2	0	100.0%	63	5	92.1%	2	0	100.0%	63	3	95.2%
48		2	0	100.0%	63	5	92.1%	2	1	50.0%	63	4	93.7%
49	43	2	0	100.0%	63	10	84.1%	2	1	50.0%	63	6	90.5%
52		2	0	100.0%	63	3	95.2%	2	0	100.0%	63	12	81.0%
53		2	1	50.0%	63	6	90.5%	2	1	50.0%	63	9	85.7%
55		2	0	100.0%	44	0	100.0%	2	0	100.0%	44	6	86.4%
56		2	0	100.0%	44	7	84.1%	2	1	50.0%	44	7	84.1%
58		2	0	100.0%	62	2	96.8%	2	0	100.0%	61	7	88.5%
59		2	0	100.0%	61	3	95.1%	2	0	100.0%	61	3	95.1%
63	19	2	0	100.0%	63	21	66.7%	2	1	50.0%	63	30	52.4%
64		2	0	100.0%	62	16	74.2%	2	0	100.0%	62	10	83.9%
66		2	0	100.0%	63	10	84.1%	2	0	100.0%	63	13	79.4%
67		2	0	100.0%	44	2	95.5%	2	0	100.0%	44	7	84.1%
68	23	2	0	100.0%	63	11	82.5%	2	1	50.0%	63	26	58.7%
69		2	0	100.0%	63	7	88.9%	2	0	100.0%	63	7	88.9%
71		2	0	100.0%	63	0	100.0%	2	0	100.0%	63	16	74.6%
72		2	0	100.0%	63	5	92.1%	2	0	100.0%	63	10	84.1%
73		2	0	100.0%	63	1	98.4%	2	0	100.0%	62	33	46.8%
74		2	0	100.0%	63	5	92.1%	2	0	100.0%	63	20	68.3%
75	23	2	0	100.0%	63	2	96.8%	2	1	50.0%	63	29	54.0%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		2	0	100.0%	63	4	93.7%	2	0	100.0%	63	30	52.4%
77		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	22	65.1%
78	13	2	0	100.0%	63	3	95.2%	2	1	50.0%	63	10	84.1%
79		2	0	100.0%	63	11	82.5%	2	0	100.0%	62	11	82.3%
80	82	2	0	100.0%	63	8	87.3%	2	1	50.0%	62	6	90.3%
84		2	0	100.0%	44	3	93.2%	2	1	50.0%	44	6	86.4%
85	43	2	0	100.0%	44	1	97.7%	2	1	50.0%	44	16	63.6%
86	44	2	0	100.0%	44	4	90.9%	2	2	0.0%	44	21	52.3%
89	39	2	1	50.0%	63	13	79.4%	2	1	50.0%	63	7	88.9%
90		2	0	100.0%	63	0	100.0%	2	0	100.0%	63	6	90.5%
93		2	0	100.0%	44	6	86.4%	2	0	100.0%	43	10	76.7%
94	21	2	1	50.0%	44	7	84.1%	2	1	50.0%	44	13	70.5%
95	34	2	0	100.0%	44	1	97.7%	2	1	50.0%	44	12	72.7%
97		2	2	0.0%	63	20	68.3%	2	0	100.0%	63	16	74.6%
98		2	0	100.0%	63	4	93.7%	2	0	100.0%	63	11	82.5%
110		2	0	100.0%	44	19	56.8%	2	0	100.0%	44	3	93.2%
111		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	3	93.2%
112		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	5	88.6%
114	Cncld	2	1	50.0%	44	9	79.5%	1	0	100.0%	43	0	100.0%
119		2	0	100.0%	44	9	79.5%	2	0	100.0%	44	3	93.2%
125	35	2	0	100.0%	44	2	95.5%	2	2	0.0%	44	8	81.8%
129		2	1	50.0%	44	14	68.2%	2	0	100.0%	44	6	86.4%
130		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	4	90.9%
131		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	0	100.0%
133		2	0	100.0%	44	19	56.8%	2	0	100.0%	44	20	54.5%
134	63	2	0	100.0%	44	4	90.9%	2	1	50.0%	44	9	79.5%
136		2	0	100.0%	44	3	93.2%	1	0	100.0%	44	3	93.2%
137		2	0	100.0%	42	8	81.0%	2	0	100.0%	42	10	76.2%
138		2	0	100.0%	44	6	86.4%	2	0	100.0%	44	2	95.5%
141	38	2	0	100.0%	44	3	93.2%	2	1	50.0%	44	9	79.5%
148		2	0	100.0%	44	4	90.9%	2	0	100.0%	43	9	79.1%
151		2	2	0.0%	63	16	74.6%	2	0	100.0%	62	16	74.2%
170	46	2	0	100.0%	41	3	92.7%	2	1	50.0%	41	10	75.6%
171		2	0	100.0%	44	3	93.2%	2	0	100.0%	44	5	88.6%
172	25	2	0	100.0%	44	4	90.9%	2	1	50.0%	44	16	63.6%
173	76	2	1	50.0%	44	3	93.2%	2	1	50.0%	44	16	63.6%
174		2	0	100.0%	44	3	93.2%	2	1	50.0%	44	9	79.5%
175	89	2	1	50.0%	44	3	93.2%	2	2	0.0%	44	10	77.3%
176		2	0	100.0%	44	3	93.2%	2	0	100.0%	44	3	93.2%
177		2	0	100.0%	44	8	81.8%	2	0	100.0%	44	20	54.5%
178		2	0	100.0%	44	7	84.1%	1	0	100.0%	44	5	88.6%
179		2	0	100.0%	44	4	90.9%	1	0	100.0%	44	10	77.3%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181	Cncld	2	1	50.0%	44	7	84.1%	1	0	100.0%	43	1	97.7%
182		2	0	100.0%	44	9	79.5%	2	0	100.0%	44	3	93.2%
183	29	2	0	100.0%	44	11	75.0%	2	1	50.0%	44	7	84.1%
184		2	0	100.0%	44	8	81.8%	2	0	100.0%	44	5	88.6%
185		2	0	100.0%	44	8	81.8%	2	0	100.0%	44	1	97.7%
186		2	0	100.0%	44	7	84.1%	2	0	100.0%	44	12	72.7%
190	19	2	1	50.0%	44	17	61.4%	2	1	50.0%	44	11	75.0%
192		2	0	100.0%	42	6	85.7%	2	0	100.0%	42	1	97.6%
193		2	0	100.0%	44	13	70.5%	2	1	50.0%	44	15	65.9%
196		2	0	100.0%	44	0	100.0%	2	0	100.0%	44	2	95.5%
197	33	2	2	0.0%	44	17	61.4%	2	2	0.0%	44	8	81.8%
232		2	0	100.0%	63	1	98.4%	2	0	100.0%	63	6	90.5%
233		2	0	100.0%	63	13	79.4%	2	1	50.0%	63	13	79.4%
234		2	0	100.0%	63	3	95.2%	2	0	100.0%	63	2	96.8%
236		2	0	100.0%	63	1	98.4%	2	0	100.0%	63	11	82.5%
237		2	0	100.0%	63	10	84.1%	2	0	100.0%	63	4	93.7%
239		2	1	50.0%	62	16	74.2%	2	0	100.0%	62	2	96.8%
240		2	1	50.0%	63	7	88.9%	2	0	100.0%	63	7	88.9%
241	18	2	2	0.0%	63	18	71.4%	2	1	50.0%	63	11	82.5%
243		2	0	100.0%	44	16	63.6%	2	0	100.0%	45	8	82.2%
244		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	15	76.2%
280		2	0	100.0%	63	3	95.2%	2	1	50.0%	63	11	82.5%
281		2	0	100.0%	63	8	87.3%	2	0	100.0%	63	5	92.1%
283		2	2	0.0%	63	10	84.1%	2	0	100.0%	63	9	85.7%
284		2	0	100.0%	63	1	98.4%	2	1	50.0%	63	6	90.5%
290		2	0	100.0%	63	18	71.4%	2	0	100.0%	62	21	66.1%
291		2	1	50.0%	63	14	77.8%	2	0	100.0%	63	12	81.0%
300		2	0	100.0%	63	2	96.8%	2	0	100.0%	62	14	77.4%
301		2	0	100.0%	62	1	98.4%	2	0	100.0%	61	9	85.2%
302		2	0	100.0%	62	6	90.3%	2	0	100.0%	60	17	71.7%
305	22	2	0	100.0%	63	5	92.1%	2	1	50.0%	62	21	66.1%
306	82	2	0	100.0%	62	2	96.8%	2	2	0.0%	61	13	78.7%
307		2	0	100.0%	62	5	91.9%	2	1	50.0%	62	12	80.6%
311	18	2	1	50.0%	62	8	87.1%	2	1	50.0%	62	15	75.8%
316		2	0	100.0%	62	3	95.2%	2	1	50.0%	62	13	79.0%
318	72	2	1	50.0%	63	10	84.1%	2	2	0.0%	62	27	56.5%
319		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	36	42.9%
329		2	0	100.0%	44	1	97.7%	2	1	50.0%	44	3	93.2%
330	23	2	0	100.0%	53	2	96.2%	2	2	0.0%	53	3	94.3%
331	42	2	2	0.0%	63	6	90.5%	2	2	0.0%	63	8	87.3%
332		2	1	50.0%	63	6	90.5%	2	1	50.0%	63	6	90.5%
334	44	2	1	50.0%	63	2	96.8%	2	1	50.0%	62	5	91.9%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335	Cncld	2	1	50.0%	63	8	87.3%	1	0	100.0%	61	9	85.2%
336		2	0	100.0%	63	1	98.4%	2	0	100.0%	63	4	93.7%
337		2	0	100.0%	63	4	93.7%	2	1	50.0%	63	6	90.5%
338	Cncld	2	1	50.0%	63	16	74.6%	1	0	100.0%	61	12	80.3%
339		2	0	100.0%	63	14	77.8%	2	0	100.0%	63	11	82.5%
341	14	2	0	100.0%	62	9	85.5%	2	1	50.0%	62	9	85.5%
342	14	2	0	100.0%	63	6	90.5%	2	1	50.0%	62	9	85.5%
350		2	0	100.0%	45	2	95.6%	2	1	50.0%	45	23	48.9%
351		2	0	100.0%	63	3	95.2%	2	1	50.0%	63	27	57.1%
352		2	0	100.0%	63	4	93.7%	2	0	100.0%	61	14	77.0%
353	16	2	0	100.0%	42	2	95.2%	2	2	0.0%	42	7	83.3%
354	77	2	0	100.0%	63	3	95.2%	2	2	0.0%	63	16	74.6%
355		2	0	100.0%	63	5	92.1%	2	0	100.0%	63	13	79.4%
364		2	1	50.0%	63	6	90.5%	2	1	50.0%	63	9	85.7%
365	45	2	0	100.0%	63	2	96.8%	2	1	50.0%	63	17	73.0%
370		2	0	100.0%	63	2	96.8%	2	0	100.0%	63	9	85.7%
371		2	0	100.0%	63	0	100.0%	2	0	100.0%	63	4	93.7%
380		2	0	100.0%	63	10	84.1%	2	0	100.0%	63	13	79.4%
381	35	2	0	100.0%	63	1	98.4%	2	1	50.0%	63	8	87.3%
382		2	0	100.0%	63	2	96.8%	2	1	50.0%	63	16	74.6%
383	24	2	0	100.0%	63	5	92.1%	2	2	0.0%	62	24	61.3%
392	28	2	0	100.0%	63	2	96.8%	2	1	50.0%	62	16	74.2%
393		2	0	100.0%	63	5	92.1%	2	0	100.0%	62	15	75.8%
417		2	0	100.0%	41	8	80.5%	2	0	100.0%	39	1	97.4%
425		2	0	100.0%	41	1	97.6%	2	0	100.0%	41	1	97.6%
448	125	2	2	0.0%	4	3	25.0%	2	2	0.0%	3	2	33.3%
449	188	2	0	100.0%	2	0	100.0%	2	1	50.0%	2	1	50.0%
470		2	0	100.0%	44	5	88.6%	2	0	100.0%	44	7	84.1%
471		2	0	100.0%	41	0	100.0%	2	0	100.0%	41	0	100.0%
473		2	0	100.0%	44	3	93.2%	2	0	100.0%	44	1	97.7%
474		2	1	50.0%	42	14	66.7%	2	1	50.0%	39	12	69.2%
475		2	0	100.0%	44	0	100.0%	2	0	100.0%	44	1	97.7%
478		2	0	100.0%	42	10	76.2%	2	0	100.0%	42	6	85.7%
479		2	1	50.0%	44	5	88.6%	2	0	100.0%	44	1	97.7%
486	47	2	0	100.0%	45	7	84.4%	2	1	50.0%	44	7	84.1%
490		2	0	100.0%	21	5	76.2%	2	0	100.0%	21	2	90.5%
494	32	2	0	100.0%	46	9	80.4%	2	1	50.0%	43	8	81.4%
495		2	0	100.0%	44	2	95.5%	2	0	100.0%	44	1	97.7%
500		2	0	100.0%	63	5	92.1%	2	0	100.0%	62	5	91.9%
502		2	0	100.0%	63	6	90.5%	2	0	100.0%	62	16	74.2%
503		2	0	100.0%	60	8	86.7%	2	1	50.0%	59	16	72.9%
504	33	2	1	50.0%	63	6	90.5%	2	1	50.0%	63	20	68.3%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
505		2	1	50.0%	63	11	82.5%	2	0	100.0%	61	13	78.7%
506		2	0	100.0%	62	9	85.5%	2	0	100.0%	61	9	85.2%
507		2	1	50.0%	63	8	87.3%	2	1	50.0%	63	23	63.5%
508	52	2	2	0.0%	61	13	78.7%	2	2	0.0%	61	15	75.4%
509		2	0	100.0%	63	4	93.7%	2	0	100.0%	63	13	79.4%
511		2	0	100.0%	63	4	93.7%	2	0	100.0%	63	12	81.0%
516		2	0	100.0%	63	9	85.7%	2	0	100.0%	63	28	55.6%
517		2	0	100.0%	63	1	98.4%	2	1	50.0%	62	23	62.9%
518	33	2	0	100.0%	63	13	79.4%	2	2	0.0%	63	38	39.7%
519		2	0	100.0%	63	3	95.2%	2	1	50.0%	63	10	84.1%
520		2	0	100.0%	40	3	92.5%	2	0	100.0%	40	2	95.0%
521		2	0	100.0%	43	0	100.0%	2	0	100.0%	43	3	93.0%
522		2	0	100.0%	43	4	90.7%	2	0	100.0%	43	4	90.7%
523	11	2	0	100.0%	43	0	100.0%	2	1	50.0%	43	5	88.4%
524		2	0	100.0%	43	2	95.3%	2	0	100.0%	43	3	93.0%
525		2	0	100.0%	43	1	97.7%	1	0	100.0%	42	5	88.1%
526		2	2	0.0%	43	8	81.4%	1	0	100.0%	42	4	90.5%
527		2	0	100.0%	43	1	97.7%	2	0	100.0%	43	2	95.3%
528	14	2	1	50.0%	43	6	86.0%	2	1	50.0%	43	11	74.4%
529		2	1	50.0%	43	4	90.7%	2	0	100.0%	43	7	83.7%
531	13	2	0	100.0%	43	1	97.7%	2	1	50.0%	43	4	90.7%
532		2	0	100.0%	43	1	97.7%	2	0	100.0%	43	7	83.7%
534		2	0	100.0%	40	5	87.5%	2	0	100.0%	40	3	92.5%
535		2	1	50.0%	40	2	95.0%	2	0	100.0%	40	1	97.5%
536		2	0	100.0%	43	4	90.7%	2	0	100.0%	43	1	97.7%
537	15	2	1	50.0%	43	4	90.7%	1	1	0.0%	42	2	95.2%
538		2	0	100.0%	43	6	86.0%	2	0	100.0%	43	5	88.4%
540		2	0	100.0%	43	4	90.7%	2	0	100.0%	41	1	97.6%
541		2	1	50.0%	43	6	86.0%	2	0	100.0%	43	11	74.4%
542		2	0	100.0%	43	3	93.0%	2	0	100.0%	42	10	76.2%
543		2	0	100.0%	43	6	86.0%	2	0	100.0%	43	12	72.1%
544		2	0	100.0%	42	2	95.2%	2	1	50.0%	42	5	88.1%
545		2	0	100.0%	43	4	90.7%	2	0	100.0%	42	4	90.5%
546	21	2	0	100.0%	43	6	86.0%	2	1	50.0%	43	6	86.0%
547	14	2	0	100.0%	43	4	90.7%	2	1	50.0%	43	8	81.4%
548		2	0	100.0%	43	8	81.4%	2	0	100.0%	43	5	88.4%
549		2	1	50.0%	40	11	72.5%	2	0	100.0%	39	6	84.6%
551		2	1	50.0%	43	7	83.7%	2	0	100.0%	41	6	85.4%
562		2	1	50.0%	61	9	85.2%	2	1	50.0%	60	7	88.3%
564		2	1	50.0%	61	7	88.5%	2	1	50.0%	58	11	81.0%
566		2	0	100.0%	61	5	91.8%	2	0	100.0%	58	6	89.7%
572		2	0	100.0%	60	6	90.0%	2	0	100.0%	59	14	76.3%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		2	0	100.0%	61	9	85.2%	2	0	100.0%	60	8	86.7%
577		2	0	100.0%	59	5	91.5%	2	1	50.0%	55	3	94.5%
580		2	0	100.0%	61	2	96.7%	2	0	100.0%	61	7	88.5%
581		2	0	100.0%	61	7	88.5%	2	1	50.0%	61	13	78.7%
582		2	0	100.0%	61	4	93.4%	2	0	100.0%	59	4	93.2%
586		2	2	0.0%	61	13	78.7%	2	0	100.0%	58	9	84.5%
587		2	0	100.0%	61	3	95.1%	2	0	100.0%	59	9	84.7%
591		2	0	100.0%	61	1	98.4%	2	0	100.0%	61	6	90.2%
593		2	0	100.0%	61	9	85.2%	2	0	100.0%	55	5	90.9%
595		2	0	100.0%	60	14	76.7%	2	0	100.0%	59	10	83.1%
600		2	0	100.0%	44	1	97.7%	2	0	100.0%	44	4	90.9%
601		2	1	50.0%	44	20	54.5%	2	0	100.0%	44	13	70.5%
605		2	2	0.0%	44	23	47.7%	2	0	100.0%	43	2	95.3%
607	56	2	0	100.0%	44	3	93.2%	2	1	50.0%	43	2	95.3%
609		2	0	100.0%	43	1	97.7%	2	0	100.0%	43	3	93.0%
620		2	1	50.0%	43	10	76.7%	2	0	100.0%	41	2	95.1%
624		2	1	50.0%	44	11	75.0%	1	0	100.0%	44	9	79.5%
639		2	2	0.0%	44	12	72.7%	2	0	100.0%	44	4	90.9%
640	22	2	0	100.0%	44	2	95.5%	2	2	0.0%	44	20	54.5%
641		2	1	50.0%	44	6	86.4%	2	0	100.0%	44	7	84.1%
642	11	2	1	50.0%	43	3	93.0%	2	1	50.0%	43	5	88.4%
643	15	2	0	100.0%	44	7	84.1%	2	1	50.0%	43	4	90.7%
644		2	0	100.0%	44	5	88.6%	2	0	100.0%	44	5	88.6%
645	35	2	0	100.0%	44	3	93.2%	2	2	0.0%	44	8	81.8%
646	45	2	1	50.0%	44	8	81.8%	2	1	50.0%	43	21	51.2%
647		2	0	100.0%	44	2	95.5%	2	0	100.0%	44	12	72.7%
648	53	2	2	0.0%	44	8	81.8%	2	1	50.0%	44	5	88.6%
649		2	1	50.0%	44	7	84.1%	2	0	100.0%	43	7	83.7%
650	14	2	0	100.0%	44	9	79.5%	2	1	50.0%	44	8	81.8%
651		2	0	100.0%	44	5	88.6%	2	0	100.0%	44	13	70.5%
652		2	0	100.0%	44	8	81.8%	2	1	50.0%	43	9	79.1%
653		2	0	100.0%	44	8	81.8%	2	0	100.0%	44	14	68.2%
654		2	2	0.0%	44	7	84.1%	2	0	100.0%	44	2	95.5%
655		2	0	100.0%	42	12	71.4%	2	1	50.0%	41	9	78.0%
656		2	1	50.0%	44	8	81.8%	2	0	100.0%	44	5	88.6%
657		2	0	100.0%	44	3	93.2%	2	0	100.0%	44	9	79.5%
658		2	0	100.0%	44	7	84.1%	2	0	100.0%	44	6	86.4%
680		2	0	100.0%	45	2	95.6%	2	0	100.0%	45	3	93.3%
681		2	0	100.0%	45	2	95.6%	2	0	100.0%	45	13	71.1%
682		2	0	100.0%	45	0	100.0%	2	0	100.0%	45	10	77.8%
683		2	0	100.0%	28	3	89.3%	2	0	100.0%	28	9	67.9%
684		2	0	100.0%	27	4	85.2%	2	0	100.0%	27	8	70.4%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

25-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	13	70.5%
686		2	0	100.0%	45	13	71.1%	2	1	50.0%	45	11	75.6%
687		2	0	100.0%	45	6	86.7%	2	0	100.0%	45	6	86.7%
688		2	0	100.0%	45	1	97.8%	2	0	100.0%	45	12	73.3%
689		1	0	100.0%	37	4	89.2%	1	0	100.0%	37	3	91.9%
702	58	2	1	50.0%	63	16	74.6%	2	1	50.0%	62	20	67.7%
703		2	0	100.0%	63	15	76.2%	2	0	100.0%	63	16	74.6%
710		2	1	50.0%	63	25	60.3%	2	0	100.0%	63	28	55.6%
711	24	2	0	100.0%	59	4	93.2%	2	1	50.0%	55	8	85.5%
712	22	2	1	50.0%	63	18	71.4%	2	1	50.0%	62	24	61.3%
713		2	0	100.0%	63	9	85.7%	2	0	100.0%	57	27	52.6%
714		2	1	50.0%	57	20	64.9%	2	0	100.0%	52	16	69.2%
715	32	2	0	100.0%	63	22	65.1%	2	2	0.0%	60	31	48.3%
716	48	2	1	50.0%	63	24	61.9%	2	1	50.0%	62	24	61.3%
717		2	0	100.0%	54	13	75.9%	2	0	100.0%	49	13	73.5%
718		2	1	50.0%	63	23	63.5%	2	0	100.0%	63	16	74.6%
719		2	1	50.0%	63	25	60.3%	2	0	100.0%	61	16	73.8%
761		2	0	100.0%	61	3	95.1%	2	0	100.0%	61	9	85.2%
765		2	1	50.0%	61	8	86.9%	2	0	100.0%	61	13	78.7%
769		2	0	100.0%	61	4	93.4%	2	0	100.0%	59	11	81.4%
770		2	0	100.0%	61	7	88.5%	2	0	100.0%	61	9	85.2%
774		2	0	100.0%	61	6	90.2%	2	0	100.0%	60	11	81.7%
779		2	0	100.0%	61	4	93.4%	2	0	100.0%	60	9	85.0%
784	32	2	1	50.0%	61	7	88.5%	2	1	50.0%	60	30	50.0%
785		2	0	100.0%	61	0	100.0%	2	0	100.0%	61	7	88.5%
790		2	0	100.0%	61	5	91.8%	2	0	100.0%	61	7	88.5%
794		2	1	50.0%	61	6	90.2%	2	0	100.0%	60	10	83.3%
821	18	2	0	100.0%	63	3	95.2%	2	2	0.0%	63	42	33.3%
822		2	0	100.0%	63	3	95.2%	2	0	100.0%	63	44	30.2%
1333	143	2	1	50.0%	63	5	92.1%	2	1	50.0%	62	27	56.5%
1340		2	0	100.0%	63	3	95.2%	2	0	100.0%	63	13	79.4%
2103		2	0	100.0%	43	3	93.0%	2	0	100.0%	43	1	97.7%
2104	48	2	1	50.0%	14	3	78.6%	2	1	50.0%	14	3	78.6%
2107	18	2	0	100.0%	44	7	84.1%	2	1	50.0%	42	1	97.6%
2108		2	0	100.0%	44	2	95.5%	2	0	100.0%	42	0	100.0%
2117		2	1	50.0%	14	4	71.4%	2	0	100.0%	14	1	92.9%
2121		2	0	100.0%	42	3	92.9%	2	0	100.0%	42	3	92.9%
2122		2	0	100.0%	44	6	86.4%	2	0	100.0%	44	3	93.2%
2124		2	0	100.0%	32	4	87.5%	2	0	100.0%	32	1	96.9%
2150		2	0	100.0%	44	9	79.5%	2	0	100.0%	44	9	79.5%
2151	30	2	0	100.0%	44	0	100.0%	2	1	50.0%	43	7	83.7%
2152	138	2	0	100.0%	40	2	95.0%	2	2	0.0%	39	11	71.8%

Amtrak On Time Performance

Trains Arriving Through: 12/2/2025

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2153		2	0	100.0%	44	6	86.4%	2	1	50.0%	44	10	77.3%
2154	42	2	1	50.0%	44	15	65.9%	2	1	50.0%	42	22	47.6%
2155		2	0	100.0%	44	2	95.5%	2	0	100.0%	42	9	78.6%
2159		2	0	100.0%	43	1	97.7%	2	0	100.0%	43	7	83.7%
2162	30	2	0	100.0%	44	2	95.5%	2	1	50.0%	43	10	76.7%
2163		2	0	100.0%	44	4	90.9%	2	0	100.0%	44	10	77.3%
2166		2	0	100.0%	44	5	88.6%	2	0	100.0%	42	6	85.7%
2167		2	0	100.0%	44	5	88.6%	2	0	100.0%	44	8	81.8%
2168		2	0	100.0%	44	2	95.5%	2	0	100.0%	44	6	86.4%
2169		2	2	0.0%	40	12	70.0%	2	1	50.0%	40	16	60.0%
2170	17	2	1	50.0%	44	8	81.8%	2	2	0.0%	44	11	75.0%
2172		2	0	100.0%	44	6	86.4%	2	0	100.0%	44	7	84.1%
2173		2	0	100.0%	43	7	83.7%	2	0	100.0%	43	18	58.1%
2190		2	0	100.0%	44	5	88.6%	2	0	100.0%	44	4	90.9%
2193	19	2	0	100.0%	43	1	97.7%	2	1	50.0%	43	10	76.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2104	NYP	48	CAR	52	CAR	52	WAS-WAS	AM	Toilet, x, LEAK IN RESTROOM ON CC1
2107	WAS	18	MTI	11	MTI	11	NWK-MET	AM	Disabled train ahead, Other, NWK-MET, CONGESTION A/C AM181 DISABLED ON 3 TRK AT MP19
2151	WAS	30	ENG	18	ENG	9	RTE-PVD	AM	Radio failure, 2015, No TSR data beginning at Tower 1, speed capped at 79mph RTE-PVD
2152	BOS	138	CAR	86	CAR	73	XSH-STM	MN	Door 3699, Outside transformer door open. Damage caused by it being an open. Had to take door apart.
2154	BOS	42	DCS	18	DCS	18	NHV-XGX	AM	Issue with automatic road crossing protection, Milepost w/Letters, NHV, XGX, a stop and protect is in effect at Miners Lane MP 120.2. NHV-XGX
2162	BOS	30	OTH	17	DCS	9	WIL-PHL	AM	T.O.L, Milepost, 13.4, Baldwin
2170	BOS	17	CTI	17	SMW	8	NYP-XSH	AM	Scheduled in track usage program, Other, XGG-XPB, HELD AT LEGGETT BEHIND AM94 FOR AM137 AND AM55 TO CLEAR 2TRK A/C 1TRK O/O/S PELHAM BAY TO LEGGETT
2193	NYP	19	ENG	18	ENG	18	XGX-XNH	AM	Other electrical failure, 2019, low main res penalty. Stopped around Division post to rebuild air.
85	RVM	43	MTI	15	MTI	15	WIL-XPV	AM	Disabled train ahead, Milepost, 44.9, ., opr 1 trk around disabled 97 on 3 trk
86	BOS	44	PTI	23	PTI	10	NCR-BWI	AM	Cross over or go around, 2104, Control Point, CARROLL TO BWI, OPERATE 1 TRACK
94	BOS	21	SMW	17	SMW	17	NYP-XSH	AM	Scheduled in track usage program, Other, XGG-XPB, HELD AT LEGGETT FOR AM137 AND AM55 TO CLEAR 2TRK A/C PELHAM BAY TO LEGGETT
95	NFK	34	FTI	41	FTI	31	FBG-RVR	CS	Follow fti301, Other, cfp41.1-11.4
114	XHM	Trn Cancelled							
125	NPN	35	FTI	34	FTI	11	FBG-ASD	CS	Follow 419, Milepost, 39.5, 23.2
134	NYP	63	POL	40	POL	40	CVS-CLP	NS	Fire department hold
141	NFK	38	PTI	24	PTI	24	ASD-RVR	CS	Meet 80, Control Point, GREENDALE
170	BOS	46	ENG	28	ENG	23	TRE-MET	AM	Unrecoverable penalty (PCS), 621, BRAKE PENALTY ON ENG.621

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/2/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
172	BOS	25	ADA	17	ADA	10	WLY-WLY	AM	Mobility Impaired, Special Needs passenger was having difficulty locating bags to deboard the train WLY	
173	WAS	76	SVS	37	SVS	37	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Depart BOS late a/c late release from SHSY, adding additional coaches BOS	
175	WAS	89	ITI	60	ITI	60	BOS-BOS	AM	Service, turn, or wye train, 170, late AM170 turn and removed a coach	
181	XHM	Trn Cancelled	CTI	3	CTI	3	NYP-NWK	AM	Follow, NJT, NJX375, Other, XBH-XHU, FLWD NJX375	
183	WAS		FTI	12	FTI	12	ABE-BAL	AM	Follow, NS38B, Control Point, GUNPOW, DELAY RELATED TO PROBLEMS WITH NS594 FROM EARLIER TODAY	
190	BOS	19	DCS	12	DCS	7	NLC-NLC	AM	Restrictive signal(s) from unknown cause, Signal Dropped, Milepost w/Letters, NLC, NLC, 2E at Groton dropped. Need to recover air, reverse and build speed a/c de-energized section XGX, NHV-NLC and in NLC	
197	WAS	33	ITI	32	ITI	32	NYP-NYP	AM	Service, turn, or wye train, 134, LATE FROM SSYD A/C LATE TURN OFF AM134	
486	GFD	47	DMW	23	DMW	23	SPG-HLK	MA	Waiting for MW clearance Waiting for Forman to clear up., Control Point, CPR 2	
494	GFD	32	FTI	17	FTI	17	NHT-GFD	MA	Follow ED9, Control Point, CPR16	
80	NYP	82	PTI	50	SVS	33	RGH-SSM	NS	PTC - Initializing PTC (no failure) Original orders changed due to no cover sheet because printer was malfunctioning. Crew was given verbal permission from Dispatch to activate orders and had to re-initialize, Control Point, S. Raleigh	
607	HAR	56	MTI	63	MTI	33	NWK-PJC	AM	Disabled train ahead, Other, XEO-XUN, NECESSARY TO MAKE REVERSE MOVE A/C AM181 DISABLED AHD AT MP19	
640	NYP	22	CTI	17	CTI	12	CWH-TRE	AM	Follow, SE, SE703, Other, CWH-XMO	
642	NYP	11	OTH	13	MTI	8	TRE-NWK	AM	Disabled train ahead, Other, NWK, AM2152 W/DOOR PROBLEMS AHD	
643	HAR	15	WTR	18	WTR	18	PHL-PAO	AM	Trees down, Control Point, malvern, single tracking a/c tree in catenary	
645	HAR	35	SVS	21	SVS	21	PHL-PAO	AM	Unplanned Wye, wye's a/c cabs cutout	
646	NYP	45	WTR	39	WTR	17	EXT-PAO	AM	Trees down, Control Point, malvern, tree in catenary opr 1 trk.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
648	NYP	53	WTR	46	WTR	38	LNC-PAO	AM	Wet / slippery rail, Control Point, malvern, tree in catenary
650	NYP	14	WTR	19	WTR	17	EXT-PAO	AM	Trees down, Control Point, malvern, tree in catenary
63	TWO	19	HLD	8	HLD	6	YNY-YNV	MN	Passenger and/or baggage
68	NYP	23	PTI	38	PTI	28	XWQ-SLQ	CN	Meet 35, Control Point, 72
241	ALB	18	CTI	20	CTI	17	CRT-POU	MN	Follow metro, Milepost, 42, 72
49	CHI	43	FTI	41	SVS	23	TOL-TOL	NS	Map missing signatures on map 100 for inspections. Engineer informed that there was Missing signature for 12/01 for daily departure test. Call CNOC to verify with Albany what had been done. Also performed brake test., Control Point, 288
448	BOS	77	CTI	77	CTI	42	SPG-WOR	MT	Blocked from station track Mr. ?, Control Point, 45
449	ALB	188	FTI	150	FTI	87	SPG-SPG	CS	Hold at SPG do to freight disabled and stalled on both main tracks between SPG and PIT. M426, M427, Control Point, 123, Control Point, 147
75	CLT	23	FTI	15	FTI	15	HPT-SAL	NS	Meet #NS24X, Control Point, Duke
78	RGH	13	PTI	12	PTI	12	KAN-SAL	NS	Meet #Amt79, Control Point, Sumner
89	SAV	39	PTI	45	PTI	25	PTB-RMT	CS	Meet P080, Control Point, Fox
41	MIA	92	FTI	115	FTI	48	KIS-XP8	FR	Meet CSX M457 had PTC issues blocking the route ahead. We received an approach signal at Poinciana followed by a stop signal at Poinciana holdout. After the service resumption, we received a limited clear still in our 30 mph speed restriction., Control Point, Poiciana, CSX M457
6	CHI	52	FTI	88	DMW	32	HAS-LNK	BN	Slowed for track defect Talked by stop signal at Grafton, broken rail at 121.9. Cleared up at Sutton., Siding, Grafton, Siding, Sutton
523	SJC	11	RTE	17	RTE	15	OKJ-OAC	UP	Run via siding or slower track due to N.A.R. Wrong lineup, lined into siding, Control Point, NI010
528	SAC	14	PTI	15	PTI	10	RIC-MTZ	UP	Follow Amtk 712 E, Milepost, 19, 31
531	OKJ	13	MBO	13	MBO	13	SUI-MTZ	UP	For maritime traffic Control Point, benicia
537	OKJ	15	MBO	26	MBO	26	SUI-MTZ	UP	For maritime traffic Control Point, rv035
546	SAC	21	TEN	22	TEN	22	OAC-OKJ	UP	PTC- Cutout due to unrecoverable penalty C6964

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
547	SJC	14	PTI	25	PTI	25	OKJ-OAC	UP	Train 546 stopped south of OAC with PTC issues 546, Control Point, NI010
504	SEA	33	PTI	28	PTI	16	KEL-CTL	BN	Meet A 11, Control Point, Vader
508	SEA	52	FTI	76	FTI	52	EUG-ALY	UP	Disabled Freight Train Freight broke knuckle ahead of us. Wait for repairs to be made., Siding, Shedd, UP 6575, Manifest
518	VAC	33	SYS	26	PTI	14	CTL-OLW	BN	Meet Amtrak 507, Control Point, Wabash
28	SPK	73	ITI	103	ITI	103	PDX-PDX	BN	Late arrival of 27 into PDX then wye, service and clean 27
821	FTW	18	FTI	28	FTI	28	ADM-GLE	BN	Meet bnsf, Control Point, s Ardmore
330	CHI	23	CTI	34	CTI	21	GLN-XWA	ME	Follow Metra, 2112, Milepost, 17.4, 5.7
331	MKE	42	CTI	37	CTI	22	XWA-GLN	ME	Follow Metra, 2109, Milepost, 2.97, 17.4
334	CHI	44	ENG	24	ENG	16	MKE-MKA	CP	Loading problem Engine will not hold load, pulled MU cable, ID4607
335	MKE	Trn Cancelled							
338	CHI	Trn Cancelled							
341	MKE	14	DCS	18	DCS	18	GLN-XRO	ME	Track signal Deerfield west talked by stop signal by dispatch restricted speed Control Point, Deerfield
342	CHI	14	ENG	6	PTI	4	XRO-GLN	ME	Meet Waited at Deerfield for 341 to be talked past a bad signal, then went 2-1 to go around a freight enter A20 on #2, Amtrak 341, Control Point, Deerfield
353	CHI	16	DCS	26	DCS	24	ROY-DET	CC	Restrictive signal(s) from known wayside signal failure Stop, Control Point, murray
354	PNT	77	SYS	55	SYS	52	CHI-XTF	AM	PTC problem or failure (cause unknown) Other, lumber
365	CHI	45	CAR	41	CAR	37	KAL-DOA	AM	Glad hands popped on a crossing ice bank and had to be repaired ID4002
784	SAN	32	ENG	36	ENG	36	CPN-VEC	UP	HEP C2114
702	BFD	58	FTI	36	FTI	24	FNO-HNF	BN	Meet bnsf 7904, Control Point, shirley
711	OKJ	24	FTI	16	TCC	14	MDR-MCD	BN	Air / Brake / Wheel C8305, Inspected CC 8305 for possible sticking break. No exceptions found
712	BFD	22	PTI	27	DCS	22	RIC-MTZ	UP	Power switch failure Control Point, rv021

Amtrak Endpoint OTP Details

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/2/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
715	OKJ	32	PTI	28	POL	18	MCD-MCD	BN	Removal of passenger by police Fare evader. Got aggressive with me and could not give me a name or reservation number
716	BFD	48	TEN	46	TEN	46	EMY-EMY	UP	Locomotive issues late departure out of OMF Departed yard around 14:22pm Originate out of Emeryville C2108
3	LAX	762	SVS	228	SVS	182	NEW-NEW	BN	Had to set out coach car 34200
4	CHI	38	FTI	59	FTI	25	NPV-XUA	BN	Meet Milepost, 15.0, 15.0, 0
305	STL	22	PTI	22	PTI	20	LCN-SPI	UP	Meet Amtrak 306, Control Point, Elkhart
306	CHI	82	RTE	33	PTI	26	ALN-CRV	UP	Meet 21, Control Point, 236
381	QCY	35	DCS	41	DCS	20	PLO-MDT	BN	Power switch failure Switch issues at zearing and electrics. Wait for 380 @ earlville, Control Point, electrics/zearing
383	QCY	24	HLD	11	CTI	8	XUA-LAG	BN	Follow metra, Control Point, Congress Park
392	CHI	28	DSR	21	DSR	18	KKI-HMW	CC	Per bulletin Milepost, 48.6, 46.8, 25, 1, Milepost, 43.2, 40.3, 25, 1
311	KCY	18	PTI	14	PTI	14	JEF-SED	UP	Meet Amtrak 318, Siding, Smithton
318	CHI	72	DCS	55	DCS	55	KCY-XRC	KC	Power switch failure Control Point, Independence Avenue
1333	MSP	143	CAR	146	CAR	146	LSE-WIN	CP	Air / Brake / Wheel 35001, BP damaged when going thru crossing. BP hose frozen

Amtrak Initial Terminal Details

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/2/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	624	12/02	1		
HAR	648	12/02	17	17	Service, turn, or wye train, 607
HAR	654	12/02	1		
PHL	151	12/02	2		
PHL	601	12/02	1		
PHL	605	12/02	1		
WAS	114	12/02	(Trn Cxld)		Engine Failure
WAS	2104	12/02	52	52	Toilet, x, LEAK IN RESTROOM ON CC1
WAS	2154	12/02	5	5	Toilet, ALL, BATHROOMS SHOWING FALSE WASTE TANKS FULL NEC'Y FOR MECHANICAL TO INSPECT
ALB	240	12/02	3	3	Hold for thruway bus
ALB	448	12/01	38	38	Planned set out / pick out of locomotives, cars or section of train Control Point, 142
BOS	173	12/02	38	37	Planned set out / pick out of locomotives, cars or section of train, Depart BOS late a/c late release from SHSY, adding additional coaches BOS
BOS	175	12/02	60	60	Service, turn, or wye train, 170, late AM170 turn and removed a coach
BOS	2169	12/02	6	6	Water, commissary, toilet/trash dumping, Depart BOS late a/c replacing turn set with set 12 from the yard, commissary loading
GFD	479	12/02	17	17	Late arrival of 486, turn for 479 486
NYP	89	12/02	12	12	Waiting for MW clearance, Other, NYP-NYP, HELD FOR SINGLE TRACKING IN THE NORTH TUBE A/C THE SOUTH TUBE O/O/S
NYP	97	12/02	13	13	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C LATE RELEASE FROM CATERING
NYP	197	12/02	32	32	Service, turn, or wye train, 134, LATE FROM SSYD A/C LATE TURN OFF AM134
NYP	239	12/02	4	4	Scheduled in track usage program, Other, NYP-NYP, CONGESTION AHD LINE 1 A/C LINE 2 O/O/S
NYP	241	12/02	3	3	Service, turn, or wye train, 290, LATE TURN OFF AM290
NYP	283	12/02	5	5	Mobility Impaired
NYP	639	12/02	3	3	Door, NA, UNSPECIFIED DOOR ISSUES
NYP	641	12/02	4	4	Passenger and/or baggage, LOADING
NYP	2117	12/02	13	13	Service, turn, or wye train, 2104, LATE TURN OFF AM2104
CHI	3	12/02	17	17	Blocked from shoving to the station 365 - B. Water, Control Point, Harrison
CHI	50	12/02	7	7	Mobility Impaired

Amtrak Initial Terminal Details

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/2/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	331	12/02	10	10	Service, turn, or wye train 330, Arrived 8:20 Note: working on major engine faults, IDTX 4604
CHI	335	12/02	(Trn Cxld)		Locomotive Failure
CHI	364	12/02	4	4	Ice / snow on or under equipment Train thawing out in Pit, Control Point, CUS
EUG	508	12/02	1	1	Departed on time at 1630.
KCY	318	12/02	1		
MKE	334	12/02	8	8	Loading problem Battery charging issues, ID4607
MKE	338	12/02	(Trn Cxld)		Locomotive Failure
SEA	505	12/02	9	9	Planned Switch
ARN	529	12/02	1		
BFD	719	12/02	8	8	Meet 712, Control Point, BFD
LAX	4	12/02	47	47	Unrecoverable penalty (PCS) Attempted to fix ATS problem, 201
LAX	586	12/02	5	5	PTC- IETMS incorrect consist Other, LAX
OKJ	526	12/02	1		
OKJ	710	12/02	1		
OKJ	714	12/02	2	2	Dispatcher hold DS held us at the OMF to bring in AMTK 711 and AMTK 531 before our departure, Control Point, magnolia
OKJ	716	12/02	(Trn Cxld)		Locomotive Failure
SAC	535	12/02	2	2	Meet Amt 6, Other, Sac Station
SAC	541	12/02	1	1	Dispatcher having trouble getting the detail to lock. Control Point, RV989
SAC	551	12/02	1		
SAC	702	12/02	4	4	Wheelchair Late arriving wheelchair at 6:25 am. Passenger Shirley Drones reservation 0958D6.
SJC	528	12/02	2	2	Loading problem F59 engine - sleep mode, C2002

Eastern Region

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.0	99.0	94.8	309	3
CDOT	95.0	90.0	95.0	92.4	20	2
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	89.9	93.4	93.8	365	37
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(02) - South of Florence, SC - Freight Train Interference

03DEC25: Train 53(02) was delayed on the CSX South End Subdivision between MP 190.4 and MP 292.9 due to following CSX I031-02.

Train	Delay	Comment
53(02)	33"	

Train 98(02) - South of Florence, SC - Freight Train Interference

03DEC25: Train 98(02) was delayed on the CSX Charleston Subdivision at MP 299.8 due to meeting CSX I031-02.

Train	Delay	Comment
98(02)	45"	

Train 97(02) South of Wilmington, DE - Engine Failure

02DEC25: Train 97(02) with E/626,E/606 and 10 cars had a undesired emergency brake application on the Philadelphia to Washington main line at MP 44.8. The crew was inspecting and found they had an air leak from E/606. After speaking with CNOC Mechanical and Amtrak Road Foreman they were able to fix the issue and they performed a brake test and proceed south.

Train	Delay	Comment
97(02)	36"	
85(02)	15"	

Train 448(01)/449(02) Springfield, MA - Freight Train Interference

02DEC25: CSX report 26-FOI-00167 00000055d1 had UNCLASSIFIED 12/17/2025 rights on the CSX Berkshire subdivision at CP 140, CSX M427-01 was stalled and CSX M426-02 was disabled. Due to this train 449(02) was held at Springfield station and 448(01) was held at Pittsfield station for an open route.

Train 449(02) was then advanced to MP 109.4, where it held for 1'15" before the route was clear.

CSX M427-01 was shoved out the way by CSX M425-02 after they tied down the their train but the crew is only good until 600P-ET. Once train 449(02) will pick up the recrew for CSX between MP 140-147 that is on duty 515P-ET enroute due to lack of transportation.

Train	Delay	Comment
448(01)	41"	
449(02)	1'47"	Hold @ SPG Station
449(02)	1'15"	MP 109.4
49(02)	3'00"	Held al ALB for 449 portion

Train 175(02) Boston, MA - Servicing

02DEC25: Train 175(02) was delayed departing Boston due to the late arrival of train 170(02) and cutting C/10002 off the rear.

Train	Delay	Comment
175(02)	1'00"	

Philadelphia to Harrisburg Main Line - Bridge Strike

02DEC25: At 219P-ET A vehicle struck the bridge at Whitford RD., MP 28.35, Philadelphia to Harrisburg Main Line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 301P-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
645(02)	06"	
SE9525(02)	06"	

New Haven to Boston Main line - Bridge Strike

02DEC25: At 1128A-ET A vehicle struck the bridge at Gardner's Wood RD., MP 117.99, New Haven to Boston Main Line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 11:54AM, the bridge was inspected and released for normal service.

Train	Delay	Comment
170(02)	06"	
2155(02)	01"	

02DEC25: At 1010A-ET, 26-FBI-00167 reported that "UNCLASSIFIED" as a 12/17/2025 in the catenary just East of MP 21.6/Malvern station on the Philadelphia to Harrisburg main line on track 1. They placed a hold on track 1 between MP 23.9/Frazer to MP 19.9/Paoli. ET was enroute. At 1117A-ET, The Cat Car TCA 16505 departed MP 68.0/Lancaster for track 1. At 200P-ET, The ET Foreman removed the tree and okayed track 1 for normal speed and service.

Train	Delay	Comment
648 (02)	42"	
646 (02)	21"	
643 (02)	18"	
650 (02)	17"	

Train 173(02) Boston, MA - Servicing

02DEC25: Train 173(02) was delayed departing Boston due to late release from the yard due to adding coaches and heavy boarding at the station.

Train	Delay	Comment
173 (02)	33"	

Train 40(02) North of Miami, FL - Engine Failure

02DEC25: Train 40(02) with E/346,E/336 and 10 cars with 58 passengers onboard was delayed on the SFRTA Miami subdivision at MP SX 1028.3 due to E/346 having a Master Controller Fault GTSO-03. Amtrak Road Foreman and crew were trouble shooting with CNOC Mechanical. Miami Mechanical was enroute to assist. The train was able to maintain HEP.

Engineer was able to recycle the engine and clear the faults, Miami Mechanical arrived and gave it a once over so they could proceed north.

Train	Delay	Comment
40 (02)	1'07"	

Train 41(30) South of Kissimmee, FL - Freight Train Interference

02DEC25: Train 41(30) was delayed on the CFRC Orlando subdivision at MP 813.0 due to disabled CSX M457-01 having PTC issues. CFRC instructed CSX M457-01 to operate with PTC cut out. Once they were back on the move train 41(30) was able to proceed south.

Train	Delay	Comment
41 (30)	48"	

Train 2152(02) West of Stamford, CT - Engine Failure

02DEC25: MNRR Reported that Next Gen 2152(02) Set 20 PC/2130 and PC/2135 made a unscheduled stop at MP 25.7/Port Chester on the MNRR New Haven Line to inspect the train for a hanging panel. Crew inspected and took no exceptions. Conductor reported they were stopped again at CP 244 they found evidence of a transformer fire in C/3699. Crew confirmed fire was not active at the present time and they were removing the panel. Crew was in contact with Amtrak Road Foreman. They were able to to isolate the 480V power from C/3699 and remove the transformer panel. After performing a brake test they were able to proceed towards Boston.

Due to the late operation of 2152(02) Boston prepared Next Gen 12 off the yard for train 2169(02).

Train	Delay	Comment
2152(02)	1'13"	
2169(02)	06"	

02DEC25: Train 134(02) delayed on the Norfolk and Western subdivision at MP 80.2 due to a Fire Department hold on all tracks.

Train	Delay	Comment
134(02)	40"	

Train 2104(02) Washington, DC - Repairing Restroom/Car Failure

02DEC25: Train 2104(02) with set 9 PC/2035, PC/2039 was delayed departing Washington due to set 9 having the restroom repaired in the S&I. Once the set was released and arrived the station passengers were boarded and commissary was loading the train.

Train	Delay	Comment
2104(02)	52"	

Train 19(01) South of Gainesville, GA - Tree Branches/Debris

02DEC25: At approximately 747A-ET, Train 19(01) with E/309,E/25 and 8 cars with 140 passengers onboard went into emergency due to striking tree branches that were left after a tree had fallen on the NS Greenville-Inman subdivision at MP 598.3. The crew was attempting to recycle the engines and restore their air. The crew reported that they had to replace the air hose between C/25097 and C/28000. After they replaced the hose they were able to restore the air and proceed south.

Train	Delay	Comment
19(01)	31"	

Train 41(01) East of Pittsburgh, PA - Signal

02DEC25: Train 41(01) was delayed on the CSX Pittsburgh PLY subdivision at MP 9.0 due to the #5 switch at Braddock would not lock and was in the reverse position. The conductor attempted to throw the switch by hand but it would not lock. CSX Maintainer was enroute and once they arrived they cleared the snow from the switch and they were able to proceed.

WBS#: B.TR.100150.6285

Train	Delay	Comment
41(01)	1'44"	

Train 181(02) West of Newark, NJ - Engine Failure

02DEC25: At 615A-ET, Train 181(02) with E/638,E/669 and 10 cars and 260 passengers onboard reported they were stopped on track 3 at MP 18.8/Rahway with no power. The Power director did issue an emergency plate and Train 607(02) was trailing. Engineer was attempting to recycle but was unsuccessful, they were speaking with a Road Foreman and attempting to set up the trail unit. Passengers were transferred to train 607(02). The weather in the area was 32 degrees and cloudy. Rescue E/610 was being readied in New York with Mechanical staff onboard. Amtrak Road Foreman was enroute. As of 719A-ET The transfer was complete to train 607(02). Train 181(02) was terminated at Newark and equipment went back to New York and Train 114(02) was cancelled in its entirety.

Train	Delay	Comment
114(02)	CANCELLED	
181(02)	TERM NWK	
607(02)	1'03"	TRANSFER 181(02) PAXS
648(02)	17"	LATE TURN OFF 607(02)

Eastern Region

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
79 (23)	RMT	326		Gear case damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 239(02) Passenger Removal at Poughkeepsie, New York – Improper Conduct***

02DEC25, Passenger on PNR unknown, traveling from New York, NY to Albany, NY was removed due to having a loud, inappropriate conversation on his phone. Amtrak Police notified.

Delay: 239 (02) 06"

Western Region

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Operating Highlights

Train 50(02) East of Connersville, IN - Signal

03DEC25: Train 50(02) was delayed at Cottage Grove/MP48.2 19 miles east of Connersville, IN/MP67.2 on the CSX Indianapolis subdivision due to restrictive signals at the interlocking. Once through the affected area, train 50(02) continued east.

Train	Delay	Comment
50(02)	32"	

Texas Eagle North of Little Rock, AR - Signal

03DEC25: Train 22(02) and Train 21(02) were delayed between Tuckerman / MP 250 and Alicia / MP 239 on UPRR Hoxie Subdivision due to Tuckerman switch will not live reverse for Train 22(02) departure. Train 22(02) went into the Tuckerman siding, while Train 21(02) passed. Once Train 21(02) passed, Train 22(02) reversed out of the south end, then proceeded north.

Train	Delay	Comment
22(02)	1'14"	
21(02)	19"	

Train 22(02) South of Dallas, TX - Routing

03DEC25: Train 22(02) was delayed at East Tex / MP 630 on TRE Main Line subdivision due to a vehicle accident ahead on the tracks at Roger's crossing.

Train	Delay	Comment
22(02)	37"	

Train 11(02) North of Chemult, OR - Freight Train Interference

03DEC25: Train 11(02) was delayed on UPRR Cascade was delay holding in the Lenz siding, approximately 20 miles north of Chemult, OR Station, holding for freight train UP 8795 to pass. Once it cleared, Train 11(02) was back on the move south.

Train	Delay	Comment
11(02)	30"	UP 8795
11(02)	05"	UP 7564

Train 1(01) West of Benson, AZ - Freight Train Interference

02DEC25: Train 1(01) operating with engines 203 and 137, 9 cars and 101 passengers onboard, was delayed following freight train UP 9655 west starting approximately 3 miles west of Benson, AZ Station on UPRR Lordsburg subdivision until MP 989, approximately 40 miles.

Train 1(01) was additionally delay by freight train UP 8772 east at MP 952.

Train	Delay	Comment
1(01)	32"	FTI UP 9655
1(01)	09"	FTI UP 8772

Train 354(02) West of Hammond-Whiting, IN - Engine Failure

02DEC25: Train 354 (26-FCI-00167 00000005501 with "UNCLASSIFIED" IDX 12/17/2025) 6 cars and 137 passengers onboard, were delay on NS Chicago Terminal subdivision after going through a detector that indicated hot wheel. The wayside detector showed that the wheel was operating at 662 degrees. Once the crew investigated, it was found to be operating within the normal range. The train was able to continue to Port Huron, per operating rule, maximum speed of 80 mph until it reaches the next mechanical facility for inspections.

Train	Delay	Comment
354(02)	33"	

Train 4(02) – Initial Terminal Delay, Los Angeles, CA – Locomotive Issue

02DEC25: During pre-departure inspection at the Los Angeles Maintenance Facility, a fault was detected in the ATS system of locomotive AMTK/201. Technicians initially anticipated extensive repairs, but the issue was resolved on-site. After successful testing, the train departed for Los Angeles Union Station.

Train	Delay	Comment
4(02)	47"	LAX - ITD

Train 1333(02) Winona, MN - Engine Failure

02DEC25: Train 1333(02) operating with engines 5 ad135, 144 passengers onboard, was delayed approximately 18 miles east of Winona, MN due to a broken brake pipe hose on car 35001 on CPKC River subdivision. The crew attempted to make repairs, but the glad-hand was shattered. Their road foreman arrived at the scene and was able to assist in change out the hose. Headend Power was disengaged will repairs were being performed.

Train	Delay	Comment
1333(02)	2'26"	

Train 790(02) – South of Santa Barbara, CA - Debris Strike

02DEC25: Train 790(02) experienced an automatic brake application after striking a bicycle on the tracks near MP 370.0, Santa Barbara Subdivision (Union Pacific Railroad), approximately three miles south of Santa Barbara. No injuries were reported among the 41 passengers or crew. Inspection revealed minor damage limited to separated compressed air hoses, which were reconnected. Following a mandatory safety inspection, the train continued to Oxnard. Amtrak Police were notified.

Train	Delay	Comment
790(02)	15"	

Train 11(02) South of Albany OR - Freight Train Interference

02DEC25: Train 11(02) was delayed 3 miles south of Albany at Hallawell siding MP 687.3 Brooklyn Subdivision Union Pacific Railroad. Union Pacific freight train MRVHK-01 (UPRR/6575) experienced a 'pull-apart' separation after breaking a knuckle coupler between freight rail cars. The freight train was stopped foul of south end switches at Hallawell blocking the mainline and siding tracks. At 9047 ft, the freight train was too long to fit into the 7420 ft siding. The crew - of the freight train - was required to replace the damaged coupler before continuing to clear the mainline for 11(02) to resume.

Train	Delay	Comment
11(02)	1'25"	
508(02)	52"	

Train 21/421(02) Bloomington-Normal, IL - Trespasser Incident

02DEC25: Train 21/421(02) headed south from Bloomington, IL Station due to a vehicle fouling the tracks approximately 9 miles ahead at MP 133.67. The driver had a medical issue. Once the vehicle was removed, the train was able to proceed south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(02)	56"	

Train 784(02) – South of Carpinteria, CA - Locomotive Shutdown - Head End Power

02DEC25: Train 784(02) stopped 16 miles south of Carpinteria at North Ventura (MP 392.9) on the Santa Barbara Subdivision, Union Pacific Railroad, after locomotive CDTX/2114 lost tractive effort and Head End Power. With remote assistance from Los Angeles Mechanical Facility, the crew restored auxiliary Head End Power and subsequently regained tractive power, allowing the train to resume service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
784(02)	36"	

Train 5(02) Chicago, IL - Engine Failure

02DEC25: Train 5(02), E/151-E/61 & 8 cars, started to pull from Chicago Union Station, then stopped due to trail E/61 with speed sensor alarms. Mechanical responded from the yard to assist. Mechanical was able to troubleshoot and resolve issue and Train 5(02) was able to depart. Upon departure, Train 5(02) reported No 1 traction motor cut-out on E/61.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(02)	1'00"	

Train 716(02) at Oakland, Originates Emeryville – Initial Terminal – Locomotive Starting

02DEC25: Train 716(02) experienced a delay at the Oakland Maintenance Facility due to locomotive CDTX/2108 failing to start. Technicians, assisted by the Road Foreman, diagnosed and resolved the issue, allowing the locomotive to restart. To minimize passenger impact, the train was originated from Emeryville, and Oakland passengers were directed to train 534(02) for connection.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(02)	46"	Emeryville

Train 334(02) East of Milwaukee, WI - Engine Issue & Hiawatha Service Adjustments

02DEC25: Train 334(02) was delayed at E/IDTX4607, 4 cars E/IDTX4604, 12/17/2025 delayed departing Milwaukee, WI/MP85.4, due to battery charger and loading issues on lead E/IDTX4607. After troubleshooting E/IDTX4607 issues resolved and Train 334(02) was able to depart Milwaukee. Train 334(02) was further delayed just east of Milwaukee due to E/IDTX4607 loading issue again. Crew pulled MU cable behind E/IDTX4607 and was able to proceed east again, with the assistant conductor riding in the rear engine E/IDTX4604. Due to the late arrival of Train 334(02) into Chicago, with the inbound engine issues, the following Hiawatha Service adjustments were in effect:

- Train 335(02) cancelled entirely. Passengers reaccommodated on Trains 7/27(02) and 337(02).
- Train 338(02) cancelled entirely. Passengers reaccommodated on Train 8/28(30).

WBS#: B.TR.100150.6284

Train	Delay	Comment
334(02)	08"	MKE
334(02)	19"	E/MKE
335(02)	Cancelled	
338(02)	Cancelled	

Train 331(02) West of Chicago, IL - Commuter Train Interference

02DEC25: Train 331(02) was delayed west of Chicago, IL, on the Metra C&M Subdivision, following Metra 2109 between MP2.97 and MP27.8.

Train	Delay	Comment
331(02)	31"	

Train 6(02) East of Colfax, CA - Passenger Train Interference

02DEC25: Train 6(02) was delayed at Gold Run, MP 152.4/UPRR Roseville Subdivision, 10.3 miles east of Colfax, meeting Train 5(30).

Train	Delay	Comment
6(02)	49"	

Train 4(01) West of Flagstaff, AZ - Freight Train Interference

02DEC25: Train 4(01) was delayed at MP352.2, 8 miles west of Flagstaff, AZ, on the BNSF Seligman Subdivision, meeting westbound BNSF freight.

Train	Delay	Comment
4(01)	30"	

Train 365(02) Dowagiac, MI - Air Hose Separation

02DEC25: Train 365(02), E/15 TX 46056 cars, C/ID4114, 12/17/2025, delayed in penalty at MP179, just east of Dowagiac, MI, on the Amtrak Michigan Line. Crew and road foreman inspected consist and found parted main res hose between the 4th and 5th cars, C/ID4114 and C/ID4002. There were no other exceptions to equipment taken. Train 365(02) was on the move west after crew secured hose, restored air and performed brake test. Train 365(02) arrived in Chicago, IL, at 1230PM-CT, 45 minutes late. At 115PM-CT, Chicago yard job, YC4, reported 365(02) equipment lost main res pressure across CP-Harrison/MP0.25, while enroute to the yard, blocking route for Train 22(01), ME811 and 3(02) equipment which was enroute to CUS. Once yard crew resolve issue and restored air, 365(02) equipment was able to clear CP-Harrison and traffic resumed. Train 3(02) was delayed departing Chicago due to the late set in CUS. Train 364(02) was delayed departing Chicago due to the late set in yard for service after the air hose separation on 365(02) deadhead equipment at CP-Harrison.

Train	Delay	Comment
365(02)	37"	
22(01)	35"	S/CHI
3(02)	17"	CHI
Metra 811	05"	

Train 318(02) East of Kansas City, MO - Switch Failure

02DEC25: Train 318(02) was delayed at MP3.0, 3 miles east of Kansas City, MO, on the KCT Kansas City Terminal Subdivision, due to switch failure. Train 318(02) held for KCT maintainer to arrive and okay switch for movement.

Train	Delay	Comment
318(02)	55"	

Train 21(01) South of Little Rock, AR - Deer Strike

02DEC25: Train 21(01), E/59 & 6 cars, with 105 passengers, was delayed at MP359.3, 13 miles south of Little Rock, AR, on the UPRR Little Rock Subdivision, due to striking a deer. There were no reported injuries to passengers or crew. The crew inspected consist and found parted air hose between the first and second cars, C/39008 and C/32016. There were no other exceptions to equipment taken. Train 21(01) was on the move south after crew secured hose, restored air and performed brake test.

Train	Delay	Comment
21(01)	20"	

Train 3(30), West of Trinidad, CO - Engine Failure

02DEC25: Train 3(30), E/168-E/0000005507 car BNCLASSIFIED delay 12/17/2025 route beginning at Trinidad, CO/MP636.7, on the BNSF Raton Subdivision, due to loading issues on lead E/168. Train 3(30) lost time enroute between Trinidad and Winslow, AZ, due to E/168 not loading. Train 3(30) was delayed beginning 15 miles east of Winslow, AZ, on the BNSF Gallup Subdivision, due to a track indication between MP270.9 and Winslow/MP285.5. Train 3(30) was delayed at Winslow, AZ/MP285.5, on the BNSF Seligman Subdivision, adding BNSF engine, E/BN5120 ahead due to the ongoing issues with E/168. BNSF pilots assisted with engine move at Winslow and remained on Train 3(30) to Kingman, AZ. Train 3(30) was delayed at W. Seligman/MP429.4, 85 miles west of Flagstaff, AZ, on the BNSF Seligman Subdivision, waiting on recrew enroute from Kingman, due to crew on hours of service at 1100AM-MT.

Train	Delay	Comment
3(30)	55"	W/FLG, recrew
3(30)	1'08"	WLO, add BN E/BN5120
3(30)	48"	TRI-WLO, E/168 not loading
3(30)	48"	E/WLO, track indication
3(30)	25"	Seligman - Crew Change
3(30)	58"	FLG-KNG Reduced Speed Operating with BNSF/5120
3(30)	10"	KNG-NDL Reduced Speed Operating with BNSF/5120
3(30)	17"	NDL-BAR Reduced Speed Operating with BNSF/5120
3(30)	19"	BAR-VRV Reduced Speed Operating with BNSF/5120
3(30)	02"	VRV-SNB Reduced Speed Operating with BNSF/5120
3(30)	10"	SNB-RIV Reduced Speed Operating with BNSF/5120

Train 5(01) East of Fort Madison, IA - Broken Rail

02DEC25: Train 5(01) was delayed at MP380.4, 83 miles east of Fort Madison, IA, on the BNSF Akron Subdivision, due to a broken rail. Train 5(01) found the broken rail while flagging through a track indication. BNSF signal maintainer responded to the scene and was able to walk Train 5(01) over location.

Train	Delay	Comment
5(01)	1'42"	

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
11 (1)	SEA	UP7156	Not enough okm road power	LAX	12/2/25
3 (30)	WLO	BNSF5120	E/168 loading issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 774(03) Passenger Removal at Oceanside, California – Fare Evader

03DEC25, Passenger on PNR 192909, traveling from Los Angeles, CA to Fullerton, CA was removed due to hiding in bathrooms beyond her destination trying to travel to San Diego, CA. Amtrak Police notified.

Delay: **774 (03)** **03"**

Consist Deviations

26-FOI-00167

00000005501

"UNCLASSIFIED"

12/17/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
--------------	---------	--------	-----------------	---------------	----------------

Reverse Consists

Train Number	Station	Reason
85 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
111 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
2107 (02)	NYP	Acela consist reversed First class at Rear
2152 (02)	WAS	Acela consist reversed First class at Front
186 (02)	NPN	Business class change only Business class seating orientation may have changed At Rear
114 (02)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
133 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
192 (02)	WAS	Consist reversed Business class seat orientation may have changed At Rear