



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, December 04, 2025

Rules: 0-6



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/03/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	53	83.0%	931	149	84.0%	18,840	2,339	87.6%
Central Division	85.5%	65	7	89.2%	198	31	84.3%	4,220	400	90.5%
Northeast Division	80.0%	101	14	86.1%	301	40	86.7%	5,897	792	86.6%
Southeast Division	72.5%	74	20	73.0%	221	41	81.4%	4,420	558	87.4%
Southwest Division	77.0%	71	12	83.1%	211	37	82.5%	4,303	589	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00167 00000005500 UNCLASSIFIED Endpoint Arrival Dates through 12/3/25 12/17/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	87,396	21,452	75%	303,661	73,653	76%	6,586,687	1,334,374	80%
Northeast Corridor	81%	41,091	7,835	81%	139,174	30,865	78%	2,961,727	553,172	81%
Acela	83%	10,623	2,487	77%	32,249	8,215	75%	626,541	126,151	80%
Northeast Regional	79%	30,468	5,348	82%	106,925	22,650	79%	2,335,186	427,021	82%
Richmond / Newport News / Norfolk	77%	8,844	2,247	75%	32,439	10,129	69%	709,513	155,705	78%
Springfield Shuttles	89%	804	56	93%	2,612	337	87%	43,579	5,011	89%
Roanoke	79%	2,239	757	66%	8,604	1,393	84%	179,120	28,545	84%
On Spine Northeast Regional	80%	18,581	2,288	88%	63,270	10,791	83%	1,402,974	237,760	83%
State Supported	80%	34,434	7,045	80%	120,559	23,956	80%	2,818,598	513,382	82%
Borealis	60%	420	126	70%	1,546	278	82%	38,024	9,912	74%
Capitol Corridor	90%	2,962	790	73%	10,950	1,376	87%	243,040	26,282	89%
Carolinian	60%	943	505	46%	3,303	904	73%	76,937	21,841	72%
Cascades	63%	1,339	312	77%	5,549	1,766	68%	152,653	37,190	76%
Downeaster	82%	1,147	163	86%	3,421	256	93%	97,470	12,073	88%
Empire	78%	4,138	1,133	73%	14,537	3,454	76%	337,829	66,868	80%
Adirondack	72%	170	95	44%	821	234	71%	21,822	6,823	69%
Ethan Allen Express	70%	442	162	63%	1,502	188	87%	38,780	11,853	69%
Maple Leaf	70%	446	376	16%	2,005	863	57%	42,203	14,098	67%
New York - Albany	85%	2,015	2	100%	6,388	465	93%	146,434	19,775	86%
New York - Niagara Falls	75%	1,065	498	53%	3,821	1,704	55%	88,590	14,319	84%
Gold Runner	73%	1,303	590	55%	6,879	2,023	71%	162,819	58,241	64%
Heartland Flyer	65%	87	43	51%	416	103	75%	12,978	7,674	41%
Hiawatha	90%	1,521	461	70%	4,654	1,597	66%	112,665	12,607	89%
Illinois	78%	1,576	745	53%	7,176	2,659	63%	157,621	42,130	73%
Carl Sandburg / Illinois Zephyr	85%	257	31	88%	1,035	386	63%	26,366	6,974	74%
Illini / Saluki	85%	402	123	69%	1,884	261	86%	56,946	13,777	76%
Lincoln Service	70%	917	591	36%	4,257	2,012	53%	74,309	21,379	71%
Keystone	92%	9,563	838	91%	26,632	3,179	88%	537,201	45,136	92%
Lincoln / Missouri	60%	493	117	76%	2,024	850	58%	50,590	25,657	49%
Mardi Gras Service	80%	233	20	91%	637	20	97%	27,513	3,742	86%
Michigan	69%	1,289	422	67%	5,910	2,693	54%	125,802	32,680	74%
Blue Water	70%	178	163	8%	1,376	743	46%	32,279	8,062	75%
Pere Marquette	85%	189	0	100%	741	0	100%	16,720	1,932	88%
Wolverine	65%	922	259	72%	3,793	1,950	49%	76,803	22,686	70%
Missouri	80%	118	70	41%	532	239	55%	15,032	3,752	75%
Pacific Surfliner	85%	4,660	115	98%	17,234	1,144	93%	436,661	60,055	86%
Pennsylvanian	72%	791	409	48%	2,568	547	79%	59,740	6,496	89%
Piedmont	73%	679	186	73%	2,937	265	91%	87,782	22,165	75%
Vermont	75%	1,172	0	100%	3,654	603	83%	86,241	18,881	78%
Long Distance	56%	11,871	6,572	45%	43,928	18,832	57%	806,362	267,820	67%
Auto Train	57%	787	460	42%	2,407	931	61%	42,425	8,182	81%
California Zephyr	50%	883	354	60%	3,096	1,493	52%	60,173	17,214	71%
Cardinal	55%	288	253	12%	696	253	64%	18,077	8,567	53%
City Of New Orleans	75%	639	10	98%	2,204	162	93%	45,639	9,928	78%
Coast Starlight	60%	971	592	39%	4,456	1,867	58%	75,335	24,383	68%
Crescent	70%	717	97	86%	2,940	216	93%	62,056	16,021	74%
Empire Builder	55%	1,058	669	37%	3,794	2,190	42%	66,437	23,026	65%
Floridian	40%	1,726	1,369	21%	6,380	3,730	42%	110,727	58,305	47%
Lake Shore Ltd	73%	994	553	44%	3,538	1,779	50%	59,669	10,086	83%
Palmetto	65%	905	117	87%	2,984	1,115	63%	63,056	9,567	85%
Silver Meteor	45%	912	428	53%	3,453	938	73%	66,558	19,346	71%
Southwest Chief	40%	801	801	0%	2,938	2,067	30%	54,913	32,592	41%
Sunset Ltd	70%	332	65	80%	1,120	93	92%	17,970	4,466	75%
Texas Eagle	50%	858	804	6%	3,922	1,998	49%	63,327	26,137	59%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00107 00000005500 "UNCLASSIFIED" 12/17/2025

Train Index Dates Through December 03, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	18,275	331,248	552	349,479	6,840,041	511

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	657	100,400	65	12,976	2,002,636	65
INFRASTRUCTURE PLANNED	135	299	100,400	30	10,880	2,002,636	54
FLEET RELIABILITY	90	3,225	331,248	97	50,896	6,840,041	74
TRAIN OPERATIONS	424	14,094	331,248	425	274,727	6,840,041	402

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/03/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	53	83.0%	931	149	84.0%	18,840	2,339	87.6%
Central Division	85.5%	65	7	89.2%	198	31	84.3%	4,220	400	90.5%
Northeast Division	80.0%	101	14	86.1%	301	40	86.7%	5,897	792	86.6%
Southeast Division	72.5%	74	20	73.0%	221	41	81.4%	4,420	558	87.4%
Southwest Division	77.0%	71	12	83.1%	211	37	82.5%	4,303	589	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/03/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	53	83.0%	931	149	84.0%	18,840	2,339	87.6%
Central Division	85.5%	65	7	89.2%	198	31	84.3%	4,220	400	90.5%
CDL	90.0%	1	0	100.0%	4	0	100.0%	118	6	94.9%
CHI	85.0%	26	5	80.8%	80	16	80.0%	1,713	153	91.1%
EUG	86.5%	2	0	100.0%	6	3	50.0%	123	18	85.4%
GRR	98.0%	1	0	100.0%	3	0	100.0%	64	0	100.0%
KCY	84.5%	2	0	100.0%	6	1	83.3%	126	12	90.5%
MKE	86.5%	6	0	100.0%	18	3	83.3%	374	33	91.2%
MSP	94.0%	1	0	100.0%	3	0	100.0%	64	3	95.3%
PDX	78.0%	5	0	100.0%	15	1	93.3%	321	47	85.4%
PNT	91.5%	3	1	66.7%	9	1	88.9%	135	6	95.6%
PTH	93.0%	1	0	100.0%	3	0	100.0%	64	2	96.9%
QCY	87.5%	2	0	100.0%	6	0	100.0%	128	12	90.6%
SEA	80.0%	8	0	100.0%	24	4	83.3%	509	78	84.7%
SPK	92.0%	1	0	100.0%	3	0	100.0%	64	1	98.4%
STL	88.0%	4	1	75.0%	12	2	83.3%	254	20	92.1%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	6	0	100.0%	128	4	96.9%
Northeast Division	80.0%	101	14	86.1%	301	40	86.7%	5,897	792	86.6%
ALB	91.5%	7	0	100.0%	21	2	90.5%	388	23	94.1%
BON	43.5%	5	0	100.0%	15	0	100.0%	302	32	89.4%
BOS	86.5%	20	1	95.0%	60	5	91.7%	1,158	108	90.7%
BRK	88.0%	5	0	100.0%	15	0	100.0%	282	13	95.4%
BTN	48.0%	1	0	100.0%	3	0	100.0%	63	17	73.0%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	6	1	83.3%	122	10	91.8%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	3	0	100.0%	64	11	82.8%
NFL	96.5%	2	0	100.0%	6	0	100.0%	128	4	96.9%
NHV	75.5%	6	2	66.7%	18	2	88.9%	325	65	80.0%
NYP	77.5%	43	10	76.7%	127	29	77.2%	2,503	459	81.7%
SAB	98.0%	1	0	100.0%	3	0	100.0%	62	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	21	0	100.0%	370	16	95.7%
TWO	84.0%	1	1	0.0%	3	1	66.7%	63	17	73.0%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	20	73.0%	221	41	81.4%	4,420	558	87.4%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	1	80.0%	15	1	93.3%	320	26	91.9%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	3	76.9%	39	12	69.2%	719	110	84.7%
LOR	69.5%	1	0	100.0%	3	1	66.7%	64	6	90.6%
MIA	87.5%	2	1	50.0%	6	1	83.3%	128	14	89.1%
MOE	94.0%	2	0	100.0%	6	0	100.0%	128	3	97.7%
NFK	86.0%	3	0	100.0%	9	1	88.9%	179	16	91.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/03/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/03/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	311	53	83.0%	931	149	84.0%	18,840	2,339	87.6%
Southeast Division	72.5%	74	20	73.0%	221	41	81.4%	4,420	558	87.4%
NOL	92.0%	5	0	100.0%	14	0	100.0%	283	14	95.1%
NPN	96.0%	2	0	100.0%	6	0	100.0%	103	7	93.2%
PGH	92.0%	1	0	100.0%	3	0	100.0%	64	1	98.4%
PHL	45.0%	5	4	20.0%	15	10	33.3%	296	133	55.1%
RGH	97.0%	4	1	75.0%	12	1	91.7%	252	4	98.4%
RNK	85.5%	2	0	100.0%	6	0	100.0%	127	14	89.0%
RVM	86.0%	1	1	0.0%	3	1	66.7%	74	12	83.8%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	1	0.0%	3	1	66.7%	64	1	98.4%
SFA	70.5%	1	0	100.0%	3	0	100.0%	64	3	95.3%
WAS	70.0%	26	8	69.2%	78	12	84.6%	1,547	189	87.8%
Southwest Division	77.0%	71	12	83.1%	211	37	82.5%	4,303	589	86.3%
ARN	60.5%	1	1	0.0%	3	2	33.3%	64	7	89.1%
BFD	75.5%	6	0	100.0%	18	1	94.4%	365	85	76.7%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	3	1	66.7%	66	18	72.7%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	3	0	100.0%	63	3	95.2%
GTA	72.5%	3	0	100.0%	9	1	88.9%	185	18	90.3%
LAX	77.5%	10	2	80.0%	28	7	75.0%	588	68	88.4%
OKC	96.0%	1	0	100.0%	3	0	100.0%	64	3	95.3%
OKJ	79.0%	12	5	58.3%	36	12	66.7%	696	164	76.4%
SAC	73.5%	14	3	78.6%	42	9	78.6%	830	95	88.6%
SAN	77.0%	12	1	91.7%	36	2	94.4%	729	67	90.8%
SAS	85.0%	1	0	100.0%	3	0	100.0%	64	3	95.3%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	21	1	95.2%	446	41	90.8%
SLO	62.0%	2	0	100.0%	6	1	83.3%	123	12	90.2%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	-	-	-	10	1	90.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		2	0	100.0%	28	1	96.4%	2	0	100.0%	28	1	96.4%
3	305	3	2	33.3%	64	6	90.6%	3	2	33.3%	64	25	60.9%
4	47	3	2	33.3%	64	8	87.5%	3	3	0.0%	64	41	35.9%
5	148	3	1	66.7%	63	8	87.3%	3	2	33.3%	62	8	87.1%
6		3	1	66.7%	64	18	71.9%	3	2	33.3%	64	23	64.1%
7		3	0	100.0%	64	4	93.8%	3	1	66.7%	64	8	87.5%
8	63	3	1	66.7%	64	21	67.2%	3	2	33.3%	64	29	54.7%
11		3	1	66.7%	63	12	81.0%	3	0	100.0%	61	7	88.5%
14		3	0	100.0%	64	9	85.9%	3	0	100.0%	63	18	71.4%
19		3	2	33.3%	64	10	84.4%	3	0	100.0%	64	11	82.8%
20		3	0	100.0%	64	6	90.6%	3	0	100.0%	64	6	90.6%
21	46	3	1	66.7%	63	9	85.7%	3	2	33.3%	63	13	79.4%
22	56	3	0	100.0%	64	3	95.3%	3	1	66.7%	63	14	77.8%
23		3	0	100.0%	64	3	95.3%	3	0	100.0%	64	10	84.4%
24	87	3	0	100.0%	64	2	96.9%	3	1	66.7%	64	7	89.1%
25		3	0	100.0%	64	0	100.0%	3	0	100.0%	64	9	85.9%
26		3	0	100.0%	64	2	96.9%	3	0	100.0%	64	11	82.8%
27		3	2	33.3%	64	3	95.3%	3	1	66.7%	64	11	82.8%
28		3	1	66.7%	64	14	78.1%	3	1	66.7%	64	9	85.9%
40	71	3	1	66.7%	64	10	84.4%	3	1	66.7%	64	23	64.1%
41	215	3	2	33.3%	64	20	68.8%	3	3	0.0%	64	42	34.4%
42		3	0	100.0%	64	1	98.4%	3	0	100.0%	64	9	85.9%
43	42	3	0	100.0%	64	5	92.2%	3	1	66.7%	64	4	93.8%
48		3	0	100.0%	64	5	92.2%	3	1	66.7%	64	4	93.8%
49	205	3	0	100.0%	64	10	84.4%	3	2	33.3%	64	7	89.1%
50	75	1	1	0.0%	27	5	81.5%	1	1	0.0%	28	14	50.0%
52		3	0	100.0%	64	3	95.3%	3	0	100.0%	64	12	81.3%
53		3	1	66.7%	64	6	90.6%	3	1	66.7%	64	9	85.9%
55		3	0	100.0%	45	0	100.0%	3	0	100.0%	45	6	86.7%
56		3	1	66.7%	45	8	82.2%	3	1	66.7%	45	7	84.4%
58		3	0	100.0%	63	2	96.8%	3	0	100.0%	62	7	88.7%
59		3	0	100.0%	62	3	95.2%	3	0	100.0%	62	3	95.2%
63		3	1	66.7%	64	22	65.6%	3	1	66.7%	64	30	53.1%
64	37	3	1	66.7%	63	17	73.0%	3	1	66.7%	63	11	82.5%
66		3	0	100.0%	64	10	84.4%	3	0	100.0%	64	13	79.7%
67		3	0	100.0%	45	2	95.6%	3	0	100.0%	45	7	84.4%
68	17	3	0	100.0%	64	11	82.8%	3	2	33.3%	64	27	57.8%
69		3	0	100.0%	64	7	89.1%	3	0	100.0%	64	7	89.1%
71	65	3	1	66.7%	64	1	98.4%	3	1	66.7%	64	17	73.4%
72	27	3	1	66.7%	64	6	90.6%	3	1	66.7%	64	11	82.8%
73		3	0	100.0%	64	1	98.4%	3	0	100.0%	63	33	47.6%
74		3	0	100.0%	64	5	92.2%	3	0	100.0%	64	20	68.8%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		3	0	100.0%	64	2	96.9%	3	1	66.7%	64	29	54.7%
76		3	0	100.0%	64	4	93.8%	3	0	100.0%	64	30	53.1%
77		3	0	100.0%	64	2	96.9%	3	0	100.0%	64	22	65.6%
78		3	0	100.0%	64	3	95.3%	3	1	66.7%	64	10	84.4%
79		3	0	100.0%	64	11	82.8%	3	0	100.0%	63	11	82.5%
80	59	3	0	100.0%	64	8	87.5%	3	2	33.3%	63	7	88.9%
84		3	0	100.0%	45	3	93.3%	3	1	66.7%	45	6	86.7%
85		3	0	100.0%	45	1	97.8%	3	1	66.7%	45	16	64.4%
86		3	1	66.7%	45	5	88.9%	3	2	33.3%	45	21	53.3%
89		3	1	66.7%	64	13	79.7%	3	1	66.7%	64	7	89.1%
90		3	1	66.7%	64	1	98.4%	3	0	100.0%	64	6	90.6%
93		3	0	100.0%	45	6	86.7%	3	0	100.0%	44	10	77.3%
94	36	3	1	66.7%	45	7	84.4%	3	2	33.3%	45	14	68.9%
95	53	3	0	100.0%	45	1	97.8%	3	2	33.3%	45	13	71.1%
97		3	3	0.0%	64	21	67.2%	3	0	100.0%	64	16	75.0%
98	62	3	0	100.0%	64	4	93.8%	3	1	66.7%	64	12	81.3%
110		3	1	66.7%	45	20	55.6%	3	0	100.0%	45	3	93.3%
111		3	0	100.0%	45	4	91.1%	3	0	100.0%	45	3	93.3%
112		3	0	100.0%	45	4	91.1%	3	0	100.0%	45	5	88.9%
114		3	1	66.7%	45	9	80.0%	2	0	100.0%	44	0	100.0%
119	21	3	0	100.0%	45	9	80.0%	3	1	66.7%	45	4	91.1%
125	26	3	0	100.0%	45	2	95.6%	3	3	0.0%	45	9	80.0%
129		3	1	66.7%	45	14	68.9%	3	0	100.0%	45	6	86.7%
130		3	0	100.0%	45	4	91.1%	3	0	100.0%	45	4	91.1%
131	42	3	0	100.0%	45	4	91.1%	3	1	66.7%	45	1	97.8%
133	32	3	0	100.0%	45	19	57.8%	3	1	66.7%	45	21	53.3%
134	70	3	0	100.0%	45	4	91.1%	3	2	33.3%	45	10	77.8%
136		3	1	66.7%	45	4	91.1%	2	0	100.0%	45	3	93.3%
137		3	0	100.0%	43	8	81.4%	3	0	100.0%	43	10	76.7%
138		3	0	100.0%	45	6	86.7%	3	0	100.0%	45	2	95.6%
141		3	0	100.0%	45	3	93.3%	3	1	66.7%	45	9	80.0%
148		3	1	66.7%	45	5	88.9%	3	0	100.0%	44	9	79.5%
151		3	3	0.0%	64	17	73.4%	3	0	100.0%	63	16	74.6%
170		3	0	100.0%	42	3	92.9%	3	1	66.7%	42	10	76.2%
171	34	3	0	100.0%	45	3	93.3%	3	1	66.7%	45	6	86.7%
172		3	0	100.0%	45	4	91.1%	3	1	66.7%	45	16	64.4%
173		3	1	66.7%	45	3	93.3%	3	1	66.7%	45	16	64.4%
174		3	0	100.0%	45	3	93.3%	3	1	66.7%	45	9	80.0%
175		3	1	66.7%	45	3	93.3%	3	2	33.3%	45	10	77.8%
176		3	0	100.0%	45	3	93.3%	3	0	100.0%	45	3	93.3%
177		3	0	100.0%	45	8	82.2%	3	0	100.0%	45	20	55.6%
178		3	0	100.0%	45	7	84.4%	2	0	100.0%	45	5	88.9%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179	18	3	0	100.0%	45	4	91.1%	2	1	50.0%	45	11	75.6%
181		3	1	66.7%	45	7	84.4%	2	0	100.0%	44	1	97.7%
182		3	0	100.0%	45	9	80.0%	3	0	100.0%	45	3	93.3%
183		3	0	100.0%	45	11	75.6%	3	1	66.7%	45	7	84.4%
184		3	0	100.0%	45	8	82.2%	3	0	100.0%	45	5	88.9%
185		3	0	100.0%	45	8	82.2%	3	0	100.0%	45	1	97.8%
186	22	3	0	100.0%	45	7	84.4%	3	1	66.7%	45	13	71.1%
190		3	1	66.7%	45	17	62.2%	3	1	66.7%	45	11	75.6%
192		3	0	100.0%	43	6	86.0%	3	0	100.0%	43	1	97.7%
193		3	0	100.0%	45	13	71.1%	3	1	66.7%	45	15	66.7%
196		3	0	100.0%	45	0	100.0%	3	0	100.0%	45	2	95.6%
197		3	3	0.0%	45	18	60.0%	3	2	33.3%	45	8	82.2%
232		3	0	100.0%	64	1	98.4%	3	0	100.0%	64	6	90.6%
233		3	1	66.7%	64	14	78.1%	3	1	66.7%	64	13	79.7%
234		3	0	100.0%	64	3	95.3%	3	0	100.0%	64	2	96.9%
236		3	0	100.0%	64	1	98.4%	3	0	100.0%	64	11	82.8%
237		3	0	100.0%	64	10	84.4%	3	0	100.0%	64	4	93.8%
239		3	1	66.7%	63	16	74.6%	3	0	100.0%	63	2	96.8%
240		3	1	66.7%	64	7	89.1%	3	0	100.0%	64	7	89.1%
241		3	3	0.0%	64	19	70.3%	3	1	66.7%	64	11	82.8%
243		3	0	100.0%	45	16	64.4%	3	0	100.0%	46	8	82.6%
244		3	0	100.0%	64	2	96.9%	3	0	100.0%	64	15	76.6%
280	45	3	0	100.0%	64	3	95.3%	3	2	33.3%	64	12	81.3%
281	46	3	0	100.0%	64	8	87.5%	3	1	66.7%	64	6	90.6%
283		3	2	33.3%	64	10	84.4%	3	0	100.0%	64	9	85.9%
284		3	0	100.0%	64	1	98.4%	3	1	66.7%	64	6	90.6%
290		3	0	100.0%	64	18	71.9%	3	0	100.0%	63	21	66.7%
291	66	3	1	66.7%	64	14	78.1%	3	1	66.7%	64	13	79.7%
300	75	3	1	66.7%	64	3	95.3%	3	1	66.7%	63	15	76.2%
301		3	0	100.0%	63	1	98.4%	3	0	100.0%	62	9	85.5%
302	44	3	0	100.0%	63	6	90.5%	3	1	66.7%	61	18	70.5%
305		3	0	100.0%	64	5	92.2%	3	1	66.7%	63	21	66.7%
306	No OS	3	0	100.0%	63	2	96.8%	3	3	0.0%	62	14	77.4%
307		3	0	100.0%	63	5	92.1%	3	1	66.7%	63	12	81.0%
311	21	3	1	66.7%	63	8	87.3%	3	2	33.3%	63	16	74.6%
316		3	0	100.0%	63	3	95.2%	3	1	66.7%	63	13	79.4%
318		3	1	66.7%	64	10	84.4%	3	2	33.3%	63	27	57.1%
319		3	0	100.0%	64	2	96.9%	3	0	100.0%	64	36	43.8%
329		3	0	100.0%	45	1	97.8%	3	1	66.7%	45	3	93.3%
330		3	0	100.0%	54	2	96.3%	3	2	33.3%	54	3	94.4%
331		3	2	33.3%	64	6	90.6%	3	2	33.3%	64	8	87.5%
332	11	3	1	66.7%	64	6	90.6%	3	2	33.3%	64	7	89.1%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334	29	3	1	66.7%	64	2	96.9%	3	2	33.3%	63	6	90.5%
335		3	2	33.3%	64	9	85.9%	2	0	100.0%	62	9	85.5%
336		3	0	100.0%	64	1	98.4%	3	0	100.0%	64	4	93.8%
337		3	0	100.0%	64	4	93.8%	3	1	66.7%	64	6	90.6%
338	16	3	1	66.7%	64	16	75.0%	2	1	50.0%	62	13	79.0%
339	22	3	1	66.7%	64	15	76.6%	3	1	66.7%	64	12	81.3%
341		3	0	100.0%	63	9	85.7%	3	1	66.7%	63	9	85.7%
342		3	0	100.0%	64	6	90.6%	3	1	66.7%	63	9	85.7%
350		3	0	100.0%	46	2	95.7%	3	1	66.7%	46	23	50.0%
351		3	0	100.0%	64	3	95.3%	3	1	66.7%	64	27	57.8%
352	22	3	0	100.0%	64	4	93.8%	3	1	66.7%	62	15	75.8%
353		3	0	100.0%	43	2	95.3%	3	2	33.3%	43	7	83.7%
354	55	3	0	100.0%	64	3	95.3%	3	3	0.0%	64	17	73.4%
355		3	1	66.7%	64	6	90.6%	3	0	100.0%	64	13	79.7%
364	178	3	2	33.3%	64	7	89.1%	3	2	33.3%	64	10	84.4%
365	55	3	0	100.0%	64	2	96.9%	3	2	33.3%	64	18	71.9%
370		3	0	100.0%	64	2	96.9%	3	0	100.0%	64	9	85.9%
371		3	0	100.0%	64	0	100.0%	3	0	100.0%	64	4	93.8%
380		3	0	100.0%	64	10	84.4%	3	0	100.0%	64	13	79.7%
381		3	0	100.0%	64	1	98.4%	3	1	66.7%	64	8	87.5%
382	No OS	3	0	100.0%	64	2	96.9%	3	2	33.3%	64	17	73.4%
383	21	3	0	100.0%	64	5	92.2%	3	3	0.0%	63	25	60.3%
392	24	3	0	100.0%	64	2	96.9%	3	2	33.3%	63	17	73.0%
393		3	0	100.0%	64	5	92.2%	3	0	100.0%	63	15	76.2%
417		3	0	100.0%	42	8	81.0%	3	0	100.0%	40	1	97.5%
425		3	0	100.0%	42	1	97.6%	3	0	100.0%	42	1	97.6%
448		3	2	33.3%	5	3	40.0%	3	2	33.3%	4	2	50.0%
449		3	0	100.0%	3	0	100.0%	3	1	66.7%	3	1	66.7%
470		3	1	66.7%	45	6	86.7%	3	0	100.0%	45	7	84.4%
471		3	0	100.0%	42	0	100.0%	3	0	100.0%	42	0	100.0%
473		3	0	100.0%	45	3	93.3%	3	0	100.0%	45	1	97.8%
474		3	2	33.3%	43	15	65.1%	3	1	66.7%	40	12	70.0%
475		3	0	100.0%	45	0	100.0%	3	0	100.0%	45	1	97.8%
478		3	0	100.0%	43	10	76.7%	3	0	100.0%	43	6	86.0%
479		3	1	66.7%	45	5	88.9%	3	0	100.0%	45	1	97.8%
486		3	0	100.0%	46	7	84.8%	3	1	66.7%	45	7	84.4%
490		3	0	100.0%	22	5	77.3%	3	0	100.0%	22	2	90.9%
494	27	3	0	100.0%	47	9	80.9%	3	2	33.3%	44	9	79.5%
495		3	0	100.0%	45	2	95.6%	3	0	100.0%	45	1	97.8%
500		3	0	100.0%	64	5	92.2%	3	0	100.0%	63	5	92.1%
502		3	0	100.0%	64	6	90.6%	3	0	100.0%	63	16	74.6%
503		3	0	100.0%	61	8	86.9%	3	1	66.7%	60	16	73.3%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504	29	3	1	66.7%	64	6	90.6%	3	2	33.3%	64	21	67.2%
505		3	1	66.7%	64	11	82.8%	3	0	100.0%	62	13	79.0%
506		3	0	100.0%	63	9	85.7%	3	0	100.0%	62	9	85.5%
507		3	1	66.7%	64	8	87.5%	3	1	66.7%	64	23	64.1%
508		3	2	33.3%	62	13	79.0%	3	2	33.3%	62	15	75.8%
509		3	0	100.0%	64	4	93.8%	3	0	100.0%	64	13	79.7%
511		3	0	100.0%	64	4	93.8%	3	0	100.0%	64	12	81.3%
516	55	3	0	100.0%	64	9	85.9%	3	1	66.7%	64	29	54.7%
517		3	0	100.0%	64	1	98.4%	3	1	66.7%	63	23	63.5%
518	58	3	0	100.0%	64	13	79.7%	3	3	0.0%	64	39	39.1%
519		3	0	100.0%	64	3	95.3%	3	1	66.7%	64	10	84.4%
520		3	0	100.0%	41	3	92.7%	3	0	100.0%	41	2	95.1%
521		3	0	100.0%	44	0	100.0%	3	0	100.0%	44	3	93.2%
522	Cncld	3	1	66.7%	44	5	88.6%	2	0	100.0%	43	4	90.7%
523		3	0	100.0%	44	0	100.0%	3	1	66.7%	44	5	88.6%
524		3	0	100.0%	44	2	95.5%	3	0	100.0%	44	3	93.2%
525		3	0	100.0%	44	1	97.7%	2	0	100.0%	43	5	88.4%
526		3	2	33.3%	44	8	81.8%	2	0	100.0%	43	4	90.7%
527		3	0	100.0%	44	1	97.7%	3	0	100.0%	44	2	95.5%
528		3	1	66.7%	44	6	86.4%	3	1	66.7%	44	11	75.0%
529		3	2	33.3%	44	5	88.6%	3	0	100.0%	44	7	84.1%
531		3	0	100.0%	44	1	97.7%	3	1	66.7%	44	4	90.9%
532		3	0	100.0%	44	1	97.7%	3	0	100.0%	44	7	84.1%
534	20	3	1	66.7%	41	6	85.4%	3	1	66.7%	41	4	90.2%
535	Cncld	3	2	33.3%	41	3	92.7%	2	0	100.0%	40	1	97.5%
536	Cncld	3	0	100.0%	44	4	90.9%	2	0	100.0%	43	1	97.7%
537		3	1	66.7%	44	4	90.9%	2	1	50.0%	43	2	95.3%
538	194	3	0	100.0%	44	6	86.4%	3	1	66.7%	44	6	86.4%
540	167	3	1	66.7%	44	5	88.6%	3	1	66.7%	42	2	95.2%
541		3	1	66.7%	44	6	86.4%	3	0	100.0%	44	11	75.0%
542	153	3	0	100.0%	44	3	93.2%	3	1	66.7%	43	11	74.4%
543		3	0	100.0%	44	6	86.4%	3	0	100.0%	44	12	72.7%
544	96	3	0	100.0%	43	2	95.3%	3	2	33.3%	43	6	86.0%
545	142	3	0	100.0%	44	4	90.9%	3	1	66.7%	43	5	88.4%
546	64	3	0	100.0%	44	6	86.4%	3	2	33.3%	44	7	84.1%
547	86	3	0	100.0%	44	4	90.9%	3	2	33.3%	44	9	79.5%
548	17	3	1	66.7%	44	9	79.5%	3	1	66.7%	44	6	86.4%
549	Cncld	3	2	33.3%	41	12	70.7%	2	0	100.0%	39	6	84.6%
551	No OS	3	2	33.3%	44	8	81.8%	3	1	66.7%	42	7	83.3%
562		3	1	66.7%	62	9	85.5%	3	1	66.7%	61	7	88.5%
564		3	1	66.7%	62	7	88.7%	3	1	66.7%	59	11	81.4%
566		3	0	100.0%	62	5	91.9%	3	0	100.0%	59	6	89.8%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572		3	0	100.0%	61	6	90.2%	3	0	100.0%	60	14	76.7%
573		3	0	100.0%	62	9	85.5%	3	0	100.0%	61	8	86.9%
577		3	0	100.0%	60	5	91.7%	3	1	66.7%	56	3	94.6%
580		3	0	100.0%	62	2	96.8%	3	0	100.0%	62	7	88.7%
581		3	0	100.0%	62	7	88.7%	3	1	66.7%	62	13	79.0%
582		3	0	100.0%	62	4	93.5%	3	0	100.0%	60	4	93.3%
586		3	3	0.0%	62	14	77.4%	3	0	100.0%	59	9	84.7%
587		3	0	100.0%	62	3	95.2%	3	0	100.0%	60	9	85.0%
591		3	0	100.0%	62	1	98.4%	3	0	100.0%	62	6	90.3%
593		3	0	100.0%	62	9	85.5%	3	0	100.0%	56	5	91.1%
595		3	1	66.7%	61	15	75.4%	3	0	100.0%	60	10	83.3%
600		3	0	100.0%	45	1	97.8%	3	0	100.0%	45	4	91.1%
601		3	2	33.3%	45	21	53.3%	3	0	100.0%	45	13	71.1%
605	11	3	3	0.0%	45	24	46.7%	3	1	66.7%	44	3	93.2%
607		3	0	100.0%	45	3	93.3%	3	1	66.7%	44	2	95.5%
609		3	0	100.0%	44	1	97.7%	3	0	100.0%	44	3	93.2%
620		3	2	33.3%	44	11	75.0%	3	0	100.0%	42	2	95.2%
624		3	1	66.7%	45	11	75.6%	2	0	100.0%	45	9	80.0%
639		3	2	33.3%	45	12	73.3%	3	0	100.0%	45	4	91.1%
640	13	3	0	100.0%	45	2	95.6%	3	3	0.0%	45	21	53.3%
641		3	2	33.3%	45	7	84.4%	3	0	100.0%	45	7	84.4%
642		3	1	66.7%	44	3	93.2%	3	1	66.7%	44	5	88.6%
643		3	0	100.0%	45	7	84.4%	3	1	66.7%	44	4	90.9%
644		3	0	100.0%	45	5	88.9%	3	0	100.0%	45	5	88.9%
645		3	0	100.0%	45	3	93.3%	3	2	33.3%	45	8	82.2%
646	37	3	1	66.7%	45	8	82.2%	3	2	33.3%	44	22	50.0%
647		3	0	100.0%	45	2	95.6%	3	0	100.0%	45	12	73.3%
648		3	2	33.3%	45	8	82.2%	3	1	66.7%	45	5	88.9%
649		3	2	33.3%	45	8	82.2%	3	0	100.0%	44	7	84.1%
650		3	0	100.0%	45	9	80.0%	3	1	66.7%	45	8	82.2%
651		3	0	100.0%	45	5	88.9%	3	0	100.0%	45	13	71.1%
652		3	0	100.0%	45	8	82.2%	3	1	66.7%	44	9	79.5%
653		3	1	66.7%	45	9	80.0%	3	0	100.0%	45	14	68.9%
654		3	3	0.0%	45	8	82.2%	3	0	100.0%	45	2	95.6%
655		3	1	66.7%	43	13	69.8%	3	1	66.7%	42	9	78.6%
656		3	2	33.3%	45	9	80.0%	3	0	100.0%	45	5	88.9%
657		3	0	100.0%	45	3	93.3%	3	0	100.0%	45	9	80.0%
658		3	0	100.0%	45	7	84.4%	3	0	100.0%	45	6	86.7%
680		3	0	100.0%	46	2	95.7%	3	0	100.0%	46	3	93.5%
681		3	0	100.0%	46	2	95.7%	3	0	100.0%	46	13	71.7%
682		3	0	100.0%	46	0	100.0%	3	0	100.0%	46	10	78.3%
683		3	0	100.0%	29	3	89.7%	3	0	100.0%	29	9	69.0%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

25-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
684		3	0	100.0%	28	4	85.7%	3	0	100.0%	28	8	71.4%
685		3	0	100.0%	45	4	91.1%	3	0	100.0%	45	13	71.1%
686		3	0	100.0%	46	13	71.7%	3	1	66.7%	46	11	76.1%
687	66	3	0	100.0%	46	6	87.0%	3	1	66.7%	46	7	84.8%
688		3	0	100.0%	46	1	97.8%	3	0	100.0%	46	12	73.9%
702	32	3	1	66.7%	64	16	75.0%	3	2	33.3%	63	21	66.7%
703		3	0	100.0%	64	15	76.6%	3	0	100.0%	64	16	75.0%
710		3	1	66.7%	64	25	60.9%	3	0	100.0%	64	28	56.3%
711		3	0	100.0%	60	4	93.3%	3	1	66.7%	56	8	85.7%
712		3	1	66.7%	64	18	71.9%	3	1	66.7%	63	24	61.9%
713	37	3	0	100.0%	64	9	85.9%	3	1	66.7%	58	28	51.7%
714		3	1	66.7%	58	20	65.5%	3	0	100.0%	53	16	69.8%
715	Cncld	3	0	100.0%	64	22	65.6%	2	2	0.0%	60	31	48.3%
716	27	3	1	66.7%	64	24	62.5%	3	2	33.3%	63	25	60.3%
717	28	3	0	100.0%	55	13	76.4%	3	1	66.7%	50	14	72.0%
718	No OS	3	2	33.3%	64	24	62.5%	3	1	66.7%	64	17	73.4%
719		3	1	66.7%	64	25	60.9%	3	0	100.0%	62	16	74.2%
761		3	0	100.0%	62	3	95.2%	3	0	100.0%	62	9	85.5%
765		3	1	66.7%	62	8	87.1%	3	0	100.0%	62	13	79.0%
769		3	0	100.0%	62	4	93.5%	3	0	100.0%	60	11	81.7%
770		3	0	100.0%	62	7	88.7%	3	0	100.0%	62	9	85.5%
774		3	0	100.0%	62	6	90.3%	3	0	100.0%	61	11	82.0%
779		3	0	100.0%	62	4	93.5%	3	0	100.0%	61	9	85.2%
784	36	3	1	66.7%	62	7	88.7%	3	2	33.3%	61	31	49.2%
785		3	0	100.0%	62	0	100.0%	3	0	100.0%	62	7	88.7%
790		3	0	100.0%	62	5	91.9%	3	0	100.0%	62	7	88.7%
794		3	1	66.7%	62	6	90.3%	3	0	100.0%	61	10	83.6%
821		3	0	100.0%	64	3	95.3%	3	2	33.3%	64	42	34.4%
822	20	3	0	100.0%	64	3	95.3%	3	1	66.7%	64	45	29.7%
1333	20	3	2	33.3%	64	6	90.6%	3	2	33.3%	63	28	55.6%
1340		3	0	100.0%	64	3	95.3%	3	0	100.0%	64	13	79.7%
1689		2	0	100.0%	13	1	92.3%	1	0	100.0%	13	0	100.0%
2103		3	0	100.0%	44	3	93.2%	3	0	100.0%	44	1	97.7%
2104		3	1	66.7%	15	3	80.0%	3	1	66.7%	15	3	80.0%
2107		3	0	100.0%	45	7	84.4%	3	1	66.7%	43	1	97.7%
2108		3	0	100.0%	45	2	95.6%	3	0	100.0%	43	0	100.0%
2117	61	3	1	66.7%	15	4	73.3%	3	1	66.7%	15	2	86.7%
2121		3	0	100.0%	43	3	93.0%	3	0	100.0%	43	3	93.0%
2122		3	1	66.7%	45	7	84.4%	3	0	100.0%	45	3	93.3%
2124	104	3	1	66.7%	33	5	84.8%	3	1	66.7%	33	2	93.9%
2150		3	0	100.0%	45	9	80.0%	3	0	100.0%	45	9	80.0%
2151		3	0	100.0%	45	0	100.0%	3	1	66.7%	44	7	84.1%

Amtrak On Time Performance

Trains Arriving Through: 12/3/2025

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2152		3	0	100.0%	41	2	95.1%	3	2	33.3%	40	11	72.5%
2153		3	0	100.0%	45	6	86.7%	3	1	66.7%	45	10	77.8%
2154	96	3	2	33.3%	45	16	64.4%	3	2	33.3%	43	23	46.5%
2155	20	3	0	100.0%	45	2	95.6%	3	1	66.7%	43	10	76.7%
2159	40	3	0	100.0%	44	1	97.7%	3	1	66.7%	44	8	81.8%
2162		3	0	100.0%	45	2	95.6%	3	1	66.7%	44	10	77.3%
2163	16	3	0	100.0%	45	4	91.1%	3	1	66.7%	45	11	75.6%
2166		3	1	66.7%	45	6	86.7%	3	0	100.0%	43	6	86.0%
2167		3	0	100.0%	45	5	88.9%	3	0	100.0%	45	8	82.2%
2168		3	0	100.0%	45	2	95.6%	3	0	100.0%	45	6	86.7%
2169		3	2	33.3%	41	12	70.7%	3	1	66.7%	41	16	61.0%
2170		3	2	33.3%	45	9	80.0%	3	2	33.3%	45	11	75.6%
2172	27	3	0	100.0%	45	6	86.7%	3	1	66.7%	45	8	82.2%
2173		3	1	66.7%	44	8	81.8%	3	0	100.0%	44	18	59.1%
2190		3	0	100.0%	45	5	88.9%	3	0	100.0%	45	4	91.1%
2193		3	0	100.0%	44	1	97.7%	3	1	66.7%	44	10	77.3%

Amtrak Endpoint OTP Details

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 12/3/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2117	WAS	61	UTL	66	UTL	59	PHL-WIL	AM	Commercial power outage, Milepost, 11.7, 29.7	
2124	NYP	104	CAR	112	CAR	112	WAS-WAS	AM	Heat / AC, PC, 2036 HEATER NOT WORKING AND NEEDED TO WYE.	
2154	BOS	96	ENG	77	ENG	77	WAS-WAS	AM	Other electrical failure, ,, I KNOW ONE OF THE PANOGRAPHS HAD TO HAVE REPAIRS ON IT, WAITING FOR A POWER CAR NO. TRAIN SPOTTED 340A AND RELEASED 710A. IN THE TRACK AT 738A. DP 807A `7" LATE	
2155	WAS	20	OTH	12	WTR	5	XGX-NHV	AM	Wet / slippery rail, Milepost, xgx, nhv, Wheelslip	
2159	WAS	40	UTL	36	UTL	36	PHL-PHL	AM	Commercial power outage, Milepost, 11.7, 29.7, Held for disposition a/c Catenary issues	
2163	WAS	16	DSR	10	DSR	5	NHV-STM	MN	Per bulletin Milepost, 41.7, 40.6, 30, 2	
2172	BOS	27	TRS	45	TRS	42	XNY-BAL	AM	Trespasser strike, Milepost, 98.2, ,, struck a trespasser, trespasser survived, continued north	
94	BOS	36	UTL	55	UTL	44	WAS-WAS	AM	Commercial power outage, Milepost, 29.7, 11.7	
95	NFK	53	UTL	53	UTL	53	XNY-WAS	AM	Commercial power outage, Control Point, ,, 95 HELD OUT DUE TO HOLDING TRAINS FOR SIGNAL OUTAGE 148, 20, 94, 41 AND VRE . HELD OUT UNTIL 27 TRACK WAS CLEAR	
119	WAS	21	CTI	25	CTI	15	BWI-XNY	AM	Follow, MARC, 433, Milepost, 95.7, 134.6	
125	NPN	26	CTI	37	UTL	27	PHL-WIL	AM	Commercial power outage, Milepost, 11.7, 29.7	
131	WAS	42	UTL	52	UTL	49	PHL-WIL	AM	Commercial power outage, Milepost, 11.7, 29.7	
133	WAS	32	DMW	18	DMW	18	XPV-BAL	AM	Held for or routed around MW work or equipment, Milepost, 79.3, ,, opr 2 trk a/c broken I joint on 3 trk at Gunpow	
134	NYP	70	UTL	63	UTL	43	WIL-PHL	AM	Commercial power outage, Milepost, 29.7, 11.7	
171	RNK	34	UTL	39	UTL	39	PHL-PHL	AM	Commercial power outage, Milepost, 11.7, 29.7, Held for disposition a/c Catenary issues	
179	PHL	18	OTH	14	SMW	7	XSH-NYP	AM	Diversion around M/W work, Other, XM9-XGG, SINGLE TRACKING ON NO.2 TRACK A/C 1 TRK O/O/S MANOR TO GATE INT.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/3/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
186	PHL	22	POL	34	POL	31	FBG-FBG	CS	Removal of passenger by police
494	GFD	27	CON	43	CON	43	NHV-NHV	AM	Hold for connecting train, Held for connection of late arrival of AM94
80	NYP	59	PTI	43	DMW	21	RMT-PTB	CS	Hold for defect repair Control Point, Gary
605	HAR	11	OTH	7	OTH	4	PAR-LNC	AM	Lost time - N.A.R.
640	NYP	13	CTI	11	SMW	10	ARD-PHL	AM	Diversions around M/W work, Control Point, .. opr 2trk Overbrook, single tracking a/c 1 trk o/o/s
646	NYP	37	CCR	29	CCR	29	PAO-PHL	AM	Cab signal failure, 9635, Wyed a/c bad order on cc 9635
687	BRK	66	TRS	68	TRS	68	WOB-HHL	MT	Vehicle strike Made contact with the front bumper of a vehicle in the tracks. Waited for Transit Police to arrive and release us, Other, Essex St
64	ALB	37	FTI	48	FTI	23	SYR-SYR	CS	Cross Traffic I161, I019, Control Point, 291
68	NYP	17	CTI	26	CTI	18	POU-CRT	MN	Follow mn, Control Point, 56
280	NYP	45	FTI	67	FTI	64	ROC-XSV	CS	- Stop Signal @ CP 334 - Holding due to M368 in emergency and waiting for M367 to clear westbound - Crossover 2 to 1 @ CP 334 and Crossover 1 to 2 @ CP 320 around M368 M368 and M367, Milepost w/Letters, CP 334, CP 320
281	NFL	46	FTI	43	FTI	37	ROC-BUF	CS	Follow Ran on approaches the whole way Crossed over 1-2 at 417, i169, Milepost, 371, 417
291	BTN	66	ENG	93	ENG	89	HUD-HUD	AM	Main res leak 9701
49	CHI	205	CON	180	CON	180	ALB-ALB	AM	Wait for the late 449.
43	PGH	42	OTH	45	OTH	42	HAR-HAR	NS	Locomotive change
71	CLT	65	RTE	56	RTE	56	RGH-RGH	NS	Late / wrong track bulletins from host railroad CSX, Other, Raleigh DOT yard
72	RGH	27	ITI	39	ITI	39	CLT-CLT	NS	Service, turn, or wye train 71
98	NYP	62	FTI	81	FTI	45	KTR-FLO	CS	Meet #csl031, Control Point, Java
40	CHI	71	HLD	47	FTI	38	XJG-SAV	CS	Cross Traffic S133, Military, Milepost, 530.6, 530.6
41	MIA	215	DCS	141	DCS	104	XFI-COV	CS	Power switch failure Milepost, 3228, 9.2
24	MOE	87	TRS	99	TRS	99	PAG-MOE	CS	Vehicle strike Milepost, 684, 684

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/3/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
5	EMY	148	POL	163	POL	163	RIC-RIC	UP	RR blocked by trespasser or vehicle strike by another train
522	SAC	Trn Cancelled							
534	SAC	20	CCR	23	CCR	23	OKJ-OKJ	UP	Door C8311, Initial terminal
535	OKJ	Trn Cancelled							
536	SAC	Trn Cancelled							
538	ARN	194	POL	196	POL	189	EMY-EMY	UP	RR blocked by trespasser or vehicle strike by another train
540	SAC	167	TRS	158	TRS	158	OKJ-OKJ	UP	Trespasser strike 536 trespasser strike 6.0 MTZ sub, Milepost, 6.0, 6.0
542	SAC	153	TRS	127	TRS	118	OKJ-OKJ	UP	Trespasser strike Holding at Oakland due to trespasser strike, Milepost, 7.18, 7.18
544	SAC	96	TRS	92	TRS	70	OAC-OAC	UP	Held at Oac for TRS incident with 536. Control Point, NI011
545	OKJ	142	POL	109	POL	109	RIC-RIC	UP	RR blocked by trespasser or vehicle strike by another train AMTK 536 trespasser strike.
546	SAC	64	POL	53	POL	25	OKJ-EMY	UP	536 Trespasser Strike
547	SJC	86	POL	77	POL	46	RIC-RIC	UP	RR blocked by trespasser or vehicle strike by another train
548	SAC	17	ITI	28	ITI	28	OKJ-OKJ	UP	Service, turn, or wye train 536, Train 536 became Train 548 at OKJ Station.
549	OKJ	Trn Cancelled							
551	OKJ	No OS Rpt							
50	NYP	75	DCS	41	DCS	32	COI-XH0	CS	Restrictive signal(s) from unknown cause Stop signal at interlocking. Permission to operate. Stayed stop. Permission past stop. Restricted speed to next signal, Stop, Control Point, cottage grove
504	SEA	29	DCS	25	DCS	15	CTL-OLW	BN	Restrictive signal(s) from unknown cause Talked by red signal. Restricted speed to MP 41.2, Stop, Control Point, Tenino
516	VAC	55	DMW	45	DMW	45	XF2-X1J	BN	Work window until 1300, cleared up a little early in time for an opening. Bridge, Fraser
518	VAC	58	MBO	30	MBO	30	XF2-X1J	BN	For maritime traffic Bridge, Fraser

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/3/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
8	CHI	63	ITI	169	ITI	169	SEA-SEA	BN	Late arrival train 7. 7
822	OKC	20	FTI	25	FTI	25	FTW-GLE	BN	Meet Siding, metro, Bnsf
332	CHI	11	CTI	12	CTI	10	GLN-XWA	ME	Follow Metra, 2126, Milepost, 9.0, 2.9
334	CHI	29	TRS	31	TRS	31	GLN-XWA	ME	Bridge strike by a vehicle or boat Semi trailer stuck under Sacramento Blvd. bridge at MP 3.89, waiting on removal and to be inspected, Control Point, Tower A-5
338	CHI	16	DCS	21	DCS	13	MKE-MKA	CP	Restrictive signal(s) from unknown cause Talked by signal. Had to walk bridge controlled by light. Tender reported bridge was locked and was Signal error not bridge error, Stop, Control Point, plankinton
339	MKE	22	CTI	23	CTI	10	GLN-XRO	ME	Follow metra, Control Point, a20
352	PNT	22	PTI	17	PTI	17	JXN-ARB	MI	Meet Amtrak Wolverine 355, Control Point, CP52
354	PNT	55	ENG	35	ENG	33	XTF-XH6	NS	Onboard HBD alarm Sensor was previously written up and not repaired or replaced for not working and it started working incorrectly tonight. It shows a reading of 662 degrees that was tested and shown to be in normal temperature range by detectors and boots on the ground, ID4613
364	PTH	178	ENG	151	ENG	151	CHI-CHI	AM	•Issue with power •Had to wait for engine to be fueled •Hot journal detector that mechanical had to inspect ID4621
365	CHI	55	ENG	33	ENG	33	NBU-NBU	AM	Onboard HBD alarm False reading bad sensor. Temp reading 664 onboard and all axles read at or under 26 degrees. Per CNOC and LP & AN 12-A. We are restricted to 80mph until it clears or mechanical forces are available to inspect, ID4621
784	SAN	36	CTI	31	PTI	18	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
702	BFD	32	PTI	24	PTI	24	FNO-HNF	BN	Meet 713, Siding, conejo
713	OKJ	37	DCS	38	DCS	38	COC-HNF	BN	Power switch failure Originally following BNSF 7040 west MT to MT1; DS attempted to reroute us at Calabrese for us to route around BNSF 7040 west, but DS was unable to get the switch to align us to MT2., Control Point, calabrese

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Region: ALL

Service: ALL

Arriving On: 12/3/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
715	OKJ	Trn Cancelled	PTI	88	PTI	88	RIC-EMY	UP	Train congestion due to AMTK 536 trespasser strike AMTK 5, AMTK 545, AMTK 538, Amtk718, amtk540, Amtk542, Milepost, 9.30, 4.55	
716	BFD	27	PTI	32	PTI	20	SKN-MOD	BN	Meet Speed in siding 25 mph, 715, Other, Riverbank Siding	
717	OKJ	28	PTI	31	DCS	11	HNF-FNO	BN	Issue with automatic road crossing protection California Ave Box 1, Milepost, 996.75, 996.75	
718	BFD	No OS Rpt	POL	115	POL	98	OKJ-OKJ	UP	RR blocked by trespasser or vehicle strike by another train Amtrak 536 struck a trespasser at Berkley. Hold for a clear track.	
3	LAX	305	CAR	124	CAR	124	CHI-CHI	AM	Set out defective car 39032, 61069	
4	CHI	47	FTI	56	FTI	30	KNG-FLG	BN	Meet Stopped at mp 352.2 waiting to go into FLG working main 2, bnsf, Milepost, 352.2, 344.8	
21	SAS	46	DMW	81	DMW	81	MVN-ARK	UP	Waiting for MW clearance Broken rail near mp 396., Control Point, cpa 393	
22	CHI	56	DCS	85	DCS	74	XDZ-WNR	UP	Power switch failure Siding, tuckerman	
300	CHI	75	CAR	35	CAR	35	STL-STL	TR	Door ID4132, Door had to be cutout on B-End bad fault stating door was open	
302	CHI	44	FTI	24	DMW	16	XUD-SMT	CC	Held for or routed around MW work or equipment Control Point, CP Canal	
306	CHI	No OS Rpt	FTI	26	FTI	20	SMT-XTF	CC	Cross Traffic unknown, Control Point, NS Brighton	
382	CHI	No OS Rpt	FTI	13	FTI	7	PLO-NPV	BN	Cross over or go around bnsf freights, Control Point, bishop, Control Point, 374, Control Point, eola	
383	QCY	21	FTI	22	FTI	11	GBB-MAC	BN	Cross over or go around bnsf, Siding, Avon	
392	CHI	24	DSR	14	RTE	10	XCS-X9R	CT	Inability to contact dispatcher Couldn't get a hold of CN desk 1 for lineup to shove into CUS, Control Point, Cermak	
311	KCY	21	ADA	31	ADA	20	HEM-HEM	UP	Wheelchair Group of 50 passengers with special needs. 8 wheelchair lifts.	
1333	MSP	20	POL	21	POL	21	WIN-WIN	CP	On-train police or DEA activity Unruly passenger	

Amtrak Initial Terminal Details

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/3/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	12/03	39	39	Service, turn, or wye train 71
HAR	620	12/03	1		
HAR	654	12/03	1		
HAR	656	12/03	1		
MIA	40	12/03	85	85	Set out defective car 28023
PHL	110	12/03	1		
PHL	151	12/03	2	2	Lost time - N.A.R., no delay reported per cdr 5:43am, section 4
PHL	601	12/03	1		
PHL	605	12/03	1		
RGH	71	12/03	56	56	Late / wrong track bulletins from host railroad CSX, Other, Raleigh DOT yard
RVM	86	12/03	15	15	Crew rest Arrived late on trip down so sign up was pushed back to accommodate 4 hour cut.
SAV	90	12/03	29	29	Freight train in emergency Other, A 490.6, M492(03)
WAS	56	12/03	4	4	Delay in Block, CONDUCTOR ADVISED US THAT COMMISSARY DIDN'T SEND THEIR STOCK OUT, BUT COMMISSARY SAID THEY REQUESTED RED MODUELS BOX'S AND THEY TOLD THE CREW THEY DIDN'T HAVE ANY.
WAS	136	12/03	2	2	Cross over or go around, 171, Control Point, WAS, 171 ARRIVING CROSS OVER
WAS	148	12/03	8	8	Commercial power outage, Milepost, 29.7, 11.7
WAS	2122	12/03	1		
WAS	2124	12/03	112	112	Heat / AC, PC, 2036 HEATER NOT WORKING AND NEEDED TO WYE.
WAS	2154	12/03	77	77	Other electrical failure, ,, I KNOW ONE OF THE PANOGRAPHS HAD TO HAVE REPAIRS ON IT, WAITING FOR A POWER CAR NO. TRAIN SPOTTED 340A AND RELEASTED 710A. IN THE TRACK AT 738A. DP 807A `7" LATE
WAS	2166	12/03	1		
WAS	2170	12/03	5	5	Commercial power outage, Milepost, 29.7, 11.7
BOS	2173	12/03	14	14	Service, turn, or wye train, 2154, DP BOS LATE DUE TO LATE TURN OF AM2154
NHV	470	12/03	3	3	Water, commissary, toilet/trash dumping, Late release from the Yard, NHV
NHV	474	12/03	11	11	Other electrical failure, 82574, MECHANICAL ISSUE BEFORE LEAVING THE YARD
NYP	19	12/03	3	3	Passenger and/or baggage, LOADING
NYP	63	12/03	4	4	Cross Traffic, NJT, NJ3814, Other, NYP

Amtrak Initial Terminal Details

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/3/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	97	12/03	24	24	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C WAITED FOR ENG.605 OFF AM98
NYP	197	12/03	2	2	Cross over or go around, 2169, Other, NYP-NYP, AM2169 XING AHD
NYP	233	12/03	3	3	Passenger and/or baggage, BOARDING
NYP	241	12/03	2	2	Cross over or go around, 655, Other, NYP-NYP, AM655 XING AHD
NYP	641	12/03	4	4	Follow, AM63, Other, NYP, AM63 XING AHD
NYP	649	12/03	2	2	Passenger and/or baggage, LOADING
NYP	653	12/03	3	3	Cross Traffic, NJ, 3858, Other, NYP-NYP, NJ3858 XING AHD
NYP	655	12/03	6	6	Undesired emergency application, 612, LATE FROM SSYD A/C PAPERWORK ISSUES
TWO	64	12/03	1		
CHI	41	12/03	45	45	Fuel
CHI	335	12/03	7	7	Service, turn, or wye train 334, 12:58 arrived 13:03 boarding passengers 13:07 cleared by Yard Master 13:12 PTC and class II brake test done
CHI	339	12/03	7	7	Removal of passenger by police Pax got on train completely intoxicated. Had removed before departure
CHI	364	12/03	151	151	•Issue with power •Had to wait for engine to be fueled •Hot journal detector that mechanical had to inspect ID4621
CHI	1333	12/03	2	2	Service, turn, or wye train 332, Car had to be removed from 332's consist
PNT	355	12/03	7	7	Door 61063, Mechanical had to short loop comm cable behind last coach and bag car. Engine reading bag car as doors open.
STL	300	12/03	65	35	Door ID4132, Door had to be cutout on B-End bad fault stating door was open
STL	300	12/03	65	30	Air / Brake Brakes were frozen STL Mechanical removed ice from train, ID4603
ARN	529	12/03	1	1	Lost time - N.A.R. Departed ARN at 6:34 and 40 seconds. We knocked down the signal at RV124 just after 6:35
LAX	4	12/03	1	1	Meet metrolink, 623, Other, LA station
LAX	586	12/03	2	2	Meet metrolink, Control Point, terminal
OKJ	522	12/03 (Trn Cxld)			Locomotive Failure
OKJ	534	12/03	23	23	Door C8311, Initial terminal
OKJ	540	12/03	158	158	Trespasser strike 536 trespasser strike 6.0 MTZ sub, Milepost, 6.0, 6.0
OKJ	548	12/03	28	28	Service, turn, or wye train 536, Train 536 became Train 548 at OKJ Station.

Amtrak Initial Terminal Details

26-FOI-00167 00000005500 "UNCLASSIFIED" 12/17/2025

Late Trains For:
Region: ALL
Division: ALL
Data Through: 12/3/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	718	12/03	98	98	RR blocked by trespasser or vehicle strike by another train Amtrak 536 struck a trespasser at Berkley. Hold for a clear track.
SAC	535	12/03	(Trn Cxld)		Locomotive Failure
SAC	549	12/03	(Trn Cxld)		Trespasser strike
SAC	551	12/03	(No OS)		
SAN	595	12/03	1		

Eastern Region

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	99.5	94.8	309	1
CDOT	95.0	100	96.7	92.4	20	0
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	92.2	93.0	93.8	371	29
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 97(03) North of Selma, NC - Police Related

04DEC25: At 12:31 a.m. train 97(03) operating with engines 39, 304, 10 cars, and 214 passengers onboard struck an occupied vehicle less than 1 mile north of Selma, NC on the CSX South End subdivision at Lizzie Mill Rd crossing ID 629953G. The crossing was equipped with pavement markings, 2 roadway gate arms, flashing lights, and 1 bell. HEP remained active and no injuries were reported by the crew or passengers onboard. Local authorities were on scene within 20 minutes of the incident occurring. Amtrak management was on scene within the hour and a relief engineer was cabled from Florence, SC to Fayetteville, NC to recrew the train.

National Response Center Number: 1449426

Train	Delay	Comment
97(03)	1'37"	

Train 291(03) Hudson, NY - Engine Failure

03DEC25: Train 291(03) operating with cab car 9701, 5 cars, and engine 708 became disabled at Hudson, NY station on track 1 due to low air on engine 708. Mechanical met the train and was able to fix the issue to allow 291(03) to operate to Albany, NY and cross platform with 235(03) equipment.

Train	Delay	Comment
291(03)	1'29"	

Train 494(03) New Haven, CT - Hold for Connection

03DEC25: Train 494(03) operating with cab car 9643, 1 car, and engine 109 was delayed departing New Haven, CT due to late connecting inbound train 94(03) with 20 connections onboard.

Train	Delay	Comment
494(03)	43"	

Train 186(03) Fredericksburg, VA - Police Related

03DEC25: Train 186(03) operating with engine 303 and 5 cars was delayed departing Fredericksburg, VA on the CSX RFP subdivision due to meeting police to remove an unruly passenger.

Train	Delay	Comment
186(03)	21"	

Train 2124(03) Washington D.C. - Engine Failure

03DEC25: Acela 2124(03) at 12:17/2025, 6 cars, and lead power car 2017 was delayed departing Washington Union Station due to HVAC failure involving the heater on lead power car 2036. The equipment was wye'd and operated reverse consist north upon departure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2124(03)	1'52"	

Train 687(03) East of Woburn, MA - Vehicle Strike

03DEC25: At approximately 5:53 p.m., Train 687(03), operating with engine 122, four cars, cab car 90224, and carrying 187 passengers, struck an occupied vehicle at a designated crossing on the Pan Am Freight Main Line, located 10 miles east of Woburn, Massachusetts. The crossing, identified as 053014E Essex Street at milepost 22.5 in Essex County, was equipped with two road arms, one passenger arm, four mast-mounted lights, and two bells. Head-End Power (HEP) remained active, and there were no reported injuries to crew members or passengers onboard. No damage was reported to the train equipment, and the vehicle occupant was confirmed to be unharmed. Local authorities, CSX, and APD arrived on scene within 30 minutes, and the site was cleared at 6:55 p.m. Train 687(03) resumed eastbound travel at 6:58 p.m., operating one hour and seven minutes behind schedule.

National Response Center Number: 1449413

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
687(03)	1'05"	

Train 2172(03) South of Baltimore, MD - Trespasser Incident

03DEC25: at approximately 433PM-ET, Train 2172(03) NG22, PC2119, 9 cars, PC2125, struck a trespasser on No.2 track at West Baltimore/MP98.5 on the Amtrak PW Line, 3 miles south of Baltimore, MD in Baltimore county. Trespasser fled the scene with some possible injuries, before authorities arrived on the scene. The incident occurred on the right of way, not at a crossing. There were no injuries to the (203) passengers or crew. Weather was 41 degrees and clear. No Damage reported to equipment.

National Response Center Number: 1449406

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2172(03)	42"	
178(03)	09"	
2121(03)	10"	
133(03)	04"	
93(03)	04"	
3 MARC's	6-11"	

PW Line South of Philadelphia, PA - Signal Power Outage

03DEC25: at approximately 12:30PM-ET, a signal power outage occurred on the PW Line between Baldwin/MP11.7 and Ragan/MP29.7. Trains 134, 125 and 2117(03) were all within the affected area. Trains were given rule 241 to continue through. At 1:49PM-ET all Wilmington Septa train service was suspended. At 2:05PM-ET all Amtrak service was suspended between Philadelphia and Washington. Multiple trains were delayed due to this. At 2:51PM-ET signal power was restored and all trains were able to resume service, with residual delays through the area.

Train	Delay	Comment
2117(03)	05"	
131(03)	04"	
133(03)	18"	
171(03)	06"	
2159(03)	09"	
2121(03)	06"	
93(03)	11"	
19(03)	10"	
97(03)	11"	
85(03)	07"	
173(03)	08"	
129(03)	02"	
2170(03)	06"	
176(03)	10"	
20(03)	07"	
178(30)	02"	
136(03)	09"	
80(30)	13"	
196(03)	11"	

Train 43(03) Harrisburg, PA - Shopped Equipment

03DEC25: Train 43(03) was delayed at Harrisburg, PA due to swapping out an engine account of original engine for 43(03), E/145 was shopped for a cracked windshield. Train 43(03) received E/121 from 42(03), which also caused a delay to 42(03) at Harrisburg.

Train	Delay	Comment
43(03)	42"	
42(03)	29"	

Train 24(03) West of Mobile, AL - Vehicle Strike

03DEC25: at approximately 10:50AM-CT, Train 24(03) E/187, 3 cars, E/180 struck an occupied vehicle at MP684.5 on the CSX NO&M Subdivision, 18 miles west of Mobile, AL station near Irvington, AL in Mobile County. The strike occurred at a Public road crossing at Bayou La Batre Highway, equipped with advanced warning signs, 2 quad gates, 2 mast mounted flashing lights, and 1 bell, DOT#351463R. There were no reported injuries to the crew, or 20 passengers onboard. The two vehicle occupants, one fled the scene and the other was taken to the hospital in an ambulance. There was no damage sustained to the equipment. The weather was reported 43 degrees and partly sunny. The crew did not request relief. Local EMS and an Amtrak Road Foreman responded to the location. After the scene was released and tracks inspected, Train 24(03) was back on the move at 12:27PM-CT.

National Response Center Number: 1449371

Train	Delay	Comment
24(03)	1'39"	

Train 2154(03) Washington, DC - Engine Failure

03DEC25: Train 2154(03) was delayed departing Washington, D.C. due to a late HSR mechanical release from the yard. (26-FBI-00187-00000009500) UNCLASSIFIED 12/17/2025

Train	Delay	Comment
2154(03)	1'17"	

Train 71(03) Raleigh, NC - System

03DEC25: Train 71(03) was delayed departing Raleigh, NC due to waiting for delayed CSX paperwork.

Train	Delay	Comment
71(03)	56"	
72(03)	39"	ITD -Equip Turn off 71

Train 280(03) East of Rochester, NY - Freight Train Interference

03DEC25: Train 71(03) was delayed 36 miles east of Rochester, NY at MP335.2 on the CSX Rochester Subdivision due to waiting for a westbound freight to pass account of disabled freight unit M368 ahead.

Train	Delay	Comment
280(03)	1'04"	

Eastern Region

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 650(3) Passenger Incident at Lancaster, Pennsylvania –Other***

3DEC25, Passenger on PNR 1AA131, traveling from Harrisburg, PA to New York, NY was traveling on the train without a ticket for the pet that they were traveling with. The passenger was asked to purchase a ticket for the pet and spoken to about the policy. The passenger became combative with the conductor. Amtrak Police notified.

Delay: 650 (3) 05"

Train 48(2) Passenger Incident at Erie, Pennsylvania –Other

3DEC25, Passenger on PNR 0407F7, traveling from Erie, PA to Rochester, NY was traveling on the train without an oversized bag. The passenger was informed of the policy. Amtrak Police notified.

Delay: 48 (2) 03"

Operating Highlights

Train 518(03) South of Vancouver, BC - Drawbridge Opening

04DEC25: Train 518(03) was delayed at MP141.1, 13.60 miles south of Vancouver, BC. station on the CN New Westminster subdivision due to the Fraser bridge opening for maritime traffic. Once the traffic cleared and the bridges closed, 518(03) was able to proceed north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518(03)	30"	

Train 11(03) North of Klamath Falls, OR - Freight Train Interference

04DEC25: Train 11(03) was delayed at MP433.6, 5.03 miles north of Klamath Falls, OR. station on the UPRR Cascade subdivision holding in the Wocus due to a meet with UP7201. Once freight train UP7201 cleared, 11(03) was able to proceed south into Klamath Falls station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
11(03)	37"	

Train 7/27(03) La Crosse, WI - Freight Train Interference

04DEC25: Train 7/27(03) was delayed beginning at MP281.4 La Crosse WI. station on the CPKC Tomah subdivision due to a freight ahead with a broken knuckle. Management responded to the freight train. and assisted in repairing the knuckle. Once repaired the freight train was on the move. Once the freight was clear, 7/27(03) was on the move again.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(03)	1'23"	

Train 3(03) East of Galesburg, IL - Signal

03DEC25: Train 3(03) was delayed at MP116.3, 46.99 miles east of Galesburg IL station on the BNSF Mendota subdivision due to signal issues. Train 3(03) proceeded through the area with signal issues at restricted speed of 20 MPH. Once through the area of the signal issues train 3(03) was able to get back up to track speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(03)	58"	

Train 7/27(02) East of Shelby, MT - Freight Train Interference

03DEC25: Train 7/27(03) was delayed at MP1036.2, 29.84 miles east of Shelby MT stations on the BNSF Hi Line subdivision due freight 5456W being stopped for mechanical issues. Mechanical responded to repair freight 5456W and was able to resolve mechanical issues. Train 7/27(03) was able to proceed west after the train cleared the route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(02)	1'25"	

Train 540(03) - Initial Terminal Delay: Oakland Jack London - Door Malfunction

03DEC25: Train 540(03) was delayed at Oakland Maintenance Facility due to malfunctioning doors on cab car CDTX/8311. After repairs restored the "trainline complete" indication and door lights, the train departed for Oakland Jack London Square. A subsequent recurrence of the issue caused further delay until the crew isolated and reactivated the door system in a prescribed sequence, clearing the fault and allowing the train to proceed.

Train	Delay	Comment
540(03)	2'38"	OKJ - Door Problems & Trespasser Strike (536(06))

Train 8/28(02) East of Havre, MT - Passenger Train Interference

03DEC25:Train 8/28(02) was delayed at MP432.1, 3.10 miles east of Havre, MT. station on the BNSF Milk River subdivision meeting train 7/27(02). Once 7/27(02) was past, 8/28(02) was able to proceed east into Havre station.

Train	Delay	Comment
8/28(02)	36"	

03DEC25: At approximately 26-FOI-00167:30000005500 Train 536(03) on 12/17/2025 with cab car CDTX/8310, 4 cars being pushed by CDTX/2003 struck a trespasser east of Emeryville. The trespasser was fatally injured as a result. The incident occurred on main track #2, 1 ½ miles east of Emeryville at MP 5.92 on the UPRR Martinez Subdivision. The location is reported as Banfield Way crossing (DOT# 751176H) within the city limits of Berkeley, CA Alameda County. There were no injuries to 34 passengers or crew onboard. There was no reported damage to train equipment. Locomotive CDTX/203 provided Head End Power for the duration of the incident. The Engineer and Conductor requested trauma relief at the scene.

Posted track speed is 79 mph. Weather was mostly cloudy and approximately 63F. Local Berkeley Police & Fire EMS, attended to investigate, aided by UPRR Police Officer, Amtrak Oakland Road Foreman and Amtrak Police responded. . Alameda County Coroner released the train and tracks at 7:10PM-PT. Amtrak Police and EAP notified. While waiting for the coroner to arrive and complete investigation the following train plan was instigated:

- Train 536(03) - After release, shoved back to Emeryville station where the service terminated. All affected passengers transferred to 538(03).
- Train 549(03) Cancelled - result of earlier cancellation of 536(03).
- Train 715(03) Was delayed at Richmond waiting for track to re-open. Once the track was re-opened, train 715(13) terminated in Emeryville, after tracks re-open. All passengers for Oakland transferred to train 545(03) in Richmond.
- Train 5(01) Was delayed at Richmond waiting for tracks to re-open.
- Train 545(03) Was delayed at Richmond, waiting open track.
- Train 547(03) Was delayed at Richmond, waiting open track.
- Train 717(03) Was delayed at Pinole, MP 20.00, Martinez Subdivision.
- Train 538(03) Was Delayed in Emeryville
- Train 718(03) was delayed in Oakland Jack London Square.
- Train 540(03) Delayed at Oakland Jack London, after earlier mechanical issues (see separate entry)
- Train 542(03) Delayed at Oakland Jack London Square.
- Train 551(03) Delayed departing Sacramento, Equipment turn from 542(03).
- Train 544(03) Delayed at Oakland Coliseum.
- Train 548(03) Delayed at Oakland Jack London Square, Equipment Turn from 536(03).

Service recovery: All affected Capitol Corridor trains- Passengers offered 20% Café discount.

Mutual AID. Bay Area Rapid Transit (BART) Honored Capitol Corridor tickets between Richmond and San Jose Berryessa/ San Francisco for the duration of the incident.

National response Center # 1449412
California Office of Emergency Services Control #25-6087.

National Response Center Number: 1449412

Train	Delay	Comment
536(03)	3'45"	Term EMY - Passengers to 538(03)
540(03)	2'38"	OKJ - ITD Door Issues and 536(06) Trespasser
540(03)	20"	Meet 536(03) - 34th Street
538(03)	3'09"	EMY
542(03)	2'08"	OKJ
542(03)	19"	OKJ-EMY Follow 540(03)
544(03)	1'10"	OAC
544(03)	13"	OAc-OKJ - Follow 542(03)
544(03)	22"	10th Street
548(03)	28"	OKJ - Equipment Turn from 536(03)
545(03)	1'49"	RIC
547(03)	1'40"	
545(03)	28"	RIC-OKJ - Meet/ Follow 540(03) /718(03) /5(01)
549(03)	Cancelled	Pax to 551(03)
5(01)	2'43"	RIC
5(01)	16"	Wait Station Track from 538(03)
715(03)	1'58"	RIC
718(03)	1'38"	OKJ - ITD
715(03)	Term EMY	Passengers to 545(03)
718(03)	17"	EMY - Waiting for Station Track
546(03)	53"	

Train 3(02) West of Las Vegas, NM - Passenger Train Interference

03DEC25: Train 3(02) 126-F01-00167.9 00000005500 west "UNCLASSIFIED" Vegas, 12/17/2025 MP770.1, on the BNSF Glorieta Subdivision, at Blanchard/MP794.0 in order to meet Train 4(02).

Train	Delay	Comment
3(02)	48"	

Chicago, IL Fuel Pad Outage

03DEC25: At 2:50PM-CT, The Chicago, IL Diesel pit reported that the power was out at the fuel pad which affected their ability to fill the fuel truck or fuel the engines at the pit. Maintenance crew troubleshooted the issue and found a broken breaker. Crew was able to replace the break and power was restored to the fuel pad at approximately 425PM CT. Several trains were delayed due to the fuel pad losing power.

Train	Delay	Comment
364(03)	2'31"	
41(03)	45"	

Train 714(03) Martinez Station CA - Trespasser Strike

03DEC25: At approximately 12:21PM-PDT Train 714(03) operating with camera equipped Cab Car locomotive CDTX/8303, struck a trespasser at the west end of Martinez station, MP 31.41 on the Martinez Subdivision, Union Pacific railroad, in Contra Costa County. Train 714(03) was approaching Martinez station as the incident occurred. The trespasser fled the scene after a brief verbal exchange with the crew. There were no reported injuries to any of the crew or 25 passengers. There was also no reported damage to the train. Timetabled track speed thru the area is 40 MPH. Weather was reported as 63°F, cloudy Locomotive CDTX/2009 provided Head End Power for the duration of the incident. The Engineer and Conductor did not request relief at the scene. After completing a mandatory compressed air test, train 714(03) resumed to Martinez. Amtrak Police and EAP advised. National Response Center report: 1449409
California Office of Emergency Services report: 25-6084

National Response Center Number: 1449409

Train	Delay	Comment
714(03)	08"	

Train 516(03) North of Bellingham, WA - Track Maintenance Work

03DEC25: Train 516(03) was delayed by Track Maintenance Foreman 48 miles north of Bellingham, WA at Fraser River Junction MP 141.1, New Westminster Subdivision, Canadian National Railway. Ahead of the train a track maintenance team was finishing their pre-assigned track work. The work was planned to be completed by 12:00PM-PT. Once the track was clear of personnel and tools train 516(03) continued to Vancouver.

Train	Delay	Comment
516(03)	45"	

Train 334(03) West of Chicago, IL - Bridge Strike

03DEC25: Train 334(03) was delayed at Chicago, IL, on the Metra C&M Subdivision, at Tower A5/MP5.4 due to a reported bridge strike ahead at MP2.8. Once the bridge inspector arrived and cleared the bridge for train movement to resume, Train 334(03) was back on the move to Chicago.

Train 335(05) was delayed departing Chicago, IL due to a late turn of 334(03)'s equipment that arrived at 12:58PM, 29 minutes late.

Train	Delay	Comment
334(03)	31"	
335(04)	07"	

Train 365(03) New Buffalo, MI - Engine Failure

03DEC25: Train 365(03), E/ID4625-6 Cars-E/ID4621, was delayed at New Buffalo, MI/MP218.9, on the Amtrak Michigan Line, inspecting E/ID4621 after an onboard hot box detector alarm went off. The crew inspected and took no exceptions. All axles read at or under 26 degrees after inspection. The issue was found to be a false reading due to bad sensor on E/ID4621. Once the inspection was complete, Train 365(03) continued to Chicago.

Train	Delay	Comment
365(03)	37"	

Train 22(03) Austin, TX - Freight Train Interference

03DEC25: Train 22(03) held at the Austin, TX station/MP179.4, on the UPRR Austin Subdivision, due to disabled freight ahead. UP5495 was disabled at McNeil/MP166.1 after losing their lead unit and requiring a rescue unit to be sent to the train. The rescue locomotive arrived quickly and tied on to the head end of the freight train. Once complete, UP5495 was back on the move north with UP7396 trailing behind. Train 22(03) was released from the Austin station and followed UP5495 and UP7396 until they were able to get by at Taylor/MP144.5.

Train	Delay	Comment
22(03)	37"	AUS Station
22(03)	26"	Follow AUS-TAY

Train 713(03) West of Corcoran, CA - Switch Failure

03DEC25: Train 713(03) was delayed at Calabrese, MP 962.6/BNSF Bakersfield Subdivision, 11.6 miles west of Corcoran, as a result of power switch failure and waiting on westbound BNSF freight train BNSF 7040 to clear through the area first.

Train	Delay	Comment
713(03)	38"	

Train 3(01) West of Flagstaff, AZ - Freight Train Interference

03DEC25: Train 3(01) was delayed starting 17.9 miles west of Flagstaff, AZ/MP344.2, on the BNSF Seligman Subdivision, between Maine/MP362.2 and West Perrin/MP385.6 following an unspecified BNSF Freight train. Train 3(01) also met an eastbound BNSF freight train at West Perrin before they could continue west.

Train	Delay	Comment
3(01)	39"	

Train 4(02) West of Kingman, AZ - Freight Train Interference

03DEC25: Train 4(02) was delayed departing Kingman, AZ/MP516.3, on the BNSF Seligman Subdivision, following BNSF 8075 from MP437.0 to the East Williams Junction/MP374.4.

Train	Delay	Comment
4(02)	42"	

Trains 522(03) & 535(03) Cancelled - Third Party Contractor Engine Failure

03DEC25: Train 522(03) was cancelled (Oakland to Sacramento) as a result of traction motor problems on locomotive E/C2124 which could not be resolved in a timely manner at the Oakland Yard. This also resulted in the cancellation of Train 535(03) (Sacramento to Oakland). Affected passengers were reaccommodated onto the next departing trains.

Train	Delay	Comment
535(03)	Cancelled	Psgrs to 537(03)
522(03)	Cancelled	Psgrs to 524(03)

Train 21(02) South of Malvern, AR - Broken Rail

03DEC25: Train 21(02) held 4.1 miles south of Malvern, AR/MP389.0, on the UPRR Little Rock Subdivision, at ABCO/MP393.1 due to a reported broken rail at MP395.77. Maintenance of Way was onsite to walk trains over the defect. Train 21(02) held at ABCO for northbound MDYNL-02 / UP7752 to be walked over first before Train 21(02) could proceed south.

Train	Delay	Comment
21(02)	1'21"	

Train 14(02) Klamath Falls, OR - Crew Rest

03DEC25: Train 14(02) was delayed at Klamath Falls, OR/MP429.5, on the UPRR Cascade Subdivision, for crew rest. The crew signed up on rest at 8:28AM-PT off of inbound Train 11(02) that arrived at 11:48PM, 1 hour and 50 minutes late.

Train	Delay	Comment
14(02)	35"	

Train 7/27(02) West of Fargo, ND - Passenger Train Interference

03DEC25: Train 7/27(02) was delayed 5.9 miles west of Fargo, ND/MP23.4X, on the BNSF Hillsboro Subdivision, at Bison/MP29.3 meeting Train 8/28(01).

Train	Delay	Comment
7/27(02)	40"	

Train 300(03) St. Louis, MO - Door/Brake Failure

03DEC25: Train 300(03), E/ID4603-5 Cars, was delayed departing St. Louis, MO/MP1.5, on the TRRA Merchants Subdivision, due to door and brake issues. Initially, St. Louis Mechanical was onboard the train working through a fault stating the door in C/ID4132 was open which resulted in the door cutout on the B-End. Additional delay due to the brakes on E/ID4603 being frozen. St. Louis Mechanical removed the ice from the train which allowed the brakes to work as intended. At 5:36AM, Train 300(03) departed St. Louis operating 1 hour and 06 minutes late.

Train	Delay	Comment
300(03)	1'06"	

Train 8/28(02) West of Sandpoint, ID - Engine Failure

03DEC25: Around 3:28 PM MT, 0000005500 8/28(02) UNCLASSIFIED E/37117/2025 350-E/33-10 Cars, reported intermittent head end power failure starting at MP11.7. This began 8.6 miles west of Sandpoint, ID/MP3.1 on the BNSF Kootenai River Subdivision with the train stopping at MP6.3 to troubleshoot. The crew thought they had it resolved and advanced to the Sandpoint station to troubleshoot as it occurred again. The train crew worked with CNOC Mechanical and was able to restore head end power. The same cycle occurred again at MP1357.3. At 5:50AM-MT, Train 8/28(02) officially lost head end power and was unable to get it back, stopping the train at Yakt/MP1343.7. During this time, there were 109 passengers onboard with the outside temperature reported 30 degrees and cloudy. The inside temperature onboard the train remained a constant 65 degrees. The issue was found to be with crew dorm car 61055 after finding arcing under the car. As a result, baggage car 61055 and crew dorm car 39019 were flat switched to the rear end of the trainset. At 7:45AM-MT, the switching of the cars was complete and head end power was restored to the trainset. AT 8:15AM-MT, Train 8/28(02) was back on the move east.

Service recovery was initiated immediately onboard which consisted of snack packs and water. Complimentary coffee, juice and tea was distributed to all passengers. The Sleeper passengers meals were not affected and continued to order off of the menu. The Diner car offered breakfast comp meals to all coach passengers.

Train	Delay	Comment
8/28(02)	17"	SPK-SPT
8/28(02)	25"	SPT
8/28(02)	2'41"	SPT-LIB

1670108167 0010000500 "UNCLASSIFIED" 11/17/2018
Canadian National Chicago Subdivision - Scheduled M/W Work - Tie Replacement

12NOV25: Canadian National will be performing tie replacement project on the Chicago Subdivision between MP 34 and MP 60 between Homewood, IL and Gilman, IL. To accommodate the work, the following Saluki Service will be replaced with bus service:

- Train 390(12NOV-18NOV) & 390(02DEC-06DEC) has been canceled in its entirety. Bus 3390 will be utilized for alternate transportation.
- Train 391(12NOV-18NOV) & 391(02DEC-06DEC) has been canceled in its entirety. Bus 3391(12NOV-18NOV) and Bus 3091(02DEC-06DEC) will be utilized for alternate transportation.

WBS#: B.TR.100150.6160

Western Region

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (2)	CHI	UP5552	E/61 Traction motors cutout		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 339(03) Passenger Denied Travel at Chicago, Illinois –Improper Conduct***

3DEC25, Passenger on PNR Unknown, traveling from Chicago, IL to Milwaukee, WI, was removed from the train by APD. The passengers were looking for two seats before departure and began moving crew bags out of the seat. The passengers were told not to move any bags by the conductor. The passengers became belligerent displaying signs of being intoxicated and the passengers were removed. One passenger left purse on the train. Amtrak Police notified.

Delay: 339 (03) 07"

Train 14(02) Passenger Removal at Klamath Falls, Oregon –Improper Conduct

3DEC25, Passenger on PNR 1456DA, traveling from San Jose, CA to Portland, WA, was removed from the train by the conductor. The passenger was using foul language while using his phone in the café car. Another passenger asked if the passenger would watch his language in front of other passengers and children. Amtrak Police notified.

Delay: 14 (02) 05"

26-FOI-00167 00000005500 UNCLASSIFIED 12/17/2025
Bus 5412(03) Passenger Removal at Pasadena, California –Improper Conduct

3DEC25, Passenger on PNR 1B1E82, traveling from Bakersfield, CA to Riverside, CA was removed from the bus by driver. The passenger opened the baggage door to remove items from luggage. When the passenger was told they would be removed for pushing operating buttons the passenger took other passengers' luggage and ran. Amtrak Police notified.

Delay: 5412(03) None

Train 3(02) Passenger Removal at La Junta, Colorado –Improper Conduct

3DEC25, Passenger on PNR 129C3D, traveling from Kansas City, MO to La Junta, CO was removed from the train by La Junta PD. The passenger didn't present as mentally stable after being seen yelling and using excessive profanity. Amtrak Police notified.

Delay: 3(02) None

Train 14(03) Passenger Removal at San Jose, California –Intoxication

3DEC25, Passenger on PNR 19066E, traveling from Los Angeles, CA to Seattle, WA was removed from the train by conductor. The passenger was intoxicated on the train with empty bottles of alcohol around his seat. The passenger began using racial slurs stating he was going to cut other passengers. Amtrak Police notified.

Delay: 14(03) None

Train 14(03) Passenger Removal at San Jose, California –Intoxication

3DEC25, Passenger on PNR 05B1A4, traveling from Los Angeles CA to Seattle, WA was removed from the train by conductor. The passenger was intoxicated on the train displaying a flask and own alcohol. Amtrak Police notified.

Delay: 14(03) None

Consist Deviations

26-FOI-00167

00000005500

"UNCLASSIFIED"

12/17/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
582 (03)	LAX	no JY/BV/cafe/wi-fi			COMET
564 (03)	LAX	no JY/BV/cafe/wi-fi			COMET
577 (03)	SAN	no JY/BV/cafe/wi-fi			COMET
593 (03)	SAN	no JY/BV/cafe/wi-fi			COMET

Reverse Consists

Train Number	Station	Reason
86 (03)	RVM	Consist reversed Business class seat orientation may have changed At Front
179 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (03)	BOS	Consist reversed Business class seat orientation may have changed At Front
151 (03)	PHL	Business class change only Business class seating orientation may have changed At Rear
111 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (03)	PHL	Business class change only Business class seating orientation may have changed At Rear
2173 (03)	BOS	Acela consist reversed First class at Rear
2155 (03)	BOS	Acela consist reversed First class at Rear
86 (04)	RVM	Consist reversed Business class seat orientation may have changed At Front
114 (03)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
182 (03)	WAS	Consist reversed Business class seat orientation may have changed At Rear
133 (03)	NYP	Consist reversed Business class seat orientation may have changed At Front
192 (03)	WAS	Consist reversed Business class seat orientation may have changed At Rear