



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, July 23, 2026

Rules: 4-39



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 07/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/22/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	58	82.0%	6,751	1,010	85.0%	88,105	12,132	86.2%
Central Division	86.0%	57	5	91.2%	1,217	121	90.1%	16,908	1,512	91.1%
East Division	82.0%	175	23	86.9%	3,557	599	83.2%	46,153	7,212	84.4%
West Division	86.0%	91	30	67.0%	1,977	290	85.3%	25,044	3,408	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00621 00000008480 UNCLASSIFIED 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	109,596	40,155	63%	2,375,578	849,568	64%	29,322,902	7,323,854	75%
Northeast Corridor	81%	48,827	13,804	72%	1,020,964	372,537	64%	12,864,745	3,155,730	75%
Acela	83%	11,046	3,225	71%	227,338	79,968	65%	2,564,103	682,645	73%
Northeast Regional	79%	37,781	10,579	72%	793,626	292,569	63%	10,300,642	2,473,085	76%
Richmond / Newport News / Norfolk	77%	10,865	4,050	63%	246,841	115,501	53%	3,197,569	929,122	71%
Springfield Shuttles	89%	695	70	90%	14,594	4,148	72%	182,628	28,362	84%
Roanoke	79%	3,947	2,003	49%	76,788	33,396	57%	969,848	208,681	78%
On Spine Northeast Regional	80%	22,274	4,456	80%	455,403	139,524	69%	5,950,597	1,306,920	78%
State Supported	80%	49,094	19,699	60%	1,068,026	298,409	72%	12,854,074	2,660,773	79%
Borealis	80%	593	233	61%	13,127	2,606	80%	164,097	33,052	80%
Capitol Corridor	90%	4,149	225	95%	83,450	12,193	85%	1,084,669	141,389	87%
Carolinian	70%	1,039	58	94%	24,679	15,660	37%	334,653	131,566	61%
Cascades	75%	2,448	1,253	49%	68,150	17,578	74%	755,794	206,138	73%
Downeaster	82%	1,929	140	93%	43,162	9,075	79%	440,660	54,545	88%
Empire	78%	6,163	2,230	64%	136,087	48,528	64%	1,590,092	362,945	77%
Adirondack	72%	390	228	42%	9,551	4,192	56%	95,984	29,676	69%
Ethan Allen Express	70%	566	542	4%	12,805	9,043	29%	163,770	56,650	65%
Maple Leaf	70%	844	445	47%	19,182	8,020	58%	194,001	74,807	61%
New York - Albany	85%	2,990	544	82%	60,868	13,712	77%	738,033	117,612	84%
New York - Niagara Falls	75%	1,373	471	66%	30,458	11,458	62%	391,917	81,237	79%
Berkshire Flyer	60%	0	0	-	3,223	2,103	35%	6,387	2,963	54%
Gold Runner	73%	1,968	1,034	47%	57,249	23,916	58%	730,869	256,014	65%
Heartland Flyer	70%	223	213	4%	6,143	3,519	43%	61,848	24,012	61%
Hiawatha	90%	2,145	0	100%	44,492	2,839	94%	502,186	53,387	89%
Illinois	78%	2,460	901	63%	58,124	20,531	65%	720,279	196,575	73%
Carl Sandburg / Illinois Zephyr	85%	463	78	83%	10,624	4,164	61%	120,178	31,970	73%
Illini / Saluki	85%	606	135	78%	18,800	6,619	65%	252,462	60,646	76%
Lincoln Service	70%	1,391	688	51%	28,700	9,748	66%	347,639	103,959	70%
Keystone	92%	9,395	1,777	81%	163,277	23,091	86%	2,220,354	233,026	90%
Lincoln / Missouri	70%	904	853	6%	16,575	9,950	40%	225,094	113,766	49%
Mardi Gras Service	80%	8	0	100%	8,250	3,392	59%	119,198	25,853	78%
Michigan	70%	2,728	680	75%	53,527	19,030	64%	573,274	183,985	68%
Blue Water	70%	985	527	46%	13,570	8,024	41%	133,796	53,358	60%
Pere Marquette	85%	179	0	100%	7,497	1,268	83%	75,069	14,598	81%
Wolverine	70%	1,564	153	90%	32,460	9,738	70%	364,409	116,029	68%
Missouri	80%	276	206	25%	4,422	1,840	58%	63,658	15,080	76%
Pacific Surfliner	85%	9,493	8,158	14%	223,621	58,441	74%	2,306,145	385,603	83%
Pennsylvanian	80%	814	429	47%	19,046	7,207	62%	257,756	49,366	81%
Piedmont	80%	759	89	88%	17,183	6,967	59%	330,568	85,521	74%
Vermont	75%	1,600	1,220	24%	27,462	12,046	56%	372,880	108,950	71%
Long Distance	70%	11,675	6,652	43%	286,588	178,622	38%	3,564,816	1,504,888	58%
Auto Train	70%	727	0	100%	18,056	6,531	64%	226,900	77,359	66%
California Zephyr	70%	1,038	834	20%	22,997	15,414	33%	283,060	100,711	64%
Cardinal	70%	0	0	-	5,282	3,581	32%	68,956	33,823	51%
City Of New Orleans	75%	616	39	94%	7,222	4,324	40%	184,586	53,941	71%
Coast Starlight	70%	1,197	634	47%	27,964	10,355	63%	332,728	114,807	65%
Crescent	70%	731	186	75%	20,549	11,709	43%	271,042	83,801	69%
Empire Builder	70%	1,262	656	48%	27,558	17,353	37%	280,619	136,105	51%
Floridian	60%	1,663	1,523	8%	33,367	31,555	5%	463,532	315,198	32%
Lake Shore Ltd	73%	1,169	379	68%	26,347	10,054	62%	277,984	81,664	71%
Palmetto	70%	774	658	15%	19,959	12,941	35%	267,732	79,039	70%
Silver Meteor	70%	430	389	10%	22,976	19,319	16%	295,357	129,471	56%
Southwest Chief	60%	513	389	24%	21,884	15,869	27%	240,534	154,281	36%
Sunset Ltd	70%	435	91	79%	7,421	4,130	44%	85,806	30,811	64%
Texas Eagle	70%	1,120	874	22%	25,006	15,487	38%	285,980	113,877	60%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00021 00000000400 "UNCLASSIFIED" 07/2020

Train Index Dates Through July 22, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	157,887	2,341,119	674	1,724,981	30,973,353	557

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	9,946	691,139	144	83,321	8,900,616	94
INFRASTRUCTURE PLANNED	135	11,285	691,139	163	90,185	8,900,616	101
FLEET RELIABILITY	90	23,438	2,341,119	100	276,468	30,973,353	89
TRAIN OPERATIONS	424	113,218	2,341,119	484	1,275,007	30,973,353	412

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/22/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/22/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	58	82.0%	6,751	1,010	85.0%	88,105	12,132	86.2%
Central Division	86.0%	57	5	91.2%	1,217	121	90.1%	16,908	1,512	91.1%
East Division	82.0%	175	23	86.9%	3,557	599	83.2%	46,153	7,212	84.4%
West Division	86.0%	91	30	67.0%	1,977	290	85.3%	25,044	3,408	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/22/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	58	82.0%	6,751	1,010	85.0%	88,105	12,132	86.2%
Central Division	86.0%	57	5	91.2%	1,217	121	90.1%	16,908	1,512	91.1%
CDL	95.0%	2	0	100.0%	41	4	90.2%	558	22	96.1%
CHI	86.0%	27	4	85.2%	572	70	87.8%	7,809	933	88.1%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	58	3	94.8%
DER	-	-	-	-	1	1	0.0%	2	2	0.0%
FTW	92.5%	1	0	100.0%	22	1	95.5%	318	35	89.0%
GBB	-	1	1	0.0%	11	9	18.2%	11	9	18.2%
GRR	95.5%	1	0	100.0%	21	0	100.0%	280	8	97.1%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	35	3	91.4%	573	43	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	129	7	94.6%	1,727	104	94.0%
MOE	97.5%	1	0	100.0%	42	1	97.6%	587	9	98.5%
MSP	96.5%	1	0	100.0%	22	0	100.0%	288	5	98.3%
NOL	94.5%	4	0	100.0%	85	6	92.9%	1,235	59	95.2%
OKC	97.0%	1	0	100.0%	22	0	100.0%	289	6	97.9%
PNT	88.0%	3	0	100.0%	57	5	91.2%	760	63	91.7%
PTH	93.0%	1	0	100.0%	22	1	95.5%	283	11	96.1%
QCY	91.0%	1	0	100.0%	30	3	90.0%	561	43	92.3%
SAS	90.5%	1	0	100.0%	22	3	86.4%	291	30	89.7%
STL	89.0%	4	0	100.0%	83	7	91.6%	1,140	97	91.5%
TOL	-	-	-	-	-	-	-	3	3	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	175	23	86.9%	3,557	599	83.2%	46,153	7,212	84.4%
ALB	88.5%	8	0	100.0%	170	8	95.3%	2,184	169	92.3%
ATL	-	-	-	-	1	1	0.0%	36	6	83.3%
BON	87.5%	5	1	80.0%	109	14	87.2%	1,421	154	89.2%
BOS	85.5%	17	1	94.1%	366	30	91.8%	5,006	592	88.2%
BRK	92.5%	5	2	60.0%	106	18	83.0%	1,407	102	92.8%
BTN	82.0%	1	0	100.0%	22	1	95.5%	281	40	85.8%
CLT	91.5%	5	0	100.0%	91	17	81.3%	1,432	149	89.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	44	5	88.6%	575	55	90.4%
GRO	-	-	-	-	4	0	100.0%	33	10	69.7%
HAR	79.5%	13	1	92.3%	236	35	85.2%	3,259	541	83.4%
HFD	-	2	1	50.0%	30	5	83.3%	177	13	92.7%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	22	1	95.5%	291	35	88.0%
MIA	89.5%	2	0	100.0%	43	6	86.0%	582	66	88.7%
MTR	79.0%	1	0	100.0%	22	4	81.8%	278	50	82.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/22/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	58	82.0%	6,751	1,010	85.0%	88,105	12,132	86.2%
East Division	82.0%	175	23	86.9%	3,557	599	83.2%	46,153	7,212	84.4%
NFK	84.5%	2	0	100.0%	44	11	75.0%	665	120	82.0%
NFL	93.5%	2	0	100.0%	44	3	93.2%	594	25	95.8%
NFS	-	-	-	-	1	1	0.0%	7	6	14.3%
NHV	78.0%	5	1	80.0%	106	20	81.1%	1,512	243	83.9%
NPN	93.0%	2	0	100.0%	42	5	88.1%	555	40	92.8%
NYP	75.5%	51	11	78.4%	1,004	234	76.7%	12,058	2,695	77.6%
PGH	93.0%	1	0	100.0%	21	3	85.7%	292	22	92.5%
PHL	48.0%	5	2	60.0%	107	46	57.0%	1,507	723	52.0%
PIT	76.0%	-	-	-	6	6	0.0%	12	11	8.3%
POR	-	-	-	-	3	3	0.0%	11	8	27.3%
RGH	95.0%	4	0	100.0%	65	6	90.8%	1,122	47	95.8%
RNK	83.5%	2	0	100.0%	44	8	81.8%	578	85	85.3%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	1	1	0.0%	6	4	33.3%
SAB	98.0%	1	0	100.0%	19	1	94.7%	278	5	98.2%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	20	0	100.0%	288	10	96.5%
SFA	88.0%	1	0	100.0%	22	2	90.9%	291	39	86.6%
SPG	92.5%	5	0	100.0%	109	9	91.7%	1,761	101	94.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	21	1	95.2%	280	57	79.6%
WAS	84.0%	30	3	90.0%	612	94	84.6%	7,208	935	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	91	30	67.0%	1,977	290	85.3%	25,044	3,408	86.4%
ARN	92.0%	1	0	100.0%	22	5	77.3%	293	24	91.8%
BFD	79.0%	7	1	85.7%	149	34	77.2%	1,835	375	79.6%
EMY	72.0%	1	1	0.0%	22	8	63.6%	309	94	69.6%
EUG	86.5%	2	1	50.0%	44	3	93.2%	580	55	90.5%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	2	1	50.0%	3	2	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	66	18	72.7%	882	132	85.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	11	7	36.4%	230	30	87.0%	2,905	306	89.5%
MCD	-	-	-	-	7	6	14.3%	15	13	13.3%
OKJ	74.5%	13	5	61.5%	254	68	73.2%	3,153	804	74.5%
PDX	86.0%	5	1	80.0%	110	9	91.8%	1,447	175	87.9%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	4	75.0%	326	33	89.9%	4,131	443	89.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 07/22/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 07/22/2026			ITP July 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	323	58	82.0%	6,751	1,010	85.0%	88,105	12,132	86.2%
West Division	86.0%	91	30	67.0%	1,977	290	85.3%	25,044	3,408	86.4%
SAN	90.5%	13	6	53.8%	285	30	89.5%	3,529	324	90.8%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	7	2	71.4%	175	23	86.9%	2,317	333	85.6%
SJC	89.0%	7	1	85.7%	154	18	88.3%	2,061	200	90.3%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	66	3	95.5%	645	63	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	0	100.0%	22	1	95.5%	288	21	92.7%
VAC	97.0%	1	0	100.0%	43	0	100.0%	573	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		10	0	100.0%	125	8	93.6%	10	6	40.0%	125	29	76.8%
3	40	22	3	86.4%	293	57	80.5%	22	11	50.0%	291	128	56.0%
4	No OS	22	2	90.9%	292	44	84.9%	22	13	40.9%	292	192	34.2%
5	96	22	3	86.4%	291	46	84.2%	21	17	19.0%	287	80	72.1%
6	195	22	8	63.6%	290	85	70.7%	22	14	36.4%	290	96	66.9%
7		22	2	90.9%	282	37	86.9%	22	8	63.6%	275	69	74.9%
8	68	22	11	50.0%	282	122	56.7%	22	18	18.2%	281	167	40.6%
11		22	4	81.8%	293	54	81.6%	22	5	77.3%	287	59	79.4%
14	35	22	4	81.8%	294	45	84.7%	22	6	72.7%	292	89	69.5%
19		22	10	54.5%	292	75	74.3%	21	11	47.6%	289	70	75.8%
20		22	5	77.3%	292	23	92.1%	22	10	54.5%	292	57	80.5%
21		22	1	95.5%	289	23	92.0%	22	15	31.8%	288	77	73.3%
22	119	22	3	86.4%	290	28	90.3%	22	14	36.4%	288	76	73.6%
25		21	0	100.0%	293	3	99.0%	21	9	57.1%	291	78	73.2%
26		21	0	100.0%	293	5	98.3%	21	6	71.4%	291	58	80.1%
27		22	4	81.8%	280	18	93.6%	22	9	59.1%	276	90	67.4%
28		22	3	86.4%	276	62	77.5%	22	3	86.4%	276	54	80.4%
40	154	21	3	85.7%	287	41	85.7%	20	18	10.0%	285	150	47.4%
41	198	20	10	50.0%	286	112	60.8%	20	20	0.0%	284	216	23.9%
42	31	22	4	81.8%	294	24	91.8%	22	8	63.6%	292	50	82.9%
43	21	22	1	95.5%	293	42	85.7%	21	12	42.9%	292	68	76.7%
48		22	4	81.8%	292	57	80.5%	22	3	86.4%	292	41	86.0%
49		22	4	81.8%	292	71	75.7%	22	7	68.2%	292	59	79.8%
50	No OS	9	3	66.7%	120	29	75.8%	10	9	10.0%	120	72	40.0%
52		22	2	90.9%	291	39	86.6%	22	7	68.2%	290	68	76.6%
53		22	1	95.5%	291	35	88.0%	22	6	72.7%	290	91	68.6%
55		15	1	93.3%	183	7	96.2%	15	4	73.3%	180	38	78.9%
56		15	1	93.3%	184	23	87.5%	14	6	57.1%	180	32	82.2%
58		11	0	100.0%	270	16	94.1%	10	4	60.0%	268	69	74.3%
59		10	4	60.0%	268	32	88.1%	9	6	33.3%	264	52	80.3%
63	94	22	10	54.5%	295	127	56.9%	21	18	14.3%	290	158	45.5%
64	23	22	2	90.9%	293	65	77.8%	22	13	40.9%	293	104	64.5%
66	20	22	6	72.7%	292	60	79.5%	20	4	80.0%	288	53	81.6%
67		15	2	86.7%	202	13	93.6%	14	4	71.4%	201	35	82.6%
68	23	22	4	81.8%	295	59	80.0%	22	12	45.5%	295	115	61.0%
69		22	4	81.8%	282	63	77.7%	22	9	59.1%	278	41	85.3%
71		22	0	100.0%	290	3	99.0%	22	11	50.0%	289	77	73.4%
72		18	2	88.9%	286	31	89.2%	18	4	77.8%	285	59	79.3%
73		17	2	88.2%	289	18	93.8%	17	10	41.2%	287	136	52.6%
74		17	3	82.4%	287	33	88.5%	17	11	35.3%	285	105	63.2%
75	17	13	1	92.3%	283	15	94.7%	12	7	41.7%	277	132	52.3%
76	15	13	2	84.6%	283	28	90.1%	12	7	41.7%	274	111	59.5%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77	12	16	3	81.3%	285	20	93.0%	16	12	25.0%	283	120	57.6%
78		21	5	76.2%	289	25	91.3%	21	12	42.9%	288	62	78.5%
79		22	1	95.5%	292	56	80.8%	22	15	31.8%	291	99	66.0%
80		22	5	77.3%	292	33	88.7%	21	11	47.6%	289	60	79.2%
84		12	2	83.3%	174	13	92.5%	12	6	50.0%	172	41	76.2%
85	65	15	0	100.0%	185	16	91.4%	15	8	46.7%	185	69	62.7%
86		15	1	93.3%	185	15	91.9%	15	10	33.3%	184	110	40.2%
89		22	6	72.7%	290	64	77.9%	22	13	40.9%	288	83	71.2%
90	34	22	0	100.0%	290	10	96.6%	22	12	45.5%	289	49	83.0%
93	42	15	0	100.0%	184	18	90.2%	15	8	46.7%	183	45	75.4%
94		15	4	73.3%	215	54	74.9%	15	10	33.3%	213	79	62.9%
95		15	1	93.3%	184	4	97.8%	15	8	46.7%	184	67	63.6%
97	393	22	20	9.1%	292	193	33.9%	22	18	18.2%	290	94	67.6%
98	33	22	3	86.4%	292	24	91.8%	22	20	9.1%	290	100	65.5%
110		15	4	73.3%	181	100	44.8%	15	2	86.7%	178	18	89.9%
111		15	1	93.3%	175	33	81.1%	15	1	93.3%	173	21	87.9%
112		15	1	93.3%	175	17	90.3%	15	2	86.7%	174	19	89.1%
113		15	2	86.7%	106	24	77.4%	15	2	86.7%	105	13	87.6%
119		12	1	91.7%	172	44	74.4%	12	2	83.3%	170	22	87.1%
125	29	15	2	86.7%	185	10	94.6%	15	7	53.3%	185	73	60.5%
129		15	2	86.7%	184	46	75.0%	15	3	80.0%	184	26	85.9%
130		15	2	86.7%	175	18	89.7%	15	1	93.3%	173	16	90.8%
131		15	5	66.7%	177	52	70.6%	15	6	60.0%	177	35	80.2%
134	58	15	3	80.0%	185	24	87.0%	15	6	60.0%	184	32	82.6%
136	55	15	3	80.0%	185	23	87.6%	15	6	60.0%	183	23	87.4%
137	83	15	4	73.3%	182	34	81.3%	15	6	60.0%	182	58	68.1%
138		15	4	73.3%	185	39	78.9%	15	6	60.0%	184	33	82.1%
141		15	0	100.0%	184	3	98.4%	15	3	80.0%	183	31	83.1%
148		15	1	93.3%	184	18	90.2%	15	4	73.3%	182	34	81.3%
151		22	7	68.2%	291	93	68.0%	22	10	54.5%	290	94	67.6%
170		15	0	100.0%	180	12	93.3%	15	0	100.0%	179	29	83.8%
171		15	0	100.0%	185	10	94.6%	15	10	33.3%	185	71	61.6%
172		15	0	100.0%	184	14	92.4%	15	4	73.3%	182	59	67.6%
173	18	12	1	91.7%	177	24	86.4%	12	4	66.7%	176	77	56.3%
174		15	0	100.0%	185	20	89.2%	15	8	46.7%	185	46	75.1%
175		15	0	100.0%	185	21	88.6%	15	5	66.7%	185	60	67.6%
176	20	12	1	91.7%	177	15	91.5%	12	5	58.3%	175	20	88.6%
177		15	1	93.3%	185	25	86.5%	15	0	100.0%	185	44	76.2%
178	57	15	1	93.3%	185	25	86.5%	15	6	60.0%	183	29	84.2%
179		15	3	80.0%	185	22	88.1%	15	7	53.3%	184	65	64.7%
181		15	2	86.7%	181	56	69.1%	15	2	86.7%	179	14	92.2%
182		15	1	93.3%	175	29	83.4%	15	2	86.7%	173	18	89.6%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
183		15	6	60.0%	184	54	70.7%	15	5	66.7%	182	38	79.1%
184		15	3	80.0%	185	32	82.7%	15	4	73.3%	184	27	85.3%
185		15	1	93.3%	185	37	80.0%	15	3	80.0%	185	14	92.4%
186	32	15	3	80.0%	184	20	89.1%	15	8	46.7%	183	48	73.8%
190		15	3	80.0%	184	65	64.7%	15	4	73.3%	183	41	77.6%
192		15	5	66.7%	182	24	86.8%	15	3	80.0%	182	17	90.7%
193		12	4	66.7%	181	75	58.6%	12	6	50.0%	180	86	52.2%
196		12	1	91.7%	181	19	89.5%	12	0	100.0%	180	15	91.7%
197	18	15	5	66.7%	185	73	60.5%	15	11	26.7%	185	64	65.4%
198		15	3	80.0%	117	17	85.5%	15	4	73.3%	116	20	82.8%
230		22	0	100.0%	129	4	96.9%	22	0	100.0%	129	6	95.3%
232		22	0	100.0%	295	11	96.3%	22	0	100.0%	295	17	94.2%
233		16	3	81.3%	267	59	77.9%	16	11	31.3%	267	84	68.5%
234		22	1	95.5%	295	20	93.2%	22	0	100.0%	295	24	91.9%
235	29	22	3	86.4%	219	30	86.3%	22	8	63.6%	219	49	77.6%
236		22	2	90.9%	279	9	96.8%	22	3	86.4%	279	39	86.0%
237		22	3	86.4%	293	55	81.2%	22	5	77.3%	291	48	83.5%
238		22	0	100.0%	219	19	91.3%	22	2	90.9%	218	16	92.7%
239		22	4	81.8%	294	76	74.1%	22	4	81.8%	293	34	88.4%
240		22	0	100.0%	294	20	93.2%	22	10	54.5%	292	54	81.5%
241		22	5	77.3%	295	73	75.3%	22	3	86.4%	295	69	76.6%
243		22	8	63.6%	231	63	72.7%	22	5	77.3%	230	31	86.5%
244	27	16	2	87.5%	267	12	95.5%	16	8	50.0%	267	46	82.8%
245		22	5	77.3%	176	32	81.8%	22	3	86.4%	175	20	88.6%
280	57	22	2	90.9%	295	13	95.6%	22	6	72.7%	295	56	81.0%
281		22	5	77.3%	295	34	88.5%	22	8	63.6%	295	55	81.4%
283		22	9	59.1%	295	73	75.3%	22	8	63.6%	295	60	79.7%
284		22	1	95.5%	295	11	96.3%	22	9	59.1%	293	51	82.6%
290	41	22	1	95.5%	295	49	83.4%	22	17	22.7%	293	108	63.1%
291	33	22	11	50.0%	294	86	70.7%	22	12	45.5%	292	70	76.0%
300	44	22	1	95.5%	279	20	92.8%	22	9	59.1%	277	65	76.5%
301	209	22	1	95.5%	293	10	96.6%	22	5	77.3%	290	55	81.0%
302		16	1	93.8%	274	32	88.3%	16	4	75.0%	270	76	71.9%
305	17	16	0	100.0%	277	28	89.9%	16	8	50.0%	273	110	59.7%
306	78	22	0	100.0%	291	15	94.8%	22	8	63.6%	290	79	72.8%
307		22	3	86.4%	283	38	86.6%	22	9	59.1%	280	79	71.8%
311	17	19	2	89.5%	290	25	91.4%	18	8	55.6%	284	58	79.6%
316	60	18	1	94.4%	286	17	94.1%	17	9	47.1%	282	73	74.1%
318	16	21	5	76.2%	293	31	89.4%	21	14	33.3%	290	138	52.4%
319	44	21	3	85.7%	294	20	93.2%	18	14	22.2%	289	159	45.0%
329		16	0	100.0%	208	8	96.2%	16	0	100.0%	208	13	93.8%
330		19	0	100.0%	250	4	98.4%	19	1	94.7%	250	14	94.4%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		22	3	86.4%	295	32	89.2%	22	2	90.9%	295	42	85.8%
332		22	2	90.9%	295	16	94.6%	22	3	86.4%	295	42	85.8%
334		22	1	95.5%	295	10	96.6%	22	1	95.5%	294	37	87.4%
335		22	0	100.0%	295	30	89.8%	22	4	81.8%	293	47	84.0%
336		22	1	95.5%	295	9	96.9%	22	2	90.9%	293	27	90.8%
337		22	1	95.5%	295	18	93.9%	22	2	90.9%	291	35	88.0%
338		22	3	86.4%	295	44	85.1%	22	7	68.2%	293	88	70.0%
339		22	2	90.9%	295	48	83.7%	22	2	90.9%	295	50	83.1%
341		22	5	77.3%	284	40	85.9%	22	4	81.8%	279	39	86.0%
342		22	0	100.0%	295	21	92.9%	22	2	90.9%	293	55	81.2%
350	25	18	1	94.4%	272	18	93.4%	16	9	43.8%	265	145	45.3%
351		22	2	90.9%	278	27	90.3%	22	7	68.2%	276	75	72.8%
352		22	1	95.5%	262	21	92.0%	22	6	72.7%	256	77	69.9%
353		18	1	94.4%	233	13	94.4%	18	2	88.9%	227	37	83.7%
354		22	7	68.2%	276	35	87.3%	19	7	63.2%	269	96	64.3%
355		18	3	83.3%	285	30	89.5%	18	9	50.0%	278	94	66.2%
364		22	2	90.9%	284	62	78.2%	22	13	40.9%	278	103	62.9%
365	83	22	1	95.5%	283	11	96.1%	22	13	40.9%	281	105	62.6%
370	Cncld	22	2	90.9%	286	35	87.8%	20	3	85.0%	277	68	75.5%
371		21	0	100.0%	280	8	97.1%	21	2	90.5%	279	29	89.6%
380		21	3	85.7%	280	27	90.4%	21	10	52.4%	280	59	78.9%
381	25	20	1	95.0%	293	12	95.9%	20	7	65.0%	292	55	81.2%
382		20	9	55.0%	292	25	91.4%	20	11	45.0%	292	95	67.5%
383		22	1	95.5%	284	26	90.8%	21	12	42.9%	281	117	58.4%
390		22	1	95.5%	277	18	93.5%	22	8	63.6%	276	71	74.3%
391	22	20	3	85.0%	278	11	96.0%	20	9	55.0%	275	74	73.1%
392		19	3	84.2%	291	8	97.3%	19	10	47.4%	289	88	69.6%
393		22	1	95.5%	295	17	94.2%	22	12	45.5%	292	89	69.5%
417		15	5	66.7%	195	43	77.9%	15	4	73.3%	186	21	88.7%
425		15	0	100.0%	197	6	97.0%	15	0	100.0%	197	7	96.4%
448		22	5	77.3%	225	43	80.9%	22	8	63.6%	223	76	65.9%
449		22	2	90.9%	223	32	85.7%	22	4	81.8%	223	40	82.1%
470		15	2	86.7%	208	36	82.7%	15	1	93.3%	202	24	88.1%
471	26	15	4	73.3%	198	10	94.9%	15	3	80.0%	198	5	97.5%
473		15	1	93.3%	204	14	93.1%	15	1	93.3%	201	9	95.5%
474		18	10	44.4%	202	61	69.8%	15	12	20.0%	187	59	68.4%
475		15	1	93.3%	202	6	97.0%	15	4	73.3%	202	14	93.1%
478		15	3	80.0%	196	30	84.7%	15	5	66.7%	194	25	87.1%
479		15	3	80.0%	203	32	84.2%	15	7	53.3%	201	29	85.6%
486		15	2	86.7%	207	30	85.5%	15	5	66.7%	201	55	72.6%
494		16	4	75.0%	209	39	81.3%	15	11	26.7%	202	55	72.8%
495		15	0	100.0%	193	3	98.4%	15	0	100.0%	191	3	98.4%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
500	20	22	1	95.5%	286	16	94.4%	21	2	90.5%	283	34	88.0%
502		22	2	90.9%	293	17	94.2%	21	1	95.2%	289	57	80.3%
503	30	22	2	90.9%	291	27	90.7%	21	10	52.4%	284	84	70.4%
504		22	1	95.5%	295	18	93.9%	22	5	77.3%	293	87	70.3%
505	21	22	1	95.5%	293	37	87.4%	21	7	66.7%	288	80	72.2%
506		22	3	86.4%	290	41	85.9%	21	4	81.0%	284	45	84.2%
507	19	22	1	95.5%	295	35	88.1%	22	8	63.6%	295	96	67.5%
508		22	2	90.9%	290	41	85.9%	21	4	81.0%	286	66	76.9%
509		22	2	90.9%	292	14	95.2%	22	3	86.4%	292	66	77.4%
511		22	1	95.5%	287	22	92.3%	22	2	90.9%	286	47	83.6%
517	23	22	0	100.0%	295	8	97.3%	22	14	36.4%	291	122	58.1%
518	45	22	0	100.0%	295	35	88.1%	22	16	27.3%	293	199	32.1%
520		16	0	100.0%	166	24	85.5%	16	0	100.0%	163	9	94.5%
521		16	0	100.0%	204	7	96.6%	16	4	75.0%	204	27	86.8%
522		16	1	93.8%	204	37	81.9%	16	0	100.0%	201	18	91.0%
523		16	1	93.8%	204	7	96.6%	16	0	100.0%	203	22	89.2%
524		16	2	87.5%	204	13	93.6%	16	2	87.5%	202	22	89.1%
525		16	2	87.5%	202	14	93.1%	15	0	100.0%	198	13	93.4%
526		16	4	75.0%	178	33	81.5%	16	2	87.5%	175	14	92.0%
527		16	1	93.8%	204	10	95.1%	16	4	75.0%	203	36	82.3%
528		16	2	87.5%	204	17	91.7%	16	1	93.8%	203	30	85.2%
529		16	0	100.0%	204	11	94.6%	16	4	75.0%	203	54	73.4%
530		16	2	87.5%	158	16	89.9%	16	5	68.8%	158	31	80.4%
531		16	0	100.0%	178	12	93.3%	16	2	87.5%	178	13	92.7%
532		16	6	62.5%	204	49	76.0%	16	4	75.0%	203	31	84.7%
534		16	1	93.8%	163	25	84.7%	16	1	93.8%	161	16	90.1%
535		16	1	93.8%	191	24	87.4%	16	1	93.8%	186	21	88.7%
536		16	6	62.5%	204	55	73.0%	15	0	100.0%	200	37	81.5%
537		16	3	81.3%	175	21	88.0%	15	2	86.7%	169	18	89.3%
538		16	0	100.0%	204	23	88.7%	16	5	68.8%	203	42	79.3%
539	28	16	3	81.3%	158	23	85.4%	16	6	62.5%	158	70	55.7%
540		15	3	80.0%	203	38	81.3%	14	0	100.0%	195	18	90.8%
541	19	16	1	93.8%	203	22	89.2%	15	3	80.0%	197	36	81.7%
542	Cncld	16	3	81.3%	203	24	88.2%	15	3	80.0%	200	35	82.5%
543	30	16	3	81.3%	204	22	89.2%	16	11	31.3%	204	61	70.1%
544		16	0	100.0%	202	20	90.1%	16	2	87.5%	199	17	91.5%
545		16	2	87.5%	204	17	91.7%	15	2	86.7%	201	24	88.1%
547		16	2	87.5%	204	39	80.9%	16	1	93.8%	204	45	77.9%
548		15	1	93.3%	199	21	89.4%	14	0	100.0%	197	14	92.9%
549		16	1	93.8%	199	26	86.9%	15	1	93.3%	191	17	91.1%
550		16	3	81.3%	158	17	89.2%	16	4	75.0%	158	35	77.8%
551	Cncld	16	2	87.5%	200	21	89.5%	15	1	93.3%	191	18	90.6%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562	35	22	1	95.5%	287	22	92.3%	22	3	86.4%	284	32	88.7%
564	80	22	2	90.9%	287	19	93.4%	22	4	81.8%	279	34	87.8%
566	99	22	5	77.3%	285	22	92.3%	22	6	72.7%	282	38	86.5%
567	50	22	1	95.5%	172	9	94.8%	22	3	86.4%	170	9	94.7%
572	103	22	1	95.5%	282	23	91.8%	21	11	47.6%	276	76	72.5%
573	21	22	0	100.0%	285	40	86.0%	22	3	86.4%	278	47	83.1%
579	78	22	1	95.5%	172	9	94.8%	22	6	72.7%	167	32	80.8%
580	19	22	0	100.0%	287	14	95.1%	22	4	81.8%	282	25	91.1%
581	162	22	4	81.8%	287	47	83.6%	22	6	72.7%	285	60	78.9%
584	85	22	6	72.7%	171	23	86.5%	21	18	14.3%	166	100	39.8%
587	84	21	1	95.2%	281	16	94.3%	21	11	47.6%	272	49	82.0%
588	71	22	4	81.8%	172	16	90.7%	22	5	77.3%	171	27	84.2%
591	39	22	2	90.9%	286	20	93.0%	22	5	77.3%	280	34	87.9%
593	26	22	7	68.2%	281	44	84.3%	20	4	80.0%	261	31	88.1%
595	No OS	22	7	68.2%	282	48	83.0%	22	8	63.6%	279	54	80.6%
600		15	0	100.0%	212	9	95.8%	15	2	86.7%	210	17	91.9%
601		15	8	46.7%	195	80	59.0%	15	2	86.7%	192	25	87.0%
605		15	8	46.7%	202	126	37.6%	15	3	80.0%	198	22	88.9%
607		15	5	66.7%	211	29	86.3%	15	3	80.0%	208	25	88.0%
609		15	1	93.3%	202	23	88.6%	15	3	80.0%	201	18	91.0%
622		12	2	83.3%	115	32	72.2%	12	0	100.0%	113	5	95.6%
626		15	3	80.0%	116	15	87.1%	15	2	86.7%	114	17	85.1%
639		14	1	92.9%	182	38	79.1%	14	0	100.0%	181	19	89.5%
640		15	0	100.0%	202	7	96.5%	15	2	86.7%	200	78	61.0%
641		15	4	73.3%	184	38	79.3%	15	1	93.3%	184	26	85.9%
642		15	0	100.0%	200	9	95.5%	15	3	80.0%	199	26	86.9%
643	33	15	2	86.7%	214	41	80.8%	15	3	80.0%	211	35	83.4%
644		15	0	100.0%	206	27	86.9%	15	3	80.0%	204	51	75.0%
645		15	3	80.0%	214	41	80.8%	14	6	57.1%	211	45	78.7%
646	11	15	5	66.7%	203	51	74.9%	15	10	33.3%	201	99	50.7%
647	69	15	1	93.3%	214	32	85.0%	15	4	73.3%	213	47	77.9%
648		15	4	73.3%	210	54	74.3%	15	2	86.7%	210	33	84.3%
649	24	15	4	73.3%	215	41	80.9%	15	2	86.7%	212	33	84.4%
650	54	15	1	93.3%	214	40	81.3%	15	4	73.3%	211	34	83.9%
651		15	0	100.0%	214	16	92.5%	15	3	80.0%	212	42	80.2%
652	19	15	2	86.7%	215	29	86.5%	15	5	66.7%	211	37	82.5%
653		15	3	80.0%	203	33	83.7%	15	4	73.3%	200	38	81.0%
654		15	3	80.0%	204	39	80.9%	14	1	92.9%	200	17	91.5%
655		15	2	86.7%	212	71	66.5%	15	4	73.3%	210	72	65.7%
656		15	1	93.3%	214	46	78.5%	15	6	60.0%	213	27	87.3%
657		15	1	93.3%	203	27	86.7%	15	1	93.3%	202	29	85.6%
658		15	1	93.3%	214	35	83.6%	15	1	93.3%	212	31	85.4%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680	15	16	3	81.3%	209	12	94.3%	16	3	81.3%	208	27	87.0%
681	14	16	2	87.5%	209	16	92.3%	15	9	40.0%	203	81	60.1%
682		16	1	93.8%	208	6	97.1%	16	4	75.0%	208	37	82.2%
683		16	1	93.8%	191	16	91.6%	16	13	18.8%	190	64	66.3%
684		16	5	68.8%	190	32	83.2%	16	5	68.8%	190	43	77.4%
685		16	3	81.3%	205	31	84.9%	16	8	50.0%	202	52	74.3%
686		16	4	75.0%	210	37	82.4%	16	9	43.8%	209	45	78.5%
687		16	3	81.3%	209	33	84.2%	16	4	75.0%	208	35	83.2%
688		16	4	75.0%	208	13	93.8%	16	6	62.5%	207	36	82.6%
701		22	3	86.4%	227	24	89.4%	22	3	86.4%	224	23	89.7%
702	22	22	1	95.5%	294	32	89.1%	21	6	71.4%	291	66	77.3%
703		22	12	45.5%	295	89	69.8%	21	11	47.6%	293	81	72.4%
704	23	22	3	86.4%	226	35	84.5%	21	4	81.0%	220	42	80.9%
710		22	7	68.2%	295	76	74.2%	22	7	68.2%	291	80	72.5%
711		22	5	77.3%	286	33	88.5%	18	3	83.3%	265	48	81.9%
712	21	22	7	68.2%	292	78	73.3%	21	7	66.7%	283	94	66.8%
713	Cncld	18	1	94.4%	164	15	90.9%	16	7	56.3%	149	63	57.7%
714		21	13	38.1%	176	71	59.7%	20	10	50.0%	163	68	58.3%
715	119	22	2	90.9%	294	60	79.6%	18	9	50.0%	271	134	50.6%
716	139	22	10	54.5%	295	117	60.3%	21	8	61.9%	289	110	61.9%
717	30	21	3	85.7%	280	65	76.8%	20	9	55.0%	261	79	69.7%
718		22	10	54.5%	295	146	50.5%	22	11	50.0%	293	102	65.2%
719		22	8	63.6%	295	96	67.5%	21	9	57.1%	280	81	71.1%
757		22	1	95.5%	80	4	95.0%	22	3	86.4%	79	7	91.1%
761	27	22	1	95.5%	291	12	95.9%	22	4	81.8%	288	38	86.8%
765	60	22	0	100.0%	291	24	91.8%	22	4	81.8%	291	40	86.3%
769	31	22	1	95.5%	291	26	91.1%	22	5	77.3%	285	54	81.1%
770	141	22	0	100.0%	291	21	92.8%	22	11	50.0%	289	85	70.6%
774	73	22	0	100.0%	291	16	94.5%	22	7	68.2%	290	63	78.3%
777	107	22	2	90.9%	176	11	93.8%	22	5	77.3%	175	39	77.7%
782	55	22	18	18.2%	176	74	58.0%	22	6	72.7%	171	21	87.7%
785	37	22	3	86.4%	291	20	93.1%	22	6	72.7%	291	52	82.1%
786	42	22	1	95.5%	80	17	78.8%	21	12	42.9%	78	39	50.0%
790	32	22	0	100.0%	291	26	91.1%	22	7	68.2%	288	39	86.5%
794	79	22	2	90.9%	291	33	88.7%	22	6	72.7%	288	61	78.8%
821	18	22	0	100.0%	289	6	97.9%	22	13	40.9%	289	116	59.9%
822	17	22	1	95.5%	291	15	94.8%	22	16	27.3%	289	134	53.6%
1333		22	3	86.4%	291	31	89.3%	22	6	72.7%	288	94	67.4%
1340	17	22	0	100.0%	290	5	98.3%	22	4	81.8%	290	46	84.1%
1689	92	13	0	100.0%	87	5	94.3%	13	2	84.6%	86	10	88.4%
2102		15	0	100.0%	61	12	80.3%	15	1	93.3%	60	5	91.7%
2103		15	2	86.7%	125	12	90.4%	15	0	100.0%	124	9	92.7%

Amtrak On Time Performance

Trains Arriving Through: 7/22/2026

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2104		15	0	100.0%	151	9	94.0%	15	2	86.7%	149	12	91.9%
2107		15	3	80.0%	182	33	81.9%	15	0	100.0%	179	20	88.8%
2108		15	0	100.0%	182	25	86.3%	15	2	86.7%	176	19	89.2%
2109		15	1	93.3%	75	10	86.7%	15	0	100.0%	74	4	94.6%
2112		15	2	86.7%	22	4	81.8%	14	2	85.7%	20	2	90.0%
2113		15	3	80.0%	61	6	90.2%	15	1	93.3%	61	8	86.9%
2115		15	4	73.3%	61	9	85.2%	15	6	60.0%	60	10	83.3%
2116	No OS	15	0	100.0%	22	0	100.0%	15	4	73.3%	22	6	72.7%
2118		15	2	86.7%	22	2	90.9%	15	6	60.0%	22	8	63.6%
2119	128	15	1	93.3%	22	3	86.4%	15	8	46.7%	22	9	59.1%
2120	No OS	15	5	66.7%	22	8	63.6%	14	9	35.7%	21	12	42.9%
2123		15	2	86.7%	60	8	86.7%	14	2	85.7%	59	15	74.6%
2124	96	15	9	40.0%	154	32	79.2%	15	9	40.0%	152	22	85.5%
2127		15	5	66.7%	22	6	72.7%	15	6	60.0%	21	6	71.4%
2128		15	2	86.7%	22	2	90.9%	15	1	93.3%	22	1	95.5%
2131	26	15	5	66.7%	22	5	77.3%	15	2	86.7%	22	2	90.9%
2150		15	0	100.0%	175	22	87.4%	15	3	80.0%	172	70	59.3%
2151	26	15	0	100.0%	124	6	95.2%	15	6	60.0%	122	35	71.3%
2152		12	3	75.0%	80	6	92.5%	12	4	66.7%	79	30	62.0%
2155		15	2	86.7%	184	16	91.3%	15	6	60.0%	180	96	46.7%
2158	34	15	1	93.3%	22	3	86.4%	15	8	46.7%	22	8	63.6%
2159	18	15	1	93.3%	177	12	93.2%	15	9	40.0%	175	57	67.4%
2160	25	15	1	93.3%	22	1	95.5%	14	10	28.6%	21	14	33.3%
2162		15	3	80.0%	183	16	91.3%	15	6	60.0%	177	83	53.1%
2165	27	12	2	83.3%	19	2	89.5%	12	7	41.7%	19	9	52.6%
2167		12	2	83.3%	171	20	88.3%	12	1	91.7%	171	37	78.4%
2171		15	1	93.3%	111	9	91.9%	15	4	73.3%	108	22	79.6%
2190		12	3	75.0%	180	27	85.0%	12	1	91.7%	178	23	87.1%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2116	NYP	No OS Rpt	DCS	15	DCS	15	XHM-XCY	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP- CLARK
2119	WAS	128	DCS	59	DCS	59	XCY-XHM	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK
2120	NYP	No OS Rpt	SMW	9	SMW	6	BAL-XPV	AM	Diversions around M/W work, Control Point, Gunpow, Opr No.1 trk a/c No.2 trk O/O/S
2124	NYP	96	ITI	107	ITI	107	WAS-WAS	AM	Service, turn, or wye train, 2119, LATE TURN OF EQUIPMENT OFF OF 2119. 2119 AR @ 722P
2131	WAS	26	MTI	22	MTI	22	PHL-PHL	AM	Disabled train ahead, Control Point, PENN, HELD FOR POSSIBLE PSGR TRANSFER FROM AM137; ORDERED TO FOLLOW AM137 AS A PROTECT TRAIN
2151	WAS	26	CTI	23	CTI	23	NHV-STM	MN	Follow MNRR, Control Point, 248
2158	BOS	34	DCS	37	DCS	37	XHM-XCY	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK
2159	WAS	18	DMW	14	DMW	10	NHV-STM	MN	Hold for defect repair Control Point, EAST NORWALK
2160	BOS	25	CTI	15	DCS	14	XHM-XCY	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK
2165	WAS	27	DCS	29	DCS	28	XCY-XHM	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS INT- CP CLARK
66	BOS	20	PTI	39	PTI	21	CVS-CLP	NS	Meet AMTK171, Control Point, Weyburn
85	WAS	65	DCS	37	DCS	36	MET-TRE	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS INT- CP CLARK
93	NFK	42	DCS	66	DCS	66	MET-XHM	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS - CP CLARK
125	NPN	29	CTI	35	SYS	14	WFD-STS	AM	Copy authority / restriction, stopped to copy TSRB addition
134	NYP	58	DCS	48	DCS	47	TRE-MET	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS INT -CP CLARK
136	SPG	55	SYS	39	SYS	39	NYP-NYP	AM	Other late crew, HELD IN STATION FOR CREW OFF AM175
137	WAS	83	ENG	46	ENG	46	PHL-PHL	AM	Unrecoverable penalty (PCS), 603 EX ES, UNRECOVERABLE PENALTY APPLICATION; FAULT CLEARED AND BACK ON THE MOVE
173	WAS	18	DCS	19	DCS	14	MET-XHM	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
176	BOS	20	OTH	20	DCS	8	BRP-NHV	MN	Stop signal Control Point, 271
178	BOS	57	SYS	60	SYS	60	NYP-NYP	AM	Other late crew, HELD A/C TO WAIT FOR CREW OFF AM137
186	PHL	32	SVS	21	SVS	21	WAS-WAS	AM	Planned Switch, ADDING 2 CARS TO H/E OF 90 REQUIRED ADDITIONAL TIME . 1 CREW WORKING TRNS 90 & 186
197	WAS	18	OTH	12	DBS	10	MET-XHM	AM	Animal strike, Other, MP53.7
471	NHV	26	ITI	27	ITI	27	HFD-HFD	AM	Service, turn, or wye train, 426, Late turn
643	HAR	33	ENG	28	ENG	15	NWK-TRE	AM	PTC - On Board Cab Signal or PTC Failure, 618 EX ES, STOPPED TO RESET ACSES ON ENG.618
646	NYP	11	OTH	7	PTI	7	PJC-NWK	AM	Follow, AM86, Other, XIS-NWK
647	HAR	69	DCS	71	DCS	71	EWR-TRE	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK
649	HAR	24	DCS	46	DCS	46	EWR-TRE	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK
650	NYP	54	DCS	51	DCS	27	TRE-PJC	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS INT TO CP CLARK
652	NYP	19	CTI	15	CTI	10	NWK-NYP	AM	Follow, NJX, 370, Other, NWK NYP
680	BON	15	ENG	12	ENG	9	XP0-HHL	MT	Cab signal failure Received permission to hit PTSO button. Finally able to move again, but held to 15 mph from SL to Rosemont, 87
681	BRK	14	PTI	17	PTI	12	POR-FRE	CS	Meet 684, Control Point, Congress
1689	BRK	92	ENG	101	ENG	29	XP0-EXR	CS	Traction motor 113
63	TWO	94	PTI	25	PTI	25	ROM-SYR	CS	Meet 48, Control Point, 278
64	NYP	23	HLD	18	HLD	16	NFS-NFS	XC	Passenger and/or baggage
68	NYP	23	POL	40	POL	40	WSP-WSP	DH	Removal of passenger by police Refused to pay and remove himself.
235	ALB	29	OTH	5	OTH	5	NYP-XSD	AM	Lost time - N.A.R.
244	NYP	27	CTI	17	DCS	10	ALB-HUD	AM	Issue with automatic road crossing protection Milepost, 138, 137
280	NYP	57	DMW	54	DMW	22	POU-CRT	MN	Waiting for MW clearance Milepost, 45, 43
290	NYP	41	CTI	44	CTI	25	POU-CRT	MN	Meet metro, 833, Control Point, 46
291	BTN	33	PTI	44	PTI	29	RHI-HUD	AM	Meet 48, 244, Control Point, 114

Amtrak Endpoint OTP Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
42	NYP	31	DCS	25	DCS	24	TRE-NWK	AM	Signal suspension, Other, SIGNAL POWER LOSS ADAMS- CP CLARK	
43	PGH	21	OTH	25	OTH	14	GNB-GNB	NS	Stopped at GNB. Engine 121 inspected by engineer and conductor due to smell of heat and felt shuddering in wheels. Temps obtained for wheels, axles and barings. All within normal range. No viable defects noted.	
75	CLT	17	FTI	12	FTI	12	SAL-KAN	NS	Meet #NS28R, Control Point, Sumner	
76	RGH	15	TCC	8	PTI	6	DNC-CYN	NS	Meet #Am79, Control Point, Sullivan	
77	CLT	12	PTI	10	FTI	6	GRO-GRO	NS	Meet #NS28R, Control Point, Elm	
90	NYP	34	FTI	79	FTI	38	RVR-XDJ	CS	Follow CSX410, Other, CFP49.9	
97	MIA	393	CTI	150	CTI	100	FBG-FBG	CS	All stop at the Fredericksburg Station waiting on VRE 313 to be released after passenger strike VRE, 313, Other, Fredericksburg station	
98	NYP	33	FTI	62	CTI	25	XDJ-ALX	CS	Follow vre, Milepost, 61.0, 105.2	
40	CHI	154	WTR	134	WTR	34	RVR-XDJ	CS	High winds Milepost w/Letters, CFP 17.0, CFP 47.0	
41	MIA	198	FTI	97	SYS	47	TPA-TPA	CS	PTC problem or failure (cause unknown) PTC NOT INITIALIZING, Other, A 882.0	
5	EMY	96	WTR	183	SYS	37	RNO-RNO	UP	Re-crew / job briefing Train arrived RNO at 1147 can't change arrival time	
6	CHI	195	WTR	171	DMW	41	PCT-NPV	BN	Held for or routed around MW work or equipment Held due to MOW window on M2. Had to wait for Amt3 & Amt5 to pass on M1, Control Point, Zearing	
539	SJC	28	PTI	19	PTI	16	GAC-SCC	UP	Meet Amt538, Control Point, Coo44	
541	OKJ	19	TEN	20	TEN	20	SAC-SAC	UP	Inspecting substantial oil leak C2001	
542	SAC	Tn Cancelled								
543	SJC	30	CTI	15	MBO	11	SUI-MTZ	UP	For maritime traffic Bridge, suisun bay bridge	
551	OKJ	Tn Cancelled								
50	NYP	No OS Rpt	ENG	355	ENG	342	XEF-XTJ	UP	Set out defective locomotive Made it to up mp 13.5 went into emergency. Would not recover. Chi mech came out to make eng dead in tow. Shoved back to CUS and grove equip was cut off as well as 356. Replaced with 63., 356	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
500	SEA	20	MBO	11	MBO	11	PDX-VAN	BN	For maritime traffic Bridge, Willamette Draw
503	EUG	30	PTI	27	WTR	20	ALY-EUG	UP	Heat order Milepost, 690.8, 647.3
505	PDX	21	MBO	18	MBO	18	VAN-VAN	BN	For maritime traffic Bridge, Columbia River
507	EUG	19	DSR	22	WTR	16	ALY-EUG	UP	Heat order Milepost, 699.42, 647.3
517	PDX	23	WTR	22	WTR	8	CTL-KEL	BN	Heat order Milepost, 54.0, 97.3
518	VAC	45	DSR	30	PTI	12	PDX-VAN	BN	Meet AMTK 11, Control Point, CP 05
14	SEA	35	DCS	62	FTI	33	RDD-DUN	UP	Meet UP 7272, UP 8018, Siding, Grey Rocks, Siding, Sims
8	CHI	68	FTI	190	FTI	65	MAL-GGW	BN	Meet Duck and tuck behind BNSF 7719E at Saco Duck and tuck behind 7021E at Tampico, BNSF 7647w, BNSF 8535w, Siding, Saco, Siding, Tampico
821	FTW	18	DSR	44	DSR	23	GLE-FTW	BN	Per bulletin Milepost, 408.5, 408.1, 60, m, Milepost, 407, 406.7, 60, m, Milepost, 403.2, 402.7, 75, m, Milepost, 401, 400.2, 25, m, Milepost, 397.5, 397.3, 50, m, Milepost, 396.3, 396.2, 30, m, Milepost, 396, 395.9, 50, m, Milepost, 393.6, 393.5, 50, m, Milepost, 392.4, 392.2, 60, m, Milepost, 389.
822	OKC	17	FTI	24	FTI	24	FTW-GLE	BN	Meet BN Freight, BN 8009, Siding, Justin, Siding, Ponder
350	PNT	25	PTI	48	PTI	24	XB0-XA5	MI	Meet AMTK353, Control Point, 99
365	CHI	83	FTI	86	FTI	60	LPE-FLN	CC	Meet EB CN 3150 entering Lapeer siding died for time while blocking the main., CN3150, Control Point, West Lapeer
370	GRR	Trn Cancelled	CAR	48	CAR	48	CHI-CHI	AM	Set out defective car ID4313, In the yard
562	SAN	35	DCS	52	DCS	31	OSD-SOL	SN	Issue with automatic road crossing protection Milepost, 226, 241
564	SAN	80	CTI	39	CTI	22	LAX-LAX	SC	Multiple trains in and out of la union station causing late departure metrolink, Other, laus
566	SAN	99	CAR	66	CAR	66	LAX-LAX	SC	Set out defective car 6400, Last minute switching. Late release of equipment.
567	LAX	50	DCS	48	DCS	18	OLT-SOL	SN	DOT Hotline malfunction Bulletin 585 DOT HOTLINE MALFUNCTION, do not exceed 20 mph overall great crossings in the San Diego, Other, OLT Sta, Other, SAN Sta
572	SAN	103	POL	33	POL	33	OSD-OSD	SN	Right of Way police hold

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 7/22/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
573	LAX	21	DCS	27	DCS	13	SOL-OSD	SN	Issue with automatic road crossing protection Milepost, 241, 225
579	LAX	78	POL	34	POL	31	SOL-SOL	SN	Right of Way police hold Hold for Police activity at mp 233.33
580	SAN	19	DSR	11	DSR	8	X98-OSD	SN	Per bulletin Milepost, 217.07, 217.57, 10, MAIN
581	LAX	162	ITI	110	ITI	110	SAN-SAN	SN	Service, turn, or wye train 770, AMTK 770 very late arrival into SAN causing late equipment turn for AMTK 581
584	SAN	85	PTI	58	PTI	44	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	84	PTI	36	PTI	36	OSD-X98	SC	Meet 782, Control Point, pulgas
588	SAN	71	ITI	42	ITI	42	LAX-LAX	SC	Service, turn, or wye train 581
591	LAX	39	PTI	32	PTI	14	OSD-X98	SN	Meet 786, Control Point, pulgas
593	LAX	26	FTI	20	ITI	12	SAN-SAN	SN	Service, turn, or wye train 782, Late arrival of equipment from train 782.
595	LAX	No OS Rpt	ITI	57	ITI	57	SAN-SAN	SN	Service, turn, or wye train 584
761	GTA	27	DCS	34	DCS	18	SOL-OSD	SN	Issue with automatic road crossing protection 20 mph x-ings, Milepost, 240, 226
765	SLO	60	CTI	40	DCS	17	SOL-OSD	SN	Issue with automatic road crossing protection Held to 20 miles an hour over all grade crossing on SAN DIEGO subdivision due to DOT Hotline malfunction, Milepost, 241, 226
769	GTA	31	DCS	31	DCS	12	SOL-OSD	SN	Issue with automatic road crossing protection 20 MPH over all crossings account crossing hotline inoperative., Other, All crossings
770	SAN	141	TRS	75	TRS	75	OSD-SOL	SN	Swatt standoff Milepost, 233.12, 233.33
774	SAN	73	CTI	50	DCS	36	LPS-X3G	UP	Restrictive signal(s) from unknown cause Red, Milepost, 312, 335
777	SLO	107	POL	71	POL	71	SOL-OSD	SN	Right of Way police hold
782	SAN	55	PTI	73	PTI	45	SNC-SNP	SC	Meet 581 785, Siding, Capistrano
785	GTA	37	PTI	24	PTI	10	VNC-CWT	SC	Meet 11, Control Point, Raymer
786	SAN	42	PTI	45	CTI	28	SIM-CWT	SC	Meet Metrolink, 123, Siding, santa susana
790	SAN	32	PTI	36	PTI	17	XRJ-FUL	BN	Follow 588, Control Point, santa fe springs

Amtrak Endpoint OTP Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
794	SAN	79	PTI	61	PTI	57	IRV-SNC	SC	Meet Single tracking from CP Trabuco to CP Mesa due to tied down freight trains on NCTD as well as tampers occupying the siding at Capistrano allows no passing of trains until CP Trabuco. 595 followed 593., 593, 595, Control Point, Trabuco	
702	BFD	22	FTI	15	PTI	15	COC-WAC	BN	Meet Amtrak 715, Siding, Sandrini	
704	BFD	23	PTI	46	PTI	19	TRK-MCD	BN	Meet amtrak 719, Siding, ballico	
712	BFD	21	DMW	20	DMW	12	SKN-MOD	BN	Waiting for MW clearance Stopped short of red flag as to not block the crossings. Awaiting for radio clearance., Milepost, 1101.6, 1101.6	
713	OKJ	Trn Cancelled	PTI	24	PTI	13	TRK-MOD	BN	Meet amtk 712, Control Point, West modesto empire	
715	OKJ	119	DMW	48	DMW	32	MCD-TRK	BN	Held for or routed around MW work or equipment Siding, East Fluhr	
716	BFD	139	TCC	63	TCC	63	OKJ-OKJ	UP	Electrical failure 6962, Notch selector indicator light not working	
717	OKJ	30	FTI	37	FTI	31	TRK-MOD	BN	Meet Shuffle, bnsf 5860, Control Point, east modesto empire	
3	LAX	40	FTI	128	FTI	65	GLP-WLO	BN	Follow Unknown, Milepost, 170.9, 189.9, Milepost, 210.4, 243.3	
4	CHI	No OS Rpt	ENG	462	ENG	205	WLO-WLO	BN	Operating with freight engine (due to mechanical failure) Went to depart Winslow. Lost HEP. Multiple alarms went off. Added BNSF engine 5326. Couldn't get MU cable to work. Finally departed at 10:08., 76	
22	CHI	119	DSR	85	FTI	37	XUD-XTF	CC	Cross Traffic Control Point, Canal, Control Point, Cermax, unknown, CN 8337	
300	CHI	44	PTI	37	PTI	28	XUD-SMT	CC	Meet Amtrak Train 301, Control Point, Lambert	
301	STL	209	CAR	211	CAR	86	XTF-XUD	CC	Air / Brake / Wheel ID4019	
305	STL	17	PTI	33	PTI	19	BNL-LCN	UP	Meet Amtk306, Siding, Athol	
306	CHI	78	CAR	112	CAR	16	LCN-BNL	UP	Air / Brake / Wheel ID4019, Brakes cut out	
381	GBB	25	RTE	17	RTE	17	PLO-MDT	BN	Dispatcher hold Single tracking betweenElectrics and Zearing, Control Point, Electrics	
391	CDL	22	DSR	18	FTI	14	HMW-KKI	CC	Meet Fti 3032, Siding, Powers	

Amtrak Endpoint OTP Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
311	KCY	17	FTI	19	FTI	19	XRC-KCY	KC	Cross Traffic UP Freight, Control Point, UPRR Interlocker
316	STL	60	FTI	65	FTI	55	SED-JEF	UP	Follow Local stalled on hill had to shove back to Jefferson City to get us a route, Control Point, Centertown, Control Point, River Jct, UP 1137
318	CHI	16	FTI	31	FTI	31	LEE-WAR	UP	Meet up 7517/8821, Siding, strausberg
319	KCY	44	DSR	36	SVS	11	STL-STL	TR	Fuel
1340	CHI	17	TRS	22	TRS	22	CBS-MKE	CP	Kids on tracks Other, CUTOFF

Amtrak Initial Terminal Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/22/2026

Terminal	Train	Date	Late	Delay	Cause
BON	683	07/22	1		
BOS	137	07/22	34	34	Planned set out / pick out of locomotives, cars or section of train, Late release from the yard
BRK	680	07/22	8	8	Wait for station track 1689, Control Point, Layover
BRK	684	07/22	1	1	Dtmf not working on conductors radio. Had to have engineer try on his radio. Control Point, cp brunswick west
HAR	658	07/22	2	2	Wait for scheduled departure time
HFD	471	07/22	27	27	Service, turn, or wye train, 426, Late turn
NHV	470	07/22	4	4	Service, turn, or wye train, 471, Late turn
NYP	69	07/22	3	3	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	89	07/22	6	6	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	97	07/22	31	33	Service, turn, or wye train, 98
NYP	241	07/22	6	8	Scheduled in track usage program, Other, NYP
NYP	243	07/22	3	3	Passenger and/or baggage
NYP	245	07/22	2	2	Passenger and/or baggage, LOADING
NYP	283	07/22	5	5	Passenger and/or baggage, HEAVY LOADING
NYP	2109	07/22	2	2	Water, commissary, toilet/trash dumping, WAITING ON COMMISSARY
NYP	2113	07/22	9	9	Restrictive signal(s) from unknown cause, N/A, Other, NYP, LOST RADIO COMMUNICATION AT PSCC
NYP	2127	07/22	1	1	Passenger and/or baggage
NYP	2190	07/22	2	2	Unrecoverable penalty (PCS), 2038 LH LP, LOSS OF POWER WITH HEADEND PC OIPERATING WITH ONLY REAR PC2016
PHL	151	07/22	4	4	Follow, 67, Control Point, .
PHL	601	07/22	1	1	Passenger and/or baggage
WAS	56	07/22	16	16	Water, commissary, toilet/trash dumping, LATE COMMISSARY
WAS	196	07/22	13	13	Other late crew, DOOR AND TRAP CLOSED BEFORE DP TIME. CREW DETRAINED ADA PAX TO MOVE THEM TO THE FRONT OF THE TRN. CS CALLED AT 610P FOR MOVE.
WAS	2124	07/22	107	107	Service, turn, or wye train, 2119, LATE TURN OF EQUIPMENT OFF OF 2119. 2119 AR @ 722P
CHI	41	07/22	218	218	Eng 124 bad ordered Eng 124 bad ordered, 78
CHI	59	07/22	3	3	Wheelchair Passenger unable to walk from wheelchair. Ramp needed

Amtrak Initial Terminal Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/22/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	301	07/22	28	28	Air / Brake / Wheel ID4019, PARKING BRAKE STUCK ON AND WOULD NOT RELEASE HAD TO RESET BREAKERS ALSO FOUND DAMAGED AUX HOSE B END WHICH HAD TO BE REPLACED
CHI	370	07/22	48	48	Set out defective car ID4313, In the yard
GBB	382	07/22	3	3	Late bulletins due to Amtrak cause Bulletins not populated.
BFD	703	07/22	1	1	Service, turn, or wye train 712, Blue flagged until 1750.
EMY	6	07/22	1	1	Copy authority / restriction Copied directive about Fire near tracks., Milepost, 10.0, 10.0
EUG	504	07/22	2	2	Passenger and/or baggage Station agent working alone, lots of checked bags arrived train side one minute before departure.
GTA	782	07/22	5	5	Meet 14, Control Point, S.Ellwood
LAX	2	07/22	4	4	Late arrival equipment from the yard due to a engine change last minute spot time in Los Angeles was 940. Baggage was not able to finish until our departure time. 344 was swapped and replaced from the 371, 344
LAX	4	07/22	9	9	Removal of passenger by police Police searched for passenger believed to be Deondre Morris 97A6FD. Found and removed w/ dogs brought to sniff his bags- police cleared us to go and we left
LAX	14	07/22	1	1	Passenger and/or baggage Red cap is delivering pax at time of departure.
LAX	564	07/22	32	10	Equipment swap at 8th street yard 564
LAX	564	07/22	32	22	Multiple trains in and out of la union station causing late departure metrolink, Other, laus
LAX	566	07/22	66	66	Set out defective car 6400, Last minute switching. Late release of equipment.
LAX	584	07/22	15	15	Service, turn, or wye train 579
LAX	588	07/22	42	42	Service, turn, or wye train 581
OKJ	522	07/22	2	3	Routine inspections Late dropping of blue flags and release of equipment by TASI Mechanical from Oakland Yard due to unspecified reasons.
OKJ	534	07/22	4	4	Meet We were ready to depart OKJ on time but had to wait for Amt 539 to arrive at OKJ, Amt 539, Control Point, N. Jack London
OKJ	536	07/22	1		
OKJ	716	07/22	(Trn Cxld)	63	Late Inbound
OKJ	718	07/22	114	114	Air / Brake Couldn't complete a class 2 properly or get PTC to initiate swap equipment with 715, C6962
PDX	502	07/22	15	15	Troubleshoot loss of HVAC system in car, crew initially discovered the system inoperable. 82744
SAC	523	07/22	2	2	Other electrical failure JPBX921
SAC	539	07/22	2	2	Blue flag issue with UPRR

Amtrak Initial Terminal Details

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/22/2026

Terminal	Train	Date	Late	Delay	Cause
SAC	541	07/22	20	20	Inspecting substantial oil leak C2001
SAC	551	07/22	(Trn Cxld)		Third Party Engine Failure
SAN	579	07/22	5	5	Late arrival of equipment on train 566. 566
SAN	581	07/22	110	110	Service, turn, or wye train 770, AMTK 770 very late arrival into SAN causing late equipment turn for AMTK 581
SAN	593	07/22	12	12	Service, turn, or wye train 782, Late arrival of equipment from train 782.
SAN	595	07/22	57	57	Service, turn, or wye train 584
SAN	777	07/22	1		
SAN	785	07/22	6	6	Late train equipment 572
SEA	11	07/22	3	3	Passenger claimed a man took photos of her daughter. Amtrak police notified and spoke with passenger. Officer told the passenger that it was not a crime and it's legal to take photos in public. Passenger was satisfied with the information and boarded.
SEA	503	07/22	10	10	PTC- IETMS incorrect consist
SJC	542	07/22	(Trn Cxld)		Third Party Engine Failure

Eastern Region

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	92.9	94.3	94.8	342	8
CDOT	95.0	96	84.2	92.4	20	1
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	89.04	92.08	88.6	356	39
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 20(22) West of Greenville, SC - Vehicle Strike

23JUL26: At approximately 2:12am-et, train 20(20) was operating with engines 201 and 369, eight coaches, and approximately 159 customers when it went into emergency approximately 12 miles west of Greenville, South Carolina, on the Norfolk Southern Greenville-Inman Subdivision at the Pendleton Street crossing. The emergency application occurred after the train struck a vehicle at milepost 495.9. Head End Power (HEP) remained active following the incident, and no injuries were reported among the crew or customers. Emergency Medical Services responded to the scene, and the incident was reported as non-fatal. The conductor walked the equipment to assess for any damage. At the time of the incident, weather conditions were approximately 78 degrees with mostly cloudy skies.

Train 20(22) engineer requested relief, and a recrew engineer was scheduled to go on duty out of Charlotte at 4:30 a.m. ET with an estimated arrival time of 6:30 a.m. Local authorities remained on scene and requested that the train be shoved backward to assist a tow truck in removing the vehicle, which had become lodged on the locomotive plow. A Norfolk Southern Trainmaster responded to the scene with an estimated arrival time of five minutes, while a Road Foreman was en route with an estimated arrival time of approximately two hours.

Once the vehicle was removed, Train 20(22) was released to proceed. An inspection determined that the locomotive sustained only minimal damage. The crew advanced the train to Greenville, where the current engineer was relieved by a Trainmaster. The Trainmaster then operated the train to Spartanburg, where a recrew engineer arriving from Charlottesville was scheduled to assume control of the train.

Train	Delay	Comment
20(22)	2'03"	

Train 97(21) Hollywood, FL - Calendar Day Inspection

23JUL26: Train 97(21), with engines 61/82, 10 coaches and 56 customers, was delayed departing Hollywood, FL, on CSX Miami subdivision, due to performing their daily calendar inspection. they were required to perform this inspection before midnight. They usually make it to Miami, FL before that inspection is due but they were operation over 5 hours late due to previous delays enroute.

Train	Delay	Comment
97(21)	1'04"	Wi-tronix estimate

Train 90(22) North of Richmond, VA - Freight Train Interference

22JUL26: Train 90(22) operating with engine 603, 8 coaches and 202 customers was delayed 36 miles north of Richmond, VA, on CSX Richmond Fredericksburg subdivision, due to following freight train CSX410 from milepost 449 to milepost 105.3. Once the freight cleared and a route was made available, train 90(22) was able to proceed at normal speed.

Train	Delay	Comment
90(22)	1'01"	

Train 137(22) - Engine Failure

22JUL26: Train 137(22) operating with engine 603, 8 coaches and 307 customers, was delayed departing Philadelphia, PA, on Amtrak PW Line, due to mechanical meeting the train to address an HVAC issue but the there was a brake issue due to an unrecoverable penalty on the engine. Mechanical was able to resolve and 137(22) was able to proceed.

Trains 2131(22) and 175(22) were both held at Philadelphia incase a passenger transfer became necessary. They both departed once 137(22) recovered.

Train	Delay	Comment
2131(22)	22"	
175(22)	7"	
137(22)	46"	

Train 52(22) - Trespasser Incident

22JUL26:

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

At approximately 7:03pm-et, train 52(22), operating with locomotives 352 and 364, 39 coaches, and approximately 385 customers, went into emergency south of Jacksonville, FL, on the CSX Sanford Subdivision after striking a vehicle. Weather conditions were partly sunny with temperatures around 91 degrees. HEP was temporarily lost but was restored shortly afterward. The crew reported that the lead locomotive had shut down following the impact and performed a walking inspection of the equipment. No injuries were reported to crew members or customers. The Engineer and Assistant Conductor requested relief, and the Road foreman was notified.

Following the inspection, the crew reported minor damage to the plow on the lead locomotive; however, the damage remained within compliance standards. The crew worked to restart the lead locomotive to clear faults that resulted from strike. Local police and fire department personnel responded to the scene, while the Assistant Superintendent and Road foreman traveled to assist. Authorities confirmed that the vehicle strike resulted in a fatality.

The train remained on hold while local authorities conducted their investigation. Police advised that an extended period would be required before the train could be released. APD was notified, and additional operating personnel were arranged, including a protect engineer from Jacksonville, and a full relief crew from Sanford and, to support continued operations once movement was authorized.

As the response continued, the ASO arrived on scene, and the medical examiner and coroner also responded. It was reported that specialized equipment was required to remove the body from the car before the investigation could be completed and the train released. Throughout the incident, no injuries were reported to crew members or customers, and railroad personnel continued coordinating with responding agencies to facilitate the safe recovery of the scene and the eventual movement of the train.

Train 52(22) was subsequently fully recreated and departed Jacksonville, resuming its route. Downline crew assignments were adjusted accordingly to support continued operations. Service recovery measures were implemented for customers aboard Train 52(22), including complimentary coffee, tea, water, and snack packs. Train 52(22) experienced additional delays due to loading issues on locomotive 364, and Train 40(22) was also delayed while holding behind Train 52(22). Despite the operational impacts, Train 52(22) resumed movement safely following completion of the investigation, equipment inspection, and crew replacement process.

NRC # 1468658

Damages:

Minor damage to plow

National Response Center Number: 1468658

Train	Delay	Comment
52(22)	27"	Loading Issues eng 364
40(22)	1'47"	
52(22)	4'35"	

Train 197(22) West of Trenton, NJ - Deer Strike

22JUL26: Train 197(22) operating with engine 655, 9 coaches and 519 customers, was delayed 3 miles west of Trenton, NJ, on Amtrak NYP Line, due to striking a deer. The crew inspected the equipment and found no exceptions. After a brake test they were able to proceed.

Train	Delay	Comment
197(22)	10"	

Train 68(22) Westport, NY - Police Related

22JUL26: Train 68(22) was delayed on the CPKC Canadian subdivision at Westport station due to a fare evader refusing to pay or leave the train held for the Police.

Train	Delay	Comment
68(22)	40"	

Train 97(22) New York, NY - Servicing

22JUL26: Train 97(22) with E/607 and 11 cars was delayed departing New York due to needing equipment off 98(21).

Train	Delay	Comment
97(22)	31"	

New York to Philadelphia Main Line - Power Loss/Signal

22JUL26: At 242P-ET, New York to Philadelphia main line had a signal power loss between MP 37.2/Adams and MP 48.7/CP Clark. At 249P-ET, Power Directors were still trouble shooting. The trouble desk was notified and C&S was enroute to place the locations on the backup system. As of 333P-ET, Power Director reported that ET was at the substation investigating the power loss. As of 407P-ET Signal power was restored at MP 48.7/CP Clark but the power remained out from MP 41.3/Midway to MP 37.2/Adams. As of 450P-ET, The signal power outage was from CP 39 to MP 41.3/Midway.

All signal power was reported restored at 5:30pm-et.

Train	Delay	Comment
2158(22)	37"	
19(22)	57"	
85(22)	36"	
97(22)	31"	
647(22)	1'11"	
93(22)	1'06"	
42(22)	25"	
94(22)	13"	
2119(22)	51"	Re-Crew ABE
173(22)	16"	
2123(22)	11"	
2160(22)	14"	
651(22)	09"	
2116(22)	15"	
184(22)	24"	
134(22)	48"	
649(22)	46"	
650(22)	50"	
2119(22)	59"	
2165(22)	28"	

Train 449(22) South of Worcester, MA - Freight Train Interference

22JUL26: Train 449(22) with E/108, E/106 and 3 cars was delayed on the CSX Boston QB MP 79.4 due to holding for a CSX work train to clear.

Train	Delay	Comment
449(22)	40"	

Train 55(22) Springfield, MA - Signal

22JUL26: Train 55(22) was delayed on the CSX Berkshire QB subdivision at MP 98.6 due to restricted signal for an unknown reason.

Train 41(20) Tampa, FL - Engine Failure

22JUL26: Train 41(20) with E/621, E/625 and 139 cars with 168 customers onboard was delayed at Tampa station due to having PTC Issues. The crew was speaking with CNOC PTC desk and able to get the PTC back up and running.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41 (20)	47"	

Train 97(21) South of Jacksonville, FL - M of W Work

22JUL26: Train 97(21) with E/61, E/82 and 10 cars was delayed on the CSX Jacksonville Terminal due to holding for the work authority and to be walked by signals at MP 642.0 and MP 642.5.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97 (21)	38"	

Train 137(22) Boston, MA - Servicing

22JUL26: Train 137(22) with E/603 and 8 cars with 264 customers onboard was delayed departing Boston due to removing the Geo cars.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
137 (22)	34"	

Train 97(21) South of Jacksonville, FL - Bridge No Power/Signal

22JUL26: Train 97(21) with E/61, E/82 and 10 cars with 270 customers onboard was delayed on the CSX Sanford A subdivision at MP 647.8 due to the Mc Girts bridge not having power. CSX Maintainer was enroute estimated to arrive by 150P-ET.

Service Recovery was initiated for customers with the coach given snack packs and bottled water and First Class customers being served scheduled lunch meal service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97 (21)	36"	

New York to Philadelphia main line - Bridge Strike

22JUL26: At 1248P-ET A vehicle struck the bridge at Kings HWY., MP 18.75, New York to Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 201P-ET, the bridge was inspected and released for normal service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
93 (22)	02"	
86 (22)	08"	

CSX Heat Orders - Weather

22JUL26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98 (22)	24"	
40 (22)	1'04"	

New York to Philadelphia Main Line - Bridge Strike

22JUL26: At 1003A-ET A 26-FOI-00621 00000008480 the "UNCLASSIFIED" C 6/7/2026 Philadelphia main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 1053A-ET, the bridge was inspected and released for normal service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
643 (22)	15"	
172 (22)	04"	
4 NJT's	02"-07"	

Train 426(22) New Haven, CT - Engine Failure

22JUL26: Train 426(22) with E/95, CC/9643 was delayed departing New Haven due to swapping equipment due to cab signal issues with the original equipment.

This also caused delayed to train 471(22) due to the late arrival of equipment. This also delayed train 470(22) due to short turning off late 471(22).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
426 (22)	39"	
471 (22)	27"	
470 (22)	05"	

Train 2154(22) and 2193(22) - Northeast Corridor - Acela Cancellations

22JUL26: Due to equipment availability, Acela Trains 2154(22) and 2193(22) have been cancelled in their entirety.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2154 (22)	Cancelled	
2193 (22)	Cancelled	

Maintenance of Way Highlights

16-FOI-006211

80090008480

"UNCLASSIFIED"

9/7/2025

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00621 00000008480 "UNCLASSIFIED" 8/7/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00621a 00000008480 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Train 718(22) Oakland, CA - Third Party Contractor Engine Failure

23JUL26: Train 718(22) CC/6962, was delayed departing Oakland, CA/ MP7.1 on the UPRR Niles Subdivision due to on going equipment issues. TASI worked troubleshooting but the train could not log on to PTC. In order to minimize the delay, the equipment was swapped to inbounds 715 equipment. Once all passengers were loaded, Train 718(22) departed Oakland, CA with E/C2013.

Train	Delay	Comment
718(22)	1'54"	

Train 716(22) Oakland, CA - Third Party Contractor Cab Car Failure

23JUL26: Train 716(22) was initially delayed departing Oakland, CA//MP7.1 on the UPRR Niles Subdivision, due to the notch selector indicator light not working properly on cab car CC/6962 and needing to change out the resistor. Due to the prolonged delay, Train 713(22) was terminated at Emeryville to turn for Train 716(22) instead, which was then originated at Emeryville. Passengers were accommodated on Train 536(22) between Oakland and Emeryville.

Train	Delay	Comment
716(22)	1'29"	Originated EMY
713(22)	Terminated EMY	

Train 41(22) West of Chicago, IL - Engine Failure

23JUL26: Train 41(22) was delayed departing initial terminal of Chicago IL Union station/MP0.0 due to engine 124 being bad ordered for a control breaker. Engine 78 was pulled off inbound train 6(20) to be added as a replacement for engine 124. Engine 78 service was completed at 843PM CT and was released to be added to train 41(22) consist. Train 41(22) make up was completed at 919PM CT and arrived to station at 940PM to board 173 passengers. Train 41(22) departed Chicago Union station at 1018PM CT.

Train	Delay	Comment
41(22)	3'38"	

Train 370(22) Chicago, IL - Car Failure

22JUL26: Train 370(22) was delayed departing Chicago IL Union station/MP0.0, due to married car pair with ID4313 and ID4114 being bad ordered for electrical issues. Cars ID 4010 and ID4007 were selected to replace the bad ordered cars and added to the consist in the yard. Train 370(22) was made up and released by the yard at 640PM CT. Train 370(22) arrived to the station at 746PM CT and began boarding 212 passengers. Train 370(22) departed Chicago IL station at 718PM CT.

Train	Delay	Comment
370(22)	48"	

Train 22(22) West of Mineola, TX - Police Related

22JUL26: Train 22(22) was delayed beginning at MP208.72, 18 miles west of Mineola TX station on the UPRR Mineola subdivision holding at a crossing to meet local police for an unruly passenger to be remove. Train 22(22) held for approximately one hour and twelve minutes without local police arriving on scene. UPRR Dispatch reached out to the local police at the next jurisdiction over and arranged a meet at a crossing. Train 22(22) advanced to the crossing at MP203.7 and was met by local police to have the passenger removed. Train 22(22) was back on the move at 721PM CT with the passenger removed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(22)	2'15"	

Train 316(22) West of Jefferson City, MO - Freight Train Interference

22JUL26: Train 316(22) was delayed beginning at MP140.5, 15.66 miles west of Jefferson City, MO station on the UPRR Sedalia subdivision due to UP Freight 1137 stalled ahead after losing a motor. Freight crew was unable to get the lost to stay running. UPRR freight 1137 shoved back to clear a route. Train 316(22) was back on the move east at 758PM CT after the route was clear.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
316(22)	55"	

Train 3(21) Supplemental Bus at Flagstaff, AZ - Car Failure

22JUL26: Train 3(21), E/39, E/25, was over capacity by 50 passengers after departing Albuquerque, NM due to car, due to coach C/34047 was reported with no working HVAC. One supplemental bus was secured and operated express Reno, NM to Los Angeles, CA.

WBS#: B.TR.100150.6927

Train 1(22) West of Houston, TX - Weather

22JUL26: Train 1(22) was delayed beginning at MP282.6, 84.8 miles west of Houston TX station on the UPRR Beaumont subdivision operating at reduced speeds due to heard orders. Train 1(22) was delayed by the heat orders until MP362.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(22)	40"	

Train 542(22)/551(22) Cancelled - Third Party Contractor Engine Failure

22JUL26: Train 542(22) was initially delayed departing San Jose, CA due to headend power issues on engine E/JPBX 921 . Unable to resolve, and no replacement equipment available, Train 542(22) was cancelled in entirety, passengers to Train 544(22) The turn of equipment Train 551(22) was also cancelled, with alternate bus transportation provided.

WBS#: B.TR.100150.6926

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
542(22)	Cancelled	
551(22)	Cancelled	w/Alt Transportation

Train 22(21) South of Chicago, IL - Freight Train Interference

22JUL26: Train 22(21) was delayed beginning at MP13.1, 91 miles south of Chicago IL station on the CN Joilet subdivision following CN freight train 8337. Train 22(21) was delayed until MP 2.9 and resumed operating track speed into Chicago Union station.

Train	Delay	Comment
22(21)	37"	

Train 1(22) West of Beaumont, TX - Freight Train Interference

22JUL26: Train 1(22) was delayed beginning at MP277, 3.2 miles west of Beaumont TX station on the UPRR Lafayette subdivision meeting CPKC 2467. Train 1(22) was delayed by the meet until MP280 after which they were able to resume operating at track speed.

Train	Delay	Comment
1(22)	34"	

Train 11(22) South of Portland, OR - Engine Failure

22JUL26: Train 11(22) E/313, E/503 and 9 cars, with 238 passengers onboard, was delayed south of Portland, OR at MP759.7 on the UPRR Brooklyn Subdivision due to trail engine E/503 shutdown and unable to load. Crew was able to continue to Salem, off the leading engine only, in order to further troubleshoot. Once at Salem, crew worked with CNOC mechanical to troubleshoot. The trail engine was able to briefly re-start however shutdown again. Crew was able to route the head end power through the lead engine and then proceeded south operating off the single lead engine.

Train	Delay	Comment
11(22)	26"	MP759.7
11(22)	32"	SLM

Train 6(20) West of Naperville, IL - M of W Work

22JUL26: Train 6(20) was delayed holding at MP95.4, 67.09 miles west of Naperville, IL station on the BNSF Mendota subdivision due to being routed to main track one because of a maintenance window on main track two. Train 6(20) held for Amtrak trains 3(22) and 5(22) to clear main track one and then routed from main track two to main track one.

Train	Delay	Comment
6(20)	41"	

Pacific Surfliner - NCTD San Diego Sub - Police Activity

22JUL26: NCTD reported a SWAT standoff on the San Diego subdivision between MP 232-233 placing a hold on all tracks. Several trains were delayed during this time until the hold on the tracks was released.

Train	Delay	Comment
572(22)	33"	
777(22)	1'11"	
770(22)	1'15"	
774(22)	02"	
579(22)	34"	

Train 8/28(21) East of Libby, MT - Freight Train Interference

22JUL26: Train 8/28(21) with 26 customers was delayed approximately 45 miles east of Libby, MT, on the BNSF Kootenai River Subdivision. The delay was caused by freight traffic congestion as Train 8/28(21) followed BNSF trains 7486 and 8139 near Rock Creek at MP 1276.4.

Train	Delay	Comment
8/28(21)	51"	

Train 22(22) North of Cleburne, TX - M of W Work

22JUL26: Train 22(22) was delayed on the BNSF Fort Worth subdivision between Cleburne/MP 317.5 and Crowley/MP 334.2 due to MOW overstay that caused freight train interference with 22(22) following BN 6644 between Joshua/MP 323.8 and Crowley/MP 317.5.

Train	Delay	Comment
22(22)	43"	

Train 20(22) South of Meridian, MS - Freight Train Interference

22JUL26: Train 20(22) with 71 customers was delayed on the NS NO&NE district 13 miles south of Meridian at Basic/MP 13.3 due to meeting 131-22

Train	Delay	Comment
20(22)	47"	

Train 774(22) Lompoc-Surf, CA - Signal

22JUL26: Train 774(22), carrying 84 customers, was delayed approximately 12 miles south of Lompoc-Surf, CA, on the UPRR Santa Barbara Subdivision. The delay occurred after the train encountered a series of restrictive signals for unknown reasons between MP 312 and MP 335, resulting in reduced operating speeds through the territory.

Train	Delay	Comment
774(22)	36"	

Train 564(22) Los Angeles, CA - Car Failure

22JUL26: Train 564(22), carrying 177 customers, experienced a departure delay from Los Angeles, CA, on the SCRRA River Subdivision due to damaged shock mount hardware on car 6400. To minimize the impact, Train 564(22) exchanged equipment with Train 566(22). Train 564(22) was spotted at the station at 7:14 a.m. and was ready for departure by 7:30 a.m. However, because of the initial delay, several Metrolink trains were dispatched ahead of Train 564(22), resulting in additional departure delays.

Train	Delay	Comment
564(22)	10"	Late set in station
564(22)	34"	following Metrolink
566(22)	1'06"	

Train 318(22) East of Lees Summit, MO - Freight Train Interference

22JUL26: Train 318(22) was delayed on the UPRR Sedalia subdivision 17 miles east of Lees Summit at Strasburg/MP 242.8 due to meeting MASHN-21, who had a broken knuckle.

Train	Delay	Comment
318(22)	31"	

Train 14(21) North of Redding, CA - Freight Train Interference

22JUL26: Train 14(21), 26-FOID00621, 00000008480, UNCLASSIFIED, 8/7/2026, approximately 11 miles north of Redding, CA, on the UPRR Valley Subdivision due to freight traffic interference. The delay occurred when Train 14(21) met UP7272 and UP8018 between Gray Rocks Siding and Sims Siding.

Train	Delay	Comment
14(21)	33"	

Train 365(22) West of Lapeer, MI - Freight Train Interference

22JUL26: Train 365(22) with 37 customers was delayed on the CN Flint subdivision two miles west of Lapeer at West Lapeer/MP 287.0 due to CN 3150 blocking the main line ahead and waiting for a relief crew. Once the crew arrived and briefed, CN 3150 cleared the main, and 365(22) continued to Flint.

Train	Delay	Comment
365(22)	1'00"	

Train 301(22) Chicago, IL - Car Failure

22JUL26: Train 301(22) with E/ID4627, five cars, and 119 customers was delayed departing Chicago due to parking brake issues on C/ID4019. Mechanical and technicians arrived to the station, repaired a loose auxiliary hose, and 301(22) departed Chicago at 743AM-CT, 28 minutes late. The crew stopped again four miles south of Summit on the CN Joliet subdivision at MP 15.8 with the same issue. A mechanical rider alighted train 300(22) and assisted train 301(22) at MP 21.9. The mechanical QMP advised there was damage to the auxiliary hose on the B-end. As a result, the parking brake was cut out on C/ID4019 as well as one truck on the B-end. For this reason, the crew continued to St. Louis operating freight speed. Train 306(22) was delayed for the same reason and operated freight speeds between St. Louis and Chicago.

Train	Delay	Comment
301(22)	28"	CHI
301(22)	1'26"	S/SMT
300(22)	28"	
301(22)	1'05"	Operating freight speed
306(22)	1'48"	Operating with freight

Tropical Storm Bertha New Orleans, LA - Weather

20JUL26: Heavy rain from Tropical Storm Bertha expanded from Florida northward towards southeast Georgia and continued west along the coast into southern Louisiana and eastern Texas. The heaviest rain was projected to fall along the coast of Florida and into southeast Louisiana and eastern Texas at four to eight inches. As a result, train 19(20) terminated at Atlanta with alternate bus transportation. Train 20(21) originated at Atlanta with alternate bus transportation. Trains 19(21-22) would terminate at Atlanta and 20(22-23) would originate at Atlanta with customer service working to source alternate bus transportation. Trains 25(21-22) and 26(21-22) were cancelled entirely with no alternate transportation. Trains 23(22) and 24(22) were cancelled entirely with no alternate transportation.

21JUL26: Due to changes in the pattern of Tropical Storm Bertha with postponed closures of some flood gates. As a result, trains 19(21-22) and 20(22-23) operated as normal.

22JUL26: Due to the changes in the pattern of Tropical Storm Bertha with postponed closures of some flood gates. As a result, trains 25(22) and 26(22) operated as normal.

BNSF Mendota Subdivision East of Mendota, IL - Loss of Shunt

20JUL26: BNSF advised that train 381(20) with E/ID4602, four cars, and 84 customers failed to activate crossings on the Mendota subdivision 11 miles east of Mendota at MP 72.18 and MP 72.05, which led to a loss of shunt. Additionally, train 380(20) with E/ID4602, four cars, and 153 customers was said to have experienced a loss of shunt between Earlville/MP 72.5 and Somonauk/MP 59.6 on the Mendota subdivision. As a result, it was necessary for these trains to stop and protect the crossings. Train 381(20) equipment was inspected by BNSF at Galesburg and train 380(20) equipment was inspected by Amtrak mechanical in Chicago. Train 6(18) was also required to stop and protect the crossings between MP 72.5 and MP 59.6 as a precaution.

BNSF signal personnel and a track inspector responded to the scene for an investigation. BNSF personnel found no exceptions to contamination or track circuits. All Amtrak trains operating on main track 1 were required to protect the crossings between Earlville/MP 72.5 and Somonauk/MP 59.6 until further notice. BNSF had trains 4(18) and 383(20) operate not exceeding 30mph through Earlville and Somonauk with flaggers in place to perform testing. These crews were not required to stop and protect account of the flaggers in place.

Train 382(20), with 53 customers onboard, was delayed at Earlville meeting BNSF freights BN/6400 and BN/4149 before crossing over to main track two and operating through the area.

21JUL26: BNSF advised that flagger teams would be in position at the two crossing locations in question to test train 381(21) and 380(21). The two crossings in question are Main Street/MP 72.22 and East Street/MP 72.07. A 30mph speed restriction was in place between Earlville and Somonauk for this reason. A 30mph speed restriction remained on main track 1 between Somonauk and Earlville with no box 2 protection required until the BNSF signal department was able to finish their investigation.

Train	Delay	Comment
381(20)	06"	
380(20)	1'43"	
383(20)	46"	
4(18)	35"	
382(20)	1'00"	
380(21)	18"	
381(21)	20"	
3(21)	04"	

Palm Springs, CA Closure - High Winds

13JAN25: Palm Springs Station located on WBS 562.2 of the Union Pacific Railway Yuma Subdivision, is subject to temporary intermittent closures caused from high winds creating a build up of sand in the switches to enter Garnet Siding. This sand build up prevents the switches from being lined, and causes the internal gear mechanism of the switch to cease up. This prevents train crews from hand lining the switch and being able to access the station platform. Standing policy states that when this occurs trains will bypass the station at Palm Springs and passengers will be transported to the next stop of Ontario, CA or Yuma, AZ, no alternate transportation will be provided.

Work Element WBS Number # B.TR.100150.5622

WBS#: B.TR.100150.5622

Train	Delay	Comment
1 (15NOV) / 421 (14NOV)	Bypass PSN	
1 (18-21FEB) / 421 (17-20FEB)	BYPASS - Palm Springs	Flooding
2/422 (18, 20, 22FEB)	Bypass Palm Springs	Flooding
1 (30) / 421 (29) (MAR)	Bypass PSN	
1 (01APR) / 421 (31MAR)	Bypass PSN	
1 (04APR) / 421 (03APR)	Bypass PSN	
1 (23, 31DEC) 421 (23, 30DEC)	Bypass PSN	Local Roads Flooded - no station access
2/422 (24DEC)	Bypass PSN - Flooding	
1 (03, 05JAN) / 421 (02, 04JAN)	BYPASS PSN - flooding	
2/422 (04, 07JAN)	BYPASS PSN - flooding	
2/422 (01, 03, 05APR)	Bypass PSN	
1 (06, 13, 18, 20, 23MAY) 421 (05, 12, 17, 19, 22MAY)	Bypass PSN	
2/422 (13, 15, 20, 24MAY)	Bypass PSN	
2/422 (17, 21, 26, 28JUN)	Bypass PSN	
1 (08, 15, 17, 20, 22, 24, 27JUN) 421 (07, 14, 16, 19, 21, 23, 26, 30JUN)	Bypass PSN	
2/422 (01, 03, 05, 07, 10JUL)	BYPASS PSN	
1 (01, 04, 08JUL) / 421 (03, 07JUL)	BYPASS PSN	
1 (18, 20JUL) / 421 (17, 19JUL)	Bypass	
2/422 (19, 22 JUL)	Bypass	

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26-FBI-00022 00000008480 "UNCLASSIFIED" 8/7/2023

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.

- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.

- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work

15JUL26:

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

- Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

- Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

BNSF Track Work West of Macomb, IL - Carl Sandburg Service TWA 26-073

29JUN26: BNSF tie gangs will perform work on the Brookfield Subdivision between Macomb, IL/MP202.3 and Colchester/MP210.7, Monday July 6th through Friday July 10th and Monday July 13th through Friday July 17th.

14JUL26: Track was extended one additional week, Monday July 20th through Friday July 24th.

To accommodate this infrastructure work, Amtrak's Carl Sandburg service adjusted as follows:

- Train 382(06JUL-10JUL), Train 382(13JUL-17JUL) and Train 382(20JUL-24JUL) will originate at Galesburg, IL, with Bus 3382 as alternate transportation between Quincy, IL and Galesburg. Bus 3382 will operate 1-hour earlier departing Quincy at 430PM-CT and Macomb at 519PM-CT.

- Train 381(06JUL-10JUL), Train 381(13JUL-17JUL) and Train 381(20JUL-24JUL) will terminate at Galesburg, IL, with Bus 3381 as alternate transportation between Galesburg and Quincy.

CPKC River Subdivision - Scheduled M/W Work 26-067

22JUN26: CPKC has tie 26-FOI-00621 00000008480 and "UNCLASSIFIED" 8/7/2026 scheduled on the River Subdivision between St. Paul, MN and La Crosse, WI starting Monday, June 22nd through Sunday, September 20th. To accommodate the outlined infrastructure work, Amtrak's Borealis Service has been adjusted as follows:

- Train 1333(22JUN-20SEP) will arrive to St. Paul 20 minutes later at 7:01PM.
 - Train 1340(22JUN-20SEP) will depart St. Paul 20 minutes earlier at 11:29AM, will depart Red Wing 10 minutes earlier at 12:27PM, and return to normal schedule departing Winona.
- WBS Element B.TR.100150.6620 has been issued.

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Western Region

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
40 (20)	ABQ	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
4 (20)	WLO	BNSF5326	E/76 MU issues	CHI	

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00621

00000008480

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
3 (21)	ABQ	(0311) BYD HVAC enroute. Please accommodate ALL passengers who are affected.			34047
371 (23)	CHI	Train 370(22) and 371(23) will not have café service due to shopped cars id4313 and Id4114. They were replaced by cars Id4010 and ID4007.	Passenger notified	133	ID4113, ID114
370 (22)	CHI	Train 370(22) and 371(23) will not have café service due to shopped cars id4313 and Id4114. They were replaced by cars Id4010 and ID4007.	Passengers notified	171	ID4313, ID4114
370 (22)	GRR	Train 370(22) and 371(23) will not have café service due to shopped cars id4313 and Id4114. They were replaced by cars Id4010 and ID4007.	Passengers notified	171	ID4313, ID4114
562 (22)	LAX	NO BIKE SPACE OR WIFI	None	0	90225
580 (22)	LAX	NO BIKE SPACE OR WIFI	none	0	90225
113 (22)	NYP	BIZ AS COACH			81514
193 (22)	NYP	193(22) will operate with a Business Class car in lieu of a coach.			81514
573 (22)	SAN	NO BIKE SPACE OR WIFI	NONE	0	90225
591 (22)	SAN	NO BIKE SPACE OR WIFI	none	0	90225
125 (22)	SPG	125(22) will operate with a club-dinette in lieu of a cafe car.			48174
84 (22)	WAS	84(22) will operate with a Business Class car in lieu of a coach.			81514

Reverse Consists

Train Number	Station	Reason
95 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
173 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front
181 (22)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00621	00000008480 "UNCLASSIFIED" 8/7/2026
190 (22)	PHL	Consist reversed Business class seat orientation may have changed At Front	
137 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front	
125 (22)	SPG	Consist reversed Business class seat orientation may have changed At Front	
86 (22)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (22)	BOS	Consist reversed Business class seat orientation may have changed At Front	
136 (22)	WAS	Consist reversed Business class seat orientation may have changed At Front	
171 (22)	BOS	Business class change only Business class seating orientation may have changed At Rear	
184 (22)	WAS	Consist reversed Business class seat orientation may have changed At Front	
86 (23)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (23)	BOS	Consist reversed Business class seat orientation may have changed At Front	
138 (23)	NFK	Consist reversed Business class seat orientation may have changed At Front	
94 (23)	NFK	Consist reversed Business class seat orientation may have changed At Front	