



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, September 25, 2026

Rules: 0-48



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/24/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	44	86.5%	7,501	1,018	86.4%	108,023	14,982	86.1%
Central Division	86.0%	57	1	98.2%	1,360	128	90.6%	20,555	1,903	90.7%
East Division	82.0%	178	26	85.4%	4,070	499	87.7%	56,890	8,629	84.8%
West Division	86.0%	92	17	81.5%	2,071	391	81.1%	30,578	4,450	85.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00774 00000008850 UNCLASSIFIED Endpoint Arrival Dates through 9/24/26 10/5/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	106,047	24,948	76%	2,440,163	616,152	75%	36,031,209	9,202,132	74%
Northeast Corridor	81%	50,916	10,153	80%	1,099,539	198,025	82%	15,814,438	3,785,307	76%
Acela	83%	14,015	3,478	75%	261,501	41,182	84%	3,224,127	800,322	75%
Northeast Regional	79%	36,901	6,675	82%	838,038	156,843	81%	12,590,311	2,984,985	76%
Richmond / Newport News / Norfolk	77%	9,352	3,071	67%	238,703	61,111	74%	3,761,502	1,108,410	71%
Springfield Shuttles	89%	797	244	69%	17,369	3,327	81%	223,771	36,465	84%
Roanoke	79%	3,676	344	91%	83,435	11,662	86%	1,197,238	261,356	78%
On Spine Northeast Regional	80%	23,076	3,016	87%	498,531	80,743	84%	7,407,800	1,578,754	79%
State Supported	80%	44,999	9,459	79%	1,061,539	277,606	74%	15,850,133	3,488,880	78%
Borealis	80%	570	426	25%	13,899	2,897	79%	201,888	43,368	79%
Capitol Corridor	90%	4,360	444	90%	94,461	13,409	86%	1,323,965	177,455	87%
Carolinian	70%	1,130	350	69%	27,790	8,404	70%	405,118	156,554	61%
Cascades	75%	2,164	1,090	50%	62,674	17,765	72%	913,310	258,419	72%
Downeaster	82%	1,715	60	97%	41,422	2,023	95%	561,402	63,868	89%
Empire	78%	5,803	1,332	77%	141,266	33,351	76%	1,983,070	488,313	75%
Adirondack	72%	379	173	54%	8,459	1,993	76%	122,554	38,946	68%
Ethan Allen Express	70%	530	34	94%	12,968	4,761	63%	199,870	77,037	61%
Maple Leaf	70%	849	365	57%	19,817	6,597	67%	248,129	96,476	61%
New York - Albany	85%	2,737	186	93%	64,526	10,254	84%	913,793	158,743	83%
New York - Niagara Falls	75%	1,308	574	56%	33,245	8,950	73%	483,637	109,459	77%
Berkshire Flyer	60%	0	0	-	2,251	796	65%	15,087	7,652	49%
Gold Runner	73%	1,915	1,425	26%	58,547	35,438	39%	888,269	344,197	61%
Heartland Flyer	70%	173	170	2%	4,482	2,971	34%	76,039	33,156	56%
Hiawatha	90%	1,796	0	100%	43,308	3,045	93%	627,085	66,892	89%
Illinois	78%	2,231	560	75%	59,535	24,680	59%	887,892	257,314	71%
Carl Sandburg / Illinois Zephyr	85%	418	106	75%	9,731	3,223	67%	147,477	42,557	71%
Illini / Saluki	85%	634	0	100%	21,073	9,675	54%	307,085	81,152	74%
Lincoln Service	70%	1,179	454	61%	28,731	11,782	59%	433,330	133,605	69%
Keystone	92%	9,960	275	97%	207,144	19,824	90%	2,721,035	276,076	90%
Lincoln / Missouri	70%	768	536	30%	17,578	12,881	27%	275,189	148,338	46%
Mardi Gras Service	80%	277	164	41%	7,707	1,507	80%	141,659	31,492	78%
Michigan	70%	2,104	515	76%	49,742	19,690	60%	723,020	245,240	66%
Blue Water	70%	717	337	53%	12,289	4,567	63%	170,914	69,711	59%
Pere Marquette	85%	325	0	100%	6,647	1,281	81%	93,128	17,634	81%
Wolverine	70%	1,062	178	83%	30,806	13,842	55%	458,978	157,895	66%
Missouri	80%	186	163	12%	5,583	3,335	40%	78,943	24,600	69%
Pacific Surfliner	85%	7,003	1,146	84%	156,251	58,517	63%	2,883,097	577,090	80%
Pennsylvanian	80%	885	8	99%	20,987	3,937	81%	313,540	59,768	81%
Piedmont	80%	632	145	77%	21,974	5,298	76%	392,902	99,899	75%
Vermont	75%	1,327	650	51%	27,189	8,634	68%	452,710	136,841	70%
Long Distance	70%	10,132	5,336	47%	279,085	140,521	50%	4,327,371	1,925,482	56%
Auto Train	70%	623	365	41%	14,937	6,294	58%	275,008	95,035	65%
California Zephyr	70%	830	464	44%	22,539	10,091	55%	343,874	136,270	60%
Cardinal	70%	237	68	71%	5,184	3,202	38%	82,200	42,453	48%
City Of New Orleans	75%	545	453	17%	14,168	12,403	12%	223,820	84,868	62%
Coast Starlight	70%	957	532	44%	25,116	8,221	67%	402,370	142,863	64%
Crescent	70%	769	200	74%	21,318	4,450	79%	326,715	98,920	70%
Empire Builder	70%	955	863	10%	26,476	14,338	46%	346,032	175,088	49%
Floridian	60%	1,254	504	60%	35,063	24,048	31%	554,969	384,054	31%
Lake Shore Ltd	73%	926	501	46%	24,328	10,062	59%	346,009	107,905	69%
Palmetto	70%	717	3	100%	19,251	6,739	65%	322,432	101,537	69%
Silver Meteor	70%	736	353	52%	21,166	10,680	50%	355,576	166,084	53%
Southwest Chief	60%	778	518	33%	20,424	13,426	34%	297,679	197,021	34%
Sunset Ltd	70%	0	0	-	5,941	2,051	65%	101,645	40,550	60%
Texas Eagle	70%	805	512	36%	23,174	14,516	37%	349,042	152,834	56%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20 FOI-00774 000000000000 "UNCLASSIFIED" 10/5/2020

Train Index Dates Through September 24, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	149,584	2,593,721	577	2,149,402	37,867,887	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	6,320	785,851	80	102,759	10,993,286	93
INFRASTRUCTURE PLANNED	135	13,174	785,851	168	128,720	10,993,286	117
FLEET RELIABILITY	90	24,593	2,593,721	95	344,138	37,867,887	91
TRAIN OPERATIONS	424	105,497	2,593,721	407	1,573,785	37,867,887	416

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/24/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	44	86.5%	7,501	1,018	86.4%	108,023	14,982	86.1%
Central Division	86.0%	57	1	98.2%	1,360	128	90.6%	20,555	1,903	90.7%
East Division	82.0%	178	26	85.4%	4,070	499	87.7%	56,890	8,629	84.8%
West Division	86.0%	92	17	81.5%	2,071	391	81.1%	30,578	4,450	85.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/24/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	44	86.5%	7,501	1,018	86.4%	108,023	14,982	86.1%
Central Division	86.0%	57	1	98.2%	1,360	128	90.6%	20,555	1,903	90.7%
CDL	95.0%	2	0	100.0%	47	5	89.4%	683	36	94.7%
CHI	86.0%	27	1	96.3%	635	86	86.5%	9,505	1,186	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	24	2	91.7%	382	40	89.5%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	22	0	100.0%	336	11	96.7%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	48	2	95.8%	696	56	92.0%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	141	5	96.5%	2,100	131	93.8%
MOE	97.5%	2	0	100.0%	48	1	97.9%	715	10	98.6%
MSP	96.5%	1	0	100.0%	24	1	95.8%	352	8	97.7%
NOL	94.5%	4	0	100.0%	103	2	98.1%	1,513	66	95.6%
OKC	97.0%	1	0	100.0%	23	0	100.0%	352	6	98.3%
PNT	88.0%	2	0	100.0%	56	3	94.6%	932	76	91.8%
PTH	93.0%	1	0	100.0%	24	2	91.7%	347	15	95.7%
QCY	91.0%	2	0	100.0%	45	1	97.8%	676	49	92.8%
SAS	90.5%	1	0	100.0%	24	3	87.5%	356	42	88.2%
STL	89.0%	4	0	100.0%	91	10	89.0%	1,387	116	91.6%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	178	26	85.4%	4,070	499	87.7%	56,890	8,629	84.8%
ALB	88.5%	8	0	100.0%	188	18	90.4%	2,672	206	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	2	60.0%	120	4	96.7%	1,741	179	89.7%
BOS	85.5%	19	2	89.5%	407	37	90.9%	6,112	677	88.9%
BRK	92.5%	5	0	100.0%	120	6	95.0%	1,715	118	93.1%
BTN	82.0%	1	1	0.0%	24	5	79.2%	343	47	86.3%
CLT	91.5%	4	0	100.0%	106	11	89.6%	1,737	178	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	46	3	93.5%	694	63	90.9%
GRO	-	1	0	100.0%	14	5	64.3%	64	16	75.0%
HAR	79.5%	13	1	92.3%	270	24	91.1%	3,977	618	84.5%
HFD	-	2	1	50.0%	34	2	94.1%	266	19	92.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	24	2	91.7%	355	42	88.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/24/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/24/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	44	86.5%	7,501	1,018	86.4%	108,023	14,982	86.1%
East Division	82.0%	178	26	85.4%	4,070	499	87.7%	56,890	8,629	84.8%
MIA	89.5%	2	0	100.0%	48	7	85.4%	706	83	88.2%
MTR	79.0%	1	0	100.0%	23	2	91.3%	341	60	82.4%
NFK	84.5%	2	0	100.0%	48	4	91.7%	793	140	82.3%
NFL	93.5%	2	1	50.0%	48	3	93.8%	722	34	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	127	31	75.6%	1,829	318	82.6%
NPN	93.0%	2	0	100.0%	48	3	93.8%	682	54	92.1%
NYP	75.5%	51	6	88.2%	1,177	180	84.7%	15,106	3,237	78.6%
PGH	93.0%	1	0	100.0%	24	1	95.8%	356	24	93.3%
PHL	48.0%	5	3	40.0%	114	49	57.0%	1,809	848	53.1%
PIT	76.0%	-	-	-	4	3	25.0%	28	22	21.4%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	1	50.0%	68	6	91.2%	1,332	60	95.5%
RNK	83.5%	2	1	50.0%	48	3	93.8%	706	96	86.4%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	21	0	100.0%	335	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	24	1	95.8%	352	13	96.3%
SFA	88.0%	1	0	100.0%	24	4	83.3%	355	51	85.6%
SPG	92.5%	5	0	100.0%	126	12	90.5%	2,088	125	94.0%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	1	0.0%	24	5	79.2%	344	68	80.2%
WAS	84.0%	33	5	84.8%	721	68	90.6%	9,090	1,142	87.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	92	17	81.5%	2,071	391	81.1%	30,578	4,450	85.4%
ARN	92.0%	1	0	100.0%	24	2	91.7%	357	30	91.6%
BFD	79.0%	7	2	71.4%	164	53	67.7%	2,277	501	78.0%
EMY	72.0%	1	1	0.0%	28	9	67.9%	377	109	71.1%
EUG	86.5%	2	0	100.0%	48	4	91.7%	708	63	91.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	65	20	69.2%	1,066	192	82.0%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	10	1	90.0%	225	31	86.2%	3,545	400	88.7%
MCD	-	-	-	-	1	1	0.0%	16	14	12.5%
OKJ	74.5%	13	4	69.2%	283	108	61.8%	3,902	1,061	72.8%
PDX	86.0%	5	0	100.0%	119	12	89.9%	1,724	237	86.3%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/24/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/24/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	327	44	86.5%	7,501	1,018	86.4%	108,023	14,982	86.1%
West Division	86.0%	92	17	81.5%	2,071	391	81.1%	30,578	4,450	85.4%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	2	87.5%	355	43	87.9%	5,074	563	88.9%
SAN	90.5%	13	3	76.9%	246	39	84.1%	4,283	431	89.9%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	1	87.5%	189	33	82.5%	2,742	413	84.9%
SJC	89.0%	7	2	71.4%	168	23	86.3%	2,508	252	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	63	5	92.1%	828	82	90.1%
SNA	-	-	-	-	1	0	100.0%	1	0	100.0%
SNC	-	-	-	-	7	1	85.7%	38	14	63.2%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	24	1	95.8%	336	30	91.1%
VAC	97.0%	2	0	100.0%	48	2	95.8%	701	16	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%
VNC	-	-	-	-	10	2	80.0%	10	2	80.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		24	11	54.2%	357	77	78.4%	24	7	70.8%	354	164	53.7%
4	60	24	6	75.0%	356	59	83.4%	24	12	50.0%	356	233	34.6%
5	85	24	5	79.2%	355	62	82.5%	24	9	62.5%	351	120	65.8%
6		24	8	66.7%	354	99	72.0%	24	10	58.3%	354	135	61.9%
7	125	24	2	91.7%	346	53	84.7%	24	5	79.2%	337	91	73.0%
8	149	24	8	66.7%	346	153	55.8%	24	16	33.3%	345	214	38.0%
11		24	5	79.2%	357	77	78.4%	24	4	83.3%	351	71	79.8%
14	100	24	9	62.5%	358	63	82.4%	24	5	79.2%	355	110	69.0%
19		24	3	87.5%	356	86	75.8%	24	6	75.0%	353	88	75.1%
20		24	0	100.0%	356	23	93.5%	24	1	95.8%	356	66	81.5%
21		24	1	95.8%	353	37	89.5%	24	10	58.3%	352	109	69.0%
22	67	24	3	87.5%	354	40	88.7%	24	17	29.2%	352	116	67.0%
23		24	1	95.8%	358	7	98.0%	24	6	75.0%	356	96	73.0%
24	146	24	0	100.0%	358	16	95.5%	24	5	79.2%	357	70	80.4%
25	42	24	0	100.0%	357	3	99.2%	24	4	83.3%	354	98	72.3%
26	21	24	1	95.8%	357	6	98.3%	24	4	83.3%	354	70	80.2%
27	144	24	4	83.3%	323	23	92.9%	24	8	66.7%	317	105	66.9%
28		24	2	91.7%	317	69	78.2%	24	6	75.0%	317	66	79.2%
40	34	24	5	79.2%	347	52	85.0%	24	11	54.2%	343	183	46.6%
41		24	15	37.5%	347	139	59.9%	24	19	20.8%	344	266	22.7%
42		24	1	95.8%	358	26	92.7%	24	4	83.3%	356	62	82.6%
43		24	1	95.8%	357	46	87.1%	24	7	70.8%	356	83	76.7%
48		24	2	91.7%	356	64	82.0%	24	7	70.8%	355	58	83.7%
49	44	24	7	70.8%	356	91	74.4%	24	8	66.7%	356	78	78.1%
51		10	3	70.0%	146	61	58.2%	10	4	60.0%	142	56	60.6%
52		24	4	83.3%	355	51	85.6%	24	5	79.2%	354	82	76.8%
53		24	2	91.7%	355	42	88.2%	24	11	54.2%	354	117	66.9%
55		17	1	94.1%	228	10	95.6%	17	2	88.2%	225	48	78.7%
56		17	1	94.1%	229	26	88.6%	17	7	58.8%	225	47	79.1%
58	87	22	1	95.5%	329	18	94.5%	22	22	0.0%	327	119	63.6%
59	49	22	10	54.5%	328	61	81.4%	21	19	9.5%	322	100	68.9%
63	34	24	6	75.0%	359	150	58.2%	24	24	0.0%	353	221	37.4%
64	25	24	5	79.2%	357	76	78.7%	24	13	45.8%	356	146	59.0%
66		24	1	95.8%	356	65	81.7%	22	3	86.4%	349	63	81.9%
67		17	3	82.4%	247	17	93.1%	17	3	82.4%	246	43	82.5%
68	19	24	2	91.7%	359	69	80.8%	24	7	70.8%	358	141	60.6%
69		24	8	66.7%	346	87	74.9%	23	4	82.6%	340	60	82.4%
71		24	1	95.8%	354	4	98.9%	23	3	87.0%	351	89	74.6%
72		24	3	87.5%	350	39	88.9%	23	3	87.0%	347	72	79.3%
75		24	6	75.0%	347	23	93.4%	24	7	70.8%	341	158	53.7%
76		24	1	95.8%	347	32	90.8%	23	9	60.9%	336	139	58.6%
77	21	24	3	87.5%	349	24	93.1%	24	8	66.7%	346	141	59.2%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		24	5	79.2%	353	34	90.4%	24	5	79.2%	350	80	77.1%
79		24	2	91.7%	356	61	82.9%	24	9	62.5%	354	121	65.8%
80	76	24	2	91.7%	356	39	89.0%	24	5	79.2%	353	76	78.5%
84		17	4	76.5%	219	23	89.5%	17	3	82.4%	215	51	76.3%
85	100	17	0	100.0%	230	18	92.2%	17	6	64.7%	230	80	65.2%
86		17	0	100.0%	230	16	93.0%	17	5	70.6%	229	126	45.0%
89		24	3	87.5%	354	81	77.1%	24	11	54.2%	352	108	69.3%
90		24	1	95.8%	354	13	96.3%	24	3	87.5%	353	63	82.2%
93	52	17	0	100.0%	229	21	90.8%	17	12	29.4%	228	67	70.6%
94	32	17	2	88.2%	260	63	75.8%	17	5	70.6%	258	94	63.6%
95		17	2	88.2%	229	8	96.5%	17	6	64.7%	229	88	61.6%
97		24	14	41.7%	356	231	35.1%	24	9	62.5%	354	129	63.6%
98		24	2	91.7%	356	30	91.6%	24	8	66.7%	354	131	63.0%
110		16	5	68.8%	225	115	48.9%	15	0	100.0%	221	22	90.0%
111		17	1	94.1%	220	38	82.7%	17	1	94.1%	218	23	89.4%
112		17	3	82.4%	220	23	89.5%	17	2	88.2%	219	22	90.0%
113		17	0	100.0%	151	33	78.1%	17	2	88.2%	150	18	88.0%
119		17	2	88.2%	217	51	76.5%	17	1	94.1%	215	27	87.4%
125		17	1	94.1%	230	13	94.3%	17	9	47.1%	230	93	59.6%
129	72	17	1	94.1%	229	51	77.7%	17	2	88.2%	229	32	86.0%
130		17	0	100.0%	220	20	90.9%	17	1	94.1%	218	17	92.2%
131		17	4	76.5%	222	61	72.5%	17	1	94.1%	222	40	82.0%
134		17	2	88.2%	230	34	85.2%	17	1	94.1%	229	43	81.2%
136		17	1	94.1%	230	28	87.8%	17	3	82.4%	228	31	86.4%
137		17	3	82.4%	227	39	82.8%	16	3	81.3%	226	65	71.2%
138	30	17	1	94.1%	230	44	80.9%	17	2	88.2%	229	40	82.5%
141		17	2	88.2%	229	6	97.4%	17	3	82.4%	228	40	82.5%
148		17	4	76.5%	229	26	88.6%	17	2	88.2%	227	42	81.5%
151	27	24	8	66.7%	355	113	68.2%	24	5	79.2%	354	104	70.6%
170		17	0	100.0%	225	12	94.7%	17	1	94.1%	224	31	86.2%
171		17	0	100.0%	230	11	95.2%	17	5	70.6%	230	93	59.6%
172		17	2	88.2%	229	21	90.8%	17	7	58.8%	227	76	66.5%
173	79	17	3	82.4%	222	28	87.4%	17	6	64.7%	221	90	59.3%
174		17	0	100.0%	230	23	90.0%	17	3	82.4%	230	55	76.1%
175		17	1	94.1%	230	24	89.6%	17	6	64.7%	230	76	67.0%
176		15	0	100.0%	220	17	92.3%	15	2	86.7%	217	28	87.1%
177		17	2	88.2%	230	30	87.0%	17	4	76.5%	230	52	77.4%
178		17	2	88.2%	230	30	87.0%	17	1	94.1%	228	37	83.8%
179		17	1	94.1%	230	26	88.7%	17	8	52.9%	229	84	63.3%
181		17	2	88.2%	226	66	70.8%	17	3	82.4%	223	20	91.0%
182		17	1	94.1%	220	32	85.5%	17	5	70.6%	218	28	87.2%
183		17	3	82.4%	229	65	71.6%	17	3	82.4%	226	47	79.2%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		17	1	94.1%	230	37	83.9%	17	1	94.1%	229	29	87.3%
185		17	5	70.6%	230	46	80.0%	17	1	94.1%	230	19	91.7%
186		17	2	88.2%	229	31	86.5%	17	3	82.4%	228	64	71.9%
190		17	11	35.3%	229	86	62.4%	17	1	94.1%	228	45	80.3%
192		17	2	88.2%	227	26	88.5%	17	0	100.0%	227	19	91.6%
193	33	17	2	88.2%	225	85	62.2%	17	9	47.1%	224	99	55.8%
196	69	17	3	82.4%	226	26	88.5%	17	1	94.1%	224	18	92.0%
197		17	3	82.4%	230	80	65.2%	17	9	47.1%	230	80	65.2%
198		17	2	88.2%	162	19	88.3%	17	4	76.5%	161	26	83.9%
230		24	0	100.0%	192	4	97.9%	24	2	91.7%	192	11	94.3%
232		24	2	91.7%	358	14	96.1%	23	2	91.3%	357	25	93.0%
233		20	4	80.0%	315	70	77.8%	20	5	75.0%	314	106	66.2%
234		24	1	95.8%	359	24	93.3%	24	0	100.0%	358	29	91.9%
235		24	4	83.3%	283	46	83.7%	24	3	87.5%	282	63	77.7%
236		24	3	87.5%	343	13	96.2%	24	1	95.8%	342	44	87.1%
237		24	7	70.8%	356	68	80.9%	24	7	70.8%	354	66	81.4%
238		23	1	95.7%	282	24	91.5%	23	2	91.3%	280	24	91.4%
239		24	4	83.3%	357	87	75.6%	24	1	95.8%	356	43	87.9%
240		24	2	91.7%	358	25	93.0%	24	2	91.7%	355	71	80.0%
241	31	24	7	70.8%	358	89	75.1%	23	7	69.6%	357	88	75.4%
243		24	3	87.5%	294	74	74.8%	24	3	87.5%	293	42	85.7%
244		20	4	80.0%	314	16	94.9%	20	9	55.0%	314	74	76.4%
245		24	2	91.7%	239	43	82.0%	24	1	95.8%	238	31	87.0%
280	47	24	1	95.8%	359	18	95.0%	24	4	83.3%	358	82	77.1%
281		24	1	95.8%	359	41	88.6%	24	6	75.0%	359	66	81.6%
283		24	5	79.2%	359	90	74.9%	24	8	66.7%	359	74	79.4%
284		24	2	91.7%	359	15	95.8%	24	7	70.8%	356	68	80.9%
290		24	5	79.2%	359	57	84.1%	24	9	62.5%	356	146	59.0%
291		24	5	79.2%	358	117	67.3%	24	5	79.2%	354	95	73.2%
300		21	4	81.0%	339	26	92.3%	20	6	70.0%	335	79	76.4%
301	34	23	1	95.7%	355	11	96.9%	23	8	65.2%	351	71	79.8%
302	22	23	3	87.0%	336	37	89.0%	23	14	39.1%	332	104	68.7%
305		23	3	87.0%	339	34	90.0%	22	11	50.0%	333	133	60.1%
306		23	1	95.7%	353	18	94.9%	23	7	69.6%	351	96	72.6%
307		23	2	91.3%	346	46	86.7%	23	8	65.2%	342	106	69.0%
311	21	24	2	91.7%	351	30	91.5%	24	16	33.3%	345	100	71.0%
316	26	24	2	91.7%	347	26	92.5%	24	16	33.3%	341	117	65.7%
318	107	24	0	100.0%	357	35	90.2%	24	20	16.7%	354	186	47.5%
319	22	24	1	95.8%	358	21	94.1%	24	21	12.5%	353	214	39.4%
329		18	1	94.4%	254	13	94.9%	18	1	94.4%	254	20	92.1%
330		21	1	95.2%	305	7	97.7%	21	1	95.2%	305	16	94.8%
331		24	3	87.5%	359	36	90.0%	24	2	91.7%	358	46	87.2%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		24	1	95.8%	358	20	94.4%	24	5	79.2%	358	51	85.8%
334		24	0	100.0%	359	11	96.9%	24	2	91.7%	357	45	87.4%
335		24	0	100.0%	359	35	90.3%	24	0	100.0%	356	55	84.6%
336		24	0	100.0%	358	10	97.2%	24	5	79.2%	356	34	90.4%
337		24	1	95.8%	359	22	93.9%	24	4	83.3%	355	51	85.6%
338		24	2	91.7%	359	56	84.4%	24	5	79.2%	356	109	69.4%
339		24	2	91.7%	359	56	84.4%	24	1	95.8%	359	59	83.6%
341		23	4	82.6%	343	55	84.0%	22	4	81.8%	336	57	83.0%
342		24	1	95.8%	359	27	92.5%	23	4	82.6%	356	65	81.7%
351		22	1	95.5%	339	30	91.2%	22	8	63.6%	337	100	70.3%
352	23	24	0	100.0%	325	24	92.6%	24	18	25.0%	319	111	65.2%
354		24	2	91.7%	340	39	88.5%	24	12	50.0%	332	128	61.4%
355		22	5	77.3%	345	42	87.8%	22	9	59.1%	336	128	61.9%
364		24	1	95.8%	348	74	78.7%	24	8	66.7%	342	128	62.6%
365	28	24	2	91.7%	347	15	95.7%	24	10	58.3%	344	134	61.0%
370		22	3	86.4%	343	42	87.8%	22	6	72.7%	330	81	75.5%
371		22	0	100.0%	336	11	96.7%	22	2	90.9%	332	32	90.4%
380		24	0	100.0%	340	30	91.2%	24	5	79.2%	339	77	77.3%
381		21	2	90.5%	352	17	95.2%	21	7	66.7%	349	78	77.7%
382	36	21	1	95.2%	351	31	91.2%	21	9	57.1%	349	125	64.2%
383		24	3	87.5%	345	30	91.3%	23	11	52.2%	341	149	56.3%
390		23	3	87.0%	339	27	92.0%	21	9	57.1%	335	95	71.6%
391		24	1	95.8%	341	15	95.6%	24	15	37.5%	336	103	69.3%
392	No OS	24	2	91.7%	354	13	96.3%	23	16	30.4%	348	119	65.8%
393		23	3	87.0%	357	22	93.8%	22	12	45.5%	352	116	67.0%
417		17	2	88.2%	238	49	79.4%	17	2	88.2%	229	27	88.2%
425		16	1	93.8%	240	8	96.7%	15	0	100.0%	238	7	97.1%
448		24	8	66.7%	283	57	79.9%	23	5	78.3%	278	94	66.2%
449		23	0	100.0%	279	34	87.8%	23	1	95.7%	279	46	83.5%
470	20	17	4	76.5%	253	44	82.6%	17	4	76.5%	247	31	87.4%
471		17	0	100.0%	242	14	94.2%	17	0	100.0%	242	6	97.5%
473		17	2	88.2%	249	17	93.2%	17	0	100.0%	246	10	95.9%
474		18	3	83.3%	246	69	72.0%	17	3	82.4%	230	74	67.8%
475		16	1	93.8%	245	9	96.3%	16	1	93.8%	245	17	93.1%
478		17	2	88.2%	241	38	84.2%	17	1	94.1%	239	29	87.9%
479	19	17	0	100.0%	248	36	85.5%	17	6	64.7%	246	42	82.9%
486		17	1	94.1%	252	36	85.7%	17	1	94.1%	246	62	74.8%
494	22	17	2	88.2%	255	49	80.8%	17	5	70.6%	247	69	72.1%
495	20	17	0	100.0%	236	4	98.3%	17	1	94.1%	234	4	98.3%
500		23	2	91.3%	332	18	94.6%	23	2	91.3%	329	38	88.4%
502		24	1	95.8%	341	20	94.1%	24	4	83.3%	337	65	80.7%
503	48	24	3	87.5%	355	43	87.9%	23	8	65.2%	347	110	68.3%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504	143	24	2	91.7%	359	22	93.9%	24	9	62.5%	357	108	69.7%
505		24	5	79.2%	351	48	86.3%	24	11	54.2%	346	102	70.5%
506	23	23	3	87.0%	353	59	83.3%	20	4	80.0%	342	55	83.9%
507		24	3	87.5%	359	52	85.5%	24	10	58.3%	359	125	65.2%
508	33	23	2	91.3%	353	45	87.3%	23	6	73.9%	349	87	75.1%
509	181	23	3	87.0%	339	18	94.7%	23	6	73.9%	339	77	77.3%
511	58	23	1	95.7%	334	26	92.2%	23	3	87.0%	333	56	83.2%
516	26	24	5	79.2%	350	40	88.6%	24	13	45.8%	349	159	54.4%
517	34	24	0	100.0%	359	8	97.8%	23	11	52.2%	354	161	54.5%
518		24	4	83.3%	359	50	86.1%	24	15	37.5%	357	247	30.8%
519		24	2	91.7%	350	11	96.9%	23	4	82.6%	347	76	78.1%
520		17	2	88.2%	211	31	85.3%	17	2	88.2%	206	13	93.7%
521	18	17	1	94.1%	249	8	96.8%	17	3	82.4%	248	34	86.3%
522		17	4	76.5%	249	47	81.1%	15	1	93.3%	244	25	89.8%
523		17	2	88.2%	249	11	95.6%	17	2	88.2%	248	28	88.7%
524		17	2	88.2%	248	19	92.3%	17	3	82.4%	245	30	87.8%
525		17	2	88.2%	246	18	92.7%	16	1	93.8%	241	16	93.4%
526	27	17	5	70.6%	223	46	79.4%	16	2	87.5%	219	20	90.9%
527		17	0	100.0%	249	10	96.0%	17	2	88.2%	247	42	83.0%
528		17	0	100.0%	249	19	92.4%	17	2	88.2%	248	34	86.3%
529		17	1	94.1%	249	14	94.4%	17	5	70.6%	248	70	71.8%
530	30	17	4	76.5%	203	22	89.2%	16	3	81.3%	202	41	79.7%
531	44	17	2	88.2%	223	16	92.8%	17	3	82.4%	223	16	92.8%
532		17	5	70.6%	249	62	75.1%	17	3	82.4%	247	38	84.6%
534		17	4	76.5%	208	32	84.6%	17	1	94.1%	205	18	91.2%
535	24	17	2	88.2%	235	28	88.1%	16	2	87.5%	229	30	86.9%
536		17	7	58.8%	249	71	71.5%	16	3	81.3%	244	44	82.0%
537		16	2	87.5%	217	26	88.0%	16	1	93.8%	211	26	87.7%
538		17	6	64.7%	249	32	87.1%	17	4	76.5%	248	50	79.8%
539	34	17	1	94.1%	203	29	85.7%	17	8	52.9%	203	90	55.7%
540		17	4	76.5%	248	48	80.6%	17	2	88.2%	238	23	90.3%
541		17	2	88.2%	248	27	89.1%	17	2	88.2%	241	43	82.2%
542		17	1	94.1%	248	26	89.5%	17	7	58.8%	245	48	80.4%
543		17	4	76.5%	249	32	87.1%	17	11	35.3%	249	84	66.3%
544		17	1	94.1%	247	23	90.7%	17	1	94.1%	243	23	90.5%
545		17	2	88.2%	249	22	91.2%	17	1	94.1%	246	30	87.8%
547		17	3	82.4%	249	50	79.9%	17	4	76.5%	249	58	76.7%
548		16	0	100.0%	240	22	90.8%	16	1	93.8%	237	18	92.4%
549		17	1	94.1%	244	28	88.5%	17	1	94.1%	234	21	91.0%
550		17	3	82.4%	203	23	88.7%	17	6	64.7%	203	50	75.4%
551		17	0	100.0%	245	23	90.6%	17	0	100.0%	235	23	90.2%
562		22	1	95.5%	348	28	92.0%	22	9	59.1%	343	46	86.6%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564		22	0	100.0%	349	19	94.6%	21	4	81.0%	340	47	86.2%
566		17	2	88.2%	342	31	90.9%	17	4	76.5%	339	58	82.9%
567		16	1	93.8%	228	12	94.7%	15	0	100.0%	225	14	93.8%
572		17	1	94.1%	339	28	91.7%	17	9	47.1%	331	104	68.6%
573		17	2	88.2%	341	46	86.5%	17	3	82.4%	333	61	81.7%
579		22	0	100.0%	234	14	94.0%	22	5	77.3%	227	50	78.0%
580		22	2	90.9%	349	20	94.3%	22	4	81.8%	342	41	88.0%
581		17	3	82.4%	344	61	82.3%	17	6	64.7%	341	81	76.2%
584	33	17	6	64.7%	228	38	83.3%	15	12	20.0%	219	144	34.2%
587	Cncld	17	2	88.2%	336	23	93.2%	16	7	56.3%	326	72	77.9%
588		17	1	94.1%	227	24	89.4%	16	3	81.3%	224	46	79.5%
591		22	3	86.4%	346	29	91.6%	21	6	71.4%	338	55	83.7%
593	Cncld	18	6	66.7%	335	59	82.4%	15	3	80.0%	309	44	85.8%
595	16	21	11	47.6%	341	71	79.2%	20	6	70.0%	337	79	76.6%
600		17	0	100.0%	257	9	96.5%	17	3	82.4%	255	25	90.2%
601		17	5	70.6%	240	95	60.4%	17	1	94.1%	237	28	88.2%
605		17	7	58.8%	247	146	40.9%	16	1	93.8%	242	24	90.1%
607		17	1	94.1%	256	31	87.9%	17	1	94.1%	253	26	89.7%
609		17	1	94.1%	247	24	90.3%	17	1	94.1%	246	24	90.2%
622		14	1	92.9%	151	36	76.2%	14	2	85.7%	148	7	95.3%
626		17	1	94.1%	161	21	87.0%	17	1	94.1%	159	19	88.1%
639		17	2	88.2%	227	42	81.5%	17	2	88.2%	225	22	90.2%
640		17	1	94.1%	247	8	96.8%	17	4	76.5%	245	88	64.1%
641		17	1	94.1%	229	44	80.8%	17	7	58.8%	229	34	85.2%
642		17	1	94.1%	245	12	95.1%	17	1	94.1%	244	28	88.5%
643	12	17	1	94.1%	259	45	82.6%	17	5	70.6%	256	44	82.8%
644		17	3	82.4%	251	31	87.6%	17	6	64.7%	249	62	75.1%
645		17	0	100.0%	259	42	83.8%	17	0	100.0%	256	55	78.5%
646	17	17	5	70.6%	248	61	75.4%	17	7	58.8%	246	120	51.2%
647		17	3	82.4%	259	38	85.3%	17	3	82.4%	257	54	79.0%
648		17	2	88.2%	255	61	76.1%	17	1	94.1%	255	36	85.9%
649		17	5	70.6%	260	49	81.2%	17	2	88.2%	256	36	85.9%
650		17	2	88.2%	259	47	81.9%	17	6	64.7%	256	45	82.4%
651		17	1	94.1%	259	18	93.1%	17	2	88.2%	256	45	82.4%
652		17	0	100.0%	260	31	88.1%	17	4	76.5%	256	45	82.4%
653		17	3	82.4%	248	39	84.3%	16	5	68.8%	243	46	81.1%
654		17	0	100.0%	249	44	82.3%	17	3	82.4%	245	23	90.6%
655		17	5	70.6%	257	79	69.3%	17	5	70.6%	254	81	68.1%
656		17	2	88.2%	259	56	78.4%	17	2	88.2%	257	35	86.4%
657	37	17	0	100.0%	248	29	88.3%	17	2	88.2%	246	32	87.0%
658		17	3	82.4%	259	40	84.6%	16	1	93.8%	256	36	85.9%
680		18	1	94.4%	255	13	94.9%	18	0	100.0%	253	27	89.3%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681		18	0	100.0%	255	18	92.9%	18	3	83.3%	248	96	61.3%
682		18	1	94.4%	254	10	96.1%	18	1	94.4%	254	43	83.1%
683		18	1	94.4%	237	19	92.0%	18	3	83.3%	236	78	66.9%
684		18	1	94.4%	236	38	83.9%	18	1	94.4%	236	48	79.7%
685		18	1	94.4%	251	34	86.5%	18	3	83.3%	248	58	76.6%
686		18	1	94.4%	256	40	84.4%	18	4	77.8%	255	56	78.0%
687		18	0	100.0%	255	38	85.1%	18	0	100.0%	254	40	84.3%
688	16	18	0	100.0%	254	15	94.1%	18	2	88.9%	253	43	83.0%
701	18	24	5	79.2%	291	35	88.0%	24	6	75.0%	288	38	86.8%
702	22	24	6	75.0%	358	42	88.3%	22	14	36.4%	353	97	72.5%
703	No OS	24	11	54.2%	359	123	65.7%	24	11	54.2%	357	111	68.9%
704	33	24	8	66.7%	290	57	80.3%	24	13	45.8%	282	72	74.5%
710		24	5	79.2%	359	84	76.6%	22	14	36.4%	353	102	71.1%
711		24	6	75.0%	350	44	87.4%	24	7	70.8%	327	72	78.0%
712		24	9	62.5%	356	100	71.9%	24	15	37.5%	346	129	62.7%
713	Cncld	22	6	72.7%	224	26	88.4%	14	10	28.6%	191	90	52.9%
714	82	24	17	29.2%	240	109	54.6%	22	18	18.2%	222	113	49.1%
715	64	24	4	83.3%	358	67	81.3%	20	15	25.0%	325	170	47.7%
716	153	24	19	20.8%	359	162	54.9%	23	20	13.0%	349	161	53.9%
717	31	23	11	52.2%	343	90	73.8%	22	15	31.8%	317	113	64.4%
718		24	19	20.8%	359	197	45.1%	22	14	36.4%	354	143	59.6%
719	52	24	11	54.2%	359	124	65.5%	23	12	47.8%	341	110	67.7%
757		20	0	100.0%	140	7	95.0%	20	2	90.0%	139	16	88.5%
761		22	2	90.9%	353	15	95.8%	22	5	77.3%	350	49	86.0%
765		22	4	81.8%	353	29	91.8%	22	10	54.5%	353	56	84.1%
769		22	2	90.9%	353	29	91.8%	22	13	40.9%	346	78	77.5%
770		22	4	81.8%	353	29	91.8%	22	11	50.0%	350	115	67.1%
774		22	0	100.0%	353	17	95.2%	22	10	54.5%	351	90	74.4%
777	55	22	2	90.9%	238	15	93.7%	22	18	18.2%	237	76	67.9%
782		22	14	36.4%	238	119	50.0%	22	7	68.2%	233	43	81.5%
785		22	3	86.4%	353	32	90.9%	22	11	50.0%	353	72	79.6%
786	Cncld	22	1	95.5%	142	24	83.1%	19	9	52.6%	135	75	44.4%
790		22	2	90.9%	353	33	90.7%	21	7	66.7%	349	61	82.5%
794		22	5	77.3%	353	45	87.3%	21	5	76.2%	348	81	76.7%
821	44	23	0	100.0%	352	6	98.3%	23	17	26.1%	352	157	55.4%
822	106	24	2	91.7%	355	20	94.4%	23	21	8.7%	352	191	45.7%
1333	27	24	3	87.5%	355	43	87.9%	24	10	58.3%	352	122	65.3%
1340	28	24	1	95.8%	354	8	97.7%	24	3	87.5%	353	59	83.3%
1689		11	0	100.0%	122	6	95.1%	11	0	100.0%	121	14	88.4%
2102		17	1	94.1%	106	17	84.0%	17	2	88.2%	105	9	91.4%
2103		17	0	100.0%	170	14	91.8%	17	4	76.5%	169	14	91.7%
2104		17	1	94.1%	196	11	94.4%	16	1	93.8%	193	14	92.7%

Amtrak On Time Performance

Trains Arriving Through: 9/24/2026

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2105		17	1	94.1%	18	2	88.9%	17	2	88.2%	18	2	88.9%
2107		16	2	87.5%	226	37	83.6%	16	1	93.8%	223	22	90.1%
2108		17	5	70.6%	227	33	85.5%	16	1	93.8%	220	28	87.3%
2109		17	3	82.4%	120	16	86.7%	17	2	88.2%	118	8	93.2%
2112		17	2	88.2%	67	8	88.1%	17	2	88.2%	65	4	93.8%
2113		16	2	87.5%	105	11	89.5%	16	2	87.5%	105	12	88.6%
2115		17	2	88.2%	106	15	85.8%	16	0	100.0%	104	12	88.5%
2116		17	1	94.1%	67	2	97.0%	17	0	100.0%	67	8	88.1%
2118		17	1	94.1%	67	5	92.5%	16	0	100.0%	66	12	81.8%
2119		16	2	87.5%	66	10	84.8%	16	2	87.5%	65	14	78.5%
2120	90	17	4	76.5%	67	23	65.7%	17	2	88.2%	65	25	61.5%
2123	94	17	5	70.6%	105	15	85.7%	17	4	76.5%	104	19	81.7%
2124	28	17	1	94.1%	198	39	80.3%	17	2	88.2%	196	26	86.7%
2126		17	3	82.4%	115	29	74.8%	17	0	100.0%	114	22	80.7%
2127		17	1	94.1%	67	11	83.6%	17	1	94.1%	66	10	84.8%
2128	37	17	2	88.2%	67	6	91.0%	17	1	94.1%	67	4	94.0%
2131		16	1	93.8%	66	11	83.3%	16	0	100.0%	66	6	90.9%
2150		17	1	94.1%	220	23	89.5%	17	1	94.1%	217	76	65.0%
2151	40	17	3	82.4%	169	10	94.1%	17	7	58.8%	167	48	71.3%
2152		17	1	94.1%	125	8	93.6%	17	1	94.1%	124	32	74.2%
2154		17	5	70.6%	128	28	78.1%	16	5	68.8%	123	50	59.3%
2155		17	0	100.0%	229	17	92.6%	16	1	93.8%	224	103	54.0%
2156		17	2	88.2%	18	2	88.9%	17	4	76.5%	18	4	77.8%
2158	26	17	2	88.2%	66	8	87.9%	17	4	76.5%	66	20	69.7%
2159	78	17	2	88.2%	222	18	91.9%	17	9	47.1%	220	78	64.5%
2160		17	1	94.1%	67	3	95.5%	17	4	76.5%	66	32	51.5%
2162		17	0	100.0%	228	23	89.9%	17	1	94.1%	222	92	58.6%
2163	22	17	2	88.2%	180	19	89.4%	17	13	23.5%	174	82	52.9%
2165	102	17	2	88.2%	64	6	90.6%	17	7	58.8%	64	28	56.3%
2167	58	17	1	94.1%	215	21	90.2%	17	5	70.6%	215	46	78.6%
2171		17	2	88.2%	156	12	92.3%	17	4	76.5%	152	27	82.2%
2190		17	5	70.6%	225	34	84.9%	16	0	100.0%	222	24	89.2%
2193		16	1	93.8%	219	27	87.7%	16	1	93.8%	217	51	76.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Region: ALL

Service: ALL

Arriving On: 9/24/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2120	NYP	90	POL	66	POL	54	BAL-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7
2123	WAS	94	POL	96	POL	84	XPV-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7, heavy congestion after fire department hold lifted
2124	NYP	28	POL	37	POL	24	BAL-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7
2128	NYP	37	ITI	44	ITI	44	WAS-WAS	AM	Late departure at initial terminal due to late arrival of inbound equipment, 2165, 2165 WAS BEHIND TRN 97 THAT WAS STOPPED NORTH OF BAL DUE TO FIRE.
2151	WAS	40	DSR	21	DSR	14	NHV-STM	MN	Per bulletin Milepost, 48.6, 40.4, 15, 2,4
2158	BOS	26	MTI	17	MTI	17	WAS-WAS	AM	Disabled train ahead, Other, SOUTH OF NHV, 2151 DELAYED ARRIVING DUE TO ISSUES RAISING PANTOGRAPH SOUTH OF NHV
2159	WAS	78	SVS	36	SVS	36	BOS-BOS	AM	Routine inspections, LATE FROM FOR INSPECTIONS
2163	WAS	22	DSR	11	DSR	6	NHV-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2
2165	WAS	102	POL	99	POL	99	XPV-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7, heavy congestion after fire department hold lifted
2167	WAS	58	POL	69	POL	69	XPV-BWI	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7, heavy congestion after fire department hold lifted
85	WAS	100	POL	107	POL	94	ABE-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7, heavy congestion after fire department hold lifted
93	NFK	52	CTI	59	CTI	14	ALX-QAN	CS	Follow VRE, 315, Milepost, 105.4, 78.9
94	BOS	32	FTI	54	FTI	50	QAN-ALX	CS	Follow M418 in emergency, M418, Milepost, 103.0, 105.2
129	WAS	72	POL	74	POL	43	WIL-WIL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7
138	NYP	30	POL	54	POL	19	BWI-BAL	AM	Fire department hold, heavy congestion after fire department hold lifted

Amtrak Endpoint OTP Details

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/24/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
151	RNK	27	OTH	19	CTI	11	BWI-XNY	AM	Follow, marc, 409, Control Point, .
173	WAS	79	POL	67	POL	67	XPV-BAL	AM	Fire department hold, heavy congestion after fire department hold lifted
193	WAS	33	CTI	23	CTI	9	BWI-NCR	AM	Follow, MARC, 455, Milepost, 106.3, 127
196	NYP	69	POL	68	POL	30	XNY-BWI	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7
470	HFD	20	SVS	15	SVS	15	NHV-NHV	AM	Planned set out / pick out of locomotives, cars or section of train, Late equipment swap @ motor storage
479	NHV	19	SMW	7	SMW	7	SPG-WNL	AM	Scheduled in track usage program, Milepost w/Letters, SPG, WNL, 30MPH S/r MP 48.5 - 49.2
494	GFD	22	CON	27	CON	27	NHV-NHV	AM	Hold for connecting train, late connection of AM94
495	NHV	20	DCS	5	DCS	5	SPG-WNL	AM	Issue with automatic road crossing protection, Other, bridge st, stop and protect
80	NYP	76	POL	80	POL	64	XNY-BAL	AM	Fire department hold, held for disposition a/c 97 disabled ahead with onboard fire at MP 85.7, heavy congestion after fire department hold lifted
643	HAR	12	CTC	10	CTC	8	PHL-PAO	AM	PTC - Stop Bypass Permission Required, Control Point, ., Stop Bypass Multiple times and code required
646	NYP	17	CTI	6	CTI	6	PAO-PHL	AM	Follow, Septa, 9518, Milepost, 19.9, 1.9
657	HAR	37	SVS	37	SVS	28	PHL-PHL	AM	Pick up equipment, E/624 ADDED ON TO TRAIN IN PHILA
688	BON	16	DCS	7	DCS	7	WOB-BON	MT	Restrictive signal(s) from known wayside signal failure Rule 241 permission to pass stop signal, Stop signal, Control Point, tower a
63	TWO	34	RTE	7	RTE	7	AMS-UCA	CS	Run via siding or slower track due to N.A.R. Siding, st johnsville
64	NYP	25	FTI	32	FTI	20	SYR-ROM	CS	Cross Traffic csx, Control Point, 283
68	NYP	19	FTI	47	FTI	47	SLQ-RSP	CN	Meet 323, Siding, Lacadie
241	ALB	31	CTI	8	CTI	5	NYP-XSD	AM	Cross Traffic, MNRR, MN, Other, XSD, HELD A/C MNRR TRAIN RTD AHD
280	NYP	47	FTI	55	FTI	33	SYR-ROM	CS	Meet 00923, Control Point, CP257

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Region: ALL

Service: ALL

Arriving On: 9/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
49	CHI	44	ENG	88	ENG	88	ALB-SDY	AM	Cab signal failure ACSES failure departing ALB reverse back into station where mechanical met train and discovered a unplugged connection they repaired the connection and we departed ALB, 99
77	CLT	21	DSR	16	DSR	13	BNC-GRO	NS	Per bulletin Milepost, 13.8, 9.9, 25, MT
40	CHI	34	DSR	57	TRS	34	PGH-ALC	NS	Trespasser strike Milepost, 18.1, 18.1
24	MOE	146	TRS	170	TRS	170	PAG-MOE	CS	Vehicle strike Fatal vehicle strike @ crossing 679.6 Waiting for release from local authorities., Milepost, 679.6, 679.6
25	NOL	42	FTI	78	FTI	78	BAS-XNO	CS	Meet CSX 520, Siding, Nicholson Ave
26	MOE	21	FTI	58	FTI	45	XNO-BAS	CS	Follow 520-24, Milepost w/Letters, 000777, Bay St Louis Station
5	EMY	85	DSR	96	PTI	77	XXP-WIP	UP	Meet Waiting on UP Passenger Special, UP 5896, Control Point, West East Portal
521	SJC	18	DSR	9	CTI	9	SCC-SJC	UP	Meet CALTRAIN, 106, Control Point, CP SHARK
526	SAC	27	MBO	39	MBO	39	MTZ-SUI	UP	For maritime traffic (2) ships., Control Point, Vista
530	SAC	30	MBO	20	MBO	20	MTZ-SUI	UP	For maritime traffic Control Point, vista
531	OKJ	44	MBO	41	MBO	41	SUI-MTZ	UP	For maritime traffic Bridge, Benicia
535	OKJ	24	FTI	21	FTI	21	MTZ-RIC	UP	Follow UP 2750, Milepost, 31.7, 27.5
539	SJC	34	MBO	23	MBO	23	SUI-MTZ	UP	For maritime traffic Control Point, Suisun bridge
503	EUG	48	PTI	34	FTI	25	ORC-SLM	UP	Meet Hold the main track(Gervais). Take the side track(Labish)., UP 2568, UP 8795, Siding, Gervais, Siding, Labish
504	SEA	143	FTI	127	FTI	95	ALY-SLM	UP	Blocked from station track Disabled freight setting out a car, unable to recover air., up8795, Siding, N. Renard
506	SEA	23	POL	26	POL	26	XA4-TUK	BN	Right of Way police hold Sounder trespasser incident, held at Sumner by dispatcher.
508	SEA	33	PTI	37	PTI	22	EUG-ALY	UP	Meet Take the side track., Amtrak 11, Siding, Shedd
509	PDX	181	POL	171	POL	171	TUK-XA4	BN	RR blocked by trespasser or vehicle strike by another train

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Region: ALL

Service: ALL

Arriving On: 9/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
511	PDX	58	TRS	53	TRS	53	TUK-TUK	BN	Trespasser strike Waited at Tukwila due to Sound Transit trespass strike at MP 17.6X, Milepost w/Letters, 17.6X, 17.6X
516	VAC	26	DCS	16	MBO	12	XF2-X1J	BN	For maritime traffic Bridge, Fraser River Bridge
517	PDX	34	PTI	29	PTI	25	MVW-STW	BN	Meet 516, Siding, stanwood
58	CHI	87	DSR	95	WTR	27	HMD-MCB	CC	Heat order Milepost, 849, 823
59	NOL	49	DSR	118	DSR	26	MCB-HMD	CC	Per dispatcher (radio/phone) Milepost, 823, 849, 40, main
14	SEA	100	TRS	110	TRS	92	XA4-SEA	BN	Trespasser strike Stopped at Auburn North due to Sounder trespass strike at mp 17.6x Kent, Control Point, auburn north
7	SEA	125	DCS	250	DCS	218	LSE-LSE	CP	CTC system failure Milepost, 281, 281
8	CHI	149	FTI	241	FTI	52	MAL-GGW	BN	Meet BN 7831, BN 6525, Siding, Hinsdale
27	PDX	-42	DSR	12	DSR	11	XPW-PSC	BN	Per bulletin Milepost, 83.9, 84.1, 30, m1, Milepost, 110.1, 110.8, 30, m1, Milepost, 118.8, 120.0, 25, mt
821	FTW	44	DSR	38	DSR	30	GLE-FTW	BN	Per bulletin Milepost, 399, 398.7, 25, M, Milepost, 396.4, 396.2, 30, M, Milepost, 395.7, 394.9, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 389, 388, 50, M, Milepost, 386, 385.3, 30, M, Milepost, 384.8, 384.4, 30, M, Milepost, 384.2, 383.4, 25, M, Milepost, 383.3, 383.2, 25, M, Milepost, 383.1, 3
822	OKC	106	FTI	78	FTI	36	FTW-GLE	BN	Meet Siding, metro, bnsf 7356
352	PNT	23	PTI	27	PTI	27	JXN-ARB	MI	Meet After completing our station work and departing on time, train made reverse move out of the station to clear the track for 355. Holding west of station till they clear CP75, Amt 355, Control Point, CP75
365	CHI	28	FTI	44	FTI	26	PTH-LPE	CC	Meet CN3195, Control Point, W. Tappan
584	SAN	33	CTI	31	ITI	15	LAX-LAX	SC	Late departure at initial terminal due to late arrival of inbound equipment 782
587	LAX	Trn Cancelled							
593	LAX	Trn Cancelled							
595	LAX	16	FTI	22	FTI	18	ANA-XFT	BN	Cross Traffic 7304, Control Point, ful jct
777	SLO	55	CTI	51	CTI	27	BUR-BUR	SC	Meet Metrolink, Other, BUR

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Region: ALL

Service: ALL

Arriving On: 9/24/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
786	SAN	Trn Cancelled	PTI	31	PTI	31	GUA-LPS	UP	Meet 765 / 14, Siding, tangair
701	SAC	18	FTI	35	FTI	17	SKT-LOD	UP	Meet UP 2748 South, Siding, Lodi
702	BFD	22	DSR	18	DSR	9	MCD-MDR	BN	Per bulletin Milepost, 1041.3, 1038.3, 25, MT, Milepost, 1026.4, 1026.2, 45, MT
703	SAC	No OS Rpt	POL	71	POL	71	HNF-FNO	BN	Right of Way police hold Held at conejo for police activity
704	BFD	33	PTI	53	PTI	27	MCD-MDR	BN	Follow AM 716, Milepost, 1056.0, 1024.0
713	OKJ	Trn Cancelled	PTI	60	PTI	20	MDR-MCD	BN	Meet amtrak, Siding, sharon
714	BFD	82	TCR	33	TCR	33	MDR-FNO	BN	Electrical failure C9306, Lost Load/Doors no power to car car restarted twice - cut out doors on loco
715	OKJ	64	FTI	42	PTI	15	ACA-XPR	BN	Meet Shuffle, amt 716, Control Point, east pittsburg
716	BFD	153	TEN	103	TEN	103	EMY-EMY	UP	Swapped out locomotives 2002 to 2123 CDTX causing delay Trip started at Emeryville per train master Chris Howell 2004and2123CDTX
717	OKJ	31	PTI	24	PTI	12	MTZ-RIC	UP	Meet 548, Control Point, Costa
719	OKJ	52	FTI	36	PTI	20	MDR-MCD	BN	Meet AMT716, AMT704, Control Point, PLANADA
4	CHI	60	FTI	146	FTI	46	BAR-NDL	BN	Follow Massive congestion due to many westbound freights, all behind one which had broken down and another which had been stopped and raided by thieves. Red signal, Amboy; stopped there for 21 minutes, in addition to having to follow traffic at slow speeds., Milepost, 674, 622, BNSF 3252 W, others
22	CHI	67	FTI	122	FTI	49	AUS-TAY	UP	Follow up5029, Control Point, q152, Other, tay depot
301	STL	34	DCS	41	PTI	20	SPI-ALN	UP	Meet amtrak 22, Milepost, 214, 214
302	CHI	22	FTI	15	FTI	15	BNL-PON	UP	Meet up 8415, Control Point, 93
382	CHI	36	FTI	35	FTI	22	MAC-GBB	BN	Cross over or go around Through GBB yard. Restricted Speed, Milepost, 166.0, 164.2, 6273, 4228, BNSF
392	CHI	No OS Rpt	FTI	28	FTI	17	DQN-CEN	CC	Follow Control Point, duquoin, cn9132
311	KCY	21	PTI	32	PTI	32	JEF-SED	UP	Meet Next siding at Smithton was open, Amtk 318, Siding, Dow

Amtrak Endpoint OTP Details

26-FOI-0077400000008850"UNCLASSIFIED"10/5/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/24/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
316	STL	26	FTI	22	FTI	9	LEE-WAR	UP	Meet UP 2632, Siding, Centerview	
318	CHI	107	FTI	76	FTI	20	SMT-XTF	CC	Cross Traffic Unknown freight, Control Point, Corwith	
319	KCY	22	DSR	20	PTI	17	JEF-SED	UP	Meet amtk 316, Siding, dow	
1333	MSP	27	PTI	31	DSR	22	XH8-MSP	CP	Per bulletin Milepost w/Letters, 395.6c, 402.5c, 25, 1, Milepost w/Letters, 402.8c, 409.1c, 25, 2, Milepost w/Letters, 409.1c, 429.9, 10, 2	
1340	CHI	28	DSR	24	DCS	17	POG-CBS	CP	T.O.L Track light out., Control Point, portage jct	

Amtrak Initial Terminal Details

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/24/2026

Terminal	Train	Date	Late	Delay	Cause
BON	685	09/24	1		
BOS	2151	09/24	7	7	Other electrical failure, 2123 NG NP, Multiple faults. Engr reports had to de-prepare and re-prepare train.
BOS	2159	09/24	36	36	Routine inspections, LATE FROM FOR INSPECTIONS
BTN	290	09/24	1		
HAR	658	09/24	1	1	Wait for scheduled departure time
HFD	473	09/24	8	8	Late departure at initial terminal due to late arrival of inbound equipment, 470
NFL	280	09/24	3	3	Mobility Impaired Last minute arrival, need help with luggage
NHV	470	09/24	15	15	Planned set out / pick out of locomotives, cars or section of train, Late equipment swap @ motor storage
NYP	19	09/24	9	9	Hold for connecting train, HELD F/PSGRS OFF AM2159
NYP	63	09/24	6	6	Meet, AM230, Other, NYP, HELD F/INBOUND AM230
NYP	79	09/24	13	13	Delay in Block, HELD BY CNOC FOR UNSPECIFIED REASON
NYP	131	09/24	5	5	Mobility Impaired, ASSISTING ADA PSGR
NYP	241	09/24	3	3	Follow, B98, B98, Other, XPI-SOB, HELD IN STATION A/C DELAYED AM48 RTD AHD IN "A" INT A/C FLWD FRIEGHT TRAIN XPI-SOB
NYP	2105	09/24	13	13	Other electrical failure, 2125, NECESSARY TO RE-CONFIGURE FOR UNSPECIFIED REASON
PHL	110	09/24	3	3	Door, 82515 AX AS, Door Bypass
PHL	151	09/24	2	2	Lost time - N.A.R., no delay reported by crew per dispatcher 5:25am, section 4
PHL	190	09/24	1	1	Passenger and/or baggage
RGH	77	09/24	9	9	Meet csx 612, Control Point, southern junct
RNK	178	09/24	29	8	Restrictive signal(s) from unknown cause Stop, Other, 8 1/2
RNK	178	09/24	29	21	Pick up rescue locomotive due to mechanical failure Amtrak 153 failed Picked up NS 1805, 153
TWO	64	09/24	2		
WAS	112	09/24	5	5	Group, GROUP OF PSX BOARDING LATE
WAS	184	09/24	2	2	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE
WAS	2120	09/24	36	36	Late departure at initial terminal due to late arrival of inbound equipment, 2119, LATE ARRIVAL OF EQUIPMENT DUE TO EQUIPMENT SWAP IN BOS
WAS	2128	09/24	44	44	Late departure at initial terminal due to late arrival of inbound equipment, 2165, 2165 WAS BEHIND TRN 97 THAT WAS STOPPED NORTH OF BAL DUE TO FIRE.

Amtrak Initial Terminal Details

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/24/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2158	09/24	17	17	Disabled train ahead, Other, SOUTH OF NHV, 2151 DELAYED ARRIVING DUE TO ISSUES RAISING PANTOGRAPH SOUTH OF NHV
CHI	3	09/24	130	130	Air / Brake / Wheel 32085
BFD	703	09/24	4	4	Hold for thruway bus
BFD	717	09/24	1		
EMY	6	09/24	3	3	Dispatcher hold Didn't give us a signal at departure time, Control Point, Emeryville
GTA	782	09/24	11	11	Meet 14, Control Point, CO 358
LAX	584	09/24	15	15	Late departure at initial terminal due to late arrival of inbound equipment 782
OKJ	710	09/24	1		
OKJ	714	09/24	16	16	Loading problem Lost load randomly leaving yard, C2108
OKJ	716	09/24	(Trn Cxld)		Third Party Engine Failure
OKJ	718	09/24	13	13	Late departure at initial terminal due to late arrival of inbound equipment 713
SAC	523	09/24	1	1	Air / Brake Engineer stated "train felt like it was dragging" stopped to investigate immediately after departure, C2014
SAC	702	09/24	2	2	ENGINE SHUT DOWN C2002
SAN	587	09/24	(Trn Cxld)		Engine Issue
SAN	593	09/24	(Trn Cxld)		Engine Issue
SAN	595	09/24	1	1	Door 6907, Double sets
SEA	8	09/24	112	112	Late departure at initial terminal due to late arrival of inbound equipment 007
SJC	530	09/24	1		
SJC	544	09/24	2	2	Meet AMT 543, Control Point, CP Shark

Eastern Region

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	99.1	94.8	342	3
CDOT	95.0	100.0	91.2	92.4	20	0
MARC	95.0	63.8	88.9	90.2	58	21
SEPTA	95.0	98.7	91.0	91.5	223	3
NJT-NED	95.0	95.1	94.5	88.6	365	18
NJT-SED	95.0	100.0	98.9	97.2	24	0

Operating Highlights

Train 49/449(24) West of Buffalo - Depew, NY - Injured or Sick Passenger or Employee

25SEP26: Train 49/449(24) operating with engines 85, 106, and 240 customers onboard met EMS 6 miles west of Buffalo-Depew, NY for two separate customers onboard who has medical emergencies. Both customers were removed by local EMS at milepost 6.2 Lake Ave crossing ID 520032R.

Train	Delay	Comment
49/449(24)	1'00"	

Train 98(24) North of Dillon, SC - Freight Train Interference

25SEP26: Train 98(24) operating with engines 353, 111, and 207 customers onboard was delayed North of Dillon, SC on the CSX South End subdivision following CSX I032-24 from milepost 246.2 until Fayetteville, NC milepost 209.5.

Train	Delay	Comment
98(24)	48"	

Train 52(24) North of Savannah, GA - Freight Train Interference

25SEP26: Train 52(24) operating with engines 360, 352, and 283 customers onboard was delayed 18 miles north of Savannah, GA on the CSX Charleston subdivision meeting CSX freight at Hardeeville milepost 474.6 and following them until milepost 469.6. 52(24) was further delayed meeting I137-24 and M491-24 just south of Florence, SC on the Charleston subdivision at milepost 318.1.

Train	Delay	Comment
52(24)	30"	
52(24)	40"	

Train 97(24) North of Baltimore, MD - Car Failure

24SEP26: At 5:36 p.m. 26-FOI-007741 00000008850 UNCLASSIFIED 10/5/2026 1 97(24) operated with engine 639, 10 coaches, and 190 customers evacuated their train at milepost 85.7 approximately 10 miles north of Baltimore on the Amtrak PW Line due to a battery box fire under coach 62506. Head end power was brought down while the fire was being extinguished. All customers were evacuated on the track 3 side while local fire worked on the equipment. The temperature outside was 65 degrees and clear. All tracks had a hold placed on them causing a holding pattern to begin for all north and south traffic. An AC plate was in effect due to the local fire department having their hoses stretched out across all 4 tracks in the area. Once the fire was contained, the train was able to be boarded again. Coach 62022 was short looped to provide headend power to the entire consist minus the last 2 pieces of equipment pertaining to the sleeper and the baggage car. Snack packs and water bottles were offered to all customers as service recovery. All 10 customers affected in the coach on fire were downgraded to coach. Upon clearing the equipment and the AC plate on all tracks, train 97(24) reboarded and traffic was released to resume normal operations at 7:30 p.m. Sleeper car 62506 was set out in Washington D.C.

Train	Delay	Comment
2126(24)	09"	
97(24)	2'04"	N/BAL
2124(24)	37"	
2120(24)	1'06"	
2165(24)	1'39"	
85(24)	1'44"	
136(24)	1'33"	
129(24)	43"	
178(24)	1'09"	
184(26)	23"	
138(24)	34"	
192(24)	26"	
173(24)	1'07"	
2123(24)	12"	
196(24)	48"	
97(24)	33"	Set out C/62506
2128(24)	44"	Late turn off 2165

Amtrak PW Line North of BWI Marshall Airport, MD - Police Hold

24SEP26: A police hold was placed on the Amtrak PW line between Bridge/MP 98.2 and Grove/MP 112. due to a possible suicidal trespasser laying in the gauge on main track 1 at MP 102.7, 4 miles north of BWI Marshall Airport Station, delaying multiple trains. Amtrak Police responded to the scene due to the trespasser walking from main track 1 to main track 2 and lingering near the tracks. Train 176(24) was held at BWI Marshall Airport until the tracks were clear. Once the tracks were confirmed to be clear of the individual, traffic was resumed through the area.

Train	Delay	Comment
2119(24)	08"	
Multiple Marc Trains	between 04"-41"	delays
176(24)	41"	

Train 68(24) North of Rouses Point, NY - Freight Train Interference

24SEP26: Train 68(24) was delayed starting at MP 30.2, 30 miles north of Rouses Point, NY, on the CNRR Rouses Point Subdivision due to freight interference. The crew held in the siding at Lacadie/MP 27.8 for CN323 to clear. Once freight was clear, Train 68(24) proceeded east.

Train	Delay	Comment
68(24)	47"	

Train 40(23) North of Rocky Mount, NC - Police Related

24SEP26: Train 40(23) 28-FCI-007741 000000088501 MP 87.4 32 miles north of Rocky Mount, NC, on the CSX North End Subdivision holding for police due a customer altercation with another customers. The crew held at the crossing on Halifax Rd for local police to respond and remove the unruly customer on board. Once the customer was removed, Train 40(23) proceeded north.

Train	Delay	Comment
40 (23)	25"	

Train 40(23) Rocky Mount, NC - Injured or Sick Passenger

24SEP26: Train 40(23) operating with locomotives 57-150, 10 cars and 166 customers onboard was delayed at Rocky Mount, NC Station for a female passenger who fell and required EMS assistance. Local EMS responded to the station to evaluate the condition of the passenger. After assessment, the passenger remained on the train and continued travel to their final destination of Washington, DC.

Train	Delay	Comment
40 (23)	29"	

Train 94(24) South of Alexandria, VA - Freight Train Interference

24SEP26: Train 94(24) operating with locomotive 328, 8 cars and 390 customers onboard was delayed 2 miles south of Alexandria at MP 103 on the CSX RF&P subdivision due to freight train interference with CSX M418-24 ahead on the No.1 track in emergency. The freight crew was able to inspect the equipment and restore their air and proceed. Train 40(23) was then able to follow M418-24 to Slaters.

Train	Delay	Comment
94 (24)	50"	

Next Gen Acela 2159(24) Boston, MA Initial Terminal Delay - Servicing

24SEP26: Next Gen Acela 2159(24), TS-15 with 118 customers, was delayed departing Boston, MA due to mechanical issues. Mechanical was unable to resolve the pantograph issues on TS-15 before departure, therefore equipment set from Next Gen Acela 2163(24), TS-14, was moved up for Next Gen Acela 2159(24). Once equipment was brought to the station from the yard, the customers were boarded and commissary was added, Next Gen Acela 2159(24) departed Boston.

Due to the late operation of train 2159(24) trains 2159(24) and 2119(24) operated out of timetable order. To mitigate an extended delay train 2119(24) equipment was turned for 2120(24) which resulted in an initial terminal delay.

Train	Delay	Comment
2159(24)	36"	
2120(24)	36"	

Train 280(24) West of Rome, NY - Freight Train Interference

24SEP26: Train 280(24) operating with engine 8005 cars and 156 customers was delayed due to freight train interference following an unspecified CSX freight train from MP 285 to MP 270 on the CSX Syracuse Terminal subdivision. Train 280(24) was again delayed 6 miles west of Rome, NY at MP 257 on the CSX Mohawk subdivision due to freight train interference meeting CSX I009-23. I009-23 crossed over track No.1 to track No.2 and back due to a track circuit between CP 257 and CP 258. Once the freight cleared the interlocking at CP 257 train 280(24) was able to proceed without further delay.

Train	Delay	Comment
280(24)	33"	CP 257
280(24)	22"	CP285 to CP270

Train 171(23) North of Lynchburg, VA - Tree Strike

24SEP26: Train 171(23) operating with engine 153, 8 coaches, and 92 customers onboard struck a tree causing significant damage to the plow and fireman side ladder north of Lynchburg, VA on the Norfolk Southern Washington District. The strike was not reported until the train arrived into Roanoke, VA and Rail Plan mechanical reported the damage. The strike occurred at approximately 8 p.m. at an unspecified milepost north of Lynchburg. Due to the damage, Washington mechanical was dispatched to travel to Roanoke and trim the plow to ensure it was in compliance. The engine was placed on the rear of the train with a rider and Norfolk Southern freight engine 1805 was sourced to provide tractive effort. Amtrak management was on site to assist mechanical and the crew in adding the freight locomotive. After NS1805 was added to the equipment in Roanoke a daily inspection of the locomotive was required before the departure of train 178(24) causing an initial terminal delay. Train 178(24) was further delayed operating at freight speeds between Roanoke and Washington, DC. At MP 54.1 on the Norfolk Southern Washington District, the freight locomotive required a software update. The crew held while the PTC-IETMS software was downloaded and installed then proceeded north. The train was further delayed in Washington D.C. due to an issue taking off the NS freight unit.

Train	Delay	Comment
178(24)	29"	Initial terminal delay
178(24)	27"	Software Update
178(24)	10"	Freight Speeds RNK-BCV
178(24)	24"	WAS

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	26-FOI-00774 00000008850 "UNCLASSIFIED" 10/5/2026
78(03)	50"	Turn of Late 77(03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.

31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between NHV and SPG, will terminate at HFD.

• Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

• Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

• Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 50Oct-90Oct, 120Oct-160Oct, 190Oct-230Oct, 260Oct-300Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
178 (24)	RNK	NS1805	E/153 no Strike damage	RNK	
41 (24)	PGH	NS7719	E/86 No HEP, won't load		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train 3(23) West of Winslow, AZ - Freight Train Interference

25SEP26: Train 3(23) was delayed at East Canyon Diablo/ MP31.5 on the BNSF Seligman Subdivision, 25 miles west of Winslow, AZ station, due to meeting freight unit CP2862, And delayed further at CP2867, meeting freight unit BN6599.

Train	Delay	Comment
3(23)	31"	

Train 7/27(23) West of Havre, MT - Passenger Train Interference

25SEP26: Train 7/27(23) was delayed at Havre Center/MP429.3 on the BNSF Milk River Subdivision, 1 mile west of Havre, MT station, due to meeting Train 8/28(23).

Train	Delay	Comment
7/27(23)	31"	

Train 786(24) South of Lompoc-Surf, CA - Passenger Train Interference

25SEP26: Train 786(24) was delayed at Tangair siding/MP293.6 5.5 miles south of Lompoc, CA/MP299.2 on the UPRR Santa Barbara subdivision, due to meeting trains 765(24) and 14(24).

Train	Delay	Comment
786(24)	31"	

Train 718(24) West of Hanford, CA - M of W Work

25SEP26: Train 718(24) was delayed at Shirley/ MP974.1 on the BNSF Bakersfield Subdivision, 6.2 miles west of Hanford, CA station, holding for a defect repair.

Train	Delay	Comment
718(24)	37"	

Train 786(24) Terminated at Irvine, CA - Engine Failure

25SEP26: Train 786(24) E/C2121, 6 Cars, and 132 passengers, was terminated at Irvine, CA/ MP185 on the SCRRA Metrolink Orange Subdivision, due to a major engine fault on E/C2121 that appeared enroute. All passengers were detrained at Irvine and accommodated onto late arriving Train 588(24). The 786 equipment was then deadheaded back to Los Angeles. As a result, Train 593(24) was cancelled in entirety with all passengers accommodated onto Train 595(24), that operated as a double-set.

Train	Delay	Comment
786(24)	Terminated	Irvine
593(24)	Cancelled	

Train 587(24) Cancelled San Diego, CA- Cab Car Failure

25SEP26: Train 587(24) with CC/C6901 on Inbound 774(24) had a malfunctioning horn and event recorder. All affected passengers on train 587 were accommodated on 591(24). Several equipment turns were also affected due to this: Train 572(24) turned for 785(24) at San Diego and inbound Train 782 coupled to the cancelled 587, and was originally scheduled to operate as a double-set as Train 593(24). 593(24) was later cancelled in entirety, and this double-set operated instead as Train 595(24).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
587(24)	Cancelled	
595(24)	01"	

Train 703(24) West of Hanford, CA - Police Related

25SEP26: Train 703(24) was delayed at Conejo/ MP983.1 on the BNSF Bakersfield Subdivision, 15.4 miles west of Hanford, CA station, due to a police hold on the tracks ahead at MP987.2. Once the hold was released, Train 703(24) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
703(24)	1'11"	

Train 509(24) South of Tukwila, WA - Sounder Transit Trespasser Incident

25SEP26: At approximately 6:20PM-PT, it was reported that a Sounder Transit Train struck a trespasser at MP 17.6x on the BNSF Seattle Subdivision approximately 7 miles south of Tukwila. The incident was a confirmed fatality. All train traffic was stopped, and tracks closed, while local police and medical examiner completed their investigations. Train 509(24) was the first train affected, and held at MP16.1x. Train 14(23) was then held at MP22.3x, 511(24) held at Tukwila and 506(24) held at Sumner/ MP29.7x. Service recovery was initiated onboard Train 509(24) with snack packs and bottled water provided to all passengers. Once tracks were re-opened at 9:05PM-PT, all trains resumed normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
509(24)	2'51"	
14(23)	1'32"	
511(24)	57"	
506(24)	26"	

Train 714(24) East of Madera, CA - Third Party Contractor Car Failure

24SEP26: Train 714(24) with CC/C8311, 7 cars, E/C2108, was delayed at Gregg/ MP1010.4 on the BNSF Stockton Subdivision, 13.6 miles east of Madera, CA station, with loading issues. Crew worked with TASI mechanical in order to troubleshoot the issue. It was determined to be an electrical issue on car C/9306. The car was restarted twice, which did not resolve the issue, then doors were cut out, allowing them to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(24)	33"	

Train 8(24) Seattle, WA - Initial Terminal Delay

24SEP26: Train 8(24) was delayed departing Seattle, due to the equipment turn and servicing offlate inbound Train 7(22) that arrived Seattle 2 hours and 5 minutes late.

Train 25(24) West of Bay Saint Louis, MS - Freight Train Interference

24SEP26: Train 25(24) ,26-FQ1-00774,100000008850 engines UNCLASSIFIED/ 344/154,10/5/2026 coaches, and 59 customers, was delayed 2 miles west of Bay Saint Louis, MS, on CSX NO&M subdivision, due to meeting CSX520 and then 26(24). Once both trains cleared and a route was made available, train 25(24) was able to proceed.

Train 26(24) was delayed following CSX520 from milepost 777 to milepost 746.

Train	Delay	Comment
25 (24)	1'18"	
26 (24)	58"	

Train 782(24) Simi Valley, CA - Disabled Metrolink

24SEP26: Train 782(24) was delayed at Simi Valley, CA/ MP 438.1 on the SCRRRA-Metrolink Ventura Subdivision due to disabled Metrolink train ML122 at Chatsworth/ MP445.46. As the delay continued, a service recovery plan was implemented under which the Train 579 equipment at Los Angeles (LAX) was assigned to operate an on-time section of Train 782 between Los Angeles and San Diego. The original delayed Train 782(24) was designated to become Train 584(24) upon arrival into Los Angeles, and passengers with travel beyond Los Angeles were permitted to remain onboard.

After the disabled Metrolink train was cleared, Train 782(24) was released and departed Simi Valley at 4:16 p.m. PT, operating 1 hour and 45 minutes late with a delay of 1 hour and 30 minutes attributable to the incident. To assist Metrolink passengers affected by the disruption, Train 790(24) was scheduled to make two additional stops at Northridge and Burbank. The equipment substitution and schedule adjustments allowed southbound service to continue while minimizing the impact of the delay on connecting passengers.

Train	Delay	Comment
790 (24)	07"	Making ADTL stops
782 (24)	1'30"	

Train 822(24) North of Fort Worth, TX - Freight Train Interference

25SEP26: Train 822(24), operating with engines 50/135, 2 coaches, and 78 customers, was delayed 31 miles north of Fort Worth, TX, on BNSF Ft. Worth subdivision due to meeting BNSF7678, at Ponder, and BSNF7356 at Metro.

Train	Delay	Comment
822 (24)	1'00"	

Train 5(22) East of Roseville, CA - Freight Train Interference

24SEP26: Train 5(22) was delayed 0.5 mile east of Roseville at MP107 on the UPRR Roseville Subdivision due to freight unit ZLCTM (UP 7713) with locomotive issues, that was adding an additional locomotive in order to proceed. Once the route was clear, Train 5(22) proceeded into Roseville,

Train	Delay	Comment
5 (22)	50"	

Train 716(24) Oakland, CA - Third Party Contractor Engine Failure

24SEP26: Train 716(24) was delayed at Oakland, CA (Jack London Square Station) due to the replacement of Locomotive C2004 after it experienced an overheating condition. Locomotive C2123 was substituted for the affected unit prior to departure. Due to experiencing a longer than expected delay swapping locomotives, Train 716(23) was originated at Emeryville, CA. All passengers were accommodated onto Train 536(24) between Oakland and Emeryville.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(24)	1'43"	Originated EMY

Train 22(24) Fort Worth, TX - Engine Failure

24SEP26: Train 22(24) was delayed at Fort Worth, TX (MP346.2), on the BNSF Fort Worth Subdivision due to a mechanical issue involving the horn lever on locomotive 311. After the horn lever was repaired, the train incurred additional delay while awaiting a signal from TRE authorizing departure before continuing its route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(24)	27"	Horn
22(24)	37"	Route

Train 713(24) Terminate Emeryville, CA - Third Party Contractor Car Failure

24SEP26: Train 713(24) was terminated in Emeryville, CA due to late operation and door issues on Car C9305. The doors would not open when the button was pressed. Terminating the train provided Mechanical personnel additional time to troubleshoot and repair the equipment before its turn for Train 718(24).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(24)	13"	ITD OKJ - Equip turn
713(24)	Terminated	EMY

Train 6(22) East of Princeton, IL - Freight Train Interference

24SEP26: Train 6(22) held 23.8 miles east of Princeton, IL (MP104.3), on the BNSF Mendota Subdivision, at Electrics (MP80.5) in order to meet BNSF 7934.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(22)	30"	

Train 821(24) South of Gainesville, TX - Temporary Speed Restrictions

24SEP26: Train 821(24) was delayed beginning 11.7 miles south of Gainesville, TX (MP410.7) on the BNSF Fort Worth Subdivision due to multiple slow orders in effect between MP399.0 and MP383.1.

822(24) was also delayed operating through the affected area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
821(24)	30"	
822(24)	30"	

Train 22(24) North of Temple, TX - Temporary Speed Restrictions

24SEP26: Train 22(24) was delayed between beginning 16 miles north of Temple, TX (MP218.2), on the BNSF Fort Worth Subdivision due to multiple temporary speed restrictions in effect between MP219.8 and MP234.1.

Train	Delay	Comment
22 (24)	31"	

Train 3(24) Chicago, IL - Car Failure

24SEP26: Train 3(24), E/167-E/198-12 Cars, was delayed departing Chicago, IL due to sleeper car 32085 being bad ordered for an air brake valve failure. Sleeper car 32059 was identified as the replacement. Upon completion of the equipment addition, the equipment set was positioned at the station to accommodate the loading of 241 waiting customers. At 3:40PM-CT, Train 3(24) departed Chicago Union Station operating 2 hours and 10 minutes late.

Train	Delay	Comment
3 (24)	2'10"	

Train 8/28(23) West of Cut Bank, MT - Freight Train Interference

24SEP26: Train 8 / 28(23) was delayed between Piegan / MP 1106.5 and Lothair / MP 1036.5 on the Burlington Northern Santa Fe Hi Line Subdivision, starting 16 miles west of the Cut Bank, MT station, following ZPTLCHC4-23 (BNSF 6550). The delay was a result of GRYMRGT9-20 (BNSF 5526), experiencing locomotive failure at Shelby / MP 1087.0.

Train 8 / 28(23) was then delayed 29 miles east of Williston, ND at Ray /MP 93.2 on the BNSF Glasgow Subdivision for a re-crew.

Train	Delay	Comment
8/28 (23)	1'52"	
8/28 (23)	43"	Re-crew

Train 311(24) East of Sedalia, MO - Passenger Train Interference

24SEP26: Train 311(24) held 22 miles east of Sedalia, MO (MP188.9), on the UPRR Sedalia Subdivision, at Dow (MP166.9) in order to meet Train 318(24).

Train	Delay	Comment
311 (24)	32"	

Suisun Bay Bridge East of Martinez, CA - Drawbridge Opening

24SEP26: Train 526(24) and Train 531(24) were delayed account of the Suisun Bay Bridge / MP 33.2 on the Union Pacific Martinez Subdivision, 2 miles east of the Martinez, CA station, opening for maritime traffic.

Train 539(24) and Train 530(24) were also delayed account of bridge opening for maritime traffic.

Train	Delay	Comment
526 (24)	39"	
531 (26)	41"	
530 (24)	20"	
539 (24)	23"	

Train 24(24) South of Mobile, AL - Vehicle Strike

24SEP26: At 10:43AM-CT, Train 24(24) E/154 struck a vehicle at the Cary Hamilton Road crossing (DOT#351460V), located on the CSX NO&M Subdivision at MP679.67, approximately 13 miles south of Mobile, AL (MP666.7) in Mobile County. The crossing was equipped with two advanced warning signs, pavement markings, an ENS sign, two quad gate arms, two mast-mounted flashing lights, and one bell. The vehicle had two occupants, who sustained fatal injuries. There were no injuries reported to the crew or the 63 customers onboard. Head end power remained on to the trainset. Minimal damage was reported to lead engine E/154. Local police, EMS, and the Mobile Road Foreman responded to the scene. Train 24(24) was operating at 77MPH at the time of the incident, with a maximum timetable speed of 79MPH through the crossing. Service recovery was enacted during the incident, with snack packs and bottled water distributed to all customers. The Conductor and Student Engineer accepted trauma relief at the scene. The Assistant Conductor and Engineer agreed to operate the train into Mobile once released by officials and then take trauma relief. At 1:16PM-CT, Train 24(24) was released from officials to proceed to Mobile.

National Response Center Number: 1474446

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
24(24)	2'50"	

Train 504(24) South of Salem, OR - Disabled Freight

24SEP26: Train 504(24) was delayed at Renard / MP 715.5 on the Union Pacific Brooklyn Subdivision, 3 miles south of the Salem, OR station, due to ZLCTM-23 (UPRR 8795) setting out a bad order locomotive. Once set out, Train 504(24) was further delayed following the freight train to Labish / MP 720.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
504(24)	1'52"	

Train 4(23) Encompassing Gallup, NM - Freight Train Interference

24SEP26: Train 4(24), with 126 customers, was delayed between West Defiance / MP 166.9 and West Gallup / MP 161.3 on the Burlington Northern Santa Fe Subdivision, starting 9 miles west of the Gallup, NM station, following ZLACNYC2-23 (BNSF 7307).

Train 4(24) was further delayed between Rio Puerco / MP 33.9 and Dalies / MP 27.3 following ZSBDWSP1-23 (BNSF 7408).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(23)	1'51"	West Defiance to West Gallup
4(23)	31"	Rio Puerco to East Isleta

Train 2/422(23) West of Yuma, AZ - Freight Train Interference

24SEP26: Train 2 / 422(23) was delayed at Yuma / MP 732.4 on the Union Pacific Gila Subdivision, just west of the Yuma, AZ station, meeting ZG2LC-21 (UPRR 5549).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2/422(23)	32"	

UPRR Alhambra Subdivision Los Angeles, CA to Palm Springs, CA - Detour TWA 26-102

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

22SEP26: To accommodate infrastructure work between Los Angeles, CA and Palm Springs, CA, the Sunset Limited and Texas Eagle services will be adjusted as follows:

Train 2/422(25) will detour over the BNSF San Bernardino Subdivision between Soto(BNSF San Bernardino subdivision) and West Colton(UPRR Alhambra subdivision), bypassing Pomona, CA (POS) and Ontario, CA (ONA). Train 802(25) was created for the detour between Los Angeles, CA (LAX) and Riverside, CA (RIV).

An Amtrak LAX pilot crew will pilot the train over the BNSF San Bernardino Subdivision.

No alternate transportation will be provided to POS and ONA.

WBS#: B.TR.100150.7207

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

26-010272A

7000007450

UNCLASSIFIED

10/5/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
11 (22AUG)	32"	
14 (22AUG)	23"	
11 (12SEP)	29"	
14 (12SEP)	58"	Detour/ FTI

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production will be **UNCLASSIFIED** on 10/5/2026. 26-FBI-00774 00000008850
Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-06Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-07Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated	MEM

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.
Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00774 00900008850 UNCLASSIFIED 10/5/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00774

00000008850

"UNCLASSIFIED"

10/5/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
566 (24)	LAX	Operating with 90215 in consist will not be able to accommodate passenger with BV reservations. CNOC CSV will need to reaccommodate any passengers impacted by this. Inventory has been updated.	no impact	0	90215
584 (24)	LAX	Operating with 90215 in consist will not be able to accommodate passenger with BV reservations. CNOC CSV will need to reaccommodate any passengers impacted by this. Inventory has been updated.	1pax impacted	1	90215
782 (24)	LAX	TRAIN WILL NOT HAVE BIKE SPACE DUE TO CHANGE OF EQUIPMENT AND HAVING CAR 90215. PLEASE NOTIFY EFFECTED PAX.			90215
97 (24)	NYP	Due to shopped car 61047 and no replacement. DHD car 62034 can be used for baggage	NO IMPACT CAR ADDED	0	61047
49 (24)	NYP	Due to shopped equipment and no replacement, 49(24) will have 43387 added for baggage.	NO IMPACT CAR ADDED	0	61059
579 (24)	SAN	Operating with 90215 in consist will not be able to accommodate passenger with BV reservations. CNOC CSV will need to reaccommodate any passengers impacted by this. Inventory has been updated.	1 pax impacted	1	90215
595 (24)	SAN	Operating with 90215 in consist will not be able to accommodate passenger with BV reservations. CNOC CSV will need to reaccommodate any passengers impacted by this. Inventory has been updated.	no impact	0	90215
593 (24)	SAN	TRAIN WILL NOT HAVE BIKE SPACE DUE TO CHANGE OF EQUIPMENT AND HAVING CAR 90215. PLEASE NOTIFY EFFECTED PAX.			90215
11 (24)	SEA	DUE TO SHOPPED 34103, NO REPLACEMENT OPERATING ONE COACH SHORT.	COACH INVENTORY RREDUCED -9	22	NO CAR

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00774 00000008850 "UNCLASSIFIED"			
		INVENTORY HAS BEEN REDUCED. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS IMPACTED.	AT EUG -13 SJC FARE PROTECT SENT TO PAX		

Reverse Consists

Train Number	Station	Reason
95 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (24)	BOS	Consist reversed Business class seat orientation may have changed At Front
136 (24)	WAS	Consist reversed Business class seat orientation may have changed At Front
94 (24)	NFK	Consist reversed Business class seat orientation may have changed At Front
193 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front
178 (24)	RNK	Consist reversed Business class seat orientation may have changed At Front
174 (24)	WAS	Consist reversed Business class seat orientation may have changed At Front
129 (24)	NYP	Consist reversed Business class seat orientation may have changed At Front
148 (24)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (25)	SPG	Consist reversed Business class seat orientation may have changed At Front
178 (25)	RNK	Consist reversed Business class seat orientation may have changed At Front
86 (25)	NPN	Consist reversed Business class seat orientation may have changed At Front