



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, September 11, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/10/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	48	84.7%	3,134	457	85.4%	103,656	14,425	86.1%
Central Division	86.0%	54	6	88.9%	575	71	87.7%	19,770	1,846	90.7%
East Division	82.0%	177	23	87.0%	1,698	197	88.4%	54,518	8,331	84.7%
West Division	86.0%	83	19	77.1%	861	189	78.0%	29,368	4,248	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008781 UNCLASSIFIED 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	96,957	24,915	74%	1,035,767	274,939	73%	34,626,813	8,860,919	74%
Northeast Corridor	81%	47,495	11,953	75%	467,348	85,106	82%	15,182,247	3,672,388	76%
Acela	83%	12,914	1,470	89%	105,927	12,917	88%	3,068,553	772,057	75%
Northeast Regional	79%	34,581	10,483	70%	361,421	72,189	80%	12,113,694	2,900,331	76%
Richmond / Newport News / Norfolk	77%	9,263	3,543	62%	107,132	30,582	71%	3,629,931	1,077,881	70%
Springfield Shuttles	89%	778	252	68%	7,271	1,193	84%	213,673	34,331	84%
Roanoke	79%	3,448	216	94%	35,816	5,748	84%	1,149,619	255,442	78%
On Spine Northeast Regional	80%	21,092	6,472	69%	211,202	34,666	84%	7,120,471	1,532,677	78%
State Supported	80%	39,412	8,250	79%	449,985	129,279	71%	15,238,579	3,340,553	78%
Borealis	80%	578	282	51%	5,969	698	88%	193,958	41,169	79%
Capitol Corridor	90%	4,033	432	89%	39,132	5,493	86%	1,268,636	169,539	87%
Carolinian	70%	1,093	325	70%	11,298	4,210	63%	388,626	152,360	61%
Cascades	75%	2,416	1,313	46%	26,865	7,705	71%	877,501	248,359	72%
Downeaster	82%	1,782	0	100%	17,821	262	99%	537,801	62,107	88%
Empire	78%	5,736	1,281	78%	60,693	14,485	76%	1,902,497	469,447	75%
Adirondack	72%	324	182	44%	3,787	986	74%	117,882	37,939	68%
Ethan Allen Express	70%	498	53	89%	5,470	1,872	66%	192,372	74,148	61%
Maple Leaf	70%	758	546	28%	8,693	2,911	67%	237,005	92,790	61%
New York - Albany	85%	2,939	299	90%	26,534	4,331	84%	875,801	152,820	83%
New York - Niagara Falls	75%	1,217	201	83%	15,052	4,369	71%	465,444	104,878	77%
Berkshire Flyer	60%	0	0	-	1,157	16	99%	13,993	6,872	51%
Gold Runner	73%	1,561	1,241	20%	24,962	13,958	44%	854,684	322,717	62%
Heartland Flyer	70%	113	43	62%	1,906	749	61%	73,463	30,934	58%
Hiawatha	90%	1,757	301	83%	18,198	2,191	88%	601,975	66,038	89%
Illinois	78%	2,090	318	85%	23,895	11,499	52%	852,252	244,133	71%
Carl Sandburg / Illinois Zephyr	85%	349	50	86%	4,035	1,092	73%	141,781	40,426	71%
Illini / Saluki	85%	853	268	69%	8,585	4,705	45%	294,597	76,182	74%
Lincoln Service	70%	888	0	100%	11,275	5,702	49%	415,874	127,525	69%
Keystone	92%	10,358	565	95%	84,781	12,181	86%	2,598,672	268,433	90%
Lincoln / Missouri	70%	740	297	60%	7,017	5,554	21%	264,628	141,011	47%
Mardi Gras Service	80%	207	0	100%	3,044	518	83%	136,996	30,503	78%
Michigan	70%	1,517	674	56%	21,556	9,071	58%	694,834	234,621	66%
Blue Water	70%	444	276	38%	5,074	2,037	60%	163,699	67,181	59%
Pere Marquette	85%	160	160	0%	2,880	604	79%	89,361	16,957	81%
Wolverine	70%	913	238	74%	13,602	6,430	53%	441,774	150,483	66%
Missouri	80%	165	165	0%	2,342	1,962	16%	75,702	23,227	69%
Pacific Surfliner	85%	2,680	667	75%	68,567	30,777	55%	2,795,413	549,350	80%
Pennsylvanian	80%	776	228	71%	8,573	2,137	75%	301,126	57,968	81%
Piedmont	80%	442	118	73%	9,268	2,074	78%	380,196	96,675	75%
Vermont	75%	1,368	0	100%	14,098	3,755	73%	439,619	131,962	70%
Long Distance	70%	10,050	4,712	53%	118,434	60,554	49%	4,166,720	1,845,515	56%
Auto Train	70%	648	0	100%	6,371	2,922	54%	266,442	91,663	66%
California Zephyr	70%	848	112	87%	9,411	3,864	59%	330,746	130,043	61%
Cardinal	70%	272	67	75%	2,113	1,403	34%	79,129	40,654	49%
City Of New Orleans	75%	500	448	10%	6,515	5,873	10%	216,167	78,338	64%
Coast Starlight	70%	972	317	67%	11,958	3,000	75%	389,212	137,642	65%
Crescent	70%	743	138	81%	8,760	1,934	78%	314,157	96,404	69%
Empire Builder	70%	982	691	30%	10,953	4,775	56%	330,509	165,525	50%
Floridian	60%	1,290	837	35%	14,744	11,238	24%	534,650	371,244	31%
Lake Shore Ltd	73%	789	474	40%	10,117	4,282	58%	331,798	102,125	69%
Palmetto	70%	1,031	404	61%	7,859	3,340	58%	311,040	98,138	68%
Silver Meteor	70%	752	439	42%	8,822	4,827	45%	343,232	160,231	53%
Southwest Chief	60%	857	481	44%	8,728	5,358	39%	285,983	188,953	34%
Sunset Ltd	70%	0	0	-	2,237	1,005	55%	97,941	39,504	60%
Texas Eagle	70%	366	304	17%	9,846	6,733	32%	335,714	145,051	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000701 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 10, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	66,367	1,099,495	604	2,066,185	36,373,661	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	2,985	338,289	88	99,424	10,545,724	94
INFRASTRUCTURE PLANNED	135	5,759	338,289	170	121,305	10,545,724	115
FLEET RELIABILITY	90	10,553	1,099,495	96	330,098	36,373,661	91
TRAIN OPERATIONS	424	47,070	1,099,495	428	1,515,358	36,373,661	417

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/10/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	48	84.7%	3,134	457	85.4%	103,656	14,425	86.1%
Central Division	86.0%	54	6	88.9%	575	71	87.7%	19,770	1,846	90.7%
East Division	82.0%	177	23	87.0%	1,698	197	88.4%	54,518	8,331	84.7%
West Division	86.0%	83	19	77.1%	861	189	78.0%	29,368	4,248	85.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/10/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	48	84.7%	3,134	457	85.4%	103,656	14,425	86.1%
Central Division	86.0%	54	6	88.9%	575	71	87.7%	19,770	1,846	90.7%
CDL	95.0%	2	0	100.0%	20	4	80.0%	656	35	94.7%
CHI	86.0%	26	6	76.9%	269	45	83.3%	9,139	1,145	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	4	4	0.0%	6	6	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	10	1	90.0%	368	39	89.4%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	-	-	-	9	0	100.0%	323	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	20	1	95.0%	668	55	91.8%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	59	2	96.6%	2,018	128	93.7%
MOE	97.5%	2	0	100.0%	20	1	95.0%	687	10	98.5%
MSP	96.5%	1	0	100.0%	10	0	100.0%	338	7	97.9%
NOL	94.5%	4	0	100.0%	43	1	97.7%	1,453	65	95.5%
OKC	97.0%	1	0	100.0%	9	0	100.0%	338	6	98.2%
PNT	88.0%	2	0	100.0%	25	2	92.0%	901	75	91.7%
PTH	93.0%	1	0	100.0%	10	0	100.0%	333	13	96.1%
QCY	91.0%	2	0	100.0%	19	1	94.7%	650	49	92.5%
SAS	90.5%	1	0	100.0%	10	1	90.0%	342	40	88.3%
STL	89.0%	3	0	100.0%	37	7	81.1%	1,333	113	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	177	23	87.0%	1,698	197	88.4%	54,518	8,331	84.7%
ALB	88.5%	8	1	87.5%	77	9	88.3%	2,561	197	92.3%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	50	0	100.0%	1,671	175	89.5%
BOS	85.5%	19	2	89.5%	186	15	91.9%	5,891	655	88.9%
BRK	92.5%	5	0	100.0%	50	1	98.0%	1,645	113	93.1%
BTN	82.0%	1	0	100.0%	10	1	90.0%	329	43	86.9%
CLT	91.5%	4	1	75.0%	44	5	88.6%	1,675	172	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	19	2	89.5%	667	62	90.7%
GRO	-	1	0	100.0%	6	2	66.7%	56	13	76.8%
HAR	79.5%	13	2	84.6%	112	16	85.7%	3,819	610	84.0%
HFD	-	2	1	50.0%	14	1	92.9%	246	20	91.9%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	10	1	90.0%	341	41	88.0%

Information Management

26-FOI-0077 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/10/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/10/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	48	84.7%	3,134	457	85.4%	103,656	14,425	86.1%
East Division	82.0%	177	23	87.0%	1,698	197	88.4%	54,518	8,331	84.7%
MIA	89.5%	2	1	50.0%	20	5	75.0%	678	81	88.1%
MTR	79.0%	1	1	0.0%	10	2	80.0%	328	60	81.7%
NFK	84.5%	2	0	100.0%	20	2	90.0%	765	138	82.0%
NFL	93.5%	2	0	100.0%	20	1	95.0%	694	32	95.4%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	48	8	83.3%	1,750	295	83.1%
NPN	93.0%	2	0	100.0%	20	1	95.0%	654	52	92.0%
NYP	75.5%	51	8	84.3%	475	76	84.0%	14,404	3,133	78.2%
PGH	93.0%	1	0	100.0%	10	1	90.0%	342	24	93.0%
PHL	48.0%	5	3	40.0%	47	19	59.6%	1,742	818	53.0%
PIT	76.0%	-	-	-	2	2	0.0%	26	21	19.2%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	2	0	100.0%	28	3	89.3%	1,292	57	95.6%
RNK	83.5%	2	0	100.0%	20	1	95.0%	678	94	86.1%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	10	0	100.0%	324	5	98.5%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	10	0	100.0%	338	12	96.4%
SFA	88.0%	1	0	100.0%	10	2	80.0%	341	49	85.6%
SPG	92.5%	5	0	100.0%	53	1	98.1%	2,015	116	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	10	1	90.0%	330	64	80.6%
WAS	84.0%	32	3	90.6%	307	19	93.8%	8,676	1,093	87.4%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	83	19	77.1%	861	189	78.0%	29,368	4,248	85.5%
ARN	92.0%	1	0	100.0%	10	1	90.0%	343	29	91.5%
BFD	79.0%	7	1	85.7%	68	20	70.6%	2,181	468	78.5%
EMY	72.0%	1	0	100.0%	10	4	60.0%	359	104	71.0%
EUG	86.5%	2	1	50.0%	19	3	84.2%	679	62	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	29	9	69.0%	1,030	181	82.4%
IRV	-	-	-	-	2	1	50.0%	6	3	50.0%
LAX	89.5%	7	2	71.4%	92	15	83.7%	3,412	384	88.7%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	5	61.5%	117	51	56.4%	3,736	1,004	73.1%
PDX	86.0%	5	0	100.0%	50	7	86.0%	1,655	232	86.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/10/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/10/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	314	48	84.7%	3,134	457	85.4%	103,656	14,425	86.1%
West Division	86.0%	83	19	77.1%	861	189	78.0%	29,368	4,248	85.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	16	3	81.3%	148	24	83.8%	4,867	544	88.8%
SAN	90.5%	5	0	100.0%	99	18	81.8%	4,136	410	90.1%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	80	16	80.0%	2,633	396	85.0%
SJC	89.0%	7	1	85.7%	70	13	81.4%	2,410	242	90.0%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	30	2	93.3%	795	79	90.1%
SNC	-	2	1	50.0%	6	1	83.3%	37	14	62.2%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	10	1	90.0%	322	30	90.7%
VAC	97.0%	2	1	50.0%	20	2	90.0%	673	16	97.6%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	32	10	3	70.0%	343	69	79.9%	10	3	70.0%	340	160	52.9%
4		10	3	70.0%	342	56	83.6%	10	4	60.0%	342	225	34.2%
5		10	1	90.0%	341	58	83.0%	10	3	70.0%	337	114	66.2%
6		10	4	60.0%	340	95	72.1%	10	5	50.0%	340	130	61.8%
7	138	10	0	100.0%	332	51	84.6%	10	1	90.0%	323	87	73.1%
8	336	10	2	80.0%	332	147	55.7%	10	6	40.0%	331	204	38.4%
11		10	3	70.0%	343	75	78.1%	10	1	90.0%	337	68	79.8%
14		10	6	40.0%	344	60	82.6%	10	0	100.0%	341	105	69.2%
19		10	1	90.0%	342	84	75.4%	10	0	100.0%	339	82	75.8%
20		10	0	100.0%	342	23	93.3%	10	1	90.0%	342	66	80.7%
21	No OS	10	0	100.0%	339	36	89.4%	10	5	50.0%	338	104	69.2%
22	88	10	1	90.0%	340	38	88.8%	10	9	10.0%	338	108	68.0%
23		10	1	90.0%	344	7	98.0%	10	4	60.0%	342	94	72.5%
24		10	0	100.0%	344	16	95.3%	10	2	80.0%	343	67	80.5%
25		10	0	100.0%	343	3	99.1%	10	0	100.0%	340	94	72.4%
26		10	1	90.0%	343	6	98.3%	10	1	90.0%	340	67	80.3%
27	125	10	3	70.0%	309	22	92.9%	10	2	80.0%	303	99	67.3%
28		10	1	90.0%	303	68	77.6%	10	1	90.0%	303	61	79.9%
40		10	3	70.0%	333	50	85.0%	10	6	40.0%	329	178	45.9%
41	157	10	8	20.0%	333	132	60.4%	10	9	10.0%	330	256	22.4%
42	25	10	1	90.0%	344	26	92.4%	10	1	90.0%	342	59	82.7%
43		10	0	100.0%	343	45	86.9%	10	5	50.0%	342	81	76.3%
48		10	0	100.0%	342	62	81.9%	10	4	60.0%	341	55	83.9%
49	42	10	2	80.0%	342	86	74.9%	10	4	60.0%	342	74	78.4%
51		4	1	75.0%	140	59	57.9%	4	2	50.0%	136	54	60.3%
52		10	2	80.0%	341	49	85.6%	10	4	60.0%	340	81	76.2%
53		10	1	90.0%	341	41	88.0%	10	5	50.0%	340	111	67.4%
55		7	0	100.0%	218	9	95.9%	7	0	100.0%	215	46	78.6%
56		7	0	100.0%	219	25	88.6%	7	4	42.9%	215	44	79.5%
58	105	10	0	100.0%	317	17	94.6%	10	10	0.0%	315	107	66.0%
59	73	10	3	70.0%	316	54	82.9%	10	9	10.0%	311	90	71.1%
63	33	10	3	70.0%	345	147	57.4%	10	10	0.0%	339	207	38.9%
64	22	10	1	90.0%	343	72	79.0%	10	5	50.0%	342	138	59.6%
66		10	1	90.0%	342	65	81.0%	10	2	80.0%	337	62	81.6%
67	18	7	0	100.0%	237	14	94.1%	7	1	85.7%	236	41	82.6%
68	53	10	2	80.0%	345	69	80.0%	10	3	70.0%	344	137	60.2%
69		10	3	70.0%	332	82	75.3%	10	3	70.0%	327	59	82.0%
71		10	0	100.0%	340	3	99.1%	10	1	90.0%	338	87	74.3%
72		10	1	90.0%	336	37	89.0%	10	1	90.0%	334	70	79.0%
75		10	3	70.0%	333	20	94.0%	10	3	70.0%	327	154	52.9%
76		10	0	100.0%	333	31	90.7%	10	3	70.0%	323	133	58.8%
77	36	10	1	90.0%	335	22	93.4%	10	3	70.0%	332	136	59.0%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		10	3	70.0%	339	32	90.6%	10	2	80.0%	336	77	77.1%
79		10	0	100.0%	342	59	82.7%	10	4	60.0%	340	116	65.9%
80		10	1	90.0%	342	38	88.9%	10	2	80.0%	339	73	78.5%
84		7	0	100.0%	209	19	90.9%	7	1	85.7%	205	49	76.1%
85		7	0	100.0%	220	18	91.8%	7	3	57.1%	220	77	65.0%
86	17	7	0	100.0%	220	16	92.7%	7	3	57.1%	219	124	43.4%
89		10	2	80.0%	340	80	76.5%	10	4	60.0%	338	101	70.1%
90		10	0	100.0%	340	12	96.5%	10	3	70.0%	339	63	81.4%
93		7	0	100.0%	219	21	90.4%	7	4	42.9%	218	59	72.9%
94	21	7	1	85.7%	250	62	75.2%	7	3	57.1%	248	92	62.9%
95		7	1	85.7%	219	7	96.8%	7	4	42.9%	219	86	60.7%
97	52	10	6	40.0%	342	223	34.8%	10	5	50.0%	340	125	63.2%
98		10	2	80.0%	342	30	91.2%	10	4	60.0%	340	127	62.6%
110	Cncld	6	1	83.3%	215	111	48.4%	5	0	100.0%	211	22	89.6%
111		7	0	100.0%	210	37	82.4%	7	0	100.0%	208	22	89.4%
112		7	1	85.7%	210	21	90.0%	7	0	100.0%	209	20	90.4%
113		7	0	100.0%	141	33	76.6%	7	0	100.0%	140	16	88.6%
119	124	7	1	85.7%	207	50	75.8%	7	1	85.7%	205	27	86.8%
125	36	7	0	100.0%	220	12	94.5%	7	4	42.9%	220	88	60.0%
129		7	1	85.7%	219	51	76.7%	7	1	85.7%	219	31	85.8%
130		7	0	100.0%	210	20	90.5%	7	0	100.0%	208	16	92.3%
131		7	0	100.0%	212	57	73.1%	7	0	100.0%	212	39	81.6%
134		7	0	100.0%	220	32	85.5%	7	0	100.0%	219	42	80.8%
136		7	1	85.7%	220	28	87.3%	7	3	57.1%	218	31	85.8%
137	47	7	2	71.4%	217	38	82.5%	6	3	50.0%	216	65	69.9%
138		7	1	85.7%	220	44	80.0%	7	1	85.7%	219	39	82.2%
141		7	1	85.7%	219	5	97.7%	7	1	85.7%	218	38	82.6%
148	45	7	2	71.4%	219	24	89.0%	7	1	85.7%	217	41	81.1%
151	23	10	3	70.0%	341	108	68.3%	10	3	70.0%	340	102	70.0%
170	38	7	0	100.0%	215	12	94.4%	7	1	85.7%	214	31	85.5%
171		7	0	100.0%	220	11	95.0%	7	2	71.4%	220	90	59.1%
172	28	7	1	85.7%	219	20	90.9%	7	4	42.9%	217	73	66.4%
173	68	7	1	85.7%	212	26	87.7%	7	1	85.7%	211	85	59.7%
174		7	0	100.0%	220	23	89.5%	7	2	71.4%	220	54	75.5%
175		7	1	85.7%	220	24	89.1%	7	3	57.1%	220	73	66.8%
176		7	0	100.0%	212	17	92.0%	7	1	85.7%	209	27	87.1%
177		7	1	85.7%	220	29	86.8%	7	2	71.4%	220	50	77.3%
178		7	0	100.0%	220	28	87.3%	7	1	85.7%	218	37	83.0%
179	126	7	1	85.7%	220	26	88.2%	7	4	42.9%	219	80	63.5%
181		7	2	71.4%	216	66	69.4%	7	2	71.4%	213	19	91.1%
182		7	0	100.0%	210	31	85.2%	7	3	57.1%	208	26	87.5%
183		7	1	85.7%	219	63	71.2%	7	1	85.7%	216	45	79.2%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		7	0	100.0%	220	36	83.6%	7	1	85.7%	219	29	86.8%
185		7	3	57.1%	220	44	80.0%	7	0	100.0%	220	18	91.8%
186		7	1	85.7%	219	30	86.3%	7	3	57.1%	218	64	70.6%
190	95	7	4	42.9%	219	79	63.9%	7	1	85.7%	218	45	79.4%
192		7	0	100.0%	217	24	88.9%	7	0	100.0%	217	19	91.2%
193		7	2	71.4%	215	85	60.5%	7	3	57.1%	214	93	56.5%
196		7	2	71.4%	216	25	88.4%	7	0	100.0%	214	17	92.1%
197		7	1	85.7%	220	78	64.5%	7	4	42.9%	220	75	65.9%
198	20	7	2	71.4%	152	19	87.5%	7	3	57.1%	151	25	83.4%
230		10	0	100.0%	178	4	97.8%	10	1	90.0%	178	10	94.4%
232		10	1	90.0%	344	13	96.2%	10	1	90.0%	344	24	93.0%
233	16	8	1	87.5%	303	67	77.9%	8	2	75.0%	302	103	65.9%
234		10	0	100.0%	345	23	93.3%	10	0	100.0%	344	29	91.6%
235		10	1	90.0%	269	43	84.0%	10	1	90.0%	268	61	77.2%
236		10	1	90.0%	329	11	96.7%	10	1	90.0%	328	44	86.6%
237		10	2	80.0%	342	63	81.6%	10	3	70.0%	340	62	81.8%
238		9	1	88.9%	268	24	91.0%	9	1	88.9%	266	23	91.4%
239		10	3	70.0%	343	86	74.9%	10	1	90.0%	342	43	87.4%
240		10	2	80.0%	344	25	92.7%	10	1	90.0%	341	70	79.5%
241		10	4	60.0%	344	86	75.0%	9	3	66.7%	343	84	75.5%
243		10	1	90.0%	280	72	74.3%	10	0	100.0%	279	39	86.0%
244	23	8	3	62.5%	302	15	95.0%	8	5	37.5%	302	70	76.8%
245		10	2	80.0%	225	43	80.9%	10	0	100.0%	224	30	86.6%
280		10	0	100.0%	345	17	95.1%	10	2	80.0%	344	80	76.7%
281		10	0	100.0%	345	40	88.4%	10	2	80.0%	345	62	82.0%
283		10	3	70.0%	345	88	74.5%	10	5	50.0%	345	71	79.4%
284		10	1	90.0%	345	14	95.9%	10	3	70.0%	342	64	81.3%
290		10	1	90.0%	345	53	84.6%	10	4	60.0%	342	141	58.8%
291		10	1	90.0%	344	113	67.2%	10	2	80.0%	340	92	72.9%
300		9	3	66.7%	327	25	92.4%	8	1	87.5%	323	74	77.1%
302		9	2	77.8%	322	36	88.8%	9	5	44.4%	318	95	70.1%
305		10	3	70.0%	326	34	89.6%	9	5	44.4%	320	127	60.3%
307		9	2	77.8%	332	46	86.1%	9	5	44.4%	328	103	68.6%
311	30	10	1	90.0%	337	29	91.4%	10	9	10.0%	331	93	71.9%
316	41	10	1	90.0%	333	25	92.5%	10	10	0.0%	327	111	66.1%
318		10	0	100.0%	343	35	89.8%	10	8	20.0%	340	174	48.8%
319	75	10	1	90.0%	344	21	93.9%	10	10	0.0%	339	203	40.1%
329		8	1	87.5%	244	13	94.7%	8	1	87.5%	244	20	91.8%
330		9	1	88.9%	293	7	97.6%	9	1	88.9%	293	16	94.5%
331		10	2	80.0%	345	35	89.9%	10	2	80.0%	344	46	86.6%
332	20	10	1	90.0%	344	20	94.2%	10	3	70.0%	344	49	85.8%
334		10	0	100.0%	345	11	96.8%	10	1	90.0%	343	44	87.2%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		10	0	100.0%	345	35	89.9%	10	0	100.0%	342	55	83.9%
336	12	10	0	100.0%	344	10	97.1%	10	3	70.0%	342	32	90.6%
337		10	1	90.0%	345	22	93.6%	10	3	70.0%	341	50	85.3%
338		10	0	100.0%	345	54	84.3%	10	2	80.0%	342	106	69.0%
339		10	1	90.0%	345	55	84.1%	10	1	90.0%	345	59	82.9%
341	23	10	2	80.0%	330	53	83.9%	10	2	80.0%	324	55	83.0%
342		10	0	100.0%	345	26	92.5%	10	2	80.0%	343	63	81.6%
351		10	1	90.0%	327	30	90.8%	10	4	60.0%	325	96	70.5%
352	31	10	0	100.0%	311	24	92.3%	10	9	10.0%	305	102	66.6%
353		10	1	90.0%	282	15	94.7%	10	3	70.0%	276	52	81.2%
354		10	1	90.0%	326	38	88.3%	10	5	50.0%	318	121	61.9%
364		10	1	90.0%	334	74	77.8%	10	5	50.0%	328	125	61.9%
365	23	10	0	100.0%	333	13	96.1%	10	4	60.0%	330	128	61.2%
370	24	9	2	77.8%	330	41	87.6%	9	2	77.8%	317	77	75.7%
380		10	0	100.0%	326	30	90.8%	10	1	90.0%	325	73	77.5%
381		9	1	88.9%	340	16	95.3%	9	1	88.9%	337	72	78.6%
382		9	1	88.9%	339	31	90.9%	9	4	55.6%	337	120	64.4%
383	19	10	3	70.0%	331	30	90.9%	9	3	66.7%	327	141	56.9%
390		10	2	80.0%	326	26	92.0%	9	5	44.4%	323	91	71.8%
391		10	0	100.0%	327	14	95.7%	10	7	30.0%	322	95	70.5%
392	36	10	2	80.0%	340	13	96.2%	9	7	22.2%	334	110	67.1%
393		10	3	70.0%	344	22	93.6%	9	6	33.3%	339	110	67.6%
417	49	7	0	100.0%	228	47	79.4%	7	1	85.7%	219	26	88.1%
425		6	0	100.0%	230	7	97.0%	6	0	100.0%	229	7	96.9%
448		10	4	60.0%	269	53	80.3%	10	3	70.0%	265	92	65.3%
449		10	0	100.0%	266	34	87.2%	10	1	90.0%	266	46	82.7%
470	22	7	1	85.7%	243	41	83.1%	7	3	57.1%	237	30	87.3%
471		7	0	100.0%	232	14	94.0%	7	0	100.0%	232	6	97.4%
473		7	1	85.7%	239	16	93.3%	7	0	100.0%	236	10	95.8%
474		8	3	62.5%	236	69	70.8%	7	1	85.7%	220	72	67.3%
475		6	0	100.0%	235	8	96.6%	6	0	100.0%	235	16	93.2%
478		7	1	85.7%	231	37	84.0%	7	1	85.7%	229	29	87.3%
479	21	7	0	100.0%	238	36	84.9%	7	1	85.7%	236	37	84.3%
486		7	1	85.7%	242	36	85.1%	7	0	100.0%	236	61	74.2%
494	32	7	1	85.7%	245	48	80.4%	7	4	42.9%	237	68	71.3%
495		7	0	100.0%	226	4	98.2%	7	0	100.0%	224	3	98.7%
500		10	1	90.0%	319	17	94.7%	10	1	90.0%	316	37	88.3%
502	17	10	1	90.0%	327	20	93.9%	10	4	60.0%	323	65	79.9%
503	55	10	2	80.0%	341	42	87.7%	9	3	66.7%	333	105	68.5%
504	41	10	2	80.0%	345	22	93.6%	10	3	70.0%	343	102	70.3%
505	46	10	3	70.0%	337	46	86.4%	10	6	40.0%	332	97	70.8%
506		10	1	90.0%	340	57	83.2%	9	2	77.8%	331	53	84.0%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507	24	10	0	100.0%	345	49	85.8%	10	3	70.0%	345	118	65.8%
508		9	1	88.9%	339	44	87.0%	9	1	88.9%	335	82	75.5%
509	19	10	3	70.0%	326	18	94.5%	10	3	70.0%	326	74	77.3%
511		10	1	90.0%	321	26	91.9%	10	1	90.0%	320	54	83.1%
516	333	10	2	80.0%	336	37	89.0%	10	5	50.0%	335	151	54.9%
517	37	10	0	100.0%	345	8	97.7%	10	4	60.0%	341	154	54.8%
518	58	10	3	70.0%	345	49	85.8%	10	7	30.0%	343	239	30.3%
519	Cncld	10	2	80.0%	336	11	96.7%	9	4	55.6%	333	76	77.2%
520		7	1	85.7%	201	30	85.1%	7	1	85.7%	196	12	93.9%
521		7	1	85.7%	239	8	96.7%	7	1	85.7%	238	32	86.6%
522		7	2	71.4%	239	45	81.2%	7	1	85.7%	236	25	89.4%
523		7	0	100.0%	239	9	96.2%	7	2	71.4%	238	28	88.2%
524		7	1	85.7%	238	18	92.4%	7	2	71.4%	235	29	87.7%
525		7	1	85.7%	236	17	92.8%	6	1	83.3%	231	16	93.1%
526	62	7	3	57.1%	213	44	79.3%	6	1	83.3%	209	19	90.9%
527		7	0	100.0%	239	10	95.8%	7	1	85.7%	237	41	82.7%
528	14	7	0	100.0%	239	19	92.1%	7	2	71.4%	238	34	85.7%
529		7	0	100.0%	239	13	94.6%	7	1	85.7%	238	66	72.3%
530		7	3	57.1%	193	21	89.1%	6	1	83.3%	192	39	79.7%
531		7	3	57.1%	213	17	92.0%	7	2	71.4%	213	15	93.0%
532		7	3	57.1%	239	60	74.9%	7	2	71.4%	237	37	84.4%
534		7	4	42.9%	198	32	83.8%	7	1	85.7%	195	18	90.8%
535		7	1	85.7%	225	27	88.0%	7	0	100.0%	220	28	87.3%
536		7	3	57.1%	239	67	72.0%	7	1	85.7%	235	42	82.1%
537		7	2	71.4%	208	26	87.5%	7	0	100.0%	202	25	87.6%
538		7	3	57.1%	239	29	87.9%	7	0	100.0%	238	46	80.7%
539	45	7	1	85.7%	193	29	85.0%	7	3	57.1%	193	85	56.0%
540		7	1	85.7%	238	45	81.1%	7	1	85.7%	228	22	90.4%
541		7	1	85.7%	238	26	89.1%	7	1	85.7%	231	42	81.8%
542		7	1	85.7%	238	26	89.1%	7	2	71.4%	235	43	81.7%
543	37	7	3	57.1%	239	31	87.0%	7	6	14.3%	239	79	66.9%
544		7	0	100.0%	237	22	90.7%	7	0	100.0%	233	22	90.6%
545		7	2	71.4%	239	22	90.8%	7	1	85.7%	236	30	87.3%
547	20	7	2	71.4%	239	49	79.5%	7	2	71.4%	239	56	76.6%
548		6	0	100.0%	230	22	90.4%	6	1	83.3%	227	18	92.1%
549		7	0	100.0%	234	27	88.5%	7	0	100.0%	224	20	91.1%
550		7	2	71.4%	193	22	88.6%	7	2	71.4%	193	46	76.2%
551		7	0	100.0%	235	23	90.2%	7	0	100.0%	225	23	89.8%
562	34	10	0	100.0%	336	27	92.0%	10	5	50.0%	331	42	87.3%
564		10	0	100.0%	337	19	94.4%	9	2	77.8%	328	45	86.3%
579		10	0	100.0%	222	14	93.7%	10	3	70.0%	215	48	77.7%
580		10	2	80.0%	337	20	94.1%	10	4	60.0%	330	41	87.6%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591	23	10	3	70.0%	334	29	91.3%	9	4	55.6%	326	53	83.7%
595	27	10	6	40.0%	330	66	80.0%	9	2	77.8%	326	75	77.0%
600		7	0	100.0%	247	9	96.4%	7	3	57.1%	245	25	89.8%
601		7	1	85.7%	230	91	60.4%	7	1	85.7%	227	28	87.7%
605		7	5	28.6%	237	144	39.2%	6	1	83.3%	232	24	89.7%
607		7	1	85.7%	246	31	87.4%	7	1	85.7%	243	26	89.3%
609		7	1	85.7%	237	24	89.9%	7	0	100.0%	236	23	90.3%
622		6	1	83.3%	143	36	74.8%	6	2	66.7%	140	7	95.0%
626		7	1	85.7%	151	21	86.1%	7	1	85.7%	149	19	87.2%
639		7	1	85.7%	217	41	81.1%	7	1	85.7%	215	21	90.2%
640		7	1	85.7%	237	8	96.6%	7	2	71.4%	235	86	63.4%
641		7	1	85.7%	219	44	79.9%	7	5	28.6%	219	32	85.4%
642		7	1	85.7%	235	12	94.9%	7	1	85.7%	234	28	88.0%
643		7	1	85.7%	249	45	81.9%	7	2	71.4%	246	41	83.3%
644	11	7	2	71.4%	241	30	87.6%	7	4	42.9%	239	60	74.9%
645		7	0	100.0%	249	42	83.1%	7	0	100.0%	246	55	77.6%
646		7	4	42.9%	238	60	74.8%	7	4	42.9%	236	117	50.4%
647		7	2	71.4%	249	37	85.1%	7	2	71.4%	247	53	78.5%
648		7	1	85.7%	245	60	75.5%	7	1	85.7%	245	36	85.3%
649	30	7	3	57.1%	250	47	81.2%	7	2	71.4%	246	36	85.4%
650		7	1	85.7%	249	46	81.5%	7	3	57.1%	246	42	82.9%
651		7	1	85.7%	249	18	92.8%	7	1	85.7%	246	44	82.1%
652		7	0	100.0%	250	31	87.6%	7	2	71.4%	246	43	82.5%
653		7	2	71.4%	238	38	84.0%	7	3	57.1%	234	44	81.2%
654		7	0	100.0%	239	44	81.6%	7	1	85.7%	235	21	91.1%
655		7	3	57.1%	247	77	68.8%	7	2	71.4%	244	78	68.0%
656		7	2	71.4%	249	56	77.5%	7	1	85.7%	247	34	86.2%
657		7	0	100.0%	238	29	87.8%	7	1	85.7%	236	31	86.9%
658		7	1	85.7%	249	38	84.7%	7	0	100.0%	247	35	85.8%
680		8	0	100.0%	245	12	95.1%	8	0	100.0%	243	27	88.9%
681	12	8	0	100.0%	245	18	92.7%	8	2	75.0%	238	95	60.1%
682		8	1	87.5%	244	10	95.9%	8	0	100.0%	244	42	82.8%
683		8	0	100.0%	227	18	92.1%	8	2	75.0%	226	77	65.9%
684		8	0	100.0%	226	37	83.6%	8	1	87.5%	226	48	78.8%
685		8	0	100.0%	241	33	86.3%	8	1	87.5%	238	56	76.5%
686		8	0	100.0%	246	39	84.1%	8	1	87.5%	245	53	78.4%
687		8	0	100.0%	245	38	84.5%	8	0	100.0%	244	40	83.6%
688		8	0	100.0%	244	15	93.9%	8	0	100.0%	243	41	83.1%
701	32	10	1	90.0%	277	31	88.8%	10	3	70.0%	274	35	87.2%
702		10	2	80.0%	344	38	89.0%	9	4	55.6%	340	87	74.4%
703	39	10	4	60.0%	345	116	66.4%	10	5	50.0%	343	105	69.4%
704	71	10	3	70.0%	276	52	81.2%	10	5	50.0%	268	64	76.1%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710	31	10	3	70.0%	345	82	76.2%	8	5	37.5%	339	93	72.6%
711	56	10	1	90.0%	336	39	88.4%	10	3	70.0%	313	68	78.3%
712	29	10	4	60.0%	342	95	72.2%	10	6	40.0%	332	120	63.9%
713	Cncld	9	3	66.7%	211	23	89.1%	6	5	16.7%	183	85	53.6%
714	32	10	7	30.0%	226	99	56.2%	9	7	22.2%	209	102	51.2%
715	93	10	2	80.0%	344	65	81.1%	8	6	25.0%	313	161	48.6%
716	Cncld	10	7	30.0%	345	150	56.5%	9	7	22.2%	335	148	55.8%
717	30	9	4	55.6%	329	83	74.8%	9	6	33.3%	304	104	65.8%
718	65	10	9	10.0%	345	187	45.8%	10	8	20.0%	342	137	59.9%
719	47	10	5	50.0%	345	118	65.8%	9	5	44.4%	327	103	68.5%
757		10	0	100.0%	130	7	94.6%	10	1	90.0%	129	15	88.4%
761		10	1	90.0%	341	14	95.9%	10	1	90.0%	338	45	86.7%
765	25	10	2	80.0%	341	27	92.1%	10	5	50.0%	341	51	85.0%
769		10	1	90.0%	341	28	91.8%	10	6	40.0%	334	71	78.7%
770		10	2	80.0%	341	27	92.1%	10	5	50.0%	338	109	67.8%
774		10	0	100.0%	341	17	95.0%	10	6	40.0%	339	86	74.6%
777		10	2	80.0%	226	15	93.4%	10	9	10.0%	225	67	70.2%
782		10	7	30.0%	226	112	50.4%	10	3	70.0%	221	39	82.4%
785	17	10	1	90.0%	341	30	91.2%	10	7	30.0%	341	68	80.1%
786	No OS	10	1	90.0%	130	24	81.5%	8	6	25.0%	124	72	41.9%
790	No OS	10	0	100.0%	341	31	90.9%	9	4	55.6%	337	58	82.8%
794		10	1	90.0%	341	41	88.0%	10	3	70.0%	337	79	76.6%
821		9	0	100.0%	338	6	98.2%	9	3	66.7%	338	143	57.7%
822	17	10	1	90.0%	341	19	94.4%	9	7	22.2%	338	177	47.6%
1333	109	10	2	80.0%	341	42	87.7%	10	3	70.0%	338	115	66.0%
1340		10	0	100.0%	340	7	97.9%	10	0	100.0%	339	56	83.5%
1689		4	0	100.0%	115	6	94.8%	5	0	100.0%	115	14	87.8%
2102		7	0	100.0%	96	16	83.3%	7	0	100.0%	95	7	92.6%
2103		7	0	100.0%	160	14	91.3%	7	1	85.7%	159	11	93.1%
2104		7	0	100.0%	186	10	94.6%	6	0	100.0%	183	13	92.9%
2105		7	0	100.0%	8	1	87.5%	7	0	100.0%	8	0	100.0%
2107		6	0	100.0%	216	35	83.8%	6	0	100.0%	213	21	90.1%
2108	Cncld	7	1	85.7%	217	29	86.6%	6	0	100.0%	210	27	87.1%
2109		7	2	71.4%	110	15	86.4%	7	0	100.0%	108	6	94.4%
2112		7	0	100.0%	57	6	89.5%	7	0	100.0%	55	2	96.4%
2113		7	1	85.7%	96	10	89.6%	7	1	85.7%	96	11	88.5%
2115		7	2	71.4%	96	15	84.4%	6	0	100.0%	94	12	87.2%
2116		7	0	100.0%	57	1	98.2%	7	0	100.0%	57	8	86.0%
2118		7	0	100.0%	57	4	93.0%	7	0	100.0%	57	12	78.9%
2120		7	1	85.7%	57	20	64.9%	7	0	100.0%	55	23	58.2%
2123		7	2	71.4%	95	12	87.4%	7	0	100.0%	94	15	84.0%
2124		7	0	100.0%	188	38	79.8%	7	0	100.0%	186	24	87.1%

Amtrak On Time Performance

Trains Arriving Through: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2126		7	1	85.7%	105	27	74.3%	7	0	100.0%	104	22	78.8%
2127		7	0	100.0%	57	10	82.5%	7	0	100.0%	56	9	83.9%
2128		7	1	85.7%	57	5	91.2%	7	0	100.0%	57	3	94.7%
2131		7	0	100.0%	57	10	82.5%	7	0	100.0%	57	6	89.5%
2150		7	0	100.0%	210	22	89.5%	7	0	100.0%	207	75	63.8%
2151		7	0	100.0%	159	7	95.6%	7	3	57.1%	157	44	72.0%
2152		7	0	100.0%	115	7	93.9%	7	0	100.0%	114	31	72.8%
2154		7	1	85.7%	118	24	79.7%	6	1	83.3%	113	46	59.3%
2155		7	0	100.0%	219	17	92.2%	7	1	85.7%	215	103	52.1%
2156		7	0	100.0%	8	0	100.0%	7	2	71.4%	8	2	75.0%
2158		7	0	100.0%	56	6	89.3%	7	1	85.7%	56	17	69.6%
2159		7	1	85.7%	212	17	92.0%	7	2	71.4%	210	71	66.2%
2160		7	1	85.7%	57	3	94.7%	7	1	85.7%	56	29	48.2%
2162		7	0	100.0%	218	23	89.4%	7	0	100.0%	212	91	57.1%
2163	53	7	0	100.0%	170	17	90.0%	7	5	28.6%	164	74	54.9%
2165		7	0	100.0%	54	4	92.6%	7	1	85.7%	54	22	59.3%
2167	26	7	1	85.7%	205	21	89.8%	7	2	71.4%	205	43	79.0%
2171		7	1	85.7%	146	11	92.5%	7	2	71.4%	142	25	82.4%
2190		7	0	100.0%	215	29	86.5%	7	0	100.0%	213	24	88.7%
2193		6	1	83.3%	209	27	87.1%	6	1	83.3%	207	51	75.4%

Amtrak Endpoint OTP Details

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/10/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	Trn Cancelled							
2163	WAS	53	ENG	32	ENG	32	NWK-NWK	AM	Other electrical failure, 2149 NG NP, MECHAINCAL ISSUES IN STATION
2167	WAS	26	DSR	15	DSR	15	NHV-STM	MN	Per bulletin Control Point, 273/234, 30, 1/2
67	NPN	18	TRS	145	TRS	115	BBY-RTE	AM	Trespasser strike, Milepost, BBY, RTE, Trespasser strike trk 1 at Sharon Station
86	NYP	17	CTI	29	CTI	15	WDB-ALX	CS	Follow vre310, Other, cfp91.3-105.0
94	BOS	21	OTH	17	POL	10	NWK-NWK	AM	On-train police or DEA activity, EMS NEEDED FOR PSNGR
110	NYP	Trn Cancelled							
119	WAS	124	ENG	77	ENG	31	EWB-TRE	AM	Cab signal failure, 602 EX ES, CAB SIGANL FAILURE ON ENG.602
125	NPN	36	FTI	33	FTI	33	RVR-RVM	CS	Follow W018-09, Milepost w/Letters, SRN 3.5, CA 84.7
137	WAS	47	ITI	51	ITI	37	BOS-BOS	AM	Service, turn, or wye train, 190, late turn
148	SPG	45	CAR	38	CAR	38	PHL-PHL	AM	Electrical failure, 81537 AX AN, MET WITH MECH A/C NO POWER TO LAST CAR; MECH COULD NOT FIX THE ISSUE AND BACK IN THE MOVE
151	RNK	23	DCS	17	ENG	14	WAS-WAS	AM	Air / Brake, 61 DX BD, Diesel needed brake pipe hose repair
170	BOS	38	MBO	30	MBO	26	BRP-NHV	MN	For maritime traffic Held west of cp 261, Control Point, cp261
172	BOS	28	TRS	31	TRS	31	NYP-NYP	AM	Trespasser strike, Other, NYP, NECESSARY TO RUN AROUND TRAIN EQUIPMENT F/SSYD A/C EARLIER TRESPASSER STRIKE
173	WAS	68	ENG	29	CAR	26	BOS-BOS	AM	Door, 43361 AX MF, door problems throughout consist, late release from the yard.
179	PHL	126	ITI	114	ITI	114	BOS-BOS	AM	Service, turn, or wye train, 182, Late turn
190	BOS	95	ITI	72	ITI	72	PHL-PHL	AM	Service, turn, or wye train, 177
198	NYP	20	OTH	24	SMW	13	NWK-NYP	AM	Scheduled in track usage program, Other, XBH-NYP, SINGLE TRACKING IN THE NORTH TUBE A/C THE SOUTH TUBE O/O/S.

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
417	NHV	49	DCS	43	DCS	28	MDN-WFD	AM	T.O.L, Milepost w/Letters, MDN, WFD, TOL trk 1 Holt to Willow. Ran restricted speed. Stop and Protect 4 crossings.
470	HFD	22	CON	16	CON	16	NHV-NHV	AM	Hold for connecting train
479	NHV	21	WTR	8	SVS	6	SPG-WNL	AM	Planned set out / pick out of locomotives, cars or section of train, C&S clearing crossing to be back in service
494	GFD	32	DCS	27	DCS	27	STS-WFD	AM	T.O.L, Milepost w/Letters, STS, WFD, SPG dspr rpts TOL trk 1 btwn Holt & Cedar and crossing out of order MP 10.6 and MP 12.3
644	NYP	11	SMW	15	DBS	11	PHL-XHM	AM	Animal strike, Control Point, N PENN, LOST CATENARY POWER A/C BIRD STRIKE
649	HAR	30	MTI	22	POL	21	NYP-NYP	AM	Removal of passenger by police, HELD TO REVERSE BACK INTO STATION A/C DISRUPTIVE PASSENGER
681	BRK	12	PTI	16	PTI	14	POR-FRE	CS	Meet 684, Control Point, Congress
63	TWO	33	ENG	21	ENG	21	NYP-NYP	AM	Air / Brake, 99, UNABLE TO GET GOOD BRAKE TEST
64	NYP	22	ADA	14	SVS	11	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train Other, ALB
68	NYP	53	PTI	39	DBS	32	POH-POH	DH	Debris strike Tree hit brake cylinder valve., Tree, Milepost, 138, 138
233	ALB	16	DMW	8	DMW	8	YNY-CRT	MN	Waiting for MW clearance Normal procedure for working limits stop sign on metro north. With a combination of 30mph through the working limits, Milepost, 26.9, 28.7
244	NYP	23	ENG	23	ENG	23	ALB-ALB	AM	Traction motor Locked axle alarm traction motor #1, 85
49	CHI	42	FTI	57	SVS	27	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train
42	NYP	25	SVS	18	SVS	18	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, SET OUT DIESEL ENG, ADDED ELECTRIC ENG; YP CREW LATE WITH EQUIPMENT
77	CLT	36	DSR	44	DSR	37	DNC-BNC	NS	Per bulletin Milepost, 27.2, 25.5, 25, mt, Milepost, 24.7, 22.5, 10, Mt, Milepost, 22.5, 21.8, 25, Mt
97	MIA	52	DSR	51	ENG	41	WAS-WAS	AM	Air / Brake, 39, MAIN RES PIPE BROKEN
41	MIA	157	FTI	111	ENG	74	CHI-CHI	AM	Waited for inbound train 6 engine 383 Late release of equipment, 383

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
526	SAC	62	TCR	66	TCR	66	RIC-RIC	UP	Wheelchair lift C8031, Foot pedal bad order, unable to swing lift back into car and thus unable to close the door.
528	SAC	14	PTI	22	PTI	16	BKY-RIC	UP	Meet 531, Control Point, RV009
539	SJC	45	ITI	18	ITI	18	SAC-SAC	UP	Service, turn, or wye train 526
543	SJC	37	CTI	15	CTI	15	GAC-SCC	UP	Meet Ace, Control Point, CO044
547	SJC	20	PTI	25	PTI	10	EMY-OKJ	UP	Wait for station track Amtk 715, Other, OKJ
502	SEA	17	PTI	20	PTI	20	VAN-KEL	BN	Meet 503, Control Point, Kelso South
503	EUG	55	MBO	57	MBO	57	VAN-PDX	BN	Open then signal problems Bridge, willamette Br
504	SEA	41	DCS	46	DCS	42	PDX-VAN	BN	Drawbridge signal issues. Signalman having to walk route of every train before talking them by, us included. Control Point, Willbridge, Control Point, Willamette River
505	PDX	46	DCS	23	DCS	14	VAN-PDX	BN	Drawbridge stuck open Bridge, Willamette Draw
507	EUG	24	FTI	41	FTI	14	PDX-ORC	UP	Meet 508, Siding, clackamas
509	PDX	19	FTI	12	PTI	10	TAC-XNI	ST	Meet 14, Control Point, Rill
516	VAC	333	FTI	328	FTI	321	X8B-XF2	BN	Held at Colebrook due to CN 8709West ran through switch and red board per RTC. Control Point, Colebrook, CN 8907
517	PDX	37	OTH	22	PTI	17	MVW-STW	BN	Meet They were late so we were late., Amtrak 516, Control Point, Logan
518	VAC	58	MBO	59	MBO	53	X8B-XF2	BN	For maritime traffic Bridge, FRB
519	SEA	Trn Cancelled							
58	CHI	105	DSR	138	DSR	31	HMD-MCB	CC	Per dispatcher (radio/phone) Milepost, 854.5, 854.3, 30, main, Milepost, 814.7, 814.3, 25, main, Milepost, 849, 823, 40, main
59	NOL	73	DSR	125	DSR	26	MCB-HMD	CC	Per dispatcher (radio/phone) Milepost, 823, 849, 40, main
7	SEA	138	POL	108	POL	108	MAL-HAV	BN	Hold for 8(08) trespasser strike at MP 388.4 Siding, Dodson
8	CHI	336	TRS	148	TRS	148	HAV-MAL	BN	Vehicle strike Milepost, 388.4, 388.4
27	PDX	-12	PTI	23	PTI	12	SPK-XPW	BN	Follow 7, Control Point, Spokane St

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/10/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	17	DSR	39	DSR	27	FTW-GLE	BN	Per bulletin Milepost, 346.1, 346.5, 25, m1, Milepost, 355.6, 355.5, 40, m2, Milepost, 356.4, 356.7, 60, m2, Milepost, 357.3, 357.6, 29, m2, Milepost, 369.5, 370.2, 60, m, Milepost, 371, 372.5, 60, m, Milepost, 374, 374.1, 60, m, Milepost, 374.7, 375.2, 60, m, Milepost, 375.2, 376.8, 60, m, Milepost
332	CHI	20	DCS	12	DCS	6	GLN-GLN	ME	PTC disengaged Every time engineers pulled the throttle PTC kept disengaging, became active about 3 times and kept dropping got permission from Metra cad manager to run with PTC disengaged 9:23 MPR, Milepost, 17.4, 17.4
336	CHI	12	CTI	11	CTI	8	GLN-XWA	ME	Follow Metra, 2118, Control Point, XRO
341	MKE	23	ENG	19	ENG	19	CHI-CHI	AM	Add engine 519 519
352	PNT	31	DSR	33	CAR	23	JXN-ARB	MI	Air / Brake / Wheel ID4011, ID4602, ID4126, Replaced both gaskets on 4011 A and B end main res.
365	CHI	23	DSR	49	DSR	19	DRD-LNS	CC	Per bulletin Milepost, 245.34, 245.34, 60, MAIN, Milepost, 241.4, 235.7, 30, MAIN, Milepost, 241.05, 240.1, 25, MAIN ONE, Milepost, 240.03, 263.2, 25, MAIN ONE, Milepost, 231.08, 231.08, 30, MAIN
370	GRR	24	FTI	20	ENG	11	CHI-CHI	AM	Waiting for the daily inspection 324
562	SAN	34	CTI	26	CTI	17	OSD-SOL	SN	Follow Milepost, 226, 241, nctd
591	LAX	23	CON	10	CON	10	IRV-IRV	SC	Hold for thruway bus
595	LAX		DCS	4	DCS	4	ANA-XFT	BN	Restrictive signal(s) from unknown cause Red, Control Point, Fullerton JCT
765	SLO	25	CTI	32	CON	27	IRV-IRV	SC	Hold for bus with passengers from train Hold for 3 busses from OSD
785	GTA	17	PTI	35	PTI	33	VNC-VNC	SC	Meet VNC Station, Amtk 786/790, Milepost, 455.05, 455.05
786	SAN	No OS Rpt	ENG	211	ENG	115	SIM-CWT	SC	Traction motor C2115
790	SAN	No OS Rpt	SYS	82	SYS	82	SIM-CWT	SC	Blocked by or assisting another, disabled Amtrak train Rescuing Amtrak 786, Control Point, Davis
701	SAC	32	PTI	26	PTI	26	TRK-MOD	BN	Shuffle M2xMTxM1 AMT 710, Control Point, East Empire
703	SAC	39	PTI	54	PTI	31	MCD-TRK	BN	Wait for station track Shuffle with Amtrak 718 at denair, amtrak 718, Control Point, denair

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/10/2026

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
704	BFD	71	FTI	25	FTI	16	LOD-SKT	UP	Meet UP 5436, Control Point, CPSP073 South Lodi
710	BFD	31	PTI	35	PTI	14	ACA-SKN	BN	Meet AMTK 711 running late due to near miss at Modesto., AMTK 711, Control Point, Holt
711	OKJ	56	FTI	20	FTI	18	TRK-MOD	BN	Blocked from station track Shuffle with AMTK 702, BNSF, Control Point, E. Modesto Empire
712	BFD	29	PTI	47	PTI	31	MOD-TRK	BN	Meet 713, Control Point, E Empire
713	OKJ	Trn Cancelled	FTI	28	FTI	21	HNF-FNO	BN	Meet BNSF 3945, Control Point, Fresno Switch, Z Train
714	BFD	32	PTI	31	PTI	22	MDR-FNO	BN	Meet amtrak 717, Siding, e. figarden
715	OKJ	93	PTI	38	FTI	21	TRK-MOD	BN	Blocked from station track Switching, bnsf 7935, Control Point, west empire
716	BFD	Trn Cancelled	TEN	15	TEN	15	OKJ-OKJ	UP	Tazzy had to pump toilet causing delay Additionally issue with door lights at OKJ per Justin Nadderman cut out door lights 90278
717	OKJ	30	FTI	22	PTI	17	BFD-WAC	BN	Meet 710, Siding, Wasco
718	BFD	65	DCS	29	DCS	29	WAC-BFD	BN	Restrictive signal(s) from known wayside signal failure Take duo control switches into hand operation., Stop, Control Point, Gomez
719	OKJ	47	PTI	38	PTI	18	BFD-WAC	BN	Meet AMT712, Siding, W WASCO
3	LAX	32	FTI	135	SVS	94	NDL-BAR	BN	Pick up equipment Picked up repaired sleeper 32039 from spur track. Had to wait to let a number of freight moves use the control point at West Amboy., Control Point, Wezt Amboy
21	SAS	No OS Rpt	TRS	458	TRS	458	ARK-HOP	UP	Vehicle strike Milepost, 417, 417
22	CHI	88	WTR	164	WTR	105	ACD-XGA	UP	Trees down Milepost, 20, 15
383	QCY	19	FTI	16	CTI	6	LAG-NPV	BN	Cross over or go around Stop signal at Fairview, before diverging clear; nothing on MT 2 between Highland and Fairview, Metra, Control Point, Fairview, Control Point, Lisle
392	CHI	36	FTI	27	PTI	16	MAT-CHM	CC	Meet amtrak 393, Control Point, north tuscola
311	KCY	30	DSR	24	DSR	10	WAR-LEE	UP	Per bulletin Milepost, 229, 229.5, 25, m, Milepost, 234.75, 235.65, 15, m, Milepost, 241.15, 241.8, 30, m
316	STL	41	DSR	27	ENG	10	LEE-WAR	UP	Undesired emergency application ID4604
319	KCY	75	FTI	75	FTI	35	IDP-XRC	UP	Follow unk, Control Point, xrc

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/10/2026

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1333	MSP	109	ENG	71	ENG	71	CHI-CHI	AM	Set out defective locomotive Was having PTC issues on 332 took it off and replaced it with another car 34113, 518

Amtrak Initial Terminal Details

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/10/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	244	09/10	23	23	Traction motor Locked axle alarm traction motor #1, 85
ALB	448	09/09	22	22	Hold for connecting train 48
BOS	137	09/10	51	37	Service, turn, or wye train, 190, late turn
BOS	137	09/10	51	14	Service, turn, or wye train, 190, Late turn
BOS	173	09/10	26	26	Door, 43361 AX MF, door problems throughout consist, late release from the yard.
CLT	78	09/10	8	8	Service, turn, or wye train 77
HAR	646	09/10	4	4	PTC - Stop Bypass Permission Required, Control Point, HAR
HAR	658	09/10	1	1	Wait for scheduled departure time
HFD	473	09/10	8	8	Service, turn, or wye train, 470
MIA	40	09/10	31	31	Air / Brake / Wheel 68015, Wheel trued
MTR	68	09/10	3	3	Air / Brake Brake pressure was at zero. Had to restore brake pressure and do a class 2., 117
NYP	49	09/10	5	5	Disabled train ahead, Other, NYP, HELD IN SUBS FOR TRACK SPACE A/C AM19 DISABLED IN NORTH TUBE
NYP	63	09/10	21	21	Air / Brake, 99, UNABLE TO GET GOOD BRAKE TEST
NYP	63	09/10	21	21	Mechanical Assessment
NYP	89	09/10	3	3	Water, commissary, toilet/trash dumping, LATE RELEASE BY CATERING
NYP	97	09/10	39	39	Planned set out / pick out of locomotives, cars or section of train, LATE RELEASE F/SSYD A/C NECESSARY TO WAIT FOR AM98 FOR COACH CAR AND SERVICING TO COMPLETE CONSIST
NYP	172	09/10	31	31	Trespasser strike, Other, NYP, NECESSARY TO RUN AROUND TRAIN EQUIPMENT F/SSYD A/C EARLIER TRESPASSER STRIKE
NYP	185	09/10	(Trn Cxld)		Car Issue
NYP	245	09/10	13	13	Service, turn, or wye train, 68
NYP	649	09/10	29	8	Disabled train ahead, Other, NORTH TUBE, HELD FOR SINGLE TRACKING A/C AM19 DISABLED IN NORTH TUBE.
NYP	649	09/10	29	21	Removal of passenger by police, HELD TO REVERSE BACK INTO STATION A/C DISRUPTIVE PASSENGER
PHL	110	09/10	(Trn Cxld)		Equipment Issues
PHL	151	09/10	1	1	Passenger and/or baggage
PHL	190	09/10	72	72	Service, turn, or wye train, 177
WAS	196	09/10	14	14	Unplanned Wye, WYE NEEDED DUE TO IB SHOPPED MTR 602
WAS	2108	09/10	(Trn Cxld)		Car Issue

Amtrak Initial Terminal Details

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/10/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2126	09/10	2	2	Water, commissary, toilet/trash dumping, TRN 2163 AR IN WAS 53" LATE CAUSING A DELAY IN TURNING TRN TO 2126
CHI	3	09/10	39	39	Air / Brake 181, 22, 322
CHI	41	09/10	176	176	Pick up equipment ENG late release of road power ENG 163 at 6:11pm. Upon release, unit needed to eye and was added in the trail. Per CHI glasshouse., Other, CHI station
CHI	50	09/10	168	168	Set out defective locomotive Burnt radiator fan connection, 196
CHI	341	09/10	19	19	Add engine 519 519
CHI	370	09/10	11	11	Waiting for the daily inspection 324
CHI	1333	09/10	81	71	Set out defective locomotive Was having PTC issues on 332 took it off and replaced it with another car 34113, 518
CHI	1333	09/10	81	10	Toilet 34113, Bad bathrooms waited for mechanical to release blue flags
BFD	717	09/10	1		
EUG	504	09/10	1	1	Mobility Impaired Last minute PAX that was hard of walking fell on the platform. She was okay and refused any medical attention. Train was delayed as she was trying to climb up the stairs to the train, was about to deploy the lift, passenger made it aboard without lift.
GTA	782	09/10	13	13	Meet 765, Control Point, CO 358
LAX	4	09/10	19	19	A/C not working properly 138
LAX	14	09/10	37	37	Locomotive Position Swap Swapped trail and lead locomotive positions, 205, 329
OKJ	526	09/10	2	2	Meet 11, Control Point, North Jack London
OKJ	534	09/10	1	1	PTC - On Board Cab Signal or PTC Failure C6964, PTC disengaged on its own 6 mins before departure time. Came back a min later after the departure time.
OKJ	710	09/10	5	5	Door C9027, Per engineer, no door light. No door light from car
OKJ	716	09/10	15	15	Tazzy had to pump toilet causing delay Additionally issue with door lights at OKJ per Justin Nadderman cut out door lights 90278
OKJ	718	09/10	(Trn Cxld)		Third Party Cab Car Failure
SAC	531	09/10	1		
SAC	539	09/10	18	18	Service, turn, or wye train 526
SAC	704	09/10	29	0	RR blocked by trespasser or vehicle strike by another train Held in SAC by UP freight strike at MP 73.82 on Fresno Sub. Instructed to hold in SAC until 1800, and proceed to Lodi until strike further ahead is cleared. Instructed to depart SAC by UP dispatch sooner, 17:49 SAC departure.
SEA	8	09/10	108	108	Service, turn, or wye train 007
SEA	505	09/10	3	3	Air / Brake / Wheel 7811, Unknown reason for emergency application

Amtrak Initial Terminal Details

Late Trains For:

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Region: ALL

Division: ALL

Data Through: 9/10/2026

Terminal	Train	Date	Late	Delay	Cause
SJC	530	09/10	1	1	Passenger and/or baggage
SLO	794	09/10	9	9	Wait for station track 14, 11, Control Point, co249
SNC	595	09/10	(No OS)		
VAC	519	09/10	(Trn Cxld)		Disabled Freight Train

Eastern Region

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	89.7	91.4	90.2	58	6
SEPTA	95.0	86.6	91.5	91.5	217	29
NJT-NED	95.0	91.6	93.9	88.6	358	30
NJT-SED	95.0	100	98.7	97.2	24	0

Operating Highlights

Train 40(09) East of Cumberland, MD - Signal

10SEP26: Train 40(09) operating with engines 182, 136, and 141 customers onboard was delayed 5 miles east of Cumberland, MD on the CSX Cumberland subdivision holding at milepost 173.2 for a CSX PTC system failure. Once the system was operational, train 40(09) was able to proceed west.

Train	Delay	Comment
40(09)	30"	

Train 97(10) L'Enfant Station Washington, D.C. - Police Related

10SEP26: Train 97(10) operating with engines 39, 346, and 205 customers onboard was delayed at L'Enfant Station Washington, D.C. holding for police activity in the surrounding area regarding a suspect being chased.

Train	Delay	Comment
97(10)	45"	

Train 125(10) South of Richmond Main Street, VA - Freight Train Interference

10SEP26: Train 125(10) operating with engine 328 and 147 customers onboard was delayed 0.4 miles south of Richmond, VA on the CSX RFP subdivision following W018-09 from milepost 4.7 to Richmond Main Street Station.

Train	Delay	Comment
125(10)	33"	

Train 77(10) East of Burlington, NC - Temporary Speed Restrictions

10SEP26: Train 77(10) operating with engines NC1869, NC102, and 90 customers onboard was delayed 5 miles east of Burlington, NC on the Norfolk Southern H Line operating through speed restrictions from milepost 26.2 until milepost 23.8.

Train	Delay	Comment
77(10)	37"	

Train 173(10) Wllmington, DE - Engine Failure

10SEP26: Train 173(10) operating with engines 639 and 939 customers onboard was delayed departing Wilmington, DE on the Amtrak PW Line due to safety penalty fault that was unrecoverable. Amtrak management met the train, helped resolve the issue, and rode onboard to Washington D.C. to assist with the equipment if there were any further issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
173(10)	44"	

Train 68(10) Port Henry, NY - Tree Strike

10SEP26: Train 68(10) operating with engines 117 and 90 customers onboard struck a tree near Port Henry, NY on the CPKC Canadian subdivision milepost 116.9 causing the brake cylinder valve to be struck. The crew inspected the equipment and took no exceptions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(10)	32"	

Train 41(08) Lakeland, FL - Freight Train Interference

10SEP26: Train 41(08) operating with locomotives 383-45, 9 cars and 129 customers onboard was delayed 2 miles north of Lakeland Station at MP 852 on the CSX Lakeland subdivision due to freight train interference. CSX freight train was disabled blocking the No.2 track at South Lakeland preventing train 41(08) from proceeding. CSX dispatched a rescue diesel from the yard to shove the train into the clear. Once the freight was clear an open route was established and train 41(08) was able to proceed without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(08)	35"	

Train 686(10) South of Woburn, MA - Tree Strike

10SEP26: Train 686(10) operating with locomotives 101-107, 5 cars and 84 customers onboard was delayed 5 miles south of Woburn Station at MP 7 on the MBTA New Hampshire Main Line after striking a tree with lead locomotive 101. The crew stopped and received track protection to pull the tree clear of the locomotive and the track structure. Once clear train 686(10) was able to proceed without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
686(10)	11"	

Train 148(10) Aberdeen, MD - Car Failure

10SEP26: Train 148(10) operating with locomotive 617, 8 cars and 353 customers was delayed at Aberdeen Station due to a hot journal alarm in locomotive 617. The crew inspected the equipment and took no exceptions. While stopped the crew identified there was no functioning HEP in the business class car 81537. Troubleshooting attempts were unsuccessful and the crew could not resolve the HEP. The train was advanced to Philadelphia without the HEP in the business class car to allow Philadelphia Mechanical to meet and make repairs. After inspecting Mechanical identified a 480 cable issue that was only able to be partially resolved by supplying auxiliary lighting to the coach until the battery eventually depleted. Business class sales were shut down.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
148(10)	38"	

Train 2163(10) Newark, NJ - Engine Failure

10SEP26: Next Gen Acela 2163(10) operating with locomotive TS-95 became disabled at Newark, NJ Station due to multiple faults on lead power car 2149. An Amtrak Road Foreman was on location and assisted the crew with depreparing and repreparing the trainset to clear the faults successfully. Once the train was clear of faults train 2163(10) was able to depart Newark without further delays.

Multiple trains were delayed as a result of train 2163(10) occupying the station platform.

Train	Delay	Comment
2163(10)	33"	
85(10)	09"	
97(10)	10"	
649(10)	14"	
19(10)	10"	

Train 19(10) New York, NY - Car Failure

10SEP26: Train 19 operating with locomotive 657, 8 cars and 124 customers became disabled 1 mile west of New York in the North Tube due to a damaged brake pipe hose on sleeper car 62000 causing an air leak. A rescue motor was dispatched to the location in the North Tube to make repairs. A temporary hose was utilized to make the repair and allow the train to rebuild air appropriately. After the air was rebuilt train 19(10) was able to continue. Washington Mechanical was notified and instructed to make a permanent replacement of the hose while performing the locomotive swap.

As a result of the location of the disabled train 19(10) a single-track route was accessible in the South Tube causing delays to trains departing New York.

Train	Delay	Comment
19(10)	1'11"	
649(10)	08"	Initial terminal delay
97(10)	39"	Initial terminal delay

CSX Heat Orders - Weather

10SEP26: CSX has imposed heat orders in effect between 1pm and 7pm for the following subdivisions: Peninsula, Richmond Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, North End, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
186(10)	09"	
98(10)	33"	
138(10)	04"	
90(10)	21"	
89(10)	19"	
80(10)	18"	
53(10)	07"	
52(10)	09"	
79(10)	19"	
40(10)	49"	
98(09)	13"	
97(09)	27"	
40(09)	53"	
41(09)	21"	
41(08)	46"	

Train 119(10) West of New York, NY - Engine Failure

10SEP26: Train 119(10) operating with locomotives 602, 607, 8 cars and 295 customers onboard was delayed 3 miles west of New York at MP 3 on the Amtrak NYP Line after the Engineer declared cab signal failure and required the cab signals to be cut-out to allow train movement to continue. After the cab signals were cut-out train 119(10) was required to operate per Norac Rule 556 with a maximum authorized speed of 59 mph to Philadelphia losing significant run time. At Philadelphia train 119(10) was wyeed to allow locomotive 602 to operate in trail and locomotive 607 to lead the movement. Train 119(10) departed Philadelphia a second time and was able to operate at maximum authorized speeds to Washington.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
119(10)	1'56"	

Train 40(10) Miami, FL - Initial Terminal Delay - Servicing

10SEP26: Train 40(10) operating with locomotives 140-341, 10 cars and 77 customers onboard was delayed at the initial terminal of Miami due to car 68015 needing to be removed from the inbound consist to have the wheels trued and added back for outbound service. After Mechanical completed their repairs and the train was released the equipment was moved into the station, customers were boarded and train 40(10) departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
40(10)	31"	

Train 190(10) Philadelphia, PA - Initial Terminal Delay

10SEP26: Train 190(10) operating with locomotive 656, 10 cars and 258 customers was delayed at the initial terminal of Philadelphia due to the late arrival of inbound train 177(09) into Philadelphia arriving 3'54" late and the servicing required for daily operations. Once the required servicing and regulatory inspections were completed the equipment was released and positioned in the station for passenger boarding and departed Philadelphia.

Due to the late operation of train 190(10) arriving Boston 1'35" late the equipment turn to train 137(10) resulted in an initial terminal delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
190(10)	1'12"	
137(10)	51"	Initial terminal delay

Train 110(10) Philadelphia, PA - Car Failure

10SEP26: Train 110(10) was cancelled in its entirety due to late operation of train 179(09) combined with the extensive servicing and shopping of coach 82678 for missing door parts and motor 665 for compressor oil leak off the set of equipment.

Train 185(10) was cancelled New York - Philadelphia due to the cancellation of train 110(10).

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77 (03)	50"	
78 (03)	50"	Turn of Late 77 (03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008781, Terminal Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FBI-00731 a 0000000878 in "UNCLASSIFIED" open 9/18/2026 Deadhead between NHV and HFD.

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 657(10) Passenger Removal at Harrisburg, Pennsylvania – Fare Evader***

10SEP26, Passenger on PNR Unknown, traveling from Lancaster, PA to Harrisburg, PA was removed from the train by APD. The trespasser boarded the train and locked themselves in the restroom. When asked for ticket the trespasser stated they did not have the means to pay for a ticket. Amtrak Police notified.

Delay: 657(10) None

Western Region

Operating Highlights

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Train 21(09) East of Fort Worth, TX - System

11SEP26: Train 21(09) was delayed holding at MP621.14, 9.91 miles east of Fort Worth TX station on the TRE Mainline subdivision performing daily inspections on engines 68 and 59. Train 21(09) was back on the move at 117AM CT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	1'13"	

Train 518(10) South of Vancouver, BC - Drawbridge Opening

11SEP26: Train 518(10) was delayed at MP141.1, 13.60 miles south of Vancouver, BC. station on the CN New Westminster subdivision due to the Fraser bridge opening for maritime traffic. Once the traffic cleared and the bridges closed, 518(10) was able to proceed north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518(10)	53"	

Train 21(09) East of Dallas, TX - Freight Train Interference

11SEP26: Train 21(09) was delayed beginning at MP169.5, 49.42 miles east of Dallas TX station on the UPRR Mineola subdivision meeting UPRR freight trains 8926 and 6518.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	32"	

Train 718(10) Turlock-Denair, CA - Disabled Passenger Carry-By

11SEP26: Train 718(10) was delayed at Turlock-Denair, CA station MP1079.5 on the BNSF Stockton Subdivision. A visually /hearing impaired customer was carried by their Modesto scheduled station stop, and the train waited for the family to arrive and pick them up. Train 703(10) was also delayed holding at MP1079.3, unable to work the station until 718(10) departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
718(10)	16"	
703(10)	31"	

Train 7/27(09) East of Whitefish, MT - Engine Failure

11SEP26: Train 7/27(09) was delayed 2 miles east of Whitefish, MT at MP1217.3 on the BNSF Hi Line Subdivision due to a hot bearing detector alarm on trail engine E/337 at MP1212.9. The crew inspected to find sticking brakes that were smoking on E/337. All attempts to release the brakes were unsuccessful, and a mechanical team was requested and dispatched by BNSF from Whitefish in order to assist. Once the mechanical team arrived and brakes successfully released, Train 7/27(09) proceeded west to Whitefish station.

Due to the lead truck on the trail E/337 being cut out, a westward facing freight engine, BN7773 was added at Spokane, WA to provide operative brakes, in order for 7(09) to proceed to Seattle.

Train 319(10) East Kansas City, MO - Freight Train Interference

10SEP26: Train 319(10) was delayed departing initial terminal of Kansas City MO station on the UPRR Sedalia subdivision meeting KCT train UNK. 26-FCI-00731-00000008781 UNCLASSIFIED 9/18/2026

Train	Delay	Comment
319(10)	35"	

Train 41(10) Chicago, IL - Initial Terminal Delay

10SEP26: Train 41(10) was delayed departing initial terminal of Chicago IL station/MP0.0 due to adding engine 163 off Amtrak train 6(08). Engine 163 was removed from train 6(08) and placed on track 14 for servicing. The electric derail on track 14 wouldn't lower. Maintainers responded and manually lowered it. Engine 163 was wye'd and added to train 41(10) in the trail position at 742PM CT. Train 41(10) was released by mechanical and set in the station at 853PM CT. Train 41(10) departed Chicago IL station at 936PM CT 2 hours and 56 minutes later after boarding 178 passengers,

Train	Delay	Comment
41(10)	2'56"	

Train 786(10) South of Lompoc-Surf, CA - Passenger Train Interference

10SEP26: Train 786(10) was delayed at Tangier siding/MP293.6 5.5 miles south of Lompoc-Surf, CA/MP299.2 on the UPRR Santa Barbara subdivision due to meeting Train 765(10).

Train	Delay	Comment
786(10)	43"	

Train 50(10) Chicago, IL - Initial Terminal Delay

10SEP26: Train 50(10) was delayed departing initial terminal of Chicago IL station/MP0.0 due to engine 196 being bad ordered for a burnt radiator fan connection. Replacement engine 169 was released at 611PM CT but due to the electronic derail on track 14 not retracting the engine could not be moved. Maintainers responded and manually lowered it. Bad ordered engine 196 was removed at 648PM CT and replacement engine 169 was added to train 50(10) at 702PM CT. Train 50(10) was released by mechanical and arrived to the station at 810PM CT. Train 50(10) departed at 843PM CT operating 2 hours and 48 minutes late after boarding 119 passengers.

Train	Delay	Comment
50(10)	2'48"	

Train 786(10) Simi Valley, CA - Engine Failure

10SEP26: Train 786(10) 26-FC-00731, 000000008785, E/C2115 UNCLASSIFIED 9/18/2026 at Simi Valley, CA reporting engine E/C2115 was unable to load. The train retained head-end power during this event and there was 113 passengers onboard. The crew contacted an Amtrak Road Foreman and Mechanical personnel to help troubleshoot the issue. After troubleshooting efforts were unable to immediately restore normal operation, a recovery plan was developed for Train 790(10) to rescue Train 786(10) by coupling to the rear and operating as a double draft into Los Angeles (LAX). The plan called for Train 790(10) to separate from Train 786(10) upon arrival at Los Angeles and continue south on its scheduled route. Passengers with onward travel on the original Train 786(10) equipment were directed to transfer to the Train 790(10) section upon arrival in Los Angeles. Due to the delay, there was a make-up section that operated from Los Angeles to San Juan Capistrano, that departed at 7:37 PM-PT, operating 1 hour and 27 minutes late. Once Train 790(10) arrived at Train 786(10) and coupled onto the disabled train, the double draft train 786/790(10) proceeded south to Los Angeles.

Train	Delay	Comment
786(10)	2'45"	
790(10)	1'22"	Rescue 786
786(10)	1'27"	LAX- Make-up section

Train 716(10) Terminated at Emeryville, CA - Third Party Contractor Cab Car Failure

10SEP26: Train 716(10) experienced an initial delay departing Oakland, CA due to the toilet in CC/90278 reaching capacity and requiring servicing. As a result, the train departed OKJ at 2:33 p.m. PT, operating 15 minutes late. Train 716(10) carrying 34 passengers, became stopped at Emeryville (EMY) due to speedometer/PTC issues on CC/90278. The crew worked with TASI Mechanical personnel to troubleshoot the problem, while an Amtrak Road Foreman responded to EMY to assist. As troubleshooting continued, the train's delay increased to approximately 32 minutes. After further evaluation, it was determined that, because of the speedometer issues, Train 716(10) would need to return to Oakland Mechanical Facility (OMF) to have engine E/C2123 added. TASI estimated approximately one hour would be required to prepare the replacement engine, resulting in an anticipated lengthy delay. Passengers were advised that they could rebook on the next available service.

Due to the expected service disruption and extended recovery time, Train 716(10) was subsequently cancelled, officially terminating the train at EMY. The equipment was routed to OMF, where CC/90278 was replaced and engine E/C8309 was assigned to protect the scheduled operation of Train 718(10). Because of the delay associated with equipment servicing and the turn, Train 718(10) was originated from Emeryville, with passengers accommodated on Train 544(10) between OKJ and EMY. In addition, inbound Train 715 equipment was planned to operate deadhead from OKJ to BFD to balance the equipment. The deadhead move was later changed to inbound 717 equipment.

Train	Delay	Comment
716(10)	Terminated EMY	
718(10)	1'23"	Originated EMY

Train 8(10) Seattle, WA - Servicing

10SEP26: Train 8(10) was delayed departing Seattle, WA due to normal servicing and needing to cut away the inbound Airo trainset. Once the trainset was removed, and consist fully serviced, Train 8(10) was released the the station to load 95 customers.

Train	Delay	Comment
8(10)	1'48"	

Train 1333(10) East of La Crosse, WI - Freight Train Interference

10SEP26: Train 1333(10) was delayed beginning at MP280, 3.97 miles east of La Crosse WI station on the CPKC Tomah subdivision meeting BNSF freight train STACNAS.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(10)	31"	

Train 21(09) North of Marshall, TX - Weather

10SEP26: Train 21(09) was delayed beginning at MP490, north of Marshall TX station on the UPRR Little Rock subdivision operating at reduced speed through heat orders. Train 21(09) operated through the heat orders until MP66.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	1'07"	

Train 712(10) West of Turlock-Denair, CA - Passenger Train Interference

10SEP26: Train 712(10) was delayed at East Empire/ MP1087.1 on the BNSF Stockton Subdivision, 7.6 miles west of Turlock-Denair, CA station, meeting 713(10).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(10)	31"	

Train 22(09) South of St. Louis, MO - Weather

10SEP26: Train 22(09), operating with engines 55/150, 7 coaches and 96 customers, was delayed 17 miles south of St. Louis, MO, on UP Desoto subdivision, due to a tree down on the tracks at milepost 15. UP Maintenance of Way crew was dispatched to remove the tree. Once the tracks were clear and inspected, train 22(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(09)	1'45"	

Train 58(10) South of Hazlehurst, MS - Freight Train Interference

10SEP26: Train 58(10) was delayed holding in the Wesson Jct Siding/MP775.4 17.8 miles south of Hazlehurst, MS station on the CN McComb subdivision for a meet with CN Freight train 2316.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(10)	37"	

Train 713(10) Martinez, CA - Third Party Contractor Car Failure

10SEP26: Train 713(10) operating with CDTX2108, 7 cars, cab car 90218, and 44 customers onboard was terminated in Martinez, CA on the UPRR Martinez subdivision due to fluctuating fuel levels and a high temperature reading on the compressor oil. Extra Train 960(10) coupled to the equipment and towed it to Oakland Maintenance Facility. The customers from Train 713(10) were reaccommodated in Train 543(10).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
543(10)	03"	MTZ- Passenger transfer
713(10)	Terminated	MTZ

Train 516(10) South of Vancouver, BC - Freight Train Interference

10SEP26: Train 516(10) operating with engines 186, 9/18/2028, cab car 90252, and 160 customers onboard was stopped at milepost 130.5, 24 miles south of Vancouver, BC on the BNSF New Westminster subdivision due to a CN freight ahead going through a switch and a red block. This had occurred on a single main track area. All train traffic in the area stopped. A relief crew for the freight train was sourced and arrived to the scene. Once the freight train was moved and the switch was spiked, Train 516(10) was able to advance. As a result, Train 519(10) was cancelled entirely with three supplemental buses provided Vancouver, BC to Seattle, WA.

WBS#: B.TR.100150.7163

Train	Delay	Comment
516(10)	5'21"	
519(10)	Cancelled	w/alt bussing

Train 503(10) East of Portland, OR - Drawbridge Opening

10SEP26: Train 503(10) operating with cab car 90253, 3 cars, WDTX1408, and 122 customers onboard was delayed at milepost 5.1, 5 miles east of Portland, OR on the BNSF Fallbridge subdivision due to the Willamette Bridge being opened. After the bridge closed, there were signal issues which prevented the train from being able to operate normally over the bridge. Onsite signalman walked the train across the bridge.

Train 504(10) operating with 135 customers onboard were delayed waiting for 503(10) to cross the bridge before they were walked over the area.

Train	Delay	Comment
504(10)	42"	
503(10)	57"	

Train 19(09) East of Tuscaloosa, AL - Signal

10SEP26: Train 19(09), operating with engine 343/376, 9 coaches and 146 customers, was delayed 8 miles east of Tuscaloosa, AL, on NS AGS South subdivision, due to a switch failure ahead of them. There was NS freight clearing the block ahead and once they were clear, train 19(09) was required to flag through the affected area.

Train	Delay	Comment
19(09)	36"	

Train 6(09) Glenwood Springs, CO - M of W Work

10SEP26: Train 6(09), operating with engines 148/15, 9 coaches, and 186 customers, was delayed departing Glenwood Springs, CO, on UP Glenwood Springs subdivision due to UP Maintenance of Way overstay. Once the Maintenance of Way crew cleared, train 5(09) was given priority into Glenwood Springs station and train 6(09) held until 5(09) entered the station.

Train	Delay	Comment
6(09)	1'30"	

Train 14(10) Los Angeles, CA - Initial Terminal Delay - Engine Failure

10SEP26: Train 14(10) operating with engine 205, 320 cars, and 171 customers was delayed departing Los Angeles, CA on the SCRRA River subdivision due to late release from the yard. The train was delayed being released due to the engines needing to be flat switched to place engine 205 in the lead. Engine 205 needed to be in the lead due to damage to the main res on the front of the engine. Once the engines were switched, the train was released from the yard and boarded. Train 14(10) departed Los Angeles at 10:28 AM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(10)	37"	

Train 58(10) Hammond, LA - Temporary Speed Restrictions

10SEP26: Train 58(10), operating with engine 198, 7 coaches, and 118 customers, was delayed 2.5 miles north of Hammond, LA, on CN McComb subdivision, due to operating through heat restrictions beginning at milepost 856, and ending at milepost 800. Once clear of the restrictions, train 58(10) was able to resume normal speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(10)	35"	

Train 526(10) Richmond, CA - Third Party Contractor Car Failure

10SEP26: Train 526(10) operating with CDTX 8307, 4 cars, CDTX 2013, and 29 customers onboard was delayed in Richmond, CA on the UPRR Martinez subdivision due to the wheelchair lift becoming disabled after use. The crew used the wheelchair lift in car 8301 to assist a customer onto the train and then the foot pedal broke. The crew was unable to close the doors to proceed. Mechanical forces responded to the train and was able to rectify the issue. The train was back on the move at 10:29 AM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
526(10)	1'06"	

Train 3(10) Chicago, IL - Initial Terminal Delay

10SEP26: Train 3(10) was delayed 1 hour 39 minutes departing Chicago, Illinois account engine issues on deadhead E/322. Flags were dropped on Track 13 to unbury E/322 and add it third and non-compliant to Train 3(10). Flags were dropped on Train 3(10) for the engine move at 1047am. Non-compliant E/322 was added and the train respotted to Pit 4 at 1215pm. The train was worked by mechanical, released at 1242pm, and began shoving at 101pm. At 120pm, while boarding 187 passengers, Train 3(10) reported parking brake issues on non-compliant E/322. Mechanical responded to address, clearing at 205pm. Train 3(10) departed CUS at 209pm, 39 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(10)	39"	

Train 1333(10) Chicago, IL - Initial Terminal Delay

10SEP26: Train 1333(10) operating with engines 264, 100731, 0000000878 and 1, 1 UNCLASSIFIED, 9/18/2026, 11 minutes departing Chicago, Illinois account late bad order coach. Prior to the arrival of Train 332(10), the crew reported coach C/34050 running warm and south-facer E/518 experiencing PTC issues. Train 332(10) arrived CUS at 954am, 20 minutes late. Mechanical inspected the reported issues. At 1024am, coach C/34050 was bad order for HVAC failure and E/518 was bad order for PTC wiring faults. No replacement for E/518 was available and coach C/34113 was identified to be added rearmost. Switching began at 1100am and the train was made up complete at 1136am. At 1110am, mechanical reported toilet issues on replacement coach C/34113. Mechanical responded to address, clearing at 1229pm. Train 1333(10) departed CUS at 1231pm, 1 hour 21 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1333(10)	1'21"	

Train 8/28(09) East of Libby, MT - Freight Train Interference

10SEP26: Train 8/28(09) operating with engines 355, 11, 9 cars, and 147 customers onboard was delayed at milepost 1272.2, 48 miles east of Libby, MT on the BNSF Kootenai River subdivision due to meeting BNSF freight trains 6752 and 7091. Once the freight trains cleared, Train 8/28(09) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(09)	36"	

Train 4(09) West of Winslow, AZ - Power Switch Failure

10SEP26: Train 4(09) operating with engines 58, 139, 78, 9 cars, and 152 customers onboard was delayed at milepost 312.1, 26 miles west of Winslow, AZ on the BNSF Seligman subdivision due to a power switch failure at control point West Canyon Diablo. Once the crew hand lined the switches for the move, Train 4(09) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(09)	33"	

Train 3(08) East of Barstow, CA - Servicing

10SEP26: Train 3(08) operating with engines 167, 138, 9 cars, and 141 customers onboard was delayed at milepost 661.7, 84 miles east of Barstow, CA on the BNSF Needles subdivision due to picking up set out car 32039. Mechanical and local management was on scene to assist with the move. Once the car was added to the consist and all necessary procedures followed, Train 3(08) advanced to the next station.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(08)	1'34"	

Train 3(09) East of Dodge City, KS - Signal

10SEP26: Train 3(09), operating with engines 170/792, 9 coaches and 184 customers, was delayed 20 miles east of Dodge City, KS, on BNSF La Junta subdivision, due signal issues which required the train to flag through the affected area. Once clear of the signal issues, train 3(09) was able to resume normal speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(09)	36"	

Train 5(09) Denver, CO - Injured or Sick Passenger or Employee

10SEP26: Train 5(09), 26-FOI-00731, 00000008781, UNCLASSIFIED, 9/18/2026, with engines 106453, 9 coaches and 237 customers, was delayed departing Denver, CO, on UP Greeley subdivision, due to a sick customer requiring EMS attention. 5(09) held waiting for EMS to arrive and once the customer was evaluated by EMS, they declined to be taken off the train and continued their trip.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(09)	35"	

Train 21(09) South of Arkadelphia, AR - Vehicle Strike

10SEP26: At approximately 5:20AM-CT, train 21(09), operating with locomotives 68 and 59, six coaches, and approximately 95 customers, went into emergency at Milepost 417.6 on the Union Pacific Railroad Little Rock Subdivision south of Arkadelphia, Arkansas, after striking a semi-truck. Following the collision, the train remained upright and on the rails, and no injuries were reported among either the crew or customers. Head End Power remained active throughout the incident. Initial inspections indicated possible damage to the lead locomotive, No. 68, and the crew began assessing the extent of the damage while coordinating with CNOC Mechanical.

Local law enforcement responded to the scene, along with Union Pacific management and a track inspector. The operating crew requested relief, and a Union Pacific Road Foreman was dispatched to assist. Union Pacific management later authorized the train to advance and clear up at Curtis Junction, Milepost 422.4. Union Pacific Mechanical personnel were also dispatched to evaluate and repair the damage. Due to the incident and the need for relief personnel and pilots, the train was expected to experience a significant delay. During the service interruption, customer service recovery measures were implemented, including the distribution of snack packs and water to passengers.

As the train remained on hold awaiting a relief crew and pilot crew, Union Pacific Mechanical forces and the Road Foreman worked to restore the damaged safety equipment on the lead locomotive. Repairs included replacing a broken headlight and subsequently repairing both damaged ditch lights. To facilitate the repairs, consideration was given to advancing the train to a nearby crossing where a ladder could be utilized. Throughout this period, freight pilots continued en route to the train.

Once the relief crew and Union Pacific pilot crews arrived, Train 21(09) was successfully recreated. Mechanical forces completed the necessary repairs, including replacing a headlight, repairing both ditch lights, and trimming the locomotive plow. With the required personnel in place and repairs completed, the train was authorized to continue service and departed the incident location at 12:28 p.m. CT.

WBS#: B.TR.100150.7164

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(09)	7'38"	

Train 7/27(09) West of Fargo, ND - Freight Train Interference

10SEP26: Train 7/27(09), operating with engines 335/337, 10 coaches, and 234 customers, was delayed 2 miles west of Fargo, ND, on BSNF Hillsboro subdivision, due to being routed around BNSF7013E. Train 7/27(09) then held for the train to clear into the yard. Once the freight cleared and a route was made available, train 7/27(09) was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(09)	46"	

Train 6(09) West of Granby, CO - Engine Failure

10SEP26: Train 6(09) delayed at MP141.5 west of Granby CO station on the UPRR Glenwood Springs subdivision due to engine 15 shutting down. Crew was able to reset the engine and get it started. Train 6(09) was back on the move at 440PM MT. Train 6(09) was delayed again at MP103.6 west of Granby, CO. due to engine 15 shutting down for a second time. Crew called in to troubleshoot with CNOC mechanical. The crew was able to get the engine restarted for a second time and was back on the move at 626PM MT. A BNSF Freight engine was requested to be added at Denver CO station and engine 7757 was set out for train 6(09). Train 6(09) arrived to Denver CO station and added BNSF freight engine 7757. Train 6(09) departed Denver CO station at 1107PM CT 4 hours and 8 minutes late after completing their daily inspections.

Train	Delay	Comment
6(09)	1'07"	
6(09)	35"	Daily Inspections
6(09)	19"	Add Freight

Midwest Service Adjustments Chicago, IL - Engine Failure

08SEP26: Due to locomotive availability and foreseen maintenance. As a result, the following trains were cancelled in their entirety with customer service working to source alternate transportation:

Lincoln Service: 307(08), 302(09), 301(10), and 306(10). Three buses were confirmed for 307(08), 305(12), 300(13). Four buses were confirmed for 302(09). 4 busses were confirmed for 306(10). One bus confirmed for 301(10)

Pere Marquette: 370(09), 371(10), 370(11), and 371(12). Two buses were confirmed for 370(09). Two buses were confirmed for 370(11). Two buses were confirmed for 371(10). Three buses were secured for 371(12)

Carl Sandburg: 381(09), 382(09), 381(11), and 382(11), 381(13), 382(13). One bus was confirmed for 381(09). bus was confirmed for 381(11). One bus confirmed for 382(09). One bus confirmed for 381(13).

Wolverine: 350(10) and 355(10). Two buses were confirmed for 350(10).

WBS#: B.TR.100150.7158

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

05SEP26: High tides along the Southern California coast caused track indication issues between San Clemente Pier (MP 204.8) and CP SONGS (MP 209.5) on the Metrolink Orange Subdivision, requiring trains to operate at restricted speed and flag through the affected territory. Metrolink personnel conducted track inspections following each train movement through the area, resulting in significant congestion and delays to Pacific Surfliner service.

The incident resulted in the following service impacts and recovery actions:

- Train 581(05), carrying 244 customers onboard, was delayed at CP SONGS (MP 209.5) while awaiting authorization to proceed through the affected territory under restricted-speed conditions.
- Train 580(05), carrying 373 customers onboard, was delayed at San Clemente Pier Station (MP 204.9) before proceeding through the area under flag protection.
- Train 785(05), carrying 374 customers onboard, was delayed at CP SONGS while awaiting the passage of Train 580(05) before proceeding toward San Clemente Pier.
- Train 587(05), carrying 410 customers onboard, was delayed at CP SONGS while awaiting track inspections and clearance through the affected territory.
- Train 782(05), carrying 411 customers onboard, was delayed at CP Serra (MP 199.7)

-Train 588(05), carrying 106 customers onboard, experienced delays approaching the affected territory.

-Train 591(05) experienced delays approaching and departing Oceanside, CA, due to congestion created by a train operating in the affected territory.

-Train 786(05) encountered downstream delays while operating south toward the affected territory.

To mitigate customer impacts, the following service adjustments were implemented:

-Train 584(05) was terminated at San Juan Capistrano, CA, with customers accommodated on Train 588(05).

-Train 786(05) was terminated at Irvine, CA, after customers detrained at Laguna Niguel/Mission Viejo Station and were accommodated on Train 790(05).

-Train 593(05) was canceled, with customers accommodated on Train 595(05).

-Train 595(05) operated late after turning from the delayed Train 782(05).

-Equipment from Trains 584(05) and 786(05) was returned to Los Angeles, CA.

Additional service adjustments for Pacific Surfliner for 9/6

Trains 566(06), 567(06), 572(06), 573(06), 581(06), 584(06), 588(06), 587(06), 593(06) are canceled entirely with customers to next available services.

Train 782(06) is canceled LAX-SAN, customers to next services.

Train 761(06) is canceled SAN-LAX, customers to next services.

Train 794(06) is canceled LAX-SAN with alternate bus 3594 transportation.

Train 564(06) will term IRV.

Train 595(06) will orig IRV.

Train 580(06) will term IRV.

Train 579(06) will orig IRV.

the following trains will operate a bus bridge between Oceanside (OSD) and Irvine (IRV): 765(06), 562(06), 777(06), 774(06), 591(06), 790(06), 769(06), 770(06), 785(06), 786(06).

6 buses were confirmed for bus bridge segment, and 2-buses for 3594 on both Sunday 9/6 and Monday 9/7.

07SEP26: Pacific Surfliner service resumed normal operations on September 7, 2026. All trains returned to the standard operating plan, with the exception of Train 567(07), due to only three trainsets being available in San Diego, CA.

The following service adjustments were implemented:

-Train 567(07) was canceled, with customers accommodated on Train 769(07).

-Equipment from Los Angeles 8th Street Yard was utilized to operate Train 572(07).

07SEP26: Tracks east of San Clemente Pier, CA, were reopened for service on September 8, 2026; however, high tides later caused washout conditions and recurring signal issues between San Clemente Pier and CP SONGS on the Metrolink Orange Subdivision. Metrolink personnel responded to replace ballast and conduct ongoing inspections of the affected track structure. As a result, Pacific Surfliner trains were required to operate at restricted speeds through the area, causing delays and congestion throughout the corridor.

The incident resulted in the following service impacts and recovery actions:

-Train 579(07), carrying 382 customers onboard, was delayed at Oceanside, CA, while maintenance personnel repaired the affected track. After departing Oceanside, the train incurred additional delays while holding at CP SONGS pending authorization to proceed through the affected territory.

-Train 581(07), carrying 364 customers onboard, was delayed at Oceanside, CA, while awaiting the reopening of the route.

-Train 782(07), carrying 405 customers onboard, was the last train authorized through the affected territory before Metrolink suspended train movements due to worsening tide conditions.

-Train 584(07), carrying 128 customers onboard, was held at Irvine, CA.

-Train 786(07), carrying 258 customers onboard, was held at Santa Ana, CA.

-Train 587(07), carrying 434 customers onboard, was held at Oceanside, CA.

-Train 588(07) was held at Los Angeles, CA.

-Train 591(07) was held at San Diego, CA.

-Trains 588(07) and 790(07) were canceled between Los Angeles and San Diego.
-Train 794(07) operated between Los Angeles and Irvine, where it terminated.
-Seven buses were secured to transport customers from Train 587(07) from Oceanside to Irvine.
26-FOI-00731 00000008781 "UNCLASSIFIED" 9/18/2026
-The same buses were then utilized to transport customers from Trains 584(07) and 786(07) from Irvine to San Diego, making all intermediate station stops.
-The buses were also used to accommodate customers from the canceled Trains 591(07), 593(07), and 595(07).
-Three additional buses were secured for customers requiring transportation south of Irvine from Trains 790(07) and 794(07).

08SEP2026: Pacific Surfliner Service Adjustments for Tuesday, September 8th and September 9th:

Trains 566, 567, 572, 573, 581, 584, 588, 587(08, 09, 10, 11), 593(08, 09,10) and 595(11) are cancelled entirely. Customers will need to book next available services.
Train 782 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, Customers to next available services.
Train 761 (08, 09, 10, 11) cancelled San Diego-Los Angeles, CA, Customers to next available services.
Train 794 (08, 09, 10, 11) cancelled Los Angeles, CA -San Diego, CA, with alternate BUS 3594 Transportation and an additional bus.
Train 564 (08, 09, 10, 11), will terminate in San Juan Capistrano, CA.
Train 595 (08, 09, 10), will originate in San Juan Capistrano, CA.
Train 580 (08, 09, 10, 11), will terminate in San Juan Capistrano, CA.
Train 579 (08, 09, 10, 11), will originate in San Juan Capistrano, CA.
Train 593(11) will originate in Santa Ana, CA
Train 790(11) will operate a Bus Bridge between Santa Ana, CA and Oceanside, CA.
Trains 765, 562, 777, 774, 591, 769, 770, 785, 786(08, 09, 10, 11) and 790(08, 09, 10) will operate a Bus Bridge between Oceanside, CA and Irvine, CA. (**Please note: Trains will operate TO AND SERVICE San Juan Capistrano (SNC) Station- WILL THEN TURN AND MEET BUS BRIDGE AT IRVINE STATION**).
Initially, there were 3 buses providing alternate transportation between Irvine, CA and San Juan Capistrano. Two additional buses were secured account of the high ridership.

WBS#: B.TR.100150.7150

Train	Delay	Comment
-------	-------	---------

584 (05)	Term SNC				
786 (05)	Term IRV				
593 (05)	Canceled				
785 (05)	50"				
587 (05)	2'19"	26-FOI-00731	00000008781	"UNCLASSIFIED"	9/18/2026
584 (05)	52"				
591 (05)	24"			late turn of 580	
591 (05)	2'17"				
782 (05)	3'35"				
588 (05)	2'52"				
790 (05)	2'11"				
595 (05)	2'36"			late turn of 782	
567 (06)	Canceled				
572 (06)	Canceled				
566 (06)	Canceled				
573 (06)	Canceled				
581 (06)	Canceled				
584 (06)	Canceled				
588 (06)	Canceled				
587 (06)	Canceled				
593 (06)	Canceled				
782 (06)	Canceled LAX-SAN				
761 (06)	Canceled SAN--LAX				
794 (06)	Canceled LAX-SAN				
564 (06)	Term IRV				
595 (06)	Orig IRV				
580 (06)	Term IRV				
579 (06)	Orig IRV				
765 (06)	Bus Bridge OSD-IRV				
562 (06)	Bus Bridge OSD-IRV				
777 (06)	Bus Bridge OSD-IRV				
774 (06)	Bus Bridge OSD-IRV				
591 (06)	Bus Bridge OSD-IRV				
790 (06)	Bus Bridge OSD-IRV				
769 (06)	Bus Bridge OSD-IRV				
770 (06)	Bus Bridge OSD-IRV				
785 (06)	Bus Bridge OSD-IRV				
786 (06)	Bus Bridge OSD-IRV				
567 (07)	Canceled				
581 (07)	1'01"				
579 (07)	1'50"				
782 (07)	2'24"				
584 (07)	41"			late turn 579	
584 (07)	Term IRV				
786 (07)	Term IRV				
587 (07)	3'47"			Bus Bridge OSD-IRV	
588 (07)	Canceled				
591 (07)	Canceled				
593 (07)	Canceled				
790 (07)	Term LAX				
595 (07)	Canceled				
794 (07)	Term IRV				
785 (07)	58"				
769 (08)	32"			IRV Bus Connect	
770 (08)	36"			OSD Bus Connect	
765 (08)	19"			IRV Bus Connect	
765 (09)	30"			IRV for bus connections	
769 (09)	25"			IRV Bus connects	
770 (09)	17"			OSD bus connects	
777 (09)	40"			OSD- Bus connection	
765 (10)	27"			IRV Bus Connections	

Maintenance of Way Highlights

Pacific Surfliner/Coast Starlight Scheduled M/W Work TWA 26-089

27JUL26:

To accommodate infrastructure work on the SCRRA Ventura and Orange subdivisions, NCTD San Diego subdivision and the UPRR Santa Barbara subdivision, Amtrak's Pacific Surfliner and Coast Starlight Services will be adjusted as follows:

COAST STARLIGHT

- Train 11(11Sep, 12Sep), which normally operates between SEA and LAX, will terminate at EMY.
- Train 14(12Sep, 13Sep), which normally operates between LAX and SEA, will originate at EMY.
- Alternate transportation will be provided between SAC and LAX via Gold Runner service for Train 11(11Sep, 12Sep)
- Alternate transportation will be provided between LAX and MTZ via Gold Runner service for Train 14(12Sep, 13Sep)

PACIFIC SURFLINER

- ALL Pacific Surfliner Trains on Saturday September 12th and Sunday September 13th are cancelled in their entirety with no alternate transportation.

AFFECTED TRAIN (ORIGIN DATE)

Train 11 (11Sep, 12Sep)
Train 567 (12Sep-13Sep)
Train 573 (12Sep-13Sep)
Train 579 (12Sep-13Sep)
Train 581 (12Sep-13Sep)
Train 587 (12Sep-13Sep)
Train 591 (12Sep-13Sep)
Train 593 (12Sep-13Sep)
Train 595 (12Sep-13Sep)
Train 757 (12Sep-13Sep)
Train 761 (12Sep-13Sep)
Train 765 (12Sep-13Sep)
Train 769 (12Sep-13Sep)
Train 777 (12Sep-13Sep)
Train 785 (12Sep-13Sep)
Train 14 (12Sep-13Sep)
Train 562 (12Sep-13Sep)
Train 564 (12Sep-13Sep)
Train 566 (12Sep-13Sep)
Train 572 (12Sep-13Sep)
Train 580 (12Sep-13Sep)
Train 584 (12Sep-13Sep)
Train 588 (12Sep-13Sep)
Train 770 (12Sep-13Sep)
Train 774 (12Sep-13Sep)
Train 782 (12Sep-13Sep)
Train 786 (12Sep-13Sep)
Train 790 (12Sep-13Sep)
Train 794 (12Sep-13Sep)

Coast Starlight - Scheduled M/W Work 26-090

03AUG26: To accommodate 26-FOI-00739 00000008781 UNCLASSIFIED 9/19/2026 infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep, 12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 009000087811"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
8 (8)	MOT	325		Strike DMG//brake pipe//PTC

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
6 (7)	EMY	UP5727	Dynamic brake	CHI	9/9/26
8 (8)	MOT	UP6662	E/325 strike DMG	CHI	9/10/26
6 (9)	DEN	BNSF7557	E/15 running, loading, air brk comp		
7 (9)	SPK	BNSF7773	E/337 stuck brakes		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
				N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 511(10) Passenger Removal at Olympia-Lacey, Washington –Improper Conduct

10SEP26, Passenger on PNR 024D06, traveling from Olympia-Lacey, WA to Vancouver, WA was removed from the train by CTL police. The passenger roamed the train looking for her crack pipe and paraphernalia to take to the restroom to use. Amtrak Police notified.

Delay: 511(10) 05"

Consist Deviations

26-FOI-00731

00000008781

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
177 (10)	BOS	club dine in lieu of all table cafe			48179
59 (10)	CHI	Operating in reverse consist due to engine move.			39029 32016 37014 33038 34045 34208 31028
364 (10)	CHI	broken PA system, d/h inline. inventory reduced with no overages.			ID4019
600 (10)	HAR	no cab car or cafe car to provide wifi. Extra coach in consist for ridership.			649
622 (10)	HAR	no cab car or cafe car to provide wifi. Extra coach in consist for ridership.			649
172 (10)	NYP	Club dine in lieu of table car.			48179
185 (10)	NYP	Short consist per plan due to car 82678 being shopped for doors, no impact to ridership.			81537
651 (10)	NYP	no cab car or cafe car to provide wifi. Extra coach in consist for ridership.			649
110 (10)	PHL	Short consist per plan due to car 82678 being shopped for doors, no impact to ridership.			81537
365 (11)	PTH	broken PA system, d/h inline. inventory reduced with no overages. CHI will correct on 9/11 for 364.			ID4019

Reverse Consists

Train Number	Station	Reason
171 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front
172 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (10)	PHL	Consist reversed Business class seat orientation may have changed At Front
185 (10)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00731 00000008781 "UNCLASSIFIED"	9/18/2026
86 (11)	NPN	Consist reversed Business class seat orientation may have changed At Front.. **Train 86(11)**	
193 (10)	NYP	Consist reversed Business class seat orientation may have changed At Rear	
137 (10)	BOS	Consist reversed Business class seat orientation may have changed At Front	
178 (11)	RNK	Consist reversed Business class seat orientation may have changed At Front.. **Train 178(11)**	
174 (10)	WAS	Consist reversed Business class seat orientation may have changed At Front	
176 (10)	WAS	Business class change only Business class seating orientation may have changed At Front.. b-end leading	