



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, December 18, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/17/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/17/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	317	56	82.3%	5,154	802	84.4%	23,063	2,992	87.0%
Central Division	85.5%	67	10	85.1%	1,113	186	83.3%	5,135	555	89.2%
Northeast Division	80.0%	101	15	85.1%	1,643	252	84.7%	7,239	1,004	86.1%
Southeast Division	72.5%	74	16	78.4%	1,193	196	83.6%	5,392	713	86.8%
Southwest Division	77.0%	75	15	80.0%	1,205	168	86.1%	5,297	720	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00197 00000005540 UNCLASSIFIED Endpoint Arrival Dates through 12/17/25 12/23/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	96,324	19,157	80%	1,670,844	415,198	75%	7,865,578	1,663,403	79%
Northeast Corridor	81%	44,817	7,001	84%	765,279	187,548	75%	3,556,680	705,432	80%
Acela	83%	10,424	3,010	71%	174,298	53,085	70%	766,498	170,764	78%
Northeast Regional	79%	34,393	3,991	88%	590,981	134,463	77%	2,790,182	534,668	81%
Richmond / Newport News / Norfolk	77%	9,953	1,003	90%	180,197	44,958	75%	846,203	188,463	78%
Springfield Shuttles	89%	920	48	95%	13,536	1,622	88%	47,058	5,317	89%
Roanoke	79%	2,644	165	94%	45,840	8,239	82%	214,593	34,988	84%
On Spine Northeast Regional	80%	20,876	2,775	87%	351,408	79,644	77%	1,682,328	305,900	82%
State Supported	80%	39,204	7,343	81%	701,553	148,994	79%	3,348,227	632,049	81%
Borealis	60%	522	0	100%	9,242	2,538	73%	45,532	12,109	73%
Capitol Corridor	90%	3,563	342	90%	58,416	6,420	89%	277,009	29,816	89%
Carolinian	60%	1,012	117	88%	18,991	6,502	66%	92,137	27,404	70%
Cascades	63%	1,759	1,446	18%	35,566	9,575	73%	181,855	44,912	75%
Downeaster	82%	1,325	165	88%	23,434	3,718	84%	114,692	15,494	86%
Empire	78%	5,285	378	93%	87,131	18,552	79%	403,315	80,097	80%
Adirondack	72%	267	0	100%	4,511	2,122	53%	25,410	8,673	66%
Ethan Allen Express	70%	586	16	97%	9,087	2,417	73%	46,080	13,938	70%
Maple Leaf	70%	767	72	91%	11,145	5,464	51%	46,527	17,252	63%
New York - Albany	85%	2,300	290	87%	40,520	3,980	90%	179,127	23,102	87%
New York - Niagara Falls	75%	1,365	0	100%	21,888	4,569	79%	106,171	17,132	84%
Gold Runner	73%	1,931	975	50%	36,788	12,216	67%	190,836	67,861	64%
Heartland Flyer	65%	122	10	92%	2,854	618	78%	15,363	8,188	47%
Hiawatha	90%	1,730	0	100%	29,479	5,147	83%	135,932	16,062	88%
Illinois	78%	2,197	1,050	52%	39,266	17,005	57%	189,103	56,323	70%
Carl Sandburg / Illinois Zephyr	85%	400	179	55%	7,293	2,358	68%	32,451	8,916	73%
Illini / Saluki	85%	822	712	13%	11,415	5,376	53%	66,239	18,835	72%
Lincoln Service	70%	975	159	84%	20,558	9,271	55%	90,413	28,572	68%
Keystone	92%	9,858	1,708	83%	148,721	23,411	84%	644,299	64,222	90%
Lincoln / Missouri	60%	622	160	74%	12,086	5,842	52%	60,386	30,498	49%
Mardi Gras Service	80%	320	0	100%	6,131	172	97%	33,804	3,931	88%
Michigan	69%	1,907	209	89%	32,819	15,825	52%	152,154	45,713	70%
Blue Water	70%	443	0	100%	7,089	3,771	47%	37,874	11,066	71%
Pere Marquette	85%	236	0	100%	4,410	1,358	69%	20,306	3,287	84%
Wolverine	65%	1,228	209	83%	21,320	10,696	50%	93,974	31,360	67%
Missouri	80%	151	21	86%	3,606	961	73%	18,176	4,497	75%
Pacific Surfliner	85%	4,016	654	84%	102,887	8,132	92%	515,875	66,279	87%
Pennsylvanian	72%	881	0	100%	14,861	1,841	88%	71,885	8,039	89%
Piedmont	73%	632	36	94%	17,030	2,838	83%	101,359	24,669	76%
Vermont	75%	1,371	72	95%	22,245	7,681	65%	104,515	25,935	75%
Long Distance	56%	12,303	4,813	61%	204,012	78,656	61%	960,671	325,922	66%
Auto Train	57%	664	405	39%	11,790	2,995	75%	51,615	10,206	80%
California Zephyr	50%	728	183	75%	13,759	5,059	63%	70,567	20,730	71%
Cardinal	55%	257	257	0%	4,431	1,956	56%	21,787	10,261	53%
City Of New Orleans	75%	639	173	73%	11,237	1,809	84%	54,563	11,531	79%
Coast Starlight	60%	951	204	79%	19,332	5,018	74%	89,870	27,393	70%
Crescent	70%	818	280	66%	15,469	2,777	82%	74,584	18,559	75%
Empire Builder	55%	986	524	47%	15,595	7,000	55%	76,012	27,261	64%
Floridian	40%	2,322	1,569	32%	28,171	18,460	34%	132,072	72,832	45%
Lake Shore Ltd	73%	1,066	0	100%	17,541	6,440	63%	73,469	14,701	80%
Palmetto	65%	1,094	366	67%	15,705	4,926	69%	75,514	13,357	82%
Silver Meteor	45%	806	412	49%	17,042	6,984	59%	79,791	25,318	68%
Southwest Chief	40%	681	286	58%	12,220	8,520	30%	63,794	38,874	39%
Sunset Ltd	70%	327	63	81%	4,871	637	87%	21,253	4,861	77%
Texas Eagle	50%	964	91	91%	16,849	6,075	64%	75,780	30,038	60%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005540 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 17, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	105,718	1,836,052	576	435,600	8,344,845	522

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,991	543,056	92	17,346	2,445,292	71
INFRASTRUCTURE PLANNED	135	2,921	543,056	54	13,502	2,445,292	55
FLEET RELIABILITY	90	20,800	1,836,052	113	68,684	8,344,845	82
TRAIN OPERATIONS	424	77,006	1,836,052	419	336,068	8,344,845	403

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/17/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/17/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	317	56	82.3%	5,154	802	84.4%	23,063	2,992	87.0%
Central Division	85.5%	67	10	85.1%	1,113	186	83.3%	5,135	555	89.2%
Northeast Division	80.0%	101	15	85.1%	1,643	252	84.7%	7,239	1,004	86.1%
Southeast Division	72.5%	74	16	78.4%	1,193	196	83.6%	5,392	713	86.8%
Southwest Division	77.0%	75	15	80.0%	1,205	168	86.1%	5,297	720	86.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-0011

Scheduled Departure Date: 12/17/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/17/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	317	56	82.3%	5,154	802	84.4%	23,063	2,992	87.0%
Central Division	85.5%	67	10	85.1%	1,113	186	83.3%	5,135	555	89.2%
CDL	90.0%	1	0	100.0%	18	1	94.4%	132	7	94.7%
CHI	85.0%	27	3	88.9%	452	95	79.0%	2,085	232	88.9%
CHM	-	1	1	0.0%	8	4	50.0%	8	4	50.0%
EUG	86.5%	2	0	100.0%	34	4	88.2%	151	19	87.4%
GRR	98.0%	1	1	0.0%	16	2	87.5%	77	2	97.4%
KCY	84.5%	2	0	100.0%	34	3	91.2%	154	14	90.9%
MKE	86.5%	6	0	100.0%	100	9	91.0%	456	39	91.4%
MSP	94.0%	1	0	100.0%	17	0	100.0%	78	3	96.2%
PDX	78.0%	5	0	100.0%	85	8	90.6%	391	54	86.2%
PNT	91.5%	3	0	100.0%	50	11	78.0%	176	16	90.9%
PTH	93.0%	1	1	0.0%	16	4	75.0%	77	6	92.2%
QCY	87.5%	2	0	100.0%	34	3	91.2%	156	15	90.4%
SEA	80.0%	8	3	62.5%	135	23	83.0%	620	97	84.4%
SPK	92.0%	1	1	0.0%	19	3	84.2%	80	4	95.0%
STL	88.0%	4	0	100.0%	66	15	77.3%	308	33	89.3%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	29	1	96.6%	151	5	96.7%
Northeast Division	80.0%	101	15	85.1%	1,643	252	84.7%	7,239	1,004	86.1%
ALB	91.5%	7	0	100.0%	119	7	94.1%	486	28	94.2%
BON	43.5%	5	0	100.0%	85	5	94.1%	372	37	90.1%
BOS	86.5%	20	0	100.0%	324	40	87.7%	1,422	143	89.9%
BRK	88.0%	5	1	80.0%	85	4	95.3%	352	17	95.2%
BTN	48.0%	1	0	100.0%	17	0	100.0%	77	17	77.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	34	3	91.2%	150	12	92.0%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	17	3	82.4%	78	14	82.1%
NFL	96.5%	2	0	100.0%	34	1	97.1%	156	5	96.8%
NHV	75.5%	6	1	83.3%	96	12	87.5%	403	75	81.4%
NYP	77.5%	43	13	69.8%	681	172	74.7%	3,057	602	80.3%
SAB	98.0%	1	0	100.0%	17	0	100.0%	76	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	117	2	98.3%	466	18	96.1%
TWO	84.0%	1	0	100.0%	17	3	82.4%	77	19	75.3%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	16	78.4%	1,193	196	83.6%	5,392	713	86.8%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	85	6	92.9%	390	31	92.1%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	6	53.8%	197	53	73.1%	877	151	82.8%
LOR	69.5%	1	0	100.0%	17	1	94.1%	78	6	92.3%
MIA	87.5%	2	1	50.0%	34	5	85.3%	156	18	88.5%
MOE	94.0%	2	0	100.0%	34	0	100.0%	156	3	98.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/17/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/17/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	317	56	82.3%	5,154	802	84.4%	23,063	2,992	87.0%
Southeast Division	72.5%	74	16	78.4%	1,193	196	83.6%	5,392	713	86.8%
NFK	86.0%	3	0	100.0%	49	7	85.7%	219	22	90.0%
NOL	92.0%	5	0	100.0%	76	3	96.1%	345	17	95.1%
NPN	96.0%	2	0	100.0%	34	0	100.0%	131	7	94.7%
PGH	92.0%	1	1	0.0%	17	2	88.2%	78	3	96.2%
PHL	45.0%	5	4	20.0%	79	51	35.4%	360	174	51.7%
RGH	97.0%	4	0	100.0%	68	4	94.1%	308	7	97.7%
RNK	85.5%	2	1	50.0%	34	5	85.3%	155	19	87.7%
RVM	86.0%	1	0	100.0%	17	2	88.2%	88	13	85.2%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	17	2	88.2%	78	2	97.4%
SFA	70.5%	1	0	100.0%	17	0	100.0%	78	3	96.2%
WAS	70.0%	26	3	88.5%	418	55	86.8%	1,887	232	87.7%
Southwest Division	77.0%	75	15	80.0%	1,205	168	86.1%	5,297	720	86.4%
ARN	60.5%	1	0	100.0%	17	1	94.1%	78	6	92.3%
BFD	75.5%	7	3	57.1%	111	24	78.4%	458	108	76.4%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	16	7	56.3%	79	24	69.6%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	17	0	100.0%	77	3	96.1%
GTA	72.5%	3	0	100.0%	51	2	96.1%	227	19	91.6%
LAX	77.5%	10	2	80.0%	159	20	87.4%	719	81	88.7%
OKC	96.0%	1	0	100.0%	17	0	100.0%	78	3	96.2%
OKJ	79.0%	13	5	61.5%	199	64	67.8%	859	216	74.9%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	16	3	81.3%	243	31	87.2%	1,031	117	88.7%
SAN	77.0%	12	0	100.0%	196	8	95.9%	889	73	91.8%
SAS	85.0%	1	0	100.0%	17	1	94.1%	78	4	94.9%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	119	8	93.3%	544	48	91.2%
SLO	62.0%	2	0	100.0%	34	1	97.1%	151	12	92.1%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		8	0	100.0%	34	1	97.1%	8	0	100.0%	34	1	97.1%
3	301	17	5	70.6%	78	9	88.5%	16	9	43.8%	77	32	58.4%
4		16	6	62.5%	77	12	84.4%	16	12	25.0%	77	50	35.1%
5		17	6	64.7%	77	13	83.1%	16	5	68.8%	75	11	85.3%
6	52	15	6	60.0%	76	23	69.7%	15	4	73.3%	76	25	67.1%
7	620	17	3	82.4%	78	7	91.0%	14	5	64.3%	75	12	84.0%
8		17	11	35.3%	78	31	60.3%	17	8	52.9%	78	35	55.1%
11		17	3	82.4%	77	14	81.8%	17	2	88.2%	75	9	88.0%
14		17	1	94.1%	78	10	87.2%	17	0	100.0%	77	18	76.6%
19		17	5	70.6%	78	13	83.3%	17	1	94.1%	78	12	84.6%
20		17	0	100.0%	78	6	92.3%	17	1	94.1%	78	7	91.0%
21		17	4	76.5%	77	12	84.4%	17	5	70.6%	77	16	79.2%
22		17	1	94.1%	78	4	94.9%	17	3	82.4%	77	16	79.2%
23		17	0	100.0%	78	3	96.2%	17	1	94.1%	78	11	85.9%
24		17	3	82.4%	78	5	93.6%	17	1	94.1%	78	7	91.0%
25		17	0	100.0%	78	0	100.0%	17	0	100.0%	78	9	88.5%
26		17	0	100.0%	78	2	97.4%	17	0	100.0%	78	11	85.9%
27	174	17	3	82.4%	78	4	94.9%	17	6	64.7%	78	16	79.5%
28		17	3	82.4%	78	16	79.5%	17	1	94.1%	78	9	88.5%
40	421	17	4	76.5%	78	13	83.3%	17	7	58.8%	78	29	62.8%
41		17	10	41.2%	78	28	64.1%	17	11	35.3%	78	50	35.9%
42		17	2	88.2%	78	3	96.2%	17	2	88.2%	78	11	85.9%
43		17	2	88.2%	78	7	91.0%	17	1	94.1%	78	4	94.9%
48		17	6	64.7%	78	11	85.9%	17	5	70.6%	78	8	89.7%
49		17	2	88.2%	78	12	84.6%	17	5	70.6%	78	10	87.2%
50	85	7	3	57.1%	33	7	78.8%	7	5	28.6%	34	18	47.1%
52		17	0	100.0%	78	3	96.2%	17	2	88.2%	78	14	82.1%
53	31	17	1	94.1%	78	6	92.3%	17	4	76.5%	78	12	84.6%
55		13	0	100.0%	55	0	100.0%	13	4	69.2%	55	10	81.8%
56		13	4	69.2%	55	11	80.0%	13	4	69.2%	55	10	81.8%
58		17	0	100.0%	77	2	97.4%	17	4	76.5%	76	11	85.5%
59		17	2	88.2%	76	5	93.4%	17	1	94.1%	76	4	94.7%
63		17	5	70.6%	78	26	66.7%	17	10	41.2%	78	39	50.0%
64		17	3	82.4%	77	19	75.3%	17	5	70.6%	77	15	80.5%
66		17	2	88.2%	78	12	84.6%	17	1	94.1%	78	14	82.1%
67		13	1	92.3%	55	3	94.5%	13	2	84.6%	55	9	83.6%
68		17	3	82.4%	78	14	82.1%	17	11	35.3%	78	36	53.8%
69		17	1	94.1%	78	8	89.7%	17	3	82.4%	78	10	87.2%
71		17	1	94.1%	78	1	98.7%	17	4	76.5%	78	20	74.4%
72		17	3	82.4%	78	8	89.7%	17	7	58.8%	78	17	78.2%
73		17	2	88.2%	78	3	96.2%	17	5	70.6%	77	38	50.6%
74		17	1	94.1%	78	6	92.3%	17	3	82.4%	78	23	70.5%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		17	0	100.0%	78	2	97.4%	17	6	64.7%	78	34	56.4%
76		17	0	100.0%	78	4	94.9%	17	4	76.5%	78	34	56.4%
77	18	17	1	94.1%	78	3	96.2%	17	6	64.7%	78	28	64.1%
78		17	0	100.0%	78	3	96.2%	17	2	88.2%	78	11	85.9%
79		17	4	76.5%	78	15	80.8%	17	3	82.4%	77	14	81.8%
80		17	2	88.2%	78	10	87.2%	17	5	70.6%	77	10	87.0%
84		13	0	100.0%	55	3	94.5%	13	3	76.9%	55	8	85.5%
85		13	1	92.3%	55	2	96.4%	13	6	53.8%	55	21	61.8%
86	28	13	1	92.3%	55	5	90.9%	13	9	30.8%	55	28	49.1%
89	44	17	5	70.6%	78	17	78.2%	17	7	58.8%	78	13	83.3%
90		17	2	88.2%	78	2	97.4%	17	3	82.4%	78	9	88.5%
93		13	1	92.3%	55	7	87.3%	13	0	100.0%	54	10	81.5%
94		13	6	53.8%	55	12	78.2%	12	4	66.7%	54	16	70.4%
95		13	0	100.0%	55	1	98.2%	13	4	69.2%	55	15	72.7%
97		17	12	29.4%	78	30	61.5%	17	3	82.4%	78	19	75.6%
98		17	1	94.1%	78	5	93.6%	17	7	58.8%	78	18	76.9%
110		13	6	53.8%	55	25	54.5%	13	2	84.6%	55	5	90.9%
111		13	3	76.9%	55	7	87.3%	13	2	84.6%	55	5	90.9%
112		13	1	92.3%	55	5	90.9%	13	1	92.3%	55	6	89.1%
114		13	3	76.9%	55	11	80.0%	12	2	83.3%	54	2	96.3%
119		13	2	84.6%	55	11	80.0%	13	2	84.6%	55	5	90.9%
125	16	13	0	100.0%	55	2	96.4%	13	8	38.5%	55	14	74.5%
129		13	6	53.8%	55	19	65.5%	13	2	84.6%	55	8	85.5%
130	30	13	0	100.0%	55	4	92.7%	13	1	92.3%	55	5	90.9%
131		13	2	84.6%	55	6	89.1%	13	4	69.2%	55	4	92.7%
133		13	4	69.2%	55	23	58.2%	13	3	76.9%	55	23	58.2%
134		13	2	84.6%	55	6	89.1%	13	3	76.9%	55	11	80.0%
136		13	2	84.6%	55	5	90.9%	12	1	91.7%	55	4	92.7%
137		13	2	84.6%	53	10	81.1%	13	3	76.9%	53	13	75.5%
138		13	1	92.3%	55	7	87.3%	13	0	100.0%	55	2	96.4%
141		13	0	100.0%	55	3	94.5%	13	4	69.2%	55	12	78.2%
148		13	1	92.3%	55	5	90.9%	13	0	100.0%	54	9	83.3%
151		17	9	47.1%	78	23	70.5%	17	6	64.7%	77	22	71.4%
170	16	13	1	92.3%	52	4	92.3%	13	5	61.5%	52	14	73.1%
171		13	1	92.3%	55	4	92.7%	13	4	69.2%	55	9	83.6%
172	23	13	2	84.6%	55	6	89.1%	13	5	61.5%	55	20	63.6%
173		13	3	76.9%	55	5	90.9%	13	6	53.8%	55	21	61.8%
174		13	0	100.0%	55	3	94.5%	13	3	76.9%	55	11	80.0%
175		13	3	76.9%	55	5	90.9%	13	5	61.5%	55	13	76.4%
176		13	1	92.3%	55	4	92.7%	13	0	100.0%	55	3	94.5%
177		13	2	84.6%	55	10	81.8%	13	4	69.2%	55	24	56.4%
178		13	1	92.3%	55	8	85.5%	12	0	100.0%	55	5	90.9%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		13	1	92.3%	55	5	90.9%	12	2	83.3%	55	12	78.2%
181		13	6	53.8%	55	12	78.2%	12	2	83.3%	54	3	94.4%
182		13	2	84.6%	55	11	80.0%	13	1	92.3%	55	4	92.7%
183		13	4	69.2%	55	15	72.7%	13	4	69.2%	55	10	81.8%
184		13	1	92.3%	55	9	83.6%	13	3	76.9%	55	8	85.5%
185		13	2	84.6%	55	10	81.8%	13	1	92.3%	55	2	96.4%
186		13	0	100.0%	55	7	87.3%	13	1	92.3%	55	13	76.4%
190		13	7	46.2%	55	23	58.2%	13	2	84.6%	55	12	78.2%
192		13	1	92.3%	53	7	86.8%	13	1	92.3%	53	2	96.2%
193		13	3	76.9%	55	16	70.9%	13	4	69.2%	55	18	67.3%
196		13	1	92.3%	55	1	98.2%	13	1	92.3%	55	3	94.5%
197		13	7	46.2%	55	22	60.0%	13	5	61.5%	55	11	80.0%
232		17	0	100.0%	78	1	98.7%	17	0	100.0%	78	6	92.3%
233		17	5	70.6%	78	18	76.9%	17	4	76.5%	78	16	79.5%
234		17	0	100.0%	78	3	96.2%	17	0	100.0%	78	2	97.4%
236	20	17	0	100.0%	78	1	98.7%	17	3	82.4%	78	14	82.1%
237		17	2	88.2%	78	12	84.6%	17	1	94.1%	78	5	93.6%
239		17	6	64.7%	77	21	72.7%	17	1	94.1%	77	3	96.1%
240		17	1	94.1%	78	7	91.0%	17	4	76.5%	78	11	85.9%
241		17	6	64.7%	78	22	71.8%	17	2	88.2%	78	12	84.6%
243	79	13	3	76.9%	55	19	65.5%	13	2	84.6%	56	10	82.1%
244		17	0	100.0%	78	2	97.4%	17	0	100.0%	78	15	80.8%
280		17	1	94.1%	78	4	94.9%	17	4	76.5%	78	14	82.1%
281		17	0	100.0%	78	8	89.7%	17	2	88.2%	78	7	91.0%
283		17	6	64.7%	78	14	82.1%	17	4	76.5%	78	13	83.3%
284		17	0	100.0%	78	1	98.7%	17	2	88.2%	78	7	91.0%
290		17	0	100.0%	78	18	76.9%	17	4	76.5%	77	25	67.5%
291		17	4	76.5%	78	17	78.2%	17	3	82.4%	78	15	80.8%
300		17	5	70.6%	78	7	91.0%	17	8	52.9%	77	22	71.4%
301		16	1	93.8%	76	2	97.4%	16	4	75.0%	75	13	82.7%
302		16	4	75.0%	76	10	86.8%	16	6	62.5%	74	23	68.9%
305		17	5	70.6%	78	10	87.2%	16	11	31.3%	76	31	59.2%
306	41	16	3	81.3%	76	5	93.4%	16	5	68.8%	75	16	78.7%
307		17	3	82.4%	77	8	89.6%	17	8	52.9%	77	19	75.3%
311		17	3	82.4%	77	10	87.0%	17	5	70.6%	77	19	75.3%
316		17	2	88.2%	77	5	93.5%	17	5	70.6%	77	17	77.9%
318		17	1	94.1%	78	10	87.2%	17	7	58.8%	77	32	58.4%
319		17	1	94.1%	78	3	96.2%	17	8	52.9%	78	44	43.6%
329		13	1	92.3%	55	2	96.4%	13	2	84.6%	55	4	92.7%
330		15	0	100.0%	66	2	97.0%	15	4	73.3%	66	5	92.4%
331		17	5	70.6%	78	9	88.5%	17	4	76.5%	78	10	87.2%
332		17	3	82.4%	78	8	89.7%	17	5	70.6%	78	10	87.2%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		17	1	94.1%	78	2	97.4%	17	6	64.7%	77	10	87.0%
335		17	5	70.6%	78	12	84.6%	16	3	81.3%	76	12	84.2%
336		17	2	88.2%	78	3	96.2%	17	1	94.1%	78	5	93.6%
337		17	0	100.0%	78	4	94.9%	17	3	82.4%	78	8	89.7%
338		17	2	88.2%	78	17	78.2%	16	5	68.8%	76	17	77.6%
339		17	3	82.4%	78	17	78.2%	17	5	70.6%	78	16	79.5%
341		15	3	80.0%	75	12	84.0%	15	4	73.3%	75	12	84.0%
342		17	1	94.1%	78	7	91.0%	17	5	70.6%	77	13	83.1%
350		17	0	100.0%	60	2	96.7%	17	11	35.3%	60	33	45.0%
351		17	6	64.7%	78	9	88.5%	17	7	58.8%	78	33	57.7%
352		17	2	88.2%	78	6	92.3%	16	5	68.8%	75	19	74.7%
353		17	3	82.4%	57	5	91.2%	17	9	47.1%	57	14	75.4%
354		17	4	76.5%	78	7	91.0%	16	10	37.5%	77	24	68.8%
355	66	16	2	87.5%	77	7	90.9%	15	7	53.3%	76	20	73.7%
364		16	8	50.0%	77	13	83.1%	15	6	60.0%	76	14	81.6%
365		16	4	75.0%	77	6	92.2%	15	9	40.0%	76	25	67.1%
370		17	3	82.4%	78	5	93.6%	17	6	64.7%	78	15	80.8%
371		16	2	87.5%	77	2	97.4%	16	3	81.3%	77	7	90.9%
380	28	17	3	82.4%	78	13	83.3%	17	5	70.6%	78	18	76.9%
381		17	1	94.1%	78	2	97.4%	17	2	88.2%	78	9	88.5%
382		17	0	100.0%	78	2	97.4%	17	4	76.5%	78	19	75.6%
383		17	4	76.5%	78	9	88.5%	17	9	47.1%	77	31	59.7%
390	47	9	4	55.6%	62	8	87.1%	9	5	44.4%	62	21	66.1%
391		9	1	88.9%	63	1	98.4%	9	2	77.8%	62	14	77.4%
392	45	17	1	94.1%	78	3	96.2%	17	11	35.3%	77	26	66.2%
393	67	17	2	88.2%	78	7	91.0%	17	6	64.7%	77	21	72.7%
417		13	1	92.3%	52	9	82.7%	12	0	100.0%	49	1	98.0%
425		13	0	100.0%	52	1	98.1%	13	0	100.0%	52	1	98.1%
448		17	8	52.9%	19	9	52.6%	16	8	50.0%	17	8	52.9%
449		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
470		13	3	76.9%	55	8	85.5%	13	2	84.6%	55	9	83.6%
471		13	1	92.3%	52	1	98.1%	13	0	100.0%	52	0	100.0%
473		13	0	100.0%	55	3	94.5%	13	0	100.0%	55	1	98.2%
474		13	5	61.5%	53	18	66.0%	12	7	41.7%	49	18	63.3%
475		13	0	100.0%	55	0	100.0%	13	0	100.0%	55	1	98.2%
478		13	2	84.6%	53	12	77.4%	13	0	100.0%	53	6	88.7%
479		13	3	76.9%	55	7	87.3%	13	1	92.3%	55	2	96.4%
486	22	13	1	92.3%	56	8	85.7%	13	3	76.9%	55	9	83.6%
490		13	1	92.3%	32	6	81.3%	13	0	100.0%	32	2	93.8%
494		13	0	100.0%	57	9	84.2%	13	4	69.2%	54	11	79.6%
495		13	0	100.0%	55	2	96.4%	13	0	100.0%	55	1	98.2%
500	40	17	1	94.1%	78	6	92.3%	17	3	82.4%	77	8	89.6%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502	67	17	1	94.1%	78	7	91.0%	17	2	88.2%	77	18	76.6%
503	25	17	3	82.4%	75	11	85.3%	17	5	70.6%	74	20	73.0%
504	187	17	2	88.2%	78	7	91.0%	17	6	64.7%	78	25	67.9%
505	74	17	2	88.2%	78	12	84.6%	17	3	82.4%	76	16	78.9%
506	37	17	3	82.4%	77	12	84.4%	17	2	88.2%	76	11	85.5%
507	101	17	2	88.2%	78	9	88.5%	17	5	70.6%	78	27	65.4%
508	33	17	2	88.2%	76	13	82.9%	17	6	64.7%	76	19	75.0%
509	80	17	2	88.2%	78	6	92.3%	17	8	52.9%	78	21	73.1%
511	36	17	2	88.2%	78	6	92.3%	17	4	76.5%	78	16	79.5%
516		15	0	100.0%	76	9	88.2%	15	4	73.3%	76	32	57.9%
517	28	17	0	100.0%	78	1	98.7%	17	7	58.8%	77	29	62.3%
518	128	17	0	100.0%	78	13	83.3%	17	10	41.2%	78	46	41.0%
519	21	15	1	93.3%	76	4	94.7%	15	4	73.3%	76	13	82.9%
520		13	4	69.2%	51	7	86.3%	12	1	91.7%	50	3	94.0%
521		13	0	100.0%	54	0	100.0%	13	1	92.3%	54	4	92.6%
522		13	4	69.2%	54	8	85.2%	12	1	91.7%	53	5	90.6%
523	23	13	0	100.0%	54	0	100.0%	13	4	69.2%	54	8	85.2%
524		13	0	100.0%	54	2	96.3%	13	1	92.3%	54	4	92.6%
525		13	2	84.6%	54	3	94.4%	12	1	91.7%	53	6	88.7%
526		13	5	61.5%	54	11	79.6%	12	1	91.7%	53	5	90.6%
527		13	0	100.0%	54	1	98.1%	13	1	92.3%	54	3	94.4%
528		13	1	92.3%	54	6	88.9%	13	2	84.6%	54	12	77.8%
529	23	13	0	100.0%	54	3	94.4%	13	3	76.9%	54	10	81.5%
530	16	8	0	100.0%	8	0	100.0%	8	1	87.5%	8	1	87.5%
531		13	0	100.0%	54	1	98.1%	13	2	84.6%	54	5	90.7%
532		13	2	84.6%	54	3	94.4%	13	1	92.3%	54	8	85.2%
534		13	1	92.3%	51	6	88.2%	13	2	84.6%	51	5	90.2%
535		12	3	75.0%	50	4	92.0%	11	1	90.9%	49	2	95.9%
536		13	2	84.6%	54	6	88.9%	12	1	91.7%	53	2	96.2%
537		13	2	84.6%	54	5	90.7%	12	1	91.7%	53	2	96.2%
538		13	1	92.3%	54	7	87.0%	13	4	69.2%	54	9	83.3%
539	11	8	1	87.5%	8	1	87.5%	8	5	37.5%	8	5	37.5%
540		13	3	76.9%	54	7	87.0%	12	1	91.7%	51	2	96.1%
541		13	4	69.2%	54	9	83.3%	13	4	69.2%	54	15	72.2%
542		13	0	100.0%	54	3	94.4%	13	1	92.3%	53	11	79.2%
543		13	0	100.0%	54	6	88.9%	13	1	92.3%	54	13	75.9%
544		13	2	84.6%	53	4	92.5%	13	3	76.9%	53	7	86.8%
545		13	2	84.6%	54	6	88.9%	13	1	92.3%	53	5	90.6%
547		13	0	100.0%	54	4	92.6%	13	2	84.6%	54	9	83.3%
548		13	2	84.6%	54	10	81.5%	13	1	92.3%	54	6	88.9%
549		13	3	76.9%	51	13	74.5%	11	0	100.0%	48	6	87.5%
550		8	2	75.0%	8	2	75.0%	8	1	87.5%	8	1	87.5%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
551		13	1	92.3%	54	7	87.0%	13	1	92.3%	52	7	86.5%
562		17	3	82.4%	76	11	85.5%	17	3	82.4%	75	9	88.0%
564		17	1	94.1%	76	7	90.8%	16	2	87.5%	72	12	83.3%
566		17	1	94.1%	76	6	92.1%	17	2	88.2%	73	8	89.0%
572		17	0	100.0%	75	6	92.0%	17	0	100.0%	74	14	81.1%
573		17	2	88.2%	76	11	85.5%	16	0	100.0%	74	8	89.2%
577		17	1	94.1%	74	6	91.9%	17	4	76.5%	70	6	91.4%
580		17	0	100.0%	76	2	97.4%	17	1	94.1%	76	8	89.5%
581		17	0	100.0%	76	7	90.8%	17	2	88.2%	76	14	81.6%
582		17	2	88.2%	76	6	92.1%	17	1	94.1%	74	5	93.2%
586	No OS	17	3	82.4%	76	14	81.6%	17	1	94.1%	73	10	86.3%
587	No OS	17	0	100.0%	76	3	96.1%	17	1	94.1%	74	10	86.5%
591	No OS	17	0	100.0%	76	1	98.7%	17	1	94.1%	76	7	90.8%
593	116	17	2	88.2%	76	11	85.5%	16	1	93.8%	69	6	91.3%
595		17	1	94.1%	75	15	80.0%	17	1	94.1%	74	11	85.1%
600		13	1	92.3%	55	2	96.4%	13	1	92.3%	55	5	90.9%
601		13	10	23.1%	55	29	47.3%	13	2	84.6%	55	15	72.7%
605		13	12	7.7%	55	33	40.0%	13	3	76.9%	54	5	90.7%
607		13	1	92.3%	55	4	92.7%	13	3	76.9%	54	4	92.6%
609		13	3	76.9%	54	4	92.6%	13	1	92.3%	54	4	92.6%
620		13	6	53.8%	54	15	72.2%	13	1	92.3%	52	3	94.2%
624		13	4	69.2%	55	14	74.5%	12	3	75.0%	55	12	78.2%
639	12	13	5	61.5%	55	15	72.7%	13	2	84.6%	55	6	89.1%
640		13	2	84.6%	55	4	92.7%	13	9	30.8%	55	27	50.9%
641		13	6	53.8%	55	11	80.0%	13	4	69.2%	55	11	80.0%
642		13	1	92.3%	54	3	94.4%	13	2	84.6%	54	6	88.9%
643	35	13	4	69.2%	55	11	80.0%	13	5	61.5%	54	8	85.2%
644	24	13	4	69.2%	55	9	83.6%	13	6	53.8%	55	11	80.0%
645	31	13	3	76.9%	55	6	89.1%	13	5	61.5%	55	11	80.0%
646	33	13	5	61.5%	55	12	78.2%	13	11	15.4%	54	31	42.6%
647		13	2	84.6%	55	4	92.7%	13	2	84.6%	55	14	74.5%
648	12	13	5	61.5%	55	11	80.0%	13	5	61.5%	55	9	83.6%
649		13	4	69.2%	55	10	81.8%	13	2	84.6%	54	9	83.3%
650	11	13	3	76.9%	55	12	78.2%	13	7	46.2%	55	14	74.5%
651		13	0	100.0%	55	5	90.9%	13	4	69.2%	55	17	69.1%
652	27	13	3	76.9%	55	11	80.0%	13	4	69.2%	54	12	77.8%
653		13	3	76.9%	55	11	80.0%	13	2	84.6%	55	16	70.9%
654		13	6	53.8%	55	11	80.0%	13	3	76.9%	55	5	90.9%
655		13	4	69.2%	53	16	69.8%	13	6	53.8%	52	14	73.1%
656		13	4	69.2%	55	11	80.0%	13	0	100.0%	55	5	90.9%
657	28	13	0	100.0%	55	3	94.5%	13	1	92.3%	55	10	81.8%
658		13	1	92.3%	55	8	85.5%	13	3	76.9%	55	9	83.6%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
680		13	0	100.0%	56	2	96.4%	13	3	76.9%	56	6	89.3%
681		13	1	92.3%	56	3	94.6%	13	4	69.2%	56	17	69.6%
682		13	0	100.0%	56	0	100.0%	13	3	76.9%	56	13	76.8%
683		13	0	100.0%	39	3	92.3%	13	3	76.9%	39	12	69.2%
684		13	2	84.6%	38	6	84.2%	13	2	84.6%	38	10	73.7%
685		13	2	84.6%	55	6	89.1%	13	2	84.6%	55	15	72.7%
686		13	2	84.6%	56	15	73.2%	13	4	69.2%	56	14	75.0%
687	59	13	2	84.6%	56	8	85.7%	13	5	61.5%	56	11	80.4%
688		13	0	100.0%	56	1	98.2%	13	2	84.6%	56	14	75.0%
689		9	0	100.0%	45	4	91.1%	8	1	87.5%	44	4	90.9%
701		10	3	70.0%	10	3	70.0%	10	2	80.0%	10	2	80.0%
702		17	2	88.2%	78	17	78.2%	17	3	82.4%	77	22	71.4%
703		17	4	76.5%	78	19	75.6%	17	4	76.5%	78	20	74.4%
704		10	3	70.0%	10	3	70.0%	9	3	66.7%	9	3	66.7%
710	22	17	7	58.8%	78	31	60.3%	17	2	88.2%	78	30	61.5%
711		17	2	88.2%	74	6	91.9%	14	3	78.6%	67	10	85.1%
712		17	4	76.5%	78	21	73.1%	17	5	70.6%	77	28	63.6%
713	Cncl'd	16	3	81.3%	77	12	84.4%	12	4	66.7%	67	31	53.7%
714		17	6	64.7%	72	25	65.3%	17	4	76.5%	67	20	70.1%
715	19	17	5	70.6%	78	27	65.4%	15	8	46.7%	73	37	49.3%
716	89	17	9	47.1%	78	32	59.0%	17	9	47.1%	77	32	58.4%
717		17	4	76.5%	69	17	75.4%	17	7	58.8%	64	20	68.8%
718	108	17	11	35.3%	78	33	57.7%	16	6	62.5%	77	22	71.4%
719	28	17	3	82.4%	78	27	65.4%	17	6	64.7%	76	22	71.1%
761		17	0	100.0%	76	3	96.1%	17	0	100.0%	76	9	88.2%
765		17	1	94.1%	76	8	89.5%	17	1	94.1%	76	14	81.6%
769		17	1	94.1%	76	5	93.4%	17	1	94.1%	74	12	83.8%
770		17	0	100.0%	76	7	90.8%	17	1	94.1%	76	10	86.8%
774	62	17	0	100.0%	76	6	92.1%	17	3	82.4%	75	14	81.3%
779		17	0	100.0%	76	4	94.7%	17	0	100.0%	75	9	88.0%
784	35	17	2	88.2%	76	8	89.5%	17	9	47.1%	75	38	49.3%
785	No OS	17	0	100.0%	76	0	100.0%	17	2	88.2%	76	9	88.2%
790	No OS	17	0	100.0%	76	5	93.4%	17	2	88.2%	76	9	88.2%
794		17	1	94.1%	76	6	92.1%	17	2	88.2%	75	12	84.0%
821		17	0	100.0%	78	3	96.2%	17	6	64.7%	78	46	41.0%
822		17	0	100.0%	78	3	96.2%	17	2	88.2%	78	46	41.0%
1333		17	4	76.5%	78	8	89.7%	17	6	64.7%	77	32	58.4%
1340		17	0	100.0%	78	3	96.2%	17	6	64.7%	78	19	75.6%
2103		13	1	92.3%	54	4	92.6%	13	2	84.6%	54	3	94.4%
2104	37	13	3	76.9%	25	5	80.0%	13	2	84.6%	25	4	84.0%
2107	17	13	4	69.2%	55	11	80.0%	13	4	69.2%	53	4	92.5%
2108		13	2	84.6%	55	4	92.7%	13	2	84.6%	53	2	96.2%

Amtrak On Time Performance

Trains Arriving Through: 12/17/2025

28-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2117	103	13	4	69.2%	25	7	72.0%	13	4	69.2%	25	5	80.0%
2121		13	3	76.9%	53	6	88.7%	13	2	84.6%	53	5	90.6%
2122	38	13	1	92.3%	55	7	87.3%	13	1	92.3%	55	4	92.7%
2124		11	2	81.8%	41	6	85.4%	11	1	90.9%	41	2	95.1%
2150		13	1	92.3%	55	10	81.8%	12	2	83.3%	54	11	79.6%
2151		13	0	100.0%	55	0	100.0%	13	5	61.5%	54	11	79.6%
2152		13	1	92.3%	51	3	94.1%	13	9	30.8%	50	18	64.0%
2153		13	0	100.0%	55	6	89.1%	13	3	76.9%	55	12	78.2%
2154		13	3	76.9%	55	17	69.1%	13	7	46.2%	53	28	47.2%
2155	20	13	1	92.3%	55	3	94.5%	13	8	38.5%	53	17	67.9%
2159	48	13	0	100.0%	54	1	98.1%	13	6	53.8%	54	13	75.9%
2162	32	13	0	100.0%	55	2	96.4%	13	4	69.2%	54	13	75.9%
2163		13	0	100.0%	55	4	92.7%	13	5	61.5%	55	15	72.7%
2166		13	1	92.3%	55	6	89.1%	13	4	69.2%	53	10	81.1%
2167		12	1	91.7%	54	6	88.9%	12	3	75.0%	54	11	79.6%
2168		13	1	92.3%	55	3	94.5%	13	1	92.3%	55	7	87.3%
2169	170	13	8	38.5%	51	18	64.7%	13	10	23.1%	51	25	51.0%
2170	27	13	3	76.9%	55	10	81.8%	13	3	76.9%	55	12	78.2%
2172		13	0	100.0%	55	6	89.1%	13	3	76.9%	55	10	81.8%
2173	29	13	3	76.9%	54	10	81.5%	13	3	76.9%	54	21	61.1%
2190		13	3	76.9%	55	8	85.5%	12	2	83.3%	54	6	88.9%
2193	22	13	1	92.3%	54	2	96.3%	13	5	61.5%	54	14	74.1%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/17/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2104	NYP	37	DET	37	DET	37	WAS-WAS	AM	Catenary failure, Control Point, WAS IVY CITY, COACH YARD, POWER 25W WAS INEFFECT WHICH DELAYED THE RELEASE OF 2104, TO COME TO THE STATION. PLATE RESTORED 729A	
2107	WAS	17	WTR	8	WTR	8	NYP-NYP	AM	Ice / snow on or under equipment, Other, NYP-NYP, LATE FROM SSYD A/C EXTREME COLD CONDITION FROZE EQUIPMENT	
2117	WAS	103	ENG	91	ENG	91	NYP-NWK	AM	Other electrical failure, 2019, AM2117 WITH STUCK HAND BRAKE CAR 3558 MISMATCH FAULT	
2122	NYP	38	ENG	33	ENG	33	WAS-WAS	AM	Air / Brake, ., 2117 HAD PARKING BRAKE ISSUE. SO THE SET WAS SHOPPED INBOUND, AND THE SHORT TURNED 2121 ARRIVED WAS 518P AND 2122 WAS DUE OUT 530P	
2155	WAS	20	ENG	24	ENG	9	XPV-BAL	AM	Undesired emergency application, 2031, OPERATING 79 MPH A/C TRANSPONDER ISSUES	
2159	WAS	48	PTI	11	BSP	5	WIL-XPV	AM	Bridge strike, Milepost, 51.88, .	
2162	BOS	32	OTH	18	SMW	11	NYP-XSH	AM	Scheduled in track usage program, Other, XPB, HELD FOR SINGLE TRACKING PELHAM BAY TO LEGGETT A/C SCHEDULED MAINTENANCE	
2169	WAS	170	ENG	148	ENG	62	NHV-NHV	MN	Full train reset 2125	
2170	BOS	27	ENG	19	ENG	19	NWK-NYP	AM	Undesired emergency application, 2117, ETS PENALTY AT "A" INT	
2173	WAS	29	CAR	29	CAR	25	MET-MET	AM	Door, 3262, DOOR ISSUED OB CAR 3262	
2193	NYP	22	DSR	15	DSR	10	XNH-STM	MN	Per bulletin Control Point, cp241, 15, 2	
86	BOS	28	CTI	30	CTI	16	NYP-XSH	AM	Cross Traffic, MNRR, MN, Other, XSH, MNRR TRAIN XING AHEAD	
125	NPN	16	ADA	19	ADA	11	ABE-ABE	AM	Wheelchair, assisting a wheelchair psgr, had problems with the wheelchair lift	
130	NYP	30	ENG	24	ENG	22	NWK-NYP	AM	Other electrical failure, 605, HELD AT TENTH AVE A/C STOP BYPASS	
170	BOS	16	CTI	15	DCS	11	NRO-BRP	MN	Restrictive signal(s) from unknown cause Stop, Control Point, 240	
172	BOS	23	OTH	17	DMW	13	STM-BRP	MN	Hold for defect repair Control Point, East Norwalk	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
486	GFD	22	CON	18	CON	18	NHV-NHV	AM	Hold for connecting train, HELD FOR CONNECTION WITH AM86
53	SFA	31	FTI	114	FTI	67	XSE-XFL	CS	Follow I031, Milepost, 172.0, 292.9
639	PHL	12	POL	17	POL	13	EWR-MET	AM	On-train police or DEA activity, NJ3883 AHEAD IN METROPARK WITH POLICE ACTIVITY
643	HAR	35	PTI	27	PTI	18	LNC-LNC	AM	Meet, 650, Control Point, ., waited for 650 ahead.
644	NYP	24	SVS	19	SVS	19	PAO-PHL	AM	Unplanned Wye
645	HAR	31	MTI	22	MTI	19	NYP-NYP	AM	Disabled train ahead, Other, CP MID, NECESSARY TO REVERSE BACK INTO STATION A/C AM2117 WITH STUCK HAND BRAKE CAR 3558
646	NYP	33	MTI	29	MTI	29	NWK-NYP	AM	Disabled train ahead, Other, CP MID, HELD FOR CONGESTION SOUTH TUBE A/C AM2117 WITH STUCK HAND BRAKE CAR 3558 MISMATCH FAULT NORTH TUBE
648	NYP	12	OTH	10	MTI	8	NWK-NYP	AM	Disabled train ahead, Other, CP MID, CONGESTION DUE TO AM2117 WITH STUCK HAND BRAKE CAR 3558 NORTH TUBE
650	NYP	11	WTR	13	WTR	13	XHM-TRE	AM	Ice / snow on or under equipment, Other, XHM-XGY, ACTIVATED DED A/C SNOW AND ICE BUILD UP
652	NYP	27	CCR	20	CCR	10	XHM-TRE	AM	Undesired emergency application, 9645, REPORTED DOUBLE DASHES AT HOLMES INT
657	HAR	28	SVS	19	SVS	19	PHL-ARD	AM	Unplanned Wye, ACSES issues with CC/9645
687	BRK	59	TRS	62	TRS	62	WOB-HHL	MT	Trespasser strike Commuter train struck trespasser in Haverhill station. Held at CPF FR until track released, Control Point, FR
236	NYP	20	PTI	17	PTI	17	YNY-XSD	MN	Cross over or go around 281, Control Point, 12
243	ALB	79	ENG	70	ENG	70	NYP-NYP	AM	Undesired emergency application, 92 , LATE FROM SSYD A/C LOSS OF POWER
77	CLT	18	SYS	15	SYS	15	SAL-KAN	NS	PTC problem or failure (cause unknown) Approach signal dropped to restricted and caused train to stop. Had to call PTC and dispatch, Control Point, reid
89	SAV	44	FTI	45	FTI	20	KTR-CHS	CS	Meet M 410, Control Point, A 376.9

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
40	CHI	421	DMW	190	DMW	190	SAV-DNK	CS	Waiting for MW clearance Stopped while crews fix broken rail for over 3hours at the mp a 475.0, Milepost, 464.5, 464.3
6	CHI	52	FTI	86	MBO	50	MTP-BRL	BN	Bridge not working. Stopped waiting for a crew to respond Control Point, lucas st
523	SJC	23	INJ	24	INJ	24	RIC-RIC	UP	Injured or sick passenger
529	SJC	23	PTI	37	PTI	20	OKJ-OAC	UP	Meet 528, Control Point, E. Oakland
530	SAC	16	RTE	26	RTE	20	FFV-DAV	UP	Line manual or spring switch Control Point, Pitt
539	SJC	11	PTI	12	PTI	10	GAC-SCC	UP	Meet Amt538, Control Point, Co044
50	NYP	85	FTI	79	CAR	53	CHI-CHI	AM	Set out defective car, 69000, Bad ordered crew car
500	SEA	40	FTI	37	FTI	37	VAN-KEL	BN	Disabled train Control Point, INSTERSTATE SOUTH, Control Point, TOTEFF, UP 7277, BNSF 5779
502	SEA	67	DCS	35	DCS	35	XNI-TAC	ST	Restrictive signal(s) from known wayside signal failure Talked By from DS, proceed at restricted speed between locations., Stop, Restricting, Stop, Control Point, Nisqually, Control Point, 19.8, Control Point, CP 188
503	EUG	25	DCS	38	DCS	33	TAC-XNI	ST	Restrictive signal(s) from known wayside signal failure Stop, Control Point, rill
504	SEA	187	DCS	92	WTR	70	SLM-SLM	UP	Trees down Downed trees and downed power lines at mp 740. Dispatcher held us at Salem station while work crews removed trees and repaired power lines., Milepost, 740, 740
505	PDX	74	DCS	51	DCS	46	TAC-XNI	ST	CTC system failure Signals down Rill to MP 19.8. Talked by red signal at Rill and CP188. Restricted speed through limits., Control Point, Rill
506	SEA	37	DCS	52	DCS	30	XNI-TAC	ST	CTC system failure Milepost, 19.0, 10.8
507	EUG	101	DCS	78	DCS	41	TAC-XNI	ST	Restrictive signal(s) from known wayside signal failure Power outage between Rill and Nisqually, Restricting , Control Point, Rill, Control Point, Nisqually
508	SEA	33	PTI	26	DCS	23	XNI-TAC	ST	Restrictive signal(s) from known wayside signal failure Stop, Control Point, 188 to 107
509	PDX	80	DCS	41	DCS	41	TAC-XNI	ST	PTC system failure (wayside) Signals down rill to nisqually, Other, lakewood sub

12/23/2025

Arriving On: 12/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
511	PDX	36	DCS	41	DCS	41	TAC-XNI	ST	Restrictive signal(s) from unknown cause Stop, Milepost, 10.4, 19.7
517	PDX	28	DCS	30	DCS	30	TAC-XNI	ST	Restrictive signal(s) from known wayside signal failure Dark signals and restricting signals due to power outage, Dark signal, Restricting , Control Point, RILL, Control Point, CP 188
518	VAC	128	FTI	56	FTI	56	EDM-EVR	BN	Meet Held for BNSF @mp 28.9 z train still hadn't arrived @Snohomish at the time of the hold per dispatcher., Milepost, 28.9, 28.9, 7722, 7722
519	SEA	21	FTI	37	FTI	18	STW-EVR	BN	Meet Bnsf 7722, Control Point, PA Jct, z train
7	SEA	620	FTI	296	SYS	256	WEN-WEN	BN	Re-crew / job briefing Recrew sent from SEA to WEN. Had to reroute crew van from US2 to I90 due to Weather over pass, Other, WEN
27	PDX	119	WTR	97	WTR	85	SPK-XPW	BN	High winds 40 MPH speed restriction due to high wind warning CP Spokane St. to MP34 20 MPH speed restriction from MP34 to MP62.3 40 MPH speed restriction from MP 62 to 119.6 high wind warning. Spokane and Lakeside Subdivisions, Other, Spokane Station, Control Point, Mesa
355	CHI	66	PTI	38	PTI	38	DER-ARB	MI	Meet 352, Control Point, 28
586	SAN	No OS Rpt							
587	LAX	No OS Rpt	TRS	98	TRS	98	FUL-FUL	BN	Trespasser strike Trespasser strike by Metrolink train at or around Mile Post 148. Amtrak train 587 held at Fullerton Station. Then given instructions for our train to turn into 586 heading back towards San Diego., Other, FUL
591	LAX	No OS Rpt	TRS	44	TRS	44	SNA-SNA	SC	Trespasser strike Instructed by Orange sub DS to hold at SNA due to track closure at Norwalk from a Metrolink trespasser strike., Other, sna
593	LAX	No OS Rpt	OTH	67	OTH	64	ANA-XFT	SC	Coupled up to Amtrak 591, dragged back to LAUS
774	SAN	62	RTE	46	RTE	46	LPS-LPS	UP	Dispatcher hold Due to rocket launch at AFB, Control Point, lps
784	SAN	35	CTI	27	PTI	18	SNC-SNP	SC	Meet 587, Control Point, serra
785	GTA	No OS Rpt	POL	215	POL	172	FUL-FUL	BN	RR blocked by trespasser or vehicle strike by another train

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/17/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
790	SAN	No OS Rpt	CTI	17	CTI	17	CML-XMR	UP	DS held us for ml127but they never went by ml, 127, Control Point, S. CML
710	BFD	22	FTI	48	FTI	10	SKN-MOD	BN	Cross over or go around Control Point, lake, BNSF 8198 w
713	OKJ	Trn Cancelled	FTI	30	FTI	13	HNF-FNO	BN	Meet BNSF 3909, Control Point, Calwa Crossing
715	OKJ	19	PTI	20	PTI	9	WAC-COC	BN	Meet 702, Control Point, West Elmo
716	BFD	89	SYS	78	SYS	70	OKJ-EMY	UP	Started trip in Emeryville due to late inbound equipment.
718	BFD	108	FTI	120	FTI	109	SKN-MOD	BN	Shoving and did not clear the OS a west Modesto Empire BNSF 6820, Control Point, West Modesto Empire
719	OKJ	28	PTI	40	PTI	13	BFD-WAC	BN	Meet amtrak712, Siding, shafter
3	LAX	301	FTI	164	CAR	122	ABQ-ABQ	NM	Set out defective car 33026, Before move was made OBS had to move food and beverage items to Diner. Set out lounge car 33026 in 312 track.
306	CHI	41	CAR	66	CAR	66	BNL-PON	UP	Air / Brake / Wheel ID4115, Popped & broken GLAD HAND @ Chenoa
380	CHI	28	FTI	37	FTI	22	MAC-GBB	BN	Follow bnsf 7789, Control Point, Avon
390	CHI	47	ENG	35	ENG	35	CHM-CHM	CC	Operating with freight engine (due to mechanical failure) ID4621
392	CHI	45	HLD	23	FTI	14	EFG-MAT	CC	Meet G 888, Control Point, N Neoga
393	CDL	67	ENG	31	ENG	31	CHI-CHI	AM	Air / Brake Replace braided hose on locomotive, ID4621

Amtrak Initial Terminal Details

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/17/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	620	12/17	1		
HAR	624	12/17	1		
HAR	640	12/17	1		
HAR	650	12/17	1		
HAR	652	12/17	1		
HAR	656	12/17	1		
MIA	40	12/17	4	4	Set out defective car 68020, Late arriving a train from the yard due to swapping out a defective diner on
PGH	42	12/17	2	2	Pittsburgh Station did not load any baggage on 42 because of 41 and 40 being late so excess baggage loading our passengers Other, Pittsburgh Station, 40,41
PHL	151	12/17	3		
PHL	190	12/17	1		
PHL	601	12/17	1		
PHL	605	12/17	2	2	PTC - Stop Bypass Permission Required, Control Point, .
RNK	134	12/17	3	3	Passenger and/or baggage Group of last minute passengers
WAS	56	12/17	5	5	Catenary failure, Control Point, C INTERLOCKING, EMERGENCY POWER PLATE IN EFFECT 25W
WAS	2104	12/17	37	37	Catenary failure, Control Point, WAS IVY CITY, COACH YARD, POWER 25W WAS INEFFECT WHICH DELAYED THE RELEASE OF 2104, TO COME TO THE STATION. PLATE RESTORED 729A
WAS	2122	12/17	33	33	Air / Brake, ., 2117 HAD PARKING BRAKE ISSUE. SO THE SET WAS SHOPPED INBOUND, AND THE SHORT TURNED 2121 ARRIVED WAS 518P AND 2122 WAS DUE OUT 530P
BRK	684	12/17	3	3	HEP 119
NHV	478	12/17	5	5	Fuel, LATE RELEASE FROM THE YARD/ BRINGING DIESEL FROM 136
NYP	97	12/17	30	30	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C LATE SERVICING OFF AM98
NYP	111	12/17	10	10	Other electrical failure, 607, LATE RELEASE BY MECHANICAL A/C UNSPECIFIED ENGINE ISSUES
NYP	119	12/17	11	12	Service, turn, or wye train, 130, LATE TURN OFF FOR AM130
NYP	131	12/17	16	2	Disabled train ahead, Other, AM2117, CONGESTION AHEAD DUE TO AM2117 AHEAD WITH STUCK HAND BRAK CAR 3558
NYP	131	12/17	16	14	Disabled train ahead, Other, CP MID, NECESSARY TO REVERSE BACK INTO STATION A/C AM2117 WITH STUCK HAND BRAKE CAR 3558
NYP	181	12/17	3	3	Passenger and/or baggage, BOARDING

Amtrak Initial Terminal Details

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/17/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	233	12/17	9	9	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	239	12/17	4	5	Disabled train ahead, Other, NYP-NYP, AM2170 PENALTY AT "A" INT
NYP	243	12/17	70	70	Undesired emergency application, 92 , LATE FROM SSYD A/C LOSS OF POWER
NYP	291	12/17	2	2	Passenger and/or baggage, BOARDING
NYP	609	12/17	9	9	Disabled train ahead, Other, CP MID , DELAYED AT DEPARTURE A/C AM2117 WITH STUCK HAND BRAK CAR 3558 NORTH TUBE
NYP	643	12/17	2	2	Passenger and/or baggage, BOARDING
NYP	645	12/17	22	19	Disabled train ahead, Other, CP MID, NECESSARY TO REVERSE BACK INTO STATION A/C AM2117 WITH STUCK HAND BRAKE CAR 3558
NYP	645	12/17	22	3	Disabled train ahead, Other, CP MID, NECESSARY TO REVERSE BACK INTO STATION A/C AM2117 WITH STUCK HAND BRAKE CAR 3558
NYP	2107	12/17	8	8	Ice / snow on or under equipment, Other, NYP-NYP, LATE FROM SSYD A/C EXTREME COLD CONDITION FROZE EQUIPMENT
CHI	41	12/17	77	77	Service, turn, or wye train 40, Train 40 arrived in CHI at 346 P
CHI	364	12/17	2	2	Mobility Impaired ADA passenger lift required came out 5 min before departure
CHI	393	12/17	31	31	Air / Brake Replace braided hose on locomotive, ID4621
CHM	390	12/17	35	35	Operating with freight engine (due to mechanical failure) ID4621
GRR	371	12/17	4	4	Wheelchair Late arriving ADA individual needing lift Conductor working alone
PTH	365	12/17	2	2	Air / Brake Train went into emergency before departing., ID4620
SEA	8	12/17	(No OS)		
SEA	509	12/17	9	9	Water, commissary, toilet/trash dumping Other, Seattle King Street Station
SEA	511	12/17	7	7	Crew from AMTK 518 had to bring set from yard to station. 518 was an hour late and crew had to walk to yard 518
SPK	27	12/15	38	38	Service, turn, or wye train 7, Late arrival train 7 into Spokane.Routine switching train 7/27 at Spokane
BFD	703	12/17	4	4	Door C8308, Cab car outside door lock stuck in the open position. Had to force key in and angle it to turn inside mechanism. B end fireman's side (going westbound) doors.
BFD	715	12/17	9	9	Held for or routed around MW work or equipment Amtrak Lead out of service unable to Depart on West End of Station. Train 715 shoved out of East End of Station onto the Main Track lined manual switches causing delay., Other, BFD Station
BFD	717	12/17	2	2	Passenger and/or baggage AC left passenger off that boarded the wrong train
EMY	6	12/17	10	10	Follow 710, Control Point, Kirkham, Control Point, West Emeryville

Amtrak Initial Terminal Details

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/17/2025

Terminal	Train	Date	Late	Delay	Cause
LAX	2	12/17	8	8	Engineer had the wrong leader and PTC would not load. 45
LAX	4	12/17	3	3	Cross Traffic Metrolink, 623, Other, LAX station
OKJ	520	12/17	1		
OKJ	526	12/17	1		
OKJ	712	12/17	6	6	Dispatcher hold After coming out of the yard held for CC TRAIN AT KING ST., Control Point, KING ST
OKJ	716	12/17	(Trn Cxld)		Third Party Engine Failure
OKJ	718	12/17	67	67	Service, turn, or wye train 715
SAC	525	12/17	4	4	Restrictive signal(s) from unknown cause Signal timed out, Red, Control Point, RV989
SAC	539	12/17	2	2	Meet Amt528, Control Point, To Rv988
SAC	541	12/17	1	1	Sacramento mechanical forgot to release blue flag protection. C2003
SJC	544	12/17	2	2	Confused Passenger

Eastern Region

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.7	98.7	94.8	309	1
CDOT	95.0	85.0	92.6	92.4	20	3
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	91.1	91.6	93.8	370	33
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 53(17) South of Florence, SC - Freight Train Interference

18DEC25: Train 53(17) operating with engines 364, 357, and 428 passengers onboard was delayed 70 miles south of Florence, SC on the CSX South End subdivision following CSX I033-17 from Parkton milepost 223.5 to Florence milepost 292.5.

Train	Delay	Comment
53(17)	44"	

Train 243(17) New York, NY - Engine Failure

18DEC25: Train 243(17) operating with engine 92, 5 cars, and engine 706 was delayed departing New York, NY due to a late release from Sunnyside yard involving a loss of power on engine 92. A rescue motor was utilized to set the equipment in the station and allow mechanical to oversee the engine for any issues. No exceptions were taken and the equipment was approved for travel. 223 passengers were boarded and train 243(17) departing New York Penn Station 1 hour and 10 minutes late.

Train	Delay	Comment
243(17)	1'10"	

Train 687(17) West of Haverhill, MA - Police Related

17DEC25: Train 687(17) operating with engine 87, 5 cars, and 234 passengers onboard was delayed 6.5 miles west of Haverhill, MA on the CSX Portland subdivision for a Keolis trespasser strike which occurred on track 2. Train 687(17) was routed around the scene on track 1 once officials opened rails to traffic.

Train	Delay	Comment
687(17)	1'02"	

17DEC25: At 259P-ET, 26-FO-00191 00000005540 Police UNCLASSIFIED 12/23/2025 reported a bridge strike at MP 51.88 UGBR MD Route 7. B&B and Trouble Desk were notified. At 327P-ET, Dual qualified B&B Supervisor Diamonte cleared track and structure for scheduled speed and service.

Train	Delay	Comment
94(17)	02"	
171(17)	03"	
2117(17)	07"	
2159(17)	05"	

Train 2169(17) Providence, RI - Engine Failure

17DEC25: AT 241P-ET, Next Generation Acela 2169(17) operating with PC/2125, 9 cars, PC/2119 and 231 passengers onboard Amtrak New Haven to Boston Subdivision stopped at Hebronville/MP 193.3 due to TSR light and had to cap their speed at 79 MPH. At 341p-ET, Next Generation Acela 2169(17) stopped at MP 143.35 east of Westerly, RI on Track 1 with multiple faults. They reached out to their foreman for assistance. Unable to clear all the faults, Next Generation Acela 2169(17) continued west at 325p-ET, still capped at 79 MPH on account of no TSR light. Upon arrival into New Haven, CT multiple faults were noted on the equipment on lead power car 2125. Amtrak management advised in isolation maneuver and 2169(17) was able to depart stil capped at 79 mph. Once train 2169(17) arrived on Metro North territory, the train was capped at 59 mph due to ACSES being cut out. Upon departure from New York, NY train 2169(17) was capped once again at 79 mph.

Train	Delay	Comment
2169(17)	25"	
2169(17)	1'32"	Capped 79 mph
2169(17)	1'02"	NHV

Train 2117(17) New York, NY - Engine Failure

17DEC25: At 1216P, Acela 2117(17) operating with PC/2019, 6 cars, PC/2014 and 192 passengers onboard, Amtrak NYP subdivision came to a stop at MP 1.9 in the North Tube. A code 500 was initiated as it was determined that C/3558 had a parking brake miss match fault. Acela 2117(17) did not lose headend power as transportation management were engaged. At 1442p Acela 2117(17) was back on the move after cutting out the truck in C/3503 and operated west at 5 miles MPH. Acela 2117(17) was followed by rescue engine 600 until the train operated just west of Bergen Interlocking, where they did some additional troubleshooting. At 116P, the train cleared the North Tube. At 142p, recovered and was okayed to continue west to Washington, DC at normal speed with a High-Speed Rail rider. Residual delays were experienced in the south tube.

Due to the late operation of Acela 2117(17), Acela 2121(17) with an estimated time of arrival into Washington, DC of 508p, short turned for Acela 2122(17) which is scheduled to depart at 530p.

Train	Delay	Comment
2117(17)	1'31"	
2159(17)	07"	
171(17)	27"	
648(17)	08"	
609(17)	09"	
182(17)	09"	
646(17)	29"	
2162(17)	08"	
645(17)	22"	
131(17)	12"	
2122(17)	33"	Short turn off 2121(17)

Washington IVT CH - YARD - Catenary or Wayside Failure

17DEC25: Washington 261-FOI-00197 T 00000005540, I UNCLASSIFIED YARD 12/23/2025 power plate 25W in effect. Morning departure out of Washington Union Station were delayed in the yard. Power plate 25W was restored at 729A-ET, High Speed Rail needed to put the pans up on Acela 2104 (17) so crew could bring it down to the station from the S&I.

Train	Delay	Comment
2104 (17)	37"	
56 (17)	05"	
130 (05)	02"	

25501-00037-0000000550 UNCLASSIFIED
VIA Oakville Subdivision Oakville, ON - Scheduled MAW Work

UPDATE 03OCT25: To accommodate infrastructure maintenance on the VIA Oakville subdivision at Oakville/MP 21.4. As a result, train 63/7098(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay. Train 64/7097(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay.

WBS#: B.TR.100150.5989

Train	Delay	Comment
64(13)	57"	

Eastern Region

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike Damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

None

Operating Highlights

Train 355(17) Battle Creek, MI - Freight Train Interference

18DEC25: Train 355(17) with E/4627, was delayed departing Battle Creek, MI, on Amtrak Michigan Line, due to a planned CN PTC outage. Train 355(17) was required to hold until the outage was over. The outage lasted from 8:30p - 9:05p.

Train	Delay	Comment
355(17)	32"	

Train 306(17) South of Pontiac, IL - Car Failure

18DEC25: Train 306(17), with 120 passengers, was delayed 10 miles south of Pontiac, IL, on UP Joliet subdivision, due to an air hose glad hand being broken on C/4115. Train 306(17) came to a stop at milepost 102 and the crew replaced the hose. Once the hose was replaced and the crew did their required brake tests, train 306(17) was able to proceed.

Train 307(17), with 173 passengers, was delayed meeting 306(17) repairing their air hose. 307(17) first came to a stop at north of Pontiac, IL at milepost 84.4 and then was advanced past Pontiac, IL, and held a second time south of Pontiac, IL at milepost 94.3 on UP Joliet subdivision. Once 306(17) finished with their repairs, they were able to proceed, clearing a route for train 307(17).

Train	Delay	Comment
306(17)	1'06"	
307(17)	1'00"	

Train Pacific Surfliner - Trespasser Incident

18DEC25: Train 785, carrying 214 passengers, was held at Fullerton, California, due to a Metrolink trespasser strike at Commerce, milepost 148, on the BNSF San Bernardino Subdivision. Train 586, with 82 passengers, was also affected. Local police responded to the scene, and all tracks were closed. Train 586 was shoved back to Los Angeles Station to wait for an open route. Metrolink later reported that the strike was fatal.

To assist stranded passengers, bus #5885 was dispatched from LAX to Fullerton to transport passengers to Bakersfield, Hanford, and Fresno, including 13 passengers transferring to Train 2/422 at Los Angeles, CA. Train 587(17) was terminated at Fullerton, CA and the equipment turned for 586(17) to San Bernardino, CA. Train 586(17) originated in Fullerton. At 9:12 p.m. PT, Train 785 resumed movement, navigating around the incident through Commerce Yard with the assistance of a BNSF pilot. The train arrived at Los Angeles at 10:25 p.m. PT.

Train 591(17), with 78 passengers, held at Santa Ana, CA for an open route. Due to Hours of Service restrictions train 591(17) was coupled to 593(17), with 34 passengers, and they double drafted to Los Angeles, CA.

Multiple other trains were delayed for an open route.

Train	Delay	Comment
785(17)	3'35"	
586(17)	2'35"	
591(17)	2'49"	holding for open route then coupling with 593(17)
593(17)	1'04"	coupling to 591(17)
593(17)	57"	hold for open route.
595(17)	22"	Hold for open route
794(17)	1'19"	Hold for open route
587(17)	Term FUL	

Train 355(17) East of Ann Arbor, MI - Passenger Train Interference

18DEC25: Train 355(17) was delayed departing Ann Arbor, MI, on Amtrak Michigan Line, at milepost 22.5, meeting train 352(17).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
355(17)	38"	

Train 393(17) Chicago, IL - Engine Failure

18DEC25: Train 393(17) was delayed departing Chicago, Illinois due to repairing leader E/ID4621. At 350pm, it was reported that there was a leaking air hose on leader E/ID4621. A replacement hose was brought from the diesel pit and the engine was repaired.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
393(17)	31"	

Train 7(15) West of Leavenworth, WA, Freight Train Interference

17DEC25: Train 7(15) after boarding passengers in Leavenworth, train 7(15) was directed into Leavenworth siding, MP 1671.6, Scenic Subdivision of the BNSF Railway. This was to allow for, 2 BNSF freight trains to pass on the single main track. Once the freight trains had cleared train 7(15) was further delayed waiting for BNSF Freight BNSF7722 to pass. Train 7(15) followed BNSF Freight train BNSF7722 from Leavenworth to Everett, WA/milepost 1782.8.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7(15)	3'32"	

Train 370(17) Chicago, IL - Car Failure

17DEC25: Train 370(17) business-coach pair cars ID4214 and ID4130 were bad ordered in Chicago, IL for carrier bolts at 3:10PM. Replacement cars 61054 and 68000 were added for axle count only. As a result, Train 370(17) was overcapacity from Chicago. 23 passengers were downgraded from Business Class to Coach. This resulted in coach class to be overcapacity by -53 passengers from Chicago. 1 bus was sourced and operated express from Chicago, IL to Grand Rapids, MI. Equipment turn of 371(18) was not overcapacity.

WBS#: B.TR.100150.6326

17DEC25: Locomotive 26-F01-0019710 00000005540 signed "UNCLASSIFIED" 716(12/25/2025) experienced a hydraulic pump failure, which could not be repaired in Oakland Maintenance Facility. This led to a shortage of serviceable locomotives in Oakland Maintenance Facility, causing the following equipment turns.

- Train 714(17) Originated in Oakland Jack London Square, using equipment from 711(17).
- Train 713(17) terminated in Emeryville with passengers for Oakland transferring to thruway 6613(17) making extra stop in Oakland. Train equipment turned in Emeryville for 716(17).
- Train 716(17) Originated in Emeryville, using equipment from inbound train 713(17). Passengers boarding in Oakland advised to use train 536(17) to connect with train 716(15) in Emeryville.
- Train 715(17) Terminated in Emeryville, with passengers for Oakland transferring to thruway 6615(17) making additional stop in Oakland. Equipment entered Oakland Maintenance Facility via Kirkham entrance to be fueled before turning as train 718(17) Originating in Oakland.
- Train 718(17) Originated in Oakland Jack London Square, using equipment from 715(17).

Cause: Pending

Train	Delay	Comment
716(17)	1'18" ORIG EMY	Oakland Passengers on 536(17)
718(17)	1'07	OKJ - ITD - Equipment from 715(17)

Train 504(17) North of Salem , OR - Signaling Problems

17DEC25: Train 504(17) was delayed 16 miles north of Salem at Gervais, MP 734.00, Brooklyn Subdivision of the Union Pacific Railroad. The local dispatcher was unable to remotely prove the integrity of signals. This led to the Engineer being required to gain verbal authority to pass signals, while operating the train at reduced speed. Once clear of the affected area - MP 743.00 Hito - the train continued at track speed to Oregon City.

Train	Delay	Comment
504(17)	45"	

Train 6(17) Roseville, CA - Passenger Removal - Medical

17DEC25: Train 6(17) was delayed departing Roseville station when paramedics were called to assist with a immobile passenger. Passenger (PNR# F27F79) - travelling from Roseville to Mount Pleasant, IA - boarded the train in Roseville, after walking the stairs could not descend the stairs. The passenger became increasingly agitated at their situation causing breathing difficulties. The attending Roseville Fire Dept. personnel boarded the train and removed the passenger for evaluation at a nearby medical center. Amtrak Police Notified.

Train	Delay	Comment
6(17)	54"	

Train 5(16) East of Fraser-Winter Park, CO - Freight Train Interference

17DEC25: Train 5(16) held 4.2 miles east of Fraser-Winter Park, CO/MP62.3, on the UPRR Moffat Tunnel Subdivision, in the West Winter Park siding/MP58.1 from freight interference. MGJNY-16 / UP8599 was stopped ahead on the single mainline at MP62 completing a knuckle change. Once the knuckle was replaced, MGJNY-16 was able to advance east in between the switches at Winter Park in order to let Train 5(16) continue west.

Train	Delay	Comment
-------	-------	---------

Train 6(15) West of Burlington, IA - B&B Work Due to Defect

17DEC25: Train 6(15) 26-FOT-001974 00000005540 West "UNCLASSIFIED" Burlington 12/23/2025 MP208.0, on the BNSF Ottumwa Subdivision, at MP208.0 behind BNSF 7685 due to the Burlington River Bridge malfunction at MP204.7. Buildings and Bridges (B&B) responded to the location to troubleshoot. Once the bridge was able to be seated and locked, Train 6(15) was on the move following BNSF 7685 until they were able to get by at Lucas St/MP206.7.

Train	Delay	Comment
6(15)	31"	BNSF 7685
6(15)	50"	Bridge

Train 504(17) North of Salem, OR - Fallen Trees & Commercial Power Lines

17DEC25: Train 504(17) was delayed by downed power lines blocking main track 22 miles North of Salem at Hito, MP 740.89 Brooklyn Subdivision of Union Pacific Railroad. A team of track maintenance workers along with local Public Utilities workers were required to make safe and remove downed power cables before train 504(17) continued to Oregon City.

Train	Delay	Comment
504(17)	1'10"	

Train 1(17) North of New Orleans, LA - Freight Train Interference

17DEC25: Train 1(17) was delayed 3 miles north of New Orleans, LA/MP0.0, on the CNRR McComb Subdivision, at East Bridge Jct/MP906.4 waiting for cross traffic to clear.

Train	Delay	Comment
1(17)	41"	

Train 503(17) South of Tacoma Dome WA. - Signal Failure

17DEC25: Train 503(17) was delayed 8 miles South of Tacoma Dome WA at Rill, MP 10.7, Lakewood Subdivision, BNSF Railway. The local dispatched was unable to remotely operate the signals in favor of the trains' route. The Engineer was required to gain authority to pass the signal while operating at reduced speed. Once clear of the affected area (at Nisqually MP 21.3) train 503(17) was able to continue at track speed to Olympia.

Train	Delay	Comment
505(17)	46"	
503(17)	33"	
500(17)	17"	
517(17)	30"	
507(17)	41"	Signal Problems Rill
507(17)	38"	Nisqually - Meet 504(17)
502(17)	17"	Nisqually - Meet 505(17)
502(17)	35"	Rill - Signal Problems
504(17)	33"	
509(17)	09"	SEA - Equipment Turn From 504(17)
11(17)	1'32"	
14(16)	25"	
508(17)	23"	
506(17)	52"	
518(17)	53"	
509(17)	57"	Signal Issues Rill
511(17)	41"	Signal Issues Rill

Train 390(17) Champaign-Urbana, IL - Engine Failure

17DEC25: Train 390(17) was delayed 35 minutes at Champaign, IL, 12/23/2025, delayed departing Champaign-Urbana, IL/MP127.9, on the CNRR Champaign Subdivision, from engine failure. This was a result of Train 391(17) reporting an oil leak on engine ID4623 at Homewood, IL. Due to the issue being with the rear unit, Train 391(17) was able to continue as is to Champaign. The train was operating push-pull due to trackwork and at Champagne, engine ID4623 was placed in the lead position. As a result, freight unit UP3040 was sourced at Champaign and added to the head end prior to departure. Amtrak's Bloomington Road Foreman was on site to assist in adding the unit. Buses were originally sourced and later cancelled. At 11:59AM, Train 390(17) departed Champagne operating 35 minutes late.

WBS#: B.TR.100150.6323

Train	Delay	Comment
390(17)	35"	ITD CHM
391(17)	05"	HMW - Inspect

Train 500(17) North of Vancouver, WA -Freight Train Interference

17DEC25: Train 500(17) was delayed 23 miles North of Vancouver at Toteff MP 114.1, Seattle Subdivision, BNSF Railway. BNSF Freight Train FOGLSE 16 (BNSF/7277) was required to inspect their train after activating a trackside dragging equipment detector. BNSF Freight PASTAC1 16 (BNSF/5779) was stopped on the adjacent track from where the crew assisted in securing a loose container door. Once cleared safe to proceed, the freight trains proceed allowing train 500(17) to continue to Kelso.

Train	Delay	Comment
500(17)	37"	
505(17)	21"	Tacoma - Meet 500(17)

Train 774(17) – South of Lompoc Surf, CA (Rocket Launch)

17DEC25: Train 774(17) was held at Lompoc Surf Station (MP 299.3, Santa Barbara Subdivision) due to a scheduled SpaceX Falcon 9 launch from Vandenberg Space Force Base. Following the launch, Union Pacific maintenance crews inspected the track for debris before authorizing the train to proceed.

Train	Delay	Comment
774(17)	46"	

Train 523(17) Richmond, CA - Passenger Removal - Injury

17DEC25: Train 523(17) was delayed departing Richmond station when paramedics were called to assist an injured passenger. Passenger PNR# 2E71E8 travelling between Sacramento and Richmond, stumbled on the last stair while attempting to exit the train causing an ankle injury. Richmond City Fire Dept. were quick to respond removing the passenger from the train for evaluation at a nearby medical center. Amtrak Police Notified.

Train	Delay	Comment
523(17)	24"	

17DEC25: A powerful 26-FOI-00197sy00000005540 impact "UNCLASSIFIED" of 12/23/2025 northern Canada and the northern United States expected to end Friday night is bringing heavy snow, blizzard conditions, and high winds to the area. This caused extensive delays to Amtrak's Empire Builder Service.

Train 7(15) was heavily delayed after departing Spokane, WA, on the BNSF Columbia River Subdivision, from high wind warnings all the way to Wenatchee, WA/MP1650.0. At Wenatchee, Train 7(15) with 87 passengers onboard held at the station for multiple downed trees to be removed ahead. Once the trees were removed, additional hold was incurred waiting on the recrew to arrive from Seattle. Weather conditions caused delays to the crews transit to Wenatchee. Service recovery was enacted which consisted of snack packs and water for all passengers. The diner offered lunch meal service for all passengers into Seattle. The Sleeper passengers meals were not affected.

Train 27(15) was headily delayed between Spokane, WA and Pasco, WA/MP145.4 from high wind warnings. Train 27(15) operated through 20MPH speed restrictions from MP34 to MP62.3 and then 40MPH from MP62 to MP119.6

Train 27(15) was delayed departing Wenatchee, WA waiting for track maintenance personnel to clear downed trees from the track ahead. Train 7(15) was delayed further at Wenatchee waiting for relief crew after the assigned crew expired maximum permitted hours of service. The relief crew were delayed arriving to the train by hazardous driving conditions and numerous road closures and washout conditions.

Train 8(16) started seeing delays 32.1 miles east of Ephrata, WA/MP1599.1, on the BNSF Columbia River Subdivision, due to high winds reducing operating speeds to 40MPH from MP1567 to Latah Jct/MP1481.6. Additional delays to Train 8/28(16) after departing Spokane, WA/MP71.6 from high wind warning reducing operating speeds to Libby, MT/MP1319.6. Addition delay holding at West Libby/MP1322.0 due to power lines down at MP1320.3. The local power company responded and was able to reroute the fiber optics under the track. Once this was complete, Train 8/28(16) had a route to continue east but was still heavily delayed from continued high winds spanning the whole state of Montana.

Due to the extensive delays taken to 8/28(16), two supplemental downline buses were secured between St. Paul and Chicago. Bus 'A' made station stops to St. Paul, Wisconsin Dells, and Chicago. Bus 'B' will make station stops to St. Paul, Red Wing, Winona, La Crosse, Tomas, Wisconsin Dells, Portage, Columbus, and Milwaukee. All passengers on buses 'B' destined east of Milwaukee will board the next eastbound Hiawatha.

Train 7/27(16) was delayed between Williston, ND and Wolf Point, MT due to High Wind Speed Restrictions. Train 7(15) operated at 20MPH from milepost 178 to milepost 317.5. Train 7/27(16) then held west of Wolf Point, MT at milepost 317.7 due to winds exceeding 100MPH as well as blizzard conditions. 7/27(16) was delayed waiting for a recrew that was delayed due to blizzard conditions. Train 7/27(16) crew was ordered by supervision to violate hours of service and they operated to the location of the recrew. 7(16) was also delayed west of Malta, MT, due to BSNF track indication. BNSF maintenance of way crews responded to the scene to inspect and repair any defects.

WBS#: B.TR.100150.6325

Train	Delay	Comment
8(16)	42"	High Winds EPH-SPK
27(15)	1'37"	High Winds SPK-PSC
7(15)	2'08"	High Winds SPK-WEN
7(15)	4'16"	WEN - Trees / Recrew
8/28(16)	39"	Power Lines W/LIB
8/28(16)	1'18"	High Winds SPK-LIB
7(15)	4'16"	WEN - Clearing Tress and Waiting Relief Crew
7(16)	3'41"	High Wind restrictions
7(16)	30"	High wind restrictions MAL-HAV
7(16)	4'44"	High wind restrictions, recrew, track defects GGW-MAL

Train 3(15) West of Gallup, NM - Freight Train Interference

17DEC25: Train 3(15) ~~26-FOI-00197~~ ~~00000005540~~ ~~UNCLASSIFIED~~ ~~12/23/2025~~ starting west of Gallup, NM/MP157.5, on the BNSF Gallup Subdivision, following a BNSF freight train from MP171.1 to Adamana/MP235.0. Additional delay incurred on the BNSF Seligman Subdivision starting 44 miles west of Winslow, AZ/MP285.5 following another BNSF freight train from MP329.5 to West Seligman/MP429.7. At West Seligman, located 85.5 miles west of Flagstaff, AZ/MP344.2, Train 3(15) held for the recrew to arrive that was riding Train 4(16) from Kingman. Once the recrew was onboard, Train 3(15) was able to proceed west.

Train	Delay	Comment
3(15)	34"	FTI GLP-WLO
3(15)	1'11"	FTI WLO-Seligman
3(15)	1'20"	Holding for Recrew

0000005481 UNCLASSIFIED 12/3/2025
Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Burlington Northern Santa Fe Brookfield Subdivision East of Quincy, IL - Scheduled M/W Work

09DEC25: To accommodate a Burlington Northern Santa Fe Brookfield Subdivision Track work December 9th through December 12th and December 15th through December 17th between Quincy, IL and Galesburg, IL, The follow operating plan will be in effect for Carl Sandburg Service Train 381:

- Train 381 (09) will operate 2-hours later between Chicago, IL and Quincy, IL.
- Train 381 (10-12) & 381 (15-17) will operate 1-hour later between Chicago and Quincy.

WBS#: B.TR.100150.6234

Western Region

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5(2)	GSC	51		Strike damage, will go in freight service to BEE

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8(16)	SEA	BN6559	Added back to 8(16) off of 7(14) due to trail eng 182 not passing departure test		
390(17)	CHM	UP3040	ID4623 oil leak	CHI	12//17/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 22(16) Passenger Removal at Joliet, Illinois – Medical***

17DEC25, Passenger on PNR 2E5D45, traveling from St. Louis, MO to Chicago, IL passenger was removed by local EMS at Joliet, IL unable to respond verbally and seemed confused and distraught. Amtrak Police notified.

Delay: 22(16) 21"

Train 6(17) Passenger Removal at Roseville, California – Medical

17DEC25, Passenger on PNR F27F79, traveling from Roseville, CA to Mount Pleasant, IA was removed from the train by EMS after becoming agitated from not being able to navigate the stairs. Passenger had difficulty breathing. Amtrak Police notified.

Delay: 6(17) 54"

Train 27(15) Passenger Removal at Bingen, Washington – Improper Behavior

17DEC25, Passenger on PNR 2863C2, traveling from Chicago, IL to Portland, OR was removed from the train by Stevenson Police after causing a ruckus when the man and woman were found in the restroom together. Amtrak Police notified.

Delay: 27(15) 41"

Train 6(17) Passenger Removal at Elko, Nevada – Improper Behavior

26-FOI-00197 00000005540 "UNCLASSIFIED" 12/23/2025

17DEC25, Passenger on PNR 1F5E45, traveling from Emeryville, CA to Chicago, IL was removed from the train by Elko Police after passenger was making racist remarks and having a "service animal" that snapped at the Conductor. Amtrak Police notified.

Delay: 6 (17) 12"

Consist Deviations

26-FOI-00197

00000005540

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
179 (17)	BOS	Train will operate with a coach care in lieu of a business class car. Please reaccommodate all affected passengers accordingly.	PAX ADV NO SEATING ASSIGNMENT	0	25117
190 (17)	BOS	Train will operate with a business class car in lieu of a coach car.			81525
137 (17)	BOS	Train will operate with a business class car in lieu of a coach car.			81525
307 (17)	CHI	Due to shopped equip, 307(17) & 302(18) will operate WITHOUT Biz class service. customer service notified of over capacity.			ID4606
50 (18)	CHI	Viewliner 1 in lieu of viewliner 2 sleeper. no impact to customers.	NO PAX IMPACT	0	62008
370 (17)	CHI	Due to shopped equipment and no replacement, we're over capacity and no biz class. customers were impacted and notified customer service			61054
371 (18)	GRR	Due to shopped equipment and no replacement, we're over capacity and no biz class. customers were impacted and notified customer service			61054
40 (17)	MIA	Due to shopped equipment in HIA, 40(17) has no diner, will only operate w/ 28022 as food service.	MIA FIX DINNER	0	28022
51 (17)	NYP	Viewliner 1 being used in lieu of viewliner 2, no impact to customers.	NO PAX IMPACT	0	62008
151 (17)	PHL	B/O 48157 WITH BEST REPLACEMENT 43397, CUSTOMER SERVICE WILL DOWNGRADE BUSINESS CLASS JY PASSENGERS	Passengers were downgraded due to change of equipment	21	48157
86 (17)	RVM	Train will operate with a coach care in lieu of a business class car. Please	PAX ADV NO SEAT ASSIGNMENT	0	25117

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		reacommodate all affected passengers accordingly.			
302 (18)	STL	Due to shopped equip, 302(18) will operate WITHOUT Biz class service. customer service notified of over capacity.			ID4606

Reverse Consists

Train Number	Station	Reason
280 (17)	NFL	Consist reversed Business class seat orientation may have changed At Front
85 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
171 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
183 (17)	NYP	Consist reversed Business class seat orientation may have changed At Front
190 (17)	PHL	Consist reversed Business class seat orientation may have changed At Front
2153 (17)	BOS	Acela consist reversed First class at Rear
94 (18)	NFK	Consist reversed Business class seat orientation may have changed At Front
86 (18)	RVM	Consist reversed Business class seat orientation may have changed At Front
137 (17)	BOS	Consist reversed Business class seat orientation may have changed At Front
134 (18)	RNK	Consist reversed Business class seat orientation may have changed At Front