

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, December 19, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-00197 Initial Terminal Performance By Division

Scheduled Departure Date: 12/18/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/18/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	58	81.5%	5,467	860	84.3%	23,376	3,050	87.0%
Central Division	85.5%	66	13	80.3%	1,179	199	83.1%	5,201	568	89.1%
Northeast Division	80.0%	100	14	86.0%	1,743	266	84.7%	7,339	1,018	86.1%
Southeast Division	72.5%	73	17	76.7%	1,266	213	83.2%	5,465	730	86.6%
Southwest Division	77.0%	74	14	81.1%	1,279	182	85.8%	5,371	734	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00197 00000005539 UNCLASSIFIED Endpoint Arrival Dates through 12/18/25 12/23/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	97,330	24,957	74%	1,771,736	440,827	75%	7,966,470	1,689,032	79%
Northeast Corridor	81%	44,497	9,784	78%	811,159	197,562	76%	3,602,560	715,446	80%
Acela	83%	10,118	2,122	79%	184,630	55,321	70%	776,830	173,000	78%
Northeast Regional	79%	34,379	7,662	78%	626,529	142,241	77%	2,825,730	542,446	81%
Richmond / Newport News / Norfolk	77%	10,349	3,289	68%	190,870	48,300	75%	856,876	191,805	78%
Springfield Shuttles	89%	994	88	91%	14,534	1,709	88%	48,056	5,404	89%
Roanoke	79%	2,691	1,184	56%	48,584	9,427	81%	217,337	36,176	83%
On Spine Northeast Regional	80%	20,345	3,101	85%	372,541	82,805	78%	1,703,461	309,061	82%
State Supported	80%	42,369	11,160	74%	745,989	160,557	78%	3,392,663	643,612	81%
Borealis	60%	547	515	6%	9,806	3,053	69%	46,096	12,624	73%
Capitol Corridor	90%	3,734	319	91%	63,274	6,807	89%	281,867	30,203	89%
Carolinian	60%	1,085	379	65%	20,108	6,887	66%	93,254	27,789	70%
Cascades	63%	2,237	1,237	45%	37,879	10,879	71%	184,168	46,216	75%
Downeaster	82%	1,339	313	77%	24,795	4,037	84%	116,053	15,813	86%
Empire	78%	5,706	2,749	52%	92,937	21,304	77%	409,121	82,849	80%
Adirondack	72%	351	267	24%	4,868	2,389	51%	25,767	8,940	65%
Ethan Allen Express	70%	575	318	45%	9,674	2,736	72%	46,667	14,257	69%
Maple Leaf	70%	828	730	12%	11,993	6,196	48%	47,375	17,984	62%
New York - Albany	85%	2,561	962	62%	43,123	4,942	89%	181,730	24,064	87%
New York - Niagara Falls	75%	1,391	472	66%	23,279	5,041	78%	107,582	17,604	84%
Gold Runner	73%	2,195	879	60%	39,104	13,133	66%	193,152	68,778	64%
Heartland Flyer	65%	206	41	80%	3,063	659	78%	15,572	8,229	47%
Hiawatha	90%	1,210	274	77%	30,728	5,421	82%	137,181	16,336	88%
Illinois	78%	2,385	488	80%	41,726	17,561	58%	191,563	56,879	70%
Carl Sandburg / Illinois Zephyr	85%	388	217	44%	7,683	2,576	66%	32,841	9,134	72%
Illini / Saluki	85%	759	97	87%	12,226	5,525	55%	67,050	18,984	72%
Lincoln Service	70%	1,238	174	86%	21,817	9,460	57%	91,672	28,761	69%
Keystone	92%	10,182	235	98%	159,062	23,662	85%	654,640	64,473	90%
Lincoln / Missouri	60%	792	598	24%	12,889	6,448	50%	61,189	31,104	49%
Mardi Gras Service	80%	368	0	100%	6,505	172	97%	34,178	3,931	88%
Michigan	69%	1,904	1,504	21%	34,800	17,337	50%	154,135	47,225	69%
Blue Water	70%	203	203	0%	7,297	3,974	46%	38,082	11,269	70%
Pere Marquette	85%	242	93	62%	4,704	1,451	69%	20,600	3,380	84%
Wolverine	65%	1,459	1,208	17%	22,799	11,912	48%	95,453	32,576	66%
Missouri	80%	285	114	60%	3,895	1,076	72%	18,465	4,612	75%
Pacific Surfliner	85%	5,181	835	84%	108,184	9,080	92%	521,172	67,227	87%
Pennsylvanian	72%	898	12	99%	15,779	1,853	88%	72,803	8,051	89%
Piedmont	73%	734	153	79%	17,783	2,992	83%	102,112	24,823	76%
Vermont	75%	1,381	515	63%	23,672	8,196	65%	105,942	26,450	75%
Long Distance	56%	10,464	4,013	62%	214,588	82,708	61%	971,247	329,974	66%
Auto Train	57%	745	0	100%	12,535	2,995	76%	52,360	10,206	81%
California Zephyr	50%	438	23	95%	14,198	5,082	64%	71,006	20,753	71%
Cardinal	55%	369	254	31%	4,806	2,216	54%	22,162	10,521	53%
City Of New Orleans	75%	604	262	57%	11,841	2,071	83%	55,167	11,793	79%
Coast Starlight	60%	1,153	939	19%	20,489	5,957	71%	91,027	28,332	69%
Crescent	70%	892	70	92%	16,378	2,848	83%	75,493	18,630	75%
Empire Builder	55%	0	0	-	15,609	7,009	55%	76,026	27,270	64%
Floridian	40%	1,577	1,364	14%	29,769	19,824	33%	133,670	74,196	44%
Lake Shore Ltd	73%	1,150	173	85%	18,699	6,613	65%	74,627	14,874	80%
Palmetto	65%	898	172	81%	16,621	5,105	69%	76,430	13,536	82%
Silver Meteor	45%	997	89	91%	18,050	7,084	61%	80,799	25,418	69%
Southwest Chief	40%	714	284	60%	12,934	8,804	32%	64,508	39,158	39%
Sunset Ltd	70%	0	0	-	4,871	637	87%	21,253	4,861	77%
Texas Eagle	50%	927	383	59%	17,788	6,463	64%	76,719	30,426	60%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005500 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 18, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	112,605	1,944,044	579	442,487	8,452,837	523

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	5,386	576,745	93	17,741	2,478,981	72
INFRASTRUCTURE PLANNED	135	3,097	576,745	54	13,678	2,478,981	55
FLEET RELIABILITY	90	21,531	1,944,044	111	69,415	8,452,837	82
TRAIN OPERATIONS	424	82,591	1,944,044	425	341,653	8,452,837	404

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/18/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/18/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	58	81.5%	5,467	860	84.3%	23,376	3,050	87.0%
Central Division	85.5%	66	13	80.3%	1,179	199	83.1%	5,201	568	89.1%
Northeast Division	80.0%	100	14	86.0%	1,743	266	84.7%	7,339	1,018	86.1%
Southeast Division	72.5%	73	17	76.7%	1,266	213	83.2%	5,465	730	86.6%
Southwest Division	77.0%	74	14	81.1%	1,279	182	85.8%	5,371	734	86.3%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/18/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/18/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	58	81.5%	5,467	860	84.3%	23,376	3,050	87.0%
Central Division	85.5%	66	13	80.3%	1,179	199	83.1%	5,201	568	89.1%
CDL	90.0%	1	0	100.0%	19	1	94.7%	133	7	94.7%
CHI	85.0%	28	6	78.6%	480	101	79.0%	2,113	238	88.7%
CHM	-	1	0	100.0%	9	4	55.6%	9	4	55.6%
EUG	86.5%	1	0	100.0%	35	4	88.6%	152	19	87.5%
GRR	98.0%	1	0	100.0%	17	2	88.2%	78	2	97.4%
KCY	84.5%	2	0	100.0%	36	3	91.7%	156	14	91.0%
MKE	86.5%	6	2	66.7%	106	11	89.6%	462	41	91.1%
MSP	94.0%	1	0	100.0%	18	0	100.0%	79	3	96.2%
PDX	78.0%	5	2	60.0%	90	10	88.9%	396	56	85.9%
PNT	91.5%	3	1	66.7%	53	12	77.4%	179	17	90.5%
PTH	93.0%	1	0	100.0%	17	4	76.5%	78	6	92.3%
QCY	87.5%	2	0	100.0%	36	3	91.7%	158	15	90.5%
SEA	80.0%	7	1	85.7%	142	24	83.1%	627	98	84.4%
SPK	92.0%	1	0	100.0%	20	3	85.0%	81	4	95.1%
STL	88.0%	4	1	75.0%	70	16	77.1%	312	34	89.1%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	31	1	96.8%	153	5	96.7%
Northeast Division	80.0%	100	14	86.0%	1,743	266	84.7%	7,339	1,018	86.1%
ALB	91.5%	7	0	100.0%	126	7	94.4%	493	28	94.3%
BON	43.5%	5	1	80.0%	90	6	93.3%	377	38	89.9%
BOS	86.5%	20	4	80.0%	344	44	87.2%	1,442	147	89.8%
BRK	88.0%	5	0	100.0%	90	4	95.6%	357	17	95.2%
BTN	48.0%	1	0	100.0%	18	0	100.0%	78	17	78.2%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	36	3	91.7%	152	12	92.1%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	18	3	83.3%	79	14	82.3%
NFL	96.5%	2	0	100.0%	36	1	97.2%	158	5	96.8%
NHV	75.5%	6	0	100.0%	102	12	88.2%	409	75	81.7%
NYP	77.5%	42	9	78.6%	723	181	75.0%	3,099	611	80.3%
SAB	98.0%	1	0	100.0%	18	0	100.0%	77	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	124	2	98.4%	473	18	96.2%
TWO	84.0%	1	0	100.0%	18	3	83.3%	78	19	75.6%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	73	17	76.7%	1,266	213	83.2%	5,465	730	86.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	90	6	93.3%	395	31	92.2%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	5	61.5%	210	58	72.4%	890	156	82.5%
LOR	69.5%	1	0	100.0%	18	1	94.4%	79	6	92.4%
MIA	87.5%	2	0	100.0%	36	5	86.1%	158	18	88.6%
MOE	94.0%	2	0	100.0%	36	0	100.0%	158	3	98.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/18/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/18/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	313	58	81.5%	5,467	860	84.3%	23,376	3,050	87.0%
Southeast Division	72.5%	73	17	76.7%	1,266	213	83.2%	5,465	730	86.6%
NFK	86.0%	3	1	66.7%	52	8	84.6%	222	23	89.6%
NOL	92.0%	4	0	100.0%	80	3	96.3%	349	17	95.1%
NPN	96.0%	2	1	50.0%	36	1	97.2%	133	8	94.0%
PGH	92.0%	1	0	100.0%	18	2	88.9%	79	3	96.2%
PHL	45.0%	5	3	40.0%	84	54	35.7%	365	177	51.5%
RGH	97.0%	4	0	100.0%	72	4	94.4%	312	7	97.8%
RNK	85.5%	2	0	100.0%	36	5	86.1%	157	19	87.9%
RVM	86.0%	1	0	100.0%	18	2	88.9%	89	13	85.4%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	18	2	88.9%	79	2	97.5%
SFA	70.5%	1	0	100.0%	18	0	100.0%	79	3	96.2%
WAS	70.0%	26	7	73.1%	444	62	86.0%	1,913	239	87.5%
Southwest Division	77.0%	74	14	81.1%	1,279	182	85.8%	5,371	734	86.3%
ARN	60.5%	1	0	100.0%	18	1	94.4%	79	6	92.4%
BFD	75.5%	7	1	85.7%	118	25	78.8%	465	109	76.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	4	4	0.0%	20	11	45.0%	83	28	66.3%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	18	0	100.0%	78	3	96.2%
GTA	72.5%	3	0	100.0%	54	2	96.3%	230	19	91.7%
LAX	77.5%	9	2	77.8%	168	22	86.9%	728	83	88.6%
OKC	96.0%	1	0	100.0%	18	0	100.0%	79	3	96.2%
OKJ	79.0%	10	2	80.0%	209	66	68.4%	869	218	74.9%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	16	2	87.5%	259	33	87.3%	1,047	119	88.6%
SAN	77.0%	12	2	83.3%	208	10	95.2%	901	75	91.7%
SAS	85.0%	1	0	100.0%	18	1	94.4%	79	4	94.9%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	1	85.7%	126	9	92.9%	551	49	91.1%
SLO	62.0%	2	0	100.0%	36	1	97.2%	153	12	92.2%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3		18	5	72.2%	79	9	88.6%	17	9	47.1%	78	32	59.0%
4	158	17	6	64.7%	78	12	84.6%	17	13	23.5%	78	51	34.6%
5		18	7	61.1%	78	14	82.1%	17	5	70.6%	76	11	85.5%
6	715	16	7	56.3%	77	24	68.8%	16	5	68.8%	77	26	66.2%
7	Cncld	18	4	77.8%	79	8	89.9%	14	5	64.3%	75	12	84.0%
8	No OS	18	12	33.3%	79	32	59.5%	18	9	50.0%	79	36	54.4%
11	167	18	3	83.3%	78	14	82.1%	18	3	83.3%	76	10	86.8%
14	38	18	1	94.4%	79	10	87.3%	18	1	94.4%	78	19	75.6%
19		18	5	72.2%	79	13	83.5%	18	1	94.4%	79	12	84.8%
20		18	0	100.0%	79	6	92.4%	18	1	94.4%	79	7	91.1%
21		18	4	77.8%	78	12	84.6%	18	5	72.2%	78	16	79.5%
22		18	1	94.4%	79	4	94.9%	18	3	83.3%	78	16	79.5%
23		18	0	100.0%	79	3	96.2%	18	1	94.4%	79	11	86.1%
24		18	3	83.3%	79	5	93.7%	18	1	94.4%	79	7	91.1%
25		18	0	100.0%	79	0	100.0%	18	0	100.0%	79	9	88.6%
26		18	0	100.0%	79	2	97.5%	18	0	100.0%	79	11	86.1%
27	Cncld	18	4	77.8%	79	5	93.7%	17	6	64.7%	78	16	79.5%
28		17	3	82.4%	78	16	79.5%	18	1	94.4%	79	9	88.6%
40	65	18	4	77.8%	79	13	83.5%	18	8	55.6%	79	30	62.0%
41	73	18	10	44.4%	79	28	64.6%	18	12	33.3%	79	51	35.4%
42		18	2	88.9%	79	3	96.2%	18	2	88.9%	79	11	86.1%
43		18	2	88.9%	79	7	91.1%	18	1	94.4%	79	4	94.9%
48		18	6	66.7%	79	11	86.1%	18	5	72.2%	79	8	89.9%
49		18	2	88.9%	79	12	84.8%	18	5	72.2%	79	10	87.3%
51	37	7	2	71.4%	34	16	52.9%	7	2	71.4%	33	11	66.7%
52		18	0	100.0%	79	3	96.2%	18	2	88.9%	79	14	82.3%
53		18	1	94.4%	79	6	92.4%	18	4	77.8%	79	12	84.8%
55		14	0	100.0%	56	0	100.0%	14	4	71.4%	56	10	82.1%
56		14	5	64.3%	56	12	78.6%	14	4	71.4%	56	10	82.1%
58		18	0	100.0%	78	2	97.4%	18	4	77.8%	77	11	85.7%
59	72	18	2	88.9%	77	5	93.5%	18	2	88.9%	77	5	93.5%
63	24	18	6	66.7%	79	27	65.8%	18	11	38.9%	79	40	49.4%
64	70	18	3	83.3%	78	19	75.6%	18	6	66.7%	78	16	79.5%
66		18	2	88.9%	79	12	84.8%	18	1	94.4%	79	14	82.3%
67		14	1	92.9%	56	3	94.6%	14	2	85.7%	56	9	83.9%
68	33	18	3	83.3%	79	14	82.3%	18	12	33.3%	79	37	53.2%
69		18	1	94.4%	79	8	89.9%	18	3	83.3%	79	10	87.3%
71	13	18	1	94.4%	79	1	98.7%	18	5	72.2%	79	21	73.4%
72	13	18	3	83.3%	79	8	89.9%	18	8	55.6%	79	18	77.2%
73		18	2	88.9%	79	3	96.2%	18	5	72.2%	78	38	51.3%
74	21	18	1	94.4%	79	6	92.4%	18	4	77.8%	79	24	69.6%
75	17	18	0	100.0%	79	2	97.5%	18	7	61.1%	79	35	55.7%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		18	0	100.0%	79	4	94.9%	18	4	77.8%	79	34	57.0%
77	15	18	1	94.4%	79	3	96.2%	18	7	61.1%	79	29	63.3%
78		18	0	100.0%	79	3	96.2%	18	2	88.9%	79	11	86.1%
79		18	4	77.8%	79	15	81.0%	18	3	83.3%	78	14	82.1%
80		18	2	88.9%	79	10	87.3%	18	5	72.2%	78	10	87.2%
84	17	14	0	100.0%	56	3	94.6%	14	4	71.4%	56	9	83.9%
85	22	14	1	92.9%	56	2	96.4%	14	7	50.0%	56	22	60.7%
86	39	14	1	92.9%	56	5	91.1%	14	10	28.6%	56	29	48.2%
89		18	5	72.2%	79	17	78.5%	18	7	61.1%	79	13	83.5%
90		18	2	88.9%	79	2	97.5%	18	3	83.3%	79	9	88.6%
93	23	14	2	85.7%	56	8	85.7%	14	1	92.9%	55	11	80.0%
94		14	6	57.1%	56	12	78.6%	13	4	69.2%	55	16	70.9%
95	24	14	0	100.0%	56	1	98.2%	14	5	64.3%	56	16	71.4%
97		18	13	27.8%	79	31	60.8%	18	3	83.3%	79	19	75.9%
98		18	1	94.4%	79	5	93.7%	18	7	61.1%	79	18	77.2%
110		14	7	50.0%	56	26	53.6%	14	2	85.7%	56	5	91.1%
111	22	14	3	78.6%	56	7	87.5%	14	3	78.6%	56	6	89.3%
112		14	1	92.9%	56	5	91.1%	14	1	92.9%	56	6	89.3%
114		14	3	78.6%	56	11	80.4%	13	2	84.6%	55	2	96.4%
119		14	2	85.7%	56	11	80.4%	14	2	85.7%	56	5	91.1%
125		14	0	100.0%	56	2	96.4%	14	8	42.9%	56	14	75.0%
129		14	6	57.1%	56	19	66.1%	14	2	85.7%	56	8	85.7%
130		14	0	100.0%	56	4	92.9%	14	1	92.9%	56	5	91.1%
131		14	2	85.7%	56	6	89.3%	14	4	71.4%	56	4	92.9%
133		14	4	71.4%	56	23	58.9%	14	3	78.6%	56	23	58.9%
134		14	2	85.7%	56	6	89.3%	14	3	78.6%	56	11	80.4%
136		14	2	85.7%	56	5	91.1%	13	1	92.3%	56	4	92.9%
137		14	2	85.7%	54	10	81.5%	14	3	78.6%	54	13	75.9%
138		14	2	85.7%	56	8	85.7%	14	0	100.0%	56	2	96.4%
141		14	0	100.0%	56	3	94.6%	14	4	71.4%	56	12	78.6%
148		14	2	85.7%	56	6	89.3%	14	0	100.0%	55	9	83.6%
151	16	18	9	50.0%	79	23	70.9%	18	7	61.1%	78	23	70.5%
170	34	14	2	85.7%	53	5	90.6%	14	6	57.1%	53	15	71.7%
171	78	14	1	92.9%	56	4	92.9%	14	5	64.3%	56	10	82.1%
172	22	14	3	78.6%	56	7	87.5%	14	6	57.1%	56	21	62.5%
173	19	14	3	78.6%	56	5	91.1%	14	7	50.0%	56	22	60.7%
174		14	0	100.0%	56	3	94.6%	14	3	78.6%	56	11	80.4%
175		14	3	78.6%	56	5	91.1%	14	5	64.3%	56	13	76.8%
176		14	1	92.9%	56	4	92.9%	14	0	100.0%	56	3	94.6%
177		14	2	85.7%	56	10	82.1%	14	4	71.4%	56	24	57.1%
178		14	1	92.9%	56	8	85.7%	13	0	100.0%	56	5	91.1%
179		14	1	92.9%	56	5	91.1%	13	2	84.6%	56	12	78.6%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181		14	7	50.0%	56	13	76.8%	13	2	84.6%	55	3	94.5%
182		14	3	78.6%	56	12	78.6%	14	1	92.9%	56	4	92.9%
183		14	5	64.3%	56	16	71.4%	14	4	71.4%	56	10	82.1%
184		14	1	92.9%	56	9	83.9%	14	3	78.6%	56	8	85.7%
185		14	2	85.7%	56	10	82.1%	14	1	92.9%	56	2	96.4%
186		14	1	92.9%	56	8	85.7%	14	1	92.9%	56	13	76.8%
190		14	7	50.0%	56	23	58.9%	14	2	85.7%	56	12	78.6%
192		14	1	92.9%	54	7	87.0%	14	1	92.9%	54	2	96.3%
193	18	14	3	78.6%	56	16	71.4%	14	5	64.3%	56	19	66.1%
196		14	1	92.9%	56	1	98.2%	14	1	92.9%	56	3	94.6%
197		14	7	50.0%	56	22	60.7%	14	5	64.3%	56	11	80.4%
232		18	0	100.0%	79	1	98.7%	18	0	100.0%	79	6	92.4%
233	19	18	6	66.7%	79	19	75.9%	18	5	72.2%	79	17	78.5%
234		18	0	100.0%	79	3	96.2%	18	0	100.0%	79	2	97.5%
236		18	0	100.0%	79	1	98.7%	18	3	83.3%	79	14	82.3%
237		18	2	88.9%	79	12	84.8%	18	1	94.4%	79	5	93.7%
239		18	6	66.7%	78	21	73.1%	18	1	94.4%	78	3	96.2%
240		18	1	94.4%	79	7	91.1%	18	4	77.8%	79	11	86.1%
241	62	18	7	61.1%	79	23	70.9%	18	3	83.3%	79	13	83.5%
243		14	3	78.6%	56	19	66.1%	14	2	85.7%	57	10	82.5%
244	22	18	0	100.0%	79	2	97.5%	18	1	94.4%	79	16	79.7%
280	16	18	1	94.4%	79	4	94.9%	18	5	72.2%	79	15	81.0%
281		18	0	100.0%	79	8	89.9%	18	2	88.9%	79	7	91.1%
283		18	6	66.7%	79	14	82.3%	18	4	77.8%	79	13	83.5%
284		18	0	100.0%	79	1	98.7%	18	2	88.9%	79	7	91.1%
290	75	18	0	100.0%	79	18	77.2%	18	5	72.2%	78	26	66.7%
291		18	4	77.8%	79	17	78.5%	18	3	83.3%	79	15	81.0%
300		18	5	72.2%	79	7	91.1%	18	8	55.6%	78	22	71.8%
301		17	1	94.1%	77	2	97.4%	17	4	76.5%	76	13	82.9%
302		17	5	70.6%	77	11	85.7%	17	6	64.7%	75	23	69.3%
305		18	5	72.2%	79	10	87.3%	17	11	35.3%	77	31	59.7%
306		17	3	82.4%	77	5	93.5%	17	5	70.6%	76	16	78.9%
307	18	18	3	83.3%	78	8	89.7%	18	9	50.0%	78	20	74.4%
311		18	3	83.3%	78	10	87.2%	18	5	72.2%	78	19	75.6%
316		18	2	88.9%	78	5	93.6%	18	5	72.2%	78	17	78.2%
318		18	1	94.4%	79	10	87.3%	18	7	61.1%	78	32	59.0%
319		18	2	88.9%	79	4	94.9%	18	8	55.6%	79	44	44.3%
329	23	14	1	92.9%	56	2	96.4%	14	3	78.6%	56	5	91.1%
330		16	0	100.0%	67	2	97.0%	16	4	75.0%	67	5	92.5%
331		18	5	72.2%	79	9	88.6%	18	4	77.8%	79	10	87.3%
332	19	18	4	77.8%	79	9	88.6%	18	6	66.7%	79	11	86.1%
334		18	1	94.4%	79	2	97.5%	18	6	66.7%	78	10	87.2%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
335		18	5	72.2%	79	12	84.8%	17	3	82.4%	77	12	84.4%
336		18	3	83.3%	79	4	94.9%	18	1	94.4%	79	5	93.7%
337	23	18	1	94.4%	79	5	93.7%	18	4	77.8%	79	9	88.6%
338		18	2	88.9%	79	17	78.5%	17	5	70.6%	77	17	77.9%
339		18	3	83.3%	79	17	78.5%	18	5	72.2%	79	16	79.7%
341	Cncld	16	4	75.0%	76	13	82.9%	15	4	73.3%	75	12	84.0%
342	13	18	1	94.4%	79	7	91.1%	18	6	66.7%	78	14	82.1%
350	24	18	0	100.0%	61	2	96.7%	18	12	33.3%	61	34	44.3%
351	97	18	7	61.1%	79	10	87.3%	18	8	55.6%	79	34	57.0%
352	20	18	2	88.9%	79	6	92.4%	17	6	64.7%	76	20	73.7%
353	18	18	3	83.3%	58	5	91.4%	18	10	44.4%	58	15	74.1%
354	64	18	4	77.8%	79	7	91.1%	17	11	35.3%	78	25	67.9%
355	36	17	2	88.2%	78	7	91.0%	16	8	50.0%	77	21	72.7%
364	166	17	9	47.1%	78	14	82.1%	16	7	56.3%	77	15	80.5%
365	43	17	4	76.5%	78	6	92.3%	16	10	37.5%	77	26	66.2%
370		18	3	83.3%	79	5	93.7%	18	6	66.7%	79	15	81.0%
371	18	17	2	88.2%	78	2	97.4%	17	4	76.5%	78	8	89.7%
380		18	3	83.3%	79	13	83.5%	18	5	72.2%	79	18	77.2%
381	27	18	1	94.4%	79	2	97.5%	18	3	83.3%	79	10	87.3%
382	57	18	0	100.0%	79	2	97.5%	18	5	72.2%	79	20	74.7%
383	56	18	4	77.8%	79	9	88.6%	18	10	44.4%	78	32	59.0%
390		10	4	60.0%	63	8	87.3%	10	5	50.0%	63	21	66.7%
391		10	1	90.0%	64	1	98.4%	10	2	80.0%	63	14	77.8%
392		18	1	94.4%	79	3	96.2%	18	11	38.9%	78	26	66.7%
393	54	18	2	88.9%	79	7	91.1%	18	7	61.1%	78	22	71.8%
417		14	1	92.9%	53	9	83.0%	13	0	100.0%	50	1	98.0%
425		14	0	100.0%	53	1	98.1%	14	0	100.0%	53	1	98.1%
448		18	8	55.6%	20	9	55.0%	17	8	52.9%	18	8	55.6%
449		17	1	94.1%	17	1	94.1%	17	3	82.4%	17	3	82.4%
470		14	3	78.6%	56	8	85.7%	14	2	85.7%	56	9	83.9%
471		14	1	92.9%	53	1	98.1%	14	0	100.0%	53	0	100.0%
473		14	0	100.0%	56	3	94.6%	14	0	100.0%	56	1	98.2%
474		14	5	64.3%	54	18	66.7%	13	7	46.2%	50	18	64.0%
475		14	0	100.0%	56	0	100.0%	14	0	100.0%	56	1	98.2%
478		14	2	85.7%	54	12	77.8%	14	0	100.0%	54	6	88.9%
479		14	3	78.6%	56	7	87.5%	14	1	92.9%	56	2	96.4%
486	24	14	1	92.9%	57	8	86.0%	14	4	71.4%	56	10	82.1%
490		14	1	92.9%	33	6	81.8%	14	0	100.0%	33	2	93.9%
494		14	0	100.0%	58	9	84.5%	14	4	71.4%	55	11	80.0%
495		14	0	100.0%	56	2	96.4%	14	0	100.0%	56	1	98.2%
500	22	18	1	94.4%	79	6	92.4%	18	4	77.8%	78	9	88.5%
502	24	18	1	94.4%	79	7	91.1%	18	3	83.3%	78	19	75.6%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
503	40	18	3	83.3%	76	11	85.5%	18	6	66.7%	75	21	72.0%
504		18	2	88.9%	79	7	91.1%	18	6	66.7%	79	25	68.4%
505	23	18	3	83.3%	79	13	83.5%	18	4	77.8%	77	17	77.9%
506	94	18	4	77.8%	78	13	83.3%	18	3	83.3%	77	12	84.4%
507	47	18	2	88.9%	79	9	88.6%	18	6	66.7%	79	28	64.6%
508	24	18	3	83.3%	77	14	81.8%	18	7	61.1%	77	20	74.0%
509		18	2	88.9%	79	6	92.4%	18	8	55.6%	79	21	73.4%
511		18	2	88.9%	79	6	92.4%	18	4	77.8%	79	16	79.7%
516		16	0	100.0%	77	9	88.3%	16	4	75.0%	77	32	58.4%
517	205	18	0	100.0%	79	1	98.7%	18	8	55.6%	78	30	61.5%
518		18	0	100.0%	79	13	83.5%	18	10	44.4%	79	46	41.8%
519		16	1	93.8%	77	4	94.8%	16	4	75.0%	77	13	83.1%
520		14	4	71.4%	52	7	86.5%	13	1	92.3%	51	3	94.1%
521		14	0	100.0%	55	0	100.0%	14	1	92.9%	55	4	92.7%
522		14	5	64.3%	55	9	83.6%	13	1	92.3%	54	5	90.7%
523		14	0	100.0%	55	0	100.0%	14	4	71.4%	55	8	85.5%
524		14	0	100.0%	55	2	96.4%	14	1	92.9%	55	4	92.7%
525		14	2	85.7%	55	3	94.5%	13	1	92.3%	54	6	88.9%
526	24	14	5	64.3%	55	11	80.0%	13	2	84.6%	54	6	88.9%
527		14	0	100.0%	55	1	98.2%	14	1	92.9%	55	3	94.5%
528		14	1	92.9%	55	6	89.1%	14	2	85.7%	55	12	78.2%
529		14	0	100.0%	55	3	94.5%	14	3	78.6%	55	10	81.8%
530		9	0	100.0%	9	0	100.0%	9	1	88.9%	9	1	88.9%
531	31	14	0	100.0%	55	1	98.2%	14	3	78.6%	55	6	89.1%
532		14	2	85.7%	55	3	94.5%	14	1	92.9%	55	8	85.5%
534		14	1	92.9%	52	6	88.5%	14	2	85.7%	52	5	90.4%
535		13	4	69.2%	51	5	90.2%	12	1	91.7%	50	2	96.0%
536	Cncld	14	3	78.6%	55	7	87.3%	12	1	91.7%	53	2	96.2%
537	Cncld	14	2	85.7%	55	5	90.9%	12	1	91.7%	53	2	96.2%
538		14	1	92.9%	55	7	87.3%	14	4	71.4%	55	9	83.6%
539	78	9	1	88.9%	9	1	88.9%	9	6	33.3%	9	6	33.3%
540		14	3	78.6%	55	7	87.3%	13	1	92.3%	52	2	96.2%
541		14	4	71.4%	55	9	83.6%	14	4	71.4%	55	15	72.7%
542		14	1	92.9%	55	4	92.7%	14	1	92.9%	54	11	79.6%
543		14	0	100.0%	55	6	89.1%	14	1	92.9%	55	13	76.4%
544		14	2	85.7%	54	4	92.6%	14	3	78.6%	54	7	87.0%
545		14	2	85.7%	55	6	89.1%	14	1	92.9%	54	5	90.7%
547		14	0	100.0%	55	4	92.7%	14	2	85.7%	55	9	83.6%
548		14	2	85.7%	55	10	81.8%	14	1	92.9%	55	6	89.1%
549		14	3	78.6%	52	13	75.0%	12	0	100.0%	49	6	87.8%
550		9	2	77.8%	9	2	77.8%	9	1	88.9%	9	1	88.9%
551	No OS	14	2	85.7%	55	8	85.5%	14	2	85.7%	53	8	84.9%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562		18	3	83.3%	77	11	85.7%	18	3	83.3%	76	9	88.2%
564		18	1	94.4%	77	7	90.9%	17	2	88.2%	73	12	83.6%
566		18	1	94.4%	77	6	92.2%	18	2	88.9%	74	8	89.2%
572		18	0	100.0%	76	6	92.1%	18	0	100.0%	75	14	81.3%
573		18	2	88.9%	77	11	85.7%	17	0	100.0%	75	8	89.3%
577		18	1	94.4%	75	6	92.0%	18	4	77.8%	71	6	91.5%
580		18	0	100.0%	77	2	97.4%	18	1	94.4%	77	8	89.6%
581		18	0	100.0%	77	7	90.9%	18	2	88.9%	77	14	81.8%
582		18	2	88.9%	77	6	92.2%	18	1	94.4%	75	5	93.3%
586	No OS	18	5	72.2%	77	16	79.2%	18	2	88.9%	74	11	85.1%
587		18	0	100.0%	77	3	96.1%	17	0	100.0%	74	9	87.8%
591	63	18	0	100.0%	77	1	98.7%	17	1	94.1%	76	7	90.8%
593	Cncld	18	3	83.3%	77	12	84.4%	16	1	93.8%	69	6	91.3%
595		18	1	94.4%	76	15	80.3%	18	1	94.4%	75	11	85.3%
600		14	1	92.9%	56	2	96.4%	14	1	92.9%	56	5	91.1%
601		14	11	21.4%	56	30	46.4%	14	2	85.7%	56	15	73.2%
605		14	13	7.1%	56	34	39.3%	14	3	78.6%	55	5	90.9%
607		14	1	92.9%	56	4	92.9%	14	3	78.6%	55	4	92.7%
609		14	3	78.6%	55	4	92.7%	14	1	92.9%	55	4	92.7%
620		14	6	57.1%	55	15	72.7%	14	1	92.9%	53	3	94.3%
624	12	14	4	71.4%	56	14	75.0%	13	4	69.2%	56	13	76.8%
639		14	5	64.3%	56	15	73.2%	14	2	85.7%	56	6	89.3%
640	11	14	2	85.7%	56	4	92.9%	14	10	28.6%	56	28	50.0%
641		14	6	57.1%	56	11	80.4%	14	4	71.4%	56	11	80.4%
642		14	2	85.7%	55	4	92.7%	14	2	85.7%	55	6	89.1%
643		14	5	64.3%	56	12	78.6%	14	5	64.3%	55	8	85.5%
644		14	5	64.3%	56	10	82.1%	14	6	57.1%	56	11	80.4%
645		14	4	71.4%	56	7	87.5%	14	5	64.3%	56	11	80.4%
646		14	6	57.1%	56	13	76.8%	14	11	21.4%	55	31	43.6%
647		14	3	78.6%	56	5	91.1%	14	2	85.7%	56	14	75.0%
648		14	5	64.3%	56	11	80.4%	14	5	64.3%	56	9	83.9%
649		14	4	71.4%	56	10	82.1%	14	2	85.7%	55	9	83.6%
650		14	3	78.6%	56	12	78.6%	14	7	50.0%	56	14	75.0%
651		14	0	100.0%	56	5	91.1%	14	4	71.4%	56	17	69.6%
652		14	3	78.6%	56	11	80.4%	14	4	71.4%	55	12	78.2%
653		14	3	78.6%	56	11	80.4%	14	2	85.7%	56	16	71.4%
654		14	7	50.0%	56	12	78.6%	14	3	78.6%	56	5	91.1%
655		14	4	71.4%	54	16	70.4%	14	6	57.1%	53	14	73.6%
656		14	5	64.3%	56	12	78.6%	14	0	100.0%	56	5	91.1%
657		14	0	100.0%	56	3	94.6%	14	1	92.9%	56	10	82.1%
658		14	1	92.9%	56	8	85.7%	14	3	78.6%	56	9	83.9%
680	32	14	0	100.0%	57	2	96.5%	14	4	71.4%	57	7	87.7%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
681		14	1	92.9%	57	3	94.7%	14	4	71.4%	57	17	70.2%
682		14	0	100.0%	57	0	100.0%	14	3	78.6%	57	13	77.2%
683		14	0	100.0%	40	3	92.5%	14	3	78.6%	40	12	70.0%
684	26	14	2	85.7%	39	6	84.6%	14	3	78.6%	39	11	71.8%
685		14	2	85.7%	56	6	89.3%	14	2	85.7%	56	15	73.2%
686		14	2	85.7%	57	15	73.7%	14	4	71.4%	57	14	75.4%
687		14	2	85.7%	57	8	86.0%	14	5	64.3%	57	11	80.7%
688		14	0	100.0%	57	1	98.2%	14	2	85.7%	57	14	75.4%
689		10	1	90.0%	46	5	89.1%	9	1	88.9%	45	4	91.1%
701		11	3	72.7%	11	3	72.7%	11	2	81.8%	11	2	81.8%
702		18	2	88.9%	79	17	78.5%	18	3	83.3%	78	22	71.8%
703		18	4	77.8%	79	19	75.9%	18	4	77.8%	79	20	74.7%
704		11	3	72.7%	11	3	72.7%	10	3	70.0%	10	3	70.0%
710		18	7	61.1%	79	31	60.8%	18	2	88.9%	79	30	62.0%
711		18	3	83.3%	75	7	90.7%	15	3	80.0%	68	10	85.3%
712		18	4	77.8%	79	21	73.4%	18	5	72.2%	78	28	64.1%
713		17	3	82.4%	78	12	84.6%	13	4	69.2%	68	31	54.4%
714	40	18	7	61.1%	73	26	64.4%	18	5	72.2%	68	21	69.1%
715	19	18	5	72.2%	79	27	65.8%	16	9	43.8%	74	38	48.6%
716	130	18	10	44.4%	79	33	58.2%	18	10	44.4%	78	33	57.7%
717	39	18	4	77.8%	70	17	75.7%	18	8	55.6%	65	21	67.7%
718	42	18	12	33.3%	79	34	57.0%	17	7	58.8%	78	23	70.5%
719		18	3	83.3%	79	27	65.8%	18	6	66.7%	77	22	71.4%
761		18	0	100.0%	77	3	96.1%	18	0	100.0%	77	9	88.3%
765		18	2	88.9%	77	9	88.3%	18	1	94.4%	77	14	81.8%
769		18	1	94.4%	77	5	93.5%	18	1	94.4%	75	12	84.0%
770		18	0	100.0%	77	7	90.9%	18	1	94.4%	77	10	87.0%
774	17	18	0	100.0%	77	6	92.2%	18	4	77.8%	76	15	80.3%
779	No OS	18	0	100.0%	77	4	94.8%	18	1	94.4%	76	10	86.8%
784	25	18	2	88.9%	77	8	89.6%	18	10	44.4%	76	39	48.7%
785	87	18	0	100.0%	77	0	100.0%	18	3	83.3%	77	10	87.0%
790	76	18	0	100.0%	77	5	93.5%	18	3	83.3%	77	10	87.0%
794	94	18	1	94.4%	77	6	92.2%	18	3	83.3%	76	13	82.9%
821		18	0	100.0%	79	3	96.2%	18	6	66.7%	79	46	41.8%
822		18	0	100.0%	79	3	96.2%	18	2	88.9%	79	46	41.8%
1333	27	18	4	77.8%	79	8	89.9%	18	7	61.1%	78	33	57.7%
1340	28	18	0	100.0%	79	3	96.2%	18	7	61.1%	79	20	74.7%
2103	31	14	1	92.9%	55	4	92.7%	14	3	78.6%	55	4	92.7%
2104		14	3	78.6%	26	5	80.8%	14	2	85.7%	26	4	84.6%
2107		14	4	71.4%	56	11	80.4%	14	4	71.4%	54	4	92.6%
2108		14	2	85.7%	56	4	92.9%	14	2	85.7%	54	2	96.3%
2117		14	4	71.4%	26	7	73.1%	14	4	71.4%	26	5	80.8%

Amtrak On Time Performance

Trains Arriving Through: 12/18/2025

28-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2121		14	3	78.6%	54	6	88.9%	14	2	85.7%	54	5	90.7%
2122		14	1	92.9%	56	7	87.5%	14	1	92.9%	56	4	92.9%
2124		12	2	83.3%	42	6	85.7%	12	1	91.7%	42	2	95.2%
2150	82	14	2	85.7%	56	11	80.4%	13	3	76.9%	55	12	78.2%
2151		14	0	100.0%	56	0	100.0%	14	5	64.3%	55	11	80.0%
2152	39	14	1	92.9%	52	3	94.2%	14	10	28.6%	51	19	62.7%
2153		14	0	100.0%	56	6	89.3%	14	3	78.6%	56	12	78.6%
2154		14	3	78.6%	56	17	69.6%	14	7	50.0%	54	28	48.1%
2155		14	1	92.9%	56	3	94.6%	14	8	42.9%	54	17	68.5%
2159		14	0	100.0%	55	1	98.2%	14	6	57.1%	55	13	76.4%
2162		14	0	100.0%	56	2	96.4%	14	4	71.4%	55	13	76.4%
2163		14	0	100.0%	56	4	92.9%	14	5	64.3%	56	15	73.2%
2166		14	1	92.9%	56	6	89.3%	14	4	71.4%	54	10	81.5%
2167	75	13	2	84.6%	55	7	87.3%	13	4	69.2%	55	12	78.2%
2168		14	2	85.7%	56	4	92.9%	14	1	92.9%	56	7	87.5%
2169	55	14	9	35.7%	52	19	63.5%	14	11	21.4%	52	26	50.0%
2170		14	3	78.6%	56	10	82.1%	14	3	78.6%	56	12	78.6%
2172		14	0	100.0%	56	6	89.3%	14	3	78.6%	56	10	82.1%
2173		14	4	71.4%	55	11	80.0%	14	3	78.6%	55	21	61.8%
2190		14	3	78.6%	56	8	85.7%	13	2	84.6%	55	6	89.1%
2193		14	1	92.9%	55	2	96.4%	14	5	64.3%	55	14	74.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/18/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2103	WAS	31	ENG	23	ENG	23	BAL-XNY	AM	PTC - On Board Cab Signal or PTC Failure, 2015, OPERATE 79 MPH, CUT OUT ACSES	
2150	BOS	82	CAR	45	CAR	45	WAS-WAS	AM	HEP, ALL, heavy repairs of NxtGen Acela sets delayed the servicing and inspection of 2150	
2152	BOS	39	CTI	12	MTI	8	BAL-XPV	AM	Disabled train ahead, Milepost, 83.7, 83.7, OPERATE 1 TRACK A/C 2150 INSPECTING ON 2 TRACK AHEAD	
2167	WAS	75	ITI	41	ITI	41	BOS-BOS	AM	Service, turn, or wye train, 2150	
2169	WAS	55	ITI	22	ITI	22	BOS-BOS	AM	Service, turn, or wye train, 2152, Late turn	
84	NYP	17	HLD	10	DMW	5	ASD-FBG	CS	Unable to contact dispatcher / MW foreman Milepost, 22.0, 23.1	
85	RVM	22	CTI	28	CTI	9	XVG-ALX	CS	Follow vre, Control Point, cp va	
86	BOS	39	DSR	35	SYS	20	WAS-WAS	AM	Other late crew, CREW REQUESTED A FOUL IN ORDER TO PULL CABLES	
93	NFK	23	DSR	35	DSR	17	BRP-STM	MN	Per bulletin Control Point, cp241, 15, 2	
95	NFK	24	CTI	30	CTI	14	WDB-FBG	CS	Follow VRE, 303, Control Point, Featherstone	
111	WAS	22	CTP	13	CTP	13	BWI-NCR	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C DISABLED MK505	
151	RNK	16	CTP	11	CTP	11	BWI-XNY	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C DISABLED MK505	
170	BOS	34	DCS	30	DCS	30	NHV-NLC	AM	Power switch failure, Milepost, nhv, nlc, the 21A end switch will not reverse.	
171	RNK	78	DCS	38	DCS	34	NLC-NHV	AM	Power switch failure, Milepost, NLC, NHV, the 21A end switch will not reverse.	
172	BOS	22	SYS	19	SYS	19	WAS-WAS	AM	Other late crew, CREW ARRIVING ON LATE MARC 407	
173	WAS	19	CTI	14	OTH	7	NLC-NHV	AM	Lost time - N.A.R.	
193	WAS	18	OTH	13	CAR	8	NWK-NWK	AM	Air / Brake / Wheel, N/A, BELLOW ISSUES	
486	GFD	24	CON	17	CON	17	NHV-NHV	AM	Hold for connecting train	
624	NYP	12	SMW	13	SMW	7	NWK-NYP	AM	Diversions around M/W work, Other, XBH-NYP, SINGLE TRACKING IN THE SOUTH TUBE	
640	NYP	11	CTI	17	CTI	7	NWK-NYP	AM	Follow, NJT, NJ6616, Other, SWIFT-NYP	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/18/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
680	BON	32	FTI	34	FTI	19	WEM-DOV	CS	Blocked from station track Setting out car, M427, Control Point, Dover East	
684	BON	26	DCS	21	DCS	8	WOB-BON	MT	Restrictive signal(s) from known wayside signal failure Stop, Control Point, Crawford	
63	TWO	24	HLD	27	OTH	17	NYP-NYP	AM	Station services did not send the people down in time . Train was in the station at 630am crew on the train 6:35am.	
64	ALB	70	ENG	46	ENG	39	XHF-SDY	AM	PTC - On Board Cab Signal or PTC Failure No acces Got rescue engines Job briefed Brake tests On the move, 103	
68	NYP	33	DCS	26	DCS	22	RSP-RSP	DH	CTC system failure Control Point, 191	
233	ALB	19	DMW	11	DMW	11	CRT-POU	MN	Waiting for MW clearance Single tracking, mobile unit 402, waited for southbound amtrak 240, Control Point, CP 53	
241	ALB	62	ITI	40	ITI	40	NYP-NYP	AM	Service, turn, or wye train, 290	
244	NYP	22	CTI	32	CTI	18	CRT-YNP	MN	Follow mn, Control Point, 33	
280	NYP	16	DCS	14	DCS	13	ALB-HUD	AM	Restrictive signal(s) from known wayside signal failure Wait for Signal Department to take local control of CP 141., Stop signal , Control Point, 141	
290	NYP	75	DCS	78	DCS	78	XWH-FED	DH	CTC system failure SYSTEMWIDE OUTAGE CPKC, Control Point, CPC 56	
71	CLT	13	DSR	18	DSR	11	DNC-GRO	NS	Per dispatcher (radio/phone) 15 HEO downgraded to a Stop and Flag per dispatcher. Swift Ave., Milepost, 53.75, 53.75, 0, Main	
72	RGH	13	DCS	16	DCS	8	CYN-RGH	NS	Issue with automatic road crossing protection Milepost, 159.9, 159.9, Milepost, 159.7, 159.7	
74	RGH	21	DCS	13	FTI	13	SAL-HPT	NS	Cross over or go around NS 24X, Control Point, Duke	
75	CLT	17	FTI	13	FTI	13	RGH-CYN	NS	Meet #NS350, #CsxL620, Control Point, Boylan	
77	CLT	15	DCS	12	FTI	11	GRO-GRO	NS	Meet Waited at Elm for 28R, #NS28R, Control Point, Elm	
40	CHI	65	FTI	112	FTI	29	PGH-ALC	NS	Follow ns 29 G, Milepost w/Letters, cp Wood, cp Alc	
41	MIA	73	FTI	141	FTI	30	SAV-XJG	CS	Follow M491, Control Point, McIntosh, Control Point, Doctortown	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
6	CHI	715	WTR	638	WTR	204	XXP-XFJ	UP	High winds Held at E Rocky for High winds. Expired at 2121, Control Point, E.Rocky
526	SAC	24	MBO	33	MBO	33	MTZ-SUI	UP	For maritime traffic Control Point, RV032
531	OKJ	31	MBO	38	MBO	38	SUI-MTZ	UP	For maritime traffic Bridge, Suisun Bridge
536	SAC	Trn Cancelled							
537	OKJ	Trn Cancelled	ENG	92	ENG	90	SUI-MTZ	UP	Loading problem Coupled into 539, C2009
539	SJC	78	SVS	35	SVS	35	SUI-MTZ	UP	Pick up equipment amt537 engine failed in route. Hooked on and pulled to OKJ., Control Point, Rv042
551	OKJ	No OS Rpt							
51	CHI	37	FTI	61	DCS	30	LAF-REN	CS	Bad signals requiring permission past signals displaying stop Milepost, 96.2, 91.1
500	SEA	22	DCS	22	DCS	15	XNI-TAC	ST	Restrictive signal(s) from known wayside signal failure Stop, Stop, Control Point, NISQUALLY, Control Point, CP 188
502	SEA	24	DCS	18	DCS	18	XNI-TAC	ST	Restrictive signal(s) from known wayside signal failure Restricted speed, Stop, Milepost, 21.4, 17.9
503	EUG	40	DCS	35	DCS	35	TAC-XNI	BN	CTC system failure Talked by Rill and 18.8 Restricted speed from Rill to Nisqually, Control Point, Rill, Control Point, Nisqually
505	PDX	23	DCS	35	DCS	35	TAC-XNI	ST	CTC system failure Control Point, Rill
506	SEA	94	PTI	94	PTI	94	PDX-PDX	BN	Train 517 arrived in PDX 3 1/2 hours late with same equipment used to go out as 506. AMT 517, Other, PDX Station
507	PDX	47	OTH	37	OTH	37	CTL-KEL	BN	Stop at MP 92.5 to assist train 517 with air problems
508	SEA	-35	DCS	13	DCS	13	XNI-TAC	ST	CTC system failure Control Point, Nisqually, Control Point, 188
517	PDX	205	CCR	133	CCR	133	CTL-KEL	BN	Air / Brake / Wheel 7911, Hit a deer and a branch. Broke brake pipe. Had to repair.
59	NOL	72	FTI	79	PTI	55	MCB-HMD	CC	Meet AMTK58, Siding, Arcola
11	LAX	167	TRS	119	TRS	119	SBA-oxn	UP	Vehicle strike Milepost, 410.4, 410.4
14	SEA	38	PTI	83	PTI	39	KEL-CTL	BN	Meet Had to reverse for AMT 517 and AMT 507., AMT 517, AMT 507, Control Point, Kelso South

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
7	SEA	Trn Cancelled	WTR	535	WTR	284	GGW-MAL	BN	High winds In addition signal power outage due to high winds between W Saco and W Bowdoin.. Milepost, 278, 343
8	CHI	No OS Rpt	WTR	414	ITI	199	SEA-SEA	BN	Service, turn, or wye train 7
27	PDX	Trn Cancelled							
329	MKE	23	CAR	21	CAR	21	XRO-SVT	CP	Air / Brake / Wheel ID4002, ID4015, Hoses to long between cars. Came apart at Roundout even with slowing
332	CHI	19	ITI	13	ITI	13	MKE-MKE	CP	Service, turn, or wye train 332
337	MKE	23	ENG	14	ENG	14	CHI-CHI	AM	Other electrical failure ID4613
341	MKE	Trn Cancelled							
342	CHI	13	CTI	18	CTI	6	GLN-XWA	ME	Cross Traffic metra, Control Point, mayfair
350	PNT	24	PTI	21	PTI	11	KAL-XGO	CC	Meet 351, 365, Control Point, Gord
351	CHI	97	FTI	100	FTI	53	PNT-TRM	CC	Due to freight blocking 354 crew from eying equipment. Shoved down to Detroit to spin equipment at sugar house wye unknown. Other, pontiac
352	PNT	20	PTI	18	PTI	18	JXN-ARB	MI	Meet Amteak Wolverine 355, Control Point, CP52
353	CHI	18	FTI	26	FTI	12	XPI-HMI	NS	Follow Followed then went around, Milepost, 482, 494, unknown
354	PNT	64	DSR	14	SYS	8	BTL-BTL	CC	PTC problem or failure (cause unknown)
355	CHI	36	OTH	20	OTH	14	ARB-JXN	MI	Flagged crossing at mp 62.95 Maute Rd procedure 1 on the MT
364	PTH	166	ENG	135	ENG	135	CHI-CHI	AM	Set out defective locomotive 4620
365	CHI	43	FTI	46	FTI	42	PTH-LPE	CC	Hold due to freight train 148 going into emergency. Rerouted, shoved into tunnel and proceeded on track 4 148, Other, Porthuron station
371	CHI	18	RTE	15	RTE	15	SJM-XPI	CS	Took Livingston siding two broken rails on the main Siding, Livingston
586	SAN	No OS Rpt							
591	LAX	63	POL	69	POL	69	SNA-SNA	SC	Right of Way police hold Held at SNA per Orange Sub Dispatch due to police activity on BNSF
593	LAX	No OS Rpt							

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/18/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
774	SAN	17	PTI	21	PTI	10	SNC-X98	SC	Meet AMTK 577, Control Point, Serra
779	SLO	No OS Rpt	POL	193	POL	116	CML-CML	UP	RR blocked by trespasser or vehicle strike by another train
784	SAN	25	PTI	35	PTI	17	SNC-SNP	SC	Meet 587, Control Point, serra
785	GTA	87	POL	103	POL	42	CML-OXN	UP	RR blocked by trespasser or vehicle strike by another train
790	SAN	76	POL	183	POL	101	VEC-VEC	UP	Right of Way police hold Holding at VEC per dispatcher due to earlier Metrolink 118 collision with a car at mp. 410.38.
794	SAN	94	TRS	102	TRS	79	LAX-LAX	SC	Trespasser strike Waiting for departure at LAUS due to TS, Milepost, 148, 148
714	BFD	-8	PTI	14	PTI	14	COC-WAC	BN	Meet AMTK 703, Siding, west Elmo
715	EMY	19	FTI	16	FTI	10	BFD-WAC	BN	Meet E. bound BNSF 6821, Milepost, 905, 905
716	BFD	-9	PTI	38	PTI	10	MDR-FNO	BN	Follow 704, Milepost, 1002, 998
717	OKJ	39	PTI	62	PTI	20	MTZ-RIC	UP	Follow Wait at CP Howard for 549 to pass then follow them., 549, Control Point, Howard
718	BFD	42	ITI	67	ITI	67	OKJ-OKJ	UP	Service, turn, or wye train 715
4	CHI	158	SVS	110	SVS	94	LAP-FMD	BN	Pick up equipment Car 39021., Other, Medill
307	STL	18	PTI	60	PTI	36	PON-BNL	UP	Meet Waiting on 306 to change a hose, Amt 306, Siding, Pontiac
381	QCY	27	FTI	18	WTR	18	KEE-GBB	BN	High winds Milepost, 119, 162
382	CHI	57	WTR	70	WTR	23	GBB-KEE	BN	High winds Milepost, 162.4, 81
383	QCY	56	FTI	27	WTR	22	PCT-KEE	BN	High winds Winds up to 55mph, Milepost, 105, 131
393	CDL	54	FTI	31	FTI	15	EFG-CEN	CC	Meet 3 way meet, cn 3352 n, Control Point, edgewood jct
1333	MSP	27	DCS	27	DCS	27	MKA-MKE	CP	CTC system failure Control Point, kk bridge
1340	CHI	28	DCS	41	DCS	41	XH8-RDW	CP	CTC system failure Other, BLACKBIRD EAST

Amtrak Initial Terminal Details

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/18/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	642	12/18	9	9	Lost time - N.A.R., late off 9trk a/c equipment issues
HAR	644	12/18	1		
HAR	646	12/18	2	2	Passenger and/or baggage
HAR	654	12/18	2	2	PTC - Stop Bypass Permission Required, Control Point, ., E/662
HAR	656	12/18	1		
NFK	138	12/18	5	5	Mobility Impaired
NPN	186	12/18	5	5	Door 82537, B end door light on even though door was closed. Engine couldn't take power to leave
PHL	110	12/18	2	2	Passenger and/or baggage
PHL	601	12/18	1		
PHL	605	12/18	1		
WAS	56	12/18	5	5	Other electrical failure, 668, MOTOR THAT WAS SHOVING TRAIN DOWN WENT INTO PENALTY
WAS	148	12/18	(No OS)		
WAS	170	12/18	2	2	Re-crew / job briefing, chocked wheel; needed respot prior to departure
WAS	172	12/18	19	19	Other late crew, CREW ARRIVING ON LATE MARC 407
WAS	182	12/18	6	6	Door, ALL, TRAINLINE ISSUES
WAS	2150	12/18	45	45	HEP, ALL, heavy repairs of NxtGen Acela sets delayed the servicing and inspection of 2150
WAS	2168	12/18	1		
BON	689	12/18	1		
BOS	93	12/18	6	6	Water, commissary, toilet/trash dumping
BOS	2167	12/18	41	41	Service, turn, or wye train, 2150
BOS	2169	12/18	22	22	Service, turn, or wye train, 2152, Late turn
BOS	2173	12/18	1		
NYP	63	12/18	17	17	Passenger and/or baggage, HEAVY BOARDING
NYP	63	12/18	17	17	Station services did not send the people down in time . Train was in the station at 630am crew on the train 6:35am.
NYP	97	12/18	8	8	Water, commissary, toilet/trash dumping, LATE FROM YARD A/C SERVICING
NYP	181	12/18	2	2	Switch private or office cars, SHOPPED CAR 82788
NYP	183	12/18	2	2	Passenger and/or baggage, BOARDING
NYP	233	12/18	8	8	Hold for connecting train, HELD FOR PSNGRS TO BOARD OFF CONNECTION

Amtrak Initial Terminal Details

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/18/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	241	12/18	40	40	Service, turn, or wye train, 290
NYP	643	12/18	1	2	Passenger and/or baggage, BOARDING
NYP	645	12/18	1	2	Passenger and/or baggage, BOARDING
NYP	647	12/18	2	2	Passenger and/or baggage, BOARDING
CHI	5	12/18	3	3	Several pax's who missed #5 yesterday due to late operation of #40 did not have their tickets reprinted to reflect today's #5. Passengers thought they had sleeper's and lower level seating but did not because of train inventory. Misinformed pax's.
CHI	7	12/18	19	19	Blocked by or assisting another, disabled Amtrak train Control Point, Washington
CHI	319	12/18	33	16	Door ID4207, Bad communication cable Displayed door open
CHI	319	12/18	33	17	Loading problem Unable to due to Car fault, ID4622
CHI	337	12/18	14	14	Other electrical failure ID4613
CHI	341	12/18	(Trn Cxld)		Engine Issue
CHI	364	12/18	135	135	Set out defective locomotive 4620
MKE	332	12/18	13	13	Service, turn, or wye train 332
MKE	336	12/18	4	4	Air / Brake / Wheel 90200
PDX	506	12/18	94	94	Train 517 arrived in PDX 3 1/2 hours late with same equipment used to go out as 506. AMT 517, Other, PDX Station
PDX	508	12/18	39	0	Wait for a bus from EUG. I tried to fix the "arrival" time back but it won't let me. Train started in PDX and I had to enter a departure time manually because it didn't auto populate. Now I can't go back and report an actual amount of time we lost waiting for the bus. 39" late.
PNT	351	12/18	8	8	Due to freight interference at the wye 354 had recrew and they came in to spin 353 equipment. And they left Pontiac out north end. Had to align switches for our shove move to sugar house unknown, Other, pontiac station
SEA	505	12/18	1		
SPK	27	12/16	(No OS)		
STL	302	12/18	2	2	Late bulletins due to Amtrak cause Printer not working
BFD	711	12/18	3	3	Wheelchair Multiple wheelchairs conductor only.
EMY	6	12/18	6	6	Late departure from yard due to removal of rear baggage car Other, omf
EMY	714	12/18	53	5	Due to locomotive issues had to wait for equipment from Amtrak 711 C2101
EMY	716	12/18	142	3	Waited for bags from ticket agent causing a delay Other, Emeryville Station
EMY	718	12/18	40		
LAX	4	12/18	1		

Amtrak Initial Terminal Details

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/18/2025

Terminal	Train	Date	Late	Delay	Cause
LAX	586	12/18	(No OS)		
OKJ	522	12/18	1		
OKJ	536	12/18	(Trn Cxld)		Engine Issue
SAC	535	12/18	5	5	Holding for AMT 6 to arrive the SAC station Milepost, 88.9, 88.9
SAC	551	12/18	9		
SAN	593	12/18	(Trn Cxld)		Trespasser Strike
SAN	765	12/18	1		
SJC	542	12/18	5	5	Meet 539, Control Point, Alameda

Eastern Region

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	98.7	94.8	309	2
CDOT	95.0	90.0	92.4	92.4	20	2
MARC	95.0	75.9	87.5	90.2	58	14
SEPTA	95.0	95.0	94.6	91.5	220	11
NJT-NED	95.0	95.4	91.9	93.8	370	17
NJT-SED	95.0	100	99.0	97.2	24	0

Operating Highlights

Train 40(18) Savannah, GA - Servicing

19DEC25: Train 40(18) operating with engines 341, 356, and 10 cars was delayed departing Savannah, GA on the CSX Savannah subdivision due to the fuel vendor needing to obtain the proper nozzle to fuel the equipment. Once the vendor returned on site with the proper tools and fueled, train 40(18) was able to proceed north.

Train	Delay	Comment
40(18)	48"	

Train 98/52(18) North of Savannah, GA - Freight Train Interference

18DEC25: Train 98(18) operating with engines 302 and 368 and train 52(18) operating with engines 352 and 360 were delayed 10 miles north of Savannah, GA on the CSX Charleston subdivision holding at milepost 481.1 for excessive freight congestion ahead. Once the area was clear, both trains proceeded north.

Train	Delay	Comment
98(18)	46"	
52(18)	1'15"	

CPKC Systemwide Outage Delays

18DEC25: CPKC reported at system wide outage with no phones or dispatcher screens working at 1:49PM-ET. The outage affected Amtrak's Borealis, Hiawatha, Ethan Allen Express and Adirondack service. Train 68(18) held at Rouses Point Stations, 290(18) held north of Fort Edward station at MP56.1, train 69(18) held at MP98.9 south of Ticonderoga station, 1340(18) stopped east of Minneapolis St. Paul station at MP383.4 and train 1333(18) was stopped west of Milwaukee station at MP83.0 CKPC worked to restore their systems and they were brought back online at 217PM ET. Once the systems were back online all affected trains were back on the move.

Train	Delay	Comment
69(18)	10"	
290(18)	1'18"	
1333(18)	27"	
1340(18)	41"	
68(18)	22"	
241(18)	40"	Late turn 291(18)

Train 171(18) North of New Haven, CT - Signal

18DEC25: Train 171(18) was delayed at MP90.0000005539 north of New Haven, CT. station on the Amtrak NHB Line due to signal issues with the 21A switch. Maintainers arrived on the scene and 171(18) was able to proceed through the switch at restricted speed. Maintainers found a broken motor wire and repaired it. The 21A switch was back in service at 1245PM ET.

Train	Delay	Comment
171(18)	34"	
2152(18)	5"	
170(05)	30"	
2150(05)	21"	
2159(25)	14"	

Train 98(18) Miami, FL - Routing

18DEC25: Train 98(18) was delayed at MP1033.5 Miami, FL. on the CSX Miami subdivision due to a Tri Rail commuter train striking a vehicle at MP1028.7. The strike occurred at approximately 615AM ET and was not a fatality. Strike caused a pole to fall on the tracks creating a single track operation. Train 98(18) departed Miami, FL station at 900AM ET and proceeded to the next signal to allow commuter train traffic to proceed south. Once the commuter trains were clear, 98(18) was back on the move north.

Train	Delay	Comment
98(18)	1'15"	

Train 41(16) Savannah, GA - Freight Train Interference

18DEC25: Train 41(16) was delayed at MP490, 7.7 miles north of Savannah, GA. stations on the CSX Columbia subdivision following freight train M491. Once around train M491, 41(16) was able to get back up to track speed.

Train	Delay	Comment
41(16)	30"	

Train 2150(18) Washington D.C. - Initial Terminal Delay

18DEC25: Acela 2150(18) operating with power car 2039, 6 cars, and power car 2035 was late departing Washington D.C. due to late servicing of equipment in the yard. Once released, the equipment proceeded to the station to load commissary and 61 passengers for departure. Train 2150(18) departed Washington DC station at 545AM ET.

Train	Delay	Comment
2150(18)	45"	
2167(18)	41"	

26"FOI 00197 00000005569 UNCLASSIFIED

WBS#: B.TR.100150.5989

Train	Delay	Comment
64 (13)	57"	

Eastern Region

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike Damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 90(18) Passenger Removal at Baltimore, Maryland – Improper Behavior***

18DEC25, Passenger on PNR B995E8, traveling from Richmond, VA to Wilmington, DE was removed from the train by local Amtrak Police for lewd behavior. Amtrak Police notified.

Delay: 90(18) 3"

Operating Highlights

Train 341(18) Chicago, IL - Engine Failure

19DEC25: Train 341(18) was cancelled and two (2) alternate buses sourced after locomotive AMTK 169 was bad ordered for flat spots and wheel gouging. As background, inbound 1340(18) arrived in Chicago at 749pm; 28 minutes late. After detraining the 174 passengers from inbound 1340(18), Train 341(18) began boarding 103 outbound passengers. At 752pm, the diesel pit called the glasshouse and said they were going to blue flag the Milwaukee on track 17. At 757pm, the diesel pit reported clear of Train 341(18) to the glasshouse yardmaster with no report of any equipment concerns. It was unknown at that time why the diesel pit had blue flagged the equipment. At 757pm, the Milwaukee Road Foreman called the Chicago Control Center because the diesel pit had mentioned to 341's conductor that engine AMTK 169 had condemnable flat spots. The Control Center had no knowledge of any equipment issues and mentioned to the Milwaukee Road Foreman that the diesel pit had just reported clear at 757pm with no reports of any equipment issues. On the 800pm Division Call, the Control Center inquired with the diesel pit general foreman about any concerns with Train 341(18)'s engines. The diesel pit general foreman said there were none that he knew of, but his foreman was calling him on the phone. After dropping off the call for approximately 1-minute, the diesel pit general foreman rejoined the 800pm Division Call at 804pm and confirmed that engine AMTK 169 was bad ordered for flat spots. The diesel pit general foreman had a note in his turnover to inspect the wheels on engine AMTK 169 when Train 1340(18) arrived in Chicago. As background, there was no mention of any wheel issues on engine AMTK 169 in the "Michigan/ St. Paul Mechanical Report" that was distributed earlier in the day. The "Michigan/ St. Paul Mechanical Report" is normally what is used to document any equipment concerns so plans can be made for any potential bad orders. It was later learned that contractor Drummack had contacted the diesel pit directly to have the Chicago Diesel Pit inspect the wheels on engine AMTK 169 when it arrived in Chicago. At 805pm, Train 341(18)'s crew was contacted by the glasshouse yardmaster to stop boarding and detrain all passengers due to the bad order locomotive. Two alternate buses were sourced arriving at 910pm and 920pm, departing at 925pm and 930pm. Bad order engine AMTK 169 was replaced with engine AMTK 518 so the equipment could deadhead to Milwaukee to represent Train 332(19) the following day. The replacement engine AMTK 518 was released at 850pm, and the deadhead equipment was made-up at 1009pm. Mechanical released the deadhead equipment at 1033pm after completing required air tests. The deadhead equipment departed Chicago at 1140pm.

Train	Delay	Comment
341(18)	CANCELLED.	

Train 591(18) Santa Ana, CA - Police Related

19DEC25: Train 591(18), with 90 passengers, was delayed holding at Santa Ana, CA, on SCRRA Orange subdivision, due to police activity north of Fullerton, CA. Police reported trains in the area were shot at. As a result train 591(18) held at Santa Ana, CA for the conclusion of the police investigation.

Train 790(18), with 113 passengers, was delayed north of Fullerton, CA at milepost 159.4 holding for open track.

Service recovery for both trains was implemented. Complimentary coffee was given out, and emergency snacks and water was given out to passengers.

Train	Delay	Comment
591(18)	1'09"	
790(18)	44"	

Train 14(18) North of Paso Robles CA, Delayed by Vehicle on Tracks

18DEC25: Train 14(18) delayed by vehicle on tracks, on Union Pacific Railroad, Coast Subdivision, 91 miles North of Paso Robles. This was due to a road vehicle which had become high-centered on the tracks at Spence Rd rail crossing (DOT#752177T). Once the vehicle was removed and tracks were inspected, train 14(18) was able to proceed. Amtrak Police Notified

Train	Delay	Comment
14(18)	55"	

Train 383(18) West of Princeton, IL - Weather

18DEC25: Train 383(18), with 82 passengers, was delayed west of Princeton, IL, on BNSF Mendota subdivision, due to operating through high speed wind restrictions that required the train to operate at 40mph from milepost 105 to milepost 228.

Train	Delay	Comment
383(18)	22"	

Amtrak Cascades - Trains 507/508(18) Terminate Originate Portland

18DEC25: The pacific northwest continues to be affected by extreme weather and winter storms. this will cause the following alterations to Amtrak Cascades services south of Portland.

Train 507(18) Terminates in Portland - replacement bus service operates all stations to Eugene.

Train 508(18) Originates in Portland - replacement bus service operates all stations Eugene thru Portland.

Train 508(18) was delayed departing Portland, waiting for passengers arriving on replacement buses.

Train	Delay	Comment
507(18)	Term Portland	Replacement Buses Operate
508(18)	Orig Portland	Replacement Buses Operate

Train 517(18) South of Centralia , WA – Livestock Strike – Cervine

18DEC25: Train 517(18) struck a deer that had wandered onto the tracks 38 miles South of Centralia at Ostrander, MP 92.5, Seattle Subdivision of the BNSF Railway. There were no reported injuries to (153) passengers or crew. The crew believed the deer suffered fatal injuries. The crew reported significant damage to compressed air valve, air hose on Cab Car AMTK/7911. The crew worked initially with technicians from CNOC Mechanical Desk but were unable to resolve the leak. A passing BNSF Coal train gave the crew a replacement hose and wrench, but the crew were unable to stem the air leak. After train 507(18) pulled alongside 517(18) both crews worked together and were able to seal the leak, which restored compressed air pressure. After a successful, mandatory air brake test the train was able to continue.

Service Recovery: Complimentary Snack Packs, Hot Beverages and Bottled Water available to affected passengers. Amtrak Police Notified.

Train	Delay	Comment
517(18)	2'13"	MP 92.5
507(18)	37"	MP 92.5 - Assist 517(18) Crew
506(18)	1'34"	PDX - Equipt Turn from 517(18)
14(17)	39"	

18DEC25: Train 364(18) held 23 miles west of Chicago, IL at 5:53pm. At 3:45pm, trail locomotive Charger ID4620 was bad ordered for a coolant leak and loading issues. Replacement locomotive Charger ID4633 was released at 4:08pm and tied on at 5:00pm. Train 364(18) was released by mechanical at 5:27pm and set in the station at 5:37pm with 210 passengers to board. Upon spotting in the station, 364's conductor reported toilet and door issues on café car ID4305. CUS Mechanical blue flagged the track work on café ID4305 and reported clear at 6:13pm. Train 364(18) departed Chicago at 6:15pm; 2 hours and 15 minutes late.

Train	Delay	Comment
364(18)	2'15"	

Train 784(18) South of Oxnard, CA - Commuter Train Interference

18DEC25: At approximately 2:00PM-PT, Metrolink Train ML/118(18) collided with a SUV 6 miles south of Oxnard CA. The incident occurred at Los Posas Road crossing (DOT# 745870K), MP 410.4, Santa Barbara Subdivision of the Union Pacific Railroad. There were no reports of injuries on board the train. The occupants of the SUV were confirmed fatally injured at the scene. The SUV sustained extensive damage own on impact, requiring extensive recovery. Damage to the train was undisclosed. Local authorities (compromising Camarillo City Police & Fire Dept) were quickly on the scene to investigate. The train crew requested trauma relief at the scene. Once the investigation was completed, a track inspector examined the rails. The SUV was removed by tow truck allowing trains to continue. Service Recovery : Affected Trains Complimentary Snack Packs, Bottled Water and Hot Beverages available to passengers.

The following alterations to service were implemented:

- Train 581(18) Turned in Los Angeles for an 'on-time' train 784(18) Los Angeles thru San Diego.
- Train 784(18) (from Goleta) Terminated in Los Angeles. Thru passengers transferred to 790(18). Equipment returned to Los Angeles Maintenance Facility.
- Train 586(18) Cancelled - Passengers to 790(18)
- Train 593(18) Cancelled - Passengers to 595(18)
- Train 582(18) Turned in San Diego for 595(18)

Update:

In order to clear routes for all delayed trains faster, the UP requested that 784(18) and 790(18) combine at Oxnard and operate as combo train to Los Angeles. Train 587(18) equipment turned for an ontime 790(18) at Los Angeles and operated to San Diego.

Cause: Pending

Train	Delay	Comment
784(18)	Terminates Los Angeles	Passengers to 790(18)
586(18)	Cancelled	Passengers to 790(18)
593(18)	Cancelled	Passengers to 595(18)
784(18)	2"	LAX section.
779(18)	3'11"	
794(18)	1'37"	
785(18)	1'43"	
790(18)	3'06"	Metrolink Trespasser strike
790(18)	29"	Combining with 784(18)
11(17)	1'59"	

Train 4(17) West of Las Vegas, NM - Passenger Train Interference

18DEC25: Train 4(17) held 23 miles west of Las Vegas, NM/MP770.1, on the BNSF Glorieta Subdivision, at Blanchard/MP793.1 meeting Train 3(17).

Train	Delay	Comment
4(17)	1'08"	

18DEC25: Train 59(17) 26-FOI-00197-00000005539.1 UNCLASSIFIED of 12/23/2025
 McComb Subdivision, at Arcola/MP840.0 meeting Train 58(18).

Train	Delay	Comment
59(17)	55"	

Trains 7/27(17) and 8/28(16) West of Fargo, ND - Weather

18DEC25: Train 7/27(17) was delayed starting 42.3 miles west of Fargo, ND/MP23.4, on the BNSF Hillsboro Subdivision, from high wind warnings starting at Taft/MP65.7 to Grand Forks, ND/MP97.9. The high winds continued on the BNSF Devils Lake Subdivision from the DL Switch/MP0.4 to MP133.0. Operating speeds through the whole area were reduced to 40MPH.

Train 7/27(17) was further delayed holding 0.3 miles east of Minot, ND/MP203.3X, on the BNSF KO Subdivision, at CP2030/MP203.0X for the recrew and pilots to arrive from Minot as the crew expired at 12:09PM-CT. Train 8/28(16) was working the station first, so Train 7/27(17) had to hold out until they cleared before being able to enter the station track. Additional delay at station servicing equipment.

Train 8/28(16) was also delayed through the area from the high winds starting 9.2 miles east of Rugby, ND/MP142.2, on the BNSF Devils Lake Subdivision, at MP133.0. Operating speeds were reduced to 40MPH until Fargo, ND/MP23.3.

Train	Delay	Comment
7/27(17)	1'58"	High Winds FAR-RUG
7/27(17)	38"	E/MOT - Holding for Recrew
7/27(17)	54"	MOT
8/28(16)	35"	MOT
8/28(16)	2'05"	High Winds RUG-FAR

Train 537(18) West of Suisun-Fairfield, CA - Third Party Contractor Engine Failure

18DEC25: Locomotive CDTX/2009 on Train 537(18) suffered a critical computer failure near MP 42.5, west of Suisun on the Martinez Subdivision (UPRR). This disabled the tractive effort of the locomotive, Head End Power continued to be operational. On-site repair was not possible. Train 539(18) coupled to the front of 537(18) to tow the disabled train. The combined consist proceeded to Oakland Maintenance Facility, where Train 537(18) portion was uncoupled. Train 539(18) then continued to San Jose.

UPDATE: Technicians in Oakland Maintenance Facility were unable to repair computer in locomotive CDTX/2009. This led to the following alteration to service:

Train 536(18) Cancelled - Passengers to 538(18).

Train 551(18) Cancelled - Replacement Bus Service operates

Train 542(18) Turns in Sacramento for 525(19) .

Service Recovery: Affected passengers offered 20% discount on cafe items.

Cause: Pending

WBS#: B.TR.100150.6329

Train	Delay	Comment
537(18)	Term SUI - 1'30"	Equipt Couple to 539(18)
	Delay	
539(18)	35"	MP 42.00 - Couple to 537(18)
539(18)	24"	Oakland Maintenance Facility - Uncouple 537(18) Portion
551(18)	Cancelled	Replacement Bus Operates

Train 59(17) South of Hazlehurst, MS - Tree Strike

18DEC25: At 12:53PM-26-FOI-00197 (00000005539), E/38 UNCLASSIFIED, 12/23/2025k a tree 8.2 miles south of Hazlehurst, MS/MP762.5, on the CNRR McComb Subdivision, at MP770.7. There were no injuries reported to the crew or 105 passengers onboard. The strike caused multiple air hose separations between E/38 and C/31021 as well as between C/34004 and C/34031. Head end power was intermittent while the crew worked in between the cars. The strike shoved the tree clear of the tracks. The crew inspected and reported the fiberglass was cracked and slight plow damage on engine 38. Once the inspection was complete and air restored, Train 59(17) was back on the move south at 1:26PM-CT.

Train	Delay	Comment
59(17)	37"	

Gold Runner - Equipment Turns Emeryville . Locomotive Shortage

18DEC25: Locomotive CDTX/2107 assigned to train 716(16) experienced a hydraulic pump failure, which could not be repaired in Oakland Maintenance Facility. This led to a shortage of serviceable locomotives in Oakland Maintenance Facility, causing the following equipment turns.

All affected trains, after terminating in Emeryville, operated to Oakland Maintenance Facility to fuel and empty waste tanks before returning to Emeryville to Originate.

- Train 711(18-19) Terminated in Emeryville - Passengers for Oakland advised to board train 535(18-19) departing Emeryville at 11:29AM-PT
- Train 714(18-19) Originated in Emeryville - Passengers Boarding in Oakland advised to use train 532(18-19) departing Oakland at 12:55PM-PT to connect in Emeryville. -
- Train 713(18-19) Terminated in Emeryville - Passengers for Oakland advised to board train 543(18-19) departing Emeryville at 4:02PM-PT
- Train 716(18-19) Originated in Emeryville - Passengers Boarding in Oakland advised to use train 536(18-19) departing Oakland at 2:58PM-PT to connect in Emeryville.
- Train 715(18-19) Terminates in Emeryville - Passengers for Oakland advised to board train 545(18-19) departing Emeryville at 5:37PM-PT
- Train 718(18-19) Originates in Emeryville - Passengers Boarding in Oakland advised to use train 544(18-19) departing Oakland at 6:35PM-PT to connect in Emeryville. -

Train	Delay	Comment
711(18)	Term EMY	Passengers to 535(18)
715(18)	Term EMY	Passengers to 545(18)
713(18)	Term EMY	Passengers to 543(18)
714(18)	53" Orig EMY	Passengers to 532(18)
718(18)	40" Orig EMY	Passengers to 544(18)
716(18)	2'22" Orig EMY	Passengers to 538(18)

Train 531(18) West of Suisun, CA – Bridge Open – Maritime traffic

18DEC25: Train 531(18) was delayed at Benicia, MP 34.5 on the UPRR Martinez Subdivision, 14 miles west of Suisun City, CA, waiting for maritime traffic. Once the vessels had cleared, train 531(18) continued to Martinez at track speed.

Train	Delay	Comment
531(18)	38"	
526(18)	33"	

Train 319(18) Chicago, IL - Door Loop Issues

18DEC25: Train 319(18) was delayed at MP209.5, 17.6 miles south of Chicago, IL account M/U faults and door loop issues. Mechanical responded and found the APTA train relays were switched off on the consist. Once rectified and blue flagged were dropped, the crew started boarding the 222 passengers. At 10:23AM, Train 319(18) departing Chicago operating 33 minutes late.

Train	Delay	Comment
319(18)	33"	

Train 51(17) South of Rensselaer, IN - Signal

18DEC25: Train 51(17) was delayed at MP96.2, 32.7 miles south of Rensselaer, IN station on the CSX Monon subdivision due to signals from MP96.2 to MP91.1 displaying stop signals. Train 51(17) proceeded through the signals at restricted speed and once clear were back up to track speed.

Train	Delay	Comment
51(17)	30"	

Train 22(18) North of San Antonio, TX - M of W Work

18DEC25: Train 22(18) was delayed north of San Antonio, TX/MP209.5, on the UPRR Austin Subdivision, at MP251 due to a reported broken rail at MP246.07. Maintenance of Way responded to the location and was able to walk Train 22(18) over the defect. Once this was complete, Train 22(18) resumed track speed.

Train	Delay	Comment
22(18)	38"	

Train 59(17) South of Carbondale, IL - Freight Train Interference

18DEC25: Train 59(17) was delayed at MP326.0, 17.6 miles south of Carbondale, IL. station on the CN Centralia subdivision due to meeting multiple freight trains. Once the freight trains cleared, train 59(17) was back on the move south towards Fulton, KY station.

Train	Delay	Comment
59(17)	49"	

Train 8/28(16) East of Malta, MT - Freight Interference / Signals

18DEC25: Train 8/28(16) was delayed at Malta, MT/MP343.2 and Glasgow, MT/MP277.5 on the BNSF Milk River Subdivision, from freight interference and signal issues. First, Train 8/28(16) met BNSF 6786 1.5 miles east of the Malta Station at Malta East/MP341.7. Additionally, Train 8/28(16) held at Bowdoin West/MP330.8 to meet BNSF 6176 followed by signal issues at East Bowdoin/MP329.1. At East Tampico/MP288.0, Train 8/28(16) had to meet BNSF 6717 and then work the frozen switch at East Tampico in order to proceed east. At the Stanley, ND station/MP54.3, on the BNSF Glasgow Subdivision, the train had to hold for the recrew to arrive from Minot. Once the recrew was onboard, Train 8/28(16) continued east.

Due to the delay, service recovery was enacted onboard consisting of snack packs and water. The Lounge offered coffee, tea, juice, and comped meals. The Diner offered lunch and dinner services to all coach passengers to Chicago. Sleeper passengers meals were not affected and they ordered as normal from the menu.

Train	Delay	Comment
8/28(16)	26"	BNSF 6786
8/28(16)	20"	Signals East Bowdoin
8/28(16)	03"	BNSF 6176
8/28(16)	31"	BNSF 6717
8/28(16)	27"	Switch Failure - East Tampico
8/28(16)	33"	STN - Recrew

Train 6(16) Denver, CO - Car Failure / High Winds

18DEC25: Train 6(16) was delayed at Denver, CO/MP0.0, on the BNSF Front Range Subdivision, while mechanical completed routine inspections and looked at C/31025 marker light failure. Mechanical could not diagnose this issue so an End of Train Device was picked up and added at 31st Street yard/MP541.2 after departing the station. Train 6(16) was further delayed operating through high wind warnings reducing train to 40MPH from 31st Street Yard/MP541.2 to MP511.4. High winds continued on much on the route east. Starting 17.2 miles east of Fort Morgan, CO/MP464.2, on the BNSF Akron Subdivision, 60MPH winds reduced operating speeds to 40MPH from MP447.0 to MP366.2. Starting again 32.3 miles east of Holdridge, NE/MP210.9, Train 6(16) continued to operate through high speed restrictions until Creston, IA/MP393.1.

Service recovery was enacted due to lateness starting with snack packs and bottled water. The Lounge car offered coffee, tea, juice, discount and comped meals to Coach Passengers. The Diner offered lunch meal service to all passengers. Sleeper meals were not affected and they received normal meals off the menu.

UPDATE: Due to the extreme lateness of train 6(16), they were delayed departing Galesburg, IL, performing their daily inspections.

Train	Delay	Comment
6(16)	36"	DEN
6(16)	10"	31st St - ETD Pickup
6(16)	26"	High Winds DEN-FMG
6(16)	1'06"	High Winds FMG-MCK
6(16)	1'00"	High Winds HLD-HAS
6(16)	3'17"	High Winds HLD-LNK
6(16)	2'24"	High Winds LNK-OTM
6(16)	43"	Daily inspections GBB

Train 4(17) Winslow, AZ - Freight Train Interference

18DEC25: Train 4(17) was delayed beginning at MP291.0, 5.7 miles east of Winslow, AZ. station on the BNSF Seligman subdivision meeting BNSF train 4194. Once the BNSF freight cleared, 4(17) was back on the move east into Winslow, AZ. station.

Train	Delay	Comment
4(17)	35"	

Train 365(18) Port Huron, MI - Freight Train Interference

18DEC25: Train 365 (26-FOI-00197 000000005539 Port "UNCLASSIFIED" MI/12/23/2025.3, on the CNRR Strathroy Subdivision, on-time but was delayed in route from freight interference. CN148 was in emergency ahead on track 3 which required Train 365(18) to shove back into the tunnel in order to come out on track 4. Once this was complete, Train 365(18) continued west at track speed.

Train	Delay	Comment
365(18)	42"	

Train 8(17) East of Everett, WA - Freight Train Interference

18DEC25: Train 8(17) was delayed 75 miles east of Everett, at MP 1707.3 Scenic Subdivision, BNSF Railroad. BNSF Freight train BNF/8453 had previously passed through the tunnel. This required train 8(17) wait for fans to clear exhaust gases from the tunnel. Once completed train 8(17) continued to Leavenworth.

Train	Delay	Comment
8(17)	1'34"	

Amtrak Cascades - South of Tacoma Dome WA. - Signal Failure

18DEC25: Amtrak Cascades trains were delayed while operating 8 miles South of Tacoma Dome WA at Rill, MP 10.7, Lakewood Subdivision, BNSF Railway. The local dispatched was unable to remotely operate the signals in favor of the trains' route. Engineers were required to gain authority to pass the signal while operating at reduced speed. Once clear of the affected area (at Nisqually MP 21.3) trains resumed at track speed to Olympia.

Train	Delay	Comment
503(18)	35"	
505(18)	35"	
500(18)	15"	
517(18)	54"	
502(18)	18"	
504(18)	15"	
518(18)	12"	

Train 3(17) West of Newton, KS - High Winds

18DEC25: Train 3(17) was delayed starting 24.9 miles west of Newton, KS/MP185.1, on the BNSF La Junta Subdivision, from high wind warnings starting at MP210.0 to MP350.0 reducing operating speeds to 40MPH. Additional 60MPH high wind warnings were issued starting 28.8 miles west of Garden City, KS/MP402.2, the BNSF La Junta Subdivision, reducing operating speeds to 40MPH from MP431 to MP516.

Train	Delay	Comment
3(17)	1'16"	HWW MP210-350
3(17)	49"	HWW MP431-516

Train 351(18) Pontiac, MI - Unable to Wye

18DEC25: Train 351(18) was delayed in route shoving from Pontiac, MI/MP25.9 to Detroit, MI/MP53.8 on the CNRR Holly and Shoreline Subdivision, making all station stops along the way. This was a result of a freight train disabled in Pontiac blocking the route to the wye. At Detroit, the equipment was able to wye and track speed resumed.

Train	Delay	Comment
351(18)	1'36"	

Train 11(17) - South of Dunsmuir, CA - Freight Train Interference

18DEC25: Train 11(17) FOI-00197 d0000005539 14 "UNCLASSIFIED" uth 12/23/2025 Dunsmuir after Union Pacific freight train UPRR/5410 experienced a mechanical issue requiring removal of a defective railcar. The procedure blocked the mainline at Gibson (MP 304.2) on the Valley Subdivision. After completion, Train 11(17) followed UPRR/5410 for 19 miles until the freight train entered the siding at Lakehead (MP 285.9), allowing Train 11(17) to resume normal speed.

Train	Delay	Comment
14(17)	12"	
11(17)	1'04"	

UNCLASSIFIED
12/3/2025
B. TR. 100150.6267
Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Western Region

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (16)	SEA	BNSF6559	E/182 failed departure test		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 1(17) Passenger Removal at Lordsburg, New Mexico – Medical

18DEC25, Passenger on PNR AB4B2A, traveling from New Orleans, LA to Tucson, AZ was removed from the train by Wilcox EMS after falling in the bathroom. Passenger was assisted up by the crew. Amtrak Police notified.

Delay: 1 (17) 27"

Consist Deviations

26-FOI-00197

00000005539

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2163 (18)	BOS	2163 IS OPERATING NEXT GEN EQUIPMENT, SCHEDULE CHANGE HAS BEEN COMPLETED			
177 (18)	BOS	BUSINESS CLASS OPERATING AS A COACH			81525
48 (17)	CHI	48(17) shipped 62007 for freeze damage. The dhd 62503 will now be the live sleeper in lieu of viewliner 1. Block rooms H-A-1-3.	No impact	0	62503
307 (18)	CHI	Due to shipped equipment and no replacement 307(18) will NOT offer biz class. customer service notified.			NOCAR
6 (18)	EMY	32018 is repeat for waste system inoperable. 39039 is added to rear as replacement. Please accomodate all pax who are affected.	None	0	39039
6 (18)	EMY	Transdorm in lieu of sleeper	No impact	0	39039
371 (18)	GRR	No business class in consist.	Pax downgraded	18	NOCAR
181 (18)	NYP	Business class in lieu of coach	No impact	0	81544
2190 (18)	NYP	2190 IS OPERATING NEXT GEN EQUIPMENT, SCHEDULE CHANGE HAS BEEN COMPLETED	n/a	0	
110 (18)	PHL	AMII in lieu of AMI business class.	No impact	0	25117
302 (19)	STL	Due to shipped equipment and no replacement 302(19) will NOT offer biz class. customer service notified.			NOCAR
172 (18)	WAS	BUSINESS CLASS OPERATING AS A COACH			81525

Reverse Consists

Train Number	Station	Reason
93 (18)	BOS	Consist reversed Business class seat orientation may have changed At Front
183 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
2150 (18)	WAS	Acela consist reversed First class at Front
2159 (18)	BOS	Acela consist reversed First class at Rear
94 (19)	NFK	Consist reversed Business class seat orientation may have changed At Front
182 (18)	WAS	Consist reversed Business class seat orientation may have changed At Rear
133 (18)	NYP	Consist reversed Business class seat orientation may have changed At Front
192 (18)	WAS	Consist reversed Business class seat orientation may have changed At Rear
2167 (18)	BOS	Acela consist reversed First class at Rear
2193 (18)	BOS	Acela consist reversed First class at Rear
2193 (18)	BOS	Acela consist reversed First class at Rear