



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Saturday, December 20, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-00197Initial Terminal Performance By Division

Scheduled Departure Date: 12/19/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/19/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	321	64	80.1%	5,823	919	84.2%	23,732	3,109	86.9%
Central Division	85.5%	71	16	77.5%	1,250	216	82.7%	5,272	585	88.9%
Northeast Division	80.0%	102	26	74.5%	1,881	295	84.3%	7,477	1,047	86.0%
Southeast Division	72.5%	74	14	81.1%	1,340	226	83.1%	5,539	743	86.6%
Southwest Division	77.0%	74	8	89.2%	1,352	182	86.5%	5,444	734	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00197 00000005538 UNCLASSIFIED Endpoint Arrival Dates through 12/19/25 12/23/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	109,243	34,995	68%	1,890,434	476,980	75%	8,085,168	1,725,185	79%
Northeast Corridor	81%	46,935	16,659	65%	859,365	214,570	75%	3,650,766	732,454	80%
Acela	83%	10,178	3,884	62%	195,027	59,240	70%	787,227	176,919	78%
Northeast Regional	79%	36,757	12,775	65%	664,338	155,330	77%	2,863,539	555,535	81%
Richmond / Newport News / Norfolk	77%	12,203	4,668	62%	203,389	53,119	74%	869,395	196,624	77%
Springfield Shuttles	89%	949	82	91%	15,487	1,794	88%	49,009	5,489	89%
Roanoke	79%	3,065	0	100%	51,723	9,464	82%	220,476	36,213	84%
On Spine Northeast Regional	80%	20,540	8,025	61%	393,739	90,953	77%	1,724,659	317,209	82%
State Supported	80%	47,693	11,567	76%	801,804	172,914	78%	3,448,478	655,969	81%
Borealis	60%	604	286	53%	10,418	3,347	68%	46,708	12,918	72%
Capitol Corridor	90%	3,451	356	90%	66,726	7,162	89%	285,319	30,558	89%
Carolinian	60%	1,083	419	61%	21,227	7,317	66%	94,373	28,219	70%
Cascades	63%	2,734	531	81%	40,722	11,461	72%	187,011	46,798	75%
Downeaster	82%	1,543	148	90%	26,367	4,190	84%	117,625	15,966	86%
Empire	78%	6,546	1,924	71%	106,744	23,724	78%	422,928	85,269	80%
Adirondack	72%	375	277	26%	5,249	2,671	49%	26,148	9,222	65%
Ethan Allen Express	70%	655	290	56%	10,358	3,051	71%	47,351	14,572	69%
Maple Leaf	70%	944	933	1%	12,956	7,146	45%	48,338	18,934	61%
New York - Albany	85%	3,084	422	86%	53,398	5,813	89%	192,005	24,935	87%
New York - Niagara Falls	75%	1,488	2	100%	24,783	5,043	80%	109,086	17,606	84%
Gold Runner	73%	2,983	1,411	53%	42,173	14,585	65%	196,221	70,230	64%
Heartland Flyer	65%	303	0	100%	3,370	662	80%	15,879	8,232	48%
Hiawatha	90%	1,825	600	67%	32,684	6,129	81%	139,137	17,044	88%
Illinois	78%	2,540	1,400	45%	44,364	18,974	57%	194,201	58,292	70%
Carl Sandburg / Illinois Zephyr	85%	329	245	26%	8,024	2,832	65%	33,182	9,390	72%
Illini / Saluki	85%	885	332	62%	13,167	5,859	56%	67,991	19,318	72%
Lincoln Service	70%	1,326	823	38%	23,173	10,283	56%	93,028	29,584	68%
Keystone	92%	9,321	723	92%	168,569	24,385	86%	664,147	65,196	90%
Lincoln / Missouri	60%	833	337	60%	13,733	6,789	51%	62,033	31,445	49%
Mardi Gras Service	80%	344	0	100%	6,863	172	97%	34,536	3,931	89%
Michigan	69%	2,151	569	74%	36,973	17,917	52%	156,308	47,805	69%
Blue Water	70%	497	226	55%	7,794	4,200	46%	38,579	11,495	70%
Pere Marquette	85%	373	184	51%	5,079	1,635	68%	20,975	3,564	83%
Wolverine	65%	1,281	159	88%	24,100	12,082	50%	96,754	32,746	66%
Missouri	80%	250	4	98%	4,148	1,083	74%	18,718	4,619	75%
Pacific Surfliner	85%	7,691	1,940	75%	115,910	11,049	90%	528,898	69,196	87%
Pennsylvanian	72%	1,023	294	71%	16,815	2,147	87%	73,839	8,345	89%
Piedmont	73%	995	153	85%	18,792	3,150	83%	103,121	24,981	76%
Vermont	75%	1,473	472	68%	25,206	8,671	66%	107,476	26,925	75%
Long Distance	56%	14,140	6,769	52%	228,790	89,496	61%	985,449	336,762	66%
Auto Train	57%	854	0	100%	13,389	2,995	78%	53,214	10,206	81%
California Zephyr	50%	1,289	805	38%	15,491	5,887	62%	72,299	21,558	70%
Cardinal	55%	298	200	33%	5,104	2,416	53%	22,460	10,721	52%
City Of New Orleans	75%	819	37	95%	12,660	2,108	83%	55,986	11,830	79%
Coast Starlight	60%	1,289	444	66%	21,790	6,407	71%	92,328	28,782	69%
Crescent	70%	1,024	258	75%	17,408	3,106	82%	76,523	18,888	75%
Empire Builder	55%	952	774	19%	16,561	7,783	53%	76,978	28,044	64%
Floridian	40%	1,716	1,256	27%	31,489	21,084	33%	135,390	75,456	44%
Lake Shore Ltd	73%	1,189	522	56%	19,898	7,137	64%	75,826	15,398	80%
Palmetto	65%	930	314	66%	17,569	5,424	69%	77,378	13,855	82%
Silver Meteor	45%	1,117	552	51%	19,170	7,636	60%	81,919	25,970	68%
Southwest Chief	40%	799	635	21%	13,734	9,440	31%	65,308	39,794	39%
Sunset Ltd	70%	809	267	67%	5,679	903	84%	22,061	5,127	77%
Texas Eagle	50%	1,055	705	33%	18,848	7,170	62%	77,779	31,133	60%
Seasonal Trains	%	475	0	100%	475	0	100%	475	0	100%
Winter Park Express	75%	475	0	100%	475	0	100%	475	0	100%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005500 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 19, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	121,001	2,060,462	587	450,883	8,569,255	526

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	5,822	613,131	95	18,177	2,515,367	72
INFRASTRUCTURE PLANNED	135	3,291	613,131	54	13,872	2,515,367	55
FLEET RELIABILITY	90	23,084	2,060,462	112	70,968	8,569,255	83
TRAIN OPERATIONS	424	88,804	2,060,462	431	347,866	8,569,255	406

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/19/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/19/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	321	64	80.1%	5,823	919	84.2%	23,732	3,109	86.9%
Central Division	85.5%	71	16	77.5%	1,250	216	82.7%	5,272	585	88.9%
Northeast Division	80.0%	102	26	74.5%	1,881	295	84.3%	7,477	1,047	86.0%
Southeast Division	72.5%	74	14	81.1%	1,340	226	83.1%	5,539	743	86.6%
Southwest Division	77.0%	74	8	89.2%	1,352	182	86.5%	5,444	734	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/19/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/19/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	321	64	80.1%	5,823	919	84.2%	23,732	3,109	86.9%
Central Division	85.5%	71	16	77.5%	1,250	216	82.7%	5,272	585	88.9%
CDL	90.0%	1	1	0.0%	20	2	90.0%	134	8	94.0%
CHI	85.0%	28	8	71.4%	508	109	78.5%	2,141	246	88.5%
CHM	-	1	0	100.0%	10	4	60.0%	10	4	60.0%
DEN	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
EUG	86.5%	2	1	50.0%	37	5	86.5%	154	20	87.0%
GRR	98.0%	1	0	100.0%	18	2	88.9%	79	2	97.5%
KCY	84.5%	2	0	100.0%	38	3	92.1%	158	14	91.1%
MKE	86.5%	6	2	66.7%	112	13	88.4%	468	43	90.8%
MSP	94.0%	1	0	100.0%	19	0	100.0%	80	3	96.3%
PDX	78.0%	5	1	80.0%	95	11	88.4%	401	57	85.8%
PNT	91.5%	3	0	100.0%	56	12	78.6%	182	17	90.7%
PTH	93.0%	1	0	100.0%	18	4	77.8%	79	6	92.4%
QCY	87.5%	2	0	100.0%	38	3	92.1%	160	15	90.6%
SEA	80.0%	8	1	87.5%	150	25	83.3%	635	99	84.4%
SPK	92.0%	2	1	50.0%	22	5	77.3%	83	6	92.8%
STL	88.0%	4	1	75.0%	74	17	77.0%	316	35	88.9%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	33	1	97.0%	155	5	96.8%
WIP	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
Northeast Division	80.0%	102	26	74.5%	1,881	295	84.3%	7,477	1,047	86.0%
ALB	91.5%	8	1	87.5%	152	10	93.4%	519	31	94.0%
BON	43.5%	5	0	100.0%	95	6	93.7%	382	38	90.1%
BOS	86.5%	19	5	73.7%	363	49	86.5%	1,461	152	89.6%
BRK	88.0%	5	0	100.0%	95	4	95.8%	362	17	95.3%
BTN	48.0%	1	0	100.0%	19	0	100.0%	79	17	78.5%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	38	4	89.5%	154	13	91.6%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	19	3	84.2%	80	14	82.5%
NFL	96.5%	2	0	100.0%	38	1	97.4%	160	5	96.9%
NHV	75.5%	6	0	100.0%	108	12	88.9%	415	75	81.9%
NYP	77.5%	44	19	56.8%	785	201	74.4%	3,161	631	80.0%
SAB	98.0%	1	0	100.0%	19	0	100.0%	78	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	131	2	98.5%	480	18	96.3%
TWO	84.0%	1	0	100.0%	19	3	84.2%	79	19	75.9%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	14	81.1%	1,340	226	83.1%	5,539	743	86.6%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	95	6	93.7%	400	31	92.3%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	3	76.9%	223	61	72.6%	903	159	82.4%
LOR	69.5%	1	0	100.0%	19	1	94.7%	80	6	92.5%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/19/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/19/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	321	64	80.1%	5,823	919	84.2%	23,732	3,109	86.9%
Southeast Division	72.5%	74	14	81.1%	1,340	226	83.1%	5,539	743	86.6%
MIA	87.5%	2	0	100.0%	38	5	86.8%	160	18	88.8%
MOE	94.0%	2	0	100.0%	38	0	100.0%	160	3	98.1%
NFK	86.0%	3	1	66.7%	55	9	83.6%	225	24	89.3%
NOL	92.0%	4	1	75.0%	84	4	95.2%	353	18	94.9%
NPN	96.0%	2	1	50.0%	38	2	94.7%	135	9	93.3%
PGH	92.0%	1	0	100.0%	19	2	89.5%	80	3	96.3%
PHL	45.0%	5	1	80.0%	89	55	38.2%	370	178	51.9%
RGH	97.0%	4	0	100.0%	76	4	94.7%	316	7	97.8%
RNK	85.5%	2	0	100.0%	38	5	86.8%	159	19	88.1%
RVM	86.0%	1	0	100.0%	19	2	89.5%	90	13	85.6%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	19	2	89.5%	80	2	97.5%
SFA	70.5%	1	0	100.0%	19	0	100.0%	80	3	96.3%
WAS	70.0%	27	7	74.1%	471	68	85.6%	1,940	245	87.4%
Southwest Division	77.0%	74	8	89.2%	1,352	182	86.5%	5,444	734	86.5%
ARN	60.5%	1	0	100.0%	19	1	94.7%	80	6	92.5%
BFD	75.5%	7	1	85.7%	125	25	80.0%	472	109	76.9%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	4	3	25.0%	24	14	41.7%	87	31	64.4%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	19	0	100.0%	79	3	96.2%
GTA	72.5%	3	0	100.0%	57	2	96.5%	233	19	91.8%
LAX	77.5%	10	1	90.0%	178	22	87.6%	738	83	88.8%
OKC	96.0%	1	0	100.0%	19	0	100.0%	80	3	96.3%
OKJ	79.0%	10	2	80.0%	219	65	70.3%	879	217	75.3%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	15	0	100.0%	273	31	88.6%	1,061	117	89.0%
SAN	77.0%	12	1	91.7%	220	10	95.5%	913	75	91.8%
SAS	85.0%	1	0	100.0%	19	1	94.7%	80	4	95.0%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	133	9	93.2%	558	49	91.2%
SLO	62.0%	2	0	100.0%	38	1	97.4%	155	12	92.3%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	-	-	-	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		8	0	100.0%	34	1	97.1%	9	0	100.0%	35	1	97.1%
2		8	3	62.5%	35	7	80.0%	8	0	100.0%	34	4	88.2%
3	336	19	5	73.7%	80	9	88.8%	18	10	44.4%	79	33	58.2%
4	83	18	5	72.2%	79	11	86.1%	18	14	22.2%	79	52	34.2%
5	46	19	7	63.2%	79	14	82.3%	18	6	66.7%	77	12	84.4%
6		17	7	58.8%	78	24	69.2%	17	5	70.6%	78	26	66.7%
7	367	19	4	78.9%	80	8	90.0%	15	6	60.0%	76	13	82.9%
8	No OS	19	13	31.6%	80	33	58.8%	19	10	47.4%	80	37	53.8%
11		19	3	84.2%	79	14	82.3%	19	3	84.2%	77	10	87.0%
14		19	1	94.7%	80	10	87.5%	19	1	94.7%	79	19	75.9%
19		19	5	73.7%	80	13	83.8%	19	1	94.7%	80	12	85.0%
20		19	0	100.0%	80	6	92.5%	19	1	94.7%	80	7	91.3%
21		19	5	73.7%	79	13	83.5%	19	5	73.7%	79	16	79.7%
22		19	1	94.7%	80	4	95.0%	19	3	84.2%	79	16	79.7%
23		19	0	100.0%	80	3	96.3%	19	1	94.7%	80	11	86.3%
24		19	4	78.9%	80	6	92.5%	19	1	94.7%	80	7	91.3%
25		19	0	100.0%	80	0	100.0%	19	0	100.0%	80	9	88.8%
26		19	0	100.0%	80	2	97.5%	19	0	100.0%	80	11	86.3%
27	310	19	4	78.9%	80	5	93.8%	18	7	61.1%	79	17	78.5%
40		19	4	78.9%	80	13	83.8%	19	8	57.9%	80	30	62.5%
41	225	19	11	42.1%	80	29	63.8%	19	13	31.6%	80	52	35.0%
42		19	2	89.5%	80	3	96.3%	19	2	89.5%	80	11	86.3%
43		19	2	89.5%	80	7	91.3%	19	1	94.7%	80	4	95.0%
48		19	7	63.2%	80	12	85.0%	19	5	73.7%	80	8	90.0%
49	61	19	2	89.5%	80	12	85.0%	19	6	68.4%	80	11	86.3%
50	49	8	3	62.5%	34	7	79.4%	8	6	25.0%	35	19	45.7%
52		19	0	100.0%	80	3	96.3%	19	2	89.5%	80	14	82.5%
53		19	1	94.7%	80	6	92.5%	19	4	78.9%	80	12	85.0%
55		15	0	100.0%	57	0	100.0%	15	4	73.3%	57	10	82.5%
56		15	5	66.7%	57	12	78.9%	15	4	73.3%	57	10	82.5%
58		19	0	100.0%	79	2	97.5%	19	4	78.9%	78	11	85.9%
59		19	3	84.2%	78	6	92.3%	19	2	89.5%	78	5	93.6%
63	57	19	7	63.2%	80	28	65.0%	19	12	36.8%	80	41	48.8%
64	25	19	3	84.2%	79	19	75.9%	19	7	63.2%	79	17	78.5%
66		19	2	89.5%	80	12	85.0%	19	1	94.7%	80	14	82.5%
67		14	1	92.9%	56	3	94.6%	15	2	86.7%	57	9	84.2%
68	78	19	3	84.2%	80	14	82.5%	19	13	31.6%	80	38	52.5%
69		19	2	89.5%	80	9	88.8%	19	3	84.2%	80	10	87.5%
71		19	1	94.7%	80	1	98.8%	19	5	73.7%	80	21	73.8%
72		19	3	84.2%	80	8	90.0%	19	8	57.9%	80	18	77.5%
73	21	19	2	89.5%	80	3	96.3%	19	6	68.4%	79	39	50.6%
74		19	1	94.7%	80	6	92.5%	19	4	78.9%	80	24	70.0%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		19	0	100.0%	80	2	97.5%	19	7	63.2%	80	35	56.3%
76		19	0	100.0%	80	4	95.0%	19	4	78.9%	80	34	57.5%
77		19	1	94.7%	80	3	96.3%	19	7	63.2%	80	29	63.8%
78		19	0	100.0%	80	3	96.3%	19	2	89.5%	80	11	86.3%
79		19	5	73.7%	80	16	80.0%	19	3	84.2%	79	14	82.3%
80		19	2	89.5%	80	10	87.5%	19	5	73.7%	79	10	87.3%
84	26	15	0	100.0%	57	3	94.7%	15	5	66.7%	57	10	82.5%
85		15	1	93.3%	57	2	96.5%	15	7	53.3%	57	22	61.4%
86	25	15	1	93.3%	57	5	91.2%	15	11	26.7%	57	30	47.4%
89		19	5	73.7%	80	17	78.8%	19	7	63.2%	80	13	83.8%
90		19	2	89.5%	80	2	97.5%	19	3	84.2%	80	9	88.8%
93		15	2	86.7%	57	8	86.0%	15	1	93.3%	56	11	80.4%
94	40	15	7	53.3%	57	13	77.2%	14	5	64.3%	56	17	69.6%
95	24	15	0	100.0%	57	1	98.2%	15	6	60.0%	57	17	70.2%
97		19	14	26.3%	80	32	60.0%	19	3	84.2%	80	19	76.3%
98	111	19	1	94.7%	80	5	93.8%	19	8	57.9%	80	19	76.3%
110	79	15	7	53.3%	57	26	54.4%	15	3	80.0%	57	6	89.5%
111		15	3	80.0%	57	7	87.7%	15	3	80.0%	57	6	89.5%
112		15	1	93.3%	57	5	91.2%	15	1	93.3%	57	6	89.5%
114		15	3	80.0%	57	11	80.7%	14	2	85.7%	56	2	96.4%
119	27	15	3	80.0%	57	12	78.9%	15	3	80.0%	57	6	89.5%
125		15	0	100.0%	57	2	96.5%	15	8	46.7%	57	14	75.4%
129		15	7	53.3%	57	20	64.9%	15	2	86.7%	57	8	86.0%
130		15	0	100.0%	57	4	93.0%	15	1	93.3%	57	5	91.2%
131		15	2	86.7%	57	6	89.5%	15	4	73.3%	57	4	93.0%
133		15	5	66.7%	57	24	57.9%	15	3	80.0%	57	23	59.6%
134		15	2	86.7%	57	6	89.5%	15	3	80.0%	57	11	80.7%
136		15	2	86.7%	57	5	91.2%	14	1	92.9%	57	4	93.0%
137	69	15	3	80.0%	55	11	80.0%	15	4	73.3%	55	14	74.5%
138	17	15	2	86.7%	57	8	86.0%	15	1	93.3%	57	3	94.7%
141		15	0	100.0%	57	3	94.7%	15	4	73.3%	57	12	78.9%
148		15	1	93.3%	57	5	91.2%	15	0	100.0%	56	9	83.9%
151		19	9	52.6%	80	23	71.3%	19	7	63.2%	79	23	70.9%
170	116	15	3	80.0%	54	6	88.9%	15	7	53.3%	54	16	70.4%
171		15	1	93.3%	57	4	93.0%	15	5	66.7%	57	10	82.5%
172	60	15	3	80.0%	57	7	87.7%	15	7	53.3%	57	22	61.4%
173	25	15	4	73.3%	57	6	89.5%	15	8	46.7%	57	23	59.6%
174		15	0	100.0%	57	3	94.7%	15	3	80.0%	57	11	80.7%
175	181	15	4	73.3%	57	6	89.5%	15	6	60.0%	57	14	75.4%
176		15	2	86.7%	57	5	91.2%	15	0	100.0%	57	3	94.7%
177		15	2	86.7%	57	10	82.5%	15	4	73.3%	57	24	57.9%
178	24	15	1	93.3%	57	8	86.0%	14	1	92.9%	57	6	89.5%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		15	1	93.3%	57	5	91.2%	14	2	85.7%	57	12	78.9%
181		15	7	53.3%	57	13	77.2%	14	2	85.7%	56	3	94.6%
182		15	3	80.0%	57	12	78.9%	15	1	93.3%	57	4	93.0%
183		15	6	60.0%	57	17	70.2%	15	4	73.3%	57	10	82.5%
184		15	2	86.7%	57	10	82.5%	15	3	80.0%	57	8	86.0%
185	109	15	3	80.0%	57	11	80.7%	15	2	86.7%	57	3	94.7%
186		15	2	86.7%	57	9	84.2%	15	1	93.3%	57	13	77.2%
190	47	15	7	53.3%	57	23	59.6%	15	3	80.0%	57	13	77.2%
192		15	1	93.3%	55	7	87.3%	15	1	93.3%	55	2	96.4%
193	37	15	4	73.3%	57	17	70.2%	15	6	60.0%	57	20	64.9%
196		15	1	93.3%	57	1	98.2%	15	1	93.3%	57	3	94.7%
197		15	8	46.7%	57	23	59.6%	15	5	66.7%	57	11	80.7%
232		19	0	100.0%	80	1	98.8%	19	0	100.0%	80	6	92.5%
233		19	6	68.4%	80	19	76.3%	19	5	73.7%	80	17	78.8%
234		19	0	100.0%	80	3	96.3%	19	0	100.0%	80	2	97.5%
235		19	1	94.7%	19	1	94.7%	19	3	84.2%	19	3	84.2%
236		19	0	100.0%	80	1	98.8%	19	3	84.2%	80	14	82.5%
237	61	19	2	89.5%	80	12	85.0%	19	2	89.5%	80	6	92.5%
238		19	2	89.5%	19	2	89.5%	19	0	100.0%	19	0	100.0%
239		19	7	63.2%	79	22	72.2%	19	1	94.7%	79	3	96.2%
240		19	1	94.7%	80	7	91.3%	19	4	78.9%	80	11	86.3%
241		19	7	63.2%	80	23	71.3%	19	3	84.2%	80	13	83.8%
243		15	3	80.0%	57	19	66.7%	15	2	86.7%	58	10	82.8%
244		19	0	100.0%	80	2	97.5%	19	1	94.7%	80	16	80.0%
280		19	1	94.7%	80	4	95.0%	19	5	73.7%	80	15	81.3%
281		19	0	100.0%	80	8	90.0%	19	2	89.5%	80	7	91.3%
283		19	7	63.2%	80	15	81.3%	19	4	78.9%	80	13	83.8%
284		19	0	100.0%	80	1	98.8%	19	2	89.5%	80	7	91.3%
290	39	19	0	100.0%	80	18	77.5%	19	6	68.4%	79	27	65.8%
291		19	4	78.9%	80	17	78.8%	19	3	84.2%	80	15	81.3%
300	64	19	6	68.4%	80	8	90.0%	19	9	52.6%	79	23	70.9%
301	29	18	1	94.4%	78	2	97.4%	18	5	72.2%	77	14	81.8%
302		18	5	72.2%	78	11	85.9%	18	6	66.7%	76	23	69.7%
305	27	19	5	73.7%	80	10	87.5%	18	12	33.3%	78	32	59.0%
306	21	18	3	83.3%	78	5	93.6%	18	6	66.7%	77	17	77.9%
307		19	4	78.9%	79	9	88.6%	19	9	52.6%	79	20	74.7%
311		19	3	84.2%	79	10	87.3%	19	5	73.7%	79	19	75.9%
316		19	2	89.5%	79	5	93.7%	19	5	73.7%	79	17	78.5%
318	32	19	1	94.7%	80	10	87.5%	19	8	57.9%	79	33	58.2%
319		19	2	89.5%	80	4	95.0%	19	8	57.9%	80	44	45.0%
329		15	1	93.3%	57	2	96.5%	15	3	80.0%	57	5	91.2%
330		17	0	100.0%	68	2	97.1%	17	4	76.5%	68	5	92.6%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		19	5	73.7%	80	9	88.8%	19	4	78.9%	80	10	87.5%
332		19	4	78.9%	80	9	88.8%	19	6	68.4%	80	11	86.3%
334	14	19	1	94.7%	80	2	97.5%	19	7	63.2%	79	11	86.1%
335	44	19	6	68.4%	80	13	83.8%	18	4	77.8%	78	13	83.3%
336		19	3	84.2%	80	4	95.0%	19	1	94.7%	80	5	93.8%
337		19	1	94.7%	80	5	93.8%	19	4	78.9%	80	9	88.8%
338	62	19	3	84.2%	80	18	77.5%	18	6	66.7%	78	18	76.9%
339	49	19	4	78.9%	80	18	77.5%	19	6	68.4%	80	17	78.8%
341		17	4	76.5%	77	13	83.1%	16	4	75.0%	76	12	84.2%
342		19	2	89.5%	80	8	90.0%	19	6	68.4%	79	14	82.3%
350	32	19	0	100.0%	62	2	96.8%	19	13	31.6%	62	35	43.5%
351		19	7	63.2%	80	10	87.5%	19	8	57.9%	80	34	57.5%
352		19	2	89.5%	80	6	92.5%	18	6	66.7%	77	20	74.0%
353		19	3	84.2%	59	5	91.5%	19	10	47.4%	59	15	74.6%
354		19	4	78.9%	80	7	91.3%	18	11	38.9%	79	25	68.4%
355		18	2	88.9%	79	7	91.1%	17	8	52.9%	78	21	73.1%
364	42	18	10	44.4%	79	15	81.0%	17	8	52.9%	78	16	79.5%
365		18	4	77.8%	79	6	92.4%	17	10	41.2%	78	26	66.7%
370		19	3	84.2%	80	5	93.8%	19	6	68.4%	80	15	81.3%
371	38	18	2	88.9%	79	2	97.5%	18	5	72.2%	79	9	88.6%
380	37	19	3	84.2%	80	13	83.8%	19	6	68.4%	80	19	76.3%
381		19	1	94.7%	80	2	97.5%	19	3	84.2%	80	10	87.5%
382	43	19	0	100.0%	80	2	97.5%	19	6	68.4%	80	21	73.8%
383	No OS	19	4	78.9%	80	9	88.8%	19	11	42.1%	79	33	58.2%
390		11	4	63.6%	64	8	87.5%	11	5	54.5%	64	21	67.2%
391		11	1	90.9%	65	1	98.5%	11	2	81.8%	64	14	78.1%
392	19	19	2	89.5%	80	4	95.0%	19	12	36.8%	79	27	65.8%
393	44	19	2	89.5%	80	7	91.3%	19	8	57.9%	79	23	70.9%
417		15	1	93.3%	54	9	83.3%	14	0	100.0%	51	1	98.0%
425	36	15	1	93.3%	54	2	96.3%	15	1	93.3%	54	2	96.3%
448		19	8	57.9%	21	9	57.1%	18	8	55.6%	19	8	57.9%
449		18	1	94.4%	18	1	94.4%	18	3	83.3%	18	3	83.3%
470	86	16	5	68.8%	58	10	82.8%	15	3	80.0%	57	10	82.5%
471		15	1	93.3%	54	1	98.1%	15	0	100.0%	54	0	100.0%
473		15	0	100.0%	57	3	94.7%	15	0	100.0%	57	1	98.2%
474		15	5	66.7%	55	18	67.3%	14	7	50.0%	51	18	64.7%
475		15	0	100.0%	57	0	100.0%	15	0	100.0%	57	1	98.2%
478		15	2	86.7%	55	12	78.2%	15	0	100.0%	55	6	89.1%
479		15	3	80.0%	57	7	87.7%	15	1	93.3%	57	2	96.5%
486		15	1	93.3%	58	8	86.2%	15	4	73.3%	57	10	82.5%
490		15	1	93.3%	34	6	82.4%	15	0	100.0%	34	2	94.1%
494		15	0	100.0%	59	9	84.7%	15	4	73.3%	56	11	80.4%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
495		15	0	100.0%	57	2	96.5%	15	0	100.0%	57	1	98.2%
500		19	1	94.7%	80	6	92.5%	19	4	78.9%	79	9	88.6%
502		19	1	94.7%	80	7	91.3%	19	3	84.2%	79	19	75.9%
503	62	19	3	84.2%	77	11	85.7%	19	7	63.2%	76	22	71.1%
504		19	2	89.5%	80	7	91.3%	19	6	68.4%	80	25	68.8%
505		19	3	84.2%	80	13	83.8%	19	4	78.9%	78	17	78.2%
506		19	4	78.9%	79	13	83.5%	19	3	84.2%	78	12	84.6%
507		19	2	89.5%	80	9	88.8%	19	6	68.4%	80	28	65.0%
508		19	4	78.9%	78	15	80.8%	19	7	63.2%	78	20	74.4%
509		19	2	89.5%	80	6	92.5%	19	8	57.9%	80	21	73.8%
511		19	2	89.5%	80	6	92.5%	19	4	78.9%	80	16	80.0%
516		17	0	100.0%	78	9	88.5%	17	4	76.5%	78	32	59.0%
517		19	0	100.0%	80	1	98.8%	19	8	57.9%	79	30	62.0%
518		19	0	100.0%	80	13	83.8%	19	10	47.4%	80	46	42.5%
519		17	1	94.1%	78	4	94.9%	17	4	76.5%	78	13	83.3%
520	Cncld	15	5	66.7%	53	8	84.9%	13	1	92.3%	51	3	94.1%
521		15	0	100.0%	56	0	100.0%	15	1	93.3%	56	4	92.9%
522		15	5	66.7%	56	9	83.9%	14	1	92.9%	55	5	90.9%
523		15	0	100.0%	56	0	100.0%	15	4	73.3%	56	8	85.7%
524		15	0	100.0%	56	2	96.4%	15	1	93.3%	56	4	92.9%
525		15	2	86.7%	56	3	94.6%	14	1	92.9%	55	6	89.1%
526		15	4	73.3%	56	10	82.1%	14	2	85.7%	55	6	89.1%
527		15	0	100.0%	56	1	98.2%	15	1	93.3%	56	3	94.6%
528		15	1	93.3%	56	6	89.3%	15	2	86.7%	56	12	78.6%
529		15	0	100.0%	56	3	94.6%	15	3	80.0%	56	10	82.1%
530		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
531		15	0	100.0%	56	1	98.2%	15	3	80.0%	56	6	89.3%
532		15	2	86.7%	56	3	94.6%	15	1	93.3%	56	8	85.7%
534		15	1	93.3%	53	6	88.7%	15	2	86.7%	53	5	90.6%
536	11	15	4	73.3%	56	8	85.7%	13	2	84.6%	54	3	94.4%
537		15	2	86.7%	56	5	91.1%	13	1	92.3%	54	2	96.3%
538		15	1	93.3%	56	7	87.5%	15	4	73.3%	56	9	83.9%
539	60	10	1	90.0%	10	1	90.0%	10	7	30.0%	10	7	30.0%
540		15	3	80.0%	56	7	87.5%	14	1	92.9%	53	2	96.2%
541		15	4	73.3%	56	9	83.9%	15	4	73.3%	56	15	73.2%
542		15	1	93.3%	56	4	92.9%	15	1	93.3%	55	11	80.0%
543		15	0	100.0%	56	6	89.3%	15	1	93.3%	56	13	76.8%
544		15	2	86.7%	55	4	92.7%	15	3	80.0%	55	7	87.3%
545		15	2	86.7%	56	6	89.3%	15	1	93.3%	55	5	90.9%
547	28	15	0	100.0%	56	4	92.9%	15	3	80.0%	56	10	82.1%
548		15	2	86.7%	56	10	82.1%	15	1	93.3%	56	6	89.3%
549		15	3	80.0%	53	13	75.5%	13	0	100.0%	50	6	88.0%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
550		10	2	80.0%	10	2	80.0%	10	1	90.0%	10	1	90.0%
551		14	1	92.9%	55	7	87.3%	14	1	92.9%	53	7	86.8%
562		19	3	84.2%	78	11	85.9%	19	3	84.2%	77	9	88.3%
564		19	1	94.7%	78	7	91.0%	18	2	88.9%	74	12	83.8%
566		19	1	94.7%	78	6	92.3%	19	2	89.5%	75	8	89.3%
572		19	1	94.7%	77	7	90.9%	19	0	100.0%	76	14	81.6%
573		19	2	89.5%	78	11	85.9%	18	0	100.0%	76	8	89.5%
577		19	1	94.7%	76	6	92.1%	19	4	78.9%	72	6	91.7%
580		19	0	100.0%	78	2	97.4%	19	1	94.7%	78	8	89.7%
581		19	0	100.0%	78	7	91.0%	19	2	89.5%	78	14	82.1%
582	30	19	2	89.5%	78	6	92.3%	19	2	89.5%	76	6	92.1%
586		19	5	73.7%	78	16	79.5%	18	1	94.4%	74	10	86.5%
587		19	0	100.0%	78	3	96.2%	18	0	100.0%	75	9	88.0%
591		19	0	100.0%	78	1	98.7%	18	1	94.4%	77	7	90.9%
593		19	3	84.2%	78	12	84.6%	17	1	94.1%	70	6	91.4%
595		19	2	89.5%	77	16	79.2%	19	1	94.7%	76	11	85.5%
600		15	1	93.3%	57	2	96.5%	15	1	93.3%	57	5	91.2%
601		15	12	20.0%	57	31	45.6%	15	2	86.7%	57	15	73.7%
605		15	13	13.3%	57	34	40.4%	15	3	80.0%	56	5	91.1%
607		15	1	93.3%	57	4	93.0%	15	3	80.0%	56	4	92.9%
609		15	3	80.0%	56	4	92.9%	15	1	93.3%	56	4	92.9%
620		15	6	60.0%	56	15	73.2%	15	1	93.3%	54	3	94.4%
624		15	5	66.7%	57	15	73.7%	14	4	71.4%	57	13	77.2%
639		15	6	60.0%	57	16	71.9%	15	2	86.7%	57	6	89.5%
640	23	15	2	86.7%	57	4	93.0%	15	11	26.7%	57	29	49.1%
641		15	6	60.0%	57	11	80.7%	15	4	73.3%	57	11	80.7%
642		15	2	86.7%	56	4	92.9%	15	2	86.7%	56	6	89.3%
643		15	6	60.0%	57	13	77.2%	15	5	66.7%	56	8	85.7%
644	12	15	5	66.7%	57	10	82.5%	15	7	53.3%	57	12	78.9%
645		15	4	73.3%	57	7	87.7%	15	5	66.7%	57	11	80.7%
646		15	6	60.0%	57	13	77.2%	15	11	26.7%	56	31	44.6%
647		15	4	73.3%	57	6	89.5%	15	2	86.7%	57	14	75.4%
648		15	5	66.7%	57	11	80.7%	15	5	66.7%	57	9	84.2%
649		15	4	73.3%	57	10	82.5%	15	2	86.7%	56	9	83.9%
650		15	4	73.3%	57	13	77.2%	15	7	53.3%	57	14	75.4%
651		15	0	100.0%	57	5	91.2%	15	4	73.3%	57	17	70.2%
652		15	4	73.3%	57	12	78.9%	15	4	73.3%	56	12	78.6%
653	18	15	3	80.0%	57	11	80.7%	15	3	80.0%	57	17	70.2%
654		15	7	53.3%	57	12	78.9%	15	3	80.0%	57	5	91.2%
655	38	15	5	66.7%	55	17	69.1%	15	7	53.3%	54	15	72.2%
656		15	5	66.7%	57	12	78.9%	15	0	100.0%	57	5	91.2%
657		15	0	100.0%	57	3	94.7%	15	1	93.3%	57	10	82.5%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
658		15	1	93.3%	57	8	86.0%	15	3	80.0%	57	9	84.2%
680		15	0	100.0%	58	2	96.6%	15	4	73.3%	58	7	87.9%
681		15	1	93.3%	58	3	94.8%	15	4	73.3%	58	17	70.7%
682		15	0	100.0%	58	0	100.0%	15	3	80.0%	58	13	77.6%
683		15	0	100.0%	41	3	92.7%	15	3	80.0%	41	12	70.7%
684	24	15	2	86.7%	40	6	85.0%	15	4	73.3%	40	12	70.0%
685		15	2	86.7%	57	6	89.5%	15	2	86.7%	57	15	73.7%
686		15	2	86.7%	58	15	74.1%	15	4	73.3%	58	14	75.9%
687		15	2	86.7%	58	8	86.2%	15	5	66.7%	58	11	81.0%
688		15	0	100.0%	58	1	98.3%	15	2	86.7%	58	14	75.9%
689		11	1	90.9%	47	5	89.4%	10	1	90.0%	46	4	91.3%
701		12	3	75.0%	12	3	75.0%	12	2	83.3%	12	2	83.3%
702		19	2	89.5%	80	17	78.8%	19	3	84.2%	79	22	72.2%
703	No OS	19	3	84.2%	80	18	77.5%	19	5	73.7%	80	21	73.8%
704		12	3	75.0%	12	3	75.0%	11	3	72.7%	11	3	72.7%
710		19	7	63.2%	80	31	61.3%	19	2	89.5%	80	30	62.5%
711		19	3	84.2%	76	7	90.8%	16	3	81.3%	69	10	85.5%
712		19	4	78.9%	80	21	73.8%	19	5	73.7%	79	28	64.6%
713	108	18	3	83.3%	79	12	84.8%	14	5	64.3%	69	32	53.6%
714	116	19	8	57.9%	74	27	63.5%	19	6	68.4%	69	22	68.1%
715		19	5	73.7%	80	27	66.3%	17	9	47.1%	75	38	49.3%
716	110	19	10	47.4%	80	33	58.8%	19	11	42.1%	79	34	57.0%
717	50	19	4	78.9%	71	17	76.1%	19	9	52.6%	66	22	66.7%
718	46	19	13	31.6%	80	35	56.3%	18	8	55.6%	79	24	69.6%
719	19	19	4	78.9%	80	28	65.0%	19	7	63.2%	78	23	70.5%
761	17	19	0	100.0%	78	3	96.2%	19	1	94.7%	78	10	87.2%
765		19	1	94.7%	78	8	89.7%	19	1	94.7%	78	14	82.1%
769		19	1	94.7%	78	5	93.6%	19	1	94.7%	76	12	84.2%
770		19	0	100.0%	78	7	91.0%	19	1	94.7%	78	10	87.2%
774		19	0	100.0%	78	6	92.3%	19	4	78.9%	77	15	80.5%
779	21	19	0	100.0%	78	4	94.9%	19	2	89.5%	77	11	85.7%
784	32	19	2	89.5%	78	8	89.7%	19	11	42.1%	77	40	48.1%
785		19	0	100.0%	78	0	100.0%	19	3	84.2%	78	10	87.2%
790		19	0	100.0%	78	5	93.6%	19	3	84.2%	78	10	87.2%
794	145	19	1	94.7%	78	6	92.3%	19	4	78.9%	77	14	81.8%
821		19	0	100.0%	80	3	96.3%	19	6	68.4%	80	46	42.5%
822		19	0	100.0%	80	3	96.3%	19	2	89.5%	80	46	42.5%
1105		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1106		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1333	20	19	4	78.9%	80	8	90.0%	19	8	57.9%	79	34	57.0%
1340		19	0	100.0%	80	3	96.3%	19	7	63.2%	80	20	75.0%
2103		15	1	93.3%	56	4	92.9%	15	3	80.0%	56	4	92.9%

Amtrak On Time Performance

Trains Arriving Through: 12/19/2025

28-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2104	116	15	4	73.3%	27	6	77.8%	15	3	80.0%	27	5	81.5%
2107		15	4	73.3%	57	11	80.7%	15	4	73.3%	55	4	92.7%
2108		15	3	80.0%	57	5	91.2%	15	2	86.7%	55	2	96.4%
2117	114	15	5	66.7%	27	8	70.4%	15	5	66.7%	27	6	77.8%
2121	60	15	4	73.3%	55	7	87.3%	15	3	80.0%	55	6	89.1%
2122		15	1	93.3%	57	7	87.7%	15	1	93.3%	57	4	93.0%
2130		3	1	66.7%	13	1	92.3%	3	0	100.0%	13	2	84.6%
2150	Cncld	15	3	80.0%	57	12	78.9%	13	3	76.9%	55	12	78.2%
2151	18	15	0	100.0%	57	0	100.0%	15	6	60.0%	56	12	78.6%
2152	90	15	1	93.3%	53	3	94.3%	15	11	26.7%	52	20	61.5%
2153	67	15	1	93.3%	57	7	87.7%	15	4	73.3%	57	13	77.2%
2154	40	15	3	80.0%	57	17	70.2%	15	8	46.7%	55	29	47.3%
2155	18	15	1	93.3%	57	3	94.7%	15	9	40.0%	55	18	67.3%
2159		15	0	100.0%	56	1	98.2%	15	6	60.0%	56	13	76.8%
2162		15	0	100.0%	57	2	96.5%	15	4	73.3%	56	13	76.8%
2163	33	15	0	100.0%	57	4	93.0%	15	6	60.0%	57	16	71.9%
2166		15	1	93.3%	57	6	89.5%	15	4	73.3%	55	10	81.8%
2168		15	2	86.7%	57	4	93.0%	15	1	93.3%	57	7	87.7%
2169	94	15	10	33.3%	53	20	62.3%	15	12	20.0%	53	27	49.1%
2170	127	15	4	73.3%	57	11	80.7%	15	4	73.3%	57	13	77.2%
2172		15	0	100.0%	57	6	89.5%	15	3	80.0%	57	10	82.5%
2173		15	4	73.3%	56	11	80.4%	15	3	80.0%	56	21	62.5%
2190		15	3	80.0%	57	8	86.0%	14	2	85.7%	56	6	89.3%
2193	51	15	1	93.3%	56	2	96.4%	15	6	60.0%	56	15	73.2%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2104	NYP	116	CAR	126	CAR	126	WAS-WAS	AM	Air / Brake / Wheel, .ALL, LATE RELEASE FROM THE HSR
2117	WAS	114	ITI	104	ITI	104	NYP-NYP	AM	Service, turn, or wye train, 2104, LATE TURN OFF FOR AM2104
2121	WAS	60	ITI	45	ITI	45	NYP-NYP	AM	Service, turn, or wye train, 2108
2150	XHM	Trn Cancelled							
2151	WAS	18	OTH	12	OTH	9	XSH-NYP	AM	Lost time - N.A.R.
2152	BOS	90	DBS	27	DBS	27	STM-STM	MN	Debris strike Other, STM
2153	WAS	67	ENG	37	ENG	37	WIL-WIL	AM	Other electrical failure, 2116, loose cable power
2154	BOS	40	CTI	8	DET	8	NYP-XSH	AM	Catenary maintenance , Other, XGG, HELD A/C SINGLE TRACKING MANOR-LEGGET A/C EMERGENCY AC PLATE AT LEGGET (DET)
2155	WAS	18	DET	12	DET	12	XSH-NYP	AM	Catenary maintenance , Other, XM9-XGG, SINGLE TRACKING MANOR-LEGGET A/C EMERGENCY AC PLATE AT LEGGET (DET)
2163	WAS	33	WTR	19	WTR	11	PHL-WIL	AM	High winds, Control Point, Phil - Baldwin, Held for North Bound Amtrak Opr No.2 trk a/c Septa No.3 trk. No.4 trk o/s down wires
2169	WAS	94	ITI	77	ITI	77	BOS-BOS	AM	Service, turn, or wye train, 2152, departed late due to late turn of AM2152 BOS
2170	BOS	127	DET	99	DET	99	NYP-NYP	AM	Catenary failure, Other, NYP, STUCK IN STATION A/C EMERGENCY AC PLATE
2193	NYP	51	CAR	48	CAR	48	XNH-STM	MN	Onboard HBD alarm 3406
84	NYP	26	DSR	8	PTI	8	NWK-NYP	AM	Follow, 97, Other, XPT-NYP
86	BOS	25	CTI	20	PTI	8	PHL-PHL	AM	Meet, 2162, Control Point, ., held for 2162 ahead.
94	BOS	40	SYS	48	SYS	48	NHV-NHV	AM	Crew rest, AM94 was held for late AM175 crew
95	NFK	24	CTI	33	CTI	20	WDB-FBG	CS	Follow VRE, 407, Control Point, Featherstone
110	NYP	79	ENG	79	ENG	79	XHM-NWK	AM	Other electrical failure, 648, STOPPED BETWEEN ADAMS AND DELCO A/C TRAILING BRAKE UNIT FAULT
119	WAS	27	CTI	14	CTI	14	BAL-BWI	AM	Follow, MARC, 435, Milepost, 95.7, 106.3

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
137	WAS	69	ITI	77	ITI	77	BOS-BOS	AM	Service, turn, or wye train, 190, departed late due to late turn of AM190 BOS
138	NYP	17	ENG	12	ENG	12	RVR-RVR	CS	Air / Brake Brakes would not release on locomotive., 79
170	BOS	116	RTE	46	RTE	46	NRO-BRP	MN	Dispatcher hold Control Point, 232
172	BOS	60	HLD	21	DCS	18	BBY-BBY	AM	T.O.L, Other, BBY, Held at COVE for TOL in Tower 1
173	WAS	25	OTH	15	DCS	14	BOS-BOS	AM	T.O.L, Milepost, BOS, BOS, Tower 1 maintainer reports the reason for the TOL over the 1091sw is being caused by a bad I joint
175	WAS	181	ITI	109	ITI	109	BOS-BOS	AM	Service, turn, or wye train, 170, departed late due to late turn of AM170 BOS
178	BOS	24	DCS	23	DCS	14	BRP-NHV	MN	Another train went into emergency Control Point, 261
185	WAS	109	ITI	92	ITI	92	NYP-NYP	AM	Service, turn, or wye train, 110, LATE TURN OFF FOR AM110
190	BOS	47	CTI	21	ENG	10	NLC-NLC	AM	Other electrical failure, 663, stop at NLC a/c unable to reset the asces breaker and will be limited to 79mph.
193	WAS	37	ITI	21	ITI	21	NYP-NYP	AM	Service, turn, or wye train, 134
425	SPG	36	ITI	41	ITI	41	GFD-GFD	MA	Train 5552 held for a bridge strike turns for train 425 5552
470	SPG	86	CON	90	CON	88	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM170
640	NYP	23	PTI	18	PTI	16	CWH-TRE	AM	Cross over or go around, AM170, Other, CWH-TRE, OPR NO.1 TRK A/C DELAYED AM170 ON NO.2 TRK
644	NYP	12	CTI	6	CTI	6	NWK-NYP	AM	Follow, NJT, NJ6222, Other, SWIFT-NYP
653	HAR	18	WTR	10	WTR	8	MID-HAR	AM	High winds, Control Point, ,, Received 241 a/c TOLs power loss
655	HAR	38	SYS	33	SYS	33	NYP-NYP	AM	Other late crew, LATE FROM SSYD A/C WAITING FOR CREW OFF AM84
684	BON	24	DCS	26	DCS	18	HHL-WOB	MT	Power switch failure Control Point, Vale
63	TWO	57	ADA	24	ADA	24	NYP-NYP	AM	Mobility Impaired, ADA PSNGR BOARDING
64	ALB	25	WTR	36	WTR	15	BUF-ROC	CS	High winds Control Point, 431
68	NYP	78	DCS	72	DCS	52	RSP-RSP	DH	PTC system failure (wayside) Control Point, 191

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
237	ALB	61	DBS	37	DBS	37	NYP-XSD	AM	Debris blocking track (no debris strike), Other, XSD, HELD AT XIW A/C DOWN TREE ON MNRR
290	NYP	39	CTI	39	CTI	19	CRT-YNP	MN	Meet metronorth, Control Point, 25
49	CHI	61	SYS	45	SYS	28	BUF-BUF	CS	PTC problem or failure (cause unknown) PTC had to be recycled due to not initializing. Kept coming up as a problem with the consist., Other, BUF station
73	CLT	21	ADA	13	PTI	9	RGH-CYN	NS	Meet #AMT40, Control Point, Boylan
98	NYP	111	PTI	108	RTE	75	MIA-HOL	FL	Dispatcher hold Held 50 min Amtrak Mia, 25 min at Tompkins for Trirail traffic P611, P613, P615 due to Trirail and vehicle strike, Other, Mia Amtrak, Control Point, Tompkins
41	MIA	225	ITI	92	ITI	77	CHI-CHI	AM	Service, turn, or wye train 40, Train 40 arrived in CHI at 346 P
5	EMY	46	WTR	134	WTR	60	MCK-FMG	BN	High winds Restricted to 40MPH, Milepost, 366, 447
520	SAC	Trn Cancelled							
536	SAC	11	PTI	17	PTI	17	DAV-SAC	UP	Wait for station track 545, Control Point, W SAC
539	SJC	60	TRS	55	TRS	55	SAC-DAV	UP	Vehicle on track ahead Milepost, 79.2, 79.2
547	SJC	28	PTI	15	TEN	14	SAC-DAV	UP	PTC - On Board Cab Signal or PTC Failure When taken off the loco AMP's are shooting up and PTC is putting the train into penalty-code "D11", 2003
50	NYP	49	FTI	73	FTI	27	STA-CVS	BB	Meet e111-16, empty coal, Siding, afton
503	EUG	62	DMW	47	DMW	47	CTL-CTL	BN	Unable to contact dispatcher / MW foreman Unable to contact form B 5016 Forman Morris, Other, CTL
7	SEA	367	FTI	323	FTI	98	MAL-HAV	BN	Blocked from station track bn 3274, Siding, have east
8	CHI	No OS Rpt	ITI	630	ITI	630	SEA-SEA	BN	Service, turn, or wye train 007
27	PDX	-7	FTI	28	DCS	10	PSC-WIH	BN	Slide fence restriction due to false actuation or out of service Restricted speed, Milepost, 147.1, 139.0
334	CHI	14	CTI	6	CTI	6	X9L-CHI	AM	Cross Traffic Stopped at Lake; two Metras exiting CUS, Metra, Control Point, Lake

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
335	MKE	44	CCR	17	CCR	17	MKA-MKE	CP	Undesired emergency application 90200, Mechanical did not lock seat; it swung around and hit the emergency brake. Walked the set, did a class 2, a roll-by, and a running brake test.
338	CHI	62	ITI	34	ITI	34	MKE-MKE	CP	Service, turn, or wye train 335, 335 in late due to numerous issues
339	MKE	49	ITI	40	ITI	40	CHI-CHI	AM	Service, turn, or wye train 338
350	PNT	32	PTI	47	PTI	29	XB0-XA5	MI	Meet 353, Siding, Albion
364	PTH	42	CAR	52	CAR	52	CHI-CHI	AM	Set out defective car ID4305, 2 cars replaced
371	CHI	38	DCS	36	DCS	34	SJM-XPI	CS	Issue with automatic road crossing protection Waited at West End new buffalo for maintainer until given permission to safely handle crossing guard gate, Milepost, 125.2, 125.2
582	SAN	30	POL	41	POL	41	SNC-X98	SC	Held out for 785's passenger removal with local police
761	SLO	17	FTI	21	FTI	21	LPS-GUA	UP	Meet up, Milepost, 273, 273
779	SLO	21	HLD	29	HLD	27	GTA-X3G	UP	Passenger medical emergency
784	SAN	32	PTI	22	PTI	22	SNC-SNP	SC	Meet amtk 587, Control Point, serra
794	SAN	145	CTI	119	CTI	97	VEC-OXN	UP	Waiting for metrolink 118s incident to clear the backlog of trains metrolink, 118, Siding, Ventura
703	SAC	No OS Rpt	PTI	14	PTI	7	WAC-COC	BN	Meet AM 714, Siding, Sandrini
713	EMY	108	PTI	39	PTI	24	SKN-ACA	BN	Meet AMTK 714, Control Point, west Sando
714	BFD	69	POL	62	POL	62	WAC-WAC	BN	Right of Way police hold Car on tracks @ Shafter
716	BFD		TEN	135	TEN	135	EMY-EMY	UP	Waited for train 713 to arrive in Oakland yard due to no train set because of bad order loco No train set due to loco bad order., C2106
717	OKJ	50	PTI	58	PTI	22	SKN-ACA	BN	Meet 718, Control Point, w sando
718	BFD	4	FTI	32	FTI	14	COC-WAC	BN	Follow bnsf e, Other, COC-allensworth
719	OKJ	19	FTI	18	FTI	18	WAC-COC	BN	Meet bnsf 7270, Siding, allensworth
3	LAX	336	WTR	125	SYS	78	FLG-KNG	BN	Re-crew / job briefing Dispatch had train stopped here while they banned over dog catch crew, Milepost, 491.0, 491.2
4	CHI	83	PTI	68	PTI	68	LMY-LSV	BN	Meet AMTK # 3, Siding, BLANCHARD

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/19/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
300	CHI	64	CAR	79	CAR	79	STL-STL	TR	Air / Brake / Wheel ID4317, Ice in Brake Line Swapped train sets with 302
301	STL	29	POL	33	POL	33	BNL-SPI	UP	Right of Way police hold Car accident near tracks. MP 184. All rail traffic stopped. Per Dispatcher
305	STL	27	DCS	21	DCS	21	PON-BNL	UP	Wayside detector failure including false actuation Milepost, 104.3, 115.1
306	CHI	21	FTI	21	FTI	11	CRV-SPI	UP	Signal not working at MP 183 N/A, Milepost, 183, 183
380	CHI	37	DCS	24	DCS	24	GBB-KEE	BN	Power switch failure Train coordination between us and the maintainers, talked by stop signal and put 1B on hand, Control Point, Bishop
382	CHI	43	FTI	60	FTI	39	MAC-GBB	BN	Meet bnsf 7894, Control Point, waterman, Control Point, knox
383	QCY	No OS Rpt	CTI	9	CTI	6	LAG-NPV	BN	Follow metra, Control Point, east npv
392	CHI	19	DSR	21	DSR	13	MAT-CHM	CC	Per bulletin Milepost, 170, 165, 60, main, Milepost, 155.84, 155.84, 60, main, Milepost, 148.3, 141.6, 25, main
393	CDL	44	DSR	37	FTI	34	CHM-MAT	CC	3 way meet Behind m334 wait on 392 back out, m334, amtk392, Siding, tolongo
318	CHI	32	FTI	33	DCS	18	BNL-PON	UP	Wayside detector failure including false actuation Dispatcher reduced speed to 30mph. Hot bearing detector false train 21 had same read. Next detector no defect, Other, Mp104.6
1333	MSP	20	POL	21	POL	21	XWA-GLN	ME	Car on tracks, waiting for car to clear before proceeding

Amtrak Initial Terminal Details

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/19/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	624	12/19	5	5	High winds, Control Point, ., Received 241 a/c TOLs power loss
HAR	650	12/19	1		
HAR	652	12/19	1		
NFK	94	12/19	3	3	Mobility Impaired Reversed Car Business & Quiet in front Last minute Business Class passenger needed wheelchair ride to business class
NOL	24	12/19	1	1	Lost time - N.A.R. Left on time with No Lost time
NPN	186	12/19	5	5	Hold for thruway bus Per CNOC.
PHL	601	12/19	2	2	Passenger and/or baggage, LATE TRAVEL
WAS	170	12/19	2	2	Water, commissary, toilet/trash dumping, Loaded stock on yard equipment and had to wait for consist to drop back to the station to load correctly
WAS	176	12/19	34	33	Disabled train ahead, Control Point, WAS, 110 DELAYED DUE TO BRAKE ISSUES ON LOCO 648 WHICH CAUSED LATE TURN OF EQUIP FOR 185 OUT OF NYP. RESULTING IN LATE TURN FOR 176 IN WAS
WAS	184	12/19	1		
WAS	2104	12/19	126	126	Air / Brake / Wheel, .ALL, LATE RELEASE FROM THE HSR
WAS	2108	12/19	15	15	Set out defective car, ., LAST MINUTE TURN SWAP WITH 2107. NEC'Y TO WYE
WAS	2150	12/19	(Trn Cxld)		Equipment Issues
WAS	2170	12/19	10	10	Service, turn, or wye train, 2153, LATE TURN
ALB	69	12/19	26		
BOS	137	12/19	77	77	Service, turn, or wye train, 190, departed late due to late turn of AM190 BOS
BOS	173	12/19	14	14	T.O.L, Milepost, BOS, BOS, Tower 1 maintainer reports the reason for the TOL over the 1091sw is being caused by a bad I joint
BOS	175	12/19	109	109	Service, turn, or wye train, 170, departed late due to late turn of AM170 BOS
BOS	2153	12/19	4	4	Door, 3653, ISSUE WITH CAFE DOOR C/3653
BOS	2169	12/19	77	77	Service, turn, or wye train, 2152, departed late due to late turn of AM2152 BOS
GFD	425	12/19	41	41	Train 5552 held for a bridge strike turns for train 425 5552
NHV	470	12/19	90	88	Hold for connecting train, departed late due to late connection of AM170
NHV	470	12/19	90	2	Hold for connecting train, departed late due to late connection of AM170
NHV	470	12/19	90	88	Hold for connecting train, departed late due to late connection of AM170
NHV	470	12/19	90	2	Hold for connecting train, departed late due to late connection of AM170
NYP	51	12/19	5	5	Water, commissary, toilet/trash dumping, DELAYED F/SSYD A/C LATE CATERING

Amtrak Initial Terminal Details

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/19/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	63	12/19	24	24	Mobility Impaired, ADA PSNGR BOARDING
NYP	79	12/19	5	5	Mobility Impaired, LAST MIN ADA PSNGR
NYP	97	12/19	14	14	Door, N/A, LATE FROM SSYD A/C DOOR BYPASS ISSUES AT LEAVING TIME
NYP	119	12/19	9	9	Service, turn, or wye train, 644, LATE TURN OFF AM644
NYP	129	12/19	9	9	Service, turn, or wye train, 114
NYP	133	12/19	2	2	Passenger and/or baggage, BOARDING
NYP	183	12/19	6	6	Door, 81502 82548 82544 43373 82506 , DOOR ISSUES IN STATION
NYP	185	12/19	92	92	Service, turn, or wye train, 110, LATE TURN OFF FOR AM110
NYP	193	12/19	21	21	Service, turn, or wye train, 134
NYP	197	12/19	9	9	Service, turn, or wye train, 84
NYP	239	12/19	5	5	Passenger and/or baggage, BOARDING
NYP	283	12/19	6	6	Passenger and/or baggage, BOARDING
NYP	639	12/19	5	5	Service, turn, or wye train, 654
NYP	643	12/19	6	6	Service, turn, or wye train, 640, LATE TURN OFF AM640
NYP	647	12/19	4	4	Service, turn, or wye train, 648, LATE TURN OFF AM648
NYP	655	12/19	33	33	Other late crew, LATE FROM SSYD A/C WAITING FOR CREW OFF AM84
NYP	2117	12/19	102	104	Service, turn, or wye train, 2104, LATE TURN OFF FOR AM2104
NYP	2121	12/19	45	45	Service, turn, or wye train, 2108
CDL	392	12/19	7	7	Inability to contact dispatcher No TGBO, unable to get train out of the rock track., Other, CDL station
CHI	21	12/19	6	6	High passenger count
CHI	41	12/19	50	50	Toilet 62034, 62518
CHI	48	12/19	225	225	Traction motor Bad order engine .. replacing second unit with engine 142 off train 6 (17) .., 107
CHI	59	12/19	158	158	59 CHI xxx car at 604PM, sleeping car/32072 BO'D for freeze damaged and replaced with sleeping C/32070 32070
CHI	307	12/19	52	52	Door 4203, Having trouble with door relay Had to cut it out per foreman Tate
CHI	335	12/19	10	10	Routine inspections Mechanical dropped flags late. The air compressor on 4618 was overheating due to a low oil level. They topped it off, making the daily mechanical inspection take longer.
CHI	339	12/19	40	40	Service, turn, or wye train 338
CHI	364	12/19	52	52	Set out defective car ID4305, 2 cars replaced

Amtrak Initial Terminal Details

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/19/2025

Terminal	Train	Date	Late	Delay	Cause
EUG	508	12/19	1	1	Platform construction.
MKE	338	12/19	34	34	Service, turn, or wye train 335, 335 in late due to numerous issues
MKE	342	12/19	10	10	Service, turn, or wye train 339
PDX	28	12/19	114	114	Late arrival of train 27. Had to wye equipment and service it
SEA	8	12/19	299	299	Service, turn, or wye train 7, Late arrival Train 7
SPK	8	12/18	45	45	Hold for bus with passengers from train
STL	300	12/19	79	79	Air / Brake / Wheel ID4317, Ice in Brake Line Swapped train sets with 302
BFD	719	12/19	7	7	Hold for thruway bus
EMY	714	12/19	48		
EMY	716	12/19	135	135	Waited for train 713 to arrive in Oakland yard due to no train set because of bad order loco No train set due to loco bad order., C2106
EMY	718	12/19	32		
LAX	572	12/19	1	1	Door 6803, Door stuck in pocket
OKJ	520	12/19	(Trn Cxld)		Engine Issue
OKJ	536	12/19	2	2	Water, commissary, toilet/trash dumping Late out of yard waiting for commissary, Other, yard
SAN	595	12/19	3	3	Service, turn, or wye train 784

Eastern Region

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	94.8	No Data	No Data
CDOT	95.0	No Data	No Data	92.4	No Data	No Data
MARC	95.0	96.6	88.1	90.2	58	2
SEPTA	95.0	96.2	94.7	91.5	210	8
NJT-NED	95.0	No Data	No Data	93.8	No Data	No Data
NJT-SED	95.0	100	99.1	97.2	22	0

Operating Highlights

Train 2193(19) East of Stamford, CT - Car Failure

19DEC25: Acela 2193(19) operating with power car 2024, 6 cars, and power car 2021 was delayed 7 miles east of Stamford, CT on the Metro North New Haven Line holding at milepost 40.5 for a hot journal alarm on car 3406. The crew was in contact with Amtrak management and was advised to cut out the monitoring system on the car. Train 2193(19) was capped at 80 mph to New York, NY.

Train	Delay	Comment
2193(19)	48"	

Train 89(19) South of Kingstree, SC - Freight Train Interference

19DEC25: Train 89(19) operating with engine 317 and 8 cars was delayed 19 miles south of Kingstree, SC on the CSX Charleston subdivision meeting CSX M410 and CSX IO30 at milepost 352.5.

Train	Delay	Comment
89(19)	40"	

Train 94(19) New Haven, CT - Recrew

19DEC25: Train 94(19) operating with engine 604 and 8 cars was delayed departing New Haven, CT waiting on fresh crew from inbound 175(19) which arrived into New Haven, CT 7:58 p.m. operating 2 hours and 14 minutes late.

Train	Delay	Comment
94(19)	48"	

Train 40(18) West of Harpers Ferry, WV - Engine Failure

19DEC25: Train 40(18) operating with engines 327, 330, and 10 cars was delayed 8 miles west of Harpers Ferry, WV on the CSX Cumberland subdivision holding at milepost 89.5 due to PTC issues on engine 327 causing a penalty. The crew was able to cut out cab signals and proceed west.

Train	Delay	Comment
40(18)	34"	

Train 138(19) Washington D.C. - Engine Failure

19DEC25: Train 138(19) operating with engine 669 and 2 cars was delayed departing Washington D.C. due to inbound diesel engine 79 having a broken air hose which caused the engine to be towed off with other equipment before engine 669 could be added.

Train	Delay	Comment
138(19)	33"	

Train 655(19) New York, NY - Servicing

19DEC25: Train 655(19) operating with engine 662, 4 cars, and cab car 9644 was delayed departing New York, NY due to a late release of equipment from Sunnyside Yard.

Train	Delay	Comment
655(19)	33"	

Train 2170(19) New York, NY - Catenary or Wayside Failure

19DEC25: Train 2170(19) operating with power car 2117, 9 vehicles, and power car 2116 was delayed departing New York Penn Station due to an emergency AC plate in effect from track 14-18 due to debris in the catenary that caused arcing. 2170(19) deboarded 346 passengers who were fare protected and awaited ET to resolve the issue. Once the scene was clear, train 2170(19) boarded passengers who wanted to continue travel north and departed New York, NY.

Train	Delay	Comment
2170(19)	1'39"	

Train 40(19) Tampa, FL - Passenger Train Interference

19DEC25: Train 40(19) operating with engines 170, 150, and 10 cars was delayed arriving into Tampa, FL station on the CSX Tampa Terminal subdivision waiting for station track that was occupied by 41(17).

Train	Delay	Comment
40(19)	32"	

Train 237(19) North of New York, NY - Debris

19DEC25: Train 237(19) operating with engine 717, 5 cars, and engine 132 was delayed 11 miles north of New York, NY on the Metro North Hudson Line at milepost 11.4 holding for maintenance of way to clear a downed tree ahead.

Train	Delay	Comment
237(19)	37"	

Train 175(19) Boston, MA - Signal

19DEC25: Train 175(19) was delayed at MP228.6 Boston, MA. on the Amtrak Dorchester subdivision due to a TOL on the 98 switch at tower 1. Maintainers responded and were able to clear the TOL and return the switch back to normal. Once the switch was normal train 175(19) looped and returned back to Boston, MA. station to load. 175(19) departed Boston, MA station at 504PM ET.

Train	Delay	Comment
175(19)	1'49"	

Train 20(19) North of Laurel, MS - Signal

19DEC25: Train 20(19) 28-FOI-00197100000005538 UNCLASSIFIED Files 12/23/2025 of Laurel, MS/MP56.4, on the NSRR NO&NE Subdivision, due to switch failure at 31st Street. The crew reported having to manually line the switch and then operate restricted speeds starting at Shop/MP5.0 into the Meridian station/MP295.0

Train	Delay	Comment
20(19)	30"	

Train 68(19) Rouses Point, NY - CPKC Outage

19DEC25: Train 68(19) was delayed at Rouses Point, NY/MP191.1, on the CPKC Canadian Subdivision. This was due to CPKC experiencing a systemwide outage with no phones or dispatch screens available. Once the systems were restored, Train 68(19) was able to proceed south.

Train	Delay	Comment
68(19)	52"	

Train 19(18) North of Birmingham, AL - Signal

19DEC25: Train 19(18) was delayed 1 mile north of Birmingham, AL/MP143.0, on the NSRR AGS South Subdivision, due to switch failure at 27th Street/MP142.0. A signal maintainer responded to the location and was able to resolve the switch issue to allow Train 19(18) to enter the station.

Train	Delay	Comment
19(18)	34"	

Train 20(18) North of Charlottesville, VA - Tree Strike

19DEC25: At 11:32AM-ET, Train 20(18), E/324-E/315-9 cars, reported striking a tree 14.5 miles north of Charlottesville, VA/MP112.2, on the NSRR Alexandria-Montview Subdivision, at MP97.7. The strike caused the main reservoir to uncouple between E/324 and E/315 as well as the 480v cable to dislodge between the cafe car 28018 and diner car 68013. Head end power was intermittent while the crew worked in between the cars. There were no injuries to the crew or 214 passengers onboard and no damage to the equipment. Weather at the time was 48 degrees and mostly sunny. The crew was able to reattach all of the cables and restore air the the trainset. At 11:54AM-ET, Train 20(18) was back on the move north.

Train	Delay	Comment
20(18)	24"	

Train 2153(20) Wilmington, DE - Engine Failure

19DEC25: Train 2153(20) was delayed at MP26.8 Wilmington, DE. station on the Amtrak PW Line due to a loose power cable on engine PC2116. Crew contacted high speed technician and was able to fix the loose connection. Train 2153(20) was back on the move at 1252PM ET.

Train	Delay	Comment
2153(20)	37"	

Train 2152(19) Stamford, CT - Signal

19DEC25: Train 2152(19) was delayed at MP23.2, Stamford, CT station on the MNCW New Haven line due to loss of switch indication at CP241. Maintainers responded and were able to establish a route for train 2152(19) to proceed north. Train 170(19) and 2154(19) were also delayed waiting for maintainers to establish the route.

Train	Delay	Comment
2152(19)	44"	
2154(19)	17"	
170(19)	46"	
86(19)	5"	
171(19)	2"	
174(19)	8"	
2159(19)	4"	
2162(19)	3"	
2163(19)	4"	

Train 170(19) New Rochelle, NY - Catenary or Wayside Failure

19DEC25: Train 170(19) was delayed at MP6.0, 9.8 miles south of New Rochelle, NY station on the Amtrak NYS Line due to the emergency plate in effect at CP216 Leggett. The emergency plate created a single track condition delays trains through the area. Maintainers responded and found a broken insulator cap. Cat car responded out of Sunnyside Yard, arrived to scene and repaired the broken insulator cap. Trains 2155(19), 125(19), 2154(19), 95(19), 2153(19), 141(19), 2152(19), 2151(19), and 190(19) were delayed due to the single tracking. Train 470(19) was held at MP72.2 New Haven CT. station for connections off train 170(19).

Train	Delay	Comment
170(19)	17"	
2155(19)	12"	
125(19)	6"	
95(19)	17"	
2154(19)	8"	
2153(19)	6"	
170(19)	13"	
2152(19)	6"	
190(19)	5"	
141(19)	10"	
2151(19)	3"	
470(19)	1'28"	Held connections

Train 41(17) North of Jacksonville, FL - Passenger Train Interference

19DEC25: Train 41(17) was delayed at MP639.0, 4.1 miles north of Jacksonville, FL. station on the CSX Jacksonville Terminal subdivision due to 97(18) occupying the station track. Once 97(18) departed, 41(17) was able to proceed south into Jacksonville station.

Train	Delay	Comment
41(17)	36"	

Train 2104(19) Washington, DC - Initial Terminal Delay

19DEC25: Train 2104(19) was delayed at MP0.3, Washington, DC station on the Amtrak PW line due to mechanical issues with earlier released sets Next Gen 22 and Legacy set 10. Repairs to both sets caused 2104(19)'s next gen set 21 to be released late from the yard. Train 2104(19) departed Washington, DC station at 1006AM ET. Train 2117(19) was delayed departing New York, NY station due to a late turn off of 2104(19). 2117(19) departed New York, NY station at 142PM ET.

Train	Delay	Comment
2104(19)	2'06"	
2117(19)	1'42"	

Train 110(19) South of Newark, NJ - Engine Failure

19DEC25: Train 110(19) at 7:28 AM south of Newark, NJ Penn station on the Amtrak NYP Line due to a trailing unit fault on engine 635. Crew worked with mechanical and isolated the engine. After isolating engine 635, train 110(19) was back on the move at 7:49 AM ET. Train 110(19) came to a stop again at MP33.7, 25.1 miles south of Newark, NJ Penn station due to a parking brake fault. Crew worked with mechanical to replace a brake hose. Once the hose was replaced the crew recycled twice and was able to clear the faults. Train 110(19) was back on the move at 8:44 AM ET. Train 185(19) was delayed departing New York, NY station due to a late turn off of 110(19).

Train	Delay	Comment
110(19)	1'19"	
185(19)	1'32"	Late Turn

Train 425(19) Greenfield, MA - Initial Terminal Delay

19DEC25: Train 425(19) was delayed at MP36.1 Greenfield MA. Station on the CSX Conn River subdivision due a late arrival of dead head equipment off train 5552(19). 5552(19) was delayed at MP7.7 Holyoke, MA. station due to a bridge strike ahead. Once the strike was cleared 5552(19) was able to depart the station and proceed north.

Train	Delay	Comment
425(19)	41"	

26"FOI 00197 00000005568 UNCLASSIFIED

WBS#: B.TR.100150.5989

Train	Delay	Comment
64 (13)	57"	

Eastern Region

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (24)	RMT	326		Vehicle strike DMG//p/up 968 (20) RMT-WAS

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

None

Operating Highlights

Train 503(19) Seattle, WA - M of W Work

19DEC25: Train 503(19) was delayed departing Centralia, WA (CTL) on the Burlington Northern Santa Fe Railway Seattle Subdivision. A Trackwork formman was not responding the the train crew on the radio to grant the crew authority to operate through the limits of a form B. Once the crew was able to obtain authority, train 503(19) was able to depart CTL at 9:52 AM-PT.

Train	Delay	Comment
503(19)	47"	

Train 383(19) East of Quincy, IL - Freight Train Interference

19DEC25: Train 383(19), with 17 passengers, was delayed 20 miles east of Quincy, IL, at milepost 241.9, on BNSF Brookfield subdivision, due to a disabled freight ahead obstructing the route. The disabled freight had a broken brake pipe and a broken knuckle. BNSF mechanical responded to the scene and was able to repair the pipe. After the repair of the broken brake pipe the freight crew ran out of Hour of Service and a recrew was required before the broken knuckle could be addressed.

Due to the length of the delay and the proximity to the Quincy, IL station, train 383(19) reversed 1/4 mile to the crossing to allow passengers who arranged their own transportation to exit the train. All but 1 passenger had arranged their own transportation and a cab was arranged for the last passenger.

Once the freight recrew arrived, they were able to repair the knuckle and get on the move, clearing a route for train 383(19).

Train	Delay	Comment
383(19)	6'00"	estimated delay

Train 785(19) San Clemente Pier, CA - Police Related

19DEC25: Train 785(19) was delayed at San Clemente Pier, CA (SNP) on the Southern California Regional Rail Authority Orange Subdivision. The train crew requested the local sheriff's office to respond and assist with the removal of a disruptive passenger. Once the passenger was removed, train 785(19) was able to proceed, departing SNP at 5:50 PM-PT.

Train	Delay	Comment
785(19)	26"	SNP - Hold for PD
582(19)	41"	

Train 14(19) San Jose, CA - Loss of HEP

19DEC25: Train 14(19), operating with locomotives E/313/345, 9 coaches, and 226 passengers, was stopped at the San Jose, CA station, on UP Coast subdivision, due to a loss of Head-End Power (HEP) on both units. The crew worked with CNOC Mechanical to troubleshoot the issue. Drummack mechanical responded to the scene to assist. Following repairs, Train 14(19) resumed its journey after HEP was restored on the trailing locomotive 345. The crew identified a loose cable as the cause.

Train	Delay	Comment
14(19)	41"	

Train 41(19) West of South Bend, IN - Vehicle on Tracks

19DEC25: Train 41(19) 26-FOI-00197la00000005538 1 mi UNCLASSIFIED" of 32/23/2025 Bend, IN, at milepost 466.7, on NS Chicago_76CD subdivision, due to a vehicle on the tracks ahead at milepost 464.8. Local police responded to the scene with a tow truck to remove the vehicle. Once the vehicle was removed and the tracks were inspected, train 41(19) was able to proceed.

Train	Delay	Comment
41(19)	24"	

Train 307(19) Chicago, IL - Car Failure

19DEC25: Train 307(19) was delayed 52 minutes departing Chicago, Illinois due to an exterior door issue on venture car ID4203. As background, Train 307(19) was released by mechanical at 540pm. At 6:05pm, the yard crew reported the exterior door kept opening and closing on venture car ID4203. At least three attempts were made to resolve the issue before the door bypass was cutout on the locomotive. Train 307(19) set in the station at 7:42pm with 137 passengers to board. Train 307(19) departed Chicago at 802pm.

Train	Delay	Comment
307(19)	52"	

Train 48/448(19) Chicago, IL - Engine Failure

19DEC25: Train 48(19) was delayed 3 hours and 45 minutes departing Chicago, Illinois due to a bad order locomotive. As background, inbound 49(18) arrived in Chicago at 1113am; 1 hour and 1-minute late and set to the yard for servicing and inspection at 1244pm. At an unknown time, trail engine AMTK 107 was bad ordered for wheel shelling and was delivered to the diesel pit at 240pm for wheel replacement. At 625pm, the diesel pit general foreman reported that after changing out one pair of wheels, another scrap wheel set was noticed while moving the unit outside the shop. Engine AMTK 107 was moved back inside the shop in anticipation of replacing the 2nd scrap wheel set. At approximately 700pm, the diesel pit elected to use trail engine AMTK 142 off inbound 6(17) instead of changing out another wheel set on engine AMTK 107. After the daily inspection was completed on engine AMTK 142 at 757pm, it was delivered to the 6/7-switch to add fuel at 835pm. Engine AMTK 142 was released from fueling at 849pm. Engine AMTK 142 was added in the trail position on Train 48(19) at 1006pm. There was a delay in adding the locomotive due to an unrecoverable cab signal penalty on lead engine AMTK 99. Mechanical assistance was necessary to reset the cab signal penalty. Train 48(19) was released by mechanical at 1149pm, shoved from yard at 1213am, and set in the station at 1228am with 248 passengers to board. Train 48(19) departed Chicago at 115am; 3 hours and 45 minutes late.

Train	Delay	Comment
48/448(19)	3'45"	

Train 382(19) South of Galesburg, IL - Freight Train Interference

19DEC25: Train 383(29) was delayed 8.5 miles south of Galesburg, IL at milepost 168.9, on BNSF Brookfield subdivision, due to disabled BNSF7894 obstructing the route. The Freight crew was able to resolve its issues and get back on the move, clearing a route for train 382(19)

Train	Delay	Comment
382(19)	39"	

Train 6(18) West of Denver, CO - Weather/Power Outage

19DEC25: Train 6(18) was delayed 59 minutes at milepost 49.9, on UP Moffat Tunnel subdivision, due to a weather related power outage causing wayside signals and switches to be out of correspondence. This caused train 6(18) to have to hand line the switches for their route and operate at restricted speed. Once train 6(18) cleared the affected area, they were able to resume normal speed.

Train	Delay	Comment
6(18)	59"	

Train 7(17) Leavenworth, WA - Freight Train Interference

19DEC25: Train 7(17) was delayed east of Leavenworth, WA (LWA) at MP 1699.5 on the Burlington Northern Santa Fe Railway Scenic Subdivision. Train 7(17) was held for opposing freight train, BNSF/6639, to clear the track ahead. Once the track ahead was clear, train 7(17) was able to proceed west at 2:35 PM-PT.

Train	Delay	Comment
7(17)	1'18"	

Train 41(19) Chicago, IL - Car Failure

19DEC25: Train 41(19) was delayed 49 minutes departing Chicago, Illinois due to a bad order sleeping car, air issues with the potential replacement car, and toilet issues on the two remaining sleeping cars. At 300pm, sleeping car 62034 was bad ordered for toilets and HVAC. Car to deadhead inline with dormitory sleeping car 69000 added to consist. At 533pm, while attempting to add C/69000 the crew could not get the brakes to release. Decision was made to not add the car and downgrade affected sleeping car passengers; train would be oversold starting in Elkhart, Indiana. Train 41(19) was made-up at 537pm and released by mechanical at 557pm. While shoving to the station, onboard services reported toilet issues on remaining sleeping cars 62044 & 62518. Train 41(19) set in the station at 610pm with 249 passengers to board. Mechanical worked until 723pm but were only able to restore functioning toilets on sleeping car 62044. Onboard services would accommodate passengers from sleeping car 62518 en route as no space was available to downgrade to coach seating. Train 41(19) departed Chicago at 729pm; 49 minutes late.

Train	Delay	Comment
41(19)	49"	

Train 539(19) West of Sacramento, CA - Trespasser Incident

19DEC25: Train 539(19) was delayed west of Sacramento, CA (SAC) at MP 79.2 on the Union Pacific Railway Martinez Subdivision. The engineer observed a vehicle to be fouling the track ahead and safely stopped the train short of the vehicle. Once the vehicle was removed, and tracks inspected train 539(19) was able to proceed west at 12:56 PM-PT.

Train	Delay	Comment
539(19)	55"	

Train 338(19) Milwaukee, WI - Late Turn

19DEC25: Train 338(19) was delayed 26 minutes departing Milwaukee, WI/MP85.4, on the CPRR C&M Subdivision, due to a late turn of Train 335(19)'s equipment that arrived 44 minutes late due to multiple delays in route.

339(19) was delayed departing Chicago, IL, due to turning from the late inbound train 338(19).

Train	Delay	Comment
338(19)	34"	
339(19)	40"	

Train 3(18) West of Raton, NM - Signal

19DEC25: Train 3(18) was delayed west of Raton, NM/MP770.1, on the BNSF Raton Subdivision, from signal issues. The crew reported operating speeds were restricted starting at MP706.5 to MP712.6 followed by MP746.3 to MP753.4.

Train	Delay	Comment
3(18)	32"	

Train 7/27(18) West of Wolf Point, MT - Signal

19DEC25: Train 7/27(18) was delayed 12 miles west of Wolf Point, MT/MP227.9, on the BNSF Glasgow Subdivision, at Oswego/MP239.9 meeting BNSF 6991. Additional delay due to signal issues at East Kintyre/MP251.4 caused restricted speeds to West Kintyre/MP253.4. At Whatley/MP272.9, Train 7/27(18) met BNSF 7758.

Train	Delay	Comment
7/27(18)	25"	BNSF 6991
7/27(18)	24"	Signals
7/27(18)	10"	BNSF 7758

Train 364(19) Chicago, IL - Car Failure

19DEC25: Train 364(19) was delayed 52 minutes departing Chicago, Illinois account late release. Train 365(19) arrived CUS at 1149am, 4 minutes late. The train was shoved to the yard and set at 1235pm. It was necessary to hold out business-coach pair C/ID4208-ID4128 for PM. The flags came down to switch at 220pm and the train was made up complete in the yard at 256pm. After working replacement C/ID4005, Train 364(19) was released in the yard at 418pm and was set in CUS at 434pm. Train 364(19) departed CUS at 158pm, 52 minutes late.

Train	Delay	Comment
364(19)	52"	

Trains 22(18) and 301(19) Springfield, IL - Police Related

19DEC25: Train 22(18) with 228 passengers onboard held at the Springfield, IL station/MP185.1, on the UPRR Springfield Subdivision, due to a police hold. Union Pacific reported RMCC was holding all tracks account a vehicle accident on the tracks 1 mile north of the station at 184.08. Train 301(19) was also delayed during this time holding in the Ridgely siding at MP182.9. Once the scene was cleared and the hold released, Train 22(18) departed the station on the way to Chicago. Train 301(19) was back on the move to St. Louis after meeting Train 22(18).

Train	Delay	Comment
301(19)	38"	
22(18)	27"	

Train 5(17) West of Salt Lake City, UT - Freight Train Interference

19DEC25: Train 5(17) was delayed starting 38 miles west of Salt Lake City, UT/0.0, on the UPRR Shafter Subdivision, at Cliffside/MP780.3 meeting UP8458 and UP5711.

Train	Delay	Comment
5(17)	50"	

Train 21(18) South of Texarkana, AR - Freight Train Interference

19DEC25: Train 21(18) was delayed starting 38 miles south Texarkana, AR/0.0, on the UPRR Little Rock Subdivision, at Kildare/MP38.0 meeting UP7509. Additional delay at Jefferson/MP51.1 meeting UP5943 and UP6764 followed by meeting UP5712 at Woodlawn/MP59.5.

Train	Delay	Comment
21(18)	15"	Kildare
21(18)	15"	Woodlawn
21(18)	22"	Jefferson

Train 3(17) East of Kingman, AZ - Car Failure

19DEC25: At 4:22AM-MST, Train 3(17), E/13-E/23-10 Cars, went into emergency 38 miles east of Kingman, AZ/MP516.3, on the BNSF Seligman Subdivision. at MP587.3. The Conductor walked the train and found a brake pipe separation between cars 61010 and 39031. Head end power was intermittent while the crew worked in between the cars with 164 passengers onboard. At 4:52AM-MST, the brake pipe was fixed and air restored to the trainset. Train 3(17) was on the move at 4:52AM-MST advancing 4 miles to hold again at MP491.0 for the recrew and pilots to arrive by van from Kingman. Once the recrew was onboard, Train 3(17) was back on the move west at 5:59AM-MST.

WBS#: B.TR.100150.6332

Train	Delay	Comment
3(17)	29"	Brake Pipe
3(17)	1'18"	Recrew

Train 371(19) West of St. Joseph-Benton Harbor, MI - Signal

19DEC25: Train 371(19) held 28.5 miles west of St. Joseph-Benton Harbor, MI/MP87.9, on the CSX Grand Rapids Subdivision, at New Buffalo/MP116.4. The hold was due to an issue with the automatic road crossing protection at MP125.2 which required a maintainers response. Once the maintainer was on site, Train 371(19) was released to continue to Chicago.

Train	Delay	Comment
371(19)	34"	

Train 300(19) St. Louis, MO - Car Failure

19DEC25: Train 300(19) with E/ID4611, 5 cars, "UNCLASSIFIED" arrived 12/23/2025 at St. Louis, MO/MP1.5, on the TRRA Merchants Subdivision, due to sticking brakes on car ID4317. To give St. Louis Mechanical time to troubleshoot the issue, Train 302(19)'s equipment was moved up to be utilized instead. Once the 51 passengers were loaded, Train 300(19) departed St. Louis at 5:49AM. 1 hour and 19 minutes late. Mechanical was able to resolve the issue to allow Train 302(19) to depart on time. There were buses secured in the event the issue was not resolved which were ultimately cancelled.

Train 307(19) with E/ID4611, 5 cars and 137 passengers, came to a stop at Summit, IL on CN Joliet subdivision, due to sticking brakes on car ID4317. The crew worked with CNOC mechanical to resolve but were unsuccessful. Mechanical was dispatched from Chicago, IL to assist. Due to the history of brake issues with this equipment the decision was made to terminate train 307(19) at Summit, IL. Train 307(19) equipment operated back to Chicago, IL.

3 buses were sourced as alternate transportation and arrived at Summit, IL and operated as follows: bus 1 operated express from Summit to Bloomington-Normal. Bus 2 operated Summit, Joliet, Pontiac, Bloomington-Normal, and Springfield. Bus 3 operated Summit, Bloomington-Normal, Lincoln, Springfield, Alton, and Saint Louis. All passengers were loaded onto the buses and departed by 11:50PM-CT.

Due to the lack of equipment, train 302(20) was cancelled. 3 buses were sourced as alternate transportation. Bus 1 operated express Saint Louis to Chicago. Bus 2 operated Saint Louis, Bloomington-Normal, Pontiac, Summit, Chicago, drop off only. Bus 3 will operated Bloomington-Normal, Pontiac, Chicago.

WBS#: B.TR.100150.6331

Train	Delay	Comment
300(19)	1'19"	
307(19)	Terminated SMT	
302(20)	Cancelled	

Trains 520(19) and 535(19) - Cancelled

19DEC25: Due to an engine shortage, Trains 520(19) and 535(19) were cancelled in their entirety with no alternate transportation provided. Affected passengers were advised to rebook to the next available service.

Train	Delay	Comment
520(19) and 535(19)	Cancelled	

UNCLASSIFIED
12/3/2025
B. TR. 100150.6267
Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Western Region

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Vehicle strike damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (16)	SEA	BNSF6559	E/182 failed departure test	CHI	12/19/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 5(18) Passenger Removal at Denver, Colorado – Medical

19DEC25, Passenger on PNR A4197B, traveling from Burlington, IA to Roseville, CA reportedly had a very swollen blood red eye upon arrival at the Denver station. Local paramedics recommended a local hospital for treatment, however the passenger declined and opted to self-transport to a Veterans Hospital for treatment. Amtrak Police notified.

Delay: 5 (18) None

Consist Deviations

26-FOI-00197

00000005538

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
2163 (19)	BOS	NEXT GEN ACELA in lieu of LEGACY Acela equipment	Reports run	0	
5 (19)	CHI	Operating with T-Dorm w/o H Room.	reaccom	1	39005
305 (19)	CHI	Due to shopped equip and no replacement 305(19) & 300(20) will NOT offer Biz class. customer service notified.	dg to coach	32	NOCAR
364 (19)	CHI	Extra cafe car as coach in consist, not per consist plan. no impact to customers			ID4305
364 (19)	CHI	due to shopped equipment and no replacement, 364(19) & 365(20) will NOT offer Biz class. customer service notified.	NO JY	35	NOCAR
48 (20)	CHI	a viewliner 2 sleeper in lieu of viewliner 1, resulting in 2 less rooms. customer service notified.	PAX REACCOM	0	62503
41 (19)	CHI	62034 byd for toilets and hvac. Bag dorm in lieu of sleepers. Customer service notified.			62034
41 (19)	CHI	62034 byd toilets/hvac deadhead inline. Replacement 69000 byd brakes. (4110) no sleeper car. Please accomodate all affected passengers			69000
6 (22)	EMY	Operating with T-Dorm w/o H Room.	reaccom	1	39005
4 (19)	LAX	Operating with SS in lieu of TDorm a/c late arrival of 3(17). Need to block DS rooms and FS room.	BLOCK 5 DS 1 F	0	32090
2190 (19)	NYP	NEXT GEN ACELA in lieu of LEGACY Acela equipment	Reports run	0	
2117 (19)	NYP	NEXT GEN ACELA in lieu of LEGACY Acela equipment	Reports run	0	
49 (19)	NYP	VWII in lieu of VWI sleeper. (4912)	No impact	0	62503
97 (19)	NYP	VWII in lieu of WI sleeper (9711)	No impact	0	62501

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
183 (19)	NYP	CONSIST IS SHORT 2 CARS, AND 18 PASSENGERS OVER CAP	over cap -21 tn enrt move 7 pax to jy	21	
365 (19)	PTH	Extra cafe car operating in consist, not per consist plan. no impact to customers.	n/a	0	ID4305
365 (20)	PTH	Due to shopped equipment 365(20) will NOT offer Biz class. customer service notified.	NO JY	35	NOCAR
300 (19)	STL	Due to equip issues and swapping equip, 300(19) will NOT offer biz class. customer service notified of overcapacity. Room in coach for accom.	NO JY	35	NOCAR
300 (20)	STL	Due to shopped equip and no replacement, 300(20) will NOT offer Biz class. Customer service notified.	DOWNGRADE TO COACH	35	NOCAR
2104 (19)	WAS	NEXT GEN ACELA in lieu of LEGACY Acela equipment	Reports run	0	
2122 (19)	WAS	NEXT GEN ACELA in lieu of LEGACY Acela equipment	Reports Run	0	
184 (19)	WAS	CONSIST IS SHORT 2 CARS AND 100 PASSENGERS OVER CAP	over cap -104 self mod link w/ fare protect sent to pax	104	

Reverse Consists

Train Number	Station	Reason
93 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
85 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front
181 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
183 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front
110 (19)	PHL	Consist reversed Business class seat orientation may have changed At Rear
190 (19)	PHL	Consist reversed Business class seat orientation may have changed At Front
2107 (19)	NYP	Acela consist reversed First class at Rear
88 (19)	BOS	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00197 00000005538 "UNCLASSIFIED"	12/23/2025
129 (19)	NYP	Consist reversed Business class seat orientation may have changed At Front	
114 (19)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
176 (19)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
193 (19)	NYP	DUE TO EQUIPMENT SWAP NYP / Consist reversed Business class seat orientation may have changed At Front	
197 (19)	NYP	DUE TO EQUIPMENT SWAP NYP / Consist reversed Business class seat orientation may have changed At Rear	