CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 23, 2026 Rules: 4-4



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: **10/22/2026**
Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/22/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	53	83.4%	6,760	955	85.9%	6,760	955	85.9%
Central Division	86.0%	59	5	91.5%	1,264	87	93.1%	1,264	87	93.1%
East Division	82.0%	170	31	81.8%	3,597	542	84.9%	3,597	542	84.9%
West Division	86.0%	91	17	81.3%	1,899	326	82.8%	1,899	326	82.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/22/26

Service	Target	Day			Month to Date			FY to Date		
		Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**91,056**	**30,871**	**66%**	**2,279,043**	**661,756**	**71%**	**2,279,043**	**661,756**	**71%**
Northeast Corridor	***81%***	***38,828***	***13,755***	***65%***	***990,833***	***243,939***	***75%***	***990,833***	***243,939***	***75%***
Acela	83%	6,907	2,094	70%	185,110	38,105	79%	185,110	38,105	79%
Northeast Regional	79%	31,921	11,661	63%	805,723	205,834	74%	805,723	205,834	74%
Richmond / Newport News / Norfolk	77%	5,983	2,888	52%	202,124	55,788	72%	202,124	55,788	72%
Springfield Shuttles	89%	748	292	61%	16,868	4,223	75%	16,868	4,223	75%
Roanoke	79%	2,633	667	75%	72,325	20,567	72%	72,325	20,567	72%
On Spine Northeast Regional	80%	22,557	7,814	65%	514,406	125,256	76%	514,406	125,256	76%
State Supported	***80%***	***42,023***	***13,418***	***68%***	***1,018,852***	***292,711***	***71%***	***1,018,852***	***292,711***	***71%***
Borealis	80%	740	321	57%	15,944	3,251	80%	15,944	3,251	80%
Capitol Corridor	90%	4,249	385	91%	93,365	17,101	82%	93,365	17,101	82%
Carolinian	70%	927	300	68%	28,575	8,325	71%	28,575	8,325	71%
Cascades	75%	3,068	1,192	61%	61,379	18,286	70%	61,379	18,286	70%
Downeaster	82%	1,402	426	70%	41,509	10,694	74%	41,509	10,694	74%
Empire	78%	6,203	1,761	72%	144,568	35,324	76%	144,568	35,324	76%
Adirondack	72%	383	12	97%	9,755	1,497	85%	9,755	1,497	85%
Ethan Allen Express	70%	634	292	54%	13,827	5,707	59%	13,827	5,707	59%
Maple Leaf	70%	795	330	58%	19,406	6,222	68%	19,406	6,222	68%
New York - Albany	85%	3,074	868	72%	70,011	12,952	82%	70,011	12,952	82%
New York - Niagara Falls	75%	1,317	259	80%	31,569	8,946	72%	31,569	8,946	72%
Gold Runner	73%	1,714	387	77%	56,656	22,136	61%	56,656	22,136	61%
Heartland Flyer	70%	142	140	1%	4,524	3,913	14%	4,524	3,913	14%
Hiawatha	90%	1,881	91	95%	41,938	3,945	91%	41,938	3,945	91%
Illinois	78%	2,615	965	63%	60,040	19,343	68%	60,040	19,343	68%
Carl Sandburg / Illinois Zephyr	85%	402	211	48%	9,432	2,407	74%	9,432	2,407	74%
Illini / Saluki	85%	863	378	56%	19,973	8,397	58%	19,973	8,397	58%
Lincoln Service	70%	1,350	376	72%	30,635	8,539	72%	30,635	8,539	72%
Keystone	92%	6,604	9	100%	160,282	18,273	89%	160,282	18,273	89%
Lincoln / Missouri	70%	862	502	42%	19,009	9,579	50%	19,009	9,579	50%
Mardi Gras Service	80%	315	124	61%	6,164	1,999	68%	6,164	1,999	68%
Michigan	70%	1,263	975	23%	48,931	11,976	76%	48,931	11,976	76%
Blue Water	70%	265	265	0%	11,577	3,824	67%	11,577	3,824	67%
Pere Marquette	85%	288	0	100%	6,701	391	94%	6,701	391	94%
Wolverine	70%	710	710	0%	30,653	7,761	75%	30,653	7,761	75%
Missouri	80%	321	143	55%	6,427	1,261	80%	6,427	1,261	80%
Pacific Surfliner	85%	6,025	3,842	36%	147,400	82,413	44%	147,400	82,413	44%
Pennsylvanian	80%	955	848	11%	21,234	7,377	65%	21,234	7,377	65%
Piedmont	80%	1,216	413	66%	26,718	7,253	73%	26,718	7,253	73%
Vermonter	75%	1,521	594	61%	34,189	10,262	70%	34,189	10,262	70%
Long Distance	***70%***	***10,205***	***3,698***	***64%***	***269,358***	***125,106***	***54%***	***269,358***	***125,106***	***54%***
Auto Train	70%	862	470	45%	14,448	10,163	30%	14,448	10,163	30%
California Zephyr	70%	911	84	91%	21,041	6,749	68%	21,041	6,749	68%
Cardinal	70%	132	70	47%	5,335	2,531	53%	5,335	2,531	53%
City Of New Orleans	75%	636	567	11%	16,581	12,199	26%	16,581	12,199	26%
Coast Starlight	70%	505	167	67%	24,551	12,661	48%	24,551	12,661	48%
Crescent	70%	1,070	22	98%	20,871	2,788	87%	20,871	2,788	87%
Empire Builder	70%	1,061	403	62%	23,174	9,549	59%	23,174	9,549	59%
Floridian	60%	743	133	82%	32,199	19,607	39%	32,199	19,607	39%
Lake Shore Ltd	73%	930	733	21%	23,698	6,815	71%	23,698	6,815	71%
Palmetto	70%	526	0	100%	17,164	3,358	80%	17,164	3,358	80%
Silver Meteor	70%	1,274	563	56%	23,393	7,403	68%	23,393	7,403	68%
Southwest Chief	60%	821	256	69%	20,115	15,248	24%	20,115	15,248	24%
Sunset Ltd	70%	0	0	-	6,220	3,241	48%	6,220	3,241	48%
Texas Eagle	70%	734	230	69%	20,568	12,794	38%	20,568	12,794	38%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through October 22, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	138,450	2,232,547	620	138,450	2,232,547	620

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	6,573	643,609	102	6,573	643,609	102
INFRASTRUCTURE PLANNED	135	14,743	643,609	229	14,743	643,609	229
FLEET RELIABILITY	90	18,380	2,232,547	82	18,380	2,232,547	82
TRAIN OPERATIONS	424	98,754	2,232,547	442	98,754	2,232,547	442

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: **10/22/2026**
Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/22/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	53	83.4%	6,760	955	85.9%	6,760	955	85.9%
Central Division	86.0%	59	5	91.5%	1,264	87	93.1%	1,264	87	93.1%
East Division	82.0%	170	31	81.8%	3,597	542	84.9%	3,597	542	84.9%
West Division	86.0%	91	17	81.3%	1,899	326	82.8%	1,899	326	82.8%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/22/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/22/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	53	83.4%	6,760	955	85.9%	6,760	955	85.9%
Central Division	86.0%	59	5	91.5%	1,264	87	93.1%	1,264	87	93.1%
CDL	95.0%	1	0	100.0%	29	2	93.1%	29	2	93.1%
CHI	86.0%	27	1	96.3%	596	47	92.1%	596	47	92.1%
CHM	-	1	0	100.0%	14	2	85.7%	14	2	85.7%
DAL	-	-	-	-	2	0	100.0%	2	0	100.0%
DET	-	1	1	0.0%	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	19	2	89.5%	19	2	89.5%
GRR	95.5%	1	0	100.0%	22	0	100.0%	22	0	100.0%
IND	-	1	0	100.0%	2	0	100.0%	2	0	100.0%
KCY	92.0%	2	0	100.0%	44	1	97.7%	44	1	97.7%
MKE	92.0%	6	0	100.0%	129	7	94.6%	129	7	94.6%
MOE	97.5%	2	0	100.0%	37	0	100.0%	37	0	100.0%
MSP	96.5%	1	0	100.0%	22	0	100.0%	22	0	100.0%
NOL	94.5%	4	0	100.0%	86	4	95.3%	86	4	95.3%
OKC	97.0%	1	0	100.0%	21	1	95.2%	21	1	95.2%
PNT	88.0%	2	2	0.0%	64	9	85.9%	64	9	85.9%
PTH	93.0%	1	1	0.0%	22	1	95.5%	22	1	95.5%
QCY	91.0%	2	0	100.0%	44	2	95.5%	44	2	95.5%
SAS	90.5%	1	0	100.0%	22	6	72.7%	22	6	72.7%
STL	89.0%	4	0	100.0%	88	2	97.7%	88	2	97.7%
East Division	82.0%	170	31	81.8%	3,597	542	84.9%	3,597	542	84.9%
ALB	88.5%	8	1	87.5%	173	12	93.1%	173	12	93.1%
ALX	-	3	2	33.3%	18	11	38.9%	18	11	38.9%
ATL	-	1	1	0.0%	10	3	70.0%	10	3	70.0%
BON	87.5%	5	1	80.0%	110	11	90.0%	110	11	90.0%
BOS	85.5%	12	2	83.3%	302	12	96.0%	302	12	96.0%
BRK	92.5%	5	1	80.0%	110	9	91.8%	110	9	91.8%
BTN	82.0%	1	0	100.0%	22	3	86.4%	22	3	86.4%
CLT	91.5%	5	0	100.0%	104	15	85.6%	104	15	85.6%
GFD	88.0%	2	0	100.0%	44	4	90.9%	44	4	90.9%
GRO	-	-	-	-	5	0	100.0%	5	0	100.0%
HAR	79.5%	13	3	76.9%	252	31	87.7%	252	31	87.7%
HFD	-	2	1	50.0%	32	7	78.1%	32	7	78.1%
JAX	-	2	0	100.0%	11	2	81.8%	11	2	81.8%
LOR	84.0%	1	0	100.0%	20	8	60.0%	20	8	60.0%
MET	-	-	-	-	1	1	0.0%	1	1	0.0%
MIA	89.5%	2	0	100.0%	43	7	83.7%	43	7	83.7%
MTR	79.0%	1	0	100.0%	22	5	77.3%	22	5	77.3%
NFK	84.5%	1	1	0.0%	38	6	84.2%	38	6	84.2%
NFL	93.5%	2	0	100.0%	44	4	90.9%	44	4	90.9%
NHV	78.0%	5	2	60.0%	111	28	74.8%	111	28	74.8%
NPN	93.0%	-	-	-	30	4	86.7%	30	4	86.7%
NYP	75.5%	38	6	84.2%	942	159	83.1%	942	159	83.1%
PGH	93.0%	2	1	50.0%	28	7	75.0%	28	7	75.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/22/2026**
Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/22/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	320	53	83.4%	6,760	955	85.9%	6,760	955	85.9%
East Division	82.0%	170	31	81.8%	3,597	542	84.9%	3,597	542	84.9%
PHL	48.0%	11	3	72.7%	164	78	52.4%	164	78	52.4%
RGH	95.0%	6	1	83.3%	90	17	81.1%	90	17	81.1%
RNK	83.5%	1	0	100.0%	39	6	84.6%	39	6	84.6%
SAB	98.0%	1	0	100.0%	22	0	100.0%	22	0	100.0%
SAV	96.0%	-	-	-	15	0	100.0%	15	0	100.0%
SFA	88.0%	1	1	0.0%	20	5	75.0%	20	5	75.0%
SPG	92.5%	5	0	100.0%	119	9	92.4%	119	9	92.4%
TWO	73.0%	1	1	0.0%	22	7	68.2%	22	7	68.2%
WAS	84.0%	33	3	90.9%	634	71	88.8%	634	71	88.8%
West Division	86.0%	91	17	81.3%	1,899	326	82.8%	1,899	326	82.8%
ARN	92.0%	1	0	100.0%	22	1	95.5%	22	1	95.5%
BFD	79.0%	7	2	71.4%	153	36	76.5%	153	36	76.5%
EMY	72.0%	1	0	100.0%	23	11	52.2%	23	11	52.2%
EUG	86.5%	2	0	100.0%	42	1	97.6%	42	1	97.6%
GAC	-	-	-	-	3	2	33.3%	3	2	33.3%
GTA	90.0%	6	4	33.3%	78	30	61.5%	78	30	61.5%
IRV	-	-	-	-	1	0	100.0%	1	0	100.0%
LAX	89.5%	10	2	80.0%	207	22	89.4%	207	22	89.4%
OKJ	74.5%	12	1	91.7%	258	79	69.4%	258	79	69.4%
PDX	86.0%	5	0	100.0%	110	11	90.0%	110	11	90.0%
SAC	88.5%	16	4	75.0%	326	29	91.1%	326	29	91.1%
SAN	90.5%	13	2	84.6%	245	51	79.2%	245	51	79.2%
SEA	85.0%	8	1	87.5%	175	21	88.0%	175	21	88.0%
SJC	89.0%	7	1	85.7%	153	22	85.6%	153	22	85.6%
SLO	90.0%	-	-	-	42	8	81.0%	42	8	81.0%
SPK	90.0%	1	0	100.0%	21	0	100.0%	21	0	100.0%
VAC	97.0%	2	0	100.0%	40	2	95.0%	40	2	95.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	193	22	6	72.7%	22	6	72.7%	22	15	31.8%	22	15	31.8%
4		22	1	95.5%	22	1	95.5%	22	18	18.2%	22	18	18.2%
5		21	1	95.2%	21	1	95.2%	21	6	71.4%	21	6	71.4%
6		21	11	47.6%	21	11	47.6%	21	7	66.7%	21	7	66.7%
7		21	1	95.2%	21	1	95.2%	21	2	90.5%	21	2	90.5%
8	36	21	6	71.4%	21	6	71.4%	21	14	33.3%	21	14	33.3%
11	41	22	3	86.4%	22	3	86.4%	22	12	45.5%	22	12	45.5%
14	No OS	22	5	77.3%	22	5	77.3%	22	13	40.9%	22	13	40.9%
19		22	4	81.8%	22	4	81.8%	21	3	85.7%	21	3	85.7%
20		22	2	90.9%	22	2	90.9%	23	3	87.0%	23	3	87.0%
21		22	2	90.9%	22	2	90.9%	22	11	50.0%	22	11	50.0%
22		22	6	72.7%	22	6	72.7%	22	15	31.8%	22	15	31.8%
23	21	19	0	100.0%	19	0	100.0%	19	5	73.7%	19	5	73.7%
24		18	0	100.0%	18	0	100.0%	18	5	72.2%	18	5	72.2%
25		18	0	100.0%	18	0	100.0%	18	5	72.2%	18	5	72.2%
26		19	0	100.0%	19	0	100.0%	19	7	63.2%	19	7	63.2%
27		21	3	85.7%	21	3	85.7%	21	4	81.0%	21	4	81.0%
28		21	3	85.7%	21	3	85.7%	21	3	85.7%	21	3	85.7%
40	17	22	8	63.6%	22	8	63.6%	22	10	54.5%	22	10	54.5%
41		22	3	86.4%	22	3	86.4%	23	12	47.8%	23	12	47.8%
42	73	22	3	86.4%	22	3	86.4%	22	9	59.1%	22	9	59.1%
43	16	22	7	68.2%	22	7	68.2%	22	9	59.1%	22	9	59.1%
48	30	22	4	81.8%	22	4	81.8%	22	8	63.6%	22	8	63.6%
49	101	22	5	77.3%	22	5	77.3%	22	3	86.4%	22	3	86.4%
50		10	0	100.0%	10	0	100.0%	10	4	60.0%	10	4	60.0%
51	51	9	3	66.7%	9	3	66.7%	10	4	60.0%	10	4	60.0%
52		20	5	75.0%	20	5	75.0%	20	10	50.0%	20	10	50.0%
53	167	20	8	60.0%	20	8	60.0%	20	17	15.0%	20	17	15.0%
55		16	0	100.0%	16	0	100.0%	16	5	68.8%	16	5	68.8%
56		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
58	74	22	1	95.5%	22	1	95.5%	22	20	9.1%	22	20	9.1%
59	85	22	1	95.5%	22	1	95.5%	22	17	22.7%	22	17	22.7%
63	35	22	9	59.1%	22	9	59.1%	22	22	0.0%	22	22	0.0%
64	25	22	7	68.2%	22	7	68.2%	22	13	40.9%	22	13	40.9%
66		21	3	85.7%	21	3	85.7%	21	1	95.2%	21	1	95.2%
67		16	3	81.3%	16	3	81.3%	16	4	75.0%	16	4	75.0%
68		22	5	77.3%	22	5	77.3%	22	4	81.8%	22	4	81.8%
69		22	9	59.1%	22	9	59.1%	22	2	90.9%	22	2	90.9%
71	30	22	1	95.5%	22	1	95.5%	22	3	86.4%	22	3	86.4%
72		22	3	86.4%	22	3	86.4%	22	2	90.9%	22	2	90.9%
73		17	3	82.4%	17	3	82.4%	17	6	64.7%	17	6	64.7%
74		17	5	70.6%	17	5	70.6%	17	8	52.9%	17	8	52.9%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	33	22	2	90.9%	22	2	90.9%	20	6	70.0%	20	6	70.0%
76	26	21	4	81.0%	21	4	81.0%	20	8	60.0%	20	8	60.0%
77	19	22	4	81.8%	22	4	81.8%	22	8	63.6%	22	8	63.6%
78		22	3	86.4%	22	3	86.4%	23	4	82.6%	23	4	82.6%
79	54	22	5	77.3%	22	5	77.3%	22	8	63.6%	22	8	63.6%
80		22	0	100.0%	22	0	100.0%	22	4	81.8%	22	4	81.8%
97		22	8	63.6%	22	8	63.6%	22	4	81.8%	22	4	81.8%
98	208	22	3	86.4%	22	3	86.4%	23	9	60.9%	23	9	60.9%
230		22	1	95.5%	22	1	95.5%	22	1	95.5%	22	1	95.5%
232		22	1	95.5%	22	1	95.5%	22	2	90.9%	22	2	90.9%
233	33	22	10	54.5%	22	10	54.5%	22	10	54.5%	22	10	54.5%
234		22	0	100.0%	22	0	100.0%	22	1	95.5%	22	1	95.5%
235		22	2	90.9%	22	2	90.9%	22	5	77.3%	22	5	77.3%
236	22	22	0	100.0%	22	0	100.0%	22	5	77.3%	22	5	77.3%
237	72	22	3	86.4%	22	3	86.4%	22	7	68.2%	22	7	68.2%
238		22	1	95.5%	22	1	95.5%	22	1	95.5%	22	1	95.5%
239		22	3	86.4%	22	3	86.4%	22	1	95.5%	22	1	95.5%
240		22	3	86.4%	22	3	86.4%	22	2	90.9%	22	2	90.9%
241		22	4	81.8%	22	4	81.8%	22	6	72.7%	22	6	72.7%
243		22	3	86.4%	22	3	86.4%	22	0	100.0%	22	0	100.0%
244		22	0	100.0%	22	0	100.0%	22	7	68.2%	22	7	68.2%
245		22	2	90.9%	22	2	90.9%	22	4	81.8%	22	4	81.8%
280		22	3	86.4%	22	3	86.4%	22	10	54.5%	22	10	54.5%
281		22	3	86.4%	22	3	86.4%	22	3	86.4%	22	3	86.4%
283		22	1	95.5%	22	1	95.5%	22	4	81.8%	22	4	81.8%
284		22	1	95.5%	22	1	95.5%	22	2	90.9%	22	2	90.9%
290	20	22	3	86.4%	22	3	86.4%	22	10	54.5%	22	10	54.5%
291		22	14	36.4%	22	14	36.4%	22	5	77.3%	22	5	77.3%
300		22	1	95.5%	22	1	95.5%	22	6	72.7%	22	6	72.7%
301		22	0	100.0%	22	0	100.0%	22	4	81.8%	22	4	81.8%
302		22	0	100.0%	22	0	100.0%	22	5	77.3%	22	5	77.3%
305		22	0	100.0%	22	0	100.0%	22	6	72.7%	22	6	72.7%
306	33	22	0	100.0%	22	0	100.0%	22	8	63.6%	22	8	63.6%
307	54	22	1	95.5%	22	1	95.5%	22	8	63.6%	22	8	63.6%
311	28	22	1	95.5%	22	1	95.5%	22	4	81.8%	22	4	81.8%
316		22	0	100.0%	22	0	100.0%	22	6	72.7%	22	6	72.7%
318	41	22	1	95.5%	22	1	95.5%	22	9	59.1%	22	9	59.1%
319		22	0	100.0%	22	0	100.0%	21	16	23.8%	21	16	23.8%
329		16	0	100.0%	16	0	100.0%	16	0	100.0%	16	0	100.0%
330		19	0	100.0%	19	0	100.0%	19	1	94.7%	19	1	94.7%
331		22	1	95.5%	22	1	95.5%	22	1	95.5%	22	1	95.5%
332		22	2	90.9%	22	2	90.9%	22	0	100.0%	22	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
334		22	0	100.0%	22	0	100.0%	22	0	100.0%	22	0	100.0%
335		22	1	95.5%	22	1	95.5%	22	1	95.5%	22	1	95.5%
336		22	0	100.0%	22	0	100.0%	22	1	95.5%	22	1	95.5%
337		22	1	95.5%	22	1	95.5%	22	1	95.5%	22	1	95.5%
338		22	2	90.9%	22	2	90.9%	22	6	72.7%	22	6	72.7%
339		22	5	77.3%	22	5	77.3%	22	4	81.8%	22	4	81.8%
341		21	5	76.2%	21	5	76.2%	21	2	90.5%	21	2	90.5%
342		22	3	86.4%	22	3	86.4%	22	2	90.9%	22	2	90.9%
350	Cncld	22	1	95.5%	22	1	95.5%	20	10	50.0%	20	10	50.0%
351	Cncld	21	3	85.7%	21	3	85.7%	19	3	84.2%	19	3	84.2%
353	300	22	3	86.4%	22	3	86.4%	21	3	85.7%	21	3	85.7%
354	147	22	5	77.3%	22	5	77.3%	21	7	66.7%	21	7	66.7%
355	31	22	4	81.8%	22	4	81.8%	21	6	71.4%	21	6	71.4%
364	31	22	1	95.5%	22	1	95.5%	22	7	68.2%	22	7	68.2%
365	319	22	1	95.5%	22	1	95.5%	22	9	59.1%	22	9	59.1%
370		22	0	100.0%	22	0	100.0%	22	2	90.9%	22	2	90.9%
371		22	0	100.0%	22	0	100.0%	22	0	100.0%	22	0	100.0%
380	22	22	0	100.0%	22	0	100.0%	22	5	77.3%	22	5	77.3%
381		22	0	100.0%	22	0	100.0%	22	6	72.7%	22	6	72.7%
382		22	2	90.9%	22	2	90.9%	22	5	77.3%	22	5	77.3%
383	18	22	0	100.0%	22	0	100.0%	22	10	54.5%	22	10	54.5%
390		21	3	85.7%	21	3	85.7%	21	5	76.2%	21	5	76.2%
391		22	1	95.5%	22	1	95.5%	22	3	86.4%	22	3	86.4%
392	36	22	1	95.5%	22	1	95.5%	22	17	22.7%	22	17	22.7%
393	22	21	4	81.0%	21	4	81.0%	21	14	33.3%	21	14	33.3%
417		16	4	75.0%	16	4	75.0%	16	6	62.5%	16	6	62.5%
425		16	0	100.0%	16	0	100.0%	16	3	81.3%	16	3	81.3%
448		19	8	57.9%	19	8	57.9%	19	6	68.4%	19	6	68.4%
449		19	0	100.0%	19	0	100.0%	19	3	84.2%	19	3	84.2%
470	20	16	2	87.5%	16	2	87.5%	16	5	68.8%	16	5	68.8%
471		16	5	68.8%	16	5	68.8%	16	4	75.0%	16	4	75.0%
473		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
474	17	16	6	62.5%	16	6	62.5%	16	7	56.3%	16	7	56.3%
475		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
478		16	2	87.5%	16	2	87.5%	16	1	93.8%	16	1	93.8%
479		16	2	87.5%	16	2	87.5%	16	7	56.3%	16	7	56.3%
486	28	16	2	87.5%	16	2	87.5%	16	3	81.3%	16	3	81.3%
494	27	17	3	82.4%	17	3	82.4%	16	5	68.8%	16	5	68.8%
495		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
500		22	2	90.9%	22	2	90.9%	22	4	81.8%	22	4	81.8%
502	18	22	1	95.5%	22	1	95.5%	22	4	81.8%	22	4	81.8%
503		22	4	81.8%	22	4	81.8%	22	11	50.0%	22	11	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
504		21	1	95.2%	21	1	95.2%	21	9	57.1%	21	9	57.1%
505		22	1	95.5%	22	1	95.5%	22	4	81.8%	22	4	81.8%
506		22	2	90.9%	22	2	90.9%	21	6	71.4%	21	6	71.4%
507	16	22	1	95.5%	22	1	95.5%	21	8	61.9%	21	8	61.9%
508	34	22	1	95.5%	22	1	95.5%	22	8	63.6%	22	8	63.6%
509	36	22	0	100.0%	22	0	100.0%	22	8	63.6%	22	8	63.6%
511		22	1	95.5%	22	1	95.5%	22	3	86.4%	22	3	86.4%
516	169	20	4	80.0%	20	4	80.0%	19	13	31.6%	19	13	31.6%
517	17	22	2	90.9%	22	2	90.9%	22	10	54.5%	22	10	54.5%
518		22	2	90.9%	22	2	90.9%	21	10	52.4%	21	10	52.4%
519		20	1	95.0%	20	1	95.0%	20	3	85.0%	20	3	85.0%
520		16	0	100.0%	16	0	100.0%	16	0	100.0%	16	0	100.0%
521		16	1	93.8%	16	1	93.8%	15	1	93.3%	15	1	93.3%
522		16	4	75.0%	16	4	75.0%	16	1	93.8%	16	1	93.8%
523		16	3	81.3%	16	3	81.3%	16	4	75.0%	16	4	75.0%
524		16	2	87.5%	16	2	87.5%	15	1	93.3%	15	1	93.3%
525		16	2	87.5%	16	2	87.5%	15	1	93.3%	15	1	93.3%
526		16	6	62.5%	16	6	62.5%	15	2	86.7%	15	2	86.7%
527		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
528		16	1	93.8%	16	1	93.8%	16	3	81.3%	16	3	81.3%
529		16	1	93.8%	16	1	93.8%	16	7	56.3%	16	7	56.3%
530		16	2	87.5%	16	2	87.5%	16	3	81.3%	16	3	81.3%
531		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
532		16	5	68.8%	16	5	68.8%	16	0	100.0%	16	0	100.0%
534		16	4	75.0%	16	4	75.0%	16	0	100.0%	16	0	100.0%
535		16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
536		16	5	68.8%	16	5	68.8%	16	0	100.0%	16	0	100.0%
537		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
538		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
539		16	3	81.3%	16	3	81.3%	16	6	62.5%	16	6	62.5%
540		15	3	80.0%	15	3	80.0%	14	0	100.0%	14	0	100.0%
541		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
542		16	3	81.3%	16	3	81.3%	15	1	93.3%	15	1	93.3%
543		16	3	81.3%	16	3	81.3%	16	9	43.8%	16	9	43.8%
544		16	5	68.8%	16	5	68.8%	16	5	68.8%	16	5	68.8%
545		16	0	100.0%	16	0	100.0%	15	0	100.0%	15	0	100.0%
547		16	1	93.8%	16	1	93.8%	16	5	68.8%	16	5	68.8%
548		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
549		16	1	93.8%	16	1	93.8%	15	2	86.7%	15	2	86.7%
550		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
551		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
562	31	20	1	95.0%	20	1	95.0%	20	12	40.0%	20	12	40.0%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
564	29	20	0	100.0%	20	0	100.0%	20	12	40.0%	20	12	40.0%
566	44	20	1	95.0%	20	1	95.0%	18	9	50.0%	18	9	50.0%
567	23	20	2	90.0%	20	2	90.0%	19	7	63.2%	19	7	63.2%
572	95	17	5	70.6%	17	5	70.6%	16	12	25.0%	16	12	25.0%
573	27	20	2	90.0%	20	2	90.0%	20	10	50.0%	20	10	50.0%
579	24	17	1	94.1%	17	1	94.1%	16	10	37.5%	16	10	37.5%
580		20	2	90.0%	20	2	90.0%	19	10	47.4%	19	10	47.4%
581	26	20	8	60.0%	20	8	60.0%	18	14	22.2%	18	14	22.2%
584	55	20	3	85.0%	20	3	85.0%	18	16	11.1%	18	16	11.1%
587	31	20	5	75.0%	20	5	75.0%	18	13	27.8%	18	13	27.8%
588	37	17	3	82.4%	17	3	82.4%	16	9	43.8%	16	9	43.8%
591	48	20	5	75.0%	20	5	75.0%	20	14	30.0%	20	14	30.0%
593	61	15	6	60.0%	15	6	60.0%	12	5	58.3%	12	5	58.3%
595	44	16	10	37.5%	16	10	37.5%	16	13	18.8%	16	13	18.8%
600		20	0	100.0%	20	0	100.0%	20	3	85.0%	20	3	85.0%
601		16	7	56.3%	16	7	56.3%	16	4	75.0%	16	4	75.0%
605		16	6	62.5%	16	6	62.5%	15	1	93.3%	15	1	93.3%
607		20	1	95.0%	20	1	95.0%	20	1	95.0%	20	1	95.0%
609		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
622		14	2	85.7%	14	2	85.7%	14	1	92.9%	14	1	92.9%
626		20	4	80.0%	20	4	80.0%	20	4	80.0%	20	4	80.0%
640		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
641		16	2	87.5%	16	2	87.5%	16	2	87.5%	16	2	87.5%
642		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
643		20	6	70.0%	20	6	70.0%	20	3	85.0%	20	3	85.0%
644		16	2	87.5%	16	2	87.5%	16	4	75.0%	16	4	75.0%
645		20	6	70.0%	20	6	70.0%	20	3	85.0%	20	3	85.0%
646		16	4	75.0%	16	4	75.0%	16	2	87.5%	16	2	87.5%
647		19	3	84.2%	19	3	84.2%	19	1	94.7%	19	1	94.7%
648		16	0	100.0%	16	0	100.0%	16	0	100.0%	16	0	100.0%
649		20	1	95.0%	20	1	95.0%	20	4	80.0%	20	4	80.0%
650		20	4	80.0%	20	4	80.0%	20	2	90.0%	20	2	90.0%
651		16	0	100.0%	16	0	100.0%	16	4	75.0%	16	4	75.0%
652		20	2	90.0%	20	2	90.0%	20	1	95.0%	20	1	95.0%
653		15	4	73.3%	15	4	73.3%	15	1	93.3%	15	1	93.3%
654		15	4	73.3%	15	4	73.3%	15	3	80.0%	15	3	80.0%
655		20	2	90.0%	20	2	90.0%	20	2	90.0%	20	2	90.0%
656		20	4	80.0%	20	4	80.0%	20	5	75.0%	20	5	75.0%
657		16	5	68.8%	16	5	68.8%	16	1	93.8%	16	1	93.8%
658		19	1	94.7%	19	1	94.7%	19	1	94.7%	19	1	94.7%
680		16	2	87.5%	16	2	87.5%	16	0	100.0%	16	0	100.0%
681		16	0	100.0%	16	0	100.0%	15	8	46.7%	15	8	46.7%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
682		16	3	81.3%	16	3	81.3%	16	3	81.3%	16	3	81.3%
683	48	16	0	100.0%	16	0	100.0%	16	14	12.5%	16	14	12.5%
684		16	2	87.5%	16	2	87.5%	16	6	62.5%	16	6	62.5%
685		16	3	81.3%	16	3	81.3%	16	7	56.3%	16	7	56.3%
686	38	16	1	93.8%	16	1	93.8%	16	9	43.8%	16	9	43.8%
687	56	16	4	75.0%	16	4	75.0%	16	7	56.3%	16	7	56.3%
688		16	0	100.0%	16	0	100.0%	16	5	68.8%	16	5	68.8%
689		8	0	100.0%	8	0	100.0%	9	2	77.8%	9	2	77.8%
701		22	2	90.9%	22	2	90.9%	22	6	72.7%	22	6	72.7%
702	113	22	2	90.9%	22	2	90.9%	22	11	50.0%	22	11	50.0%
703		22	4	81.8%	22	4	81.8%	22	5	77.3%	22	5	77.3%
704		22	3	86.4%	22	3	86.4%	22	2	90.9%	22	2	90.9%
710		22	5	77.3%	22	5	77.3%	22	5	77.3%	22	5	77.3%
711		22	3	86.4%	22	3	86.4%	18	2	88.9%	18	2	88.9%
712		22	6	72.7%	22	6	72.7%	22	8	63.6%	22	8	63.6%
713	Cncld	21	8	61.9%	21	8	61.9%	17	5	70.6%	17	5	70.6%
714		22	11	50.0%	22	11	50.0%	21	13	38.1%	21	13	38.1%
715		22	4	81.8%	22	4	81.8%	21	12	42.9%	21	12	42.9%
717	Cncld	22	11	50.0%	22	11	50.0%	19	8	57.9%	19	8	57.9%
718		22	14	36.4%	22	14	36.4%	22	9	59.1%	22	9	59.1%
719		22	4	81.8%	22	4	81.8%	22	5	77.3%	22	5	77.3%
757	149	20	0	100.0%	20	0	100.0%	20	10	50.0%	20	10	50.0%
761	46	20	0	100.0%	20	0	100.0%	20	7	65.0%	20	7	65.0%
765	30	20	0	100.0%	20	0	100.0%	20	12	40.0%	20	12	40.0%
769	53	20	1	95.0%	20	1	95.0%	20	14	30.0%	20	14	30.0%
770		20	1	95.0%	20	1	95.0%	19	12	36.8%	19	12	36.8%
774	54	20	5	75.0%	20	5	75.0%	19	16	15.8%	19	16	15.8%
777	28	20	1	95.0%	20	1	95.0%	19	15	21.1%	19	15	21.1%
782	31	20	15	25.0%	20	15	25.0%	19	15	21.1%	19	15	21.1%
785		20	10	50.0%	20	10	50.0%	20	13	35.0%	20	13	35.0%
786	24	20	6	70.0%	20	6	70.0%	16	11	31.3%	16	11	31.3%
790	60	20	1	95.0%	20	1	95.0%	20	13	35.0%	20	13	35.0%
794	63	20	10	50.0%	20	10	50.0%	20	12	40.0%	20	12	40.0%
821	46	21	1	95.2%	21	1	95.2%	21	17	19.0%	21	17	19.0%
822	19	21	2	90.5%	21	2	90.5%	21	20	4.8%	21	20	4.8%
1019		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
1020		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
1040		6	1	83.3%	6	1	83.3%	6	1	83.3%	6	1	83.3%
1041		5	2	60.0%	5	2	60.0%	5	1	80.0%	5	1	80.0%
1071	22	6	5	16.7%	6	5	16.7%	6	3	50.0%	6	3	50.0%
1078	27	6	1	83.3%	6	1	83.3%	6	3	50.0%	6	3	50.0%
1079		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1080		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
1082	62	9	1	88.9%	9	1	88.9%	9	2	77.8%	9	2	77.8%
1087		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
1088	45	9	1	88.9%	9	1	88.9%	9	2	77.8%	9	2	77.8%
1090		6	1	83.3%	6	1	83.3%	6	0	100.0%	6	0	100.0%
1094	20	6	2	66.7%	6	2	66.7%	6	2	66.7%	6	2	66.7%
1095		6	3	50.0%	6	3	50.0%	6	0	100.0%	6	0	100.0%
1097		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
1098	18	6	0	100.0%	6	0	100.0%	6	2	66.7%	6	2	66.7%
1099	16	9	0	100.0%	9	0	100.0%	9	2	77.8%	9	2	77.8%
1103		9	4	55.6%	9	4	55.6%	9	1	88.9%	9	1	88.9%
1107		9	4	55.6%	9	4	55.6%	9	2	77.8%	9	2	77.8%
1109		9	0	100.0%	9	0	100.0%	9	1	88.9%	9	1	88.9%
1111		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
1116		9	1	88.9%	9	1	88.9%	9	1	88.9%	9	1	88.9%
1118		9	2	77.8%	9	2	77.8%	9	0	100.0%	9	0	100.0%
1124		8	1	87.5%	8	1	87.5%	8	1	87.5%	8	1	87.5%
1126		9	0	100.0%	9	0	100.0%	9	2	77.8%	9	2	77.8%
1127		9	1	88.9%	9	1	88.9%	9	1	88.9%	9	1	88.9%
1128		9	2	77.8%	9	2	77.8%	8	1	87.5%	8	1	87.5%
1129		9	0	100.0%	9	0	100.0%	9	2	77.8%	9	2	77.8%
1135	67	9	1	88.9%	9	1	88.9%	9	7	22.2%	9	7	22.2%
1138		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
1140		9	3	66.7%	9	3	66.7%	9	1	88.9%	9	1	88.9%
1142		9	3	66.7%	9	3	66.7%	9	3	66.7%	9	3	66.7%
1143	20	9	0	100.0%	9	0	100.0%	9	4	55.6%	9	4	55.6%
1144		9	7	22.2%	9	7	22.2%	9	2	77.8%	9	2	77.8%
1146		9	1	88.9%	9	1	88.9%	9	1	88.9%	9	1	88.9%
1147	18	9	0	100.0%	9	0	100.0%	9	3	66.7%	9	3	66.7%
1150		9	6	33.3%	9	6	33.3%	9	1	88.9%	9	1	88.9%
1151		9	2	77.8%	9	2	77.8%	9	5	44.4%	9	5	44.4%
1152	51	9	2	77.8%	9	2	77.8%	9	3	66.7%	9	3	66.7%
1153		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
1155	30	8	1	87.5%	8	1	87.5%	8	4	50.0%	8	4	50.0%
1156		9	3	66.7%	9	3	66.7%	9	6	33.3%	9	6	33.3%
1160		9	0	100.0%	9	0	100.0%	9	3	66.7%	9	3	66.7%
1161	26	9	0	100.0%	9	0	100.0%	9	6	33.3%	9	6	33.3%
1162	25	9	0	100.0%	9	0	100.0%	9	4	55.6%	9	4	55.6%
1163	58	9	0	100.0%	9	0	100.0%	9	6	33.3%	9	6	33.3%
1164	54	9	1	88.9%	9	1	88.9%	9	4	55.6%	9	4	55.6%
1165	53	9	0	100.0%	9	0	100.0%	9	4	55.6%	9	4	55.6%
1167	134	9	1	88.9%	9	1	88.9%	9	2	77.8%	9	2	77.8%

Amtrak On Time Performance

Trains Arriving Through: 10/22/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1168		9	3	66.7%	9	3	66.7%	9	2	77.8%	9	2	77.8%
1169		8	3	62.5%	8	3	62.5%	7	2	71.4%	7	2	71.4%
1179		6	3	50.0%	6	3	50.0%	6	0	100.0%	6	0	100.0%
1180		6	3	50.0%	6	3	50.0%	6	5	16.7%	6	5	16.7%
1194	28	9	2	77.8%	9	2	77.8%	9	1	88.9%	9	1	88.9%
1195		9	0	100.0%	9	0	100.0%	9	1	88.9%	9	1	88.9%
1333	45	22	2	90.9%	22	2	90.9%	22	5	77.3%	22	5	77.3%
1340		22	0	100.0%	22	0	100.0%	22	4	81.8%	22	4	81.8%
2101		9	1	88.9%	9	1	88.9%	9	1	88.9%	9	1	88.9%
2103		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
2105		16	1	93.8%	16	1	93.8%	16	1	93.8%	16	1	93.8%
2106		9	0	100.0%	9	0	100.0%	9	2	77.8%	9	2	77.8%
2114	21	9	2	77.8%	9	2	77.8%	9	3	66.7%	9	3	66.7%
2115		16	0	100.0%	16	0	100.0%	16	2	87.5%	16	2	87.5%
2116		16	0	100.0%	16	0	100.0%	16	0	100.0%	16	0	100.0%
2118		16	2	87.5%	16	2	87.5%	15	2	86.7%	15	2	86.7%
2120		16	3	81.3%	16	3	81.3%	16	3	81.3%	16	3	81.3%
2122		9	2	77.8%	9	2	77.8%	9	2	77.8%	9	2	77.8%
2123		16	1	93.8%	16	1	93.8%	16	2	87.5%	16	2	87.5%
2133		9	0	100.0%	9	0	100.0%	9	0	100.0%	9	0	100.0%
2148	19	9	1	88.9%	9	1	88.9%	8	1	87.5%	8	1	87.5%
2149	28	9	2	77.8%	9	2	77.8%	9	9	0.0%	9	9	0.0%
2150	57	16	0	100.0%	16	0	100.0%	16	9	43.8%	16	9	43.8%
2151	19	16	0	100.0%	16	0	100.0%	16	9	43.8%	16	9	43.8%
2152	25	16	0	100.0%	16	0	100.0%	16	1	93.8%	16	1	93.8%
2155		16	0	100.0%	16	0	100.0%	15	1	93.3%	15	1	93.3%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2114	NYP	21	TRS	16	TRS	16	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
2148	BOS	19	TRS	33	TRS	33	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
2149	WAS	28	DMW	15	DMW	15	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2150	BOS	57	ENG	23	DBB	20	XGX-PVD	AM	Stuck open bridges, Bridge, Mystic Bridge, AM2150 stopped trk 1 at Mystic River a/c unable to lock bridge
2151	WAS	19	TRS	16	TRS	16	PHL-WIL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
2152	NYP	25	TRS	18	TRS	18	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
470	HFD	20	ITI	16	ITI	16	NHV-NHV	AM	Late departure at initial terminal due to late arrival of inbound equipment, 471, SHORT TURN OF 471
474	SPG	17	CON	16	CON	16	NHV-NHV	AM	Hold for connecting train, late connection of AM474
486	GFD	28	CON	35	CON	35	NHV-NHV	AM	Hold for connecting train, late connection of AM1164
494	GFD	27	ITI	44	ITI	44	NHV-NHV	AM	Late departure at initial terminal due to late arrival of inbound equipment, 417, late turn of AM417
1071	RNK	22	DBS	39	DBS	39	MSS-CLP	NS	Debris blocking track (no debris strike) Down wires on Track, Milepost, 46.2, 46.2
1078	ALX	27	DSR	11	DSR	4	CLP-MSS	NS	Per bulletin Milepost, 40.0, 40.4, 25, 1
1082	BOS	62	DCS	37	DCS	29	XGX-KIN	AM	T.O.L, Milepost w/Letters, XGX, KIN, restricting cabs trk 1 XGX a/c signals issues ahead TOL trk 1 at Mystic River, traffic locked west at Mystic River
1088	BOS	45	DCS	50	DCS	30	XGX-KIN	AM	T.O.L, Milepost w/Letters, XGX, XHI, restricted speed trk 1 XGX - MP 133.5 a/c TOL, signal issues trk 1 at Mystic River
1094	ALX	20	ENG	20	ENG	20	NFK-NFK	NS	Issue with setting the trailing unit 204
1099	WAS	16	OTH	19	TRS	12	PHL-WIL	AM	Vandalism, Control Point, PHIL, T.O.L. ALL TRKS A/C VANDALISM
1135	WAS	67	CTI	46	CTP	24	RTE-PVD	AM	Delay due to mechanical problems on a Commuter train, AM1135 delayed due to MT839 having flat spots on E/2006, AM1135 crossed over trk 2 - 1 at Junction

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
1143	WAS	20	TRS	17	TRS	17	PHL-WIL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
1147	WAS	18	TRS	12	TRS	12	PHL-WIL	AM	Vandalism, Control Point, PHIL, T.O.L. ALL TRKS A/C VANDALISM
1152	NYP	51	ENG	48	ENG	48	WAS-WAS	AM	HEP, 670|EX|ES, MTR 670 SHOPPED FOR HOT BEARINGS.
1155	WAS	30	SMW	21	SMW	21	WIL-XPV	AM	Diversions around M/W work, Control Point, Davis - Bacon, OPR No.1 TRK A/C No.3 TRK O/O/S
1161	WAS	26	OTH	17	DSR	16	BRP-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 1, Milepost, 41.7, 40.4, 30, 1, Milepost, 35.1, 34.4, 30, 1
1162	BOS	25	HLD	14	TRS	14	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
1163	WAS	58	CTI	39	SMW	28	KIN-WLY	AM	Diversions around M/W work, Milepost, KIN, XHI, Stopped at High st. waiting for 1162 to crossover trk 1-2
1164	BOS		CTI	22	TRS	18	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
1165	WAS	53	SMW	27	DMW	23	KIN-KIN	AM	Held for or routed around MW work or equipment, Control Point, KIN, AM1165 held at KIN and XHI a/d waited for late AM1164 to clear XHI due to trk 2 OOS Mystic River - High St
1167	PHL	134	SMW	82	SMW	74	KIN-WLY	AM	Diversions around M/W work, Control Point, XHI, AM1167 held at High St, waited for AM1082 and AM1088 to clear a/c signal issues at Mystic River
1194	BOS	28	DCS	16	TRS	15	WIL-PHL	AM	Vandalism, Control Point, PHIL, T.O.L. ALL TRKS A/C VANDALISM
53	SFA	167	DSR	100	ENG	38	XFL-XOU	CS	Coolant leak 380
79	CLT		SYS	65	SYS	65	RGH-RGH	NS	PTC problem or failure (cause unknown) Other, Raleigh Station
683	BRK	48	PTI	41	PTI	36	SAO-ORB	CS	Meet 686, Control Point, Ocean Park
686	BON	38	DCS	39	DCS	39	POR-ORB	CS	PTC- I-ETMS Red Fence/Signal Status Unknown Issue trying to clear red fence., Control Point, Rigby East
687	BRK	56	ITI	23	ITI	23	BON-BON	MT	Late departure at initial terminal due to late arrival of inbound equipment 686
63	TWO	35	DSR	10	CTI	5	CRT-POU	MN	Follow metro north, 842, Milepost, 39.7, 61.4

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
64	NYP	25	FTI	30	FTI	20	SYR-ROM	CS	Cross Traffic csx, Control Point, 289
233	ALB	33	DMW	20	DMW	12	CRT-POU	MN	Held for or routed around MW work or equipment Single track conditions, hold for 1 southbound, Control Point, 39, Control Point, 46
236	NYP	22	PTI	14	PTI	14	YNY-XSD	MN	Cross over or go around 281, Control Point, 12
237	ALB	72	SYS	61	SYS	48	POU-XCP	MN	Blocked by or assisting another, disabled Amtrak train Held for AMT49 to extinguish bolster fire., Control Point, CP75
290	NYP	20	CTI	27	CTI	17	POU-CRT	MN	Follow metro north, Milepost, 72, 34
48	NYP	30	FTI	90	FTI	39	TOL-TOL	NS	Meet We were held in the station due to NS 23-G who experienced a train separation somewhere around CP 287, 23-G, Control Point, 287
49	CHI	101	FTI	92	ENG	43	XHF-UCA	CS	Loading problem 372
42	NYP	73	FTI	56	FTI	23	JST-ALT	NS	Follow NS 256, Milepost, 266, 250
43	PGH	16	FTI	26	FTI	16	ALT-JST	NS	Follow 33 A, Milepost, 236.1, 243.5
71	CLT	30	TCC	19	TCC	10	DNC-GRO	NS	Heavy train with one powered motor and one CCU. NC102
75	CLT	33	FTI	20	FTI	20	DNC-BNC	NS	Meet #NsP07, Control Point, Merrill
76	RGH	26	RTE	28	RTE	28	DNC-CYN	NS	Dispatcher original plan was to hold us at Clegg for Amtrak 79 Control Point, Clegg
77	CLT	19	FTI	18	FTI	18	HPT-SAL	NS	Held at lake for NS light engines Held at lake for clear track due to light engines on 1, NS Light Engines, Control Point, Lake
98	JAX	208	TRS	205	TRS	205	WPB-XDY	FL	Vehicle strike Other, 968.24
1098	NYP	18	TRS	17	TRS	17	WIL-PHL	AM	Vandalism, Control Point, PHIL, OPERATE THROUGH TOL
40	CHI		FTI	76	FTI	32	SOB-XPI	NS	Follow 23G, Milepost, 455, 482
23	NOL	21	FTI	61	FTI	51	BAS-XNO	CS	Follow Milepost, 745.1, 746.8, csx 605
51	CHI		FTI	65	FTI	30	CRF-LAF	CS	Cross Traffic 642, Control Point, Lafayette
502	SEA	18	FTI	26	FTI	15	KEL-CTL	BN	Meet UP5804, Control Point, Chehalis Jct
507	EUG	16	OTH	37	OTH	14	PDX-ORC	UP	PTI Met 508 at Clackamas siding

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
508	SEA	34	OTH	44	OTH	35	KEL-CTL	BN	Stopped at CP 72 due to massive Freight Delays EDR not functioning correctly had to put it in OTH UP 8102
509	PDX	36	OTH	44	OTH	13	OLW-CTL	BN	13 mins 4 mins DSR mp 42.2 to mp 42.3 60 mph main 2 mp 47.6 to mp 47.7 40 mph main 2 9 mins PTI Meet 506 at Wabash eDR will not allow any locations to be input
516	VAC	169	DMW	129	DMW	122	BEL-X8B	BN	Waiting for MW clearance Per disp, wait on derailed MoW equipment to clear tracks ahead. Stopped just South of Blaine Xing. Once equipment rerailed and tracks inspected, we were able to proceed at track speed., Other, Between White Rock and MP 127
517	PDX	17	PTI	20	DMW	12	EDM-SEA	BN	Waiting for MW clearance Milepost, 6.5, 5.0
58	CHI	74	DSR	100	FTI	34	YAZ-GWD	CC	Follow CN #3837, Milepost, 141.5, 130.9
59	NOL	85	DSR	122	PTI	37	MCB-HMD	CC	Meet AMTK59, Siding, Arcola
11	LAX	41	DCS	100	DCS	62	SLO-SBA	UP	CTC system failure Track and time from south tangair to north Elwood, Control Point, south tangair
14	SEA	No OS Rpt	TRS	184	TRS	184	CIC-RDD	UP	Trespasser strike Trespasser fatality, Milepost, 244.0, 244.0
8	CHI	36	FTI	123	CON	87	SPK-SPK	BN	Hold for connecting train 28
821	FTW	46	DCS	36	DCS	36	PVL-ADM	BN	Track indication btwn S Pvl and Winniewood Flagging speed, Milepost, 495, 489.1
822	OKC	19	DSR	44	DSR	30	FTW-GLE	BN	Per bulletin Milepost, 347.5, 347.9, 25, M1, Milepost, 349.6, 350.1, 25, M1, Milepost, 350.6, 352.5, 30, M1, Milepost, 351.2, 355.4, 25, M1, Milepost, 357.3, 357.6, 50, M2, Milepost, 357.6, 357.8, 30, M2, Milepost, 358.2, 358.7, 30, M2, Milepost, 369.0, 370.2, 60, MT, Milepost, 371.0, 372.5, 60, MT,
350	PNT	Trn Cancelled	PTI	227	PTI	200	NLS-NLS	AM	Wait for station track 351, Control Point, 192

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
351	CHI	Trn Cancelled	ITI	86	ITI	86	PNT-PNT	CC	Late departure at initial terminal due to late arrival of inbound equipment 354, Due to vehicle strike of 351 which took place on October 21 . Held up all trains
353	CHI	300	POL	251	POL	154	PNT-PNT	CC	RR blocked by trespasser or vehicle strike by another train
354	PNT	147	SYS	89	SYS	76	CHI-CHI	AM	Residual PTI from this mornings train car incident that cancelled the morning and afternoon wolverine services Other, chi track 22
355	CHI		PTI	18	PTI	15	XPI-HMI	NS	Meet 48, Control Point, 501
364	PTH	31	TRS	46	TRS	46	XTF-XH6	NS	Bridge strike by a vehicle or boat Other, 518
365	CHI	319	CAR	173	CAR	173	PTH-PTH	CC	Set out defective car NOCAR, Car number 4004 also conductor was working alone
562	SAN	31	PTI	22	PTI	20	SNC-X98	SC	Meet Amtk 765, Control Point, Serra
564	SAN	29	DCS	19	PTI	11	SNC-SNP	SC	Meet 567, Control Point, serra
566	SAN	44	PTI	34	PTI	34	SNC-SNP	SC	Meet 769, Control Point, Serra
567	LAX	23	CTI	22	CTI	15	FUL-XRJ	BN	Follow SCAX, ML 707, Milepost, 163.4, 144.5
572	SAN	95	ENG	39	ENG	39	LAX-LAX	SC	PTC issue initially engine would not restart once we got it started. We were having a door issues because battery was low and then unable to do a load test due to doors got that fixed and then train line out of track 12 got that resolved. C2114
573	LAX	27	DCS	17	DCS	14	OSD-X98	SN	Restrictive signal(s) from known wayside signal failure Flagging to X98, Stop, Control Point, Songs
579	LAX	24	PTI	17	PTI	10	OSD-X98	SN	Meet 572, Control Point, Pulgas
581	LAX	26	WTR	19	WTR	14	OSD-X98	SN	Flood / washout Control Point, songs
584	SAN	55	PTI	46	PTI	37	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
587	LAX	31	WTR	30	WTR	30	OSD-OSD	SN	High tides affecting signal system between cp songs and cp pier. Held at OSD station since 782 and metrolink both south bound train were going through single tracks. Wait at platform instead of the waiting at songs to let passengers exit train if they want to, Control Point, shell
588	SAN	37	PTI	34	PTI	34	SNC-SNP	SC	Meet 591, Siding, Serra

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
591	LAX	48	DMW	18	DMW	17	OSD-X98	SC	Held for or routed around MW work or equipment Held at Songs while track inspector evaluates track conditions ahead, Control Point, songs
593	LAX	61	PTI	42	PTI	40	OSD-X98	SN	Meet Met Amtrak 588 at CP Pulgas due to single tracking caused by BNSF local on Main 2 between Songs and Don., 588, Control Point, Pulgas
595	LAX	44	PTI	21	PTI	21	OSD-X98	SN	Meet 790, Control Point, song
757	GTA	149	CTI	129	CTI	114	VNC-NRG	SC	Meet Disabled at NRG, eventually they had MLTK 104 hookup and tow them out of the way., mltk, 102, Milepost, 455, 453
761	GTA	46	PTI	26	CTI	25	VNC-NRG	SC	Meet Held at CP Raymer to allow delayed Metrolink train pass due to disabled Metrolink 102, Metrolink, 106, Control Point, Raymer
765	GTA	30	PTI	22	DCS	15	OSD-X98	SC	CTC system failure Flag, Control Point, songs
769	GTA	53	PTI	29	PTI	26	OXN-VEC	UP	Meet 782, Control Point, N ventura
774	SAN	54	PTI	51	PTI	21	SNC-SNP	SC	Follow 572, Other, snc-snp
777	GTA	28	PTI	26	PTI	20	OXN-VEC	UP	Meet 790, Siding, vec
782	SAN	31	PTI	60	PTI	27	SNC-SNP	SC	Meet 785, Control Point, serra
786	SAN	24	WTR	34	WTR	14	SNP-X98	SC	Flood / washout Control Point, pier
790	SAN	60	PTI	52	PTI	46	SNC-SNP	SC	Meet 593, Other, serra
794	SAN	63	WTR	72	WTR	56	SNC-X98	SC	High tides causing trains to flag at cp pier Control Point, pier
702	BFD	113	TRS	95	TRS	95	MDR-FNO	BN	Trespasser strike Other, MP 1004.5
713	OKJ	Trn Cancelled							
717	OKJ	Trn Cancelled	ITI	99	ITI	99	BFD-BFD	BN	Late departure at initial terminal due to late arrival of inbound equipment 702, And coupling into 713 to deadhead equipment
3	LAX	193	FTI	88	TRS	56	KNG-NDL	BN	Red signal. Service interruption; freight stopped and raided by thieves. Many trains backed up on both tracks On restricted (red) signal, train ahead., Other, ., After 5087 got started slowly with remaining units, met 6267 E, 7798 E, 7102 E, 7109 E, Amtrak 3, and 7793 E before getting a clear s
306	CHI	33	FTI	53	FTI	40	SMT-XTF	CC	Cross Traffic NA, Control Point, Brighton

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/22/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
307	STL	54	FTI	28	CAR	24	PON-BNL	UP	Air / Brake / Wheel ID4303, Replace air hose
380	CHI	22	DSR	30	DSR	15	MAC-GBB	BN	Per bulletin Other, new long east, 10, m2
383	QCY	18	FTI	18	FTI	10	PLO-MDT	BN	Meet Control Point, Electrics, BN 6861
392	CHI	36	FTI	34	FTI	28	MAT-CHM	CC	Follow Follow CN 2987 from South Humboldt to South Tuscola, CN2987, Control Point, South Humboldt, Control Point, South Tuscola
393	CDL	22	DSR	26	DSR	16	CHM-MAT	CC	Per bulletin Milepost, 135.45, 136.65, 30, main, Milepost, 150.7, 159.2, 28, main 1 / main, Milepost, 161.26, 162.9, 25, main
311	KCY	28	FTI	39	FTI	39	WAR-LEE	UP	Follow Follow and then shuffle at Pleasant Hill train too long for siding, UP 8215, Siding, Centerview, Siding, Pleasant Hill
318	CHI	41	FTI	31	FTI	12	WAR-SED	UP	Meet 8215, Siding, dresden
1333	MSP	45	ENG	42	ENG	39	RDW-XH8	CP	Cab signal failure 63

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/22/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	10/21	12	12	Fuel Fuel and normal cut
ALX	1095	10/22	10	10	Late departure at initial terminal due to late arrival of inbound equipment 1078, Late inbound train 178 from RNK
ALX	1179	10/22	3	3	High passenger count 160 on
ATL	19	10/21	12	12	Follow 241, Milepost w/Letters, Atlanta station, 633.5
BON	687	10/22	23	23	Late departure at initial terminal due to late arrival of inbound equipment 686
BOS	67	10/22	13	13	Late departure at initial terminal due to late arrival of inbound equipment, 1164, late turn of AM1164
BOS	1167	10/22	19	19	Switch private or office cars, delayed out of BOS due to coaches removed
BRK	682	10/22	1		
HAR	642	10/22	2	2	Other electrical failure, 620|EX|ES, door bypass
HAR	650	10/22	2	2	Door, ENTIRE CONSIST, DOOR BYPASS CUT OUT
HAR	654	10/22	1	1	Passenger and/or baggage
HFD	471	10/22	6	6	Late departure at initial terminal due to late arrival of inbound equipment, 426, Late turn of equipment
NFK	1094	10/22	20	20	Issue with setting the trailing unit 204
NHV	470	10/22	16	16	Late departure at initial terminal due to late arrival of inbound equipment, 471, SHORT TURN OF 471
NHV	494	10/22	44	44	Late departure at initial terminal due to late arrival of inbound equipment, 417, late turn of AM417
NYP	49	10/22	2	2	Passenger and/or baggage, BOARDING
NYP	233	10/22	7	7	Late departure at initial terminal due to late arrival of inbound equipment, 236, LATE TURN OFF AM236
NYP	1097	10/22	13	13	Passenger and/or baggage, BOARDING
NYP	1103	10/22	4	4	Passenger and/or baggage, BOARDING
NYP	1169	10/21	2		
NYP	2105	10/22	2	2	Passenger and/or baggage, BOARDING
PGH	40	10/21	12	12	Scheduled shove move station track 4 - 1 at Penn and Solomon. Conductor working alone.
PHL	601	10/22	3	3	PTC - Stop Bypass Permission Required, Control Point, .
PHL	653	10/22	2	2	High passenger count, PER DSPR; 652P
PHL	657	10/22	21	21	Hold for connecting train, HELD OF PASSENGER FROM TRAIN 1165
RGH	79	10/22	65	65	PTC problem or failure (cause unknown) Other, Raleigh Station

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/22/2026

Terminal	Train	Date	Late	Delay	Cause
SFA	52	10/22	68	23	Meet CFRC, 326, Control Point, XSF
SFA	52	10/22	68	48	Late departure at initial terminal due to late arrival of inbound equipment 53
TWO	64	10/22	4		
WAS	1080	10/22	(No OS)		
WAS	1152	10/22	48	48	HEP, 670|EX|ES, MTR 670 SHOPPED FOR HOT BEARINGS.
WAS	2122	10/22	2	2	Passenger and/or baggage, BAGGAGE ASISTANCE AND TRAVEL
CHI	354	10/22	188	188	PTC - On Board Cab Signal or PTC Failure Itcs connection issue, ID4614
DET	355	10/22	32	12	(Scheduled departure time is 5:51pm. Actual delay is 32 minutes) Late arrival of AMT 350 due to earlier service disruption of AMT 351. Also wait for bus from PNT, TRM, and PNT. Other, DET
PNT	351	10/22	86	86	Late departure at initial terminal due to late arrival of inbound equipment 354, Due to vehicle strike of 351 which took place on October 21 . Held up all trains
PNT	353	10/22	154	154	RR blocked by trespasser or vehicle strike by another train
PTH	365	10/22	173	173	Set out defective car NOCAR, Car number 4004 also conductor was working alone
BFD	713	10/22	(Trn Cxld)		Third Party Engine Failure
BFD	717	10/22	99	99	Late departure at initial terminal due to late arrival of inbound equipment 702, And coupling into 713 to deadhead equipment
GTA	774	10/22	155		
GTA	782	10/22	26	9	Wait for station track Held at Ellwood sidings to allow AMTK 14 to pass, AMTK 14, Control Point, CO 358
GTA	782	10/22	26	17	Meet Held siding at Elwood to allow AMTK 765 enter spur at Goleta, AMTK 765, Control Point, CO358
GTA	786	10/22	18		
GTA	794	10/22	3	1	Late departure at initial terminal due to late arrival of inbound equipment 777
LAX	14	10/22	5	5	Restrictive signal(s) from unknown cause Train departed on time but Metrolink dispatcher was out of contact and hadn't lined us up., Stop, Other, track 10
LAX	572	10/22	39	39	PTC issue initially engine would not restart once we got it started. We were having a door issues because battery was low and then unable to do a load test due to doors got that fixed and then train line out of track 12 got that resolved. C2114
OKJ	532	10/22	5	5	Welding/repairing shock mount causing delay informed operations West Danielle of said delay C8201
SAC	523	10/22	1	1	Loading problem C2005
SAC	527	10/22	14	14	Unplanned Wye
SAC	537	10/22	1		
SAC	541	10/22	6	6	Train would load, engine would rev up, but the train would not move. JPBX921

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/22/2026

Terminal	Train	Date	Late	Delay	Cause
SAN	595	10/22	12	12	Late departure at initial terminal due to late arrival of inbound equipment 584
SAN	785	10/22	14	14	Late departure at initial terminal due to late arrival of inbound equipment 774
SEA	503	10/22	11	11	Was held at Lander by sounder 322 had to wait until sounder landed on track 207 before we could exit Lander and go to KS five sounder, 322, Other, Yard
SJC	530	10/22	4	4	Door JPBX922, All doors on the entire train doors are closed. We get no door light.

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	99.3	94.8	342	3
CDOT	95.0	95.8	89.6	92.4	24	1
MARC	95.0	89.7	87.0	90.2	58	6
SEPTA	95.0	84.7	88.8	91.5	216	33
NJT-NED	95.0	89.5	90.9	88.6	200	21
NJT-SED	95.0	100.0	98.7	97.2	24	0

Operating Highlights

Train 53(22) South of Fayetteville, NC - Freight Train Interference

23OCT26: Train 53(22) operating with engines 354, 336, and 490 customers onboard was delayed 6 miles south of Fayetteville, NC on the CSX South End subdivision operating through freight train interference caused by a track side fire located at milepost 243.6. Train 53(22) operated restricted speed through the freight congestion from milepost 207.6 until milepost 218.7.

Train	Delay	Comment
53(22)	40"	

Train 67(22) New York, NY - Engine Failure

23OCT26: Train 67(22) operating with engines 617, 664, and 341 customers onboard was delayed departing New York Penn Station due to loss of head end power upon arrival on engine 617. New York mechanical was able to short loop engine 664 to resolve the issue and the train was able to depart. Customers destined to Philadelphia, PA or any stops prior were given the option to travel on train 1169(22).

Train	Delay	Comment
67(22)	56"	

Train 79(22) Raleigh, NC - Engine Failure

22OCT26: Train 79(22) operating with engine 379 and 80 customers onboard was delayed departing Raleigh, NC on the Norfolk Southern H Line due to PTC issues that were resolved by receiving new paperwork from the host dispatch.

Train	Delay	Comment
79(22)	1'05"	

Train 494(22) New Haven, CT - Servicing

22OCT26: Train 494(22) operating with engine 125 and 37 customers onboard was delayed departing New Haven, CT due to short turn of equipment from inbound train 417(22) which arrived after 494(22) scheduled departure.

Amtrak NHB Line - East of New London, CT - Temporary Speed Restrictions

22OCT26: Multiple trains were affected due to a track occupancy light that appeared at approximately 5:30 p.m. at Mystic River interlocking milepost 131.9 located 9 miles east of New London, CT. TOLs were cleared at approximately 7:48 p.m.

Train	Delay	Comment
1088(22)	30"	
1167(22)	1'14"	
1082(22)	06"	
1194(22)	11"	

Train 49(22) North of Poughkeepsie. NY - Truck Bolster Fire

22OCT26: At 5:25 p.m train 49(22) operating with engine 715 and 191 customers onboard stopped 2.5 miles north of Poughkeepsie, NY on the MNRR Hudson Line at milepost 76.0 due to a bolster fire on the b-end truck of car 68003. The crew brought down head end power while working under and around the equipment. The ambient temperature was 64 degrees and the weather was clear. The crew, Metro North personnel, and Albany mechanical were unsuccessful in extinguishing the bolster fire and contacted the local fire department to assist. Amtrak management responded to the scene at approximately 7:00 p.m. Upon arrival, the local fire department set up their equipment and was able to successfully extinguish the fire. Train 237(22) held south of train 49(22) until the scene was cleared by the fire department and rail travel could resume.

Train	Delay	Comment
49(22)	1'45"	
237(22)	48"	

Train 52(22) Sanford, FL - Initial Terminal Delay

22OCT26: Train 52(22) operating with engines 360, 352, 48 cars, and 244 customers onboard was delayed departing Sanford, FL on CFRC Territory due to turn of late equipment from Train 53(21).

Train	Delay	Comment
52(22)	48"	

Train 486(22) New Haven, CT - Hold for Connection

22OCT26: Train 486(22) operating with engine 87, 1 car, cab car 9635, and 24 customers onboard was delayed departing New Haven, CT on the Metro North New Haven Line due to holding for connections from late Train 1164(22) that arrived in New Haven at 3:37 PM-ET. Once the connections were boarded, Train 486(22) departed the station.

Train	Delay	Comment
486(22)	35"	

Train 686(22) South of Portland, ME - I-ETMS Failure - Signal

22OCT26: Train 686(22) operating with cab car 90224, 5 cars, engine 99, and 69 customers onboard was delayed at milepost 13.4, 2 miles south of Portland, ME on the CSX Portland subdivision due to a Red Fence/ Signal Status Unknown issue with the I-ETMS system. The crew was able to troubleshoot the issue and was back on the move.

Train	Delay	Comment
686(22)	39"	
683(22)	36"	

Train 68(22) North of Rouses Point, NY - Freight Train Interference

22OCT26: Train 68(22) operating with engine 115, 5 cars, and 87 customers onboard was delayed beginning at milepost 1.2, 1 mile north of Rouses Point, NY on the Canadian National Roues Point subdivision due to following freight train 528. Once the freight train cleared, Train 68(22) advanced to the next station.

Train	Delay	Comment
68(22)	49"	

PW Line Phil Interlocking Track Occupancy Light - Vandalism - Trespasser Incident

22OCT26: At 6:30 AM-ET, it was reported that there was a track occupancy light on all tracks in Phil Interlocking at milepost 5 on the Amtrak PW Line. Communications and Signals responded to the scene as well as Amtrak Police Department. It was reported that the wire in the area had been vandalized and cut. All trains scheduled to operate through the area were delayed due to getting Rule 241 through.

Train	Delay	Comment
2106(22)	21"	
1152(22)	15"	
1164(22)	18"	
1155(22)	17"	
1103(22)	19"	
2150(22)	18"	
2105(22)	13"	
2148(22)	33"	
1153(22)	14"	
1111(22)	18"	
56(22)	21"	
2103(22)	14"	
1098(22)	17"	
1079(22)	11"	
2101(22)	13"	
1162(22)	14"	
1109(22)	10"	
1160(22)	15"	
1082(22)	18"	
1118(22)	21"	
1127(22)	21"	
1143(22)	17"	
2149(22)	14"	
1088(22)	16"	
1195(22)	14"	
2151(22)	16"	
2152(22)	18"	
2133(22)	15"	
1140(22)	13"	
2114(22)	16"	
2116(22)	11"	
1099(22)	12"	
1194(22)	15"	
1147(22)	12"	
1161(22)	15"	
1019(22)	09"	
2123(22)	14"	
1020(22)	05"	
1097(22)	05"	
1116(22)	06"	
2118(22)	06"	
1156(22)	05"	

Train 98(22) North of West Palm Beach, FL - Occupied Vehicle Strike - Trespasser Incident

22OCT26: At approximately 8:43 AM-ET, Train 98(22), operating with engines 330, 319, 6 cars, and 73 customers, struck an occupied vehicle at DOTX crossing 628119K at MP 968.2 on SFRTA. The train remained intact on the rails with head-end power (HEP) available. The weather was reported as 73°F and cloudy. There were no reported injuries to the crew or customers, and the strike was non-fatal. The crew requested relief. The train sustained damage to a communication cable receptacle. Emergency services responded to the scene. Train 98(22) advanced to Mangonia Park (MP 966.4), where local management and mechanical responded. Mechanical was able to secure the damaged part of the equipment. Train 98(22) resumed operation at 12:07P-ET.

National Response Center Number: 1476778

Train	Delay	Comment
98(22)	3'25"	

Train 1152(02) Washington, DC - Initial Terminal Delay - Engine Failure

22OCT26: Train 1152(22) operating with engine 670, 8 cars, and 163 customers was delayed departing Washington, DC on the Amtrak WT Line due to engine 670 being shopped for hot bearing alarms. The engine was removed from the consist and replaced with engine 655. Once the new engine was added and all necessary tests complete, Train 1152(22) departed Washington at 9:10 AM-ET.

Train	Delay	Comment
1152(02)	48"	

Washington Terminal 'A' Interlocking - Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, Northeast Regional Services - M of W Work

05OCT26: Due to Diamond Replacement at Washington Terminal 'A' interlocking from Friday, October 16, 2026 to Monday, October 26,2026. There will be several service adjustments made to the following services Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services will be adjusted as follows:

PALMETTO
Northbound
- Train 90 (16Oct-26Oct) is canceled in its entirety.
- Train 1090 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between SAV and WAS.

Southbound
- Train 89 (15Oct-25Oct) is canceled in its entirety.
- Train 1089 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and SAV.

CARDINAL
Eastbound
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct), which normally operates between CHI and NYP, will terminate at IND.

Westbound
- Train 51 (18Oct, 21Oct, 23Oct, 25Oct), which normally operates between NYP and CHI, will originate at IND.

EQUIPMENT
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct) will turn for Train 51 (18Oct, 21Oct, 23Oct, 25Oct) at IND.

Northbound
• Train 20 (16Oct-25Oct), which normally operates between NOL and NYP, will terminate at ATL.
• Train 1020 (17Oct-25Oct) will operate and provide service between WAS and NYP.
• There will be no service between ATL and WAS.
Southbound
• Train 19 (16Oct-25Oct), which normally operates between NYP and NOL, will originate at ATL.
• Train 1019 (17Oct-25Oct) will operate and provide service between NYP and WAS.
• There will be no service between WAS and ATL.
EQUIPMENT
• Train 20 (16Oct-25Oct) will turn for Train 19 (16Oct-25Oct) at ATL.
o (Note: Train 19's departure days from ATL are 17Oct-26Oct)

SILVER METEOR
Northbound
• Train 98 (16Oct-25Oct), which normally operates between MIA and NYP, will terminate at JAX.
• Train 1098 (17Oct-25Oct) will operate and provide service between WAS and NYP.
• There will be no service between JAX and WAS.
Southbound
• Train 97 (16Oct-25Oct), which normally operates between NYP and MIX, will originate at JAX.
• Train 1097 (17Oct-25Oct) will operate and provide service between NYP and WAS.
• There will be no service between WAS and JAX.
EQUIPMENT
• Train 98 (16Oct-25Oct) will turn for Train 97 (16Oct-25Oct) at JAX.
o (Note: Train 97's departure days from JAX are 17Oct-26Oct)

FLORIDIAN
Northbound
• Train 40 (16Oct-24Oct), which normally operates between MIA and CHI, will originate at PGH.
• Train 1040 (17Oct-24Oct) will operate and provide service between MIA and JAX.
• There will be no service between JAX and PGH.
Southbound
• Train 41 (16Oct-24Oct), which normally operates between CHI and MIA, will terminate at PGH.
• Train 1041 (18Oct-25Oct) will operate and provide service between JAX and MIA.
• There will be no service between PGH and JAX.
EQUIPMENT
• Train 41 (16Oct-24Oct) will turn for Train 40 (16Oct-24Oct) at PGH
o (Note: Train 40's departure days from PGH are 17Oct-25Oct)

• Train 1040 (17Oct-24Oct) will turn for Train 1041 (18Oct-25Oct) at JAX

CAROLINIAN
Northbound
• Train 80 (17Oct-25Oct), which normally operates between CLT and NYP, will terminate at RGH.
• Train 1180 (17Oct-25Oct) is a new train that will operate between RGH and ALX, departing RGH at 11:00am.
• Train 1080 (17Oct-25Oct) is a new train that will operate between WAS and NYP, departing WAS at 5:15pm.
Southbound
• Train 79 (17Oct-25Oct), which normally operates between NYP and CLT, will originate at RGH.
• Train 1079 (17Oct-25Oct) is a new train that will operate between NYP and WAS, departing NYP at 7:05am.
• Train 1179 (17Oct-25Oct) is a new train that will operate between ALX and RGH, departing ALX at 1:00pm.
ALTERNATE TRANSPORTATION
• Train 1180 (17Oct-25Oct) will connect to Bus 1480 (17Oct-25Oct) at ALX
• Train 1079 (17Oct-25Oct) will connect to Bus 1479 (17Oct-25Oct) at WAS
EQUIPMENT

- Train 1179 (25Oct) will turn at RGH for Deadhead Train 80 to operate to WAS
- Northeast Regional Train 1094 (17Oct-25Oct) will make a same day turn at ALX for Train 1179 (17Oct-25Oct)
- Train 80 (17Oct-25Oct) will make a same day turn at RGH for Train 79 (17Oct-25Oct)

NORTHEAST REGIONAL
Norfolk
- Train 1094 (17Oct-25Oct) will operate between NFK and ALX
- Train 1095 (17Oct-25Oct) will operate between ALX and NFK

Roanoke
- Train 1071 (17Oct-25Oct) will operate between ALX and RNK
- Train 1078 (17Oct-25Oct) will operate between RNK and ALX

Newport News
- Train 65 (16OCt), which normally operates between BOS and NPN, will terminate at PHL.
- Train 65 (17Oct, 23OCt-24Oct), which normally operates between BOS and NPN, will terminate at WAS.
- Train 67 (15OCt, 18Oct-22Oct), which normally operates between BOS and NPN, will terminate at WAS.
- Train 67 (25Oct), which normally operates between BOS and NPN, is canceled in entirety with no alternate transportation.

ALTERNATE TRANSPORTATION
- Bus 1495 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1095 (17Oct-25Oct) at ALX
- Train 1094 (17Oct-25Oct) will connect to Bus 1494 (17Oct-25Oct) at ALX
- Bus 1471 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1071 (17Oct-25Oct) at ALX
- Train 1078 (17Oct-25Oct) will connect to Bus 1478 (17Oct-25Oct) at ALX
- Bus 1454 (17-Oct- 25Oct) will operate RNK - LYH - WAS.
- Bus 1455 (17-Oct- 25Oct) will operate WAS - LYH - RNK.
- Bus 1456 (17-Oct- 25Oct) will operate CVS - WAS
- Bus 1457 (17-Oct- 25Oct) will operate WAS - CVS

ALX-WAS Buses will unload in front of Union Station utilizing the middle lane of Columbus Circle, with WAS-ALX buses boarding up on the Union Station bus deck
EQUIPMENT
- Carolinian Train 1180 (17Oct-25Oct) will make a same day turn at ALX for Train 1071 (17Oct-25Oct)
- Train 1071 (17Oct-24Oct) will turn for Train 1078 (18Oct-25Oct) at RNK
- Train 1071 (25Oct) will turn for Train 156(26Oct) at RNK
- Train 1078 (17Oct-25Oct) will make a same day turn at ALX for Train 1095 (17Oct-25Oct)
- Train 1095 (17Oct-24Oct) will turn for Train 1094 (18Oct-25Oct) at NFK
- Train 1095 (25Oct) will turn for Train 94 (26Oct) at NFK

WBS#: B.TR.100151.0856

Maintenance of Way Highlights

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:
- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION
- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

	Projected Need		Number Operated			
Train	Cars	Seats	Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

Train 354(22) West of New Buffalo, MI - Freight Train Interference

23OCT26: Train 354(22) was delayed at MP507.6, 46.54 miles west of New Buffalo MI station on the Norfolk Southern Chicago 76 subdivision meeting CPKC freight train 8796. Train 354(22) was back on the move at 224AM ET after the freight cleared.

Train	Delay	Comment
354(22)	38"	

Train 306(22) South of Chicago, IL - Freight Train Interference

23OCT26: Train 306(22) was delayed holding at Brighton/MP5.1, 4.91 miles south of Chicago IL station on the CN Freeport subdivision due to meeting multiple CN freight trains. Train 306(22) was back on the move at 1059PM CT.

Train	Delay	Comment
306(22)	40"	

Train 6(22) West of Elko, NV - Wayside Detector

23OCT26: Train 6(22), operating with engines 69/146, 8 coaches, and 100 customers, was delayed 111 miles west of Elko, NV, on UP Shafter subdivision, due to a wayside dragging detector alarm. This required the crew to do a visual inspection of the equipment as well as a rollby to ensure there was nothing dragging on the equipment. After all the necessary tests were complete and the crew found now exceptions, train 6(22) was able to proceed.

Train	Delay	Comment
6(22)	37"	

Train 508(22) North of Kelso-Longview, WA - Freight Train Interference

23OCT26: Train 508(22), operating with engine 7001, 7 coaches, and 183 customers was delayed 25 miles north of Kelso, WA, on BNSF Seattle subdivision, due to meeting multiple freights.

Train	Delay	Comment
508(22)	35"	

Train 14(22) North of Salinas, CA - Signal

23OCT26: Train 14(22), operating with engines 318/322, 9 coaches, and 243 customers, was delayed 7 miles north of Salinas, CA, on UP Coast subdivision, due to wayside signal failure requiring flagging through the affected area.

Train	Delay	Comment
14(22)	33"	

Train 1333(22) East of St. Paul-Minneapolis, MN - Engine Failure

22OCT26: Train 1333(22) was delayed at MP378.7, 33.3 miles east of St. Paul-Minneapolis, MN station on the CPKC River subdivision due to cab signal faults on engine 63. Crew spoke with CNOC mechanical who advised them to reset the PTC breakers. The fault was cleared after resetting the breakers and train 1333(22) was back on the move at 702PM CT.

Train	Delay	Comment
1333(22)	39"	

Train 3(21) East of Gallup, NM - Weather

23OCT26: Train 3(21), operating with engines 40/179, 9 coaches, and 181 customers, was delayed 91 miles east of Gallup, NM on BNSF Gallup subdivision, due to severe weather causing flash flood restrictions from milepost 75.1 to milepost 80.5. Train 3(21) was required to operated at a reduced speed until clear of the affected area.

Train	Delay	Comment
3(21)	45"	

Train 19(21) North of Meridian, MS - Freight Train Interference

22OCT26: Train 19(21) was delayed holding at MP294.8, .2 miles north of Meridian MS station on the Norfolk Southern AGS South subdivision due to a meet with Norfolk Southern freight train 29S.

Train	Delay	Comment
19(21)	31"	

Train 59(21) North of Hammond, LA - Passenger Train Interference

22OCT26: Train 59(21) was delayed holding at the Arcola siding/MP840, 21.7 miles north of Hammond LA station on the CN McComb subdivision meeting Amtrak 58(22). Train 59(21) was back on the move at 327PM CT after 58(22) cleared to the north.

Train	Delay	Comment
59(21)	37"	

Train 516(22) Vancouver, BC - Commuter Train Interference

23OCT26: Train 516(22), operating with engine 1401, 7 coaches and 132 customers, was delayed .5 miles outside vancouver, BC, on CN New Westminster subdivision, due to meeting VIA rail train 6420.

Train	Delay	Comment
516(22)	40"	

Train 516(22) South of Vancouver, BC - M of W Work

22OCT26: Train 516(22) operating with locomotive WS1401, 6 cars and NPCU 90252 was delayed 36 miles south of Vancouver, BC at MP 119 on the BNSF Bellingham subdivision due to MOW workers failing to clear up before train arrival. BNSF crews were working to get track equipment back on the tracks requiring train 516(22) to hold for clearance. Once the equipment was rerailed and track authority was returned train 516(22) was able to proceed without further delay.

Train 311(22) West of Warrensburg, MO - Freight Train Interference

22OCT26: Train 311(22) was delayed starting 7 miles west of Warrensburg, MO (MP218.5), on the UPRR Sedalia Subdivision, following UP 8215 from Centerview (MP225.5) to Pleasant Hill (MP249.8).

Train	Delay	Comment
311(22)	39"	

Train 572(22) Los Angeles, CA - Engine Failure

22OCT26: Train 572(22), E/C2114-5 cars- CC/C6952, was delayed departing Los Angeles, CA due to locomotive issues on E/C2114. The crew could not restart the locomotive once it shut down. The crew held with 101 customers on board for Los Angeles mechanical to respond and troubleshoot. Once locomotive issues were resolved, the crew was unable to perform a load test due to door issues. Once all issues were resolved, Train 572(22) departed.

Train	Delay	Comment
572(22)	39"	

Train 702(22) North of Fresno, CA - Trespasser Strike

22OCT26: Train 702(22) at 10:20am-pt operating with locomotive C2108, 7 cars and NPCU 90278 in lead fatally struck a trespasser 2 miles north of Fresno, CA at MP 100.4 on the BNSF Stockton subdivision. This incident occurred in the city of Fresno, CA in Fresno County. There were no reports of injuries to the customers or crew and no reported damages to infrastructure or equipment. The onboard Engineer and Conductor did request relief and A recrew Engineer was ordered from Merced to report to the Fresco. The Assistant Conductor was moved up to the position of Conductor for the remainder of the trip. Local responders and an Amtrak Road Foreman responded to the location and the authorities conducted the necessary investigation and once completed released the train back into service. The crew advanced the train to Fresno and once the recrew Engineer was onboard train 702(22) was able to proceed without further delay.

As a result of the late operation of train 702(22) the turn of equipment resulted in an initial terminal delay to train 717(22).

WBS#: **B.TR.100150.7295**

National Response Center Number: **1476801**

Train	Delay	Comment
702(22)	1'35"	
702(22)	15"	Recrew job briefing
710(22)	26"	Hold MDR
717(22)	1'39"	Late turn of 702(22)

Train 11(22) Portland, OR - Freight Train Interference

23OCT26: Train 11(22), operating with engines 343/350, 9 coaches and 202 customers, was delayed departing Portland, OR, on UP Brooklyn subdivision, due to holding for UP7464 to clear ahead of them. Once the freight cleared and a route was made available, train 11(22) was able to proceed.

Train	Delay	Comment
11(22)	35"	

Train 21(21) East of Mineola, TX - Freight Train Interference

22OCT26: Train 21(21) held 23.2 miles east of Mineola, TX (MP136.1), on the UPRR Mineola Subdivision, at Big Sandy (MP112.9) in order meet UP 6309.

Train	Delay	Comment
21(21)	49"	

Train 23(22) Gulfport, MS - Freight Train Interference

22OCT26: Train 23(22) was delayed on the CSX NO&M Subdivision following CSX 605 from Gulfport, MS (MP739.4) to SE Harbin (MP746.8).

Train	Delay	Comment
23(22)	54"	

Train 8/28(21) West of Whitefish, MT - Freight Train Interference

22OCT26: Train 8/28(21) operating with locomotives 339-310, 9 cars and 65 customers was delayed 5 miles west of Whitefish, MT at MP 1224 on the BNSF Kootenai River subdivision due to freight train interference meeting BNSF 8393 at Vista. Once the freight was clear and an open route was established train 8/28(21) was able to proceed without further delay.

Train	Delay	Comment
8/28(21)	32"	

Train 4(21) East of Kingman, AZ - Freight Train Interference

22OCT26: Train 4(21), operating with 128 customers, was delayed starting at MP 511.5, 5 miles east of Kingman, AZ, on the BNSF Seligman Subdivision due to freight interference. The crew followed BNSF 7798 from MP 511.5 until West Pica/MP 446.8. The crew was further delayed following BNSF 7195 starting at West Doublea/MP 395.2 until Flagstaff/MP 344.2 where they were able to operate around.

Train	Delay	Comment
4(21)	1'12"	

Train 713(22) Bakersfield, CA - Engine Failure

22OCT26: Train 713(22) scheduled to operate with locomotive C2101 and 7 cars was cancelled in its entirety due to locomotive failure of C2101 prior to departure. It was necessary to have train 717(22) equipment double up to the set and tow the equipment Bakersfield to Oakland for repair.

Train	Delay	Comment
713(22)	Cancelled	

Train 770(22) Santa Barbara, CA - Weather

22OCT26: Train 770(22), with 70 customers on board, was delayed departing Santa Barbara, CA/ MP 367.2 on the UPRR Santa Barbara Subdivision due to trees on the tracks ahead at MP 376.1. The crew held at station for UPRR personnel to respond to scene and remove the fallen trees. Once the trees were cleared and the tracks were reopened, Train 770(20) departed.

Train	Delay	Comment

Train 757(22) South of Los Angelos, California - Commuter Train Interference

22OCT26: Train 757(22) operating with locomotiveC2111, 6 cars and 15 customers was delayed 4 miles south of Northridge Station at MP 453 on the SCRRA Ventura subdivision due to disabled Metrolink 102 ahead. A rescue locomotive was required to be dispatched to rescue train 102 and pull it clear of the main line. Once train 102 was clear an open route was established and train 757(22) was able to proceed.

As a result of the late operation of train 757(22) the turn of equipment resulted in an initial terminal delay to train 774(22) at Goleta. An on-time section was utilized to represent 774(22) Los Angeles to San Diego.

Train	Delay	Comment
757(22)	1'54"	
774(22)	2'33"	Initial terminal delay

Train 821(22) Pauls Valley, OK - Signal

22OCT26: Train 821(22) was delayed 1.9 miles south of Pauls Valley, OK (MP495.5) on the BNSF Red Rock Subdivision flagging through a track indication at South Pauls Valley (MP493.6). Once clear of the affected area, the train resumed operating at authorized track speed.

Train	Delay	Comment
821(22)	36"	

Train 351(22) West of Dearborn, MI - Trespasser Incident

22OCT26: Around 8:30AM-ET, Train 351(22) E/ID4608-5 Cars and 136 customers onboard struck an occupied flatbed truck carrying dumpsters at the South Merriman Road Crossing/MP15.6 (DOT#545184J) in Wayne, MI, Wayne County. The incident occurred 5.9 miles west of the Dearborn, MI station (MP9.7), on the Michigan DOT Michigan Line on Main Track 1. The crossing was equipped with ample protection at the time of the incident. Weather conditions were reported as 44 degrees and sunny. The truck became lodged beneath the locomotive, fouling both main tracks and resulting in the suspension of rail traffic through the area until cleared. The train remained intact and on the rail; however, engine ID4608 sustained extensive front-end damage and shut down, resulting in the loss of head-end power. Police, fire, and EMS personnel responded quickly to the scene. Amtrak Transportation management, Mechanical forces, APD, and track personnel also responded to assist with the incident and recovery efforts. A signal maintainer inspected the crossing and reported no apparent damage. At 11:00AM, a wrecker was on location with the expectation of a route on Main Track 2 by 12:00PM. There was difficulty getting the scene cleared. At 2:12PM, Main Track 2 was released for movement.

Two customers initially reported non-life-threatening injuries but did not identify themselves for evaluation by EMS. Additionally, one customer initially reported as experiencing a panic attack but declined EMS assistance and recovered without further medical intervention. Two additional customers later reported minor injuries and were evaluated by EMS. The onboard LSA was evaluated by local EMS for minor injuries and was expected to travel by bus upon arrival in Chicago. The crew requested trauma relief following the incident. Service recovery measures were implemented with snack packs, bottled water, and non-perishable items distributed onboard.

Train 351(22) was terminated at the incident location with five buses secured. Bus#1 arrived train side at 11:30AM and departed at 12:09PM making local stops to Chicago. Bus #2 departed train side at 12:10PM express to Chicago. A third train side bus arrived at 12:17PM but was not needed and routed instead to Pontiac to assist in Trains 350(22) and 355(22) bus bridge between Detroit and Pontiac. Two additional buses were secured for downline customers boarding between Ann Arbor and Chicago.

Train 353(22), with 14 customers onboard, was held at Pontiac, MI for disposition. At

Train 350(22), with 190 customers onboard, was held at Niles, MI, awaiting a relief crew positioned at Battle Creek, MI, for transportation to the scene and subsequent coordination of train movements while avoiding blocked crossings. The recrew was on duty at 11:00AM-ET to van to Battle Creek arriving at 1:45PM. Train 350(22) as released at 12:49PM to continue east. Due to the lengthy delay, Train 350(22) was later terminated at Detroit, MI with one alternate bus secured making all stops to Pontiac.

Train 352(22), with 255 impacted customers, was cancelled entirely with five alternate buses secured between Chicago, IL and Pontiac, MI.

Train 355(22) originated at Detroit, MI with one alternate bus for the affected customers between Pontiac and Detroit.

Train 354(22) was delayed departing Chicago, IL due to a late turn of Train 353(22)'s equipment that arrived at 715PM CT. Train 354(22) originally departed Chicago IL station at 858PM CT and went to diesel pit to correct an ITCS paperwork error. Due to the paperwork error engine ID4620 ITCS was re-tested and failed to pass. Technicians from the yard and responded to help the crew troubleshoot. An antenna extender was added but failed the ITCS test again. Crew was re-spotted and the test was attempted again. Test failed at the re-spot and the decision was made to wye the train. Train 354(22) completed the wye and departed at 1225AM ET operating 6 hours and 25 minutes late.

As a result of ID 4207 ITCS failure train 351(23) was cancelled in it's entirety with no alternate transportation. Customers notified to re-book on train 353(23).

WBS#: **B.TR.100150.7291**

National Response Center Number: **1476783**

Train	Delay	Comment
351(22)	TERM DER	
350(22)	TERM DET	
353(22)	2'24"	PNT - Hold
353(22)	1'37"	DER - Hold
352(22)	Cancelled	
350(22)	3'20"	NLS - Hold
354(22)	3'08"	ITD CHI - Turn of 353(22)
355(22)	32"	ORIG DET
354(22)	3'26"	ITCS Failure
351(23)	Cancelled	

Train 14(21) South of Redding, CA - Trespasser Strike

22OCT26: Train 14(21) operating with locomotives 327-338, 9 cars and 203 customers onboard fatally struck a trespasser at MP 222 on the UPRR Valley subdivision in Red Bluff, CA. This incident did not occur at a grade crossing and there were no reports of injuries to the crew or customers and no reported damage to the equipment or infrastructure. The incident occurred at 5:55am-pt, weather conditions were clear and dark skies and the onboard crew requested relief at the scene. Once the equipment was released the train was able to shove back to Rawson to hold for the relief crew. Once the new crew was onboard and a job briefing was complete train 14(21) was able to depart and proceed without further delay.

As a result of the late operation of train 14(21) the following service recovery was initiated: Coach Customers - All Coach customers received complimentary bottled water, hot beverages and snack packs at request. Lunch service was provided including beef stew, mashed potatoes and complimentary beverages. Dinner service was provided including Salisbury steak, vegetables and complimentary beverages. First Class Customers - First Class customers received lunch and dinner service in the dining car as planned.

WBS#: **B.TR.100150.7290**

National Response Center Number: **1476775**

Train	Delay	Comment
14(21)	3'04"	

Train 5(20) East of Elko, NV - Freight Train Interference

22OCT26: Train 5(20), with 163 customers on board, was delayed starting at MP 727.4, 60 miles east of Elko, NV, on the UPRR Shafter Subdivision due to freight interference. The crew held at Ruby/MP 727.4 for UP8078 to clear route. Once freight cleared, Train 5(20) was further delayed due to UP7267 on main track one. The crew operated at restricted speed from MP 561 to MP 559, stopping to throw switches.

Train	Delay	Comment
5(20)	40"	

Train 51(21) North of Lafayette, IN - Freight Train Interference

22OCT26: Train 51(21) held 1.2 north of Lafayette, IN (MP120.1), on the CSX Monon Subdivision, at 9th St (MP118.9) waiting on CSX M642-22 to finish clearing into Lafayette yard.

Train	Delay	Comment
51(21)	57"	

Train 49/449(21) Toledo, OH - Freight Train Interference

22OCT26: Train 49/449(21) was delayed at Toledo, OH (MP288.3), on the NSRR Chicago Line, due to NS 337 stalled ahead. Once the freight train recovered and cleared the main line, Train 49/449(21) was released to proceed west.

Train	Delay	Comment
49/449(21)	30"	

Train 40(20) West of South Bend, IN - Freight Train Interference

22OCT26: Train 40(20) was delayed starting 16.4 miles west of South Bend, IN (MP438.6), on the NSRR Chicago Line, following NS 23G from MP455 to MP490.

Train	Delay	Comment
40(20)	47"	

Train 4(20) West of Topeka, KS - Passenger Train Interference

22OCT26: Train 4(20) held 59.7 miles west of Topeka, KS (MP51.3), on the BNSF Topeka Subdivsion, at N.R. Jct (MP111.0) in order to meet Train 3(21).

Train	Delay	Comment
4(20)	38"	

Train 21(21) South of Little Rock, AR - Switch Failure

22OCT26: Train 21(21) was delayed 6 miles south of Little Rock, AR (MP345.7), on the UPRR Little Rock Subdivision, due to switch failure at Ensign (MP351.7). Maintenance of Way responded for repair. Once the switch was properly lined for train movement, Train 21(21) was released to continue south.

Train	Delay	Comment
21(21)	57"	

Train 4(21) West of Kingman, AZ - Freight Train Interference

22OCT26: Train 4(21), with 133 customers on board, was delayed at MP 542.1, 26 miles west of Kingman, AZ, on the BNSF Seligman Subdivision due to freight interference. All traffic was stopped due to BN5087 being vandalized. Once the freight was able to resolve issues and cleared route, the crew held for 5 freights (BN6267, BN7798, BN7102, BN7109 and BN7793) as well a meet with Train 3(20). Once all traffic was cleared, Train 4(21) proceeded east.

Train	Delay	Comment
3(20)	1'00"	
4(21)	1'11"	

Train 41(21) East of Alliance, OH - Freight Train Interference

22OCT26: Train 41(21) was delayed starting 37.8 miles east of Alliance, OH (MP83.1), on the NSRR Fort Wayne Line, following NS 28X from Enon (MP45.3) to East Conway (MP20.8).

Train	Delay	Comment
41(21)	30"	

Train 48/448(21) Toledo, OH - Freight Train Interference

22OCT26: Train 48/448(21) was delayed at Toledo, OH (MP288.3), on the NSRR Chicago Line, due to NS 23G in emergency ahead blocking the route out of the station. Once the freight train recovered from the emergency and cleared the main line, Train 48/448(21) was released to continue east.

Train	Delay	Comment
48/448(21)	39"	

Train 365(22) Port Huron, MI - Car Failure

22OCT26: Train 365(22), E/ID4614-6 Cars-E/ID4617, was delayed departing Port Huron, MI (MP334.2) on the CNRR Strathroy Subdivision after car ID4004 was set out prior to departure due to flat spots. Once the setout was completed, the train departed Port Huron at 9:13AM operating 2 hours and 53 minutes late. Additional delay was incurred en route to Battle Creek while operating at a reduced maximum speed of 60 MPH and 30MPH at crossings due to operating with a reduced axle count of 28. Upon reaching Battle Creek, the train resumed normal track speed for the remainder of the trip to Chicago.

Train	Delay	Comment
365(22)	2'06"	Reduced Speed - Axle Count
365(22)	2'53"	ITD PTH

Heartland Flyer Service South of Gainesville, TX - Temporary Speed Restrictions

29SEP26: Train 821(29) was delayed beginning 1.2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remain in effect between MP409.5 and MP396.4 resulting in delays to the Heartland Flyer Service operating through the affected area.

19OCT26: Temporary speed restrictions remained in effect between MP49.5 and MP396.4 resulting in delays to Heartland Flyer Service operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	
821(02)	34"	
822(02)	29"	
822(03)	33"	
821(03)	25"	
821(04)	35"	
822(04)	32"	
821(05)	35"	
822(05)	26"	
821(06)	26"	
822(06)	37"	
821(07)	35"	
822(08)	32"	
821(09)	32"	
822(09)	36"	
822(10)	23"	
822(11)	41"	
822(12)	48"	
821(12)	21"	
821(13)	22"	
822(13)	36"	
821(14)	35"	
822(14)	17"	
821(15)	26"	
821(16)	41"	
822(15)	34"	
822(16)	19"	
821(17)	24"	
821(19)	39"	
822(19)	22"	
821(20)	29"	
822(20)	32"	
821(21)	46"	
821(22)	32"	
822(21)	19"	
822(22)	30"	

Hiawatha and Borealis Services M of W Work TWA 26-099

10SEP26: Due to tire and surfacing work on the CPKC C&M Subdivision starting Monday, September 28th through Friday October 23rd, Amtrak's Hiawatha and Borealis Service has been adjusted as follows:

· Train 329 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at MKE, arriving at 7:49am.

· Train 331 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at MKE, arriving at 10:04am.

· Train 335 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at MKE, arriving at 2:44pm.

· Train 337 (28Sep-23Oct) will have 10-minutes of recovery added at MKE, arriving at 4:54pm.

· Train 339 (28Sep-23Oct) will have 10-minutes of recovery added at MKE, arriving at 6:55pm.

· Train 341 (28Sep-23Oct) will have 10-minutes of recovery added at MKE, arriving at 9:44pm.

· Train 343 (2Oct, 9Oct, 16Oct, 23Oct) will have 10-minutes of recovery added at MKE, arriving at 1:04am.

· Train 1333 (28Sep-23Oct), will have 20-minutes of recovery added at MSP, arriving at 7:01pm.

· Train 330 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at CHI, arriving at 8:07am.

· Train 332 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at CHI, arriving at 9:44am.

· Train 334 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at CHI, arriving at 12:39pm.

· Train 336 (28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct) will have 10-minutes of recovery added at CHI, arriving at 2:44pm.

· Train 338 (28Sep-23Oct) will have 10-minutes of recovery added at CHI, arriving at 4:39pm.

· Train 342 (28Sep-23Oct) will have 10-minutes of recovery added at CHI, arriving at 9:14pm.

· Train 1340 (28Sep-23Oct) will have 10-minutes of recovery added at CHI, arriving at 7:31pm.

WBS#: B.TR.100150.7161

Maintenance of Way Highlights

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL. Beginning Monday October 12th, Bus 3391 will operate 41-minutes later between Champaign and Carbondale, departing Champaign at 1130am.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
351(21)	DER	ID4605		Strike Damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Train 6(21) Passenger Removal at Grand Junction, Colorado – Improper Behavior

22OCT26, Passenger on PNR 3F2647, traveling from Richmond CA to Chicago, IL was removed from the train by the Conductor for having a pet that was jumping all over the seats and making a mess. Passenger was argumentative with the crew and was asked to leave the train. Amtrak Police notified.

Delay: 6(21) None

Consist Deviations

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
381 (22)	CHI	two single coaches in lieu of venture cafe married pair. food served in club dinette. y-inventory increased. no customer impact.	No impact	0	ID4020, ID4017
6 (23)	EMY	Operating with sleeper in lieu of T-Dorm. Schedule change was already been performed. Customer Service please ensure DS and FS room have blocked off.			32002
770 (22)	LAX	Equipment change operating with 90215 in consist unable to accommodate paxs with BV reservations. Inventory adjusted to reflect change. CNOC CSV will need to reaccommodate any paxs impacted by this.			90215
588 (22)	LAX	Equipment change operating with 90215 in consist unable to accommodate paxs with BV reservations. Inventory adjusted to reflect change. CNOC CSV will need to reaccommodate any paxs impacted by this.			90215
641 (22)	NYP	ACS64 in lieu of cab car. 43389 added to set for wi-fi.	No impact	0	43389
365 (22)	PTH	ID4004 set out in pth due to flat spots. 365(22) short one coach. Y is over capacity by 29 seats.	Passengers notified	29	ID4004
382 (22)	QCY	two single coaches in lieu of venture cafe married pair. food served in club dinette. y-inventory increased. no customer impact.	No impact	0	ID4020, ID4017
581 (22)	SAN	Equipment change operating with 90215 in consist unable to accommodate paxs with BV reservations. Inventory adjusted to reflect change. CNOC CSV will need to reaccommodate any paxs impacted by this.			90215

Reverse Consists

Train Number	Station	Reason
1164 (22)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
1161 (22)	BOS	Consist reversed | Business class seat orientation may have changed | At Front

Train Number	Station	Reason
1097 (22)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1135 (22)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1194 (22)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
1082 (22)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
66 (22)	RNK	Consist reversed | Business class seat orientation may have changed | At Front