



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, September 07, 2026

Rules: 0-49



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/06/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	280	33	88.2%	1,884	290	84.6%	102,406	14,258	86.1%
Central Division	86.0%	55	6	89.1%	349	53	84.8%	19,544	1,828	90.6%
East Division	82.0%	148	10	93.2%	1,007	118	88.3%	53,827	8,252	84.7%
West Division	86.0%	77	17	77.9%	528	119	77.5%	29,035	4,178	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00731 00000008777 UNCLASSIFIED 9/18/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	98,445	20,924	79%	620,484	179,502	71%	34,211,530	8,765,482	74%
Northeast Corridor	81%	43,100	3,416	92%	276,128	53,178	81%	14,991,027	3,640,460	76%
Acela	83%	7,582	825	89%	60,213	7,883	87%	3,022,839	767,023	75%
Northeast Regional	79%	35,518	2,591	93%	215,915	45,295	79%	11,968,188	2,873,437	76%
Richmond / Newport News / Norfolk	77%	12,436	1,500	88%	63,158	19,365	69%	3,585,957	1,066,664	70%
Springfield Shuttles	89%	570	0	100%	4,333	781	82%	210,735	33,919	84%
Roanoke	79%	2,976	173	94%	22,387	5,170	77%	1,136,190	254,864	78%
On Spine Northeast Regional	80%	19,536	918	95%	126,037	19,979	84%	7,035,306	1,517,990	78%
State Supported	80%	41,906	10,684	75%	274,290	85,638	69%	15,062,884	3,296,912	78%
Borealis	80%	683	0	100%	3,644	158	96%	191,633	40,629	79%
Capitol Corridor	90%	2,705	410	85%	22,900	3,612	84%	1,252,404	167,658	87%
Carolinian	70%	908	5	99%	6,227	3,574	43%	383,555	151,724	60%
Cascades	75%	2,844	227	92%	16,016	4,931	69%	866,652	245,585	72%
Downeaster	82%	2,035	0	100%	10,284	12	100%	530,264	61,857	88%
Empire	78%	6,298	1,598	75%	37,330	10,275	72%	1,879,134	465,237	75%
Adirondack	72%	388	0	100%	2,253	553	75%	116,348	37,506	68%
Ethan Allen Express	70%	852	768	10%	3,377	1,522	55%	190,279	73,798	61%
Maple Leaf	70%	915	97	89%	5,421	1,563	71%	233,733	91,442	61%
New York - Albany	85%	2,558	398	84%	16,043	3,137	80%	865,310	151,626	82%
New York - Niagara Falls	75%	1,585	335	79%	9,629	3,500	64%	460,021	104,009	77%
Berkshire Flyer	60%	0	0	-	607	0	100%	13,443	6,856	49%
Gold Runner	73%	2,088	507	76%	15,011	8,943	40%	844,733	317,702	62%
Heartland Flyer	70%	287	36	87%	1,200	307	74%	72,757	30,492	58%
Hiawatha	90%	1,850	485	74%	11,226	1,078	90%	595,003	64,925	89%
Illinois	78%	2,507	693	72%	14,095	9,781	31%	842,452	242,415	71%
Carl Sandburg / Illinois Zephyr	85%	456	0	100%	2,454	998	59%	140,200	40,332	71%
Illini / Saluki	85%	917	485	47%	4,940	3,864	22%	290,952	75,341	74%
Lincoln Service	70%	1,134	208	82%	6,701	4,919	27%	411,300	126,742	69%
Keystone	92%	5,699	457	92%	47,762	6,159	87%	2,561,653	262,411	90%
Lincoln / Missouri	70%	1,058	787	26%	3,909	3,633	7%	261,520	139,090	47%
Mardi Gras Service	80%	470	10	98%	1,788	309	83%	135,740	30,294	78%
Michigan	70%	2,518	762	70%	13,494	6,782	50%	686,772	232,332	66%
Blue Water	70%	770	27	96%	3,069	1,367	55%	161,694	66,511	59%
Pere Marquette	85%	339	149	56%	1,899	444	77%	88,380	16,797	81%
Wolverine	70%	1,409	586	58%	8,526	4,971	42%	436,698	149,024	66%
Missouri	80%	291	210	28%	1,420	1,215	14%	74,780	22,480	70%
Pacific Surfliner	85%	6,238	4,471	28%	48,534	18,712	61%	2,775,380	537,285	81%
Pennsylvanian	80%	803	26	97%	5,131	1,472	71%	297,684	57,303	81%
Piedmont	80%	1,224	0	100%	6,135	1,620	74%	377,063	96,221	74%
Vermont	75%	1,400	0	100%	8,184	3,065	63%	433,705	131,272	70%
Long Distance	70%	13,439	6,824	49%	70,066	40,686	42%	4,118,352	1,825,647	56%
Auto Train	70%	594	283	52%	3,845	2,251	41%	263,916	90,992	66%
California Zephyr	70%	1,062	589	45%	5,415	2,700	50%	326,750	128,879	61%
Cardinal	70%	262	262	0%	1,327	1,065	20%	78,343	40,316	49%
City Of New Orleans	75%	646	644	0%	3,838	3,449	10%	213,490	75,914	64%
Coast Starlight	70%	1,342	459	66%	7,201	1,894	74%	384,455	136,536	64%
Crescent	70%	778	51	93%	5,038	1,365	73%	310,435	95,835	69%
Empire Builder	70%	1,241	644	48%	6,532	2,855	56%	326,088	163,605	50%
Floridian	60%	2,385	2,385	0%	8,402	7,179	15%	528,308	367,185	30%
Lake Shore Ltd	73%	983	290	70%	6,090	2,499	59%	327,771	100,342	69%
Palmetto	70%	836	11	99%	4,658	2,643	43%	307,839	97,441	68%
Silver Meteor	70%	930	146	84%	5,086	3,982	22%	339,496	159,386	53%
Southwest Chief	60%	899	389	57%	5,165	3,512	32%	282,420	187,107	34%
Sunset Ltd	70%	350	251	28%	1,214	600	51%	96,918	39,099	60%
Texas Eagle	70%	1,131	420	63%	6,255	4,692	25%	332,123	143,010	57%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00701 00000000777 "UNCLASSIFIED" 0/10/2020

Train Index Dates Through September 06, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	40,618	662,483	613	2,040,436	35,936,650	568

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,912	201,334	95	98,351	10,408,769	94
INFRASTRUCTURE PLANNED	135	3,252	201,334	162	118,798	10,408,769	114
FLEET RELIABILITY	90	6,448	662,483	97	325,993	35,936,650	91
TRAIN OPERATIONS	424	29,006	662,483	438	1,497,294	35,936,650	417

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	09/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/06/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	280	33	88.2%	1,884	290	84.6%	102,406	14,258	86.1%
Central Division	86.0%	55	6	89.1%	349	53	84.8%	19,544	1,828	90.6%
East Division	82.0%	148	10	93.2%	1,007	118	88.3%	53,827	8,252	84.7%
West Division	86.0%	77	17	77.9%	528	119	77.5%	29,035	4,178	85.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0073 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/06/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 09/06/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	280	33	88.2%	1,884	290	84.6%	102,406	14,258	86.1%
Central Division	86.0%	55	6	89.1%	349	53	84.8%	19,544	1,828	90.6%
CDL	95.0%	2	0	100.0%	12	3	75.0%	648	34	94.8%
CHI	86.0%	26	5	80.8%	164	32	80.5%	9,034	1,132	87.5%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	1	1	0.0%	2	2	0.0%	4	4	0.0%
ELP	-	-	-	-	-	-	-	1	1	0.0%
FTW	92.5%	1	0	100.0%	6	1	83.3%	364	39	89.3%
GBB	-	-	-	-	-	-	-	15	12	20.0%
GRR	95.5%	1	0	100.0%	6	0	100.0%	320	11	96.6%
HOS	-	-	-	-	1	1	0.0%	1	1	0.0%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	12	1	91.7%	660	55	91.7%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	0	100.0%	35	2	94.3%	1,994	128	93.6%
MOE	97.5%	2	0	100.0%	12	1	91.7%	679	10	98.5%
MSP	96.5%	1	0	100.0%	6	0	100.0%	334	7	97.9%
NOL	94.5%	4	0	100.0%	25	0	100.0%	1,435	64	95.5%
OKC	97.0%	1	0	100.0%	5	0	100.0%	334	6	98.2%
PNT	88.0%	2	0	100.0%	16	2	87.5%	892	75	91.6%
PTH	93.0%	1	0	100.0%	6	0	100.0%	329	13	96.0%
QCY	91.0%	2	0	100.0%	12	1	91.7%	643	49	92.4%
SAS	90.5%	1	0	100.0%	6	1	83.3%	338	40	88.2%
STL	89.0%	3	0	100.0%	23	6	73.9%	1,319	112	91.5%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	148	10	93.2%	1,007	118	88.3%	53,827	8,252	84.7%
ALB	88.5%	8	1	87.5%	47	4	91.5%	2,531	192	92.4%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	30	0	100.0%	1,651	175	89.4%
BOS	85.5%	18	2	88.9%	111	4	96.4%	5,816	644	88.9%
BRK	92.5%	5	0	100.0%	30	1	96.7%	1,625	113	93.0%
BTN	82.0%	1	0	100.0%	6	1	83.3%	325	43	86.8%
CLT	91.5%	5	0	100.0%	27	3	88.9%	1,658	170	89.7%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	11	1	90.9%	659	61	90.7%
GRO	-	-	-	-	3	1	66.7%	53	12	77.4%
HAR	79.5%	7	0	100.0%	66	7	89.4%	3,773	601	84.1%
HFD	-	-	-	-	8	0	100.0%	240	19	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	6	1	83.3%	337	41	87.8%

Information Management

26-FOI-007 Initial Terminal Performance By Terminal

Scheduled Departure Date: 09/06/2026										
Amtrak or Commuter: Amtrak										
Location	Target	ITP 09/06/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	280	33	88.2%	1,884	290	84.6%	102,406	14,258	86.1%
East Division	82.0%	148	10	93.2%	1,007	118	88.3%	53,827	8,252	84.7%
MIA	89.5%	2	0	100.0%	12	4	66.7%	670	80	88.1%
MTR	79.0%	1	0	100.0%	6	1	83.3%	324	59	81.8%
NFK	84.5%	2	0	100.0%	12	2	83.3%	757	138	81.8%
NFL	93.5%	2	0	100.0%	12	1	91.7%	686	32	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	2	50.0%	28	5	82.1%	1,730	292	83.1%
NPN	93.0%	2	0	100.0%	12	1	91.7%	646	52	92.0%
NYP	75.5%	38	3	92.1%	280	48	82.9%	14,209	3,105	78.1%
PGH	93.0%	1	0	100.0%	6	1	83.3%	338	24	92.9%
PHL	48.0%	4	0	100.0%	28	10	64.3%	1,723	809	53.0%
PIT	76.0%	-	-	-	1	1	0.0%	25	20	20.0%
POR	-	-	-	-	-	-	-	23	15	34.8%
RGH	95.0%	4	0	100.0%	18	3	83.3%	1,282	57	95.6%
RNK	83.5%	2	0	100.0%	12	1	91.7%	670	94	86.0%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	7	4	42.9%
SAB	98.0%	1	0	100.0%	6	0	100.0%	320	5	98.4%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	3	3	0.0%
SAV	96.0%	1	0	100.0%	6	0	100.0%	334	12	96.4%
SFA	88.0%	1	1	0.0%	6	2	66.7%	337	49	85.5%
SPG	92.5%	6	0	100.0%	31	1	96.8%	1,993	116	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	6	0	100.0%	326	63	80.7%
WAS	84.0%	24	1	95.8%	180	14	92.2%	8,549	1,088	87.3%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	77	17	77.9%	528	119	77.5%	29,035	4,178	85.6%
ARN	92.0%	1	1	0.0%	6	1	83.3%	339	29	91.4%
BFD	79.0%	7	2	71.4%	40	13	67.5%	2,153	461	78.6%
EMY	72.0%	1	0	100.0%	6	2	66.7%	355	102	71.3%
EUG	86.5%	2	0	100.0%	11	2	81.8%	671	61	90.9%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	1	1	0.0%	9	6	33.3%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	2	33.3%	17	4	76.5%	1,018	176	82.7%
IRV	-	2	1	50.0%	2	1	50.0%	6	3	50.0%
LAX	89.5%	7	2	71.4%	60	8	86.7%	3,380	377	88.8%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	2	77.8%	69	30	56.5%	3,688	983	73.3%
PDX	86.0%	5	0	100.0%	30	5	83.3%	1,635	230	85.9%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	09/06/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 09/06/2026			ITP September 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	280	33	88.2%	1,884	290	84.6%	102,406	14,258	86.1%
West Division	86.0%	77	17	77.9%	528	119	77.5%	29,035	4,178	85.6%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	1	91.7%	88	17	80.7%	4,807	537	88.8%
SAN	90.5%	7	4	42.9%	72	12	83.3%	4,109	404	90.2%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	0	100.0%	48	12	75.0%	2,601	392	84.9%
SJC	89.0%	7	2	71.4%	42	8	81.0%	2,382	237	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	18	1	94.4%	783	78	90.0%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	6	1	83.3%	318	30	90.6%
VAC	97.0%	2	0	100.0%	12	1	91.7%	665	15	97.7%
VAN	-	-	-	-	-	-	-	27	16	40.7%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		3	2	33.3%	145	38	73.8%	2	0	100.0%	139	29	79.1%
3		6	2	66.7%	339	68	79.9%	6	1	83.3%	336	158	53.0%
4		6	0	100.0%	338	53	84.3%	6	2	66.7%	338	223	34.0%
5	153	6	1	83.3%	337	58	82.8%	6	2	66.7%	333	113	66.1%
6		6	2	66.7%	336	93	72.3%	6	4	33.3%	336	129	61.6%
7		6	0	100.0%	328	51	84.5%	6	0	100.0%	319	86	73.0%
8	76	6	1	83.3%	328	146	55.5%	6	3	50.0%	327	201	38.5%
11		6	3	50.0%	339	75	77.9%	6	1	83.3%	333	68	79.6%
14		6	4	33.3%	340	58	82.9%	6	0	100.0%	337	105	68.8%
19		6	1	83.3%	338	84	75.1%	6	0	100.0%	335	82	75.5%
20		6	0	100.0%	338	23	93.2%	6	1	83.3%	338	66	80.5%
21		6	0	100.0%	335	36	89.3%	6	3	50.0%	334	102	69.5%
22	148	6	1	83.3%	336	38	88.7%	6	6	0.0%	334	105	68.6%
23		6	1	83.3%	340	7	97.9%	6	3	50.0%	338	93	72.5%
24		6	0	100.0%	340	16	95.3%	6	1	83.3%	339	66	80.5%
25		6	0	100.0%	339	3	99.1%	6	0	100.0%	336	94	72.0%
26		6	0	100.0%	339	5	98.5%	6	1	83.3%	336	67	80.1%
27		6	3	50.0%	305	22	92.8%	6	1	83.3%	299	98	67.2%
28		6	0	100.0%	299	67	77.6%	6	1	83.3%	299	61	79.6%
40	96	6	2	66.7%	329	49	85.1%	6	5	16.7%	325	177	45.5%
41	328	6	5	16.7%	329	129	60.8%	6	6	0.0%	326	253	22.4%
42		6	1	83.3%	340	26	92.4%	6	0	100.0%	338	58	82.8%
43		6	0	100.0%	339	45	86.7%	6	4	33.3%	338	80	76.3%
48		6	0	100.0%	338	62	81.7%	6	3	50.0%	337	54	84.0%
49		6	1	83.3%	338	85	74.9%	6	1	83.3%	338	71	79.0%
50	88	3	1	66.7%	138	35	74.6%	3	3	0.0%	136	86	36.8%
52	58	6	2	66.7%	337	49	85.5%	6	4	33.3%	336	81	75.9%
53		6	1	83.3%	337	41	87.8%	6	3	50.0%	336	109	67.6%
54		2	0	100.0%	121	8	93.4%	2	0	100.0%	121	17	86.0%
57		2	0	100.0%	120	5	95.8%	2	0	100.0%	120	10	91.7%
58	106	6	0	100.0%	313	17	94.6%	6	6	0.0%	311	103	66.9%
59	128	6	2	66.7%	312	53	83.0%	6	5	16.7%	307	86	72.0%
63	57	6	2	66.7%	341	146	57.2%	6	6	0.0%	335	203	39.4%
64		6	0	100.0%	339	71	79.1%	6	2	66.7%	338	135	60.1%
65		3	0	100.0%	105	13	87.6%	2	0	100.0%	103	14	86.4%
66		6	1	83.3%	338	65	80.8%	6	2	66.7%	333	62	81.4%
68		6	1	83.3%	341	68	80.1%	6	2	66.7%	340	136	60.0%
69		6	2	66.7%	328	81	75.3%	6	1	83.3%	323	57	82.4%
71		6	0	100.0%	336	3	99.1%	6	1	83.3%	334	87	74.0%
72		6	1	83.3%	332	37	88.9%	6	1	83.3%	330	70	78.8%
73		3	1	66.7%	331	24	92.7%	3	0	100.0%	329	148	55.0%
74		3	0	100.0%	329	35	89.4%	3	2	33.3%	327	120	63.3%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		6	2	66.7%	329	19	94.2%	6	3	50.0%	323	154	52.3%
76		6	0	100.0%	329	31	90.6%	6	2	66.7%	319	132	58.6%
77		6	1	83.3%	331	22	93.4%	6	1	83.3%	328	134	59.1%
78		6	1	83.3%	335	30	91.0%	7	2	71.4%	333	77	76.9%
79		6	0	100.0%	338	59	82.5%	6	4	33.3%	336	116	65.5%
80		6	1	83.3%	338	38	88.8%	6	2	66.7%	335	73	78.2%
82		2	0	100.0%	79	10	87.3%	2	0	100.0%	79	24	69.6%
87		2	0	100.0%	124	26	79.0%	2	0	100.0%	124	45	63.7%
88		2	1	50.0%	120	17	85.8%	2	1	50.0%	120	26	78.3%
89		6	0	100.0%	336	78	76.8%	6	4	33.3%	334	101	69.8%
90		6	0	100.0%	336	12	96.4%	6	2	66.7%	335	62	81.5%
97		6	3	50.0%	338	220	34.9%	6	4	33.3%	336	124	63.1%
98		6	2	66.7%	338	30	91.1%	6	4	33.3%	336	127	62.2%
99		2	0	100.0%	123	12	90.2%	2	0	100.0%	120	67	44.2%
101		2	0	100.0%	78	8	89.7%	2	0	100.0%	78	12	84.6%
103		2	0	100.0%	122	24	80.3%	2	0	100.0%	122	11	91.0%
106		2	0	100.0%	94	11	88.3%	2	0	100.0%	93	14	84.9%
107		2	0	100.0%	94	30	68.1%	2	1	50.0%	93	16	82.8%
109		2	0	100.0%	61	9	85.2%	2	0	100.0%	61	6	90.2%
118		2	0	100.0%	122	8	93.4%	2	0	100.0%	122	8	93.4%
124		2	0	100.0%	121	9	92.6%	2	1	50.0%	120	35	70.8%
126		2	1	50.0%	57	10	82.5%	2	1	50.0%	57	14	75.4%
127		2	1	50.0%	57	18	68.4%	2	1	50.0%	57	7	87.7%
128		2	0	100.0%	124	20	83.9%	1	0	100.0%	123	26	78.9%
135		2	0	100.0%	123	18	85.4%	2	1	50.0%	123	58	52.8%
140		2	0	100.0%	122	15	87.7%	2	0	100.0%	121	29	76.0%
142		2	0	100.0%	77	8	89.6%	2	0	100.0%	76	9	88.2%
143		2	0	100.0%	121	13	89.3%	2	0	100.0%	121	29	76.0%
144		2	1	50.0%	79	53	32.9%	2	0	100.0%	78	11	85.9%
146		2	1	50.0%	121	19	84.3%	2	0	100.0%	121	42	65.3%
147		2	0	100.0%	80	10	87.5%	2	0	100.0%	80	27	66.3%
150		2	1	50.0%	120	63	47.5%	2	1	50.0%	118	56	52.5%
151		6	2	66.7%	337	107	68.2%	6	1	83.3%	336	100	70.2%
152		2	0	100.0%	79	6	92.4%	2	0	100.0%	79	27	65.8%
153		2	0	100.0%	122	11	91.0%	2	0	100.0%	122	19	84.4%
155		2	0	100.0%	124	20	83.9%	2	0	100.0%	124	43	65.3%
156		2	0	100.0%	124	12	90.3%	2	0	100.0%	124	43	65.3%
158		2	0	100.0%	123	22	82.1%	2	0	100.0%	123	27	78.0%
159		2	1	50.0%	77	9	88.3%	1	0	100.0%	76	11	85.5%
160		2	0	100.0%	121	8	93.4%	2	0	100.0%	118	27	77.1%
161		2	0	100.0%	122	10	91.8%	2	0	100.0%	121	81	33.1%
162		2	0	100.0%	122	10	91.8%	2	0	100.0%	122	58	52.5%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
163	32	2	0	100.0%	77	15	80.5%	2	2	0.0%	77	64	16.9%
164	143	2	0	100.0%	124	9	92.7%	2	1	50.0%	124	52	58.1%
165	129	2	0	100.0%	122	27	77.9%	2	1	50.0%	122	48	60.7%
167		2	0	100.0%	80	16	80.0%	2	0	100.0%	79	22	72.2%
168		2	0	100.0%	78	14	82.1%	2	0	100.0%	78	28	64.1%
169		2	0	100.0%	122	13	89.3%	1	0	100.0%	121	26	78.5%
194		2	0	100.0%	79	18	77.2%	2	0	100.0%	78	23	70.5%
195		2	0	100.0%	122	5	95.9%	2	0	100.0%	122	66	45.9%
230		6	0	100.0%	174	4	97.7%	6	1	83.3%	174	10	94.3%
232		6	0	100.0%	340	12	96.5%	6	1	83.3%	340	24	92.9%
233	17	5	1	80.0%	300	67	77.7%	5	1	80.0%	299	102	65.9%
234		6	0	100.0%	341	23	93.3%	6	0	100.0%	340	29	91.5%
235		6	1	83.3%	265	43	83.8%	6	1	83.3%	264	61	76.9%
236		6	0	100.0%	325	10	96.9%	6	0	100.0%	324	43	86.7%
237	47	6	2	66.7%	338	63	81.4%	6	3	50.0%	336	62	81.5%
238		6	1	83.3%	265	24	90.9%	6	1	83.3%	263	23	91.3%
239		6	2	66.7%	339	85	74.9%	6	0	100.0%	338	42	87.6%
240		6	2	66.7%	340	25	92.6%	6	1	83.3%	337	70	79.2%
241		6	2	66.7%	340	84	75.3%	6	2	66.7%	340	83	75.6%
243		6	1	83.3%	276	72	73.9%	6	0	100.0%	275	39	85.8%
244		5	1	80.0%	299	13	95.7%	5	3	40.0%	299	68	77.3%
245		6	1	83.3%	221	42	81.0%	6	0	100.0%	220	30	86.4%
280		6	0	100.0%	341	17	95.0%	6	2	66.7%	340	80	76.5%
281		6	0	100.0%	341	40	88.3%	6	1	83.3%	341	61	82.1%
283		6	2	66.7%	341	87	74.5%	6	5	16.7%	341	71	79.2%
284	69	6	1	83.3%	341	14	95.9%	6	3	50.0%	338	64	81.1%
290	32	6	1	83.3%	341	53	84.5%	6	3	50.0%	338	140	58.6%
291		6	1	83.3%	340	113	66.8%	6	2	66.7%	336	92	72.6%
301		6	1	83.3%	338	11	96.7%	6	5	16.7%	334	68	79.6%
302		6	2	66.7%	319	36	88.7%	6	5	16.7%	315	95	69.8%
305		6	2	66.7%	322	33	89.8%	5	4	20.0%	316	126	60.1%
306		6	1	83.3%	336	18	94.6%	6	5	16.7%	334	94	71.9%
307	39	6	2	66.7%	329	46	86.0%	6	4	33.3%	325	102	68.6%
311	21	6	1	83.3%	333	29	91.3%	6	6	0.0%	327	90	72.5%
316	55	6	1	83.3%	329	25	92.4%	6	6	0.0%	323	107	66.9%
318	28	6	0	100.0%	339	35	89.7%	6	6	0.0%	336	172	48.8%
319	47	6	1	83.3%	340	21	93.8%	6	6	0.0%	335	199	40.6%
331	32	6	2	66.7%	341	35	89.7%	6	2	66.7%	340	46	86.5%
332		6	1	83.3%	340	20	94.1%	6	2	66.7%	340	48	85.9%
334		6	0	100.0%	341	11	96.8%	6	0	100.0%	339	43	87.3%
335		6	0	100.0%	341	35	89.7%	6	0	100.0%	338	55	83.7%
336		6	0	100.0%	340	10	97.1%	6	1	83.3%	338	30	91.1%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
337		6	0	100.0%	341	21	93.8%	6	1	83.3%	337	48	85.8%
338	45	6	0	100.0%	341	54	84.2%	6	2	66.7%	338	106	68.6%
339	13	6	1	83.3%	341	55	83.9%	6	1	83.3%	341	59	82.7%
341	15	6	1	83.3%	326	52	84.0%	6	1	83.3%	320	54	83.1%
342		6	0	100.0%	341	26	92.4%	6	2	66.7%	339	63	81.4%
350		6	1	83.3%	316	21	93.4%	6	4	33.3%	308	178	42.2%
351		6	1	83.3%	323	30	90.7%	6	4	33.3%	321	96	70.1%
352	68	6	0	100.0%	307	24	92.2%	6	5	16.7%	301	98	67.4%
353		6	1	83.3%	278	15	94.6%	6	2	66.7%	272	51	81.3%
354	76	6	1	83.3%	322	38	88.2%	6	4	33.3%	314	120	61.8%
355		6	2	66.7%	329	39	88.1%	6	3	50.0%	320	122	61.9%
364		6	1	83.3%	330	74	77.6%	6	4	33.3%	324	124	61.7%
365		6	0	100.0%	329	13	96.0%	6	2	66.7%	326	126	61.3%
370		6	1	83.3%	327	40	87.8%	6	1	83.3%	314	76	75.8%
371	32	6	0	100.0%	320	11	96.6%	6	2	66.7%	316	32	89.9%
380		6	0	100.0%	322	30	90.7%	6	1	83.3%	321	73	77.3%
381		6	1	83.3%	337	16	95.3%	6	1	83.3%	334	72	78.4%
382		6	1	83.3%	336	31	90.8%	6	4	33.3%	334	120	64.1%
383		6	3	50.0%	327	30	90.8%	5	2	60.0%	323	140	56.7%
390		6	1	83.3%	322	25	92.2%	6	4	33.3%	320	90	71.9%
391	43	6	0	100.0%	323	14	95.7%	6	6	0.0%	318	94	70.4%
392	52	6	2	66.7%	336	13	96.1%	5	5	0.0%	330	108	67.3%
393	20	6	3	50.0%	340	22	93.5%	5	5	0.0%	335	109	67.5%
400		2	0	100.0%	101	6	94.1%	2	0	100.0%	99	2	98.0%
405		2	0	100.0%	94	0	100.0%	2	0	100.0%	94	4	95.7%
448		6	2	66.7%	265	51	80.8%	6	2	66.7%	261	91	65.1%
449		6	0	100.0%	262	34	87.0%	6	0	100.0%	262	45	82.8%
450		2	1	50.0%	97	30	69.1%	2	0	100.0%	95	30	68.4%
460		2	1	50.0%	97	31	68.0%	2	1	50.0%	94	32	66.0%
461		2	0	100.0%	102	5	95.1%	2	1	50.0%	101	4	96.0%
463		2	0	100.0%	52	4	92.3%	2	0	100.0%	52	0	100.0%
464		2	0	100.0%	98	21	78.6%	2	0	100.0%	95	29	69.5%
467		2	0	100.0%	52	1	98.1%	2	0	100.0%	51	3	94.1%
488		2	0	100.0%	107	29	72.9%	2	1	50.0%	97	15	84.5%
499		2	1	50.0%	98	15	84.7%	2	0	100.0%	95	6	93.7%
500		6	1	83.3%	315	17	94.6%	6	1	83.3%	312	37	88.1%
502		6	0	100.0%	323	19	94.1%	6	1	83.3%	319	62	80.6%
503	18	6	2	66.7%	337	42	87.5%	5	1	80.0%	329	103	68.7%
504		6	1	83.3%	341	21	93.8%	6	2	66.7%	339	101	70.2%
505		6	2	66.7%	333	45	86.5%	6	5	16.7%	328	96	70.7%
506		6	1	83.3%	336	57	83.0%	5	1	80.0%	327	52	84.1%
507		6	0	100.0%	341	49	85.6%	6	2	66.7%	341	117	65.7%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508		5	1	80.0%	335	44	86.9%	5	1	80.0%	331	82	75.2%
509		6	2	66.7%	322	17	94.7%	6	1	83.3%	322	72	77.6%
511		6	1	83.3%	317	26	91.8%	6	1	83.3%	316	54	82.9%
516	17	6	1	83.3%	332	36	89.2%	6	3	50.0%	331	149	55.0%
517		6	0	100.0%	341	8	97.7%	6	2	66.7%	337	152	54.9%
518		6	3	50.0%	341	49	85.6%	6	5	16.7%	339	237	30.1%
519		6	1	83.3%	332	10	97.0%	6	3	50.0%	330	75	77.3%
562	38	6	0	100.0%	332	27	91.9%	6	1	83.3%	327	38	88.4%
564	Cncld	6	0	100.0%	333	19	94.3%	5	2	60.0%	324	45	86.1%
567	Cncld	6	1	83.3%	218	12	94.5%	5	0	100.0%	215	14	93.5%
579		6	0	100.0%	218	14	93.6%	6	1	83.3%	211	46	78.2%
580		6	1	83.3%	333	19	94.3%	6	2	66.7%	326	39	88.0%
591		6	2	66.7%	330	28	91.5%	6	2	66.7%	323	51	84.2%
595		6	4	33.3%	326	64	80.4%	6	1	83.3%	323	74	77.1%
611		2	0	100.0%	50	35	30.0%	2	0	100.0%	50	5	90.0%
637		2	0	100.0%	75	7	90.7%	1	0	100.0%	74	6	91.9%
660		2	0	100.0%	93	13	86.0%	2	0	100.0%	92	26	71.7%
661		2	0	100.0%	121	12	90.1%	2	0	100.0%	120	45	62.5%
662		2	0	100.0%	52	0	100.0%	2	0	100.0%	52	1	98.1%
663		2	0	100.0%	94	15	84.0%	2	0	100.0%	93	9	90.3%
664		2	0	100.0%	93	8	91.4%	2	0	100.0%	93	16	82.8%
665		2	0	100.0%	94	10	89.4%	2	0	100.0%	94	25	73.4%
666		2	0	100.0%	92	22	76.1%	2	0	100.0%	92	7	92.4%
667		2	0	100.0%	92	7	92.4%	2	0	100.0%	90	16	82.2%
669	38	2	0	100.0%	92	7	92.4%	2	1	50.0%	90	23	74.4%
670		2	0	100.0%	94	13	86.2%	2	0	100.0%	92	17	81.5%
671		2	0	100.0%	92	8	91.3%	2	0	100.0%	90	11	87.8%
672		2	0	100.0%	94	10	89.4%	2	0	100.0%	94	18	80.9%
674		2	0	100.0%	92	30	67.4%	2	0	100.0%	92	7	92.4%
690		2	0	100.0%	98	2	98.0%	2	0	100.0%	97	5	94.8%
691		2	0	100.0%	98	8	91.8%	2	0	100.0%	96	28	70.8%
692		2	0	100.0%	98	4	95.9%	2	0	100.0%	97	15	84.5%
693		2	0	100.0%	98	14	85.7%	2	0	100.0%	96	31	67.7%
694		2	0	100.0%	97	10	89.7%	2	0	100.0%	97	15	84.5%
695		2	0	100.0%	96	10	89.6%	2	0	100.0%	96	16	83.3%
696		2	0	100.0%	98	11	88.8%	2	0	100.0%	98	27	72.4%
697		2	0	100.0%	98	23	76.5%	2	0	100.0%	98	19	80.6%
698		2	0	100.0%	96	3	96.9%	2	0	100.0%	96	8	91.7%
701		6	0	100.0%	273	30	89.0%	6	1	83.3%	270	33	87.8%
702		6	1	83.3%	340	37	89.1%	5	3	40.0%	336	86	74.4%
703		6	3	50.0%	341	115	66.3%	6	3	50.0%	339	103	69.6%
704		6	2	66.7%	272	51	81.3%	6	3	50.0%	264	62	76.5%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
710		6	1	83.3%	341	80	76.5%	5	3	40.0%	336	91	72.9%
711		6	1	83.3%	332	39	88.3%	6	1	83.3%	309	66	78.6%
712		6	3	50.0%	338	94	72.2%	6	3	50.0%	328	117	64.3%
713	24	5	2	60.0%	207	22	89.4%	4	4	0.0%	181	84	53.6%
714	Cncld	6	5	16.7%	222	97	56.3%	5	4	20.0%	205	99	51.7%
715		6	1	83.3%	340	64	81.2%	5	3	40.0%	310	158	49.0%
716	153	6	3	50.0%	341	146	57.2%	6	5	16.7%	332	146	56.0%
717	91	5	3	40.0%	325	82	74.8%	5	3	40.0%	300	101	66.3%
718		6	5	16.7%	341	183	46.3%	6	5	16.7%	338	134	60.4%
719		6	3	50.0%	341	116	66.0%	6	2	66.7%	324	100	69.1%
720		2	2	0.0%	105	11	89.5%	2	0	100.0%	105	6	94.3%
723		2	0	100.0%	105	5	95.2%	2	1	50.0%	105	12	88.6%
724		2	0	100.0%	105	5	95.2%	2	1	50.0%	103	23	77.7%
727		2	0	100.0%	105	9	91.4%	2	0	100.0%	105	15	85.7%
728	32	2	0	100.0%	105	7	93.3%	2	1	50.0%	105	19	81.9%
729	Cncld	2	1	50.0%	104	17	83.7%	1	0	100.0%	102	25	75.5%
732		2	1	50.0%	103	20	80.6%	1	0	100.0%	100	21	79.0%
733		2	0	100.0%	105	14	86.7%	2	1	50.0%	100	33	67.0%
734		2	1	50.0%	105	17	83.8%	2	1	50.0%	104	25	76.0%
736		2	0	100.0%	81	8	90.1%	2	0	100.0%	79	12	84.8%
737		2	1	50.0%	81	8	90.1%	2	1	50.0%	80	15	81.3%
738		2	0	100.0%	105	15	85.7%	2	1	50.0%	99	15	84.8%
741	40	2	0	100.0%	105	15	85.7%	2	1	50.0%	105	21	80.0%
742		2	0	100.0%	102	13	87.3%	2	0	100.0%	99	7	92.9%
743		2	0	100.0%	105	21	80.0%	2	0	100.0%	101	12	88.1%
744		2	2	0.0%	105	18	82.9%	2	0	100.0%	105	34	67.6%
745		2	0	100.0%	105	13	87.6%	2	0	100.0%	104	16	84.6%
746		2	0	100.0%	105	9	91.4%	2	0	100.0%	104	15	85.6%
747		2	0	100.0%	105	16	84.8%	2	0	100.0%	105	25	76.2%
748		2	0	100.0%	104	14	86.5%	2	0	100.0%	104	14	86.5%
749		2	0	100.0%	102	15	85.3%	2	0	100.0%	93	12	87.1%
751		2	0	100.0%	104	17	83.7%	2	0	100.0%	100	11	89.0%
757		6	0	100.0%	126	7	94.4%	6	1	83.3%	125	15	88.0%
761	35	6	1	83.3%	337	14	95.8%	6	1	83.3%	334	45	86.5%
765	28	6	1	83.3%	337	26	92.3%	6	2	66.7%	337	48	85.8%
769	32	6	1	83.3%	337	28	91.7%	6	3	50.0%	330	68	79.4%
770	54	6	1	83.3%	337	26	92.3%	6	2	66.7%	334	106	68.3%
774	71	6	0	100.0%	337	17	95.0%	6	3	50.0%	335	83	75.2%
777	22	6	0	100.0%	222	13	94.1%	6	6	0.0%	221	64	71.0%
782		6	3	50.0%	222	108	51.4%	6	2	66.7%	217	38	82.5%
785	123	6	1	83.3%	337	30	91.1%	6	4	33.3%	337	65	80.7%
786	49	6	1	83.3%	126	24	81.0%	5	3	40.0%	121	69	43.0%

Amtrak On Time Performance

Trains Arriving Through: 9/6/2026

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
790	32	6	0	100.0%	337	31	90.8%	6	2	66.7%	334	56	83.2%
794	186	6	0	100.0%	337	40	88.1%	7	3	57.1%	334	79	76.3%
794	33	6	0	100.0%	337	40	88.1%	7	3	57.1%	334	79	76.3%
821		5	0	100.0%	334	6	98.2%	5	2	60.0%	334	142	57.5%
822		6	1	83.3%	337	19	94.4%	5	3	40.0%	334	173	48.2%
1333		6	0	100.0%	337	40	88.1%	6	1	83.3%	334	113	66.2%
1340		6	0	100.0%	336	7	97.9%	6	0	100.0%	335	56	83.3%
1689		2	0	100.0%	113	6	94.7%	3	0	100.0%	113	14	87.6%
2203		2	0	100.0%	67	9	86.6%	2	0	100.0%	67	17	74.6%
2207		2	0	100.0%	30	5	83.3%	2	0	100.0%	30	6	80.0%
2208		2	0	100.0%	23	5	78.3%	2	0	100.0%	23	5	78.3%
2211		2	1	50.0%	13	2	84.6%	2	1	50.0%	13	3	76.9%
2219		2	0	100.0%	23	4	82.6%	2	0	100.0%	23	6	73.9%
2224		2	0	100.0%	38	6	84.2%	2	0	100.0%	37	4	89.2%
2226		2	0	100.0%	43	8	81.4%	2	0	100.0%	41	10	75.6%
2250		2	0	100.0%	111	12	89.2%	2	0	100.0%	110	35	68.2%
2252		2	0	100.0%	118	10	91.5%	2	0	100.0%	116	32	72.4%
2254		2	0	100.0%	53	3	94.3%	2	0	100.0%	53	13	75.5%
2255		2	0	100.0%	120	12	90.0%	2	0	100.0%	119	55	53.8%
2256		2	0	100.0%	20	3	85.0%	2	0	100.0%	19	7	63.2%
2258		2	0	100.0%	56	9	83.9%	2	0	100.0%	55	24	56.4%
2259		2	0	100.0%	76	26	65.8%	2	0	100.0%	75	35	53.3%
2260	40	2	1	50.0%	22	3	86.4%	2	1	50.0%	22	13	40.9%
2262		2	0	100.0%	28	5	82.1%	2	0	100.0%	28	9	67.9%
2263		2	1	50.0%	17	1	94.1%	2	1	50.0%	16	3	81.3%
2265		2	1	50.0%	57	7	87.7%	2	0	100.0%	56	29	48.2%
2267		2	0	100.0%	20	3	85.0%	2	0	100.0%	19	10	47.4%
2271		2	0	100.0%	103	11	89.3%	2	0	100.0%	102	47	53.9%
2293		2	0	100.0%	21	3	85.7%	2	0	100.0%	21	3	85.7%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2260	BOS	40	ENG	33	ENG	24	NHV-XGX	AM	Air / Brake, 2131 NG NP, AM2260 stopped east of Miners Ln trk 2 due to the train experiencing multiple faults on E/2131, was able to clear the faults on E/2131
163	WAS	32	SMW	19	SMW	15	XSH-NYP	AM	Scheduled in track usage program, Other, HELD FOR AM88, AM164
164	BOS	143	ENG	126	ENG	126	NCR-BWI	AM	HEP, 611 EX ES, Stopped at New Carrollton a/c CTB fault
165	WAS	129	SVS	140	SVS	140	BOS-BBY	AM	Water, commissary, toilet/trash dumping, short turn of AM152 for AM165, the cleaning crew will just remove the trash from 152eq, after AM165 initial equipment lost overhead power at BBY, then initial train rptd down wire on top of AM165 at BBY also damage to the pantograph
52	LOR	58	ITI	108	ITI	108	SFA-SFA	FR	Service, turn, or wye train 53
669	HAR	38	DBS	16	DBS	16	TRE-XHM	AM	Debris strike (supply details in comment area), REPORTS A SMOKE CONDITIONS IN THE CAB CAR. , Other, MP68.3
63	TWO	57	CTI	10	CTI	10	CRT-POU	MN	Follow mn, Control Point, 46
233	ALB	17	CTI	20	CTI	20	CRT-POU	MN	Follow mnrr, 8819, Milepost, 50, 72
237	ALB	47	ITI	38	ITI	38	NYP-NYP	AM	Service, turn, or wye train, 284
284	NYP	69	CTI	61	CTI	32	RHI-XCP	MN	Blocked from station track metro north, Control Point, 75
290	NYP	32	CTI	37	CTI	25	POU-CRT	MN	Follow metro, 8844, Milepost, 72, 39
40	CHI	96	FTI	105	FTI	43	RMT-PTB	CS	Meet CSX M407, CSX M419, CSX I111, Control Point, Delmar, Control Point, Weldon, Control Point, Trego
41	MIA	328	FTI	127	ITI	71	CHI-CHI	AM	Service, turn, or wye train 40, Late inbound train, 240pm 5hrs 55 mins late.
5	EMY	153	ENG	172	ENG	84	XFJ-XXP	UP	Pick up rescue locomotive due to mechanical failure 179, 206
728	SAC	32	POL	39	POL	39	SUI-SUI	UP	Fire department hold Fire reported at MP 49.3
729	SJC	Trn Cancelled	DCS	10	DCS	8	RLN-RSV	UP	Power switch failure Control Point, RV106
741	SJC	40	POL	42	POL	32	FFV-FFV	UP	Fire department hold
50	NYP	88	ITI	85	ITI	85	CHI-CHI	AM	Service, turn, or wye train 51
503	EUG	18	PTI	40	PTI	31	ALY-EUG	UP	Meet Amtrak 14, Milepost, 659.1, 659.1

Amtrak Endpoint OTP Details

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 9/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
516	VAC	17	DSR	17	FTI	14	MVW-BEL	BN	Meet Per NB disp , waiting on empty coal train, Siding, Bow, BNSF 3703, Empty Coal
58	CHI	106	DSR	124	CAR	26	XCS-X9R	CT	Air / Brake / Wheel NOCAR
59	NOL	128	DSR	110	ENG	32	CHI-CHI	AM	Late release from the yard due to engine problems 193
8	CHI	76	FTI	234	FTI	113	ESM-GPK	BN	Meet Meet the BNSF 3893W/3872W at Summit and follow the BNSF 8003E from Summit to Bison. BNSF 3893W stalled out backing up traffic., BNSF 3893W, BNSF 3872W, BNSF 8003E, Control Point, Summit
331	MKE	32	CTI	22	CTI	14	XWA-GLN	ME	Follow METRA, 2601, Control Point, A5, Other, MP16.1 Golf
338	CHI	45	DBS	40	DBS	40	XRO-GLN	ME	Debris strike Train hit debris near Lake Forest, cut a hole in brake hose. Had to swap it out completely, very difficult to loosen with wrench., Unknown , Milepost, 30.0, 29.0
339	MKE	13	ITI	22	ITI	22	CHI-CHI	AM	Service, turn, or wye train 338
341	MKE	15	ENG	14	ENG	14	CHI-CHI	AM	Tied on the AMTK 57 , lack of mechanical, crew had to do the load test, brake test, and put together the hoses and cables 57
352	PNT	68	PTI	43	PTI	39	JXN-ARB	MI	Meet Held at CP 75 for meet with Amtrak 355, 355, Control Point, CP
354	PNT	76	PTI	63	PTI	43	KAL-KAL	MI	Holding. Holding at Kalamazoo station for pax comfort. Waiting until 355 went past ALI., Amtrak 355, Other, Kalamazoo Station
371	CHI	32	MBO	37	MBO	31	BAM-SJM	CS	For maritime traffic Control Point, st joesph bridge
562	SAN	38	CTI	16	CTI	9	SOL-SOL	SN	Meet Coaster, 671, Control Point, Valley
564	SAN	Trn Cancelled	PTI	7	PTI	7	SNA-IRV	SC	Meet Amtk 765, Control Point, Tinkham
567	LAX	Trn Cancelled							
761	GTA	35	CTI	12	CTI	12	LAX-GDL	SC	Follow Metrolink, Milepost, 3.0, 5.8
765	SLO	28	DCS	30	DCS	13	SAN-SAN	SN	PTC due to station stop modifications. Consist in two parts IRV—>lax, and our San—>OSD with bus bridge OSD—>irv Control Point, Ash

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Region: ALL

Service: ALL

Arriving On: 9/6/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
769	GTA	32	DCS	14	DCS	5	SAN-SAN	SN	PTC system failure (wayside) PTC could not be initialized from original track 2, shoved the equipment east passing CP Broadway to depart from track 4 per DS, passenger boarding was delayed., Control Point, ash
770	SAN	54	CAR	16	CTI	13	OSD-SOL	SN	Meet coaster, 677, Control Point, ponto
774	SAN	71	CON	77	CON	77	OSD-OSD	SN	Held for bus passengers - irv-osd bus bridge
777	SLO	22	HLD	55	HLD	53	IRV-IRV	SC	Waited for 7 buses from OSD
785	GTA	123	POL	110	POL	110	CML-CML	UP	RR blocked by trespasser or vehicle strike by another train 794 struck vehicle 405.5, waiting for clearance to continue
786	SAN	49	PTI	55	PTI	55	GUA-LPS	UP	Meet 765, 14, Siding, Tangair
790	SAN	32	DCS	31	DCS	29	LAX-LAX	SC	Power switch failure Control Point, Mission
794	SAN	33	DSR	24	ITI	21	LAX-LAX	SC	Service, turn, or wye train 587
794	LAX	No OS Rpt	TRS	192	TRS	192	OXN-CML	UP	Vehicle strike Fatal vehicle strike, Milepost, 405.3, 405.3
713	OKJ	24	PTI	21	PTI	21	MTZ-RIC	UP	Follow 741, Milepost, 31.0, 12.0
714	BFD	Trn Cancelled	CCR	81	CCR	74	OKJ-EMY	UP	Main reservoir was dropping under 100 psi. C2003
716	BFD	153	TCC	77	POL	56	ACA-SKN	BN	RR blocked by trespasser or vehicle strike by another train 714 vehicle strike at Stockton
717	OKJ	91	SYS	93	SYS	93	MCD-MCD	BN	Re-crew / job briefing
22	CHI	148	FTI	221	FTI	136	LVW-MHL	UP	Disabled Freight Train UP 2746, Control Point, R-076
307	STL	39	ENG	32	ENG	32	CHI-CHI	AM	Accommodating passenger from cancelled 305 IDTX 4631 engine trouble, ID4633
391	CDL	43	PTI	34	PTI	24	X9R-XCS	CT	Meet AM 58, Control Point, 21st St
392	CHI	52	WTR	50	WTR	12	CEN-EFG	CC	Heat order Other, champagne sub
393	CDL	20	WTR	26	FTI	8	EFG-CEN	CC	Meet cn 1874, Siding, tonti
311	KCY	21	WTR	27	WTR	9	WAR-LEE	UP	Heat order Milepost, 128.0, 276.72
316	STL	55	WTR	35	WTR	15	SED-JEF	UP	Heat order Milepost w/Letters, SED, JEF
318	CHI	28	DSR	36	FTI	15	DWT-JOL	UP	Cross Traffic Other, CPX037 UD TOWER, unk
319	KCY	47	DSR	29	PTI	21	JEF-SED	UP	Meet amtk 316, Siding, dow

Amtrak Initial Terminal Details

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/6/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	240	09/06	3	3	Late release from mechanical shop Other, Albany Station
BOS	2263	09/06	10	10	Service, turn, or wye train, 2255, late swap of equipment and late loading commissary
BOS	2265	09/06	17	17	Water, commissary, toilet/trash dumping, Delayed due to commissary loading at Station
NHV	450	09/06	6	6	Service, turn, or wye train, 405, Late turn of AM405
NHV	460	09/06	6	6	Planned set out / pick out of locomotives, cars or section of train, Late release coming out from the yard
NYP	49	09/06	134	134	Other electrical failure, CAP WITH E/94, AM49 DELAYED IN SSYD WITH A SHOPPED ENGINE 703
NYP	159	09/06	3	3	Passenger and/or baggage
NYP	237	09/06	38	38	Service, turn, or wye train, 284
SFA	52	09/06	17	17	Air / Brake 384
WAS	2260	09/06	9	9	Other electrical failure, 2131 NG NP, HVAC ISSUSE WITH POWER CAR 2131. MECHANICAL HAD TO RECYCLE THE SYSTEM
CHI	3	09/06	12		
CHI	41	09/06	10	10	Water, commissary, toilet/trash dumping Commissary. Train spotted in station at 618pm.
CHI	331	09/06	19	9	Heat / AC ID4017, Hot humid car
CHI	331	09/06	19	10	Mechanical inspection Other, CHI TRK 19
CHI	339	09/06	22	22	Service, turn, or wye train 338
CHI	341	09/06	14	14	Tied on the AMTK 57 , lack of mechanical, crew had to do the load test, brake test, and put together the hoses and cables 57
DER	355	09/06	15	13	Late arriving busses to DER
ARN	729	09/06	1		
BFD	717	09/06	2	2	Hold for thruway bus
BFD	719	09/06	14	14	Hold for thruway bus
GTA	770	09/06	12	12	Air / Brake / Wheel 6409, GTA mechanical changing out brake shoes late turn over
GTA	782	09/06	14	14	Meet 765, Control Point, CO 358
IRV	595	09/06	4	4	Door 6900
LAX	2	09/06	2	2	Follow 11Q, Milepost, 0.0, 0.0
LAX	14	09/06	12	12	Loading prombles coaches
OKJ	714	09/06	7	7	Main reservoir dropping under 100psi C2003

Amtrak Initial Terminal Details

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 9/6/2026

Terminal	Train	Date	Late	Delay	Cause
OKJ	720	09/06	4	4	Door C6964, Door Leaf #6 in cab car CDTX 6964 was stuck in pocket and would not close. Door had to be located, manually forced closed and locked out.
SAC	737	09/06	2	2	On-train police or DEA activity Departure hold requested by Amtrak Police while they swept the train for a missing at-risk juvenile.
SAN	567	09/06	(Trn Cxld)		Track Washout
SAN	761	09/06	(Trn Cxld)		Track Washout
SAN	765	09/06	13	13	PTC due to station stop modifications. Consist in two parts IRV—>lax, and our San—>OSD with bus bridge OSD—>irv Control Point, Ash
SAN	769	09/06	5	5	PTC system failure (wayside) PTC could not be initialized from original track 2, shoved the equipment east passing CP Broadway to depart from track 4 per DS, passenger boarding was delayed., Control Point, ash
SJC	734	09/06	11	11	Meet San Jose control held us at SJC until 733 got all the way into the station delaying us 11 minutes, 733, Other, SJC depot
SJC	744	09/06	8	8	Service, turn, or wye train 741

Eastern Region

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	98.7	94.8	166	1
CDOT	95.0	100.0	91.1	92.4	16	0
MARC	95.0	91.7	92.2	90.2	12	1
SEPTA	95.0	95.5	93.3	91.5	110	5
NJT-NED	95.0	97.4	93.9	88.6	191	5
NJT-SED	95.0	100.0	98.6	97.2	24	0

Operating Highlights

Train 53(06) - Florence, SC - Recrew/System

07SEP26: Train 53(06) was delayed at Florence, Station/MP 292.8 on the CSX Charleston Subdivision due to holding for a recrew.

Train	Delay	Comment
53(06)	30"	

Train 19(06) - Washington, DC - Engine Failure

06SEP26: Train 19(06) was delayed at Washington Union Terminal due to E/343 repeatedly displaying faults, which were eventually cleared by mechanical personnel.

Train	Delay	Comment
19(06)	30"	

Train 49(06) New York, NY - Engine Failure

06SEP26: Train 49(06) with E/94, E/703 and 9 cars was delayed departing New York due to E/703 being shopped and it was necessary to cap with E/94.

Train	Delay	Comment
49(06)	2'14"	

Train 237(06) New York, NY - Servicing

06SEP26: Train 237(06) with E/713, E/117 and 5 cars was delayed departing New York due to the late turn off 284(06).

Train	Delay	Comment
237(06)	38"	

Train 165(06) Boston, MA - Catenary or Wayside Failure

06SEP26: As of 316-ET, 26-FOI=00731 165(06) with "UNCLASSIFIED" 9/18/2026 was delayed on the Amtrak New Haven to Boston main line at Boston Back Bay station due to the loss of overhead catenary power between MP 228.0/Cove and MP 224.3/Plains on tracks 1 and 3. MBTA Police reported excessive arcing coming near Plains. Boston was getting a rescue set ready to pull 165(06) under power. As of 355P-ET, ET reported that there was down wire on top of 165(06) at Back Bay and damage to the pantograph. As of 422P-ET, ET reported they were able to get power back on track 3 between Cove and Plains. Track 3 ok for Diesel and Electric moves along with track 2 as well.

As of 456P-ET, Train 167(06) took all customers off 165(06). As of 459P-ET, Train 169(06) equipment will be moved up and used for late 165(06). As of 515P-ET Boston reported that the cleaning crew would need 25-30" to clean the equipment off 152(06) to use for 165(06).

Train 2271(06) was able to depart operating on track 2.

Train	Delay	Comment
2271(06)	02"	
167(06)	09"	BBY
165(06)	2'16"	

CSX Heat Orders - Weather

06SEP26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(06)	1'01"	
52(06)	21"	
98(06)	1'02"	
97(05)	27"	

Train 41(04) Jacksonville, FL - Re-Crew/System

06SEP26: Train 41(04) with E/145, E/199 and 10 cars was delayed on the CSX Jacksonville Terminal A due to holding for recrew engineer to bring the train into the station.

Train	Delay	Comment
41(04)	51"	

Train 164(06) New Carrollton, MD - Engine Failure

06SEP26: At 925A-ET, Train 164(06) with E/611 and 8 cars with 408 customers onboard was delayed at New Carrollton station on track 2 due to having power issues with E/611. Crew was speaking with Amtrak Road Foreman. Crew reported that the MCB kept opening and HEP was working intermittently they did attempt to recycle two times but were unsuccessful.

The train was 5 cars out of New Carrollton station and was not a good spot for customer transfer. Washington was preparing E/614 as a rescue and will be added ahead with a tech rider. As of 1028A-ET, Crew reported that HEP was restored. As of 1039A-ET, The rescue E/614 was enroute to the train and arrived to New Carrollton at 1055A-ET. As of 1124A-ET, Engine 614 was added ahead and the train was able to proceed north.

Service Recovery was initiated with snack packs and water.

Train	Delay	Comment
164(06)	2'02"	
118(06)	13"	

Train 41(04) South of Columbia, SC - Passenger Train Interference

06SEP26: Train 41(4) with 45" delay and 40(5) was delayed on the CSX Columbia S at MP 385.4 due to meeting 40(05).

Train	Delay	Comment
41 (04)	45"	

Metro North Track Outage Croton, NY - M of W Work

29AUG26: Due to Metro North track outages on the Hudson Line between Croton, NY and Poughkeepsie, NY, multiple Amtrak trains were delayed due to single tracking conditions.

Train	Delay	Comment
240 (29)	29"	
280 (29)	18"	
233 (29)	54"	
283 (29)	64"	
284 (29)	39"	
291 (29)	36"	
290 (29)	47"	
49 (29)	49"	
235 (29)	49"	
48 (28)	31"	
237 (29)	36"	
239 (29)	1' 10"	
69 (30)	51"	
240 (30)	35"	
1233 (30)	18"	
291 (30)	45"	LATE TURN OFF 240 (30)
284 (06)	1' 01"	

Maintenance of Way Highlights

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 80 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Burlington 10-minutes later and operate 25-minutes later between Durham and Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will be canceled in entirety and replaced by bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-10Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 20Oct-40Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77 (03)	50"	
78 (03)	50"	Turn of Late 77 (03)

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, B0000008777 Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

26-FBI-00731 a 00000008772 in "UNCLASSIFIED" open 9/18/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
159 (5)	BAL	E/665		Speed sensor

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Train 1(05)/421(04) East of Yuma, AZ - Freight Train Interference

07SEP26: Train 1(05)/421(04) was delayed east of Yuma, AZ, at Fortuna (MP 743.1) on the Union Pacific Gila Subdivision due to freight traffic interference. Freight train ILBG4-06, led by UP 6552, was required to set out a leaning railcar at the East Yuma Yard, temporarily blocking train movements through the area. Once the setout was completed and the route cleared, Train 1(05)/421(04) resumed its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(05)/421(04)	1'06"	

Train 716(06) East of Hanford, CA - Third Party Contractor Cab Car Failure

06SEP26: Train 716(06), operating with cab car 90218, seven cars, locomotive C2108, and carrying 62 customers onboard, was delayed just east of Hanford, CA, at MP 966.8 on the BNSF Bakersfield Subdivision due to a Positive Train Control (PTC) issue caused by a failed speedometer in the cab car. The crew coordinated with Amtrak management and BNSF personnel and were granted authorization to operate with PTC cut out and subject to a maximum authorized speed of 59mph.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
716(06)	1'17"	

Train 3(05) East of Flagstaff, AZ - Freight Train Interference

06SEP26: Train 3(05), carrying 173 customers onboard, was delayed east of Flagstaff, AZ, on the BNSF Seligman Subdivision due to freight traffic interference. The train followed a BNSF freight train from East Darling (MP 326.7) through East Flagstaff (MP 340.6), resulting in reduced operating speeds and delays through the area.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(05)	43"	

Train 794(06) South of Oxnard, CA - Vehicle Strike

06SEP26: At approximately 05:05 PM, Train 794(06), consisting with cab car C6952, five cars, locomotive C2114, and carrying 392 customers onboard, struck a vehicle south of Oxnard, CA, at MP 405.25 on the Union Pacific Santa Barbara Subdivision at the Santa Rosa Avenue crossing in the City of Oxnard, Ventura County, California. The incident occurred at DOT Crossing No. 745854B, a single-main-track public grade crossing equipped with advance warning signs, signals, pavement markings, and functioning gate arms. No injuries to customers or crew members were reported. The vehicle occupants were found unresponsive and were removed from the scene by emergency medical personnel. Local law enforcement, EMS, Amtrak Police, the fire department, an Amtrak Road Foreman, and a Union Pacific Track Inspector responded to the scene. Head-end power remained operational throughout the incident.

The incident resulted in the following service impacts and recovery actions:

- Train 785(06) was delayed while holding at Camarillo, CA, pending restoration of train movements through the affected territory.
- To maintain service, Train 785(06) was routed around the scene via a freight yard after a freight train occupying the siding cleared the route, allowing the train to proceed through Oxnard and continue north.
- A relief crew was dispatched from Los Angeles, CA, to assume operation of Train 794(06).
- Following removal of the vehicle, completion of investigative activities, and required air brake testing, Train 794(06) was released for service and continued its trip with the relief crew.

National Response Center Number: 1472947

Train	Delay	Comment
794(06)	3'12"	
785(06)	1'50"	

Train 5(06) East of Creston, IA - Freight Train Interference

06SEP26: Train 5(06), with 225 customers onboard, held at control point 3818/MP381.8, 11 miles east of Creston, IA/MP393.1, on the BNSF Ottumwa subdivision meeting BNSF freight BN/6132. Once the route was clear, train 5(06) continued west.

Train	Delay	Comment
5(06)	35"	

Train 59(06) South of Kankakee, IL - Passenger Train Interference

06SEP26: Train 59(06), with 239 customers onboard, was delayed at Delrey/MP87.3, 31 miles south of Kankakee, IL/MP55.9, on the CN Chicago subdivision meeting Amtrak train 392(06). Once the route was clear, train 59(06) continued south.

Train	Delay	Comment
59(06)	32"	

Train 22(06)/422(04) Marshall, TX - Freight Train Interference

06SEP26: Train 22(06)/422(04), 0000000877114 "UNCLASSIFIED" onb 9/18/2026 held at Marshall, TX/MP66.5 on the UP Little Rock subdivision due to UP key train UP/6840 disabled at mile post 39.7. UP mechanical arrived on the scene to assist the freight conductor with the inspection. A broken knuckle was identified and replaced. Air pressure was restored. Train 22(06)/422(04) departed Marshall Station to close the distance while UP/6840 prepared to move. Once on the move, train 22(06)/422(04) followed the freight to Texarkana, AR/MP0.0.

Train	Delay	Comment
22(06)/422(04)	51"	Holding at MHL
22(06)/422(04)	1'22"	Follow FRT to TXA

Train 352(06) West of Jackson, MI - Passenger Train Interference

06SEP26: Train 352(06), with 269 customers onboard, was delayed at control point 75/MP75.7, 0.2 miles west of Jackson, MI/MP75.5, on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(06). Once the route was clear, train 352(06) continued east.

Train	Delay	Comment
352(06)	39"	

Train 714(06) Stockton, CA - Car Strikes Train

06SEP26: At approximately 3:54 PM PT, Train 714(06), operating with cab car C8309, seven cars, locomotive C2003, and carrying 102 customers onboard, was struck by a vehicle fleeing law enforcement at Stockton Station (MP 1121.1) on the BNSF Stockton Subdivision in the City of Stockton, San Joaquin County, California. The incident occurred at DOT Crossing No. 029608S, a double-main-track public grade crossing equipped with advance warning signs, signals, pavement markings, and functioning gate arms. No injuries to customers or crew members were reported. Head-end power remained operational throughout the incident. Local authorities, an Amtrak Road Foreman, and Amtrak management personnel responded to the scene.

Following the collision, Train 714(06) remained in an undesired emergency brake application, blocking both the crossing and station platform while damage assessments were conducted. Due to the operational impact of the incident, the following service adjustments were implemented:

- Train 716(06), carrying 91 customers onboard, was held at Holt (MP 1129.4) on the BNSF Stockton Subdivision before advancing to Stockton Station.
- Customers from Train 714(06) were transferred to Train 716(06) for continued travel.
- Train 714(06) was terminated at Stockton, CA pending equipment inspection and repair.
- Mechanical personnel determined the equipment required replacement of a damaged valve before it could be returned to service.
- Following repairs, the equipment operated as a deadhead movement to Bakersfield, CA.

The incident also resulted in downstream crew impacts. Train 717(06) was delayed at Merced, CA, while awaiting a replacement engineer after the originally assigned engineer became involved in the response to the Train 714(06) incident. Once the relief engineer arrived, Train 717(06) resumed its scheduled operation.

National Response Center Number: 1472935

Train	Delay	Comment
714(06)	Term SKN	
716(06)	1'07"	
717(06)	1'33"	

Train 58(06) South of Greenwood, MS - Freight Train Interference

06SEP26: Train 58(06), with engines IDTX4625 and IDTX4610, 5 cars, and 149 customers onboard, was delayed at Sidon siding/MP128.8, 6 miles south of Greenwood, MS/MP122.5 on the CN Yazoo subdivision meeting CN freight CN8006. Once the route was clear, train 58(06) continued north.

Train	Delay	Comment
58(06)	30"	

Train 6(05) Fraser-Winter Park, CO - Signal

06SEP26: Train 6(05), with 170 customers onboard, was delayed at East Winter Park/MP56.6, 6 miles east of the Fraser-Winter Park Station/MP62.3, on the UP Moffat Tunnel subdivision due to a stop signal issued by dispatch. Once the route was clear, train 6(05) continued east.

Train	Delay	Comment
6(05)	35"	

Train 728(06) Suisun-Fairfield, CA -Fire on Tracks

06SEP26: Train 728(06) with 145 passengers onboard was stopped at Suisun Fairfield, CA due to a reported fire ahead near MP 49.3 on the UPRR Martinez Subdivision. Authorities responded and subsequently issued an all-clear. Rail traffic remained suspended pending a track inspection. The track inspector completed the inspection and authorized rail traffic to resume.

Train	Delay	Comment
728(06)	39"	
741(06)	31"	

Train 338(06) West of Glenview, IL - Debris Strike

06SEP26: Train 338(06), with engines IDTX4625 and IDTX4610, 5 cars, and 149 customers onboard, struck debris on the track around mile post 30.0, 12.5 miles west of Glenview, IL/MP17.32, on the CPKC C&M subdivision. There were no injuries reported by the customers or crew. The crew had to replace a damaged brake hose in order to recover air pressure. Once the brake test was completed, train 338(06) continued east.

Train	Delay	Comment
338(06)	40"	

Train 503(06) North of Eugene, OR - Passenger Train Interference

06SEP26: Train 503(06), carrying 58 customers onboard, was delayed north of Eugene, OR, at Swain (MP 659.2) on the Union Pacific Brooklyn Subdivision while meeting Amtrak Train 14(05).

Train	Delay	Comment
503(06)	31"	

Train 786(06) North of Lompoc-Surf, CA - Passenger Train Interference

06SEP26: Train 786(06), carrying 87 customers onboard, was delayed approximately 5 miles north of Lompoc-Surf Station, while holding at Tangair Siding (MP 294.7) on the Union Pacific Santa Barbara Subdivision to meet Amtrak Trains 765(06) and 14(06).

Train 714(06) South of Emeryville, CA - Third Party Contractor Engine Failure

06SEP26: Train 714(06) added by 000000087779 with 211 passengers onboard, stopped at MP 5.7, approximately 2 miles south of Emeryville, CA, on the UPRR Niles Subdivision after losing main reservoir air pressure. TASI responded and began troubleshooting the equipment. The issue was successfully resolved, and the equipment was returned to service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
714(06)	1'14"	

Train 22(06)/422(04) Fort Worth, TX - Servicing

06SEP26: Train 22(06)/422(04) with 119 customers was delayed on the BNSF Fort Worth subdivision departing Fort Worth due to fueling. Once the service and inspection was complete, 22(06)/422(04) depart Fort Worth at 258PM-CT, 35 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(06)/422(04)	35"	

Train 59(05) South of McComb, MS - Temporary Speed Restrictions

06SEP26: Train 59(05) with 126 customers was delayed on the CN McComb subdivision starting one mile south of McComb between MP 808.4 and MP 856.2 due to temporary speed restrictions.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(05)	30"	

Train 729(06) Martinez, CA - Third Party Contractor Engine Failure

06SEP26: Train 729(06) with 144 passengers reported C2001 stopped loading at Martinez, CA on the UPRR Martinez subdivision. HEP remained available, and the crew began troubleshooting the issue. Due to the loading failure, passengers from 729(06) were transferred to 733(06). Train 729(06) was subsequently terminated at Martinez station while the crew continued troubleshooting.

Following corrective actions, C2001 successfully passed a load test. The equipment was cleared and was then deadheaded (DH) to San Jose, CA for its scheduled turn..

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
729(06)	term MTZ	
733(06)	3"	Board 729(06) pax

Train 2(04) East of Houston, TX - Routing

06SEP26: Train 2(04) with 106 customers was delayed east of Houston due to being routed over the lengthier UPRR Beaumont subdivision between Houston and Beaumont.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
2(04)	33"	

Train 5(05) Denver, CO - Signal

06SEP26: Train 5(05) with 190 customers was delayed departing Denver on the UPRR Greeley subdivision due to a power outage that caused switch issues. C&S responded to the scene and took the switches in hand to create a route for train 5(05). Once the route was lined up, train 5(05) departed Denver at 931AM-MT, 45 minutes late.

Train 59(05) South of Memphis, TN - Freight Train Interference

06SEP26: Train 59(05) with 100 customers was delayed on the CN Yazoo subdivision starting 13 miles south of Memphis between Lakeview/MP 13.1 and Rials/MP 29.8 due to following CN 8929.

25-FOI-00731 00000008777 UNCLASSIFIED 9/18/2026

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(05)	30"	

Train 331(06) Chicago, IL - Car Failure

06SEP26: Train 331(06) with E/ID4610, four cars, and E/ID4625 departed Chicago at 844AM-CT, 19 minutes late due to C/ID4017 reported hot and unable to repair. As a result, the following trains were over capacity: 334(06), 335(06), 331(07), 335(07), 338(07), and 342(07). All customers were advised of over capacity conditions and fare protected. There was no alternate transportation available for train 334(06). One bus was secured for train 335(06) and cancelled due to no longer being over capacity after messaging was sent. One express bus was secured for each of trains 331(07) and 335(07) operating between Chicago and Milwaukee.

WBS#: B.TR.100150.7154

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
331(06)	19"	

Train 58(05) Chicago, IL - Car Failure

06SEP26: Train 58(05) with 160 customers was delayed four miles south of Chicago at 16th Street/MP 2.1 due to air issues. The crew rectified the issues and continued to Chicago. As a result, train 391(06) was also delayed meeting train 58(05) at 21st Street/MP 2.7.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
58(05)	26"	
391(06)	24"	

Train 371(06) East of St. Joseph-Benton Harbor, MI - Drawbridge Opening

06SEP26: Train 371(06) with 118 customers was delayed on the CSX Grand Rapids subdivision one miles east of St. Joseph-Benton Harbor due to maritime traffic at the St. Joseph's Bridge/MP 87.6.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
371(06)	31"	

Train 8/28(04) East of Fargo, ND - Freight Train Interference

06SEP26: Train 8/28(04) with 200 customers was delayed on the BNSF Staples subdivision starting five miles east of Fargo between Watts/MP 1.0 and Hawley/MP 233.8 due to following HGFDBRC1-05.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(04)	37"	

Train 6(05) West of Salt Lake City, UT - Passenger Train Interference

06SEP26: Train 6(05), 26-FOI-00731 00000008777 UNCLASSIFIED 9/18/2026, delayed just west of Salt Lake City, UT, at MP 744.9 on the Union Pacific Provo Subdivision while awaiting station occupancy at Salt Lake City. The train held while Amtrak Train 5(04) completed station work, allowing Train 6(05) to subsequently proceed into the depot.

Train	Delay	Comment
6(05)	1'04"	

Train 3(04) East of Kingman, AZ - Freight Train Interference

06SEP26: Train 3(04), carrying 127 customers onboard, was delayed east of Kingman, AZ, on the BNSF Seligman Subdivision while meeting BNSF 6867 at Yampai (MP 453.5). The train incurred additional delay while following a BNSF freight train between MP 507 and Kingman Station (MP 516.3).

Train	Delay	Comment
3(04)	49"	

Wolverine Service - Pontiac, MI Wye OOS

04SEP26: Canadian National reported that the Pontiac, MI wye on the CNRR Holly Subdivision was removed from service due to wide gauge and was expected to remain out of service until Tuesday, September 7. As a result, Train 355(04) departed Pontiac on time but incurred delay en route to Detroit, MI while completing a shove move to Milwaukee Jct (MP4.1) to wye the equipment. After the wye move was completed, Train 355(04) continued toward Chicago operating at track speed.

05SEP26: Train 351(05), with 14 customers onboard, departed Pontiac, MI 2 hours and 31 minutes late due to the late wyeing of the engines at Milwaukee Jct prior to departure. The wye move was delayed by the late arrival of inbound Train 354(04), which arrived at 3:16AM-ET.

Due to the Pontiac, MI wye being out of service and Chicago unable to support a push-pull trainset, Train 350(05-07) was terminated at Detroit, MI, with two alternate buses secured for 05SEP, one alternate bus secured for 06SEP, and two alternate buses secured for 07SEP. Train 355(05-07) originated at Dearborn, MI, with two alternate buses secured for 355(05), two alternate buses secured for 355(06), and three alternate buses secured for 355(07) between Pontiac, MI, and Dearborn, MI, to accommodate customers.

WBS#: B.TR.100150.7144

Train	Delay	Comment
355(04)	31"	
351(05)	2'31"	ITD PNT
355(05-06)	ORIG DER	
350(05-06)	TERM DET	
355(05)	56"	Air Issues @DER

Union Pacific Sedalia, Jefferson City, Springfield and Joliet Subdivision Kansas City, MO to St. Louis, MO to Joliet, IL - Heat Restrictions

31AUG26: Union Pacific placed Level 2 heat restrictions on the entire Sedalia and Jefferson City Sub division from Kansas City, MO and St. Louis, MO. Trains were limited to 40mph. Train 311(31), 316(31), 318(31), and Train 319(31) were delayed account of the restrictions.

01SEP26: Union Pacific also added Level 2 heat restrictions on the Joliet and Springfield Subdivision from St. Louis, MO and Joliet, IL. Trains were limited to 50mph through 04SEP.

WBS#: B.TR.100150.7132

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Train	Delay	Comment
316(31)	31"	
319(31)	32"	
318(31)	14"	
311(31)	12"	
301(01)	1'30"	JOL to STL
302(01)	1'04"	LCN to JOL
311(01)	51"	HEM to KCY
305(01)	1'05"	JOL-LCN
22(31)	1'02"	ALN-JOL
307(01)	20"	JOL-DWT
21(01)	1'58"	JOL-ALN
306(01)	1'04"	
301(02)	1'05"	
22(01)/422(30)	1'58"	
302(02)	1'02"	
21(02)	1'57"	
319(02)	1'53"	
307(02)	24"	
305(02)	1'09"	
306(02)	1'01"	
311(02)	44"	
316(02)	36"	
318(02)	2'16"	
316(01)	28"	
318(01)	2'41"	
319(01)	2'28"	
302(03)	1'10"	
301(03)	1'35"	
311(03)	52"	
22(02)	1'52"	
319(03)	2'45"	
318(03)	3'11"	
305(03)	1'16"	
306(03)	1'08"	
307(03)	26"	
316(03)	44"	
21(03)	1'40"	
311(04)	33"	
302(04)	1'25"	
301(04)	1'25"	
307(04)	45"	Turn 302(04)
22(03)	1'46"	
305(04)	20"	
306(04)	44"	
318(04)	2'01"	
316(04)	42"	
319(04)	2'23"	
21(04)	1'59"	
300(05)	09"	
302(05)	23"	
301(05)	44"	
22(04)	45"	
311(05)	1'16"	
316(05)	27"	ITD KCY - Turn of 311(05)
316(05)	23"	Heat Orders
21(05)	03"	
319(05)	1'37"	
318(05)	2'22"	
306(05)	37"	
311(06)	27"	
316(06)	23"	
319(06)	26"	

Maintenance of Way Highlights

Coast Starlight - Scheduled M/W Work 26-090

26-010273 90000077 UNCLASSIFIED 9/18/2026

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 19Sep, 26Sep), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 19Sep 26Sep), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
14 (22)	23"	
11 (22)	32"	

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT has trackwork scheduled on the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:

- Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
 - Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
 - Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
 - Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
- *Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm
- Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

- Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.
- Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track work projects on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
 - Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
 - Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
 - Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
 - Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
 - Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.
- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
 - Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
 - Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
 - Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
 - Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
 - Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has t26-FOI-00731 00900008777"UNCLASSIFIED" 9/18/2026
Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

26-FOI-00731 00000008777
Western Region

"UNCLASSIFIED"

9/18/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
	Thenard, CA	76		MU issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
5 (4)	EMY	UP5727	Dynamic brakes		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00731

00000008777

"UNCLASSIFIED"

9/18/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
331 (06)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	YES	54	ID4017
335 (06)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	NONE	0	ID4017
339 (06)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	NONE	0	ID4017
331 (07)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	YES	16	ID4017
335 (07)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	YES	44	ID4017
339 (07)	CHI	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	NONE	0	ID4017
5 (07)	CHI	Operating with standard coach in lieu of bag coach. Inventory has been increased to reflect lower level seating. No bag coach on yard to correct consist.	N/A	0	34052
21 (07)	CHI	Operating with snack coach in lieu of standard coach for transfer car.	N/A	0	35005
782 (06)	GTA	DUE TO EQUIPMENT SWAP UTILIZING 90225 WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS.	NONE	0	90225
761 (06)	LAX	DUE TO EQUIPMENT SWAP UTILIZING 90225 WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV RESERVATIONS.	YES	6	90225
334 (06)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	YES	45	ID4017
338 (06)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	NONE	0	ID4017
330 (07)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	NONE	0	ID4017
334 (07)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted	NONE	0	ID4017

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00731 00000008777 "UNCLASSIFIED" 9/18/2019			
		customers.			
338 (07)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	YES	16	ID4017
342 (07)	MKE	BYD HVAC, Y-Reduced. Please reaccomodate any impacted customers.	yes	42	ID4017
22 (07)	STL	Operating with snack coach in lieu of standard coach for transfer car.	N/A	0	35005

Reverse Consists

Train Number	Station	Reason
161 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
195 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
87 (06)	BOS	Consist reversed Business class seat orientation may have changed At Front
128 (06)	NFK	Consist reversed Business class seat orientation may have changed At Front
164 (06)	NPN	Consist reversed Business class seat orientation may have changed At Front
150 (06)	PHL	Consist reversed Business class seat orientation may have changed At Front
150 (06)	PHL	Consist reversed Business class seat orientation may have changed At Front
194 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front
88 (06)	WAS	Consist reversed Business class seat orientation may have changed At Front
128 (07)	NFK	Consist reversed Business class seat orientation may have changed At Front