



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Thursday, July 24, 2025

Rules:1-50



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/23/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/23/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	6,636	792	88.1%	85,343	8,461	90.1%
Central Division	91.5%	65	9	86.2%	1,510	167	88.9%	19,539	1,907	90.2%
Northeast Division	95.0%	95	8	91.6%	2,091	286	86.3%	28,046	3,049	89.1%
Southeast Division	94.5%	69	6	91.3%	1,464	176	88.0%	18,893	1,890	90.0%
Southwest Division	90.5%	71	9	87.3%	1,571	163	89.6%	18,865	1,615	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/23/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	92,838	28,164	70%	2,378,688	759,650	68%	27,764,081	7,477,631	73%
Northeast Corridor	80%	39,827	9,329	77%	1,023,691	309,856	70%	12,324,101	3,186,502	74%
Acela	82%	9,269	2,548	73%	208,395	62,455	70%	2,562,312	617,121	76%
Northeast Regional	78%	30,558	6,781	78%	815,296	247,401	70%	9,761,789	2,569,381	74%
Richmond / Newport News / Norfolk	73%	9,936	2,427	76%	260,204	108,019	58%	3,150,356	1,080,556	66%
Springfield Shuttles	89%	387	100	74%	9,979	2,397	76%	175,976	27,041	85%
Roanoke	70%	2,356	1,813	23%	68,115	19,695	71%	822,292	216,920	74%
On Spine Northeast Regional	83%	17,879	2,441	86%	476,998	117,290	75%	5,613,165	1,244,864	78%
State Supported	80%	41,131	9,714	76%	1,047,676	270,670	74%	11,859,223	2,630,403	78%
Borealis	60%	514	62	88%	14,319	8,971	37%	171,026	72,149	58%
Capitol Corridor	90%	3,657	417	89%	78,564	6,287	92%	887,759	94,991	89%
Carolinian	60%	929	665	28%	24,294	12,411	49%	340,104	140,835	59%
Cascades	60%	2,446	1,077	56%	69,362	20,550	70%	752,242	258,576	66%
Downeaster	82%	1,419	63	96%	42,382	8,632	80%	421,064	101,625	76%
Empire	83%	5,167	950	82%	135,194	51,882	62%	1,597,176	354,178	78%
Adirondack	75%	259	103	60%	9,492	5,705	40%	87,487	28,404	68%
Ethan Allen Express	85%	520	305	41%	14,650	9,806	33%	159,861	43,130	73%
Maple Leaf	75%	713	169	76%	20,421	12,033	41%	216,498	67,196	69%
New York - Albany	90%	2,406	303	87%	53,994	13,833	74%	740,970	117,267	84%
New York - Niagara Falls	75%	1,269	70	94%	33,272	8,548	74%	387,105	95,447	75%
Berkshire Flyer	60%	0	0	-	3,365	1,957	42%	5,255	2,734	48%
Heartland Flyer	70%	232	220	5%	6,042	4,846	20%	65,561	30,909	53%
Hiawatha	90%	1,898	419	78%	49,456	5,926	88%	499,968	65,291	87%
Illinois	78%	2,243	628	72%	62,426	21,128	66%	732,838	178,205	76%
Carl Sandburg / Illinois Zephyr	80%	499	1	100%	11,173	2,027	82%	117,851	15,116	87%
Illini / Saluki	80%	700	87	88%	20,937	5,048	76%	259,234	33,919	87%
Lincoln Service	75%	1,044	540	48%	30,316	14,053	54%	355,753	129,170	64%
Keystone	92%	8,593	763	91%	178,079	14,594	92%	2,142,867	289,276	87%
Lincoln / Missouri	60%	772	452	41%	19,984	12,350	38%	213,961	117,231	45%
Michigan	69%	2,086	163	92%	57,637	14,538	75%	575,652	160,997	72%
Blue Water	70%	490	133	73%	14,100	3,951	72%	142,699	41,843	71%
Pere Marquette	85%	342	0	100%	7,236	1,256	83%	76,312	9,888	87%
Wolverine	65%	1,254	30	98%	36,301	9,331	74%	356,641	109,266	69%
Missouri	80%	165	51	69%	6,006	3,862	36%	64,838	23,350	64%
Pacific Surfliner	85%	6,823	904	87%	167,688	25,559	85%	1,702,297	274,910	84%
Pennsylvanian	72%	802	120	85%	22,007	6,957	68%	258,022	69,338	73%
Piedmont	73%	808	289	64%	22,825	6,492	72%	332,016	79,914	76%
San Joaquins	73%	1,416	1,310	7%	61,057	31,769	48%	724,869	206,139	72%
Vermonter	75%	1,161	1,161	0%	30,354	13,916	54%	376,963	112,489	70%
Long Distance	57%	11,880	9,121	23%	307,321	179,124	42%	3,537,232	1,657,124	53%
Auto Train	57%	674	332	51%	18,790	6,381	66%	221,562	137,584	38%
California Zephyr	45%	1,651	1,651	0%	27,157	20,926	23%	289,800	127,426	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	0	0	-	5,929	2,833	52%	79,979	39,848	50%
City Of New Orleans	75%	649	648	0%	13,883	7,013	49%	188,683	55,222	71%
Coast Starlight	65%	928	819	12%	24,609	8,477	66%	310,410	129,223	58%
Crescent	60%	709	363	49%	24,150	8,641	64%	256,218	66,165	74%
Empire Builder	55%	1,196	695	42%	28,275	16,712	41%	283,266	125,215	56%
Floridian	40%	1,692	1,561	8%	34,982	29,029	17%	398,337	292,809	26%
Lake Shore Ltd	70%	880	488	45%	25,609	10,029	61%	297,446	82,657	72%
Palmetto	65%	484	335	31%	22,748	11,064	51%	290,896	112,180	61%
Silver Meteor	45%	848	323	62%	23,804	15,783	34%	273,190	143,689	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,028	1,020	1%	24,603	19,807	19%	237,539	146,733	38%
Sunset Ltd	50%	582	510	12%	6,538	3,405	48%	78,177	29,201	63%
Texas Eagle	60%	559	376	33%	26,244	19,024	28%	274,134	146,676	46%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 23, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	169,602	2,401,878	706	1,881,783	30,845,815	610

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	8,543	700,792	122	99,627	9,028,871	110
INFRASTRUCTURE PLANNED	90	5,527	700,792	79	92,673	9,028,871	103
FLEET RELIABILITY	83	30,135	2,401,878	125	299,015	30,845,815	97
TRAIN OPERATIONS	382	125,397	2,401,878	522	1,390,468	30,845,815	451

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Acela Cancellations - Shopped Equipment

24JUL25: Due to multiple shopped Acela train sets, the following service adjustment were necessary: Acela Trains 2190(24), 2163(24), 2152(24) and 2169(24) were canceled in entirety for Thursday, July 24th, 2025. Passengers were notified via Service 360 and able to re-book to next available services.

Train 2166(23) Boston, MA - Engine Failure

23JUL25: at approximately 8:02PM-ET the Boston Chief reported that Train 2166(23), TS6, PC/2030, 6 cars, PC/2031, was disabled at Boston, MA Back Bay station. The crew reported both of their pantographs dropped as they were pulling into the station. Crew worked with an Amtrak Road Foreman and mechanical to try and resolve the issue. The crew was to expire on hours of service at 8:30PM-ET, therefore a yard crew was dispatched from Boston SHSY to protect the train into Boston. Still unable to resolve the issue, the decision was made to transfer all 103 passengers to Keolis 874 and terminate the train. The crew was later able to raise the pantographs but were still unable to proceed with power car PC/2030 in the lead. Due to this, the train made a shove move into to Boston station, arriving at 8:53PM-ET.

Train	Delay	Comment
2166(23)	Terminated	BBY

Train 20(23) Meridian, MS - Injured or Sick Passenger

23JUL25: Train 20(23) was delayed departing Meridian, MS due to waiting for EMS to remove a sick passenger with reported low blood sugar.

Train	Delay	Comment
20(23)	32"	

Train 20(23) North of Birmingham, AL - Switch Issue

23JUL25: Train 20(23) was delayed at Lovick/ MP787.7, 12 miles north of Birmingham, AL on the Norfolk Southern East End Subdivision, due to switch failure and unable to line. Once signal maintainer arrived and was able to line the switch, Train 20(23) continued north.

Train	Delay	Comment
20(23)	1'17"	

Train 52(23) Sanford, FL - initializing PTC - System

23JUL25: Train 52(23) was delayed departing Sanford due to having problems initializing PTC.

Train	Delay	Comment
52(23)	42"	

Train 64(23) East of Syracuse, NY - Freight Train Interference

23JUL25: Train 64(23) was delayed on the CSX Syracuse Terminal at MP 287.0 due to the CSX meeting I019-23 set out cars and then meeting I104-22, I003-23.

Train	Delay	Comment
64 (23)	55"	

Train 40(22) North of Rocky Mount, NC - EMS/Police Related

23JUL25: Train 40(22) was delayed on the CSX North End A subdivision at MP 53.4/Jarrett and held for EMS for a unresponsive passengers. EMS arrived and the passenger was removed.

Train	Delay	Comment
40 (22)	51"	

Train 486(23) New Haven, CT - Hold for Connection

23JUL25: Train 486(23) was held in New Haven for connections off late train 86(23) at 305P-ET 47" late.

Train	Delay	Comment
486(23)	33"	

Train 79(23) Washington, DC - Adding Engine /Servicing

23JUL25: Train 79(23) was delayed departing Washington due to attempting to add E/749 to rear for Lorton. The crew was having parking brake issues and it was decided to cut the engine off and proceed with out it.

Train	Delay	Comment
79 (23)	54"	

AMTEC Systemwide Outage - CETC System

23JUL25: At 1031A-ET, Washington Terminal reported that K Tower lost AMTEC system and were now working in local control with C&S to make shifts in the terminal. As of 1050A-ET, CETC reported that the AMTEC system was coming back slowly. As of 1055A-ET, CETC reported that all sections were back under CETC control with the exception of section 5 which was in local control. As of 1118A-ET, CETC control for sections 5 for Penn Interlocking was restored and Remote control was restored for State Interlocking.

Train	Delay	Comment
2108 (23)	28"	
174 (23)	29"	
642 (23)	04"	
43 (23)	04"	
182 (23)	04"	
2153 (23)	10"	
114 (23)	23"	
646 (23)	40"	
190 (23)	03"	
607 (23)	02"	
2162 (23)	29"	
643 (23)	38"	
185 (23)	30"	
86 (23)	39"	
645 (23)	03"	
84 (23)	03"	
648 (23)	21"	
183 (23)	21"	
3 MARC'S	17"-24"	

Train 55(23) Essex Junction-Burlington, VT - Temporary Speed Restrictions

23JUL25: Train 55(23) was delayed on the NECR Roxbury subdivision starting 10 miles north of Essex Junction between MP 118.0 and MP 114.0 due to temporary speed restrictions. Train 56(23) was also delayed due to these restrictions.

Train	Delay	Comment
55 (23)	37"	
56 (23)	47"	

Train 2190(23) East of New York, NY - Engine Failure

23JUL25: Train 2190(23) with set 13 PC/2033,PC/2027 was delayed on the NYS main line at Leggett Interlocking due to an undesired emergency application. The crew was able to cut out the Alerter and proceed east.

Train	Delay	Comment
2190 (23)	33"	
66 (22)	25"	

NYS Main Line - Bridge Strike

23JUL25: At 825A-ET A vehicle struck the bridge at Kings Highway, MP 18.75, NYS Main Line between Manor and Division Post. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 955A-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
2151 (23)	02"	
2150 (23)	07"	
2153 (23)	02"	
170 (23)	03"	

Train 40(22) - South of Columbia, SC - Near Miss/Vehicle on Tracks

23JUL25: Train 40(22) was delayed on the CSX Columbia Subdivision at MP 371.9 due to a near miss with a vehicle on the tracks. The train held for a tow truck to remove the vehicle. The tow truck arrived at 640A-ET and the vehicle was cleared as of 657A-ET. The train was able to proceed north.

Service Recovery was initiated with complimentary coffee and tea in the cafe car.

WBS#: B.TR.100150.5918

Train	Delay	Comment
40 (22)	1' 47"	

Train 151(23) - New York, NY - Car Failure

23JUL25: Train 151(23) was delayed at its initial terminal at New York Penn Station due to coach 82531 being shopped and replaced.

Train	Delay	Comment
151 (23)	35"	

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District - Trackwork East of Solana Beach, CA
19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad.

Each project will be over selected Sunday and Monday nights:
from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

Sunday May 19 - Tuesday May 21
Sunday June 02- Tuesday June 04
Sunday June 16 - Tuesday June 18
Sunday June 23 - no extended window account Padres game.
Sunday June 30 - Tuesday July 2
Sunday July 7 - Tuesday July 9
Sunday July 14 - Tuesday July 16
Sunday July 21 - Tuesday July 23
Sunday July 28 - Tuesday July 30
Sunday August 4 - Tuesday August 6
Sunday August 11 - no extended window account Padres game
Sunday August 18th - Tuesday 20th
Sunday August 25 - Tuesday August 27
Sunday September 8 - Tuesday September 10.
Sunday September 15 - Monday September 16
Sunday September 22 - Tuesday September 24.
Sunday October 27 - Tuesday October 29.
Sunday November 3 - Tuesday November 5.
Sunday December 8-Tuesday December 10.
Sunday December 15-Tuesday December 17.
2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)
Sunday May 20 - Tuesday May 22

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

San Juanquins South of Stockton, CA - Signal

24JUL25: Multiple San Juanquins trains were delayed 1 mile south of Stockton, CA, on BNSF Stockton subdivision due to a power outage causing signal failure. This caused heavy traffic for all trains operating through the affected area.

Train	Delay	Comment
719 (23)	1'19"	
717 (23)	49"	
703 (23)	37"	
718 (23)	35"	
718 (23)	40"	Meeting 717/716 (23)

Train 59(23) Chicago, IL - Engine Failure

24JUL25: Train 59(23) was delayed departing Chicago account late release due to late train make up. As background, Train 58(22) arrived in CUS at 11:08am and set in the yard at 11:52am for inspection and servicing. Due to multiple b/o and no replacements, C/33034 was held off to Train 7(23), no replacement. Train 59(23) was also required to operate with an additional 2nd engine due to temperatures in excess of 100-degrees Fahrenheit. E/334 off inbound Train 8(21) was designated as the additional lead loco. Train 8(21) arrived in CUS at 05:43pm. Train 8(21) wyed to the yard at 06:38pm and set in Pit 3 at 07:07pm. After cuts were made, E/334 was held off at 07:32pm. E/334 was swung over to Track 12, Train 59(23) was m/u complete at 07:47pm. After servicing E/334 and completing Class II, Mechanical released train at 08:42pm. YC13 advanced into CUS at 08:50pm and set at 08:55pm. Boarding of 196 passengers commenced at 09:09pm. South Gate cleared at 09:32pm, Train 59(23) departed CUS at 09:45pm; 1 hour and 40 minutes late.

Train	Delay	Comment
59 (23)	1'40"	

Train 339(23) Chicago, IL - Initial Terminal Delay

24JUL25: Train 339(23) was delayed departing Chicago account late turn of equipment of Train 338(23) which arrived at 05:06pm; 27 minutes late due to a 22-minute delay 13 miles west of Glenview, IL for air hose separation between C/ID4208 and C/ID4017 and 7 minutes in commuter train interference. After detraining 115 passengers, boarding of 207 passengers commenced at 05:16pm. Train 339(23) was further delayed due to piston on front fireman side Cab Car 90221 not traveling correctly. Yard Mechanical was notified at 05:26pm. After deciding to address issues with Cab Car upon return of Train 342 to the yard, Mechanical cleared at 06:03pm. After initialized I-ETMS and conducted the required Class II air test, Train 339(23) departed CUS at 06:06pm; 58 minutes late.

Train 342(23) was delayed departing Milwaukee, Wisconsin, due to turning of late 339(23).

Train	Delay	Comment
339 (23)	58"	
342 (23)	39"	

Train 518(23) North of Mount Vernon, WA – Search and Rescue Operation

23JUL25: Train 518(23) was delayed 16 miles north of Mount Vernon, WA at Tunnel 18, MP 83.1, Scenic Subdivision, BNSF Railway. Local Emergency Responders were conducting a search and rescue effort to locate a missing person believed to have fell on the tracks. Once completed, with personnel clear of the rails, tracks were opened allowing train 518(23) to continue to Bellingham. Amtrak Police Notified.

Train	Delay	Comment
518 (23)	47"	

Train 21(22) North of San Antonio, TX - Freight Train Interference

23JUL25: Train 21(22) was delayed 13 miles north of San Antonio, TX, on UP Austin subdivision, due to disabled BNSF8240 with air issues obstructing the route. The disabled freight replaced a gasket on its rear car and was able to recover its air. Once recovered, the freight was able to proceed, clearing a route for train 21(22).

Train	Delay	Comment
21(22)	42"	

Train 716(23) East of Turlock Denair, CA – Locomotive Oil Pressure – Cancelled

23JUL25: Train 716(23) stopped 10 miles east of Turlock/Denair, Fairfield when locomotive CDTX/2003 developed a low oil pressure warning. The train stopped on the single mainline at east Fluhr MP 1065.5, Stockton Subdivision of BNSF Railway. The locomotive was unable to provide tractive effort. Head End Power was temporarily shut down for 20 minutes while diagnosing the cause.

There were 106 passengers on board. Outside temperature was 88 degrees and sunny. With no availability of replacement buses or rescue locomotives in the area the following amended operating plan applied:

Train 716(23) was cancelled at Merced.

To prevent engine damage, trains 716(23) & 717(23) were coupled together at site with both trains returning to Merced. Passengers for 716(24) disembarked at Merced to wait for train 718(23) to destination. The combined trainset then continued west.

Train 717/716(23) combined trainset terminated in Emeryville where passengers for Oakland boarded thruway 6617(23) making additional stop in Oakland.

Train 717(24) was cancelled, with all affected passengers advised to use alternate departures.

Service Recovery: All San Joaquin trains offer complimentary snacks and soda.

Cause: Pending

WBS#: B.TR.100150.5919

Train	Delay	Comment
716(23)	Terminates Merced	Passengers to 718(23)
717(24)	Cancelled	Passengers to Alternate Departures

Train 507(23) South of Seattle, WA – Interior Door Jammed Shut

23JUL25: Train 507(23) was delayed 6 miles south of Seattle when the crew reported the interior door in Bistro car C/48187 became lodged shut. The train returned to Seattle King Street station from Boeing, MP 6.3X, Seattle Subdivision, BNSF Railway. Technicians were waiting in Seattle for the train to arrive. They were able to free the jammed door allowing the train to depart for a second time.

Cause: Pending

Train	Delay	Comment
507(23)	1'19"	

Train 715(23) West of Hanford – Train Interference

23JUL25: Train 715(23) was delayed 27 miles west of Hanford at Calwa station, MP 994.9, Bakersfield Subdivision of the BNSF Railway. Unidentified BNSF Freight train BNSF was operating into Calwa yard. Once cleared, train 715(23) was further delayed waiting for the station track from train 712(23). Once 712(23) had departed, train 715(23) entered Fresno station.

Train	Delay	Comment
715(23)	12"	Calwa Crossing - Meet BNSF
717(23)	20"	Calwa Crossing - meet BNSF
715(23)	20"	Calwa Crossing - Meet 712(23)

Train 517(23) South of Tukwila WA - Signal Failure

23JUL25: Train 517(23) was delayed 14 miles south of Tukwila at Pacific, milepost 24.0X, Seattle Subdivision , of the BNSF Railway. This was because the Dispatcher was unable to gain remote control of the signals. Train 517(23) was required to stop & wait for the dispatcher authority to proceed. Once granted, the train advanced at reduced speed until clear of the affected area. Then train 517(23) was able to continue at track speed to Tacoma.

Train	Delay	Comment
517(23)	43"	

Train 5(21) West of Truckee, CA- Freight Train Interference

23JUL25: Train 5(21) was delayed 13 miles east of Truckee at MP 191.2, West Norden, Roseville Subdivision, of the Union Pacific Railroad. This was to allow for Union Pacific train GSFOAT- 22 (UPRR/7229) to use crossover switches ahead. Once the track ahead was cleared, train 5(21) continued to Colfax.

Train	Delay	Comment
5(21)	52"	

Train 710(23) East of Merced CA - Freight / Passenger Train Interference

23JUL25: Train 710(23) was delayed 13 miles east of Merced CA at Savana/Sharon Siding, MP 1042.0, Stockton Subdivision of the BNSF Railroad. This was to allow for BNSF train BNSF/8158 and train 713(23) to pass. Once the track ahead was cleared train 710(23) was continued to Madera Acres.

WBS#: B.TR.100150.5916

Train	Delay	Comment
710(23)	24"	Sharon Meet 713(23)
710(23)	15"	Sharon Meet BNSF 8158

Trains 3(23) and 7(23) Chicago, IL - Car Failure

23JUL25: Train 3(23) with E/167-182 and 9 cars was delayed departing Chicago due to C/38064 bad ordered for refrigeration and replaced with C/38067. The delay was prolonged once arriving Union Station at 331PM-CT to board 223 passengers due to toilet issues on the coach cars. Mechanical was on scene to assist in repairs. Once repairs were made, 3(23) departed Chicago at 435PM-CT, 2 hours, and 10 minutes late.

Additionally, train 7(23) with E/361-304 and 10 cars was delayed departing Chicago due to C/39037 bad ordered for Box 5 TFW and ripped back. Also, C/34107 was bad ordered for HVAC and replaced with C/33034.

Finally, train 364(23) with E/ID4627, 6 cars, and E/ID4618 was delayed departing Chicago due to C/ID4002 bad ordered for hi-low and replaced with C/ID4003. The equipment was released and set in the station at 420PM-CT to board 212 passengers.

Train	Delay	Comment
3(23)	2'10"	
364(23)	42"	
7(23)	3'41"	

Train 713(23) West of Corcoran, CA – Freight Train Interference – Terminates Emeryville

23JUL25: Train 713(23) was delayed west of Corcoran - on the BNSF Railway - while waiting for various BNSF Freight trains to pass:

Location	Milepost	Subdivision	Opposing Train
Guernsey	MP 959.4	Bakersfield	BNSF 6743
Fresno	MP 997.7	Stockton	BNSF 6847
Gregg	MP 1010.7	Stockton	BNSF 6423

To assist service crews - turning the trainset for 718(23) - train 713(23) was terminated in Emeryville. Twenty-One (21) passengers travelling to Oakland were provided bus transport to complete their trip.

WBS#: B.TR.100150.5917

Train	Delay	Comment
713(23)	20"	Guernsey - Meet BNSF 6743
713(23)	49"	Fresno - meet BNSF 6847
713(23)	12"	Gregg - Meet BNSF 6423
713(23)	Terminates Emeryville	Passengers to replacement bus

Train 8/28(22) St. Paul-Minneapolis, MN - Car Failure

23JUL25: Due to train 8/28(22) operating with E/306-50 and 10 cars with C/31024 bad ordered for toilets. As a result, two buses were secured as alternate transportation between St. Paul-Minneapolis and Chicago. Bus A operated express between St. Paul-Minneapolis and Chicago. Bus B operated between St. Paul-Minneapolis, Redwing, Winona, La Crosse, Tomah, Wisconsin Dells, Portage, Columbus, and Milwaukee. Passengers traveling east of Milwaukee were accommodated on the next available Hiawatha services.

WBS#: B.TR.100150.5915

Train 22(22)/422(20) South of Texarkana, AR - Passenger Train Interference

23JUL25: Train 22(22)/422(20) was delayed seven miles south of Texarkana on the UPRR Little Rock subdivision due to meeting 21/421(22) at Sulphur/MP 6.8.

Train	Delay	Comment
22(22)/422(20)	48"	

Train 11(22) South of Dunsmuir CA – Train Interference

23JUL25: Train 11(22) was delayed 60 miles south of Dunsmuir at Silverhorn, MP263.4, Valley Subdivision of the Union Pacific Railroad. This was to allow for the safe passage of Union Pacific Freight train UPRR/7964 and Amtrak train 14(22) using the single track ahead. Once the traffic had safely passed, train 11(22) continued to Redding.

Train	Delay	Comment
11(22)	29"	Silverhorn - Meet UPRR/7964
11(22)	09"	Silverhorn - Meet 14(22)

Train 6(23) Initial Terminal Emeryville, CA - Late Inbound Equipment

23JUL25: Train 6(23) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, as a result of the late turning and servicing of equipment off inbound Train 5(20) which arrived in Emeryville eight hours, three minutes late at 1:00AM-PT. Also, as a result of crew rest, Train 6(23)'s crew signed-up at 10:00AM-PT. Train 6(23) departed Emeryville at 11:53AM-PT.

Train	Delay	Comment
6(23)	3'28"	

Train 6(21) West of McCook, NE - Passenger Train Interference

23JUL25: Train 6(21) was delayed 11 miles west of McCook on the BNSF Akron subdivision due to meeting 5(22) at Culbertson/MP 299.2.

Train	Delay	Comment
6(21)	35"	

Train 11(22), South of Klamath Falls OR, Freight Train Interference

23JUL25: Train 11(22) was delayed 55 miles south of Klamath Falls while following a slower operating freight train. The freight train (UPRR/9049) was followed between South Kegg MP 374.00 and Black Butte MP 346.00 Black Butte Subdivision UPRR Railroad. At Black Butte the freight train entered the siding allowing train 11(22) to continue to Dunsmuir at track speed.

Train	Delay	Comment
11(22)	50"	

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 03AUG) will originate at Washington with no alternate transportation.

UPDATE: As of 7/23/25 the trackwork has been cancelled for 25JUL,26JUL and 27JUL, 28JUL.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Train 6(23) East of Roseville – Trackwork/Freight Train Interference

23JUL25: Union Pacific track maintenance workers closed track #2 at Colfax to repair heat damaged rail joints at MP 141.00 Roseville Subdivision, Union Pacific Railroad. This required train 6(23) wait for UPRR freight MROMI -22 (UPRR 6584) to pass on track #2. Once the track ahead was clear, train 6(23) shoved back to cross to track #1 then proceed at track speed to Truckee.

Train	Delay	Comment
6 (23)	46"	

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/23/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/23/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	6,636	792	88.1%	85,343	8,461	90.1%
Central Division	91.5%	65	9	86.2%	1,510	167	88.9%	19,539	1,907	90.2%
Northeast Division	95.0%	95	8	91.6%	2,091	286	86.3%	28,046	3,049	89.1%
Southeast Division	94.5%	69	6	91.3%	1,464	176	88.0%	18,893	1,890	90.0%
Southwest Division	90.5%	71	9	87.3%	1,571	163	89.6%	18,865	1,615	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/23/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/23/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	6,636	792	88.1%	85,343	8,461	90.1%
Central Division	91.5%	65	9	86.2%	1,510	167	88.9%	19,539	1,907	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	50	3	94.0%	593	17	97.1%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	26	6	76.9%	609	96	84.2%	7,885	981	87.6%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	1	50.0%	46	1	97.8%	570	20	96.5%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	22	0	100.0%	295	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	45	2	95.6%	574	39	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	2	66.7%	134	7	94.8%	1,697	95	94.4%
MSP	95.0%	1	0	100.0%	23	2	91.3%	284	14	95.1%
PDX	78.0%	5	0	100.0%	111	9	91.9%	1,423	161	88.7%
PNT	94.0%	3	0	100.0%	68	2	97.1%	815	58	92.9%
PTH	96.0%	1	0	100.0%	23	0	100.0%	294	11	96.3%
QCY	94.0%	2	0	100.0%	44	0	100.0%	574	18	96.9%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	0	100.0%	185	32	82.7%	2,312	332	85.6%
SPK	92.0%	1	0	100.0%	21	1	95.2%	292	14	95.2%
STL	96.0%	3	0	100.0%	79	8	89.9%	1,156	61	94.7%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	46	0	100.0%	567	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	8	91.6%	2,091	286	86.3%	28,046	3,049	89.1%
ALB	96.0%	6	0	100.0%	138	5	96.4%	1,987	127	93.6%
BON	94.5%	5	0	100.0%	113	8	92.9%	1,377	91	93.4%
BOS	97.0%	19	0	100.0%	410	46	88.8%	5,527	512	90.7%
BRK	97.0%	2	0	100.0%	80	2	97.5%	1,341	68	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	1	0.0%	23	4	82.6%	294	21	92.9%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	1	0	100.0%	39	2	94.9%	566	54	90.5%
HFD	-	2	0	100.0%	32	4	87.5%	178	17	90.4%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/23/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/23/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	6,636	792	88.1%	85,343	8,461	90.1%
Northeast Division	95.0%	95	8	91.6%	2,091	286	86.3%	28,046	3,049	89.1%
MTR	97.0%	1	1	0.0%	23	3	87.0%	294	29	90.1%
NFL	97.0%	2	0	100.0%	46	1	97.8%	592	24	95.9%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	1	80.0%	106	18	83.0%	1,513	152	90.0%
NYP	94.5%	42	4	90.5%	889	167	81.2%	11,882	1,805	84.8%
POR	-	3	1	66.7%	30	10	66.7%	30	10	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	21	4	81.0%	292	9	96.9%
SPG	95.5%	4	0	100.0%	111	9	91.9%	1,807	85	95.3%
TWO	96.0%	1	0	100.0%	23	0	100.0%	293	11	96.2%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	69	6	91.3%	1,464	176	88.0%	18,893	1,890	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	112	9	92.0%	1,466	94	93.6%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	257	12	95.3%	3,202	100	96.9%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	23	5	78.3%	290	93	67.9%
MIA	90.0%	2	1	50.0%	44	8	81.8%	569	55	90.3%
NFK	94.5%	3	0	100.0%	65	13	80.0%	815	67	91.8%
NOL	92.0%	3	0	100.0%	51	3	94.1%	658	46	93.0%
NPN	96.0%	2	0	100.0%	46	4	91.3%	565	21	96.3%
PGH	92.0%	1	0	100.0%	23	3	87.0%	295	17	94.2%
PHL	97.0%	5	1	80.0%	98	24	75.5%	1,264	181	85.7%
RGH	97.0%	4	0	100.0%	84	3	96.4%	1,187	37	96.9%
RNK	94.0%	2	0	100.0%	41	2	95.1%	558	64	88.5%
RVM	90.0%	1	0	100.0%	23	1	95.7%	287	34	88.2%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	21	1	95.2%	277	11	96.0%
SFA	83.0%	1	1	0.0%	23	2	91.3%	290	80	72.4%
WAS	94.5%	25	3	88.0%	543	76	86.0%	7,017	957	86.4%
Southwest Division	90.5%	71	9	87.3%	1,571	163	89.6%	18,865	1,615	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	23	0	100.0%	296	7	97.6%
BFD	90.0%	6	1	83.3%	136	15	89.0%	1,759	151	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	23	18	21.7%	303	94	69.0%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	22	2	90.9%	328	42	87.2%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/23/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/23/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	300	32	89.3%	6,636	792	88.1%	85,343	8,461	90.1%
Southwest Division	90.5%	71	9	87.3%	1,571	163	89.6%	18,865	1,615	91.4%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	69	3	95.7%	865	63	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	10	0	100.0%	217	24	88.9%	2,276	315	86.2%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	20	0	100.0%	291	6	97.9%
OKJ	91.0%	12	5	58.3%	254	44	82.7%	3,107	294	90.5%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	2	85.7%	301	24	92.0%	3,532	149	95.8%
SAN	90.0%	12	0	100.0%	270	20	92.6%	2,692	238	91.2%
SAS	85.0%	1	0	100.0%	23	6	73.9%	292	41	86.0%
SJC	95.0%	7	0	100.0%	160	6	96.3%	1,900	72	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	46	0	100.0%	579	27	95.3%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	6	0	100.0%	53	11	79.2%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		10	0	100.0%	125	15	88.0%	10	4	60.0%	125	34	72.8%
3	171	23	7	69.6%	290	57	80.3%	23	18	21.7%	286	159	44.4%
4	187	23	5	78.3%	291	70	75.9%	23	19	17.4%	290	150	48.3%
5	95	23	11	52.2%	293	50	82.9%	22	16	27.3%	290	99	65.9%
6	282	23	18	21.7%	293	87	70.3%	23	19	17.4%	292	101	65.4%
7		23	7	69.6%	287	43	85.0%	23	7	69.6%	282	74	73.8%
8	58	23	16	30.4%	288	108	62.5%	23	17	26.1%	286	138	51.7%
11	41	23	2	91.3%	295	46	84.4%	23	4	82.6%	288	65	77.4%
14	119	23	7	69.6%	296	89	69.9%	23	9	60.9%	294	129	56.1%
19		23	0	100.0%	296	33	88.9%	23	8	65.2%	295	57	80.7%
20	73	23	1	95.7%	296	14	95.3%	23	6	73.9%	295	48	83.7%
21		23	1	95.7%	295	35	88.1%	23	7	69.6%	289	90	68.9%
22	No OS	23	6	73.9%	292	43	85.3%	23	19	17.4%	291	127	56.4%
27		21	4	81.0%	283	21	92.6%	20	7	65.0%	273	93	65.9%
28		20	3	85.0%	276	68	75.4%	20	4	80.0%	275	76	72.4%
40	74	23	5	78.3%	253	38	85.0%	22	17	22.7%	248	156	37.1%
41	75	21	14	33.3%	250	109	56.4%	21	19	9.5%	246	196	20.3%
42		23	3	87.0%	296	18	93.9%	23	7	69.6%	296	81	72.6%
43		23	2	91.3%	296	25	91.6%	23	7	69.6%	296	67	77.4%
48		23	6	73.9%	295	54	81.7%	23	4	82.6%	295	45	84.7%
49		23	10	56.5%	296	60	79.7%	23	7	69.6%	296	54	81.8%
50	138	10	5	50.0%	126	40	68.3%	10	8	20.0%	125	90	28.0%
52		23	2	91.3%	290	80	72.4%	23	6	73.9%	290	153	47.2%
53	111	23	5	78.3%	290	93	67.9%	23	6	73.9%	290	146	49.7%
55		16	3	81.3%	205	9	95.6%	16	9	43.8%	205	48	76.6%
56	113	16	3	81.3%	205	36	82.4%	16	13	18.8%	204	56	72.5%
58	112	23	2	91.3%	288	23	92.0%	23	7	69.6%	285	60	78.9%
59	205	23	9	60.9%	287	61	78.7%	22	9	59.1%	283	36	87.3%
63		23	14	39.1%	296	60	79.7%	23	20	13.0%	296	152	48.6%
64	41	23	0	100.0%	296	11	96.3%	23	4	82.6%	296	72	75.7%
66	35	23	3	87.0%	294	56	81.0%	23	2	91.3%	292	38	87.0%
67		16	1	93.8%	204	18	91.2%	16	4	75.0%	202	43	78.7%
68		23	3	87.0%	296	29	90.2%	23	17	26.1%	296	121	59.1%
69	56	23	2	91.3%	296	22	92.6%	22	8	63.6%	291	35	88.0%
71		22	2	90.9%	295	7	97.6%	22	8	63.6%	293	66	77.5%
72		23	3	87.0%	296	22	92.6%	23	8	65.2%	294	75	74.5%
73		23	4	82.6%	296	16	94.6%	23	9	60.9%	294	144	51.0%
74	34	23	1	95.7%	292	21	92.8%	23	9	60.9%	290	99	65.9%
75	13	23	3	87.0%	294	8	97.3%	23	11	52.2%	292	118	59.6%
76	25	23	4	82.6%	292	20	93.2%	22	14	36.4%	290	127	56.2%
77	26	23	2	91.3%	293	12	95.9%	23	11	52.2%	291	131	55.0%
78		23	0	100.0%	294	10	96.6%	22	6	72.7%	293	70	76.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79	87	23	5	78.3%	296	40	86.5%	21	7	66.7%	293	105	64.2%
80	53	23	3	87.0%	296	24	91.9%	23	14	39.1%	296	87	70.6%
84		16	0	100.0%	204	8	96.1%	16	6	62.5%	203	75	63.1%
85	16	16	0	100.0%	202	16	92.1%	16	11	31.3%	201	137	31.8%
86	55	16	1	93.8%	202	23	88.6%	16	14	12.5%	202	139	31.2%
89	47	23	2	91.3%	295	36	87.8%	23	11	52.2%	293	109	62.8%
90	91	23	1	95.7%	295	12	95.9%	22	9	59.1%	290	73	74.8%
93		16	0	100.0%	205	14	93.2%	16	10	37.5%	204	96	52.9%
94	27	16	6	62.5%	205	20	90.2%	16	9	43.8%	204	75	63.2%
95		16	0	100.0%	205	5	97.6%	16	7	56.3%	205	88	57.1%
97		23	17	26.1%	292	138	52.7%	23	12	47.8%	291	96	67.0%
98		23	4	82.6%	292	19	93.5%	23	15	34.8%	292	151	48.3%
110	20	16	6	62.5%	203	39	80.8%	16	4	75.0%	201	43	78.6%
111		16	3	81.3%	202	50	75.2%	16	2	87.5%	200	32	84.0%
112		16	3	81.3%	197	38	80.7%	16	3	81.3%	195	24	87.7%
114		16	3	81.3%	201	54	73.1%	16	3	81.3%	197	30	84.8%
119		16	1	93.8%	199	39	80.4%	16	3	81.3%	196	30	84.7%
125		16	1	93.8%	205	10	95.1%	16	9	43.8%	205	116	43.4%
129		16	4	75.0%	203	42	79.3%	16	7	56.3%	202	45	77.7%
130		16	1	93.8%	199	20	89.9%	16	1	93.8%	196	22	88.8%
131		16	2	87.5%	196	34	82.7%	16	2	87.5%	194	28	85.6%
133	19	16	7	56.3%	203	75	63.1%	16	13	18.8%	203	106	47.8%
134	33	16	0	100.0%	204	15	92.6%	16	8	50.0%	204	99	51.5%
136		16	1	93.8%	205	40	80.5%	16	4	75.0%	203	42	79.3%
137		16	5	68.8%	205	26	87.3%	16	7	56.3%	205	82	60.0%
138		16	3	81.3%	204	24	88.2%	16	8	50.0%	204	51	75.0%
141		16	0	100.0%	205	3	98.5%	16	8	50.0%	205	98	52.2%
148		16	1	93.8%	205	18	91.2%	16	4	75.0%	205	43	79.0%
151	44	23	5	78.3%	293	37	87.4%	23	6	73.9%	292	99	66.1%
170		16	0	100.0%	204	12	94.1%	16	6	62.5%	204	51	75.0%
171	52	16	3	81.3%	205	10	95.1%	16	9	43.8%	205	103	49.8%
172		16	2	87.5%	204	15	92.6%	16	7	56.3%	202	66	67.3%
173		16	0	100.0%	205	26	87.3%	16	5	68.8%	205	68	66.8%
174		16	2	87.5%	205	6	97.1%	16	5	68.8%	204	47	77.0%
175	21	16	6	62.5%	204	36	82.4%	16	9	43.8%	203	75	63.1%
176		16	4	75.0%	205	20	90.2%	16	1	93.8%	204	25	87.7%
177		16	3	81.3%	205	29	85.9%	16	6	62.5%	204	43	78.9%
178		16	1	93.8%	205	30	85.4%	16	8	50.0%	204	44	78.4%
179		16	3	81.3%	203	15	92.6%	16	10	37.5%	203	71	65.0%
181		16	6	62.5%	200	40	80.0%	16	1	93.8%	196	27	86.2%
182		16	2	87.5%	200	48	76.0%	16	9	43.8%	199	54	72.9%
183	18	16	3	81.3%	205	27	86.8%	16	2	87.5%	205	26	87.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		16	6	62.5%	205	30	85.4%	16	2	87.5%	204	25	87.7%
185	32	16	2	87.5%	205	34	83.4%	16	3	81.3%	205	27	86.8%
186		16	2	87.5%	202	13	93.6%	16	7	56.3%	200	57	71.5%
190		16	7	56.3%	205	42	79.5%	16	7	56.3%	205	52	74.6%
192		16	3	81.3%	101	17	83.2%	16	4	75.0%	99	13	86.9%
193		16	5	68.8%	203	35	82.8%	16	6	62.5%	202	72	64.4%
196		16	1	93.8%	205	70	65.9%	16	3	81.3%	202	59	70.8%
197		16	8	50.0%	204	52	74.5%	16	4	75.0%	203	56	72.4%
232		23	1	95.7%	284	10	96.5%	23	1	95.7%	284	22	92.3%
233		20	5	75.0%	291	85	70.8%	20	10	50.0%	290	101	65.2%
234		23	1	95.7%	284	7	97.5%	23	2	91.3%	284	22	92.3%
236		23	0	100.0%	284	5	98.2%	23	3	87.0%	283	47	83.4%
237		20	0	100.0%	279	28	90.0%	20	2	90.0%	277	32	88.4%
239		23	5	78.3%	283	30	89.4%	23	7	69.6%	283	23	91.9%
240		23	0	100.0%	288	24	91.7%	23	5	78.3%	287	27	90.6%
241	28	23	4	82.6%	296	37	87.5%	22	9	59.1%	295	45	84.7%
243		16	6	62.5%	205	38	81.5%	16	7	56.3%	204	29	85.8%
244		20	1	95.0%	291	8	97.3%	20	10	50.0%	291	49	83.2%
280		23	0	100.0%	295	11	96.3%	23	2	91.3%	295	53	82.0%
281		23	2	91.3%	296	60	79.7%	22	5	77.3%	294	60	79.6%
283		23	8	65.2%	296	65	78.0%	23	10	56.5%	295	63	78.6%
284		23	1	95.7%	296	13	95.6%	23	1	95.7%	295	59	80.0%
290	35	23	4	82.6%	296	23	92.2%	22	18	18.2%	294	71	75.9%
291	38	23	9	60.9%	296	47	84.1%	23	18	21.7%	295	64	78.3%
300		21	1	95.2%	285	8	97.2%	21	7	66.7%	283	70	75.3%
302	26	22	3	86.4%	290	21	92.8%	22	10	54.5%	287	100	65.2%
305	18	23	3	87.0%	290	22	92.4%	23	17	26.1%	289	113	60.9%
307		22	2	90.9%	289	38	86.9%	21	11	47.6%	286	106	62.9%
311		22	3	86.4%	286	18	93.7%	22	17	22.7%	282	113	59.9%
316	22	22	1	95.5%	284	19	93.3%	22	16	27.3%	282	105	62.8%
318	47	23	1	95.7%	292	20	93.2%	23	15	34.8%	288	162	43.8%
319	30	23	1	95.7%	294	19	93.5%	23	18	21.7%	289	179	38.1%
329		16	2	87.5%	206	18	91.3%	16	1	93.8%	206	17	91.7%
330		19	1	94.7%	239	5	97.9%	19	1	94.7%	238	15	93.7%
331		23	1	95.7%	287	20	93.0%	23	2	91.3%	283	27	90.5%
332		23	1	95.7%	292	17	94.2%	23	3	87.0%	291	44	84.9%
334		23	0	100.0%	292	9	96.9%	23	3	87.0%	287	71	75.3%
335	11	23	2	91.3%	295	31	89.5%	23	6	73.9%	286	62	78.3%
336		23	1	95.7%	281	7	97.5%	23	6	73.9%	280	81	71.1%
337		23	2	91.3%	284	17	94.0%	23	6	73.9%	283	63	77.7%
338	27	23	3	87.0%	294	38	87.1%	23	8	65.2%	284	123	56.7%
339	66	23	1	95.7%	294	43	85.4%	23	3	87.0%	292	51	82.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
341		22	10	54.5%	279	55	80.3%	22	11	50.0%	273	58	78.8%
342	45	23	1	95.7%	295	19	93.6%	23	2	91.3%	294	45	84.7%
350		23	2	91.3%	255	27	89.4%	23	16	30.4%	252	129	48.8%
351		23	0	100.0%	284	24	91.5%	23	5	78.3%	283	78	72.4%
352		23	3	87.0%	289	27	90.7%	23	10	56.5%	284	81	71.5%
353		23	0	100.0%	248	6	97.6%	23	1	95.7%	243	36	85.2%
354		22	0	100.0%	288	26	91.0%	22	4	81.8%	285	102	64.2%
355		22	2	90.9%	288	32	88.9%	22	5	77.3%	284	73	74.3%
364		23	2	91.3%	294	56	81.0%	23	5	78.3%	293	79	73.0%
365		23	0	100.0%	294	11	96.3%	23	8	65.2%	293	86	70.6%
370		22	2	90.9%	295	12	95.9%	21	4	81.0%	294	37	87.4%
371		22	0	100.0%	295	4	98.6%	22	3	86.4%	295	28	90.5%
380		23	1	95.7%	293	11	96.2%	23	1	95.7%	293	27	90.8%
381		23	2	91.3%	293	8	97.3%	23	6	73.9%	292	29	90.1%
382		23	1	95.7%	292	11	96.2%	23	6	73.9%	292	39	86.6%
383		23	0	100.0%	294	29	90.1%	23	9	60.9%	293	68	76.8%
390		23	3	87.0%	291	13	95.5%	23	7	69.6%	289	43	85.1%
391	33	23	1	95.7%	294	7	97.6%	22	5	77.3%	291	54	81.4%
392		22	0	100.0%	293	8	97.3%	22	6	72.7%	290	32	89.0%
393		23	1	95.7%	293	13	95.6%	23	9	60.9%	290	42	85.5%
417		16	2	87.5%	201	32	84.1%	15	1	93.3%	198	29	85.4%
470		17	2	88.2%	207	15	92.8%	15	2	86.7%	202	28	86.1%
471		16	2	87.5%	205	14	93.2%	15	0	100.0%	203	11	94.6%
473		16	2	87.5%	205	7	96.6%	15	1	93.3%	204	3	98.5%
474		16	2	87.5%	203	30	85.2%	15	6	60.0%	199	60	69.8%
478		14	1	92.9%	203	21	89.7%	13	1	92.3%	201	20	90.0%
479		16	1	93.8%	205	30	85.4%	16	2	87.5%	204	24	88.2%
486	18	16	0	100.0%	207	16	92.3%	16	8	50.0%	205	72	64.9%
494	47	16	6	62.5%	210	33	84.3%	16	10	37.5%	204	60	70.6%
495		16	1	93.8%	202	3	98.5%	16	2	87.5%	202	6	97.0%
500		23	1	95.7%	285	22	92.3%	22	4	81.8%	283	82	71.0%
502		23	0	100.0%	283	13	95.4%	22	1	95.5%	281	79	71.9%
503	18	23	2	91.3%	296	31	89.5%	23	10	56.5%	285	91	68.1%
504	39	23	1	95.7%	284	10	96.5%	22	6	72.7%	283	113	60.1%
505		23	2	91.3%	288	33	88.5%	22	6	72.7%	285	103	63.9%
506	38	23	3	87.0%	288	27	90.6%	22	6	72.7%	286	72	74.8%
507	78	23	3	87.0%	287	33	88.5%	23	11	52.2%	286	91	68.2%
508		23	0	100.0%	291	13	95.5%	23	7	69.6%	289	85	70.6%
509	52	23	3	87.0%	286	31	89.2%	22	7	68.2%	285	101	64.6%
511		23	1	95.7%	287	23	92.0%	23	5	78.3%	284	77	72.9%
516		23	2	91.3%	287	26	90.9%	23	12	47.8%	285	130	54.4%
517	67	23	0	100.0%	288	5	98.3%	23	10	56.5%	287	173	39.7%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
518	59	23	3	87.0%	288	32	88.9%	23	11	52.2%	286	172	39.9%
519		23	0	100.0%	285	11	96.1%	23	4	82.6%	284	59	79.2%
520		16	3	81.3%	37	5	86.5%	16	0	100.0%	37	1	97.3%
521		16	0	100.0%	205	4	98.0%	16	1	93.8%	204	16	92.2%
522		16	1	93.8%	205	4	98.0%	15	0	100.0%	204	11	94.6%
523		16	0	100.0%	206	4	98.1%	16	1	93.8%	206	26	87.4%
524		16	1	93.8%	206	6	97.1%	15	3	80.0%	205	36	82.4%
525		16	0	100.0%	204	4	98.0%	16	0	100.0%	203	10	95.1%
526		16	0	100.0%	37	4	89.2%	16	3	81.3%	37	7	81.1%
527		16	0	100.0%	206	3	98.5%	16	0	100.0%	205	29	85.9%
528		16	0	100.0%	205	5	97.6%	16	2	87.5%	205	32	84.4%
529		16	0	100.0%	206	0	100.0%	16	4	75.0%	206	40	80.6%
531		16	1	93.8%	205	3	98.5%	16	3	81.3%	204	16	92.2%
532		16	0	100.0%	206	9	95.6%	16	0	100.0%	204	20	90.2%
534		16	2	87.5%	206	15	92.7%	16	1	93.8%	205	15	92.7%
535		16	2	87.5%	37	3	91.9%	15	1	93.3%	36	3	91.7%
536	32	16	1	93.8%	206	9	95.6%	16	2	87.5%	204	10	95.1%
537		15	0	100.0%	36	1	97.2%	15	0	100.0%	36	2	94.4%
538		16	1	93.8%	206	5	97.6%	16	3	81.3%	206	37	82.0%
540	14	16	0	100.0%	206	5	97.6%	16	3	81.3%	201	21	89.6%
541		16	0	100.0%	206	8	96.1%	16	4	75.0%	206	44	78.6%
542		16	1	93.8%	206	8	96.1%	16	3	81.3%	206	35	83.0%
543		16	0	100.0%	206	6	97.1%	16	8	50.0%	206	32	84.5%
544		15	1	93.3%	204	11	94.6%	15	0	100.0%	203	15	92.6%
545		16	1	93.8%	206	8	96.1%	16	1	93.8%	204	21	89.7%
546		16	0	100.0%	206	7	96.6%	16	3	81.3%	205	31	84.9%
547		16	2	87.5%	206	9	95.6%	16	3	81.3%	206	29	85.9%
548		16	0	100.0%	204	12	94.1%	16	0	100.0%	202	11	94.6%
549	23	16	5	68.8%	206	24	88.3%	15	1	93.3%	200	30	85.0%
551		16	0	100.0%	206	10	95.1%	16	1	93.8%	201	18	91.0%
562		23	2	91.3%	292	33	88.7%	22	1	95.5%	282	31	89.0%
564		23	3	87.0%	290	20	93.1%	23	3	87.0%	287	27	90.6%
566		23	0	100.0%	115	10	91.3%	23	1	95.7%	115	12	89.6%
572	16	23	2	91.3%	245	21	91.4%	23	7	69.6%	241	45	81.3%
573		23	1	95.7%	284	38	86.6%	23	3	87.0%	278	46	83.5%
577		23	0	100.0%	38	0	100.0%	23	2	91.3%	38	2	94.7%
580		23	0	100.0%	292	21	92.8%	23	1	95.7%	291	53	81.8%
581		23	3	87.0%	292	36	87.7%	23	6	73.9%	288	57	80.2%
582		23	1	95.7%	38	1	97.4%	23	2	91.3%	38	3	92.1%
586		23	1	95.7%	243	30	87.7%	23	3	87.0%	236	41	82.6%
587		23	3	87.0%	243	28	88.5%	22	5	77.3%	236	51	78.4%
591		23	0	100.0%	292	32	89.0%	23	2	91.3%	288	40	86.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
593		23	4	82.6%	38	6	84.2%	23	4	82.6%	38	7	81.6%
595		23	3	87.0%	284	61	78.5%	23	2	91.3%	282	50	82.3%
600		16	2	87.5%	204	4	98.0%	16	2	87.5%	202	26	87.1%
601		16	3	81.3%	204	20	90.2%	16	3	81.3%	203	34	83.3%
605		16	1	93.8%	204	11	94.6%	16	0	100.0%	202	26	87.1%
607		16	2	87.5%	205	19	90.7%	16	0	100.0%	204	10	95.1%
609		16	1	93.8%	205	13	93.7%	15	1	93.3%	204	30	85.3%
620		16	1	93.8%	205	6	97.1%	16	3	81.3%	203	27	86.7%
622		13	2	84.6%	162	8	95.1%	13	2	84.6%	161	47	70.8%
639		16	1	93.8%	205	26	87.3%	16	2	87.5%	204	24	88.2%
640		16	0	100.0%	205	0	100.0%	16	3	81.3%	205	101	50.7%
641		16	0	100.0%	205	18	91.2%	16	0	100.0%	205	34	83.4%
642		16	0	100.0%	205	0	100.0%	16	1	93.8%	204	42	79.4%
643	32	16	0	100.0%	205	13	93.7%	16	2	87.5%	204	43	78.9%
644		16	1	93.8%	205	9	95.6%	15	2	86.7%	202	46	77.2%
645		16	1	93.8%	205	15	92.7%	15	3	80.0%	204	52	74.5%
646	47	16	1	93.8%	205	18	91.2%	16	4	75.0%	202	100	50.5%
647		16	1	93.8%	205	15	92.7%	15	5	66.7%	204	80	60.8%
648	12	16	0	100.0%	205	12	94.1%	16	5	68.8%	203	35	82.8%
649		16	0	100.0%	205	20	90.2%	16	4	75.0%	204	39	80.9%
650		16	0	100.0%	205	10	95.1%	16	1	93.8%	204	30	85.3%
651		16	2	87.5%	205	25	87.8%	16	4	75.0%	205	81	60.5%
652		16	1	93.8%	205	4	98.0%	16	5	68.8%	205	37	82.0%
653		16	1	93.8%	205	14	93.2%	16	5	68.8%	204	67	67.2%
654		16	1	93.8%	205	5	97.6%	16	0	100.0%	203	20	90.1%
655		16	3	81.3%	204	32	84.3%	16	5	68.8%	202	71	64.9%
656		16	2	87.5%	205	5	97.6%	16	2	87.5%	204	45	77.9%
657		16	1	93.8%	205	14	93.2%	16	1	93.8%	205	50	75.6%
658		16	0	100.0%	205	6	97.1%	16	4	75.0%	204	54	73.5%
680		17	0	100.0%	207	2	99.0%	17	1	94.1%	206	32	84.5%
681		17	0	100.0%	206	12	94.2%	17	7	58.8%	203	80	60.6%
682		17	0	100.0%	207	5	97.6%	17	1	94.1%	207	95	54.1%
683	18	16	0	100.0%	159	4	97.5%	16	8	50.0%	159	64	59.7%
684		15	4	73.3%	158	13	91.8%	15	7	53.3%	157	83	47.1%
685		15	0	100.0%	162	12	92.6%	15	8	46.7%	162	59	63.6%
686		17	6	64.7%	206	42	79.6%	17	8	52.9%	206	85	58.7%
687		17	1	94.1%	207	29	86.0%	17	7	58.8%	207	79	61.8%
688		17	1	94.1%	207	8	96.1%	17	2	88.2%	207	89	57.0%
689		5	1	80.0%	150	7	95.3%	5	1	80.0%	151	30	80.1%
702	66	23	3	87.0%	296	20	93.2%	23	14	39.1%	295	99	66.4%
703	79	23	2	91.3%	296	29	90.2%	23	10	56.5%	296	75	74.7%
710	107	23	8	65.2%	296	50	83.1%	22	16	27.3%	289	86	70.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/23/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
711	34	23	0	100.0%	295	10	96.6%	23	11	52.2%	286	37	87.1%
712	34	23	3	87.0%	296	46	84.5%	22	13	40.9%	293	91	68.9%
713	Cncld	22	0	100.0%	294	9	96.9%	18	13	27.8%	275	63	77.1%
714	46	23	7	69.6%	295	42	85.8%	23	12	47.8%	290	74	74.5%
715	57	23	3	87.0%	295	42	85.8%	22	16	27.3%	284	93	67.3%
716	Cncld	23	6	73.9%	295	34	88.5%	21	6	71.4%	293	62	78.8%
717	Cncld	22	3	86.4%	290	33	88.6%	19	6	68.4%	273	68	75.1%
718	No OS	23	7	69.6%	296	44	85.1%	22	6	72.7%	294	55	81.3%
719	109	23	7	69.6%	296	30	89.9%	23	14	39.1%	288	71	75.3%
761	43	23	1	95.7%	292	18	93.8%	23	4	82.6%	292	37	87.3%
765		23	1	95.7%	292	13	95.5%	23	2	91.3%	283	41	85.5%
769		23	2	91.3%	290	13	95.5%	23	4	82.6%	286	54	81.1%
770		23	0	100.0%	292	17	94.2%	23	6	73.9%	289	40	86.2%
774		23	0	100.0%	292	8	97.3%	23	3	87.0%	288	65	77.4%
779		23	0	100.0%	38	1	97.4%	23	3	87.0%	38	7	81.6%
784		23	1	95.7%	292	33	88.7%	23	11	52.2%	289	116	59.9%
785		23	2	91.3%	292	15	94.9%	23	1	95.7%	290	44	84.8%
790		23	2	91.3%	292	16	94.5%	23	2	91.3%	289	43	85.1%
794		23	0	100.0%	292	22	92.5%	22	1	95.5%	290	58	80.0%
821	58	20	0	100.0%	291	6	97.9%	20	17	15.0%	291	151	48.1%
822	28	22	2	90.9%	293	13	95.6%	22	22	0.0%	293	153	47.8%
1333		23	2	91.3%	289	52	82.0%	23	19	17.4%	288	185	35.8%
1340		23	2	91.3%	288	14	95.1%	23	15	34.8%	286	98	65.7%
2103		15	0	100.0%	201	11	94.5%	15	1	93.3%	198	23	88.4%
2107		16	4	75.0%	201	37	81.6%	16	1	93.8%	197	27	86.3%
2108	15	15	1	93.3%	197	20	89.8%	14	4	71.4%	194	31	84.0%
2121		15	1	93.3%	198	32	83.8%	14	4	71.4%	193	45	76.7%
2122		16	3	81.3%	200	37	81.5%	16	4	75.0%	194	35	82.0%
2124		13	2	84.6%	160	28	82.5%	12	3	75.0%	156	35	77.6%
2150	16	16	0	100.0%	205	7	96.6%	16	4	75.0%	205	64	68.8%
2151		16	0	100.0%	205	0	100.0%	15	5	66.7%	204	50	75.5%
2152		15	2	86.7%	202	7	96.5%	15	8	46.7%	196	82	58.2%
2153	16	15	0	100.0%	200	5	97.5%	15	9	40.0%	198	48	75.8%
2154	14	16	3	81.3%	203	17	91.6%	15	11	26.7%	199	90	54.8%
2155		15	1	93.3%	195	13	93.3%	15	6	60.0%	188	79	58.0%
2159	37	16	2	87.5%	202	16	92.1%	16	6	62.5%	197	64	67.5%
2162	27	15	1	93.3%	203	16	92.1%	14	7	50.0%	197	71	64.0%
2163		16	0	100.0%	204	15	92.6%	16	10	37.5%	198	82	58.6%
2166	Cncld	16	3	81.3%	204	12	94.1%	15	8	46.7%	201	47	76.6%
2167		16	1	93.8%	205	28	86.3%	16	7	56.3%	203	53	73.9%
2168		16	3	81.3%	205	17	91.7%	16	6	62.5%	204	48	76.5%
2169		15	4	73.3%	201	49	75.6%	14	6	57.1%	194	68	64.9%

Amtrak On Time Performance

Trains Arriving Through: 7/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
Train	Late												
2170		15	3	80.0%	195	15	92.3%	14	4	71.4%	191	46	75.9%
2172		15	2	86.7%	191	23	88.0%	15	6	60.0%	187	41	78.1%
2173		15	2	86.7%	199	21	89.4%	15	5	66.7%	199	48	75.9%
2190	40	16	0	100.0%	204	14	93.1%	16	1	93.8%	201	17	91.5%
2193	30	14	1	92.9%	199	26	86.9%	14	6	57.1%	192	69	64.1%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/23/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2108	NYP	15	CTC	28	CTC	28	WAS-WAS	AM	CETC/PSCC system failure, Control Point, was, loss of amtec
2150	BOS	16	CTI	13	BSP	11	NYP-XSH	AM	Bridge strike, Other, KINGS HIGHWAY
2153	WAS	16	DCS	17	DCS	10	XHM-PHL	AM	CTC system failure, Control Point, ., OT network issue causing the rapid bouncing of communication with Penn, leading to the slow down of the system
2154	BOS	14	DSR	11	DSR	8	STM-NHV	MN	Per bulletin Milepost, 32.3, 33.6, 30, 2, Milepost, 40.6, 41.7, 30, 4, Milepost, 41.7, 42, 15, 4, Control Point, 271, 30, 1
2159	WAS	37	CTI	15	CTC	15	XHM-PHL	AM	RTU Failure, Control Point, Clearfield
2162	BOS	27	DCS	29	DCS	17	XPV-WIL	AM	CTC system failure, Control Point, XPV-WIL, OT network issue with Penn caused AMTEC failure
2166	BOS	Trn Cancelled	DBS	12	DBS	12	XGX-PVD	AM	Debris blocking track (no debris strike), Milepost, xm6, pvd, Held for ET to clear osprey nest on fire in the catenary at MP136
2190	BOS	40	ENG	52	ENG	33	NYP-XSH	AM	Undesired emergency application, 2033, EMERGENCY APPLICATION AT LEGGETT INT.
2193	NYP	30	DCS	22	DCS	15	XGX-XNH	AM	Restrictive signal(s) from unknown cause, cab went from clear, approach to restricting running, Control Point, Brook-Fitter, cab went from clear, approach to restricting running
66	BOS		CTI	34	MTI	25	NYP-XSH	AM	Disabled train ahead, Other, XGG-XPB, AM2190 AHEAD ON NO.1 TRACK, LEGGETT INT, IN EMERGENCY
85	RVM	16	CTI	22	DSR	8	BRP-STM	MN	Per bulletin Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.6, 30, 2
86	BOS	55	CTI	29	DCS	14	WIL-WIL	AM	CTC system failure, Control Point, WIL, OT network issue with Penn caused AMTEC failure
94	BOS	27	PTI	21	PTI	13	NHV-OSB	AM	Follow, 2193, Milepost, xgu, xvw, Held for later 2193 track 2-1 at Fitter
110	NYP	20	CTI	12	CAR	12	PHL-PHL	AM	Set out defective car, 82802, shopped due to brake pads and broken hold down latch for the inner pad
133	WAS	19	DMW	9	PTI	8	BAL-BAL	AM	Follow, 2121, Milepost, 95.7, ., held for 2121 ahead then followed
134	NYP	33	HLD	11	PTI	8	ALX-XVG	CS	Wait for station track n/a, Control Point, Virginia

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/23/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
151	RNK	44	CAR	35	CAR	35	NYP-NYP	AM	Air / Brake / Wheel, 00000, SWITCH COACH CARS, NO CAR NUMBER SPECIFIED
171	RNK	52	PTI	27	PTI	14	CLP-CVS	NS	Meet 66, Control Point, Winston
175	WAS	21	CON	20	CON	20	NHV-NHV	MN	Hold for thruway bus
183	WAS	18	DCS	21	DCS	21	BAL-BWI	AM	CTC system failure, Milepost, 95.7, 106.3, OT network issue with Penn caused AMTEC failure
185	WAS	32	DCS	20	DCS	20	XHM-PHL	AM	CTC system failure, Control Point, ., OT network issue causing the rapid bouncing of communication with Penn, leading to the slow down of the system
486	GFD	18	CON	34	CON	34	NHV-NHV	AM	Hold for connecting train
494	GFD	47	FTI	30	FTI	30	X1X-HLK	MA	Freight edpl 23 5974, Milepost, 2, 3
53	SFA	111	SYS	69	SYS	69	XFL-XFL	CS	PTC problem or failure (cause unknown) A 292.9. Engine358. Failed to load PTC. NSt train used our same bulletin number. Issued new bulletin., Control Point, xfl
79	CLT	87	FTI	66	ENG	54	WAS-WAS	AM	Failure of diesel engine, 746, TRYING TO GET YARD DIESEL (746) TO LORTON FOR YARD WORK COULD NOT FIGURE OUT HOW TO GET BRAKES TO RELEASE SO MEC. ENDED UP CUTTING IT OFF
80	NYP	53	FTI	59	FTI	32	RMT-PTB	CS	Cross over or go around Shove train after M415, CSX M415, Control Point, FOX
643	HAR	32	DCS	34	DCS	34	XHM-PHL	AM	CTC system failure, Control Point, ., OT network issue causing the rapid bouncing of communication with Penn, leading to the slow down of the system
646	NYP	47	DCS	40	DCS	40	PAO-PHL	AM	CTC system failure, Control Point, PAO-PHL, OT network issue with Penn caused AMTEC failure
648	NYP	12	DCS	21	DCS	19	ELT-LNC	AM	CTC system failure, Control Point, ELT-LNC, OT network issue with Penn caused AMTEC failure
20	NYP	73	FTI	87	FTI	49	ATL-GNS	NS	NS 242 had Engine failure. Waited for rescue engine to arrive. NS 242, Control Point, Daluth
683	POR	18	PTI	11	PTI	8	SAO-ORB	CS	Meet 686 Eng AMTK 90220, Control Point, Ocean Park
64	ALB	41	FTI	63	FTI	63	SYR-ROM	CS	Meet Held at cp 286 for multiple east and westbound freight, csx, Control Point, 286

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/23/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
69	MTR	49	PTI	44	WTR	42	XLQ-SLQ	CN	Heat order Milepost, 1.2, 36
241	ALB	28	CTI	15	CTI	15	CRT-POU	MN	Follow metro north, Milepost, 36, 72
290	NYP	35	DSR	47	DSR	37	BTN-VRN	VR	Per bulletin Milepost w/Letters, mp 116.86, mp 115.78, 10, main, Milepost w/Letters, mp 113.30, mp 111.0, 10, main, Milepost w/Letters, mp 111.0, mp 105.68, 25, main, Milepost w/Letters, mp 105.68, mp 105.19, 15, main, Milepost w/Letters, mp 105.19, mp 101.0, 50, main, Milepost w/Letters, mp 101.0,
291	BTN	38	DSR	29	DSR	24	VRN-BTN	VR	Per bulletin Milepost, 100.63, 101, 10, main, Milepost, 105.19, 105.68, 15, main, Milepost, 107.91, 109.71, 25, main, Milepost, 109.71, 111, 25, main, Milepost, 111.0, 113.30, 10, main, Milepost, 115.78, 116.86, 10, main
74	RGH	34	FTI	21	FTI	21	CLT-KAN	NS	Follow Stop signal at AT&O Jct; waiting for #NS28r to clear., #NS28r, Control Point, AT&O Jct
75	CLT	13	PTI	18	PTI	14	HPT-SAL	NS	Meet Waited on 74 before entering into Salisbury, Amtk74, Control Point, Spencer
76	RGH	25	DSR	18	DSR	9	GRO-DNC	NS	Per bulletin Control Point, 46.7, 10, main
77	CLT	26	PTI	23	PTI	23	DNC-BNC	NS	Meet #Amt74, Control Point, Merrill
89	SAV	47	PTI	53	PTI	38	PTB-RMT	CS	Meet 80, Control Point, Stony Creek
90	NYP	91	PTI	80	PTI	60	RMT-PTB	CS	Follow P092, Control Point, Enfield
56	SAB	113	DSR	63	DSR	37	ESX-SAB	NE	Per bulletin Milepost, 106.0, 115.0, 10, main, Milepost, 114.39, 114.59, 25, main, Milepost, 115.0, 116.0, 25, main
40	CHI	74	ADA	65	SVS	20	PGH-PGH	NS	Fuel
41	MIA	75	FTI	70	DMW	54	WAS-XVG	AM	Held for or routed around MW work or equipment, Control Point, WAS , 41 HAD TO MAKE A DOUBLE MOVE TO GET TO THE LOW LEVEL 24 TRACK
5	EMY	95	CON	122	CON	122	CHI-CHI	AM	Hold for connecting train 49
6	CHI	282	FTI	191	SVS	75	EMY-EMY	UP	Planned set out / pick out of locomotives, cars or section of train Adding/Inspecting Engines and Cars 134/22/10020/69007 and 9800. Being shuttled to Sacramento., Other, OMF
536	SAC	32	ENG	28	ENG	28	OKJ-OKJ	UP	HEP HEP dropped after we switched ends...we check all cables and ended up short looping, 171

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/23/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
540	SAC	14	DCS	20	DCS	20	MTZ-SUI	UP	Restrictive signal(s) from known wayside signal failure Red, Control Point, rv042	
549	OKJ	23	ENG	22	ENG	22	SAC-SAC	UP	Air / Brake 171	
50	NYP	138	FTI	51	CAR	38	CHI-CHI	AM	Toilet 25063	
503	EUG	18	SYS	18	SYS	14	TAC-XNI	ST	Efficiency test involving Amtrak officer(s) Control Point, rill	
504	SEA	39	FTI	41	FTI	19	SLM-ORC	UP	Follow UP 7185, Milepost, 735.5, 756.1, Z	
506	SEA	38	PTI	52	PTI	20	PDX-VAN	BN	Follow Amtrak 14 departed PDX before us and had to manually line a switch at cp .5, amtrak 14, Milepost, 0, 9.9	
507	EUG	78	CAR	79	CAR	79	SEA-TUK	BN	Door 48187, A end door stuck closed after departure. Returned to SEA to fix.	
509	PDX	52	PTI	20	PTI	20	CTL-KEL	BN	Meet AMTK506, Control Point, Chehalis jct	
517	PDX	67	DCS	53	DCS	43	XA4-XTW	BN	Restrictive signal(s) from known wayside signal failure Stopped at Pacific due to signal Correspondence issue, Approah Medium, Approach, Approach, Stop, Control Point, Rainer, Control Point, Auburn Yard, Control Point, Ellington, Control Point, Pacific	
518	VAC	59	POL	47	POL	47	MVW-BEL	BN	Right of Way police hold Person fell onto tracks ahead of us.	
58	CHI	112	WTR	69	WTR	38	HMD-MCB	CC	Heat order Milepost, 859, 806.9	
59	NOL	205	SVS	166	SVS	144	CHI-CHI	AM	Late arriving train, signed up on rest, switched out 5900 car, servicing and watering train. Passenger issue in the 01 which prevented boarding in that car. thx	
11	LAX	41	FTI	147	FTI	50	KFS-DUN	UP	Follow Followed up 9049 south from +/- mp 374 until they cleared at cp vp 346, up 9049 south, Control Point, cp vp 346	
14	SEA	119	DCS	88	DCS	35	SJC-OKJ	UP	Power switch failure Control Point, NI014	
8	CHI	58	DSR	64	SVS	28	MOT-MOT	BN	Routine inspections	
821	FTW	58	FTI	58	FTI	26	ADM-GLE	BN	Follow bnsf 4216, Other, marrietta - thackerville	
822	OKC	28	DSR	37	DSR	21	GLE-ADM	BN	Per bulletin Milepost, 413.6, 462.0, 40, m, Milepost, 414.6, 415.1, 60, m, Milepost, 423.6, 424.2, 50, m, Milepost, 426.3, 426.4, 50, m	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/23/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
335	MKE	11	DMW	10	DMW	8	GLN-XRO	ME	Held for or routed around MW work or equipment #8184 Foreman Gavinia work train on MT1, dropping RR ties, Control Point, Deerfield 1-2
338	CHI	27	CAR	22	CAR	22	XRO-GLN	ME	Air / Brake / Wheel ID4208, ID4017, Hose came apart between cars over rondout. Hose still hanging fairly low when re connected
339	MKE	66	CCR	54	CCR	54	CHI-CHI	AM	Air / Brake / Wheel 90221, Piston on the 90221 fireman's side front was not traveling correctly. The piston would not go in more than couple inches without getting pushed in. Brakes were released on gauges but shoe barely moved so had mech check out per asa baker
342	CHI	45	ITI	39	ITI	39	MKE-MKE	CP	Service, turn, or wye train 339
572	SAN	16	FTI	10	FTI	10	XRJ-FUL	BN	Meet bnsf1631, Control Point, Bandin, 7631
761	SLO	43	RTE	32	RTE	32	X3G-LPS	UP	Dispatcher hold Holding for space x launch, Control Point, gaviotta
702	BFD	66	FTI	54	FTI	29	MDR-FNO	BN	Follow 6847E, Other, in route, BNSF
703	SAC	No OS Rpt	DCS	45	DCS	37	MOD-XSK	BN	Power switch failure Power switch failure. Flagged from hanshaw to keddie junction, Control Point, hanshaw
710	BFD	107	FTI	46	DBS	26	MDR-FNO	BN	Debris blocking track (no debris strike) Other, 1005.1
711	OKJ	34	DSR	40	DSR	11	FNO-MDR	BN	Per bulletin Milepost, 995.8, 1002.0, 25, Main Trk
712	BFD	34	DSR	40	DSR	17	MDR-FNO	BN	Per bulletin Milepost, 1000.5, 998.1, 25, m 1-2
713	OKJ	Trn Cancelled	FTI	98	FTI	49	HNF-FNO	BN	Meet 6847, Control Point, fresno
714	BFD	46							
715	OKJ	57	PTI	38	PTI	20	HNF-FNO	BN	Meet amt 712, Control Point, calwa
716	BFD	Trn Cancelled	ENG	188	ENG	188	TRK-MCD	BN	Failure of diesel engine 2003
717	OKJ	Trn Cancelled	SYS	102	SYS	70	MCD-TRK	BN	Blocked by or assisting another, disabled Amtrak train Attach to 716 at mp 1065.5. Take back to merced to detrain
718	BFD	No OS Rpt	PTI	43	PTI	40	SKN-MOD	BN	Meet 717/716, Siding, Riverbank

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/23/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
719	OKJ	109	DCS	81	DCS	79	MOD-SKN	BN	Power switch failure Power outage causing power switch failure and crossing at grade failure. Multiple trains stacked up in front of us due to power outage., Control Point, keddie jct	
3	LAX	171	CON	101	CON	101	CHI-CHI	AM	Hold for connecting train 49	
4	CHI	187	DSR	83	ENG	26	MDT-NPV	BN	Unrecoverable penalty (PCS) ATS penalty, 188	
22	CHI	No OS Rpt	ENG	387	ENG	351	MIN-LVW	UP	Air / Brake 58	
302	CHI	26	FTI	25	FTI	10	DWT-JOL	UP	Follow UP 1450, Milepost, 73, 63	
305	STL	18	DSR	29	FTI	9	PON-BNL	UP	Meet UP 9785, Siding, Pontiac siding	
391	CDL	33	FTI	28	PTI	14	RTL-CHM	CC	Meet AMTK390, Other, CHM yard lead	
316	STL	22	DCS	25	DCS	25	JEF-HEM	UP	PTC system failure (wayside) Control Point, Ames	
318	CHI	47	DSR	43	PTI	15	SPI-LCN	UP	Meet amt 21, Control Point, x181	
319	KCY	30	DCS	21	DCS	14	HEM-JEF	UP	PTC- I-ETMS Red Fence/Signal Status Unknown PTC kept dropping, giving switch position unknown. Restricted speed to mp 104.3, Control Point, Ames	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/23/2025

Terminal	Train	Date	Late	Delay	Cause
MIA	98	07/23	7	7	PTC problem or failure (cause unknown) PTC would not accept bulletins, PTC breaker was flipped and orders accepted after
PHL	110	07/23	12	12	Set out defective car, 82802, shopped due to brake pads and broken hold down latch for the inner pad
SFA	52	07/23	42	42	PTC- IETMS incorrect consist No PTC consist entered
WAS	56	07/23	22	21	Commercial power outage, Control Point, C INTERLOCKING, CATENARY IN THE S&I OUT
WAS	2108	07/23	27	28	CETC/PSCC system failure, Control Point, was, loss of amtec
WAS	2166	07/23	5	5	Door, 3215, 3554, FIRST CLASS CAR 3215 AND QUIET 3554 CAR BOTH HAD DOOR ISSUES AT DP TIME
BTN	290	07/23	4	4	Unable to contact dispatcher / MW foreman Unable to initially contact foreman for permission through Burlington yard limits., Other, Btn
MTR	68	07/23	18	18	Water, commissary, toilet/trash dumping Other, MTR
NHV	494	07/23	20	20	Service, turn, or wye train, 417, late turn
NYP	97	07/23	20	20	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C WAITED FOR CARS OFF AM98
NYP	151	07/23	35	35	Air / Brake / Wheel, 00000, SWITCH COACH CARS, NO CAR NUMBER SPECIFIED
NYP	283	07/23	6	6	Passenger and/or baggage, HEAVY LOADING
NYP	655	07/23	5	5	Undesired emergency application, 9644 615, TRAIN LINE ISSUES
POR	686	07/23	15		
CHI	3	07/23	130	130	Set out defective car 38067, There were two dinners witch out
CHI	7	07/23	212	212	Set out defective car 33034, 33040 was replaced by 33034
CHI	41	07/23	8	8	Per (control center) late train set Other, Chicago Union Station
CHI	59	07/23	100	100	Planned set out / pick out of locomotives, cars or section of train
CHI	339	07/23	58	54	Air / Brake / Wheel 90221, Piston on the 90221 fireman's side front was not traveling correctly. The piston would not go in more than couple inches without getting pushed in. Brakes were released on gauges but shoe barely moved so had mech check out per asa baker
CHI	339	07/23	58	4	Service, turn, or wye train 338
CHI	364	07/23	42	42	Set out defective car ID4003, Replaced 4002 car with 4003
EUG	504	07/23	9	9	Set out defective car 82514
MKE	338	07/23	6	6	Service, turn, or wye train 335
MKE	342	07/23	39	39	Service, turn, or wye train 339
BFD	719	07/23	7	7	Service, turn, or wye train 710

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/23/2025

Terminal	Train	Date	Late	Delay	Cause
EMY	6	07/23	208	208	Service, turn, or wye train 5, Late train. Late leaving yard due to cleaning service and fixing diner
OKJ	520	07/23	10	10	Planned set out / pick out of locomotives, cars or section of train Add Loco AMTK190. Blue flag protection released @ 05:01., Other, Oakland Mechanical facility
OKJ	536	07/23	28	28	HEP HEP dropped after we switched ends...we check all cables and ended up short looping, 171
OKJ	714	07/23	26		
OKJ	716	07/23	19	19	Service, turn, or wye train 715, Ended up taking 714's equipment due to them taking our equipment. We have 715's equipment from last night but had to remove loco 2124 after 2003 was placed on top of it and then had 2003 put back on.
OKJ	718	07/23	16	16	Service, turn, or wye train 713, Late arrival of trainset.
SAC	549	07/23	22	22	Air / Brake 171
SAC	702	07/23	27	27	Late bulletins due to Amtrak cause Printer wasn't receiving orders, had to call several times to get orders emailed., Other, sac

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.4	93.9	95.2	341	9
CDOT	95.0	90.0	95.5	96.4	20	2
MARC	95.0	No Data	No Data	83.5	No Data	No Data
SEPTA	95.0	No Data	No Data	96.2	No Data	No Data
NJT-NED	95.0	92.1	92.1	95.2	369	29
NJT-SED	95.0	No Data	No Data	91.2	No Data	No Data

Operating Highlights

Train 2166(23) Boston, MA - Engine Failure

23JUL25: at approximately 8:02PM-ET the Boston Chief reported that Train 2166(23), TS6, PC/2030, 6 cars, PC/2031, was disabled at Boston, MA Back Bay station. The crew reported both of their pantographs dropped as they were pulling into the station. Crew worked with an Amtrak Road Foreman and mechanical to try and resolve the issue. The crew was to expire on hours of service at 8:30PM-ET, therefore a yard crew was dispatched from Boston SHSY to protect the train into Boston. Still unable to resolve the issue, the decision was made to transfer all 103 passengers to Keolis 874 and terminate the train. The crew was later able to raise the pantographs but were still unable to proceed with power car PC/2030 in the lead. Due to this, the train made a shove move into to Boston station, arriving at 8:53PM-ET.

Train	Delay	Comment
2166(23)	Terminated	BBY

Train 20(23) Meridian, MS - Injured or Sick Passenger

23JUL25: Train 20(23) was delayed departing Meridian, MS due to waiting for EMS to remove a sick passenger with reported low blood sugar.

Train	Delay	Comment
20(23)	32"	

Train 20(23) North of Birmingham, AL - Switch Issue

23JUL25: Train 20(23) was delayed at Lovick/ MP787.7, 12 miles north of Birmingham, AL on the Norfolk Southern East End Subdivision, due to switch failure and unable to line. Once signal maintainer arrived and was able to line the switch, Train 20(23) continued north.

Train	Delay	Comment
20(23)	1'17"	

Train 52(23) Sanford, FL - initializing PTC - System

23JUL25: Train 52(23) was delayed departing Sanford due to having problems initializing PTC.

Train	Delay	Comment
52 (23)	42"	

Train 64(23) East of Syracuse, NY - Freight Train Interference

23JUL25: Train 64(23) was delayed on the CSX Syracuse Terminal at MP 287.0 due to the CSX meeting I019-23 set out cars and then meeting I104-22, I003-23.

Train	Delay	Comment
64 (23)	55"	

Train 40(22) North of Rocky Mount, NC - EMS/Police Related

23JUL25: Train 40(22) was delayed on the CSX North End A subdivision at MP 53.4/Jarrett and held for EMS for a unresponsive passengers. EMS arrived and the passenger was removed.

Train	Delay	Comment
40 (22)	51"	

Train 486(23) New Haven, CT - Hold for Connection

23JUL25: Train 486(23) was held in New Haven for connections off late train 86(23) at 305P-ET 47" late.

Train	Delay	Comment
486 (23)	33"	

Train 79(23) Washington, DC - Adding Engine /Servicing

23JUL25: Train 79(23) was delayed departing Washington due to attempting to add E/749 to rear for Lorton. The crew was having parking brake issues and it was decided to cut the engine off and proceed with out it.

Train	Delay	Comment
79 (23)	54"	

AMTEC Systemwide Outage - CETC System

23JUL25: At 1031A-ET, Washington Terminal reported that K Tower lost AMTEC system and were now working in local control with C&S to make shifts in the terminal. As of 1050A-ET, CETC reported that the AMTEC system was coming back slowly. As of 1055A-ET, CETC reported that all sections were back under CETC control with the exception of section 5 which was in local control. As of 1118A-ET, CETC control for sections 5 for Penn Interlocking was restored and Remote control was restored for State Interlocking.

Train	Delay	Comment
2108 (23)	28"	
174 (23)	29"	
642 (23)	04"	
43 (23)	04"	
182 (23)	04"	
2153 (23)	10"	
114 (23)	23"	
646 (23)	40"	
190 (23)	03"	
607 (23)	02"	
2162 (23)	29"	
643 (23)	38"	
185 (23)	30"	
86 (23)	39"	
645 (23)	03"	
84 (23)	03"	
648 (23)	21"	
183 (23)	21"	
3 MARC'S	17"-24"	

Train 55(23) Essex Junction-Burlington, VT - Temporary Speed Restrictions

23JUL25: Train 55(23) was delayed on the NECR Roxbury subdivision starting 10 miles north of Essex Junction between MP 118.0 and MP 114.0 due to temporary speed restrictions. Train 56(23) was also delayed due to these restrictions.

Train	Delay	Comment
55 (23)	37"	
56 (23)	47"	

Train 2190(23) East of New York, NY - Engine Failure

23JUL25: Train 2190(23) with set 13 PC/2033,PC/2027 was delayed on the NYS main line at Leggett Interlocking due to an undesired emergency application. The crew was able to cut out the Alerter and proceed east.

Train	Delay	Comment
2190 (23)	33"	
66 (22)	25"	

NYS Main Line - Bridge Strike

23JUL25: At 825A-ET A vehicle struck the bridge at Kings Highway, MP 18.75, NYS Main Line between Manor and Division Post. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 955A-ET, the bridge was inspected and released for normal service.

Train	Delay	Comment
2151 (23)	02"	
2150 (23)	07"	
2153 (23)	02"	
170 (23)	03"	

Train 40(22) - South of Columbia, SC - Near Miss/Vehicle on Tracks

23JUL25: Train 40(22) was delayed on the CSX Columbia Subdivision at MP 371.9 due to a near miss with a vehicle on the tracks. The train held for a tow truck to remove the vehicle. The tow truck arrived at 640A-ET and the vehicle was cleared as of 657A-ET. The train was able to proceed north.

Service Recovery was initiated with complimentary coffee and tea in the cafe car.

WBS#: B.TR.100150.5918

Train	Delay	Comment
40 (22)	1' 47"	

Train 151(23) - New York, NY - Car Failure

23JUL25: Train 151(23) was delayed at its initial terminal at New York Penn Station due to coach 82531 being shopped and replaced.

Train	Delay	Comment
151(23)	35"	

Acela Cancellations - Shopped Equipment

24JUL25: Due to multiple shopped Acela train sets, the following service adjustment were necessary: Acela Trains 2190(24), 2163(24), 2152(24) and 2169(24) were canceled in entirety for Thursday, July 24th, 2025. Passengers were notified via Service 360 and able to re-book to next available services.

Valley Flyer Service Cancellations - Engine Failure

21JUL25: Due to Engine shop counts, the following Valley Flyer the following service adjustments have been made:

- Train 5552(21-23) DH Equipment - was cancelled
- Train 425(21-23) was cancelled with alternate bus transportation
- Train 475(21-23) was cancelled with alternate bus transportation
- Train 478(21-23) was cancelled with alternate bus transportation

UPDATE: As of 1012A-ET on 7/23/25 Train 478(23) will operate as a live train no busses.

Train	Delay	Comment
DH 5552(21)	Cancelled	
425(21)	Cancelled	Bussing Secured

Maintenance of Way Highlights

Amtrak Washington Terminal Washington, DC - M of W Work

11JUL25: To accommodate 434/436 and 436/438 switch installs on the Amtrak Washington terminal at C Interlocking/MP 135.0 the following adjustments are in place. Trains 41(11, 18, 01AUG) will be canceled entirely with no alternate transportation. Trains 41(12, 19, 02AUG) will originate at Washington with no alternate transportation. Trains 40(11, 12, 18, 19, 01, 02AUG) will terminate at Washington with no alternate transportation. Trains 40(13, 20, 03AUG) will originate at Washington with no alternate transportation.

UPDATE: As of 7/23/25 the trackwork has been cancelled for 25JUL,26JUL and 27JUL, 28JUL.

WBS#: B.TR.100150.5743

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

06JUN25: This is now extended to run into the Lake Shore Limited MBTA Keolis Worcester Main Line Trackwork. Train 448(02-26JUN) will terminate Albany and 449(02-28JUN) will originate Albany. Alternate buses 3448 and 3449 will operate between Albany and Boston in lieu of train service making all stops except Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 2 extended to July Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 2(Update 3) extended until July 1st:

Train 691(28Jun-29Jun) will Terminate WEM

Train 696(28Jun-29Jun) will Originate WEM

Train 681 (24Jun-27Jun, 30Jun-01Jul) will terminate at WEM

Train 686 (24Jun-27Jun, 30Jun-01Jul) will originate at WEM.

Train 692 (21Jun-22Jun, 28Jun-29Jun) will depart BRK 40-minutes Earlier, at 6:30am

Train 683 /684 /685 (24Jun-27Jun, 30Jun-01Jul) is canceled in its entirety with no alternate transportation.

Trains 693 /695 /694 (28Jun-29Jun), which normally operates between BON and BRK, is canceled in its entirety with no alternate transportation.

Train 682 (23Jun-27Jun, 30Jun-1Jul) will depart BRK 40-minutes Earlier, at 6:30am.

Train 1697(24Jun-1Jul) is a new train that will operate between BON and BRK, departing BON at 5:57pm.

ALTERNATE TRANSPORTATION

- Buses 3681 and 3691 will provide alternate transportation between WEM and BRK making all stops except SAO and ORB.
- Buses 3686 and 3696 will provide alternate transportation between BRK and WEM making all stops except ORB and SAO.

Phase 3, begins July 8th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-29Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-29Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
97	ORL	1	WPB	N/A
2122	NYP	2	NCL	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 68(23) Passenger Removal at Rouses Point, New York-Customs

23JUL25, Passenger on PNR 3ED3DE, traveling from Montreal, QC to New York, NY was reportedly denied travel across the border by Customs Border patrol. Amtrak Police notified.

Delay: 68 (23) None

Train 20(23) Passenger Removal at Laurel, Mississippi – Improper Conduct

23JUL25, Passenger on PNR 1FA133, was reportedly removed by local police due to getting into a verbal altercation with the conductor over smoke break stops. Amtrak Police notified.

Delay: 20 (23) 05"

Train 20(23) Passenger Removal at Meridian, Mississippi – Medical

23JUL25, Passenger on PNR 330CFE, was reportedly removed by local EMS due to having low blood sugar. Amtrak Police notified.

Delay: 20 (23) 32"

Train 79(23) Passenger Removal at Greensboro, North Carolina - Medical

23JUL25, Passenger on PNR 3D9DB0, traveling from New York, NY to Greensboro, NC was removed at destination by local EMS. Passenger contacted EMS on their own, no visible injury noted by crew. Amtrak Police notified.

Delay: 69 (23) 15"

Western Region

Operating Highlights

San Juanquins South of Stockton, CA - Signal

24JUL25: Multiple San Juanquins trains were delayed 1 mile south of Stockton, CA, on BNSF Stockton subdivision due to a power outage causing signal failure. This caused heavy traffic for all trains operating through the affected area.

Train	Delay	Comment
719(23)	1'19"	
717(23)	49"	
703(23)	37"	
718(23)	35"	
718(23)	40"	Meeting 717/716(23)

Train 59(23) Chicago, IL - Engine Failure

24JUL25: Train 59(23) was delayed departing Chicago account late release due to late train make up. As background, Train 58(22) arrived in CUS at 11:08am and set in the yard at 11:52am for inspection and servicing. Due to multiple b/o and no replacements, C/33034 was held off to Train 7(23), no replacement. Train 59(23) was also required to operate with an additional 2nd engine due to temperatures in excess of 100-degrees Fahrenheit. E/334 off inbound Train 8(21) was designated as the additional lead loco. Train 8(21) arrived in CUS at 05:43pm. Train 8(21) wyed to the yard at 06:38pm and set in Pit 3 at 07:07pm. After cuts were made, E/334 was held off at 07:32pm. E/334 was swung over to Track 12, Train 59(23) was m/u complete at 07:47pm. After servicing E/334 and completing Class II, Mechanical released train at 08:42pm. YC13 advanced into CUS at 08:50pm and set at 08:55pm. Boarding of 196 passengers commenced at 09:09pm. South Gate cleared at 09:32pm, Train 59(23) departed CUS at 09:45pm; 1 hour and 40 minutes late.

Train	Delay	Comment
59(23)	1'40"	

Train 339(23) Chicago, IL - Initial Terminal Delay

24JUL25: Train 339(23) was delayed departing Chicago account late turn of equipment of Train 338(23) which arrived at 05:06pm; 27 minutes late due to a 22-minute delay 13 miles west of Glenview, IL for air hose separation between C/ID4208 and C/ID4017 and 7 minutes in commuter train interference. After detraining 115 passengers, boarding of 207 passengers commenced at 05:16pm. Train 339(23) was further delayed due to piston on front fireman side Cab Car 90221 not traveling correctly. Yard Mechanical was notified at 05:26pm. After deciding to address issues with Cab Car upon return of Train 342 to the yard, Mechanical cleared at 06:03pm. After initialized I-ETMS and conducted the required Class II air test, Train 339(23) departed CUS at 06:06pm; 58 minutes late.

Train 342(23) was delayed departing Milwaukee, Wisconsin, due to turning of late 339(23).

Train	Delay	Comment
339(23)	58"	
342(23)	39"	

Train 518(23) North of Mount Vernon, WA – Search and Rescue Operation

23JUL25: Train 518(23) was delayed 16 miles north of Mount Vernon, WA at Tunnel 18, MP 83.1, Scenic Subdivision, BNSF Railway. Local Emergency Responders were conducting a search and rescue effort to locate a missing person believed to have fell on the tracks. Once completed, with personnel clear of the rails, tracks were opened allowing train 518(23) to continue to Bellingham. Amtrak Police Notified.

Train	Delay	Comment
518(23)	47"	

Train 21(22) North of San Antonio, TX - Freight Train Interference

23JUL25: Train 21(22) was delayed 13 miles north of San Antonio, TX, on UP Austin subdivision, due to disabled BNSF8240 with air issues obstructing the route. The disabled freight replaced a gasket on its rear car and was able to recover its air. Once recovered, the freight was able to proceed, clearing a route for train 21(22).

Train	Delay	Comment
21(22)	42"	

Train 716(23) East of Turlock Denair, CA – Locomotive Oil Pressure – Cancelled

23JUL25: Train 716(23) stopped 10 miles east of Turlock/Denair, Fairfield when locomotive CDTX/2003 developed a low oil pressure warning. The train stopped on the single mainline at east Fluhr MP 1065.5, Stockton Subdivision of BNSF Railway. The locomotive was unable to provide tractive effort. Head End Power was temporarily shut down for 20 minutes while diagnosing the cause. There were 106 passengers on board. Outside temperature was 88 degrees and sunny. With no availability of replacement buses or rescue locomotives in the area the following amended operating plan applied: Train 716(23) was cancelled at Merced. To prevent engine damage, trains 716(23) & 717(23) were coupled together at site with both trains returning to Merced. Passengers for 716(24) disembarked at Merced to wait for train 718(23) to destination. The combined trainset then continued west. Train 717/716(23) combined trainset terminated in Emeryville where passengers for Oakland boarded thruway 6617(23) making additional stop in Oakland. Train 717(24) was cancelled, with all affected passengers advised to use alternate departures. Service Recovery: All San Joaquin trains offer complimentary snacks and soda.

Cause: Pending

WBS#: B.TR.100150.5919

Train	Delay	Comment
716(23)	Terminates Merced	Passengers to 718(23)
717(24)	Cancelled	Passengers to Alternate Departures

Train 507(23) South of Seattle, WA – Interior Door Jammed Shut

23JUL25: Train 507(23) was delayed 6 miles south of Seattle when the crew reported the interior door in Bistro car C/48187 became lodged shut. The train returned to Seattle King Street station from Boeing, MP 6.3X , Seattle Subdivision, BNSF Railway. Technicians were waiting in Seattle for the train to arrive. They were able to free the jammed door allowing the train to depart for a second time.

Cause: Pending

Train	Delay	Comment
507(23)	1'19"	

Train 715(23) West of Hanford – Train Interference

23JUL25: Train 715(23) was delayed 27 miles west of Hanford at Calwa station, MP 994.9, Bakersfield Subdivision of the BNSF Railway. Unidentified BNSF Freight train BNSF was operating into Calwa yard. Once cleared, train 715(23) was further delayed waiting for the station track from train 712(23). Once 712(23) had departed, train 715(23) entered Fresno station.

Train	Delay	Comment
715(23)	12"	Calwa Crossing - Meet BNSF
717(23)	20"	Calwa Crossing - meet BNSF
715(23)	20"	Calwa Crossing - Meet 712(23)

Train 517(23) South of Tukwila WA - Signal Failure

23JUL25: Train 517(23) was delayed 14 miles south of Tukwila at Pacific, milepost 24.0X, Seattle Subdivision , of the BNSF Railway. This was because the Dispatcher was unable to gain remote control of the signals. Train 517(23) was required to stop & wait for the dispatcher authority to proceed. Once granted, the train advanced at reduced speed until clear of the affected area. Then train 517(23) was able to continue at track speed to Tacoma.

Train	Delay	Comment
517(23)	43"	

Train 5(21) West of Truckee, CA- Freight Train Interference

23JUL25: Train 5(21) was delayed 13 miles east of Truckee at MP 191.2, West Norden, Roseville Subdivision, of the Union Pacific Railroad. This was to allow for Union Pacific train GSFOAT- 22 (UPRR/7229) to use crossover switches ahead. Once the track ahead was cleared, train 5(21) continued to Colfax.

Train	Delay	Comment
5(21)	52"	

Train 710(23) East of Merced CA - Freight / Passenger Train Interference

23JUL25: Train 710(23) was delayed 13 miles east of Merced CA at Savana/Sharon Siding, MP 1042.0, Stockton Subdivision of the BNSF Railroad. This was to allow for BNSF train BNSF/8158 and train 713(23) to pass. Once the track ahead was cleared train 710(23) was continued to Madera Acres.

WBS#: B.TR.100150.5916

Train	Delay	Comment
710(23)	24"	Sharon Meet 713(23)
710(23)	15"	Sharon Meet BNSF 8158

Trains 3(23) and 7(23) Chicago, IL - Car Failure

23JUL25: Train 3(23) with E/167-182 and 9 cars was delayed departing Chicago due to C/38064 bad ordered for refrigeration and replaced with C/38067. The delay was prolonged once arriving Union Station at 331PM-CT to board 223 passengers due to toilet issues on the coach cars. Mechanical was on scene to assist in repairs. Once repairs were made, 3(23) departed Chicago at 435PM-CT, 2 hours, and 10 minutes late.

Additionally, train 7(23) with E/361-304 and 10 cars was delayed departing Chicago due to C/39037 bad ordered for Box 5 TFW and ripped back. Also, C/34107 was bad ordered for HVAC and replaced with C/33034.

Finally, train 364(23) with E/ID4627, 6 cars, and E/ID4618 was delayed departing Chicago due to C/ID4002 bad ordered for hi-low and replaced with C/ID4003. The equipment was released and set in the station at 420PM-CT to board 212 passengers.

Train	Delay	Comment
3(23)	2'10"	
364(23)	42"	
7(23)	3'41"	

Train 713(23) West of Corcoran, CA – Freight Train Interference – Terminates Emeryville

23JUL25: Train 713(23) was delayed west of Corcoran - on the BNSF Railway - while waiting for various BNSF Freight trains to pass:

Location	Milepost	Subdivision	Opposing Train
Guernsey	MP 959.4	Bakersfield	BNSF 6743
Fresno	MP 997.7	Stockton	BNSF 6847
Gregg	MP 1010.7	Stockton	BNSF 6423

To assist service crews - turning the trainset for 718(23) - train 713(23) was terminated in Emeryville. Twenty-One (21) passengers travelling to Oakland were provided bus transport to complete their trip.

WBS#: B.TR.100150.5917

Train	Delay	Comment
713(23)	20"	Guernsey - Meet BNSF 6743
713(23)	49"	Fresno - meet BNSF 6847
713(23)	12"	Gregg - Meet BNSF 6423
713(23)	Terminates Emeryville	Passengers to replacement bus

Train 8/28(22) St. Paul-Minneapolis, MN - Car Failure

23JUL25: Due to train 8/28(22) operating with E/306-50 and 10 cars with C/31024 bad ordered for toilets. As a result, two buses were secured as alternate transportation between St. Paul-Minneapolis and Chicago. Bus A operated express between St. Paul-Minneapolis and Chicago. Bus B operated between St. Paul-Minneapolis, Redwing, Winona, La Crosse, Tomah, Wisconsin Dells, Portage, Columbus, and Milwaukee. Passengers traveling east of Milwaukee were accommodated on the next available Hiawatha services.

WBS#: B.TR.100150.5915

Train 22(22)/422(20) South of Texarkana, AR - Passenger Train Interference

23JUL25: Train 22(22)/422(20) was delayed seven miles south of Texarkana on the UPRR Little Rock subdivision due to meeting 21/421(22) at Sulphur/MP 6.8.

Train	Delay	Comment
22(22)/422(20)	48"	

Train 11(22) South of Dunsmuir CA – Train Interference

23JUL25: Train 11(22) was delayed 60 miles south of Dunsmuir at Silverhorn, MP263.4, Valley Subdivision of the Union Pacific Railroad. This was to allow for the safe passage of Union Pacific Freight train UPRR/7964 and Amtrak train 14(22) using the single track ahead. Once the traffic had safely passed, train 11(22) continued to Redding.

Train	Delay	Comment
11(22)	29"	Silverhorn - Meet UPRR/7964
11(22)	09"	Silverhorn - Meet 14(22)

Train 6(23) Initial Terminal Emeryville, CA - Late Inbound Equipment

23JUL25: Train 6(23) was delayed departing Emeryville, MP 4.5/UPRR Martinez Subdivision, as a result of the late turning and servicing of equipment off inbound Train 5(20) which arrived in Emeryville eight hours, three minutes late at 1:00AM-PT. Also, as a result of crew rest, Train 6(23)'s crew signed-up at 10:00AM-PT. Train 6(23) departed Emeryville at 11:53AM-PT.

Train	Delay	Comment
6(23)	3'28"	

Train 6(21) West of McCook, NE - Passenger Train Interference

23JUL25: Train 6(21) was delayed 11 miles west of McCook on the BNSF Akron subdivision due to meeting 5(22) at Culbertson/MP 299.2.

Train	Delay	Comment
6(21)	35"	

Train 11(22), South of Klamath Falls OR, Freight Train Interference

23JUL25: Train 11(22) was delayed 55 miles south of Klamath Falls while following a slower operating freight train. The freight train (UPRR/9049) was followed between South Kegg MP 374.00 and Black Butte MP 346.00 Black Butte Subdivision UPRR Railroad. At Black Butte the freight train entered the siding allowing train 11(22) to continue to Dunsmuir at track speed.

Train	Delay	Comment
11(22)	50"	

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District – Trackwork East of Solana Beach, CA
19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:
from 10:00PM-PT thru 7:00AM-PT.
Selected work dates are:
Sunday May 19 – Tuesday May 21
Sunday June 02- Tuesday June 04
Sunday June 16 – Tuesday June 18

Sunday June 23 - no extended window account Padres game.
 Sunday June 30 - Tuesday July 2
 Sunday July 7 - Tuesday July 9
 Sunday July 14 - Tuesday July 16
 Sunday July 21 - Tuesday July 23
 Sunday July 28 - Tuesday July 30
 Sunday August 4 - Tuesday August 6
 Sunday August 11 - no extended window account Padres game
 Sunday August 18th - Tuesday 20th
 Sunday August 25 - Tuesday August 27
 Sunday September 8 - Tuesday September 10.
 Sunday September 15 - Monday September 16
 Sunday September 22 - Tuesday September 24.
 Sunday October 27 - Tuesday October 29.
 Sunday November 3 - Tuesday November 5.
 Sunday December 8-Tuesday December 10.
 Sunday December 15-Tuesday December 17.
 2025
 Sunday February 9 - Tuesday February 11.
 Sunday April 06th - Tuesday April 08th (CANCELLED)
 Sunday May 20 - Tuesday May 22

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Train 22(22)/422(20) West of Longview, TX - Engine Failure

23JUL25: Train 22(22)/422(20), with engine 58, 9 cars, and 197 passengers, was delayed at mile post 93.5 4 miles west of Longview, TX/MP89.5 on the UP Mineola subdivision due to air compressor failure on the engine 58. The crew worked with CNOC Mechanical Desk and Los Angeles Mechanical by phone but the air compressor could not be recovered. HEP remained active, except for brief outages while troubleshooting. An Amtrak Road Foreman responded to the scene from Ft Worth, TX. Union Pacific freight UP/6769 was sourced out of Red, TX/MP87.8 to rescue the equipment. Once the equipment was made up complete with freight UP/6769 in the lead, train 22(22)/422(20) continued into Longview Station, TX. At Longview, the train was held to board an Amtrak relief crew with UPRR pilots. Once the crews were briefed and on board, 22(22)/422(20) departed Longview at 506AM-CT, 10 hours, and 53 minutes late.

Customer service recovery was implemented with coffee, tea, water, and juice. Charley's Restaurant delivered individual boxed lunches to St. Louis for dinner.

Train	Delay	Comment
22(22)/422(20)	5'37"	
22(22)/422(20)	1'00"	LVW - relief crew

Train 1333(22) East of Red Wing, MN - Signal

23JUL25: Train 1333(22) was delayed two miles east of Red Wing on the CPKC River subdivision due to switch issues at Colvill West/MP 369.0.

Train	Delay	Comment
1333(22)	1'33"	

CN Heat Orders - Weather

22JUL25: Trains were delayed on the following subdivisions due to CN heat orders implemented between 1000AM-CT and 1000PM-CT on July 22 through July 24: Centralia, Cairo, Fulton, Shelby, Yazoo, McComb, and Beaumont.

Train	Delay	Comment
58(22)	1'09"	
59(21)	1'03"	
391(22)	10"	
392(22)	11"	
58(23)	1'01"	
392(23)	10"	
391(23)	13"	

Maintenance of Way Highlights

Train 6(23) East of Roseville – Trackwork/Freight Train Interference

23JUL25: Union Pacific track maintenance workers closed track #2 at Colfax to repair heat damaged rail joints at MP 141.00 Roseville Subdivision, Union Pacific Railroad. This required train 6(23) wait for UPRR freight MROMI -22 (UPRR 6584) to pass on track #2. Once the track ahead was clear, train 6(23) shoved back to cross to track #1 then proceed at track speed to Truckee.

Train	Delay	Comment
6(23)	46"	

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike DMG// MP372.5
7 (8)	WTN	348		Hot axle

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
LVW	LVW	UP6769	E/58 AIR COMPRESSOR		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 14(22) Passenger Incident at Chemult, Oregon – Medical

22JUL25, Passenger on PNR 3450a3, traveling from Sacramento, CA to Portland, OR was evaluated by EMS and they determined the passenger was ok to travel. Amtrak Police notified.

Delay: 14 (22) 7"

Train 354(23) Passenger Removal at Hammond-Whiting, Indiana – Refusal to Pay

23JUL25, Passenger on PNR none, was removed due to not having a ticket and attempting to panhandle money from other passengers to purchase one. Amtrak Police notified.

Delay: 354 (23) 03"

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/23/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	299	30	90%	6,634	596	91%	85,403	6,621	92%
Northeast Corridor	98%	80	9	89%	1,745	240	86%	22,930	2,473	89%
Acela	98%	24	4	83%	485	85	82%	6,400	853	87%
Northeast Regional	98%	56	5	91%	1,260	155	88%	16,530	1,620	90%
State Supported	98%	191	14	93%	4,257	228	95%	53,680	2,741	95%
Long Distance	98%	28	7	75%	632	128	80%	8,655	1,401	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/23/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	299	30	90%	6,634	596	91%	85,403	6,621	92%
Northeast Corridor	98%	80	9	89%	1,745	240	86%	22,930	2,473	89%
Acela	98%	24	4	83%	485	85	82%	6,400	853	87%
Northeast Regional	98%	56	5	91%	1,260	155	88%	16,530	1,620	90%
On Spine Northeast Regional	98%	30	1	97%	655	77	88%	8,389	855	90%
Richmond / Newport News / Norfolk	98%	12	2	83%	269	63	77%	3,449	527	85%
Roanoke	98%	4	2	50%	92	10	89%	1,178	160	86%
Springfield Shuttles	98%	10	-	100%	244	5	98%	3,514	78	98%
State Supported	98%	191	14	93%	4,257	228	95%	53,680	2,741	95%
Borealis	98%	2	-	100%	46	6	87%	577	65	89%
Capitol Corridor	98%	28	5	82%	600	24	96%	7,060	159	98%
Carolinian	98%	2	1	50%	46	8	83%	592	50	92%
Cascades	98%	14	2	86%	322	16	95%	4,023	284	93%
Downeaster	98%	10	-	100%	226	1	100%	2,814	45	98%
Empire	98%	20	-	100%	460	31	93%	6,346	331	95%
Adirondack	98%	2	-	100%	46	2	96%	592	43	93%
Berkshire Flyer	98%	-	-	100%	9	2	78%	15	4	73%
Ethan Allen Express	98%	2	-	100%	46	5	89%	592	39	93%
Maple Leaf	98%	2	-	100%	46	3	93%	592	57	90%
New York - Albany	98%	10	-	100%	221	8	96%	3,372	95	97%
New York - Niagara Falls	98%	4	-	100%	92	11	88%	1,183	93	92%
Heartland Flyer	98%	2	-	100%	42	1	98%	584	17	97%
Hiawatha	98%	12	2	83%	267	10	96%	3,380	125	96%
Illinois	98%	12	-	100%	298	26	91%	4,065	282	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	92	3	97%	1,172	46	96%
Illini / Saluki	98%	4	-	100%	91	8	91%	1,171	44	96%
Lincoln Service	98%	4	-	100%	115	15	87%	1,722	192	89%
Keystone	98%	27	2	93%	533	29	95%	6,847	417	94%
Lincoln / Missouri	98%	2	-	100%	46	9	80%	586	84	86%
Michigan	98%	10	1	90%	226	19	92%	2,830	273	90%
Blue Water	98%	2	1	50%	46	5	89%	588	87	85%
Pere Marquette	98%	2	-	100%	44	2	95%	590	27	95%
Wolverine	98%	6	-	100%	136	12	91%	1,652	159	90%
Missouri	98%	2	-	100%	44	1	98%	570	15	97%
Pacific Surfliner	98%	24	-	100%	552	13	98%	6,330	235	96%
Pennsylvanian	98%	2	-	100%	46	7	85%	592	67	89%
Piedmont	98%	8	-	100%	183	1	99%	2,352	33	99%
San Joaquins	98%	12	1	92%	274	20	93%	3,540	201	94%
Vermont	98%	2	-	100%	46	6	87%	592	58	90%
Long Distance	98%	28	7	75%	632	128	80%	8,655	1,401	84%
Auto Train	98%	2	-	100%	46	6	87%	580	99	83%
California Zephyr	98%	2	-	100%	46	15	67%	589	137	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	1		19	8	58%	251	52	79%
City Of New Orleans	98%	2	-	100%	46	6	87%	578	52	91%
Coast Starlight	98%	2	1	50%	48	4	92%	595	89	85%
Crescent	98%	2	-	100%	46	4	91%	592	68	89%
Empire Builder	98%	4	1	75%	87	13	85%	1,138	146	87%
Floridian	98%	2	-	100%	44	15	66%	501	176	65%
Lake Shore Ltd	98%	2	1	50%	46	16	65%	990	117	88%
Palmetto	98%	2	-	100%	46	4	91%	590	38	94%
Silver Meteor	98%	2	-	100%	46	10	78%	588	118	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	46	12	74%	590	149	75%
Sunset Ltd	98%	1	1		20	6	70%	250	45	82%
Texas Eagle	98%	2	1	50%	46	9	80%	662	90	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/23/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	11	96%	6,661	179	97%	85,440	2,051	98%
Northeast Corridor	98%	80	3	96%	1,745	47	97%	22,882	645	97%
Acela	98%	24	1	96%	485	13	97%	6,402	169	97%
Northeast Regional	98%	56	2	96%	1,260	34	97%	16,480	476	97%
State Supported	98%	191	6	97%	4,258	72	98%	53,665	892	98%
Long Distance	98%	30	2	93%	658	60	91%	8,755	512	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/23/25											
Day			Month to Date						Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	11	96%		6,661	179	97%	85,440	2,051	98%
Central Division	98%	65	5	92%		1,512	72	95%	19,551	679	97%
Northeast Division	98%	96	2	98%		2,114	44	98%	28,130	658	98%
Southeast Division	98%	69	2	97%		1,464	40	97%	18,894	448	98%
Southwest Division	98%	71	2	97%		1,571	23	99%	18,865	266	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/23/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	11	96%	6,661	179	97%	85,440	2,051	98%
Central Division	98%	65	5	92%	1,512	72	95%	19,551	679	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	50	1	98%	593	3	99%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	26	4	85%	609	50	92%	7,885	437	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	1	50%	46	1	98%	570	4	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	22	-	100%	295	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	45	-	100%	574	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	134	4	97%	1,697	13	99%
MSP	98%	1	-	100%	23	1	96%	284	7	98%
PDX	98%	5	-	100%	111	1	99%	1,423	36	97%
PNT	98%	3	-	100%	68	1	99%	815	8	99%
PTH	98%	1	-	100%	23	-	100%	294	6	98%
QCY	98%	2	-	100%	44	-	100%	574	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	185	10	95%	2,312	123	95%
SPK	98%	1	-	100%	23	-	100%	304	2	99%
STL	98%	3	-	100%	79	3	96%	1,156	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	46	-	100%	567	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	2	98%	2,114	44	98%	28,130	658	98%
ALB	98%	7	-	100%	161	1	99%	2,070	26	99%
BON	98%	5	-	100%	113	-	100%	1,377	3	100%
BOS	98%	19	-	100%	410	8	98%	5,527	130	98%
BRK	98%	2	-	100%	80	-	100%	1,341	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	23	-	100%	294	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	1	-	100%	39	-	100%	566	-	100%
HFD	98%	2	-	100%	32	-	100%	178	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	23	1	96%	294	6	98%
NFL	98%	2	-	100%	46	-	100%	592	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	106	-	100%	1,513	35	98%
NYP	98%	42	2	95%	889	33	96%	11,883	418	96%
POR	98%	3	-	100%	30	-	100%	30	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	21	-	100%	292	1	100%
SPG	98%	4	-	100%	111	1	99%	1,807	20	99%
TWO	98%	1	-	100%	23	-	100%	293	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	69	2	97%	1,464	40	97%	18,894	448	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	112	1	99%	1,466	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/23/25										
Day				Month to Date				Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	301	11	96%	6,661	179	97%	85,440	2,051	98%
Southeast Division	98%	69	2	97%	1,464	40	97%	18,894	448	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	257	2	99%	3,202	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	23	1	96%	290	12	96%
MIA	98%	2	-	100%	44	4	91%	569	32	94%
NFK	98%	3	-	100%	65	2	97%	815	5	99%
NOL	98%	3	-	100%	51	1	98%	658	21	97%
NPN	98%	2	-	100%	46	1	98%	565	4	99%
PGH	98%	1	-	100%	23	-	100%	295	3	99%
PHL	98%	5	1	80%	98	4	96%	1,264	37	97%
RGH	98%	4	-	100%	84	-	100%	1,187	5	100%
RNK	98%	2	-	100%	41	-	100%	558	8	99%
RVM	98%	1	-	100%	23	-	100%	287	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	21	1	95%	277	1	100%
SFA	98%	1	-	100%	23	-	100%	290	18	94%
WAS	98%	25	1	96%	543	23	96%	7,018	270	96%
Southwest Division	98%	71	2	97%	1,571	23	99%	18,865	266	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	23	-	100%	296	-	100%
BFD	98%	6	-	100%	136	-	100%	1,759	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	23	4	83%	303	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	22	-	100%	328	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	69	-	100%	865	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	10	-	100%	217	2	99%	2,276	64	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	20	-	100%	291	-	100%
OKJ	98%	12	1	92%	254	10	96%	3,107	71	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	1	93%	301	2	99%	3,532	14	100%
SAN	98%	12	-	100%	270	4	99%	2,692	26	99%
SAS	98%	1	-	100%	23	1	96%	292	3	99%
SJC	98%	7	-	100%	160	-	100%	1,900	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	46	-	100%	579	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	6	-	100%	53	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/23/2025 12:00..	Diesel Locomotive	Caltrans Locomotive	Superliner II	Amfleet I	High Speed Trainset			Cab Car		Electric Locomotive	California Cars (Cal..)	Surfliner	Grand Total
	ENG	ENG	CAR	CAR	ENG	CAR	MTI	ENG	CCR	ENG	CAR	CAR	
Air Compressor Problem	387												387
Engine Dead/Shut ..		188											188
Car Hot: Air Condition			163	3									166
Door Problems				94		5				4	10	6	119
Air/Brake Problems	35			9					54	4			102
Alertor Problems					52		45						97
Wheel Defects			5	35									40
I-ETMS Problem	36												36
On-Board Hot Jour..	35												35
Battery/Battery Ch..	34												34
480V Trainline Problem	28												28
HEP Problems	19												19
Truck Problems				12									12
ACES Failure					3					7			10
Electrical Problems										6			6
Tilt System Problem..						6							6
M/U Trainline Cabl..								5					5
PA System Problem..			5										5
Grand Total	574	188	173	153	55	11	45	5	54	21	10	6	1,295