



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, July 25, 2025

Rules:5-54



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/24/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	36	87.8%	6,931	828	88.1%	85,638	8,497	90.1%
Central Division	91.5%	66	15	77.3%	1,576	182	88.5%	19,605	1,922	90.2%
Northeast Division	95.0%	92	8	91.3%	2,183	294	86.5%	28,138	3,057	89.1%
Southeast Division	94.5%	68	3	95.6%	1,532	179	88.3%	18,961	1,893	90.0%
Southwest Division	90.5%	69	10	85.5%	1,640	173	89.5%	18,934	1,625	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/24/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	96,669	28,647	70%	2,480,540	789,753	68%	27,865,933	7,507,734	73%
Northeast Corridor	80%	40,206	9,745	76%	1,066,753	320,223	70%	12,367,163	3,196,869	74%
Acela	82%	7,433	2,587	65%	216,376	65,148	70%	2,570,293	619,814	76%
Northeast Regional	78%	32,773	7,158	78%	850,377	255,075	70%	9,796,870	2,577,055	74%
Richmond / Newport News / Norfolk	73%	10,132	3,949	61%	271,027	112,152	59%	3,161,179	1,084,689	66%
Springfield Shuttles	89%	379	110	71%	10,385	2,520	76%	176,382	27,164	85%
Roanoke	70%	2,590	591	77%	70,839	20,420	71%	825,016	217,645	74%
On Spine Northeast Regional	83%	19,672	2,508	87%	498,126	119,983	76%	5,634,293	1,247,557	78%
State Supported	80%	42,897	11,168	74%	1,092,780	282,588	74%	11,904,327	2,642,321	78%
Borealis	60%	581	230	60%	14,965	9,212	38%	171,672	72,390	58%
Capitol Corridor	90%	3,719	111	97%	82,289	6,400	92%	891,484	95,104	89%
Carolinian	60%	477	462	3%	24,834	12,936	48%	340,644	141,360	59%
Cascades	60%	2,603	520	80%	72,264	21,229	71%	755,144	259,255	66%
Downeaster	82%	1,738	252	86%	44,230	8,886	80%	422,912	101,879	76%
Empire	83%	5,215	1,527	71%	140,731	53,491	62%	1,602,713	355,787	78%
Adirondack	75%	148	37	75%	9,660	5,744	41%	87,655	28,443	68%
Ethan Allen Express	85%	546	546	0%	15,269	10,389	32%	160,480	43,713	73%
Maple Leaf	75%	877	776	12%	21,322	12,819	40%	217,399	67,982	69%
New York - Albany	90%	2,346	7	100%	56,478	13,873	75%	743,454	117,307	84%
New York - Niagara Falls	75%	1,298	161	88%	34,637	8,709	75%	388,470	95,608	75%
Berkshire Flyer	60%	0	0	-	3,365	1,957	42%	5,255	2,734	48%
Heartland Flyer	70%	235	114	51%	6,291	4,973	21%	65,810	31,036	53%
Hiawatha	90%	1,965	196	90%	51,562	6,189	88%	502,074	65,554	87%
Illinois	78%	2,320	714	69%	64,864	21,893	66%	735,276	178,970	76%
Carl Sandburg / Illinois Zephyr	80%	456	279	39%	11,656	2,306	80%	118,334	15,395	87%
Illini / Saluki	80%	764	6	99%	21,742	5,058	77%	260,039	33,929	87%
Lincoln Service	75%	1,100	429	61%	31,466	14,529	54%	356,903	129,646	64%
Keystone	92%	8,683	1,498	83%	187,302	16,096	91%	2,152,090	290,778	86%
Lincoln / Missouri	60%	917	917	0%	20,965	13,325	36%	214,942	118,206	45%
Michigan	69%	1,980	987	50%	59,718	15,541	74%	577,733	162,000	72%
Blue Water	70%	311	0	100%	14,432	3,967	73%	143,031	41,859	71%
Pere Marquette	85%	128	0	100%	7,387	1,256	83%	76,463	9,888	87%
Wolverine	65%	1,541	987	36%	37,899	10,318	73%	358,239	110,253	69%
Missouri	80%	178	22	88%	6,199	3,896	37%	65,031	23,384	64%
Pacific Surfliner	85%	7,531	978	87%	175,278	26,537	85%	1,709,887	275,888	84%
Pennsylvanian	72%	883	618	30%	22,931	7,579	67%	258,946	69,960	73%
Piedmont	73%	706	71	90%	23,590	6,590	72%	332,781	80,012	76%
San Joaquins	73%	1,892	1,361	28%	63,040	33,210	47%	726,852	207,580	71%
Vermont	75%	1,274	590	54%	31,727	14,605	54%	378,336	113,178	70%
Long Distance	57%	13,566	7,734	43%	321,007	186,942	42%	3,550,918	1,664,942	53%
Auto Train	57%	754	754	0%	19,544	7,135	63%	222,316	138,338	38%
California Zephyr	45%	1,277	452	65%	28,443	21,387	25%	291,086	127,887	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	664	601	9%	6,593	3,434	48%	80,643	40,449	50%
City Of New Orleans	75%	672	672	0%	14,555	7,685	47%	189,355	55,894	70%
Coast Starlight	65%	981	523	47%	25,612	9,022	65%	311,413	129,768	58%
Crescent	60%	920	282	69%	25,086	8,934	64%	257,154	66,458	74%
Empire Builder	55%	1,131	450	60%	29,415	17,170	42%	284,406	125,673	56%
Floridian	40%	1,498	1,234	18%	36,496	30,279	17%	399,851	294,059	26%
Lake Shore Ltd	70%	1,025	15	99%	26,637	10,044	62%	298,474	82,672	72%
Palmetto	65%	1,329	628	53%	24,089	11,704	51%	292,237	112,820	61%
Silver Meteor	45%	903	854	5%	24,717	16,637	33%	274,103	144,543	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,056	825	22%	25,664	20,637	20%	238,600	147,563	38%
Sunset Ltd	50%	0	0	-	6,538	3,405	48%	78,177	29,201	63%
Texas Eagle	60%	1,356	444	67%	27,618	19,469	30%	275,508	147,121	47%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 24, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	176,625	2,505,980	705	1,888,806	30,949,918	610

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	9,041	731,326	124	100,125	9,059,405	111
INFRASTRUCTURE PLANNED	90	5,627	731,326	77	92,773	9,059,405	102
FLEET RELIABILITY	83	31,443	2,505,980	125	300,323	30,949,918	97
TRAIN OPERATIONS	382	130,514	2,505,980	521	1,395,585	30,949,918	451

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Train 98(25) Miami, FL - Canceled /Shopped Engine

25JUL25: Train 98(25) was canceled in entirety due to shopped engine E/124 for smoking batteries and protect engine E/336 for continued speed sensor issue. Account of no available replacement engines and expected high temperatures in excess of 100 degrees on the route, the decision was made to cancel the train.

Train	Delay	Comment
98 (25)	Canceled	

Train 80(24) Baltimore, MD - Engine Failure

24JUL25: at approximately 7:26P-ET, Train 80(24), E/637, 7 cars, with approximately 171 passengers onboard became disabled at Baltimore, MD/MP95.7 on the Amtrak PW Line. Crew reported main circuit breaker (MCB) had opened and pantograph dropped while coming into the station. There was no headend power for approximately 20 minutes. The weather was a reported 91 degrees. Crew worked with mechanical and an Amtrak Road Foreman to troubleshoot. Train 192(24) was held at Baltimore in case a passenger transfer became necessary. At 7:45P-ET the engineer was able to raise the pantograph and restore HEP. At 7:58P-ET Train 80(24) departed Baltimore with 192(24) shadowing the train.

Train	Delay	Comment
80 (24)	28"	
192 (24)	18"	

Train 76(24) West of High Point, NC - Fatal Trespasser Strike

24JUL25:

At approximately 6:06P-ET Train 76(24) NC1869, 4 cars, NC105 fatally struck a trespasser at MP301.34 on the NS Montview-Salisbury Subdivision on track-2, 2 miles west of Highpoint, NC in Guilford County. The incident occurred on the right of way, not at a crossing, with the trespasser in the gauge and struck by the train. Local authorities responded to the scene for an investigation. There were no injuries to the (85) passengers or crew. Track speed was 76mph. Weather was a reported 89 degrees and partly cloudy. Operating Crew requested and was granted relief. No Damage reported to equipment. An Amtrak Road Foreman responded to the scene. Amtrak Police and EAP advised. The train was released at 806P-ET, advanced to the next crossing and met the local fire department to hose down the engine then was able to proceed to High Point, NC to be re-crewed. Once re-crew was onboard and briefed, Train 79(24) departed High Point at 9:09P-ET.

At 9:00P-ET the medical examiner arrived on the scene and both tracks remained closed to rail traffic for investigation and clean-up. Train 78(24) was held at Lake/MP310.55 and Train 79(24) was held just east of High Point, NC at MP297.8. The tracks were released at 10:38P-ET allowing both trains to resume operation.

National Response Center Number: 1437882

Train	Delay	Comment
76 (24)	3'05"	
78 (24)	2'02"	
79 (24)	2'06"	
79 (24)	21"	KAN- Recrew

Train 68(24) North of Westport, NY - Passenger Train Interference

24JUL25: Train 69(24) held 20.8 miles north of Westport, NY/MP127.8, on the CPRR Canadian Subdivision, at Rockland/MP148.6 meeting Train 68(24).

Train	Delay	Comment
68 (24)	32"	

Train 281(24) East of Utica, NY - Engine Failure

24JUL25: At 2:55PM, Train 281(24), E/707-5 Cars, reported losing main reservoir pressure 12.8 miles east of Utica, NY/MP237.5, on the CSX Mohawk Subdivision, stopping at MP224.7. No leaks were found upon inspection. The crew reset the air compressor and the pressure built back up. During this time, head end power was on to the trainset. At 3:19PM, Train 281(24) was back on the move west. At 5:20PM-ET, Train 281(24) was further delayed 22 miles west of Syracuse, NY at MP/QC309 with same issue. Crew reset the air compressor again to resolve the issue and proceed.

Train	Delay	Comment
281 (24)	35"	
281 (24)	25"	W/SYR

Train 68(24) South of St-Lambert, QC - Heat Orders

24JUL25: Train 68(24) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to heat orders between Southwark/MP42.7 and Rouses Point/MP0.0. Operating speeds were reduced to not exceed 25MPH through the area.

Train	Delay	Comment
68 (24)	43"	

Train 2166(24) Washington, DC - Engine / Car Failure

24JUL25: Train 2166(24), TS#14, was delayed departing Washington Union Station account multiple alarms going off in lead power car 2010. High Speed Rail Mechanical responded and was able to resolve the issue for Train 2166(24) to depart the station.

At Gunpow/MP79.3, on the Amtrak PW Line, Train 2166(24) stopped to inspect due to a reported panel hanging from under the train. After inspection, the panel was confirmed hanging from beneath First Class C/3208. The crew contacted their Road Foreman who granted permission to proceed to 30th Street Station where the train would be met by High Speed Rail Mechanical. 2166(24) was back on the move north for a few miles then set off a dragging equipment detector. The train stopped on the No. 2 track in between Wood/MP75.3 and Bush/MP71.6 with protection across No. 3 track. After inspection, it was found that the panel was ripped off. Train 2166(24) then proceeded north operating not exceeding 125MPH.

Train 184(24) received a temporary speed restriction to operate restricted speed from MP74.0 to Wood on the No. 2 track to be on the look out for the panel. Train 184(24)'s crew reported the panel was broken into small pieced at the Edgewood Station/MP75.1 in the gauge. At that point the speed restriction was lifted and Train 184(24) proceeded north at track speed. Train 94(24) stopped short of Edgewood to remove the pieces from the railroad.

Train	Delay	Comment
2166 (24)	21"	WAS
125 (24)	05"	
184 (24)	52"	
131 (24)	09"	
94 (24)	13"	
2168 (24)	18"	
95 (24)	17"	
2166 (24)	44"	Panel

CSX Heat Orders

24JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Grand Rapids, Monon, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, North End, Old Main Line, Portland, RF&P, Rochester, and Syracuse Terminal.

Train	Delay	Comment
48 (23)	16"	
41 (23)	30"	
40 (23)	27"	
53 (24)	13"	
63 (24)	31"	
64 (24)	44"	
79 (24)	25"	
80 (24)	17"	
90 (24)	25"	
93 (24)	03"	
95 (24)	17"	
125 (24)	26"	
138 (24)	07"	
141 (25)	17"	
186 (24)	10"	
281 (24)	19"	
283 (24)	16"	
683 (24)	05"	
684 (24)	03"	
685 (24)	07"	
686 (24)	08"	
688 (24)	04"	
687 (24)	05"	

Train 80(24) Raleigh, NC - Programmed Move

24JUL25: Train 80(24) was delayed at Raleigh, NC/MP80.9, on the NSRR Goldsboro-Greensboro Subdivision, completing a programmed move adding E/38 and E/33 to the consist.

Train	Delay	Comment
80 (24)	41"	

Train 19(23) North of Spartanburg, SC - Passenger Train Interference

24JUL25: Train 19(23) was delayed 15.1 miles north of Spartanburg, SC/MP452.6, on the NSRR Salisbury-Greenville Subdivision, at Thicketty/MP437.5 meeting Train 20(23).

Train	Delay	Comment
19 (23)	35"	

NEC Service Adjustments - Impending Extreme Temperatures

24JUL25: Due to the impending forecast of extreme temperatures over 100 degrees and storms along the Northeast Corridor for Friday July 25,2025, the following service adjustments have been made:

- Trains 112(25), 192(25), 178(25), 133(25), 131(25) and 173(25) are cancelled in their entirety with no alternate.
- Trains 2154(25), 2155(25), 2173(25), and 2172(25) are cancelled in their entirety with no alternate.

Train	Delay	Comment
112(25)	cancelled	
192(25)	cancelled	
178(25)	cancelled	
131(25)	cancelled	
133(25)	cancelled	
173(25)	cancelled	
2154(25)	cancelled	
2173(25)	cancelled	
2155(25)	cancelled	
2172(25)	cancelled	

Amtrak NHB Line - Conn River Bridge Defect

24JUL25: At 8:00AM, the New London Dispatcher reported that the Connecticut River Bridge at MP106.8 was stuck in the open position, unable to close. Located 1.7 miles east of the Old Saybrook, CT station/MP105.1, on the Amtrak NHB Line. B&B Potter responded to the location to troubleshoot. During this time, Trains 2155(24), 95(24), 66(23), and CT 1606 were all delayed. At 9:20AM, the bridge was reported seated and locked allowing all traffic to resume.

Train	Delay	Comment
95(24)	1'21"	
66(23)	1'26"	
CT 1606	34"	
2155(24)	24"	
93(24)	04"	

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District - Trackwork East of Solana Beach, CA
19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:

from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

- Sunday May 19 - Tuesday May 21
- Sunday June 02- Tuesday June 04
- Sunday June 16 - Tuesday June 18
- Sunday June 23 - no extended window account Padres game.
- Sunday June 30 - Tuesday July 2
- Sunday July 7 - Tuesday July 9
- Sunday July 14 - Tuesday July 16
- Sunday July 21 - Tuesday July 23
- Sunday July 28 - Tuesday July 30
- Sunday August 4 - Tuesday August 6
- Sunday August 11 - no extended window account Padres game
- Sunday August 18th - Tuesday 20th
- Sunday August 25 - Tuesday August 27
- Sunday September 8 - Tuesday September 10.
- Sunday September 15 - Monday September 16
- Sunday September 22 - Tuesday September 24.
- Sunday October 27 - Tuesday October 29.
- Sunday November 3 - Tuesday November 5.

Sunday December 8-Tuesday December 10.
Sunday December 15-Tuesday December 17.
2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)
Sunday May 20 - Tuesday May 22

During the project the following service adjustments will apply:
Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.
Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.
Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.
Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.
WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Train 41(24) Chicago, IL - Initial Terminal Delay

25JUL25: Train 41(24) was delayed 3 hours and 45 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(22). Train 40(22) arrived in Chicago at 258pm; 6 hours and 13 minutes late due to a 25-minute initial terminal delay in Miami, Florida, 1 hour and 57 minutes in Gaston, South Carolina for a vehicle stuck on the tracks, 1 hour and 36 minutes for freight train interference, 51 minutes in Jarratt, Virginia for an injured or sick passenger, 33 minutes for commuter train interference, 24 minutes between Selma, North Carolina and Rocky Mount, North Carolina for an efficiency test involving Amtrak officers, and 23 minutes in Pittsburgh, Pennsylvania fueling the locomotives. Equipment set to the yard for servicing and inspection at 416pm. At 508pm, lead engine 204 was bad ordered for wheels with engine 147 off inbound 6(22) designated as the replacement. Upon Train 6(22) setting to the yard at 528pm, the fuel foreman reported engine 147 was not equipped with Amtrak cab signals. At 538pm, the replacement locomotive was changed to engine 78 off inbound 6(22) which needed to wye. Engine 78 wyeed and tied on at 758pm. Train 41(24) was released by mechanical at 925pm and set in the station at 942pm with 240 passengers to board. Train 41(24) departed Chicago at 1025pm; 3 hours and 45 minutes late. An additional 12-minute delay was incurred wyeing the train set on departure.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
41(24)	3'45"	

Train 591(24) West of San Diego Old Town , CA – Locomotive Shutdown – Loss HEP

24JUL25: Train 591(24) -operating with locomotive CDTX/2113 - was delayed shortly after departing San Diego Old Town station when the locomotive shut down losing all tractive effort and Head End Power. The train stopped at MP 258.5, San Diego Subdivision, San Diego Northern Railroad. There were 236 passengers on board. Outside temperature 68 °F, cloudy. The crew were required to shut down and restart the locomotive which restored all power, allowing the service to resume.

Locomotive CDTX/2113 shut down a second time at MP 252.5, San Diego Subdivision, the crew again performed a cold restart to restore power.

Cause: Pending

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
591(24)	35"	MP 252.5 - Locomotive Shut Down
591(24)	10"	MP 258.5 - Locomotive Shut Down

Train 718(24) & 715(24) West of Stockton, CA – Freight Train Interference

24JUL25: Train 718(24) & 715(24) were delayed 14 miles West of Stockton. The crew of BNSF Freight Train RICBAR1 - 23 were required to inspect their train after activating a trackside detector on single main track at Oakley MP 1144.5 Stockton Subdivision of the BNSF Railway. The detector measures for hot wheel bearings, the freight crew reported a bearing integrity failure on one of the freight cars. This required further inspection by a qualified technician.

The attending BNSF technician authorized freight train RICBAR1-23 to advance - at walking pace - to Orwood siding to remove affected rail car.

Due to the crew on 715(24) running out of hours of service, they coupled with train 719(24) and they continued on as a combo set to Oakland, CA. Train 715(24) coupled to train 719(24) while waiting for the freight to clear and there was no delay to the train due to combining the 2 train sets.

WBS#: B.TR.100150.5922

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
715(24)	4'22"	
719(24)	1'28"	
718(24)	4'12"	

Train 59(24) Chicago, IL - System

25JUL25: Train 59(24) was delayed 30 minutes departing Chicago, Illinois holding for crew rest at 818pm due to the late arrival of inbound 58(23). Train 58(23) arrived in Chicago at 1206pm; 2 hours and 51 minutes late due to 1 hour and 44 minutes of freight train interference, 1 hour and 1-minute of heat orders, 37 minutes for speed restrictions, and 22 minutes in Jackson, Mississippi holding for crew rest. After servicing in the yard, equipment set in the station and was pre-boarded of all 228 passengers prior to the road crew going back on-duty at 918pm. Train 59(24) departed Chicago at 835pm; 30 minutes late.

Train	Delay	Comment
59(24)	30"	

Train 4(24) East of Fullerton CA - Police Activity

24JUL25: Train 4(24) was delayed 14 miles east of Fullerton while local police were searching for a near the tracks. The train was delayed at east Esperaza MP 41.2, San Bernardino Subdivision, BNSF Railway. Once the searching personnel had cleared the area tracks were re-opened and train 4(24) continued to Riverside. Amtrak Police Notified

Train	Delay	Comment
4(24)	1'06"	

Train 714(24) East of Madera Acres, CA - Freight Train Interference

24JUL25: Train 714(24) was delayed following an unidentified BNSF freight train east of Madera Acres. The freight train was able to enter the siding at east Madera 1018.3, Stockton Subdivision of the BNSF Railway. This cleared the track ahead for train 714(24) to proceed at track speed.

Train	Delay	Comment
714(24)	30"	

Train 784(24) West of Northridge, CA , - Locomotive Shut Down- Loss of Head End Power

24JUL25: At 3:58PM-PT, train 784(24) was delayed departing Northridge station when locomotive CDTX/2116 shut down with no Head End Power or tractive power. Northridge station is located at MP 449.3, Ventura Subdivision, Metrolink Railroad. There were 246 passengers on board. Ambient temperature 86°F, sunny.

The crew worked to resolve the problem - after shutting down the locomotive and performing a restart procedure, power was restored. After re-initializing Positive Train Control, the train was able to depart Northridge after 32 mins delay.

The fault returned at Van Nuys station wen locomotive CDTX/2116 shut down when attempting to depart. After diagnosing the fault - by telephone- with technicians, it was determined the fault would return each time the locomotive attempted to restart from stationary. To prevent recurrences of the issue the following plan was implemented:

Train 784(24) Equipment was terminated at Van Nuys. All passengers transferred to waiting Metrolink train 120 for Los Angeles. Passengers travelling stations to San Diego were advised to transfer to train 586(24) on arrival. Passengers for 784(24) at Los Angeles were advised to use train 586(24).

Train 593(24) - Train 593(24) Cancelled entirely with passengers advised to board train 595(24).

Service Recovery: Train 784(24) passengers were offered complimentary bottled water, ice, hot beverages and snack packs.

Mutual Aid: Tickets for 784(24) valid on Metrolink train 120.

Cause: Pending

WBS#: B.TR.100150.5921

Train	Delay	Comment
784(24)	Terminates Van Nuys	Passengers to Metrolink 120
593(24)	Cancelled	Passengers to 595(24)

Train 352(24) West of Battle Creek, MI - Signal

25JUL25: Train 352(24) was delayed 5 miles west of Battle Creek, MI, on Amtrak Michigan Line subdivision, due to power switch failure at Control Point 124. 352(24) held while a maintainer worked to fix it. The maintainer wedged and clamped the switch and 352(24) was able to proceed.

Train	Delay	Comment
352(24)	1'16"	

Train 22(24) Marshall, TX - Freight Train Interference

25JUL25: Train 22(24) was delayed operating between Marshall, TX, and Texarkana, TX, on the UP Little Rock subdivision, due to following UP6005. Once the freight cleared and a route was made available, train 22(24) was able to resume normal speed.

Train	Delay	Comment
22(24)	1'03"	

Train 6(24) East of Truckee, CA - Debris Strike – Rocks

24JUL25: Train 6(24) operating with camera equipped locomotive AMTK 15 struck rocks placed on the tracks 8 miles east of Truckee. This caused the train to stop at MP 214.4 East Truckee on the Roseville Subdivision of the Union Pacific Railroad. No injuries reported to (156) passengers or crew. Crew inspected train, reporting damage to wheels of locomotive AMTK/15. The crew contacted Reno Road Foreman - after reviewing pictures of the damage authorized the train to proceed to Reno without restriction. The train was inspected in Reno with no condemnable damage found. Amtrak Police Notified

Train	Delay	Comment
6(24)	33"	
6(33)	06"	Reno - Wheel Inspection

Train 5(22) at Roseville, CA – Passenger Removal – Police Request

24JUL25: Train 5(22) was delayed departing Roseville station while police searched for a person of interest on board. Officers located and removed passenger Noah Rudat (PNR# 43771B) - travelling from Denver to Sacramento for outstanding warrants. Amtrak Police Notified.

Train	Delay	Comment
5(22)	12"	

Train 59(23) South of McComb, MS - Passenger Train Interference

24JUL25: Train 59(23) was delayed at Osyka / MP 825.5 on the Canadian National McComb Subdivision, 19 miles south of the McComb, MS station, meeting Train 58(24).

Train	Delay	Comment
59(23)	35"	

Train 714(24) East of Antioch, CA - Passenger Train Interference

24JUL25: - Train 714(24) was delayed at east Orwood MP 1136.4 16 miles east of Antioch at while waiting for Amtrak train 713(24) to clear the track ahead. Once the track was cleared, train 714(24) continued to Stockton.

Train	Delay	Comment
714(24)	33"	

Train 7/27(24) Chicago, IL - Car Failure

24JUL25: Train 7/27(24) was delayed departing the Chicago, IL Union station due to late release of cars. The equipment was released from mechanical at 2:45 p.m. (CDT), 20 minutes prior to the departure time.

Train	Delay	Comment
7/27(24)	37"	

Train 6(23) West of Green River, UT - Routing

24JUL25: Train 6(23) was delayed at Green River / MP 555.8 on the Union Pacific Green River Subdivision, just west of the Green River, UT station, waiting on authority from the Union Pacific Dispatcher.

Train	Delay	Comment
6(23)	39"	

Surrounding Chicago, IL - Severe Weather

24JUL25: High wind and flash flood warnings reported surrounding Chicago, IL. There were reports of winds in excess of 70 mph and rainfall of a rate of 1.5 inches per hour. Trains operating through the area were instructed to operate at reduced speed.

Train	Delay	Comment
5 (24)	34"	Flash Floods
21 (24)	35"	
4 (22)	20"	
6 (22)	1'21"	
3 (24)	54"	CHI-NPV
3 (24)	2'28"	E/KCY

Train 5(24) Chicago, IL - Car Failure

24JUL25: Train 5(24) was delayed departing the Chicago, IL Union Station due to the HVAC failure on the A-End of Car 31044. Mechanical responded but was unable to repair. The decision was made to allow the train to continue without the HVAC on the A-End.

Train	Delay	Comment
5 (24)	1'53"	

Train 21(24) Chicago, IL - Engine Failure

24JUL25: Train 21(24) was delayed departing the Chicago, IL Union Station due to head end power with Locomotive 53 and Locomotive 30. Mechanical responded to the station to rectify the issue.

Train	Delay	Comment
21 (24)	1'03"	

Train 14(23), North of Klamath Falls, OR - Freight Train Interference

24JUL25: Train 14(23) was delayed 28 miles after departing Klamath Falls, at Chiloquin, MP 456.80 Cascades Subdivision of the Union Pacific Railroad. This was to allow for Union Pacific train UPRR/8961 to pass on the mainline. Once the freight train had cleared, 14(23) continued to Chemult, OR.

Train	Delay	Comment
14 (23)	31"	

Train 712(24) Originated at Emeryville, CA - Late Release/Servicing and Repairs

24JUL25: Train 712(24) originated at Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of servicing equipment after being swapped with Train 714(24) as well as battery charger issues on assigned locomotives E/C2108 and E/C2101. Train 712(24) departed Emeryville at 11:12AM-PT. Passengers boarding at Oakland were reaccommodated onto Train 528(24) to Emeryville to connect with 712(24).

Work Element WBS # B.TR.100150.5920

WBS#: B.TR.100150.5920

Train	Delay	Comment
712(24)	1'26"	Originated at EMY
703(24)	07"	BFD - Equipment Turn from 712(24)

Train 5(23) East of Fraser-Winter Park, CO - Engine Failure

24JUL25: Train 5(23), operating with Locomotive 39, Locomotive 55 and 10 cars, stopped at MP 36.4 on the Union Pacific Tunnel Subdivision, 26 miles east of the Fraser - Winter Park, CO station, due to a ground fault. The crew was able to clear the fault after cutting out traction motor #4 on Locomotive 39.

Train	Delay	Comment
5 (23)	42"	

Train 350(24) East of Battle Creek, MI - Passenger Train Interference

24JUL25: Train 350(24) was delayed at CP 96 / MP 96.2 on the Michigan Department of Transportation Michigan Line, 24 miles east of the Battle Creek, MI station, meeting Train 353(24).

Train	Delay	Comment
350 (24)	37"	

Train 5(22) West of Winnemucca, NV - Struck Animal

24JUL25: Train 5(22) was delayed at MP 369.0/UPRR Nevada Subdivision, 46.1 miles west of Winnemucca, as a result of striking a cow on the tracks. There were no injuries to passengers (174) or crew. Some air hoses were found to be disconnected as a result of the strike. The crew reconnected the hoses and departed following a successful air test.

Train	Delay	Comment
5 (22)	37"	

Maintenance of Way Highlights

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Train 40(23) North of Rocky Mount, NC - M of W Work

24JUL25: Train 40(23) was delayed 8.6 miles north of Rocky Mount, NC/MP119.6, on the CSX North End Subdivision, due to Maintenance of Way overstay. A frog replacement was taking place ahead and taking longer than anticipated. Once complete, Train 40(23) was released to continue north.

Train	Delay	Comment
40 (23)	56"	

Train 55(24) South of St. Albans, VT - M of W Work

24JUL25: Train 55(24) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area.

Train	Delay	Comment
55 (24)	37"	

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/24/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	36	87.8%	6,931	828	88.1%	85,638	8,497	90.1%
Central Division	91.5%	66	15	77.3%	1,576	182	88.5%	19,605	1,922	90.2%
Northeast Division	95.0%	92	8	91.3%	2,183	294	86.5%	28,138	3,057	89.1%
Southeast Division	94.5%	68	3	95.6%	1,532	179	88.3%	18,961	1,893	90.0%
Southwest Division	90.5%	69	10	85.5%	1,640	173	89.5%	18,934	1,625	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/24/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	36	87.8%	6,931	828	88.1%	85,638	8,497	90.1%
Central Division	91.5%	66	15	77.3%	1,576	182	88.5%	19,605	1,922	90.2%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	52	3	94.2%	595	17	97.1%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	27	10	63.0%	636	106	83.3%	7,912	991	87.5%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	1	50.0%	48	2	95.8%	572	21	96.3%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	23	0	100.0%	296	4	98.6%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	47	2	95.7%	576	39	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	1	83.3%	140	8	94.3%	1,703	96	94.4%
MSP	95.0%	1	0	100.0%	24	2	91.7%	285	14	95.1%
PDX	78.0%	5	1	80.0%	116	10	91.4%	1,428	162	88.7%
PNT	94.0%	3	0	100.0%	71	2	97.2%	818	58	92.9%
PTH	96.0%	1	0	100.0%	24	0	100.0%	295	11	96.3%
QCY	94.0%	2	0	100.0%	46	0	100.0%	576	18	96.9%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	2	75.0%	193	34	82.4%	2,320	334	85.6%
SPK	92.0%	1	0	100.0%	22	1	95.5%	293	14	95.2%
STL	96.0%	3	0	100.0%	82	8	90.2%	1,159	61	94.7%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	48	0	100.0%	569	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	92	8	91.3%	2,183	294	86.5%	28,138	3,057	89.1%
ALB	96.0%	6	0	100.0%	144	5	96.5%	1,993	127	93.6%
BON	94.5%	5	0	100.0%	118	8	93.2%	1,382	91	93.4%
BOS	97.0%	16	0	100.0%	426	46	89.2%	5,543	512	90.8%
BRK	97.0%	2	0	100.0%	82	2	97.6%	1,343	68	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	1	0.0%	24	5	79.2%	295	22	92.5%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	41	2	95.1%	568	54	90.5%
HFD	-	2	0	100.0%	34	4	88.2%	180	17	90.6%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/24/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	36	87.8%	6,931	828	88.1%	85,638	8,497	90.1%
Northeast Division	95.0%	92	8	91.3%	2,183	294	86.5%	28,138	3,057	89.1%
MTR	97.0%	1	0	100.0%	24	3	87.5%	295	29	90.2%
NFL	97.0%	2	0	100.0%	48	1	97.9%	594	24	96.0%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	111	18	83.8%	1,518	152	90.0%
NYP	94.5%	40	7	82.5%	929	174	81.3%	11,922	1,812	84.8%
POR	-	3	0	100.0%	33	10	69.7%	33	10	69.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	22	4	81.8%	293	9	96.9%
SPG	95.5%	5	0	100.0%	116	9	92.2%	1,812	85	95.3%
TWO	96.0%	1	0	100.0%	24	0	100.0%	294	11	96.3%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	68	3	95.6%	1,532	179	88.3%	18,961	1,893	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	117	9	92.3%	1,471	94	93.6%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	270	12	95.6%	3,215	100	96.9%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	24	5	79.2%	291	93	68.0%
MIA	90.0%	2	0	100.0%	46	8	82.6%	571	55	90.4%
NFK	94.5%	3	0	100.0%	68	13	80.9%	818	67	91.8%
NOL	92.0%	2	0	100.0%	53	3	94.3%	660	46	93.0%
NPN	96.0%	2	0	100.0%	48	4	91.7%	567	21	96.3%
PGH	92.0%	1	0	100.0%	24	3	87.5%	296	17	94.3%
PHL	97.0%	5	0	100.0%	103	24	76.7%	1,269	181	85.7%
RGH	97.0%	4	0	100.0%	88	3	96.6%	1,191	37	96.9%
RNK	94.0%	2	0	100.0%	43	2	95.3%	560	64	88.6%
RVM	90.0%	1	0	100.0%	24	1	95.8%	288	34	88.2%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	22	1	95.5%	278	11	96.0%
SFA	83.0%	1	0	100.0%	24	2	91.7%	291	80	72.5%
WAS	94.5%	25	3	88.0%	568	79	86.1%	7,042	960	86.4%
Southwest Division	90.5%	69	10	85.5%	1,640	173	89.5%	18,934	1,625	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	24	0	100.0%	297	7	97.6%
BFD	90.0%	5	2	60.0%	141	17	87.9%	1,764	153	91.3%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	24	19	20.8%	304	95	68.8%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	23	2	91.3%	329	42	87.2%
FUL	-	-	-	-	-	-	-	12	5	58.3%
GLE	-	-	-	-	-	-	-	4	4	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/24/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/24/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	36	87.8%	6,931	828	88.1%	85,638	8,497	90.1%
Southwest Division	90.5%	69	10	85.5%	1,640	173	89.5%	18,934	1,625	91.4%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	72	3	95.8%	868	63	92.7%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	3	66.7%	226	27	88.1%	2,285	318	86.1%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	21	0	100.0%	292	6	97.9%
OKJ	91.0%	12	2	83.3%	266	46	82.7%	3,119	296	90.5%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	1	92.9%	315	25	92.1%	3,546	150	95.8%
SAN	90.0%	12	1	91.7%	282	21	92.6%	2,704	239	91.2%
SAS	85.0%	1	0	100.0%	24	6	75.0%	293	41	86.0%
SJC	95.0%	7	0	100.0%	167	6	96.4%	1,907	72	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	48	0	100.0%	581	27	95.4%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	6	0	100.0%	53	11	79.2%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	47	24	7	70.8%	291	57	80.4%	24	19	20.8%	287	160	44.3%
4	167	24	5	79.2%	292	70	76.0%	24	20	16.7%	291	151	48.1%
5		24	12	50.0%	294	51	82.7%	23	16	30.4%	291	99	66.0%
6	85	24	19	20.8%	294	88	70.1%	24	20	16.7%	293	102	65.2%
7		24	8	66.7%	288	44	84.7%	24	7	70.8%	283	74	73.9%
8	65	24	16	33.3%	289	108	62.6%	24	18	25.0%	287	139	51.6%
11		24	2	91.7%	296	46	84.5%	24	4	83.3%	289	65	77.5%
14		24	8	66.7%	297	90	69.7%	24	9	62.5%	295	129	56.3%
19		24	0	100.0%	297	33	88.9%	24	8	66.7%	296	57	80.7%
20		24	1	95.8%	297	14	95.3%	24	6	75.0%	296	48	83.8%
21		24	2	91.7%	296	36	87.8%	24	7	70.8%	290	90	69.0%
22		24	6	75.0%	293	43	85.3%	24	19	20.8%	292	127	56.5%
27		22	4	81.8%	284	21	92.6%	21	7	66.7%	274	93	66.1%
28		21	4	81.0%	277	69	75.1%	21	4	81.0%	276	76	72.5%
40	373	24	5	79.2%	254	38	85.0%	23	18	21.7%	249	157	36.9%
41	40	22	15	31.8%	251	110	56.2%	22	20	9.1%	247	197	20.2%
42	48	24	3	87.5%	297	18	93.9%	24	8	66.7%	297	82	72.4%
43		24	2	91.7%	297	25	91.6%	24	7	70.8%	297	67	77.4%
48		24	6	75.0%	296	54	81.8%	24	4	83.3%	296	45	84.8%
49		24	10	58.3%	297	60	79.8%	24	7	70.8%	297	54	81.8%
51	47	10	1	90.0%	126	23	81.7%	10	3	70.0%	120	41	65.8%
52		24	2	91.7%	291	80	72.5%	24	6	75.0%	291	153	47.4%
53		24	5	79.2%	291	93	68.0%	24	6	75.0%	291	146	49.8%
55	77	17	3	82.4%	206	9	95.6%	17	10	41.2%	206	49	76.2%
56	50	17	3	82.4%	206	36	82.5%	17	14	17.6%	205	57	72.2%
58	171	24	2	91.7%	289	23	92.0%	24	8	66.7%	286	61	78.7%
59	151	24	10	58.3%	288	62	78.5%	23	10	56.5%	284	37	87.0%
63	97	24	15	37.5%	297	61	79.5%	24	21	12.5%	297	153	48.5%
64		24	0	100.0%	297	11	96.3%	24	4	83.3%	297	72	75.8%
66	89	24	3	87.5%	295	56	81.0%	24	3	87.5%	293	39	86.7%
67	17	17	1	94.1%	205	18	91.2%	17	5	70.6%	203	44	78.3%
68	137	24	3	87.5%	297	29	90.2%	24	18	25.0%	297	122	58.9%
69		24	2	91.7%	297	22	92.6%	23	8	65.2%	292	35	88.0%
71		23	2	91.3%	296	7	97.6%	23	8	65.2%	294	66	77.6%
72		24	3	87.5%	297	22	92.6%	24	8	66.7%	295	75	74.6%
73		24	4	83.3%	297	16	94.6%	24	9	62.5%	295	144	51.2%
74		24	1	95.8%	293	21	92.8%	24	9	62.5%	291	99	66.0%
75		24	3	87.5%	295	8	97.3%	24	11	54.2%	293	118	59.7%
76	193	24	4	83.3%	293	20	93.2%	23	15	34.8%	291	128	56.0%
77		24	2	91.7%	294	12	95.9%	24	11	54.2%	292	131	55.1%
78	135	24	0	100.0%	295	10	96.6%	23	7	69.6%	294	71	75.9%
79	161	24	5	79.2%	297	40	86.5%	22	8	63.6%	294	106	63.9%

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80	133	24	3	87.5%	297	24	91.9%	24	15	37.5%	297	88	70.4%
84		17	0	100.0%	205	8	96.1%	17	6	64.7%	204	75	63.2%
85	29	17	0	100.0%	203	16	92.1%	17	12	29.4%	202	138	31.7%
86	28	17	1	94.1%	203	23	88.7%	17	15	11.8%	203	140	31.0%
89	50	24	2	91.7%	296	36	87.8%	24	12	50.0%	294	110	62.6%
90		24	1	95.8%	296	12	95.9%	23	9	60.9%	291	73	74.9%
93		17	0	100.0%	206	14	93.2%	17	10	41.2%	205	96	53.2%
94	30	17	6	64.7%	206	20	90.3%	17	10	41.2%	205	76	62.9%
95	139	17	0	100.0%	206	5	97.6%	17	8	52.9%	206	89	56.8%
97		24	17	29.2%	293	138	52.9%	24	12	50.0%	292	96	67.1%
98		24	4	83.3%	293	19	93.5%	24	15	37.5%	293	151	48.5%
110		17	6	64.7%	204	39	80.9%	17	4	76.5%	202	43	78.7%
111		17	4	76.5%	203	51	74.9%	17	2	88.2%	201	32	84.1%
112		17	3	82.4%	198	38	80.8%	17	3	82.4%	196	24	87.8%
114		17	3	82.4%	202	54	73.3%	17	3	82.4%	198	30	84.8%
119		17	1	94.1%	200	39	80.5%	17	3	82.4%	197	30	84.8%
125	41	17	1	94.1%	206	10	95.1%	17	10	41.2%	206	117	43.2%
129		17	4	76.5%	204	42	79.4%	17	7	58.8%	203	45	77.8%
130		17	1	94.1%	200	20	90.0%	17	1	94.1%	197	22	88.8%
131		17	2	88.2%	197	34	82.7%	17	2	88.2%	195	28	85.6%
133	28	17	7	58.8%	204	75	63.2%	17	14	17.6%	204	107	47.5%
134		17	0	100.0%	205	15	92.7%	17	8	52.9%	205	99	51.7%
136		17	1	94.1%	206	40	80.6%	17	4	76.5%	204	42	79.4%
137		17	5	70.6%	206	26	87.4%	17	7	58.8%	206	82	60.2%
138		17	3	82.4%	205	24	88.3%	17	8	52.9%	205	51	75.1%
141	27	17	0	100.0%	206	3	98.5%	17	9	47.1%	206	99	51.9%
148		17	1	94.1%	206	18	91.3%	17	4	76.5%	206	43	79.1%
151	30	24	5	79.2%	294	37	87.4%	24	7	70.8%	293	100	65.9%
170		17	0	100.0%	205	12	94.1%	17	6	64.7%	205	51	75.1%
171	19	17	3	82.4%	206	10	95.1%	17	10	41.2%	206	104	49.5%
172	24	17	2	88.2%	205	15	92.7%	17	8	52.9%	203	67	67.0%
173		17	0	100.0%	206	26	87.4%	17	5	70.6%	206	68	67.0%
174		17	2	88.2%	206	6	97.1%	17	5	70.6%	205	47	77.1%
175		17	6	64.7%	205	36	82.4%	17	9	47.1%	204	75	63.2%
176		17	4	76.5%	206	20	90.3%	17	1	94.1%	205	25	87.8%
177		17	3	82.4%	206	29	85.9%	17	6	64.7%	205	43	79.0%
178		17	1	94.1%	206	30	85.4%	17	8	52.9%	205	44	78.5%
179		17	3	82.4%	204	15	92.6%	17	10	41.2%	204	71	65.2%
181		17	6	64.7%	201	40	80.1%	17	1	94.1%	197	27	86.3%
182		17	2	88.2%	201	48	76.1%	17	9	47.1%	200	54	73.0%
183	17	17	3	82.4%	206	27	86.9%	17	3	82.4%	206	27	86.9%
184	48	17	6	64.7%	206	30	85.4%	17	3	82.4%	205	26	87.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
185		17	2	88.2%	206	34	83.5%	17	3	82.4%	206	27	86.9%
186		17	2	88.2%	203	13	93.6%	17	7	58.8%	201	57	71.6%
190		17	7	58.8%	206	42	79.6%	17	7	58.8%	206	52	74.8%
192		17	3	82.4%	102	17	83.3%	17	4	76.5%	100	13	87.0%
193		17	5	70.6%	204	35	82.8%	17	6	64.7%	203	72	64.5%
196		17	1	94.1%	206	70	66.0%	17	3	82.4%	203	59	70.9%
197		17	8	52.9%	205	52	74.6%	17	4	76.5%	204	56	72.5%
232		24	1	95.8%	285	10	96.5%	24	1	95.8%	285	22	92.3%
233		21	5	76.2%	292	85	70.9%	21	10	52.4%	291	101	65.3%
234		24	1	95.8%	285	7	97.5%	24	2	91.7%	285	22	92.3%
236		24	0	100.0%	285	5	98.2%	24	3	87.5%	284	47	83.5%
237		21	0	100.0%	280	28	90.0%	21	2	90.5%	278	32	88.5%
239		24	5	79.2%	284	30	89.4%	24	7	70.8%	284	23	91.9%
240		24	0	100.0%	289	24	91.7%	24	5	79.2%	288	27	90.6%
241		24	4	83.3%	297	37	87.5%	23	9	60.9%	296	45	84.8%
243		17	7	58.8%	206	39	81.1%	17	7	58.8%	205	29	85.9%
244		21	1	95.2%	292	8	97.3%	21	10	52.4%	292	49	83.2%
280		24	0	100.0%	296	11	96.3%	24	2	91.7%	296	53	82.1%
281	53	24	2	91.7%	297	60	79.8%	23	6	73.9%	295	61	79.3%
283		24	8	66.7%	297	65	78.1%	24	10	58.3%	296	63	78.7%
284		24	1	95.8%	297	13	95.6%	24	1	95.8%	296	59	80.1%
290	25	24	5	79.2%	297	24	91.9%	23	19	17.4%	295	72	75.6%
291	94	24	10	58.3%	297	48	83.8%	24	19	20.8%	296	65	78.0%
300	47	22	1	95.5%	286	8	97.2%	22	8	63.6%	284	71	75.0%
302		23	3	87.0%	291	21	92.8%	23	10	56.5%	288	100	65.3%
305		24	3	87.5%	291	22	92.4%	24	17	29.2%	290	113	61.0%
307		23	2	91.3%	290	38	86.9%	22	11	50.0%	287	106	63.1%
311		23	3	87.0%	287	18	93.7%	23	17	26.1%	283	113	60.1%
316		23	1	95.7%	285	19	93.3%	23	16	30.4%	283	105	62.9%
318	92	24	1	95.8%	293	20	93.2%	24	16	33.3%	289	163	43.6%
319	55	24	1	95.8%	295	19	93.6%	24	19	20.8%	290	180	37.9%
329		17	3	82.4%	207	19	90.8%	17	1	94.1%	207	17	91.8%
330		20	1	95.0%	240	5	97.9%	20	1	95.0%	239	15	93.7%
331		24	1	95.8%	288	20	93.1%	24	2	91.7%	284	27	90.5%
332		24	1	95.8%	293	17	94.2%	24	3	87.5%	292	44	84.9%
334	15	24	0	100.0%	293	9	96.9%	24	4	83.3%	288	72	75.0%
335		24	3	87.5%	296	32	89.2%	24	6	75.0%	287	62	78.4%
336	16	24	1	95.8%	282	7	97.5%	24	7	70.8%	281	82	70.8%
337		24	2	91.7%	285	17	94.0%	24	6	75.0%	284	63	77.8%
338		24	4	83.3%	295	39	86.8%	24	8	66.7%	285	123	56.8%
339		24	1	95.8%	295	43	85.4%	24	3	87.5%	293	51	82.6%
341		23	10	56.5%	280	55	80.4%	23	11	52.2%	274	58	78.8%

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
342		24	1	95.8%	296	19	93.6%	24	2	91.7%	295	45	84.7%
350	34	24	2	91.7%	256	27	89.5%	24	17	29.2%	253	130	48.6%
351		24	0	100.0%	285	24	91.6%	24	5	79.2%	284	78	72.5%
352	102	24	3	87.5%	290	27	90.7%	24	11	54.2%	285	82	71.2%
353	23	24	0	100.0%	249	6	97.6%	24	2	91.7%	244	37	84.8%
354		23	1	95.7%	289	27	90.7%	23	4	82.6%	286	102	64.3%
355	29	23	2	91.3%	289	32	88.9%	23	6	73.9%	285	74	74.0%
364	46	24	2	91.7%	295	56	81.0%	24	6	75.0%	294	80	72.8%
365		24	0	100.0%	295	11	96.3%	24	8	66.7%	294	86	70.7%
370	38	23	3	87.0%	296	13	95.6%	22	5	77.3%	295	38	87.1%
371		23	0	100.0%	296	4	98.6%	23	3	87.0%	296	28	90.5%
380	16	24	1	95.8%	294	11	96.3%	24	2	91.7%	294	28	90.5%
381	19	24	2	91.7%	294	8	97.3%	24	7	70.8%	293	30	89.8%
382		24	1	95.8%	293	11	96.2%	24	6	75.0%	293	39	86.7%
383	46	24	0	100.0%	295	29	90.2%	24	10	58.3%	294	69	76.5%
390		24	3	87.5%	292	13	95.5%	24	7	70.8%	290	43	85.2%
391		24	1	95.8%	295	7	97.6%	23	5	78.3%	292	54	81.5%
392		23	0	100.0%	294	8	97.3%	23	6	73.9%	291	32	89.0%
393		24	1	95.8%	294	13	95.6%	24	9	62.5%	291	42	85.6%
417	16	17	2	88.2%	202	32	84.2%	16	2	87.5%	199	30	84.9%
425		14	0	100.0%	187	5	97.3%	14	0	100.0%	187	7	96.3%
470		18	2	88.9%	208	15	92.8%	16	2	87.5%	203	28	86.2%
471		17	2	88.2%	206	14	93.2%	16	0	100.0%	204	11	94.6%
473		17	2	88.2%	206	7	96.6%	16	1	93.8%	205	3	98.5%
474	17	17	2	88.2%	204	30	85.3%	16	7	56.3%	200	61	69.5%
475		14	2	85.7%	202	8	96.0%	14	3	78.6%	199	19	90.5%
478		15	1	93.3%	204	21	89.7%	14	1	92.9%	202	20	90.1%
479		17	1	94.1%	206	30	85.4%	17	2	88.2%	205	24	88.3%
486		17	0	100.0%	208	16	92.3%	17	8	52.9%	206	72	65.0%
494	24	17	6	64.7%	211	33	84.4%	17	11	35.3%	205	61	70.2%
495		17	1	94.1%	203	3	98.5%	17	2	88.2%	203	6	97.0%
500		24	1	95.8%	286	22	92.3%	23	4	82.6%	284	82	71.1%
502		24	0	100.0%	284	13	95.4%	23	1	95.7%	282	79	72.0%
503		24	3	87.5%	297	32	89.2%	24	10	58.3%	286	91	68.2%
504	38	24	2	91.7%	285	11	96.1%	23	7	69.6%	284	114	59.9%
505		24	2	91.7%	289	33	88.6%	23	6	73.9%	286	103	64.0%
506		24	3	87.5%	289	27	90.7%	23	6	73.9%	287	72	74.9%
507		24	3	87.5%	288	33	88.5%	24	11	54.2%	287	91	68.3%
508		24	0	100.0%	292	13	95.5%	24	7	70.8%	290	85	70.7%
509		24	3	87.5%	287	31	89.2%	23	7	69.6%	286	101	64.7%
511		24	1	95.8%	288	23	92.0%	24	5	79.2%	285	77	73.0%
516	26	24	3	87.5%	288	27	90.6%	24	13	45.8%	286	131	54.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
517		24	0	100.0%	289	5	98.3%	24	10	58.3%	288	173	39.9%
518		24	3	87.5%	289	32	88.9%	24	11	54.2%	287	172	40.1%
519		24	0	100.0%	286	11	96.2%	24	4	83.3%	285	59	79.3%
520		17	3	82.4%	38	5	86.8%	17	0	100.0%	38	1	97.4%
521		17	0	100.0%	206	4	98.1%	17	1	94.1%	205	16	92.2%
522		17	1	94.1%	206	4	98.1%	16	0	100.0%	205	11	94.6%
523		17	0	100.0%	207	4	98.1%	17	1	94.1%	207	26	87.4%
524		17	1	94.1%	207	6	97.1%	16	3	81.3%	206	36	82.5%
525		17	0	100.0%	205	4	98.0%	17	0	100.0%	204	10	95.1%
526		17	0	100.0%	38	4	89.5%	17	3	82.4%	38	7	81.6%
527		17	0	100.0%	207	3	98.6%	17	0	100.0%	206	29	85.9%
528		17	0	100.0%	206	5	97.6%	17	2	88.2%	206	32	84.5%
529		17	0	100.0%	207	0	100.0%	17	4	76.5%	207	40	80.7%
531		17	1	94.1%	206	3	98.5%	17	3	82.4%	205	16	92.2%
532		17	0	100.0%	207	9	95.7%	17	0	100.0%	205	20	90.2%
534		17	2	88.2%	207	15	92.8%	17	1	94.1%	206	15	92.7%
535	15	17	3	82.4%	38	4	89.5%	16	2	87.5%	37	4	89.2%
536		17	1	94.1%	207	9	95.7%	17	2	88.2%	205	10	95.1%
537		16	0	100.0%	37	1	97.3%	16	0	100.0%	37	2	94.6%
538		17	1	94.1%	207	5	97.6%	17	3	82.4%	207	37	82.1%
540		17	0	100.0%	207	5	97.6%	17	3	82.4%	202	21	89.6%
541	15	17	0	100.0%	207	8	96.1%	17	5	70.6%	207	45	78.3%
542		17	1	94.1%	207	8	96.1%	17	3	82.4%	207	35	83.1%
543		17	0	100.0%	207	6	97.1%	17	8	52.9%	207	32	84.5%
544		16	1	93.8%	205	11	94.6%	16	0	100.0%	204	15	92.6%
545		17	1	94.1%	207	8	96.1%	17	1	94.1%	205	21	89.8%
546		17	0	100.0%	207	7	96.6%	17	3	82.4%	206	31	85.0%
547		17	2	88.2%	207	9	95.7%	17	3	82.4%	207	29	86.0%
548		17	0	100.0%	205	12	94.1%	17	0	100.0%	203	11	94.6%
549		17	5	70.6%	207	24	88.4%	16	1	93.8%	201	30	85.1%
551		17	0	100.0%	207	10	95.2%	17	1	94.1%	202	18	91.1%
562		24	2	91.7%	293	33	88.7%	23	1	95.7%	283	31	89.0%
564		24	3	87.5%	291	20	93.1%	24	3	87.5%	288	27	90.6%
566		24	0	100.0%	116	10	91.4%	24	1	95.8%	116	12	89.7%
572	17	24	3	87.5%	246	22	91.1%	24	8	66.7%	242	46	81.0%
573		24	1	95.8%	285	38	86.7%	24	3	87.5%	279	46	83.5%
577		24	0	100.0%	39	0	100.0%	24	2	91.7%	39	2	94.9%
580		24	0	100.0%	293	21	92.8%	24	1	95.8%	292	53	81.8%
581	22	24	3	87.5%	293	36	87.7%	24	7	70.8%	289	58	79.9%
582		24	1	95.8%	39	1	97.4%	24	2	91.7%	39	3	92.3%
586		24	2	91.7%	244	31	87.3%	24	3	87.5%	237	41	82.7%
587		24	3	87.5%	244	28	88.5%	23	5	78.3%	237	51	78.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/24/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
591	59	24	0	100.0%	293	32	89.1%	24	3	87.5%	289	41	85.8%
593	No OS	24	5	79.2%	39	7	82.1%	24	5	79.2%	39	8	79.5%
595		24	3	87.5%	285	61	78.6%	24	2	91.7%	283	50	82.3%
600		17	1	94.1%	205	3	98.5%	17	2	88.2%	203	26	87.2%
601		17	3	82.4%	205	20	90.2%	17	3	82.4%	204	34	83.3%
605		17	1	94.1%	205	11	94.6%	17	0	100.0%	203	26	87.2%
607		17	2	88.2%	206	19	90.8%	17	0	100.0%	205	10	95.1%
609		17	2	88.2%	206	14	93.2%	16	1	93.8%	205	30	85.4%
620		17	1	94.1%	206	6	97.1%	17	3	82.4%	204	27	86.8%
622		14	2	85.7%	163	8	95.1%	14	2	85.7%	162	47	71.0%
639		17	1	94.1%	206	26	87.4%	17	2	88.2%	205	24	88.3%
640		17	0	100.0%	206	0	100.0%	17	3	82.4%	206	101	51.0%
641	30	17	0	100.0%	206	18	91.3%	17	1	94.1%	206	35	83.0%
642		17	1	94.1%	206	1	99.5%	17	1	94.1%	205	42	79.5%
643		17	0	100.0%	206	13	93.7%	17	2	88.2%	205	43	79.0%
644	15	17	1	94.1%	206	9	95.6%	16	3	81.3%	203	47	76.8%
645	21	17	2	88.2%	206	16	92.2%	16	4	75.0%	205	53	74.1%
646		17	1	94.1%	206	18	91.3%	17	4	76.5%	203	100	50.7%
647	13	17	1	94.1%	206	15	92.7%	16	6	62.5%	205	81	60.5%
648		17	0	100.0%	206	12	94.2%	17	5	70.6%	204	35	82.8%
649		17	0	100.0%	206	20	90.3%	17	4	76.5%	205	39	81.0%
650		17	0	100.0%	206	10	95.1%	17	1	94.1%	205	30	85.4%
651		17	2	88.2%	206	25	87.9%	17	4	76.5%	206	81	60.7%
652		17	1	94.1%	206	4	98.1%	17	5	70.6%	206	37	82.0%
653		17	1	94.1%	206	14	93.2%	17	5	70.6%	205	67	67.3%
654		17	1	94.1%	206	5	97.6%	17	0	100.0%	204	20	90.2%
655	42	17	4	76.5%	205	33	83.9%	17	6	64.7%	203	72	64.5%
656		17	2	88.2%	206	5	97.6%	17	2	88.2%	205	45	78.0%
657		17	1	94.1%	206	14	93.2%	17	1	94.1%	206	50	75.7%
658		17	0	100.0%	206	6	97.1%	17	4	76.5%	205	54	73.7%
680		18	0	100.0%	208	2	99.0%	18	1	94.4%	207	32	84.5%
681		18	0	100.0%	207	12	94.2%	18	7	61.1%	204	80	60.8%
682		18	0	100.0%	208	5	97.6%	18	1	94.4%	208	95	54.3%
683		17	0	100.0%	160	4	97.5%	17	8	52.9%	160	64	60.0%
684		16	4	75.0%	159	13	91.8%	16	7	56.3%	158	83	47.5%
685	26	16	0	100.0%	163	12	92.6%	16	9	43.8%	163	60	63.2%
686	16	18	6	66.7%	207	42	79.7%	18	9	50.0%	207	86	58.5%
687		18	1	94.4%	208	29	86.1%	18	7	61.1%	208	79	62.0%
688		18	1	94.4%	208	8	96.2%	18	2	88.9%	208	89	57.2%
702	29	24	3	87.5%	297	20	93.3%	24	15	37.5%	296	100	66.2%
703		24	3	87.5%	297	30	89.9%	24	10	58.3%	297	75	74.7%
710	40	24	9	62.5%	297	51	82.8%	23	17	26.1%	290	87	70.0%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
711		24	0	100.0%	296	10	96.6%	24	11	54.2%	287	37	87.1%
712	96	24	4	83.3%	297	47	84.2%	23	14	39.1%	294	92	68.7%
713	21	23	0	100.0%	295	9	96.9%	19	14	26.3%	276	64	76.8%
714	60	24	7	70.8%	296	42	85.8%	24	13	45.8%	291	75	74.2%
715	No OS	24	4	83.3%	296	43	85.5%	23	17	26.1%	285	94	67.0%
716		24	6	75.0%	296	34	88.5%	22	6	72.7%	294	62	78.9%
718	No OS	24	7	70.8%	297	44	85.2%	23	7	69.6%	295	56	81.0%
719	No OS	24	7	70.8%	297	30	89.9%	24	15	37.5%	289	72	75.1%
761		24	1	95.8%	293	18	93.9%	24	4	83.3%	293	37	87.4%
765		24	1	95.8%	293	13	95.6%	24	2	91.7%	284	41	85.6%
769		24	2	91.7%	291	13	95.5%	24	4	83.3%	287	54	81.2%
770		24	0	100.0%	293	17	94.2%	24	6	75.0%	290	40	86.2%
774		24	0	100.0%	293	8	97.3%	24	3	87.5%	289	65	77.5%
779		24	0	100.0%	39	1	97.4%	24	3	87.5%	39	7	82.1%
784	No OS	24	1	95.8%	293	33	88.7%	24	12	50.0%	290	117	59.7%
785		24	2	91.7%	293	15	94.9%	24	1	95.8%	291	44	84.9%
790		24	2	91.7%	293	16	94.5%	24	2	91.7%	290	43	85.2%
794		24	0	100.0%	293	22	92.5%	23	1	95.7%	291	58	80.1%
821		21	0	100.0%	292	6	97.9%	21	17	19.0%	292	151	48.3%
822	64	23	2	91.3%	294	13	95.6%	23	23	0.0%	294	154	47.6%
1333	47	24	2	91.7%	290	52	82.1%	24	20	16.7%	289	186	35.6%
1340		24	2	91.7%	289	14	95.2%	24	15	37.5%	287	98	65.9%
1689		15	0	100.0%	75	0	100.0%	15	3	80.0%	74	16	78.4%
2103		16	0	100.0%	202	11	94.6%	16	1	93.8%	199	23	88.4%
2107		17	4	76.5%	202	37	81.7%	17	1	94.1%	198	27	86.4%
2108		16	1	93.8%	198	20	89.9%	15	4	73.3%	195	31	84.1%
2121		16	1	93.8%	199	32	83.9%	15	4	73.3%	194	45	76.8%
2122		17	3	82.4%	201	37	81.6%	17	4	76.5%	195	35	82.1%
2124		14	2	85.7%	161	28	82.6%	13	3	76.9%	157	35	77.7%
2150	19	17	0	100.0%	206	7	96.6%	17	5	70.6%	206	65	68.4%
2151		17	0	100.0%	206	0	100.0%	16	5	68.8%	205	50	75.6%
2152	Cncld	16	3	81.3%	203	8	96.1%	15	8	46.7%	196	82	58.2%
2153		16	0	100.0%	201	5	97.5%	16	9	43.8%	199	48	75.9%
2154	Cncld	17	4	76.5%	204	18	91.2%	15	11	26.7%	199	90	54.8%
2155	50	16	1	93.8%	196	13	93.4%	16	7	56.3%	189	80	57.7%
2159		17	2	88.2%	203	16	92.1%	17	6	64.7%	198	64	67.7%
2162	27	16	1	93.8%	204	16	92.2%	15	8	46.7%	198	72	63.6%
2166	60	17	4	76.5%	205	13	93.7%	16	9	43.8%	202	48	76.2%
2167		17	1	94.1%	206	28	86.4%	17	7	58.8%	204	53	74.0%
2168	15	17	3	82.4%	206	17	91.7%	17	7	58.8%	205	49	76.1%
2170	24	16	3	81.3%	196	15	92.3%	15	5	66.7%	192	47	75.5%
2172		16	2	87.5%	192	23	88.0%	16	6	62.5%	188	41	78.2%

Amtrak On Time Performance

Trains Arriving Through: 7/24/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
Train	Late												
2193		15	1	93.3%	200	26	87.0%	15	6	60.0%	193	69	64.2%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/24/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2150	BOS	19	OTH	16	DCS	8	XNH-XGX	AM	T.O.L, Milepost, xss, xgx, T.O.L. track 2
2152	BOS	Trn Cancelled							
2154	BOS	Trn Cancelled							
2155	WAS	50	DBB	24	DBB	24	XGX-NHV	AM	Stuck open bridges, Bridge, Conn River
2162	BOS	27	ENG	12	ENG	12	XPV-WIL	AM	Undesired emergency application, 2022, WENT INTO EMERGENCY, INSPECTED AND TOOK NO EXCEPTIONS
2166	BOS	60	CAR	53	CAR	44	BAL-XPV	AM	Legitimate wayside HBD or DED actuation, C/3208, loose panel on 6th car, stopped between Gunpow and River to secure, could not secure it, tripped dragger at MP 75.1, north of Wood crew reported panel ripped off on its own
2168	BOS	15	MTI	18	MTI	18	BAL-XPV	AM	Disabled train ahead, Milepost, 75.1, 81, 2166 ahead with mechanical issues
2170	BOS	24	DSR	19	ENG	17	NYP-XSH	AM	Undesired emergency application, 2035, STOPPED AT LEGGETT ON 2TRK A/C LEVEL 2 WHEEL SLIP ALARM ON LEAD POWER CAR #2035
66	BOS	89	DBB	144	DBB	86	OSB-OSB	AM	Stuck open bridges, Bridge, CONN RIVER
67	NPN	17	CTI	37	FTI	22	RVR-RVM	CS	Meet cdx M418-24, Control Point, cfp1.8
85	RVM	29	CTI	20	CTI	12	BWI-NCR	AM	Follow, MARC, 445, Milepost, 106.3, 127
86	BOS	28	ENG	26	ENG	14	NYP-XSH	AM	Air / Brake, 611, BRAKE PENALTY ON ENG.611
94	BOS	30	MTI	13	MTI	13	BAL-XPV	AM	Disabled train ahead, Milepost, 75.1, 81, 2166 ahead with mechanical issues
95	NFK	139	DBB	81	DBB	81	NLC-OSB	AM	Stuck open bridges, Bridge, CONN RIVER
125	NPN	41	CTI	51	OTH	10	STS-NHV	AM	Lost time - N.A.R.
133	WAS	28	HLD	12	DCS	6	EWR-TRE	AM	Restrictive signal(s) from unknown cause, NA, Other, XLT-XUN, 30MPH S/R BLEEDOVER FROM "A" TRACK
141	NFK	27	PTI	38	PTI	14	ASD-RVR	CS	Wait for station track p138, Control Point, Greendale
151	RNK	30	SYS	30	SYS	30	WAS-WAS	AM	Conductor working alone/crew shortage., DIESELS LATE FROM PIT DUE TO SHORT CREWS
171	RNK	19	OTH	17	OTH	9	XSH-NYP	AM	Lost time - N.A.R.

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/24/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
172	BOS	24	DMW	23	DMW	16	NYP-XSH	AM	Hold for defect repair, Other, XGG, HELD AT GATE F/AM125-AM2155-AM95 A/C IMPOSED 30 MPH S/R ON 1 TRK BETWEEN LEGGETT & GATE A/C TRACK DEFECT	
183	WAS	17	MTI	19	MTI	19	NWK-MET	AM	Disabled train ahead, Other, XLT-XEO, AM641 W/ACSES PENALTY AHD	
184	BOS	48	MTI	52	MTI	52	BAL-XPV	AM	Disabled train ahead, Milepost, 75.1, 81, 2166 ahead with mechanical issues	
417	NHV	16	CTI	15	CTI	11	WFD-STG	AM	Meet, ctrail, 4476, Milepost w/Letters, wfd, sts, AM417 met ctrail 4476	
474	SPG	17	DMW	16	DMW	16	WFD-MDN	AM	Held for or routed around MW work or equipment, Milepost w/Letters, wfd, mdn, AM474 met AM475 and AM55 at the runaround	
494	GFD	24	CON	27	CON	27	NHV-NHV	AM	Hold for connecting train, Held for late conx of AM94	
79	CLT	161	POL	126	POL	126	GRO-HPT	NS	RR blocked by trespasser or vehicle strike by another train NC 76	
80	NYP	133	PTI	46	ENG	28	BAL-BAL	AM	HEP, E/637, MCB opened and lost HEP in Baltimore	
641	HAR	30	CTI	21	ENG	20	NWK-MET	AM	Unrecoverable penalty (PCS), 633, ELMORA ACSES PENALTY ON ENG.633	
644	NYP	15	CCR	18	CCR	18	NWK-NYP	AM	Unrecoverable penalty (PCS), 9641, ACSES PENALTY ON CC9641	
645	HAR	21	CCR	23	CCR	23	NYP-NYP	AM	Cab signal failure, 9641, LATE F/SSYD EQUIPMENT MANIPULATION A/C ACSES FAILURE ON CC9641	
647	HAR	13	PTI	16	PTI	9	EWB-TRE	AM	Follow, 133 19 2121, Other, XLT-TRE, FLWD AM133 , AM19 AND AM2121 ON 3TRK	
655	HAR	42	SYS	48	SYS	48	NYP-NYP	AM	Conductor working alone/crew shortage., LATE FROM SSYD A/C SHORTAGE OF YARD CREWS	
685	POR	26	DCS	9	DCS	9	XP0-EXR	CS	Wayside detector failure including false actuation Not working, Other, Newton Det 83.7	
686	BON		WTR	8	PTI	5	ORB-SAO	CS	Meet 683, Control Point, Surf	
63	TWO	97	WTR	31	WTR	18	XSV-ROC	CS	Heat order Milepost, 291, 371	
68	NYP	137	PTI	96	PTI	64	XWH-FED	DH	Wait for station track 291 had signal failure at cp 56., 291, Control Point, 56	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/24/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
281	NFL	53	ENG	60	ENG	35	AMS-UCA	CS	Air / Brake Main res pressure dropped. Stopped at cp225 to inspect for leaks. No leaks. Reset air compressor and pressure came back up., 707
290	NYP	25	DSR	37	DSR	31	BTN-VRN	VR	Per bulletin Milepost, 116.86, 115.78, 10, main, Milepost, 113.30, 111.0, 10, main, Milepost, 111.0, 107.91, 25, main, Milepost, 107.91, 105.19, 50, main, Milepost, 105.68, 105.19, 15, main, Milepost, 105.19, 101, 50, main, Milepost, 101.0, 100.63, 25, main
291	BTN	94	DSR	38	FTI	24	XSY-SAR	DH	Meet 528, Control Point, 33
42	NYP	48	ENG	25	ENG	25	HAR-ELT	AM	Other electrical failure, E/86, Acceleration issues
76	RGH	193	TRS	185	TRS	185	KAN-GRO	NS	Trespasser strike Milepost, 301, 301
78	RGH	135	TRS	122	TRS	122	SAL-HPT	NS	Trespasser strike Stop signal at Lake due to train congestion from earlier trespasser strike., Control Point, Lake
89	SAV	50	FTI	46	FTI	14	CHS-YEM	CS	Meet All stop waiting, Control Point, Ravenel, CSXT 196
55	WAS	77	DSR	89	DSR	37	SAB-ESX	NE	Per bulletin Milepost, 118.00, 116.00, 25, main, Milepost, 114.39, 114.59, 25, main, Milepost, 106.00, 115.00, 10, main
56	SAB	50	DSR	58	DSR	31	ESX-SAB	NE	Per bulletin Milepost, 106, 114, 10, Track, Milepost, 114.39, 114.59, 25, Track, Milepost, 119, 120, 25, Track, Milepost, 114, 115, 25, Track
40	CHI	373	TRS	117	TRS	117	DNK-CLB	CS	Vehicle on track ahead Vehicle stuck on the tracks @ Busbee Street Crossing. Had to wait for authorities and tow truck to arrive. DOT# 634690S, Milepost w/Letters, S 371.9, S 371.9
41	MIA	40	DSR	57	CTI	14	DLD-WPK	FR	Meet CFRC, 312, Control Point, Blue Springs
6	CHI	85	DSR	89	WTR	56	NPV-XUA	BN	High winds Expired around MP 6.0 @1547 / also FF warning from MP 24.0 - 6.0, Milepost, 28.5, 0.8
535	OKJ	15	MBO	19	MBO	19	SUI-MTZ	UP	For maritime traffic Control Point, BENICIA
541	SJC	15	PTI	12	MBO	10	SUI-MTZ	UP	For maritime traffic Bridge, Suisun
51	CHI	47	FTI	93	FTI	47	COI-IND	CS	Meet TO4323, Milepost, 115.7, 119.3
504	SEA	38	CAR	38	CAR	28	EUG-EUG	UP	Set out defective car 82514, Pick up car.
516	VAC	26	MBO	21	MBO	21	X8B-XF2	BN	For maritime traffic Bridge, fraser river

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/24/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
58	CHI	171	FTI	106	FTI	24	HMW-XCS	CT	Follow CN 3322, Control Point, Kelley, Control Point, 21st Street	
59	NOL	151	SVS	102	SVS	100	CHI-CHI	AM	Planned set out / pick out of locomotives, cars or section of train	
8	CHI	65	FTI	69	DSR	26	RDW-WIN	CP	Per bulletin Milepost, 365.1, 364.9, 40, Main, Milepost, 363.0, 362.7, 40, Main, Milepost, 357.6, 356.3, 10, Main, Milepost, 356.3, 350.9, 25, Main	
822	OKC	64	FTI	51	FTI	20	FTW-GLE	BN	Meet bnsf 7798, Siding, valley view	
334	CHI	15	PTI	13	PTI	13	SVT-XRO	CP	Meet Waiting for A1333 to clear #8188 Foreman Gavinia's work limits (single tracking) before we're able to continue, Amtrak 1333, Control Point, Rondout tower 2-1	
336	CHI	16	DMW	16	DMW	16	SVT-XRO	ME	Held for or routed around MW work or equipment Milepost, 32.4, 31.5	
350	PNT	34	PTI	44	PTI	37	XB0-XA5	MI	Meet 353, Siding, albion	
352	PNT	102	DCS	76	DCS	76	KAL-XGO	MI	Power switch failure Control Point, 124	
353	CHI	23	HLD	13	SYS	10	DER-ARB	MI	PTC problem or failure (cause unknown) No mode light entering ITCS territory. After station work pulled down to CP9 and perform MTIE operation. Took 3 tries to be successful.	
355	CHI	29	DSR	23	DSR	12	KAL-DOA	AM	Per bulletin Stop and protect xing. Elm at & N park at, Other, mp143.6, 0, all, Other, mp144, 0, all	
364	PTH	46	DSR	37	DSR	25	DOA-KAL	AM	Per dispatcher (radio/phone) Also had a crossing protection @ 144.0 Elm st, Milepost, 143, 144, 20, 1	
370	GRR	38	DCS	24	DCS	24	SJM-BAM	CS	Restrictive signal(s) from unknown cause Restricting, Control Point, EE Kirk	
572	SAN	17	CTI	16	CTI	6	LAX-LAX	SC	Meet Metrolink, 321, Control Point, Terminal	
581	LAX	22	FTI	15	FTI	10	FUL-XRJ	BN	Follow 7745, Milepost, 165, 144	
591	LAX	59	ENG	45	ENG	35	OLT-SOL	SN	Failure of diesel engine Engine shut down again. Troubleshoot via phone with cnoc mechanical., C2113	
593	LAX	No OS Rpt								
784	SAN	No OS Rpt	ENG	41	ENG	38	NRG-NRG	SC	Failure of diesel engine C2116	
702	BFD	29	FTI	46	FTI	24	FNO-HNF	BN	Meet BN 7157, BN 8366, Control Point, Calwa Crossing, Siding, Conejo	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/24/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
710	BFD	40	PTI	25	PTI	14	MCD-MDR	BN	Meet AMTK 713, Siding, La Grand
712	BFD	96	SVS	86	SVS	86	EMY-EMY	UP	Last minute servicing to the equipment Other, YARD
713	OKJ	21	DSR	24	DSR	12	SKN-ACA	BN	Per bulletin Milepost, 1129.4, 11334.4, 30, M1, Milepost, 1133.5, 1133.7, 15, m2/zmt, Milepost, 1137.4, 1137.7, 45, MT
714	BFD	60	PTI	49	PTI	33	ACA-SKN	BN	Meet 713, Siding, orwood
715	OKJ	No OS Rpt	FTI	296	FTI	262	SKN-ACA	BN	Freight train set off hot box detector Freight train on single main with a hot journal. Setting out bad car., Siding, Orwood, BNSF, BNSF
718	BFD	No OS Rpt	FTI	252	FTI	252	ACA-SKN	BN	Meet Ricbar required mechanical to scene, unknown why the wait due to double tracks, Control Point, oakley, bnsf RICBAR1 23A
719	OKJ	No OS Rpt	FTI	122	FTI	88	SKN-ACA	BN	Freight train broke down Freight train broke down at Orwood due to a hotbox detector. Had to wait for them to clear up and try to move their equipment. Had a couple in with 715 due to them dying on the hours of service., Control Point, orwood, bnsf ??
3	LAX	47	DSR	85	FTI	24	XIA-GLP	BN	Follow UNKN BNSF W, Milepost, 30, 58.8
4	CHI	167	WTR	77	SVS	46	PCT-MDT	BN	Pick up equipment Control Point, Zearing
300	CHI	47	FTI	40	FTI	28	CRV-SPI	UP	Meet UP8978, Control Point, lles
380	CHI	16	FTI	14	FTI	14	MAC-GBB	BN	Cross over or go around 8202, Siding, Abington
381	QCY	19	DSR	23	DMW	7	MAC-QCY	BN	Held for or routed around MW work or equipment Siding, macomb
383	QCY	46	FTI	21	WTR	12	LAG-NPV	BN	Flash flood warning Milepost, 6.0, 24.0
318	CHI	92	DSR	38	PTI	23	KCY-XRC	KC	Meet Amtrak management wouldn't hold train 4 for an additional 7 minutes to not take delay., 4, Other, Grand ave
319	KCY	55	DSR	38	DSR	12	SMT-XUD	CC	Per dispatcher (radio/phone) Milepost, 17.0, 18.0, 10, Main 1 and 2
1333	MSP	47	DSR	44	DSR	22	WIN-RDW	CP	Per bulletin Milepost, 349.4, 350.0, 25, main, Milepost, 350.9, 356.3, 25, main, Milepost, 356.3, 357.6, 10, main, Milepost, 362.7, 363.0, 40, main, Milepost, 364.9, 365.1, 40, main

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/24/2025

Terminal	Train	Date	Late	Delay	Cause
WAS	2152	07/24	(Trn Cxld)		equipment issues
WAS	2154	07/24	(Trn Cxld)		equipment issues
WAS	2166	07/24	21	22	Onboard HBD alarm, 2010, MULTIPLE ALARMS ON POWER CAR 2010; MECHANICAL REQUIRED
BTN	290	07/24	6	6	Planned Switch Switching ends / break test
NYP	63	07/24	13	13	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C SERVICING
NYP	111	07/24	7	7	Air / Brake, 651, HELD IN STATION BY MECHANICAL A/C BRAKE ISSUES.
NYP	243	07/24	14	14	Service, turn, or wye train, 244, LATE TURN OFF OF AM244
NYP	291	07/24	19	19	Undesired emergency application, 9700, BRAKE ISSUES ON ENG.9700
NYP	609	07/24	16	16	Service, turn, or wye train, 646, LATE TURN OFF AM646
NYP	645	07/24	23	23	Cab signal failure, 9641, LATE F/SSYD EQUIPMENT MANIPULATION A/C ACSES FAILURE ON CC9641
NYP	655	07/24	48	48	Conductor working alone/crew shortage., LATE FROM SSYD A/C SHORTAGE OF YARD CREWS
CHI	5	07/24	113	35	Heat / AC 31044, HVAC failure. Train was released and allowed to shove from the yard in this condition.
CHI	5	07/24	113	78	Bad order fridges 33030
CHI	7	07/24	37	37	Add on lounge and 731 car 33027
CHI	21	07/24	63	43	HEP 53, 30
CHI	21	07/24	63	20	Power switch failure Control Point, Lumber
CHI	41	07/24	225	225	Service, turn, or wye train 40, Arrived in CHI @ 259pm
CHI	50	07/24	69	69	Set out defective locomotive 37
CHI	59	07/24	30	30	Crew rest Late inbound 58, Other, CHI
CHI	329	07/24	6	6	Air / Brake / Wheel 90221, Piston not retracting as it should. Gee mech approval to depart
CHI	335	07/24	4	4	Service, turn, or wye train 334, 12:54 arrival 12:59 passengers disembarked 13:03 red cap service, wheelchair lift and class II done, called for boarding of passengers 13:08 cleared by North gate and Yard Master 13:10 departure
CHI	354	07/24	5	5	Mobility Impaired Last minute Ada requiring wheelchair lift
CHI	370	07/24	10	10	Fuel
EUG	504	07/24	28	28	Set out defective car 82514, Pick up car.
MKE	338	07/24	6	6	Late turnover

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/24/2025

Terminal	Train	Date	Late	Delay	Cause
PDX	28	07/24	11	2	Conductor working alone/crew shortage.
PDX	28	07/24	11	9	Mobility Impaired
SEA	503	07/24	25	25	Unplanned Wye Had to why from track 7, Other, Yard
SEA	516	07/24	4	4	Late departure from yard due to waiting for sounder train to clear main 1 at lander street and change engine number on get sdrx unknown, Control Point, lander
BFD	703	07/24	7	7	Service, turn, or wye train 712, Late arrival of equipment, train was being serviced
BFD	715	07/24	60	60	Service, turn, or wye train 702, Late turn trainset from delayed 702.
EMY	6	07/24	5	5	Service, turn, or wye train 5, Mechanical cleaning and repairing defects
LAX	14	07/24	18	18	Water, commissary, toilet/trash dumping Per Train Manager TM C. Marques. Late leaving the yard due to commissary., Other, yard
LAX	572	07/24	6	6	Meet Metrolink, 321, Control Point, Terminal
LAX	586	07/24	8	8	Blocked by or assisting another, disabled Amtrak train Waited on passengers from disabled train 784
OKJ	710	07/24	12	12	Loading problem Per engineer, loco not loading, fault showing "reverser wiring". Electricians performed load test, successfully. No other errors detected., C2005
OKJ	712	07/24	(Trn Cxld)		Late make up
SAC	535	07/24	5	5	Cross Traffic STOP FOR THE RAIL ROAD MUSEUM TO CROSS IN FRONT OF US, CSRM, Control Point, RV 988
SAN	593	07/24	(No OS)		

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.5	94.1	95.2	341	5
CDOT	95.0	95.0	95.5	96.4	20	1
MARC	95.0	89.3	78.3	83.5	56	6
SEPTA	95.0	98.2	96.1	96.2	224	4
NJT-NED	95.0	92.4	92.1	95.2	370	28
NJT-SED	95.0	100	98.1	91.2	24	0

Operating Highlights

Train 98(25) Miami, FL - Canceled /Shopped Engine

25JUL25: Train 98(25) was canceled in entirety due to shopped engine E/124 for smoking batteries and protect engine E/336 for continued speed sensor issue. Account of no available replacement engines and expected high temperatures in excess of 100 degrees on the route, the decision was made to cancel the train.

Train	Delay	Comment
98 (25)	Canceled	

Train 80(24) Baltimore, MD - Engine Failure

24JUL25: at approximately 7:26P-ET, Train 80(24), E/637, 7 cars, with approximately 171 passengers onboard became disabled at Baltimore, MD/MP95.7 on the Amtrak PW Line. Crew reported main circuit breaker (MCB) had opened and pantograph dropped while coming into the station. There was no headend power for approximately 20 minutes. The weather was a reported 91 degrees. Crew worked with mechanical and an Amtrak Road Foreman to troubleshoot. Train 192(24) was held at Baltimore in case a passenger transfer became necessary. At 7:45P-ET the engineer was able to raise the pantograph and restore HEP. At 7:58P-ET Train 80(24) departed Baltimore with 192(24) shadowing the train.

Train	Delay	Comment
80 (24)	28"	
192 (24)	18"	

Train 76(24) West of High Point, NC - Fatal Trespasser Strike

24JUL25:

At approximately 6:06P-ET Train 76(24) NC1869, 4 cars, NC105 fatally struck a trespasser at MP301.34 on the NS Montview-Salisbury Subdivision on track-2, 2 miles west of Highpoint, NC in Guilford County. The incident occurred on the right of way, not at a crossing, with the trespasser in the gauge and struck by the train. Local authorities responded to the scene for an investigation. There were no injuries to the (85) passengers or crew. Track speed was 76mph. Weather was a reported 89 degrees and partly cloudy. Operating Crew requested and was granted relief. No Damage reported to equipment. An Amtrak Road Foreman responded to the scene. Amtrak Police and EAP advised. The train was released at 806P-ET, advanced to the next crossing and met the local fire department to hose down the engine then was able to proceed to High Point, NC to be re-crewed. Once re-crew was onboard and briefed, Train 79(24) departed High Point at 9:09P-ET.

At 9:00P-ET the medical examiner arrived on the scene and both tracks remained closed to rail traffic for investigation and clean-up. Train 78(24) was held at Lake/MP310.55 and Train 79(24) was held just east of High Point, NC at MP297.8. The tracks were released at 10:38P-ET allowing both trains to resume operation.

National Response Center Number: 1437882

Train	Delay	Comment
76(24)	3'05"	
78(24)	2'02"	
79(24)	2'06"	
79(24)	21"	KAN- Recrew

Train 68(24) North of Westport, NY - Passenger Train Interference

24JUL25: Train 69(24) held 20.8 miles north of Westport, NY/MP127.8, on the CPRR Canadian Subdivision, at Rockland/MP148.6 meeting Train 68(24).

Train	Delay	Comment
68(24)	32"	

Train 281(24) East of Utica, NY - Engine Failure

24JUL25: At 2:55PM, Train 281(24), E/707-5 Cars, reported losing main reservoir pressure 12.8 miles east of Utica, NY/MP237.5, on the CSX Mohawk Subdivision, stopping at MP224.7. No leaks were found upon inspection. The crew reset the air compressor and the pressure built back up. During this time, head end power was on to the trainset. At 3:19PM, Train 281(24) was back on the move west. At 5:20PM-ET, Train 281(24) was further delayed 22 miles west of Syracuse, NY at MP/QC309 with same issue. Crew reset the air compressor again to resolve the issue and proceed.

Train	Delay	Comment
281(24)	35"	
281(24)	25"	W/SYR

Train 68(24) South of St-Lambert, QC - Heat Orders

24JUL25: Train 68(24) was delayed starting 2.2 miles south of St-Lambert, QC/MP70.3, on the CNRR Rouses Point Subdivision, due to heat orders between Southwark/MP42.7 and Rouses Point/MP0.0. Operating speeds were reduced to not exceed 25MPH through the area.

Train	Delay	Comment
68(24)	43"	

Train 2166(24) Washington, DC - Engine / Car Failure

24JUL25: Train 2166(24), TS#14, was delayed departing Washington Union Station account multiple alarms going off in lead power car 2010. High Speed Rail Mechanical responded and was able to resolve the issue for Train 2166(24) to depart the station.

At Gunpow/MP79.3, on the Amtrak PW Line, Train 2166(24) stopped to inspect due to a reported panel hanging from under the train. After inspection, the panel was confirmed hanging from beneath First Class C/3208. The crew contacted their Road Foreman who granted permission to proceed to 30th Street Station where the train would be met by High Speed Rail Mechanical. 2166(24) was back on the move north for a few miles then set off a dragging equipment detector. The train stopped on the No. 2 track in between Wood/MP75.3 and Bush/MP71.6 with protection across No. 3 track. After inspection, it was found that the panel was ripped off. Train 2166(24) then proceeded north operating not exceeding 125MPH.

Train 184(24) received a temporary speed restriction to operate restricted speed from MP74.0 to Wood on the No. 2 track to be on the look out for the panel. Train 184(24)'s crew reported the panel was broken into small pieced at the Edgewood Station/MP75.1 in the gauge. At that point the speed restriction was lifted and Train 184(24) proceeded north at track speed. Train 94(24) stopped short of Edgewood to remove the pieces from the railroad.

Train	Delay	Comment
2166(24)	21"	WAS
125(24)	05"	
184(24)	52"	
131(24)	09"	
94(24)	13"	
2168(24)	18"	
95(24)	17"	
2166(24)	44"	Panel

CSX Heat Orders

24JUL25: CSX issued heat orders between 1:00PM and 7:00PM for the following subdivisions: Grand Rapids, Monon, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, North End, Old Main Line, Portland, RF&P, Rochester, and Syracuse Terminal.

Train	Delay	Comment
48(23)	16"	
41(23)	30"	
40(23)	27"	
53(24)	13"	
63(24)	31"	
64(24)	44"	
79(24)	25"	
80(24)	17"	
90(24)	25"	
93(24)	03"	
95(24)	17"	
125(24)	26"	
138(24)	07"	
141(25)	17"	
186(24)	10"	
281(24)	19"	
283(24)	16"	
683(24)	05"	
684(24)	03"	
685(24)	07"	
686(24)	08"	
688(24)	04"	
687(24)	05"	

Train 80(24) Raleigh, NC - Programmed Move

24JUL25: Train 80(24) was delayed at Raleigh, NC/MP80.9, on the NSRR Goldsboro-Greensboro Subdivision, completing a programmed move adding E/38 and E/33 to the consist.

Train	Delay	Comment
80 (24)	41"	

Train 19(23) North of Spartanburg, SC - Passenger Train Interference

24JUL25: Train 19(23) was delayed 15.1 miles north of Spartanburg, SC/MP452.6, on the NSRR Salisbury-Greenville Subdivision, at Thicketty/MP437.5 meeting Train 20(23).

Train	Delay	Comment
19 (23)	35"	

NEC Service Adjustments - Impending Extreme Temperatures

24JUL25: Due to the impending forecast of extreme temperatures over 100 degrees and storms along the Northeast Corridor for Friday July 25,2025, the following service adjustments have been made:

- Trains 112(25), 192(25), 178(25), 133(25), 131(25) and 173(25) are cancelled in their entirety with no alternate.
- Trains 2154(25), 2155(25), 2173(25), and 2172(25) are cancelled in their entirety with no alternate.

Train	Delay	Comment
112(25)	cancelled	
192(25)	cancelled	
178(25)	cancelled	
131(25)	cancelled	
133(25)	cancelled	
173(25)	cancelled	
2154(25)	cancelled	
2173(25)	cancelled	
2155(25)	cancelled	
2172(25)	cancelled	

Amtrak NHB Line - Conn River Bridge Defect

24JUL25: At 8:00AM, the New London Dispatcher reported that the Connecticut River Bridge at MP106.8 was stuck in the open position, unable to close. Located 1.7 miles east of the Old Saybrook, CT station/MP105.1, on the Amtrak NHB Line. B&B Potter responded to the location to troubleshoot. During this time, Trains 2155(24), 95(24), 66(23), and CT 1606 were all delayed. At 9:20AM, the bridge was reported seated and locked allowing all traffic to resume.

Train	Delay	Comment
95 (24)	1'21"	
66 (23)	1'26"	
CT 1606	34"	
2155 (24)	24"	
93 (24)	04"	

Acela Cancellations - Shopped Equipment

24JUL25: Due to multiple shopped Acela train sets, the following service adjustment were necessary: Acela Trains 2190(24), 2163(24), 2152(24), 2169(24), 2154(24) and 2173(24) were canceled in their entirety for Thursday, July 24th, 2025. Passengers were notified via Service 360 and able to re-book to next available services.

Train	Delay	Comment
2152/2169(24)	Cancelled	Entirely
2190/2163(24)	Cancelled	Entirely
2154/2173(24)	Cancelled	Entirely

Maintenance of Way Highlights

Train 40(23) North of Rocky Mount, NC - M of W Work

24JUL25: Train 40(23) was delayed 8.6 miles north of Rocky Mount, NC/MP119.6, on the CSX North End Subdivision, due to Maintenance of Way overstay. A frog replacement was taking place ahead and taking longer than anticipated. Once complete, Train 40(23) was released to continue north.

Train	Delay	Comment
40(23)	56"	

Train 55(24) South of St. Albans, VT - M of W Work

24JUL25: Train 55(24) was delayed starting 4.1 miles south of St. Albans, VT/MP132.1, on the NECR Roxbury Subdivision, due to a 10MPH speed restriction from MP128-MP119 due to Maintenance of Way working in the area.

Train	Delay	Comment
55(24)	37"	

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:
-Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
-Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
-Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
-Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
-Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:
-Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
-Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
-Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
-Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
-Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.
*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

· Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.

· Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.

· Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

· Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

· Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

· Bus 3490 will provide alternate transportation between NHV and SPG making all local stops

· Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only

· Bus 3470 will provide alternate transportation between HFD and SPG

· Buses 3471 and 3473 will provide alternate transportation between SPG and HFD

· Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

· Deadhead Train 426 will turn for Train 471 at HFD

· Train 470 will turn for Train 473 at HFD

WBS#: B.TR.100151.0738

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 2162(24) Passenger Non-Removal at New York, New York – Other

24JUL25, Passenger on PNR 1F1803, traveling from Washington, DC to New York, NY couldn't not find her baggage on the train causing a delay. Passenger was taken to Station Services. Amtrak Police notified.

Delay: 2162 (24) 03"

Train 2122(24) Passenger Incident at Metropark (Iselin), New Jersey - Other

24JUL25, Passenger on PNR 3EBAC9, traveling from Washington, DC to Metropark, NJ was witnessed by NJT employees to have open emergency handle at Metropark, NJ due to missing their stop. Passenger was identified by Conductor and reported to CTEC 8 and Amtrak Police.

Delay: 2122 (24) 03"

Train 95(24) Passenger Incident at Norfolk, Virginia – Improper Conduct

24JUL25, Passenger on PNR A64C2C, traveling from New York, NY to Norfolk, VA became irate during the deboarding process and threatened to jump off the train. In efforts to prevent this, the Conductor raised arms to block the passenger's walker hit the conductor and rolled back into the passenger causing them to stumble and fall in the vestibule. Passenger accused the conductor of assaulting them and called the police. Passenger

was assisted further by the A/C stating they were injured but declined medical attention. Amtrak Police notified.

Delay: **95 (24)** **55"**

Western Region

Operating Highlights

Train 41(24) Chicago, IL - Initial Terminal Delay

25JUL25: Train 41(24) was delayed 3 hours and 45 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(22). Train 40(22) arrived in Chicago at 258pm; 6 hours and 13 minutes late due to a 25-minute initial terminal delay in Miami, Florida, 1 hour and 57 minutes in Gaston, South Carolina for a vehicle stuck on the tracks, 1 hour and 36 minutes for freight train interference, 51 minutes in Jarratt, Virginia for an injured or sick passenger, 33 minutes for commuter train interference, 24 minutes between Selma, North Carolina and Rocky Mount, North Carolina for an efficiency test involving Amtrak officers, and 23 minutes in Pittsburgh, Pennsylvania fueling the locomotives. Equipment set to the yard for servicing and inspection at 416pm. At 508pm, lead engine 204 was bad ordered for wheels with engine 147 off inbound 6(22) designated as the replacement. Upon Train 6(22) setting to the yard at 528pm, the fuel foreman reported engine 147 was not equipped with Amtrak cab signals. At 538pm, the replacement locomotive was changed to engine 78 off inbound 6(22) which needed to wye. Engine 78 wyed and tied on at 758pm. Train 41(24) was released by mechanical at 925pm and set in the station at 942pm with 240 passengers to board. Train 41(24) departed Chicago at 1025pm; 3 hours and 45 minutes late. An additional 12-minute delay was incurred wyeing the train set on departure.

Train	Delay	Comment
41(24)	3' 45"	

Train 591(24) West of San Diego Old Town , CA – Locomotive Shutdown – Loss HEP

24JUL25: Train 591(24) -operating with locomotive CDTX/2113 - was delayed shortly after departing San Diego Old Town station when the locomotive shut down losing all tractive effort and Head End Power. The train stopped at MP 258.5, San Diego Subdivision, San Diego Northern Railroad. There were 236 passengers on board. Outside temperature 68 °F, cloudy. The crew were required to shut down and restart the locomotive which restored all power, allowing the service to resume. Locomotive CDTX/2113 shut down a second time at MP 252.5, San Diego Subdivision, the crew again performed a cold restart to restore power.

Cause: Pending

Train	Delay	Comment
591(24)	35"	MP 252.5 - Locomotive Shut Down
591(24)	10"	MP 258.5 - Locomotive Shut Down

Train 718(24) & 715(24) West of Stockton, CA – Freight Train Interference

24JUL25: Train 718(24) & 715(24) were delayed 14 miles West of Stockton. The crew of BNSF Freight Train RICBAR1 - 23 were required to inspect their train after activating a trackside detector on single main track at Oakley MP 1144.5 Stockton Subdivision of the BNSF Railway. The detector measures for hot wheel bearings, the freight crew reported a bearing integrity failure on one of the freight cars. This required further inspection by a qualified technician.

The attending BNSF technician authorized freight train RICBAR1-23 to advance - at walking pace - to Orwood siding to remove affected rail car.

Due to the crew on 715(24) running out of hours of service, they coupled with train 719(24) and they continued on as a combo set to Oakland, CA. Train 715(24) coupled to train 719(24) while waiting for the freight to clear and there was no delay to the train due to combining the 2 train sets.

WBS#: B.TR.100150.5922

Train	Delay	Comment
715(24)	4'22"	
719(24)	1'28"	
718(24)	4'12"	

Train 59(24) Chicago, IL - System

25JUL25: Train 59(24) was delayed 30 minutes departing Chicago, Illinois holding for crew rest at 818pm due to the late arrival of inbound 58(23). Train 58(23) arrived in Chicago at 1206pm; 2 hours and 51 minutes late due to 1 hour and 44 minutes of freight train interference, 1 hour and 1-minute of heat orders, 37 minutes for speed restrictions, and 22 minutes in Jackson, Mississippi holding for crew rest. After servicing in the yard, equipment set in the station and was pre-boarded of all 228 passengers prior to the road crew going back on-duty at 918pm. Train 59(24) departed Chicago at 835pm; 30 minutes late.

Train	Delay	Comment
59(24)	30"	

Train 4(24) East of Fullerton CA - Police Activity

24JUL25: Train 4(24) was delayed 14 miles east of Fullerton while local police were searching for a near the tracks. The train was delayed at east Esperaza MP 41.2, San Bernardino Subdivision, BNSF Railway. Once the searching personnel had cleared the area tracks were re-opened and train 4(24) continued to Riverside. Amtrak Police Notified

Train	Delay	Comment
4(24)	1'06"	

Train 714(24) East of Madera Acres, CA - Freight Train Interference

24JUL25: Train 714(24) was delayed following an unidentified BNSF freight train east of Madera Acres. The freight train was able to enter the siding at east Madera 1018.3, Stockton Subdivision of the BNSF Railway. This cleared the track ahead for train 714(24) to proceed at track speed.

Train	Delay	Comment
714(24)	30"	

Train 784(24) West of Northridge, CA , - Locomotive Shut Down- Loss of Head End Power

24JUL25: At 3:58PM-PT, train 784(24) was delayed departing Northridge station when locomotive CDTX/2116 shut down with no Head End Power or tractive power. Northridge station is located at MP 449.3, Ventura Subdivision, Metrolink Railroad. There were 246 passengers on board. Ambient temperature 86°F, sunny.

The crew worked to resolve the problem - after shutting down the locomotive and performing a restart procedure, power was restored. After re-initializing Positive Train Control, the train was able to depart Northridge after 32 mins delay.

The fault returned at Van Nuys station wen locomotive CDTX/2116 shut down when attempting to depart. After diagnosing the fault - by telephone- with technicians, it was determined the fault would return each time the locomotive attempted to restart from stationary. To prevent recurrences of the issue the following plan was implemented:

Train 784(24) Equipment was terminated at Van Nuys. All passengers transferred to waiting Metrolink train 120 for Los Angeles. Passengers travelling stations to San Diego were advised to transfer to train 586(24) on arrival. Passengers for 784(24) at Los Angeles were advised to use train 586(24).

Train 593(24) - Train 593(24) Cancelled entirely with passengers advised to board train 595(24).

Service Recovery: Train 784(24) passengers were offered complimentary bottled water, ice, hot beverages and snack packs.

Mutual Aid: Tickets for 784(24) valid on Metrolink train 120.

Cause: Pending
WBS#: B.TR.100150.5921

Train	Delay	Comment
784(24)	Terminates Van Nuys	Passengers to Metrolink 120
593(24)	Cancelled	Passengers to 595(24)

Train 22(24) Marshall, TX - Freight Train Interference

25JUL25: Train 22(24) was delayed operating between Marshall, TX, and Texarkana, TX, on the UP Little Rock subdivision, due to following UP6005. Once the freight cleared and a route was made available, train 22(24) was able to resume normal speed.

Train	Delay	Comment
22(24)	1'03"	

Train 352(24) West of Battle Creek, MI - Signal

25JUL25: Train 352(24) was delayed 5 miles west of Battle Creek, MI, on Amtrak Michigan Line subdivision, due to power switch failure at Control Point 124. 352(24) held while a maintainer worked to fix it. The maintainer wedged and clamped the switch and 352(24) was able to proceed.

Train	Delay	Comment
352(24)	1'16"	

Train 6(24) East of Truckee, CA - Debris Strike – Rocks

24JUL25: Train 6(24) operating with camera equipped locomotive AMTK 15 struck rocks placed on the tracks 8 miles east of Truckee. This caused the train to stop at MP 214.4 East Truckee on the Roseville Subdivision of the Union Pacific Railroad. No injuries reported to (156) passengers or crew. Crew inspected train, reporting damage to wheels of locomotive AMTK/15. The crew contacted Reno Road Foreman - after reviewing pictures of the damage authorized the train to proceed to Reno without restriction. The train was inspected in Reno with no condemnable damage found. Amtrak Police Notified

Train	Delay	Comment
6(24)	33"	
6(33)	06"	Reno - Wheel Inspection

Train 5(22) at Roseville, CA – Passenger Removal – Police Request

24JUL25: Train 5(22) was delayed departing Roseville station while police searched for a person of interest on board. Officers located and removed passenger Noah Rudat (PNR# 43771B) - travelling from Denver to Sacramento for outstanding warrants. Amtrak Police Notified.

Train	Delay	Comment
5(22)	12"	

Train 59(23) South of McComb, MS - Passenger Train Interference

24JUL25: Train 59(23) was delayed at Osyka / MP 825.5 on the Canadian National McComb Subdivision, 19 miles south of the McComb, MS station, meeting Train 58(24).

Train	Delay	Comment
59(23)	35"	

Train 714(24) East of Antioch, CA - Passenger Train Interference

24JUL25: - Train 714(24) was delayed at east Orwood MP 1136.4 16 miles east of Antioch at while waiting for Amtrak train 713(24) to clear the track ahead. Once the track was cleared, train 714(24) continued to Stockton.

Train	Delay	Comment
714(24)	33"	

Train 7/27(24) Chicago, IL - Car Failure

24JUL25: Train 7/27(24) was delayed departing the Chicago, IL Union station due to late release of cars. The equipment was released from mechanical at 2:45 p.m. (CDT), 20 minutes prior to the departure time.

Train	Delay	Comment
7/27(24)	37"	

Train 6(23) West of Green River, UT - Routing

24JUL25: Train 6(23) was delayed at Green River / MP 555.8 on the Union Pacific Green River Subdivision, just west of the Green River, UT station, waiting on authority from the Union Pacific Dispatcher.

Train	Delay	Comment
6(23)	39"	

Surrounding Chicago, IL - Severe Weather

24JUL25: High wind and flash flood warnings reported surrounding Chicago, IL. There were reports of winds in excess of 70 mph and rainfall of a rate of 1.5 inches per hour. Trains operating through the area were instructed to operate at reduced speed.

Train	Delay	Comment
5 (24)	34"	Flash Floods
21 (24)	35"	
4 (22)	20"	
6 (22)	1'21"	
3 (24)	54"	CHI-NPV
3 (24)	2'28"	E/KCY

Train 5(24) Chicago, IL - Car Failure

24JUL25: Train 5(24) was delayed departing the Chicago, IL Union Station due to the HVAC failure on the A-End of Car 31044. Mechanical responded but was unable to repair. The decision was made to allow the train to continue without the HVAC on the A-End.

Train	Delay	Comment
5 (24)	1'53"	

Train 21(24) Chicago, IL - Engine Failure

24JUL25: Train 21(24) was delayed departing the Chicago, IL Union Station due to head end power with Locomotive 53 and Locomotive 30. Mechanical responded to the station to rectify the issue.

Train	Delay	Comment
21 (24)	1'03"	

Train 14(23), North of Klamath Falls, OR - Freight Train Interference

24JUL25: Train 14(23) was delayed 28 miles after departing Klamath Falls, at Chiloquin, MP 456.80 Cascades Subdivision of the Union Pacific Railroad. This was to allow for Union Pacific train UPRR/8961 to pass on the mainline. Once the freight train had cleared, 14(23) continued to Chemult, OR.

Train	Delay	Comment
14 (23)	31"	

Train 712(24) Originated at Emeryville, CA - Late Release/Servicing and Repairs

24JUL25: Train 712(24) originated at Emeryville, MP 4.5/UPRR Martinez Subdivision, following a late yard release as a result of servicing equipment after being swapped with Train 714(24) as well as battery charger issues on assigned locomotives E/C2108 and E/C2101. Train 712(24) departed Emeryville at 11:12AM-PT. Passengers boarding at Oakland were reaccommodated onto Train 528(24) to Emeryville to connect with 712(24).

Work Element WBS # B.TR.100150.5920

WBS#: B.TR.100150.5920

Train	Delay	Comment
712(24)	1'26"	Originated at EMY
703(24)	07"	BFD - Equipment Turn from 712(24)

Train 5(23) East of Fraser-Winter Park, CO - Engine Failure

24JUL25: Train 5(23), operating with Locomotive 39, Locomotive 55 and 10 cars, stopped at MP 36.4 on the Union Pacific Tunnel Subdivision, 26 miles east of the Fraser - Winter Park, CO station, due to a ground fault. The crew was able to clear the fault after cutting out traction motor #4 on Locomotive 39.

Train	Delay	Comment
5 (23)	42"	

Train 350(24) East of Battle Creek, MI - Passenger Train Interference

24JUL25: Train 350(24) was delayed at CP 96 / MP 96.2 on the Michigan Department of Transportation Michigan Line, 24 miles east of the Battle Creek, MI station, meeting Train 353(24).

Train	Delay	Comment
350 (24)	37"	

Train 5(22) West of Winnemucca, NV - Struck Animal

24JUL25: Train 5(22) was delayed at MP 369.0/UPRR Nevada Subdivision, 46.1 miles west of Winnemucca, as a result of striking a cow on the tracks. There were no injuries to passengers (174) or crew. Some air hoses were found to be disconnected as a result of the strike. The crew reconnected the hoses and departed following a successful air test.

Train	Delay	Comment
5 (22)	37"	

North County Transit District - Planned Trackwork East of Solana Beach

North County Transit District - Trackwork East of Solana Beach, CA
19MAY24, Commencing 19th May, North County Transit District will close tracks to work on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:
from 10:00PM-PT thru 7:00AM-PT.
Selected work dates are:
Sunday May 19 - Tuesday May 21
Sunday June 02- Tuesday June 04
Sunday June 16 - Tuesday June 18
Sunday June 23 - no extended window account Padres game.
Sunday June 30 - Tuesday July 2
Sunday July 7 - Tuesday July 9
Sunday July 14 - Tuesday July 16
Sunday July 21 - Tuesday July 23
Sunday July 28 - Tuesday July 30
Sunday August 4 - Tuesday August 6
Sunday August 11 - no extended window account Padres game
Sunday August 18th - Tuesday 20th
Sunday August 25 - Tuesday August 27
Sunday September 8 - Tuesday September 10.
Sunday September 15 - Monday September 16
Sunday September 22 - Tuesday September 24.
Sunday October 27 - Tuesday October 29.
Sunday November 3 - Tuesday November 5.
Sunday December 8-Tuesday December 10.
Sunday December 15-Tuesday December 17.
2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Train 716(23) East of Turlock Denair, CA – Locomotive Oil Pressure – Cancelled

23JUL25: Train 716(23) stopped 10 miles east of Turlock/Denair, Fairfield when locomotive CDTX/2003 developed a low oil pressure warning. The train stopped on the single mainline at east Fluhr MP 1065.5, Stockton Subdivision of BNSF Railway. The locomotive was unable to provide tractive effort. Head End Power was temporarily shut down for 20 minutes while diagnosing the cause.

There were 106 passengers on board. Outside temperature was 88 degrees and sunny. With no availability of replacement buses or rescue locomotives in the area the following amended operating plan applied:

Train 716(23) was cancelled at Merced.
To prevent engine damage, trains 716(23) & 717(23) were coupled together at site with both trains returning to Merced. Passengers for 716(23) disembarked at Merced to wait for train 718(23) to destination. The combined trainset then continued west.
Train 717/716(23) combined trainset terminated in Emeryville where passengers for Oakland boarded thruway 6617(23) making additional stop in Oakland.
Train 717(24) was cancelled, with all affected passengers advised to use alternate departures.

Service Recovery: All San Joaquin trains offer complimentary snacks and soda.
24JUL25: After the cancellation of train 717(24), train 702(24) was required to short turn in Bakersfield for train 715(24) causing delayed departure.
Train 702(24) arrived Bakersfield 12:26PM-PT - Train 715(24) departed 1 hour late at 1:12PM-PT.

WBS#: B.TR.100150.5919

Train	Delay	Comment
716(23)	Terminates Merced	Passengers to 718(23)
717(24)	Cancelled	Passengers to Alternate Departures
715(24)	1'00"	BFD - Equipment Turn from 702(24)
717(23)	1'10"	MP 1065.5 - Couple to 716(23)
715/716(23)	30"	MCD - Waiting for relief engineer
717(23)	53"	Fluhr - Wait for BNSF 7336 and BNSF 5985 to clear - delayed by failed 716(23)
717(23)	Terminates Emeryville	Passengers to thruway service

CN Heat Orders - Weather

22JUL25: Trains were delayed on the following subdivisions due to CN heat orders implemented between 1000AM-CT and 1000PM-CT on July 22 through July 24: Centralia, Cairo, Fulton, Shelby, Yazoo, McComb, and Beaumont.

Train	Delay	Comment
58(22)	1'09"	
59(21)	1'03"	
391(22)	10"	
392(22)	11"	
58(23)	1'01"	
392(23)	10"	
391(23)	13"	
58(24)	54"	
391(24)	12"	
392(24)	21"	

Maintenance of Way Highlights

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike DMG// MP372.5
7 (8)	WTN	348		Hot axle

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 14(24) Passenger Removal at Goleta, California – Improper Behavior

24JUL25, Passenger on PNR 204E4C, traveling from Santa Barbara, CA to Oakland, CA was removed from the train by the Conductor after refusing to move to assigned seat. Passenger called the Conductor a racist and spit at her. Amtrak Police notified.

Delay: 14 (24) None

Train 577(24) Passenger Removal at Irvine, California – Refusal to Pay

24JUL25, Passenger on PNR 457BD6, traveling from Old Town San Diego, CA to San Juan Capistrano, CA passenger stayed onboard and changed destination to Santa Ana, CA then to Fullerton, CA but refused to purchase additional ticket. Passenger was asked to exit train at Irvine, CA. Amtrak Police Notified.

Delay: 577 (24) NONE

Train 577(24) Passenger Removal at Irvine, California – Refusal to Pay

24JUL25, Passenger on PNR 45173D, traveling from Old Town San Diego, CA to San Juan Capistrano, CA passenger stayed onboard and changed destination to Santa Ana, CA then to Fullerton, CA but refused to purchase additional

ticket. Passenger was asked to exit train at Irvine, CA. Amtrak Police Notified.

Delay: 577 (24) NONE

Train 319(24) Passenger Removal at Kirkwood, Missouri – Improper Conduct

24JUL25, Passenger on PNR 430923, traveling from Chicago, IL to Independence, MO was removed at Kirkwood MO by local Police Department. Passenger continued to disturb the comfort of other passengers using vulgar language. Amtrak Police Notified.

Delay: 319 (24) 3"

Train 5(22) Passenger Removal at Roseville, California - Other

24JUL25, Passenger on PNR 43771B, traveling from Denver, CO to Sacramento, CA was removed by Amtrak Police at Roseville, CA due to a warrant for arrest. Amtrak Police notified.

Delay: 5 (2) 12"

Train 5(23) Passenger Removal at Glenwood Springs, Colorado – Improper Conduct

24JUL25, Passengers on PNR 73D07D, traveling from Winter Park / Fraser, CO to Martinez, CA. had multiple incidents onboard with both Conductor and Assistant Conductor regarding their conduct. They became combative and refused to follow direction of Conductor and removed at Glenwood Springs, CO by the local Police department. Amtrak Police notified.

Delay: 5 (23) 5"

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/24/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	295	28	91%	6,929	624	91%	85,698	6,649	92%
Northeast Corridor	98%	78	13	83%	1,823	253	86%	23,008	2,486	89%
Acela	98%	20	5	75%	505	90	82%	6,420	858	87%
Northeast Regional	98%	58	8	86%	1,318	163	88%	16,588	1,628	90%
State Supported	98%	190	13	93%	4,447	241	95%	53,870	2,754	95%
Long Distance	98%	27	2	93%	659	130	80%	8,682	1,403	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/24/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	295	28	91%	6,929	624	91%	85,698	6,649	92%
Northeast Corridor	98%	78	13	83%	1,823	253	86%	23,008	2,486	89%
Acela	98%	20	5	75%	505	90	82%	6,420	858	87%
Northeast Regional	98%	58	8	86%	1,318	163	88%	16,588	1,628	90%
On Spine Northeast Regional	98%	30	4	87%	685	81	88%	8,419	859	90%
Richmond / Newport News / Norfolk	98%	12	4	67%	281	67	76%	3,461	531	85%
Roanoke	98%	4	-	100%	96	10	90%	1,182	160	86%
Springfield Shuttles	98%	12	-	100%	256	5	98%	3,526	78	98%
State Supported	98%	190	13	93%	4,447	241	95%	53,870	2,754	95%
Borealis	98%	2	-	100%	48	6	88%	579	65	89%
Capitol Corridor	98%	28	-	100%	628	24	96%	7,088	159	98%
Carolinian	98%	2	1	50%	48	9	81%	594	51	91%
Cascades	98%	14	1	93%	336	17	95%	4,037	285	93%
Downeaster	98%	10	-	100%	236	1	100%	2,824	45	98%
Empire	98%	20	2	90%	480	33	93%	6,366	333	95%
Adirondack	98%	2	-	100%	48	2	96%	594	43	93%
Berkshire Flyer	98%	-	-	100%	9	2	78%	15	4	73%
Ethan Allen Express	98%	2	1	50%	48	6	88%	594	40	93%
Maple Leaf	98%	2	-	100%	48	3	94%	594	57	90%
New York - Albany	98%	10	-	100%	231	8	97%	3,382	95	97%
New York - Niagara Falls	98%	4	1	75%	96	12	88%	1,187	94	92%
Heartland Flyer	98%	2	-	100%	44	1	98%	586	17	97%
Hiawatha	98%	12	1	92%	279	11	96%	3,392	126	96%
Illinois	98%	12	-	100%	310	26	92%	4,077	282	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	96	3	97%	1,176	46	96%
Illini / Saluki	98%	4	-	100%	95	8	92%	1,175	44	96%
Lincoln Service	98%	4	-	100%	119	15	87%	1,726	192	89%
Keystone	98%	27	4	85%	560	33	94%	6,874	421	94%
Lincoln / Missouri	98%	2	-	100%	48	9	81%	588	84	86%
Michigan	98%	10	-	100%	236	19	92%	2,840	273	90%
Blue Water	98%	2	-	100%	48	5	90%	590	87	85%
Pere Marquette	98%	2	-	100%	46	2	96%	592	27	95%
Wolverine	98%	6	-	100%	142	12	92%	1,658	159	90%
Missouri	98%	2	-	100%	46	1	98%	572	15	97%
Pacific Surfliner	98%	24	2	92%	576	15	97%	6,354	237	96%
Pennsylvanian	98%	2	1	50%	48	8	83%	594	68	89%
Piedmont	98%	8	-	100%	191	1	99%	2,360	33	99%
San Joaquins	98%	11	1	91%	285	21	93%	3,551	202	94%
Vermont	98%	2	-	100%	48	6	88%	594	58	90%
Long Distance	98%	27	2	93%	659	130	80%	8,682	1,403	84%
Auto Train	98%	2	-	100%	48	6	88%	582	99	83%
California Zephyr	98%	2	-	100%	48	15	69%	591	137	77%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	20	8	60%	252	52	79%
City Of New Orleans	98%	2	-	100%	48	6	88%	580	52	91%
Coast Starlight	98%	2	-	100%	50	4	92%	597	89	85%
Crescent	98%	2	-	100%	48	4	92%	594	68	89%
Empire Builder	98%	4	-	100%	91	13	86%	1,142	146	87%
Floridian	98%	2	-	100%	46	15	67%	503	176	65%
Lake Shore Ltd	98%	2	-	100%	48	16	67%	992	117	88%
Palmetto	98%	2	-	100%	48	4	92%	592	38	94%
Silver Meteor	98%	2	2		48	12	75%	590	120	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	-	100%	48	12	75%	592	149	75%
Sunset Ltd	98%	-	-	100%	20	6	70%	250	45	82%
Texas Eagle	98%	2	-	100%	48	9	81%	664	90	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/24/25										
Day			Month to Date			Year to Date				
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	11	96%	6,957	190	97%	85,736	2,062	98%
Northeast Corridor	98%	78	2	97%	1,823	49	97%	22,960	647	97%
Acela	98%	20	1	95%	505	14	97%	6,422	170	97%
Northeast Regional	98%	58	1	98%	1,318	35	97%	16,538	477	97%
State Supported	98%	190	5	97%	4,448	77	98%	53,855	897	98%
Long Distance	98%	28	4	86%	686	64	91%	8,783	516	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/24/25										
Day			Month to Date					Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	11	96%	6,957	190	97%	85,736	2,062	98%
Central Division	98%	66	6	91%	1,578	78	95%	19,617	685	97%
Northeast Division	98%	93	3	97%	2,207	47	98%	28,223	661	98%
Southeast Division	98%	68	1	99%	1,532	41	97%	18,962	449	98%
Southwest Division	98%	69	1	99%	1,640	24	99%	18,934	267	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/24/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	11	96%	6,957	190	97%	85,736	2,062	98%
Central Division	98%	66	6	91%	1,578	78	95%	19,617	685	97%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	52	1	98%	595	3	99%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	27	5	81%	636	55	91%	7,912	442	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	1	50%	48	2	96%	572	5	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	23	-	100%	296	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	47	-	100%	576	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	140	4	97%	1,703	13	99%
MSP	98%	1	-	100%	24	1	96%	285	7	98%
PDX	98%	5	-	100%	116	1	99%	1,428	36	97%
PNT	98%	3	-	100%	71	1	99%	818	8	99%
PTH	98%	1	-	100%	24	-	100%	295	6	98%
QCY	98%	2	-	100%	46	-	100%	576	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	193	10	95%	2,320	123	95%
SPK	98%	1	-	100%	24	-	100%	305	2	99%
STL	98%	3	-	100%	82	3	96%	1,159	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	48	-	100%	569	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	93	3	97%	2,207	47	98%	28,223	661	98%
ALB	98%	7	-	100%	168	1	99%	2,077	26	99%
BON	98%	5	-	100%	118	-	100%	1,382	3	100%
BOS	98%	16	-	100%	426	8	98%	5,543	130	98%
BRK	98%	2	-	100%	82	-	100%	1,343	10	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	24	-	100%	295	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	41	-	100%	568	-	100%
HFD	98%	2	-	100%	34	-	100%	180	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	24	1	96%	295	6	98%
NFL	98%	2	-	100%	48	-	100%	594	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	111	-	100%	1,518	35	98%
NYP	98%	40	3	93%	929	36	96%	11,923	421	96%
POR	98%	3	-	100%	33	-	100%	33	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	22	-	100%	293	1	100%
SPG	98%	5	-	100%	116	1	99%	1,812	20	99%
TWO	98%	1	-	100%	24	-	100%	294	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	68	1	99%	1,532	41	97%	18,962	449	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	117	1	99%	1,471	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/24/25										
Day				Month to Date				Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	11	96%	6,957	190	97%	85,736	2,062	98%
Southeast Division	98%	68	1	99%	1,532	41	97%	18,962	449	98%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	270	2	99%	3,215	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	24	1	96%	291	12	96%
MIA	98%	2	-	100%	46	4	91%	571	32	94%
NFK	98%	3	-	100%	68	2	97%	818	5	99%
NOL	98%	2	-	100%	53	1	98%	660	21	97%
NPN	98%	2	-	100%	48	1	98%	567	4	99%
PGH	98%	1	-	100%	24	-	100%	296	3	99%
PHL	98%	5	-	100%	103	4	96%	1,269	37	97%
RGH	98%	4	-	100%	88	-	100%	1,191	5	100%
RNK	98%	2	-	100%	43	-	100%	560	8	99%
RVM	98%	1	-	100%	24	-	100%	288	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	22	1	95%	278	1	100%
SFA	98%	1	-	100%	24	-	100%	291	18	94%
WAS	98%	25	1	96%	568	24	96%	7,043	271	96%
Southwest Division	98%	69	1	99%	1,640	24	99%	18,934	267	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	24	-	100%	297	-	100%
BFD	98%	5	-	100%	141	-	100%	1,764	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	24	4	83%	304	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	23	-	100%	329	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	72	-	100%	868	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	-	100%	226	2	99%	2,285	64	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	21	-	100%	292	-	100%
OKJ	98%	12	1	92%	266	11	96%	3,119	72	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	315	2	99%	3,546	14	100%
SAN	98%	12	-	100%	282	4	99%	2,704	26	99%
SAS	98%	1	-	100%	24	1	96%	293	3	99%
SJC	98%	7	-	100%	167	-	100%	1,907	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	48	-	100%	581	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	6	-	100%	53	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT DA.. 7/24/2025 12:00..	Diesel Loc omotive		High Speed Trainset			Electric Locomotives			Sup erline r II	Cab Car			Amfl eet I	Sup erlin er I	Surfl iner	Caltr ans Loc..	Calif ornia Car..	Gran d To tal
	ENG	MTI	ENG	CAR	MTI	ENG	CAR	MTI	CAR	ENG	CAR	CCR	CAR	CAR	CAR	ENG	CAR	
Computer Fault	35		24		103													162
Air/Brake Problems	59					33				19		6	28					145
ACSES Failure		15						31				41						87
Food Service/Smal..									78									78
Traction Motor Pro..	50		3															53
Engine Dead/Shut ..	51																	51
HEP Problems	43						3											46
Door Problems				8							3		8		20		5	44
MCB Tripping						28		8										36
Car Hot: Air Condi..														35				35
M/U Trainline Cabl..	29																	29
Air Compressor Pr..	25																	25
Electrical Problems	25																	25
I-ETMS Problem	20												5					25
Loading Problems	4															12		16
ATS - Automatic T..	11																	11
Cab Signal Failure	10																	10
Reverser Problems	10																	10
Rough Ride				10														10
Interior Fixtures/A..													7					7
Tilt System Proble..				6														6
Dragging/Loose E..				3														3
Grand Total	372	15	27	27	103	61	3	39	78	19	3	47	48	35	20	12	5	914