



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, July 29, 2025

Rules:5-54



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/28/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	298	21	93.0%	8,053	960	88.1%	86,761	8,629	90.1%
Central Division	91.5%	65	4	93.8%	1,834	221	87.9%	19,863	1,961	90.1%
Northeast Division	95.0%	95	9	90.5%	2,538	340	86.6%	28,493	3,103	89.1%
Southeast Division	94.5%	68	6	91.2%	1,771	208	88.3%	19,201	1,922	90.0%
Southwest Division	90.5%	70	2	97.1%	1,910	191	90.0%	19,204	1,643	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/28/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	103,348	32,562	68%	2,903,741	925,134	68%	28,289,593	7,643,435	73%
Northeast Corridor	80%	46,443	14,583	69%	1,243,189	375,524	70%	12,543,599	3,252,170	74%
Acela	82%	9,411	2,247	76%	250,778	73,466	71%	2,604,695	628,132	76%
Northeast Regional	78%	37,032	12,336	67%	992,411	302,058	70%	9,938,904	2,624,038	74%
Richmond / Newport News / Norfolk	73%	12,109	5,073	58%	317,888	132,460	58%	3,208,040	1,104,997	66%
Springfield Shuttles	89%	413	47	89%	12,517	2,889	77%	178,514	27,533	85%
Roanoke	70%	2,860	1,834	36%	82,687	24,492	70%	836,864	221,717	74%
On Spine Northeast Regional	83%	21,650	5,382	75%	579,319	142,217	75%	5,715,486	1,269,791	78%
State Supported	80%	43,428	9,677	78%	1,286,037	332,527	74%	12,098,043	2,692,580	78%
Borealis	60%	506	72	86%	17,377	9,794	44%	174,084	72,972	58%
Capitol Corridor	90%	3,462	109	97%	94,485	7,055	93%	903,680	95,759	89%
Carolinian	60%	1,103	700	37%	30,179	15,129	50%	345,989	143,553	59%
Cascades	60%	2,639	1,177	55%	85,194	24,754	71%	768,074	262,780	66%
Downeaster	82%	1,551	74	95%	51,986	10,321	80%	430,668	103,314	76%
Empire	83%	5,885	1,837	69%	165,164	61,526	63%	1,627,146	363,822	78%
Adirondack	75%	405	255	37%	11,601	6,510	44%	89,596	29,209	67%
Ethan Allen Express	85%	641	366	43%	17,958	11,952	33%	163,169	45,276	72%
Maple Leaf	75%	912	435	52%	24,987	15,307	39%	221,064	70,470	68%
New York - Albany	90%	2,525	522	79%	65,834	15,906	76%	752,810	119,340	84%
New York - Niagara Falls	75%	1,402	259	82%	40,491	9,517	76%	394,324	96,416	76%
Berkshire Flyer	60%	0	0	-	4,293	2,334	46%	6,183	3,111	50%
Heartland Flyer	70%	273	134	51%	7,675	6,077	21%	67,194	32,140	52%
Hiawatha	90%	1,891	0	100%	60,620	7,006	88%	511,132	66,371	87%
Illinois	78%	2,375	386	84%	75,092	25,427	66%	745,504	182,504	76%
Carl Sandburg / Illinois Zephyr	80%	526	77	85%	13,834	2,966	79%	120,512	16,055	87%
Illini / Saluki	80%	831	67	92%	25,524	5,689	78%	263,821	34,560	87%
Lincoln Service	75%	1,018	242	76%	35,734	16,772	53%	361,171	131,889	63%
Keystone	92%	8,251	1,690	80%	216,460	21,779	90%	2,181,707	296,781	86%
Lincoln / Missouri	60%	870	684	21%	24,852	16,018	36%	218,829	120,899	45%
Michigan	69%	2,282	547	76%	70,199	18,094	74%	588,214	164,553	72%
Blue Water	70%	575	0	100%	17,254	4,730	73%	145,853	42,622	71%
Pere Marquette	85%	356	0	100%	9,087	1,415	84%	78,163	10,047	87%
Wolverine	65%	1,351	547	60%	43,858	11,949	73%	364,198	111,884	69%
Missouri	80%	200	4	98%	7,417	4,244	43%	66,249	23,732	64%
Pacific Surfliner	85%	7,266	962	87%	213,065	32,058	85%	1,747,674	281,409	84%
Pennsylvanian	72%	922	336	64%	26,670	8,885	67%	262,685	71,266	73%
Piedmont	73%	799	9	99%	27,915	8,896	68%	337,106	82,318	76%
San Joaquins	73%	1,982	301	85%	74,349	37,036	50%	738,161	211,406	71%
Vermonter	75%	1,171	655	44%	37,338	18,428	51%	383,947	117,001	70%
Long Distance	57%	13,477	8,302	38%	374,515	217,083	42%	3,604,426	1,695,083	53%
Auto Train	57%	791	428	46%	22,753	7,563	67%	225,525	138,766	38%
California Zephyr	45%	1,301	777	40%	33,526	24,861	26%	296,169	131,361	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	340	81	76%	7,823	4,072	48%	81,873	41,087	50%
City Of New Orleans	75%	761	304	60%	17,577	8,821	50%	192,377	57,030	70%
Coast Starlight	65%	1,152	164	86%	29,997	10,086	66%	315,798	130,832	59%
Crescent	60%	1,065	574	46%	29,240	10,523	64%	261,308	68,047	74%
Empire Builder	55%	1,447	1,152	20%	33,824	20,809	38%	288,815	129,312	55%
Floridian	40%	1,408	1,408	0%	42,668	35,768	16%	406,023	299,548	26%
Lake Shore Ltd	70%	1,199	138	88%	31,254	10,742	66%	303,091	83,370	72%
Palmetto	65%	963	795	17%	27,782	13,850	50%	295,930	114,966	61%
Silver Meteor	45%	509	406	20%	28,033	18,345	35%	277,419	146,251	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	982	953	3%	29,760	24,655	17%	242,696	151,581	38%
Sunset Ltd	50%	294	203	31%	7,824	3,826	51%	79,463	29,622	63%
Texas Eagle	60%	1,265	919	27%	32,454	23,162	29%	280,344	150,814	46%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 28, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	203,362	2,918,797	697	1,915,543	31,362,917	611

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	10,453	846,415	123	101,537	9,174,494	111
INFRASTRUCTURE PLANNED	90	6,610	846,415	78	93,756	9,174,494	102
FLEET RELIABILITY	83	35,844	2,918,797	123	304,724	31,362,917	97
TRAIN OPERATIONS	382	150,455	2,918,797	515	1,415,526	31,362,917	451

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

Northeast Corridor Service Adjustments - Heat Related Cancellations

27JUL25: Due to the impending forecast of extreme temperatures over 98 degrees and storms along the Northeast Corridor for Tuesday July 29th & Wednesday July 30th 2025 the following service adjustments have been made: 112(29, 30) 192(29,30) 178(29,30) 131(29,30) 133(29,30) and 173(29,30) are cancelled in their entirety. This will allow protect regional trainsets in BOS, NYP & WAS.

Acela service cancellations were added as of 7/27/25 for trains 2159(29-30) and 2162(29-30) cancelled in their entirety.

Train	Delay	Comment
112(29-30)	Cancelled	
192(29-30)	Cancelled	
178(29-30)	Cancelled	
131(29-30)	Cancelled	
133(29-30)	Cancelled	
173(29-30)	Cancelled	
2159(29-30)	cancelled	
2162(29-30)	cancelled	

New Haven to Boston Main Line - Bridge Strike

28JUL25: At 453P-ET A vehicle struck the bridge at Gypsy Lane., MP 16.80 New Haven to Boston main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 549P-ET, the bridge was inspected and released for normal service.

Washington Terminal Switch Failure - Signal

28JUL25: Washington Terminal reported a bad I-Joint over 324/326 switches causing TOL across K Interlocking blocking all routes in and of Washington Terminal. Which caused delays to multiple trains in and out of Washington Terminal.

Train	Delay	Comment
2159(28)	31"	
131(28)	22"	
5 Marcs	05"-18"	
186(28)	7"	
176(28)	18"	
171(28)	35"	

Train 138(28) South of Petersburg, VA- Freight Train Interference

28JUL25: Train 138(28) was delayed on CSX North End subdivision at MP 26.1 due to being blocked from the station track by a track inspector.

Train	Delay	Comment
138(28)	38"	

Train 97(28) New York, NY - Initial Terminal Delay

28JUL25: Train 97(28) was delayed departing New York Station waiting for cars 62506 and 62003 off late train 97(27).

Train	Delay	Comment
97(28)	1'17"	

Train 41(27) East of Cumberland, MD - Freight Train Interference

28JUL25: Train 41(27) was delayed following freight train C782/26 at MP 175.5 east of Cumberland station on the CSX Cumberland subdivision.

Train	Delay	Comment
41 (27)	30"	

NS Piedmont Heat Orders - Miscellaneous Amtrak Responsible

28JUL25: The NS issues Heat Orders on the Piedmont subdivision from 2P-ET to 6P-ET from MP 42.1NC-42.8NC, 44.4NC-44.7NC, and 46.1NC-46.7NC at 25 MPH.

Train	Delay	Comment
77 (28)	02"	
79 (28)	05"	

New Haven to Boston Mainline - North of Old Saybrook, CT - Signal

28JUL25: As of 10:11AM ET Boston Chief reported micro lock at MP 115.0/Crescent interlocking. C & S was on scene attempting to make repairs. As of 142P-ET The CPU board at location A was replaced at Crescent interlocking and was functioning as intended.

Train	Delay	Comment
170 (28)	21"	
93 (28)	20"	
2152 (28)	20"	
CDOT-1	31"	
2155 (28)	5"	
2159 (28)	8"	
2150 (28)	18"	
190 (28)	12"	
170 (28)	10"	
CDOT-2	18"	

CSX Heat Orders - Northeast and Southeast Regions

28JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Grand Rapids, Monon, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, North End, Old Main Line, Peninsula, RF&P, Rochester, Syracuse Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
79 (28)	49"	
64 (28)	1'02"	
63 (28)	15"	
52 (28)	20"	
141 (28)	33"	
98 (28)	51"	
125 (28)	14"	
186 (28)	05"	
90 (28)	24"	
53 (28)	32"	
283 (28)	19"	
138 (28)	49"	
281 (28)	52"	
89 (28)	52"	
95 (28)	24"	
40 (28)	35"	
41 (27)	40"	
40 (27)	34"	

Northeast Corridor Heat Restrictions - Miscellaneous Amtrak Responsible

28JUL25: The following heat orders are in effect July 25th 2025:

NYP B Track Lack Int Limits 25MPH 12PM to 730PM

NYP 5 Track Hunter Int Limits 25MPH 12PM to 730PM

NYP 1 Track Ham Int Limits 25MPH 12PM to 730PM

HUD 2 Track MP 7.0 and MP 8.0 25MPH 12PM to 730PM

HUD1 Track Inwood Int Limits 25MPH 12PM to 730PM

Train	Delay	Comment
645 (28)	03"	
2108 (28)	05"	
2122 (28)	04"	
197 (22)	07"	
193 (28)	10"	
2169 (28)	10"	
2172 (28)	05"	
2167 (28)	06"	
148 (28)	10"	
652 (28)	03"	
173 (28)	09"	
129 (28)	03"	
2170 (28)	10"	
651 (28)	05"	
94 (28)	05"	
184 (28)	08"	
85 (28)	09"	
85 (28)	09"	
283 (28)	16"	
649 (28)	05"	
2121 (28)	08"	
647 (28)	15"	
93 (28)	04"	
133 (28)	03"	
2159 (28)	05"	
174 (28)	04"	

Train 607(28) Philadelphia, PA - Engine Failure

28JUL25: Train 607(28) was delayed departing Philadelphia due to having brake cylinder issues.

Train	Delay	Comment
607 (28)	34"	

Train 42(28) Pittsburgh, PA - Engine Failure

28JUL25: Train 42(28) experienced engine failure with E/101 at initial terminal Pittsburgh PA. Freight engine 1095 was secured from Norfolk southern to deadhead the equipment to Harrisburg PA. In Harrisburg PA E/638 was added. Buses were sourced for customers from Pittsburgh to Harrisburg.

UPDATE: As of 727A-ET Mechanical was able to get E/101 running and the train was reinstated between Pittsburgh and Harrisburg.

Train	Delay	Comment
42 (28)	33"	

Train 601(28) - Philadelphia, PA - Initial Terminal Delay

28JUL25: Train 601(28) was delayed at its initial terminal in Philadelphia, PA due to a late release from mechanical.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
601(28)	23"	

Train 151(28) - New York Penn Station/Sunnyside Yard - NY - Initial Terminal Delay

28JUL25: Train 151(28) was delayed at its initial terminal at New York Penn Station due to being turned off late arriving 124(27).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
151(28)	53"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold

371(19) - 10 oversold

305(18) - 13 oversold

300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold

371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold

371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.

- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.

- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train

Delay

Comment

301 (15)	Cancelled, with alt	CHI-STL
302 (15)	Cancelled, with alt	STL-CHI
307 (14)	Cancelled, with alt	CHI-STL
301 (16Jul-04Aug)	Cancelled, with alt	CHI-STL
306 (16Jul-04Aug)	Cancelled, with alt	STL-CHI
381 (05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382 (05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Train 718(28) West of Modesto, CA - Police Related

28JUL25: Train 718(28) was delayed 10 miles west of Modesto on the BNSF Stockton subdivision due to a vehicle on the tracks in the vicinity of Escalon/MP 1101.1. Once the vehicle was removed and the tracks were inspected, 718(28) continued to Modesto.

Train	Delay	Comment
703 (28)	22"	
718 (28)	1'03"	

Train 22(28) South of Hope, AR - Freight Train Interference

28JUL25: Train 22(28) was delayed 12 miles south of Hope on the UPRR Little Rock subdivision due to ILBMN-25 stopped at Fulton/MP 469.4 with brake issues. The freight crew was able to shove into the clear to provide the route for 22(28), who continued to Hope.

Train	Delay	Comment
22 (28)	38"	

Train 4(27) East of Trinidad, CO - Signal

28JUL25: Train 4(27) was delayed 31 miles east of Trinidad on the BNSF Raton subdivision at Simpson/MP 605.6 due to signal issues. The crew tested the switch and received permission to proceed east.

Train	Delay	Comment
4 (27)	38"	

Train 518(28) South of Vancouver, BC - Freight Train Interference

28JUL25: Train 518(28) was delayed three miles south of Vancouver on the CN New Westminster subdivision at Still Creek/MP 153.9 due to CN 1537 yard job working ahead.

Train	Delay	Comment
518 (28)	42"	

Train 4(27) East of Trinidad, CO - Weather

28JUL25: Train 4(27) was delayed on the BNSF Raton subdivision starting two miles west of Trinidad between MP 638.0 and MP 587.0 due flash flood warnings.

Train	Delay	Comment
4 (27)	56"	

Train 4(28) Los Angeles, CA - Engine Failure

28JUL25: Trian 4(28) was delayed departing the initial terminal of Los Angeles, CA (LAX) on the Southern California Regional Rail Authority (Metrolink) River Subdivision. There was a problem with locomotive AMTK/207 which required it to be removed from the train and replaced with AMTK/7. Once the locomotive swap was complete, trian 4(28)was able to depart LAX at 6:06 PM-PT.

Train	Delay	Comment
4 (28)	47"	

Train 354(28) East of Dowagiac, MI - Signal

28JUL25: Train 354(28) with E/56 and 5 cars was delayed on the Amtrak Michigan Line eight miles east of Dowagiac due to code line failure between MP 171.0 and the west leg of MP 147.0. Train 354(28) was delayed operating reduced speed through the area. Additionally, 355(28) with E/ID4621 and 5 cars lost their mode light on E/ID4621 at MP 156.5 account of potential code line failure and cut out ITCS on E/ID4621 at MP 161.0. Train 355(28) continued to Chicago operating per Rule 596. At Chicago, E/ID4621 was bad ordered for hydrostatic oil leak fault.

Train	Delay	Comment
354 (28)	35"	
355 (28)	1'18"	

Train 8(28) Seattle, WA - Servicing

28JUL25: Train 8(28) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. A protect locomotive, AMTK/333, was added to train 8(28) to be ferried to Spokane, WA where it would be removed and added to train 7(27), which was having problems with locomotive AMTK/317. With the protect locomotive added, trian 8(28) was able to depart SEA at 5:51 PM-PT.

Train	Delay	Comment
8 (28)	56"	SEA - Initial Terminal
8 (28)	Est. 30"	SPK - remove protect locomotive

Train 58(28) North of Jackson, MS - Freight Train Interference

28JUL25: Train 58(28) was delayed on the CN Yazoo subdivision at Flora/MP 203.7 due to A48971-29 in emergency at MP 201.9 with air issues. The crew walked the train and was working to make repairs. CN mechanical was enroute to assist. The freight crew identified an air hose disconnected and attached the air hose to restore air and operate into the clear. Train 58(28) continued to Yazoo.

Train	Delay	Comment
58 (28)	1'02"	

Train 6(28) East of Reno, NV - Trespasser Incident

28JUL25: At approximately 4:09 PM-PT train 6(28) - operating with camera equipped locomotive AMTK/148, AMTK/146 and 10 cars - struck a vehicle at MP 258.23 on the Union Pacific Railway Nevada Subdivision near the city of Sparks, NV, Storey County, Nevada. This incident occurred on a public highway crossing at grade, Waltham Way (US DOT 913207E); the crossing is equipped with gates, flashing lights, and audible warning devices which were observed to be working at the time the incident occurred. There were no initial reports of injuries to the 188 passengers or crew and no initial reports of damage to Amtrak equipment. Train 6(28) was operating at an estimated 70MPH on the single main track with a posted track speed of 70MPH at the time the incident occurred. Local police and fire along with Union Pacific and Amtrak management responded to the scene. Once the scene was released by authorities train 6(28) advanced to Clark siding where the train held for a relief crew. While operating to the siding, the crew noticed there was no working bell or whistle on locomotive AMTK/148. The crew also reported minor accident damage to the front pilot (cow catcher) of the locomotive. The crew swapped the order of the locomotive (flat switched) so that AMTK/146 was leading while waiting for the relief crew to arrive. Once the relief crew arrived train 6(28) was able to resume operation and proceed east. Additional delays were attributed to E/146 with a continuous persistent parking brake alarm. The crew confirmed all hand brakes were released with no MU cables crossed and had free rolling wheels. The crew continued 10 miles, re-inspected with no exceptions, and continued operating to Winnemucca.

National Response Center: 1438227
Nevada Department of Emergency Management: Called, department declined to take report account no injuries.
Google Maps Location of Incident:
<https://maps.app.goo.gl/4SXHpHQnPHVHVeVB8>
39.554017, -119.553622
Waltham Way, Sparks, NV 89434

National Response Center Number: 1438227

Train	Delay	Comment
6(28)	5'50"	

Train 8/28(27) East of Wolf Point, MT - Freight Train Interference

28JUL25: Train 8/28(27) was delayed seven miles east of Wolf Point on the BNSF Glasgow subdivision at Macon/MP 220.9, meeting BN 5935 and at Bainville/MP 158.9, meeting BN 7605.

Train	Delay	Comment
8/28(27)	30"	BN 5935
8/28(27)	14"	BN 7605

Train 355(28) North of Detroit, MI - Weather

28JUL25: Train 355(28) was delayed one mile north of Detroit on the CN Holly subdivision at D&M/MP 4.4 due to commercial power lines down on the tracks at Beaubien/MP 54.0. The Power Company responded to the scene, repaired the pole, re-hung the wires, and trains were talked through the effected area. Additional wires were reported down on the Conrail shared assets, which prolonged delays. These wires were cleared with commercial power reported down and tracks inspected, so 355(28) continued to be talked into Detroit for this reason. After 355(28) operated in the clear, train 352(28) continued to be talked through the effected area. Train 354(28) was delayed holding at Kalamazoo and Battle Creek for late arriving crew off 355(28).

Train	Delay	Comment
355(28)	2'50"	
352(28)	1'07"	
354(28)	1'44"	

Train 718(28) Oakland, CA - Engine Failure

28JUL25: Train 718(28) was delayed departing the initial terminal of Oakland, CA (OKJ) on the Union Pacific Railway Martinez Subdivision. There was a problem with locomotive CDTX/2102 showing a "low fuel pressure" warning on the displays. Technicians from Oakland Maintenance Facility (OMF) responded and were able to resolve the issue. Upon arrival at Emeryville, CA (EMY) the crew reported there was a problem with the air brake system; technicians from OMF responded a second time and worked to resolve the problem. While enroute between Richmond, CA (RIC) at Martinez, CA (MTZ) the crew reported reduced tractive effort. With the continued mechanical issues the following recovery plan was enacted:

- 715(28) Terminate Martinez, CA - Passengers to 717(28)
- 718(28) swap equipment with 715(28) at Martinez, CA and continue to Bakersfield, CA (BFD)
- 717(28) couple to disabled equipment and tow back to Oakland, CA (OKJ)
- 718(28) refueled at Calwa Yard (near Fresno) as equipment did not return to OMF for servicing.

Train	Delay	Comment
718(28)	11"	OKJ
718(28)	1'07"	EMY
715(28)	Terminate MTZ	Pax to 717(28)
718(28)	20"	MTZ - Equipt Swap
717(28)	47"	MTZ - couple to disabled 718(28) equipt
718(28)	45"	FNO - Fuel

Train 715(28) Antioch-Pittsburg, CA - Police Related

28JUL25: Train 715(28) was delayed at Antioch, CA (ACA) on the Burlington Northern Santa Fe Railway Stockton Subdivision. The local fire department had requested all train traffic halted while attending to a fire near the track ahead. Once the hold was released trian 715(28) was able to proceed. Once underway a second fire department hold was requested to attend to a "hot spot" that had flared back up. Once the second hold was released, train 715(28) was able to proceed at 7:04 PM-PT.

Train	Delay	Comment
715(28)	1'35"	Total Delay

Train 22(28) Fort Worth, TX - Fueling

28JUL25: Train 22(28), E/69-E/68 & 6 cars, was delayed at Fort Worth, TX waiting on fuel vendor to fuel Train 21/421(27), engines, E/63-E/22 first, and then 22(28)'s power, E/69-E/68.

Train	Delay	Comment
22(28)	1'00"	
21/421(27)	13"	

Train 517(28) Tukwila, WA - Car Failure

28JUL25: Train 517(28) was delayed at Tukwila, WA (TUK) on the Burlington Northern Santa Fe Railway Seattle (MPXX) subdivision. There was a problem with the air brake system on car C/7200 causing multiple undesired emergency brake applications. Technicians from Seattle Mechanical arrived to assist in resolving the issue. Once the issue was resolved train 517(28) was able to resume operation.

Train	Delay	Comment
517(28)	1'56"	
507(28)	16"	Blocked at TUK by 517
506(28)	1'05"	Late turn from inbound 517(28)

Train 5(27) East of Fraser-Winter Park, CO - Freight Train Interference

28JUL25: Train 5(27) was delayed 12 miles east of Fraser-Winter Park on the BNSF Moffatt Tunnel subdivision at East Portal/MP 50.1, meeting NS 8087 with a tunnel flush.

Train	Delay	Comment
5 (27)	30"	

Train 2/422(27) East of Tucson, AZ - Freight Train Interference

28JUL25: Train 2/422(27) was delayed east of Tucson, AZ/MP983.9, on the UPRR Lordsburg Subdivision, following UP 7450 between MP1000 and MP1032 and further delayed following UP 7666 between MP1032 and MP1061. UPRR 7401 was tied down at Fenner/MP1035 with loco issues resulting in congestion through the area.

Train	Delay	Comment
2/422 (27)	1'01"	

Train 4(27) East of Albuquerque, NM - Car Failure

29JUL25: Train 4(27) with E/188-151 and 9 cars reported the water dumping in the diner C/38049 after departing Albuquerque and suspected a leak. Plans were implemented to water C/38049 at La Junta and or Kansas City. Customer service recovery was enacted with pizza delivered for dinner at La Junta for all passengers.

WBS#: B.TR.100150.5938

Train 21/421(27) Dallas, TX - PTC

28JUL25: Train 21/421(27), E/63-E/22 & 8 cars, was delayed at Dallas, TX/MP214.4, on the UPRR Dallas Subdivision, due to PTC issues arriving into Dallas station. The engineer was able to resolve issue after logging off and then back in to PTC on E/63. Train 21/421(27) was then further delayed resolving an issue with the TRE GTB's.

Train	Delay	Comment
21/421 (27)	31"	

Train 1340(28) East of Red Wing, MN - Temporary Speed Restrictions

28JUL25: Train 1340(28) was delayed on the CPKC River subdivision between MP 364.9 and MP 326.8 due to operating with temporary speed restrictions.

Train	Delay	Comment
1340 (28)	30"	
1333 (28)	29"	
8/28 (26)	33"	
7/27 (28)	20"	

Train 5(27) East of Fort Morgan, CO - Freight Train Interference

28JUL25: Train 5(27) was delayed at MP431.4, 33 miles east of Fort Morgan, CO, on the BNSF Akron Subdivision, due to BNSF 6546 stopped in emergency ahead. Train 5(27) held for BNSF 6546 to inspect consist, restore air and operate in the clear.

Train	Delay	Comment
5 (27)	39"	

Train 1(26)/421(25) Palm Springs, CA - Freight Train Interference

28JUL25: Train 1(26)/421(25) was delayed at Myoma/MP605, 17 miles east of Palm Springs, CA, on the UPRR Yuma Subdivision, due to UP8945 actuated dragging equipment detector on No 2 Track and then held for UP 7660 to clear ahead on No 1 in order to cross-over to No 2 Track around UP 8495 to route into Palm Springs, CA.

Train	Delay	Comment
1(26)/421(25)	51"	

Train 517(28) Seattle, WA - Servicing

28JUL25: Train 517(28) was delayed at Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. Train 517(28) was delayed for technicians to service the septic system and water the entire train. Once technicians completed their work, train 517(28) departed SEA at 1:11 PM-PT.

Train	Delay	Comment
517(28)	30"	

UPRR Heat Restrictions Springfield Subdivision - Texas Eagle/Lincoln/Missouri River Runner Services

28JUL25: UPRR level 2 heat restrictions were in effect on the Springfield Subdivision 1000AM-CT until 900PM-CT between Bloomington-Normal, IL/MP124 and MP189, 4 miles south of Springfield, IL. Trains were delayed operating 50MPH through the affected areas.

Train	Delay	Comment
22(27)/422(25)	25"	
319(28)	28"	
305(28)	25"	
318(28)	38"	
21(28)	30"	

Train 521(28) West of Richmond, CA - Debris Strike

28JUL25: Train 521(28), operating with camera-equipped locomotive E/C2012 and 4 cars was delayed at MP 7.1/UPRR Martinez Subdivision, 4.9 miles west of Richmond, as a result of striking a shopping cart (filled with bottles and cans) that had been placed on the tracks. There were no injuries reported. Crew reported some air hoses had become disconnected. Train was on the move once the hoses had been reconnected followed by a successful air test. Amtrak Police notified.

Train	Delay	Comment
521(28)	12"	

Maintenance of Way Highlights

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Train 55(28) St. Albans, VT - M of W Work

28JUL25: Train 55(28) was delayed between St Albans and Waterbury VT due to track work.

Train	Delay	Comment
55 (28)	38"	

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Train 11(28) Portland, OR - M of W Work

28JUL25: Trian 11(28) was delayed at Portland, OR (PDX) on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. A Union Pacific Maintenance of Way (MOW) crew overstayed their hours south of PDX while replacing a rail. Once the MOW crew completed their work and released the track, train 11(28) was able to depart PDX at 3:03 PM-PT.

Train	Delay	Comment
11(28)	41"	

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/28/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	298	21	93.0%	8,053	960	88.1%	86,761	8,629	90.1%
Central Division	91.5%	65	4	93.8%	1,834	221	87.9%	19,863	1,961	90.1%
Northeast Division	95.0%	95	9	90.5%	2,538	340	86.6%	28,493	3,103	89.1%
Southeast Division	94.5%	68	6	91.2%	1,771	208	88.3%	19,201	1,922	90.0%
Southwest Division	90.5%	70	2	97.1%	1,910	191	90.0%	19,204	1,643	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/28/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	298	21	93.0%	8,053	960	88.1%	86,761	8,629	90.1%
Central Division	91.5%	65	4	93.8%	1,834	221	87.9%	19,863	1,961	90.1%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	60	3	95.0%	603	17	97.2%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	26	2	92.3%	740	129	82.6%	8,016	1,014	87.4%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	56	3	94.6%	580	22	96.2%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	27	0	100.0%	300	4	98.7%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	55	3	94.5%	584	40	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	0	100.0%	163	9	94.5%	1,726	97	94.4%
MSP	95.0%	1	0	100.0%	28	2	92.9%	289	14	95.2%
PDX	78.0%	5	1	80.0%	136	13	90.4%	1,448	165	88.6%
PNT	94.0%	3	0	100.0%	82	3	96.3%	829	59	92.9%
PTH	96.0%	1	0	100.0%	28	0	100.0%	299	11	96.3%
QCY	94.0%	2	0	100.0%	54	0	100.0%	584	18	96.9%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	1	87.5%	225	40	82.2%	2,352	340	85.5%
SPK	92.0%	1	-	100.0%	26	1	96.2%	297	14	95.3%
STL	96.0%	3	0	100.0%	94	11	88.3%	1,171	64	94.5%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	56	0	100.0%	577	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	9	90.5%	2,538	340	86.6%	28,493	3,103	89.1%
ALB	96.0%	6	0	100.0%	168	5	97.0%	2,017	127	93.7%
BON	94.5%	5	0	100.0%	138	8	94.2%	1,402	91	93.5%
BOS	97.0%	18	0	100.0%	493	48	90.3%	5,610	514	90.8%
BRK	97.0%	2	0	100.0%	90	3	96.7%	1,351	69	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	28	6	78.6%	299	23	92.3%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	1	50.0%	49	3	93.9%	576	55	90.5%
HFD	-	2	1	50.0%	38	5	86.8%	184	18	90.2%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/28/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	298	21	93.0%	8,053	960	88.1%	86,761	8,629	90.1%
Northeast Division	95.0%	95	9	90.5%	2,538	340	86.6%	28,493	3,103	89.1%
MTR	97.0%	1	0	100.0%	28	4	85.7%	299	30	90.0%
NFL	97.0%	2	0	100.0%	56	1	98.2%	602	24	96.0%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	130	18	86.2%	1,537	152	90.1%
NYP	94.5%	41	5	87.8%	1,075	208	80.7%	12,068	1,846	84.7%
POR	-	3	2	33.3%	45	15	66.7%	45	15	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	26	4	84.6%	297	9	97.0%
SPG	95.5%	5	0	100.0%	139	9	93.5%	1,835	85	95.4%
TWO	96.0%	1	0	100.0%	28	0	100.0%	298	11	96.3%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	68	6	91.2%	1,771	208	88.3%	19,201	1,922	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	0	100.0%	136	13	90.4%	1,490	98	93.4%
DNC	-	-	-	-	1	1	0.0%	1	1	0.0%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	310	13	95.8%	3,256	101	96.9%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	28	6	78.6%	295	94	68.1%
MIA	90.0%	2	0	100.0%	53	9	83.0%	578	56	90.3%
NFK	94.5%	3	0	100.0%	79	13	83.5%	829	67	91.9%
NOL	92.0%	3	0	100.0%	63	3	95.2%	670	46	93.1%
NPN	96.0%	2	0	100.0%	56	5	91.1%	575	22	96.2%
PGH	92.0%	1	1	0.0%	28	4	85.7%	300	18	94.0%
PHL	97.0%	5	3	40.0%	118	29	75.4%	1,284	186	85.5%
RGH	97.0%	4	0	100.0%	104	3	97.1%	1,207	37	96.9%
RNK	94.0%	2	1	50.0%	51	4	92.2%	568	66	88.4%
RVM	90.0%	1	0	100.0%	28	2	92.9%	292	35	88.0%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	26	1	96.2%	282	11	96.1%
SFA	83.0%	1	0	100.0%	28	2	92.9%	295	80	72.9%
WAS	94.5%	24	1	95.8%	652	90	86.2%	7,126	971	86.4%
Southwest Division	90.5%	70	2	97.1%	1,910	191	90.0%	19,204	1,643	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	28	0	100.0%	301	7	97.7%
BFD	90.0%	6	0	100.0%	165	19	88.5%	1,788	155	91.3%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	0	100.0%	28	19	32.1%	308	95	69.2%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	27	2	92.6%	333	42	87.4%
FUL	-	-	-	-	-	-	-	12	5	58.3%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/28/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/28/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	298	21	93.0%	8,053	960	88.1%	86,761	8,629	90.1%
Southwest Division	90.5%	70	2	97.1%	1,910	191	90.0%	19,204	1,643	91.4%
GLE	-	-	-	-	-	-	-	4	4	0.0%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	84	3	96.4%	880	63	92.8%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	1	88.9%	264	34	87.1%	2,323	325	86.0%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	25	0	100.0%	296	6	98.0%
OKJ	91.0%	12	1	91.7%	308	52	83.1%	3,161	302	90.4%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	0	100.0%	365	26	92.9%	3,596	151	95.8%
SAN	90.0%	12	0	100.0%	330	23	93.0%	2,752	241	91.2%
SAS	85.0%	1	0	100.0%	28	6	78.6%	297	41	86.2%
SJC	95.0%	7	0	100.0%	195	6	96.9%	1,935	72	96.3%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	56	0	100.0%	589	27	95.4%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	6	0	100.0%	53	11	79.2%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	32	12	0	100.0%	127	15	88.2%	12	5	58.3%	127	35	72.4%
3	301	28	8	71.4%	295	58	80.3%	28	23	17.9%	291	164	43.6%
4	173	28	6	78.6%	296	71	76.0%	28	24	14.3%	295	155	47.5%
5		28	14	50.0%	298	53	82.2%	27	17	37.0%	295	100	66.1%
6	54	28	19	32.1%	298	88	70.5%	28	23	17.9%	297	105	64.6%
7		28	10	64.3%	292	46	84.2%	28	9	67.9%	287	76	73.5%
8	67	28	19	32.1%	293	111	62.1%	28	22	21.4%	291	143	50.9%
11		28	3	89.3%	300	47	84.3%	28	4	85.7%	293	65	77.8%
14		28	9	67.9%	301	91	69.8%	28	10	64.3%	299	130	56.5%
19	174	28	0	100.0%	301	33	89.0%	28	10	64.3%	300	59	80.3%
20		28	1	96.4%	301	14	95.3%	28	6	78.6%	300	48	84.0%
21		28	5	82.1%	300	39	87.0%	28	8	71.4%	294	91	69.0%
22	31	28	6	78.6%	297	43	85.5%	28	23	17.9%	296	131	55.7%
27		26	5	80.8%	288	22	92.4%	25	9	64.0%	278	95	65.8%
28		25	6	76.0%	281	71	74.7%	25	6	76.0%	280	78	72.1%
40	38	28	5	82.1%	258	38	85.3%	27	21	22.2%	253	160	36.8%
41	138	26	18	30.8%	255	113	55.7%	26	23	11.5%	251	200	20.3%
42		28	4	85.7%	301	19	93.7%	28	8	71.4%	301	82	72.8%
43	35	28	2	92.9%	301	25	91.7%	28	10	64.3%	301	70	76.7%
48		28	6	78.6%	300	54	82.0%	28	5	82.1%	300	46	84.7%
49		28	13	53.6%	301	63	79.1%	28	7	75.0%	301	54	82.1%
51		12	3	75.0%	128	25	80.5%	12	3	75.0%	122	41	66.4%
52		28	2	92.9%	295	80	72.9%	28	6	78.6%	295	153	48.1%
53	31	28	6	78.6%	295	94	68.1%	28	7	75.0%	295	147	50.2%
55	99	19	3	84.2%	208	9	95.7%	19	12	36.8%	208	51	75.5%
56	34	19	3	84.2%	208	36	82.7%	19	16	15.8%	207	59	71.5%
58		28	2	92.9%	293	23	92.2%	28	9	67.9%	290	62	78.6%
59		28	11	60.7%	292	63	78.4%	27	10	63.0%	288	37	87.2%
63	26	28	18	35.7%	301	64	78.7%	28	25	10.7%	301	157	47.8%
64	43	28	0	100.0%	301	11	96.3%	28	6	78.6%	301	74	75.4%
66		28	4	85.7%	299	57	80.9%	28	3	89.3%	297	39	86.9%
67		19	1	94.7%	207	18	91.3%	19	5	73.7%	205	44	78.5%
68	28	28	4	85.7%	301	30	90.0%	28	20	28.6%	301	124	58.8%
69		28	2	92.9%	301	22	92.7%	27	8	70.4%	296	35	88.2%
71		27	2	92.6%	300	7	97.7%	27	9	66.7%	298	67	77.5%
72		28	4	85.7%	301	23	92.4%	28	9	67.9%	299	76	74.6%
73		28	4	85.7%	301	16	94.7%	28	12	57.1%	299	147	50.8%
74		28	3	89.3%	297	23	92.3%	28	12	57.1%	295	102	65.4%
75	15	28	3	89.3%	299	8	97.3%	27	14	48.1%	296	121	59.1%
76		28	6	78.6%	297	22	92.6%	27	18	33.3%	295	131	55.6%
77		28	2	92.9%	298	12	96.0%	28	13	53.6%	296	133	55.1%
78		28	0	100.0%	299	10	96.7%	27	9	66.7%	298	73	75.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
79	31	28	6	78.6%	301	41	86.4%	26	9	65.4%	298	107	64.1%
80	42	28	3	89.3%	301	24	92.0%	28	17	39.3%	301	90	70.1%
84		19	0	100.0%	207	8	96.1%	19	7	63.2%	206	76	63.1%
85	17	19	0	100.0%	205	16	92.2%	19	14	26.3%	204	140	31.4%
86	35	19	1	94.7%	205	23	88.8%	19	17	10.5%	205	142	30.7%
89	63	28	2	92.9%	300	36	88.0%	28	15	46.4%	298	113	62.1%
90	37	28	1	96.4%	300	12	96.0%	27	12	55.6%	295	76	74.2%
93	41	19	0	100.0%	208	14	93.3%	19	12	36.8%	207	98	52.7%
94		19	6	68.4%	208	20	90.4%	19	11	42.1%	207	77	62.8%
95	45	19	0	100.0%	208	5	97.6%	19	10	47.4%	208	91	56.3%
98		27	5	81.5%	296	20	93.2%	27	16	40.7%	296	152	48.6%
110		19	7	63.2%	206	40	80.6%	19	4	78.9%	204	43	78.9%
111		19	5	73.7%	205	52	74.6%	19	3	84.2%	203	33	83.7%
112		18	3	83.3%	199	38	80.9%	18	3	83.3%	197	24	87.8%
114		19	4	78.9%	204	55	73.0%	19	3	84.2%	200	30	85.0%
119		19	2	89.5%	202	40	80.2%	19	3	84.2%	199	30	84.9%
124	86	9	0	100.0%	93	6	93.5%	9	4	55.6%	93	20	78.5%
125	40	19	1	94.7%	208	10	95.2%	19	11	42.1%	208	118	43.3%
128		9	2	77.8%	93	27	71.0%	9	2	77.8%	93	24	74.2%
129		19	5	73.7%	206	43	79.1%	19	8	57.9%	205	46	77.6%
130		19	1	94.7%	202	20	90.1%	19	1	94.7%	199	22	88.9%
131	27	18	2	88.9%	198	34	82.8%	18	3	83.3%	196	29	85.2%
132		4	1	75.0%	44	11	75.0%	4	1	75.0%	44	7	84.1%
133	44	18	7	61.1%	205	75	63.4%	18	15	16.7%	205	108	47.3%
134	30	19	0	100.0%	207	15	92.8%	19	10	47.4%	207	101	51.2%
137	23	19	5	73.7%	208	26	87.5%	19	9	52.6%	208	84	59.6%
138	27	19	3	84.2%	207	24	88.4%	19	10	47.4%	207	53	74.4%
139	43	4	0	100.0%	44	2	95.5%	4	2	50.0%	43	12	72.1%
141		19	0	100.0%	208	3	98.6%	19	10	47.4%	208	100	51.9%
148		19	2	89.5%	208	19	90.9%	19	5	73.7%	208	44	78.8%
151	78	28	6	78.6%	298	38	87.2%	28	9	67.9%	297	102	65.7%
166		4	0	100.0%	44	15	65.9%	4	1	75.0%	44	20	54.5%
169		9	3	66.7%	93	10	89.2%	9	1	88.9%	92	9	90.2%
170	19	19	0	100.0%	207	12	94.2%	19	7	63.2%	207	52	74.9%
171	46	19	3	84.2%	208	10	95.2%	19	12	36.8%	208	106	49.0%
172		19	3	84.2%	207	16	92.3%	19	8	57.9%	205	67	67.3%
173	23	18	0	100.0%	207	26	87.4%	18	6	66.7%	207	69	66.7%
174	23	19	2	89.5%	208	6	97.1%	19	7	63.2%	207	49	76.3%
175	77	19	6	68.4%	207	36	82.6%	19	11	42.1%	206	77	62.6%
176		19	4	78.9%	208	20	90.4%	19	2	89.5%	207	26	87.4%
177		19	3	84.2%	208	29	86.1%	19	7	63.2%	207	44	78.7%
181		19	7	63.2%	203	41	79.8%	19	2	89.5%	199	28	85.9%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
182		19	3	84.2%	203	49	75.9%	19	10	47.4%	202	55	72.8%
183		19	4	78.9%	208	28	86.5%	19	4	78.9%	208	28	86.5%
184		19	6	68.4%	208	30	85.6%	19	3	84.2%	207	26	87.4%
185		19	2	89.5%	208	34	83.7%	19	3	84.2%	208	27	87.0%
186	18	19	3	84.2%	205	14	93.2%	19	9	52.6%	203	59	70.9%
190		19	7	63.2%	208	42	79.8%	19	7	63.2%	208	52	75.0%
192		18	3	83.3%	103	17	83.5%	18	4	77.8%	101	13	87.1%
193	33	19	6	68.4%	206	36	82.5%	19	8	57.9%	205	74	63.9%
196		19	1	94.7%	208	70	66.3%	19	3	84.2%	205	59	71.2%
197		19	9	52.6%	207	53	74.4%	19	4	78.9%	206	56	72.8%
232		28	1	96.4%	289	10	96.5%	28	1	96.4%	289	22	92.4%
233		24	5	79.2%	295	85	71.2%	24	11	54.2%	294	102	65.3%
234		28	1	96.4%	289	7	97.6%	28	2	92.9%	289	22	92.4%
236		28	0	100.0%	289	5	98.3%	28	3	89.3%	288	47	83.7%
237		24	0	100.0%	283	28	90.1%	24	2	91.7%	281	32	88.6%
239	38	28	6	78.6%	288	31	89.2%	28	8	71.4%	288	24	91.7%
240		28	0	100.0%	293	24	91.8%	28	5	82.1%	292	27	90.8%
241		28	6	78.6%	301	39	87.0%	27	11	59.3%	300	47	84.3%
244	18	24	1	95.8%	295	8	97.3%	24	11	54.2%	295	50	83.1%
245		9	2	77.8%	110	17	84.5%	9	2	77.8%	111	11	90.1%
280		28	0	100.0%	300	11	96.3%	28	2	92.9%	300	53	82.3%
281		28	2	92.9%	301	60	80.1%	27	7	74.1%	299	62	79.3%
283		28	9	67.9%	301	66	78.1%	28	10	64.3%	300	63	79.0%
284		28	1	96.4%	301	13	95.7%	28	1	96.4%	300	59	80.3%
290	20	28	6	78.6%	301	25	91.7%	27	21	22.2%	299	74	75.3%
291		28	11	60.7%	301	49	83.7%	28	20	28.6%	300	66	78.0%
300		26	2	92.3%	290	9	96.9%	26	10	61.5%	288	73	74.7%
302		27	5	81.5%	295	23	92.2%	27	12	55.6%	292	102	65.1%
305	25	28	5	82.1%	295	24	91.9%	28	20	28.6%	294	116	60.5%
307		27	4	85.2%	294	40	86.4%	26	12	53.8%	291	107	63.2%
311		27	3	88.9%	291	18	93.8%	27	17	37.0%	287	113	60.6%
316		27	2	92.6%	289	20	93.1%	27	18	33.3%	287	107	62.7%
318	52	28	1	96.4%	297	20	93.3%	28	18	35.7%	293	165	43.7%
319	50	28	1	96.4%	299	19	93.6%	28	23	17.9%	294	184	37.4%
329		19	4	78.9%	209	20	90.4%	19	1	94.7%	209	17	91.9%
330		23	1	95.7%	243	5	97.9%	23	1	95.7%	242	15	93.8%
331		28	1	96.4%	292	20	93.2%	28	2	92.9%	288	27	90.6%
332		28	1	96.4%	297	17	94.3%	28	3	89.3%	296	44	85.1%
334		28	0	100.0%	297	9	97.0%	28	6	78.6%	292	74	74.7%
335		28	4	85.7%	300	33	89.0%	28	7	75.0%	291	63	78.4%
336		28	1	96.4%	286	7	97.6%	28	8	71.4%	285	83	70.9%
337		28	2	92.9%	289	17	94.1%	28	6	78.6%	288	63	78.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
338		28	5	82.1%	299	40	86.6%	28	10	64.3%	289	125	56.7%
339		28	3	89.3%	299	45	84.9%	28	3	89.3%	297	51	82.8%
341		27	10	63.0%	284	55	80.6%	27	12	55.6%	278	59	78.8%
342		28	1	96.4%	300	19	93.7%	28	2	92.9%	299	45	84.9%
350	28	28	2	92.9%	260	27	89.6%	28	19	32.1%	257	132	48.6%
351		28	1	96.4%	289	25	91.3%	28	6	78.6%	288	79	72.6%
352	77	28	4	85.7%	294	28	90.5%	28	13	53.6%	289	84	70.9%
353		27	0	100.0%	252	6	97.6%	27	2	92.6%	247	37	85.0%
354	22	27	2	92.6%	293	28	90.4%	27	6	77.8%	290	104	64.1%
355	237	27	2	92.6%	293	32	89.1%	27	7	74.1%	289	75	74.0%
364		28	2	92.9%	299	56	81.3%	28	6	78.6%	298	80	73.2%
365		28	0	100.0%	299	11	96.3%	28	9	67.9%	298	87	70.8%
370		27	3	88.9%	300	13	95.7%	26	5	80.8%	299	38	87.3%
371		27	0	100.0%	300	4	98.7%	27	3	88.9%	300	28	90.7%
380		28	1	96.4%	298	11	96.3%	28	3	89.3%	298	29	90.3%
381		28	2	92.9%	298	8	97.3%	28	9	67.9%	297	32	89.2%
382		28	1	96.4%	297	11	96.3%	28	7	75.0%	297	40	86.5%
383	33	28	0	100.0%	299	29	90.3%	28	13	53.6%	298	72	75.8%
390		28	3	89.3%	296	13	95.6%	28	7	75.0%	294	43	85.4%
391	19	28	1	96.4%	299	7	97.7%	27	7	74.1%	296	56	81.1%
392		27	0	100.0%	298	8	97.3%	27	8	70.4%	295	34	88.5%
393		28	1	96.4%	298	13	95.6%	28	9	67.9%	295	42	85.8%
417		19	2	89.5%	204	32	84.3%	18	3	83.3%	201	31	84.6%
425		16	1	93.8%	189	6	96.8%	16	0	100.0%	189	7	96.3%
470		20	2	90.0%	210	15	92.9%	18	2	88.9%	205	28	86.3%
471		19	2	89.5%	208	14	93.3%	18	0	100.0%	206	11	94.7%
473		19	3	84.2%	208	8	96.2%	18	1	94.4%	207	3	98.6%
474	29	19	2	89.5%	206	30	85.4%	18	9	50.0%	202	63	68.8%
475		16	2	87.5%	204	8	96.1%	16	3	81.3%	201	19	90.5%
478		17	1	94.1%	206	21	89.8%	16	1	93.8%	204	20	90.2%
479		19	1	94.7%	208	30	85.6%	19	2	89.5%	207	24	88.4%
486		19	0	100.0%	210	16	92.4%	19	9	52.6%	208	73	64.9%
494		19	6	68.4%	213	33	84.5%	19	11	42.1%	207	61	70.5%
495		19	1	94.7%	205	3	98.5%	19	2	89.5%	205	6	97.1%
500		28	1	96.4%	290	22	92.4%	27	5	81.5%	288	83	71.2%
502	18	28	0	100.0%	288	13	95.5%	27	3	88.9%	286	81	71.7%
503		28	3	89.3%	301	32	89.4%	28	12	57.1%	290	93	67.9%
504	28	28	2	92.9%	289	11	96.2%	27	10	63.0%	288	117	59.4%
505		28	2	92.9%	293	33	88.7%	27	6	77.8%	290	103	64.5%
506	50	28	4	85.7%	293	28	90.4%	27	7	74.1%	291	73	74.9%
507		28	3	89.3%	292	33	88.7%	28	12	57.1%	291	92	68.4%
508		28	1	96.4%	296	14	95.3%	28	8	71.4%	294	86	70.7%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
509	25	28	4	85.7%	291	32	89.0%	27	9	66.7%	290	103	64.5%
511		28	1	96.4%	292	23	92.1%	28	5	82.1%	289	77	73.4%
516		28	4	85.7%	292	28	90.4%	28	14	50.0%	290	132	54.5%
517	175	28	0	100.0%	293	5	98.3%	28	11	60.7%	292	174	40.4%
518	67	28	3	89.3%	293	32	89.1%	28	13	53.6%	291	174	40.2%
519		28	0	100.0%	290	11	96.2%	28	4	85.7%	289	59	79.6%
520		19	4	78.9%	40	6	85.0%	19	0	100.0%	40	1	97.5%
521		19	0	100.0%	208	4	98.1%	19	1	94.7%	207	16	92.3%
522		19	1	94.7%	208	4	98.1%	18	0	100.0%	207	11	94.7%
523		19	0	100.0%	209	4	98.1%	19	1	94.7%	209	26	87.6%
524		19	1	94.7%	209	6	97.1%	18	3	83.3%	208	36	82.7%
525		19	0	100.0%	207	4	98.1%	19	0	100.0%	206	10	95.1%
526		19	0	100.0%	40	4	90.0%	19	3	84.2%	40	7	82.5%
527		19	0	100.0%	209	3	98.6%	19	0	100.0%	208	29	86.1%
528		19	0	100.0%	208	5	97.6%	19	2	89.5%	208	32	84.6%
529		19	0	100.0%	209	0	100.0%	19	4	78.9%	209	40	80.9%
531		19	1	94.7%	208	3	98.6%	19	4	78.9%	207	17	91.8%
532		19	0	100.0%	209	9	95.7%	19	0	100.0%	207	20	90.3%
534		19	2	89.5%	209	15	92.8%	19	1	94.7%	208	15	92.8%
535		19	3	84.2%	40	4	90.0%	18	2	88.9%	39	4	89.7%
536		19	1	94.7%	209	9	95.7%	19	2	89.5%	207	10	95.2%
537		18	0	100.0%	39	1	97.4%	18	0	100.0%	39	2	94.9%
538		19	1	94.7%	209	5	97.6%	19	3	84.2%	209	37	82.3%
540		19	0	100.0%	209	5	97.6%	19	3	84.2%	204	21	89.7%
541		19	0	100.0%	209	8	96.2%	19	6	68.4%	209	46	78.0%
542		19	1	94.7%	209	8	96.2%	19	3	84.2%	209	35	83.3%
543	15	19	0	100.0%	209	6	97.1%	19	10	47.4%	209	34	83.7%
544		18	1	94.4%	207	11	94.7%	18	0	100.0%	206	15	92.7%
545		19	1	94.7%	209	8	96.2%	19	1	94.7%	207	21	89.9%
546		19	0	100.0%	209	7	96.7%	19	3	84.2%	208	31	85.1%
547		19	2	89.5%	209	9	95.7%	19	3	84.2%	209	29	86.1%
548		19	0	100.0%	207	12	94.2%	19	0	100.0%	205	11	94.6%
549		19	5	73.7%	209	24	88.5%	18	1	94.4%	203	30	85.2%
551		19	0	100.0%	209	10	95.2%	19	1	94.7%	204	18	91.2%
562		28	4	85.7%	297	35	88.2%	27	2	92.6%	287	32	88.9%
564		28	5	82.1%	295	22	92.5%	27	4	85.2%	291	28	90.4%
566		28	0	100.0%	120	10	91.7%	28	2	92.9%	120	13	89.2%
572		28	4	85.7%	250	23	90.8%	28	9	67.9%	246	47	80.9%
573		28	1	96.4%	289	38	86.9%	28	4	85.7%	283	47	83.4%
577		28	1	96.4%	43	1	97.7%	27	2	92.6%	42	2	95.2%
580		28	0	100.0%	297	21	92.9%	28	1	96.4%	296	53	82.1%
581	19	28	4	85.7%	297	37	87.5%	28	9	67.9%	293	60	79.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
582		28	1	96.4%	43	1	97.7%	28	2	92.9%	43	3	93.0%
586	17	28	2	92.9%	248	31	87.5%	28	5	82.1%	241	43	82.2%
587		28	3	89.3%	248	28	88.7%	27	6	77.8%	241	52	78.4%
591		28	0	100.0%	297	32	89.2%	28	4	85.7%	293	42	85.7%
593		28	5	82.1%	43	7	83.7%	27	4	85.2%	42	7	83.3%
595		28	3	89.3%	289	61	78.9%	28	2	92.9%	287	50	82.6%
600		19	1	94.7%	207	3	98.6%	19	2	89.5%	205	26	87.3%
601	35	19	4	78.9%	207	21	89.9%	19	4	78.9%	206	35	83.0%
605		19	1	94.7%	207	11	94.7%	19	0	100.0%	205	26	87.3%
607	23	19	3	84.2%	208	20	90.4%	19	1	94.7%	207	11	94.7%
609		19	2	89.5%	208	14	93.3%	17	1	94.1%	206	30	85.4%
620		19	1	94.7%	208	6	97.1%	19	3	84.2%	206	27	86.9%
622		15	2	86.7%	164	8	95.1%	15	2	86.7%	163	47	71.2%
637	18	4	1	75.0%	44	6	86.4%	4	2	50.0%	44	9	79.5%
639	16	19	1	94.7%	208	26	87.5%	19	4	78.9%	207	26	87.4%
640		19	0	100.0%	208	0	100.0%	19	3	84.2%	208	101	51.4%
641		19	1	94.7%	208	19	90.9%	19	1	94.7%	208	35	83.2%
642		19	0	100.0%	208	0	100.0%	19	1	94.7%	207	42	79.7%
643		19	0	100.0%	208	13	93.8%	19	2	89.5%	207	43	79.2%
644		19	1	94.7%	208	9	95.7%	18	3	83.3%	205	47	77.1%
645		19	2	89.5%	208	16	92.3%	18	4	77.8%	207	53	74.4%
646		19	1	94.7%	208	18	91.3%	19	4	78.9%	205	100	51.2%
647	23	19	1	94.7%	208	15	92.8%	18	8	55.6%	207	83	59.9%
648		19	0	100.0%	208	12	94.2%	19	5	73.7%	206	35	83.0%
649		19	0	100.0%	208	20	90.4%	19	5	73.7%	207	40	80.7%
650		19	0	100.0%	208	10	95.2%	19	1	94.7%	207	30	85.5%
651	28	19	2	89.5%	208	25	88.0%	19	6	68.4%	208	83	60.1%
652	12	19	1	94.7%	208	4	98.1%	19	7	63.2%	208	39	81.3%
653	30	19	2	89.5%	208	15	92.8%	19	7	63.2%	207	69	66.7%
654		19	1	94.7%	208	5	97.6%	19	0	100.0%	206	20	90.3%
655		19	5	73.7%	207	34	83.6%	19	7	63.2%	205	73	64.4%
656		19	3	84.2%	208	6	97.1%	19	2	89.5%	207	45	78.3%
657	12	19	1	94.7%	208	14	93.3%	19	2	89.5%	208	51	75.5%
658		19	1	94.7%	208	7	96.6%	19	4	78.9%	207	54	73.9%
680		20	0	100.0%	210	2	99.0%	20	1	95.0%	209	32	84.7%
681		20	0	100.0%	209	12	94.3%	20	7	65.0%	206	80	61.2%
682		20	0	100.0%	210	5	97.6%	20	2	90.0%	210	96	54.3%
683		19	0	100.0%	162	4	97.5%	19	9	52.6%	162	65	59.9%
684	15	18	6	66.7%	161	15	90.7%	18	8	55.6%	160	84	47.5%
685		18	0	100.0%	165	12	92.7%	18	10	44.4%	165	61	63.0%
686		20	6	70.0%	209	42	79.9%	20	10	50.0%	209	87	58.4%
687	51	20	1	95.0%	210	29	86.2%	20	9	55.0%	210	81	61.4%

Amtrak On Time Performance													
Trains Arriving Through: 7/28/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
688		20	2	90.0%	210	9	95.7%	20	2	90.0%	210	89	57.6%
699		5	0	100.0%	71	3	95.8%	5	1	80.0%	71	10	85.9%
702		28	4	85.7%	301	21	93.0%	28	16	42.9%	300	101	66.3%
703	17	28	3	89.3%	301	30	90.0%	28	12	57.1%	301	77	74.4%
710		28	11	60.7%	301	53	82.4%	27	19	29.6%	294	89	69.7%
711		28	0	100.0%	300	10	96.7%	28	11	60.7%	291	37	87.3%
712		28	4	85.7%	301	47	84.4%	27	15	44.4%	298	93	68.8%
713		27	0	100.0%	299	9	97.0%	23	15	34.8%	280	65	76.8%
714		28	7	75.0%	300	42	86.0%	28	13	53.6%	295	75	74.6%
715	Cncld	28	6	78.6%	300	45	85.0%	25	18	28.0%	287	95	66.9%
716		28	6	78.6%	300	34	88.7%	26	7	73.1%	298	63	78.9%
717	38	26	3	88.5%	294	33	88.8%	23	8	65.2%	277	70	74.7%
718	No OS	28	8	71.4%	301	45	85.0%	27	8	70.4%	299	57	80.9%
719		28	7	75.0%	301	30	90.0%	27	16	40.7%	292	73	75.0%
761		28	1	96.4%	297	18	93.9%	28	5	82.1%	297	38	87.2%
765		28	1	96.4%	297	13	95.6%	28	2	92.9%	288	41	85.8%
769	51	28	2	92.9%	295	13	95.6%	28	6	78.6%	291	56	80.8%
770		28	0	100.0%	297	17	94.3%	28	6	78.6%	294	40	86.4%
774		28	0	100.0%	297	8	97.3%	28	3	89.3%	293	65	77.8%
779		28	0	100.0%	43	1	97.7%	28	3	89.3%	43	7	83.7%
784		28	1	96.4%	297	33	88.9%	27	12	55.6%	293	117	60.1%
785		28	2	92.9%	297	15	94.9%	28	1	96.4%	295	44	85.1%
790		28	2	92.9%	297	16	94.6%	28	2	92.9%	294	43	85.4%
794		28	0	100.0%	297	22	92.6%	27	1	96.3%	295	58	80.3%
821		25	0	100.0%	296	6	98.0%	25	19	24.0%	296	153	48.3%
822	68	27	2	92.6%	298	13	95.6%	27	27	0.0%	298	158	47.0%
1333		28	2	92.9%	294	52	82.3%	28	22	21.4%	293	188	35.8%
1340		28	2	92.9%	293	14	95.2%	28	15	46.4%	291	98	66.3%
2103		18	0	100.0%	204	11	94.6%	18	1	94.4%	201	23	88.6%
2107		19	4	78.9%	204	37	81.9%	19	1	94.7%	200	27	86.5%
2108		18	2	88.9%	200	21	89.5%	17	4	76.5%	197	31	84.3%
2121	32	18	1	94.4%	201	32	84.1%	17	6	64.7%	196	47	76.0%
2122		19	3	84.2%	203	37	81.8%	19	4	78.9%	197	35	82.2%
2124	23	15	2	86.7%	162	28	82.7%	14	4	71.4%	158	36	77.2%
2150		19	0	100.0%	208	7	96.6%	19	6	68.4%	208	66	68.3%
2151		19	0	100.0%	208	0	100.0%	18	5	72.2%	207	50	75.8%
2152	27	18	3	83.3%	205	8	96.1%	17	9	47.1%	198	83	58.1%
2153		18	0	100.0%	203	5	97.5%	18	10	44.4%	201	49	75.6%
2154	25	18	5	72.2%	205	19	90.7%	16	12	25.0%	200	91	54.5%
2155	20	17	1	94.1%	197	13	93.4%	17	8	52.9%	190	81	57.4%
2159	33	19	2	89.5%	205	16	92.2%	19	8	57.9%	200	66	67.0%
2162		18	1	94.4%	206	16	92.2%	17	9	47.1%	200	73	63.5%

Amtrak On Time Performance

Trains Arriving Through: 7/28/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2167		19	1	94.7%	208	28	86.5%	19	7	63.2%	206	53	74.3%
2168		19	3	84.2%	208	17	91.8%	19	7	63.2%	207	49	76.3%
2169		17	4	76.5%	203	49	75.9%	16	7	56.3%	196	69	64.8%
2170		18	3	83.3%	198	15	92.4%	17	5	70.6%	194	47	75.8%
2172		17	2	88.2%	193	23	88.1%	17	6	64.7%	189	41	78.3%
2173	63	16	2	87.5%	200	21	89.5%	16	6	62.5%	200	49	75.5%
2190		18	0	100.0%	206	14	93.2%	18	1	94.4%	203	17	91.6%
2193		17	1	94.1%	202	26	87.1%	17	6	64.7%	195	69	64.6%
2275		4	2	50.0%	42	8	81.0%	3	1	66.7%	40	13	67.5%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2121	WAS	32	DMW	31	DMW	31	BAL-XNY	AM	Hold for defect repair, Control Point, ., Held a/c defective I-joint	
2124	NYP	23	CTP	15	CTP	15	XHM-XCY	AM	Delay due to mechanical problems on a Commuter train, XHM-XMO OPRD 1TRK A/C NJ ATLANTIC CITY EXTRA DISABLED ON 2TRK AT MP62.8	
2152	BOS	27	DCS	20	DCS	20	NHV-XGX	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), STOP, Other, XL3-X15, MICROLOCK FAILURE AT CRESCENT INTERLOCKING	
2154	BOS	25	CTI	17	SVS	17	WAS-WAS	AM	Water, commissary, toilet/trash dumping, COMMISSARY IS WORKING WITH ONLY 1 VEHICLE FOR DELIVERY OFF STOCK TO THE HSR TRAINS.	
2155	WAS	20	CTI	17	ENG	12	BAL-BAL	AM	Traction motor, 2010, MCB OPEN REAR POWER CAR	
2159	WAS	33	DMW	31	DMW	31	BWI-XNY	AM	Hold for defect repair, Control Point, ., Held a/c defective I-joint	
2173	WAS	63	CTP	25	CTP	20	NWK-MET	AM	Delay due to mechanical problems on a Commuter train, PLATFORM OFF 1TRK AFTER AM2124 CLEARED NJ3735 ON 3TRK A/C NJ3861 BROKEN PANTOGRAPH ON 4TRK WEST OF METUCHEN	
85	RVM	17	SVS	19	SVS	19	WAS-WAS	AM	Planned Switch, CONGESTION ON LOWER-LEVEL WITH 93, 138	
86	BOS	35	CTI	32	PTI	12	NHV-NLC	AM	Meet, 2169, Milepost w/Letters, nhv, nlc, Held for AM2169 to clear trk 1	
93	NFK	41	CTI	34	DCS	20	NLC-OSB	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), STOP, Other, X15-XL3, MICROLOCK FAILURE AT CRESCENT INTERLOCKING	
95	NFK	45	CTI	27	PTI	18	FBG-RVR	CS	Follow Amt-53, Milepost, 7.2, 4.6	
124	NYP	86	WTR	65	WTR	29	ASD-FBG	CS	Flash flood warning Milepost, 15.9, 59.3	
125	NPN	40	WTR	18	WTR	8	FBG-ASD	CS	Heat order Other, rf&p sub	
131	WAS	27	DMW	22	DMW	22	BWI-XNY	AM	Hold for defect repair, Control Point, ., Held a/c defective I-joint	
133	WAS	44	DMW	28	DMW	28	NCR-XNY	AM	Hold for defect repair, Control Point, ., Held a/c defective I-joint	
134	NYP	30	FTI	18	FTI	18	ALX-XVG	CS	Meet I 031, Control Point, RO	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
137	WAS	23	CTI	37	CTP	11	EWR-TRE	AM	Delay due to mechanical problems on a Commuter train, XLT-TRE CONGESTION A/C NJ3861 WITH BROKEN PANTOGRAH ON 4TRK WEST OF METUCHEN	
138	NYP	27	WTR	49	FTI	35	X3V-XV7	CS	Blocked from station track Track inspector, Control Point, BX	
139	WAS	43	SMW	20	SMW	12	OSB-NHV	AM	Diversions around M/W work, Control Point, XBC, Waited at Branford for 96 to clear single track	
151	RNK	78	ITI	52	ITI	52	NYP-NYP	AM	Service, turn, or wye train, 124	
170	BOS	19	DCS	21	DCS	21	NHV-NLC	AM	Restrictive signal(s) from known wayside signal failure (supply details in comment area), stop, Other, XL3-X15, MICROLOCK FAILURE AT CRESCENT INTERLOCKING	
171	RNK	46	DMW	35	DMW	35	NCR-XNY	AM	Hold for defect repair, Control Point, ., Held a/c defective I-joint	
173	WAS	23	CTI	14	CAR	10	PHL-PHL	AM	Door, 2010, MET BY MECHANICAL A/C DOOR ISSUES.	
174	BOS	23	CTI	29	CTI	6	BBY-BOS	AM	Follow, mbta, 870, Milepost w/Letters, bby, bos, Followed signals of late MT870	
175	WAS	77	DCS	42	DCS	30	KIN-MYS	AM	Issue with automatic road crossing protection, Milepost, kin, mys, stop and protect crossing malfunction at Latimer Point Rd and Wamphassuc	
186	NYP	18	SVS	26	SVS	26	WBG-RVM	CS	Planned Switch Had to go switch from operating to manual back to operating to get the signal, Milepost w/Letters, CA 49..2, CA 49.2	
193	WAS	33	HLD	11	CTP	10	EWR-MET	AM	Delay due to mechanical problems on a Commuter train, NECESSARY TO MAKE METRO PARK ON 1TRK A/C NJ3861 ON 4TRK BROKEN PANTOGRAPH WEST OF LINCOLN	
474	SPG	29	SMW	12	SMW	12	WFD-MDN	AM	Diversions around M/W work, Milepost w/Letters, wfd, mdn, Waited for AM475 to clear runaround	
53	SFA	31	WTR	64	CTI	16	XDD-XSF	FR	Cross Traffic CFRC, Control Point, Lake Beresford	
79	CLT	31	WTR	49	CAR	20	PTB-RMT	CS	Air / Brake / Wheel 81523, Backup hose bursted and stop at A104.3	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
80	NYP	42	WTR	25	DMW	17	ALX-XVG	CS	Waiting for MW clearance Had to run DIB at restricted speed thru TC Shipley limits, Milepost w/Letters, cfp 107.2, cfp 110.8
601	HAR	35	ENG	22	ENG	22	PHL-PHL	AM	Other electrical failure, 649, power test issues, necessary to swap sets
607	HAR	23	ENG	34	ENG	34	PHL-PHL	AM	Air / Brake, 632, BRAKE CYLINDER ISSUE
637	PHL	18	SMW	14	SMW	10	MET-TRE	AM	Scheduled in track usage program, Other, MET-XCY
639	PHL	16	CTP	8	CTP	8	EWB-MET	AM	Delay due to mechanical problems on a Commuter train, PLATFORM OFF 1TRK NJ3885 ON 3TRK A/C NJ3861 BROKEN PANTOGRAPH ON 4TRK WEST OF METUCHEN
647	HAR	23	WTR	15	CCR	10	PHL-PHL	AM	Electrical failure, 9641, TROUBLE PULLING POWER FROM CAB CAR 9641.
651	HAR	28	ENG	24	ENG	24	NWK-TRE	AM	HEP, 9634 621, STOPPED AT MP24 JUST WEST OF MENLO ON NO.3 TRACK LOST HEP/TRACTION POWER
652	NYP	12	CTP	8	CTP	8	NBK-MET	AM	Delay due to mechanical problems on a Commuter train, CONGESTION A/C NJ3861 WITH BROKEN PANTOGRAH ON 4TRK WEST OF METUCHEN
653	HAR	30	CTP	25	CTP	25	NWK-TRE	AM	Delay due to mechanical problems on a Commuter train, XUN-XCY CONGESTION A/C NJ3861 WITH BROKEN PANTOGRAH ON 4TRK WEST OF METUCHEN
657	HAR	12	CTP	15	CTP	15	NWK-PJC	AM	Delay due to mechanical problems on a Commuter train, XUN-XCY CONGESTION A/C NJ3861 WITH BROKEN PANTOGRAPH ON 4TRK WEST OF METUCHEN
19	NOL	174	ENG	269	ENG	269	BAL-XNY	AM	HEP, 602, Stopped on 3trk with No HEP and Broken Pantograph. Annulled at New Carrollton Station.
684	BON		CTI	9	CTI	9	HHL-WOB	MT	Cross Traffic Kelli's, 241, Control Point, fr
687	BRK	51	DSR	24	DSR	20	FRE-BRK	CS	Per dispatcher (radio/phone) Milepost, 9.5, 4.0, 25, single
63	TWO	26	FTI	27	FTI	27	XSV-ROC	CS	Follow csxt, Control Point, 349
64	ALB	43	WTR	62	WTR	22	ROC-XSV	CS	Heat order Other, rochester sub
68	NYP	28	WTR	49	WTR	49	SLQ-RSP	CN	Heat order Other, RSP SD

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
239	ALB	38	CTI	20	ENG	18	NYP-NYP	AM	Undesired emergency application, 709, LATE FROM SSYD A/C UNKNOWN PENALTY ON ENG 709	
244	NYP	18	CTI	21	CTI	12	POU-CRT	MN	Follow MNRR, Control Point, 61, Control Point, 35	
290	NYP	20	DSR	32	CTI	15	POU-CRT	MN	Follow metro, Milepost, 62, 39	
43	PGH	35	DSR	20	PET	8	TRE-XHM	AM	Scheduled in track usage program, Other, XMO, HELD TO FLW AM2155 ON 4 TRK A/C ET INSPECTION ON 3 TRK	
75	CLT	15	ADA	9	PTI	7	HPT-SAL	NS	Cross over or go around #Amtrk74, Control Point, lake	
89	SAV	63	WTR	67	FTI	22	XDJ-RVR	CS	Follow L195, Milepost w/Letters, cfp41.1, cfp4.8	
90	NYP	37	FTI	52	FTI	20	FAY-SSM	CS	Meet CSX???, Control Point, S.Dunn	
55	WAS	99	DSR	58	DSR	30	ESX-WAB	NE	Per bulletin Milepost, 108, 107, 10, m, Milepost, 107, 102, 25, m, Milepost, 102, 99, 10, m	
56	SAB	34	DSR	42	DSR	15	WAB-ESX	NE	Per bulletin Milepost, 98, 104, 25, main	
40	CHI	38	WTR	83	DCS	36	RMT-PTB	CS	Restrictive signal(s) from unknown cause Track inspector, Stop, Other, Appomattox	
41	MIA	138	WTR	151	WTR	50	XDJ-RVR	CS	High winds Milepost w/Letters, cfp 53.9, cfp 28.0	
6	CHI	54	FTI	155	PTI	29	XDC-XBB	UP	Meet Amt 5, Control Point, E Range	
543	SJC	15	CTI	11	CTI	11	GAC-SCC	UP	Meet ace, Control Point, expressway	
502	SEA	18	SYS	9	FTI	8	TUK-SEA	BN	Meet BNSF 8178, Control Point, Black River	
504	SEA	28	PTI	29	PTI	27	XA4-TUK	BN	Wait for station track Train 517 mechanical issues at Tukwila station on Main 1. Pulled past Tukwila station and backed up on Main 3 for Tukwila Station work, 517, Control Point, Glacier Park	
506	SEA	50	ITI	65	ITI	65	PDX-PDX	BN	Service, turn, or wye train 517, 517 arrived into PDX at 6:30	
509	PDX	25	FTI	20	FTI	12	XA4-XTW	BN	Follow BNSF 288, Control Point, Sumner	
517	PDX	175	CAR	116	CAR	116	TUK-XA4	BN	Air / Brake / Wheel 7200, Air dumped 5 times leaving TUK, troubleshooting doors with CNOC mechanical, sea mechanical arrived on scene to help troubleshoot	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
518	VAC	67	FTI	48	FTI	42	XF2-X1J	BN	Cross Traffic Held at Still Creek waiting for a yard transfer to yard their train at CN Main Yard, Control Point, Still Creek, CN Job 1537, Yard Transfer
8	CHI	67	FTI	141	CON	38	SPK-SPK	BN	Hold for thruway bus
822	OKC	68	DSR	46	DSR	20	GLE-ADM	BN	Per bulletin Milepost, 413.6, 462.0, 40, m, Milepost, 414.6, 415.1, 60, m, Milepost, 423.6, 424.2, 50, m, Milepost, 426.3, 426.4, 50, m
350	PNT	28	PTI	31	PTI	29	XB0-XA5	MI	Meet 353, Siding, albion
352	PNT	77	RTE	37	RTE	30	DER-DER	MI	Dispatcher hold Other, DER
354	PNT	22	DSR	24	DSR	10	TRM-PNT	CC	Per bulletin Milepost, 18.4, 19, 30, MAIN ONE, Milepost, 20, 21.2, 30, MAIN ONE
355	CHI	237	DBS	170	DBS	170	ROY-DET	CC	Debris blocking track (no debris strike) Power lines across the track at CP Beaubien. Held at CP D&M until power company came to remove them. Authority past CP Murray from CN Desk 10. Permission past CP Beaubien by Branch Line Dispatcher at walking speed per maintainer at CP Beaubien., Control Point
581	LAX	19	DSR	9	PTI	9	OLT-SOL	SN	Meet Amtk 774, Control Point, Torrey
586	SAN	17	PTI	16	PTI	16	XRJ-FUL	BN	Meet SW Chief, Control Point, inter 164
769	GTA	51	PTI	40	PTI	24	VEC-CPN	UP	Meet 784, Siding, Seacliff
703	SAC	17	TRS	22	TRS	22	MOD-XSK	BN	Vehicle on track ahead Milepost, 1101.89, 1101.89
715	OKJ	Trn Cancelled	POL	95	POL	66	ACA-ACA	BN	Fire department hold
717	OKJ	38	SYS	47	SYS	47	MTZ-MTZ	UP	Blocked by or assisting another, disabled Amtrak train Couple into 718 equipment
718	BFD	No OS Rpt	ENG	78	ENG	67	EMY-EMY	UP	Traction motor Locomotive not providing much power to get up to speed., C2102
3	LAX	301	FTI	327	FTI	120	GBB-FMD	BN	Follow bnsf 8007, Control Point, ormonde
4	CHI	173	POL	105	POL	105	LAJ-LMR	BN	Meet BNSF 1970-W held due to vehicle strike, Siding, Caddoa
1	LAX	32	FTI	216	TRS	99	XFA-XKG	UP	Trespasser strike Struck trespasser at mp 145.5 put train into emergency and got train stopped at mp 145.8, Milepost, 145.5, 145.8
22	CHI	31	SVS	79	SVS	79	FTW-FTW	TE	Fuel

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/28/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
305	STL	25	WTR	25	WTR	17	BNL-LCN	UP	Heat order Milepost, 126.4, 189.00	
383	QCY	33	POL	17	POL	17	GBB-MAC	BN	Removal of passenger by police Passenger removed by Bushnell PD	
391	CDL	19	CTI	20	CTI	20	X9R-XCS	CT	Cross Traffic Ran one Metra, metra, metra, Control Point, 21 st	
318	CHI	52	WTR	38	PTI	24	SPI-LCN	UP	Meet amt 21, Control Point, x181	
319	KCY	50	WTR	34	FTI	27	SMT-XUD	CC	Cross Traffic unknown, Control Point, canal	

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/28/2025

Terminal	Train	Date	Late	Delay	Cause
PGH	42	07/28	33	33	Late departure due to engine 101, dead batteries. PGH mechanical worked rapidly to get charge into locomotive batteries. Mechanical got the locomotive fired and cleared up off of the train at 7:25am, started boarding shortly thereafter Also some time was spent still deciding if the train would run a
PHL	110	07/28	12	12	Air / Brake / Wheel, ENTIRE TRAIN, AIR ISSUES, BRAKE TEST, OK TO PROCEED EAST
PHL	601	07/28	22	22	Other electrical failure, 649, power test issues, necessary to swap sets
PHL	607	07/28	34	34	Air / Brake, 632, BRAKE CYLINDER ISSUE
RNK	66	07/28	5	5	Water, commissary, toilet/trash dumping Late train 151
WAS	2154	07/28	17	17	Water, commissary, toilet/trash dumping, COMMISSARY IS WORKING WITH ONLY 1 VEHICLE FOR DELIVERY OFF STOCK TO THE HSR TRAINS.
GFD	425	07/28	10	10	Late inbound equipment 5552
HFD	473	07/28	9	9	Hold for thruway bus, Late bus departure
NYP	49	07/28	5	5	Cross over or go around, 284, Other, NYP-NYP, AM284 AHEAD
NYP	97	07/28	77	77	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C WAITED FOR CARS OFF AM98
NYP	151	07/28	52	52	Service, turn, or wye train, 124
NYP	239	07/28	18	18	Undesired emergency application, 709, LATE FROM SSYD A/C UNKNOWN PENALTY ON ENG 709
NYP	283	07/28	10	10	Passenger and/or baggage, LOADING
POR	684	07/28	5		
POR	688	07/28	4	4	Wait for station track 685, Other, Portland
CHI	329	07/28	7	7	Service, turn, or wye train 329, Equipment late from yard. Yard crew could not get it to load, had to shove it. Engineer was able to proceed with out any issue.
CHI	354	07/28	13	13	Other electrical failure Light for door circuit is in failure, per amt3 it must be fully functioning. We were ordered out by diesel pit foreman Leondre Dismukes via glasshouse., 56
PDX	506	07/28	65	65	Service, turn, or wye train 517, 517 arrived into PDX at 6:30
SEA	8	07/28	56	56	Pick up rescue locomotive due to mechanical failure Locomotive add for SPK train 7, 333
LAX	4	07/28	47	47	Radio failure Late yard engine swap 207 for engine 7. Bad radio., 207
OKJ	718	07/28	11	11	Low fuel pressure warning light Oakland mechanical inspected locomotive, C2102

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	No Data	No Data	95.2	No Data	No Data
CDOT	95.0	No Data	No Data	96.4	No Data	No Data
MARC	95.0	No Data	No Data	83.5	No Data	No Data
SEPTA	95.0	No Data	No Data	96.2	No Data	No Data
NJT-NED	95.0	96.4	92.4	95.2	364	13
NJT-SED	95.0	No Data	No Data	91.2	No Data	No Data

Operating Highlights

New Haven to Boston Main Line - Bridge Strike

28JUL25: At 453P-ET A vehicle struck the bridge at Gypsy Lane., MP 16.80 New Haven to Boston main line. Special Instruction 132-S2 was placed in effect requiring restricted speed not exceeding 20 mph until an inspection could be performed. At 549P-ET, the bridge was inspected and released for normal service.

Washington Terminal Switch Failure - Signal

28JUL25: Washington Terminal reported a bad I-Joint over 324/326 switches causing TOL across K Interlocking blocking all routes in and of Washington Terminal. Which caused delays to multiple trains in and out of Washington Terminal.

Train	Delay	Comment
2159 (28)	31"	
131 (28)	22"	
5 Marcs	05"-18"	
186 (28)	7"	
176 (28)	18"	
171 (28)	35"	

Train 138(28) South of Petersburg, VA- Freight Train Interference

28JUL25: Train 138(28) was delayed on CSX North End subdivision at MP 26.1 due to being blocked from the station track by a track inspector.

Train	Delay	Comment
138 (28)	38"	

Train 97(28) New York, NY - Initial Terminal Delay

28JUL25: Train 97(28) was delayed departing New York Station waiting for cars 62506 and 62003 off late train 97(27).

Train	Delay	Comment
97 (28)	1'17"	

Train 41(27) East of Cumberland, MD - Freight Train Interference

28JUL25: Train 41(27) was delayed following freight train C782/26 at MP 175.5 east of Cumberland station on the CSX Cumberland subdivision.

Train	Delay	Comment
41 (27)	30"	

NS Piedmont Heat Orders - Miscellaneous Amtrak Responsible

28JUL25: The NS issues Heat Orders on the Piedmont subdivision from 2P-ET to 6P-ET from MP 42.1NC-42.8NC, 44.4NC-44.7NC, and 46.1NC-46.7NC at 25 MPH.

Train	Delay	Comment
77 (28)	02"	
79 (28)	05"	

New Haven to Boston Mainline - North of Old Saybrook, CT - Signal

28JUL25: As of 10:11AM ET Boston Chief reported micro lock at MP 115.0/Crescent interlocking. C & S was on scene attempting to make repairs. As of 142P-ET The CPU board at location A was replaced at Crescent interlocking and was functioning as intended.

Train	Delay	Comment
170 (28)	21"	
93 (28)	20"	
2152 (28)	20"	
CDOT-1	31"	
2155 (28)	5"	
2159 (28)	8"	
2150 (28)	18"	
190 (28)	12"	
170 (28)	10"	
CDOT-2	18"	

CSX Heat Orders - Northeast and Southeast Regions

28JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Grand Rapids, Monon, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Capital, Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, North End, Old Main Line, Peninsula, RF&P, Rochester, Syracuse Terminal, Auburndale, Carters, Charleston, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, South End and Tampa Terminal.

Train	Delay	Comment
79 (28)	49"	
64 (28)	1'02"	
63 (28)	15"	
52 (28)	20"	
141 (28)	33"	
98 (28)	51"	
125 (28)	14"	
186 (28)	05"	
90 (28)	24"	
53 (28)	32"	
283 (28)	19"	
138 (28)	49"	
281 (28)	52"	
89 (28)	52"	
95 (28)	24"	
40 (28)	35"	
41 (27)	40"	
40 (27)	34"	

Northeast Corridor Heat Restrictions - Miscellaneous Amtrak Responsible

28JUL25: The following heat orders are in effect July 25th 2025:

NYP B Track Lack Int Limits 25MPH 12PM to 730PM

NYP 5 Track Hunter Int Limits 25MPH 12PM to 730PM

NYP 1 Track Ham Int Limits 25MPH 12PM to 730PM

HUD 2 Track MP 7.0 and MP 8.0 25MPH 12PM to 730PM

HUD1 Track Inwood Int Limits 25MPH 12PM to 730PM

Train	Delay	Comment
645 (28)	03"	
2108 (28)	05"	
2122 (28)	04"	
197 (22)	07"	
193 (28)	10"	
2169 (28)	10"	
2172 (28)	05"	
2167 (28)	06"	
148 (28)	10"	
652 (28)	03"	
173 (28)	09"	
129 (28)	03"	
2170 (28)	10"	
651 (28)	05"	
94 (28)	05"	
184 (28)	08"	
85 (28)	09"	
85 (28)	09"	
283 (28)	16"	
649 (28)	05"	
2121 (28)	08"	
647 (28)	15"	
93 (28)	04"	
133 (28)	03"	
2159 (28)	05"	
174 (28)	04"	

Train 607(28) Philadelphia, PA - Engine Failure

28JUL25: Train 607(28) was delayed departing Philadelphia due to having brake cylinder issues.

Train	Delay	Comment
607 (28)	34"	

Train 42(28) Pittsburgh, PA - Engine Failure

28JUL25: Train 42(28) experienced engine failure with E/101 at initial terminal Pittsburgh PA. Freight engine 1095 was secured from Norfolk southern to deadhead the equipment to Harrisburg PA. In Harrisburg PA E/638 was added. Buses were sourced for customers from Pittsburgh to Harrisburg.

UPDATE: As of 727A-ET Mechanical was able to get E/101 running and the train was reinstated between Pittsburgh and Harrisburg.

Train	Delay	Comment
42 (28)	33"	

Train 601(28) - Philadelphia, PA - Initial Terminal Delay

28JUL25: Train 601(28) was delayed at its initial terminal in Philadelphia, PA due to a late release from mechanical.

Train	Delay	Comment
601(28)	23"	

Train 151(28) - New York Penn Station/Sunnyside Yard - NY - Initial Terminal Delay

28JUL25: Train 151(28) was delayed at its initial terminal at New York Penn Station due to being turned off late arriving 124(27).

Train	Delay	Comment
151(28)	53"	

Northeast Corridor Service Adjustments - Heat Related Cancellations

27JUL25: Due to the impending forecast of extreme temperatures over 98 degrees and storms along the Northeast Corridor for Tuesday July 29th & Wednesday July 30th 2025 the following service adjustments have been made: 112(29, 30) 192(29,30) 178(29,30) 131(29,30) 133(29,30) and 173(29,30) are cancelled in their entirety. This will allow protect regional trainsets in BOS, NYP & WAS.

Acela service cancellations were added as of 7/27/25 for trains 2159(29-30) and 2162(29-30) cancelled in their entirety.

Train	Delay	Comment
112(29-30)	Cancelled	
192(29-30)	Cancelled	
178(29-30)	Cancelled	
131(29-30)	Cancelled	
133(29-30)	Cancelled	
173(29-30)	Cancelled	
2159(29-30)	cancelled	
2162(29-30)	cancelled	

Maintenance of Way Highlights

Train 55(28) St. Albans, VT - M of W Work

28JUL25: Train 55(28) was delayed between St Albans and Waterbury VT due to track work.

Train	Delay	Comment
55 (28)	38"	

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 107(27) Passenger Removal at New Carrollton, Maryland – Medical

28JUL25, Passenger on PNR 205820, traveling from New York, NY to Washington, D.C. was removed by EMS due to falling on platform 14 at New Carrollton, MD. Unknown injury if any. Amtrak Police notified.

Delay: 107 (27) None

Train 69(28) Passenger Removal at Rouses Point, New York – Customs

28JUL25, Passenger on PNR 3B2D0C, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69 (28) None

Western Region

Operating Highlights

Train 718(28) West of Modesto, CA - Police Related

28JUL25: Train 718(28) was delayed 10 miles west of Modesto on the BNSF Stockton subdivision due to a vehicle on the tracks in the vicinity of Escalon/MP 1101.1. Once the vehicle was removed and the tracks were inspected, 718(28) continued to Modesto.

Train	Delay	Comment
703(28)	22"	
718(28)	1'03"	

Train 22(28) South of Hope, AR - Freight Train Interference

28JUL25: Train 22(28) was delayed 12 miles south of Hope on the UPRR Little Rock subdivision due to ILBMN-25 stopped at Fulton/MP 469.4 with brake issues. The freight crew was able to shove into the clear to provide the route for 22(28), who continued to Hope.

Train	Delay	Comment
22(28)	38"	

Train 4(27) East of Trinidad, CO - Signal

28JUL25: Train 4(27) was delayed 31 miles east of Trinidad on the BNSF Raton subdivision at Simpson/MP 605.6 due to signal issues. The crew tested the switch and received permission to proceed east.

Train	Delay	Comment
4(27)	38"	

Train 518(28) South of Vancouver, BC - Freight Train Interference

28JUL25: Train 518(28) was delayed three miles south of Vancouver on the CN New Westminster subdivision at Still Creek/MP 153.9 due to CN 1537 yard job working ahead.

Train	Delay	Comment
518(28)	42"	

Train 4(27) East of Trinidad, CO - Weather

28JUL25: Train 4(27) was delayed on the BNSF Raton subdivision starting two miles west of Trinidad between MP 638.0 and MP 587.0 due flash flood warnings.

Train	Delay	Comment
4(27)	56"	

Train 4(28) Los Angeles, CA - Engine Failure

28JUL25: Trian 4(28) was delayed departing the initial terminal of Los Angeles, CA (LAX) on the Southern California Regional Rail Authority (Metrolink) River Subdivision. There was a problem with locomotive AMTK/207 which required it to be removed from the train and replaced with AMTK/7. Once the locomotive swap was complete, trian 4(28)was able to depart LAX at 6:06 PM-PT.

Train	Delay	Comment
4 (28)	47"	

Train 354(28) East of Dowagiac, MI - Signal

28JUL25: Train 354(28) with E/56 and 5 cars was delayed on the Amtrak Michigan Line eight miles east of Dowagiac due to code line failure between MP 171.0 and the west leg of MP 147.0. Train 354(28) was delayed operating reduced speed through the area. Additionally, 355(28) with E/ID4621 and 5 cars lost their mode light on E/ID4621 at MP 156.5 account of potential code line failure and cut out ITCS on E/ID4621 at MP 161.0. Train 355(28) continued to Chicago operating per Rule 596. At Chicago, E/ID4621 was bad ordered for hydrostatic oil leak fault.

Train	Delay	Comment
354 (28)	35"	
355 (28)	1'18"	

Train 8(28) Seattle, WA - Servicing

28JUL25: Train 8(28) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. A protect locomotive, AMTK/333, was added to train 8(28) to be ferried to Spokane, WA where it would be removed and added to train 7(27), which was having problems with locomotive AMTK/317. With the protect locomotive added, trian 8(28) was able to depart SEA at 5:51 PM-PT.

Train	Delay	Comment
8 (28)	56"	SEA - Initial Terminal
8 (28)	Est. 30"	SPK - remove protect locomotive

Train 58(28) North of Jackson, MS - Freight Train Interference

28JUL25: Train 58(28) was delayed on the CN Yazoo subdivision at Flora/MP 203.7 due to A48971-29 in emergency at MP 201.9 with air issues. The crew walked the train and was working to make repairs. CN mechanical was enroute to assist. The freight crew identified an air hose disconnected and attached the air hose to restore air and operate into the clear. Train 58(28) continued to Yazoo.

Train	Delay	Comment
58 (28)	1'02"	

Train 6(28) East of Reno, NV - Trespasser Incident

28JUL25: At approximately 4:09 PM-PT train 6(28) - operating with camera equipped locomotive AMTK/148, AMTK/146 and 10 cars - struck a vehicle at MP 258.23 on the Union Pacific Railway Nevada Subdivision near the city of Sparks, NV, Storey County, Nevada. This incident occurred on a public highway crossing at grade, Waltham Way (US DOT 913207E); the crossing is equipped with gates, flashing lights, and audible warning devices which were observed to be working at the time the incident occurred. There were no initial reports of injuries to the 188 passengers or crew and no initial reports of damage to Amtrak equipment. Train 6(28) was operating at an estimated 70MPH on the single main track with a posted track speed of 70MPH at the time the incident occurred. Local police and fire along with Union Pacific and Amtrak management responded to the scene. Once the scene was released by authorities train 6(28) advanced to Clark siding where the train held for a relief crew. While operating to the siding, the crew noticed there was no working bell or whistle on locomotive AMTK/148. The crew also reported minor accident damage to the front pilot (cow catcher) of the locomotive. The crew swapped the order of the locomotive (flat switched) so that AMTK/146 was leading while waiting for the relief crew to arrive. Once the relief crew arrived train 6(28) was able to resume operation and proceed east. Additional delays were attributed to E/146 with a continuous persistent parking brake alarm. The crew confirmed all hand brakes were released with no MU cables crossed and had free rolling wheels. The crew continued 10 miles, re-inspected with no exceptions, and continued operating to Winnemucca.

National Response Center: 1438227
Nevada Department of Emergency Management: Called, department declined to take report account no injuries.
Google Maps Location of Incident:
<https://maps.app.goo.gl/4SXHpHQnPHVHVeVB8>
39.554017, -119.553622
Waltham Way, Sparks, NV 89434

National Response Center Number: 1438227

Train	Delay	Comment
6(28)	5'50"	

Train 8/28(27) East of Wolf Point, MT - Freight Train Interference

28JUL25: Train 8/28(27) was delayed seven miles east of Wolf Point on the BNSF Glasgow subdivision at Macon/MP 220.9, meeting BN 5935 and at Bainville/MP 158.9, meeting BN 7605.

Train	Delay	Comment
8/28(27)	30"	BN 5935
8/28(27)	14"	BN 7605

Train 355(28) North of Detroit, MI - Weather

28JUL25: Train 355(28) was delayed one mile north of Detroit on the CN Holly subdivision at D&M/MP 4.4 due to commercial power lines down on the tracks at Beaubien/MP 54.0. The Power Company responded to the scene, repaired the pole, re-hung the wires, and trains were talked through the effected area. Additional wires were reported down on the Conrail shared assets, which prolonged delays. These wires were cleared with commercial power reported down and tracks inspected, so 355(28) continued to be talked into Detroit for this reason. After 355(28) operated in the clear, train 352(28) continued to be talked through the effected area. Train 354(28) was delayed holding at Kalamazoo and Battle Creek for late arriving crew off 355(28).

Train	Delay	Comment
355(28)	2'50"	
352(28)	1'07"	
354(28)	1'44"	

Train 718(28) Oakland, CA - Engine Failure

28JUL25: Train 718(28) was delayed departing the initial terminal of Oakland, CA (OKJ) on the Union Pacific Railway Martinez Subdivision. There was a problem with locomotive CDTX/2102 showing a "low fuel pressure" warning on the displays. Technicians from Oakland Maintenance Facility (OMF) responded and were able to resolve the issue. Upon arrival at Emeryville, CA (EMY) the crew reported there was a problem with the air brake system; technicians from OMF responded a second time and worked to resolve the problem. While enroute between Richmond, CA (RIC) at Martinez, CA (MTZ) the crew reported reduced tractive effort. With the continued mechanical issues the following recovery plan was enacted:

- 715(28) Terminate Martinez, CA - Passengers to 717(28)
- 718(28) swap equipment with 715(28) at Martinez, CA and continue to Bakersfield, CA (BFD)
- 717(28) couple to disabled equipment and tow back to Oakland, CA (OKJ)
- 718(28) refueled at Calwa Yard (near Fresno) as equipment did not return to OMF for servicing.

Train	Delay	Comment
718(28)	11"	OKJ
718(28)	1'07"	EMY
715(28)	Terminate MTZ	Pax to 717(28)
718(28)	20"	MTZ - Equipt Swap
717(28)	47"	MTZ - couple to disabled 718(28) equipt
718(28)	45"	FNO - Fuel

Train 715(28) Antioch-Pittsburg, CA - Police Related

28JUL25: Train 715(28) was delayed at Antioch, CA (ACA) on the Burlington Northern Santa Fe Railway Stockton Subdivision. The local fire department had requested all train traffic halted while attending to a fire near the track ahead. Once the hold was released trian 715(28) was able to proceed. Once underway a second fire department hold was requested to attend to a "hot spot" that had flared back up. Once the second hold was released, train 715(28) was able to proceed at 7:04 PM-PT.

Train	Delay	Comment
715(28)	1'35"	Total Delay

Train 22(28) Fort Worth, TX - Fueling

28JUL25: Train 22(28), E/69-E/68 & 6 cars, was delayed at Fort Worth, TX waiting on fuel vendor to fuel Train 21/421(27), engines, E/63-E/22 first, and then 22(28)'s power, E/69-E/68.

Train	Delay	Comment
22(28)	1'00"	
21/421(27)	13"	

Train 517(28) Tukwila, WA - Car Failure

28JUL25: Train 517(28) was delayed at Tukwila, WA (TUK) on the Burlington Northern Santa Fe Railway Seattle (MPXX) subdivision. There was a problem with the air brake system on car C/7200 causing multiple undesired emergency brake applications. Technicians from Seattle Mechanical arrived to assist in resolving the issue. Once the issue was resolved train 517(28) was able to resume operation.

Train	Delay	Comment
517(28)	1'56"	
507(28)	16"	Blocked at TUK by 517
506(28)	1'05"	Late turn from inbound 517(28)

Train 5(27) East of Fraser-Winter Park, CO - Freight Train Interference

28JUL25: Train 5(27) was delayed 12 miles east of Fraser-Winter Park on the BNSF Moffatt Tunnel subdivision at East Portal/MP 50.1, meeting NS 8087 with a tunnel flush.

Train	Delay	Comment
5 (27)	30"	

Train 2/422(27) East of Tucson, AZ - Freight Train Interference

28JUL25: Train 2/422(27) was delayed east of Tucson, AZ/MP983.9, on the UPRR Lordsburg Subdivision, following UP 7450 between MP1000 and MP1032 and further delayed following UP 7666 between MP1032 and MP1061. UPRR 7401 was tied down at Fenner/MP1035 with loco issues resulting in congestion through the area.

Train	Delay	Comment
2/422 (27)	1'01"	

Train 4(27) East of Albuquerque, NM - Car Failure

29JUL25: Train 4(27) with E/188-151 and 9 cars reported the water dumping in the diner C/38049 after departing Albuquerque and suspected a leak. Plans were implemented to water C/38049 at La Junta and or Kansas City. Customer service recovery was enacted with pizza delivered for dinner at La Junta for all passengers.

WBS#: B.TR.100150.5938

Train 21/421(27) Dallas, TX - PTC

28JUL25: Train 21/421(27), E/63-E/22 & 8 cars, was delayed at Dallas, TX/MP214.4, on the UPRR Dallas Subdivision, due to PTC issues arriving into Dallas station. The engineer was able to resolve issue after logging off and then back in to PTC on E/63. Train 21/421(27) was then further delayed resolving an issue with the TRE GTB's.

Train	Delay	Comment
21/421 (27)	31"	

Train 1340(28) East of Red Wing, MN - Temporary Speed Restrictions

28JUL25: Train 1340(28) was delayed on the CPKC River subdivision between MP 364.9 and MP 326.8 due to operating with temporary speed restrictions.

Train	Delay	Comment
1340 (28)	30"	
1333 (28)	29"	
8/28 (26)	33"	
7/27 (28)	20"	

Train 5(27) East of Fort Morgan, CO - Freight Train Interference

28JUL25: Train 5(27) was delayed at MP431.4, 33 miles east of Fort Morgan, CO, on the BNSF Akron Subdivision, due to BNSF 6546 stopped in emergency ahead. Train 5(27) held for BNSF 6546 to inspect consist, restore air and operate in the clear.

Train	Delay	Comment
5 (27)	39"	

Train 1(26)/421(25) Palm Springs, CA - Freight Train Interference

28JUL25: Train 1(26)/421(25) was delayed at Myoma/MP605, 17 miles east of Palm Springs, CA, on the UPRR Yuma Subdivision, due to UP8945 actuated dragging equipment detector on No 2 Track and then held for UP 7660 to clear ahead on No 1 in order to cross-over to No 2 Track around UP 8495 to route into Palm Springs, CA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(26)/421(25)	51"	

Train 517(28) Seattle, WA - Servicing

28JUL25: Train 517(28) was delayed at Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. Train 517(28) was delayed for technicians to service the septic system and water the entire train. Once technicians completed their work, train 517(28) departed SEA at 1:11 PM-PT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
517(28)	30"	

UPRR Heat Restrictions Springfield Subdivision - Texas Eagle/Lincoln/Missouri River Runner Services

28JUL25: UPRR level 2 heat restrictions were in effect on the Springfield Subdivision 1000AM-CT until 900PM-CT between Bloomington-Normal, IL/MP124 and MP189, 4 miles south of Springfield, IL. Trains were delayed operating 50MPH through the affected areas.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(27)/422(25)	25"	
319(28)	28"	
305(28)	25"	
318(28)	38"	
21(28)	30"	

Train 521(28) West of Richmond, CA - Debris Strike

28JUL25: Train 521(28), operating with camera-equipped locomotive E/C2012 and 4 cars was delayed at MP 7.1/UPRR Martinez Subdivision, 4.9 miles west of Richmond, as a result of striking a shopping cart (filled with bottles and cans) that had been placed on the tracks. There were no injuries reported. Crew reported some air hoses had become disconnected. Train was on the move once the hoses had been reconnected followed by a successful air test. Amtrak Police notified.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
521(28)	12"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold
371(19) - 10 oversold
305(18) - 13 oversold
300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold
371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold
371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.
370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.
371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train

- 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
 - Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
 - Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.
- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.
- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
301(16Jul-04Aug)	Cancelled, with alt	CHI-STL
306(16Jul-04Aug)	Cancelled, with alt	STL-CHI
381(05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382(05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Train 8(26) Seattle, WA - Car Failure

26JUL25: Train 8(26) with E/369 and 7 cars departed Seattle with C/34105 bad ordered toilets. As a result, one supplemental bus was secured to operate between Seattle and Spokane due to oversold conditions. Customer service was working to source additional alternate transportation due to oversold conditions between Grand Forks, North Dakota and Chicago, Illinois.

27JUL25: Train 8/28(26) was delayed departing Spokane on the BNSF Spokane subdivision due to holding for the late arriving supplemental bus from Seattle. Once the bus arrived and the passengers boarded, 8/28(26) departed Spokane.

28JUL25: To alleviate oversold conditions, two supplemental busses were also secured at St. Paul-Minneapolis, MN. The first bus operated St. Paul-Minneapolis to Chicago express. The second bus made all stops between St. Paul-Minneapolis and Milwaukee, WI. Passengers traveling east of Milwaukee were then accommodated on the next available Hiawatha service train.

WBS#: B.TR.100150.5932

Train	Delay	Comment
8(26)	38"	SPK - hold for supplemental bus

Maintenance of Way Highlights

Train 11(28) Portland, OR - M of W Work

28JUL25: Trian 11(28) was delayed at Portland, OR (PDX) on the Burlington Northern Santa Fe Railway Fallbridge Subdivision. A Union Pacific Maintenance of Way (MOW) crew overstayed their hours south of PDX while replacing a rail. Once the MOW crew completed their work and released the track, train 11(28) was able to depart PDX at 3:03 PM-PT.

Train	Delay	Comment
11 (28)	41"	

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (25)	CHI	BN6235		Corwrith Yard	7/28/25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
4(27)	FLG	1	WLO	N/A
500(28)	OLW	1	TAC	N/A
507(27)	SLM	2	ALY	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Bus 5619(27) Passenger Removal at Bakersfield, California – Other

28JUL25, Passenger on PNR 304600, traveling from Hanford, CA to Las Vegas, NV was removed by the police due to investigating two of the passengers being runaways. Amtrak Police notified.

Delay: **5619 (27)** **30"**

Train 3(27) Passenger Removal at Raton, New Mexico – Improper Conduct

28JUL25, Passenger on PNR 49682c, traveling from Chicago, IL to Los Angeles, CA was removed by Raton PD officer Stewart badge# 1440 due to continuing to answer the door naked making others uncomfortable. Amtrak Police notified.

Delay: **3 (27)** **17"**

Train 769 (28) Passenger Incident at Irvine, California – Medical

28JUL25, Passenger on PNR 3D6F80, traveling from San Juan Capistrano, CA to Goleta, CA was evaluated by EMS due to the passenger falling in the vestibule of car 1 while boarding. Amtrak Police notified.

Delay: 769 (28) 15"

Train 3 (27) Passenger Removal at Las Vegas, New Mexico – Improper Conduct

28JUL25, Passenger on PNR 47C899, traveling from Las Vegas, New Mexico to Los Angeles, CA was removed by Las Vegas PD due to continuing inappropriate conversations. Amtrak Police notified.

Delay: 3 (27) 07"

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/28/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	303	22	93%	8,052	740	91%	86,822	6,765	92%
Northeast Corridor	98%	84	5	94%	2,112	288	86%	23,297	2,521	89%
Acela	98%	23	1	96%	581	101	83%	6,496	869	87%
Northeast Regional	98%	61	4	93%	1,531	187	88%	16,801	1,652	90%
State Supported	98%	192	13	93%	5,171	295	94%	54,595	2,808	95%
Long Distance	98%	27	4	85%	769	157	80%	8,792	1,430	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/28/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	303	22	93%	8,052	740	91%	86,822	6,765	92%
Northeast Corridor	98%	84	5	94%	2,112	288	86%	23,297	2,521	89%
Acela	98%	23	1	96%	581	101	83%	6,496	869	87%
Northeast Regional	98%	61	4	93%	1,531	187	88%	16,801	1,652	90%
On Spine Northeast Regional	98%	32	3	91%	790	98	88%	8,524	876	90%
Richmond / Newport News / Norfolk	98%	13	1	92%	327	72	78%	3,507	536	85%
Roanoke	98%	4	-	100%	112	12	89%	1,198	162	86%
Springfield Shuttles	98%	12	-	100%	302	5	98%	3,572	78	98%
State Supported	98%	192	13	93%	5,171	295	94%	54,595	2,808	95%
Borealis	98%	2	-	100%	56	6	89%	587	65	89%
Capitol Corridor	98%	28	1	96%	728	29	96%	7,188	164	98%
Carolinian	98%	2	1	50%	56	10	82%	602	52	91%
Cascades	98%	14	1	93%	392	21	95%	4,093	289	93%
Downeaster	98%	10	-	100%	276	1	100%	2,864	45	98%
Empire	98%	20	1	95%	560	39	93%	6,446	339	95%
Adirondack	98%	2	-	100%	56	2	96%	602	43	93%
Berkshire Flyer	98%	-	-	100%	12	2	83%	18	4	78%
Ethan Allen Express	98%	2	-	100%	56	6	89%	602	40	93%
Maple Leaf	98%	2	-	100%	56	6	89%	602	60	90%
New York - Albany	98%	10	1	90%	268	10	96%	3,419	97	97%
New York - Niagara Falls	98%	4	-	100%	112	13	88%	1,203	95	92%
Heartland Flyer	98%	2	-	100%	52	1	98%	594	17	97%
Hiawatha	98%	12	-	100%	325	12	96%	3,438	127	96%
Illinois	98%	12	1	92%	358	33	91%	4,125	289	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	112	3	97%	1,192	46	96%
Illini / Saluki	98%	4	-	100%	111	10	91%	1,191	46	96%
Lincoln Service	98%	4	1	75%	135	20	85%	1,742	197	89%
Keystone	98%	28	5	82%	643	45	93%	6,958	433	94%
Lincoln / Missouri	98%	2	-	100%	56	11	80%	596	86	86%
Michigan	98%	10	-	100%	275	23	92%	2,879	277	90%
Blue Water	98%	2	-	100%	56	6	89%	598	88	85%
Pere Marquette	98%	2	-	100%	54	2	96%	600	27	96%
Wolverine	98%	6	-	100%	165	15	91%	1,681	162	90%
Missouri	98%	2	-	100%	54	1	98%	580	15	97%
Pacific Surfliner	98%	24	-	100%	672	18	97%	6,450	240	96%
Pennsylvanian	98%	2	1	50%	56	11	80%	602	71	88%
Piedmont	98%	8	-	100%	223	2	99%	2,392	34	99%
San Joaquins	98%	12	2	83%	333	24	93%	3,599	205	94%
Vermonter	98%	2	-	100%	56	8	86%	602	60	90%
Long Distance	98%	27	4	85%	769	157	80%	8,792	1,430	84%
Auto Train	98%	2	-	100%	56	7	88%	590	100	83%
California Zephyr	98%	2	1	50%	56	19	66%	599	141	76%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	24	10	58%	256	54	79%
City Of New Orleans	98%	2	1	50%	56	7	88%	588	53	91%
Coast Starlight	98%	2	-	100%	58	4	93%	605	89	85%
Crescent	98%	2	1	50%	56	6	89%	602	70	88%
Empire Builder	98%	4	-	100%	107	17	84%	1,158	150	87%
Floridian	98%	2	-	100%	54	17	69%	511	178	65%
Lake Shore Ltd	98%	2	-	100%	56	17	70%	1,000	118	88%
Palmetto	98%	2	-	100%	56	4	93%	600	38	94%
Silver Meteor	98%	1	-	100%	54	14	74%	596	122	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	-	100%	56	16	71%	600	153	75%
Sunset Ltd	98%	1	-	100%	24	7	71%	254	46	82%
Texas Eagle	98%	2	1	50%	56	12	79%	672	93	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/28/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	299	9	97%	8,083	233	97%	86,863	2,105	98%
Northeast Corridor	98%	80	1	99%	2,112	57	97%	23,249	655	97%
Acela	98%	22	-	100%	581	14	98%	6,498	170	97%
Northeast Regional	98%	58	1	98%	1,531	43	97%	16,751	485	97%
State Supported	98%	191	6	97%	5,172	98	98%	54,580	918	98%
Long Distance	98%	28	2	93%	799	78	90%	8,896	530	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/28/25										
Day			Month to Date					Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	299	9	97%	8,083	233	97%	86,863	2,105	98%
Central Division	98%	65	2	97%	1,836	92	95%	19,875	699	96%
Northeast Division	98%	96	1	99%	2,566	63	98%	28,582	677	98%
Southeast Division	98%	68	4	94%	1,771	48	97%	19,202	456	98%
Southwest Division	98%	70	2	97%	1,910	30	98%	19,204	273	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/28/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	299	9	97%	8,083	233	97%	86,863	2,105	98%
Central Division	98%	65	2	97%	1,836	92	95%	19,875	699	96%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	60	1	98%	603	3	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	26	1	96%	740	65	91%	8,016	452	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	56	2	96%	580	5	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	27	-	100%	300	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	55	-	100%	584	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	163	4	98%	1,726	13	99%
MSP	98%	1	-	100%	28	1	96%	289	7	98%
PDX	98%	5	-	100%	136	1	99%	1,448	36	98%
PNT	98%	3	-	100%	82	2	98%	829	9	99%
PTH	98%	1	-	100%	28	-	100%	299	6	98%
QCY	98%	2	-	100%	54	-	100%	584	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	1	88%	225	13	94%	2,352	126	95%
SPK	98%	1	-	100%	28	-	100%	309	2	99%
STL	98%	3	-	100%	94	3	97%	1,171	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	56	-	100%	577	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	1	99%	2,566	63	98%	28,582	677	98%
ALB	98%	7	-	100%	196	1	99%	2,105	26	99%
BON	98%	5	-	100%	138	-	100%	1,402	3	100%
BOS	98%	18	-	100%	493	9	98%	5,610	131	98%
BRK	98%	2	-	100%	90	1	99%	1,351	11	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	28	-	100%	299	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	49	-	100%	576	-	100%
HFD	98%	2	-	100%	38	-	100%	184	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	28	2	93%	299	7	98%
NFL	98%	2	-	100%	56	-	100%	602	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	130	-	100%	1,537	35	98%
NYP	98%	41	1	98%	1,075	49	95%	12,069	434	96%
POR	98%	3	-	100%	45	-	100%	45	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	26	-	100%	297	1	100%
SPG	98%	5	-	100%	139	1	99%	1,835	20	99%
TWO	98%	1	-	100%	28	-	100%	298	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	68	4	94%	1,771	48	97%	19,202	456	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	136	1	99%	1,490	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/28/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	299	9	97%	8,083	233	97%	86,863	2,105	98%
Southeast Division	98%	68	4	94%	1,771	48	97%	19,202	456	98%
DNC	98%	-	-	100%	1	-	100%	1	-	100%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	310	2	99%	3,256	22	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	28	1	96%	295	12	96%
MIA	98%	2	-	100%	53	5	91%	578	33	94%
NFK	98%	3	-	100%	79	2	97%	829	5	99%
NOL	98%	3	-	100%	63	1	98%	670	21	97%
NPN	98%	2	-	100%	56	1	98%	575	4	99%
PGH	98%	1	1		28	1	96%	300	4	99%
PHL	98%	5	3	40%	118	7	94%	1,284	40	97%
RGH	98%	4	-	100%	104	-	100%	1,207	5	100%
RNK	98%	2	-	100%	51	-	100%	568	8	99%
RVM	98%	1	-	100%	28	-	100%	292	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	26	1	96%	282	1	100%
SFA	98%	1	-	100%	28	-	100%	295	18	94%
WAS	98%	24	-	100%	652	26	96%	7,127	273	96%
Southwest Division	98%	70	2	97%	1,910	30	98%	19,204	273	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	28	-	100%	301	-	100%
BFD	98%	6	-	100%	165	-	100%	1,788	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	28	4	86%	308	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	27	-	100%	333	5	98%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	84	-	100%	880	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	1	89%	264	5	98%	2,323	67	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	25	-	100%	296	-	100%
OKJ	98%	12	1	92%	308	13	96%	3,161	74	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	365	2	99%	3,596	14	100%
SAN	98%	12	-	100%	330	5	98%	2,752	27	99%
SAS	98%	1	-	100%	28	1	96%	297	3	99%
SJC	98%	7	-	100%	195	-	100%	1,935	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	56	-	100%	589	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	6	-	100%	53	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/28/2025 12:00..	Diesel Loco moti..	Talgo	Electric Locomotives		Califo rnia C ars (..	Cab Car		Caltra ns Lo com..	Amfle et I	High Speed Trainset		Super liner II	Viewli ner II	Surfli ner	Grand Total
	ENG	CAR	ENG	CAR	ENG	ENG	CCR	ENG	CAR	ENG	CAR	CAR	ENG	CAR	
Air/Brake Problems	3	116	60		67				20				7		273
I-ETMS Problem	58														58
Radio Problems	47														47
Electrical Problems	33						10								43
ATS - Automatic T..	29														29
Door Problems			6	10					6					5	27
M/U Trainline Cabl..						24									24
ACSES Failure			15												15
MCB Tripping										15					15
Engine Dead/Shut ..								14							14
480V Trainline Pro..								13							13
Fuel/Fuel Gauge P..	11														11
Toilets Inoperative												8			8
Tilt System Proble..											5				5
Loading Problems						3									3
Grand Total	181	116	81	10	67	27	10	27	26	15	5	8	7	5	585