



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, July 30, 2025

Rules:5-54



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/29/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/29/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	289	54	81.3%	8,342	1,016	87.8%	87,050	8,685	90.0%
Central Division	91.5%	66	12	81.8%	1,900	233	87.7%	19,929	1,973	90.1%
Northeast Division	95.0%	90	22	75.6%	2,628	362	86.2%	28,583	3,125	89.1%
Southeast Division	94.5%	63	11	82.5%	1,834	221	87.9%	19,264	1,935	90.0%
Southwest Division	90.5%	70	9	87.1%	1,980	200	89.9%	19,274	1,652	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/29/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	89,138	32,997	63%	2,955,074	958,155	68%	28,340,926	7,676,456	73%
Northeast Corridor	80%	36,052	13,135	64%	1,280,590	389,264	70%	12,581,000	3,265,910	74%
Acela	82%	7,855	4,524	42%	258,877	78,075	70%	2,612,794	632,741	76%
Northeast Regional	78%	28,197	8,611	69%	1,021,713	311,189	70%	9,968,206	2,633,169	74%
Richmond / Newport News / Norfolk	73%	10,827	2,989	72%	329,120	135,679	59%	3,219,272	1,108,216	66%
Springfield Shuttles	89%	347	53	85%	12,894	2,950	77%	178,891	27,594	85%
Roanoke	70%	1,421	189	87%	84,214	24,778	71%	838,391	222,003	74%
On Spine Northeast Regional	83%	15,602	5,380	66%	595,485	147,782	75%	5,731,652	1,275,356	78%
State Supported	80%	39,911	12,159	70%	1,286,696	344,056	73%	12,098,702	2,704,109	78%
Borealis	60%	547	400	27%	17,951	10,194	43%	174,658	73,372	58%
Capitol Corridor	90%	3,632	672	81%	98,121	7,727	92%	907,316	96,431	89%
Carolinian	60%	908	461	49%	31,104	15,607	50%	346,914	144,031	58%
Cascades	60%	2,354	557	76%	87,743	25,442	71%	770,623	263,468	66%
Downeaster	82%	1,201	731	39%	53,235	11,057	79%	431,917	104,050	76%
Empire	83%	4,969	2,183	56%	170,278	63,793	63%	1,632,260	366,089	78%
Adirondack	75%	343	241	30%	11,956	6,761	43%	89,951	29,460	67%
Ethan Allen Express	85%	559	342	39%	18,546	12,311	34%	163,757	45,635	72%
Maple Leaf	75%	657	620	6%	25,671	15,952	38%	221,748	71,115	68%
New York - Albany	90%	2,177	440	80%	68,058	16,372	76%	755,034	119,806	84%
New York - Niagara Falls	75%	1,233	540	56%	41,754	10,063	76%	395,587	96,962	75%
Berkshire Flyer	60%	0	0	-	4,293	2,334	46%	6,183	3,111	50%
Heartland Flyer	70%	208	99	52%	7,889	6,182	22%	67,408	32,245	52%
Hiawatha	90%	1,894	860	55%	62,619	7,866	87%	513,131	67,231	87%
Illinois	78%	2,003	507	75%	77,177	25,949	66%	747,589	183,026	76%
Carl Sandburg / Illinois Zephyr	80%	377	102	73%	14,233	3,069	78%	120,911	16,158	87%
Illini / Saluki	80%	685	178	74%	26,251	5,867	78%	264,548	34,738	87%
Lincoln Service	75%	941	227	76%	36,693	17,013	54%	362,130	132,130	64%
Keystone	92%	8,482	1,490	82%	184,764	22,264	88%	2,150,011	297,266	86%
Lincoln / Missouri	60%	733	632	14%	25,621	16,684	35%	219,598	121,565	45%
Michigan	69%	2,269	919	59%	72,508	19,022	74%	590,523	165,481	72%
Blue Water	70%	453	0	100%	17,721	4,730	73%	146,320	42,622	71%
Pere Marquette	85%	255	0	100%	9,349	1,415	85%	78,425	10,047	87%
Wolverine	65%	1,561	919	41%	45,438	12,877	72%	365,778	112,812	69%
Missouri	80%	192	21	89%	7,617	4,265	44%	66,449	23,753	64%
Pacific Surfliner	85%	5,971	463	92%	219,045	32,525	85%	1,753,654	281,876	84%
Pennsylvanian	72%	450	226	50%	27,143	9,118	66%	263,158	71,499	73%
Piedmont	73%	612	349	43%	28,560	9,245	68%	337,751	82,667	76%
San Joaquins	73%	2,274	783	66%	76,721	37,832	51%	740,533	212,202	71%
Vermont	75%	1,212	806	33%	38,600	19,284	50%	385,209	117,857	69%
Long Distance	57%	13,175	7,703	42%	387,788	224,835	42%	3,617,699	1,702,835	53%
Auto Train	57%	721	0	100%	23,474	7,563	68%	226,246	138,766	39%
California Zephyr	45%	1,160	903	22%	34,715	25,765	26%	297,358	132,265	56%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	0	0	-	7,823	4,072	48%	81,873	41,087	50%
City Of New Orleans	75%	635	385	39%	18,213	9,206	49%	193,013	57,415	70%
Coast Starlight	65%	988	224	77%	30,994	10,312	67%	316,795	131,058	59%
Crescent	60%	883	75	92%	30,135	10,603	65%	262,203	68,127	74%
Empire Builder	55%	1,242	687	45%	35,074	21,504	39%	290,065	130,007	55%
Floridian	40%	1,737	1,636	6%	44,418	37,417	16%	407,773	301,197	26%
Lake Shore Ltd	70%	1,050	298	72%	32,309	11,040	66%	304,146	83,668	72%
Palmetto	65%	1,388	874	37%	29,175	14,729	50%	297,323	115,845	61%
Silver Meteor	45%	1,008	916	9%	29,041	19,261	34%	278,427	147,167	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,094	875	20%	30,866	25,542	17%	243,802	152,468	37%
Sunset Ltd	50%	304	136	55%	8,128	3,962	51%	79,767	29,758	63%
Texas Eagle	60%	965	694	28%	33,423	23,859	29%	281,313	151,511	46%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 29, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	211,592	3,029,964	698	1,923,773	31,474,084	611

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	11,356	883,696	129	102,440	9,211,775	111
INFRASTRUCTURE PLANNED	90	6,782	883,696	77	93,928	9,211,775	102
FLEET RELIABILITY	83	37,868	3,029,964	125	306,748	31,474,084	97
TRAIN OPERATIONS	382	155,586	3,029,964	513	1,420,657	31,474,084	451

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

OTP Acela/Regional Cancellations - Miscellaneous Amtrak Responsible

29JUL25: In an effort to improve Northeast Regional OTP the following service adjustments have been made:

Acela Trains 2163(28-30SEP) and 2166(28-30SEP) will be cancelled from July 28,2025 thru September 30,2025.

Train 170(31-30SEP) will be suspended Monday thru Friday from July 31,2025 to September 30,2025.

Train 137(31-30SEP) will be suspended Monday thru Thursday and truncated to operate New York to Washington only on Friday.

Train 123(31-30SEP) suspended Sunday

Train 139(31-30SEP) truncated at Philadelphia on Sunday will operate Boston to Philadelphia.

Northeast Corridor Service Adjustments - Heat Related Cancellations

27JUL25: Due to the impending forecast of extreme temperatures over 98 degrees and storms along the Northeast Corridor for Tuesday July 29th & Wednesday July 30th 2025 the following service adjustments have been made: 112(29, 30) 192(29,30) 178(29,30) 131(29,30) 133(29,30) and 173(29,30) are cancelled in their entirety. This will allow protect regional trainsets in BOS, NYP & WAS.

Acela service cancellations were added as of 7/27/25 for trains 2159(29-30) and 2162(29-30) cancelled in their entirety.

Train	Delay	Comment
112(29-30)	Cancelled	
192(29-30)	Cancelled	
178(29-30)	Cancelled	
131(29-30)	Cancelled	
133(29-30)	Cancelled	
173(29-30)	Cancelled	
2159(29-30)	cancelled	
2162(29-30)	cancelled	

Train 244(29) - North of Hudson, NY - Engine Failure

29JUL25: Train 244(29) was delayed on the Amtrak Hudson Line at MP 136.4 due to E/709 dropping HEP after multiple faults. Mechanical personnel from Albany responded. the lead engine 709 was isolated and the rear engine 90 was set up to provide all power and HEP.

Train	Delay	Comment
244(29)	31"	
243(29)	59"	Turn off 244(29)

Train 20(29) - Southwest of Atlanta, GA - Tree Strike

29JUL25: Train 20(29) was delayed on the Norfolk Southern East End Subdivision at MP 694.6 due to striking a tree and losing air, which put the train into emergency. The conductor inspected, discovered uncouples air hoses and remedied. HEP on the train was down for a brief moment while the conductor worked on recoupling the hoses.

Train	Delay	Comment
20(29)	30"	

Train 2167(29) - North of Baltimore, MD - Engine Failure

29JUL25: Train 2167(29) was delayed on the Amtrak PW Line at MP 87.5 due to losing all power and going into UDE. The train lost HEP. The crew consulted with the on-duty Road Foreman and was able to restore HEP after a few minutes. After recycling, the crew conducted a brake test and proceeded south into Washington Union Terminal. Train 97(29) shadowed Train 2167(29) into Washington, to provide passenger rescue if needed.

Train	Delay	Comment
97(29)	23"	
2167(29)	24"	

Train 197(29) - Philadelphia, PA - Engine Failure

29JUL25: Train 197(29) was extensively delayed at 30th Street Station/MP 1.4 in Philadelphia, PA due to the engine 667 being shopped. The crew requested mechanical personnel meet them upon arrival to inspect E/667, which started to vibrate violently when over 90mph. Management in Philadelphia decided to swap the engine out and replace with E/664. Passengers on Train 197(29) were transferred to Train 137(29) and Train 55(29).

Train	Delay	Comment
197(29)	1'50"	
137(29)	12"	
55(29)	02"	
197(29)	40"	Hold at WIL for EN Recrew

Train 97(29) New York, NY - Engine Failure

29JUL25: Train 97(29) was delayed departing New York due to shopped engine and equipment need off late inbound 98(28).

Train	Delay	Comment
97(29)	3'03"	

Train 66(29) Roanoke, VA - Initial Terminal Delay

29JUL25: 66(29) was delayed departing Roanoke, VA due to late turn of equipment from 151(29) which arrived to Roanoke VA at 335PM ET.

Train	Delay	Comment
66(29)	48"	

Train 19(29) New York, NY - Initial Terminal Delay

29JUL25: Train 19(29) was delayed departing New York station due to late release from the yard. This was due to waiting for E/668, Car 62008, water commissary service and trash dumping.

Train	Delay	Comment
19(29)	35"	

Train 609(29) New Brunswick, NJ - Engine Failure

29JUL25: At 140P-ET, Train 609(29) with E/649, CC/9643 and 4 cars was disabled on the New York to Philadelphia main line at MP 34.0 with 246 passengers onboard and HEP was down. The crew was able to restore HEP as of 204P-ET but they were still having issues building air for the brake test. It was determined that the passengers would be transferred to train 43(29) and 647(29). The KN crew will couple to train 609(29) to bring them into Philadelphia. Train 656(29) will be cancelled Harrisburg to Philadelphia and will operate Philadelphia to New York.

As of 420P-ET Train 609(29) equipment was on the move towards Philadelphia. Train 43(29) Harrisburg crew was signing up off a cut at 655P-ET.

Train	Delay	Comment
609(29)	TERM MET	
43(29)	45"	TRANSFER PAX
656(29)	03"	Orig PHL
43(29)	09"	HAR crew s/u 655p-et

Train 171(29) New York, NY - Engine Failure

29JUL25: Train 171(29) was delayed departing New York due to E/662 having HEP issues and adding E/618.

Train	Delay	Comment
171(29)	36"	

Train 170(29) Providence, RI - Catenary or Wayside Failure

29JUL25: Train 170(29) was stopped at Providence Station due to debris in the catenary at Orms interlocking on track 2 which caused a TOL. ET reported no trains on track 2 between Orms and Lawn due to trolley wire being down. As of 1250P-ET, C&S arrived on the scene at Orms. Train 2167(29) was held at Route 128.

As of 243P-ET Boston Chief reported that train 2167(29) and 137(29) reported losing over catenary power on track 1 between Providence and Lawn. Train 2169(29) was held at Hebronville maintaining Overhead Catenary. As of 251P-ET the overhead catenary was restored on track 1 Providence to Lawn.

As of 337P-ET Boston Chief reported overhead catenary was restored on track 2.

As of 341P-ET Boston Chief reported overhead catenary was restored Davisville to Lawn. Overhead catenary down all tracks Law to Hold. 172(29) held at Providence and 175(29) held at Route 28.

As of 350PM train 86(29) ran around 888(29) at Davisville and held in Providence. Train 2173(29) held in Boston. Tree branch found was found the wires and ET responded to remove the branch from the wires.

UPDATE: Branch found in feeder wire ET on scene attempting to remove.

Train	Delay	Comment
170(29)	1'01"	
175(29)	46"	
172(29)	1'21"	
137(29)	33"	
2169(29)	40"	
2167(29)	1'08"	
2173(29)	32"	
86(29)	20"	
177(29)	1'16"	Turn off 172(29)

Train 43(29) New York Station - Car Failure

29JUL25: Train 43(29) was delayed departing New York Station due to AC issues with C/25083 and C/25048 and replaced with C/25010 and C/25054 which caused a late release from the yard.

Train	Delay	Comment
43 (29)	2' 52"	

Piedmont Service Adjustments - NS Heat Orders - Weather

29JUL25: Due to NS Heat Orders between Raleigh and Durham from 2p-ET til 6P-ET at 25MPH and 30 miles from Raleigh to Selma form 2P-ET til 6P-ET at 25MPH the following Piedmont Service adjustments were made Train 74(29) was terminated at Greensboro with alternate bus transportation from Greensboro to Raleigh and train 77(29) was originated at Greensboro with alternate bus transportation from Raleigh to Greensboro.

Train	Delay	Comment
74 (29)	TERM GRO	ALT BUS
77 (29)	2' 25"	ORIG GRO ALT BUS

CSX Heat Orders - Northeast and Southeast Regions

29JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Capital, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Grand Rapids, Monon Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, Old Main Line, Peninsula, RF&P, Rochester, Syracuse Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, and Tampa Terminal.

Train	Delay	Comment
40 (29)	47"	
64 (29)	58"	
98 (29)	1' 06"	
52 (29)	15"	
283 (29)	19"	
125 (29)	29"	
687 (29)	07"	
186 (29)	16"	
281 (29)	39"	
95 (29)	21"	
90 (29)	26"	
685 (29)	10"	
63 (29)	34"	
138 (29)	18"	
53 (29)	12"	
686 (29)	15"	
80 (29)	37"	
684 (29)	05"	
683 (29)	07"	
79 (29)	34"	
141 (29)	25"	
40 (28)	33"	
97 (28)	50"	
41 (28)	18"	

Northeast Corridor Heat Restrictions - Weather

29JUL25: Due to the extreme temperatures throughout the Northeast Corridor the following heat orders were in effect:

New Haven to Boston main line from 2P-ET thru 530P-ET level 1 tracks 1 and 2 from Packard and Cranston , from 3P-ET thru 630P-ET level 1 tracks 1 and 2 from MP190.8 and MP 227.0.

New Haven to Boston main line from 11A-ET thru 730P-ET level 3 track 1 at Shore Line Junction Interlocking Limits, from 10A-ET thru 8P-ET track 1 Atwells Interlocking Limits

MRS main line from 1P-ET thru 7P-ET level 1 tracks 1 and 2 for Berlin station and Wood.

New York to Philadelphia main line level 1 from 1230P-ET thru 730P-ET all tracks at Hunter and MP 76.0 and MP 76.0 - Shore, level 3 from 12P-ET thru 730P-ET track B at Lack Interlocking Limits, tracks 5 and A at Hunter Interlocking Limits, track 1 at Union Interlocking limits, track 1 at Ham Interlocking limits.

Hudson main line from 11A-ET thru 7P-ET level 1 track 1 from MP 124.3-MP 127.0, track 2 MP 124.3-MP 141.1, track 1 MP 135.0 - MP 141.1 and all tracks from MP 149.0-MP 156.3. Level 3 from 12P thru 730P-ET on track 2 from MP7.0-8.0 and track 1 at Inwood Interlocking Limits.

Philadelphia to Washington main line level 1 all tracks from 12P-ET-6P-ET Bush-CP Ave, Level 3 from 12P-ET-6P-ET track 3 Limits of Perry Interlocking and MP 126.0-MP 127.0.

Washington Terminal from 12P-ET- 6P-ET level 3 CP Ave and K Bridge

Philadelphia to Harrisburg main line level 3 from 12P-ET-8P-ET Limits of Overbrook Interlocking.

Train	Delay	Comment
654 (29)	10"	
2168 (29)	09"	
175 (29)	03"	
197 (29)	11"	
2193 (29)	08"	
2167 (29)	06"	
193 (29)	08"	
2154 (29)	03"	
97 (29)	03"	
137 (29)	04"	
2169 (29)	04"	
176 (29)	07"	
2172 (29)	10"	
653 (29)	05"	
2122 (29)	02"	
171 (29)	15"	
80 (29)	03"	
148 (29)	05"	
651 (29)	11"	
93 (29)	07"	
42 (29)	03"	
647 (29)	03"	
2170 (29)	05"	
85 (29)	03"	
94 (29)	10"	
283 (29)	02"	
125 (29)	08"	
43 (29)	07"	
2121 (29)	13"	
2168 (29)	09"	
2155 (29)	09"	
119 (29)	03"	
2153 (29)	09"	
95 (29)	10"	
645 (29)	04"	
2108 (29)	05"	
20 (28)	05"	

Train 183(29) At Philadelphia Station - Car Failure

29JUL25: Train 183(29) was delayed at Philadelphia 30th St. Station due to high low between cars 82640 & 43389. Mechanical responded and was able to resolve the issue.

Train	Delay	Comment
183(29)	33"	

Train 2154(29) Wilmington, DE - Engine Failure

29JUL25: Train 2154(29) with set 19 with PC/2021,PC/2024 was delayed at MP 26.8/Wilmington station on the Philadelphia to Washington main line due to ACSSES issues upon arrival. Engineer was resetting the ACSSES and was able to correct the issue.

Train	Delay	Comment
2154(29)	31"	

Train 41(28) Connellsville, PA - Trespasser Incident

29JUL25: Train 41(28) went into emergency on the CSX Keystone Subdivision at MP 242.9 due to a near miss with a trespasser.

Train	Delay	Comment
41(28)	18"	

Train 63(29)/69(29) New York, NY - Initial Terminal Delay

29JUL25: Combo train 63(29)/69(29) was delayed departing New York station due to a late release from the yard.

Train	Delay	Comment
63(29)/69(29)	41"	

Train 2107(29) New York, NY - Initial Terminal Delay

29JUL25: Train 2107(29) was delayed departing New York yard due to a bird on the pantograph.

Train	Delay	Comment
2107(29)	53"	

Train 151(29) - New York Penn Station/Sunnyside Yard - NY - Initial Terminal Delay

29JUL25: Train 151(29) was delayed at its initial terminal at New York Penn Station due to an engine being shopped late at Sunnyside Yard.

Train	Delay	Comment
151(29)	2'13"	

Train 2103(29) - Northeast Corridor - Cancelled

29JUL25: Train 2103(29) was cancelled due to equipment availability. No alternate transportation was provided.

Train	Delay	Comment
2103(29)	Cancelled	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold

371(19) - 10 oversold

305(18) - 13 oversold

300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold

371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold

371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on

370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.
- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.
- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.
- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.
- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
301(16Jul-04Aug)	Cancelled, with alt	CHI-STL
306(16Jul-04Aug)	Cancelled, with alt	STL-CHI
381(05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382(05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Train 6(28) West of Denver, CO - Servicing

30JUL25: Train 6(28) with E/146-148 and 10 cars was delayed just west of Denver at 23rd Street/MP 0.8 due to the crew stopping at 1154PM-MT to perform a calendar day inspection.

Train	Delay	Comment
6(28)	38"	

Train 6(29) East of Elko, NV - Freight Train Interference

29JUL25: Train 6(29) was delayed 110 miles east of Elko on the UPRR Shafter subdivision due to meeting GSMDPX-27 at Clifside/MP 781.6.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(29)	40"	

Train 22(29)/421(27) North of Texarkana, AR - Freight Train Interference

29JUL25: Train 22(29)/421(27) was delayed 13 miles north of Texarkana on the UPRR Little Rock subdivision due to MEWNL-28 with a repeat HBD and necessary to set out a car at Hope/MP 458.1. After the car was set out and the train was on the move, 22(29)/421(27) followed MEWNL-28 and MBZAS-28 to Beirne Jct./MP 429.3.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(29)	2'07"	

Train 307(29) South of Pontiac, IL - Engine Failure

29JUL25: Train 307(29) with E/ID4621 and 5 cars was delayed two miles south of Pontiac on the UPRR Joliet subdivision due to E/ID4621 shutdown with no coolant or HEP. There were 181 passengers on board and the weather was reported as 80 degrees and cloudy. A plan was put in place to use south facing UPRR 9636 from adjacent train IG4SIB-29 to be added to train 307(29), who operated dark to Bloomington-Normal, where they were terminated with alternate bus transportation. The decision was made to continue to Bloomington-Normal due to it being staffed, open, and able to accommodate the passengers on board. Local police were enroute to Bloomington-Normal station to assist. Amtrak Road Foreman and mechanical were enroute. Once UP 9636 was tied on and laced up, train 307(29) was back on the move at 1112PM-CT.

At Bloomington-Normal there were two buses for alternate transportation with an estimated spot time of 1245AM-CT. The buses arrived at 207AM-CT. Bus 1 operated between Bloomington-Normal, Lincoln, Springfield and St. Louis, departing Bloomington-Normal at 231AM-CT. Bus 2 operated express between Bloomington-Normal and St. Louis, departing Bloomington-Normal at 226AM-CT. The equipment deadhead Bloomington-Normal to St. Louis and was added to the rear of train 302(30) to deadhead back to Chicago. As a result of equipment changes, train 300(30) was cancelled with alternate bus transportation.

WBS#: B.TR.100150.5941

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(29)	2'36"	Term BNL
300(30)	Cancelled STL-CHI	W/ alt

Train 354(29) Kalamazoo, MI - Car Failure

30JUL25: Train 354(29) with E/56 and 5 cars was delayed on the Amtrak Michigan Line at Kalamazoo due to C/ID4203 shutdown and preventing E/56 from loading. As a result, the car was locked out and passengers were accommodated in additional space. Additionally, due to these issues unable to be repaired in Pontiac, train 353(30) had 35 business class downgrades to coach with the train oversold 14 passengers between Jackson, MI and Chicago, IL. Customer service was working to source alternate transportation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(29)	23"	

Train 508(29) South of Oregon City, OR - Passenger Train Interference

29JUL25: Train 508(29) was delayed six miles south of Oregon City on the UPRR Brooklyn subdivision due to meeting 507(29) and UP 6025 at Coalca/MP 750.4.

Train	Delay	Comment
508(29)	21"	507(29)
508(29)	15"	UP 6025

Train 59(29) Chicago, IL - Initial Terminal Delay

29JUL25: Train 59(29) with E/13-11 and 15 cars was delayed departing Chicago due to E/837 bad ordered and scheduled to be replaced with E/11 from 6(27), which arrived Chicago at 428PM-CT, 1 hour, and 49 minutes late. Due to no available fuel truck, it was necessary to hold off E/11, which was sent to the diesel pit for fuel and servicing. The train was worked up and released at 916PM-CT to board 199 passengers. Once the train was boarded, 59(29) departed Chicago at 1020PM-CT, 2 hours, and 15 minutes late. After departing, the crew stopped at Harrison/MP 0.3 due to loading issues and shoved back to Chicago to meet mechanical technicians and troubleshoot. Once the issue was repaired, 59(29) departed Chicago a second time at 1122PM-CT, 3 hours, and 17 minutes late.

Train	Delay	Comment
59(29)	2'15"	CHI - late release
59(29)	1'02"	Loading issues

Train 543(29) Emeryville, CA – Police Search for Suspect

29JUL25 Train 543(29) was delayed when rail traffic was stopped in the vicinity Emeryville station MP 4.00, Martinez Subdivision of the Union Pacific Railroad. This was to allow for local police to apprehend a trespasser threatening self-harm on or near tracks. Once the suspect was in the custody of police tracks re-opened. Amtrak Police Notified.

Train	Delay	Comment
543(29)	12"	

Train 7/27(29) West of Milwaukee, WI - Passenger Train Interference

29JUL25: Train 7/27(29) was delayed 19 miles west of Milwaukee on the CPKC Watertown subdivision due to meeting 1340(29) at Pewaukee/MP 104.2.

Train	Delay	Comment
7/27(29)	35"	

Train 534(29) East of Martinez-Switch Failure

29JUL25: Train 534(29) was delayed at Park, milepost 36.00, Martinez Subdivision, of the Union Pacific Railroad. The dispatcher was unable to gain remote control of the switches. The crew of train 534(29) was required to manually operate switches before gaining verbal authority to pass the signal. The Engineer was required to operate the train at reduced speed until within sight of the next verified remote signal.

Train	Delay	Comment
534(29)	29"	

Train 4(28) East of Las Vegas, NM - Passenger Train Interference

29JUL25: Train 4(28) was delayed 11 miles east of Las Vegas on the BNSF Raton subdivision due to meeting 3(27) at Onava/MP 758.8.

Train	Delay	Comment
4(28)	1'21"	

Train 1(28)/421(27) West of El Paso, TX - Freight Train Interference

29JUL25: Train 1(28)/421(27) was delayed 30 miles west of El Paso on the UPRR Lordsburg subdivision due to following MEWWC-27 between MP 1256.0 and MP 1228.0.

Train	Delay	Comment
1(28)/421(27)	37"	

Train 8/28(27) West of Glenview, IL - Signal

29JUL25: Train 8/28(27) was delayed 25 miles west of Glenview on the CPKC C&M subdivision due to signal issues at Wadsworth/MP 44.3.

Train	Delay	Comment
8/28(27)	43"	

Train 319(29) South of Springfield, IL - Engine

29JUL25: Train 319(29), E/IDTX4632 & 7 cars, was delayed at MP188.6, 3 miles south of Springfield, IL, on the UPRR Springfield Subdivision, due to a hot journal alarm on E/IDTX4632. Crew was in contact with mechanical, inspected axles and took no exceptions. Train 319(29) operated 50MPH for 10 miles, reinspected and took exceptions.

Train	Delay	Comment
319(29)	35"	

Train 4(28) East of Las Vegas, NM - Flash Flood Warnings

29JUL25: BNSF issued flash flood warnings on the Raton Subdivision between MP745, 25 miles east of Las Vegas, NM, and MP733 and between MP637, 1 mile west of Trinidad, CO and MP648. Trains 4(28) and 3(28) were delayed operating through the affected areas.

Train	Delay	Comment
4(28)	51"	
3(28)	1'08"	

Train 6(27) East of Burlington, IA - Debris Strike

29JUL25: Train 6(27), E/11-E/164 & 10 cars, with 253 passengers, stopped in emergency at MP174.2, 30 miles east of Burlington, IA, on the BNSF Ottumwa Subdivision. Crew inspected consist and reported air blowing from apparent debris strike of two metal plates. There were no reported injuries to passengers or crew. HEP was down for approximately 30 minutes while crew worked to resolve air issues. Outside temperature was reported at approximately 82 degrees. After troubleshooting air issues, HEP was restored and Train 6(27) was on the move east. Train 6(27) stopped in emergency again at MP169.2. BNSF mechanical responder requested to assist. Crew inspected consist and found parted air hoses between the first and second cars, C/61037 and C/39023 and between the 6th and 7th cars, C/38066 and C/33019. There were no other exceptions to equipment reported. Crew secured hoses between C/38066 and C/33019 and replaced hose gaskets and hoses between C/61037 and C/39023. Crew reported issues resolved prior to BNSF mechanical arriving on scene and Train 6(27) was able to proceed east again from MP 169.2.

WBS#: B.TR.100150.5940

Train	Delay	Comment
6(27)	40"	MP174.2
6(27)	27"	MP169.4

CPKC River Subdivision East of Red Wing, MN - Temporary Speed Restrictions

29JUL25: Trains were delayed operating over the CPKC River subdivision between Red Wing, MN and Winoma, MN due to temporary speed restrictions between MP 365.1 and MP 326.4.

Train	Delay	Comment
1340(29)	16"	
8/28(27)	11"	
1333(29)	17"	
7/27(29)	21"	

Train 527(29) South of Oakland Jack London Sq, CA - Vehicle on Tracks

29JUL25: Train 527(29) was delayed departing Oakland Jack London Sq. A vehicle accident blocked the rail crossing at High Street Oakland (DOT # 749712Y) MP 10.37, Niles Subdivision of Union Pacific Railroad. Delays were extended waiting for local police to attend the site, leading to Amtrak Police officers being dispatched to assist. Once investigation was completed, the vehicles removed and tracks inspected, train 527(29) resumed to Oakland Coliseum. Amtrak Police Notified.

Service Recovery: 20 % discount on café items offered on trains 527(29), 529(29), 528(29) and 532(29).

Train	Delay	Comment
527(29)	1'58"	
528(29)	1'18"	
529(29)	1'03"	
11(28)	1'30"	
532(28)	56"	SJC - Equipment Turn from 527(29)

Train 564(29), East of Los Angeles CA – Freight Train Interference

29JUL25: BNSF Freight train YWA19601-28A experienced a mechanical failure Train 564(29) was delayed 19 miles east of Los Angeles at MP 163.00 Basta, San Bernardino Subdivision of the BNSF Railway. After temporary repairs were made, the freight train was able to resume with a 30MPH maximum speed restriction. This caused a backlog of trains thru the area. Train 562(29) was required to follow slower BNSF Freight train BNSF/6956 – for 18 miles – between Eastern Avenue (MP 147.3) and Fullerton (MP 164.00). Subsequent trains were also delayed by train interference in the area.

Train	Delay	Comment
564(29)	51"	Follow BNSF/6956
566(29)	34"	

Train 4(27) East of Dodge City, KS - Signal Issues

29JUL25: Train 4(27) was delayed east of Dodge City, KS/MP352.5, on the BNSF La Junta Subdivision, due to signal issues between Dodge City and Belpre/MP286.1. Train 4(27) was delayed flagging through the affected area. Train 3(28) was delayed at MP220.7, 2 miles west of Hutchinson, KS, on the BNSF La Junta Subdivision, meeting Train 4(27).

Train	Delay	Comment
3(28)	30"	
4(27)	44"	

Train 330(29) Late Departure Milwaukee, WI - Engine

29JUL25: Train 330(29), E/IDTX4608-4 cars-CC/90221, was delayed departing Milwaukee, WI, due to E/IDTX4608 indicating doors open. After troubleshooting with mechanical crew was able to resolve issue by cutting out door bypass and Train 330(29) departed Milwaukee at 642AM-CT, 27 minutes late. Train 331(29) was delayed departing Chicago, IL, due to late turn of equipment off Train 330(29) which arrived at 843AM-CT, 36 minutes late.

Train	Delay	Comment
330(29)	27"	MKE
331(29)	34"	CHI

Train 3(27) West of Barstow, CA - Freight Train Interference

29JUL25: Train 3(27) was delayed west of Barstow, CA/MP0.4, on the BNSF Cajon Subdivision, following westbound freight traffic between Barstow and Lenwood/MP6.8 and then at Lenwood holding for BNSF cross-traffic to clear ahead.

Train	Delay	Comment
3(27)	1'07"	

Train 520(29) - Oakland Jack London Square - Servicing Equipment

29JUL25: Train 520(29), CC/8310-3 cars-E/CDTX2103, was delayed departing Origin Oakland Jack London Square, CA,. Overnight – in Oakland Maintenance Facility – Cafe car C/8808 was removed for maintenance replaced with car C/8804. from delayed inbound 717(28). Problems with compressed air pressure led to late release to commissary, who were required to perform a complete stock as the replacement Café Car was from San Joaquin Service. Additionally there was no chiller or coffee machine in Café Car C/8804 leading to café service of non-perishable items only and no coffee service on trains 520(29)/531(29) .

Cause: Pending

Train	Delay	Comment
520(29)	1'05"	OKJ - ITD
522(29)	22"	OKJ- ITD -Late servicing - crews working on 520(29)

Train 21(28) South of Texarkana, AR - Deer Strike

29JUL25: Train 21(28), E/53-E/139 & 6 cars, with 119 passengers, stopped in emergency at MP11.7, 11 miles south of Texarkana, AR, on the UPRR Little Rock Subdivision, due to striking a deer. There were no reported injuries to passengers or crew. The crew inspected consist, found parted air hose between E/139 and C/39001 and secured same. There were no other exceptions to equipment taken. Train 21(28) was on the move south after restoring air and performing brake test. Train 21(28) stopped in emergency at MP111.8, 22 miles west of Longview, TX, on the UPRR Mineola Subdivision. Crew inspected consist and found air hose parted again between E/139 and C/39001. Crew reported no other exceptions to equipment. Train 21(28) was on the move west after crew changed out air hose and performed brake test.

Train	Delay	Comment
21 (28)	10"	S/TXA
21 (28)	37"	

Maintenance of Way Highlights

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

A-Report Detail



Information Management

Initial Terminal Performance By Division

Scheduled Departure Date:	07/29/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/29/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	289	54	81.3%	8,342	1,016	87.8%	87,050	8,685	90.0%
Central Division	91.5%	66	12	81.8%	1,900	233	87.7%	19,929	1,973	90.1%
Northeast Division	95.0%	90	22	75.6%	2,628	362	86.2%	28,583	3,125	89.1%
Southeast Division	94.5%	63	11	82.5%	1,834	221	87.9%	19,264	1,935	90.0%
Southwest Division	90.5%	70	9	87.1%	1,980	200	89.9%	19,274	1,652	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/29/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/29/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	289	54	81.3%	8,342	1,016	87.8%	87,050	8,685	90.0%
Central Division	91.5%	66	12	81.8%	1,900	233	87.7%	19,929	1,973	90.1%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	2	0	100.0%	62	3	95.2%	605	17	97.2%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	27	8	70.4%	767	137	82.1%	8,043	1,022	87.3%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	1	50.0%	58	4	93.1%	582	23	96.0%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	28	0	100.0%	301	4	98.7%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	57	3	94.7%	586	40	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	1	83.3%	169	10	94.1%	1,732	98	94.3%
MSP	95.0%	1	0	100.0%	29	2	93.1%	290	14	95.2%
PDX	78.0%	5	0	100.0%	141	13	90.8%	1,453	165	88.6%
PNT	94.0%	3	0	100.0%	85	3	96.5%	832	59	92.9%
PTH	96.0%	1	0	100.0%	29	0	100.0%	300	11	96.3%
QCY	94.0%	2	0	100.0%	56	0	100.0%	586	18	96.9%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	1	87.5%	233	41	82.4%	2,360	341	85.6%
SPK	92.0%	1	0	100.0%	27	1	96.3%	298	14	95.3%
STL	96.0%	3	1	66.7%	97	12	87.6%	1,174	65	94.5%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	58	0	100.0%	579	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	90	22	75.6%	2,628	362	86.2%	28,583	3,125	89.1%
ALB	96.0%	6	0	100.0%	174	5	97.1%	2,023	127	93.7%
BON	94.5%	5	1	80.0%	143	9	93.7%	1,407	92	93.5%
BOS	97.0%	16	5	68.8%	509	53	89.6%	5,626	519	90.8%
BRK	97.0%	2	0	100.0%	92	3	96.7%	1,353	69	94.9%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	29	6	79.3%	300	23	92.3%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	51	3	94.1%	578	55	90.5%
HFD	-	2	0	100.0%	40	5	87.5%	186	18	90.3%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/29/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/29/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	289	54	81.3%	8,342	1,016	87.8%	87,050	8,685	90.0%
Northeast Division	95.0%	90	22	75.6%	2,628	362	86.2%	28,583	3,125	89.1%
MTR	97.0%	1	0	100.0%	29	4	86.2%	300	30	90.0%
NFL	97.0%	2	0	100.0%	58	1	98.3%	604	24	96.0%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	5	0	100.0%	135	18	86.7%	1,542	152	90.1%
NYP	94.5%	38	15	60.5%	1,113	223	80.0%	12,106	1,861	84.6%
POR	-	3	1	66.7%	48	16	66.7%	48	16	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	27	4	85.2%	298	9	97.0%
SPG	95.5%	5	0	100.0%	144	9	93.8%	1,840	85	95.4%
TWO	96.0%	1	0	100.0%	29	0	100.0%	299	11	96.3%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	63	11	82.5%	1,834	221	87.9%	19,264	1,935	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	2	60.0%	141	15	89.4%	1,495	100	93.3%
DNC	-	-	-	-	1	1	0.0%	1	1	0.0%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	12	2	83.3%	322	17	94.7%	3,268	105	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	29	6	79.3%	296	94	68.2%
MIA	90.0%	2	1	50.0%	55	10	81.8%	580	57	90.2%
NFK	94.5%	3	0	100.0%	82	13	84.1%	832	67	91.9%
NOL	92.0%	2	0	100.0%	65	3	95.4%	672	46	93.2%
NPN	96.0%	2	0	100.0%	58	5	91.4%	577	22	96.2%
PGH	92.0%	1	0	100.0%	29	4	86.2%	301	18	94.0%
PHL	97.0%	6	1	83.3%	124	30	75.8%	1,290	187	85.5%
RGH	97.0%	4	1	75.0%	108	4	96.3%	1,211	38	96.9%
RNK	94.0%	2	1	50.0%	53	5	90.6%	570	67	88.2%
RVM	90.0%	1	0	100.0%	29	2	93.1%	293	35	88.1%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	27	1	96.3%	283	11	96.1%
SFA	83.0%	1	0	100.0%	29	2	93.1%	296	80	73.0%
WAS	94.5%	20	3	85.0%	672	93	86.2%	7,146	974	86.4%
Southwest Division	90.5%	70	9	87.1%	1,980	200	89.9%	19,274	1,652	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	29	0	100.0%	302	7	97.7%
BFD	90.0%	6	0	100.0%	171	19	88.9%	1,794	155	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	1	0.0%	29	20	31.0%	309	96	68.9%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	28	2	92.9%	334	42	87.4%
FUL	-	-	-	-	-	-	-	12	5	58.3%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/29/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/29/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	289	54	81.3%	8,342	1,016	87.8%	87,050	8,685	90.0%
Southwest Division	90.5%	70	9	87.1%	1,980	200	89.9%	19,274	1,652	91.4%
GLE	-	-	-	-	-	-	-	4	4	0.0%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	87	3	96.6%	883	63	92.9%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	1	88.9%	273	35	87.2%	2,332	326	86.0%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	26	0	100.0%	297	6	98.0%
OKJ	91.0%	12	3	75.0%	320	55	82.8%	3,173	305	90.4%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	1	92.9%	379	27	92.9%	3,610	152	95.8%
SAN	90.0%	12	0	100.0%	342	23	93.3%	2,764	241	91.3%
SAS	85.0%	1	1	0.0%	29	7	75.9%	298	42	85.9%
SJC	95.0%	7	2	71.4%	202	8	96.0%	1,942	74	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	58	0	100.0%	591	27	95.4%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	6	0	100.0%	53	11	79.2%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		12	3	75.0%	127	24	81.1%	13	4	69.2%	123	23	81.3%
3	109	29	9	69.0%	296	59	80.1%	29	24	17.2%	292	165	43.5%
4	291	29	6	79.3%	297	71	76.1%	29	25	13.8%	296	156	47.3%
5	173	29	15	48.3%	299	54	81.9%	28	18	35.7%	296	101	65.9%
6	109	29	20	31.0%	299	89	70.2%	29	24	17.2%	298	106	64.4%
7		29	10	65.5%	293	46	84.3%	29	9	69.0%	288	76	73.6%
8	60	29	19	34.5%	294	111	62.2%	29	23	20.7%	292	144	50.7%
11		29	4	86.2%	301	48	84.1%	29	4	86.2%	294	65	77.9%
14		29	10	65.5%	302	92	69.5%	29	10	65.5%	300	130	56.7%
19		29	1	96.6%	302	34	88.7%	29	10	65.5%	301	59	80.4%
20		29	1	96.6%	302	14	95.4%	29	6	79.3%	301	48	84.1%
21		29	6	79.3%	301	40	86.7%	29	8	72.4%	295	91	69.2%
22	51	29	7	75.9%	298	44	85.2%	29	24	17.2%	297	132	55.6%
27		27	5	81.5%	289	22	92.4%	26	9	65.4%	279	95	65.9%
28		26	6	76.9%	282	71	74.8%	26	6	76.9%	281	78	72.2%
40	32	29	6	79.3%	259	39	84.9%	28	22	21.4%	254	161	36.6%
41	139	27	18	33.3%	256	113	55.9%	27	24	11.1%	252	201	20.2%
42	21	29	4	86.2%	302	19	93.7%	29	9	69.0%	302	83	72.5%
43	263	29	3	89.7%	302	26	91.4%	29	11	62.1%	302	71	76.5%
48	39	29	6	79.3%	301	54	82.1%	29	6	79.3%	301	47	84.4%
49		29	14	51.7%	302	64	78.8%	29	7	75.9%	302	54	82.1%
52		29	2	93.1%	296	80	73.0%	29	6	79.3%	296	153	48.3%
53		29	6	79.3%	296	94	68.2%	29	7	75.9%	296	147	50.3%
55	71	20	3	85.0%	209	9	95.7%	20	13	35.0%	209	52	75.1%
56	65	20	3	85.0%	209	36	82.8%	20	17	15.0%	208	60	71.2%
58		29	2	93.1%	294	23	92.2%	29	9	69.0%	291	62	78.7%
59		29	12	58.6%	293	64	78.2%	28	10	64.3%	289	37	87.2%
63	88	29	19	34.5%	302	65	78.5%	29	26	10.3%	302	158	47.7%
64	17	29	0	100.0%	302	11	96.4%	29	7	75.9%	302	75	75.2%
66		29	5	82.8%	300	58	80.7%	29	3	89.7%	298	39	86.9%
67		20	2	90.0%	208	19	90.9%	20	5	75.0%	206	44	78.6%
68	26	29	4	86.2%	302	30	90.1%	29	21	27.6%	302	125	58.6%
69		29	2	93.1%	302	22	92.7%	28	8	71.4%	297	35	88.2%
71		28	2	92.9%	301	7	97.7%	28	9	67.9%	299	67	77.6%
72		29	4	86.2%	302	23	92.4%	29	9	69.0%	300	76	74.7%
73	27	29	4	86.2%	302	16	94.7%	29	13	55.2%	300	148	50.7%
74	Cncld	29	3	89.7%	298	23	92.3%	28	12	57.1%	295	102	65.4%
75	54	29	3	89.7%	300	8	97.3%	28	15	46.4%	297	122	58.9%
76	64	29	7	75.9%	298	23	92.3%	28	19	32.1%	296	132	55.4%
77	150	29	3	89.7%	299	13	95.7%	29	14	51.7%	297	134	54.9%
78	83	29	1	96.6%	300	11	96.3%	28	10	64.3%	299	74	75.3%
79		29	7	75.9%	302	42	86.1%	27	9	66.7%	299	107	64.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80		29	3	89.7%	302	24	92.1%	29	17	41.4%	302	90	70.2%
84		20	0	100.0%	208	8	96.2%	20	7	65.0%	207	76	63.3%
85	18	20	0	100.0%	206	16	92.2%	20	15	25.0%	205	141	31.2%
86	68	20	1	95.0%	206	23	88.8%	20	18	10.0%	206	143	30.6%
89	31	29	2	93.1%	301	36	88.0%	29	16	44.8%	299	114	61.9%
90		29	1	96.6%	301	12	96.0%	28	12	57.1%	296	76	74.3%
93		20	0	100.0%	209	14	93.3%	20	12	40.0%	208	98	52.9%
94		20	6	70.0%	209	20	90.4%	20	11	45.0%	208	77	63.0%
95		20	0	100.0%	209	5	97.6%	20	10	50.0%	209	91	56.5%
97	52	28	21	25.0%	297	142	52.2%	28	14	50.0%	296	98	66.9%
98	80	28	5	82.1%	297	20	93.3%	28	17	39.3%	297	153	48.5%
110		20	7	65.0%	207	40	80.7%	20	4	80.0%	205	43	79.0%
111		20	6	70.0%	206	53	74.3%	20	3	85.0%	204	33	83.8%
114		20	4	80.0%	205	55	73.2%	20	3	85.0%	201	30	85.1%
119		20	2	90.0%	203	40	80.3%	20	3	85.0%	200	30	85.0%
125	38	20	1	95.0%	209	10	95.2%	20	12	40.0%	209	119	43.1%
129		20	6	70.0%	207	44	78.7%	20	8	60.0%	206	46	77.7%
130		20	2	90.0%	203	21	89.7%	20	1	95.0%	200	22	89.0%
134		20	0	100.0%	208	15	92.8%	20	10	50.0%	208	101	51.4%
136		20	1	95.0%	209	40	80.9%	20	4	80.0%	207	42	79.7%
137	63	20	5	75.0%	209	26	87.6%	20	10	50.0%	209	85	59.3%
138		20	3	85.0%	208	24	88.5%	20	10	50.0%	208	53	74.5%
141		20	0	100.0%	209	3	98.6%	20	10	50.0%	209	100	52.2%
148		20	2	90.0%	209	19	90.9%	20	5	75.0%	209	44	78.9%
151	139	29	7	75.9%	299	39	87.0%	29	10	65.5%	298	103	65.4%
170	73	20	0	100.0%	208	12	94.2%	20	8	60.0%	208	53	74.5%
171	119	20	3	85.0%	209	10	95.2%	20	13	35.0%	209	107	48.8%
172	137	20	3	85.0%	208	16	92.3%	20	9	55.0%	206	68	67.0%
174		20	2	90.0%	209	6	97.1%	20	7	65.0%	208	49	76.4%
175	103	20	7	65.0%	208	37	82.2%	20	12	40.0%	207	78	62.3%
176		20	4	80.0%	209	20	90.4%	20	2	90.0%	208	26	87.5%
177	71	20	4	80.0%	209	30	85.6%	20	8	60.0%	208	45	78.4%
178		18	1	94.4%	207	30	85.5%	19	8	57.9%	207	44	78.7%
179	20	20	4	80.0%	207	16	92.3%	20	12	40.0%	207	73	64.7%
181		20	7	65.0%	204	41	79.9%	20	2	90.0%	200	28	86.0%
182		20	3	85.0%	204	49	76.0%	20	10	50.0%	203	55	72.9%
183	27	20	4	80.0%	209	28	86.6%	20	5	75.0%	209	29	86.1%
184		20	7	65.0%	209	31	85.2%	20	3	85.0%	208	26	87.5%
185		20	2	90.0%	209	34	83.7%	20	3	85.0%	209	27	87.1%
186		20	3	85.0%	206	14	93.2%	20	9	55.0%	204	59	71.1%
190		20	7	65.0%	209	42	79.9%	20	7	65.0%	209	52	75.1%
193	22	20	7	65.0%	207	37	82.1%	20	9	55.0%	206	75	63.6%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
196		20	1	95.0%	209	70	66.5%	20	3	85.0%	206	59	71.4%
197	165	20	10	50.0%	208	54	74.0%	20	5	75.0%	207	57	72.5%
232		29	1	96.6%	290	10	96.6%	29	1	96.6%	290	22	92.4%
233		25	5	80.0%	296	85	71.3%	25	11	56.0%	295	102	65.4%
234		29	1	96.6%	290	7	97.6%	29	2	93.1%	290	22	92.4%
236		29	0	100.0%	290	5	98.3%	29	3	89.7%	289	47	83.7%
237		25	0	100.0%	284	28	90.1%	25	2	92.0%	282	32	88.7%
239		29	6	79.3%	289	31	89.3%	29	8	72.4%	289	24	91.7%
240		29	0	100.0%	294	24	91.8%	29	5	82.8%	293	27	90.8%
241	24	29	6	79.3%	302	39	87.1%	28	12	57.1%	301	48	84.1%
243		20	9	55.0%	209	41	80.4%	20	9	55.0%	208	31	85.1%
244	51	25	1	96.0%	296	8	97.3%	25	12	52.0%	296	51	82.8%
280		29	0	100.0%	301	11	96.3%	29	2	93.1%	301	53	82.4%
281		29	2	93.1%	302	60	80.1%	28	7	75.0%	300	62	79.3%
283		29	10	65.5%	302	67	77.8%	29	10	65.5%	301	63	79.1%
284	24	29	1	96.6%	302	13	95.7%	29	2	93.1%	301	60	80.1%
290	44	29	6	79.3%	302	25	91.7%	28	22	21.4%	300	75	75.0%
291	22	29	11	62.1%	302	49	83.8%	29	21	27.6%	301	67	77.7%
300	40	27	2	92.6%	291	9	96.9%	27	11	59.3%	289	74	74.4%
302		28	5	82.1%	296	23	92.2%	28	12	57.1%	293	102	65.2%
305		29	5	82.8%	296	24	91.9%	29	20	31.0%	295	116	60.7%
307		28	4	85.7%	295	40	86.4%	27	12	55.6%	292	107	63.4%
311		28	4	85.7%	292	19	93.5%	28	17	39.3%	288	113	60.8%
316		28	2	92.9%	290	20	93.1%	28	18	35.7%	288	107	62.8%
318	39	29	1	96.6%	298	20	93.3%	29	19	34.5%	294	166	43.5%
319	35	29	1	96.6%	300	19	93.7%	29	24	17.2%	295	185	37.3%
329		20	4	80.0%	210	20	90.5%	20	1	95.0%	210	17	91.9%
330	36	24	2	91.7%	244	6	97.5%	24	2	91.7%	243	16	93.4%
331	29	29	2	93.1%	293	21	92.8%	29	3	89.7%	289	28	90.3%
332		29	1	96.6%	298	17	94.3%	29	3	89.7%	297	44	85.2%
334		29	0	100.0%	298	9	97.0%	29	6	79.3%	293	74	74.7%
335		29	4	86.2%	301	33	89.0%	29	7	75.9%	292	63	78.4%
336		29	1	96.6%	287	7	97.6%	29	8	72.4%	286	83	71.0%
337		29	2	93.1%	290	17	94.1%	29	6	79.3%	289	63	78.2%
338	27	29	5	82.8%	300	40	86.7%	29	11	62.1%	290	126	56.6%
339	28	29	4	86.2%	300	46	84.7%	29	4	86.2%	298	52	82.6%
341	18	28	11	60.7%	285	56	80.4%	28	13	53.6%	279	60	78.5%
342		29	1	96.6%	301	19	93.7%	29	2	93.1%	300	45	85.0%
350	24	29	2	93.1%	261	27	89.7%	29	20	31.0%	258	133	48.4%
351	40	29	1	96.6%	290	25	91.4%	29	7	75.9%	289	80	72.3%
352		29	4	86.2%	295	28	90.5%	29	13	55.2%	290	84	71.0%
353		28	0	100.0%	253	6	97.6%	28	2	92.9%	248	37	85.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
354	143	28	2	92.9%	294	28	90.5%	28	7	75.0%	291	105	63.9%
355		28	2	92.9%	294	32	89.1%	28	7	75.0%	290	75	74.1%
364		29	2	93.1%	300	56	81.3%	29	6	79.3%	299	80	73.2%
365		29	0	100.0%	300	11	96.3%	29	9	69.0%	299	87	70.9%
370		28	3	89.3%	301	13	95.7%	27	5	81.5%	300	38	87.3%
371		28	0	100.0%	301	4	98.7%	28	3	89.3%	301	28	90.7%
380		29	1	96.6%	299	11	96.3%	29	3	89.7%	299	29	90.3%
381		29	2	93.1%	299	8	97.3%	29	9	69.0%	298	32	89.3%
382		29	1	96.6%	298	11	96.3%	29	7	75.9%	298	40	86.6%
383	33	29	1	96.6%	300	30	90.0%	29	14	51.7%	299	73	75.6%
390	20	29	3	89.7%	297	13	95.6%	29	8	72.4%	295	44	85.1%
391		29	1	96.6%	300	7	97.7%	28	7	75.0%	297	56	81.1%
392		28	0	100.0%	299	8	97.3%	28	8	71.4%	296	34	88.5%
393		29	1	96.6%	299	13	95.7%	29	9	69.0%	296	42	85.8%
417		20	2	90.0%	205	32	84.4%	19	3	84.2%	202	31	84.7%
425		17	1	94.1%	190	6	96.8%	17	0	100.0%	190	7	96.3%
470		21	2	90.5%	211	15	92.9%	19	2	89.5%	206	28	86.4%
471		20	2	90.0%	209	14	93.3%	19	0	100.0%	207	11	94.7%
473		20	3	85.0%	209	8	96.2%	19	1	94.7%	208	3	98.6%
474	17	20	2	90.0%	207	30	85.5%	19	10	47.4%	203	64	68.5%
475	40	17	2	88.2%	205	8	96.1%	17	4	76.5%	202	20	90.1%
478		18	1	94.4%	207	21	89.9%	17	1	94.1%	205	20	90.2%
479		20	1	95.0%	209	30	85.6%	20	2	90.0%	208	24	88.5%
486	16	20	0	100.0%	211	16	92.4%	20	10	50.0%	209	74	64.6%
494		20	6	70.0%	214	33	84.6%	20	11	45.0%	208	61	70.7%
495		20	1	95.0%	206	3	98.5%	20	2	90.0%	206	6	97.1%
500		29	1	96.6%	291	22	92.4%	28	5	82.1%	289	83	71.3%
502	16	29	0	100.0%	289	13	95.5%	28	4	85.7%	287	82	71.4%
503		29	3	89.7%	302	32	89.4%	29	12	58.6%	291	93	68.0%
504		29	2	93.1%	290	11	96.2%	28	10	64.3%	289	117	59.5%
505	18	29	2	93.1%	294	33	88.8%	28	7	75.0%	291	104	64.3%
506		29	4	86.2%	294	28	90.5%	28	7	75.0%	292	73	75.0%
507	18	29	3	89.7%	293	33	88.7%	29	13	55.2%	292	93	68.2%
508		29	2	93.1%	297	15	94.9%	29	8	72.4%	295	86	70.8%
509		29	4	86.2%	292	32	89.0%	28	9	67.9%	291	103	64.6%
511		29	1	96.6%	293	23	92.2%	29	5	82.8%	290	77	73.4%
516	19	29	4	86.2%	293	28	90.4%	29	15	48.3%	291	133	54.3%
517		29	0	100.0%	294	5	98.3%	29	11	62.1%	293	174	40.6%
518		29	3	89.7%	294	32	89.1%	29	13	55.2%	292	174	40.4%
519		29	0	100.0%	291	11	96.2%	29	4	86.2%	290	59	79.7%
520	71	20	5	75.0%	41	7	82.9%	20	1	95.0%	41	2	95.1%
521		20	0	100.0%	209	4	98.1%	20	1	95.0%	208	16	92.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
522	17	20	2	90.0%	209	5	97.6%	19	1	94.7%	208	12	94.2%
523		20	0	100.0%	210	4	98.1%	20	1	95.0%	210	26	87.6%
524		20	1	95.0%	210	6	97.1%	19	3	84.2%	209	36	82.8%
525		20	0	100.0%	208	4	98.1%	20	0	100.0%	207	10	95.2%
526		20	0	100.0%	41	4	90.2%	20	3	85.0%	41	7	82.9%
527	113	20	0	100.0%	210	3	98.6%	20	1	95.0%	209	30	85.6%
528	80	20	0	100.0%	209	5	97.6%	20	3	85.0%	209	33	84.2%
529	69	20	0	100.0%	210	0	100.0%	20	5	75.0%	210	41	80.5%
531	12	20	1	95.0%	209	3	98.6%	20	5	75.0%	208	18	91.3%
532	62	20	1	95.0%	210	10	95.2%	20	1	95.0%	208	21	89.9%
534	24	20	2	90.0%	210	15	92.9%	20	2	90.0%	209	16	92.3%
535		20	3	85.0%	41	4	90.2%	19	2	89.5%	40	4	90.0%
536		20	1	95.0%	210	9	95.7%	20	2	90.0%	208	10	95.2%
537		19	1	94.7%	40	2	95.0%	19	0	100.0%	40	2	95.0%
538		20	1	95.0%	210	5	97.6%	20	3	85.0%	210	37	82.4%
540		20	0	100.0%	210	5	97.6%	20	3	85.0%	205	21	89.8%
541		20	0	100.0%	210	8	96.2%	20	6	70.0%	210	46	78.1%
542		20	1	95.0%	210	8	96.2%	20	3	85.0%	210	35	83.3%
543	16	20	0	100.0%	210	6	97.1%	20	11	45.0%	210	35	83.3%
544		19	2	89.5%	208	12	94.2%	19	0	100.0%	207	15	92.8%
545		20	1	95.0%	210	8	96.2%	20	1	95.0%	208	21	89.9%
546		20	0	100.0%	210	7	96.7%	20	3	85.0%	209	31	85.2%
547		20	2	90.0%	210	9	95.7%	20	3	85.0%	210	29	86.2%
548		20	0	100.0%	208	12	94.2%	20	0	100.0%	206	11	94.7%
549		20	5	75.0%	210	24	88.6%	19	1	94.7%	204	30	85.3%
551		20	0	100.0%	210	10	95.2%	20	1	95.0%	205	18	91.2%
562		29	4	86.2%	298	35	88.3%	28	2	92.9%	288	32	88.9%
564	51	29	5	82.8%	296	22	92.6%	28	5	82.1%	292	29	90.1%
566	19	29	0	100.0%	121	10	91.7%	29	3	89.7%	121	14	88.4%
572		29	4	86.2%	251	23	90.8%	29	9	69.0%	247	47	81.0%
573		29	1	96.6%	290	38	86.9%	29	4	86.2%	284	47	83.5%
577		29	1	96.6%	44	1	97.7%	28	2	92.9%	43	2	95.3%
580		29	0	100.0%	298	21	93.0%	29	1	96.6%	297	53	82.2%
581		29	4	86.2%	298	37	87.6%	29	9	69.0%	294	60	79.6%
582		29	1	96.6%	44	1	97.7%	29	2	93.1%	44	3	93.2%
586		29	2	93.1%	249	31	87.6%	29	5	82.8%	242	43	82.2%
587		29	3	89.7%	249	28	88.8%	28	6	78.6%	242	52	78.5%
591		29	0	100.0%	298	32	89.3%	29	4	86.2%	294	42	85.7%
593		29	5	82.8%	44	7	84.1%	28	4	85.7%	43	7	83.7%
595		29	3	89.7%	290	61	79.0%	29	2	93.1%	288	50	82.6%
600		20	2	90.0%	208	4	98.1%	20	2	90.0%	206	26	87.4%
601		20	4	80.0%	208	21	89.9%	20	4	80.0%	207	35	83.1%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
605		20	1	95.0%	208	11	94.7%	20	0	100.0%	206	26	87.4%
607		20	3	85.0%	209	20	90.4%	20	1	95.0%	208	11	94.7%
609	Cncld	20	2	90.0%	209	14	93.3%	17	1	94.1%	206	30	85.4%
620		20	1	95.0%	209	6	97.1%	20	3	85.0%	207	27	87.0%
622		16	2	87.5%	165	8	95.2%	16	2	87.5%	164	47	71.3%
639		20	1	95.0%	209	26	87.6%	20	4	80.0%	208	26	87.5%
640		20	0	100.0%	209	0	100.0%	20	3	85.0%	209	101	51.7%
641		20	1	95.0%	209	19	90.9%	20	1	95.0%	209	35	83.3%
642		20	1	95.0%	209	1	99.5%	20	1	95.0%	208	42	79.8%
643		20	0	100.0%	209	13	93.8%	20	2	90.0%	208	43	79.3%
644		20	1	95.0%	209	9	95.7%	19	3	84.2%	206	47	77.2%
645		20	2	90.0%	209	16	92.3%	19	4	78.9%	208	53	74.5%
646		20	1	95.0%	209	18	91.4%	20	4	80.0%	206	100	51.5%
647	56	20	1	95.0%	209	15	92.8%	19	9	52.6%	208	84	59.6%
648		20	0	100.0%	209	12	94.3%	20	5	75.0%	207	35	83.1%
649		20	0	100.0%	209	20	90.4%	20	5	75.0%	208	40	80.8%
650		20	0	100.0%	209	10	95.2%	20	1	95.0%	208	30	85.6%
651	30	20	2	90.0%	209	25	88.0%	20	7	65.0%	209	84	59.8%
652		20	1	95.0%	209	4	98.1%	20	7	65.0%	209	39	81.3%
653	12	20	2	90.0%	209	15	92.8%	20	8	60.0%	208	70	66.3%
654		20	2	90.0%	209	6	97.1%	20	0	100.0%	207	20	90.3%
655	34	20	6	70.0%	208	35	83.2%	20	8	60.0%	206	74	64.1%
656		20	4	80.0%	209	7	96.7%	20	2	90.0%	208	45	78.4%
657		20	1	95.0%	209	14	93.3%	20	2	90.0%	209	51	75.6%
658		20	2	90.0%	209	8	96.2%	20	4	80.0%	208	54	74.0%
680	42	21	0	100.0%	211	2	99.1%	21	2	90.5%	210	33	84.3%
681		21	0	100.0%	210	12	94.3%	21	7	66.7%	207	80	61.4%
682	41	21	0	100.0%	211	5	97.6%	21	3	85.7%	211	97	54.0%
683	25	20	0	100.0%	163	4	97.5%	20	10	50.0%	163	66	59.5%
684	28	19	7	63.2%	162	16	90.1%	19	9	52.6%	161	85	47.2%
685	35	19	0	100.0%	166	12	92.8%	19	11	42.1%	166	62	62.7%
686	43	21	6	71.4%	210	42	80.0%	21	11	47.6%	210	88	58.1%
687	55	21	2	90.5%	211	30	85.8%	21	10	52.4%	211	82	61.1%
688		21	2	90.5%	211	9	95.7%	21	2	90.5%	211	89	57.8%
689	24	7	1	85.7%	152	7	95.4%	6	2	66.7%	152	31	79.6%
702		29	4	86.2%	302	21	93.0%	29	16	44.8%	301	101	66.4%
703		29	3	89.7%	302	30	90.1%	29	12	58.6%	302	77	74.5%
710	16	29	11	62.1%	302	53	82.5%	28	20	28.6%	295	90	69.5%
711		29	0	100.0%	301	10	96.7%	29	11	62.1%	292	37	87.3%
712		29	5	82.8%	302	48	84.1%	28	15	46.4%	299	93	68.9%
713		28	0	100.0%	300	9	97.0%	24	15	37.5%	281	65	76.9%
714		29	7	75.9%	301	42	86.0%	29	13	55.2%	296	75	74.7%

Amtrak On Time Performance													
Trains Arriving Through: 7/29/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
715		29	6	79.3%	301	45	85.0%	26	18	30.8%	288	95	67.0%
716	17	29	6	79.3%	301	34	88.7%	27	8	70.4%	299	64	78.6%
717	28	27	3	88.9%	295	33	88.8%	24	9	62.5%	278	71	74.5%
718		29	8	72.4%	302	45	85.1%	28	8	71.4%	300	57	81.0%
719	19	29	7	75.9%	302	30	90.1%	28	17	39.3%	293	74	74.7%
761		29	1	96.6%	298	18	94.0%	29	5	82.8%	298	38	87.2%
765		29	1	96.6%	298	13	95.6%	29	2	93.1%	289	41	85.8%
769		29	2	93.1%	296	13	95.6%	29	6	79.3%	292	56	80.8%
770		29	0	100.0%	298	17	94.3%	29	6	79.3%	295	40	86.4%
774		29	0	100.0%	298	8	97.3%	29	3	89.7%	294	65	77.9%
779		29	0	100.0%	44	1	97.7%	29	3	89.7%	44	7	84.1%
784		29	1	96.6%	298	33	88.9%	28	12	57.1%	294	117	60.2%
785		29	2	93.1%	298	15	95.0%	29	1	96.6%	296	44	85.1%
790		29	2	93.1%	298	16	94.6%	29	2	93.1%	295	43	85.4%
794		29	0	100.0%	298	22	92.6%	28	1	96.4%	296	58	80.4%
821		26	0	100.0%	297	6	98.0%	26	19	26.9%	297	153	48.5%
822	64	28	2	92.9%	299	13	95.7%	28	28	0.0%	299	159	46.8%
1333	33	29	2	93.1%	295	52	82.4%	29	23	20.7%	294	189	35.7%
1340	47	29	2	93.1%	294	14	95.2%	29	16	44.8%	292	99	66.1%
2107	41	20	5	75.0%	205	38	81.5%	20	2	90.0%	201	28	86.1%
2108		19	2	89.5%	201	21	89.6%	18	4	77.8%	198	31	84.3%
2121	21	19	1	94.7%	202	32	84.2%	18	7	61.1%	197	48	75.6%
2122		20	3	85.0%	204	37	81.9%	20	4	80.0%	198	35	82.3%
2124		16	3	81.3%	163	29	82.2%	15	4	73.3%	159	36	77.4%
2150	14	20	0	100.0%	209	7	96.7%	20	7	65.0%	209	67	67.9%
2151		20	0	100.0%	209	0	100.0%	19	5	73.7%	208	50	76.0%
2152		19	3	84.2%	206	8	96.1%	18	9	50.0%	199	83	58.3%
2153	12	19	0	100.0%	204	5	97.5%	19	11	42.1%	202	50	75.2%
2154	123	19	5	73.7%	206	19	90.8%	17	13	23.5%	201	92	54.2%
2155	25	18	1	94.4%	198	13	93.4%	18	9	50.0%	191	82	57.1%
2167	101	20	1	95.0%	209	28	86.6%	20	8	60.0%	207	54	73.9%
2168		20	3	85.0%	209	17	91.9%	20	7	65.0%	208	49	76.4%
2169	60	18	4	77.8%	204	49	76.0%	17	8	52.9%	197	70	64.5%
2170	47	19	3	84.2%	199	15	92.5%	18	6	66.7%	195	48	75.4%
2172	21	18	2	88.9%	194	23	88.1%	18	7	61.1%	190	42	77.9%
2173	75	17	3	82.4%	201	22	89.1%	17	7	58.8%	201	50	75.1%
2190		19	0	100.0%	207	14	93.2%	19	1	94.7%	204	17	91.7%
2193	40	18	1	94.4%	203	26	87.2%	18	7	61.1%	196	70	64.3%

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2107	WAS	41	DBS	53	DBS	53	NYP-NYP	AM	Animal strike, Other, NYP, LATE F/SSYD A/C BIRD IN PANTOGRAPH
2121	WAS	21	CTI	17	CTI	10	PHL-XPV	AM	Meet, ., ., Other, ., no train ahead
2150	BOS	14	DMW	14	DMW	14	XNY-BWI	AM	Waiting for MW clearance, Control Point, ., C and S late testing 2 trk Bowie - Grove
2153	WAS	12	DSR	11	OTH	8	XSH-NYP	AM	Lost time - N.A.R.
2154	BOS	123	DET	59	DET	59	PVD-RTE	AM	Catenary failure, Milepost w/Letters, pvd, rte, OCS still down all trks Law to Holden
2155	WAS	25	CTI	14	PET	8	XCY-XHM	AM	Scheduled in track usage program, Other, XMO-XHM, OPR 4 TRK A/C ET INSPECTION ON 3 TRK
2167	WAS	101	DET	68	DET	51	RTE-PVD	AM	Catenary failure, Milepost w/Letters, rte, pvd, AM2167 rpts losing OCS on Trk 1 b/t PVD and Lawn
2169	WAS	60	DET	51	DET	27	RTE-PVD	AM	Catenary failure, Milepost w/Letters, rte, xhe, AM2167 & AM137 rpts loosing OCS on Trk 1 btwn PVD and Lawn. AM2169 stopped at Hebronville maintaining OCS
2170	BOS	47	SYS	29	SYS	29	NYP-NYP	AM	Crew rest, WAITIED FOR CREW OFF LATE AM2167
2172	BOS	21	DCS	22	DCS	22	NYP-XSH	AM	Power switch failure, Other, XHR-XHR, HELD AT HAROLD FOR AM55 TO CLEAR 1TRK A/C 21SW AT HAROLD FAILING TO NORMAL
2173	WAS	75	DET	32	DET	32	BOS-BOS	AM	Catenary failure, Control Point, bos, AM2173 held in BOS a/c OCS couldn't hold power b/t Orms and Holden
2193	NYP	40	SMW	32	SMW	32	XSH-NYP	AM	Diversions around M/W work, Other, XM9, HELD AT MANOR FOR AM136 TO CLEAR 1 TRACK A/C 2 TRACK O/O/S BTWN GATE AND MANOR
85	RVM	18	OTH	13	CTI	11	XVG-ALX	CS	Follow break, 337, Milepost, 111.1, 104.3
86	BOS	68	DET	38	DET	20	KIN-PVD	AM	Catenary failure, Milepost w/Letters, kin, pvd, AM86 will run around AM888 at Davisville and hold in PVD a/c OCS down all trks btwn Orms and Holden all trains have HEP
125	NPN	38	WTR	37	WTR	11	FBG-ASD	CS	Heat order Other, FBG to ASD
137	WAS	63	DET	33	DET	33	RTE-PVD	AM	Catenary failure, Milepost w/Letters, rte, pvd, AM137 rpts loosing OCS on Trk 1 btwn PVD and Lawn

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
151	RNK	139	ENG	131	ENG	131	NYP-NYP	AM	Set out defective locomotive, 616, " LATE DUE TO SHOPPED ENGINE AND LATE RELEASE FROM THE YARD
170	BOS	73	DET	68	DET	64	PVD-PVD	AM	Catenary failure, Other, ORMS, TROLLEY WIRE DOWN TRACK 2
171	RNK	119	ENG	61	ENG	36	NYP-NYP	AM	HEP, 662, ADDED ENG.618 A/C HEP PROBLEM ON ENG.662
172	BOS	137	DET	113	DET	83	PVD-PVD	AM	Catenary failure, Milepost w/Letters, pvd, pvd, AM172 stopped in PVD Zone 10 rpts Emergency Plate Order all trks Davisville to Mansfield
175	WAS	103	DET	81	DET	44	RTE-RTE	AM	Catenary failure, Milepost w/Letters, rte, rte, AM175 holding at RTE a/c Zone 10 rpts Emergency Plate Order all trks Davisville to Mansfield
177	PHL	71	ITI	76	ITI	76	BOS-BOS	AM	Service, turn, or wye train, 172, Dp BOS late a/c late AM172
179	PHL	20	CTI	16	CTI	10	NYP-NWK	AM	Follow, NJT, NJMM92, Other, NYP-NWK, FLWD NJMM92
183	WAS	27	CAR	39	CAR	33	PHL-PHL	AM	Air / Brake / Wheel, 82640, 43389, HIGH LO BELLOW
193	WAS	22	CTI	15	WTR	8	MET-XHM	AM	Heat order, Other, MET-XHM, HEAT ORDERS
197	WAS	165	ENG	108	ENG	108	PHL-PHL	AM	Pick up rescue locomotive due to mechanical failure, E/664
474	SPG	17	SMW	13	SMW	13	WFD-MDN	AM	Diversions around M/W work, Milepost w/Letters, wfd, mdn, Heat patrol ahead
475	NHV	40	PTI	36	PTI	22	SPG-WNL	AM	Meet, 486, Milepost w/Letters, spg, wnl, Met AM486 at field
486	GFD	16	PTI	13	PTI	13	WND-WNL	AM	Meet, 55, Milepost w/Letters, wnd, wnl, AM486 met AM55 at hayden
609	XHM	Trn Cancelled	CTI	3	CTI	3	NYP-NWK	AM	Cross Traffic, NJT, NJ6627, Other, XPT
647	HAR	56	MTI	23	MTI	23	EWB-TRE	AM	Disabled train ahead, Other, XLT-TRE, CONGESTION AHD A/C AM609 DISABLED ON 3TRK WEST OF DELCO
651	HAR	30	CCR	25	CCR	25	PHL-PAO	AM	Set out defective cab car, 9634, WYE JOB
653	HAR	12	DCS	9	DCS	9	NYP-NWK	AM	Restrictive signal(s) from unknown cause, NA, Other, XHU-NWK, TOL OVER 79SW REVERSE AT DOCK

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
655	HAR	34	ITI	44	ITI	44	NYP-NYP	AM	Service, turn, or wye train, 652, LATE TURN OFF AM652
680	BON	42	DSR	37	DSR	22	BRK-FRE	CS	Per bulletin Milepost w/Letters, bru 4.0, 8.3, 10, single
682	BON	41	DSR	40	DSR	20	BRK-FRE	CS	Per bulletin Milepost w/Letters, bru 15.6, bru 8.3, 25, 1
683	POR	25	PTI	8	PTI	8	EXR-DHM	CS	Meet 684, Control Point, rockingham
684	BON		DCS	9	DMW	8	WOB-BON	MT	Waiting for MW clearance Control Point, Winchester
685	POR	35	PTI	22	PTI	22	ORB-POR	CS	Meet 688, Control Point, mountain
686	BON		WTR	15	PTI	12	ORB-SAO	CS	Meet 683, Control Point, surf
687	BRK	55	DSR	42	DSR	36	FRE-BRK	CS	Per dispatcher (radio/phone) Milepost, 8.3, 1, 10, s
689	BRK	24	DSR	26	DSR	18	FRE-BRK	CS	Per bulletin Milepost, 4.0, 8.3, 10, single
63	TWO	88	SVS	41	SVS	41	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
64	ALB	17	WTR	58	WTR	23	ROC-XSV	CS	Heat order Milepost, 371.0, 323.0
68	NYP	26	WTR	52	WTR	52	SLQ-RSP	CN	Heat order Milepost, 42, 2
241	ALB	24	CTI	28	CTI	17	CRT-POU	MN	Follow Held us CP32 to put the 869 in front of us, then followed it all the way to POU., metro, Milepost, 33.3, 72.0
244	NYP	51	ENG	31	ENG	31	ALB-HUD	AM	Traction motor Engine 709 lost HEP with multiple faults. Wait for ALB mechanical to arrive and isolate lead engine and set up rear engine as source of power, 709
284	NYP	24	RTE	27	RTE	25	POU-CRT	MN	Dispatcher hold Single tracking 61-72, Control Point, 72
290	NYP	44	DCS	48	DCS	42	XWH-FED	DH	Power switch failure Control Point, 77
291	BTN	22	PTI	26	PTI	26	SAR-SAR	DH	Meet 68, Other, saratoga
48	NYP	39	FTI	51	FTI	15	ERI-BUF	CS	Follow I 162, Milepost, 25.0, 15.0
42	NYP	21	DSR	18	CAR	13	PHL-PHL	AM	Door, 81543
43	PGH	263	CAR	172	CAR	172	NYP-NYP	AM	Air / Brake / Wheel, 25083-25048, LATE F/SSYD SHOPPED CARS 25083-25048 FOR UNSPECIFIED REASONS SUBBED CARS 25010-25054
73	CLT	27	FTI	22	FTI	22	CYN-DNC	NS	Meet #NSE50, Control Point, D&S Jct

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
74	RGH	Tm Cancelled							
75	CLT	54	FTI	34	FTI	34	HPT-SAL	NS	Meet Nothing between Duke and North Kannapolis. Dispatcher PCG, Control Point, Duke, #NS28R
76	RGH	64	PTI	45	PTI	45	GRO-DNC	NS	Meet #Amt79, Control Point, Isom
77	CLT	150	CON	145	CON	145	GRO-GRO	NS	Hold for bus with passengers from train Bus Bridge from RGH to GRO.
78	RGH	83	ITI	88	ITI	88	CLT-CLT	NS	Service, turn, or wye train 77
89	SAV	31	FTI	23	WTR	21	CHS-YEM	CS	Flash flood warning Milepost w/Letters, a 408.9, a 428.0
97	MIA	52	SVS	80	SVS	77	NYP-NYP	AM	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C WAITED FOR CARS OFF AM98
98	NYP	80	WTR	81	SYS	26	KTR-FLO	CS	PTC-caused slow-down or penalty stop IMMEDIATELY AFTER LIGHTNING STRIKE, SIGNAL DROPPED AND PTC PLACED TRAIN INTO AN EMERGENCY BRAKE APPLICATION. RADIO WOULD NOT TONE BACK, HAD TO INITIALLY CONTACT DISP BY PHONE. PREFORMED WALKING AND NECESSARY INSPECTIONS W/PERMISSION TO LEAVE FROM 314.5, Other, 31
55	WAS	71	DSR	51	DSR	12	ESX-WAB	NE	Per bulletin Milepost, 8.00, 104.00, 25, main
56	SAB	65	DSR	38	DMW	22	WNM-WRJ	NE	Waiting for MW clearance Milepost, 0, 15
40	CHI	32	WTR	92	PTI	30	SAV-DNK	CS	Meet amt 41, Siding, denmark
41	MIA	139	WTR	92	FTI	30	CUM-MRB	CS	Follow C782/26, Milepost w/Letters, Cum Strn., Mexico
5	EMY	173	TRS	214	TRS	214	OMA-LNK	BN	Trespasser strike Trespasser strike, Milepost, 56.8, 56.8
6	CHI	109	FTI	66	DBS	40	BRL-GBB	BN	Debris strike 2 pieces of metal, Other, MP 174.2
520	SAC	71	TCR	65	TCR	65	OKJ-OKJ	UP	Had air issues, seem like a few gaskets needed to be changed. And commissary was on board. San Joaquin's food want drinks were on a capitol and the train did not have a chiller and b/o coffee maker. C8310

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
522	SAC	17	TCC	22	TCC	22	OKJ-OKJ	UP	HEP C8301, C8024, NO HEP / BATHROOM ISSUES IN CAR 8024 // TRAIN WASNT CLEANED LATE YARD RELEASE
527	SJC	113	TRS	112	TRS	112	OKJ-OKJ	UP	Vehicle on track ahead MP 10.86 Niles sub, Other, MP 10.86
528	SAC	80	TRS	81	TRS	58	HAY-HAY	UP	Vehicle on track ahead AA to A to Stop into HAY acct dispatcher having us wait on a vehicle collision ahead at MP10.37 Niles sub. Then had to wait on train routing backlog., Milepost, 10.37, 10.37
529	SJC	69	POL	63	POL	63	OKJ-OKJ	UP	Right of Way police hold Vehicle crash on/near tracks
531	OKJ	12	PTI	6	PTI	6	EMY-OKJ	UP	Meet 711, Control Point, king
532	SAC	62	ITI	56	ITI	56	SJC-SJC	UP	Service, turn, or wye train 527
534	SAC	24	DCS	29	DCS	29	MTZ-SUI	UP	Power switch failure Control Point, Park
543	SJC	16	POL	12	POL	12	EMY-EMY	UP	Right of Way police hold
502	SEA	16	OTH	7	OTH	7	XA4-TUK	BN	Lost time - N.A.R.
505	PDX	18	DCS	15	DCS	15	VAN-PDX	BN	Restrictive signal(s) from unknown cause Authority by red signals. Restricted speed, Red, Red, Control Point, willbridge, Control Point, 2.2
507	EUG	18	FTI	27	MBO	22	VAN-PDX	BN	For maritime traffic Bridge, willamette
516	VAC	19	ENG	20	ENG	20	EVR-STW	BN	HEP Lost HEP twice on curves going through Delta Yard on curves. Cables loosen on their own and unseat themselves., WS1403
8	CHI	60	FTI	86	FTI	30	WPT-WTN	BN	Meet BNSF 5935, Siding, Macon
822	OKC	64	DSR	47	FTI	25	GLE-ADM	BN	Meet Bnsf 3927, Siding, Gainesville
330	CHI	36	CTI	31	ENG	27	MKE-MKE	CP	Doors showed open, checked all doors, Checked Train end relay, No traction - door bypass cutout - 2478834 - ok to cut out 629am FDS and CNOC Mech FB 642am ID4608
331	MKE	29	ITI	34	ITI	34	CHI-CHI	AM	Service, turn, or wye train 330
338	CHI	27	CTI	31	CTI	10	GLN-XWA	ME	Cross Traffic Metra, 2242, Metra, 2229, Control Point, A5
339	MKE	28	CTI	27	CTI	14	GLN-XRO	ME	Follow Metra, 2137, Milepost, 17.4, 30.1
341	MKE	18	ITI	17	ITI	17	CHI-CHI	AM	Service, turn, or wye train 1340

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/29/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
350	PNT	24	PTI	36	PTI	28	XB0-XA5	MI	Meet Amtrak Wolverine 353, Control Point, CP96
351	CHI	40	PTI	22	PTI	18	KAL-X90	AM	Meet Amtk 351, Siding, LAWTON
354	PNT	143	PTI	97	PTI	89	KAL-KAL	MI	Meet amt355, Other, kal
564	SAN	51	FTI	51	FTI	51	XRJ-FUL	BN	Follow BNSF 6956, Milepost, 147, 164
566	SAN	19	FTI	34	FTI	34	XRJ-FUL	BN	Disabled BNSF freight train causing service disruption on the San Bernardino sub. BNSF, Milepost, 164, 164
710	BFD	16	PTI	19	PTI	19	MCD-MDR	BN	Meet AMTK 713, Siding, La Grand
716	BFD	17	PTI	30	PTI	30	SKN-MOD	BN	Meet 715, Siding, riverbank
717	OKJ	28	PTI	29	PTI	12	MDR-MCD	BN	Meet 716, Siding, Sharon
719	OKJ	19	PTI	35	PTI	12	TRK-MOD	BN	Meet 718, Control Point, W Denair
3	LAX	109	FTI	159	FTI	47	BAR-VRV	BN	Follow BNSF, Control Point, lenwood
4	CHI	291	FTI	99	WTR	56	TRI-LAJ	BN	Flash flood warning Milepost, 637, 587
22	CHI	51	FTI	106	SVS	60	FTW-FTW	TE	Fuel Other, FTW Station
300	CHI	40	DCS	35	DCS	24	XWR-XW1	UP	Restrictive signal(s) from unknown cause Stop, Control Point, wood river
383	QCY	33	FTI	19	FTI	12	GBB-MAC	BN	Meet Control Point, albington, bnsf 8338
390	CHI	20	DSR	15	DMW	12	XCS-X9R	CT	Held for or routed around MW work or equipment Control Point, 16 th st
318	CHI	39	FTI	46	FTI	23	STL-XQT	TR	Cross Traffic Control Point, Gratiot, BNSF8376
319	KCY	35	ENG	35	ENG	35	SPI-CRV	UP	Engine had a Hot journal alarm Conductor and engineer both check first 2 axels with a tempo stick No defects found CNOC inform us to proceed for 10 miles not exceeding 50mph and re-check No defects were found a second no Alarms in Engine at this time ID4632
1333	MSP	33	FTI	35	DSR	17	WIN-RDW	CP	Per bulletin Milepost, 326.4, 326.8, 25, m, Milepost, 355.2, 361.8, 25, m, Milepost, 362.7, 363, 40, m, Milepost, 364.9, 365.1, 40, m
1340	CHI	47	DSR	49	DSR	18	CBS-MKE	CP	Per dispatcher (radio/phone) Milepost, 121.09, 108.0, 25, m

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/29/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	76	07/29	12	12	Service, turn, or wye train 75
CLT	78	07/29	88	88	Service, turn, or wye train 77
HAR	654	07/29	8	8	Wheelchair, 4:30pm/section b
HAR	658	07/29	4	4	Door, 9633, DOOR BY PASS CUT OUT
MIA	40	07/29	14	14	Air / Brake / Wheel 62029, Cut out car because of wheels
PHL	656	07/29	(No OS)		
RGH	77	07/29	(Trn Cxld)		NS Heat Orders
RNK	66	07/29	48	48	Service, turn, or wye train 151, Inbound train 151 arrived late to the storage yard.
WAS	130	07/29	15	15	Air / Brake, 658, stuck brake
WAS	184	07/29	18	18	Door, . UNKNOWN, THERE WAS A HIGH LOW BEFORE THE TRAIN DP NYP WHITCH DELAYED THE TRAIN HERE.
WAS	2124	07/29	7	7	Other electrical failure, ., ENG - LOCOMOTIVE ISSUES ON 662 CAUSED CREW TO ARRIVE LATE OFF TRAIN 171, 97" LATE
BON	687	07/29	10	10	Service, turn, or wye train 686
BOS	67	07/29	9	9	Door, c/48156 & c/82598, AM67 dp BOS 9" late a/c door issues on c/48156 & c/82598.
BOS	175	07/29	12	12	Service, turn, or wye train, 170, Late / short turn of AM170
BOS	177	07/29	76	76	Service, turn, or wye train, 172, Dp BOS late a/c late AM172
BOS	179	07/29	5	3	High passenger count, 210 pax boarding at BOS
BOS	179	07/29	5	2	Mobility Impaired, Special service request for pax w/ impaired mobility at BOS
BOS	2173	07/29	32	32	Catenary failure, Control Point, bos, AM2173 held in BOS a/c OCS couldn't hold power b/t Orms and Holden
NYP	19	07/29	35	35	Water, commissary, toilet/trash dumping, LATE F/SSYD WAITING FOR CAR 62008 & ENG.668
NYP	43	07/29	172	172	Air / Brake / Wheel, 25083-25048, LATE F/SSYD SHOPPED CARS 25083-25048 FOR UNSPECIFIED REASONS SUBBED CARS 25010-25054
NYP	49	07/29	32	32	Water, commissary, toilet/trash dumping, LATE FROM SSYD A/C LATE RELEASE BY CATERING
NYP	63	07/29	41	41	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	79	07/29	18	18	Water, commissary, toilet/trash dumping, LATE F/SSYD LATE RELEASE BY MECHANICAL
NYP	97	07/29	183	183	Undesired emergency application, 620 602, LATE FROM SSYD A/C WAITED FOR CARS OFF AM98 AND SHOPPED ENGS620/602 AND REPLACED WITH ENG.670

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/29/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	111	07/29	9	9	Undesired emergency application, 626, LATE FROM SSYD A/C UNSPECIFIED MECHANICAL ISSUE WITH REAR ENGING 626.
NYP	129	07/29	27	27	Door, ALL, LATE FROM SSYD A/C DOOR ISSUES THRU OUT TRAIN
NYP	151	07/29	131	131	Set out defective locomotive, 616, " LATE DUE TO SHOPPED ENGINE AND LATE RELEASE FROM THE YARD
NYP	193	07/29	5	5	Follow, NJ, 6431, Other, NYP, CONGESTION AHEAD DUE TO LATE NJ6431
NYP	197	07/29	19	19	Water, commissary, toilet/trash dumping, LATE FROMM SSYD A/C LATE RELEASE BY MECHANICAL
NYP	243	07/29	59	59	Service, turn, or wye train, 244, LATE TURN OFF OF AM244
NYP	283	07/29	24	24	HEP, 119, LATE F/SSYD UNSPECIFIED ENGINE PROBLEM
NYP	655	07/29	44	44	Service, turn, or wye train, 652, LATE TURN OFF AM652
NYP	2107	07/29	53	53	Animal strike, Other, NYP, LATE F/SSYD A/C BIRD IN PANTOGRAPH
POR	684	07/29	6		
CHI	3	07/29	25	25	Late release due to engine issues 152
CHI	5	07/29	5	5	Other electrical failure HVAC failure. No air conditioning even though it was written up on MAP-100, 78
CHI	21	07/29	8	8	Water, commissary, toilet/trash dumping Other, Chicago Union station
CHI	59	07/29	135	135	Late release of engine 11
CHI	331	07/29	34	34	Service, turn, or wye train 330
CHI	339	07/29	10	10	Service, turn, or wye train 338
CHI	341	07/29	17	17	Service, turn, or wye train 1340
CHI	383	07/29	8	8	HEP No a/c on lead engine, ID4602
EUG	508	07/29	4	4	Clear the Eugene siding and return to the siding after the arrival of a Northbound UP train. UP engine unknown, Other, Eugene
MKE	330	07/29	27	27	Doors showed open, checked all doors, Checked Train end relay, No traction - door bypass cutout - 2478834 - ok to cut out 629am FDS and CNOC Mech FB 642am ID4608
SEA	11	07/29	14	14	Late Yard Move Switch crew unavailable for normal yard move due to hot bearing on Sounder equipment; road crew unfamiliar with yard; job briefing and map review before moving equipment
STL	311	07/29	7	7	Meet AMT 22, Control Point, STL Station
EMY	6	07/29	7	7	Meet amtk 527, Control Point, shellmound
LAX	14	07/29	8	8	Hold for connecting train 3

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/29/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	520	07/29	65	65	Had air issues, seem like a few gaskets needed to be changed. And commissary was on board. San Joaquin's food want drinks were on a capitol and the train did not have a chiller and b/o coffee maker. C8310
OKJ	522	07/29	22	22	HEP C8301, C8024, NO HEP / BATHROOM ISSUES IN CAR 8024 // TRAIN WASNT CLEANED LATE YARD RELEASE
OKJ	712	07/29	6	6	Vehicle on track ahead Vehicle on tracks at East Oakland causing train congestion at OKJ, Control Point, east oakland
SAC	537	07/29	4	4	Waiting for MW clearance Milepost, 88.9, 88.9
SAS	22	07/29	8	8	Train 2 was obstructing Train 22 on track 3 could not load passengers or bags Other, SAS DEPO
SJC	532	07/29	56	56	Service, turn, or wye train 527
SJC	544	07/29	6	6	Restrictive signal(s) from unknown cause Red, Control Point, Shark

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	96.8	94.9	95.2	341	11
CDOT	95.0	95.0	92.5	96.4	20	1
MARC	95.0	92.9	79.4	83.5	56	4
SEPTA	95.0	95.1	96.3	96.2	223	11
NJT-NED	95.0	91.7	92.4	95.2	362	30
NJT-SED	95.0	100.0	98.2	91.2	24	0

Operating Highlights

Train 244(29) - North of Hudson, NY - Engine Failure

29JUL25: Train 244(29) was delayed on the Amtrak Hudson Line at MP 136.4 due to E/709 dropping HEP after multiple faults. Mechanical personnel from Albany responded. the lead engine 709 was isolated and the rear engine 90 was set up to provide all power and HEP.

Train	Delay	Comment
244 (29)	31"	
243 (29)	59"	Turn off 244 (29)

Train 20(29) - Southwest of Atlanta, GA - Tree Strike

29JUL25: Train 20(29) was delayed on the Norfolk Southern East End Subdivision at MP 694.6 due to striking a tree and losing air, which put the train into emergency. The conductor inspected, discovered uncouples air hoses and remedied. HEP on the train was down for a brief moment while the conductor worked on recoupling the hoses.

Train	Delay	Comment
20 (29)	30"	

Train 2167(29) - North of Baltimore, MD - Engine Failure

29JUL25: Train 2167(29) was delayed on the Amtrak PW Line at MP 87.5 due to losing all power and going into UDE. The train lost HEP. The crew consulted with the on-duty Road Foreman and was able to restore HEP after a few minutes. After recycling, the crew conducted a brake test and proceeded south into Washington Union Terminal. Train 97(29) shadowed Train 2167(29) into Washington, to provide passenger rescue if needed.

Train	Delay	Comment
97 (29)	23"	
2167 (29)	24"	

Train 197(29) - Philadelphia, PA - Engine Failure

29JUL25: Train 197(29) was extensively delayed at 30th Street Station/MP 1.4 in Philadelphia, PA due to the engine 667 being shopped. The crew requested mechanical personnel meet them upon arrival to inspect E/667, which started to vibrate violently when over 90mph. Management in Philadelphia decided to swap the engine out and replace with E/664. Passengers on Train 197(29) were transferred to Train 137(29) and Train 55(29).

Train	Delay	Comment
197(29)	1'50"	
137(29)	12"	
55(29)	02"	
197(29)	40"	Hold at WIL for EN Recrew

Train 97(29) New York, NY - Engine Failure

29JUL25: Train 97(29) was delayed departing New York due to shopped engine and equipment need off late inbound 98(28).

Train	Delay	Comment
97(29)	3'03"	

Train 66(29) Roanoke, VA - Initial Terminal Delay

29JUL25: 66(29) was delayed departing Roanoke, VA due to late turn of equipment from 151(29) which arrived to Roanoke VA at 335PM ET.

Train	Delay	Comment
66(29)	48"	

Train 19(29) New York, NY - Initial Terminal Delay

29JUL25: Train 19(29) was delayed departing New York station due to late release from the yard. This was due to waiting for E/668, Car 62008, water commissary service and trash dumping.

Train	Delay	Comment
19(29)	35"	

Train 609(29) New Brunswick, NJ - Engine Failure

29JUL25: At 140P-ET, Train 609(29) with E/649, CC/9643 and 4 cars was disabled on the New York to Philadelphia main line at MP 34.0 with 246 passengers onboard and HEP was down. The crew was able to restore HEP as of 204P-ET but they were still having issues building air for the brake test. It was determined that the passengers would be transferred to train 43(29) and 647(29). The KN crew will couple to train 609(29) to bring them into Philadelphia. Train 656(29) will be cancelled Harrisburg to Philadelphia and will operate Philadelphia to New York. As of 420P-ET Train 609(29) equipment was on the move towards Philadelphia. Train 43(29) Harrisburg crew was signing up off a cut at 655P-ET.

Train	Delay	Comment
609(29)	TERM MET	
43(29)	45"	TRANSFER PAX
656(29)	03"	Orig PHL
43(29)	09"	HAR crew s/u 655p-et

Train 171(29) New York, NY - Engine Failure

29JUL25: Train 171(29) was delayed departing New York due to E/662 having HEP issues and adding E/618.

Train	Delay	Comment
171(29)	36"	

Train 170(29) Providence, RI - Catenary or Wayside Failure

29JUL25: Train 170(29) was stopped at Providence Station due to debris in the catenary at Orms interlocking on track 2 which caused a TOL. ET reported no trains on track 2 between Orms and Lawn due to trolley wire being down. As of 1250P-ET, C&S arrived on the scene at Orms. Train 2167(29) was held at Route 128.

As of 243P-ET Boston Chief reported that train 2167(29) and 137(29) reported losing over catenary power on track 1 between Providence and Lawn. Train 2169(29) was held at Hebronville maintaining Overhead Catenary. As of 251P-ET the overhead catenary was restored on track 1 Providence to Lawn.

As of 337P-ET Boston Chief reported overhead catenary was restored on track 2.

As of 341P-ET Boston Chief reported overhead catenary was restored Davisville to Lawn. Overhead catenary down all tracks Law to Hold. 172(29) held at Providence and 175(29) held at Route 28.

As of 350PM train 86(29) ran around 888(29) at Davisville and held in Providence. Train 2173(29) held in Boston. Tree branch found was found the wires and ET responded to remove the branch from the wires.

UPDATE: Branch found in feeder wire ET on scene attempting to remove.

Train	Delay	Comment
170(29)	1'01"	
175(29)	46"	
172(29)	1'21"	
137(29)	33"	
2169(29)	40"	
2167(29)	1'08"	
2173(29)	32"	
86(29)	20"	
177(29)	1'16"	Turn off 172(29)

Train 43(29) New York Station - Car Failure

29JUL25: Train 43(29) was delayed departing New York Station due to AC issues with C/25083 and C/25048 and replaced with C/25010 and C/25054 which caused a late release from the yard.

Train	Delay	Comment
43(29)	2'52"	

Piedmont Service Adjustments - NS Heat Orders - Weather

29JUL25: Due to NS Heat Orders between Raleigh and Durham from 2p-ET til 6P-ET at 25MPH and 30 miles from Raleigh to Selma form 2P-ET til 6P-ET at 25MPH the following Piedmont Service adjustments were made Train 74(29) was terminated at Greensboro with alternate bus transportation from Greensboro to Raleigh and train 77(29) was originated at Greensboro with alternate bus transportation from Raleigh to Greensboro.

Train	Delay	Comment
74(29)	TERM GRO	ALT BUS
77(29)	2'25"	ORIG GRO ALT BUS

CSX Heat Orders - Northeast and Southeast Regions

29JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Capital, Alleghany, Baltimore Terminal, Berkshire, Boston, Buffalo Terminal, Grand Rapids, Monon Cumberland, Kanawha, Keystone, Metropolitan, Mohawk, New River, Old Main Line, Peninsula, RF&P, Rochester, Syracuse Terminal, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah, and Tampa Terminal.

Train	Delay	Comment
40 (29)	47"	
64 (29)	58"	
98 (29)	1'06"	
52 (29)	15"	
283 (29)	19"	
125 (29)	29"	
687 (29)	07"	
186 (29)	16"	
281 (29)	39"	
95 (29)	21"	
90 (29)	26"	
685 (29)	10"	
63 (29)	34"	
138 (29)	18"	
53 (29)	12"	
686 (29)	15"	
80 (29)	37"	
684 (29)	05"	
683 (29)	07"	
79 (29)	34"	
141 (29)	25"	
40 (28)	33"	
97 (28)	50"	
41 (28)	18"	

Northeast Corridor Heat Restrictions - Weather

29JUL25: Due to the extreme temperatures throughout the Northeast Corridor the following heat orders were in effect:

New Haven to Boston main line from 2P-ET thru 530P-ET level 1 tracks 1 and 2 from Packard and Cranston , from 3P-ET thru 630P-ET level 1 tracks 1 and 2 from MP190.8 and MP 227.0.

New Haven to Boston main line from 11A-ET thru 730P-ET level 3 track 1 at Shore Line Junction Interlocking Limits, from 10A-ET thru 8P-ET track 1 Atwells Interlocking Limits

MRS main line from 1P-ET thru 7P-ET level 1 tracks 1 and 2 for Berlin station and Wood.

New York to Philadelphia main line level 1 from 1230P-ET thru 730P-ET all tracks at Hunter and MP 76.0 and MP 76.0 - Shore, level 3 from 12P-ET thru 730P-ET track B at Lack Interlocking Limits, tracks 5 and A at Hunter Interlocking Limits, track 1 at Union Interlocking limits, track 1 at Ham Interlocking limits.

Hudson main line from 11A-ET thru 7P-ET level 1 track 1 from MP 124.3-MP 127.0, track 2 MP 124.3-MP 141.1, track 1 MP 135.0 - MP 141.1 and all tracks from MP 149.0-MP 156.3. Level 3 from 12P thru 730P-ET on track 2 from MP7.0-8.0 and track 1 at Inwood Interlocking Limits.

Philadelphia to Washington main line level 1 all tracks from 12P-ET-6P-ET Bush-CP Ave, Level 3 from 12P-ET-6P-ET track 3 Limits of Perry Interlocking and MP 126.0-MP 127.0.

Washington Terminal from 12P-ET- 6P-ET level 3 CP Ave and K Bridge

Philadelphia to Harrisburg main line level 3 from 12P-ET-8P-ET Limits of Overbrook Interlocking.

Train	Delay	Comment
654 (29)	10"	
2168 (29)	09"	
175 (29)	03"	
197 (29)	11"	
2193 (29)	08"	
2167 (29)	06"	
193 (29)	08"	
2154 (29)	03"	
97 (29)	03"	
137 (29)	04"	
2169 (29)	04"	
176 (29)	07"	
2172 (29)	10"	
653 (29)	05"	
2122 (29)	02"	
171 (29)	15"	
80 (29)	03"	
148 (29)	05"	
651 (29)	11"	
93 (29)	07"	
42 (29)	03"	
647 (29)	03"	
2170 (29)	05"	
85 (29)	03"	
94 (29)	10"	
283 (29)	02"	
125 (29)	08"	
43 (29)	07"	
2121 (29)	13"	
2168 (29)	09"	
2155 (29)	09"	
119 (29)	03"	
2153 (29)	09"	
95 (29)	10"	
645 (29)	04"	
2108 (29)	05"	
20 (28)	05"	

Train 183(29) At Philadelphia Station - Car Failure

29JUL25: Train 183(29) was delayed at Philadelphia 30th St. Station due to high low between cars 82640 & 43389. Mechanical responded and was able to resolve the issue.

Train	Delay	Comment
183(29)	33"	

Train 2154(29) Wilmington, DE - Engine Failure

29JUL25: Train 2154(29) with set 19 with PC/2021,PC/2024 was delayed at MP 26.8/Wilmington station on the Philadelphia to Washington main line due to ACSSES issues upon arrival. Engineer was resetting the ACSSES and was able to correct the issue.

Train	Delay	Comment
2154(29)	31"	

Train 41(28) Connellsville, PA - Trespasser Incident

29JUL25: Train 41(28) went into emergency on the CSX Keystone Subdivision at MP 242.9 due to a near miss with a trespasser.

Train	Delay	Comment
41(28)	18"	

Train 63(29)/69(29) New York, NY - Initial Terminal Delay

29JUL25: Combo train 63(29)/69(29) was delayed departing New York station due to a late release from the yard.

Train	Delay	Comment
63(29)/69(29)	41"	

Train 2107(29) New York, NY - Initial Terminal Delay

29JUL25: Train 2107(29) was delayed departing New York yard due to a bird on the pantograph.

Train	Delay	Comment
2107(29)	53"	

Train 151(29) - New York Penn Station/Sunnyside Yard - NY - Initial Terminal Delay

29JUL25: Train 151(29) was delayed at its initial terminal at New York Penn Station due to an engine being shopped late at Sunnyside Yard.

Train	Delay	Comment
151(29)	2'13"	

Train 2103(29) - Northeast Corridor - Cancelled

29JUL25: Train 2103(29) was cancelled due to equipment availability. No alternate transportation was provided.

Train	Delay	Comment
2103(29)	Cancelled	

OTP Acela/Regional Cancellations - Miscellaneous Amtrak Responsible

29JUL25: In an effort to improve Northeast Regional OTP the following service adjustments have been made:

Acela Trains 2163(28-30SEP) and 2166(28-30SEP) will be cancelled from July 28,2025 thru September 30,2025.

Train 170(31-30SEP) will be suspended Monday thru Friday from July 31,2025 to September 30,2025.

Train 137(31-30SEP) will be suspended Monday thru Thursday and truncated to operate New York to Washington only on Friday.

Train 123(31-30SEP) suspended Sunday

Train 139(31-30SEP) truncated at Philadelphia on Sunday will operate Boston to Philadelphia.

Northeast Corridor Service Adjustments - Heat Related Cancellations

27JUL25: Due to the impending forecast of extreme temperatures over 98 degrees and storms along the Northeast Corridor for Tuesday July 29th & Wednesday July 30th 2025 the following service adjustments have been made: 112(29, 30) 192(29,30) 178(29,30) 131(29,30) 133(29,30) and 173(29,30) are cancelled in their entirety. This will allow protect regional trainsets in BOS, NYP & WAS.

Acela service cancellations were added as of 7/27/25 for trains 2159(29-30) and 2162(29-30) cancelled in their entirety.

Train	Delay	Comment
112(29-30)	Cancelled	
192(29-30)	Cancelled	
178(29-30)	Cancelled	
131(29-30)	Cancelled	
133(29-30)	Cancelled	
173(29-30)	Cancelled	
2159(29-30)	cancelled	
2162(29-30)	cancelled	

Maintenance of Way Highlights

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Downeaster Service Trackwork - CSX Portland Subdivision (Phase 2-3)

CSX/Portland Subdivision from Boston North Station, MA to Brunswick, ME Trackwork System Tie Gang. Phase 3 Portland, ME (POR) to Brunswick, ME (BRK) from Tuesday July 8th to Tuesday July 29th,

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Phase 3, begins July 8th - Extended through July 30th:

Northbound:

- Trains 681/683/685(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BON and BRK, will terminate at POR.
- Train 691/693/695(12Jul-13Jul, 26Jul-27Jul), which normally operates between BON and BRK, will terminate at POR.

Southbound:

- Train 682(7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-30Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 684/686/688(8Jul-11Jul, 14Jul-15Jul, 22Jul-25Jul, 28Jul-30Jul), which normally operates between BRK and BON, will originate at POR.
- Train 692 (12Jul-13Jul, 19Jul-20Jul, 26Jul-27Jul) will depart BRK 40-minutes Earlier, at 6:30am.
- Train 694/696/698(12Jul-13Jul, 26Jul-27Jul), which normally operates between BRK and BON, will originate at POR.

ALTERNATE TRANSPORTATION

- Buses 3681, 3683, 3685, 3691, 3693, and 3695 will provide alternate transportation between POR and BRK.
- Buses 3684, 3686, 3688, 3694, 3696, and 3698 will provide alternate transportation between BRK and POR.

WBS#: B.TR.100150.5488

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
197	PHL	667		Off due to L2 wheel defect E/664 added

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 20(29) Passenger Removal at Meridian, Mississippi – Other

29JUL25, Passenger on PNR 46f416, traveling from New Orleans, LA to Washington D.C. was reportedly removed due to sneaking a pet on the train that didn't meet the pet policy. Amtrak Police notified.

Delay: 20 (29) None

Train 95(29) Passenger Removal at Baltimore, Maryland – Other

29JUL25, Passenger on PNR 475833, traveling from New York, NY to Washington D.C. was reportedly removed due to not following the pet policy. Amtrak Police notified.

Delay: 95 (29) 03"

Train 69(29) Passenger Removal at Rouses Point, New York – Customs

29jul25, Passenger on PNR 4BDB23, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69 (29) None

Western Region

Operating Highlights

Train 6(28) West of Denver, CO - Servicing

30JUL25: Train 6(28) with E/146-148 and 10 cars was delayed just west of Denver at 23rd Street/MP 0.8 due to the crew stopping at 1154PM-MT to perform a calendar day inspection.

Train	Delay	Comment
6(28)	38"	

Train 6(29) East of Elko, NV - Freight Train Interference

29JUL25: Train 6(29) was delayed 110 miles east of Elko on the UPRR Shafter subdivision due to meeting GSMDPX-27 at Clifside/MP 781.6.

Train	Delay	Comment
6(29)	40"	

Train 22(29)/421(27) North of Texarkana, AR - Freight Train Interference

29JUL25: Train 22(29)/421(27) was delayed 13 miles north of Texarkana on the UPRR Little Rock subdivision due to MEWNL-28 with a repeat HBD and necessary to set out a car at Hope/MP 458.1. After the car was set out and the train was on the move, 22(29)/421(27) followed MEWNL-28 and MBZAS-28 to Beirne Jct./MP 429.3.

Train	Delay	Comment
22(29)	2'07"	

Train 307(29) South of Pontiac, IL - Engine Failure

29JUL25: Train 307(29) with E/ID4621 and 5 cars was delayed two miles south of Pontiac on the UPRR Joliet subdivision due to E/ID4621 shutdown with no coolant or HEP. There were 181 passengers on board and the weather was reported as 80 degrees and cloudy. A plan was put in place to use south facing UPRR 9636 from adjacent train IG4SIB-29 to be added to train 307(29), who operated dark to Bloomington-Normal, where they were terminated with alternate bus transportation. The decision was made to continue to Bloomington-Normal due to it being staffed, open, and able to accommodate the passengers on board. Local police were enroute to Bloomington-Normal station to assist. Amtrak Road Foreman and mechanical were enroute. Once UP 9636 was tied on and laced up, train 307(29) was back on the move at 1112PM-CT.

At Bloomington-Normal there were two buses for alternate transportation with an estimated spot time of 1245AM-CT. The buses arrived at 207AM-CT. Bus 1 operated between Bloomington-Normal, Lincoln, Springfield and St. Louis, departing Bloomington-Normal at 231AM-CT. Bus 2 operated express between Bloomington-Normal and St. Louis, departing Bloomington-Normal at 226AM-CT. The equipment deadhead Bloomington-Normal to St. Louis and was added to the rear of train 302(30) to deadhead back to Chicago. As a result of equipment changes, train 300(30) was cancelled with alternate bus transportation.

WBS#: B.TR.100150.5941

Train	Delay	Comment
307(29)	2'36"	Term BNL
300(30)	Cancelled	STL-CHI W/ alt

Train 354(29) Kalamazoo, MI - Car Failure

30JUL25: Train 354(29) with E/56 and 5 cars was delayed on the Amtrak Michigan Line at Kalamazoo due to C/ID4203 shutdown and preventing E/56 from loading. As a result, the car was locked out and passengers were accommodated in additional space. Additionally, due to these issues unable to be repaired in Pontiac, train 353(30) had 35 business class downgrades to coach with the train oversold 14 passengers between Jackson, MI and Chicago, IL. Customer service was working to source alternate transportation.

Train	Delay	Comment
354(29)	23"	

Train 508(29) South of Oregon City, OR - Passenger Train Interference

29JUL25: Trian 508(29) was delayed six miles south of Oregon City on the UPRR Brooklyn subdivision due to meeting 507(29) and UP 6025 at Coalca/MP 750.4.

Train	Delay	Comment
508(29)	21"	507(29)
508(29)	15"	UP 6025

Train 59(29) Chicago, IL - Initial Terminal Delay

29JUL25: Train 59(29) with E/13-11 and 15 cars was delayed departing Chicago due to E/837 bad ordered and scheduled to be replaced with E/11 from 6(27), which arrived Chicago at 428PM-CT, 1 hour, and 49 minutes late. Due to no available fuel truck, it was necessary to hold off E/11, which was sent to the diesel pit for fuel and servicing. The train was worked up and released at 916PM-CT to board 199 passengers. Once the train was boarded, 59(29) departed Chicago at 1020PM-CT, 2 hours, and 15 minutes late. After departing, the crew stopped and Harrison/MP 0.3 due to loading issues and shoved back to Chicago to meet mechanical technicians and troubleshoot. Once the issue was repaired, 59(29) departed Chicago a second time at 1122PM-CT, 3 hours, and 17 minutes late.

Train	Delay	Comment
59(29)	2'15"	CHI - late release
59(29)	1'02"	Loading issues

Train 543(29) Emeryville, CA – Police Search for Suspect

29JUL25 Train 543(29) was delayed when rail traffic was stopped in the vicinity Emeryville station MP 4.00, Martinez Subdivision of the Union Pacific Railroad. This was to allow for local police to apprehend a trespasser threatening self-harm on or near tracks. Once the suspect was in the custody of police tracks re-opened. Amtrak Police Notified.

Train	Delay	Comment
543(29)	12"	

Train 7/27(29) West of Milwaukee, WI - Passenger Train Interference

29JUL25: Train 7/27(29) was delayed 19 miles west of Milwaukee on the CPKC Watertown subdivision due to meeting 1340(29) at Pewaukee/MP 104.2.

Train	Delay	Comment
7/27(29)	35"	

Train 534(29) East of Martinez-Switch Failure

29JUL25: Train 534(29) was delayed at Park, milepost 36.00, Martinez Subdivision, of the Union Pacific Railroad. The dispatcher was unable to gain remote control of the switches. The crew of train 534(29) was required to manually operate switches before gaining verbal authority to pass the signal. The Engineer was required to operate the train at reduced speed until within sight of the next verified remote signal.

Train	Delay	Comment
534(29)	29"	

Train 4(28) East of Las Vegas, NM - Passenger Train Interference

29JUL25: Train 4(28) was delayed 11 miles east of Las Vegas on the BNSF Raton subdivision due to meeting 3(27) at Onava/MP 758.8.

Train	Delay	Comment
4(28)	1'21"	

Train 1(28)/421(27) West of El Paso, TX - Freight Train Interference

29JUL25: Train 1(28)/421(27) was delayed 30 miles west of El Paso on the UPRR Lordsburg subdivision due to following MEWWC-27 between MP 1256.0 and MP 1228.0.

Train	Delay	Comment
1(28)/421(27)	37"	

Train 8/28(27) West of Glenview, IL - Signal

29JUL25: Train 8/28(27) was delayed 25 miles west of Glenview on the CPKC C&M subdivision due to signal issues at Wadsworth/MP 44.3.

Train	Delay	Comment
8/28(27)	43"	

Train 319(29) South of Springfield, IL - Engine

29JUL25: Train 319(29), E/IDTX4632 & 7 cars, was delayed at MP188.6, 3 miles south of Springfield, IL, on the UPRR Springfield Subdivision, due to a hot journal alarm on E/IDTX4632. Crew was in contact with mechanical, inspected axles and took no exceptions. Train 319(29) operated 50MPH for 10 miles, reinspected and took exceptions.

Train	Delay	Comment
319(29)	35"	

Train 4(28) East of Las Vegas, NM - Flash Flood Warnings

29JUL25: BNSF issued flash flood warnings on the Raton Subdivision between MP745, 25 miles east of Las Vegas, NM, and MP733 and between MP637, 1 mile west of Trinidad, CO and MP648. Trains 4(28) and 3(28) were delayed operating through the affected areas.

Train	Delay	Comment
4(28)	51"	
3(28)	1'08"	

Train 6(27) East of Burlington, IA - Debris Strike

29JUL25: Train 6(27), E/11-E/164 & 10 cars, with 253 passengers, stopped in emergency at MP174.2, 30 miles east of Burlington, IA, on the BNSF Ottumwa Subdivision. Crew inspected consist and reported air blowing from apparent debris strike of two metal plates. There were no reported injuries to passengers or crew. HEP was down for approximately 30 minutes while crew worked to resolve air issues. Outside temperature was reported at approximately 82 degrees. After troubleshooting air issues, HEP was restored and Train 6(27) was on the move east. Train 6(27) stopped in emergency again at MP169.2. BNSF mechanical responder requested to assist. Crew inspected consist and found parted air hoses between the first and second cars, C/61037 and C/39023 and between the 6th and 7th cars, C/38066 and C/33019. There were no other exceptions to equipment reported. Crew secured hoses between C/38066 and C/33019 and replaced hose gaskets and hoses between C/61037 and C/39023. Crew reported issues resolved prior to BNSF mechanical arriving on scene and Train 6(27) was able to proceed east again from MP 169.2.

WBS#: B.TR.100150.5940

Train	Delay	Comment
6(27)	40"	MP174.2
6(27)	27"	MP169.4

CPKC River Subdivision East of Red Wing, MN - Temporary Speed Restrictions

29JUL25: Trains were delayed operating over the CPKC River subdivision between Red Wing, MN and Winoma, MN due to temporary speed restrictions between MP 365.1 and MP 326.4.

Train	Delay	Comment
1340(29)	16"	
8/28(27)	11"	
1333(29)	17"	
7/27(29)	21"	

Train 527(29) South of Oakland Jack London Sq, CA - Vehicle on Tracks

29JUL25: Train 527(29) was delayed departing Oakland Jack London Sq. A vehicle accident blocked the rail crossing at High Street Oakland (DOT # 749712Y) MP 10.37, Niles Subdivision of Union Pacific Railroad. Delays were extended waiting for local police to attend the site, leading to Amtrak Police officers being dispatched to assist. Once investigation was completed, the vehicles removed and tracks inspected, train 527(29) resumed to Oakland Coliseum. Amtrak Police Notified.

Service Recovery: 20 % discount on café items offered on trains 527(29), 529(29), 528(29) and 532(29).

Train	Delay	Comment
527(29)	1'58"	
528(29)	1'18"	
529(29)	1'03"	
11(28)	1'30"	
532(28)	56"	SJC - Equipment Turn from 527(29)

Train 564(29), East of Los Angeles CA – Freight Train Interference

29JUL25: BNSF Freight train YWA19601-28A experienced a mechanical failure Train 564(29) was delayed 19 miles east of Los Angeles at MP 163.00 Basta, San Bernardino Subdivision of the BNSF Railway. After temporary repairs were made, the freight train was able to resume with a 30MPH maximum speed restriction. This caused a backlog of trains thru the area. Train 562(29) was required to follow slower BNSF Freight train BNSF/6956 – for 18 miles – between Eastern Avenue (MP 147.3) and Fullerton (MP 164.00). Subsequent trains were also delayed by train interference in the area.

Train	Delay	Comment
564(29)	51"	Follow BNSF/6956
566(29)	34"	

Train 4(27) East of Dodge City, KS - Signal Issues

29JUL25: Train 4(27) was delayed east of Dodge City, KS/MP352.5, on the BNSF La Junta Subdivision, due to signal issues between Dodge City and Belpre/MP286.1. Train 4(27) was delayed flagging through the affected area. Train 3(28) was delayed at MP220.7, 2 miles west of Hutchinson, KS, on the BNSF La Junta Subdivision, meeting Train 4(27).

Train	Delay	Comment
3(28)	30"	
4(27)	44"	

Train 330(29) Late Departure Milwaukee, WI - Engine

29JUL25: Train 330(29), E/IDTX4608-4 cars-CC/90221, was delayed departing Milwaukee, WI, due to E/IDTX4608 indicating doors open. After troubleshooting with mechanical crew was able to resolve issue by cutting out door bypass and Train 330(29) departed Milwaukee at 642AM-CT, 27 minutes late. Train 331(29) was delayed departing Chicago, IL, due to late turn of equipment off Train 330(29) which arrived at 843AM-CT, 36 minutes late.

Train	Delay	Comment
330(29)	27"	MKE
331(29)	34"	CHI

Train 3(27) West of Barstow, CA - Freight Train Interference

29JUL25: Train 3(27) was delayed west of Barstow, CA/MP0.4, on the BNSF Cajon Subdivision, following westbound freight traffic between Barstow and Lenwood/MP6.8 and then at Lenwood holding for BNSF cross-traffic to clear ahead.

Train	Delay	Comment
3(27)	1'07"	

Train 520(29) - Oakland Jack London Square - Servicing Equipment

29JUL25: Train 520(29), CC/8310-3 cars-E/CDTX2103, was delayed departing Origin Oakland Jack London Square, CA,. Overnight – in Oakland Maintenance Facility – Cafe car C/8808 was removed for maintenance replaced with car C/8804. from delayed inbound 717(28). Problems with compressed air pressure led to late release to commissary, who were required to perform a complete stock as the replacement Café Car was from San Joaquin Service. Additionally there was no chiller or coffee machine in Café Car C/8804 leading to café service of non-perishable items only and no coffee service on trains 520(29)/531(29) .

Cause: Pending

Train	Delay	Comment
520(29)	1'05"	OKJ - ITD
522(29)	22"	OKJ- ITD -Late servicing - crews working on 520(29)

Train 21(28) South of Texarkana, AR - Deer Strike

29JUL25: Train 21(28), E/53-E/139 & 6 cars, with 119 passengers, stopped in emergency at MP11.7, 11 miles south of Texarkana, AR, on the UPRR Little Rock Subdivision, due to striking a deer. There were no reported injuries to passengers or crew. The crew inspected consist, found parted air hose between E/139 and C/39001 and secured same. There were no other exceptions to equipment taken. Train 21(28) was on the move south after restoring air and performing brake test. Train 21(28) stopped in emergency at MP11.8, 22 miles west of Longview, TX, on the UPRR Mineola Subdivision. Crew inspected consist and found air hose parted again between E/139 and C/39001. Crew reported no other exceptions to equipment. Train 21(28) was on the move west after crew changed out air hose and performed brake test.

Train	Delay	Comment
21(28)	10"	S/TXA
21(28)	37"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold
371(19) - 10 oversold
305(18) - 13 oversold
300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold
371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold
371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.

- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.

- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train

Delay

Comment

301 (15)	Cancelled, with alt	CHI-STL
302 (15)	Cancelled, with alt	STL-CHI
307 (14)	Cancelled, with alt	CHI-STL
301 (16Jul-04Aug)	Cancelled, with alt	CHI-STL
306 (16Jul-04Aug)	Cancelled, with alt	STL-CHI
381 (05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382 (05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Maintenance of Way Highlights

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage
7 (8)	WTN	348		HEP

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (22)	LVW	UP6769	E/58 air compressor failure		
307(29)	BNL	UP9636	ID4621 with coolant leak		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
7(29)	POG	1	RDW	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 383(28) Passenger Removal at Bushnell, Illinois – Improper Conduct

29JUL25, Passenger on PNR 4AD8C7, traveling from Chicago, IL to Macomb, IL was removed by the local police at Bushnell, IL (MP190.8 on the BNSF Railroad on the Brookfield Subdivision) due to being angry with the Conductor for asking him to use headphones and for cursing at the Conductor. Amtrak Police notified.

Delay: **383 (28)** **17"**

Train 5(29) Passenger Removal at Galesburg, Illinois – Improper Conduct

29JUL25, Passenger on PNR 489423, traveling from Chicago, IL to Sacramento, CA was removed by the Conductor at Galesburg, IL due to his erratic behavior and loud music disturbing the other passengers. Amtrak Police notified.

Delay: **5 (29)** **None**

Train 5(29) Passenger Removal at Omaha, Nebraska – Improper Conduct

29JUL25, Passenger on PNR 3D8943, traveling from Chicago, IL to Emeryville, CA was removed by the Conductor due to having his own alcohol and making inappropriate comments to the other passengers. Amtrak Police notified.

Delay: 5 (29) None

Train 28(29) Passenger Removal at Pasco, Washington – Improper Conduct

29JUL25, Passenger on PNR 3A902E, traveling from Portland, OR to Spokane, WA was removed by the local police at Pasco, WA due to his erratic behavior. Amtrak Police notified.

Delay: 28 (29) 16"

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/29/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	290	32	89%	8,258	769	91%	87,028	6,794	92%
Northeast Corridor	98%	72	16	78%	2,184	304	86%	23,369	2,537	89%
Acela	98%	19	3	84%	600	104	83%	6,515	872	87%
Northeast Regional	98%	53	13	75%	1,584	200	87%	16,854	1,665	90%
State Supported	98%	191	13	93%	5,278	305	94%	54,702	2,818	95%
Long Distance	98%	27	3	89%	796	160	80%	8,819	1,433	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/29/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	290	32	89%	8,258	769	91%	87,028	6,794	92%
Northeast Corridor	98%	72	16	78%	2,184	304	86%	23,369	2,537	89%
Acela	98%	19	3	84%	600	104	83%	6,515	872	87%
Northeast Regional	98%	53	13	75%	1,584	200	87%	16,854	1,665	90%
On Spine Northeast Regional	98%	25	7	72%	815	105	87%	8,549	883	90%
Richmond / Newport News / Norfolk	98%	12	3	75%	339	75	78%	3,519	539	85%
Roanoke	98%	4	3	25%	116	15	87%	1,202	165	86%
Springfield Shuttles	98%	12	-	100%	314	5	98%	3,584	78	98%
State Supported	98%	191	13	93%	5,278	305	94%	54,702	2,818	95%
Borealis	98%	2	-	100%	58	6	90%	589	65	89%
Capitol Corridor	98%	28	-	100%	756	29	96%	7,216	164	98%
Carolinian	98%	2	-	100%	58	10	83%	604	52	91%
Cascades	98%	14	1	93%	406	22	95%	4,107	290	93%
Downeaster	98%	10	-	100%	286	1	100%	2,874	45	98%
Empire	98%	20	3	85%	580	41	93%	6,466	341	95%
Adirondack	98%	2	-	100%	58	2	97%	604	43	93%
Berkshire Flyer	98%	-	-	100%	12	2	83%	18	4	78%
Ethan Allen Express	98%	2	-	100%	58	6	90%	604	40	93%
Maple Leaf	98%	2	-	100%	58	5	91%	604	59	90%
New York - Albany	98%	10	2	80%	278	12	96%	3,429	99	97%
New York - Niagara Falls	98%	4	1	75%	116	14	88%	1,207	96	92%
Heartland Flyer	98%	2	-	100%	54	1	98%	596	17	97%
Hiawatha	98%	12	1	92%	337	13	96%	3,450	128	96%
Illinois	98%	12	1	92%	370	35	91%	4,137	291	93%
Carl Sandburg / Illinois Zephyr	98%	4	1	75%	116	4	97%	1,196	47	96%
Illini / Saluki	98%	4	-	100%	115	11	90%	1,195	47	96%
Lincoln Service	98%	4	-	100%	139	20	86%	1,746	197	89%
Keystone	98%	27	2	93%	586	43	93%	6,901	431	94%
Lincoln / Missouri	98%	2	1	50%	58	12	79%	598	87	85%
Michigan	98%	10	2	80%	285	26	91%	2,889	280	90%
Blue Water	98%	2	-	100%	58	6	90%	600	88	85%
Pere Marquette	98%	2	-	100%	56	2	96%	602	27	96%
Wolverine	98%	6	2	67%	171	18	89%	1,687	165	90%
Missouri	98%	2	-	100%	56	1	98%	582	15	97%
Pacific Surfliner	98%	24	-	100%	696	18	97%	6,474	240	96%
Pennsylvanian	98%	2	2	-	58	13	78%	604	73	88%
Piedmont	98%	8	-	100%	231	2	99%	2,400	34	99%
San Joaquins	98%	12	-	100%	345	24	93%	3,611	205	94%
Vermont	98%	2	-	100%	58	8	86%	604	60	90%
Long Distance	98%	27	3	89%	796	160	80%	8,819	1,433	84%
Auto Train	98%	2	-	100%	58	7	88%	592	100	83%
California Zephyr	98%	2	1	50%	58	20	66%	601	142	76%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	-	-	100%	24	10	58%	256	54	79%
City Of New Orleans	98%	2	-	100%	58	7	88%	590	53	91%
Coast Starlight	98%	2	-	100%	60	4	93%	607	89	85%
Crescent	98%	2	-	100%	58	6	90%	604	70	88%
Empire Builder	98%	4	-	100%	111	17	85%	1,162	150	87%
Floridian	98%	2	-	100%	56	17	70%	513	178	65%
Lake Shore Ltd	98%	2	-	100%	58	17	71%	1,002	118	88%
Palmetto	98%	2	-	100%	58	4	93%	602	38	94%
Silver Meteor	98%	2	-	100%	56	14	75%	598	122	80%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	58	17	71%	602	154	74%
Sunset Ltd	98%	1	-	100%	25	7	72%	255	46	82%
Texas Eagle	98%	2	1	50%	58	13	78%	674	94	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/29/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	290	17	94%	8,373	248	97%	87,153	2,120	98%
Northeast Corridor	98%	71	7	90%	2,183	64	97%	23,320	662	97%
Acela	98%	19	1	95%	600	15	98%	6,517	171	97%
Northeast Regional	98%	52	6	88%	1,583	49	97%	16,803	491	97%
State Supported	98%	191	5	97%	5,363	101	98%	54,771	921	98%
Long Distance	98%	28	5	82%	827	83	90%	8,924	535	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/29/25											
Day				Month to Date				Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	
Amtrak System	98%	290	17	94%	8,373	248	97%	87,153	2,120	98%	
Central Division	98%	66	5	92%	1,902	97	95%	19,941	704	96%	
Northeast Division	98%	91	7	92%	2,657	68	97%	28,673	682	98%	
Southeast Division	98%	63	5	92%	1,834	53	97%	19,265	461	98%	
Southwest Division	98%	70	-	100%	1,980	30	98%	19,274	273	99%	

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/29/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	290	17	94%	8,373	248	97%	87,153	2,120	98%
Central Division	98%	66	5	92%	1,902	97	95%	19,941	704	96%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	2	-	100%	62	1	98%	605	3	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	27	4	85%	767	69	91%	8,043	456	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	58	2	97%	582	5	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	28	-	100%	301	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	57	-	100%	586	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	1	83%	169	5	97%	1,732	14	99%
MSP	98%	1	-	100%	29	1	97%	290	7	98%
PDX	98%	5	-	100%	141	1	99%	1,453	36	98%
PNT	98%	3	-	100%	85	2	98%	832	9	99%
PTH	98%	1	-	100%	29	-	100%	300	6	98%
QCY	98%	2	-	100%	56	-	100%	586	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	233	13	94%	2,360	126	95%
SPK	98%	1	-	100%	29	-	100%	310	2	99%
STL	98%	3	-	100%	97	3	97%	1,174	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	58	-	100%	579	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	91	7	92%	2,657	68	97%	28,673	682	98%
ALB	98%	7	-	100%	203	1	100%	2,112	26	99%
BON	98%	5	-	100%	143	-	100%	1,407	3	100%
BOS	98%	16	1	94%	509	10	98%	5,626	132	98%
BRK	98%	2	-	100%	92	1	99%	1,353	11	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	29	-	100%	300	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	51	-	100%	578	-	100%
HFD	98%	2	-	100%	40	-	100%	186	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	29	2	93%	300	7	98%
NFL	98%	2	-	100%	58	-	100%	604	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	5	-	100%	135	-	100%	1,542	35	98%
NYP	98%	38	6	84%	1,113	53	95%	12,107	438	96%
POR	98%	3	-	100%	48	-	100%	48	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	27	-	100%	298	1	100%
SPG	98%	5	-	100%	144	1	99%	1,840	20	99%
TWO	98%	1	-	100%	29	-	100%	299	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	63	5	92%	1,834	53	97%	19,265	461	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	141	1	99%	1,495	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/29/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	290	17	94%	8,373	248	97%	87,153	2,120	98%
Southeast Division	98%	63	5	92%	1,834	53	97%	19,265	461	98%
DNC	98%	-	-	100%	1	-	100%	1	-	100%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	12	1	92%	322	3	99%	3,268	23	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	29	1	97%	296	12	96%
MIA	98%	2	1	50%	55	6	89%	580	34	94%
NFK	98%	3	-	100%	82	2	98%	832	5	99%
NOL	98%	2	-	100%	65	1	98%	672	21	97%
NPN	98%	2	-	100%	58	1	98%	577	4	99%
PGH	98%	1	-	100%	29	1	97%	301	4	99%
PHL	98%	6	-	100%	124	7	94%	1,290	40	97%
RGH	98%	4	-	100%	108	-	100%	1,211	5	100%
RNK	98%	2	-	100%	53	-	100%	570	8	99%
RVM	98%	1	-	100%	29	-	100%	293	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	27	1	96%	283	1	100%
SFA	98%	1	-	100%	29	-	100%	296	18	94%
WAS	98%	20	3	85%	672	29	96%	7,147	276	96%
Southwest Division	98%	70	-	100%	1,980	30	98%	19,274	273	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	29	-	100%	302	-	100%
BFD	98%	6	-	100%	171	-	100%	1,794	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	29	4	86%	309	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	28	-	100%	334	5	99%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	87	-	100%	883	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	-	100%	273	5	98%	2,332	67	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	26	-	100%	297	-	100%
OKJ	98%	12	-	100%	320	13	96%	3,173	74	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	379	2	99%	3,610	14	100%
SAN	98%	12	-	100%	342	5	99%	2,764	27	99%
SAS	98%	1	-	100%	29	1	97%	298	3	99%
SJC	98%	7	-	100%	202	-	100%	1,942	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	58	-	100%	591	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	6	-	100%	53	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DA.. 7/29/2025 12:00..	Electric Locomotives		Diesel Loco moti..	Amfle et I	Amfle et II	High Speed Trainset			Super liner II	Cab Car		Viewli ner I	Talgo	Califo rnia C ars (..	Grand Total
	ENG	MTI	ENG	CAR	CAR	ENG	CAR	MTI	CAR	CAR	CCR	CAR	CCR	CAR	
Air/Brake Problems	198		7									14			219
MCB Tripping	131	59													190
Car Hot: Air Condi..				9	172										181
Blower Problems			164												164
HEP Problems	68	18	55												141
Door Problems			30	91			3			7				3	134
Wheel Defects	108														108
ACSES Failure						39		19			25				83
Loading Problems	15		61												76
Pantograph Proble..		73													73
Engine Dead/Shut ..			8			25		23							56
Hand/Parking Brak..				40											40
Air Hose Parted									37						37
HI-Low Condition				33											33
I-ETMS Problem			23										7		30
ITCS Problem			20												20
Traction Motor Pro..			8			6									14
Engineer Cab Furn..			13												13
480V Trainline Pro..				12											12
3RD Rail Equipme..			10												10
Grand Total	520	150	399	185	172	70	3	42	37	7	25	14	7	3	1,634