



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, August 01, 2025

Rules:0-57



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/31/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/31/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	28	90.5%	8,926	1,070	88.0%	87,634	8,739	90.0%
Central Division	91.5%	63	8	87.3%	2,025	247	87.8%	20,054	1,987	90.1%
Northeast Division	95.0%	95	8	91.6%	2,815	380	86.5%	28,770	3,143	89.1%
Southeast Division	94.5%	67	6	91.0%	1,965	235	88.0%	19,395	1,949	90.0%
Southwest Division	90.5%	70	6	91.4%	2,121	208	90.2%	19,415	1,660	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Customer On Time Performance
Endpoint Arrival Dates through 7/31/25

Day					Month to Date			FY to Date		
Service	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	76%	119,045	39,445	67%	3,269,740	1,065,303	67%	28,655,592	7,783,604	73%
Northeast Corridor	80%	51,930	15,612	70%	1,413,342	434,965	69%	12,713,752	3,311,611	74%
Acela	82%	12,405	3,640	71%	287,180	85,197	70%	2,641,097	639,863	76%
Northeast Regional	78%	39,525	11,972	70%	1,126,162	349,768	69%	10,072,655	2,671,748	73%
Richmond / Newport News / Norfolk	73%	11,492	3,642	68%	367,194	150,428	59%	3,257,346	1,122,965	66%
Springfield Shuttles	89%	616	86	86%	14,496	3,084	79%	180,493	27,728	85%
Roanoke	70%	3,335	190	94%	94,063	28,543	70%	848,240	225,768	73%
On Spine Northeast Regional	83%	24,082	8,054	67%	650,409	167,713	74%	5,786,576	1,295,287	78%
State Supported	80%	47,547	11,195	76%	1,431,845	382,253	73%	12,243,851	2,742,306	78%
Borealis	60%	545	449	18%	20,171	11,389	44%	176,878	74,567	58%
Capitol Corridor	90%	3,828	298	92%	109,960	9,675	91%	919,155	98,379	89%
Carolinian	60%	1,161	553	52%	34,495	16,867	51%	350,305	145,291	59%
Cascades	60%	2,695	595	78%	96,809	26,930	72%	779,689	264,956	66%
Downeaster	82%	1,774	194	89%	58,466	12,890	78%	437,148	105,883	76%
Empire	83%	5,772	2,190	62%	188,712	71,150	62%	1,650,694	373,446	77%
Adirondack	75%	474	268	43%	13,463	7,770	42%	91,458	30,469	67%
Ethan Allen Express	85%	612	288	53%	20,590	13,917	32%	165,801	47,241	72%
Maple Leaf	75%	823	434	47%	28,313	17,217	39%	224,390	72,380	68%
New York - Albany	90%	2,480	1,169	53%	76,199	19,608	74%	763,175	123,042	84%
New York - Niagara Falls	75%	1,383	31	98%	45,854	10,304	78%	399,687	97,203	76%
Berkshire Flyer	60%	0	0	-	4,293	2,334	46%	6,183	3,111	50%
Heartland Flyer	70%	300	296	1%	8,635	6,922	20%	68,154	32,985	52%
Hiawatha	90%	2,053	139	93%	70,016	8,101	88%	520,528	67,466	87%
Illinois	78%	2,543	1,457	43%	82,759	28,627	65%	753,171	185,704	75%
Carl Sandburg / Illinois Zephyr	80%	529	35	93%	15,777	3,567	77%	122,455	16,656	86%
Illini / Saluki	80%	564	23	96%	28,049	5,892	79%	266,346	34,763	87%
Lincoln Service	75%	1,450	1,399	4%	38,933	19,168	51%	364,370	134,285	63%
Keystone	92%	9,920	803	92%	215,197	26,390	88%	2,180,444	301,392	86%
Lincoln / Missouri	60%	866	373	57%	28,279	18,595	34%	222,256	123,476	44%
Michigan	69%	2,795	1,262	55%	80,093	20,688	74%	598,108	167,147	72%
Blue Water	70%	651	364	44%	19,420	5,094	74%	148,019	42,986	71%
Pere Marquette	85%	380	0	100%	10,438	1,415	86%	79,514	10,047	87%
Wolverine	65%	1,764	898	49%	50,235	14,179	72%	370,575	114,114	69%
Missouri	80%	209	177	15%	8,200	4,516	45%	67,032	24,004	64%
Pacific Surfliner	85%	7,320	852	88%	240,569	36,839	85%	1,775,178	286,190	84%
Pennsylvanian	72%	929	458	51%	30,483	11,042	64%	266,498	73,423	72%
Piedmont	73%	944	213	77%	31,379	10,958	65%	340,570	84,380	75%
San Joaquins	73%	2,521	848	66%	84,086	39,639	53%	747,898	214,009	71%
Vermonter	75%	1,372	38	97%	43,536	21,035	52%	390,145	119,608	69%
Long Distance	57%	19,568	12,638	35%	424,553	248,085	42%	3,654,464	1,726,085	53%
Auto Train	57%	1,593	859	46%	26,536	8,752	67%	229,308	139,955	39%
California Zephyr	45%	1,491	1,316	12%	37,597	28,362	25%	300,240	134,862	55%
Capitol Ltd	70%	0	0	-	0	0	-	19,093	4,761	75%
Cardinal	55%	676	456	33%	8,957	4,860	46%	83,007	41,875	50%
City Of New Orleans	75%	779	350	55%	19,978	10,162	49%	194,778	58,371	70%
Coast Starlight	65%	1,310	506	61%	33,911	11,117	67%	319,712	131,863	59%
Crescent	60%	1,583	879	44%	32,893	11,827	64%	264,961	69,351	74%
Empire Builder	55%	1,688	1,013	40%	38,398	23,456	39%	293,389	131,959	55%
Floridian	40%	1,640	1,393	15%	48,021	40,611	15%	411,376	304,391	26%
Lake Shore Ltd	70%	1,837	686	63%	35,610	12,559	65%	307,447	85,187	72%
Palmetto	65%	1,720	1,179	31%	32,171	16,353	49%	300,319	117,469	61%
Silver Meteor	45%	1,806	1,583	12%	31,828	21,755	32%	281,214	149,661	47%
Silver Star	45%	0	0	-	0	0	-	38,502	17,735	54%
Southwest Chief	40%	1,266	1,218	4%	33,481	28,100	16%	246,417	155,026	37%
Sunset Ltd	50%	0	0	-	8,412	4,000	52%	80,051	29,796	63%
Texas Eagle	60%	2,179	1,200	45%	36,760	26,171	29%	284,650	153,823	46%
Seasonal Trains	%	0	0	-	0	0	-	43,525	3,602	92%
Winter Park Express	75%	0	0	-	0	0	-	43,525	3,602	92%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

Train Index Dates Through July 31, 2025

Month to Date					FY to Date		
Service	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	525	224,664	3,241,664	693	1,936,845	31,685,784	611

Month to Date					FY to Date		
Department	Target	ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	126	12,183	945,336	129	103,267	9,273,415	111
INFRASTRUCTURE PLANNED	90	7,137	945,336	75	94,283	9,273,415	102
FLEET RELIABILITY	83	40,153	3,241,664	124	309,033	31,685,784	98
TRAIN OPERATIONS	382	165,191	3,241,664	510	1,430,262	31,685,784	451

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Incident Narratives

OTP Acela/Regional Cancellations - Miscellaneous Amtrak Responsible

29JUL25: In an effort to improve Northeast Regional OTP the following service adjustments have been made:

Acela Trains 2163(28JUL-30SEP) and 2166(28-30SEP) will be cancelled from July 28,2025 thru September 30,2025.

Train 170(31JUL-30SEP) will be suspended Monday thru Friday from July 31,2025 to September 30,2025.

Train 137(31JUL-30SEP) will be suspended Monday thru Thursday and truncated to operate New York to Washington only on Friday.

Train 123(31JUL-30SEP) suspended Sunday

Train 139(31JUL-30SEP) truncated at Philadelphia on Sunday will operate Boston to Philadelphia.

Train 52(31) Savannah, GA - Engine Failure

01AUG25: Train 52(31) with engines 322 and 364 was delayed at Savannah, GA due to lead engine 322 losing HEP for unknown reason causing the engineer to safely coast the train close to the station. Headend power was brought up on the rear unit 364 to ensure passengers remained comfortable. Savannah mechanical met the train on the mainline and performed tests while keeping the headend power on the trail unit to ensure the stress was kept off of the lead unit 322.

Train	Delay	Comment
52(31)	1'37"	

Train 97(31) North of Richmond, VA - Police Related

31JUL25: Train 97(31) with engines 315 and 366 was delayed holding at milepost 51.3 on the CSX RFP subdivision north of Richmond, VA waiting for EMS to remove a passenger with a medical condition.

Train	Delay	Comment
97(31)	50"	

Train 98(31) North of Jesup, GA - Freight Train Interference

31JUL25: Train 98(31) was delayed north of Jesup, GA starting at milepost 523.0 on the CSX Nahunta subdivision due to freight congestion that was followed until milepost 510.0.

Train	Delay	Comment
98(31)	57"	

Train 66(31) Roanoke, VA - Flash Flood

31JUL25: Train 66(31) was delayed from departure at Roanoke, VA to just north of Lynchburg, VA at milepost 172.0 for flash flood warnings and having to operate at restricted speed.

Train	Delay	Comment
66(31)	57"	

Train 244/243(31) North of New York, NY - Engine Failure

31JUL25: Train 244(31) with engine 717, 5 cars, and cab car was delayed at Harmon station milepost 33.2 on the Amtrak Hudson line due to ACSES failure on engine 717. Train 244(31) had to operate restricted to New York, NY and train 243(31) departed late as a result.

Train	Delay	Comment
243(31)	47"	
244(31)	30"	

Train 622(31) West of Downingtown, PA - Signal

31JUL25: Train 622(31) with engine 632 was delayed from Park interlocking milepost 46.3 to Thorn interlocking milepost 35.0 on the Amtrak PH line west of Downingtown, PA due to restrictive signals. Trouble desk was notified to resolve the issue.

Train	Delay	Comment
622(31)	34"	

Train 52(31) North of Jacksonville, FL - Police Related

31JUL25: Train 52(31) with 435 passengers onboard was stopped at 7:28 p.m. at milepost 624.5 on the CSX Nahunta subdivision due to a chlorine leak at the local water maintenance facility in the city of Callahan, FL. The hold was released at 8:45 p.m. and there were no injuries to crew or passengers.

Train	Delay	Comment
52(31)	1' 39"	

Train 69(31) South of Port Kent, NY - Passenger Train Interference

31JUL25: Train 69(31) was delayed 4 miles south of Port Kent, NY at Rockland Siding/MP150.5 on the CFRC Canadian Subdivision due to meeting Train 68(31).

Train	Delay	Comment
69(31)	30"	

Train 685(31) North of Portland, ME - Occupied Vehicle Strike

31JUL25: At approximately 3:30PM-CT, train 685(31) operating with camera equipped locomotive AMTK/333, 05 cars collided with an occupied vehicle 01 miles North of Portland, ME. The incident occurred at DOT crossing # DOT 837470X, Brighton Ave, Portland, Maine, Cumberland County, MP 195.678, Pan Am Railway, Freight Mainline Subdivision of the CSX Railroad. The crossing is protected with audible bells, stop sign, railroad crossing sign, crossing arms with LED flashing lights. There were no reported injuries, to the (39) passengers, or onboard crew of the train. The owner/driver of the vehicle was also not reported injured. The track speed is 30MPH. Weather was reported as 64°F, heavy rain. Locomotive AMTK/333 provided Head End Power for the duration of the incident. Local authorities comprising Portland Police, and Cumberland County fire Dept. attended the scene. The train crew did not request CARE relief at the scene. Once the police investigation was completed & vehicle removed, tracks were re-opened at 4:00PM-CT.

Service Recovery:
Amtrak Police Notified.
National Response Centre Number - 1438521
Maine Dept. Emergency Services Number - 2025-

National Response Center Number: 1438521

Train	Delay	Comment
685(31)	40"	

Train 20(31) South of Meridian, MS - Freight Train Interference

31JUL25: Train 20(31) was delayed 1 mile south of Meridian, MS at MP.9 on the Norfolk Southern NO&NE Subdivision due to meeting freight unit 29K.

Train	Delay	Comment
20(31)	56"	

Train 40(29) West of Connellsville, PA - Freight Train Interference

31JUL25: Train 40(29) was delayed 15 miles west of Connellsville, PA, due to following IO115-30 between MP283.5 on the CSX Pittsburgh_BF to MP11.7 on the CSX Pittsburgh_PLY Subdivision.

Train	Delay	Comment
40(29)	43"	

CSX Heat Orders - Weather

31JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Kanawha, New River, Peninsula, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(31)	24"	
186(31)	11"	
98(31)	18"	
97(30)	13"	
41(30)	20"	
40(30)	20"	

PW Line North of Wilmington, DE - Weather

31JUL25: Due severe storms/weather conditions, and high water conditions at milepost 24.5 on the Amtrak PW Line between Holly/MP20.3 and Landlith/MP25.4 several trains were delayed holding at Philadelphia station and Wilmington station until route was clear.

Train	Delay	Comment
173(31)	57"	
129(31)	47"	
2167(31)	33"	
136(31)	07"	
2122(31)	08"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

- 370(18) - 59 oversold
- 371(19) - 10 oversold
- 305(18) - 13 oversold
- 300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

- 300(20) - 59 oversold
- 371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

- 300(21) - 62 oversold
- 371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

- 370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

- 371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL.

Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on 370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.

- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.

- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).

- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.

- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).

- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.

- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.

- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.

- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
301(16Jul-04Aug)	Cancelled, with alt	CHI-STL
306(16Jul-04Aug)	Cancelled, with alt	STL-CHI
381(05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382(05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Train 59(30) South of Hazlehurst, MS - Passenger Train Interference

01AUG25: Train 59(30) was delayed 11 miles south of Hazelhurst, MS, on CN McComb subdivision, meeting train 58(31) at control point Central Jct.

Train	Delay	Comment
59(30)	36"	

Train 3(30) East of Albuquerque, NM - Commuter Train Interference

01AUG25: Train 3(30) was delayed 8 miles east of Albuquerque, NM, on NMRX Albuquerque subdivision, due to meeting NMRX train at Alameda siding.

Train	Delay	Comment
3(30)	31"	

Train 4(30) East of Lamy, NM - Passenger Train Interference

01AUG25: Train 4(30) was delayed 15 miles east of Lamy, NM, on BNSF Glorieta subdivision due to meeting train 3(30) at Fox siding.

Train	Delay	Comment
4(30)	41"	

Train 383(31) West of Macomb, IL - Freight Train Interference

01AUG25: Train 383(31) was delayed 8 miles west of Macomb, IL, on BNSF Brookfield subdivision, due to meeting BNSF5484 at Control Point Colchester. BNSF5484 was blocking the route due to inspecting their equipment after setting off a hot box detector. Once the freight finished inspecting their equipment, they were able to proceed, clearing a route for train 383(31).

Train	Delay	Comment
383(31)	53"	

Train 305(31) Chicago, IL - Servicing

01AUG25: Train 305(31) was delayed 53 minutes departing Chicago, Illinois account late makeup in CUS. Train 305(31) turned with equipment off inbound Train 302(31), which arrived at 1206pm, 26 minutes late. Due to ongoing congestion in the terminal, Train 302(31) shoved from CUS at 320pm. The train was set to the yard at 400pm. The rear of the two trainsets was cut off in the yard. Train 305(31) was set in CUS at 505pm. After mechanical worked and released the train, Train 305(31) departed CUS at 613pm, 53 minutes late.

Train	Delay	Comment
305(31)	53"	

Train 341(31) Chicago, IL - Engine Failure

31JUL25: Train 41(31) was delayed 4 hours and 57 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(29) and backfilling the locomotive as one of the original locomotives was used to replace a bad order on California Zephyr Train 5(31). As background, inbound 40(29) arrived in Chicago at 106pm; 4 hours and 21 minutes late due to 1 hour and 39 minutes of heat orders, 42 minutes for passenger's and/or baggage, 2 hours and 12 minutes for freight interference, 55 minutes for speed restrictions, and 29 minutes for passenger train interference. Equipment set to the yard for servicing and inspection at 257pm with no scheduled program moves. At 330pm, engine 14 on California Zephyr Train 5(31) was bad ordered for loading issues. Due to a high shop count at the locomotive shop, engine 126 off Train 41(31) was selected as the replacement for Train 5(31) to be backfilled with engine 203 off inbound 4(29). Train 4(29) arrived in Chicago at 505pm; 2 hours and 23 minutes late and set to the yard at 647pm. Engine 203 was released at 748pm and tied on at 846pm. Train 41(31) was released by mechanical at 933pm and set in the station at 943pm. Because of the additional delay on Train 41(31) caused by the bad order locomotive on Train 5(31), the road crew only had approximately 1 hour and 27 minutes left to work. Train 41(31) was held for a re-crew before departing Chicago. Train 41(31) departed Chicago at 1137pm; 4 hours and 57 minutes late.

Train	Delay	Comment
341(31)	4'57"	

Train 544(31) North of Oakland Coliseum, CA - Trackside Fire

31JUL25: Train 544(31) was delayed departing Oakland Coliseum Station. This was to allow for fire crews to work a car fire near the tracks at MP 11.17, Niles Subdivision of the Union Pacific. All train traffic in was halted to allow fire crews to place their hoses and other equipment across the tracks to get closer to the fire. Once the fire had been extinguished, tracks were opened and train 544(31) was able to proceed to Oakland Jack London. Amtrak Police Notified.

Train	Delay	Comment
544(31)	53"	

Train 5(31) West of Chicago, IL - Injured or Sick Passenger or Employee

31JUL25: Train 5(31) came to a stop at Metras, Cicero station, 7 miles west of Chicago, IL, on BNSF Chicago subdivision, due to a passenger becoming unresponsive on the train. 5(31) came to a stop to wait for emergency services to arrive and asses the passenger. Once EMS arrived they determined that the passenger was deceased. Once the passenger was taken off the train by EMS, train 5(31) held for Amtrak Police to arrive and investigate. Once the police concluded their investigation the released the train and train 5(31) was able to proceed.

Train	Delay	Comment
5(31)	1'10"	

Train 22(31) West of Longview, TX - Freight Train Interference

31JUL25: Train 22(31) was delayed 6 miles west of Longview, TX, on Up Mineola subdivision, due to UP work train MNLEW finishing up some work. Once the work train cleared, train 22(31) was able to proceed.

Train	Delay	Comment
22(31)	1'02"	

Train 5(31) Chicago, IL - Engine Failure

31JUL25: Train 5(31) was delayed 4 hours 13 minutes departing Chicago, Illinois account bad order engine in CUS. Train 5(31) reported at 139pm that the engine had loading issues. Mechanical responded and repaired, clearing the train again at 231pm. When attempting to depart again at 238pm, they experienced the same issues. At 330pm, the leader E/14 was bad ordered. Replacement E/126 was released at 421pm. Bad order E/14 was held off at 435pm. Train 5(31) was made up complete at 548pm. Mechanical worked and released at 606pm. Train 5(31) departed CUS at 613pm, 4 hours 13 minutes late.

Train	Delay	Comment
5 (31)	4 '13"	

Train 6(29) East of Osceola, IA - Freight Train Interference

31JUL25: Train 6(29) was delayed at MP 356.9, 3 miles east of Osceola,IA, on the BNSF Ottumwa Subdivision due to meet with BNSF 6083. Crew held on main track two until west bound freight cleared then crossed over to main one to continue east.

Train	Delay	Comment
6 (29)	33"	

Train 5(29) West of Truckee CA –Passenger Train Interference

31JUL25: Train 5(29) was delayed at 26 miles West of Truckee CA at Shed 10, MP 178.2 on the UPRR Roseville Subdivision. This was to allow for Amtrak traun 6(31) to operate eastbound over the crossover switches ahead. Once cleared, train 5(29) was able to continue to Colfax.

Train	Delay	Comment
5 (29)	46"	

Train 2/422(30) East of Tucson, AZ - Freight Train Interference

31JUL25: Train 2/422(30) was delayed starting at MP 985, 1 mile east of Tucson, AZ, to Chamiso/MP 1029 on the BNSF Gila Subdivision due to meet with UP2567 then following freight on main track two. Once able to get around freight, crew was able to proceed east at track speed.

Train	Delay	Comment
2/422 (30)	1 '16"	

Train 3(30) East of Raton, NM - Loading Issues

31JUL25: Train 3(30) was delayed at MP 649.2, 10 miles east of Raton, NM, on the BNSF Raton Subdivision due to loading issues on E/188. Crew contacted CNOC mechanical to troubleshoot. Once problem was identified and problem was resolves, Train 3(30) was able to proceed west.

Train	Delay	Comment
3 (30)	39"	

Chicago, IL - Freight Unit PTC Issues

31JUL25: Multiple trains were delayed in and out of the yard in Chicago, IL due to CN234 having PTC issues on bridge at 21st street needing yard crew to rescue with yard engine. Train traffic was halted while yard crew readied yard engine and responded. Once crew got to location and coupled to freight, rail traffic was able to resume.

Train	Delay	Comment
319(31)	53"	
51(30)	39"	
49(30)	1'06"	
351(31)	26"	

Train 761(31) North of Goleta – Space Rocket Launch

31JUL25: The US Space Force scheduled the launch of Space X, Falcon 9 Rocket, from Vandenberg Space Force Base in Southern California, between 9:29AM-PT and 1:29PM-PT. The safe exclusion zone for this launch encompassed the railroad tracks north of Goleta Station. This required that train 761(31) be held 21 miles north of Goleta - at Gaviota, MP 336.3 Santa Barbara Subdivision - until the rocket was safely underway. Once the rocket had been launched, the train was further delayed while UPRR maintenance-of-way personnel searched the tracks for potential fallen debris.

Train	Delay	Comment
761(31)	1'14"	

Train 3(29) East of Victorville, CA - Freight Train Interference

31JUL25: Train 3(29) was delayed starting at MP 11.1, 25 miles east of Victorville, CA, on the BNSF Cajon Subdivision due to meet and follow of BNSF freight. Due to vandalism, there was single track conditions near Victorville, crew held for meet with BNSF 3899 and BNSF 6555. Once those freights cleared, they followed those freights until MP 47, 10 miles west of Victorville, where they were able to get around.

Train	Delay	Comment
3(29)	56"	

Train 51(30) North of Crawfordsville, IN - Freight Train Interference

31JUL25: Train 51(30) was delayed at Linden/MP 136.1, 10 miles north of Crawfordsville, IN, on the CSX Monon Subdivision due to following CSX M642. Once freight cleared route, Train 50(30) was able to proceed at track speed.

Train	Delay	Comment
51(30)	41"	

Train 21(30) Malvern, AR - Suspicious Bag

31JUL25: Train 21(30) was delayed departing Malvern, AR on the UPRR Little Rock Subdivision due to a suspicious bag found in the baggage car. Crew found a bag in the baggage car that was chained up to the bike rack with no identification or baggage check tags on it. Train 21(30) held in Malvern while police were contacted and the crew looked for who the bag may belong to. Amtrak police were notified and started sourcing a canine crew to inspect bag. The owner of the bag was identified and the crew verified the bag. Crew had owner detach bag and properly tag bag. Once everything was verified and it was safe to proceed, Train 21(30) departed Malvern.

Train	Delay	Comment
21(30)	36"	

Maintenance of Way Highlights

NSRR Pittsburgh Line Trackwork

18JUL25: Norfolk Southern has tie installation trackwork scheduled on the Pittsburgh Line between MP144 and MP224. The dates for the trackwork will be July 28th through July 31st, August 4th through August 7th, and August 11th through August 14th. To accommodate this infrastructure work, Amtrak's Pennsylvanian Service will be adjusted as follows:

- Train 42 (28Jul-31Jul, 4Aug-7Aug, 11Aug-14Aug) will operate 45-minutes LATER between CP Cannon (XNN) and New York
- Train 43 (28Jul-31Jul, 4Aug-7Aug, 11Aug-14Aug) will not have a schedule adjustment and will be subject to arrive 45 to 60-minutes late at Pittsburgh.

WBS#: B.TR.100150.5896

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

UPRR Santa Barbara Subdivision North of Santa Barbara, CA - M of W Work

31JUL25: As a result of scheduled bridge work Thursday July 31, 2025 through Saturday August 16, 2025 at MP 305/UPRR Santa Barbara Subdivision, 62.4 miles north of Santa Barbara, the following service changes will occur on the Coast Starlight and Pacific Surfliner services:

COAST STARLIGHT

- Train 11 (31Jul-15Aug), which normally operates between SEA and LAX, will terminate at EMY.
- Train 14 (1Aug-16Aug), which normally operates between LAX and SEA, will originate at EMY.
- Alternate transportation will be provided between SAC and LAX via San Joaquin service for Train 11 (31Jul-15Aug).
- Alternate transportation will be provided between LAX and MTZ via San Joaquin service for Train 14 (1Aug-16Aug).

PACIFIC SURFLINER

Southbound:

- Train 774 (1Aug-16Aug), which normally operates between SLO and SAN, will Originate at GTA.
- Train 794 (1Aug-16Aug), which normally operates between SLO and SAN, will Originate at GTA.

Northbound:

- Train 761 (1Aug-16Aug), which normally operates between SAN and SLO, will Terminate at GTA.
- Train 779 (31Jul-16Aug), which normally operates between SAN and SLO, will Terminate at GTA.
- Alternate transportation will be handled via the Rt. 17 Buses. Additional buses will be provided for connections between SLO and SBA for Trains 761, 794, 774, and 779.

Work Element WBS # B.TR.100150.5840

WBS#: B.TR.100150.5840

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

A-Report Detail



Information Management
Initial Terminal Performance By Division

Scheduled Departure Date:	07/31/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/31/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	28	90.5%	8,926	1,070	88.0%	87,634	8,739	90.0%
Central Division	91.5%	63	8	87.3%	2,025	247	87.8%	20,054	1,987	90.1%
Northeast Division	95.0%	95	8	91.6%	2,815	380	86.5%	28,770	3,143	89.1%
Southeast Division	94.5%	67	6	91.0%	1,965	235	88.0%	19,395	1,949	90.0%
Southwest Division	90.5%	70	6	91.4%	2,121	208	90.2%	19,415	1,660	91.4%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/31/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/31/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	28	90.5%	8,926	1,070	88.0%	87,634	8,739	90.0%
Central Division	91.5%	63	8	87.3%	2,025	247	87.8%	20,054	1,987	90.1%
ARB	-	-	-	-	-	-	-	1	1	0.0%
BNL	-	-	-	-	-	-	-	3	3	0.0%
BTL	-	-	-	-	-	-	-	4	3	25.0%
CDL	97.0%	1	0	100.0%	64	3	95.3%	607	17	97.2%
CEN	-	-	-	-	-	-	-	1	1	0.0%
CHI	90.0%	26	8	69.2%	818	148	81.9%	8,094	1,033	87.2%
CHM	-	-	-	-	-	-	-	3	3	0.0%
DEN	-	-	-	-	-	-	-	69	5	92.8%
EUG	91.0%	2	0	100.0%	62	4	93.5%	586	23	96.1%
EVR	-	-	-	-	-	-	-	2	2	0.0%
GBB	-	-	-	-	2	2	0.0%	11	4	63.6%
GRR	98.0%	1	0	100.0%	30	0	100.0%	303	4	98.7%
IND	-	-	-	-	-	-	-	4	2	50.0%
KCY	92.0%	2	0	100.0%	61	3	95.1%	590	40	93.2%
KFS	-	-	-	-	1	1	0.0%	2	2	0.0%
MEM	-	-	-	-	-	-	-	2	0	100.0%
MHL	-	-	-	-	-	-	-	33	19	42.4%
MKE	97.0%	6	0	100.0%	181	10	94.5%	1,744	98	94.4%
MSP	95.0%	1	0	100.0%	31	2	93.5%	292	14	95.2%
PDX	78.0%	5	0	100.0%	151	13	91.4%	1,463	165	88.7%
PNT	94.0%	3	0	100.0%	91	3	96.7%	838	59	93.0%
PTH	96.0%	1	0	100.0%	31	0	100.0%	302	11	96.4%
QCY	94.0%	2	0	100.0%	60	0	100.0%	590	18	96.9%
SBY	-	-	-	-	-	-	-	2	0	100.0%
SEA	90.0%	8	0	100.0%	249	43	82.7%	2,376	343	85.6%
SPK	92.0%	1	-	100.0%	29	1	96.6%	300	14	95.3%
STL	96.0%	2	0	100.0%	101	13	87.1%	1,178	66	94.4%
TOL	-	-	-	-	1	1	0.0%	2	2	0.0%
VAC	95.0%	2	0	100.0%	62	0	100.0%	583	12	97.9%
WIP	-	-	-	-	-	-	-	69	23	66.7%
Northeast Division	95.0%	95	8	91.6%	2,815	380	86.5%	28,770	3,143	89.1%
ALB	96.0%	6	0	100.0%	186	5	97.3%	2,035	127	93.8%
BON	94.5%	5	0	100.0%	153	9	94.1%	1,417	92	93.5%
BOS	97.0%	17	1	94.1%	542	55	89.9%	5,659	521	90.8%
BRK	97.0%	5	0	100.0%	99	5	94.9%	1,360	71	94.8%
BRP	-	-	-	-	1	1	0.0%	1	1	0.0%
BTN	94.5%	1	0	100.0%	31	6	80.6%	302	23	92.4%
DHM	-	-	-	-	-	-	-	2	2	0.0%
DOV	-	-	-	-	-	-	-	9	0	100.0%
EXR	-	-	-	-	-	-	-	9	8	11.1%
GFD	90.5%	2	0	100.0%	55	3	94.5%	582	55	90.5%
HFD	-	2	0	100.0%	44	5	88.6%	190	18	90.5%
HHL	-	-	-	-	-	-	-	2	2	0.0%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/31/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/31/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	28	90.5%	8,926	1,070	88.0%	87,634	8,739	90.0%
Northeast Division	95.0%	95	8	91.6%	2,815	380	86.5%	28,770	3,143	89.1%
MTR	97.0%	1	0	100.0%	31	4	87.1%	302	30	90.1%
NFL	97.0%	2	0	100.0%	62	1	98.4%	608	24	96.1%
NHT	-	-	-	-	3	0	100.0%	5	1	80.0%
NHV	90.5%	6	1	83.3%	146	20	86.3%	1,553	154	90.1%
NYP	94.5%	41	5	87.8%	1,194	233	80.5%	12,187	1,871	84.6%
POR	-	-	-	-	51	17	66.7%	51	17	66.7%
RUD	94.5%	-	-	-	-	-	-	1	1	0.0%
SAB	98.0%	1	0	100.0%	29	4	86.2%	300	9	97.0%
SPG	95.5%	5	1	80.0%	154	10	93.5%	1,850	86	95.4%
TWO	96.0%	1	0	100.0%	31	0	100.0%	301	11	96.3%
WEM	-	-	-	-	3	2	33.3%	44	19	56.8%
Southeast Division	94.5%	67	6	91.0%	1,965	235	88.0%	19,395	1,949	90.0%
ATL	-	-	-	-	-	-	-	33	5	84.8%
CLT	92.0%	5	1	80.0%	151	18	88.1%	1,505	103	93.2%
DNC	-	-	-	-	1	1	0.0%	1	1	0.0%
GRO	-	-	-	-	10	10	0.0%	10	10	0.0%
HAR	98.0%	13	0	100.0%	348	18	94.8%	3,294	106	96.8%
JAX	-	-	-	-	-	-	-	17	5	70.6%
LNC	-	-	-	-	-	-	-	92	12	87.0%
LOR	84.0%	1	0	100.0%	31	6	80.6%	298	94	68.5%
MIA	90.0%	2	0	100.0%	59	10	83.1%	584	57	90.2%
NFK	94.5%	3	0	100.0%	88	14	84.1%	838	68	91.9%
NOL	92.0%	2	0	100.0%	70	3	95.7%	677	46	93.2%
NPN	96.0%	2	0	100.0%	62	5	91.9%	581	22	96.2%
PGH	92.0%	1	0	100.0%	31	4	87.1%	303	18	94.1%
PHL	97.0%	5	1	80.0%	134	31	76.9%	1,300	188	85.5%
RGH	97.0%	4	1	75.0%	116	5	95.7%	1,219	39	96.8%
RNK	94.0%	2	1	50.0%	57	6	89.5%	574	68	88.2%
RVM	90.0%	1	0	100.0%	31	2	93.5%	295	35	88.1%
RVR	95.0%	-	-	-	-	-	-	1	1	0.0%
SAV	97.0%	1	0	100.0%	29	1	96.6%	285	11	96.1%
SFA	83.0%	1	0	100.0%	31	2	93.5%	298	80	73.2%
WAS	94.5%	24	2	91.7%	716	99	86.2%	7,190	980	86.4%
Southwest Division	90.5%	70	6	91.4%	2,121	208	90.2%	19,415	1,660	91.4%
ABQ	-	-	-	-	-	-	-	3	2	33.3%
ARN	96.0%	1	0	100.0%	31	0	100.0%	304	7	97.7%
BFD	90.0%	6	1	83.3%	183	20	89.1%	1,806	156	91.4%
DAL	-	-	-	-	-	-	-	2	1	50.0%
EMY	65.0%	1	0	100.0%	31	20	35.5%	311	96	69.1%
FMT	-	-	-	-	-	-	-	1	0	100.0%
FNO	-	-	-	-	-	-	-	7	2	71.4%
FTW	90.0%	1	0	100.0%	30	2	93.3%	336	42	87.5%
FUL	-	-	-	-	-	-	-	12	5	58.3%

Information Management
Initial Terminal Performance By Terminal

Scheduled Departure Date:	07/31/2025
Amtrak or Commuter:	Amtrak

Location	Target	ITP 07/31/2025			ITP July 2025 To Date			ITP Fiscal Year 2025 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	93.0%	295	28	90.5%	8,926	1,070	88.0%	87,634	8,739	90.0%
Southwest Division	90.5%	70	6	91.4%	2,121	208	90.2%	19,415	1,660	91.4%
GLE	-	-	-	-	-	-	-	4	4	0.0%
GLP	-	-	-	-	-	-	-	1	1	0.0%
GTA	88.0%	3	0	100.0%	93	3	96.8%	889	63	92.9%
IRV	-	-	-	-	-	-	-	87	6	93.1%
LAX	85.0%	9	2	77.8%	292	37	87.3%	2,351	328	86.0%
MPK	-	-	-	-	-	-	-	6	4	33.3%
OKC	96.0%	1	0	100.0%	28	0	100.0%	299	6	98.0%
OKJ	91.0%	12	2	83.3%	344	57	83.4%	3,197	307	90.4%
OSD	-	-	-	-	-	-	-	188	50	73.4%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	95.0%	14	0	100.0%	407	28	93.1%	3,638	153	95.8%
SAN	90.0%	12	1	91.7%	366	25	93.2%	2,788	243	91.3%
SAS	85.0%	1	0	100.0%	31	7	77.4%	300	42	86.0%
SJC	95.0%	7	0	100.0%	216	8	96.3%	1,956	74	96.2%
SKN	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	2	0	100.0%	62	0	100.0%	595	27	95.5%
SNC	-	-	-	-	-	-	-	279	28	90.0%
SOL	-	-	-	-	6	0	100.0%	53	11	79.2%

Initial terminal tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	123	31	10	67.7%	298	60	79.9%	31	26	16.1%	294	167	43.2%
4	143	31	6	80.6%	299	71	76.3%	31	27	12.9%	298	158	47.0%
5	69	31	16	48.4%	301	55	81.7%	30	20	33.3%	298	103	65.4%
6	227	31	20	35.5%	301	89	70.4%	31	26	16.1%	300	108	64.0%
7		31	12	61.3%	295	48	83.7%	31	9	71.0%	290	76	73.8%
8	45	31	20	35.5%	296	112	62.2%	31	24	22.6%	294	145	50.7%
11		31	5	83.9%	303	49	83.8%	31	4	87.1%	296	65	78.0%
14		31	11	64.5%	304	93	69.4%	31	10	67.7%	302	130	57.0%
19	71	31	1	96.8%	304	34	88.8%	31	11	64.5%	303	60	80.2%
20		31	1	96.8%	304	14	95.4%	31	6	80.6%	303	48	84.2%
21		31	6	80.6%	303	40	86.8%	31	9	71.0%	297	92	69.0%
22		31	7	77.4%	300	44	85.3%	31	25	19.4%	299	133	55.5%
27		29	4	86.2%	291	21	92.8%	28	9	67.9%	281	95	66.2%
28		28	6	78.6%	284	71	75.0%	28	6	78.6%	283	78	72.4%
40	261	31	6	80.6%	261	39	85.1%	30	24	20.0%	256	163	36.3%
41	38	29	19	34.5%	258	114	55.8%	29	26	10.3%	254	203	20.1%
42	33	31	4	87.1%	304	19	93.8%	31	10	67.7%	304	84	72.4%
43	22	31	3	90.3%	304	26	91.4%	31	13	58.1%	304	73	76.0%
48		31	7	77.4%	303	55	81.8%	31	6	80.6%	303	47	84.5%
49	45	31	14	54.8%	304	64	78.9%	31	8	74.2%	304	55	81.9%
51	62	13	3	76.9%	129	25	80.6%	13	4	69.2%	123	42	65.9%
52		31	2	93.5%	298	80	73.2%	31	7	77.4%	298	154	48.3%
53		31	6	80.6%	298	94	68.5%	31	7	77.4%	298	147	50.7%
55		22	3	86.4%	211	9	95.7%	22	14	36.4%	211	53	74.9%
56		22	4	81.8%	211	37	82.5%	22	17	22.7%	210	60	71.4%
58		31	2	93.5%	296	23	92.2%	31	9	71.0%	293	62	78.8%
59	213	31	13	58.1%	295	65	78.0%	30	12	60.0%	291	39	86.6%
63	25	31	19	38.7%	304	65	78.6%	31	27	12.9%	304	159	47.7%
64		31	0	100.0%	304	11	96.4%	31	8	74.2%	304	76	75.0%
66		31	6	80.6%	302	59	80.5%	31	3	90.3%	300	39	87.0%
67		22	2	90.9%	210	19	91.0%	22	5	77.3%	208	44	78.8%
68	34	31	4	87.1%	304	30	90.1%	31	23	25.8%	304	127	58.2%
69		31	2	93.5%	304	22	92.8%	30	8	73.3%	299	35	88.3%
71	16	30	2	93.3%	303	7	97.7%	30	11	63.3%	301	69	77.1%
72		31	5	83.9%	304	24	92.1%	31	10	67.7%	302	77	74.5%
73	37	31	5	83.9%	304	17	94.4%	31	15	51.6%	302	150	50.3%
74	11	31	5	83.9%	300	25	91.7%	30	14	53.3%	297	104	65.0%
75	15	31	3	90.3%	302	8	97.4%	30	17	43.3%	299	124	58.5%
76		31	7	77.4%	300	23	92.3%	30	20	33.3%	298	133	55.4%
77	14	31	3	90.3%	301	13	95.7%	31	16	48.4%	299	136	54.5%
78		31	1	96.8%	302	11	96.4%	30	10	66.7%	301	74	75.4%
79		31	7	77.4%	304	42	86.2%	29	9	69.0%	301	107	64.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
80	43	31	3	90.3%	304	24	92.1%	31	18	41.9%	304	91	70.1%
84		22	0	100.0%	210	8	96.2%	22	8	63.6%	209	77	63.2%
85	37	22	1	95.5%	208	17	91.8%	22	17	22.7%	207	143	30.9%
86	26	22	1	95.5%	208	23	88.9%	22	20	9.1%	208	145	30.3%
89		31	2	93.5%	303	36	88.1%	31	16	48.4%	301	114	62.1%
90		31	1	96.8%	303	12	96.0%	30	13	56.7%	298	77	74.2%
93	30	22	0	100.0%	211	14	93.4%	22	14	36.4%	210	100	52.4%
94		22	6	72.7%	211	20	90.5%	22	11	50.0%	210	77	63.3%
95		22	0	100.0%	211	5	97.6%	22	10	54.5%	211	91	56.9%
97	68	30	23	23.3%	299	144	51.8%	30	16	46.7%	298	100	66.4%
98	75	30	5	83.3%	299	20	93.3%	30	19	36.7%	299	155	48.2%
110		22	8	63.6%	209	41	80.4%	22	4	81.8%	207	43	79.2%
111		22	6	72.7%	208	53	74.5%	22	3	86.4%	206	33	84.0%
112		19	3	84.2%	200	38	81.0%	19	3	84.2%	198	24	87.9%
114		22	5	77.3%	207	56	72.9%	22	3	86.4%	203	30	85.2%
119		22	4	81.8%	205	42	79.5%	22	4	81.8%	202	31	84.7%
125		22	1	95.5%	211	10	95.3%	22	13	40.9%	211	120	43.1%
129	42	22	6	72.7%	209	44	78.9%	22	9	59.1%	208	47	77.4%
130		22	3	86.4%	205	22	89.3%	22	1	95.5%	202	22	89.1%
131		19	2	89.5%	199	34	82.9%	19	3	84.2%	197	29	85.3%
133		19	7	63.2%	206	75	63.6%	19	15	21.1%	206	108	47.6%
134		22	0	100.0%	210	15	92.9%	22	11	50.0%	210	102	51.4%
136		22	1	95.5%	211	40	81.0%	22	5	77.3%	209	43	79.4%
138		22	4	81.8%	210	25	88.1%	22	10	54.5%	210	53	74.8%
141		22	0	100.0%	211	3	98.6%	22	10	54.5%	211	100	52.6%
148		22	3	86.4%	211	20	90.5%	22	6	72.7%	211	45	78.7%
151		31	7	77.4%	301	39	87.0%	31	10	67.7%	300	103	65.7%
171	21	22	3	86.4%	211	10	95.3%	22	15	31.8%	211	109	48.3%
172		22	3	86.4%	210	16	92.4%	22	10	54.5%	208	69	66.8%
173	54	19	0	100.0%	208	26	87.5%	19	7	63.2%	208	70	66.3%
174		22	2	90.9%	211	6	97.2%	22	7	68.2%	210	49	76.7%
175	19	22	7	68.2%	210	37	82.4%	22	14	36.4%	209	80	61.7%
176		22	4	81.8%	211	20	90.5%	22	3	86.4%	210	27	87.1%
177	No OS	22	5	77.3%	211	31	85.3%	22	10	54.5%	210	47	77.6%
179	89	22	4	81.8%	209	16	92.3%	22	13	40.9%	209	74	64.6%
181		22	7	68.2%	206	41	80.1%	22	2	90.9%	202	28	86.1%
182		22	3	86.4%	206	49	76.2%	22	11	50.0%	205	56	72.7%
183		22	4	81.8%	211	28	86.7%	22	5	77.3%	211	29	86.3%
184		22	8	63.6%	211	32	84.8%	22	3	86.4%	210	26	87.6%
185		22	2	90.9%	211	34	83.9%	22	3	86.4%	211	27	87.2%
186		22	3	86.4%	208	14	93.3%	22	9	59.1%	206	59	71.4%
190		22	7	68.2%	211	42	80.1%	22	7	68.2%	211	52	75.4%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
192		19	3	84.2%	104	17	83.7%	19	4	78.9%	102	13	87.3%
193		22	7	68.2%	209	37	82.3%	22	9	59.1%	208	75	63.9%
196		22	1	95.5%	211	70	66.8%	22	3	86.4%	208	59	71.6%
197		22	11	50.0%	210	55	73.8%	22	6	72.7%	209	58	72.2%
232		31	1	96.8%	292	10	96.6%	31	1	96.8%	292	22	92.5%
233	24	27	6	77.8%	298	86	71.1%	27	12	55.6%	297	103	65.3%
234		31	1	96.8%	292	7	97.6%	31	2	93.5%	292	22	92.5%
236	26	31	0	100.0%	292	5	98.3%	31	4	87.1%	291	48	83.5%
237		27	0	100.0%	286	28	90.2%	27	3	88.9%	284	33	88.4%
239	23	31	6	80.6%	291	31	89.3%	31	10	67.7%	291	26	91.1%
240		31	0	100.0%	296	24	91.9%	31	5	83.9%	295	27	90.8%
241		31	7	77.4%	304	40	86.8%	30	13	56.7%	303	49	83.8%
243	32	22	11	50.0%	211	43	79.6%	22	11	50.0%	210	33	84.3%
244	25	27	1	96.3%	298	8	97.3%	27	14	48.1%	298	53	82.2%
280		31	0	100.0%	303	11	96.4%	31	2	93.5%	303	53	82.5%
281		31	2	93.5%	304	60	80.3%	30	7	76.7%	302	62	79.5%
283		31	10	67.7%	304	67	78.0%	31	10	67.7%	303	63	79.2%
284		31	1	96.8%	304	13	95.7%	31	2	93.5%	303	60	80.2%
290	22	31	6	80.6%	304	25	91.8%	30	24	20.0%	302	77	74.5%
291		31	11	64.5%	304	49	83.9%	31	22	29.0%	303	68	77.6%
302	26	30	6	80.0%	298	24	91.9%	30	14	53.3%	295	104	64.7%
305	37	30	6	80.0%	297	25	91.6%	30	21	30.0%	296	117	60.5%
307	41	30	5	83.3%	297	41	86.2%	28	13	53.6%	293	108	63.1%
311	18	30	4	86.7%	294	19	93.5%	30	18	40.0%	290	114	60.7%
316	18	30	2	93.3%	292	20	93.2%	30	20	33.3%	290	109	62.4%
318		31	1	96.8%	300	20	93.3%	31	20	35.5%	296	167	43.6%
319	100	31	1	96.8%	302	19	93.7%	31	26	16.1%	297	187	37.0%
329		22	4	81.8%	212	20	90.6%	22	1	95.5%	212	17	92.0%
330		26	2	92.3%	246	6	97.6%	26	2	92.3%	245	16	93.5%
331		31	2	93.5%	295	21	92.9%	31	3	90.3%	291	28	90.4%
332	No OS	31	1	96.8%	300	17	94.3%	31	4	87.1%	299	45	84.9%
334		31	0	100.0%	300	9	97.0%	31	6	80.6%	295	74	74.9%
335		31	4	87.1%	303	33	89.1%	31	7	77.4%	294	63	78.6%
336		31	1	96.8%	289	7	97.6%	31	8	74.2%	288	83	71.2%
337		31	2	93.5%	292	17	94.2%	31	6	80.6%	291	63	78.4%
338		31	5	83.9%	302	40	86.8%	31	11	64.5%	292	126	56.8%
339		31	4	87.1%	302	46	84.8%	31	4	87.1%	300	52	82.7%
341	117	30	12	60.0%	287	57	80.1%	30	14	53.3%	281	61	78.3%
342		31	1	96.8%	303	19	93.7%	31	2	93.5%	302	45	85.1%
350	17	31	2	93.5%	263	27	89.7%	31	22	29.0%	260	135	48.1%
351	34	31	1	96.8%	292	25	91.4%	31	8	74.2%	291	81	72.2%
352		31	4	87.1%	297	28	90.6%	31	13	58.1%	292	84	71.2%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
353	16	30	0	100.0%	255	6	97.6%	30	3	90.0%	250	38	84.8%
354		30	3	90.0%	296	29	90.2%	30	8	73.3%	293	106	63.8%
355		30	2	93.3%	296	32	89.2%	30	7	76.7%	292	75	74.3%
364		31	2	93.5%	302	56	81.5%	31	6	80.6%	301	80	73.4%
365	27	31	0	100.0%	302	11	96.4%	31	10	67.7%	301	88	70.8%
370		30	3	90.0%	303	13	95.7%	29	5	82.8%	302	38	87.4%
371		30	0	100.0%	303	4	98.7%	30	3	90.0%	303	28	90.8%
380		31	1	96.8%	301	11	96.3%	31	3	90.3%	301	29	90.4%
381		31	2	93.5%	301	8	97.3%	31	9	71.0%	300	32	89.3%
382		31	1	96.8%	300	11	96.3%	31	8	74.2%	300	41	86.3%
383	58	31	1	96.8%	302	30	90.1%	31	16	48.4%	301	75	75.1%
390		31	3	90.3%	299	13	95.7%	31	8	74.2%	297	44	85.2%
393		31	1	96.8%	301	13	95.7%	31	9	71.0%	298	42	85.9%
417	39	22	3	86.4%	207	33	84.1%	21	4	81.0%	204	32	84.3%
425		19	1	94.7%	192	6	96.9%	19	0	100.0%	192	7	96.4%
470		23	2	91.3%	213	15	93.0%	21	2	90.5%	208	28	86.5%
471		22	2	90.9%	211	14	93.4%	21	0	100.0%	209	11	94.7%
473		22	3	86.4%	211	8	96.2%	21	1	95.2%	210	3	98.6%
474		22	2	90.9%	209	30	85.6%	21	10	52.4%	205	64	68.8%
475		19	2	89.5%	207	8	96.1%	19	4	78.9%	204	20	90.2%
478		20	2	90.0%	209	22	89.5%	19	1	94.7%	207	20	90.3%
479	21	22	1	95.5%	211	30	85.8%	22	3	86.4%	210	25	88.1%
486		22	0	100.0%	213	16	92.5%	22	10	54.5%	211	74	64.9%
490	No OS	1	1	0.0%	118	20	83.1%	1	1	0.0%	116	14	87.9%
494		22	6	72.7%	216	33	84.7%	22	11	50.0%	210	61	71.0%
495		22	1	95.5%	208	3	98.6%	22	2	90.9%	208	6	97.1%
500		31	1	96.8%	293	22	92.5%	30	5	83.3%	291	83	71.5%
502		31	0	100.0%	291	13	95.5%	30	4	86.7%	289	82	71.6%
503		31	3	90.3%	304	32	89.5%	31	12	61.3%	293	93	68.3%
504		31	2	93.5%	292	11	96.2%	30	10	66.7%	291	117	59.8%
505	24	31	2	93.5%	296	33	88.9%	30	8	73.3%	293	105	64.2%
506		31	4	87.1%	296	28	90.5%	30	7	76.7%	294	73	75.2%
507	16	31	3	90.3%	295	33	88.8%	31	14	54.8%	294	94	68.0%
508		31	2	93.5%	299	15	95.0%	31	8	74.2%	297	86	71.0%
509	19	31	4	87.1%	294	32	89.1%	30	10	66.7%	293	104	64.5%
511		31	1	96.8%	295	23	92.2%	31	5	83.9%	292	77	73.6%
516		31	4	87.1%	295	28	90.5%	31	15	51.6%	293	133	54.6%
517		31	0	100.0%	296	5	98.3%	31	12	61.3%	295	175	40.7%
518	30	31	3	90.3%	296	32	89.2%	31	14	54.8%	294	175	40.5%
519		31	0	100.0%	293	11	96.2%	31	4	87.1%	292	59	79.8%
520		22	5	77.3%	43	7	83.7%	22	1	95.5%	43	2	95.3%
521		22	0	100.0%	211	4	98.1%	22	1	95.5%	210	16	92.4%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
522		22	2	90.9%	211	5	97.6%	21	1	95.2%	210	12	94.3%
523		22	0	100.0%	212	4	98.1%	22	1	95.5%	212	26	87.7%
524		22	1	95.5%	212	6	97.2%	21	3	85.7%	211	36	82.9%
525		22	0	100.0%	210	4	98.1%	22	0	100.0%	209	10	95.2%
526		22	0	100.0%	43	4	90.7%	22	3	86.4%	43	7	83.7%
527		22	0	100.0%	212	3	98.6%	22	1	95.5%	211	30	85.8%
528		22	0	100.0%	211	5	97.6%	22	4	81.8%	211	34	83.9%
529		22	0	100.0%	212	0	100.0%	22	6	72.7%	212	42	80.2%
531		22	1	95.5%	211	3	98.6%	22	5	77.3%	210	18	91.4%
532		22	1	95.5%	212	10	95.3%	22	1	95.5%	210	21	90.0%
534		22	2	90.9%	212	15	92.9%	22	3	86.4%	211	17	91.9%
535		22	3	86.4%	43	4	90.7%	21	2	90.5%	42	4	90.5%
536		22	1	95.5%	212	9	95.8%	22	2	90.9%	210	10	95.2%
537		21	1	95.2%	42	2	95.2%	21	0	100.0%	42	2	95.2%
538		22	1	95.5%	212	5	97.6%	22	3	86.4%	212	37	82.5%
540		22	0	100.0%	212	5	97.6%	22	4	81.8%	207	22	89.4%
541		22	0	100.0%	212	8	96.2%	22	6	72.7%	212	46	78.3%
542	14	22	1	95.5%	212	8	96.2%	22	5	77.3%	212	37	82.5%
543		22	0	100.0%	212	6	97.2%	22	11	50.0%	212	35	83.5%
544	42	21	2	90.5%	210	12	94.3%	21	1	95.2%	209	16	92.3%
545		22	1	95.5%	212	8	96.2%	22	2	90.9%	210	22	89.5%
546		22	0	100.0%	212	7	96.7%	22	3	86.4%	211	31	85.3%
547		22	3	86.4%	212	10	95.3%	22	3	86.4%	212	29	86.3%
548	14	22	0	100.0%	210	12	94.3%	22	1	95.5%	208	12	94.2%
549		22	5	77.3%	212	24	88.7%	21	1	95.2%	206	30	85.4%
551		22	0	100.0%	212	10	95.3%	22	1	95.5%	207	18	91.3%
562	17	31	4	87.1%	300	35	88.3%	30	3	90.0%	290	33	88.6%
564		31	6	80.6%	298	23	92.3%	30	5	83.3%	294	29	90.1%
566		31	0	100.0%	123	10	91.9%	31	3	90.3%	123	14	88.6%
572		31	4	87.1%	253	23	90.9%	31	10	67.7%	249	48	80.7%
573	24	31	1	96.8%	292	38	87.0%	31	5	83.9%	286	48	83.2%
577		31	1	96.8%	46	1	97.8%	30	2	93.3%	45	2	95.6%
580		31	0	100.0%	300	21	93.0%	31	1	96.8%	299	53	82.3%
581		31	4	87.1%	300	37	87.7%	31	9	71.0%	296	60	79.7%
582		31	1	96.8%	46	1	97.8%	31	3	90.3%	46	4	91.3%
586		31	2	93.5%	251	31	87.6%	31	5	83.9%	244	43	82.4%
587		31	3	90.3%	251	28	88.8%	30	6	80.0%	244	52	78.7%
591		31	0	100.0%	300	32	89.3%	31	4	87.1%	296	42	85.8%
593		31	6	80.6%	46	8	82.6%	30	4	86.7%	45	7	84.4%
595		31	4	87.1%	292	62	78.8%	31	2	93.5%	290	50	82.8%
600		22	3	86.4%	210	5	97.6%	22	2	90.9%	208	26	87.5%
601		22	4	81.8%	210	21	90.0%	22	4	81.8%	209	35	83.3%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
605		22	2	90.9%	210	12	94.3%	22	1	95.5%	208	27	87.0%
607		22	3	86.4%	211	20	90.5%	22	1	95.5%	210	11	94.8%
609		22	2	90.9%	211	14	93.4%	19	1	94.7%	208	30	85.6%
620		22	1	95.5%	211	6	97.2%	22	3	86.4%	209	27	87.1%
622	35	18	2	88.9%	167	8	95.2%	18	3	83.3%	166	48	71.1%
639		22	1	95.5%	211	26	87.7%	22	4	81.8%	210	26	87.6%
640		22	1	95.5%	211	1	99.5%	22	4	81.8%	211	102	51.7%
641		22	1	95.5%	211	19	91.0%	22	1	95.5%	211	35	83.4%
642	16	22	0	100.0%	211	0	100.0%	22	2	90.9%	210	43	79.5%
643		22	0	100.0%	211	13	93.8%	22	2	90.9%	210	43	79.5%
644		22	1	95.5%	211	9	95.7%	21	3	85.7%	208	47	77.4%
645		22	2	90.9%	211	16	92.4%	21	5	76.2%	210	54	74.3%
646	15	22	1	95.5%	211	18	91.5%	22	5	77.3%	208	101	51.4%
647		22	1	95.5%	211	15	92.9%	21	10	52.4%	210	85	59.5%
648		22	0	100.0%	211	12	94.3%	22	6	72.7%	209	36	82.8%
649		22	0	100.0%	211	20	90.5%	22	5	77.3%	210	40	81.0%
650		22	0	100.0%	211	10	95.3%	22	1	95.5%	210	30	85.7%
651		22	2	90.9%	211	25	88.2%	22	7	68.2%	211	84	60.2%
652		22	1	95.5%	211	4	98.1%	22	7	68.2%	211	39	81.5%
653	52	22	3	86.4%	211	16	92.4%	22	10	54.5%	210	72	65.7%
654		22	2	90.9%	211	6	97.2%	22	0	100.0%	209	20	90.4%
655		22	6	72.7%	210	35	83.3%	22	9	59.1%	208	75	63.9%
656		22	3	86.4%	211	6	97.2%	22	2	90.9%	210	45	78.6%
657		22	1	95.5%	211	14	93.4%	22	2	90.9%	211	51	75.8%
658		22	2	90.9%	211	8	96.2%	22	4	81.8%	210	54	74.3%
680		23	1	95.7%	213	3	98.6%	23	3	87.0%	212	34	84.0%
681		23	0	100.0%	212	12	94.3%	23	7	69.6%	209	80	61.7%
682		23	1	95.7%	213	6	97.2%	23	3	87.0%	213	97	54.5%
683	19	22	0	100.0%	165	4	97.6%	22	12	45.5%	165	68	58.8%
684		21	8	61.9%	164	17	89.6%	21	10	52.4%	163	86	47.2%
685	48	21	0	100.0%	168	12	92.9%	21	13	38.1%	168	64	61.9%
686		23	6	73.9%	212	42	80.2%	23	12	47.8%	212	89	58.0%
687		23	2	91.3%	213	30	85.9%	23	11	52.2%	213	83	61.0%
688	62	23	2	91.3%	213	9	95.8%	23	3	87.0%	213	90	57.7%
689	15	8	1	87.5%	153	7	95.4%	8	4	50.0%	154	33	78.6%
702		31	4	87.1%	304	21	93.1%	31	16	48.4%	303	101	66.7%
703	31	31	3	90.3%	304	30	90.1%	31	13	58.1%	304	78	74.3%
710		31	12	61.3%	304	54	82.2%	30	20	33.3%	297	90	69.7%
711		31	1	96.8%	303	11	96.4%	31	11	64.5%	294	37	87.4%
712		31	5	83.9%	304	48	84.2%	30	15	50.0%	301	93	69.1%
713		30	0	100.0%	302	9	97.0%	26	16	38.5%	283	66	76.7%
714	34	31	7	77.4%	303	42	86.1%	31	14	54.8%	298	76	74.5%

Amtrak On Time Performance													
Trains Arriving Through: 7/31/2025													
		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
715		31	6	80.6%	303	45	85.1%	28	18	35.7%	290	95	67.2%
716	19	31	6	80.6%	303	34	88.8%	29	9	69.0%	301	65	78.4%
717	31	29	3	89.7%	297	33	88.9%	26	10	61.5%	280	72	74.3%
718		31	9	71.0%	304	46	84.9%	30	8	73.3%	302	57	81.1%
719		31	7	77.4%	304	30	90.1%	30	17	43.3%	295	74	74.9%
761	60	31	1	96.8%	300	18	94.0%	31	7	77.4%	300	40	86.7%
765		31	1	96.8%	300	13	95.7%	31	3	90.3%	291	42	85.6%
769		31	2	93.5%	298	13	95.6%	31	7	77.4%	294	57	80.6%
770		31	0	100.0%	300	17	94.3%	31	6	80.6%	297	40	86.5%
774		31	0	100.0%	300	8	97.3%	31	3	90.3%	296	65	78.0%
779		31	0	100.0%	46	1	97.8%	31	3	90.3%	46	7	84.8%
784	22	31	1	96.8%	300	33	89.0%	30	13	56.7%	296	118	60.1%
785		31	2	93.5%	300	15	95.0%	31	1	96.8%	298	44	85.2%
790		31	2	93.5%	300	16	94.7%	31	2	93.5%	297	43	85.5%
794		31	0	100.0%	300	22	92.7%	30	1	96.7%	298	58	80.5%
821	19	28	0	100.0%	299	6	98.0%	28	21	25.0%	299	155	48.2%
822	106	30	2	93.3%	301	13	95.7%	30	30	0.0%	301	161	46.5%
1333	19	31	2	93.5%	297	52	82.5%	31	24	22.6%	296	190	35.8%
1340	24	31	2	93.5%	296	14	95.3%	31	18	41.9%	294	101	65.6%
2103		20	0	100.0%	206	11	94.7%	20	1	95.0%	203	23	88.7%
2107		22	5	77.3%	207	38	81.6%	22	2	90.9%	203	28	86.2%
2108		21	2	90.5%	203	21	89.7%	20	4	80.0%	200	31	84.5%
2121	11	21	1	95.2%	204	32	84.3%	20	9	55.0%	199	50	74.9%
2122		22	3	86.4%	206	37	82.0%	22	4	81.8%	200	35	82.5%
2124		18	3	83.3%	165	29	82.4%	17	4	76.5%	161	36	77.6%
2150		22	0	100.0%	211	7	96.7%	22	7	68.2%	211	67	68.2%
2151		22	0	100.0%	211	0	100.0%	21	5	76.2%	210	50	76.2%
2152		21	3	85.7%	208	8	96.2%	20	9	55.0%	201	83	58.7%
2153	11	21	0	100.0%	206	5	97.6%	21	13	38.1%	204	52	74.5%
2154		21	5	76.2%	208	19	90.9%	19	13	31.6%	203	92	54.7%
2155		20	1	95.0%	200	13	93.5%	20	9	55.0%	193	82	57.5%
2159		20	2	90.0%	206	16	92.2%	20	8	60.0%	201	66	67.2%
2162	17	19	1	94.7%	207	16	92.3%	18	10	44.4%	201	74	63.2%
2166	No OS	19	5	73.7%	207	14	93.2%	18	11	38.9%	204	50	75.5%
2167	26	22	1	95.5%	211	28	86.7%	22	9	59.1%	209	55	73.7%
2168		22	3	86.4%	211	17	91.9%	22	8	63.6%	210	50	76.2%
2169		20	4	80.0%	206	49	76.2%	19	8	57.9%	199	70	64.8%
2170		21	3	85.7%	201	15	92.5%	20	7	65.0%	197	49	75.1%
2172		20	2	90.0%	196	23	88.3%	20	8	60.0%	192	43	77.6%
2173		19	3	84.2%	203	22	89.2%	19	8	57.9%	203	51	74.9%
2190		21	0	100.0%	209	14	93.3%	21	1	95.2%	206	17	91.7%
2193	34	20	1	95.0%	205	26	87.3%	20	9	55.0%	198	72	63.6%

Amtrak Endpoint OTP Details

Late Trains For

Region: ALL

Service: ALL

Arriving On: 7/31/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2121	WAS	11	CTI	23	CTI	9	PHL-XPV	AM	Meet, ., ., Other, ., no train ahead
2153	WAS	11	PET	8	PET	8	XCY-XHM	AM	Scheduled in track usage program, Other, XFR-XHM, OPR 4 TRK A/C ET INSPECTION ON 3 TRK
2162	BOS	17	CTI	17	PTI	10	NWK-NYP	AM	Follow, AM98, Other, NWK-NYP
2166	BOS	No OS Rpt							
2167	WAS	26	WTR	33	WTR	33	PHL-PHL	AM	Flood / washout, Control Point, ., Held for service disruption a/c High water on all tracks MP 24.5
2193	NYP	34	ENG	16	ENG	12	RTE-RTE	AM	PTC - On Board Cab Signal or PTC Failure, n/a, Restriction at Transfer trk 1 had cut out on board TL per ground foreman
85	RVM	37	DCS	22	DCS	12	RVR-RVM	CS	Restrictive signal(s) from unknown cause Stop, Control Point, amtrak jct
86	BOS	26	PTI	29	PTI	9	NHV-NLC	AM	Cross over or go around, 2169, Milepost w/Letters, nhv, xss, Waited for AM2169 to crossover 2-1 at shWS COVE A/C PSNGR IN THE GUAGE TRK 1 AT NLC
93	NFK	30	WTR	46	WTR	23	X3V-NFK	NS	Flash flood warning Milepost w/Letters, N 37.20, N 1.60
129	WAS	42	WTR	47	WTR	47	PHL-PHL	AM	Flash flood warning, Control Point, ., Held for service disruption a/c High water on all tracks MP 24.5
171	RNK	21	CTI	17	WTR	10	PHL-WIL	AM	Storm, Milepost, 16.8, 20.3, TOL No.3 trk Hook - Holly int
173	WAS	54	WTR	58	WTR	58	PHL-WIL	AM	Flood / washout, Control Point, ., Held at Holly int for service disruption a/c High water on all tracks MP 24.5
175	WAS	19	SMW	17	SMW	17	XSH-NYP	AM	Scheduled in track usage program, Other, XPB-XPB, HLED AT PELHAM BAY FOR AM2172 TO CLEAR 1TRK A/C 2TRK O/O/S LEGGETT TO PELHAM BAY
177	PHL	No OS Rpt	CON	35	CON	35	NHV-NHV	MN	Hold for connecting train 417
179	PHL	89	SYS	52	SYS	52	NHV-NHV	MN	Other late crew Control Point, 272
417	NHV	39	CCR	28	CCR	28	SPG-SPG	AM	Set out defective cab car, CC/9632, AM417 will dp SPG late and need to WYE a/c wipers not working on lead CC/9632.
479	NHV	21	PTI	8	CTI	8	WND-HFD	AM	Meet, ctrail, 4466, Milepost w/Letters, wnd, hfd, Met ctrail 4466 at hart
490	SPG	No OS Rpt							

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/31/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
80	NYP	43	PTI	48	PTI	14	RMT-PTB	CS	Wait for station track P04030, Control Point, appomattox	
622	PHL	35	DCS	30	DCS	27	PAR-DOW	AM	Restrictive signal(s) from unknown cause, 1E, Control Point, PARK INTERLOCKING	
642	NYP	16	SVS	21	SVS	21	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, added E/633	
646	NYP	15	CTI	10	DMW	8	NWK-NYP	AM	Held for or routed around MW work or equipment, Other, NWK-XHU, OPR 1 TRK A/C TRACK DEFECT ON 2 TRK REA INT	
653	HAR	52	ENG	28	ENG	12	NYP-NYP	AM	Undesired emergency application, 9638 653, ACSES ISSUES ON ENG.9638	
19	NOL	71	FTI	82	CTP	25	WAS-WAS	AM	Delay due to mechanical problems on a Commuter train, ELECTRICAL FIRE ON VRE 9313	
683	BRK	19	PTI	9	PTI	9	EXR-DHM	CS	Meet 684, Control Point, rockingham	
685	BRK	48	TRS	40	TRS	40	POR-FRE	CS	Vehicle strike Other, Brighton Ave	
688	BON	62	POL	40	POL	40	FRE-POR	CS	RR blocked by trespasser or vehicle strike by another train 685 had vehicle strike at Brighton Ave MP PLD 10.68	
689	BRK	15	FTI	14	FTI	14	XP0-EXR	CS	Meet 427, Control Point, plaistow	
63	TWO	25	HLD	13	OTH	9	NYP-XSD	AM	Lost time - N.A.R.	
68	NYP	34	PTI	34	PTI	34	XWH-FED	DH	Meet 291, Other, fed siding	
233	ALB	24	ITI	13	ITI	13	NYP-NYP	AM	Service, turn, or wye train, 236, LATE TURN OFF AM236	
236	NYP	26	RTE	17	RTE	17	YNY-XSD	AM	Dispatcher hold Control Point, 12	
239	ALB	23	CTI	13	CTI	9	CRT-POU	MN	Follow mn, Control Point, 46	
243	ALB	32	ITI	23	ITI	23	NYP-NYP	AM	Service, turn, or wye train, 244, LATE FROM SSYD A/C LATE TURN OFF AM244	
244	NYP	25	ENG	30	ENG	19	ALB-HUD	AM	PTC- Cutout due to unrecoverable penalty 717	
290	NYP	22	DSR	28	DSR	20	BTN-VRN	VR	Per bulletin Milepost, 117.03, 116.86, 10, Main, Milepost, 116.86, 115.78, 25, Main, Milepost, 113.3, 109.71, 25, Main, Milepost, 109.71, 105.68, 50, Main, Milepost, 105.68, 105.19, 25, Main, Milepost, 105.19, 101.0, 50, Main, Milepost, 101.0, 100.63, 25, Main	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/31/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
49	CHI	45	SYS	79	SYS	67	XH6-XTF	NS	CN locomotive 2934 PTC inoperable / blocking caused bottle neck issue. Per Control Center CUS Control Point, 21st Street	
42	NYP	33	DSR	34	SVS	29	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train, Added Engine on North end, removed diesel engine from South end. and Added test engine to South end of train.	
43	PGH	22	FTI	34	FTI	22	HGD-TYR	NS	Follow 29G, Milepost, 202, 222	
71	CLT	16	DCS	10	DCS	10	SAL-KAN	NS	Wayside detector failure including false actuation Wayside detector not working, Other, 341.3	
73	CLT	37	FTI	20	DSR	9	KAN-CLT	NS	Per bulletin Milepost, 355.9, 360.1, 25, 2	
74	RGH	11	DSR	9	DSR	9	CLT-KAN	NS	Per bulletin Milepost, 360.1, 355.9, 25, 2	
75	CLT	15	FTI	11	FTI	8	GRO-HPT	NS	Meet #NS E-42, Control Point, Pomona	
77	CLT	14	PTI	14	PTI	14	DNC-BNC	NS	Meet #Amt74, Control Point, Merrill	
97	MIA	68	PTI	56	SVS	54	NYP-NYP	AM	Water, commissary, toilet/trash dumping, WAITING ON CARS FROM AM98	
98	NYP	75	CAR	39	CAR	29	WAS-WAS	AM	Air / Brake / Wheel, 25021, Brakes were not properly released on car # 25021, when the test was being administered, so adjustments were made, and retested to maintain the safety and integrity of the consist and its passengers.	
40	CHI	261	FTI	132	FTI	43	COV-XFI	CS	Follow IO115-30, Milepost, 283.5, 11.7	
41	MIA	38	RTE	68	SVS	24	WAS-WAS	AM	Planned set out / pick out of locomotives, cars or section of train, CUTTING 3 CARS FROM THE REAR END 69007, 10020, 9800	
5	EMY	69	DSR	93	PTI	46	TRU-XSO	UP	Meet Amtrak-6, Control Point, Shed-10	
6	CHI	227	FTI	214	ENG	66	DEN-DEN	RT	Air / Brake Traction motors/ Air, would not pass inspection., 169	
542	SAC	14	PTI	19	PTI	17	GAC-FMT	UP	Meet Amtk543south, Control Point, N Albrae	
544	SAC	42	POL	53	POL	53	OAC-OAC	UP	Fire department hold Stop signal at NI011 for a trackside fire north of 66th Ave.	
548	SAC	14	MBO	31	MBO	31	MTZ-SUI	UP	For maritime traffic Control Point, RV033	
51	CHI	62	FTI	57	FTI	41	CRF-LAF	CS	Follow M642, Milepost w/Letters, Q 136.0, Q120.0	
505	PDX	24	FTI	18	FTI	13	KEL-VAN	BN	Meet up 5931, Control Point, felida	

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/31/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
507	EUG	16	PTI	21	PTI	14	PDX-ORC	UP	Meet 508, Siding, clackamas
509	PDX	19	FTI	23	FTI	15	XA4-XTW	BN	Follow Unknown, Milepost w/Letters, 21.5x, 36.0x
518	VAC	30	DCS	27	MBO	14	XF2-X1J	BN	Bridge had to let freight train go due to signal failure at mud bay. Bridge, fraser river
59	NOL	213	CAR	181	CAR	181	CHI-CHI	AM	Short equipment 34055
8	CHI	45	FTI	102	FTI	29	GGW-WPT	BN	Meet BNSF, Siding, Kintyre
821	FTW	19	DSR	36	DSR	22	GLE-FTW	BN	Per bulletin Starting at noon, Milepost, 389.7, 389.5, 40, m, Milepost, 372.8, 372.4, 25, m, Milepost, 365.4, 365.3, 60, 1m, Milepost, 358.5, 358.4, 30, 1m, Milepost, 355.7, 355.5, 65, 1m, Milepost, 354.5, 354.0, 40, 1m, Milepost, 351.2, 351.1, 50, 1m, Milepost, 347.0, 346.7, 25, 1m, Milepost, 411.3
822	OKC	106	DSR	60	DSR	48	FTW-GLE	BN	Per bulletin Milepost, 346.7, 347.0, 25, M1, Milepost, 353.6, 353.8, 40, M2, Milepost, 354.0, 354.0, 35, M2, Milepost, 355.9, 411.3, 40, M1, MT, Milepost, 358.4, 358.5, 30, M1, Milepost, 372.4, 372.8, 25, MT, Milepost, 386.8, 388.5, 10, Siding
332	CHI	No OS Rpt	OTH	5	RTE	2	XRO-GLN	ME	Crossover(s) due to N.A.R. 1, Control Point, Roundout
341	MKE	117	ENG	98	ENG	98	CHI-CHI	AM	Blue car expires at midnight on AMTK 25 add AMTK 514 to consist 25
350	PNT	17	PTI	43	PTI	21	DOA-KAL	AM	Meet AMTK 351, Siding, DOA SIDING
351	CHI	34	SYS	35	SYS	26	XH6-XTF	NS	PTC problem or failure (cause unknown) CN inoperative locomotive, Milepost, 518, 521
353	CHI	16	DSR	15	MBO	7	HMI-XTF	NS	For maritime traffic Other, SOUTHBRANCH
365	CHI	27	FTI	25	FTI	21	LNS-BTL	CC	Meet CN2906, Milepost, 216, 216
562	SAN	17	PTI	23	PTI	14	SOL-SOL	SN	Meet amtk 769, Other, SOL
573	LAX	24	DCS	21	PTI	11	X98-SNC	SC	Meet amtk 770, Control Point, Capistrano
761	SLO	60	RTE	74	RTE	74	X3G-LPS	UP	Dispatcher hold Hold for rocket launch at Vandenburg AFB, Control Point, n gaviota
784	SAN	22	PTI	17	PTI	17	SNC-SNP	SC	Meet Amtk 587, Siding, Capistrano
703	SAC	31	PTI	28	TRS	15	MOD-MOD	BN	Unticketed or fare evading passenger Fare evader hiding in bathroom from Merced finally walked off train, Other, modesto
714	BFD	34	PTI	41	PTI	16	ACA-SKN	BN	Meet 713, Control Point, oakley

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 7/31/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
716	BFD	19							
717	OKJ	31	PTI	48	PTI	25	HNF-FNO	BN	Meet 714, Control Point, Calwa crossing
3	LAX	123	FTI	164	FTI	49	BAR-VRV	BN	Cross over or go around Stopped at restricting signal at MP 11.35, meeting BNSF 3899 and then BNSF 6555 behind a train which stopped ahead of us. After it moved and we got a yellow signal, we proceeded on yellow and approach medium signals overtaking five freights., BNSF various, Milepost, 13.47, 3
4	CHI	143	FTI	120	FTI	45	GLP-XIA	BN	Follow Unknown, Milepost, 143.1, 27.5
302	CHI	26	FTI	20	PTI	18	XUD-SMT	CC	Meet 319, Control Point, canal
305	STL	37	SVS	53	SVS	53	CHI-CHI	AM	LATE MAKE UP OF TRAIN
307	STL	41	FTI	30	RTE	19	XTF-SMT	CC	Inability to contact dispatcher Control Point, CORWITH
383	QCY	58	FTI	53	FTI	53	MAC-QCY	BN	Meet Had to wait for crew to walk train after they had a bad detector, BNSF 5484, Control Point, Colchester
311	KCY	18	DSR	19	PTI	13	JEF-SED	UP	Meet AMT 318, Siding, Shell
316	STL	18	DSR	25	DSR	19	WAR-SED	UP	Per bulletin Milepost, 198.0, 194.5, 40, MT, Milepost, 194.5, 192.25, 15, MT
319	KCY	100	SYS	55	SYS	53	CHI-XTF	AM	PTC problem or failure (cause unknown) Freight Engine PTC issues Waited for yard crew to rescue Engine from Bridge at 21st Street, Control Point, Roosevelt Rd
1333	MSP	19	DSR	37	DSR	20	WIN-RDW	CP	Per bulletin Milepost, 353.7, 363.3, 25, main, Milepost, 364.9, 365.1, 40, main
1340	CHI	24	DSR	38	DSR	18	RDW-WIN	CP	Per bulletin Milepost, 365.1, 364.9, 40, Main, Milepost, 363.3, 353.7, 25, Main

Amtrak Initial Terminal Details

Late Trains For:

Region: ALL

Division: ALL

Data Through: 7/31/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	74	07/31	5	5	Service, turn, or wye train 73, Late arriving 73 with ADA passengers with lifts. ADA passengers with lifts boarding outbound 74
PHL	110	07/31	(No OS)		
RGH	73	07/31	7	7	
RNK	66	07/31	9	9	
WAS	56	07/31	(No OS)		
WAS	2166	07/31	(No OS)		
BOS	85	07/31	7	7	Traction motor, 641, unable to release the traction motors at South station
NHV	490	07/31	(No OS)		
NYP	97	07/31	29	29	
NYP	119	07/31	9	9	
NYP	233	07/31	13	13	
NYP	243	07/31	47	47	
NYP	653	07/31	12	12	
SPG	417	07/31	28	28	
CHI	3	07/31	81	81	Water, commissary, toilet/trash dumping Late release, Control Point, CHI YARD
CHI	5	07/31	253	253	
CHI	7	07/31	28	28	
CHI	41	07/31	297	261	
CHI	41	07/31	297	36	
CHI	305	07/31	53	53	
CHI	307	07/31	26	26	
CHI	341	07/31	98	98	
CHI	354	07/31	12	12	
BFD	711	07/31	13	13	
LAX	14	07/31	23	23	Hold for connecting train 3
LAX	564	07/31	9	9	Failure of diesel engine 2116

Amtrak Initial Terminal Details

Late Trains For:
Region: ALL
Division: ALL
Data Through: 7/31/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	710	07/31	10	10	Dispatcher hold Per UP DS 62, held @ Magnolia for meet w/AMTK 524, Control Point, Magnolia
OKJ	718	07/31	12	12	HEP C2009
SAN	593	07/31	4	4	PTC - Initializing PTC (no failure) Waiting for BNSF to update GTB's for PTC.

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	95.2	95.2	341	2
CDOT	95.0	95	92.3	96.4	20	1
MARC	95.0	89.1	80.2	83.5	55	6
SEPTA	95.0	98.7	96.3	96.2	224	3
NJT-NED	95.0	96.8	92.7	95.2	370	12
NJT-SED	95.0	100	98.3	91.2	18	0

Operating Highlights

Train 52(31) Savannah, GA - Engine Failure

01AUG25: Train 52(31) with engines 322 and 364 was delayed at Savannah, GA due to lead engine 322 losing HEP for unknown reason causing the engineer to safely coast the train close to the station. Headend power was brought up on the rear unit 364 to ensure passengers remained comfortable. Savannah mechanical met the train on the mainline and performed tests while keeping the headend power on the trail unit to ensure the stress was kept off of the lead unit 322.

Train	Delay	Comment
52 (31)	1' 37"	

Train 97(31) North of Richmond, VA - Police Related

31JUL25: Train 97(31) with engines 315 and 366 was delayed holding at milepost 51.3 on the CSX RFP subdivision north of Richmond, VA waiting for EMS to remove a passenger with a medical condition.

Train	Delay	Comment
97 (31)	50"	

Train 98(31) North of Jesup, GA - Freight Train Interference

31JUL25: Train 98(31) was delayed north of Jesup, GA starting at milepost 523.0 on the CSX Nahunta subdivision due to freight congestion that was followed until milepost 510.0.

Train	Delay	Comment
98 (31)	57"	

Train 66(31) Roanoke, VA - Flash Flood

31JUL25: Train 66(31) was delayed from departure at Roanoke, VA to just north of Lynchburg, VA at milepost 172.0 for flash flood warnings and having to operate at restricted speed.

Train	Delay	Comment
66 (31)	57"	

Train 244/243(31) North of New York, NY - Engine Failure

31JUL25: Train 244(31) with engine 717, 5 cars, and cab car was delayed at Harmon station milepost 33.2 on the Amtrak Hudson line due to ACSES failure on engine 717. Train 244(31) had to operate restricted to New York, NY and train 243(31) departed late as a result.

Train	Delay	Comment
243(31)	47"	
244(31)	30"	

Train 622(31) West of Downingtown, PA - Signal

31JUL25: Train 622(31) with engine 632 was delayed from Park interlocking milepost 46.3 to Thorn interlocking milepost 35.0 on the Amtrak PH line west of Downingtown, PA due to restrictive signals. Trouble desk was notified to resolve the issue.

Train	Delay	Comment
622(31)	34"	

Train 52(31) North of Jacksonville, FL - Police Related

31JUL25: Train 52(31) with 435 passengers onboard was stopped at 7:28 p.m. at milepost 624.5 on the CSX Nahunta subdivision due to a chlorine leak at the local water maintenance facility in the city of Callahan, FL. The hold was released at 8:45 p.m. and there were no injuries to crew or passengers.

Train	Delay	Comment
52(31)	1' 39"	

Train 69(31) South of Port Kent, NY - Passenger Train Interference

31JUL25: Train 69(31) was delayed 4 miles south of Port Kent, NY at Rockland Siding/MP150.5 on the CFRC Canadian Subdivision due to meeting Train 68(31).

Train	Delay	Comment
69(31)	30"	

Train 685(31) North of Portland, ME - Occupied Vehicle Strike

31JUL25: At approximately 3:30PM-CT, train 685(31) operating with camera equipped locomotive AMTK/333, 05 cars collided with an occupied vehicle 01 miles North of Portland, ME. The incident occurred at DOT crossing # DOT 837470X, Brighton Ave, Portland, Maine, Cumberland County, MP 195.678, Pan Am Railway, Freight Mainline Subdivision of the CSX Railroad. The crossing is protected with audible bells, stop sign, railroad crossing sign, crossing arms with LED flashing lights. There were no reported injuries, to the (39) passengers, or onboard crew of the train. The owner/driver of the vehicle was also not reported injured. The track speed is 30MPH. Weather was reported as 64°F, heavy rain. Locomotive AMTK/333 provided Head End Power for the duration of the incident. Local authorities comprising Portland Police, and Cumberland County fire Dept. attended the scene. The train crew did not request CARE relief at the scene. Once the police investigation was completed & vehicle removed, tracks were re-opened at 4:00PM-CT.

Service Recovery:
Amtrak Police Notified.
National Response Centre Number - 1438521
Maine Dept. Emergency Services Number - 2025-

National Response Center Number: 1438521

Train	Delay	Comment
685(31)	40"	

Train 20(31) South of Meridian, MS - Freight Train Interference

31JUL25: Train 20(31) was delayed 1 mile south of Meridian, MS at MP.9 on the Norfolk Southern NO&NE Subdivision due to meeting freight unit 29K.

Train	Delay	Comment
20(31)	56"	

Train 40(29) West of Connellsville, PA - Freight Train Interference

31JUL25: Train 40(29) was delayed 15 miles west of Connellsville, PA, due to following IO115-30 between MP283.5 on the CSX Pittsburgh_BF to MP11.7 on the CSX Pittsburgh_PLY Subdivision.

Train	Delay	Comment
40(29)	43"	

CSX Heat Orders - Weather

31JUL25: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Alleghany, Kanawha, New River, Peninsula, Auburndale, Carters, Jacksonville Terminal, Lakeland, Nahunta, Sanford, Savannah and Tampa Terminal.

Train	Delay	Comment
40(31)	24"	
186(31)	11"	
98(31)	18"	
97(30)	13"	
41(30)	20"	
40(30)	20"	

PW Line North of Wilmington, DE - Weather

31JUL25: Due severe storms/weather conditions, and high water conditions at milepost 24.5 on the Amtrak PW Line between Holly/MP20.3 and Landlith/MP25.4 several trains were delayed holding at Philadelphia station and Wilmington station until route was clear.

Train	Delay	Comment
173 (31)	57"	
129 (31)	47"	
2167 (31)	33"	
136 (31)	07"	
2122 (31)	08"	

OTP Acela/Regional Cancellations - Miscellaneous Amtrak Responsible

29JUL25: In an effort to improve Northeast Regional OTP the following service adjustments have been made:

Acela Trains 2163(28JUL-30SEP) and 2166(28-30SEP) will be cancelled from July 28,2025 thru September 30,2025.

Train 170(31JUL-30SEP) will be suspended Monday thru Friday from July 31,2025 to September 30,2025.

Train 137(31JUL-30SEP) will be suspended Monday thru Thursday and truncated to operate New York to Washington only on Friday.

Train 123(31JUL-30SEP) suspended Sunday

Train 139(31JUL-30SEP) truncated at Philadelphia on Sunday will operate Boston to Philadelphia.

Maintenance of Way Highlights

NSRR Pittsburgh Line Trackwork

18JUL25: Norfolk Southern has tie installation trackwork scheduled on the Pittsburgh Line between MP144 and MP224. The dates for the trackwork will be July 28th through July 31st, August 4th through August 7th, and August 11th through August 14th. To accommodate this infrastructure work, Amtrak's Pennsylvanian Service will be adjusted as follows:

- Train 42 (28Jul-31Jul, 4Aug-7Aug, 11Aug-14Aug) will operate 45-minutes LATER between CP Cannon (XNN) and New York
- Train 43 (28Jul-31Jul, 4Aug-7Aug, 11Aug-14Aug) will not have a schedule adjustment and will be subject to arrive 45 to 60-minutes late at Pittsburgh.

WBS#: B.TR.100150.5896

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Bay.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division/ Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12,2025 to Friday October 10,2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Hartford Line - Windsor Locks Station Project - M of W Work

22APR25: Amtrak MRS Line/Northeast Division trackwork between New Haven, CT to Greenfield, MA for the Windsor Locks Station Project at MP 47.4 from April 22,2025 to October 31,2025 Monday thru Friday. Expect the following Major Holidays: Monday, May 26,2025, Friday, July 04,2025, Monday, September 1,2025.

Amtrak Operating Plan:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line Service will be adjusted as follows:

Northbound:

- Train 490 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by a bus; 1 express and 1 local.
- Train 470 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between NHV and SPG, will terminate at HFD.
- Train 426 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct) is a new train that will operate Deadhead between NHV and HFD.

Southbound:

- Train 471 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (2Jun-6Jun, 9Jun-13Jun, 16Jun-20Jun, 23Jun-27Jun, 30Jun-3Jul, 7Jul-11Jul, 14Jul-18Jul, 21Jul-25Jul, 28Jul-1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug, 25Aug-29Aug, 2Sep-5Sep, 8Sep-12Sep, 15Sep-19Sep, 22Sep-26Sep, 29Sep-3Oct, 6Oct-10Oct, 13Oct-17Oct, 20Oct-24Oct, 27oct-31Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

EQUIPMENT

(For the dates listed in the "Operating Plan" Section):

- Deadhead Train 426 will turn for Train 471 at HFD
- Train 470 will turn for Train 473 at HFD

Eastern Region

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
600 (1)		Wifi		No WIFI

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 97(31) Passenger Removal at Fredericksburg, Virginia – Medical

31JUL25, Passenger on PNR 3B299A, traveling from New York, NY to West Palm Beach, FL was removed from the train by Spotsylvania Fire Department and taken to Spotsylvania Medical Center. The passenger complained of chest pain and was vomiting. Amtrak Police notified.

Delay: 97 (31) 50"

Train 98(31) Passenger Removal at Jacksonville, Florida – Other

31JUL25, Passenger on PNR 4A5832, traveling from Fort Lauderdale, FL to New York, NY was removed from the train by Jacksonville Sheriff Office. The passengers service animal was barking and lunged at the conductor. Amtrak Police notified.

Delay: 98 (31) 3"

Western Region

Operating Highlights

Train 59(30) South of Hazlehurst, MS - Passenger Train Interference

01AUG25: Train 59(30) was delayed 11 miles south of Hazelhurst, MS, on CN McComb subdivision, meeting train 58(31) at control point Central Jct.

Train	Delay	Comment
59 (30)	36"	

Train 3(30) East of Albuquerque, NM - Commuter Train Interference

01AUG25: Train 3(30) was delayed 8 miles east of Albuquerque, NM, on NMRX Albuquerque subdivision, due to meeting NMRX train at Alameda siding.

Train	Delay	Comment
3 (30)	31"	

Train 4(30) East of Lamy, NM - Passenger Train Interference

01AUG25: Train 4(30) was delayed 15 miles east of Lamy, NM, on BNSF Glorieta subdivision due to meeting train 3(30) at Fox siding.

Train	Delay	Comment
4 (30)	41"	

Train 383(31) West of Macomb, IL - Freight Train Interference

01AUG25: Train 383(31) was delayed 8 miles west of Macomb, IL, on BNSF Brookfield subdivision, due to meeting BNSF5484 at Control Point Colchester. BNSF5484 was blocking the route due to inspecting their equipment after setting off a hot box detector. Once the freight finished inspecting their equipment, they were able to proceed, clearing a route for train 383(31).

Train	Delay	Comment
383 (31)	53"	

Train 305(31) Chicago, IL - Servicing

01AUG25: Train 305(31) was delayed 53 minutes departing Chicago, Illinois account late makeup in CUS. Train 305(31) turned with equipment off inbound Train 302(31), which arrived at 1206pm, 26 minutes late. Due to ongoing congestion in the terminal, Train 302(31) shoved from CUS at 320pm. The train was set to the yard at 400pm. The rear of the two trainsets was cut off in the yard. Train 305(31) was set in CUS at 505pm. After mechanical worked and released the train, Train 305(31) departed CUS at 613pm, 53 minutes late.

Train	Delay	Comment
305 (31)	53"	

Train 341(31) Chicago, IL - Engine Failure

31JUL25: Train 41(31) was delayed 4 hours and 57 minutes departing Chicago, Illinois due to a late turn of equipment off inbound 40(29) and backfilling the locomotive as one of the original locomotives was used to replace a bad order on California Zephyr Train 5(31). As background, inbound 40(29) arrived in Chicago at 106pm; 4 hours and 21 minutes late due to 1 hour and 39 minutes of heat orders, 42 minutes for passenger's and/or baggage, 2 hours and 12 minutes for freight interference, 55 minutes for speed restrictions, and 29 minutes for passenger train interference. Equipment set to the yard for servicing and inspection at 257pm with no scheduled program moves. At 330pm, engine 14 on California Zephyr Train 5(31) was bad ordered for loading issues. Due to a high shop count at the locomotive shop, engine 126 off Train 41(31) was selected as the replacement for Train 5(31) to be backfilled with engine 203 off inbound 4(29). Train 4(29) arrived in Chicago at 505pm; 2 hours and 23 minutes late and set to the yard at 647pm. Engine 203 was released at 748pm and tied on at 846pm. Train 41(31) was released by mechanical at 933pm and set in the station at 943pm. Because of the additional delay on Train 41(31) caused by the bad order locomotive on Train 5(31), the road crew only had approximately 1 hour and 27 minutes left to work. Train 41(31) was held for a re-crew before departing Chicago. Train 41(31) departed Chicago at 1137pm; 4 hours and 57 minutes late.

Train	Delay	Comment
341(31)	4'57"	

Train 544(31) North of Oakland Coliseum, CA - Trackside Fire

31JUL25: Train 544(31) was delayed departing Oakland Coliseum Station. This was to allow for fire crews to work a car fire near the tracks at MP 11.17, Niles Subdivision of the Union Pacific. All train traffic in was halted to allow fire crews to place their hoses and other equipment across the tracks to get closer to the fire. Once the fire had been extinguished, tracks were opened and train 544(31) was able to proceed to Oakland Jack London. Amtrak Police Notified.

Train	Delay	Comment
544(31)	53"	

Train 5(31) West of Chicago, IL - Injured or Sick Passenger or Employee

31JUL25: Train 5(31) came to a stop at Metras, Cicero station, 7 miles west of Chicago, IL, on BNSF Chicago subdivision, due to a passenger becoming unresponsive on the train. 5(31) came to a stop to wait for emergency services to arrive and asses the passenger. Once EMS arrived they determined that the passenger was deceased. Once the passenger was taken off the train by EMS, train 5(31) held for Amtrak Police to arrive and investigate. Once the police concluded their investigation the released the train and train 5(31) was able to proceed.

Train	Delay	Comment
5(31)	1'10"	

Train 22(31) West of Longview, TX - Freight Train Interference

31JUL25: Train 22(31) was delayed 6 miles west of Longview, TX, on Up Mineola subdivision, due to UP work train MNLEW finishing up some work. Once the work train cleared, train 22(31) was able to proceed.

Train	Delay	Comment
22(31)	1'02"	

Train 5(31) Chicago, IL - Engine Failure

31JUL25: Train 5(31) was delayed 4 hours 13 minutes departing Chicago, Illinois account bad order engine in CUS. Train 5(31) reported at 139pm that the engine had loading issues. Mechanical responded and repaired, clearing the train again at 231pm. When attempting to depart again at 238pm, they experienced the same issues. At 330pm, the leader E/14 was bad ordered. Replacement E/126 was released at 421pm. Bad order E/14 was held off at 435pm. Train 5(31) was made up complete at 548pm. Mechanical worked and released at 606pm. Train 5(31) departed CUS at 613pm, 4 hours 13 minutes late.

Train	Delay	Comment
5 (31)	4'13"	

Train 6(29) East of Osceola, IA - Freight Train Interference

31JUL25: Train 6(29) was delayed at MP 356.9, 3 miles east of Osceola,IA, on the BNSF Ottumwa Subdivision due to meet with BNSF 6083. Crew held on main track two until west bound freight cleared then crossed over to main one to continue east.

Train	Delay	Comment
6 (29)	33"	

Train 5(29) West of Truckee CA –Passenger Train Interference

31JUL25: Train 5(29) was delayed at 26 miles West of Truckee CA at Shed 10, MP 178.2 on the UPRR Roseville Subdivision. This was to allow for Amtrak traun 6(31) to operate eastbound over the crossover switches ahead. Once cleared, train 5(29) was able to continue to Colfax.

Train	Delay	Comment
5 (29)	46"	

Train 2/422(30) East of Tucson, AZ - Freight Train Interference

31JUL25: Train 2/422(30) was delayed starting at MP 985, 1 mile east of Tucson, AZ, to Chamiso/MP 1029 on the BNSF Gila Subdivision due to meet with UP2567 then following freight on main track two. Once able to get around freight, crew was able to proceed east at track speed.

Train	Delay	Comment
2/422 (30)	1'16"	

Train 3(30) East of Raton, NM - Loading Issues

31JUL25: Train 3(30) was delayed at MP 649.2, 10 miles east of Raton, NM, on the BNSF Raton Subdivision due to loading issues on E/188. Crew contacted CNOC mechanical to troubleshoot. Once problem was identified and problem was resolves, Train 3(30) was able to proceed west.

Train	Delay	Comment
3 (30)	39"	

Chicago, IL - Freight Unit PTC Issues

31JUL25: Multiple trains were delayed in and out of the yard in Chicago, IL due to CN234 having PTC issues on bridge at 21st street needing yard crew to rescue with yard engine. Train traffic was halted while yard crew readied yard engine and responded. Once crew got to location and coupled to freight, rail traffic was able to resume.

Train	Delay	Comment
319(31)	53"	
51(30)	39"	
49(30)	1'06"	
351(31)	26"	

Train 761(31) North of Goleta – Space Rocket Launch

31JUL25: The US Space Force scheduled the launch of Space X, Falcon 9 Rocket, from Vandenberg Space Force Base in Southern California, between 9:29AM-PT and 1:29PM-PT. The safe exclusion zone for this launch encompassed the railroad tracks north of Goleta Station. This required that train 761(31) be held 21 miles north of Goleta - at Gaviota, MP 336.3 Santa Barbara Subdivision - until the rocket was safely underway. Once the rocket had been launched, the train was further delayed while UPRR maintenance-of-way personnel searched the tracks for potential fallen debris.

Train	Delay	Comment
761(31)	1'14"	

Train 3(29) East of Victorville, CA - Freight Train Interference

31JUL25: Train 3(29) was delayed starting at MP 11.1, 25 miles east of Victorville, CA, on the BNSF Cajon Subdivision due to meet and follow of BNSF freight. Due to vandalism, there was single track conditions near Victorville, crew held for meet with BNSF 3899 and BNSF 6555. Once those freights cleared, they followed those freights until MP 47, 10 miles west of Victorville, where they were able to get around.

Train	Delay	Comment
3(29)	56"	

Train 51(30) North of Crawfordsville, IN - Freight Train Interference

31JUL25: Train 51(30) was delayed at Linden/MP 136.1, 10 miles north of Crawfordsville, IN, on the CSX Monon Subdivision due to following CSX M642. Once freight cleared route, Train 50(30) was able to proceed at track speed.

Train	Delay	Comment
51(30)	41"	

Train 21(30) Malvern, AR - Suspicious Bag

31JUL25: Train 21(30) was delayed departing Malvern, AR on the UPRR Little Rock Subdivision due to a suspicious bag found in the baggage car. Crew found a bag in the baggage car that was chained up to the bike rack with no identification or baggage check tags on it. Train 21(30) held in Malvern while police were contacted and the crew looked for who the bag may belong to. Amtrak police were notified and started sourcing a canine crew to inspect bag. The owner of the bag was identified and the crew verified the bag. Crew had owner detach bag and properly tag bag. Once everything was verified and it was safe to proceed, Train 21(30) departed Malvern.

Train	Delay	Comment
21(30)	36"	

Chicago, IL High Car Shop Count - Supplemental Bus

18JUN25: As a result of a high shop count of cars in Chicago, IL the following trains 370(18), 370(19), 305(18) and 300(19) operated supplemental buses for the oversold conditions.

370(18) - 59 oversold
371(19) - 10 oversold
305(18) - 13 oversold
300(19) - 68 oversold

20JUN25: As a result of the ongoing high car shop count in Chicago, IL. Supplemental bus was required for Train 300(20) and Train 371(20) account of oversold conditions.

300(20) - 59 oversold
371(20) - 38 oversold

21JUN25: Shop count in Chicago, IL continues to be high. Supplemental bus was required for Train 300(21) and Train 371(21) account of oversold conditions.

300(21) - 62 oversold
371(21) - 33 oversold.

22JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 370(22) account of oversold conditions.

370(22) - 21 oversold

25JUN25: Due to the ongoing high car shop count in Chicago, supplemental bus was required for Train 371(25) account of oversold conditions.

371(25) - 46 oversold. ** Note: Due to traffic conditions the bus did not make it to the scheduled stops prior to Train 371(25). Passengers were accommodated in cafe **

28JUN25: Due to ongoing high shop count in Chicago, supplemental bus was required for Train 319(28) account of oversold conditions due to bad ordered C/4014 for non-working toilets. Train 319(28) was further delayed departing Chicago due to door issues with ID4014/ID4116/ID4125/ID4203/ID4312. Once mechanical responded and solved issues, Train 319(28) departed.

29JUN25: Train 318(29) was oversold by 54 seats. A bus was secured to operate St. Louis, MO to Chicago, IL. Trains 301(29) was oversold by 67 seats and 306(29) was oversold by 15 seats due to high shop count in Chicago. Two supplemental buses were secured for 301(29) operating express from Chicago to St Louis. Trains 307(29) and 300(30) were both cancelled with alternate bus transportation.

30JUN25: Train 319(30) was oversold by 68 seats. Four buses were secured operating between Chicago, IL and St Louis, MO. Train 301(30) was oversold by 67 seats. Two buses were secured operating from Chicago, IL to St Louis, MO express.

Trains 307(30) and 300(01JUL) were both cancelled with alternate bus transportation due to equipment shortage.

03JUL25: Train 390(03) oversold by 60 seats, Train 301(03) oversold by 60 seats, Train 337(03) oversold by 38 seats and Train 306(03) oversold by 61 seats account of shortage of coach cars.

One bus was secured for Train 390(03) to express between Champaign, IL and Chicago, IL for the 61 passengers oversold.

One Bus was secured for Train 301(03) to express between Chicago, IL and Bloomington-Normal, IL.

One bus was secured for Train 306(03) to express between St. Louis, MO and Chicago, IL. Two buses were secured for Train 337(03) to express between Chicago, IL and Milwaukee, IL

12JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 370(12) & 371(13) operated without business class. 11 passengers impacted on Train 370(12) and 13 passengers on 371(13).

- Trains 305(12) & 300(13) operated without business class. 15 passengers impacted on Train 305(12) and 6 passengers on 300(13).

Affected passengers were notified and downgraded/rebooked as necessary.

13JUL25: Due to equipment availability consist deviations to Midwest State Supported services as follows:

- Trains 305(13) & 300(14) operated without business class. 34 passengers impacted on Train 305(13) and 18 passengers on 300(14).

- Trains 370(13) & 371(14) operated without business class. 27 passengers impacted on

370(13) & 25 passengers on 371(14).

14JUL25: Due to the high shop count, equipment availability and consist deviations:

- Train 1340(14) had two supplemental buses operate St. Paul-Minneapolis, MN to Milwaukee, WI express due to a hot car in consist.
- Train 319(14) had one supplemental bus operate Chicago to Bloomington-Normal, IL to alleviate overbooked condition.
- Train 307(14) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.

15JUL25: Due to the high shop count and equipment availability in Chicago:

- Train 302(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Train 301(15) cancelled entirely, with alternate transportation between Chicago and St. Louis. Busses secured for Train 301(15) or passengers may rebook on Train 319(15).
- Train 306(15) cancelled entirely, with alternate transportation between St. Louis and Chicago.
- Trains 371(15), 370(15) and 371(16) operated without business class. 8 passengers impacted on 371(15), 19 passengers on 370(15) and 11 passengers on 371(16).
- Trains 381(15) and 382(15) operated without a food service car. Limited service recovery food items/beverages were available to passengers.

16JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(16-29) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(16-29) cancelled, with alternate transportation between St. Louis and Chicago.

28JUL25: Due to the high shop counts in Chicago, additional adjustments to Lincoln Service as follows:

- Trains 301(30Jul-04Aug) cancelled, with alternate transportation between Chicago, IL and St. Louis, MO.
- Trains 306(30Jul-04Aug) cancelled, with alternate transportation between St. Louis, MO and Chicago, IL.
- Trains 381(05Aug-13Aug) cancelled, with alternate transportation between Chicago, IL and Quincy, IL.
- Trains 382(05Aug-13Aug) cancelled, with alternate transportation between Quincy, IL and Chicago, IL.

WBS#: B.TR.100150.5774

Train	Delay	Comment
301(15)	Cancelled, with alt	CHI-STL
302(15)	Cancelled, with alt	STL-CHI
307(14)	Cancelled, with alt	CHI-STL
301(16Jul-04Aug)	Cancelled, with alt	CHI-STL
306(16Jul-04Aug)	Cancelled, with alt	STL-CHI
381(05Aug-13Aug)	Cancelled, with alt	CHI-QCY
382(05Aug-13Aug)	Cancelled, with alt	QCY-CHI

Maintenance of Way Highlights

UPRR Santa Barbara Subdivision North of Santa Barbara, CA - M of W Work

31JUL25: As a result of scheduled bridge work Thursday July 31, 2025 through Saturday August 16, 2025 at MP 305/UPRR Santa Barbara Subdivision, 62.4 miles north of Santa Barbara, the following service changes will occur on the Coast Starlight and Pacific Surfliner services:

COAST STARLIGHT

- Train 11 (31Jul-15Aug), which normally operates between SEA and LAX, will terminate at EMY.
- Train 14 (1Aug-16Aug), which normally operates between LAX and SEA, will originate at EMY.
- Alternate transportation will be provided between SAC and LAX via San Joaquin service for Train 11 (31Jul-15Aug).
- Alternate transportation will be provided between LAX and MTZ via San Joaquin service for Train 14 (1Aug-16Aug).

PACIFIC SURFLINER

Southbound:

- Train 774 (1Aug-16Aug), which normally operates between SLO and SAN, will Originate at GTA.
- Train 794 (1Aug-16Aug), which normally operates between SLO and SAN, will Originate at GTA.

Northbound:

- Train 761 (1Aug-16Aug), which normally operates between SAN and SLO, will Terminate at GTA.
- Train 779 (31Jul-16Aug), which normally operates between SAN and SLO, will Terminate at GTA.
- Alternate transportation will be handled via the Rt. 17 Buses. Additional buses will be provided for connections between SLO and SBA for Trains 761, 794, 774, and 779.

Work Element WBS # B.TR.100150.5840

WBS#: B.TR.100150.5840

CPKC C&M Subdivision - Trackwork

21JUL25: CPKC has a tie replacement project scheduled on the C&M Subdivision between Tower A20/MP20.5 and Rondout/MP32.3 starting July 21st through August 24th. To accommodate the above outlined infrastructure work, Amtrak's Hiawatha Service is adjusted as follows:

- Train 329 (21Jul-25Jul, 28Jul1Aug, 4Aug-8Aug, 11Aug-15Aug, 18Aug-22Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 7:49am.
- Train 331 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 10:04am.
- Train 335 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 2:44pm.
- Train 337 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 4:54pm.
- Train 339 (21Jul-24Aug) will have 10-minutes of recovery added at Milwaukee, arriving at 6:55pm.
- Train 330 (21Jul-26Jul, 28Jul-2Aug, 4Aug-9Aug, 11Aug-16Aug, 18Aug-23Aug) will have 10-minutes of recovery added at Chicago, arriving at 8:07am.
- Train 332 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 9:44am.
- Train 334 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 12:39pm.
- Train 336 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 2:44pm
- Train 338 (21Jul-24Aug) will have 10-minutes of recovery added at Chicago, arriving at 4:39pm

WBS#: B.TR.100150.5875

CPKC Track Work West of Winona, MN - Borealis Schedule Adjustments

15JUL25: CPKC will perform tie replacement and surfacing work on the River Subdivision west of Winona, MN/MP308 between MP320 and MP372. The work will take place Monday July 21st through Saturday August 30th. To accommodate this project, Amtrak's Borealis Service adjusted as follows:

- Train 1333(21JUL-30AUG) will have 15-minutes of recovery added at St. Paul-Minneapolis, MN, arriving at 656PM-CT.
- Train 1340(21JUL-30AUG) will depart St. Paul-Minneapolis, MN, 15-minutes earlier at 1134AM-CT, depart Winona 10-minutes earlier at 131PM-CT, depart La Crosse, WI 5-minutes earlier at 212PM-CT and depart Milwaukee at normal time 544PM-CT.

WBS#: B.TR.100150.5886

Western Region

Major Maintenance of Way Projects

Start	End	Carrier	Between	Type of Work	Route	Service Impact
None						

Train Consist Deviations

Train	Over/Under Coach	Service Blanked	Service Substituted	Customer Impact
None				

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
500	TUK	1	SEA	N/A
518	STW	1	EVR	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 5(30) Passenger Removal at Hastings, Nebraska – Refusal to Pay

31JUL25, Passenger on PNR 4E19A5, traveling from Galesburg, IL to Osceola, IA was discovered smoking in the lower-level lounge area. Passenger unable to provide a ticket for travel Osceola, IA to Denver, CO. Passenger was removed at Hastings, NE by local Police, Amtrak Police notified.

Delay: 5 (30) 3"

Train 6(31) Passenger Removal at Martinez, California – Improper Conduct

31JUL25, Passenger on PNR 4CE421, traveling from Emeryville, CA to Colfax, CA was removed from the train due to service animal biting another passenger. Amtrak Police notified.

Delay: 6 (31) None

Train 3(30) Passenger Removal at Raton, New Mexico – Improper Conduct

31JUL25, Passenger on PNR 4D14E1, traveling from Galesburg, IL to Las Angelas, CA was removed from the train by Raton PD. The passenger was yelling, cursing and threatening other passengers on board. Amtrak Police notified.

Delay: 3 (30) 8"

Train 5(31) Passenger Removal at Ottumwa, Iowa – Intoxication

31JUL25, Passenger on PNR 4C41E8, traveling from Galesburg, IL to Denver, CO was removed from the train for being intoxicated. The passenger was laying on the floor and taking up passengers' seat next to him. The conductor couldn't wake passenger. Amtrak Police notified.

Delay: 5 (31) None

Train 22(31) Passenger Removal at Longview, Texas –Improper Conduct

31JUL25, Passenger on PNR 4E1F49, traveling from San Marcos, TX to Bloomington-Normal, IL was removed from the train because the passenger had a service animal that was uncontrolled. The pet was growling and ready to attack the conductor. Amtrak Police notified.

Delay: 22 (31) 6"

Train 5(31) Passenger Removal at Naperville, Illinois –Medical

31JUL25, Passenger on PNR 4F8486, traveling from Chicago, IL to Burlington, IA was removed from the train because the passenger was found unresponsive. Amtrak Police notified.

Delay: 5 (31) None

Information Management
Mechanical Arrival Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/31/25										
		Day			Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	294	22	93%	8,840	821	91%	87,610	6,854	92%
Northeast Corridor	98%	79	7	91%	2,335	321	86%	23,520	2,562	89%
Acela	98%	23	3	87%	643	109	83%	6,558	879	87%
Northeast Regional	98%	56	4	93%	1,692	212	87%	16,962	1,683	90%
State Supported	98%	188	8	96%	5,654	325	94%	55,078	2,838	95%
Long Distance	98%	27	7	74%	851	175	79%	8,874	1,448	84%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Arrival Performance by Service

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible En-Route Delay

Mechanical Arrival Performance through 7/31/25

Service	Target	Day			Month to Date			Year to Date		
		Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay	Trains Operated	Trains Incurring Mech Delay	% Trains w/o Mech Delay
Amtrak System	98%	294	22	93%	8,840	821	91%	87,610	6,854	92%
Northeast Corridor	98%	79	7	91%	2,335	321	86%	23,520	2,562	89%
Acela	98%	23	3	87%	643	109	83%	6,558	879	87%
Northeast Regional	98%	56	4	93%	1,692	212	87%	16,962	1,683	90%
On Spine Northeast Regional	98%	27	1	96%	866	111	87%	8,600	893	90%
Richmond / Newport News / Norfolk	98%	12	2	83%	363	79	78%	3,543	545	85%
Roanoke	98%	4	-	100%	124	16	87%	1,210	166	86%
Springfield Shuttles	98%	13	1	92%	339	6	98%	3,609	79	98%
State Supported	98%	188	8	96%	5,654	325	94%	55,078	2,838	95%
Borealis	98%	2	-	100%	62	6	90%	593	65	89%
Capitol Corridor	98%	28	-	100%	812	32	96%	7,272	167	98%
Carolinian	98%	2	-	100%	62	10	84%	608	52	91%
Cascades	98%	14	-	100%	434	22	95%	4,135	290	93%
Downeaster	98%	10	-	100%	306	2	99%	2,894	46	98%
Empire	98%	20	2	90%	620	43	93%	6,506	343	95%
Adirondack	98%	2	-	100%	62	2	97%	608	43	93%
Berkshire Flyer	98%	-	-	100%	12	2	83%	18	4	78%
Ethan Allen Express	98%	2	-	100%	62	6	90%	608	40	93%
Maple Leaf	98%	2	-	100%	62	5	92%	608	59	90%
New York - Albany	98%	10	1	90%	298	13	96%	3,449	100	97%
New York - Niagara Falls	98%	4	1	75%	124	15	88%	1,215	97	92%
Heartland Flyer	98%	2	-	100%	58	1	98%	600	17	97%
Hiawatha	98%	12	1	92%	361	15	96%	3,474	130	96%
Illinois	98%	9	-	100%	388	36	91%	4,155	292	93%
Carl Sandburg / Illinois Zephyr	98%	4	-	100%	124	4	97%	1,204	47	96%
Illini / Saluki	98%	2	-	100%	120	11	91%	1,200	47	96%
Lincoln Service	98%	3	-	100%	144	21	85%	1,751	198	89%
Keystone	98%	27	1	96%	640	47	93%	6,955	435	94%
Lincoln / Missouri	98%	2	-	100%	62	12	81%	602	87	86%
Michigan	98%	10	1	90%	305	28	91%	2,909	282	90%
Blue Water	98%	2	-	100%	62	6	90%	604	88	85%
Pere Marquette	98%	2	-	100%	60	2	97%	606	27	96%
Wolverine	98%	6	1	83%	183	20	89%	1,699	167	90%
Missouri	98%	2	-	100%	60	1	98%	586	15	97%
Pacific Surfliner	98%	24	2	92%	744	21	97%	6,522	243	96%
Pennsylvanian	98%	2	-	100%	62	14	77%	608	74	88%
Piedmont	98%	8	-	100%	247	2	99%	2,416	34	99%
San Joaquins	98%	12	1	92%	369	25	93%	3,635	206	94%
Vermonter	98%	2	-	100%	62	8	87%	608	60	90%
Long Distance	98%	27	7	74%	851	175	79%	8,874	1,448	84%
Auto Train	98%	2	-	100%	62	8	87%	596	101	83%
California Zephyr	98%	2	1	50%	62	22	65%	605	144	76%
Capitol Ltd	98%	-	-	100%	-	-	100%	83	12	86%
Cardinal	98%	1	-	100%	26	10	62%	258	54	79%
City Of New Orleans	98%	2	1	50%	62	9	85%	594	55	91%
Coast Starlight	98%	2	1	50%	64	5	92%	611	90	85%
Crescent	98%	2	-	100%	62	6	90%	608	70	88%
Empire Builder	98%	4	-	100%	119	18	85%	1,170	151	87%
Floridian	98%	2	1	50%	60	18	70%	517	179	65%
Lake Shore Ltd	98%	2	-	100%	62	17	73%	1,006	118	88%
Palmetto	98%	2	-	100%	62	5	92%	606	39	94%
Silver Meteor	98%	2	1	50%	60	16	73%	602	124	79%
Silver Star	98%	-	-	100%	-	-	100%	78	13	83%
Southwest Chief	98%	2	1	50%	62	19	69%	606	156	74%
Sunset Ltd	98%	-	-	100%	26	7	73%	256	46	82%
Texas Eagle	98%	2	1	50%	62	15	76%	678	96	86%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	6	96%
Winter Park Express	98%	-	-	100%	-	-	100%	138	6	96%

By arrival date. Mechanical responsible en-route delays include CAR, CCR, ENG, & MTI. Mechanical en-route delays are included if they exceed 50% of end point tolerance. End point tolerances are between 10 and 30 minutes by service.

Information Management
Mechanical Initial Terminal Performance

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/31/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	10	97%	8,959	269	97%	87,739	2,142	98%
Northeast Corridor	98%	80	2	98%	2,335	69	97%	23,472	668	97%
Acela	98%	23	-	100%	643	15	98%	6,560	171	97%
Northeast Regional	98%	57	2	96%	1,692	54	97%	16,912	497	97%
State Supported	98%	188	6	97%	5,739	110	98%	55,147	930	98%
Long Distance	98%	28	2	93%	885	90	90%	8,982	542	94%
Seasonal Trains	98%	-	-	100%	-	-	100%	138	2	99%
Winter Park Express	98%	-	-	100%	-	-	100%	138	2	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Division

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/31/25											
Day					Month to Date			Year to Date			
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM		Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	10	97%		8,959	269	97%	87,739	2,142	98%
Central Division	98%	63	4	94%		2,027	105	95%	20,066	712	96%
Northeast Division	98%	96	4	96%		2,846	72	97%	28,862	687	98%
Southeast Division	98%	67	-	100%		1,965	57	97%	19,396	465	98%
Southwest Division	98%	70	2	97%		2,121	35	98%	19,415	278	99%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only										
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays										
Mechanical Initial Terminal Delay through 7/31/25										
Day					Month to Date			Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	10	97%	8,959	269	97%	87,739	2,142	98%
Central Division	98%	63	4	94%	2,027	105	95%	20,066	712	96%
ARB	98%	-	-	100%	-	-	100%	1	-	100%
BNL	98%	-	-	100%	-	-	100%	3	1	67%
BTL	98%	-	-	100%	-	-	100%	4	-	100%
CDL	98%	1	-	100%	64	1	98%	607	3	100%
CEN	98%	-	-	100%	-	-	100%	1	-	100%
CHI	98%	26	4	85%	818	75	91%	8,094	462	94%
CHM	98%	-	-	100%	-	-	100%	3	1	67%
DEN	98%	-	-	100%	-	-	100%	69	1	99%
EUG	98%	2	-	100%	62	2	97%	586	5	99%
EVR	98%	-	-	100%	-	-	100%	2	-	100%
GBB	98%	-	-	100%	2	-	100%	11	-	100%
GRR	98%	1	-	100%	30	-	100%	303	1	100%
IND	98%	-	-	100%	-	-	100%	4	-	100%
KCY	98%	2	-	100%	61	-	100%	590	5	99%
KFS	98%	-	-	100%	1	-	100%	2	-	100%
MEM	98%	-	-	100%	-	-	100%	2	-	100%
MHL	98%	-	-	100%	-	-	100%	33	1	97%
MKE	98%	6	-	100%	181	5	97%	1,744	14	99%
MSP	98%	1	-	100%	31	1	97%	292	7	98%
PDX	98%	5	-	100%	151	2	99%	1,463	37	97%
PNT	98%	3	-	100%	91	2	98%	838	9	99%
PTH	98%	1	-	100%	31	-	100%	302	6	98%
QCY	98%	2	-	100%	60	-	100%	590	8	99%
SBY	98%	-	-	100%	-	-	100%	2	-	100%
SEA	98%	8	-	100%	249	14	94%	2,376	127	95%
SPK	98%	1	-	100%	31	-	100%	312	2	99%
STL	98%	2	-	100%	101	3	97%	1,178	19	98%
TOL	98%	-	-	100%	1	-	100%	2	-	100%
VAC	98%	2	-	100%	62	-	100%	583	2	100%
WIP	98%	-	-	100%	-	-	100%	69	1	99%
Northeast Division	98%	96	4	96%	2,846	72	97%	28,862	687	98%
ALB	98%	7	-	100%	217	1	100%	2,126	26	99%
BON	98%	5	-	100%	153	-	100%	1,417	3	100%
BOS	98%	17	1	94%	542	11	98%	5,659	134	98%
BRK	98%	5	-	100%	99	1	99%	1,360	11	99%
BRP	98%	-	-	100%	1	-	100%	1	-	100%
BTN	98%	1	-	100%	31	-	100%	302	2	99%
DHM	98%	-	-	100%	-	-	100%	2	-	100%
DOV	98%	-	-	100%	-	-	100%	9	-	100%
EXR	98%	-	-	100%	-	-	100%	9	-	100%
GFD	98%	2	-	100%	55	-	100%	582	-	100%
HFD	98%	2	-	100%	44	-	100%	190	-	100%
HHL	98%	-	-	100%	-	-	100%	2	-	100%
MTR	98%	1	-	100%	31	2	94%	302	7	98%
NFL	98%	2	-	100%	62	-	100%	608	7	99%
NHT	98%	-	-	100%	3	-	100%	5	-	100%
NHV	98%	6	-	100%	146	-	100%	1,553	35	98%
NYP	98%	41	2	95%	1,194	55	95%	12,188	440	96%
POR	98%	-	-	100%	51	-	100%	51	-	100%
RUD	98%	-	-	100%	-	-	100%	1	-	100%
SAB	98%	1	-	100%	29	-	100%	300	1	100%
SPG	98%	5	1	80%	154	2	99%	1,850	21	99%
TWO	98%	1	-	100%	31	-	100%	301	-	100%
WEM	98%	-	-	100%	3	-	100%	44	-	100%
Southeast Division	98%	67	-	100%	1,965	57	97%	19,396	465	98%
ATL	98%	-	-	100%	-	-	100%	33	-	100%
CLT	98%	5	-	100%	151	1	99%	1,505	7	100%

Information Management
Mechanical Initial Terminal Performance by Terminal

Confidential - Internal Use Only
Trains Incurring Mechanical Responsible Initial Terminal (ITM) Delays

Mechanical Initial Terminal Delay through 7/31/25										
Day				Month to Date				Year to Date		
Service	Target	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM	Trains Operated	Trains Incurring ITM	% Trains w/o ITM
Amtrak System	98%	296	10	97%	8,959	269	97%	87,739	2,142	98%
Southeast Division	98%	67	-	100%	1,965	57	97%	19,396	465	98%
DNC	98%	-	-	100%	1	-	100%	1	-	100%
GRO	98%	-	-	100%	10	-	100%	10	-	100%
HAR	98%	13	-	100%	348	3	99%	3,294	23	99%
JAX	98%	-	-	100%	-	-	100%	17	-	100%
LNC	98%	-	-	100%	-	-	100%	92	2	98%
LOR	98%	1	-	100%	31	2	94%	298	13	96%
MIA	98%	2	-	100%	59	6	90%	584	34	94%
NFK	98%	3	-	100%	88	2	98%	838	5	99%
NOL	98%	2	-	100%	70	1	99%	677	21	97%
NPN	98%	2	-	100%	62	1	98%	581	4	99%
PGH	98%	1	-	100%	31	1	97%	303	4	99%
PHL	98%	5	-	100%	134	7	95%	1,300	40	97%
RGH	98%	4	-	100%	116	-	100%	1,219	5	100%
RNK	98%	2	-	100%	57	-	100%	574	8	99%
RVM	98%	1	-	100%	31	-	100%	295	1	100%
RVR	98%	-	-	100%	-	-	100%	1	-	100%
SAV	98%	1	-	100%	29	1	97%	285	1	100%
SFA	98%	1	-	100%	31	-	100%	298	18	94%
WAS	98%	24	-	100%	716	32	96%	7,191	279	96%
Southwest Division	98%	70	2	97%	2,121	35	98%	19,415	278	99%
ABQ	98%	-	-	100%	-	-	100%	3	-	100%
ARN	98%	1	-	100%	31	-	100%	304	-	100%
BFD	98%	6	-	100%	183	-	100%	1,806	23	99%
DAL	98%	-	-	100%	-	-	100%	2	-	100%
EMY	98%	1	-	100%	31	4	87%	311	24	92%
FMT	98%	-	-	100%	-	-	100%	1	-	100%
FNO	98%	-	-	100%	-	-	100%	7	-	100%
FTW	98%	1	-	100%	30	-	100%	336	5	99%
FUL	98%	-	-	100%	-	-	100%	12	-	100%
GLE	98%	-	-	100%	-	-	100%	4	-	100%
GLP	98%	-	-	100%	-	-	100%	1	-	100%
GTA	98%	3	-	100%	93	-	100%	889	11	99%
IRV	98%	-	-	100%	-	-	100%	87	-	100%
LAX	98%	9	1	89%	292	6	98%	2,351	68	97%
MPK	98%	-	-	100%	-	-	100%	6	-	100%
OKC	98%	1	-	100%	28	-	100%	299	-	100%
OKJ	98%	12	1	92%	344	16	95%	3,197	77	98%
OSD	98%	-	-	100%	-	-	100%	188	1	99%
RNO	98%	-	-	100%	1	-	100%	1	-	100%
SAC	98%	14	-	100%	407	3	99%	3,638	15	100%
SAN	98%	12	-	100%	366	5	99%	2,788	27	99%
SAS	98%	1	-	100%	31	1	97%	300	3	99%
SJC	98%	7	-	100%	216	-	100%	1,956	12	99%
SKN	98%	-	-	100%	-	-	100%	1	-	100%
SLO	98%	2	-	100%	62	-	100%	595	5	99%
SNC	98%	-	-	100%	-	-	100%	279	6	98%
SOL	98%	-	-	100%	6	-	100%	53	1	98%

Mechanical responsible initial terminal delays include CAR, CCR, & ENG. Tolerance = 3 minutes.
Report calculates based on scheduled departure date.

CNOC Daily Mechanical Delays >3 Minutes Report

INCIDENT_DATE 7/31/2025 12:00..	Diesel Locomotive		Amfleet I	High Speed Trainset		Cab Car		Viewliner I	California Cars (Cal..	Superliner I	Caltrans Locomotive	Electric Locomotive..	Grand Total
	ENG	CAR	CAR	ENG	CAR	ENG	CCR	CAR	CCR	CAR	ENG	ENG	
Blower Problems	253												253
I-ETMS Problem	106						5						111
Door Problems	5		33		19								57
ACES Failure	15					28						4	47
Auxiliary Faults	39												39
HEP Problems									22		12		34
Tilt System Problem..				16	16								32
Dragging/Loose E..			30										30
Toilets Inoperative										16			16
Traction Motor Pro..	9											7	16
Air Hose Parted								15					15
Electrical Problems		13											13
Water Problems								11					11
Loading Problems	10												10
Engine Dead/Shut ..	9												9
Air/Brake Problems					8								8
ATS - Automatic T..	7												7
Car Hot: Air Condi..			7										7
Truck Problems				5									5
Grand Total	453	13	70	21	43	28	5	26	22	16	12	11	720