CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 02, 2026 Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

27-FOI-00044

Scheduled Departure Date: **10/01/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/01/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System		327	36	89.0%	327	36	89.0%	327	36	89.0%
Central Division	-	59	2	96.6%	59	2	96.6%	59	2	96.6%
East Division		178	20	88.8%	178	20	88.8%	178	20	88.8%
West Division		90	14	84.4%	90	14	84.4%	90	14	84.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/1/26

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**105,117**	**23,210**	**78%**	**105,117**	**23,210**	**78%**	**105,117**	**23,210**	**78%**
Northeast Corridor	***81%***	***48,426***	***5,856***	***88%***	***48,426***	***5,856***	***88%***	***48,426***	***5,856***	***88%***
Acela	83%	11,713	1,654	86%	11,713	1,654	86%	11,713	1,654	86%
Northeast Regional	79%	36,713	4,202	89%	36,713	4,202	89%	36,713	4,202	89%
Richmond / Newport News / Norfolk	77%	9,545	2,010	79%	9,545	2,010	79%	9,545	2,010	79%
Springfield Shuttles	89%	905	79	91%	905	79	91%	905	79	91%
Roanoke	79%	3,529	124	96%	3,529	124	96%	3,529	124	96%
On Spine Northeast Regional	80%	22,734	1,989	91%	22,734	1,989	91%	22,734	1,989	91%
State Supported	***80%***	***46,286***	***11,407***	***75%***	***46,286***	***11,407***	***75%***	***46,286***	***11,407***	***75%***
Borealis	80%	574	0	100%	574	0	100%	574	0	100%
Capitol Corridor	90%	4,315	898	79%	4,315	898	79%	4,315	898	79%
Carolinian	70%	1,098	294	73%	1,098	294	73%	1,098	294	73%
Cascades	75%	2,390	356	85%	2,390	356	85%	2,390	356	85%
Downeaster	82%	1,708	1,236	28%	1,708	1,236	28%	1,708	1,236	28%
Empire	78%	6,182	1,386	78%	6,182	1,386	78%	6,182	1,386	78%
Adirondack	72%	367	0	100%	367	0	100%	367	0	100%
Ethan Allen Express	70%	582	204	65%	582	204	65%	582	204	65%
Maple Leaf	70%	769	177	77%	769	177	77%	769	177	77%
New York - Albany	85%	3,150	571	82%	3,150	571	82%	3,150	571	82%
New York - Niagara Falls	75%	1,314	434	67%	1,314	434	67%	1,314	434	67%
Gold Runner	73%	2,640	815	69%	2,640	815	69%	2,640	815	69%
Heartland Flyer	70%	132	132	0%	132	132	0%	132	132	0%
Hiawatha	90%	1,746	0	100%	1,746	0	100%	1,746	0	100%
Illinois	78%	2,202	587	73%	2,202	587	73%	2,202	587	73%
Carl Sandburg / Illinois Zephyr	85%	330	73	78%	330	73	78%	330	73	78%
Illini / Saluki	85%	687	0	100%	687	0	100%	687	0	100%
Lincoln Service	70%	1,185	514	57%	1,185	514	57%	1,185	514	57%
Keystone	92%	9,969	1,130	89%	9,969	1,130	89%	9,969	1,130	89%
Lincoln / Missouri	70%	753	650	14%	753	650	14%	753	650	14%
Mardi Gras Service	80%	256	0	100%	256	0	100%	256	0	100%
Michigan	70%	2,069	385	81%	2,069	385	81%	2,069	385	81%
Blue Water	70%	462	203	56%	462	203	56%	462	203	56%
Pere Marquette	85%	276	0	100%	276	0	100%	276	0	100%
Wolverine	70%	1,331	182	86%	1,331	182	86%	1,331	182	86%
Missouri	80%	159	0	100%	159	0	100%	159	0	100%
Pacific Surfliner	85%	7,236	2,552	65%	7,236	2,552	65%	7,236	2,552	65%
Pennsylvanian	80%	944	250	74%	944	250	74%	944	250	74%
Piedmont	80%	529	92	83%	529	92	83%	529	92	83%
Vermonter	75%	1,384	644	53%	1,384	644	53%	1,384	644	53%
Long Distance	***70%***	***10,405***	***5,947***	***43%***	***10,405***	***5,947***	***43%***	***10,405***	***5,947***	***43%***
Auto Train	70%	680	432	36%	680	432	36%	680	432	36%
California Zephyr	70%	737	243	67%	737	243	67%	737	243	67%
Cardinal	70%	532	451	15%	532	451	15%	532	451	15%
City Of New Orleans	75%	544	465	15%	544	465	15%	544	465	15%
Coast Starlight	70%	991	56	94%	991	56	94%	991	56	94%
Crescent	70%	798	228	71%	798	228	71%	798	228	71%
Empire Builder	70%	399	303	24%	399	303	24%	399	303	24%
Floridian	60%	1,226	884	28%	1,226	884	28%	1,226	884	28%
Lake Shore Ltd	73%	999	358	64%	999	358	64%	999	358	64%
Palmetto	70%	696	136	80%	696	136	80%	696	136	80%
Silver Meteor	70%	744	671	10%	744	671	10%	744	671	10%
Southwest Chief	60%	793	793	0%	793	793	0%	793	793	0%
Texas Eagle	70%	1,266	927	27%	1,266	927	27%	1,266	927	27%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00048 00000000058 "UNCLASSIFIED" 10/10/2026~~

Train Index Dates Through October 01, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	4,514	109,453	412	4,514	109,453	412

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	121	35,590	34	121	35,590	34
INFRASTRUCTURE PLANNED	135	567	35,590	159	567	35,590	159
FLEET RELIABILITY	90	574	109,453	52	574	109,453	52
TRAIN OPERATIONS	424	3,252	109,453	297	3,252	109,453	297

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

27-FOI-00044

Scheduled Departure Date: **10/01/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/01/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System		327	36	89.0%	327	36	89.0%	327	36	89.0%
Central Division	-	59	2	96.6%	59	2	96.6%	59	2	96.6%
East Division		178	20	88.8%	178	20	88.8%	178	20	88.8%
West Division		90	14	84.4%	90	14	84.4%	90	14	84.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/01/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/01/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System		327	36	89.0%	327	36	89.0%	327	36	89.0%
Central Division	-	59	2	96.6%	59	2	96.6%	59	2	96.6%
CDL	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
CHI	-	28	1	96.4%	28	1	96.4%	28	1	96.4%
FTW	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
GRR	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
KCY	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
MKE	-	6	0	100.0%	6	0	100.0%	6	0	100.0%
MOE	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
MSP	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
NOL	-	4	1	75.0%	4	1	75.0%	4	1	75.0%
OKC	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
PNT	-	3	0	100.0%	3	0	100.0%	3	0	100.0%
PTH	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
QCY	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
SAS	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
STL	-	4	0	100.0%	4	0	100.0%	4	0	100.0%
East Division		178	20	88.8%	178	20	88.8%	178	20	88.8%
ALB		8	0	100.0%	8	0	100.0%	8	0	100.0%
BON	-	5	0	100.0%	5	0	100.0%	5	0	100.0%
BOS	-	19	0	100.0%	19	0	100.0%	19	0	100.0%
BRK	-	5	1	80.0%	5	1	80.0%	5	1	80.0%
BTN	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
CLT	-	4	1	75.0%	4	1	75.0%	4	1	75.0%
GFD	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
GRO	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
HAR	-	13	3	76.9%	13	3	76.9%	13	3	76.9%
HFD	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
LOR	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
MIA	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
MTR	-	1	1	0.0%	1	1	0.0%	1	1	0.0%
NFK	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
NFL	-	2	1	50.0%	2	1	50.0%	2	1	50.0%
NHV	-	5	1	80.0%	5	1	80.0%	5	1	80.0%
NPN	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
NYP	-	51	6	88.2%	51	6	88.2%	51	6	88.2%
PGH	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
PHL	-	5	3	40.0%	5	3	40.0%	5	3	40.0%
RGH	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
RNK	-	2	1	50.0%	2	1	50.0%	2	1	50.0%
SAB	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
SAV	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
SFA	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
SPG	-	5	0	100.0%	5	0	100.0%	5	0	100.0%
TWO	-	1	1	0.0%	1	1	0.0%	1	1	0.0%

Information Management

27-FOI-00044

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/01/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/01/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System		327	36	89.0%	327	36	89.0%	327	36	89.0%
East Division		178	20	88.8%	178	20	88.8%	178	20	88.8%
WAS	-	33	1	97.0%	33	1	97.0%	33	1	97.0%
West Division		90	14	84.4%	90	14	84.4%	90	14	84.4%
ARN	-	1	0	100.0%	1	0	100.0%	1	0	100.0%
BFD	-	7	2	71.4%	7	2	71.4%	7	2	71.4%
EMY	-	1	1	0.0%	1	1	0.0%	1	1	0.0%
EUG	-	2	0	100.0%	2	0	100.0%	2	0	100.0%
GTA	-	3	1	66.7%	3	1	66.7%	3	1	66.7%
LAX	-	10	1	90.0%	10	1	90.0%	10	1	90.0%
OKJ	-	13	2	84.6%	13	2	84.6%	13	2	84.6%
PDX	-	4	0	100.0%	4	0	100.0%	4	0	100.0%
SAC	-	16	2	87.5%	16	2	87.5%	16	2	87.5%
SAN	-	13	1	92.3%	13	1	92.3%	13	1	92.3%
SEA	-	7	0	100.0%	7	0	100.0%	7	0	100.0%
SJC	-	7	4	42.9%	7	4	42.9%	7	4	42.9%
SLO	-	3	0	100.0%	3	0	100.0%	3	0	100.0%
SPK		1	-	100.0%	1	-	100.0%	1	-	100.0%
VAC	-	2	0	100.0%	2	0	100.0%	2	0	100.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	109	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
4	300	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
5		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
6	471	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
7	692	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
8	525			0.0%			0.0%	1	1	0.0%	1	1	0.0%
11		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
14		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
19		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
20		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
21		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
22	55	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
23		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
24		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
25		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
26		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
27	704	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
28				0.0%			0.0%	1	0	100.0%	1	0	100.0%
40	128	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
41	319	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
42	18	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
43		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
48		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
49		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
51	66			0.0%			0.0%	1	1	0.0%	1	1	0.0%
52		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
53	52	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
55	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
56		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
58	113	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
59	87	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
63	67	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
64		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
66		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
67		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
68		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
69		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
71		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
72		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
75		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
76		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
77	16	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
79	34	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
80		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
84		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
85		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
86		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
89		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
90		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
93		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
94		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
95		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
97	133	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
98	70	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
110		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
111		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
112		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
113		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
119		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
125	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
129		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
130		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
131	90	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
134		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
136		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
137		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
138		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
141		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
148		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
151		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
170		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
171		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
172		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
173		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
174		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
175		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
176		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
177		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
178		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
179		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
181		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
182		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
183		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
185		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
186		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
190		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
192		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
193		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
196		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
197		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
198		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
230		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
232		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
233		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
234		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
235	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
236		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
237		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
238		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
239		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
240		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
241	50	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
243		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
244		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
245		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
280	30	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
281		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
283		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
284		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
290		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
291		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
300		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
301	33	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
302		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
305	38	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
306		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
307		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
311		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
316		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
318	48	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
319	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
329		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
330		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
331		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
334		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
335		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
336		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
337		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
338		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
339		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
341		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
342		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
350		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
351		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
352	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
353		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
354		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
355		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
364	20	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
365		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
370		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
371		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
380		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
381	16	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
382	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
383		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
390		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
391		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
392		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
393		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
417		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
425		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
448		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
449		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
470		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
471		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
473		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
474		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
475		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
478		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
479		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
486		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
494		2	2	0.0%	2	2	0.0%	1	0	100.0%	1	0	100.0%
495		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
500		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
503		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
504	37	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
505		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
506		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
507		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
508		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
509		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
511		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
516	52	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
517		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
518		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
519		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
520		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
521		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
522		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
523		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
524		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
525		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
526		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
527		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
528		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
529		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
530		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
531		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
532		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
534		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
535		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
536		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
537		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
538	35	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
539	77	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
540		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
541		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
542		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
543	27	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
544	36	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
545		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
547		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
548		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
549		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
550	75	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%

Amtrak On Time Performance

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
551		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
562		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
564	34	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
566		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
567		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
572	61	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
573	16	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
579		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
580		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
581	28	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
584	36	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
587	18	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
588		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
591	24	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
593		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
595		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
600		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
601		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
605	22	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
607		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
609		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
622		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
626		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
639		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
640		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
641		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
642		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
643		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
644		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
645		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
646	42	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
647		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
648		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
649		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
650		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
651	20	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
652		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
653		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
654		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
655	24	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
656		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
657		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
658		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
680		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
681	23	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
682	44	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
683	40	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
684	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
685	40	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
686	28	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
687	17	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
688	17	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
689				0.0%			0.0%	1	0	100.0%	1	0	100.0%
701		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
702		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
703		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
704		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
710		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
711		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
712	16	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
713		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
714		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
715		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
716		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
717		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
718	273	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
719		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
757		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
761		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
765		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
769		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
770	19	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
774		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
777		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
782		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
785		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
786	22	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
790		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
794	21	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
821	221	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
822	130	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
1333		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
1340		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2102	Cncld	1	0	100.0%	1	0	100.0%			0.0%			0.0%

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/1/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2103		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2104		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2105		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2107		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2108		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2109		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2112		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2113	Cncld	1	1	0.0%	1	1	0.0%			0.0%			0.0%
2115		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2116		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2118		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2119		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2120		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2123		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2124		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2126		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2127		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2128		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2131		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
2150		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2151		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2152		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2154		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2155		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2156		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2158		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2159	39	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2160	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2162		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2163	22	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
2165		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2167		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2171		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2190		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2193		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak Endpoint OTP Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2102	NYP	Trn Cancelled	CTI	5	CTI	5	XNY-BAL	AM	Follow, marc, 9500, Milepost, 134.6, 127.0
2113	WAS	Trn Cancelled							
2159	WAS	39	ENG	14	ENG	14	NYP-NYP	AM	HEP, 2138, UNSPECIFIED MECHANICAL ISSUES
2160	BOS	26	DSR	47	DSR	42	STM-NHV	MN	Per bulletin Restricted speed cat pole 533 - 535, cp 241 - East Norwalk PSGR speed 15. Stop signal cp 261 due to possible debris from an early train., Milepost, 33.6, 72.1, 30, 2,4
2163	WAS	22	MBO	11	MBO	11	XSH-NYP	AM	For maritime traffic, Other, PELHAM BAY
125	NPN	26	POL	22	POL	22	ASD-RVR	CS	Right of Way police hold CFP 6.2
131	WAS	90	ENG	86	ENG	60	NYP-NWK	AM	HEP, 646, HEP PROBLEM ON ENG.646
53	SFA	52	FTI	105	FTI	35	XSE-XFL	CS	Meet 243, Milepost, 273.5, 275.5
79	CLT	34	SYS	34	DSR	19	BNC-GRO	NS	Per bulletin Milepost, 7.2, 5.7, 10, 1, Milepost, 5.7, 2.4, 25, 1, Milepost, .2, .01, 25, 1
605	HAR	22	ENG	26	ENG	26	PHL-ARD	AM	Air / Brake, 9644|CB|CC, INOPERABLE SPEEDOMETER
646	NYP	42	ENG	33	ENG	29	PHL-XHM	AM	Undesired emergency application, 9644|CB|CC, WYE OUTBOUND
651	HAR	20	SVS	15	SVS	15	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND
655	HAR	24	SVS	19	SVS	19	PHL-ARD	AM	Unplanned Wye, WYE ON THE OUTBOUND
681	BRK	23	DCS	14	DCS	14	DOV-WEM	CS	Power switch failure Switch off power. Permission past stop signal, Control Point, Rollinsford
682	BON	44	ENG	22	ENG	14	BRK-FRE	CS	Traction motor Traction motor 4 issues. C/O traction motor 4, 112
683	BRK	40	PTI	17	PTI	17	EXR-DHM	CS	Meet 684, Control Point, rockingham
684	BON	26	PTI	16	PTI	16	FRE-POR	CS	Meet amt 681, Control Point, Mountain
685	BRK	40	PTI	18	PTI	11	ORB-POR	CS	Meet amt 688, Control Point, Mountain
686	BON	28	PTI	18	PTI	18	ORB-SAO	CS	Meet Held for a 30m late 683 even though we were only 5m late, 683, Control Point, Surf
687	BRK	17	DCS	9	DCS	5	HHL-XP0	CS	PTC system failure (wayside) Clear on the wayside. I-ETMS shows stop, Control Point, SL

Amtrak Endpoint OTP Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
688	BON	17	FTI	11	FTI	9	POR-ORB	CS	Standing equipment on track 2 blocking the meet with 685 standing equipment, Control Point, mountain, standing
63	TWO	67	FTI	14	FTI	14	XSV-ROC	CS	Meet csx, Control Point, 359
235	ALB	19	CTI	20	CTI	13	CRT-POU	MN	Follow mn, Milepost, 39, 63
241	ALB	50	ENG	26	ENG	26	NYP-NYP	AM	Other electrical failure, 702|DX|DM, HELD IN STATION A/C WAITING FOR UPDATED PAPERWORK
280	NYP	30	DSR	24	DSR	9	XCP-POU	MN	Per bulletin Milepost, 75.0, 74.0, 10, 3
42	NYP	18	OTH	19	MTI	7	TRE-NWK	AM	Disabled train ahead, Other, metro park, CONGESTION AHD A/C AM184 WITH DOOR ISSUES AT METRO PARK
77	CLT	16	DSR	27	DSR	23	BNC-GRO	NS	Per bulletin Milepost, 7.2, 5.7, 10, mt, Milepost, 5.7, 2.4, 25, mt
97	MIA	133	RTE	114	RTE	90	SAV-SAV	CS	Dispatcher hold Other, SAV STA
98	NYP	70	FTI	112	FTI	37	FLO-XDI	CS	Meet #CSL243, #AM53, #CSI137, Control Point, WN
55	WAS	21	CTI	33	RTE	12	SPG-WNL	AM	Dispatcher hold, Milepost w/Letters, SPG, WNL, AM55 held on CSX side due to trk speed restriction
40	CHI	128	INJ	81	INJ	81	WAS-WAS	AM	Injured or sick passenger, EMS & APD REQUIRED TO ASSIST & REMOVE PAX FOR MEDICAL EMERGENCY
41	MIA	319	RTE	145	ENG	106	CHI-CHI	AM	Delayed delivery of equipment from Mechanical (not due to mechanical failure) 111
6	CHI	471	WTR	465	WTR	282	HAS-LNK	BN	Storm Siding, Denton
538	ARN	35	TEN	26	TEN	26	SJC-SJC	UP	Bad starter on Engine 920 Engine 920, C2102
539	SJC	77	CTI	23	CTI	23	FMT-GAC	UP	Meet ACE, 4, Siding, S.Albrae
543	SJC	27	CTI	20	CTI	20	GAC-SCC	UP	Meet Ace, Ace8, Control Point, CO044
544	SAC	36	DSR	8	DSR	2	GAC-FMT	UP	Per bulletin Milepost, 37, 36.75, 60, Main
550	SAC	75	ITI	91	ITI	91	SJC-SJC	UP	Late departure at initial terminal due to late arrival of inbound equipment 547
51	CHI	66	PTI	42	PTI	38	CVS-STA	BB	Meet amtk 50, Control Point, Afton
504	SEA	37	PTI	20	PTI	13	OLW-XNI	ST	Meet Amtk 517, Control Point, Nisqually

Amtrak Endpoint OTP Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
516	VAC	52	FTI	33	FTI	31	XF2-X1J	BN	Blocked from station track Control Point, Still Creek, Job 561
58	CHI	113	DSR	76	FTI	26	JAN-YAZ	CC	Meet GTW 5834 s, Control Point, n. jan yard
59	NOL	87	DSR	102	FTI	28	EFG-CEN	CC	Follow 271, Control Point, Kinmundy
7	SEA	692	FTI	849	FTI	733	MOT-MOT	BN	Hold due to freight derailment Milepost, 0.6, 2.5, BNSF ?E
8	CHI	525	FTI	585	FTI	264	STN-MOT	BN	Hold due to freight derailment Control Point, CP 189, BNSF unknown
27	PDX	-29	FTI	19	FTI	11	SPK-XPW	BN	Follow BNSF UNKNOWN, Control Point, Spokane St, Control Point, Cheney
821	FTW	221	WTR	231	WTR	113	GLE-FTW	BN	Flash flood warning Milepost, 411.3, 346
822	OKC	130	FTI	105	FTI	95	FTW-GLE	BN	Meet bnsf 6927 & 8365, Siding, Ponder
352	PNT	19	PTI	26	PTI	26	JXN-ARB	MI	Meet After completing station work and departing on time, train was requested to make a reverse move out of JXN to allow 355 to enter station. After 355 departed we were given the signal to head east., Amt 355, Control Point, CP75
364	PTH	20	DSR	29	DCS	13	XPI-XMC	AM	Issue with automatic road crossing protection Other, 235.59 N. 365E
564	SAN	34	CTI	30	CTI	14	SOL-OLT	SN	Meet coaster, Control Point, delmar
572	SAN	61	ITI	43	ITI	43	LAX-LAX	SC	Late departure at initial terminal due to late arrival of inbound equipment 770, Management swapped 572 and 770 equipment due to late 770. Had to wait for comet set from yard. Loading for 3 trains on a 5 car set.
573	LAX	16	FTI	20	FTI	13	OSD-X98	SC	Meet Bnsf 6535, Control Point, Songs
581	LAX	28	CTI	16	CTI	16	SOL-OSD	SN	Meet coaster, Control Point, swami
584	SAN	36	CTI	39	PTI	12	XRJ-FUL	BN	Wait for station track Amtk 4, Other, Station FUL
587	LAX	18	ADA	8	CTI	7	SOL-OSD	SN	Meet coaster, Control Point, swami
591	LAX	24	DSR	19	DCS	11	OSD-X98	SN	Wayside detector failure including false actuation Integrity failure main 2, detector 210.3. Stop and Inspect both sides of train., Other, mp210.3
770	SAN	19	ENG	35	ENG	29	SIM-SIM	SC	Loading problem C2116
786	SAN	22	DCS	28	PTI	12	GUA-LPS	UP	Meet 765, Siding, Tangier

Amtrak Endpoint OTP Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
794	SAN	21	PTI	36	POL	35	GUA-LPS	UP	Dispatcher hold Held for rocket launch, Control Point, 289
712	BFD	16	PTI	18	PTI	9	RIC-MTZ	UP	Meet 531, Control Point, Costa
718	BFD	273	TCC	105	TCC	105	EMY-EMY	UP	Whistle failure C8308, The train whistle failed in route. Mechanical boarding to work the issue., C8308
3	LAX	109	FTI	208	FTI	51	XIA-GLP	BN	Follow bnsf unknown, Milepost, 73.1, 94.2
4	CHI	300	FTI	357	FTI	86	FLG-WLO	BN	Follow BNSF 6681 E, Milepost, 340.8, 288.4
22	CHI	55	FTI	125	SVS	47	FTW-FTW	TE	Planned set out / pick out of locomotives, cars or section of train Other, FTW STATION
301	STL	33	FTI	43	FTI	26	XTF-XUD	CC	Cross Traffic wb bnsf, Control Point, corwith
305	STL	38	CAR	31	CAR	17	SMT-XUD	CC	Air / Brake / Wheel ID4009, Tail hose uncoupled
381	QCY	16	DCS	22	DCS	22	MAC-QCY	BN	Restrictive signal(s) from known wayside signal failure Stop/restricting, Control Point, west camp point
382	CHI	19	FTI	20	FTI	17	MAC-GBB	BN	Cross over or go around New Long 3 Restricted Speed, Control Point, Saluda, 5155, BNSF
318	CHI	48	DCS	28	PTI	15	SED-JEF	UP	Meet 311, Siding, dow
319	KCY	19	FTI	24	FTI	21	XTF-SMT	CC	Cross Traffic Unknown, Control Point, Corwith

Amtrak Initial Terminal Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/1/2026

Terminal	Train	Date	Late	Delay	Cause
NOL	20	10/01	18	18	PTC problem or failure (cause unknown) Engine 369 failed to initialize
BRK	682	10/01	8	8	Loading problem Engine would not load, 112
CLT	72	10/01	1		
HAR	622	10/01	1	1	Passenger and/or baggage
HAR	626	10/01	3	3	Re-crew / job briefing, ENGR ESTABLISHING COMMUNICATION WITH CNDR
HAR	654	10/01	1	1	Passenger and/or baggage
MTR	68	10/01	2	2	Air / Brake Brake test on account of low pressure on Engine, 105
NFL	280	10/01	6	6	Inability to contact dispatcher Stop signal cp 28. Unable to initially contact NG dispatcher to request signal., Control Point, cp 28
NHV	470	10/01	9	9	Dispatcher hold, Milepost, nhv, nhv, Late into the station platform
NHV	494	10/01	17	1	Hold for connecting train
NHV	494	10/01	17	16	Hold for connecting train, late connection of AM94
NHV	494	10/01	17	1	Hold for connecting train
NHV	494	10/01	17	16	Hold for connecting train, late connection of AM94
NYP	193	10/01	2	2	Passenger and/or baggage, BOARDING
NYP	241	10/01	26	26	Other electrical failure, 702|DX|DM, HELD IN STATION A/C WAITING FOR UPDATED PAPERWORK
NYP	291	10/01	7	7	Late departure at initial terminal due to late arrival of inbound equipment, 240, LATE TURN OFF AM240
NYP	655	10/01	11	11	On-train police or DEA activity, EMS ONBOARD FOR PSNGR
NYP	2113	10/01	(Trn Cxld)		Engine Issue
NYP	2131	10/01	2	2	Passenger and/or baggage, BOARDING
PHL	110	10/01	2	2	Passenger and/or baggage, PASSENGER DROPPED SOMETHING ON TRACKS
PHL	151	10/01	3	3	Lost time - N.A.R., train late out of yard
PHL	190	10/01	2	2	PTC - Stop Bypass Permission Required, Control Point, .
RNK	66	10/01	5	5	Air / Brake Engine unable to load properly. Mechanical called back to the train. Able to resolve the issue. Permission to line out at 4:14., 174
TWO	64	10/01	5		
WAS	2120	10/01	10	10	Disabled train ahead, Other, NYP, 2159 DELAYED DEPARTING OUT OF BOS DUE TO ISSUES WITH PANTOGRAPH
CHI	3	10/01	60	60	Cab signal failure 152
BFD	713	10/01	1	1	Door C9303, Door on A end would not respond to train line key operations.

Amtrak Initial Terminal Details

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/1/2026

Terminal	Train	Date	Late	Delay	Cause
BFD	715	10/01	5	2	Wheelchair wheelchairs working conductor only
BFD	715	10/01	5	3	Door C9806, Not getting a door light had to run cut out
EMY	6	10/01	1	1	Meet Amtk 527, Control Point, Emeryville
GTA	782	10/01	6	6	Wait for station track 14, Control Point, S ELLWOOD
LAX	572	10/01	43	43	Late departure at initial terminal due to late arrival of inbound equipment 770, Management swapped 572 and 770 equipment due to late 770. Had to wait for comet set from yard. Loading for 3 trains on a 5 car set.
OKJ	712	10/01	2	2	Other electrical failure Engineer could not get amp., 2124
OKJ	718	10/01	1		
SAC	539	10/01	1		
SAC	702	10/01	2	2	In cab car reverser in and forward and throttle in run one and locomotive still died. Had to restart. C2012
SAN	587	10/01	5	3	Wheelchair Due to single level equipment 2 pax in manual wheelchairs boarding in SAN requiring the wheelchair lift which wasn't on track 4.
SAN	587	10/01	5	2	Blocked from station track BNSF train passing through ash towards broadway, blocking pax walkway to track 4 where 587 was located., BNSF, Other, santa fe depot
SJC	538	10/01	26	26	Bad starter on Engine 920 Engine 920, C2102
SJC	542	10/01	14	14	Late departure at initial terminal due to late arrival of inbound equipment 539
SJC	544	10/01	50	50	Took over 543 equipment as soon as they arrived to SJC.
SJC	550	10/01	91	91	Late departure at initial terminal due to late arrival of inbound equipment 547

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100	100	94.8	342	0
CDOT	95.0	90.0	90.0	92.4	20	2
MARC	95.0	89.7	89.7	90.2	58	6
SEPTA	95.0	87.0	87.0	91.5	216	28
NJT-NED	95.0	96.4	96.4	88.6	362	13
NJT-SED	95.0	100	100	97.2	24	0

Operating Highlights

Train 98(01) North of Fayetteville, NC - Freight Train Interference

02OCT26: Train 98(01) operating with engines 83, 371, and 210 customers onboard was delayed 5 miles north of Fayetteville, NC on the CSX North End subdivision meeting CSX freight at milepost 204.5.

Train	Delay	Comment
98(01)	38"	

Train 53(01) Selma, NC - Freight Train Interference

01OCT26: Train 53(01) operating with engines 352, 360, and 420 customers onboard was delayed holding at Selma, NC on the CSX South End subdivision awaiting for open track after CSX I111-30 fatally struck a trespasser south of the station at milepost 164.2. The freight crew requested relief which arrived at 10:00 p.m. Upon release of the scene, train 53(01) was able to proceed south.

Train	Delay	Comment
53(01)	2'12"	

Train 175(01) New Haven, CT - Commuter Train Interference

01OCT26: Train 175(01) operating with engine 655 and 522 customers onboard was delayed on the MNRR New Haven Line following Metro North commuter traffic from New Haven to Stamford.

Train	Delay	Comment
175(01)	30"	

Train 2160(01) West of New Haven, CT - Temporary Speed Restrictions

01OCT26: Acela 2160(01) operating with power cars 2104, 3463, and 359 customers onboard was delayed west of New Haven, CT on the MNRR New Haven Line operating through restrictive signals from milepost 33.6 to milepost 72.1.

Train	Delay	Comment
2160(01)	42"	

27-FOI-00048 0000008958 "UNCLASSIFIED", 10/19/2026

Train 41(30) South of Petersburg, VA - Police Related

01OCT26: Train 41(30) operating with engines 57, 315, and 161 customers onboard was delayed 50 miles south of Petersburg, VA on the CSX North End subdivision holding at milepost 73.8 while local police searched for a missing child near the tracks.

Train	Delay	Comment
41(30)	39"	

Train 41(29) North of Savannah, GA - Freight Train Interference

01OCT26: Train 41(29) operating with engines 111, 37, 10 cars, and 157 customers on board was delayed at milepost 490.1, 9 miles north of Savannah, GA on the CSX Charleston subdivision due to meeting CSX freight train 728. Once the freight train cleared, Train 41(29) advanced to the next station.

Train	Delay	Comment
41(29)	32"	

Train 131(01) Newark, NJ - Head End Power Loss - Engine Failure

01OCT26: At approximately 12:27P-ET, Train 131(01), operating with Engine 646, 10 cars, Engine 636, and 458 customers, experienced a head-end power (HEP) loss at the Newark, NJ station on the Amtrak NYP Line. The crew worked to troubleshoot the issue and attempted to restore HEP from the rear engine. An Amtrak Road Foreman of Engines was notified and worked with the crew. HEP was restored at 12:53P-ET and operated from rear Engine 636, allowing the train to resume operation. Train 131(01) departed the Newark, NJ station at 1:14P-ET; however, the train subsequently lost HEP again when an MCB opened on Engine 646. The train reversed back into the Newark, NJ station, arriving at 1:27P-ET, where Mechanical personnel responded onboard to assist. HEP was later restored; however, the train experienced a Truck #1 fault. The crew continued troubleshooting and isolated Traction Motor #1 due to a blower fault. Train 131(01) resumed operation at 1:44P-ET. Mechanical personnel rode the head end and were scheduled to meet the train upon arrival at the Philadelphia, PA 30th Street Station. The weather was reported as 74°F.

Train	Delay	Comment
131(01)	1'19"	

Train 97(30) South of Savannah, GA - Freight Train Interference

01OCT26: Train 97(30) operating with engines 328, 348, 10 cars, and 191 customers onboard was delayed at milepost 522.5, 31 miles south of Savannah, GA on the CSX Nahunta subdivision due to meeting a CSX freight train. Once the freight train cleared, Train 97(30) advanced to the next station.

Train	Delay	Comment
97(30)	41"	

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Train 605(01) Philadelphia, PA - Cab Car Speedometer Failure

01OCT26: Train 605(01) operating with cab car 9644, 4 cars, engine 611, and 16 customers on board was delayed after departing Philadelphia, PA on the Amtrak PH Line due to speedometer failure on cab car 9644 which required the train to be wyed after departure. The train advanced to the next station after the move was completed.

The equipment was not able to be successfully fixed in Harrisburg. The equipment had to be wyed for the subsequent turns for the day on Trains 646(01) and 655(01) due to cab car 9644 being unable to lead.

Train	Delay	Comment
605(01)	26"	
646(01)	29"	
655(01)	19"	

Train 2102(01) South of Wilmington, DE - Engine Failure

01OCT26: Train 2102(01) operating with 79 customers onboard experienced an undesired emergency brake application for an unknown reason and was stopped south of the Wilmington, DE station on the Amtrak PW Line. The crew performed troubleshooting; however, de-prepare procedures were unsuccessful. Customers were transferred to Train 130(01). Train 2102(01) was subsequently terminated where it stood, and the equipment was deadheaded to Washington, DC Union Station. As a result of the incident, Train 2113(01) was canceled in its entirety.

Train	Delay	Comment
2102(01)	Terminated	
130(01)	24"	
2113(01)	Cancelled	

CSX Nahunta Subdivision, North of Jesup, GA - Disabled Freight

01OCT26: Freight train M691 was disabled on the Chessie, Seaboard and X Nahunta Subdivision between Doctortown (MP A543.7) and Backswamp (MP A540.1), 5 miles north of the Jesup, GA station, on single main track due to a broken wrong-end drawbar. A rescue locomotive and Mechanical personnel responded to the scene. The freight train was subsequently moved, clearing the route for train operations.

Train 41(29), with 163 customers, arrived at the Savannah, GA station at 6:31A-ET and was held due to the freight interference. The train departed at 8:49A-ET and was operating 4 hours and 46 minutes late.

Train 97(30), with 191 customers, arrived at the Savannah, GA station at 7:30A-ET and was held due to the freight interference. The train departed at 8:55A-ET and was operating 2 hours and 6 minutes late.

Train	Delay	Comment
97(30)	1'30"	
41(29)	1'33"	

Train 40(30) North of Savannah, GA - Broken Rail

27-FOI-00046 0000008958 "UNCLASSIFIED" 10/19/2026

01OCT26: Train 40(30) originating with engine 53, 15 and 124 customers onboard was delayed 15 miles north of Savannah. GA on the CSX Columbia subdivision holding at milepost 474.6 for a broken rail at the north end of Stillwell milepost 468.9. A foot of rail was missing and CSX personnel were able to bar up the section and walk train 40(30) over the affected area.

Train 41(29) and Train 40(30) met in route and exchanged crews to ensure that the train could make it to Jacksonville. The trains met at milepost 490.1.

Train	Delay	Comment
40(30)	2'23"	
41(29)	35"	Recrew

Maintenance of Way Highlights

27-FOI-00046 0000008858 UNCLASSIFIED 10/19/2026

MBTA Downeaster Track Work - Scheduled M/W Work - TW 26-094 - 9/12-10/11

21AUG26: To support the MBTA bridge replacement at MP 8.99 the below service adjustments have been made:

To accommodate the above outlined infrastructure work, Amtrak's Downeaster Service will be adjusted as follows:

Northbound
• Trains 693 and 695 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 699 (13Sep, 20Sep, 4Oct, 10Oct-11Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

• Train 1689 (12Sep, 19Sep, 26Sep-27Sep, 3Oct), which normally operates between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

o Please note Trains 691 and 697 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct) will operate NORMAL.

Southbound
• Trains 690, 692, 694, 696, and 698 (12Sep-13Sep, 19Sep-20Sep, 26Sep-27Sep, 3Oct-4Oct, 10Oct-11Oct), which normally operate between BON and HHL on the MBTA/Keolis New Hampshire Mainline, will detour over the Western Route and will bypass WOB with no alternate transportation. Minimal delays could be expected.

WBS#: B.TR.100150.7065

NS Danville District East of Greensboro, NC - Scheduled M/W Work - TW 26-095

31AUG26: To accommodate rail replacement on the NS Danville district between Elm/MP 284.4 and Isom/MP 34.1. The following service adjustments are in place:

Train 72 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Charlotte and Raleigh, will terminate at Greensboro.

Train 72 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Train 74 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 74 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 76 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Charlotte and Raleigh, departing Charlotte 70-minutes later.

Train 76 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

Train 78 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, departing Charlotte 105-minutes Later.

Train 78 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct- 11Oct) will operate on an adjusted schedule.

Raleigh.

Train 80 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct,9Oct-11Oct) will operate on an adjusted schedule.

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Train 71 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule, making all stops between Raleigh and Charlotte, departing Raleigh 15-minutes earlier.

Train 71 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct), will operate on an adjusted schedule.

Train 73 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will be canceled in entirety and replaced by one bus.

Train 73 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 75 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct), which normally operates between Raleigh and Charlotte, will originate at Greensboro 65-minutes later.

Train 75 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 77 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will depart Raleigh 2-hours later and operate on an adjusted schedule between Raleigh and Charlotte.

Train 77 (4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule.

Train 79 (31Aug-3Sep, 8Sep-10Sep, 14Sep-17Sep, 21Sep-24Sep, 28Sep-1Oct, 5Oct-8Oct) will operate on an adjusted schedule between Durham and Charlotte.

Train 79(4Sep-7Sep, 11Sep-13Sep, 18Sep-20Sep, 25Sep-27Sep, 2Oct-4Oct, 9Oct-11Oct) will operate on an adjusted schedule between Durham and Charlotte.

WBS#: B.TR.100150.7085

Train	Delay	Comment
77(03)	50"	
78(03)	50"	Turn of Late 77(03)

27-FOI-00046, 00000008958 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) will operate as a deadhead train that will operate as a deadhead between NHV and HFD.

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
698(27)	BON	90		Air issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Train 550(01) San Jose, CA - Third Party Contractor Engine Failure

02OCT26: Train 550(01) was delayed departing San Jose, CA/ MP47.6 on the UPRR Coast Subdivision, due to E/JPBX920 with mechanical issues. This trainset with the JPBX920 was initially slated to be used for Train 544(01), and due to a prolonged mechanical delay, several equipment turns were changed. Train 544(01) was delayed departing San Jose, needing to utilize inbound 543's equipment. Train 542(01) was delayed departing San Jose needing to utilize 539's equipment. The mechanical team had resolved the issues on the JPBX920 set for Train 550(01), and after releasing the train, mechanical issued persisted and the train was unable to depart. As a result, Train 550(01) needed to utilize the next inbound train 547's equipment, and departed San Jose 1 hour and 31 minutes late.

Train	Delay	Comment
544(01)	50"	
542(01)	14"	
550(01)	1'31"	

Train 14(01) South of San Jose, CA - Commuter Train Interference

02OCT26: Train 14(01) was delayed at Gilroy/ MP77 on the UPRR Coast Subdivision, 29.4 miles south of San Jose, CA station, due to meeting Caltrain JPBX822.

Train	Delay	Comment
14(01)	30"	

Train 1(30)/421(29) West of Maricopa, AZ - Freight Train Interference

02OCT26: Train 1(30) 421(29) was delayed following an unspecified UP freight unit between Gila Bend/ MP857.4 to Sentinel/ MP831.2 on the UPRR Gila Subdivision, beginning 40.3 miles west of Maricopa, AZ station.

Train	Delay	Comment
1(30)421(29)	39"	

Train 794(01) North of Goleta, CA - Passenger Train Interference

02OCT26: Train 794(01) was delayed at Gaviota /MP336.3 on the UPRR Santa Barbara Subdivision, 21.6 miles north of Goleta, CA station, due to meeting Train 777(01).

Train	Delay	Comment
794(01)	30"	

Train 6(01) Reno, NV - Freight Train Interference

02OCT26: Train 6(01) was delayed at Reno, NV/ MP240.7 on the UPRR Roseville Subdivision, due to a UP dispatch hold for freight train congestion at Sparks yard. Train 6(01) was further delayed at MP247 and MP265.2 meeting freight units UP5398 and 7713.

Train	Delay	Comment
6(01)	1'29"	

27-FOI-00046 000000008958 "UNCLASSIFIED" 10/19/2026

Train 7/27(30) West of Havre, MT - System

02OCT26: Train 7/27(30) was delayed at Tessmer/MP1006.7 on the BNSF Hi Line Subdivision, 46.4 miles west of Havre, MT station, due to picking up previously set-out sleeper car C/32000. An Amtrak Road Foreman was on scene to assist the crew with the move, and once added to the rear of the consist, Train 7/27(30) proceeded west.

46.43 west

Train	Delay	Comment
7/27(30)	59"	

Train 21(01) North of Arcadia, MO - Freight Train Interference

02OCT26: Train 21(01) was delayed holding at Mineral Point/MP61.3, 28.02 miles north of Arcadia, MO station on the UPRR Desoto subdivision meeting UPRR freight train 7925. Train 22(01) was back on the move at 1017PM CT after the freight train cleared.

Train	Delay	Comment
21(01)	32"	

Train 822(01) South of Gainesville, TX - Freight Train Interference

01OCT26: Train 822(01) was delayed holding at MP378.3, 32.5 miles south of Gainesville, TX station on the BNSF Ft. Worth subdivision meeting BNSF freight trains 6927 and 8365. Train 822(01) was back on the move at 745PM CT after both trains cleared to the south.

Train	Delay	Comment
822(01)	1'35"	

Train 25(01) North of New Orleans, LA - Passenger Train Interference

01OCT26: Train 25(01) was delayed holding in the Nicholson Ave siding/MP754.72, 56.84 miles north of New Orleans LA station on the CSX NO and M subdivision meeting Amtrak train 26(01).

Train	Delay	Comment
25(01)	30"	

Train 21(30) North of Temple, TX - Temporary Speed Restrictions

01OCT26: Train 21(30) was delayed beginning at MP239.8, 21.79 miles north of Temple TX station on the UPRR Ft. Worth subdivision operating through temporary speed restrictions. Train 21(30) operated through the speed restrictions until MP220.8.

Train	Delay	Comment
21(30)	35"	

Train 20(01) North of Meridian, MS - Freight Train Interference

01OCT26: Train 20(01) was delayed beginning at MP290, 5 miles north of Meridian MS station on the Norfolk Southern AGS south subdivision following Norfolk Southern freight train 344. Train 20(01) followed the freight until MP 232.

Train	Delay	Comment
20(01)	39"	

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Train 4(29) East of Kansas City, MO - Weather

01OCT26: Train 4(29), operating with engines 108/23, 9 coaches, and 215 customers, was delayed operating between Kansas City, MO, on BNSF Marceline subdivision, due to operating through flash flood warnings between Kansas City, MO, and La Plata, MO. Train 4(29) was delayed also delayed by a freight train that was also being delayed by the flash flood restrictions. Train 4(29) was clear of both flash flood restrictions and the freight at milepost 360.

Train	Delay	Comment
4(29)	30"	Flash Flood Restrictions
4(29)	49"	Following Freight

Train 516(01) South of Vancouver, BC - Freight Train Interference

01OCT26: Train 516(01) was delayed starting at Still Creek/MP 153.9, 2 miles south of Vancouver, BC, on the CNRR New Westminster Subdivision due to a freight yard crew working, blocking station track. The crew held for the yard crew to complete their work, then proceeded north.

Train	Delay	Comment
516(01)	31"	

Train 821(01) South of Pauls Valley, OK - Weather

01OCT26: Train 821(01), operating with engines 135/203, 2 coaches, and 46 customers, was delayed operating between Pauls Valley, OK and Fort Worth, TX, on BNSF Red Rock subdivision, due to flash flood speed restrictions. There were 8 customers connecting to train 21(30). 7 of them were accommodated on alternate transportation and 1 was housed at a hotel. There were 2 customers connecting to 22(01) and they were accommodated on alternate transportation.

Train	Delay	Comment
821(01)	3'51"	

Train 3(30) East of Raton, NM - Weather

01OCT26: Train 3(30) was delayed starting at Raton/MP 658.0, 1 mile east of Raton station, on the BNSF Raton Subdivision due to high wind warnings. Due to the weather, the BNSF placed high wind warnings between MP 658 and MP 697, and between, MP 753 and MP 796 on the Raton Subdivision. Train 3(30) was delayed operating at restricted speed through the affected area. Train 4(30) was also delayed due to weather related signal issues om the Raton Subdivision between MP722.7 and 699.5.

Train	Delay	Comment
3(30)	37"	
4(30)	1'07"	

Train 3(01) Chicago, IL - Initial Terminal Delay

01OCT26: Train 3(01), operating with engine 152/29, 9 coaches and 219 customers, was delayed departing chi due to Cab Signal Failure on engine 152. Mechanical met the train and was able to resolve the issue.

Train	Delay	Comment
3(01)	1'00"	

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Train 770(01) South of Oxnard, CA - Engine Failure

01OCT26: Train 770(01), 2/6900-5 cars-E/C2116 was delayed starting at Oxnard, CA/MP 404.1 on the UPRR Santa Barbara Subdivision due to loading issues with E/2116. The crew experienced loading issues between Oxnard and Camarillo, CA, then again, between Camarillo and Moorpark, CA. With the issue continuing, the crew contacted mechanical at Simi Valley, CA to troubleshoot. While troubleshooting head end power(HEP) was intermittent for short periods. There were 110 customers on board and the ambient outside temperature was 73 degrees. Once the crew restarted the locomotive, the issue was remained. The crew was able to continue south following a brake test and equipment swaps were made in Los Angeles, CA for E/C2116 to go to the yard for repairs.

Comet set started being prepared due to the locomotive issues on E/C2116 as the original equipment slated for Train 572(01) was used to operate at Train 770(01) between Los Angeles and San Diego. Train 572(01),E/510-5 cars-CC/9700 and 79 customers, was delayed departing Los Angeles due to the equipment having loading issues. Mechanical worked in the yard to resolve issues. Once issues were resolved, the equipment was taken to the station for boarding. After all customers were boarded, Train 572(01) departed.

Train	Delay	Comment
770(01)	35"	
572(01)	43"	ITD LAX

Train 8/28(29) East of Staples, MN - Freight Train Interference

01OCT26: Train 8/28(29), operating with engines 301/205/326, ten coaches, and 174 customer was delayed 30 miles east of Staples, MN, on BNSF Staples subdivision, due to meeting BSNF72 at milepost 118.8. The BNSF freight was having PTC issues. After troubleshooting the issue, BNSF72 was able to proceed, with 8/28(29) following. BNSF72 Hours of service Expired shortly after getting back on the move with a re-crew enroute with a 2'00" eta. Once the re-crew arrived the freight was able to proceed with 8/28(29) following.

Train	Delay	Comment
8/28(29)	3'35"	

Train 51(30) Indianapolis, IN - Adding Beech Grove Equipment

01OCT26: Train 51(30), operating with engines 363/754/160/4502, sixteen coaches and 117 customers, was delayed departing Indianapolis, IN, on CSX Shelbyville subdivision, due to adding equipment from Beech Grove to be taken to Chicago. The crew added 13 pieces of equipment consisting of 3 locomotives and 10 coaches. Once the equipment was added and the necessary brake tests were complete, train 51(30) was able to proceed.

Train	Delay	Comment
51(30)	29"	ADDING EQUIPMENT
51(30)	14"	SLOW SPEED DUE TO HEAVIER TRAIN

Train 5(30) East Omaha, NE - Tornado Warnings Downed Trees Washout BNSF Hastings sub

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

01OCT26: Due to a weather-related washout on the BNSF Hastings Subdivision between MP 64 and MP 65, 6(29) and 5(30) experienced significant delays. BNSF established a detour through Cobb Yard between Hall and Lincoln, requiring pilot crews to guide both trains through the affected area. 6(29), carrying 139 customers, was initially delayed 2 hours and 45 minutes and later held near MP 68.1 while awaiting pilots, whose arrival was delayed by flooded roadways.

5(30), carrying 183 customers, was additionally delayed west of Omaha when a tree blocked the tracks near MP 39. After BNSF crews removed the tree and inspected the track, the train was recrewed and proceeded to Lincoln, where pilots boarded for the detour route. The same pilots and relief crew later transferred to 6(29) to assist it through the washout area. 6(29) subsequently arrived at Lincoln, was recrewed, resolved a PTC issue, and continued west.

Later, 5(30) encountered a second tree obstruction west of Lincoln near MP 69.7, resulting in another delay of approximately two hours while BNSF crews cleared and inspected the track. The train resumed operation under weather-related speed restrictions but was projected to exceed Hours of Service limits. A relief crew was dispatched from Denver, and 5(30) departed Hastings at 3:39 p.m. CT operating 13 hours and 17 minutes late before proceeding to Kenesaw Siding to await the recrew. Train 5(30) was back on the move at 736PM CT with the re-crew on duty. Train 5(30) was delayed at McCook NE completing daily inspections.

As a result of the washout, multiple weather-related track obstructions, speed restrictions, and crew shortages, both 6(29) and 5(30) incurred substantial delays throughout the territory. The service disruptions also resulted in the cancellation of 6(3) and 5(5), with no alternate transportation provided.

02OCT26: Tracks open at the scene of the washout at 1230AM CT.

Train	Delay	Comment
5(30)	33"	Flash Flood warnings
5(30)	4'06"	Downed Trees
5(30)	3'47"	Re-crew
5(30)	45"	Daily Inspections MCK
5(05)	Cancelled	
6(03)	Cancelled	
5(30)	28"	LNK Routing
6(29)	7'20"	Holding W/LNK

Train 718(30) East of Hanford, CA - M of W Work

01OCT26: Train 718(30) was delayed starting at MP 963.5, 8 miles east of Hanford, CA, on the BNSF Bakersfield Subdivision due to maintenance of way(MOW) crew ahead at Calabrese/MP 962.8. The crew with 45 customers on board held at MP 963.5 for the crew to clear route. Once route was cleared, Train 718(30) proceeded east.

Train	Delay	Comment
718(30)	30"	

27-FOI-00046 000000008958 UNCLASSIFIED 10/19/2026

Train 703(30) South of Modesto, CA - Freight Train Interference

01OCT26: Train 703(30) was delayed at Hanshaw/MP1117.8 and Keddie Jct /MP1120.7 on the BNSF Stockton Subdivision, 1 mile south of Stockton, CA station, due to a train meet with BN4256, UP5762, UP5566 and then Amtrak 718(30). Met BN4256 at Hanshaw, then was held at Keddie for UP5762 that was holding for UP5566 and 718(30). Train 703(30) pulled into the transfer track, (with red signal at other end for UP 5762) and did not fully clear Keddie Jct. in order for 718(30) to clear and proceed, causing all 4 trains to be stopped. The crew received authority from the dispatcher to proceed by the red signal, in order to clear Keddie, which allowed BN 5566 to proceed, followed by 718(30), then Train 703(30) was able to proceed.

Train	Delay	Comment
703(30)	56"	FTI
703(30)	20"	Meeting 718(20)
718(30)	38"	

BNSF Glasgow Subdivision West of Minot, ND - Freight Train Interference

30SEP26: The BNSF reported a freight derailment on the Glasgow subdivision just west of Minot at Shoo Tower/MP 0.63 with seven stack cars and 26 containers on the ground on the 6th Street overpass and blocking both main tracks. There were no hazmat cars involved in the derailment. The derailment ruptured a local gas line. Heavy equipment arrived on scene through 300PM-CT to aid in the cleanup efforts with 25 ballast cars enroute. Train 7/27(29) had access to the Minot depot. Train 7/27(29) arrived Minot at 951AM-CT, 51 minutes late and held for disposition. The rough estimated time for main track 2 to be opened was 800PM-CT. Customer service worked to source alternate bus transportation for a potential bus bridge with train 8/28(29) between Minot and Stanley. There were 197 customers on train 7/27(29) that were affected. Customer service recovery was initiated in Minot with Papa Johns pizza for lunch and a chicken dinner. There were 179 customers on train 8/28(29) that were affected.

BNSF advised that the estimated time of track opening was pushed back until midnight. As a result, a bus bridge was initially implemented between Minot and Stanley. Four buses were sourced at Minot for customers on train 7/27(29) between Minot and Stanley and staged at 500PM-CT. Four buses were sourced for customers on train 8/28(29) between Stanley and Minot and staged at 730PM-CT. All busses were released after an update was given for track opening to be 11:15PM-CT, account of the expected logistics involved regarding the wye and crew hours of service.

Train 8/28(29) was held just west of the derailment at CP189/MP18.9 for disposition. Main track #2 was opened at 10:32PM-CT with a 25mph speed restriction, and 7/27(29) departed Minot at 10:55PM-CT operating 13 hours and 11 minutes late. Train 8/28(29) was behind multiple freights and also had to wait and allow all stacked-up westbound trains to pass, including 7/27(29), before proceeding into Minot. Main track #1 returned to service October 1st at 12:00P-CT.

Due to the late operation of Train 7/27(29), service recovery was initiated with Jimmy Johns sandwiches and chips for dinner being provided to all customers upon arrival into Spokane, WA.

WBS#: B.TR.100150.7228

Train	Delay	Comment
8/28(01)	Canceled	
7/27(04)	Canceled	
8/28(29)	4'24"	
7/27(29)	12'13"	

Train 821(29) South of Gainesville, TX - Temporary Speed Restrictions

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/19/2026

29SEP26: Train 821(29) was delayed beginning the 2 miles south of Gainesville, TX, on the BNSF Fort Worth Subdivision, operating through temporary speed restrictions in effect between MP409.5 and MP396.4. Train 822(29) was also delayed operating through the affected area.

30SEP26: The temporary speed restrictions remained in effect between MP409.5 and MP396.4. Trains 821(30) and 822(30) were delayed operating through the affected area.

Train	Delay	Comment
822(29)	32"	
821(29)	27"	
821(30)	34"	
822(30)	30"	
822(01)	30"	

Maintenance of Way Highlights

27-FOIA-00046 700000008958 UNCLASSIFIED 10/18/2026

Union Pacific Brooklyn Subdivision Portland, OR - Portland Marathon TWA 27-003

04OCT26: The Portland Marathon occurred in Portland, OR, resulting in closure of rail operations at Southeast Stark Street (DOT #754542S) / MP 769.78 on the Brooklyn Subdivision, 1 mile south of the Portland, OR Union Station due to event-related roadway and crossing closure. As a result, the following operating plan was implemented:

Train 503(04) terminated in Portland.

Train 504(04) originated in Portland and operate 1-hour later.

Buses were secured to provide alternate transportation to customers traveling to and from all missed station stops.

WBS#: B.TR.100150.7209

Metrolink Orange Subdivision - Scheduled M/W Work 27-001

02OCT26: To accommodate the infrastructure work on the Metrolink Orange Subdivision beginning Friday, October 2nd at 10:00P-PT through Saturday, October 3rd at 6:00A-PT the following service adjustments were made affecting the Pacific Surfliner Service.

- Train 794(02-03OCT), which normally operates between San Luis Obispo, CA to San Diego, CA, terminated in Los Angeles, CA. Alternate bus 3594 was provided between Los Angeles and San Diego, making all station stops except San Juan Capistrano.
- Train 595(02-03OCT), which normally operates between San Diego, CA and Los Angeles, CA, was cancelled in its entirety. Customers were able to utilize bus 5811 as an alternative.

WBS#: B.TR.100150.7133

UPRR Coast Subdivision South of Oakland, CA - Scheduled M/W Work 27-009

02OCT26: The UPRR performed a switch removal at MP 14.992 on the Coast Subdivision beginning at 7A-PT on Saturday, October 3rd. To accommodate the infrastructure work, the following service adjustments were made.

- Train 11(02OCT), which normally operates between Oakland, CA and San Jose, CA on the UPRR Coast Subdivision detoured over the Niles Subdivision between Elmhurst/MP 14 and Newark/ MP 31 with no stops missed.

WBS#: B.TR.100150.7230

Coast Starlight - Scheduled M/W Work 26-090

03AUG26: To accommodate the outlined infrastructure work, Amtrak's Coast Starlight Service will be adjusted as follows:

- Train 11(22Aug, 29Aug, 5Sep,12Sep, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between CIC and SAC, will detour over the Valley and Martinez subdivisions with no missed stops. Delays of 20-minutes can be expected.
- Train 14(22Aug, 29Aug, 5Sep, 12SEP, 26Sep, 03Oct), which normally operates on the UPRR Sacramento Subdivision between SAC and CIC, will detour over the Martinez and Valley subdivisions with no missed stops. Delays of 20-minutes can be expected.

WBS#: B.TR.100151.0836

Train	Delay	Comment
11(22AUG)	32"	
14(22AUG)	23"	
11(12SEP)	29"	
14(12SEP)	50"	Detours/ ETI

27-FOIA-00046 00000008958 "UNCLASSIFIED" 10/19/2026

Amtrak / MDOT Michigan Line - Scheduled M/W Work 26-082

29JUL26: Amtrak / MDOT have coordinated schedules for the Michigan Line starting August 3rd through September 25th between MP53 to MP 57 in order to complete the Chelsea Siding Outage / Turnout Installation project. In order to complete the outlined infrastructure work, Amtrak's Wolverine Service has been adjusted as follows:
-Train 352 (3Aug-31Oct) will operate 20-minutes later between Chicago and Ann Arbor, 25-minutes later between Ann Arbor and Troy, and arrive 30-minutes later at Pontiac.
-Train 352 (1Sep-25Sep) will operate 20-minutes later between Chicago and Pontiac.
-Train 355 (3Aug-31Oct) will operate 25-minutes earlier between Pontiac and Detroit, 20-minutes earlier between Detroit and Battle Creek, and 15-minutes earlier between Battle Creek and Chicago.
-Train 355 (1Sep-25Sep) will operate 20-minutes earlier between Pontiac and Chicago.
*Please Note: 352 and 355 will bypass Troy, MI August 3-7 (Reference TWA-26-079) due to CN Track Work.

WBS#: B.TR.100150.6961

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday October 7th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:
-Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
-Train 59(27Jul-29Jul, 31Jul-12Oct) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
-Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
-Train 58(28Jul-30Jul, 1Aug-13Oct) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

21SEP26: Train 59(21) terminated at Memphis, TN, due to late operation and CN taking the work block on the Yazoo Subdivision as planned and no route available for Train 59(21) to proceed. Five busses were secured as alternate transportation for Train 59(21) passengers between Memphis and New Orleans. The equipment operated deadhead to New Orleans upon completion of the work curfew.

29SEP26: CN tie gang curfew moved north of Marks, MS/MP67.3 between Crenshaw/MP48.8 and Rials/MP29.8 with the work window between 12:00pm and 8:00PM.

WBS#: B.TR.100150.6867

Train	Delay	Comment
59(21)	Terminated MEM	

27-FOI-00046 0000008958 UNCLASSIFIED 10/19/2026

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track and project work multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:
  Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
  Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
  Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
  Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
  Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.
  Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:
  Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
  Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
  Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
  Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
  Arrive Los Angles, CA fifteen minutes later at 8:12AM-PT.
  Note: Fullerton, CA will be a "discharge only " stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
3(1)	NEW	BNSF7818	E/152 loading issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
		1		N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost

Passenger Removals and/or Isolations

Consist Deviations

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
449 (02)	BOS	All table lounge in lieu of AMII lounge due to PM/equipment availability.			43397
392 (01)	CDL	No cafe service or food service due to not having a biz cafe car.	NA	0	31020
391 (01)	CHI	No cafe service or food service due to not having a biz cafe car.	Notified passengers	0	31020
572 (01)	LAX	OPERATING WITH COMET SET. WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV OR JY RESERVATION. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS. INVENTORY HAS BEEN ADJUSTED TO REFLECT THE CHANGE.	1 bv / 32 jy	33	C5006 C5010 C5004 C5007 C5005 9700
562 (02)	LAX	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 90215 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.	No impact	0	90215
580 (02)	LAX	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 90215 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.	No impact	0	90215
20 (02)	NOL	all table lounge in lieu of AMII lounge for coach pax. AMII lounge in lieu of AMII diner for sleeper pax.			43378, 28016
97 (01)	NYP	9711 car using VII in lieu of VI (2 less rooms). Crew will be on 9710 car. schedule changes performed for 9710 and 9711. check war report.			62509
587 (01)	SAN	OPERATING WITH COMET SET. WILL NOT BE ABLE TO ACCOMMODATE PASSENGERS WITH BV OR JY RESERVATION. CNOC CSV WILL NEED TO REACCOMMODATE PASSENGERS. INVENTORY HAS BEEN ADJUSTED TO REFLECT THE CHANGE.	29 no jy / 0 bv	29	9700 C5005 C5007 C5004 C5010 C5006
573 (02)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 90215 BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.	No impact	3	90215
591 (02)	SAN	TRAIN WILL OPERATE WITHOUT BIKE SPACE DUE TO CAR 90215	No impact	0	90215

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		BEING IN THE CONSIST. PLEASE NOTIFY ALL EFFECTED PAX.			

27-FOI-00046 00000008958 "UNCLASSIFIED" 10/[illegible]/2023

Reverse Consists

Train Number	Station	Reason
95 (01)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
171 (01)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
85 (01)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
190 (01)	PHL	Consist reversed | Business class seat orientation may have changed | At Front
110 (01)	PHL	Consist reversed | Business class seat orientation may have changed | At Rear
185 (01)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
174 (01)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
193 (01)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
137 (01)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
184 (01)	WAS	Consist reversed | Business class seat orientation may have changed | At Front
94 (02)	NFK	Consist reversed | Business class seat orientation may have changed | At Front
178 (02)	RNK	Consist reversed | Business class seat orientation may have changed | At Front