

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Tuesday, December 16, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/15/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/15/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	315	81	74.3%	4,527	672	85.2%	22,436	2,862	87.2%
Central Division	85.5%	67	16	76.1%	981	164	83.3%	5,003	533	89.3%
Northeast Division	80.0%	100	42	58.0%	1,444	207	85.7%	7,040	959	86.4%
Southeast Division	72.5%	74	20	73.0%	1,046	159	84.8%	5,245	676	87.1%
Southwest Division	77.0%	74	3	95.9%	1,056	142	86.6%	5,148	694	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00197 00000005542 UNCLASSIFIED Endpoint Arrival Dates through 12/15/25 12/23/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	96,024	46,940	51%	1,478,717	359,643	76%	7,673,451	1,607,848	79%
Northeast Corridor	81%	45,876	29,944	35%	674,529	162,776	76%	3,465,930	680,660	80%
Acela	83%	11,796	6,608	44%	152,679	44,379	71%	744,879	162,058	78%
Northeast Regional	79%	34,080	23,336	32%	521,850	118,397	77%	2,721,051	518,602	81%
Richmond / Newport News / Norfolk	77%	11,549	7,392	36%	159,699	40,449	75%	825,705	183,954	78%
Springfield Shuttles	89%	847	358	58%	11,839	1,513	87%	45,361	5,208	89%
Roanoke	79%	2,596	745	71%	40,474	7,604	81%	209,227	34,353	84%
On Spine Northeast Regional	80%	19,088	14,841	22%	309,838	68,831	78%	1,640,758	295,087	82%
State Supported	80%	38,977	11,571	70%	623,534	128,174	79%	3,270,208	611,229	81%
Borealis	60%	496	39	92%	8,189	2,531	69%	44,479	12,102	73%
Capitol Corridor	90%	3,146	75	98%	51,162	5,821	89%	269,755	29,217	89%
Carolinian	60%	1,070	794	26%	17,165	5,750	67%	90,311	26,652	70%
Cascades	63%	2,163	314	85%	31,913	7,938	75%	178,202	43,275	76%
Downeaster	82%	1,224	823	33%	20,667	3,108	85%	111,925	14,884	87%
Empire	78%	5,172	842	84%	76,550	15,954	79%	392,734	77,499	80%
Adirondack	72%	289	190	34%	3,922	1,876	52%	24,821	8,427	66%
Ethan Allen Express	70%	496	2	100%	7,939	2,269	71%	44,932	13,790	69%
Maple Leaf	70%	686	602	12%	9,671	4,767	51%	45,053	16,555	63%
New York - Albany	85%	2,407	0	100%	35,771	2,987	92%	174,378	22,109	87%
New York - Niagara Falls	75%	1,204	48	96%	19,247	4,055	79%	103,550	16,618	84%
Gold Runner	73%	2,359	404	83%	33,638	10,999	67%	187,686	66,644	64%
Heartland Flyer	65%	112	59	47%	2,626	608	77%	15,135	8,178	46%
Hiawatha	90%	1,388	101	93%	26,041	5,145	80%	132,494	16,060	88%
Illinois	78%	2,343	674	71%	34,895	15,089	57%	184,732	54,407	71%
Carl Sandburg / Illinois Zephyr	85%	309	215	30%	6,562	2,177	67%	31,720	8,735	72%
Illini / Saluki	85%	700	240	66%	9,720	3,945	59%	64,544	17,404	73%
Lincoln Service	70%	1,334	219	84%	18,613	8,967	52%	88,468	28,268	68%
Keystone	92%	8,512	4,538	47%	129,658	16,749	87%	625,236	57,560	91%
Lincoln / Missouri	60%	697	357	49%	10,788	5,303	51%	59,088	29,959	49%
Mardi Gras Service	80%	335	0	100%	5,503	172	97%	33,176	3,931	88%
Michigan	69%	1,934	1,034	47%	28,810	13,894	52%	148,145	43,782	70%
Blue Water	70%	189	0	100%	6,231	3,374	46%	37,016	10,669	71%
Pere Marquette	85%	335	328	2%	3,949	1,180	70%	19,845	3,109	84%
Wolverine	65%	1,410	706	50%	18,630	9,340	50%	91,284	30,004	67%
Missouri	80%	174	0	100%	3,322	904	73%	17,892	4,440	75%
Pacific Surfliner	85%	5,482	245	96%	93,862	7,220	92%	506,850	65,367	87%
Pennsylvanian	72%	742	82	89%	13,158	1,439	89%	70,182	7,637	89%
Piedmont	73%	667	249	63%	15,767	2,651	83%	100,096	24,482	76%
Vermont	75%	961	941	2%	19,820	6,899	65%	102,090	25,153	75%
Long Distance	56%	11,171	5,425	51%	180,654	68,693	62%	937,313	315,959	66%
Auto Train	57%	665	310	53%	10,430	2,236	79%	50,255	9,447	81%
California Zephyr	50%	799	270	66%	12,136	4,370	64%	68,944	20,041	71%
Cardinal	55%	372	272	27%	4,174	1,699	59%	21,530	10,004	54%
City Of New Orleans	75%	713	285	60%	10,003	1,369	86%	53,329	11,091	79%
Coast Starlight	60%	1,065	31	97%	17,342	4,791	72%	87,880	27,166	69%
Crescent	70%	1,042	690	34%	13,881	2,354	83%	72,996	18,136	75%
Empire Builder	55%	934	501	46%	13,655	6,181	55%	74,072	26,442	64%
Floridian	40%	1,714	1,470	14%	24,967	16,016	36%	128,868	70,388	45%
Lake Shore Ltd	73%	541	0	100%	15,037	5,585	63%	70,965	13,846	80%
Palmetto	65%	854	573	33%	14,190	4,156	71%	73,999	12,587	83%
Silver Meteor	45%	983	492	50%	15,350	6,039	61%	78,099	24,373	69%
Southwest Chief	40%	673	524	22%	10,831	7,850	28%	62,405	38,204	39%
Sunset Ltd	70%	293	1	100%	4,220	553	87%	20,602	4,777	77%
Texas Eagle	50%	523	6	99%	14,438	5,494	62%	73,369	29,457	60%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005542 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 15, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	91,166	1,613,912	565	421,048	8,122,705	518

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	3,818	476,381	80	16,173	2,378,617	68
INFRASTRUCTURE PLANNED	135	2,620	476,381	55	13,201	2,378,617	55
FLEET RELIABILITY	90	18,003	1,613,912	112	65,887	8,122,705	81
TRAIN OPERATIONS	424	66,725	1,613,912	413	325,787	8,122,705	401

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/15/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/15/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	315	81	74.3%	4,527	672	85.2%	22,436	2,862	87.2%
Central Division	85.5%	67	16	76.1%	981	164	83.3%	5,003	533	89.3%
Northeast Division	80.0%	100	42	58.0%	1,444	207	85.7%	7,040	959	86.4%
Southeast Division	72.5%	74	20	73.0%	1,046	159	84.8%	5,245	676	87.1%
Southwest Division	77.0%	74	3	95.9%	1,056	142	86.6%	5,148	694	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-0011

Scheduled Departure Date: 12/15/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/15/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	315	81	74.3%	4,527	672	85.2%	22,436	2,862	87.2%
Central Division	85.5%	67	16	76.1%	981	164	83.3%	5,003	533	89.3%
CDL	90.0%	1	0	100.0%	16	1	93.8%	130	7	94.6%
CHI	85.0%	27	7	74.1%	398	86	78.4%	2,031	223	89.0%
CHM	-	1	0	100.0%	6	3	50.0%	6	3	50.0%
EUG	86.5%	2	0	100.0%	30	4	86.7%	147	19	87.1%
GRR	98.0%	1	1	0.0%	15	1	93.3%	76	1	98.7%
KCY	84.5%	2	0	100.0%	30	3	90.0%	150	14	90.7%
MKE	86.5%	6	0	100.0%	88	9	89.8%	444	39	91.2%
MSP	94.0%	1	0	100.0%	15	0	100.0%	76	3	96.1%
PDX	78.0%	5	0	100.0%	75	6	92.0%	381	52	86.4%
PNT	91.5%	3	1	66.7%	44	10	77.3%	170	15	91.2%
PTH	93.0%	1	1	0.0%	14	2	85.7%	75	4	94.7%
QCY	87.5%	2	1	50.0%	30	3	90.0%	152	15	90.1%
SEA	80.0%	8	2	75.0%	119	18	84.9%	604	92	84.8%
SPK	92.0%	1	-	100.0%	17	2	88.2%	78	3	96.2%
STL	88.0%	4	2	50.0%	59	15	74.6%	301	33	89.0%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	1	50.0%	25	1	96.0%	147	5	96.6%
Northeast Division	80.0%	100	42	58.0%	1,444	207	85.7%	7,040	959	86.4%
ALB	91.5%	7	0	100.0%	105	6	94.3%	472	27	94.3%
BON	43.5%	5	0	100.0%	75	5	93.3%	362	37	89.8%
BOS	86.5%	20	10	50.0%	286	36	87.4%	1,384	139	90.0%
BRK	88.0%	5	0	100.0%	75	2	97.3%	342	15	95.6%
BTN	48.0%	1	0	100.0%	15	0	100.0%	75	17	77.3%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	1	50.0%	30	3	90.0%	146	12	91.8%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	1	0.0%	15	3	80.0%	76	14	81.6%
NFL	96.5%	2	0	100.0%	30	0	100.0%	152	4	97.4%
NHV	75.5%	6	0	100.0%	84	11	86.9%	391	74	81.1%
NYP	77.5%	42	30	28.6%	596	136	77.2%	2,972	566	81.0%
SAB	98.0%	1	0	100.0%	15	0	100.0%	74	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	103	2	98.1%	452	18	96.0%
TWO	84.0%	1	0	100.0%	15	3	80.0%	75	19	74.7%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	74	20	73.0%	1,046	159	84.8%	5,245	676	87.1%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	0	100.0%	75	4	94.7%	380	29	92.4%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	4	69.2%	171	39	77.2%	851	137	83.9%
LOR	69.5%	1	0	100.0%	15	1	93.3%	76	6	92.1%
MIA	87.5%	2	0	100.0%	30	4	86.7%	152	17	88.8%
MOE	94.0%	2	0	100.0%	30	0	100.0%	152	3	98.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/15/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/15/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	315	81	74.3%	4,527	672	85.2%	22,436	2,862	87.2%
Southeast Division	72.5%	74	20	73.0%	1,046	159	84.8%	5,245	676	87.1%
NFK	86.0%	3	1	66.7%	43	6	86.0%	213	21	90.1%
NOL	92.0%	5	0	100.0%	67	3	95.5%	336	17	94.9%
NPN	96.0%	2	0	100.0%	30	0	100.0%	127	7	94.5%
PGH	92.0%	1	1	0.0%	15	1	93.3%	76	2	97.4%
PHL	45.0%	5	5	0.0%	69	43	37.7%	350	166	52.6%
RGH	97.0%	4	0	100.0%	60	4	93.3%	300	7	97.7%
RNK	85.5%	2	0	100.0%	30	4	86.7%	151	18	88.1%
RVM	86.0%	1	0	100.0%	15	2	86.7%	86	13	84.9%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	15	2	86.7%	76	2	97.4%
SFA	70.5%	1	0	100.0%	15	0	100.0%	76	3	96.1%
WAS	70.0%	26	9	65.4%	366	46	87.4%	1,835	223	87.8%
Southwest Division	77.0%	74	3	95.9%	1,056	142	86.6%	5,148	694	86.5%
ARN	60.5%	1	0	100.0%	15	1	93.3%	76	6	92.1%
BFD	75.5%	7	1	85.7%	97	20	79.4%	444	104	76.6%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	0	100.0%	14	5	64.3%	77	22	71.4%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	15	0	100.0%	75	3	96.0%
GTA	72.5%	3	0	100.0%	45	2	95.6%	221	19	91.4%
LAX	77.5%	9	1	88.9%	140	18	87.1%	700	79	88.7%
OKC	96.0%	1	0	100.0%	15	0	100.0%	76	3	96.1%
OKJ	79.0%	13	0	100.0%	173	54	68.8%	833	206	75.3%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	16	1	93.8%	211	24	88.6%	999	110	89.0%
SAN	77.0%	10	0	100.0%	174	8	95.4%	867	73	91.6%
SAS	85.0%	1	0	100.0%	15	1	93.3%	76	4	94.7%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	105	7	93.3%	530	47	91.1%
SLO	62.0%	2	0	100.0%	30	1	96.7%	147	12	91.8%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	2	0	100.0%	6	0	100.0%	16	1	93.8%

Initial terminal tolerance = 0 minutes.

Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1		7	0	100.0%	33	1	97.0%	7	0	100.0%	33	1	97.0%
3	359	15	5	66.7%	76	9	88.2%	14	7	50.0%	75	30	60.0%
4	48	14	5	64.3%	75	11	85.3%	14	12	14.3%	75	50	33.3%
5		15	6	60.0%	75	13	82.7%	14	4	71.4%	73	10	86.3%
6		13	4	69.2%	74	21	71.6%	13	3	76.9%	74	24	67.6%
7	48	15	3	80.0%	76	7	90.8%	12	3	75.0%	73	10	86.3%
8		15	9	40.0%	76	29	61.8%	15	8	46.7%	76	35	53.9%
11		15	2	86.7%	75	13	82.7%	15	2	86.7%	73	9	87.7%
14		15	1	93.3%	76	10	86.8%	15	0	100.0%	75	18	76.0%
19		15	4	73.3%	76	12	84.2%	15	1	93.3%	76	12	84.2%
20	44	15	0	100.0%	76	6	92.1%	15	1	93.3%	76	7	90.8%
21	139	15	3	80.0%	75	11	85.3%	15	5	66.7%	75	16	78.7%
22		15	1	93.3%	76	4	94.7%	15	3	80.0%	75	16	78.7%
23		15	0	100.0%	76	3	96.1%	15	1	93.3%	76	11	85.5%
24		15	3	80.0%	76	5	93.4%	15	1	93.3%	76	7	90.8%
25		15	0	100.0%	76	0	100.0%	15	0	100.0%	76	9	88.2%
26		15	0	100.0%	76	2	97.4%	15	0	100.0%	76	11	85.5%
27		15	2	86.7%	76	3	96.1%	15	4	73.3%	76	14	81.6%
28		15	2	86.7%	76	15	80.3%	15	1	93.3%	76	9	88.2%
40	36	15	3	80.0%	76	12	84.2%	15	6	60.0%	76	28	63.2%
41		15	8	46.7%	76	26	65.8%	15	10	33.3%	76	49	35.5%
42		15	1	93.3%	76	2	97.4%	15	1	93.3%	76	10	86.8%
43		15	2	86.7%	76	7	90.8%	15	1	93.3%	76	4	94.7%
48	370	15	6	60.0%	76	11	85.5%	15	5	66.7%	76	8	89.5%
49		15	1	93.3%	76	11	85.5%	15	4	73.3%	76	9	88.2%
51		6	2	66.7%	33	16	51.5%	6	1	83.3%	32	10	68.8%
52		15	0	100.0%	76	3	96.1%	15	2	86.7%	76	14	81.6%
53	44	15	1	93.3%	76	6	92.1%	15	2	86.7%	76	10	86.8%
55	38	11	0	100.0%	53	0	100.0%	11	3	72.7%	53	9	83.0%
56	167	11	2	81.8%	53	9	83.0%	11	3	72.7%	53	9	83.0%
58	48	15	0	100.0%	75	2	97.3%	15	3	80.0%	74	10	86.5%
59		15	1	93.3%	74	4	94.6%	15	1	93.3%	74	4	94.6%
63	67	15	4	73.3%	76	25	67.1%	15	9	40.0%	76	38	50.0%
64		15	3	80.0%	75	19	74.7%	15	5	66.7%	75	15	80.0%
66		15	2	86.7%	76	12	84.2%	15	1	93.3%	76	14	81.6%
67	80	11	1	90.9%	53	3	94.3%	11	2	81.8%	53	9	83.0%
68	24	15	3	80.0%	76	14	81.6%	15	10	33.3%	76	35	53.9%
69		15	1	93.3%	76	8	89.5%	15	3	80.0%	76	10	86.8%
71	11	15	1	93.3%	76	1	98.7%	15	3	80.0%	76	19	75.0%
72	13	15	2	86.7%	76	7	90.8%	15	6	60.0%	76	16	78.9%
73	21	15	2	86.7%	76	3	96.1%	15	5	66.7%	75	38	49.3%
74		15	1	93.3%	76	6	92.1%	15	3	80.0%	76	23	69.7%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75	35	15	0	100.0%	76	2	97.4%	15	6	60.0%	76	34	55.3%
76	20	15	0	100.0%	76	4	94.7%	15	4	73.3%	76	34	55.3%
77		15	1	93.3%	76	3	96.1%	15	4	73.3%	76	26	65.8%
78		15	0	100.0%	76	3	96.1%	15	2	86.7%	76	11	85.5%
79	81	15	3	80.0%	76	14	81.6%	15	2	86.7%	75	13	82.7%
80	64	15	1	93.3%	76	9	88.2%	15	4	73.3%	75	9	88.0%
84	47	11	0	100.0%	53	3	94.3%	11	3	72.7%	53	8	84.9%
85	17	11	0	100.0%	53	1	98.1%	11	5	54.5%	53	20	62.3%
86	57	11	1	90.9%	53	5	90.6%	11	7	36.4%	53	26	50.9%
89	56	15	4	73.3%	76	16	78.9%	15	5	66.7%	76	11	85.5%
90		15	2	86.7%	76	2	97.4%	15	2	86.7%	76	8	89.5%
93		11	1	90.9%	53	7	86.8%	11	0	100.0%	52	10	80.8%
94	40	11	5	54.5%	53	11	79.2%	10	4	60.0%	52	16	69.2%
95	50	11	0	100.0%	53	1	98.1%	11	3	72.7%	53	14	73.6%
97	282	15	10	33.3%	76	28	63.2%	15	3	80.0%	76	19	75.0%
98		15	1	93.3%	76	5	93.4%	15	6	60.0%	76	17	77.6%
110	81	11	5	54.5%	53	24	54.7%	11	2	81.8%	53	5	90.6%
111	61	11	1	90.9%	53	5	90.6%	11	2	81.8%	53	5	90.6%
112	119	11	1	90.9%	53	5	90.6%	11	1	90.9%	53	6	88.7%
114	54	11	2	81.8%	53	10	81.1%	10	1	90.0%	52	1	98.1%
119	25	11	1	90.9%	53	10	81.1%	11	2	81.8%	53	5	90.6%
125	28	11	0	100.0%	53	2	96.2%	11	7	36.4%	53	13	75.5%
128	101	4	2	50.0%	23	5	78.3%	5	1	80.0%	23	2	91.3%
129	31	11	5	54.5%	53	18	66.0%	11	1	90.9%	53	7	86.8%
130		11	0	100.0%	53	4	92.5%	11	0	100.0%	53	4	92.5%
131	145	11	1	90.9%	53	5	90.6%	11	3	72.7%	53	3	94.3%
133	87	11	3	72.7%	53	22	58.5%	11	2	81.8%	53	22	58.5%
134		11	1	90.9%	53	5	90.6%	11	3	72.7%	53	11	79.2%
137	55	11	2	81.8%	51	10	80.4%	11	3	72.7%	51	13	74.5%
138		11	1	90.9%	53	7	86.8%	11	0	100.0%	53	2	96.2%
139	223	2	2	0.0%	12	2	83.3%	3	2	33.3%	12	4	66.7%
141	87	11	0	100.0%	53	3	94.3%	11	3	72.7%	53	11	79.2%
148		11	1	90.9%	53	5	90.6%	11	0	100.0%	52	9	82.7%
151	42	15	8	46.7%	76	22	71.1%	15	6	60.0%	75	22	70.7%
166	41	2	1	50.0%	12	1	91.7%	3	1	66.7%	12	3	75.0%
169	39	4	0	100.0%	23	2	91.3%	5	1	80.0%	23	4	82.6%
170	114	11	1	90.9%	50	4	92.0%	11	3	72.7%	50	12	76.0%
171	35	11	1	90.9%	53	4	92.5%	11	4	63.6%	53	9	83.0%
172	58	11	1	90.9%	53	5	90.6%	11	3	72.7%	53	18	66.0%
173	114	11	3	72.7%	53	5	90.6%	11	6	45.5%	53	21	60.4%
174	23	11	0	100.0%	53	3	94.3%	11	3	72.7%	53	11	79.2%
175	79	11	2	81.8%	53	4	92.5%	11	5	54.5%	53	13	75.5%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
176		11	1	90.9%	53	4	92.5%	11	0	100.0%	53	3	94.3%
177	69	11	1	90.9%	53	9	83.0%	11	3	72.7%	53	23	56.6%
181	60	11	4	63.6%	53	10	81.1%	10	1	90.0%	52	2	96.2%
182	49	11	2	81.8%	53	11	79.2%	11	1	90.9%	53	4	92.5%
183	77	11	3	72.7%	53	14	73.6%	11	3	72.7%	53	9	83.0%
184	42	11	1	90.9%	53	9	83.0%	11	3	72.7%	53	8	84.9%
185	44	11	2	81.8%	53	10	81.1%	11	1	90.9%	53	2	96.2%
186		11	0	100.0%	53	7	86.8%	11	1	90.9%	53	13	75.5%
190		11	5	54.5%	53	21	60.4%	11	2	81.8%	53	12	77.4%
192	17	11	1	90.9%	51	7	86.3%	11	1	90.9%	51	2	96.1%
193	58	11	3	72.7%	53	16	69.8%	11	4	63.6%	53	18	66.0%
196	60	11	1	90.9%	53	1	98.1%	11	1	90.9%	53	3	94.3%
197	38	11	7	36.4%	53	22	58.5%	11	4	63.6%	53	10	81.1%
232		15	0	100.0%	76	1	98.7%	15	0	100.0%	76	6	92.1%
233		15	3	80.0%	76	16	78.9%	15	3	80.0%	76	15	80.3%
234		15	0	100.0%	76	3	96.1%	15	0	100.0%	76	2	97.4%
236		15	0	100.0%	76	1	98.7%	15	1	93.3%	76	12	84.2%
237		15	2	86.7%	76	12	84.2%	15	1	93.3%	76	5	93.4%
239		15	5	66.7%	75	20	73.3%	15	1	93.3%	75	3	96.0%
240		15	1	93.3%	76	7	90.8%	15	3	80.0%	76	10	86.8%
241		15	6	60.0%	76	22	71.1%	15	2	86.7%	76	12	84.2%
243		11	2	81.8%	53	18	66.0%	11	1	90.9%	54	9	83.3%
244		15	0	100.0%	76	2	97.4%	15	0	100.0%	76	15	80.3%
245		4	1	75.0%	23	6	73.9%	5	0	100.0%	23	1	95.7%
280		15	0	100.0%	76	3	96.1%	15	3	80.0%	76	13	82.9%
281		15	0	100.0%	76	8	89.5%	15	2	86.7%	76	7	90.8%
283		15	6	60.0%	76	14	81.6%	15	4	73.3%	76	13	82.9%
284		15	0	100.0%	76	1	98.7%	15	2	86.7%	76	7	90.8%
290		15	0	100.0%	76	18	76.3%	15	4	73.3%	75	25	66.7%
291		15	2	86.7%	76	15	80.3%	15	3	80.0%	76	15	80.3%
300	20	15	5	66.7%	76	7	90.8%	15	8	46.7%	75	22	70.7%
301		15	1	93.3%	75	2	97.3%	15	4	73.3%	74	13	82.4%
302		14	4	71.4%	74	10	86.5%	14	6	57.1%	72	23	68.1%
305		15	5	66.7%	76	10	86.8%	14	10	28.6%	74	30	59.5%
306		15	3	80.0%	75	5	93.3%	15	4	73.3%	74	15	79.7%
307		15	3	80.0%	75	8	89.3%	15	8	46.7%	75	19	74.7%
311		15	3	80.0%	75	10	86.7%	15	5	66.7%	75	19	74.7%
316		15	2	86.7%	75	5	93.3%	15	4	73.3%	75	16	78.7%
318		15	1	93.3%	76	10	86.8%	15	7	53.3%	75	32	57.3%
319	23	15	0	100.0%	76	2	97.4%	15	7	53.3%	76	43	43.4%
329		11	1	90.9%	53	2	96.2%	11	2	81.8%	53	4	92.5%
330		13	0	100.0%	64	2	96.9%	13	4	69.2%	64	5	92.2%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
331		15	5	66.7%	76	9	88.2%	15	4	73.3%	76	10	86.8%
332		15	3	80.0%	76	8	89.5%	15	5	66.7%	76	10	86.8%
334		15	1	93.3%	76	2	97.4%	15	6	60.0%	75	10	86.7%
335		15	5	66.7%	76	12	84.2%	14	3	78.6%	74	12	83.8%
336		15	2	86.7%	76	3	96.1%	15	1	93.3%	76	5	93.4%
337		15	0	100.0%	76	4	94.7%	15	3	80.0%	76	8	89.5%
338	17	15	2	86.7%	76	17	77.6%	14	5	64.3%	74	17	77.0%
339		15	3	80.0%	76	17	77.6%	15	5	66.7%	76	16	78.9%
341		13	3	76.9%	73	12	83.6%	13	4	69.2%	73	12	83.6%
342		15	1	93.3%	76	7	90.8%	15	5	66.7%	75	13	82.7%
350	61	15	0	100.0%	58	2	96.6%	15	10	33.3%	58	32	44.8%
351		15	5	66.7%	76	8	89.5%	15	6	60.0%	76	32	57.9%
352		15	2	86.7%	76	6	92.1%	14	4	71.4%	73	18	75.3%
353	21	15	3	80.0%	55	5	90.9%	15	9	40.0%	55	14	74.5%
354	28	15	4	73.3%	76	7	90.8%	14	9	35.7%	75	23	69.3%
355	Cncld	14	2	85.7%	75	7	90.7%	13	5	61.5%	74	18	75.7%
364	Cncld	14	6	57.1%	75	11	85.3%	13	6	53.8%	74	14	81.1%
365	Cncld	14	2	85.7%	75	4	94.7%	13	8	38.5%	74	24	67.6%
370	No OS	15	3	80.0%	76	5	93.4%	15	6	60.0%	76	15	80.3%
371	43	15	1	93.3%	76	1	98.7%	15	3	80.0%	76	7	90.8%
380	23	15	3	80.0%	76	13	82.9%	15	4	73.3%	76	17	77.6%
381		15	1	93.3%	76	2	97.4%	15	2	86.7%	76	9	88.2%
382	No OS	15	0	100.0%	76	2	97.4%	15	4	73.3%	76	19	75.0%
383	36	15	4	73.3%	76	9	88.2%	15	9	40.0%	75	31	58.7%
390		7	3	57.1%	60	7	88.3%	7	3	57.1%	60	19	68.3%
391		7	1	85.7%	61	1	98.4%	7	2	71.4%	60	14	76.7%
392	24	15	1	93.3%	76	3	96.1%	15	9	40.0%	75	24	68.0%
393		15	1	93.3%	76	6	92.1%	15	4	73.3%	75	19	74.7%
417		11	1	90.9%	50	9	82.0%	10	0	100.0%	47	1	97.9%
425		11	0	100.0%	50	1	98.0%	11	0	100.0%	50	1	98.0%
448	Cncld	15	8	46.7%	17	9	47.1%	14	8	42.9%	15	8	46.7%
449		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
470	72	11	3	72.7%	53	8	84.9%	11	1	90.9%	53	8	84.9%
471		11	1	90.9%	50	1	98.0%	11	0	100.0%	50	0	100.0%
473		11	0	100.0%	53	3	94.3%	11	0	100.0%	53	1	98.1%
474	27	11	5	54.5%	51	18	64.7%	10	7	30.0%	47	18	61.7%
475		11	0	100.0%	53	0	100.0%	11	0	100.0%	53	1	98.1%
478		11	1	90.9%	51	11	78.4%	11	0	100.0%	51	6	88.2%
479	30	11	3	72.7%	53	7	86.8%	11	1	90.9%	53	2	96.2%
486	60	11	1	90.9%	54	8	85.2%	11	2	81.8%	53	8	84.9%
490		11	1	90.9%	30	6	80.0%	11	0	100.0%	30	2	93.3%
494	21	11	0	100.0%	55	9	83.6%	11	3	72.7%	52	10	80.8%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Train	Late	Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
495		11	0	100.0%	53	2	96.2%	11	0	100.0%	53	1	98.1%
500		15	1	93.3%	76	6	92.1%	15	2	86.7%	75	7	90.7%
502		15	0	100.0%	76	6	92.1%	15	1	93.3%	75	17	77.3%
503		15	3	80.0%	73	11	84.9%	15	4	73.3%	72	19	73.6%
504		15	2	86.7%	76	7	90.8%	15	5	66.7%	76	24	68.4%
505		15	2	86.7%	76	12	84.2%	15	2	86.7%	74	15	79.7%
506		15	3	80.0%	75	12	84.0%	15	1	93.3%	74	10	86.5%
507		15	2	86.7%	76	9	88.2%	15	3	80.0%	76	25	67.1%
508		15	2	86.7%	74	13	82.4%	15	5	66.7%	74	18	75.7%
509		15	1	93.3%	76	5	93.4%	15	7	53.3%	76	20	73.7%
511		15	1	93.3%	76	5	93.4%	15	3	80.0%	76	15	80.3%
516		13	0	100.0%	74	9	87.8%	13	4	69.2%	74	32	56.8%
517	22	15	0	100.0%	76	1	98.7%	15	6	60.0%	75	28	62.7%
518		15	0	100.0%	76	13	82.9%	15	9	40.0%	76	45	40.8%
519		13	1	92.3%	74	4	94.6%	13	2	84.6%	74	11	85.1%
520		11	2	81.8%	49	5	89.8%	10	0	100.0%	48	2	95.8%
521		11	0	100.0%	52	0	100.0%	11	1	90.9%	52	4	92.3%
522		11	3	72.7%	52	7	86.5%	10	1	90.0%	51	5	90.2%
523		11	0	100.0%	52	0	100.0%	11	3	72.7%	52	7	86.5%
524		11	0	100.0%	52	2	96.2%	11	1	90.9%	52	4	92.3%
525		11	1	90.9%	52	2	96.2%	10	1	90.0%	51	6	88.2%
526		11	4	63.6%	52	10	80.8%	10	1	90.0%	51	5	90.2%
527		11	0	100.0%	52	1	98.1%	11	1	90.9%	52	3	94.2%
528		11	1	90.9%	52	6	88.5%	11	2	81.8%	52	12	76.9%
529		11	0	100.0%	52	3	94.2%	11	2	81.8%	52	9	82.7%
530		6	0	100.0%	6	0	100.0%	6	0	100.0%	6	0	100.0%
531		11	0	100.0%	52	1	98.1%	11	2	81.8%	52	5	90.4%
532		11	2	81.8%	52	3	94.2%	11	1	90.9%	52	8	84.6%
534	18	11	1	90.9%	49	6	87.8%	11	2	81.8%	49	5	89.8%
535		10	3	70.0%	48	4	91.7%	9	1	88.9%	47	2	95.7%
536		11	2	81.8%	52	6	88.5%	10	1	90.0%	51	2	96.1%
537		11	1	90.9%	52	4	92.3%	10	1	90.0%	51	2	96.1%
538		11	1	90.9%	52	7	86.5%	11	3	72.7%	52	8	84.6%
539	12	6	0	100.0%	6	0	100.0%	6	4	33.3%	6	4	33.3%
540		11	3	72.7%	52	7	86.5%	10	1	90.0%	49	2	95.9%
541		11	2	81.8%	52	7	86.5%	11	4	63.6%	52	15	71.2%
542		11	0	100.0%	52	3	94.2%	11	1	90.9%	51	11	78.4%
543		11	0	100.0%	52	6	88.5%	11	1	90.9%	52	13	75.0%
544		11	1	90.9%	51	3	94.1%	11	3	72.7%	51	7	86.3%
545		11	1	90.9%	52	5	90.4%	11	1	90.9%	51	5	90.2%
547		11	0	100.0%	52	4	92.3%	11	2	81.8%	52	9	82.7%
548		11	2	81.8%	52	10	80.8%	11	1	90.9%	52	6	88.5%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
549		11	3	72.7%	49	13	73.5%	9	0	100.0%	46	6	87.0%
550		6	2	66.7%	6	2	66.7%	6	1	83.3%	6	1	83.3%
551		11	1	90.9%	52	7	86.5%	11	1	90.9%	50	7	86.0%
562		15	3	80.0%	74	11	85.1%	15	3	80.0%	73	9	87.7%
564		15	1	93.3%	74	7	90.5%	14	2	85.7%	70	12	82.9%
566		15	1	93.3%	74	6	91.9%	15	2	86.7%	71	8	88.7%
572		15	0	100.0%	73	6	91.8%	15	0	100.0%	72	14	80.6%
573		15	2	86.7%	74	11	85.1%	14	0	100.0%	72	8	88.9%
577		15	1	93.3%	72	6	91.7%	15	4	73.3%	68	6	91.2%
580		15	0	100.0%	74	2	97.3%	15	1	93.3%	74	8	89.2%
581		15	0	100.0%	74	7	90.5%	15	2	86.7%	74	14	81.1%
582		15	2	86.7%	74	6	91.9%	15	1	93.3%	72	5	93.1%
586		15	3	80.0%	74	14	81.1%	15	0	100.0%	71	9	87.3%
587		15	0	100.0%	74	3	95.9%	15	0	100.0%	72	9	87.5%
591		15	0	100.0%	74	1	98.6%	15	0	100.0%	74	6	91.9%
593		15	2	86.7%	74	11	85.1%	14	0	100.0%	67	5	92.5%
595		15	1	93.3%	73	15	79.5%	15	0	100.0%	72	10	86.1%
600		11	0	100.0%	53	1	98.1%	11	0	100.0%	53	4	92.5%
601	89	11	8	27.3%	53	27	49.1%	11	1	90.9%	53	14	73.6%
605	129	11	10	9.1%	53	31	41.5%	11	2	81.8%	52	4	92.3%
607	12	11	0	100.0%	53	3	94.3%	11	2	81.8%	52	3	94.2%
609		11	1	90.9%	52	2	96.2%	11	0	100.0%	52	3	94.2%
620		11	4	63.6%	52	13	75.0%	11	0	100.0%	50	2	96.0%
637	47	2	1	50.0%	13	1	92.3%	3	1	66.7%	13	1	92.3%
639		11	4	63.6%	53	14	73.6%	11	0	100.0%	53	4	92.5%
640		11	1	90.9%	53	3	94.3%	11	8	27.3%	53	26	50.9%
641	25	11	5	54.5%	53	10	81.1%	11	3	72.7%	53	10	81.1%
642	15	11	1	90.9%	52	3	94.2%	11	2	81.8%	52	6	88.5%
643	13	11	3	72.7%	53	10	81.1%	11	4	63.6%	52	7	86.5%
644	55	11	3	72.7%	53	8	84.9%	11	4	63.6%	53	9	83.0%
645	55	11	1	90.9%	53	4	92.5%	11	3	72.7%	53	9	83.0%
646	63	11	4	63.6%	53	11	79.2%	11	9	18.2%	52	29	44.2%
647	67	11	1	90.9%	53	3	94.3%	11	1	90.9%	53	13	75.5%
648	83	11	4	63.6%	53	10	81.1%	11	3	72.7%	53	7	86.8%
649	14	11	4	63.6%	53	10	81.1%	11	1	90.9%	52	8	84.6%
650	18	11	1	90.9%	53	10	81.1%	11	5	54.5%	53	12	77.4%
651	22	11	0	100.0%	53	5	90.6%	11	3	72.7%	53	16	69.8%
652	20	11	1	90.9%	53	9	83.0%	11	3	72.7%	52	11	78.8%
653	26	11	3	72.7%	53	11	79.2%	11	1	90.9%	53	15	71.7%
654	14	11	5	54.5%	53	10	81.1%	11	2	81.8%	53	4	92.5%
655	36	11	4	63.6%	51	16	68.6%	11	5	54.5%	50	13	74.0%
656		11	3	72.7%	53	10	81.1%	11	0	100.0%	53	5	90.6%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
657		11	0	100.0%	53	3	94.3%	11	0	100.0%	53	9	83.0%
658	18	11	1	90.9%	53	8	84.9%	11	2	81.8%	53	8	84.9%
680	31	11	0	100.0%	54	2	96.3%	11	3	72.7%	54	6	88.9%
681	20	11	1	90.9%	54	3	94.4%	11	3	72.7%	54	16	70.4%
682	30	11	0	100.0%	54	0	100.0%	11	3	72.7%	54	13	75.9%
683	33	11	0	100.0%	37	3	91.9%	11	2	81.8%	37	11	70.3%
684	24	11	1	90.9%	36	5	86.1%	11	1	90.9%	36	9	75.0%
685	34	11	2	81.8%	53	6	88.7%	11	2	81.8%	53	15	71.7%
686	33	11	1	90.9%	54	14	74.1%	11	3	72.7%	54	13	75.9%
687		11	2	81.8%	54	8	85.2%	11	4	63.6%	54	10	81.5%
688		11	0	100.0%	54	1	98.1%	11	2	81.8%	54	14	74.1%
701		8	3	62.5%	8	3	62.5%	8	2	75.0%	8	2	75.0%
702		15	2	86.7%	76	17	77.6%	15	3	80.0%	75	22	70.7%
703		15	3	80.0%	76	18	76.3%	15	3	80.0%	76	19	75.0%
704		8	2	75.0%	8	2	75.0%	7	3	57.1%	7	3	57.1%
710		15	6	60.0%	76	30	60.5%	15	1	93.3%	76	29	61.8%
711		15	1	93.3%	72	5	93.1%	12	3	75.0%	65	10	84.6%
712		15	3	80.0%	76	20	73.7%	15	5	66.7%	75	28	62.7%
713		14	3	78.6%	75	12	84.0%	12	4	66.7%	67	31	53.7%
714		15	6	60.0%	70	25	64.3%	15	4	73.3%	65	20	69.2%
715		15	4	73.3%	76	26	65.8%	14	7	50.0%	72	36	50.0%
716	30	15	7	53.3%	76	30	60.5%	15	7	53.3%	75	30	60.0%
717		15	3	80.0%	67	16	76.1%	15	6	60.0%	62	19	69.4%
718		15	9	40.0%	76	31	59.2%	14	5	64.3%	75	21	72.0%
719		15	3	80.0%	76	27	64.5%	15	4	73.3%	74	20	73.0%
761		15	0	100.0%	74	3	95.9%	15	0	100.0%	74	9	87.8%
765		15	1	93.3%	74	8	89.2%	15	1	93.3%	74	14	81.1%
769		15	1	93.3%	74	5	93.2%	15	1	93.3%	72	12	83.3%
770		15	0	100.0%	74	7	90.5%	15	1	93.3%	74	10	86.5%
774		15	0	100.0%	74	6	91.9%	15	2	86.7%	73	13	82.2%
779		15	0	100.0%	74	4	94.6%	15	0	100.0%	73	9	87.7%
784		15	2	86.7%	74	8	89.2%	15	7	53.3%	73	36	50.7%
785		15	0	100.0%	74	0	100.0%	15	1	93.3%	74	8	89.2%
790		15	0	100.0%	74	5	93.2%	15	0	100.0%	74	7	90.5%
794		15	1	93.3%	74	6	91.9%	15	2	86.7%	73	12	83.6%
821	17	15	0	100.0%	76	3	96.1%	15	6	60.0%	76	46	39.5%
822		15	0	100.0%	76	3	96.1%	15	2	86.7%	76	46	39.5%
1333		15	4	73.3%	76	8	89.5%	15	6	60.0%	75	32	57.3%
1340		15	0	100.0%	76	3	96.1%	15	6	60.0%	76	19	75.0%
1689		5	0	100.0%	16	1	93.8%	5	0	100.0%	17	0	100.0%
2103	16	11	1	90.9%	52	4	92.3%	11	1	90.9%	52	2	96.2%
2104		11	1	90.9%	23	3	87.0%	11	1	90.9%	23	3	87.0%

Amtrak On Time Performance

Trains Arriving Through: 12/15/2025

28-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2107	82	11	2	81.8%	53	9	83.0%	11	2	81.8%	51	2	96.1%
2108	58	11	2	81.8%	53	4	92.5%	11	2	81.8%	51	2	96.1%
2117		11	3	72.7%	23	6	73.9%	11	2	81.8%	23	3	87.0%
2121	18	11	2	81.8%	51	5	90.2%	11	1	90.9%	51	4	92.2%
2122		11	0	100.0%	53	6	88.7%	11	0	100.0%	53	3	94.3%
2124		9	2	77.8%	39	6	84.6%	9	1	88.9%	39	2	94.9%
2150	44	11	1	90.9%	53	10	81.1%	11	2	81.8%	53	11	79.2%
2151	60	11	0	100.0%	53	0	100.0%	11	4	63.6%	52	10	80.8%
2152	122	11	1	90.9%	49	3	93.9%	11	8	27.3%	48	17	64.6%
2153		11	0	100.0%	53	6	88.7%	11	3	72.7%	53	12	77.4%
2154	65	11	3	72.7%	53	17	67.9%	11	6	45.5%	51	27	47.1%
2155		11	1	90.9%	53	3	94.3%	11	6	45.5%	51	15	70.6%
2159	25	11	0	100.0%	52	1	98.1%	11	4	63.6%	52	11	78.8%
2162		11	0	100.0%	53	2	96.2%	11	2	81.8%	52	11	78.8%
2163	20	11	0	100.0%	53	4	92.5%	11	4	63.6%	53	14	73.6%
2166	16	11	0	100.0%	53	5	90.6%	11	3	72.7%	51	9	82.4%
2167	73	11	1	90.9%	53	6	88.7%	11	3	72.7%	53	11	79.2%
2168		11	1	90.9%	53	3	94.3%	11	1	90.9%	53	7	86.8%
2169	115	11	7	36.4%	49	17	65.3%	11	8	27.3%	49	23	53.1%
2170		11	3	72.7%	53	10	81.1%	11	2	81.8%	53	11	79.2%
2172		11	0	100.0%	53	6	88.7%	11	3	72.7%	53	10	81.1%
2173	48	11	3	72.7%	52	10	80.8%	11	2	81.8%	52	20	61.5%
2190	21	11	2	81.8%	53	7	86.8%	10	2	80.0%	52	6	88.5%
2193	31	11	1	90.9%	52	2	96.2%	11	3	72.7%	52	12	76.9%
2275	40	2	1	50.0%	12	3	75.0%	3	2	33.3%	12	6	50.0%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2103	WAS	16	OTH	67	OTH	67	NWK-MET	AM	Lost time - N.A.R.
2107	WAS	82	ENG	64	ENG	35	PHL-WIL	AM	Air / Brake, PC 2024, Stopped at Hook, with brake issues. Cut out all brakes release switch.
2108	NYP	58	WTR	70	WTR	63	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN TRAIN ICE WITH THE DOORS AND BRAKES
2121	WAS	18	ITI	25	ITI	25	NYP-NYP	AM	Service, turn, or wye train, 2108, LATE TURN OFF AM2108
2150	BOS	44	WTR	51	WTR	47	BAL-XPV	AM	Ice / snow on or under equipment, Control Point, GUNPOW, 23 SWITCH OUT OF CORRESPONDENCE
2151	WAS	60	DMW	41	DMW	41	NHV-STM	MN	Held for or routed around MW work or equipment Reversed Direction to Change Tracks. Switch Failure, Control Point, STM
2152	BOS	122	POL	86	POL	45	RTE-BBY	AM	Fire department hold, HELD DUE TO FIRE ON MP 224.69 ON TRK 1
2154	BOS	65	POL	65	POL	27	BBY-BBY	AM	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
2159	WAS	25	OTH	10	SMW	7	XSH-NYP	AM	Scheduled in track usage program, Other, XPB, HELD FOR SINGLE TRACKING PELHAM BAY TO LEGGETT A/C SCHEDULED MAINTENANCE
2163	WAS	20	PTI	17	PTI	9	BWI-XNY	AM	Follow, 131, Control Point, .
2166	BOS	16	PTI	12	PTI	10	NWK-NYP	AM	Cross over or go around, AM97, Other, XBH, LATE AM97 XING AHEAD
2167	WAS	73	POL	90	POL	52	BOS-BOS	AM	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
2169	WAS	115	ITI	99	ITI	99	BOS-BOS	AM	Service, turn, or wye train, 2152, departed late due to late turn of AM2152
2173	WAS	48	CTI	18	DSR	15	NHV-STM	MN	Per bulletin Control Point, 248, 30, 1, Milepost, 42, 41.7, 15, 2, Milepost, 41.7, 40.6, 30, 2, Milepost, 33.6, 32.3, 30, 2
2190	BOS	21	ENG	17	ENG	14	PVD-PVD	AM	Other electrical failure, 2038, HELD TO CLOSE MCB
2193	NYP	31	CTI	13	SVS	13	BOS-BOS	AM	Water, commissary, toilet/trash dumping, AM2193/PC2024 DP South Station at 619P/14" late, a/c return to SHSY to refill water supply
2275	WAS	40	ITI	23	ITI	23	BOS-BOS	AM	Service, turn, or wye train, 2250, departed late due to late turn of AM2250

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
67	NPN	80	WTR	103	WTR	69	XPV-BAL	AM	Ice / snow on or under equipment, Control Point, GUNPOW, 23 SWITCH OUT OF CORRESPONDENCE	
84	NYP	47	WTR	28	WTR	19	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE TRAINS DUE TO SNOW AND ICE AND FROZEN DOORS	
85	RVM	17	DSR	14	ADA	6	RVR-RVR	CS	Wheelchair Lift off. Frozen doors	
86	BOS	57	WTR	48	WTR	28	WIL-PHL	AM	Ice / snow on or under equipment, Control Point, PHL, reversed back to opr No.1 trk a/c 77 sw fails normal	
94	BOS	40	HLD	28	PTI	12	XPV-WIL	AM	Follow, 184, Control Point, .	
95	NFK	50	CTI	32	SVS	14	WAS-WAS	AM	Planned set out / pick out of locomotives, cars or section of train, HAD TO SET OUT A GOOD COACH 82985 DUE TO BOST NOT SETTING IT OUT BEFORE DP TIME. NORFOLK CAN NOT HANDLE 10 CAR 1 HAD TO COME OFF	
110	NYP	81	WTR	86	WTR	80	PHL-PHL	AM	Ice / snow on or under equipment, Control Point, ., Routine inspections, Late release from yard	
111	WAS	61	ITI	31	ITI	31	NYP-NYP	AM	Service, turn, or wye train, 0, LATE TURN OF EQUIPMENT A/C INCLEMENT WEATHER CAUSING MULTIPLE MW ISSUES.	
112	NYP	119	WTR	101	WTR	92	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVING TURN TRAINS, FRONZEN DOORS	
114	NYP	54	WTR	36	WTR	34	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN EQUIPMENT AND FROZEN DOORS.	
119	WAS	25	PTI	15	PTI	9	BWI-XNY	AM	Follow, 95, Control Point, .	
125	NPN	28	WTR	25	CTI	9	QAN-FBG	CS	Follow vre, Milepost, 78.9, 59.3	
128	NYP	101	SYS	75	SYS	53	WAS-WAS	AM	Other late crew, CREW OFF LATE INBOUND A87	
129	WAS	31	WTR	39	WTR	20	TRE-XHM	AM	Ice / snow on or under equipment, Other, XGY-XHM, DED ACTIVATED AT MP73.5 A/C SNOW AND ICE BUILD UP.	
131	WAS	145	ITI	135	ITI	135	NYP-NYP	AM	Service, turn, or wye train, 112, LATE TURN OFF AM112	
133	WAS	87	ITI	64	ITI	64	NYP-NYP	AM	Service, turn, or wye train, 112, LATE TURN OFF FOR AM112	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
137	WAS	55	POL	49	POL	49	BOS-BOS	AM	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
139	WAS	223	ITI	165	ITI	165	BOS-BOS	AM	Service, turn, or wye train, 162, AM139 dp BOS 2'45" late a/c late AM162 turn and main res issues on e/619
141	NFK	87	CTI	26	FTI	15	ASD-RVR	CS	Follow m705, Milepost w/Letters, ASD, RVR
151	RNK	42	WTR	59	WTR	29	XPV-BAL	AM	Ice / snow on or under equipment, Control Point, GUNPOW, 23 SWITCH OUT OF CORRESPONDENCE
166	BOS	41	HLD	19	DBB	10	NHV-NLC	AM	Stuck open bridges, Milepost w/Letters, NHV, NLC, Held due to Conn bridge would not close, after closed, no signal, C&S on scene 241 issued NHV-NLC
169	PHL	39	DBB	25	DBB	25	NLC-NHV	AM	Stuck open bridges, Milepost w/Letters, NLC, NHV, Held due to Conn bridge would not close, after closed, no signal, C&S on scene 241 issued NLC-NHV
170	BOS	114	WTR	61	WTR	52	BAL-XPV	AM	Ice / snow on or under equipment, Control Point, GUNPOW, 23 SWITCH OUT OF CORRESPONDENCE
171	RNK	35	DCS	34	DCS	34	CLP-CVS	NS	Power switch failure Control Point, Orange
172	BOS	58	WTR	31	WTR	25	NWK-NYP	AM	Snow removal equipment working ahead, Other, XBH-NYP, HELD FOR SINGLE TRACKING DUE TO ICE PATROL
173	WAS	114	WTR	86	WTR	55	BOS-BOS	AM	Ice / snow on or under equipment, Other, BOS, Departing South Station late due to consist thawing out in S&I building
174	BOS	23	WTR	22	CTI	10	STM-BRP	MN	Blocked from station track Waterbury clearing the station, mnrr, Control Point, BRP
175	WAS	79	ITI	58	ITI	45	BOS-BOS	AM	Service, turn, or wye train, 170, late departure due to late turn of AM170
177	PHL	69	CTI	43	ITI	20	BOS-BOS	AM	Service, turn, or wye train, 172, departed late due to late turn of AM172
181	WAS	60	DET	50	DET	50	NYP-NYP	AM	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
182	NYP	49	WTR	54	WTR	31	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, 111/182 ARRIVED WAS 923A 61" LATE DUE TO WEATHER FROZEN DOOR

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
183	WAS	77	DET	65	DET	65	NYP-NYP	AM	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS	
184	BOS	42	WTR	44	WTR	21	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE TURN TRAIN AND FORZEN DOORS	
185	WAS	44	ITI	49	ITI	49	NYP-NYP	AM	Service, turn, or wye train, 110, LATE TURN OFF AM110	
192	NYP	17	PTI	26	PTI	14	TRE-NWK	AM	Follow, AM136, Other, TRE-NWK	
193	WAS	58	ITI	38	ITI	38	NYP-NYP	AM	Service, turn, or wye train, 84, LATE TURN OFF OF AM84	
196	NYP	60	SYS	48	SYS	48	WAS-WAS	AM	Other late crew, CREW ARRIVED LATE Off 131 delayed arrival	
197	WAS	38	ITI	29	ITI	29	NYP-NYP	AM	Service, turn, or wye train, 134, LATE TURN OFF OF AM134	
470	SPG	72	CON	70	CON	70	NHV-NHV	AM	Hold for connecting train	
474	SPG	27	CON	19	CON	19	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM174	
479	NHV	30	ITI	29	ITI	29	GFD-GFD	MA	Late turn from late 486 486	
486	GFD	60	CON	24	CON	24	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM86	
494	GFD	21	CON	34	CON	34	NHV-NHV	AM	Hold for connecting train, departed late due to late connection of AM94	
53	SFA	44	FTI	118	FTI	45	XSA-XJG	CS	Follow M693 ahead looking out for possible broken rail @ A 525.7, M69314, Control Point, McIntosh, Control Point, Jesup	
79	CLT	81	FTI	36	DMW	25	PTB-RMT	CS	Defect detector malfunctions at WHITAKERS Other, whitakers	
80	NYP	64	DCS	34	FTI	33	RMT-PTB	CS	Meet C344, C410, Control Point, Enfield	
601	HAR	89	WTR	86	WTR	73	PHL-PHL	AM	Ice / snow on or under equipment, Control Point, .., Late release from yard, brakes won't release (due to ice build up and cold)	
605	HAR	129	WTR	116	WTR	104	PHL-PHL	AM	Ice / snow on or under equipment, Control Point, .., Set came in late and the crew had to replace a car. Set was back together for mechanical at 0440.	
607	HAR	12	WTR	15	CTI	8	NWK-PJC	AM	Follow, NJT, NJ3503, Other, NWK-PJC	
637	PHL	47	CAR	23	CAR	23	NYP-NYP	AM	Door, N/A, AS PER PSSCC, DOOR ISSUES. NO CAR NUMBER AND DOOR SPECIFIED.	

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
641	HAR	25	WTR	14	DCS	8	PJC-XHM	AM	Power switch failure, Other, PJC-TRE, OPR NO.4 TRK A/C POWER SWITCH FAILURE HAM INT
642	NYP	15	WTR	14	CTI	9	PAO-PHL	AM	Follow, Septa, 9502, Control Point, .
643	HAR	13	OTH	7	BSP	4	EXT-EXT	AM	Addition to TSRB a/c bridge strike, Control Point, .
644	NYP	55	WTR	59	WTR	53	HAR-HAR	AM	Ice / snow on or under equipment, Control Point, ., Late turn off Amtrak 601
645	HAR	55	ITI	29	ITI	29	NYP-NYP	AM	Service, turn, or wye train, 644, LATE TURN OFF AM644
646	NYP	63	WTR	51	WTR	38	HAR-HAR	AM	Ice / snow on or under equipment, Control Point, ., Late turn a/c Set came in late and the crew had to replace a car.
647	HAR	67	ITI	51	ITI	51	NYP-NYP	AM	Service, turn, or wye train, 648, LATE TURN OFF OF AM648
648	NYP	83	WTR	80	WTR	67	HAR-HAR	AM	Ice / snow on or under equipment, Control Point, ., Late turn off Amtrak 605 a/c Set came in late and the crew had to replace a car
649	HAR	14	PTI	20	PTI	11	NYP-NYP	AM	Cross over or go around, AM56, Other, HLD ON LOOPS A/C AM56 XING AHEAD
650	NYP	18	OTH	12	SMW	8	ELT-MJY	AM	Diversions around M/W work, Control Point, Rheems, Held for Amtrak 643 a/c No.1 trk o/s
651	HAR	22	OTH	13	WTR	5	DOW-PAR	AM	Wet / slippery rail, Control Point, .
652	NYP	20	ENG	19	ENG	19	PHL-PHL	AM	Air / Brake, E/616, met mech for air leak
653	HAR	26	DCS	11	DCS	11	NYP-NYP	AM	Power switch failure, Other, NYP, NECESSARY TO REVERSE INTO LINE 1 TO REROUTE A/C 89 SW. FAILURE "A" TOWER
654	NYP	14	WTR	21	ITI	13	HAR-HAR	AM	Service, turn, or wye train, 645, late turn off 645
655	HAR	36	PTI	17	PTI	7	NWK-TRE	AM	Follow, AM197, Other, NWK-TRE
658	NYP	18	PTI	21	PTI	9	NWK-NYP	AM	Follow, AM138, Other, NWK-NYP
20	NYP	44	SVS	85	SVS	72	MEI-TCL	NS	Pick up equipment Replace main res hose
680	BON	31	ENG	20	ENG	20	HHL-WOB	MT	PTC- Cutout due to unrecoverable penalty 90214
681	BRK	20	PTI	10	PTI	10	POR-FRE	CS	Meet 684, Control Point, Fields

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
682	BON	30	DCS	16	DCS	12	HHL-WOB	MT	Issue with automatic road crossing protection Other, main st
683	BRK	33	PTI	39	PTI	28	EXR-DHM	CS	Meet 684, Control Point, rockingham
684	BON	24	ENG	22	ENG	22	BRK-FRE	CS	Traction motor 122
685	BRK	34	DCS	17	DCS	9	BON-WOB	MT	Issue with automatic road crossing protection Control Point, high st
686	BON	33	DCS	15	ENG	14	DOV-DHM	CS	Loading problem Not loading amps, Reset fault, recovered, 87
63	TWO	67	PTI	42	CAR	29	ALB-ALB	AM	Water pump 48159
68	NYP	24	PTI	20	PTI	17	PLB-WSP	DH	Meet 69, Control Point, 148
48	NYP	370	CAR	144	CAR	98	XTF-XH6	NS	Air / Brake / Wheel 62009, Brakes sticking on both A and B end of car. Cut out both trucks per CNOC mechanical. Heavy block of solid ice around cut out valve. Melt And break away ice to access.
448	BOS	Tn Cancelled							
71	CLT	11	DCS	17	DCS	15	DNC-GRO	NS	Restrictive signal(s) from unknown cause Restricted speed w DND to Funston, Dark signal , Other, W DNC
72	RGH	13	DSR	9	DCS	7	KAN-SAL	NS	Restrictive signal(s) from unknown cause Red/stop, Control Point, Salisbury
73	CLT	21	DCS	11	DCS	11	DNC-BNC	NS	Restrictive signal(s) from known wayside signal failure Signal at 52.1nc was dark; restricted speed to Funston., Approach/ west Durham , Milepost w/Letters, 54.3nc, 49.8nc
75	CLT	35	PTI	24	PTI	24	CYN-DNC	NS	Meet #Am72, Control Point, Nelson
76	RGH	20	PTI	26	PTI	26	GRO-DNC	NS	Meet #Am79, Control Point, Functon
89	SAV	56	FTI	52	FTI	20	CHS-YEM	CS	Meet M410, Control Point, A 388.4
97	MIA	282	ITI	196	ITI	196	NYP-NYP	AM	Service, turn, or wye train, 98
55	WAS	38	OTH	39	TRS	16	MDN-MDN	AM	Unticketed or fare evading passenger, Other, MDN, delay due to fate evading psngr MDN
56	SAB	167	WTR	156	WTR	152	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN EQUIPMENT AND FROZEN DOORS
40	CHI	36	SVS	85	SVS	64	CLE-ELY	NS	Fuel Stop to meet dual truck at Industrial Park West, Other, 188
534	SAC	18	MBO	31	MBO	31	MTZ-SUI	UP	For maritime traffic Control Point, RV033

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
539	SJC	12	PTI	20	PTI	12	SUI-MTZ	UP	Meet 530, Control Point, RV038
517	PDX	22	FTI	22	FTI	11	STW-EVR	BN	Cross over or go around Siding, English, BNSF
58	CHI	48	DSR	51	DCS	18	EFG-MAT	CC	Flagged signal at MP 199.5 Restricted speed, Milepost, 199.2, 196.8
7	SEA	48	FTI	194	FTI	91	XST-SCD	BN	BNSF 5529 went into emergency blocking us behind them Milepost, 15.5, 15.5, BNSf 5529
821	FTW	17	DSR	23	FTI	14	OKC-NOR	BN	Meet bnsf 7434, Other, flynn
338	CHI	17	CTI	14	PTI	6	SVT-XRO	ME	Meet 7 / 337, Control Point, XRO
350	PNT	61	PTI	29	PTI	29	XB0-XA5	MI	Meet 353, Siding, albion
353	CHI	21	ADA	16	FTI	11	XA5-XB0	CC	Cross Traffic n/a, Control Point, baron
354	PNT	28	FTI	15	FTI	15	DET-ROY	CC	Cross over or go around 5983, Control Point, Moterm
355	CHI	Trn Cancelled	CAR	183	CAR	183	ARB-JXN	MI	Air / Brake / Wheel ID4111, Valve / seal for the main break system for the car 4111 broke and leak air
364	PTH	Trn Cancelled							
365	CHI	Trn Cancelled							
370	GRR	No OS Rpt	CAR	10	CAR	10	CHI-CHI	AM	Toilet ID4120, ID4206, Two restrooms not working. Ordered out of Chicago with only 50 percent restrooms working.
371	CHI	43	POL	46	POL	46	SJM-XPI	CS	Fire department hold Fire ahead per dispatcher
716	BFD	30	TCC	37	TCC	29	MCD-MDR	BN	PTC- Train speed selector switch set incorrect C8304, Speedometer and PTC 8 miles an hour off caused penalty
3	LAX	359	DCS	161	DCS	88	GBB-FMD	BN	Power switch failure Met 4 BN trains as well ... 7613 6068 8369 8189, Control Point, Ormonde
4	CHI	48	SYS	82	SYS	68	KCY-KCY	KC	Crew rest Control Point, kansas city
21	SAS	139	FTI	278	FTI	130	LRK-MVN	UP	Meet Frt crew inspection of train due to wheel impact detector., up 7103, Other, Traskwood
300	CHI	20	FTI	29	FTI	25	SPI-LCN	UP	Meet UP 5528, Siding, Ridgley

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/15/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
380	CHI	23	CAR	19	DMW	6	QCY-MAC	BN	Held for broken rail Control Point, East Macomb	
382	CHI	No OS Rpt	DMW	20	DMW	20	LAG-XUA	BN	Held for or routed around MW work or equipment Wait for Metra- unable to use track 2 due to MOW., Control Point, cicero	
383	QCY	36	CAR	41	CAR	40	CHI-CHI	AM	Door 48181, Exterior side doors wouldn't close in yard	
392	CHI	24	DSR	19	PTI	18	MAT-CHM	CC	Meet Am 393, Control Point, N Tuscola	
319	KCY	23	DCS	34	DCS	20	PON-BNL	UP	Wayside detector failure including false actuation Also had to go to the the next detector 30 mph, Milepost, 104.3, 104.3	

Amtrak Initial Terminal Details

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/15/2025

Terminal	Train	Date	Late	Delay	Cause
HAR	644	12/15	53	53	Ice / snow on or under equipment, Control Point, ., Late turn off Amtrak 601
HAR	646	12/15	38	38	Ice / snow on or under equipment, Control Point, ., Late turn a/c Set came in late and the crew had to replace a car.
HAR	648	12/15	67	67	Ice / snow on or under equipment, Control Point, ., Late turn off Amtrak 605 a/c Set came in late and the crew had to replace a car
HAR	654	12/15	13	13	Service, turn, or wye train, 645, late turn off 645
NFK	94	12/15	3	3	Passenger and/or baggage Frozen doors, only able to open one door and board safely
PGH	42	12/15	4	4	Follow Wait for signal at Pitt due to late departure of 41, 41, Control Point, Pitt
PHL	110	12/15	80	80	Ice / snow on or under equipment, Control Point, ., Routine inspections, Late release from yard
PHL	151	12/15	1		
PHL	190	12/15	4	4	Ice / snow on or under equipment, Control Point, ., FROZEN DOORS A/C WEATHER.
PHL	601	12/15	73	73	Ice / snow on or under equipment, Control Point, ., Late release from yard, brakes won't release (due to ice build up and cold)
PHL	605	12/15	104	104	Ice / snow on or under equipment, Control Point, ., Set came in late and the crew had to replace a car. Set was back together for mechanical at 0440.
WAS	56	12/15	152	152	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN EQUIPMENT AND FROZEN DOORS
WAS	112	12/15	92	92	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVING TURN TRAINS, FRONZEN DOORS
WAS	114	12/15	34	34	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN EQUIPMENT AND FROZEN DOORS.
WAS	136	12/15	114	114	Ice / snow on or under equipment, Control Point, K INTERLOCKING, legacy delay of push-pull set originating in WAS as 112/131 late turn due to inclement weather and frozen doors
WAS	182	12/15	31	31	Ice / snow on or under equipment, Control Point, WAS, 111/182 ARRIVED WAS 923A 61" LATE DUE TO WEATHER FROZEN DOOR
WAS	184	12/15	21	21	Ice / snow on or under equipment, Control Point, WAS, LATE TURN TRAIN AND FORZEN DOORS
WAS	196	12/15	48	48	Other late crew, CREW ARRIVED LATE Off 131 delayed arrival
WAS	2108	12/15	63	63	Ice / snow on or under equipment, Control Point, WAS, LATE ARRIVAL TURN TRAIN ICE WITH THE DOORS AND BRAKES
WAS	2124	12/15	1		
ALB	448	12/14	(No OS)		
BOS	93	12/15	7	4	High passenger count, HEAVY TRAVEL 157/ON

Amtrak Initial Terminal Details

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/15/2025

Terminal	Train	Date	Late	Delay	Cause
BOS	93	12/15	7	3	Mobility Impaired, MULTIPLE ADA REQUEST
BOS	137	12/15	49	49	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
BOS	173	12/15	55	55	Ice / snow on or under equipment, Other, BOS, Departing South Station late due to consist thawing out in S&I building
BOS	175	12/15	58	13	Service, turn, or wye train, 170, late departure due to late turn of AM170
BOS	175	12/15	58	45	Service, turn, or wye train, 170, late departure due to late turn of AM170
BOS	177	12/15	20	20	Service, turn, or wye train, 172, departed late due to late turn of AM172
BOS	179	12/15	4	4	Door, 43362, 82994, 82706, AM179 departed late due to frozen doors
BOS	2167	12/15	77	25	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
BOS	2167	12/15	77	52	Fire department hold, HELD DUE TO FIRE AT MP 224.69 ON TRK 1
BOS	2169	12/15	99	99	Service, turn, or wye train, 2152, departed late due to late turn of AM2152
BOS	2173	12/15	10	10	Service, turn, or wye train, 2154, departed late due to late turn of AM2154
BOS	2193	12/15	13	13	Water, commissary, toilet/trash dumping, AM2193/PC2024 DP South Station at 619P/14" late, a/c return to SHSY to refill water supply
GFD	479	12/15	41	12	Restrictive signal(s) from unknown cause Stop Signal, Control Point, CPF 385
GFD	479	12/15	41	29	Late turn from late 486 486
MTR	68	12/15	3	3	Service, turn, or wye train 68, Train late coming out of MMC (Shop)
NHV	470	12/15	71	70	Hold for connecting train
NYP	19	12/15	14	14	Cross over or go around, AM853, Other, SSYD, LATE F/SSYD A/C NECESSARY TO HOLD THEN REVERSE DUE TO AM853 PREFERRED AHEAD
NYP	49	12/15	150	150	PTC - On Board Cab Signal or PTC Failure, 703, NECESSARY TO RETURN TO SSYD FOR ENGINE SWAP A/C ASCES ISSUES
NYP	63	12/15	7	7	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
NYP	89	12/15	12	12	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
NYP	97	12/15	79	79	Service, turn, or wye train, 98, LATE TURN OFF OF AM98
NYP	111	12/15	31	31	Service, turn, or wye train, 0, LATE TURN OF EQUIPMENT A/C INCLEMENT WEATHER CAUSING MULTIPLE MW ISSUES.
NYP	119	12/15	4	5	Snow removal equipment working ahead, Other, NYP-XBH, DELAYED FROM STATION A/C SINGLE TRACKING DUE TO ICE PATROL
NYP	129	12/15	9	9	Ice / snow on or under equipment, Other, NYP, FROZEN DOORS THROUGHOUT TRAIN
NYP	131	12/15	135	135	Service, turn, or wye train, 112, LATE TURN OFF AM112

Amtrak Initial Terminal Details

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/15/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	133	12/15	64	64	Service, turn, or wye train, 112, LATE TURN OFF FOR AM112
NYP	181	12/15	50	50	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
NYP	183	12/15	65	65	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
NYP	185	12/15	49	49	Service, turn, or wye train, 110, LATE TURN OFF AM110
NYP	193	12/15	38	38	Service, turn, or wye train, 84, LATE TURN OFF OF AM84
NYP	197	12/15	29	29	Service, turn, or wye train, 134, LATE TURN OFF OF AM134
NYP	237	12/15	4	4	Passenger and/or baggage
NYP	241	12/15	6	6	Wet / slippery rail, Other, NYP, FROZEN DOORS
NYP	243	12/15	3	3	Passenger and/or baggage
NYP	283	12/15	2	2	Passenger and/or baggage
NYP	639	12/15	3	3	Passenger and/or baggage, LOADING
NYP	641	12/15	4	4	Catenary failure, Other, SSYD, LATE RELEASE F/SSYD DUE TO UNEXPECTED POWER LOSS ON THE LOOPS
NYP	643	12/15	1	3	Door, 82588, DOOR ISSUES
NYP	645	12/15	29	29	Service, turn, or wye train, 644, LATE TURN OFF AM644
NYP	647	12/15	51	51	Service, turn, or wye train, 648, LATE TURN OFF OF AM648
NYP	649	12/15	11	11	Cross over or go around, AM56, Other, HLD ON LOOPS A/C AM56 XING AHEAD
NYP	653	12/15	11	11	Power switch failure, Other, NYP, NECESSARY TO REVERSE INTO LINE 1 TO REROUTE A/C 89 SW. FAILURE "A" TOWER
NYP	655	12/15	4	4	Passenger and/or baggage, LOADING
NYP	2103	12/15	2	2	Passenger and/or baggage, LOADING
NYP	2117	12/15	3	3	Passenger and/or baggage, HEAVY BOARDING AT LEAVING TIME
NYP	2121	12/15	25	25	Service, turn, or wye train, 2108, LATE TURN OFF AM2108
CHI	5	12/15	2	2	Injured or sick employee Service attendant cut finger in the diner. Held for new employee from ready crew from crew base.
CHI	48	12/15	4	4	Mobility Impaired ADA wheelchair lift .. brought passenger out late at 920 P ..
CHI	301	12/15	8	8	Crew rest 318, Late sign up due to late arrival 318. Sign up 6:55 am
CHI	354	12/15	9	9	Engineer refused to take AMTK 58 without a coach door closed light indicator on the engine, until we were ordered out. AMTK 58
CHI	364	12/15	(Trn Cxld)		Car Issue

Amtrak Initial Terminal Details

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/15/2025

Terminal	Train	Date	Late	Delay	Cause
CHI	370	12/15	10	10	Toilet ID4120, ID4206, Two restrooms not working. Ordered out of Chicago with only 50 percent restrooms working.
CHI	383	12/15	40	40	Door 48181, Exterior side doors wouldn't close in yard
GRR	371	12/15	2	2	Door 4304, Door would not close
PNT	355	12/15	34	5	PTC- IETMS incorrect consist As crew 355 tried to depart PNT station but was not able to initially due to back/wrong train consist
PNT	355	12/15	34	19	Mechanical had to complete there work and release train 355 to on duty crew.
PNT	355	12/15	34	10	Re-crew / job briefing Crew 350 died for time on Main Track 2 at mp25.9. Had to get authorization to utilize engine to complete crew 350's yard work and tie onto the train consist to make it become 355. Had to wait for mechanical to complete there work and drop blue flags
PTH	365	12/15	(Trn Cxld)		Equipment Issues
QCY	380	12/15	5	5	Door ID4211, Steps for train wouldn't go in. Had to wrestle with it in order for it to close
SEA	8	12/15	95	95	Set out defective locomotive Late engine swop Amtk 325, 325
SEA	11	12/15	4	4	Inability to contact dispatcher Could not get ahold of the dispatcher until 930am, Other, Amtrak Seattle Yard
STL	302	12/15	8	8	Late bulletins due to Amtrak cause
STL	306	12/15	2	2	Mobility Impaired
BFD	715	12/15	1		
LAX	4	12/15	18	18	Set out defective locomotive 157
SAC	535	12/15	8	8	Dispatcher hold Waiting for signal in time at RV989, Control Point, RV989
VAC	519	12/15	5	5	United States Only 2 agents

Eastern Region

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	90.9	98.7	94.8	309	28
CDOT	95.0	100.0	92.9	92.4	20	0
MARC	95.0	70.7	88.2	90.2	58	17
SEPTA	95.0	90.0	94.6	91.5	190	19
NJT-NED	95.0	91.8	91.5	93.8	367	30
NJT-SED	95.0	95.8	98.8	97.2	24	1

Operating Highlights

Train 40(15) - Savannah, GA - Refueling/Servicing

16DEC25: Train 40(15) was delayed at Savannah Station/MP 491.0 on the CSX Savannah Subdivision due to the fuel vendor arriving late.

Train	Delay	Comment
40(15)	41"	

Train 171(15) - South of Culpeper, VA - Switch Failure

16DEC25: Train 171(15) was delayed on the Norfolk Southern Danville/Alexandria-Montview Subdivision at MP 84.5 due to switch failure ahead at CP Orange/MP 84.7.

Train	Delay	Comment
171(15)	34"	

Train 494(15) - New Haven, CT - Hold for Connection

16DEC25: Train 494(15) was delayed at its initial terminal at New Haven Station due to being held for connections on late arriving Train 94(15).

Train	Delay	Comment
494(15)	34"	

Train 53(15) - North of Florence, SC - Engine Failure

16DEC25: Train 53(15) was delayed on the CSX North End Subdivision at MP 84.6 after PTC caused an emergency stoppage. The crew walked the train and took no exceptions. Train 53(15) was delayed on the CSX South End Subdivision at MP 262.7 due to lead engine 358 having an unrecoverable penalty. The crew walked the train and took no exceptions. The engineer was able to clear the penalty.

Train	Delay	Comment
53(15)	37"	MP 262.7 South End
53(15)	40"	MP 84.6 North End

15DEC25: Train 97(14) held at the Ocala Division due to meeting train 52(15) at MP 727.1.

Train	Delay	Comment
97(14)	31"	

Train 49(15) New York, NY - Engine Failure

15DEC25: Train 49(15) with E/703,E/702 was delayed departing New York due to E/703 having ACSES issues and it was the lead engine. New York had to swap engine 702 to be in the lead.

Train	Delay	Comment
49(15)	2'30"	

Multiple Train Delays - Boston, MA - Servicing

15DEC25: There were multiple initial terminal delays in Boston due to late arrival of equipment from yesterdays weather and frozen equipment and late turns off inbound trains.

Train	Delay	Comment
173(15)	55"	
93(15)	07"	
175(15)	58"	late turn off 170(15)
2167(15)	1'17"	late turn off 2150(15)

Train 2151(15) South of Wilmington, DE - Weather

15DEC25: Acela 2151(15) operating with PC/2019, 6 cars, PC/2014 and 243 passengers onboard Amtrak PW Line actuated dragger on track 3 at MP46.7 approximately 20 miles south of Wilmington, DE just north of Bacon Interlocking. The crew stopped to inspect the train. The crew cleared ice and snow from the train then they were on the move south.

Train	Delay	Comment
2151(15)	30"	

Train 2167(15) Boston Back Bay , MA -Mass Fire/ Police Related

15DEC25: Boston Chief reported that the Boston Fire Department reported a fire in the signal mass at MP 224.69 on track 1 on the New Haven to Boston main line. Train 2167(15) was being held at Back Bay station until further instruction. Fire Department requested a hold on all tracks between MP 224.30/Plains and MP 226.50/Ruggles.

UPDATE: Boston Fire Department originally reported a signal fire but it was actually the 12SW at Plains Interlocking. The fire was extinguished and all personnel were clear. As of 158P-ET Traffic was okayed for normal service. Track Car was sent out to the scene.

Train	Delay	Comment
2167(15)	1'05"	
137(15)	35"	
2152(15)	42"	
2154(15)	14"	
4 CDOT'S	21"-45"	
2169(15)	1'39"	LATE TURN OFF 2152(15)
2173(15)	10"	late turn off 2154(15)

Multiple Initial Terminal Delays - Washington, DC - Servicing

15DEC25: There were multiple initial terminal delays in Washington due to late arrival of equipment from yesterday's weather and frozen equipment.

Train	Delay	Comment
182(15)	31"	
112(15)	1'32"	
56(15)	2'32"	
114(15)	34"	late turn off 181(14)
2108(15)	1'03"	late turn off 2107(15)
184(15)	21"	late turn off 183(15)
196(14)	48"	late crew turn off 131(15)
136(15)	1'54"	

Washington to Philadelphia Main line - Switch Failure at Gunpow - Signal

15DEC25: At 502A-ET, CETC reported switch failure at MP 79.3/Gunpow on the Washington to Philadelphia main line. As of 532-ET, Maintainers were on scene. Several Trains were delayed while repairs were made.

Train	Delay	Comment
2150(15)	49"	
67(14)	1'00"	
170(15)	56"	
151(15)	30"	
2152(15)	21"	
3 MARC'S	55"-1'44"	
470(15)	1'10"	HOLDING FOR CONN OFF 170(15)

Multiple Initial Terminal Delays - Philadelphia, PA - Servicing

15DEC25: There were multiple initial terminal delays in Philadelphia due to late arrival of equipment from yesterday's weather and frozen equipment.

Train 601(15) was delayed departing Philadelphia due to the late release of the equipment from the yard caused by frozen doors due to weather conditions.

This also caused train 605(15) and 110(15) to be delayed due to late release from the yard.

Train	Delay	Comment
601(15)	1'13"	
110(15)	51"	
605(15)	1'44"	
644(15)	53"	late turn off 601(15)
646(15)	38"	late turn off 607(15)
648(15)	1'07"	late turn off 605(15)
654(15)	13"	LATE TURN OFF 645(15)
647(15)	51"	LATE TURN OFF 648(15)
645(15)	29"	LATE TURN OFF 644(15)

Multiple Initial Terminal Delays - New York, NY - Servicing

15DEC25: There were multiple initial delays due to the late arrival of equipment due to yesterday's weather event and the late release from the yard due to servicing and frozen equipment.

Train 111(15) was delayed departing New York due to the late arrival and servicing of equipment caused by yesterdays weather. This also caused delay to train 181(15).

Train 97(15) was delayed departing New York due to utilizing equipment off inbound Train 98(13) after finding 3 frozen cars on Trai 97(15) equipment.

Train	Delay	Comment
111(15)	31"	
181(15)	50"	
183(15)	1'05"	
185(15)	49"	late tun off 110(15)
131(15)	2'15"	
133(15)	1'04"	late turn off 112(15)
97(15)	1'19"	Equip off 98(14)
653(15)	11"	late turn off 650(15)
193(15)	38"	Turn off 84(15)
197(15)	29"	late turn off 134(15)

Train 40(15) - North of Savannah, GA - Broken Rail

16DEC25: Train 40(15) was delayed on the CSX Columbia Subdivision at MP 474.7 due to broken rail ahead at MP 464.5.

Train	Delay	Comment
41(14)	1'30"	Estimated
40(15)	2'30"	Estimated

12DEC25: Metro North weekend outages:

New Haven Line:

- Continuous outage No.1trk CP 240 to CP241 began Monday 12/08/25 Mud spot remediation.
- Continuous outage No.2trk CP 217 to CP 223. Began 12/01/25 expected to return to service Tomorrow morning.
- Continuous outage No.1 & 3trks CP241 to CP243. Walk bridge OOS for 18 months began 7/19/24.
- No.3 track CP 266 to CP271 11:59pm Friday(12) to 6pm Sunday (14). There will be a Rule 22 (Working Limits) during the day for Both Saturday and Sunday. Approx Mp70.4 to Mp70.7.
- 4-track outage Saturday(13) only 12:40A to 5A. AC power will be removed. No.4trk will be the running track thru area.

Hudson Line:

- No 1 & 3trks CP 26 to CP 33 to Replace Rail 12:30A Saturday(13) to 5A Monday(15).
- No.2trk between CP 53 and CP 58. On Tuesday 12/16/25 during the day. Anticipated delays 10-15minutes for this outage.

VIA Oakville Subdivision Oakville, ON - Scheduled M/W Work

UPDATE 03OCT25: To accommodate infrastructure maintenance on the VIA Oakville subdivision at Oakville/MP 21.4. As a result, train 63/7098(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay. Train 64/7097(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay.

WBS#: B.TR.100150.5989

Train	Delay	Comment
64(13)	57"	

Eastern Region

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
80 (25)	RMT	326		Gear case damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 69(15) Passenger Removal at Rouses Point, New York- Customs***

15DEC25, Passenger on PNR E2C799, traveling from New York, NY to Montreal, QC was reportedly denied travel across the border by Customs Border Patrol. Amtrak Police notified.

Delay: 69(15) None

Train 96(14) Passenger Removal at Westwood, Massachusetts – Medical

15DEC25, Passenger on PNR 94D3A9, traveling from New York, NY to Boston, MA was reportedly had motion sickness in the train vestibule and gestured to vomit but hit their head and passed out. Other travelers onboard assisted until paramedics arrived for transport to Needham Hospital. Amtrak Police notified.

Delay: 96(14) 10"

Train 170(15) Passenger Removal at Metropark, New Jersey – Improper Conduct

26-FOI-00197 00000005542 "UNCLASSIFIED" 12/23/2025

15DEC25, Passenger on PNR 289114, traveling from Washington D.C. to Wilmington, DE reportedly refused to detrain at his destination after being informed multiple times by crew members. The travel advised that police would be needed. As a result, local authorities assisted with the removal. Amtrak Police notified.

Delay: 170(15) 12"

Train 69(14) Passenger Removal at Rouses Point, New York – Border Patrol

14DEC25, Passenger on PNR 27B2E0, traveling from New York, NY to Montreal, QC was reportedly removed from the train by Canadian Customs Agents. Amtrak Police notified.

Delay: 69(14) None

Train 99(14) Passenger Removal at New Haven, Connecticut – Medical

14DEC25, Passenger on PNR 1DE5B9 traveling from Boston, MA to New York, NY reportedly lost her balance several times while walking through train cars. According to crew members the passenger had slurred speech and seemed disoriented. Emergency Medical Services assisted with transport to Yale New Haven Hospital. Amtrak Police notified.

Delay: 99(14) 15"

Operating Highlights

Train 21/421(14) South of Taylor, TX - Freight Train Interference

15DEC25: Train 21/421(14) was delayed at Round Rock/MP161.9 16 miles south of Taylor, TX/MP144.5 on the UP Austin subdivision due to freight congestion. Once the route was clear, train 21/421(15) continued south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21/421(14)	38"	

Train 3(14) West of Albuquerque, NM - Freight Train Interference

15DEC25: Train 3(14) was delayed at Abajo/MP903.84 1 mile west of Albuquerque, NM/MP902.45 on the Rio Metro Albuquerque subdivision due to freight congestion. Once the route was clear, train 3(14) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(14)	40"	

Train 1(15) East of Houston, TX - Routing

15DEC25: Train 1(15) was delayed entering Houston, TX/MP362.3 on the UP Houston subdivision due to routing changes ordered by dispatch. Train 1(15) crossed over from Houston subdivision to Houston East subdivision and then to Houston West subdivision. Train 1(15) was then ordered to cross over to Houston subdivision and operate to Chaney Junction/MP363.5 where it shoved back into the Houston depot.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(15)	32"	

Train 3(14) East of Las Vegas, NM - Passenger Train Interference

15DEC25: Train 3(14) was delayed at Onava siding/MP760.3 10 miles east of Las Vegas, NM/MP770.1 on the BNSF Raton subdivision meeting Amtrak train 4(14). Once the route was clear, train 3(14) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(14)	31"	

Train 383(15) Chicago, IL - Car Failure

15DEC25: Train 383(15), with engine 339, 4 cars, and 77 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to door issues on car 48181 in the yard. Once Chicago Mechanical released again, train 383(15) shoved into depot, boarded passengers, and departed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(15)	40"	

Train 8(15) Initial Terminal Delay at Seattle, WA - Servicing Equipment

15DEC25: Train 8(15) was delayed at Martinez, CA after servicing and servicing equipment off inbound train 7(13) which arrived in Seattle at 12:17PM-PDT, 48 minutes late. Preparations for departure were extended when third locomotive AMTK 369 was removed, remaining locomotives AMTK 325 and AMTK 319 were required to be switched positions in the consist.
UPDATE: Waste pipes in sleeper car C/32086 reported blocked, requiring repair . Train 8(22) departed Seattle at 6:30PM-PT.

Train	Delay	Comment
8(15)	1'35"	SEA - ITD

Train 534(15) East of Martinez, CA - Bridge Open-Marine Traffic

15DEC25: - Train 534(15) was delayed at Suisun Bay Bridge MP 33.7/UPRR Martinez Subdivision, 1 mile east of Martinez. This was due to movable bridge open for the passage of marine traffic. Once the bridge was lowered, train 534(15) was able to proceed to Suisun.
Service Recovery - Passengers offered 20% discount on cafe items.

Train	Delay	Comment
534(15)	31"	
543(15)	03"	

Train 21/421(14) West of Mineola, TX - Broken Rail

15DEC25: Train 21/421(14) was delayed at MP183.35, 46 miles west of Mineola, TX, on the UPRR Mineola Subdivision, due to UPRR MoW completing repairs to a broken rail ahead.

Train	Delay	Comment
21/421(14)	30"	

Train 5(14) Denver, CO - Engine Failure

15DEC25: Train 5(14), E/207-E/140 & 8 cars, was delayed at Denver, CO, flat switching engines due to a bad order ps13 pressure switch on E/207. Train 5(14) departed Denver with E/140 lead and E/207 in trail position to Emeryville, CA.

Train	Delay	Comment
5(14)	1'20"	

Train 371(15) St. Joseph-Benton Harbor, MI - Fire Department Activity

15DEC25: Train 371(15) was delayed at St. Joseph-Benton Harbor, MI/MP87.9, on the CSX Grand Rapids Subdivision, due to local fire department on scene of a structure fire near right of way ahead at MP94.14. Train 371(15) was delayed holding for fire department to clear the scene and release hold through the area.

Train	Delay	Comment
371(15)	46"	

Train 21/421(14) South of Little Rock, AR - Freight Train Interference

15DEC25: Train 21/421(14) was delayed at Traskwood/MP378.3, 32 miles south of Little Rock, AR, on the UPRR Little Rock Subdivision, due to MEWNL-14 (UP 7209) actuated wheel impact detector on the 602nd axle ahead at MP386. UPRR crew inspected consist and took no exceptions. UP 7209 was authorized to proceed north at 30MPH. Train 21/421(14) was delayed holding for open route ahead.

Train	Delay	Comment
21/421(14)	2'10"	

Train 3(14) East of Kansas City, MO - Freight Train Interference

14DEC25: Train 3(14) was delayed at mile post 415.4 36 miles east of Kansas City, MO/MP6.85 on the BNSF Marceline subdivision due to a disabled BNSF freight ahead. BNSF granted train 3(14) permission to shove 10 miles back to Hardin, crossover to main track 2, and operate around the disabled freight. Once the route was clear, train 3(14) continued west.

15DEC25: Train 4(13) was delayed at Kansas City, MO/MP6.85, on the KCT Kansas City Terminal, due to crew rest. The crew signed up on rest at 801AM-CT off Train 3(14) which arrived in Kansas City at 1151PM-CT, 2 hours and 03 minutes late.

Train	Delay	Comment
3(14)	1'58"	
4(13)	1'08"	

Train 7/27(14) East of Whitefish, MT - Tree Strike

16DEC25: Train 7/27(14), with engines 60, 317, and 182, 10 cars, and 111 passengers, struck a tree east of Whitefish, MT/MP1219.3 on the BNSF Hi Line subdivision. After departing Whitefish, MT, train 7/27(14) stopped to inspect excessive noise from the lead engine 60. The crew noted condemnable plow damage, now less than 2 inches from the rail. BNSF mechanical forces were unavailable to cut the plow. Engine 60 was set out at on East Rip Track at Whitefish, MT. Train 7/27(14) continued west. BNSF freight 6559 was sourced at Spokane, WA to add to the equipment.

Train	Delay	Comment
7/27(14)	3'01"	

Train 370(15) Bangor, MI - Freight Train Interference

16DEC25: Train 370(15) was delayed departing Bangor, MI/MP60.6 on the CSX Grand Rapids subdivision due to CSX freight R598-15 stopped ahead with a broken drawbar. Once the drawbar was repaired, the freight was delayed again as the power to the freight stalled repeatedly on the grade. A freight recrew signed up and vanned to Grand Rapids, MI to pick up additional power to bring to the freight to complete the grade. At 4:26AM ET, freight R598-15 began to advance to Wells siding to clear the route for train 370(15).

Train	Delay	Comment
370(15)	6'40"	as of 5:00AM ET

Train 355(15) Ann Arbor, MI - Engine Failure

15DEC25: At around 8:26 PM ET 0000005542: 355 UNCLASSIFIED with 12/23/2025 IDTX4622, 5 cars, and 149 passengers, stopped at mile post 40.0 2.5 miles west of Ann Arbor, MI/MP37.5 on the Michigan Department of Transportation Michigan Line subdivision due to main reservoir issues. The crew inspected the air hoses and worked with CNOC Mechanical Desk and a responding road foreman to determine a seal leaking behind the emergency portion of car IDTX4111. Stopping the leak required cutting out the brakes on both trucks of car IDTX4111, leaving the equipment at 83% braking capacity and forced to operate at a maximum of 40MPH or half of the current speed limit, whichever is lower. The equipment continued west to Battle Creek, MI/175.74 and arrived at 1:24AM ET where the passengers boarded buses to Chicago and destinations west. Train 355(15) terminated at Battle Creek, MI. The 355(15) equipment continued deadhead to Chicago, IL, departing Battle Creek, MI at 1:34AM ET.

Train 354(15) held at Battle Creek, MI to provide train 355(15) a route to Battle Creek, MI. Train 354(15) shoved back to allow 355(15) access to the station and then continued east.

The 355(15) deadhead equipment stopped while operating through Kalamazoo, MI awaiting a recrew.

WBS#: B.TR.100150.6317

Train	Delay	Comment
355(15)	Terminated	
354(15)	3'19"	PTI 355(15)

Train 8/28(14) East of Essex, MT - Weather

15DEC25: Train 8/28(14) was delayed at MP1142.9, 23 miles east of Essex, MT, on the BNSF Hi Line Subdivision, due to winds in excess of 75MPH ahead. Once the winds diminished below 75MPH, Train 8/28(14) was on the move east operating reduced speed due to high wind warnings still in effect between MP1118 and MP1090.1.

Train	Delay	Comment
8/28(14)	50"	E/ESM, high wind warnings
8/28(14)	30"	E/BRO, high wind warnings

Train 48/448(14) East of Chicago, IL - Car Failure

15DEC25: Train 48/448(14) with 100000005642 cars, and 245 passengers, was delayed at Hammond Station/MP506.8 16 miles east of Chicago Union Station, IL/MP0.0 on the NS Chicago Terminal subdivision due to sticking brakes on both the front and rear trucks of deadhead car 62009. The crew worked with CNOC Mechanical Desk and determined that both trucks needed to be cut out. The crew had to break away ice in order to cut out the trucks. Train 48/448(14) was able to continue at freight speed due to having 92% braking efficiency after cutting out 2 trucks.

Train 48/448(14) was further delayed by signal failure at control point CP506. NS MoW crew was onsite troubleshooting. Once the signal was given, train 48/448(14) continued east.

Train 355(14) was delayed between control point CP500/MP501.1 and control point CP502/MP502.8 due to the signal failure at control point CP506 and then meeting train 48/448(14). Once the route was clear, train 355(14) continued into Chicago Union Station, IL.

Train 48/448(14) delayed at Buffalo Depew, NY due to car 62009 having Spalding wheels. The car was set out at the Buffalo station on track 4. Due to the late operation of Train 48/448(14), Train 448(14) will terminate in Albany, NY with alternate transportation protecting all stops Albany, NY to Boston, MA with drop-off only at Framingham, MA and Boston Back Bay Stations. Due to Train 448(14) cancellation, Train 449(16) will originate in Albany, NY with alternate transportation, with no pick-up and drop-off at Boston Back Bay or Framingham, MA stations.

Train 63(15) was delayed east of Buffalo Depew Station due to Train 48/448(14) blocking the station while they set out the bad order car.

Train	Delay	Comment
48/448(14)	1'38"	CAR Troubleshooting C/62009
48/448(14)	31"	DCS Signal failure at CP506
355(14)	2'13"	DCS Signal failure CP506
48/448(14)	1'13"	E/HMI-CLE, op freight speeds
48/448(14)	1'20"	setting out C/62009
448(14)	TERM ALB	BUSES ALB-BOS
449(16)	ORIG ALB	BUSES BOS-ALB
63(15)	28"	

Train 364(14) West of Kalamazoo, MI - Car Failure

14DEC25: Train 364(14) 26-FOH-00197 e00900005542 IDTX4022 UNCLASSIFIED IDTX422205 6 cars, and 282 passengers, was west of Kalamazoo, MI/MP143.4 on the Michigan Department of Transportation Michigan Line when the conductor reported that the toilets were out of service on cars IDTX4208, IDTX4128, IDTX4017, and IDTX4014. The conductor also noted that the B end doors on cars IDTX4128, IDTX4107, and IDTX4305 were also out of service. The conductor suspected the equipment was frozen. Port Huron Mechanical acknowledged that they would inspect upon arrival and attempt to repair and/or thaw the equipment. Buses were sourced to shadow train 365(15) if equipment limitations exceeded passenger count.

15DEC25: Due to the loss of toilets and required operational side doors for initial terminal departure, Train 365(15) was cancelled, with alternate transportation between Port Huron, MI and Chicago, IL. Five buses were sourced for train 365(15). Buses one and two operated between East Lansing, MI and Chicago, IL, picking up Chicago passengers only and staging at 8:30AM ET. Bus three operated between East Lansing, Kalamazoo, MI, and Chicago, picking up Chicago passengers only and staging at 8:30AM ET. Bus four operated between Port Huron, Flint, MI, and Chicago, picking up Chicago passengers only and staging at 6:00AM ET. Bus five operated between Port Huron and Chicago, making all stops, pick-up and drop-off, and staging at 6:00AM ET. Equipment was deadheaded to Chicago to be serviced for Train 364(15).

Due to the inbound equipment issues and anticipated late departure from Chicago due to replacing bad order C/ID4017, Train 364(15) was cancelled, with alternate transportation between Chicago and Port Huron, MI. Two busses operated express Chicago to Lansing, MI and two operated Chicago to Port Huron making all stops. Once equipment released, it operated deadhead to Port Huron to be in position for 365(16).

WBS#: B.TR.100150.6316

Train	Delay	Comment
365(15)	Cancelled, with alt	PTH-CHI
364(15)	Cancelled, with alt	CHI-PTH

UNCLASSIFIED
12/3/2025
B. TR. 100150.6267

Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Burlington Northern Santa Fe Brookfield Subdivision East of Quincy, IL - Scheduled M/W Work

09DEC25: To accommodate a Burlington Northern Santa Fe Brookfield Subdivision Track work December 9th through December 12th and December 15th through December 17th between Quincy, IL and Galesburg, IL, The follow operating plan will be in effect for Carl Sandburg Service Train 381:

- Train 381 (09) will operate 2-hours later between Chicago, IL and Quincy, IL.
- Train 381 (10-12) & 381 (15-17) will operate 1-hour later between Chicago and Quincy.

WBS#: B.TR.100150.6234

Western Region

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
3 (8)	FMD		39021	HEP

Leased Freight Locomotive

Train	Location	Eng	Purpose	Location Returned	Date Returned
	SEA Yard	UP2092	Yard switcher		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
3(14)	GLP	1	Passenger on PNR 277715 will be taken to FLG	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 6(13) Passenger Removal at Omaha, Nebraska – Improper Conduct***

15DEC25, Passenger on PNR 1D4894, traveling from Denver, CO to Naperville, IL reportedly had a loaded firearm that was discovered by the Douglas County Sheriff and Omaha Police Departments during a random search of passengers. It was said that the firearm was registered by the traveler and there were no warrants. The traveler was removed from the property and released by the authorities. Amtrak Police notified.

Delay: 6(13) None

Train 5(14) Passenger Removal at Hastings, Nebraska – Improper Conduct

15DEC25, Passenger on PNR 0AD1ED, traveling from Chicago, IL to Emeryville, CA was reportedly acting irrational calling police and stating that they and the conductor had killed someone onboard. Local authorities assisted with the removal. Amtrak Police notified.

Delay: 5(14) None

26-FOI-00197 00000005542 "UNCLASSIFIED" 12/23/2025
Train 448(14) Passenger Removal at Cleveland, Ohio – Improper Conduct

15DEC25, Passenger on PNR C23FA7, traveling from Chicago, IL to Springfield, MA was reportedly moving seat locations several times and when asked to relocate from the accessible seat the traveler became verbally abusive with the crew member. The traveler was removed without incident. Amtrak Police notified.

Delay: 448 (14) None

Thruway 5815(15) Passenger Removal at Bakersfield, California – Medical

15DEC25, Passenger on PNR 2A9E6A, traveling from Los Angeles, CA to Bakersfield, CA was reportedly unresponsive upon the thruway arrival into Bakersfield. Attempts by the driver and Amtrak staff to awake the traveler were unsuccessful and paramedics were contacted and transported the traveler to a local hospital for treatment. Amtrak Police notified.

Delay: 5815 (15) None

Train 502(15) Passenger Removal at Tacoma, Washington – Improper Conduct

15DEC25, Passenger on PNR 2BC8AD, traveling from Olympia, WA to Seattle, WA was reportedly drinking alcohol from his personal stock while onboard and was talking inappropriately to a female traveler and disturbing the peace of the male traveler seating next to them. Once the crew became aware the traveler was removed. Amtrak Police notified.

Delay: 502 (15) None

Train 3(13) Passenger Removal at Hutchinson, Kansas - Medical

14DEC25, Passenger on PNR 29DFB0, traveling from Lawrence, KS to Albuquerque, NM was removed by EMS at Hutchinson, KS. Due to falling ill passenger and infant detained. Amtrak Police notified.

Delay: 3 (13) 14"

Train 765(14) Passenger Removal at Ventura, California – Fare Evader

14DEC25, Unknown Passenger traveling without a reservation from Los Angeles, CA to Ventura, CA was reportedly threatening an ADA passenger who contacted Amtrak Police. The traveler was later found hiding inside the bathroom. Amtrak Police notified.

Delay: 765 (14) 01"

Train 422(12) Passenger Removal at Taylor, Texas – Improper Conduct

14DEC25, Passenger on PNR 28C345, traveling from Los Angeles, Ca to Little Rock, AR was reportedly upset about the seating arrangements and argued with crew members and physically slapped the car attendant's leg. Local authorities assisted with the removal. Amtrak Police notified.

Delay: 422(12) 09"

Train 5(13) Passenger Removal at Salt Lake City, Utah – Improper Conduct

15DEC25, Passenger on PNR 293062, traveling from Chicago, IL to Emeryville, CA was reportedly changing seats and spending a lot of time in the lounge restroom where drug paraphernalia was later found. The traveler was asked to exit and complied without incident. Amtrak Police notified.

Delay: 5(13) NONE

Consist Deviations

26-FOI-00197

00000005542

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
48 (14)	BUF	Team NYP car 62009 has been set out at BUF(wheels). Train 48(14) will arrive needing a replacement sleeper for 49(16). Preferably a VW I sleeper.	Passengers loss their sleeper accommodations due to car being set out.	17	62009
307 (15)	CHI	Team due to an equipment change trains 307(15)-307(16)-302(16)-302(17) will not have business class. All sales have been closed. Please re-accommodate all affected passengers.	passengers downgraded	25	ID42XX
307 (16)	CHI	Team due to an equipment change trains 307(15)-307(16)-302(16)-302(17) will not have business class. All sales have been closed. Please re-accommodate all affected passengers.	passengers downgraded	27	ID42XX
656 (15)	HAR	Due to no available Cab Car, 609(16) will operate with 5 coaches and no Wi-Fi.	passengers notified	215	
97 (15)	NYP	Team due to a change in equipment on 97(15) -line 9711it was necessary to perform a schedule change. Please utilize the WAR report to ensure any affected customers are re-accommodated.	passengers moved to available room	2	62520
609 (15)	NYP	Due to no available Cab Car, 609(16) will operate with 5 coaches and no Wi-Fi.	passengers notified	207	
355 (15)	PNT	Team due to cars (BYD-Frozen) id4111 and id4202 now showing d/h in line train 355(15) is over capacity in JY seating please try to re-accommodate all affected passengers. All sales have been closed.	PASSENGERS NOTIFIED AND DOWNGRADED	18	ID4111, ID4202
302 (16)	STL	Team due to an equipment change trains 307(15)-307(16)-302(16)-302(17) will not have business class. All sales have been closed. Please re-accommodate all affected passengers.	passengers downgraded	15	ID42XX

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
302 (16)	STL	26-FOI-00197 00000005542 "UNCLASSIFIED"	passengers downgraded	8	ID42XX

Reverse Consists

Train Number	Station	Reason
138 (15)	NFK	Consist reversed Business class seat orientation may have changed At Front
134 (15)	RNK	Consist reversed Business class seat orientation may have changed At Front
171 (15)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (15)	BOS	Consist reversed Business class seat orientation may have changed At Front
197 (15)	NYP	Consist reversed Business class seat orientation may have changed At Rear
141 (15)	SPG	Business class change only Business class seating orientation may have changed At Rear
183 (15)	NYP	Consist reversed Business class seat orientation may have changed At Front
111 (15)	NYP	Consist reversed Business class seat orientation may have changed At Front
2117 (15)	NYP	Acela consist reversed First class at Rear
133 (15)	NYP	Consist reversed Business class seat orientation may have changed At Front
192 (15)	WAS	Consist reversed Business class seat orientation may have changed At Rear
182 (15)	WAS	Consist reversed Business class seat orientation may have changed At Rear