



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, December 17, 2025

Rules: 1-8



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/16/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	73	76.5%	4,837	746	84.6%	22,746	2,936	87.1%
Central Division	85.5%	65	12	81.5%	1,046	176	83.2%	5,068	545	89.2%
Northeast Division	80.0%	98	29	70.4%	1,542	237	84.6%	7,138	989	86.1%
Southeast Division	72.5%	73	21	71.2%	1,119	180	83.9%	5,318	697	86.9%
Southwest Division	77.0%	74	11	85.1%	1,130	153	86.5%	5,222	705	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00197 00000005541 UNCLASSIFIED Endpoint Arrival Dates through 12/16/25 12/23/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	90,823	33,870	63%	1,572,167	395,016	75%	7,766,901	1,643,221	79%
Northeast Corridor	81%	43,024	16,229	62%	719,250	180,177	75%	3,510,651	698,061	80%
Acela	83%	10,635	5,445	49%	163,643	49,962	69%	755,843	167,641	78%
Northeast Regional	79%	32,389	10,784	67%	555,607	130,215	77%	2,754,808	530,420	81%
Richmond / Newport News / Norfolk	77%	9,838	3,178	68%	169,896	43,847	74%	835,902	187,352	78%
Springfield Shuttles	89%	765	46	94%	12,616	1,582	87%	46,138	5,277	89%
Roanoke	79%	2,593	461	82%	43,138	8,074	81%	211,891	34,823	84%
On Spine Northeast Regional	80%	19,193	7,099	63%	329,957	76,712	77%	1,660,877	302,968	82%
State Supported	80%	36,850	12,520	66%	661,242	141,003	79%	3,307,916	624,058	81%
Borealis	60%	481	0	100%	8,696	2,538	71%	44,986	12,109	73%
Capitol Corridor	90%	3,649	257	93%	54,843	6,078	89%	273,436	29,474	89%
Carolinian	60%	757	581	23%	17,951	6,360	65%	91,097	27,262	70%
Cascades	63%	1,722	153	91%	33,741	8,113	76%	180,030	43,450	76%
Downeaster	82%	1,380	418	70%	22,081	3,542	84%	113,339	15,318	86%
Empire	78%	5,100	2,163	58%	81,745	18,144	78%	397,929	79,689	80%
Adirondack	72%	305	231	24%	4,238	2,117	50%	25,137	8,668	66%
Ethan Allen Express	70%	527	132	75%	8,477	2,401	72%	45,470	13,922	69%
Maple Leaf	70%	677	599	12%	10,365	5,382	48%	45,747	17,170	62%
New York - Albany	85%	2,362	694	71%	38,175	3,681	90%	176,782	22,803	87%
New York - Niagara Falls	75%	1,229	507	59%	20,490	4,563	78%	104,793	17,126	84%
Gold Runner	73%	1,075	218	80%	34,809	11,227	68%	188,857	66,872	65%
Heartland Flyer	65%	102	0	100%	2,731	608	78%	15,240	8,178	46%
Hiawatha	90%	1,644	0	100%	27,714	5,147	81%	134,167	16,062	88%
Illinois	78%	1,763	541	69%	36,734	15,645	57%	186,571	54,963	71%
Carl Sandburg / Illinois Zephyr	85%	324	0	100%	6,888	2,179	68%	32,046	8,737	73%
Illini / Saluki	85%	511	404	21%	10,285	4,362	58%	65,109	17,821	73%
Lincoln Service	70%	928	137	85%	19,561	9,104	53%	89,416	28,405	68%
Keystone	92%	8,753	4,686	46%	138,610	21,554	84%	634,188	62,365	90%
Lincoln / Missouri	60%	629	364	42%	11,436	5,671	50%	59,736	30,327	49%
Mardi Gras Service	80%	294	0	100%	5,804	172	97%	33,477	3,931	88%
Michigan	69%	2,066	1,696	18%	30,884	15,595	50%	150,219	45,483	70%
Blue Water	70%	410	392	4%	6,641	3,766	43%	37,426	11,061	70%
Pere Marquette	85%	217	174	20%	4,166	1,354	67%	20,062	3,283	84%
Wolverine	65%	1,439	1,130	21%	20,077	10,475	48%	92,731	31,139	66%
Missouri	80%	121	33	73%	3,452	937	73%	18,022	4,473	75%
Pacific Surfliner	85%	5,004	258	95%	98,869	7,478	92%	511,857	65,625	87%
Pennsylvanian	72%	781	386	51%	13,952	1,826	87%	70,976	8,024	89%
Piedmont	73%	590	147	75%	16,380	2,801	83%	100,709	24,632	76%
Vermont	75%	939	619	34%	20,810	7,567	64%	103,080	25,821	75%
Long Distance	56%	10,949	5,121	53%	191,675	73,836	61%	948,334	321,102	66%
Auto Train	57%	696	354	49%	11,126	2,590	77%	50,951	9,801	81%
California Zephyr	50%	889	504	43%	13,029	4,874	63%	69,837	20,545	71%
Cardinal	55%	0	0	-	4,174	1,699	59%	21,530	10,004	54%
City Of New Orleans	75%	590	267	55%	10,596	1,636	85%	53,922	11,358	79%
Coast Starlight	60%	1,025	22	98%	18,377	4,814	74%	88,915	27,189	69%
Crescent	70%	761	139	82%	14,648	2,497	83%	73,763	18,279	75%
Empire Builder	55%	947	294	69%	14,605	6,475	56%	75,022	26,736	64%
Floridian	40%	873	873	0%	25,849	16,891	35%	129,750	71,263	45%
Lake Shore Ltd	73%	1,433	855	40%	16,472	6,440	61%	72,400	14,701	80%
Palmetto	65%	395	395	0%	14,609	4,558	69%	74,418	12,989	83%
Silver Meteor	45%	877	524	40%	16,234	6,570	60%	78,983	24,904	68%
Southwest Chief	40%	707	383	46%	11,539	8,234	29%	63,113	38,588	39%
Sunset Ltd	70%	323	21	93%	4,543	574	87%	20,925	4,798	77%
Texas Eagle	50%	1,433	490	66%	15,874	5,984	62%	74,805	29,947	60%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00197 00000005541 "UNCLASSIFIED" 12/20/2025

Train Index Dates Through December 16, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	99,271	1,722,093	576	429,153	8,230,886	521

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	4,786	509,357	94	17,141	2,411,593	71
INFRASTRUCTURE PLANNED	135	2,766	509,357	54	13,347	2,411,593	55
FLEET RELIABILITY	90	19,740	1,722,093	115	67,624	8,230,886	82
TRAIN OPERATIONS	424	71,979	1,722,093	418	331,041	8,230,886	402

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 12/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/16/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	73	76.5%	4,837	746	84.6%	22,746	2,936	87.1%
Central Division	85.5%	65	12	81.5%	1,046	176	83.2%	5,068	545	89.2%
Northeast Division	80.0%	98	29	70.4%	1,542	237	84.6%	7,138	989	86.1%
Southeast Division	72.5%	73	21	71.2%	1,119	180	83.9%	5,318	697	86.9%
Southwest Division	77.0%	74	11	85.1%	1,130	153	86.5%	5,222	705	86.5%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

26-FOI-0011

Scheduled Departure Date: 12/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/16/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	73	76.5%	4,837	746	84.6%	22,746	2,936	87.1%
Central Division	85.5%	65	12	81.5%	1,046	176	83.2%	5,068	545	89.2%
CDL	90.0%	1	0	100.0%	17	1	94.1%	131	7	94.7%
CHI	85.0%	27	6	77.8%	425	92	78.4%	2,058	229	88.9%
CHM	-	1	0	100.0%	7	3	57.1%	7	3	57.1%
EUG	86.5%	2	0	100.0%	32	4	87.5%	149	19	87.2%
GRR	98.0%	-	-	-	15	1	93.3%	76	1	98.7%
KCY	84.5%	2	0	100.0%	32	3	90.6%	152	14	90.8%
MKE	86.5%	6	0	100.0%	94	9	90.4%	450	39	91.3%
MSP	94.0%	1	0	100.0%	16	0	100.0%	77	3	96.1%
PDX	78.0%	5	2	60.0%	80	8	90.0%	386	54	86.0%
PNT	91.5%	3	1	66.7%	47	11	76.6%	173	16	90.8%
PTH	93.0%	1	1	0.0%	15	3	80.0%	76	5	93.4%
QCY	87.5%	2	0	100.0%	32	3	90.6%	154	15	90.3%
SEA	80.0%	8	2	75.0%	127	20	84.3%	612	94	84.6%
SPK	92.0%	1	-	100.0%	18	2	88.9%	79	3	96.2%
STL	88.0%	3	0	100.0%	62	15	75.8%	304	33	89.1%
TRM	-	-	-	-	-	-	-	35	5	85.7%
VAC	95.0%	2	0	100.0%	27	1	96.3%	149	5	96.6%
Northeast Division	80.0%	98	29	70.4%	1,542	237	84.6%	7,138	989	86.1%
ALB	91.5%	7	0	100.0%	112	7	93.8%	479	28	94.2%
BON	43.5%	5	0	100.0%	80	5	93.8%	367	37	89.9%
BOS	86.5%	18	4	77.8%	304	40	86.8%	1,402	143	89.8%
BRK	88.0%	5	1	80.0%	80	3	96.3%	347	16	95.4%
BTN	48.0%	1	0	100.0%	16	0	100.0%	76	17	77.6%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	86.0%	2	0	100.0%	32	3	90.6%	148	12	91.9%
HFD	-	-	-	-	-	-	-	46	3	93.5%
MTR	79.5%	1	0	100.0%	16	3	81.3%	77	14	81.8%
NFL	96.5%	2	1	50.0%	32	1	96.9%	154	5	96.8%
NHV	75.5%	6	0	100.0%	90	11	87.8%	397	74	81.4%
NYP	77.5%	42	23	45.2%	638	159	75.1%	3,014	589	80.5%
SAB	98.0%	1	0	100.0%	16	0	100.0%	75	0	100.0%
SAR	-	-	-	-	-	-	-	1	1	0.0%
SPG	88.0%	7	0	100.0%	110	2	98.2%	459	18	96.1%
TWO	84.0%	1	0	100.0%	16	3	81.3%	76	19	75.0%
WEM	-	-	-	-	-	-	-	17	11	35.3%
Southeast Division	72.5%	73	21	71.2%	1,119	180	83.9%	5,318	697	86.9%
ATL	-	-	-	-	-	-	-	1	0	100.0%
CLT	92.0%	5	2	60.0%	80	6	92.5%	385	31	91.9%
GRO	-	-	-	-	-	-	-	4	2	50.0%
HAR	62.0%	13	8	38.5%	184	47	74.5%	864	145	83.2%
LOR	69.5%	1	0	100.0%	16	1	93.8%	77	6	92.2%
MIA	87.5%	2	0	100.0%	32	4	87.5%	154	17	89.0%
MOE	94.0%	2	0	100.0%	32	0	100.0%	154	3	98.1%

Information Management

26-FOI-0011 Initial Terminal Performance By Terminal

Scheduled Departure Date: 12/16/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 12/16/2025			ITP December 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	310	73	76.5%	4,837	746	84.6%	22,746	2,936	87.1%
Southeast Division	72.5%	73	21	71.2%	1,119	180	83.9%	5,318	697	86.9%
NFK	86.0%	3	1	66.7%	46	7	84.8%	216	22	89.8%
NOL	92.0%	4	0	100.0%	71	3	95.8%	340	17	95.0%
NPN	96.0%	2	0	100.0%	32	0	100.0%	129	7	94.6%
PGH	92.0%	1	0	100.0%	16	1	93.8%	77	2	97.4%
PHL	45.0%	5	4	20.0%	74	47	36.5%	355	170	52.1%
RGH	97.0%	4	0	100.0%	64	4	93.8%	304	7	97.7%
RNK	85.5%	2	0	100.0%	32	4	87.5%	153	18	88.2%
RVM	86.0%	1	0	100.0%	16	2	87.5%	87	13	85.1%
RVR	-	-	-	-	-	-	-	3	3	0.0%
SAV	91.5%	1	0	100.0%	16	2	87.5%	77	2	97.4%
SFA	70.5%	1	0	100.0%	16	0	100.0%	77	3	96.1%
WAS	70.0%	26	6	76.9%	392	52	86.7%	1,861	229	87.7%
Southwest Division	77.0%	74	11	85.1%	1,130	153	86.5%	5,222	705	86.5%
ARN	60.5%	1	0	100.0%	16	1	93.8%	77	6	92.2%
BFD	75.5%	7	1	85.7%	104	21	79.8%	451	105	76.7%
DAL	-	-	-	-	-	-	-	1	0	100.0%
EMY	50.0%	1	1	0.0%	15	6	60.0%	78	23	70.5%
FNO	-	-	-	-	-	-	-	6	3	50.0%
FTW	89.5%	1	0	100.0%	16	0	100.0%	76	3	96.1%
GTA	72.5%	3	0	100.0%	48	2	95.8%	224	19	91.5%
LAX	77.5%	9	0	100.0%	149	18	87.9%	709	79	88.9%
OKC	96.0%	1	0	100.0%	16	0	100.0%	77	3	96.1%
OKJ	79.0%	13	5	61.5%	186	59	68.3%	846	211	75.1%
RNO	-	-	-	-	1	1	0.0%	1	1	0.0%
SAC	73.5%	16	4	75.0%	227	28	87.7%	1,015	114	88.8%
SAN	77.0%	10	0	100.0%	184	8	95.7%	877	73	91.7%
SAS	85.0%	1	0	100.0%	16	1	93.8%	77	4	94.8%
SBA	-	-	-	-	-	-	-	1	1	0.0%
SJC	87.5%	7	0	100.0%	112	7	93.8%	537	47	91.2%
SLO	62.0%	2	0	100.0%	32	1	96.9%	149	12	91.9%
SNC	-	-	-	-	-	-	-	2	0	100.0%
SOL	-	2	0	100.0%	8	0	100.0%	18	1	94.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		6	2	66.7%	33	6	81.8%	7	0	100.0%	33	4	87.9%
3	166	16	5	68.8%	77	9	88.3%	15	8	46.7%	76	31	59.2%
4		15	5	66.7%	76	11	85.5%	15	12	20.0%	76	50	34.2%
5	79	16	6	62.5%	76	13	82.9%	15	5	66.7%	74	11	85.1%
6		14	5	64.3%	75	22	70.7%	14	3	78.6%	75	24	68.0%
7	199	16	3	81.3%	77	7	90.9%	13	4	69.2%	74	11	85.1%
8		16	10	37.5%	77	30	61.0%	16	8	50.0%	77	35	54.5%
11		16	3	81.3%	76	14	81.6%	16	2	87.5%	74	9	87.8%
14		16	1	93.8%	77	10	87.0%	16	0	100.0%	76	18	76.3%
19		16	5	68.8%	77	13	83.1%	16	1	93.8%	77	12	84.4%
20		16	0	100.0%	77	6	92.2%	16	1	93.8%	77	7	90.9%
21		16	4	75.0%	76	12	84.2%	16	5	68.8%	76	16	78.9%
22		16	1	93.8%	77	4	94.8%	16	3	81.3%	76	16	78.9%
23		16	0	100.0%	77	3	96.1%	16	1	93.8%	77	11	85.7%
24		16	3	81.3%	77	5	93.5%	16	1	93.8%	77	7	90.9%
25		16	0	100.0%	77	0	100.0%	16	0	100.0%	77	9	88.3%
26		16	0	100.0%	77	2	97.4%	16	0	100.0%	77	11	85.7%
27	197	16	2	87.5%	77	3	96.1%	16	5	68.8%	77	15	80.5%
28		16	3	81.3%	77	16	79.2%	16	1	93.8%	77	9	88.3%
40		16	3	81.3%	77	12	84.4%	16	6	62.5%	77	28	63.6%
41	362	16	9	43.8%	77	27	64.9%	16	11	31.3%	77	50	35.1%
42	71	16	1	93.8%	77	2	97.4%	16	2	87.5%	77	11	85.7%
43		16	2	87.5%	77	7	90.9%	16	1	93.8%	77	4	94.8%
48		16	6	62.5%	77	11	85.7%	16	5	68.8%	77	8	89.6%
49	97	16	2	87.5%	77	12	84.4%	16	5	68.8%	77	10	87.0%
52		16	0	100.0%	77	3	96.1%	16	2	87.5%	77	14	81.8%
53	45	16	1	93.8%	77	6	92.2%	16	3	81.3%	77	11	85.7%
55	34	12	0	100.0%	54	0	100.0%	12	4	66.7%	54	10	81.5%
56	122	12	3	75.0%	54	10	81.5%	12	4	66.7%	54	10	81.5%
58	79	16	0	100.0%	76	2	97.4%	16	4	75.0%	75	11	85.3%
59		16	2	87.5%	75	5	93.3%	16	1	93.8%	75	4	94.7%
63	38	16	5	68.8%	77	26	66.2%	16	10	37.5%	77	39	49.4%
64		16	3	81.3%	76	19	75.0%	16	5	68.8%	76	15	80.3%
66		16	2	87.5%	77	12	84.4%	16	1	93.8%	77	14	81.8%
67		12	1	91.7%	54	3	94.4%	12	2	83.3%	54	9	83.3%
68	28	16	3	81.3%	77	14	81.8%	16	11	31.3%	77	36	53.2%
69		16	1	93.8%	77	8	89.6%	16	3	81.3%	77	10	87.0%
71	54	16	1	93.8%	77	1	98.7%	16	4	75.0%	77	20	74.0%
72	24	16	3	81.3%	77	8	89.6%	16	7	56.3%	77	17	77.9%
73		16	2	87.5%	77	3	96.1%	16	5	68.8%	76	38	50.0%
74		16	1	93.8%	77	6	92.2%	16	3	81.3%	77	23	70.1%
75		16	0	100.0%	77	2	97.4%	16	6	62.5%	77	34	55.8%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
76		16	0	100.0%	77	4	94.8%	16	4	75.0%	77	34	55.8%
77	15	16	1	93.8%	77	3	96.1%	16	5	68.8%	77	27	64.9%
78		16	0	100.0%	77	3	96.1%	16	2	87.5%	77	11	85.7%
79	169	16	4	75.0%	77	15	80.5%	16	3	81.3%	76	14	81.6%
80	33	16	2	87.5%	77	10	87.0%	16	5	68.8%	76	10	86.8%
84		12	0	100.0%	54	3	94.4%	12	3	75.0%	54	8	85.2%
85	28	12	1	91.7%	54	2	96.3%	12	6	50.0%	54	21	61.1%
86	31	12	1	91.7%	54	5	90.7%	12	8	33.3%	54	27	50.0%
89	87	16	5	68.8%	77	17	77.9%	16	6	62.5%	77	12	84.4%
90	106	16	2	87.5%	77	2	97.4%	16	3	81.3%	77	9	88.3%
93		12	1	91.7%	54	7	87.0%	12	0	100.0%	53	10	81.1%
94		12	6	50.0%	54	12	77.8%	11	4	63.6%	53	16	69.8%
95	37	12	0	100.0%	54	1	98.1%	12	4	66.7%	54	15	72.2%
97		16	11	31.3%	77	29	62.3%	16	3	81.3%	77	19	75.3%
98	62	16	1	93.8%	77	5	93.5%	16	7	56.3%	77	18	76.6%
110		12	6	50.0%	54	25	53.7%	12	2	83.3%	54	5	90.7%
111		12	2	83.3%	54	6	88.9%	12	2	83.3%	54	5	90.7%
112		12	1	91.7%	54	5	90.7%	12	1	91.7%	54	6	88.9%
114	28	12	3	75.0%	54	11	79.6%	11	2	81.8%	53	2	96.2%
119		12	1	91.7%	54	10	81.5%	12	2	83.3%	54	5	90.7%
125		12	0	100.0%	54	2	96.3%	12	7	41.7%	54	13	75.9%
129	30	12	6	50.0%	54	19	64.8%	12	2	83.3%	54	8	85.2%
130		12	0	100.0%	54	4	92.6%	12	0	100.0%	54	4	92.6%
131	23	12	1	91.7%	54	5	90.7%	12	4	66.7%	54	4	92.6%
133	18	12	4	66.7%	54	23	57.4%	12	3	75.0%	54	23	57.4%
134		12	1	91.7%	54	5	90.7%	12	3	75.0%	54	11	79.6%
136	136	12	2	83.3%	54	5	90.7%	11	1	90.9%	54	4	92.6%
137		12	2	83.3%	52	10	80.8%	12	3	75.0%	52	13	75.0%
138		12	1	91.7%	54	7	87.0%	12	0	100.0%	54	2	96.3%
141	39	12	0	100.0%	54	3	94.4%	12	4	66.7%	54	12	77.8%
148		12	1	91.7%	54	5	90.7%	12	0	100.0%	53	9	83.0%
151		16	8	50.0%	77	22	71.4%	16	6	62.5%	76	22	71.1%
170	76	12	1	91.7%	51	4	92.2%	12	4	66.7%	51	13	74.5%
171		12	1	91.7%	54	4	92.6%	12	4	66.7%	54	9	83.3%
172	107	12	2	83.3%	54	6	88.9%	12	4	66.7%	54	19	64.8%
173		12	3	75.0%	54	5	90.7%	12	6	50.0%	54	21	61.1%
174		12	0	100.0%	54	3	94.4%	12	3	75.0%	54	11	79.6%
175		12	3	75.0%	54	5	90.7%	12	5	58.3%	54	13	75.9%
176		12	1	91.7%	54	4	92.6%	12	0	100.0%	54	3	94.4%
177	47	12	2	83.3%	54	10	81.5%	12	4	66.7%	54	24	55.6%
178		12	1	91.7%	54	8	85.2%	11	0	100.0%	54	5	90.7%
179		12	1	91.7%	54	5	90.7%	11	2	81.8%	54	12	77.8%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
181	64	12	5	58.3%	54	11	79.6%	11	2	81.8%	53	3	94.3%
182		12	2	83.3%	54	11	79.6%	12	1	91.7%	54	4	92.6%
183	68	12	4	66.7%	54	15	72.2%	12	4	66.7%	54	10	81.5%
184		12	1	91.7%	54	9	83.3%	12	3	75.0%	54	8	85.2%
185		12	2	83.3%	54	10	81.5%	12	1	91.7%	54	2	96.3%
186		12	0	100.0%	54	7	87.0%	12	1	91.7%	54	13	75.9%
190		12	6	50.0%	54	22	59.3%	12	2	83.3%	54	12	77.8%
192		12	1	91.7%	52	7	86.5%	12	1	91.7%	52	2	96.2%
193		12	3	75.0%	54	16	70.4%	12	4	66.7%	54	18	66.7%
196		12	1	91.7%	54	1	98.1%	12	1	91.7%	54	3	94.4%
197	25	12	7	41.7%	54	22	59.3%	12	5	58.3%	54	11	79.6%
232		16	0	100.0%	77	1	98.7%	16	0	100.0%	77	6	92.2%
233	63	16	4	75.0%	77	17	77.9%	16	4	75.0%	77	16	79.2%
234		16	0	100.0%	77	3	96.1%	16	0	100.0%	77	2	97.4%
236	36	16	0	100.0%	77	1	98.7%	16	2	87.5%	77	13	83.1%
237		16	2	87.5%	77	12	84.4%	16	1	93.8%	77	5	93.5%
239		16	5	68.8%	76	20	73.7%	16	1	93.8%	76	3	96.1%
240	23	16	1	93.8%	77	7	90.9%	16	4	75.0%	77	11	85.7%
241		16	6	62.5%	77	22	71.4%	16	2	87.5%	77	12	84.4%
243		12	2	83.3%	54	18	66.7%	12	1	91.7%	55	9	83.6%
244		16	0	100.0%	77	2	97.4%	16	0	100.0%	77	15	80.5%
280	74	16	1	93.8%	77	4	94.8%	16	4	75.0%	77	14	81.8%
281		16	0	100.0%	77	8	89.6%	16	2	87.5%	77	7	90.9%
283		16	6	62.5%	77	14	81.8%	16	4	75.0%	77	13	83.1%
284		16	0	100.0%	77	1	98.7%	16	2	87.5%	77	7	90.9%
290		16	0	100.0%	77	18	76.6%	16	4	75.0%	76	25	67.1%
291		16	3	81.3%	77	16	79.2%	16	3	81.3%	77	15	80.5%
300		16	5	68.8%	77	7	90.9%	16	8	50.0%	76	22	71.1%
302		15	4	73.3%	75	10	86.7%	15	6	60.0%	73	23	68.5%
305	25	16	5	68.8%	77	10	87.0%	15	11	26.7%	75	31	58.7%
307		16	3	81.3%	76	8	89.5%	16	8	50.0%	76	19	75.0%
311		16	3	81.3%	76	10	86.8%	16	5	68.8%	76	19	75.0%
316	80	16	2	87.5%	76	5	93.4%	16	5	68.8%	76	17	77.6%
318		16	1	93.8%	77	10	87.0%	16	7	56.3%	76	32	57.9%
319	170	16	1	93.8%	77	3	96.1%	16	8	50.0%	77	44	42.9%
329		12	1	91.7%	54	2	96.3%	12	2	83.3%	54	4	92.6%
330		14	0	100.0%	65	2	96.9%	14	4	71.4%	65	5	92.3%
331		16	5	68.8%	77	9	88.3%	16	4	75.0%	77	10	87.0%
332		16	3	81.3%	77	8	89.6%	16	5	68.8%	77	10	87.0%
334		16	1	93.8%	77	2	97.4%	16	6	62.5%	76	10	86.8%
335		16	5	68.8%	77	12	84.4%	15	3	80.0%	75	12	84.0%
336		16	2	87.5%	77	3	96.1%	16	1	93.8%	77	5	93.5%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
337		16	0	100.0%	77	4	94.8%	16	3	81.3%	77	8	89.6%
338		16	2	87.5%	77	17	77.9%	15	5	66.7%	75	17	77.3%
339		16	3	81.3%	77	17	77.9%	16	5	68.8%	77	16	79.2%
341		14	3	78.6%	74	12	83.8%	14	4	71.4%	74	12	83.8%
342		16	1	93.8%	77	7	90.9%	16	5	68.8%	76	13	82.9%
350	20	16	0	100.0%	59	2	96.6%	16	11	31.3%	59	33	44.1%
351	29	16	6	62.5%	77	9	88.3%	16	7	56.3%	77	33	57.1%
352	64	16	2	87.5%	77	6	92.2%	15	5	66.7%	74	19	74.3%
353		16	3	81.3%	56	5	91.1%	16	9	43.8%	56	14	75.0%
354	276	16	4	75.0%	77	7	90.9%	15	10	33.3%	76	24	68.4%
355	22	15	2	86.7%	76	7	90.8%	14	6	57.1%	75	19	74.7%
364		15	7	53.3%	76	12	84.2%	14	6	57.1%	75	14	81.3%
365	110	15	3	80.0%	76	5	93.4%	14	9	35.7%	75	25	66.7%
370		16	3	81.3%	77	5	93.5%	16	6	62.5%	77	15	80.5%
380		16	3	81.3%	77	13	83.1%	16	4	75.0%	77	17	77.9%
381		16	1	93.8%	77	2	97.4%	16	2	87.5%	77	9	88.3%
382		16	0	100.0%	77	2	97.4%	16	4	75.0%	77	19	75.3%
383		16	4	75.0%	77	9	88.3%	16	9	43.8%	76	31	59.2%
390	22	8	3	62.5%	61	7	88.5%	8	4	50.0%	61	20	67.2%
391		8	1	87.5%	62	1	98.4%	8	2	75.0%	61	14	77.0%
392	38	16	1	93.8%	77	3	96.1%	16	10	37.5%	76	25	67.1%
393	23	16	1	93.8%	77	6	92.2%	16	5	68.8%	76	20	73.7%
417		12	1	91.7%	51	9	82.4%	11	0	100.0%	48	1	97.9%
425		12	0	100.0%	51	1	98.0%	12	0	100.0%	51	1	98.0%
448		16	8	50.0%	18	9	50.0%	15	8	46.7%	16	8	50.0%
470	58	12	3	75.0%	54	8	85.2%	12	2	83.3%	54	9	83.3%
471		12	1	91.7%	51	1	98.0%	12	0	100.0%	51	0	100.0%
473		12	0	100.0%	54	3	94.4%	12	0	100.0%	54	1	98.1%
474		12	5	58.3%	52	18	65.4%	11	7	36.4%	48	18	62.5%
475		12	0	100.0%	54	0	100.0%	12	0	100.0%	54	1	98.1%
478		12	1	91.7%	52	11	78.8%	12	0	100.0%	52	6	88.5%
479		12	3	75.0%	54	7	87.0%	12	1	91.7%	54	2	96.3%
486		12	1	91.7%	55	8	85.5%	12	2	83.3%	54	8	85.2%
490		12	1	91.7%	31	6	80.6%	12	0	100.0%	31	2	93.5%
494	17	12	0	100.0%	56	9	83.9%	12	4	66.7%	53	11	79.2%
495		12	0	100.0%	54	2	96.3%	12	0	100.0%	54	1	98.1%
500		16	1	93.8%	77	6	92.2%	16	2	87.5%	76	7	90.8%
502		16	1	93.8%	77	7	90.9%	16	1	93.8%	76	17	77.6%
503		16	3	81.3%	74	11	85.1%	16	4	75.0%	73	19	74.0%
504		16	2	87.5%	77	7	90.9%	16	5	68.8%	77	24	68.8%
505		16	2	87.5%	77	12	84.4%	16	2	87.5%	75	15	80.0%
506		16	3	81.3%	76	12	84.2%	16	1	93.8%	75	10	86.7%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
507	22	16	2	87.5%	77	9	88.3%	16	4	75.0%	77	26	66.2%
508		16	2	87.5%	75	13	82.7%	16	5	68.8%	75	18	76.0%
509		16	1	93.8%	77	5	93.5%	16	7	56.3%	77	20	74.0%
511		16	1	93.8%	77	5	93.5%	16	3	81.3%	77	15	80.5%
516		14	0	100.0%	75	9	88.0%	14	4	71.4%	75	32	57.3%
517		16	0	100.0%	77	1	98.7%	16	6	62.5%	76	28	63.2%
518		16	0	100.0%	77	13	83.1%	16	9	43.8%	77	45	41.6%
519	33	14	1	92.9%	75	4	94.7%	14	3	78.6%	75	12	84.0%
520	31	12	3	75.0%	50	6	88.0%	11	1	90.9%	49	3	93.9%
521		12	0	100.0%	53	0	100.0%	12	1	91.7%	53	4	92.5%
522		12	4	66.7%	53	8	84.9%	11	1	90.9%	52	5	90.4%
523		12	0	100.0%	53	0	100.0%	12	3	75.0%	53	7	86.8%
524		12	0	100.0%	53	2	96.2%	12	1	91.7%	53	4	92.5%
525		12	1	91.7%	53	2	96.2%	11	1	90.9%	52	6	88.5%
526		12	4	66.7%	53	10	81.1%	11	1	90.9%	52	5	90.4%
527		12	0	100.0%	53	1	98.1%	12	1	91.7%	53	3	94.3%
528		12	1	91.7%	53	6	88.7%	12	2	83.3%	53	12	77.4%
529		12	0	100.0%	53	3	94.3%	12	2	83.3%	53	9	83.0%
530		7	0	100.0%	7	0	100.0%	7	0	100.0%	7	0	100.0%
531		12	0	100.0%	53	1	98.1%	12	2	83.3%	53	5	90.6%
532		12	2	83.3%	53	3	94.3%	12	1	91.7%	53	8	84.9%
534		12	1	91.7%	50	6	88.0%	12	2	83.3%	50	5	90.0%
535		11	3	72.7%	49	4	91.8%	10	1	90.0%	48	2	95.8%
536		12	2	83.3%	53	6	88.7%	11	1	90.9%	52	2	96.2%
537		12	2	83.3%	53	5	90.6%	11	1	90.9%	52	2	96.2%
538	37	12	1	91.7%	53	7	86.8%	12	4	66.7%	53	9	83.0%
539		7	0	100.0%	7	0	100.0%	7	4	42.9%	7	4	42.9%
540		12	3	75.0%	53	7	86.8%	11	1	90.9%	50	2	96.0%
541		12	3	75.0%	53	8	84.9%	12	4	66.7%	53	15	71.7%
542		12	0	100.0%	53	3	94.3%	12	1	91.7%	52	11	78.8%
543		12	0	100.0%	53	6	88.7%	12	1	91.7%	53	13	75.5%
544		12	1	91.7%	52	3	94.2%	12	3	75.0%	52	7	86.5%
545		12	2	83.3%	53	6	88.7%	12	1	91.7%	52	5	90.4%
547		12	0	100.0%	53	4	92.5%	12	2	83.3%	53	9	83.0%
548		12	2	83.3%	53	10	81.1%	12	1	91.7%	53	6	88.7%
549		12	3	75.0%	50	13	74.0%	10	0	100.0%	47	6	87.2%
550		7	2	71.4%	7	2	71.4%	7	1	85.7%	7	1	85.7%
551		12	1	91.7%	53	7	86.8%	12	1	91.7%	51	7	86.3%
562		16	3	81.3%	75	11	85.3%	16	3	81.3%	74	9	87.8%
564		16	1	93.8%	75	7	90.7%	15	2	86.7%	71	12	83.1%
566		16	1	93.8%	75	6	92.0%	16	2	87.5%	72	8	88.9%
572		16	0	100.0%	74	6	91.9%	16	0	100.0%	73	14	80.8%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		16	2	87.5%	75	11	85.3%	15	0	100.0%	73	8	89.0%
577		16	1	93.8%	73	6	91.8%	16	4	75.0%	69	6	91.3%
580		16	0	100.0%	75	2	97.3%	16	1	93.8%	75	8	89.3%
581		16	0	100.0%	75	7	90.7%	16	2	87.5%	75	14	81.3%
582		16	2	87.5%	75	6	92.0%	16	1	93.8%	73	5	93.2%
586		16	3	81.3%	75	14	81.3%	16	0	100.0%	72	9	87.5%
587		16	0	100.0%	75	3	96.0%	16	0	100.0%	73	9	87.7%
591		16	0	100.0%	75	1	98.7%	16	0	100.0%	75	6	92.0%
593		16	2	87.5%	75	11	85.3%	15	0	100.0%	68	5	92.6%
595	No OS	16	1	93.8%	74	15	79.7%	16	1	93.8%	73	11	84.9%
600	184	12	1	91.7%	54	2	96.3%	12	1	91.7%	54	5	90.7%
601	22	12	9	25.0%	54	28	48.1%	12	2	83.3%	54	15	72.2%
605	89	12	11	8.3%	54	32	40.7%	12	3	75.0%	53	5	90.6%
607	54	12	1	91.7%	54	4	92.6%	12	3	75.0%	53	4	92.5%
609	13	12	2	83.3%	53	3	94.3%	12	1	91.7%	53	4	92.5%
620	14	12	5	58.3%	53	14	73.6%	12	1	91.7%	51	3	94.1%
624	26	12	3	75.0%	54	13	75.9%	11	3	72.7%	54	12	77.8%
639	22	12	5	58.3%	54	15	72.2%	12	1	91.7%	54	5	90.7%
640	24	12	1	91.7%	54	3	94.4%	12	9	25.0%	54	27	50.0%
641	63	12	6	50.0%	54	11	79.6%	12	4	66.7%	54	11	79.6%
642		12	1	91.7%	53	3	94.3%	12	2	83.3%	53	6	88.7%
643		12	3	75.0%	54	10	81.5%	12	4	66.7%	53	7	86.8%
644	19	12	4	66.7%	54	9	83.3%	12	5	58.3%	54	10	81.5%
645	16	12	2	83.3%	54	5	90.7%	12	4	66.7%	54	10	81.5%
646	64	12	5	58.3%	54	12	77.8%	12	10	16.7%	53	30	43.4%
647	57	12	2	83.3%	54	4	92.6%	12	2	83.3%	54	14	74.1%
648	57	12	5	58.3%	54	11	79.6%	12	4	66.7%	54	8	85.2%
649	15	12	4	66.7%	54	10	81.5%	12	2	83.3%	53	9	83.0%
650	33	12	2	83.3%	54	11	79.6%	12	6	50.0%	54	13	75.9%
651	42	12	0	100.0%	54	5	90.7%	12	4	66.7%	54	17	68.5%
652		12	2	83.3%	54	10	81.5%	12	3	75.0%	53	11	79.2%
653	11	12	3	75.0%	54	11	79.6%	12	2	83.3%	54	16	70.4%
654	51	12	6	50.0%	54	11	79.6%	12	3	75.0%	54	5	90.7%
655	22	12	4	66.7%	52	16	69.2%	12	6	50.0%	51	14	72.5%
656		12	3	75.0%	54	10	81.5%	12	0	100.0%	54	5	90.7%
657		12	0	100.0%	54	3	94.4%	12	0	100.0%	54	9	83.3%
658	17	12	1	91.7%	54	8	85.2%	12	3	75.0%	54	9	83.3%
680		12	0	100.0%	55	2	96.4%	12	3	75.0%	55	6	89.1%
681	14	12	1	91.7%	55	3	94.5%	12	4	66.7%	55	17	69.1%
682		12	0	100.0%	55	0	100.0%	12	3	75.0%	55	13	76.4%
683	27	12	0	100.0%	38	3	92.1%	12	3	75.0%	38	12	68.4%
684	22	12	1	91.7%	37	5	86.5%	12	2	83.3%	37	10	73.0%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685		12	2	83.3%	54	6	88.9%	12	2	83.3%	54	15	72.2%
686	18	12	2	83.3%	55	15	72.7%	12	4	66.7%	55	14	74.5%
687		12	2	83.3%	55	8	85.5%	12	4	66.7%	55	10	81.8%
688		12	0	100.0%	55	1	98.2%	12	2	83.3%	55	14	74.5%
689		8	0	100.0%	44	4	90.9%	7	1	85.7%	43	4	90.7%
701		9	3	66.7%	9	3	66.7%	9	2	77.8%	9	2	77.8%
702		16	2	87.5%	77	17	77.9%	16	3	81.3%	76	22	71.1%
703	40	16	3	81.3%	77	18	76.6%	16	4	75.0%	77	20	74.0%
704		9	3	66.7%	9	3	66.7%	8	3	62.5%	8	3	62.5%
710		16	7	56.3%	77	31	59.7%	16	1	93.8%	77	29	62.3%
711		16	2	87.5%	73	6	91.8%	13	3	76.9%	66	10	84.8%
712		16	3	81.3%	77	20	74.0%	16	5	68.8%	76	28	63.2%
713	Cncld	15	3	80.0%	76	12	84.2%	12	4	66.7%	67	31	53.7%
714		16	6	62.5%	71	25	64.8%	16	4	75.0%	66	20	69.7%
715	Cncld	16	4	75.0%	77	26	66.2%	14	7	50.0%	72	36	50.0%
716	46	16	8	50.0%	77	31	59.7%	16	8	50.0%	76	31	59.2%
717	17	16	3	81.3%	68	16	76.5%	16	7	56.3%	63	20	68.3%
718		16	10	37.5%	77	32	58.4%	15	5	66.7%	76	21	72.4%
719	98	16	3	81.3%	77	27	64.9%	16	5	68.8%	75	21	72.0%
761		16	0	100.0%	75	3	96.0%	16	0	100.0%	75	9	88.0%
765		16	1	93.8%	75	8	89.3%	16	1	93.8%	75	14	81.3%
769		16	1	93.8%	75	5	93.3%	16	1	93.8%	73	12	83.6%
770		16	0	100.0%	75	7	90.7%	16	1	93.8%	75	10	86.7%
774		16	0	100.0%	75	6	92.0%	16	2	87.5%	74	13	82.4%
779		16	0	100.0%	75	4	94.7%	16	0	100.0%	74	9	87.8%
784	33	16	2	87.5%	75	8	89.3%	16	8	50.0%	74	37	50.0%
785		16	0	100.0%	75	0	100.0%	16	1	93.8%	75	8	89.3%
790	48	16	0	100.0%	75	5	93.3%	16	1	93.8%	75	8	89.3%
794		16	1	93.8%	75	6	92.0%	16	2	87.5%	74	12	83.8%
821		16	0	100.0%	77	3	96.1%	16	6	62.5%	77	46	40.3%
822		16	0	100.0%	77	3	96.1%	16	2	87.5%	77	46	40.3%
1333		16	4	75.0%	77	8	89.6%	16	6	62.5%	76	32	57.9%
1340		16	0	100.0%	77	3	96.1%	16	6	62.5%	77	19	75.3%
2103	18	12	1	91.7%	53	4	92.5%	12	2	83.3%	53	3	94.3%
2104		12	2	83.3%	24	4	83.3%	12	1	91.7%	24	3	87.5%
2107	39	12	3	75.0%	54	10	81.5%	12	3	75.0%	52	3	94.2%
2108		12	2	83.3%	54	4	92.6%	12	2	83.3%	52	2	96.2%
2117	20	12	4	66.7%	24	7	70.8%	12	3	75.0%	24	4	83.3%
2121	19	12	3	75.0%	52	6	88.5%	12	2	83.3%	52	5	90.4%
2122		12	0	100.0%	54	6	88.9%	12	0	100.0%	54	3	94.4%
2124		10	2	80.0%	40	6	85.0%	10	1	90.0%	40	2	95.0%
2150	Cncld	12	1	91.7%	54	10	81.5%	11	2	81.8%	53	11	79.2%

Amtrak On Time Performance

Trains Arriving Through: 12/16/2025

28-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2151	35	12	0	100.0%	54	0	100.0%	12	5	58.3%	53	11	79.2%
2152	93	12	1	91.7%	50	3	94.0%	12	9	25.0%	49	18	63.3%
2153		12	0	100.0%	54	6	88.9%	12	3	75.0%	54	12	77.8%
2154	47	12	3	75.0%	54	17	68.5%	12	7	41.7%	52	28	46.2%
2155	45	12	1	91.7%	54	3	94.4%	12	7	41.7%	52	16	69.2%
2159	65	12	0	100.0%	53	1	98.1%	12	5	58.3%	53	12	77.4%
2162	36	12	0	100.0%	54	2	96.3%	12	3	75.0%	53	12	77.4%
2163	53	12	0	100.0%	54	4	92.6%	12	5	58.3%	54	15	72.2%
2166	24	12	1	91.7%	54	6	88.9%	12	4	66.7%	52	10	80.8%
2168		12	1	91.7%	54	3	94.4%	12	1	91.7%	54	7	87.0%
2169	76	12	8	33.3%	50	18	64.0%	12	9	25.0%	50	24	52.0%
2170		12	3	75.0%	54	10	81.5%	12	2	83.3%	54	11	79.6%
2172		12	0	100.0%	54	6	88.9%	12	3	75.0%	54	10	81.5%
2173		12	3	75.0%	53	10	81.1%	12	2	83.3%	53	20	62.3%
2190		12	3	75.0%	54	8	85.2%	11	2	81.8%	53	6	88.7%
2193	21	12	1	91.7%	53	2	96.2%	12	4	66.7%	53	13	75.5%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

Train	Terminal	Late	Max Type		Max Single Delay Item				
			Type	Mins	Type	Mins	Between	Host	Delay Reason
2103	WAS	18	DMW	11	DMW	11	XPV-BAL	AM	Hold for defect repair, Milepost, 88.5, 88.5, OPERATE 1 TRACK A/C BROKEN RAIL MP 88.5
2107	WAS	39	DMW	10	CTI	9	BAL-XNY	AM	Follow, MARC, 9423, Control Point, GROVE TO AVENUE
2117	WAS	20	DSR	10	DSR	10	PHL-WIL	AM	Per dispatcher (radio/phone), Control Point, HOLLY, 10, 3
2121	WAS	19	HLD	17	HLD	15	NYP-NYP	AM	Passenger and/or baggage, HELD DUE TO PSNGRS DEPARTING FROM AM280
2150	XHM	Trn Cancelled	ENG	38	ENG	38	BAL-XPV	AM	Undesired emergency application, 2035 2039, LOW MAIN RES ALARM MP 84.9
2151	WAS	35	DMW	21	DMW	13	NHV-STM	MN	Hold for defect repair Control Point, East Norwalk
2152	BOS	93	ENG	40	ENG	32	BAL-XPV	AM	Undesired emergency application, 2035 2039, PANTOGRAPH DROPPED, LOW MAIN RES
2154	BOS	47	WTR	24	WTR	22	PVD-RTE	AM	Ice / snow on or under equipment, Milepost, xmf, xmf, Stopped at Mansfield crossover track and Engr Couldn't not see signal a/c sun in Eng. Eyes
2155	WAS	45	DSR	23	DSR	14	NHV-STM	MN	Per MW foreman Waited for clearance from mobile unit 803 for permission through the working limits, Milepost, 41.1, 40.3, 30, 3
2159	WAS	65	ENG	55	ENG	55	XCY-XHM	AM	Other electrical failure, 2019, STOPPED DUE TO MISMATCHED HAND BRAKE INDICATION
2162	BOS	36	WTR	30	WTR	14	NYP-NYP	AM	Snow removal equipment working ahead, Other, XBH-NYP, DELAYED FROM STATION A/C SINGLE TRACKING DUE TO ICE PATROL
2163	WAS	53	ENG	27	ENG	27	WIL-XPV	AM	Air / Brake, PC/2011, stopped at MP 33 a/c MCB opened and brake line issues
2166	BOS	24	HLD	12	MTI	7	XCY-NWK	AM	Disabled train ahead, Other, XIS-XEO, AM650 DISDABLE EAST OF LINDEN STATION
2169	WAS	76	ITI	64	ITI	64	BOS-BOS	AM	Service, turn, or wye train, 2152, LATE A/C LATE TURN OF AM2152
2193	NYP	21	SMW	20	SMW	20	XSH-NYP	AM	Scheduled in track usage program, Other, XM9-XM9, HELD FOR AM136 ON NO.2 TRK A/C NO.1 TRK OOS PELHAM BAY TO LEGGETT

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
85	RVM	28	SVS	48	SVS	48	BOS-BOS	AM	Planned set out / pick out of locomotives, cars or section of train, Late release from yard a/c mechanical issues
86	BOS	31	CTI	21	CTI	9	NHV-NLC	AM	Follow, CDOT, 1632, Milepost w/Letters, XL3, XSS, SIGNALS OF CD1632 AHEAD TRK 2 CONN - SHAWS COVE
95	NFK	37	PTI	55	PTI	23	WDB-FBG	CS	Follow vre303, Other, cfp88.9-58.9
114	NYP	28	WTR	34	WTR	34	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, WAS, LATE TURN TRAIN ARRIVAL, AND FROZEN DOORS
129	WAS	30	CTI	15	ITI	13	NYP-NYP	AM	Service, turn, or wye train, 114
131	WAS	23	OTH	8	CTI	7	PJC-TRE	AM	Follow, NJT, 3839, Other, PJC-TRE
133	WAS	18	ITI	8	ITI	8	NYP-NYP	AM	Service, turn, or wye train, 182, LATE TURN OFF AM182
136	SPG	136	WTR	129	WTR	114	WAS-WAS	AM	Ice / snow on or under equipment, Control Point, K INTERLOCKING, legacy delay of push-pull set originating in WAS as 112/131 late turn due to inclement weather and frozen doors
141	NFK	39	FTI	39	FTI	18	FBG-ASD	CS	Follow I031, Milepost w/Letters, FBG, ASD
170	BOS	76	MTI	57	MTI	32	BAL-XPV	AM	Disabled train ahead, Milepost, 84.9, 26.8, FOLLOWED 2150 AHEAD
172	BOS	107	WTR	68	WTR	55	WAS-WAS	AM	Ice / snow on or under equipment, Other, Washington Union Station , 173 turning for 130 arrived 2hrs late due to severe weather in Boston which put S&I behind delaying 172's entrance to S&I along with shop car.
177	PHL	47	ITI	40	ITI	40	BOS-BOS	AM	Service, turn, or wye train, 172, LATE TURN OF AM172
181	WAS	64	DMW	57	DMW	52	NYP-NYP	AM	Hold for defect repair, Other, NYP-NYP, DELAYED DUE TO BROKEN RAIL IN LINE 4
183	WAS	68	DMW	72	DMW	69	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
197	WAS	25	CTI	18	CTI	8	NYP-NWK	AM	Follow, NJT, NJ3271, Other, NYP-NWK
470	SPG	58	CON	56	CON	56	NHV-NHV	AM	Hold for connecting train
494	GFD	17	FTI	18	FTI	18	NHT-GFD	MA	Meet EDPL, Control Point, CPR18
53	SFA	45	DCS	48	DCS	42	XSA-XJG	CS	Power switch failure Control Point, ogeechee

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
79	CLT	169	DMW	189	DMW	189	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
80	NYP	33	POL	21	POL	21	XHM-TRE	AM	On-train police or DEA activity, AM654 AHEAD IN TRENTON NO.1 TRK WITH POLICE AND EMS
600	NYP	184	ENG	129	ENG	129	PHL-XHM	AM	Other electrical failure, 656, Unable to keep pantographs raised.
601	HAR	22	WTR	17	WTR	13	PAR-PAR	AM	Ice / snow on or under equipment, Control Point, ., FROZEN DOORS WHOLE WAY THROUGH.
605	HAR	89	WTR	85	WTR	66	PHL-PHL	AM	Ice / snow on or under equipment, Control Point, ., FROZEN DOORS. ASSISTED BY MECHANICAL.
607	HAR	54	DMW	65	DMW	65	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
609	HAR	13	CTP	20	CTP	20	NYP-NYP	AM	Delay due to mechanical problems on a Commuter train, DELAYED DUE TO NJ3838 DISABLED IN "A" INT
620	PHL	14	ITI	19	ITI	19	HAR-HAR	AM	Service, turn, or wye train, 651, late turn off 651
624	NYP	26	CAR	10	CAR	10	NWK-NWK	AM	Door, N/A, AS PER SECTION B DSPR, AM624 HAVING DOOR ISSUES NO DOOR OR CAR SPECIFIED.
639	PHL	22	ITI	27	ITI	27	NYP-NYP	AM	Service, turn, or wye train, 654
640	NYP	24	WTR	21	WTR	8	EXT-EXT	AM	Ice / snow on or under equipment, Control Point, EXT , FROZEN DOORS
641	HAR	63	DMW	44	DMW	44	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
644	NYP	19	WTR	12	CTC	7	HAR-HAR	AM	PTC - Stop Bypass Permission Required, Control Point, ., STOP BYPASS ON E/ 646
645	HAR	16	WTR	8	WTR	6	PAR-PAR	AM	Ice / snow on or under equipment, Control Point, ., frozen doors
646	NYP	64	ITI	49	ITI	49	HAR-HAR	AM	Service, turn, or wye train, 605
647	HAR	57	ITI	29	ITI	29	NYP-NYP	AM	Service, turn, or wye train, 648, LATE TURN OFF AM648
648	NYP	57	ITI	36	ITI	36	HAR-HAR	AM	Service, turn, or wye train, 607

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
649	HAR	15	ENG	16	ENG	16	PAR-LNC	AM	PTC - On Board Cab Signal or PTC Failure, E/660, cabs went to restricting at MP 53.0
650	NYP	33	ENG	31	ENG	31	PJC-NWK	AM	HEP, 625, LOST HEP AT MP17.3
651	HAR	42	CTP	25	SVS	23	PHL-PHL	AM	Planned set out / pick out of locomotives, cars or section of train
653	HAR	11	OTH	7	OTH	3	EXT-DOW	AM	Lost time - N.A.R., insufficient run time
654	NYP	51	CTP	57	CTP	22	PAR-DOW	AM	Delay due to mechanical problems on a Commuter train, disabled SEPTA 5344 ahead
655	HAR	22	CTI	10	CTI	7	NWK-TRE	AM	Blocked from station track, NJT, NJ3871, Other, TRE-TRE
658	NYP	17	OTH	14	DSR	10	TRE-NWK	AM	Per MW foreman, Other, XCY-XIS, 10, 2, 10 MPH S/R NO.2 TRK LINCOLN INT LIMITS
681	BRK	14	DCS	17	DCS	10	SAO-POR	CS	Power switch failure Rule 241, Control Point, Cooks
683	BRK	27	DCS	19	PTI	17	EXR-DHM	CS	Meet 684, Control Point, rockingham
684	BON	22	DCS	12	DCS	10	POR-SAO	CS	Restrictive signal(s) from known wayside signal failure Cooks, Control Point, cooks
686	BON	18	DCS	15	DCS	15	POR-SAO	CS	Restrictive signal(s) from unknown cause R 241, Stop signal, Stop signal, Control Point, Rigby East, Control Point, Cooks
63	TWO	38	DMW	53	DMW	46	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
68	NYP	28	CTI	17	CTI	17	POU-CRT	MN	Follow Metro North, 892, Other, New Hamburg, Control Point, 39
233	ALB	63	ITI	41	ITI	41	NYP-NYP	AM	Service, turn, or wye train, 236, LATE TURN OFF AM236
236	NYP	36	ENG	36	ENG	24	POU-POU	MN	Troubleshooting with Albany mechanical to reset the air compressor 714
240	NYP	23	CTI	14	CTI	14	POU-CRT	MN	Follow metro north, local, Control Point, 46
280	NYP	74	SYS	54	SYS	54	NFL-NFL	CS	Other late crew
49	CHI	97	ENG	150	ENG	150	NYP-NYP	AM	PTC - On Board Cab Signal or PTC Failure, 703, NECESSARY TO RETURN TO SSYD FOR ENGINE SWAP A/C ASCES ISSUES
42	NYP	71	DCS	41	DCS	41	LAB-JST	NS	Power switch failure Control Point, CP-CONPIT
71	CLT	54	DCS	51	DCS	51	KAN-CLT	NS	Power switch failure Control Point, AT&O

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
72	RGH	24	ITI	17	ITI	17	CLT-CLT	NS	Service, turn, or wye train 71
77	CLT	15	PTI	15	PTI	9	HPT-SAL	NS	Meet #Amt76, Control Point, Duke
89	SAV	87	DMW	140	DMW	93	NYP-NYP	AM	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
90	NYP	106	FTI	105	FTI	105	XDJ-ALX	CS	Cross over or go around Made reverse move to the cfp87.2 to go around, 410, Other, cfp95.3
98	NYP	62	CTI	50	CTI	23	XDJ-ALX	CS	Follow VRE, 304, Milepost w/Letters, CFP 79.5, CFP 92.0
55	WAS	34	PTI	33	PTI	10	WNL-HFD	AM	Meet, 486, Milepost w/Letters, WNL, HFD, MET AM486 AT HFD
56	SAB	122	WTR	124	WTR	124	WAS-WAS	AM	Ice / snow on or under equipment, Other, Washington Union Station , 173 turning for 130 arrived 2hrs late due to severe weather in Boston which put S&I behind delaying 172's entrance to S&I along with shop car.
41	MIA	362	DMW	214	DMW	123	SAV-XJG	CS	Hold for defect repair Milepost, 520.0, 520.0
5	EMY	79	FTI	164	ENG	80	DEN-DEN	RT	Air / Brake Air brakes wouldn't bail off on engine 207. Swapped engines at DUS., 207
520	SAC	31	ITI	25	ITI	25	OKJ-OKJ	UP	Service, turn, or wye train 520, Radio was not working in Cab Car 8314had to swap equipment with 522.
538	ARN	37	POL	56	POL	54	FMT-HAY	UP	Right of Way police hold
507	EUG	22	PTI	27	PTI	27	PDX-ORC	UP	Meet 508 was delayed after emergency brake application from striking tree branches, amtrak 508, Siding, Clackamas
519	SEA	33	DCS	22	PTI	18	EDM-SEA	BN	Wait for station track Amtrak 8, Control Point, North Portal
58	CHI	79	DMW	60	DMW	60	EFG-MAT	CC	Hold for defect repair Broken rail, Milepost, 180.92, 180.92
7	SEA	199	CAR	217	CAR	192	WFH-LIB	BN	Plow damaged from a tree strike. 60
27	PDX	-2	FTI	34	FTI	9	PSC-WIH	BN	Follow BN 6380, Control Point, West Towal, Siding, Maryhill
350	PNT	20	PTI	28	ENG	21	HMI-HMI	NS	Air / Brake Was able to rectify the issue with the compressor. Low MR and low brake pipe pressure, ID4627

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
351	CHI	29	CAR	18	CAR	18	DER-ARB	MI	Air / Brake / Wheel ID4203, 2 air hose separations between last car and backup tailhose. After 2nd separation removed tailhose completely. RFE and west Ops notified of actions taken and okayed by RFE
352	PNT	64	RTE	42	RTE	34	BTL-BTL	CC	Routed to abnormal station track due to N.A.R. Inbound trn routed to wrong station track by CN dispatcher, Control Point, gord
354	PNT	276	PTI	201	PTI	199	BTL-XB0	CC	Meet 355, 354, Control Point, btl
355	CHI	22	PTI	26	PTI	14	ARB-JXN	MI	Meet 352, Milepost, 70, 72
365	CHI	110	SVS	55	SVS	55	PTH-PTH	CC	Routine inspections Train 364 left CHICAGO late on 12/15. Arriving Port Huron late. PTH mechanical service and inspection of train., Other, PTH Station
595	LAX	No OS Rpt	FTI	92	FTI	92	OSD-OSD	SN	Hold due to freight train breaking in half 7649, Control Point, Shell
784	SAN	33	CTI	31	PTI	16	SNC-SNP	SC	Meet 587, Control Point, serra
790	SAN	48	FTI	63	FTI	63	X98-OSD	SN	Meet Broken knuckle on freight train, bnsf, Control Point, pulgas
703	SAC	40	PTI	36	FTI	27	MCD-MCD	BN	BNSF 6820 blocking Modesto empire. Trains are back up all the way to Merced. bnsf 6820, Control Point, merced
713	OKJ	Trn Cancelled	FTI	28	FTI	21	WAC-COC	BN	Meet Z (both), bnsf 8025, bnsf 3732, Siding, Angiola
715	OKJ	Trn Cancelled	PTI	32	PTI	13	ACA-XPR	BN	Meet 716, Siding, Pittsburg
716	BFD	46	PTI	39	PTI	17	TRK-MCD	BN	Meet 717, Control Point, Ballico
717	OKJ	17	POL	27	POL	27	MDR-MCD	BN	Blocked by the removal of a trespasser on the right of way
719	OKJ	98	FTI	124	FTI	113	TRK-MOD	BN	Train stuck on shunt. Had to wait for clearance. bnsf 6820, Control Point, west empire
3	LAX	166	FTI	142	FTI	118	LAP-XC7	BN	Blocked from station track I was stopped at CA JCT because BN 5904 wasn't working, then I was told by the dispatcher to shove back from CA JCT to Hardin, so I would be able to go around., 5904, Control Point, CA JCT
305	STL	25	RTE	23	RTE	23	BNL-BNL	UP	Dispatcher hold Held at BNL station, due to bad order ahead of us, Control Point, BNL

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Region: ALL

Service: ALL

Arriving On: 12/16/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
390	CHI	22	DCS	21	DCS	15	KKI-HMW	CC	Restrictive signal(s) from unknown cause Flag n KKI clr 46.20, Stop, Control Point, n kki	
392	CHI	38	PTI	28	PTI	28	MAT-CHM	CC	Meet amtrak 393, Siding, tolong	
393	CDL	23	FTI	35	FTI	21	GLM-RTL	CC	Follow cn 8953s, Milepost, 80, 100	
316	STL	80	PTI	40	PTI	40	JEF-HEM	UP	Meet AMT 319, Control Point, Moreau	
319	KCY	170	ENG	109	ENG	109	CHI-CHI	AM	Set out defective locomotive Swapped out Engines Was IDTX 4602 For IDTX 4622, ID4602	

Amtrak Initial Terminal Details

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/16/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	72	12/16	17	17	Service, turn, or wye train 71
CLT	80	12/16	2	2	Loading problem Door circuit not complete and doors were shut, 348
HAR	600	12/16	1		
HAR	620	12/16	19	19	Service, turn, or wye train, 651, late turn off 651
HAR	644	12/16	7	7	PTC - Stop Bypass Permission Required, Control Point, ., STOP BYPASS ON E/ 646
HAR	646	12/16	49	49	Service, turn, or wye train, 605
HAR	648	12/16	36	36	Service, turn, or wye train, 607
HAR	650	12/16	2	2	High passenger count, PER DSPR 1213P
HAR	652	12/16	1		
HAR	654	12/16	1		
NFK	94	12/16	1		
PHL	110	12/16	3	3	Ice / snow on or under equipment, Control Point, PAR, FROZEN DOORS. ALL DOORS.
PHL	190	12/16	1		
PHL	601	12/16	1		
PHL	605	12/16	66	66	Ice / snow on or under equipment, Control Point, ., FROZEN DOORS. ASSISTED BY MECHANICAL.
WAS	56	12/16	124	124	Ice / snow on or under equipment, Other, Washington Union Station , 173 turning for 130 arrived 2hrs late due to severe weather in Boston which put S&I behind delaying 172's entrance to S&I along with shop car.
WAS	114	12/16	34	34	Ice / snow on or under equipment, Control Point, WAS, LATE TURN TRAIN ARRIVAL, AND FROZEN DOORS
WAS	172	12/16	55	55	Ice / snow on or under equipment, Other, Washington Union Station , 173 turning for 130 arrived 2hrs late due to severe weather in Boston which put S&I behind delaying 172's entrance to S&I along with shop car.
WAS	178	12/16	2	2	Planned Switch, MARC DSL'S SHIFTING TO THE UPPER LEVEL TO BE SET OFF ON TRAINS
WAS	2104	12/16	2	2	Follow, MARC, 610, Bridge, H BRIDGE, MARC 610 WAS HAVING MECH. ISSUES 42 TRACK JUST SOUTH OF K BRIDGE
WAS	2166	12/16	1		
BOS	85	12/16	48	48	Planned set out / pick out of locomotives, cars or section of train, Late release from yard a/c mechanical issues
BOS	175	12/16	8	8	Service, turn, or wye train, 170, LATE A/C LATE TURN OF AM170
BOS	177	12/16	40	40	Service, turn, or wye train, 172, LATE TURN OF AM172

Amtrak Initial Terminal Details

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/16/2025

Terminal	Train	Date	Late	Delay	Cause
BOS	2169	12/16	64	64	Service, turn, or wye train, 2152, LATE A/C LATE TURN OF AM2152
BRK	686	12/16	2	2	Inability to contact dispatcher Tried to call for msgs at facility and was put on hold for 10m so hung up to do at station. Once we prepped and boarded the train I tried dispatcher again at departure. Was able to get through and had no msgs., Control Point, Brunswick West
NFL	280	12/16	54	54	Other late crew
NYP	19	12/16	32	32	Ice / snow on or under equipment, Control Point, LINE 2, HELD A/C ICE PATROL LINE 2
NYP	49	12/16	5	5	Routine inspections, LATE F/SSYD A/C UNSPECIFIED REASONS
NYP	63	12/16	46	46	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	79	12/16	189	189	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	89	12/16	92	93	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	97	12/16	112	112	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C NEEDED 3 SLEEPER AND 1 BAGGAGE CAR OFF AM98
NYP	111	12/16	2	2	Passenger and/or baggage, BOARDING
NYP	129	12/16	13	13	Service, turn, or wye train, 114
NYP	133	12/16	7	8	Service, turn, or wye train, 182, LATE TURN OFF AM182
NYP	181	12/16	52	52	Hold for defect repair, Other, NYP-NYP, DELAYED DUE TO BROKEN RAIL IN LINE 4
NYP	183	12/16	69	69	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	233	12/16	41	41	Service, turn, or wye train, 236, LATE TURN OFF AM236
NYP	291	12/16	9	9	Passenger and/or baggage, HELD FOR TRAVEL OFF AM280
NYP	607	12/16	65	65	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	609	12/16	20	20	Delay due to mechanical problems on a Commuter train, DELAYED DUE TO NJ3838 DISABLED IN "A" INT
NYP	639	12/16	27	27	Service, turn, or wye train, 654
NYP	641	12/16	44	44	Held for or routed around MW work or equipment, Other, LINE 4, DELAYED DUE TO BROKEN RAIL LINE 4
NYP	645	12/16	4	4	Service, turn, or wye train, 644, LATE TURN OFF AM644
NYP	647	12/16	29	29	Service, turn, or wye train, 648, LATE TURN OFF AM648

Amtrak Initial Terminal Details

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/16/2025

Terminal	Train	Date	Late	Delay	Cause
NYP	2107	12/16	3	3	Hold for defect repair, Other, NYP-NYP, DELAYED DUE TO BROKEN RAIL IN LINE 4
NYP	2117	12/16	2	2	Passenger and/or baggage, BOARDING
NYP	2121	12/16	15	15	Passenger and/or baggage, HELD DUE TO PSNGRS DEPARTING FROM AM280
NYP	2190	12/16	3	3	Passenger and/or baggage, TRAVEL
CHI	21	12/16	4	4	Mobility Impaired
CHI	41	12/16	27	27	Late arrival of train 6 to put on train 41 170
CHI	50	12/16	105	105	Set out defective car 69000, Bad ordered crew car
CHI	59	12/16	77	77	Electrical failure 37016, 480 failure
CHI	319	12/16	109	109	Set out defective locomotive Swapped out Engines Was IDTX 4602 For IDTX 4622, ID4602
CHI	364	12/16	14	14	Service, turn, or wye train 365
PDX	28	12/16	17	17	Water, commissary, toilet/trash dumping
PDX	502	12/16	2	2	Loading problem Would not load. Fault Hot Diodes., 186
PNT	351	12/16	8	8	Wait for station track Wait for 354 to arrive, complete station work and reverse out before we could do our station work., Amt354, Other, service track
PTH	365	12/16	55	55	Routine inspections Train 364 left CHICAGO late on 12/15. Arriving Port Huron late. PTH mechanical service and inspection of train., Other, PTH Station
SEA	8	12/16	266	67	Pick up rescue locomotive due to mechanical failure BNSF 6559, 182
SEA	8	12/16	266	199	Service, turn, or wye train 7
SEA	11	12/16	20	20	Was not able to automatically or manually start engine. Had to get SEA mechanical to assist 301
BFD	711	12/16	1		
EMY	6	12/16	15	15	Late departure from yard Switch out coffee maker in diner and fixed water issue Other, omf
OKJ	520	12/16	25	25	Service, turn, or wye train 520, Radio was not working in Cab Car 8314had to swap equipment with 522.
OKJ	522	12/16	8	8	Radio failure Radio filter replacement at Yard. 520 took our initial set., C8314
OKJ	710	12/16	1	1	Door C9006, C9006 B end door did not train line close
OKJ	716	12/16	(Trn Cxld)		Third Party Engine Failure

Amtrak Initial Terminal Details

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 12/16/2025

Terminal	Train	Date	Late	Delay	Cause
OKJ	718	12/16	22	22	Pick up rescue locomotive due to mechanical failure Bad loco on 716 of 12/16 CDTX 2107 Late turn of 715 for 718 Due to 716 taking 713 equipment, 1
SAC	537	12/16	2	2	Door C8302, Unknown car load loss door
SAC	541	12/16	1	1	Loading problem Engine had an issue getting a load., C2102
SAC	545	12/16	3	3	Door C8812, Could not get a door light
SAC	704	12/16	1		

Eastern Region

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	97.4	98.6	94.8	309	8
CDOT	95.0	95.0	93.1	92.4	10	1
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	94.3	91.7	93.8	370	21
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 90(16) - South of Alexandria, VA - Freight Train Interference

17DEC25: Train 90(16) was delayed on the CSX RF&P Subdivision at MP 87.2 due to being shoved back to be routed around CSX Train M410-16, which was holding the main ahead.

Train	Delay	Comment
90(16)	1'45"	

Train 53(16) - North of Florence, SC - Freight Train Interference

17DEC25: Train 53(16) was delayed on the CSX South End Subdivision between MP 172.0 and MP 292.2 due to following CSX I031-16.

Train	Delay	Comment
53(16)	1'07"	

Train 2163(16) - South of Wilmington, DE - Engine Failure

17DEC25: Train 2163(16) was delayed on the PW Line at MP 33 due to experiencing brake and MCB issues. The crew was able to resolve the issues.

WBS#: B.TR.100151.0792

Train	Delay	Comment
2163(16)	27"	

Train 19(16) - North of Charlottesville, VA - Smokey Conditions in Cafe Car

16DEC25: Train 19(16) was delayed on the Norfolk Southern Hagerstown/Alexandria-Montview Subdivision at MP 84.5 due to smoke conditions in the cafe car 28018. The crew evacuated the car. There were no reported injuries to crew or passengers. Orange City Volunteer Fire Department responded and investigated. The train was released from the scene by the Fire Department with the source of the smoke unfound. Crews remained vigilant in monitoring the car.

Train	Delay	Comment
19(16)	1'24"	

Train 85(16) Boston, MA - Servicing

16DEC25: Train 85(16) delayed departing Boston, MA on 12/23/2025 having mechanical issues in the yard which caused the late release of the equipment.

Cause: Pending

Train	Delay	Comment
85(16)	48"	

Train 89/90(16) South of Petersburg, VA - M of W Work

16DEC25: Train 89(16) operating with E/355, 7cars and 186 passengers onboard and Train 90(16) operating with E/317, 7cars and 123 passengers onboard came to a stop due to a broken rail on CSX North End Subdivision at MP A63.1. Train 89(16) stopped north of the area at approximately 307P-ET at Fox/MP A57.8 and Train 90(16) stopped south of the area at approximately 309P-ET at Emporia/MP A64.6. Repairs were completed and Train 90(16) was on the move at approximately 339P-ET and Train 89(16) was on the move at approximately 349P-ET.

Train	Delay	Comment
90(16)	38"	
89(16)	39"	

Train 172(16) Washington, DC - Weather

16DEC25: Train 172(16) operating with E/635, 10 cars and 46 passengers onboard was delayed departing Washington, DC on Amtrak WT Line subdivision due to bad order car 82703. Train 172(16) was delayed in the S & I due to late. Train 173(15) which turned for Train 130(16) and needed to be serviced. Additionally, Train 172(16) was delayed due to ice and snow build up.

Train	Delay	Comment
172(16)	55"	
177(16)	40"	LATE TURN OFF 172(16)

Train 97(16) New York, NY - Car Failure

16DEC25: Train 97(16) was delayed departing New York due to needing 3 sleepers and 1 baggage car off inbound 98(15).

Train	Delay	Comment
97(16)	1'52"	

Train 19(16) New York, NY - Weather

16DEC25: Train 19(16) was delayed departing New York due to Ice Patrol in Line 2.

Train	Delay	Comment
19(16)	32"	

Train 40(15) North O Selma-Smithfield, NC - Engine Failure

16DEC25: At 155P-ET, 28-FOI-0019740 00000005841 with E/UNCLASSIFIED 305 a 12/23/2025 cars was stopped on the CSX South End A subdivision at MP 139.4 due to the trail unit e/305 shutting down and losing HEP. The crew was speaking with CNOC Mechanical and was able to set up HEP as of 225P-ET from the lead unit E/333. They pulled and stopped again at MP 137.3 due to the M/U alarms going off in the trail E/305. The crew swapped out the MU cables and were able to proceed toward Washington where they would swap out both engines.

Train	Delay	Comment
40(15)	57"	

Train 2159(16) Princeton Junction, NJ - Engine Failure

16DEC25: At 154PM - ET, Acela 2159(16) operating with PC/2019, 6 cars, PC/2014 and 199 passengers onboard stopped on track 3 west of Midway/MP41.3 on Amtrak New York Line with break issues. The engineer investigated and found park brake mismatch fault. Road Foreman Baxter was enroute to assist. They cut out the parking brake on PC/2019 and PC/2014 but the air was still blowing. The crew was able to resolve the issue on both power cars and the train was on the move west at 230PM - ET. Acela 2159(16) did not lose headend power during this incident.

Train	Delay	Comment
2159(16)	55"	

Train 56(16) Washington, DC - Car Failure

16DEC25: Train 56(16) operating with E/624, 6 cars and 83 passengers onboard was delayed departing Washington, DC on Amtrak WT subdivision due to delays in the S and I. Train 56(16) waited on repairs that were being made to 172(16) which had to bad order car 82703 that was shopped for bad t-cable plug housing. Additionally, Train 56(16) had frozen doors which further delayed them.

Train	Delay	Comment
56(16)	2'04"	

NJT 3838(16) - New York, NY- Disabled NJT/ Commuter Train Interference

16DEC25: NJT 3838(16) was disabled with mechanical issues at 'A' Interlocking in New York that caused congestion and delays to several Amtrak trains.

Train	Delay	Comment
609(16)	20"	
600(16)	49"	
182(16)	10"	
86(16)	03"	

Train 280(16) Poughkeepsie, NY - Commuter Train Interference

16DEC25: Train 280(16) was delayed on the MNRR Hudson Line due to meeting disabled MNRR 858 then following from MP 43 to MP 46.

Train	Delay	Comment
280(16)	30"	

Train 600(16) Philadelphia, PA - Engine Failure

16DEC25: At 925AM-E/637 in 00000005546) of UNCLASSIFIED with 12/23/2025 CC/9649, 4 cars, E/656 and 327 passengers onboard the train, stopped on track 2 at Holmes approximately 10 miles east of Philadelphia, PA at MP 77.7 on Amtrak PW Line due to issues with engine issues. Train 600(16) lost power and the pantographs dropped. The crew was able to reconfigure the pantograph and maintain headend power. Conductors made frequent announcements throughout the train. E/637 was dispatched from Philadelphia and was used to cap CC/9649. E/656 was isolated with pantographs dropped and set up for movement in the trail.

Train	Delay	Comment
600(16)	2'09"	

Train 470(16) New Haven, CT - Hold for Connection

16DEC25: Train 470(16) was held at New Haven for late train 170(16) connections.

Train	Delay	Comment
470(16)	56"	

Train 236(16) Poughkeepsie, NY - Engine Failure

16DEC25: Train 236(16) with E/714 and 6 cars with 297 passengers onboard was delayed on the MNRR Hudson Line at Poughkeepsie station due to E/714 having compressor faults. MNRR Mechanical was able to reset the breaker and cleared the compressor fault. Train 63/69(16) was held for station track.

Train	Delay	Comment
236(16)	24"	
63/69(16)	28"	

Train 605(16) Philadelphia, PA - Weather

16DEC25: TRAIN 605(16) operating with CC/9645, 4 cars, E/630 with 14 passengers onboard, Amtrak PW Line was delayed departing Philadelphia, PA after setting on Track 8 at the station. Mechanical force were dispatched to free up several frozen doors that were stuck in their pockets. Heat was applied to the pockets and were able to clear up several doors for service.

Due to the late arrival of Train 605(16) into Harrisburg, PA, Train 646(16) was delayed departing Harrisburg, PA.

Train	Delay	Comment
646(16)	49"	Late turn of 605(16)
605(16)	1'06"	PHL
646(16)	4"	646(16) LNC, EXT - door snow removal
605(16)	12"	605(16) - ARD/PAO/EXT/DOW/ELT - door snow removal

16DEC25: At 805A-ET, CETC reported that track 3 was out of service between MP 89.3/River and MP 79.3Gunpow on the Philadelphia to Washington main line due to a broken rail. Repairs were being made.

Train	Delay	Comment
2103(16)	11"	
151(16)	09"	
67(15)	06"	
2151(16)	05"	
2108(16)	05"	
183(16)	03"	
141(16)	06"	
56(16)	05"	
182(16)	06"	
2154(16)	07"	
2107(16)	07"	
181(16)	05"	
172(16)	08"	

Train 41(14) South of Savannah, GA - Broken Rail - M of W Work

16DEC25: Train 41(14) was delayed on the CSX Nahunta subdivision at MP 520.4 due to a broken rail ahead between MP 522.0 - 533.0. Once the repairs were made the train continued south.

Train	Delay	Comment
41(14)	2'03"	

NYP Line 4 - West of New York, NY -Broken Rail/M of W Work

16DEC25: At 400AM-ET, a Track Occupancy Light was reported on Line 4 at the mouth of the tunnel at C interlocking (4E04T Circuit). C & S responded to the scene and requested to foul time to investigate, confirming a broken rail at MP 0.22 North Rail. At 458AM-ET, Line 4 was taken out of service and track department was dispatched to the scene to make repairs. With an estimated time of restoration, the produced delays to our service. Trains 89(16) and 79(16) were scheduled to depart New York, NY with Reversed Consists having to be looped to get into the station. Line 4 was returned to service at scheduled speed with no restrictions at 745AM-ET resuming normal operation.

Train	Delay	Comment
89(16)	1'33"	
2151(16)	03"	
183(16)	1'09"	
141(16)	10"	
641(16)	44"	
63/69(16)	46"	
232(16)	02"	
607(16)	1'05"	
181(16)	52"	
79(16)	3'09"	
2107(16)	03"	
648(16)	36"	late turn off 607(16)
79(16)	3'09"	
647(16)	29"	LATE TURN OFF 648(16)

Train 2150(16) North of Baltimore, MD - Engine Failure

16DEC25: Train 2150 (26-FOI-001971 00000005541 PC/20035 2039 12/23/2025) 134 passengers onboard was stopped at MP 84.9 on the Philadelphia to Washington main line with a low main res penalty. The engineer was trouble shooting. Amtrak Road Foreman was onboard assisting, they were able to clear the penalty and proceed north. They stopped again at MP 72 with the same issue. Train 2150(16) was terminated in Wilmington and passengers went to trains 2152(16) and 170(16).

Train 2150(16) original equipment deadhead back to Washington.

Train	Delay	Comment
2150(16)	TERM WIL	
2167(16)	CANCELLED	
2152(16)	40"	
170(16)	57"	
2169(16)	1'04"	LATE TURN OFF 2152(16)

Train 280(16) Niagara Falls, NY - System

16DEC25: Train 280(16) was delayed departing Niagara Falls due to no engineer at sign up time regular engineer arrived late.

Train	Delay	Comment
280(16)	54"	

Train 40(15) - North of Savannah, GA - Broken Rail

16DEC25: Train 40(15) was delayed on the CSX Columbia Subdivision at MP 474.7 due to broken rail ahead at MP 464.5. Train 41(14) was also held at MP 460.0 until repairs were made.

WBS#: B.TR.100150.6320

Train	Delay	Comment
41(14)	1'20"	
40(15)	2'56"	

12DEC25: Metro North weekend outages:

New Haven Line:

- Continuous outage No.1trk CP 240 to CP241 began Monday 12/08/25 Mud spot remediation.
- Continuous outage No.2trk CP 217 to CP 223. Began 12/01/25 expected to return to service Tomorrow morning.
- Continuous outage No.1 & 3trks CP241 to CP243. Walk bridge OOS for 18 months began 7/19/24.
- No.3 track CP 266 to CP271 11:59pm Friday(12) to 6pm Sunday (14). There will be a Rule 22 (Working Limits) during the day for Both Saturday and Sunday. Approx Mp70.4 to Mp70.7.
- 4-track outage Saturday(13) only 12:40A to 5A. AC power will be removed. No.4trk will be the running track thru area.

Hudson Line:

- No 1 & 3trks CP 26 to CP 33 to Replace Rail 12:30A Saturday(13) to 5A Monday(15).
- No.2trk between CP 53 and CP 58. On Tuesday 12/16/25 during the day. Anticipated delays 10-15minutes for this outage.

VIA Oakville Subdivision Oakville, ON - Scheduled M/W Work

UPDATE 03OCT25: To accommodate infrastructure maintenance on the VIA Oakville subdivision at Oakville/MP 21.4. As a result, train 63/7098(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay. Train 64/7097(13DEC-14DEC and 20DEC-21DEC) will operate over the Halton/Weston detour and will bypass Oakville with no alternate transportation with a minimum of 40 minutes delay.

WBS#: B.TR.100150.5989

Train	Delay	Comment
64(13)	57"	

Eastern Region

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
79 (23)	RMT	326		Gear case damage

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 173(15) Passenger Removal at Wilmington, Delaware – Improper Conduct***

16DEC25, Passenger on PNR 2C5793, traveling from Newark, NJ to Washington D.C. was reportedly traveling with a child seated in the café car across from another passenger displaying irrational behavior and possible drug use. Amtrak Police assisted with the removal. Amtrak Police notified.

Delay: 173(15) None

Train 486(15) Passenger Removal at Windsor, Connecticut – Medical

16DEC25, Passenger on PNR 2BA365, traveling from New Haven, CT to Springfield, MA reportedly had symptoms of a seizure, and paramedics were contacted to assist with transport to a local hospital for treatment. Amtrak Police notified.

Delay: 486(15) 25"

Operating Highlights

Train 7/27(16) East of La Crosse, WI - M of W Work

17DEC25: Train 7/27(16) was delayed at Grand Crossing/MP280.0 1 mile east of La Crosse, WI/MP281.2 on the CPKC Tomah subdivision due to track work. Train 7/27(16) was routed around the track work and shoved into the La Crosse depot. Once the station work was completed, train 7/27(16) departed La Crosse.

Train	Delay	Comment
7/27(16)	42"	

Train 1(15)/421(14) West of El Paso, TX - Unruly Passenger

17DEC25: Train 1(15)/421(14) was delayed at Santa Teresa Terminal/MP1271.3 25 miles west of El Paso, TX/MP1296.0 on the UP Lordsburg subdivision holding for local police to remove an unruly passenger, PNR# 23CBD8. The police did not meeting the train. The crew advanced the train to Deming, NM/MP1208.2 and met Deming Police to remove an unruly passenger. Once the passenger was removed, train 1(15)/421(14) continued west.

Train	Delay	Comment
1(15)/421(14)	36"	POL at DEM
1(15)/421(14)	19"	POL at X5S

Train 5(14) East of Elko, NV - Freight Train Interference

17DEC25: Train 5(14) was delayed at Elburz/MP573.2 16 miles east of Elko, NV/MP557.0 on the UP Lakeside subdivision due to disabled UP freight UP/8662. Train 5(14) was routed onto main track 2 to get around UP/8662. Once the route was clear, train 5(14) continued west.

Train	Delay	Comment
5(14)	1'03"	

Train 508(16) North of Oregon City, OR - Tree Strike

17DEC25: Train 508(16), with engine WDTX1404, 4 cars, and 54 passengers, struck a tree at control point VP757.5 1 mile north of Oregon City, OR/MP756.4 on the UP Brooklyn subdivision. The equipment lost main reservoir pressure, and the crew walked the train to investigate. Air hoses were reconnected between cars 82793 and 82664 and between cars 82664 and 48187. Air pressure was restored, and the crew performed a successful air test before departing.

Train	Delay	Comment
508(16)	12"	

Train 719(16) East of Modesto, CA - Freight Train Interference

17DEC25: Train 719(16) was delayed at West Oceanside/MP1090.8 1 mile east of Modesto, CA/MP1091.5 on the BNSF Stockton subdivision due to BNSF freight BN/6820 stopped ahead. BN/6820 had stopped on a shunt due to issues with the BNSF track tracking system. BNSF put a hold on rail traffic during the investigation. After the investigation concluded, BN/6820 pulled into the siding to clear the route. Train 790(16) was given authority to continue west. Trains 718(16) and 703(16) were also delayed holding for a route.

Train	Delay	Comment
718(16)	1'40"	
703(16)	27"	
719(16)	1'53"	

Train 790(16) West of Oceanside, CA - Freight Train Interference

17DEC25: Train 790(16) was delayed at Don/MP216.0 10 miles west of Oceanside, CA/MP226.4 on the SCRRA San Diego subdivision due to a BNSF freight 7649 disabled with a broken knuckle at Pulgas/MP218.09. The freight crew replaced the knuckle and shoved their equipment into the clear. Once the route was clear, train 790(16) was able to continue east. Train 595(16) was also delayed, holding for a route.

Train	Delay	Comment
595(16)	1'32"	
790(16)	1'03"	

Train 352(16) Battle Creek, MI - Routing

17DEC25: Train 352(16) was delayed at Battle Creek, MI/MP175.74 on the CN South Bend subdivision due to dispatch routing the train to the wrong station track. Once the station work was completed, train 352(16) departed Battle Creek, MI.

Train	Delay	Comment
352(16)	34"	

Train 59(16) Chicago, IL - Car Failure

16DEC25: Train 59(16), with engine 335, 7 cars, and 147 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late shopping of sleeper 32011. Sleeper car 32011 was not holding 480v power. The car was replaced with sleeper car 32060. Once the equipment was made up complete, train 59(16) shoved into the depot, boarded passengers, and departed Chicago Union Station, IL.

Train	Delay	Comment
59(16)	1'17"	

Train 50(16) Chicago, IL - Car Failure

16DEC25: Train 50(16), with engines 518, 205, 167, and 79, 7 cars, and 127 passengers, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to the late shopping of baggage/dorm car 69000. No replacement baggage/dorm cars were available. Baggage car 61040 was added. Once the equipment was made up complete, train 50(16) shoved into the depot, boarded passengers, and departed.

Train	Delay	Comment
50(16)	1'45"	

Train 717(16) West of Madera Acres, CA - Police Activity

16DEC25: All rail traffic as of 12/23/2025 was delayed - "UNCLASSIFIED" was 12/23/2025 Madera- in the vicinity of MP 1052.6, Planada, Stockton Subdivision of the BNSF Railway. This was to allow for local police to capture and detain a trespasser on or near the tracks. Once the police confirmed the tracks were clear, train 717(16) continued to Merced. Amtrak Police Notified

Train	Delay	Comment
717(16)	27"	

Train 8(16) Initial Terminal Delay at Seattle, WA – Servicing Equipment

16DEC25: Train 8(16) was delayed departing Seattle after turning and servicing equipment off inbound train 7(14) which arrived in Seattle at 2:48PM-PDT, 3 hours 19 minutes late.

UPDATE: Preparations for departure were delayed when Seattle Switch Crew were unable to access the yard Wye track. Preparations were delayed further when locomotive AMTK 182 failed departure test, requiring BNSF freight locomotive BNSF/6559 was re-added to the train. This required additional wye moves.

Train 8(16) departed Seattle at 9:21PM-PT.

Train	Delay	Comment
8(16)	4'26"	

Train 28(16) Initial Terminal Delay at Portland , OR – Servicing Equipment

16DEC25: Train 28(16) was delayed departing Portland after turning and servicing equipment off inbound train 27(14) which arrived in Portland at 2:34PM-PDT, 3 hours 17 minutes late. Train 28(16) departed Portland at 5:02PM-PT.

Train	Delay	Comment
28(16)	17"	PDX - ITD

Train 3(15) Albuquerque, NM - Car Failure

16DEC25: Train 3(15) was delayed departing Albuquerque, NM/MP902.45 on the Rio Metro Albuquerque subdivision setting out car 33026 for a broken main spring discovered during a calendar day inspection. Once the car was removed and the consist made up complete, train 3(15) departed Albuquerque, NM.

Train	Delay	Comment
3(15)	2'02"	

Train 538(16) – North of Fremont: Police Activity (Vandalism)

16DEC25: Train 538(16) was delayed 2 miles north of Fremont, near Shinn, MP 30.00 on the Niles Subdivision due to a track closure. Local police responded to reports of trespassers vandalizing railroad property. Service resumed after a Union Pacific track inspector confirmed switches and signals were undamaged.

Train	Delay	Comment
538(16)	54"	

16DEC25: Train 716(15) was delayed in Oakland Maintenance Facility. Locomotive CDTX/2107 developed a hydraulic pump failure. This component could not be repaired/ replaced in Oakland Maintenance Facility. With no serviceable locomotives available in Oakland, the following equipment manipulations were instigated:

- Train 713(16) terminated in Emeryville with passengers for Oakland transferring to thruway 6613(16) making extra stop in Oakland. Train equipment turned in Emeryville for 716(16).
- Train 716(16) Originated in Emeryville, using equipment from inbound train 713(16). Passengers boarding in Oakland advised to use train 536(16) to connect with train 716(16) in Emeryville.
- Train 715(16) Terminated in Emeryville, with passengers for Oakland transferring to thruway 6615(16) making additional stop in Oakland. Equipment entered Oakland Maintenance Facility via Kirkham entrance to be fueled before turning as train 718(16) Originating in Oakland.
- Train 718(16) Originated in Oakland Jack London Square, using equipment from 715(16).

Cause: Pending

Train	Delay	Comment
716(16)	44"	ITD Orig EMY
713(16)	Term EMY	Passengers to 6613(16)
715(16)	Term EMY	Passengers to 6615(16)
718(16)	22"	ITD - OKJ - Equipt From 715(16)

Train 319(16) South of Summit, IL - UDE

16DEC25: Train 319(16), E/IDTX4622 & 7 cars, with 221 passengers, stopped in emergency at MP14.9, 3 miles south of Summit, IL, on the CN Joliet Subdivision. Crew inspected consist and found parted air hoses between the second and third cars, C/ID4016 and C/ID4112. Crew reported a hole in the air hose on C/ID4016 and necessary to replace hose. There were no other exceptions to equipment taken. Train 319(16) was on the move south after crew replaced and secured hose and performed Class II brake test.

Train	Delay	Comment
319(16)	42"	

Train 7/27(15) West of Minot, ND - High Wind Warnings

16DEC25: Train 7/27(15) was delayed beginning 16 miles west of Minot, ND, on the BNSF Glasgow Subdivision, operating through high wind warnings between MP16 and MP59.

Train	Delay	Comment
7/27(15)	1'01"	

Train 319(16) Late Departure Chicago, IL - Engine

16DEC25: Train 319(16) was delayed departing Chicago, IL, due to replacing bad order E/IDTX4602 which was shopped for hydraulic issues. It was necessary to use E/IDTX4622 off late deadhead 355(15) equipment which arrived at 740AM-CT. E/IDTX4622 had to be worked up and serviced by mechanical before released as replacement engine for Train 319(16). Train 319(16), E/IDTX4622 & 7 cars, departed Chicago at 1139AM-CT, 1 hour and 49 minutes late.

Train	Delay	Comment
319(16)	1'49"	

Train 2(14) West of Houston, TX - Near Miss with Tractor Trailer

16DEC25: Train 2(14), 26-FCL-00197E/160800005541 car "UNCLASSIFIED" 01 p12/23/2025, stopped in emergency at MP17.69, 17 miles west of Houston, TX, on the UPRR Glidden Subdivision, due to a near miss with a tractor trailer. There were no reported injuries to passengers or crew and no reported damages. Train 2(14) was on the move east after crew inspected consist and performed Class II.

Train	Delay	Comment
2(14)	14"	

Train 5(14) East of Elko, NV - Freight Train Interference

16DEC25: Train 5(14) was delayed east of Elko, NV/MP557.0, on the UPRR Lakeside Subdivision, due to UP 8662 ahead with mechanical issues. Train 5(14) crossed over from 1 to 2 track at Elburz crossover/MP573.2 and was delayed hand throwing switches and derails to operate through the area.

Train	Delay	Comment
5(14)	1'03"	

Train 522(18) East of Martinez, CA - Marine Traffic

16DEC25: Train 520(16) was delayed 1 mile east of Martinez at Vista MP 33.0 Martinez subdivision of the Union Pacific Railroad. The structure was raised to allow for the passage of marine traffic. Once the vessels had cleared, the bridge was lowered and train 520(16) was able to continue to Suisun..

Train	Delay	Comment
520(16)	20"	

Train 351(16) West of Dearborn, MI - Car Failure

16DEC25: Train 351(16), E/IDTX4611 & 5 cars, had emergency applications at MP13.4, 4 miles west of Dearborn, MI, on the MDOT Michigan Line, and at MP16.1. Crew inspected consist at MP13.4 and found air hose separated between the last car, C/ID4203 and backup tailhose. No other exceptions were taken and Train 351(16) was able to proceed west after performing Class II. Train 351(16) inspected consist again at MP16.1 and found same air hose separation on C/ID4203. Crew removed backup tailhose completely from C/ID4203 and was able to restore air and perform Class II. Train 351(16) was further delayed at MP24.9 due to dragging equipment detector actuation axle 24. Crew tie strapped low hanging air hoses on C/ID4203 and reported no other exceptions to equipment.

Train	Delay	Comment
351(16)	16"	W/DER, MP24.9
351(16)	18"	W/DER, MP13.1 & MP16.1

Train 58(15) North of Effingham, IL - Broken Rail

16DEC25: Train 58(15) was delayed at MP180.92, 19 miles north of Effingham, IL, on the CN Champaign Subdivision, due to a broken rail ahead. Train 58(15) held for CN MW to arrive and complete repairs.

Train	Delay	Comment
58(15)	1'00"	

Train 7/27(14) East of Whitefish, MT - Tree Strike

16DEC25: Train 7/27(14) with engines 60, 315, and 1223, 20 cars, and 111 passengers, struck a tree east of Whitefish, MT/MP1219.3 on the BNSF Hi Line subdivision. After departing Whitefish, MT, train 7/27(14) stopped to inspect excessive noise from the lead engine 60. The crew noted condemnable plow damage, now less than 2 inches from the rail. BNSF mechanical forces were unavailable to cut the plow. Engine 60 was set out at on East Rip Track at Whitefish, MT. Train 7/27(14) continued west. BNSF freight 6559 was sourced at Spokane, WA to add to the equipment. Train 7(14) was delayed between Spokane and Seattle, operating at reduced speed with BNSF locomotive BNSF/6559 leading.

UPDATE: Locomotive AMTK/60 after repairs, was added to train 7(15) at Whitefish, MT. The locomotive will be added in 3rd position.

Train	Delay	Comment
7/27(14)	3'01"	
7/27(14)	29"	SPT - Re-Crew
7(14)	12"	SPK-SEA - Operating with freight locomotive
7/27(15)	1'23"	Adding E/60 at ABQ

UNCLASSIFIED
12/3/2025
B. TR. 100150.6267

Canadian National Champaign Subdivision affecting Siski Service - Scheduled M/W Work

08DEC25: Daily from 8:00 a.m. (CST) to 4:00 p.m. (CST), beginning December 10th and continuing to December 22nd, Canadian National will have a tie gang working on the Champaign Subdivision between South Tolono / MP 137.5 and Humboldt / MP 163.3, between Champaign, IL and Mattoon, IL. To accommodate the work, the following operating plan will be implemented:

Train 390 (10DEC to 22DEC) will originate at the Champaign, IL station and will operate one hour later than its usual schedule. Bus 3390 will provide alternate transportation between Carbondale, IL and Champaign, IL.

Train 391 (10DEC to 22DEC) will terminate in Champaign, IL. Bus 3391 will provide alternate transportation between Champaign, IL and Carbondale, IL.

WBS#: B.TR.100150.6267

Burlington Northern Santa Fe Brookfield Subdivision East of Quincy, IL - Scheduled M/W Work

09DEC25: To accommodate a Burlington Northern Santa Fe Brookfield Subdivision Track work December 9th through December 12th and December 15th through December 17th between Quincy, IL and Galesburg, IL, The follow operating plan will be in effect for Carl Sandburg Service Train 381:

- Train 381 (09) will operate 2-hours later between Chicago, IL and Quincy, IL.
- Train 381 (10-12) & 381 (15-17) will operate 1-hour later between Chicago and Quincy.

WBS#: B.TR.100150.6234

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (8)	DEN	83		Shelling on wheel 1
7 (14)	WFH	60		ENG had been picked up on 7 (15) to SEA

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
8 (16)	SEA	BN6559	Added back to 8 (16) off of 7 (14) due to trail eng 182 not passing departure test		
8 (14)	SEA	BN7513	Lead eng 331 taken off to rescue 8 (14) fgt added to 11 (15)	LAX	12-17-25

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:

Western Region

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 591(15) Passenger Removal at Oceanside, California – Fare Evader

16DEC25, Passenger on PNR 2CC533, traveling from San Diego, CA to Oceanside, CA reportedly boarded without a ticket and was found hiding in business class and once again in the bathroom. The traveler finally convinced another passenger to purchase a ticket going to Oceanside. However, once the train arrived the traveler refused to exit and pleaded for a free ride to Anaheim. The traveler finally agreed to exit after delaying the train five minutes. Amtrak Police notified.

Delay: 591(15) 05"

Train 421(15) Passenger Removal at Deming, New Mexico – Improper Conduct

16DEC25, Passenger on PNR 23CBD8, traveling from Austin, TX to Los Angeles, CA reportedly had a half gallon of Jack Daniels, and was drunk and disorderly towards other travelers and crew members. Local authorities assisted with the removal. Amtrak Police notified.

Delay: 421(15) 36"

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Consist Deviations

26-FOI-00197

00000005541

"UNCLASSIFIED"

12/23/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
85 (16)	BOS	b/o 81527 best replacement 25117	none	0	25117
177 (16)	BOS	Reduced capacity due to using an AN (AMI Business Class car) in lieu of an AS (AMI coach).	The passengers were reduced	0	81525
319 (16)	CHI	id42xx to 481xx 18 less jy seats, best available replacement, customer service downgraded affected passengers	Reduce number of business class seat due to changed of equipment.	15	48164
307 (17)	CHI	Train will operate without a business class car. All sales have been closed. please re-accomodate all affected passengers.	Will need to confirm equipment changes	0	ID42XX
370 (16)	CHI	Trains 370(16) and 371(17) will not have business class seating due to an equipment change. Please re-accommodate all affected passengers.	PASSENGERS NOTIFIED AND DOWNGRADED	10	ID42XX
5 (16)	CHI	SLEEPER OPERATING IN LIEU OF A DORM.	There was no adverse impact to passengers	0	32118
50 (16)	CHI	b/o 69000 crew dorm best replacement was 61040 baggage car, downgraded sleeper passeners	Passengers were downgraded	7	69000
371 (17)	GRR	Trains 370(16) and 371(17) will not have business class seating due to an equipment change. Please re-accommodate all affected passengers.	PASSENGERS NOTIFIED AND DOWNGRADED	15	ID42XX
19 (16)	NYP	62010 sleeper and 61068 bag in place of a crew dorm			61068
79 (16)	NYP	Do to trains 79(16) and 89(16) leaving NYP backwards it was necessary to perform a schedule change. Utilize the WAR report to ensure all affected passengers are accommodated			81503

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
89 (16)	NYP	Do to trains 79(16) and 89(16) leaving NYP backwards it was necessary to perform a schedule change. Utilize the WAR report to ensure all affected passengers are accommodated			81537
22 (16)	SAS	Diner operating in lieu of a lounge.	none	0	38065
302 (17)	STL	Train will operate without a business class car. All sales have been closed. please re-accomodate all affected passengers.	The pax were downgraded	0	ID42XX
172 (16)	WAS	Reduced capacity due to using an AN (AMI Business Class car) in lieu of an AS (AMI coach).	NONE	0	81525

Reverse Consists

Train Number	Station	Reason
134 (16)	RNK	Consist reversed Business class seat orientation may have changed At Front
94 (16)	NFK	Consist reversed Business class seat orientation may have changed At Front
85 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
197 (16)	NYP	Consist reversed Business class seat orientation may have changed At Rear
190 (16)	PHL	Consist reversed Business class seat orientation may have changed At Front
137 (16)	BOS	Consist reversed Business class seat orientation may have changed At Front
79 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
89 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
181 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front
114 (16)	WAS	Consist reversed Business class seat orientation may have changed At Rear
129 (16)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason
184 (16)	WAS	Consist reversed Business class seat orientation may have changed At Front