CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Friday, October 16, 2026 Rules: 3-3



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

27-FOI-00058 [illegible] 10/27/2026

Scheduled Departure Date: **10/15/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/15/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	300	46	84.7%	4,596	618	86.6%	4,596	618	86.6%
Central Division	86.0%	59	8	86.4%	855	56	93.5%	855	56	93.5%
East Division	82.0%	155	24	84.5%	2,468	346	86.0%	2,468	346	86.0%
West Division	86.0%	86	14	83.7%	1,273	216	83.0%	1,273	216	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

Endpoint Arrival Dates through 10/15/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	**80%**	**98,181**	**30,460**	**69%**	**1,603,378**	**456,530**	**72%**	**1,603,378**	**456,530**	**72%**
Northeast Corridor	***81%***	***41,251***	***10,236***	***75%***	***709,723***	***176,503***	***75%***	***709,723***	***176,503***	***75%***
Acela	83%	6,546	1,211	82%	140,788	28,887	79%	140,788	28,887	79%
Northeast Regional	79%	34,705	9,025	74%	568,935	147,616	74%	568,935	147,616	74%
Richmond / Newport News / Norfolk	77%	6,508	2,143	67%	151,101	45,647	70%	151,101	45,647	70%
Springfield Shuttles	89%	767	95	88%	12,287	3,164	74%	12,287	3,164	74%
Roanoke	79%	2,728	959	65%	54,332	14,364	74%	54,332	14,364	74%
On Spine Northeast Regional	80%	24,702	5,828	76%	351,215	84,441	76%	351,215	84,441	76%
State Supported	***80%***	***45,620***	***14,560***	***68%***	***706,738***	***189,799***	***73%***	***706,738***	***189,799***	***73%***
Borealis	80%	716	73	90%	10,803	1,873	83%	10,803	1,873	83%
Capitol Corridor	90%	4,927	560	89%	63,800	12,287	81%	63,800	12,287	81%
Carolinian	70%	2,246	1,306	42%	20,239	5,122	75%	20,239	5,122	75%
Cascades	75%	2,495	1,126	55%	40,306	11,935	70%	40,306	11,935	70%
Downeaster	82%	1,628	536	67%	29,788	8,711	71%	29,788	8,711	71%
Empire	78%	6,851	863	87%	100,660	21,773	78%	100,660	21,773	78%
Adirondack	72%	495	23	95%	6,894	1,139	83%	6,894	1,139	83%
Ethan Allen Express	70%	679	77	89%	9,479	3,333	65%	9,479	3,333	65%
Maple Leaf	70%	885	385	56%	13,443	3,605	73%	13,443	3,605	73%
New York - Albany	85%	3,425	243	93%	48,608	8,215	83%	48,608	8,215	83%
New York - Niagara Falls	75%	1,367	135	90%	22,236	5,481	75%	22,236	5,481	75%
Gold Runner	73%	1,834	1,013	45%	39,727	14,880	63%	39,727	14,880	63%
Heartland Flyer	70%	221	220	0%	3,347	2,928	13%	3,347	2,928	13%
Hiawatha	90%	1,682	666	60%	27,967	2,487	91%	27,967	2,487	91%
Illinois	78%	2,640	1,052	60%	41,403	14,082	66%	41,403	14,082	66%
Carl Sandburg / Illinois Zephyr	85%	416	286	31%	6,615	1,751	74%	6,615	1,751	74%
Illini / Saluki	85%	921	450	51%	13,652	5,302	61%	13,652	5,302	61%
Lincoln Service	70%	1,303	316	76%	21,136	7,029	67%	21,136	7,029	67%
Keystone	92%	6,352	104	98%	118,419	10,936	91%	118,419	10,936	91%
Lincoln / Missouri	70%	961	729	24%	12,907	6,857	47%	12,907	6,857	47%
Mardi Gras Service	80%	321	84	74%	3,830	1,456	62%	3,830	1,456	62%
Michigan	70%	2,102	18	99%	33,426	7,175	79%	33,426	7,175	79%
Blue Water	70%	512	1	100%	7,904	2,225	72%	7,904	2,225	72%
Pere Marquette	85%	309	0	100%	4,522	271	94%	4,522	271	94%
Wolverine	70%	1,281	17	99%	21,000	4,679	78%	21,000	4,679	78%
Missouri	80%	240	0	100%	4,305	944	78%	4,305	944	78%
Pacific Surfliner	85%	6,880	4,784	30%	102,089	51,195	50%	102,089	51,195	50%
Pennsylvanian	80%	1,010	487	52%	14,339	4,865	66%	14,339	4,865	66%
Piedmont	80%	969	363	63%	16,257	2,905	82%	16,257	2,905	82%
Vermonter	75%	1,545	576	63%	23,126	7,388	68%	23,126	7,388	68%
Long Distance	***70%***	***11,310***	***5,664***	***50%***	***186,917***	***90,228***	***52%***	***186,917***	***90,228***	***52%***
Auto Train	70%	763	508	33%	9,967	7,371	26%	9,967	7,371	26%
California Zephyr	70%	916	364	60%	13,938	4,875	65%	13,938	4,875	65%
Cardinal	70%	395	84	79%	4,324	2,181	50%	4,324	2,181	50%
City Of New Orleans	75%	776	714	8%	11,338	7,970	30%	11,338	7,970	30%
Coast Starlight	70%	1,045	749	28%	17,165	7,966	54%	17,165	7,966	54%
Crescent	70%	938	347	63%	13,703	1,937	86%	13,703	1,937	86%
Empire Builder	70%	1,034	297	71%	15,306	6,677	56%	15,306	6,677	56%
Floridian	60%	1,467	799	46%	24,137	16,393	32%	24,137	16,393	32%
Lake Shore Ltd	73%	993	474	52%	16,770	4,738	72%	16,770	4,738	72%
Palmetto	70%	1,031	243	76%	13,848	3,334	76%	13,848	3,334	76%
Silver Meteor	70%	848	236	72%	14,194	5,369	62%	14,194	5,369	62%
Southwest Chief	60%	417	405	3%	13,696	10,682	22%	13,696	10,682	22%
Sunset Ltd	70%	0	0	-	4,271	1,678	61%	4,271	1,678	61%
Texas Eagle	70%	687	444	35%	14,260	9,057	36%	14,260	9,057	36%

Note: "This report contains preliminary data and is intended to be used for trend analyis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

~~27 FOI 00056 00000000000 "UNCLASSIFIED" 10/15/2026~~

Train Index Dates Through October 15, 2026

		Month to Date			FY to Date		
Service	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
Amtrak System	585	94,511	1,585,577	596	94,511	1,585,577	596

		Month to Date			FY to Date		
Department	**Target**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**	**ACD Minutes**	**Train Miles**	**ACD per 10K TM**
INFRASTRUCTURE UNPLANNED	107	4,912	465,967	105	4,912	465,967	105
INFRASTRUCTURE PLANNED	135	10,270	465,967	220	10,270	465,967	220
FLEET RELIABILITY	90	11,529	1,585,577	73	11,529	1,585,577	73
TRAIN OPERATIONS	424	67,800	1,585,577	428	67,800	1,585,577	428

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

27-FOI-00058 [illegible] 10/27/2026

Scheduled Departure Date: **10/15/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/15/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	300	46	84.7%	4,596	618	86.6%	4,596	618	86.6%
Central Division	86.0%	59	8	86.4%	855	56	93.5%	855	56	93.5%
East Division	82.0%	155	24	84.5%	2,468	346	86.0%	2,468	346	86.0%
West Division	86.0%	86	14	83.7%	1,273	216	83.0%	1,273	216	83.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

27-FOI-00054 [illegible]

Scheduled Departure Date: **10/15/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/15/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	300	46	84.7%	4,596	618	86.6%	4,596	618	86.6%
Central Division	86.0%	59	8	86.4%	855	56	93.5%	855	56	93.5%
CDL	95.0%	1	0	100.0%	20	2	90.0%	20	2	90.0%
CHI	86.0%	28	3	89.3%	406	32	92.1%	406	32	92.1%
CHM	-	1	0	100.0%	9	1	88.9%	9	1	88.9%
DAL	-	-	-	-	2	0	100.0%	2	0	100.0%
FTW	92.5%	1	0	100.0%	13	1	92.3%	13	1	92.3%
GRR	95.5%	1	0	100.0%	15	0	100.0%	15	0	100.0%
KCY	92.0%	2	0	100.0%	30	0	100.0%	30	0	100.0%
MKE	92.0%	6	2	66.7%	88	6	93.2%	88	6	93.2%
MOE	97.5%	2	0	100.0%	23	0	100.0%	23	0	100.0%
MSP	96.5%	1	0	100.0%	15	0	100.0%	15	0	100.0%
NOL	94.5%	4	0	100.0%	55	2	96.4%	55	2	96.4%
OKC	97.0%	1	0	100.0%	15	1	93.3%	15	1	93.3%
PNT	88.0%	3	2	33.3%	44	5	88.6%	44	5	88.6%
PTH	93.0%	1	0	100.0%	15	0	100.0%	15	0	100.0%
QCY	91.0%	2	0	100.0%	30	2	93.3%	30	2	93.3%
SAS	90.5%	1	1	0.0%	15	3	80.0%	15	3	80.0%
STL	89.0%	4	0	100.0%	60	1	98.3%	60	1	98.3%
East Division	82.0%	155	24	84.5%	2,468	346	86.0%	2,468	346	86.0%
ALB	88.5%	8	1	87.5%	120	11	90.8%	120	11	90.8%
ATL	-	-	-	-	4	1	75.0%	4	1	75.0%
BON	87.5%	5	1	80.0%	75	9	88.0%	75	9	88.0%
BOS	85.5%	12	0	100.0%	231	6	97.4%	231	6	97.4%
BRK	92.5%	5	0	100.0%	75	6	92.0%	75	6	92.0%
BTN	82.0%	1	1	0.0%	15	2	86.7%	15	2	86.7%
CLT	91.5%	4	0	100.0%	69	8	88.4%	69	8	88.4%
GFD	88.0%	2	0	100.0%	30	3	90.0%	30	3	90.0%
GRO	-	-	-	-	5	0	100.0%	5	0	100.0%
HAR	79.5%	13	1	92.3%	173	20	88.4%	173	20	88.4%
HFD	-	2	1	50.0%	22	5	77.3%	22	5	77.3%
LOR	84.0%	1	0	100.0%	14	5	64.3%	14	5	64.3%
MIA	89.5%	2	0	100.0%	30	6	80.0%	30	6	80.0%
MTR	79.0%	1	0	100.0%	15	4	73.3%	15	4	73.3%
NFK	84.5%	2	0	100.0%	30	4	86.7%	30	4	86.7%
NFL	93.5%	2	0	100.0%	30	3	90.0%	30	3	90.0%
NHV	78.0%	5	2	60.0%	75	18	76.0%	75	18	76.0%
NPN	93.0%	2	1	50.0%	29	4	86.2%	29	4	86.2%
NYP	75.5%	37	6	83.8%	671	114	83.0%	671	114	83.0%
PGH	93.0%	1	0	100.0%	15	3	80.0%	15	3	80.0%
PHL	48.0%	11	6	45.5%	99	51	48.5%	99	51	48.5%
RGH	95.0%	4	1	75.0%	50	4	92.0%	50	4	92.0%
RNK	83.5%	2	1	50.0%	30	3	90.0%	30	3	90.0%
SAB	98.0%	1	0	100.0%	15	0	100.0%	15	0	100.0%
SAV	96.0%	1	0	100.0%	15	0	100.0%	15	0	100.0%

Information Management

27-FOI-00048

Initial Terminal Performance By Terminal

Scheduled Departure Date: **10/15/2026**

Amtrak or Commuter: **Amtrak**

Location	Target	ITP 10/15/2026			ITP October 2026 To Date			ITP Fiscal Year 2027 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	300	46	84.7%	4,596	618	86.6%	4,596	618	86.6%
East Division	82.0%	155	24	84.5%	2,468	346	86.0%	2,468	346	86.0%
SFA	88.0%	1	0	100.0%	14	3	78.6%	14	3	78.6%
SPG	92.5%	5	0	100.0%	81	8	90.1%	81	8	90.1%
TWO	73.0%	1	0	100.0%	15	4	73.3%	15	4	73.3%
WAS	84.0%	24	2	91.7%	421	41	90.3%	421	41	90.3%
West Division	86.0%	86	14	83.7%	1,273	216	83.0%	1,273	216	83.0%
ARN	92.0%	1	0	100.0%	15	0	100.0%	15	0	100.0%
BFD	79.0%	6	1	83.3%	104	24	76.9%	104	24	76.9%
EMY	72.0%	1	1	0.0%	16	8	50.0%	16	8	50.0%
EUG	86.5%	1	0	100.0%	28	1	96.4%	28	1	96.4%
GAC	-	-	-	-	2	1	50.0%	2	1	50.0%
GTA	90.0%	3	1	66.7%	39	13	66.7%	39	13	66.7%
LAX	89.5%	8	0	100.0%	133	13	90.2%	133	13	90.2%
OKJ	74.5%	13	6	53.8%	177	59	66.7%	177	59	66.7%
PDX	86.0%	5	0	100.0%	75	6	92.0%	75	6	92.0%
SAC	88.5%	16	0	100.0%	223	21	90.6%	223	21	90.6%
SAN	90.5%	11	2	81.8%	159	28	82.4%	159	28	82.4%
SEA	85.0%	8	1	87.5%	119	16	86.6%	119	16	86.6%
SJC	89.0%	7	1	85.7%	104	19	81.7%	104	19	81.7%
SLO	90.0%	3	1	66.7%	39	6	84.6%	39	6	84.6%
SPK	90.0%	1	-	100.0%	14	0	100.0%	14	0	100.0%
VAC	97.0%	2	0	100.0%	26	1	96.2%	26	1	96.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	100	15	3	80.0%	15	3	80.0%	15	10	33.3%	15	10	33.3%
4	No OS	15	0	100.0%	15	0	100.0%	15	13	13.3%	15	13	13.3%
5	53	14	1	92.9%	14	1	92.9%	14	5	64.3%	14	5	64.3%
6		14	8	42.9%	14	8	42.9%	14	5	64.3%	14	5	64.3%
7		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
8		14	5	64.3%	14	5	64.3%	14	9	35.7%	14	9	35.7%
11	19	15	2	86.7%	15	2	86.7%	15	5	66.7%	15	5	66.7%
14		15	3	80.0%	15	3	80.0%	15	7	53.3%	15	7	53.3%
19	46	15	1	93.3%	15	1	93.3%	14	3	78.6%	14	3	78.6%
20		15	2	86.7%	15	2	86.7%	15	0	100.0%	15	0	100.0%
21	85	15	1	93.3%	15	1	93.3%	15	8	46.7%	15	8	46.7%
22	58	15	3	80.0%	15	3	80.0%	15	11	26.7%	15	11	26.7%
23		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
24	34	11	0	100.0%	11	0	100.0%	11	5	54.5%	11	5	54.5%
25		11	0	100.0%	11	0	100.0%	11	3	72.7%	11	3	72.7%
26		12	0	100.0%	12	0	100.0%	12	4	66.7%	12	4	66.7%
27		14	3	78.6%	14	3	78.6%	14	2	85.7%	14	2	85.7%
28		14	1	92.9%	14	1	92.9%	14	2	85.7%	14	2	85.7%
40		15	3	80.0%	15	3	80.0%	15	9	40.0%	15	9	40.0%
41	114	15	3	80.0%	15	3	80.0%	15	11	26.7%	15	11	26.7%
42	17	15	3	80.0%	15	3	80.0%	15	7	53.3%	15	7	53.3%
43		15	5	66.7%	15	5	66.7%	15	4	73.3%	15	4	73.3%
48	79	15	4	73.3%	15	4	73.3%	15	6	60.0%	15	6	60.0%
49		15	3	80.0%	15	3	80.0%	15	1	93.3%	15	1	93.3%
51		6	2	66.7%	6	2	66.7%	7	3	57.1%	7	3	57.1%
52		14	3	78.6%	14	3	78.6%	14	8	42.9%	14	8	42.9%
53	39	14	5	64.3%	14	5	64.3%	14	12	14.3%	14	12	14.3%
55		11	0	100.0%	11	0	100.0%	11	3	72.7%	11	3	72.7%
56		11	1	90.9%	11	1	90.9%	11	3	72.7%	11	3	72.7%
58	101	15	0	100.0%	15	0	100.0%	15	13	13.3%	15	13	13.3%
59	125	15	0	100.0%	15	0	100.0%	15	11	26.7%	15	11	26.7%
63	32	15	8	46.7%	15	8	46.7%	15	15	0.0%	15	15	0.0%
64	24	15	4	73.3%	15	4	73.3%	15	7	53.3%	15	7	53.3%
66		15	1	93.3%	15	1	93.3%	15	0	100.0%	15	0	100.0%
67	22	11	0	100.0%	11	0	100.0%	11	4	63.6%	11	4	63.6%
68		15	4	73.3%	15	4	73.3%	15	3	80.0%	15	3	80.0%
69		15	6	60.0%	15	6	60.0%	15	2	86.7%	15	2	86.7%
71		15	0	100.0%	15	0	100.0%	15	0	100.0%	15	0	100.0%
72		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
73		10	0	100.0%	10	0	100.0%	10	1	90.0%	10	1	90.0%
74	21	10	2	80.0%	10	2	80.0%	10	4	60.0%	10	4	60.0%
75	Cncld	15	2	86.7%	15	2	86.7%	13	2	84.6%	13	2	84.6%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		15	2	86.7%	15	2	86.7%	15	5	66.7%	15	5	66.7%
78	16	15	3	80.0%	15	3	80.0%	16	4	75.0%	16	4	75.0%
79		15	1	93.3%	15	1	93.3%	15	6	60.0%	15	6	60.0%
80		15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
89	72	14	0	100.0%	14	0	100.0%	15	7	53.3%	15	7	53.3%
90		15	0	100.0%	15	0	100.0%	15	4	73.3%	15	4	73.3%
94		13	2	84.6%	13	2	84.6%	13	2	84.6%	13	2	84.6%
97		15	7	53.3%	15	7	53.3%	15	4	73.3%	15	4	73.3%
98		15	3	80.0%	15	3	80.0%	15	5	66.7%	15	5	66.7%
230		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
232		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
233	33	15	6	60.0%	15	6	60.0%	15	8	46.7%	15	8	46.7%
234		15	0	100.0%	15	0	100.0%	15	0	100.0%	15	0	100.0%
235		15	1	93.3%	15	1	93.3%	15	4	73.3%	15	4	73.3%
236		15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
237		15	2	86.7%	15	2	86.7%	15	3	80.0%	15	3	80.0%
238		15	1	93.3%	15	1	93.3%	15	0	100.0%	15	0	100.0%
239		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
240		15	3	80.0%	15	3	80.0%	15	2	86.7%	15	2	86.7%
241		15	4	73.3%	15	4	73.3%	15	4	73.3%	15	4	73.3%
243		15	2	86.7%	15	2	86.7%	15	0	100.0%	15	0	100.0%
244		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
245		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
280		15	3	80.0%	15	3	80.0%	15	6	60.0%	15	6	60.0%
281		15	2	86.7%	15	2	86.7%	15	2	86.7%	15	2	86.7%
283		15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
284		15	0	100.0%	15	0	100.0%	15	1	93.3%	15	1	93.3%
290		15	2	86.7%	15	2	86.7%	15	5	66.7%	15	5	66.7%
291		15	10	33.3%	15	10	33.3%	15	4	73.3%	15	4	73.3%
300		15	0	100.0%	15	0	100.0%	15	4	73.3%	15	4	73.3%
301		15	0	100.0%	15	0	100.0%	15	3	80.0%	15	3	80.0%
302		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
305		15	0	100.0%	15	0	100.0%	15	6	60.0%	15	6	60.0%
306	30	15	0	100.0%	15	0	100.0%	15	6	60.0%	15	6	60.0%
307	17	15	1	93.3%	15	1	93.3%	15	7	53.3%	15	7	53.3%
311		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
316		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
318	88	15	0	100.0%	15	0	100.0%	15	7	53.3%	15	7	53.3%
319	18	15	0	100.0%	15	0	100.0%	15	12	20.0%	15	12	20.0%
329		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
330		13	0	100.0%	13	0	100.0%	13	1	92.3%	13	1	92.3%
331		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		15	2	86.7%	15	2	86.7%	15	0	100.0%	15	0	100.0%
334		15	0	100.0%	15	0	100.0%	15	0	100.0%	15	0	100.0%
335	44	15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
336		15	0	100.0%	15	0	100.0%	15	1	93.3%	15	1	93.3%
337		15	1	93.3%	15	1	93.3%	15	1	93.3%	15	1	93.3%
338	67	15	2	86.7%	15	2	86.7%	15	4	73.3%	15	4	73.3%
339	69	15	3	80.0%	15	3	80.0%	15	2	86.7%	15	2	86.7%
341		14	3	78.6%	14	3	78.6%	14	1	92.9%	14	1	92.9%
342	34	15	2	86.7%	15	2	86.7%	15	1	93.3%	15	1	93.3%
350		15	1	93.3%	15	1	93.3%	15	9	40.0%	15	9	40.0%
351		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
352		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
353		15	2	86.7%	15	2	86.7%	15	1	93.3%	15	1	93.3%
354		15	3	80.0%	15	3	80.0%	14	4	71.4%	14	4	71.4%
355	Cncld	15	1	93.3%	15	1	93.3%	14	3	78.6%	14	3	78.6%
364		15	0	100.0%	15	0	100.0%	15	4	73.3%	15	4	73.3%
365		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
370		15	0	100.0%	15	0	100.0%	15	1	93.3%	15	1	93.3%
371		15	0	100.0%	15	0	100.0%	15	0	100.0%	15	0	100.0%
380	16	15	0	100.0%	15	0	100.0%	15	3	80.0%	15	3	80.0%
381	32	15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
382	18	15	2	86.7%	15	2	86.7%	15	5	66.7%	15	5	66.7%
383		15	0	100.0%	15	0	100.0%	15	7	53.3%	15	7	53.3%
390		14	2	85.7%	14	2	85.7%	14	2	85.7%	14	2	85.7%
391		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
392	20	15	1	93.3%	15	1	93.3%	15	13	13.3%	15	13	13.3%
393	17	14	3	78.6%	14	3	78.6%	14	7	50.0%	14	7	50.0%
417		11	3	72.7%	11	3	72.7%	11	4	63.6%	11	4	63.6%
425		11	0	100.0%	11	0	100.0%	11	2	81.8%	11	2	81.8%
448	98	14	6	57.1%	14	6	57.1%	15	5	66.7%	15	5	66.7%
449	18	15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
470		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
471		11	3	72.7%	11	3	72.7%	11	3	72.7%	11	3	72.7%
473		11	2	81.8%	11	2	81.8%	11	0	100.0%	11	0	100.0%
474		11	5	54.5%	11	5	54.5%	11	4	63.6%	11	4	63.6%
475		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
478		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
479		11	1	90.9%	11	1	90.9%	11	6	45.5%	11	6	45.5%
486	26	11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
494		12	2	83.3%	12	2	83.3%	11	4	63.6%	11	4	63.6%
495		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
500		15	1	93.3%	15	1	93.3%	15	4	73.3%	15	4	73.3%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
502		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
503		15	3	80.0%	15	3	80.0%	15	8	46.7%	15	8	46.7%
505		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
506	16	15	1	93.3%	15	1	93.3%	14	4	71.4%	14	4	71.4%
507		15	0	100.0%	15	0	100.0%	14	5	64.3%	14	5	64.3%
508		15	1	93.3%	15	1	93.3%	15	5	66.7%	15	5	66.7%
509		15	0	100.0%	15	0	100.0%	15	5	66.7%	15	5	66.7%
511		15	1	93.3%	15	1	93.3%	15	2	86.7%	15	2	86.7%
516	60	13	3	76.9%	13	3	76.9%	12	8	33.3%	12	8	33.3%
517	55	15	2	86.7%	15	2	86.7%	15	7	53.3%	15	7	53.3%
518	16	15	1	93.3%	15	1	93.3%	14	7	50.0%	14	7	50.0%
519	76	13	0	100.0%	13	0	100.0%	13	2	84.6%	13	2	84.6%
520		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
521		11	1	90.9%	11	1	90.9%	10	0	100.0%	10	0	100.0%
522		11	2	81.8%	11	2	81.8%	11	0	100.0%	11	0	100.0%
523		11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
524		11	1	90.9%	11	1	90.9%	11	0	100.0%	11	0	100.0%
525		11	2	81.8%	11	2	81.8%	10	1	90.0%	10	1	90.0%
526		11	6	45.5%	11	6	45.5%	10	2	80.0%	10	2	80.0%
527		11	0	100.0%	11	0	100.0%	11	2	81.8%	11	2	81.8%
528		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
529		11	0	100.0%	11	0	100.0%	11	4	63.6%	11	4	63.6%
530		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
531		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
532		11	2	81.8%	11	2	81.8%	11	0	100.0%	11	0	100.0%
534		11	2	81.8%	11	2	81.8%	11	0	100.0%	11	0	100.0%
535		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
536		11	4	63.6%	11	4	63.6%	11	0	100.0%	11	0	100.0%
537		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
538		11	1	90.9%	11	1	90.9%	11	1	90.9%	11	1	90.9%
539		11	3	72.7%	11	3	72.7%	11	5	54.5%	11	5	54.5%
540		11	2	81.8%	11	2	81.8%	10	0	100.0%	10	0	100.0%
541		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
542		11	3	72.7%	11	3	72.7%	10	1	90.0%	10	1	90.0%
543		11	2	81.8%	11	2	81.8%	11	7	36.4%	11	7	36.4%
544		11	4	63.6%	11	4	63.6%	11	4	63.6%	11	4	63.6%
545		11	0	100.0%	11	0	100.0%	10	0	100.0%	10	0	100.0%
547		11	1	90.9%	11	1	90.9%	11	4	63.6%	11	4	63.6%
548		11	1	90.9%	11	1	90.9%	11	0	100.0%	11	0	100.0%
549		11	0	100.0%	11	0	100.0%	10	1	90.0%	10	1	90.0%
550		11	2	81.8%	11	2	81.8%	11	3	72.7%	11	3	72.7%
551		11	2	81.8%	11	2	81.8%	11	3	72.7%	11	3	72.7%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
562	37	13	1	92.3%	13	1	92.3%	13	8	38.5%	13	8	38.5%
564		13	0	100.0%	13	0	100.0%	13	7	46.2%	13	7	46.2%
566		13	1	92.3%	13	1	92.3%	11	5	54.5%	11	5	54.5%
567		13	2	84.6%	13	2	84.6%	12	3	75.0%	12	3	75.0%
573		13	1	92.3%	13	1	92.3%	13	7	46.2%	13	7	46.2%
580	19	13	1	92.3%	13	1	92.3%	13	6	53.8%	13	6	53.8%
581	40	13	5	61.5%	13	5	61.5%	12	8	33.3%	12	8	33.3%
584	75	13	1	92.3%	13	1	92.3%	12	10	16.7%	12	10	16.7%
587		13	3	76.9%	13	3	76.9%	12	7	41.7%	12	7	41.7%
591	36	13	2	84.6%	13	2	84.6%	13	8	38.5%	13	8	38.5%
595	No OS	10	4	60.0%	10	4	60.0%	10	7	30.0%	10	7	30.0%
600		13	0	100.0%	13	0	100.0%	13	2	84.6%	13	2	84.6%
601		11	4	63.6%	11	4	63.6%	11	1	90.9%	11	1	90.9%
605		11	5	54.5%	11	5	54.5%	10	1	90.0%	10	1	90.0%
607		13	0	100.0%	13	0	100.0%	13	1	92.3%	13	1	92.3%
609		11	1	90.9%	11	1	90.9%	11	0	100.0%	11	0	100.0%
622		9	2	77.8%	9	2	77.8%	9	1	88.9%	9	1	88.9%
626	80	13	3	76.9%	13	3	76.9%	13	3	76.9%	13	3	76.9%
640		11	0	100.0%	11	0	100.0%	11	3	72.7%	11	3	72.7%
641		11	1	90.9%	11	1	90.9%	11	1	90.9%	11	1	90.9%
642		11	0	100.0%	11	0	100.0%	11	2	81.8%	11	2	81.8%
643		13	5	61.5%	13	5	61.5%	13	3	76.9%	13	3	76.9%
644		11	1	90.9%	11	1	90.9%	11	2	81.8%	11	2	81.8%
645		13	4	69.2%	13	4	69.2%	13	2	84.6%	13	2	84.6%
646	71	11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
647		13	2	84.6%	13	2	84.6%	13	0	100.0%	13	0	100.0%
648		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
649		13	1	92.3%	13	1	92.3%	13	2	84.6%	13	2	84.6%
650		13	2	84.6%	13	2	84.6%	13	1	92.3%	13	1	92.3%
651		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
652		13	1	92.3%	13	1	92.3%	13	0	100.0%	13	0	100.0%
653		11	2	81.8%	11	2	81.8%	11	1	90.9%	11	1	90.9%
654		11	3	72.7%	11	3	72.7%	11	3	72.7%	11	3	72.7%
655		13	2	84.6%	13	2	84.6%	13	1	92.3%	13	1	92.3%
656		13	3	76.9%	13	3	76.9%	13	2	84.6%	13	2	84.6%
657		11	2	81.8%	11	2	81.8%	11	1	90.9%	11	1	90.9%
658		13	0	100.0%	13	0	100.0%	13	0	100.0%	13	0	100.0%
680		11	1	90.9%	11	1	90.9%	11	0	100.0%	11	0	100.0%
681	16	11	0	100.0%	11	0	100.0%	10	6	40.0%	10	6	40.0%
682		11	2	81.8%	11	2	81.8%	11	2	81.8%	11	2	81.8%
683	44	11	0	100.0%	11	0	100.0%	11	11	0.0%	11	11	0.0%
684	29	11	1	90.9%	11	1	90.9%	11	6	45.5%	11	6	45.5%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685	29	11	3	72.7%	11	3	72.7%	11	7	36.4%	11	7	36.4%
686		11	1	90.9%	11	1	90.9%	11	7	36.4%	11	7	36.4%
687		11	2	81.8%	11	2	81.8%	11	5	54.5%	11	5	54.5%
688	25	11	0	100.0%	11	0	100.0%	11	4	63.6%	11	4	63.6%
689		4	0	100.0%	4	0	100.0%	5	1	80.0%	5	1	80.0%
701	125	15	2	86.7%	15	2	86.7%	15	3	80.0%	15	3	80.0%
702	121	15	1	93.3%	15	1	93.3%	15	5	66.7%	15	5	66.7%
703	17	15	3	80.0%	15	3	80.0%	15	3	80.0%	15	3	80.0%
704		15	3	80.0%	15	3	80.0%	15	2	86.7%	15	2	86.7%
710		15	4	73.3%	15	4	73.3%	15	3	80.0%	15	3	80.0%
711	Cncld	15	2	86.7%	15	2	86.7%	12	2	83.3%	12	2	83.3%
712		15	5	66.7%	15	5	66.7%	15	5	66.7%	15	5	66.7%
714	159	15	7	53.3%	15	7	53.3%	14	8	42.9%	14	8	42.9%
715		15	2	86.7%	15	2	86.7%	15	7	53.3%	15	7	53.3%
716	39	15	10	33.3%	15	10	33.3%	14	5	64.3%	14	5	64.3%
717	Cncld	15	7	53.3%	15	7	53.3%	13	6	53.8%	13	6	53.8%
718	277	15	11	26.7%	15	11	26.7%	15	7	53.3%	15	7	53.3%
719		15	4	73.3%	15	4	73.3%	15	5	66.7%	15	5	66.7%
757	26	13	0	100.0%	13	0	100.0%	13	7	46.2%	13	7	46.2%
761	16	13	0	100.0%	13	0	100.0%	13	3	76.9%	13	3	76.9%
765	17	13	0	100.0%	13	0	100.0%	13	7	46.2%	13	7	46.2%
769		13	1	92.3%	13	1	92.3%	13	7	46.2%	13	7	46.2%
770	59	13	1	92.3%	13	1	92.3%	13	8	38.5%	13	8	38.5%
774	58	13	0	100.0%	13	0	100.0%	13	10	23.1%	13	10	23.1%
777	129	13	1	92.3%	13	1	92.3%	13	10	23.1%	13	10	23.1%
782	89	13	11	15.4%	13	11	15.4%	13	9	30.8%	13	9	30.8%
785	84	13	5	61.5%	13	5	61.5%	13	7	46.2%	13	7	46.2%
786	171	13	2	84.6%	13	2	84.6%	12	8	33.3%	12	8	33.3%
790	60	13	1	92.3%	13	1	92.3%	13	6	53.8%	13	6	53.8%
794	85	13	4	69.2%	13	4	69.2%	13	7	46.2%	13	7	46.2%
821	47	15	1	93.3%	15	1	93.3%	15	12	20.0%	15	12	20.0%
822	121	15	1	93.3%	15	1	93.3%	15	15	0.0%	15	15	0.0%
1082		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1087		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1088		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
1099		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1103		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1107		4	3	25.0%	4	3	25.0%	4	1	75.0%	4	1	75.0%
1109		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1111		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1116		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1118		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1124	No OS	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
1126		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1127		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1128		4	1	75.0%	4	1	75.0%	3	1	66.7%	3	1	66.7%
1129	37	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1135	27	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
1138		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1140		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
1142	30	4	2	50.0%	4	2	50.0%	4	2	50.0%	4	2	50.0%
1143		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1144		4	3	25.0%	4	3	25.0%	4	0	100.0%	4	0	100.0%
1146		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1147		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1150		4	3	25.0%	4	3	25.0%	4	0	100.0%	4	0	100.0%
1151	20	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
1152	19	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
1153		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1155	16	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
1156	33	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
1160		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1161	46	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
1162		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1163	60	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
1164	25	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
1165		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1167		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
1168		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
1169	16	3	1	66.7%	3	1	66.7%	2	1	50.0%	2	1	50.0%
1194		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
1195		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
1333		15	1	93.3%	15	1	93.3%	15	3	80.0%	15	3	80.0%
1340		15	0	100.0%	15	0	100.0%	15	2	86.7%	15	2	86.7%
2101	33	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
2103		11	1	90.9%	11	1	90.9%	11	1	90.9%	11	1	90.9%
2105		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
2106		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2114		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2115		11	0	100.0%	11	0	100.0%	11	1	90.9%	11	1	90.9%
2116		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
2118		11	2	81.8%	11	2	81.8%	10	1	90.0%	10	1	90.0%
2120		11	3	72.7%	11	3	72.7%	11	2	81.8%	11	2	81.8%
2122		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Amtrak On Time Performance

Trains Arriving Through: 10/15/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2123		11	1	90.9%	11	1	90.9%	11	1	90.9%	11	1	90.9%
2133		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2148		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
2149	27	4	1	75.0%	4	1	75.0%	4	4	0.0%	4	4	0.0%
2150	23	11	0	100.0%	11	0	100.0%	11	5	54.5%	11	5	54.5%
2151	54	11	0	100.0%	11	0	100.0%	11	6	45.5%	11	6	45.5%
2152		11	0	100.0%	11	0	100.0%	11	0	100.0%	11	0	100.0%
2155		11	0	100.0%	11	0	100.0%	10	1	90.0%	10	1	90.0%

Amtrak Endpoint OTP Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2101	WAS	33	ENG	41	ENG	41	NYP-NYP	AM	HEP, 0000, NECESSARY TO SWAP EQUIPMENT A/C MULTIPLE FAULTS ON ORIGINAL EQUIPMENT
2149	WAS	27	DMW	14	DMW	14	NHV-STM	MN	Hold for defect repair Control Point, Unknown
2150	BOS	23	DSR	17	DCS	11	XNH-XGX	AM	Signal suspension, Milepost w/Letters, XM4, XBC, dark signal MP 79.62
2151	WAS	54	OTH	24	RTE	24	XNY-WAS	AM	Dispatcher hold, Control Point, K INTERLOCKING
67	NPN	22	CTI	38	FTI	17	ALX-QAN	CS	Follow IO 111, Milepost, 105.1, 97.9
486	GFD	26	DCS	40	DCS	40	NHV-NHV	MN	Power switch failure, Control Point, NHV, 42sw at CP247 out of correspondence, AM486 held until fixed
1124	PHL	No OS Rpt	DSR	6	DSR	5	WBG-RVM	CS	Per bulletin Milepost, 54.6, 54.9, 25, main, Milepost, 56.7, 56.8, 25, main
1129	WAS	37	ENG	17	ENG	17	NCR-NCR	AM	HEP, 604|EX|ES, lost HEP
1135	WAS	27	SMW	29	SMW	10	KIN-KIN	AM	Diversions around M/W work, Milepost w/Letters, KIN, XHI, AM1135 held at KIN and XHI a/c meet with late AM2150 due to trk 2 OOS
1142	NYP	30	ENG	29	ENG	29	WAS-WAS	AM	Radio failure, 636|EX|ES, MECHANICAL REQUESTED FOR RADIO ISSUES
1151	RNK	20	PTI	28	PTI	18	CVS-LYH	NS	Meet AMT, Control Point, HAMNER
1152	NYP	19	SMW	31	SMW	17	XPV-NRK	AM	Diversions around M/W work, Control Point, Bacon - Davis, Held, Opr No.1 trk a/c No.3 trk o/o/s
1155	NFK	16	CTI	35	OTH	24	WAS-XVG	AM	Lost time - N.A.R.
1156	NYP	33	DCS	48	DCS	35	ALX-XVG	AM	Restrictive signal(s) from unknown cause Stop signal , Control Point, CP-va
1161	WAS	46	SMW	35	DSR	28	BRP-STM	MN	Per bulletin WLSS @MP37.0, Milepost, 35.1, 37.0, 30, 3, Milepost, 42.0, 41.7, 15, 2, Milepost, 41.7, 40.4, 30, 1
1163	WAS	60	CTI	30	CTI	20	BRP-STM	MN	Follow MN, Milepost, 55, 33
1164	BOS	25	OTH	127	OTH	43	WAS-XNY	AM	Lost time - N.A.R.
1169	PHL								
53	SFA	39	FTI	64	SVS	21	XDD-XSF	FR	Hold at vsmf for yard job. Control Point, vsmf

Amtrak Endpoint OTP Details

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
626	NYP	80	CCR	98	CCR	72	PHL-PHL	AM	Set out defective cab car, CANCEL|XX|XX, 626 ORIGINATED IN PHL DUE TO CAB CAR FAILURE ON ORIGINAL EQUIPMENT OUT OF HAR . HELD FOR 622 EQUIPMENT IN PHL
646	PHL	71	ENG	66	ENG	23	MID-MID	AM	PTC - On Board Cab Signal or PTC Failure, 9641|CB|CC
19	NOL	46	FTI	100	DCS	36	MSS-CLP	NS	Restrictive signal(s) from unknown cause Stop/ Calverton, Control Point, Calverton
681	BRK	16	DMW	9	DMW	4	ORB-POR	CS	Waiting for MW clearance Milepost, 16.3, 14.0
683	BRK	44	PTI	42	PTI	23	EXR-DHM	CS	Meet 684, Control Point, Rockingham
684	BON	29	POL	9	POL	9	EXR-EXR	CS	Removal of passenger by police Passenger Leroy got on in Saco and purchased ticket from AC Dowell. Pax threatened Conductor in a multitude of ways.
685	BRK	29	PTI	16	PTI	16	ORB-POR	CS	Wait for station track amt 688, Control Point, mountain trk 1
688	BON	25	FTI	8	FTI	8	HHL-WOB	MT	Follow csx, Control Point, vale-lj
63	TWO	32	OTH	10	SVS	9	ALB-ALB	AM	Engine change
64	NYP	24	CUI	26	CUI	26	NFL-NFL	CS	U.S. Border Patrol Waited on a few that were held for questioning No one was detained
233	ALB	33	DMW	21	DMW	18	CRT-POU	MN	Held for or routed around MW work or equipment Track car causing single track conditions, hold for 2 southbound, Control Point, 61, Control Point, 72
48	NYP	79	SYS	112	SYS	105	TOL-TOL	NS	Other late crew Waiting on engineer
448	BOS	3	FTI	18	FTI	18	ALB-XRD	CS	Meet csx, Control Point, 187
449	ALB	18	FTI	17	FTI	17	PIT-XRD	CS	Follow 427, Control Point, 176
42	NYP	17	DCS	37	DCS	23	HGD-LEW	NS	CTC system failure NS Harrisburg Terminal TD reported that they were experiencing signal and radio failure between CP-LONG and CP-MIFFLIN. Had to get talked by the STOP signals at CP-LONG and CP-LEWIS by the Harrisburg Terminal TD., Milepost, 168, 165
74	RGH	21	PTI	15	PTI	15	BNC-DNC	NS	Meet amtk77, Control Point, Isom
75	CLT	Trn Cancelled							

Amtrak Endpoint OTP Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
78	RGH	16	FTI	10	FTI	10	SAL-HPT	NS	Restricted speed passing train in emergency Finally passed rear between Sharp and Lee, Control Point, Duke, #NS203
89	SAV	72	FTI	100	FTI	20	PTB-RMT	CS	Meet 410, Other, a105.0
41	MIA	114	WTR	84	WTR	56	DNK-SAV	CS	Trees down Hit a tree removed tree from underneath the train, Milepost w/Letters, S 465.5, S 465.5
24	MOE	34	FTI	52	FTI	38	XEJ-XNO	NS	Follow Stop sgl @ CP Paris #2Tk, following CSXT M305 to Gentilly Yd., Control Point, Paris, CSXT M305, Manifest
5	EMY	53	FTI	103	WTR	82	GSC-GSC	UP	Landslide / rockslide Other, West Glenwood-East Chacra
506	SEA	16	MBO	12	MBO	12	PDX-VAN	BN	For maritime traffic Bridge, Columbia bridge
516	VAC	60	POL	36	POL	36	STW-MVW	BN	Removal of passenger by police PNR 3C0573 Nicolas Frabrasilio removed by police at siding at Logen due to spitting, yelling obscenities, while walking through the train car to car.
517	PDX	55	PTI	52	PTI	52	MVW-STW	BN	Meet 516 Needed police, stopped at N Stanwood. I called N Branch to try and get us moving first or to use the siding at the depot but that was denied., Amtk 516, Control Point, Logen
518	VAC	16	RTE	16	FTI	12	MVW-BEL	BN	Meet bnsf 5775, Siding, bow
519	SEA	76	FTI	55	FTI	55	VAC-XVB	BN	Blocked from station track CN5150, Other, Via yard
58	CHI	101	DSR	96	DSR	16	MKS-MEM	CC	Per bulletin Milepost, 64.1, 63.65, 60, 1, Milepost, 62.5, 62.1, 60, 1, Milepost, 59.5, 59.1, 30, 1, Milepost, 55.8, 55.10, 60, 1, Milepost, 46.5, 46.2, 60, 1, Milepost, 54.8, 54.4, 25, 1, Milepost, 34.3, 34, 60, 1, Milepost, 23.5, 21, 25, 1, Milepost, 21.6, 21, 60, 1, Milepost, 12.7, 12, 25, 1, Mil
59	NOL	125	DSR	118	FTI	22	MEM-MKS	CC	Meet CN 3837, Siding, Crenshaw
11	LAX	19	DCS	88	TRS	51	ALY-EUG	UP	Vehicle on track ahead Held for disabled car on tracks, Milepost, 659.1, 659.1
821	FTW	47	DSR	35	DSR	26	GLE-FTW	BN	Per bulletin Milepost, 411.2, 410.8, 45, M, Milepost, 407.9, 407.1, 30, M, Milepost, 396.7, 396.1, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 385.5, 385.3, 30, M, Milepost, 384.2, 383.4, 25, M, Milepost, 383.1, 381.7, 40, M, Milepost, 380.8, 379.5, 40, M, Milepost, 355.9, 355.5, 50, 1, Milepost,

Amtrak Endpoint OTP Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
822	OKC	121	FTI	97	DSR	34	FTW-GLE	BN	Per bulletin Milepost, 346.3, 349.2, 15, m1, Milepost, 350.3, 350.4, 30, crossover, Milepost, 350.9, 351.3, 60, m2, Milepost, 351.5, 352.3, 60, m2, Milepost, 352.8, 353.3, 60, m2, Milepost, 353.5, 354.1, 60, m2, Milepost, 354.7, 355.2, 60, m2, Milepost, 355.1, 355.6, 60, m2, Milepost, 355.6, 355.8,
335	MKE	44	SYS	38	SYS	38	CHI-CHI	AM	PTC problem or failure (cause unknown) Amtrak had an systemwide outage, unable to get PTC information on locomotive, C'noc trouble shooting issue, Control Point, Madison 2.0
338	CHI	67	ITI	40	ITI	40	MKE-MKE	CP	Late departure at initial terminal due to late arrival of inbound equipment 335
339	MKE	69	ITI	52	ITI	52	CHI-CHI	AM	Late departure at initial terminal due to late arrival of inbound equipment 338
342	CHI	34	ITI	40	ITI	40	MKE-MKE	CP	Late departure at initial terminal due to late arrival of inbound equipment 339
355	CHI	Trn Cancelled							
562	SAN	37	CTI	33	PTI	18	SNC-X98	SC	Meet Amtk 765, Control Point, Serra
580	SAN	19	DCS	22	DCS	7	SNP-X98	SC	Restrictive signal(s) from known wayside signal failure Flagging due to high tide signal outages., Stop, Restricted Proceed, Control Point, Pier, Other, Intermidiate 206
581	LAX	40	DCS	31	DCS	19	OSD-X98	SC	Restrictive signal(s) from known wayside signal failure Flagged, Stop, Control Point, songs
584	SAN	75	PTI	25	SYS	18	LAX-XRJ	SC	PTC problem or failure (cause unknown) Sync failure, multiple trains affected, Control Point, mission
591	LAX	36	PTI	40	PTI	40	OSD-X98	SC	Meet coaster, Control Point, pulgas
595	LAX	No OS Rpt	PTI	39	PTI	39	OSD-X98	SN	Meet 786 790, Control Point, pulgas
757	SLO	26	CTI	43	CTI	43	MPK-XMR	SC	Meet Waited at las posas for late 104, metrolink, 104, Control Point, las posas
761	GTA	16	PTI	19	PTI	19	VNC-NRG	SC	Meet LATE 106., SCRRA 106, Control Point, raymer
765	SLO	17	DCS	24	CTI	8	SAN-OLT	SN	Meet HELD by NCTD dispatch for late coaster., nets, 620, Control Point, ash
770	SAN	59	CTI	42	PTI	20	VEC-OXN	UP	Meet 757, Control Point, S. Ventura
774	SAN	58	PTI	78	PTI	29	CPN-VEC	UP	Meet 761, Siding, seacliff

Amtrak Endpoint OTP Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
777	SLO	129	SYS	63	SYS	52	SIM-MPK	SC	PTC problem or failure (cause unknown) METROLINK PTC NETWORK OUTAGE, Control Point, millhouse
782	SAN	89	DCS	56	DCS	50	IRV-IRV	SC	PTC system failure Other, irv
785	GTA	84	DCS	79	DCS	50	OSD-X98	SC	CTC system failure Control Point, songs
786	SAN	171	DCS	123	DCS	70	CML-XMR	SC	Restrictive signal(s) from known wayside signal failure Signal failure, Red Las Posas, Control Point, Los Posas
790	SAN	60	DCS	85	DCS	54	CML-CML	UP	CTC system failure Held platform at CML due to metrolink network outage, Control Point, S Camarillo
794	SAN	85	ITI	99	ITI	99	SLO-SLO	UP	Late departure at initial terminal due to late arrival of inbound equipment 765, Also spotted train in spur track for fuel
701	SAC	125	TRS	75	TRS	75	LOD-XEC	UP	Trespasser strike Fatal trespasser strike at Bond Rd grade crossing., Milepost, 50.95, 50.95
702	BFD	121	TCC	128	TCC	35	TRK-MCD	BN	PTC - On Board Cab Signal or PTC Failure 90218, PTC keeps disengaging, advised by PTC to reset PTC breaker
703	SAC	17	FTI	19	FTI	17	SKT-SKT	UP	Meet up 8117, Control Point, ace
711	OKJ	Trn Cancelled	TRS	204	TRS	204	FNO-MDR	BN	Trespasser strike Waiting for recrew at figarden, Milepost, 999.7, 999.7
714	BFD	159	TCC	64	TCC	57	WAC-BFD	BN	Electrical failure 6964, Batteries on the cab completely died. We stopped at e shafter between the switches. 716 tied into our train. Then drug it into Bakersfield.
716	BFD	39	TCC	40	TCC	40	WAC-BFD	BN	Pick up rescue locomotive due to mechanical failure 6464, Rescued 714 equipment at Shafter due to them losing HEP
717	OKJ	Trn Cancelled	ITI	79	ITI	79	BFD-BFD	BN	Late departure at initial terminal due to late arrival of inbound equipment 702
718	BFD	277	POL	259	POL	259	OKJ-OKJ	UP	Suspicious bag or bomb threat Police hold due to bomb threat on 540 at BKY.
3	LAX	100	FTI	160	FTI	47	FLG-KNG	BN	Follow BNSF 7249, Milepost, 427.7, 516.2

Amtrak Endpoint OTP Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For
Region: ALL
Service: ALL
Arriving On: 10/15/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
4	CHI	No OS Rpt	FTI	643	FTI	432	BAR-NDL	BN	Hold due to freight derailment Remained stopped at 645.5 per DS, until track inspector could arrive and OK use of MT 1 at West Danby. Then moved to West Danby. Met BNSF 7027 W, BNSF 7088 W, BNSF 7645 W, AMTK 3, and three others., Milepost, 645.5, 637.02, BNSF 8401, COFC
21	SAS	85	FTI	292	FTI	57	FTW-X55	UP	Cross Traffic up8152, Control Point, t951
22	CHI	58	FTI	80	FTI	65	XUD-XTF	CC	Cross Traffic unknown, Control Point, Corwith
306	CHI	30	PTI	48	PTI	25	LCN-BNL	UP	Meet 305, Control Point, athol
307	STL	17	POL	29	POL	29	SPI-SPI	UP	Removal of passenger by police
380	CHI	16	DSR	21	DSR	7	QCY-MAC	BN	Per bulletin Milepost, 168.4, 167.9, 30, MT
381	QCY	32	FTI	29	FTI	20	GBB-MAC	BN	Meet bnsf 8780, Control Point, knox
382	CHI	18	CTI	14	CTI	11	NPV-LAG	BN	Follow Metra, Milepost, 28.4, 13.7
392	CHI	20	DSR	34	DSR	11	EFG-MAT	CC	Per bulletin Milepost, 185.20, 184.45, 10, m, Milepost, 182.55, 181.55, 30, m
393	CDL	17	DSR	22	DSR	9	CHM-MAT	CC	Per bulletin Milepost, 151.7, 152.5, 25, main, Milepost, 153.3, 155.7, 25, main
318	CHI	88	FTI	77	FTI	43	CRV-SPI	UP	Cross Traffic NS freight, Control Point, Hazell Dell
319	KCY	18	CAR	29	CAR	29	STL-STL	TR	Door ID4133

Amtrak Initial Terminal Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/15/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	240	10/15	13	13	Late bulletins due to Amtrak cause Waited for copies of Metro North Operating Schedule Order No.4
BON	685	10/15	3	3	Restrictive signal(s) from known wayside signal failure Bad switch leaving BON station, Red, Other, starter signal
BTN	290	10/15	2	2	Late bulletins due to Amtrak cause Other, BTN
HAR	626	10/15	(Trn Cxld)		Cab Car Issue
HFD	471	10/15	8	8	Late departure at initial terminal due to late arrival of inbound equipment, 426
NHV	474	10/15	11	11	Follow, CDOT, 1634, Control Point, NHV, AM474 held for CD1634 to pass
NHV	486	10/15	40	40	Power switch failure, Control Point, NHV, 42sw at CP247 out of correspondence, AM486 held until fixed
NPN	1164	10/15	1	1	EDR showed the incorrect departure time Departing on time at 0408
NYP	69	10/15	6	6	Passenger and/or baggage, LATE GATE
NYP	233	10/15	2	2	Passenger and/or baggage, LOADING
NYP	291	10/15	3	3	Crew rest, 240, LATE TURN OFF AM240
NYP	1107	10/15	(No OS)		
NYP	2101	10/15	41	41	HEP, 0000, NECESSARY TO SWAP EQUIPMENT A/C MULTIPLE FAULTS ON ORIGINAL EQUIPMENT
NYP	2103	10/15	2	2	Passenger and/or baggage, LOADING
PHL	601	10/15	2	2	PTC - Stop Bypass Permission Required, Control Point, .
PHL	605	10/15	2	2	PTC - Stop Bypass Permission Required, Control Point, ., 2 stop bypasses
PHL	657	10/15	1	1	Passenger and/or baggage
PHL	1144	10/15	2	2	Other electrical failure, 663|EX|ES, door light was on
PHL	1150	10/15	1	1	Passenger and/or baggage
PHL	1151	10/15	3	3	Lost time - N.A.R., no delay reported by crew per dispatcher 5:31am, section 3
RGH	75	10/15	(Trn Cxld)		Engine Issue
RNK	1156	10/15	6	6	Meet 19w, Other, Roanoke yard
WAS	1118	10/15	2	2	Other late crew, CREW IDENTIFIED & RESOLVED DOOR ISSUE
WAS	1142	10/15	29	29	Radio failure, 636|EX|ES, MECHANICAL REQUESTED FOR RADIO ISSUES
CHI	3	10/15	44	44	Unrecoverable penalty (PCS) 40
CHI	335	10/15	38	38	PTC problem or failure (cause unknown) Amtrak had an systemwide outage, unable to get PTC information on locomotive, C'noc trouble shooting issue, Control Point, Madison 2.0

Amtrak Initial Terminal Details

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Late Trains For:
Region: ALL
Division: ALL
Data Through: 10/15/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	339	10/15	62	10	Held for mechanical department by glasshouse. Mechanical was needed for 1340 not 339.
CHI	339	10/15	62	52	Late departure at initial terminal due to late arrival of inbound equipment 338
MKE	338	10/15	40	40	Late departure at initial terminal due to late arrival of inbound equipment 335
MKE	342	10/15	40	40	Late departure at initial terminal due to late arrival of inbound equipment 339
PNT	351	10/15	4	4	Door ID4103, Door would not stay close. Kept coming open had to lock it out to stay close.
PNT	355	10/15	(Trn Cxld)		HEP Issue
SAS	22	10/15	191	191	Late departure at initial terminal due to late arrival of inbound equipment 21
BFD	717	10/15	79	79	Late departure at initial terminal due to late arrival of inbound equipment 702
EMY	6	10/15	2	2	Follow 710, Control Point, East Emeryville
GTA	782	10/15	11	11	Meet AMTK 14, Control Point, south Elwood
OKJ	522	10/15	7	7	Delayed delivery of equipment from Mechanical (not due to mechanical failure) Late swap, C2010
OKJ	536	10/15	3	3	Follow Following train 716, departed Oakland maintenance yard late. Waiting for Train 541west to arrive at OKJ and clear the control point for our departure, Amtk716east, Control Point, NI005
OKJ	710	10/15	7	7	Routine inspections Late release from TASI. Resolving issues w/Loco alarms, HEP & restrooms
OKJ	714	10/15	14	14	Short equipment turn at the yard.
OKJ	716	10/15	31	31	Delayed delivery of equipment from Mechanical (not due to mechanical failure) C2123, Tasie had to perform mechanical issues in the yard and the resulting in us having a late departure
OKJ	718	10/15	2	2	PTC problem or failure (cause unknown)
SAN	595	10/15	35	35	Late departure at initial terminal due to late arrival of inbound equipment 584
SAN	785	10/15	5	5	Dispatcher hold Control Point, ash
SEA	8	10/15	97	97	Other electrical failure Over speed not working as intended., AMTK 57
SJC	544	10/15	2	2	Meet JPBX/Caltrain, AMTK 543, Control Point, CP Shark
SLO	794	10/15	18	18	Wait for station track 11, Other, Amtrak Spur

Eastern Region

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.1	99.2	94.8	342	3
CDOT	95.0	91.7	88.9	92.4	24	2
MARC	95.0			90.2		
SEPTA	95.0			91.5		
NJT-NED	95.0	91.5	90.3	88.6	200	17
NJT-SED	95.0			97.2		

Operating Highlights

Train 52(15) South of Florence, SC - Freight Train Interference

16OCT26: Train 52(15), operating with engines 380/352, 50 coaches and 256 customers, was delayed 18 miles south of Florence, SC, on CSX Charleston subdivision, due to meeting and then following XSX410 and CSX31 between Control Point Coward and Control Point New Hope.

Train	Delay	Comment
52(15)	47"	

Train 626(15) Elizabethtown, PA - Cab Car Failure

15OCT26: At approximately 8:15pm-et, operating with Engine 620, 4 coaches, CC9646, and 36 customers, experienced intermittent power loss and a head-end power (HEP) loss at the Elizabethtown, PA station. The crew reported that the pantograph was down and worked with CNOC Mechanical to troubleshoot the issue. The issue was determined to be with the cab car. Train 626(15) subsequently returned to Harrisburg, PA, where cancelled and all customers boarded Train 622(15). Train 622(15) departed Harrisburg, PA on time. Train 626(15) was planned to originate at Philadelphia, PA 30th Street Station and operate to New York, NY Penn Station utilizing Train 622(15) equipment.

Train	Delay	Comment
626(15)	1'12"	ORIG PHL
1169(15)	34"	Crew deadheading on Late 626(15)

Train 40(15) East of Tampa, FL - Trespasser Incident

15OCT26: Train 40(15), operating with Engine 324/320, 11 coaches and 152 customers, went into emergency at MP 870.1 on the CSX Lakeland_A Subdivision to avoid striking a vehicle on the tracks. There was no strike. The crew performed a brake test before resuming operations.

Train	Delay	Comment
40(15)	14"	

27-FOI-00056 00000008836 "UNCLASSIFIED" 10/19/2026

Train 79(14) South of Petersburg, VA - Freight Train Interference

15OCT26: Train 79(14) operating with engine 279, 7 coaches, and 230 customers, was delayed 15.5 miles south of Petersburg, VA, on CSX North End_A subdivision, due to following freight trains M410 and I031 from milepost 37.7 to milepost 112.5.

Train	Delay	Comment
79(14)	1'20"	

MNRR New Haven Line - Switch Failure

15OCT26: Multiple trains were delayed on the MNRR New Haven line due to switch failure at CP 274. MNRR reported switch failure of the 12sw and the 42sw being out of correspondence. Signal maintainers responded to the location and made repairs to allow dispatcher control to resume. Once corrected, normal train operations were able to resume.

Train	Delay	Comment
1156(15)	10"	
486(15)	38"	

Train 646(15) Middletown, PA - Cab Car Failure

15OCT26: Train 646(15) operating with locomotive 624, 4 coaches and cab car 9641 in lead was delayed at Middletown, PA station due to unrecoverable brake penalty on cab car 9641. The crew was unable to reset the penalty and was required to cut out cab signals to allow the fault to clear. Train 646(15) was then required to operate rule 556 with a maximum authorized speed of 59 MPH to Philadelphia causing significant lost run time.

Train	Delay	Comment
646(15)	1'11"	

Train 75(15) Raleigh, NC - Engine Failure

15OCT26: Train 75(15) scheduled to operate with locomotive NC1755, 5 cars and 97 customers was cancelled due to locomotive failure after diesel NC1755 experienced failure while moving into Raleigh Station. The equipment was returned to the yard to be inspected by Mechanical forces. Upon inspection it was determined that the locomotive would not be repaired and as a result trains 75(15) and 76(15) were cancelled in their entirety. No alternate transportation was provided to the customers of train 75(15) and they were given the opportunity to self-modify to train 77(15). Alternate transportation was provided by one bus to the customers of train 76(15) and they were offered to self-modify to train 78(15) if they chose to.

WBS#: B.TR.100150.7273

Train	Delay	Comment
75(15)	cancelled	
76(15)	cancelled	

Amtrak NYP Line - Bridge Strike

15OCT26: Multiple trains were delayed due to a bridge strike on the Amtrak NYP line at Handy Street after a truck became wedged under the overpass. As a result of the bridge strike, SI 132-S2 was placed in effect between New Brunswick Station and MP 32. Once the truck was removed the structure was inspected and the bridge was returned to service and the special instruction was removed.

Train	Delay	Comment
1195(15)	03"	
1164(15)	07"	
2106(15)	10"	
2133(15)	08"	
648(15)	07"	
1118(15)	08"	
Multiple NJ Transits	21"	total

Train 80(15) East of Greensboro, NC - Freight Train Interference

15OCT26: Train 80(15) was delayed east of Greensboro, NC on the NS Goldsboro-Greensboro subdivision following NS 6D4-09 from MP 2.5 to Merrill. Once the freight was cleared into the siding train 80(15) was able to depart Burlington, NC without further delay.

Train	Delay	Comment
80(15)	43"	

Train 2101(15) New York, NY - Initial Terminal Delay - Engine Failure

15OCT26: Next Gen Acela train 2101(15) scheduled to operate with TS-11 was delayed at the initial terminal of New York due to faults in lead power car 2116. The engineer was unable to clear the faults and requested assistance from HSR Mechanical. Upon arrival the HSR Mechanical technician was unable to clear the faults requiring the set to be replaced with TS-24 for the operation of train 2101(15). The customers were transferred to the new set and train 2101(15) was able to depart New York.

Train	Delay	Comment
2101(15)	41"	Initial terminal delay - engine

Train 41(13) Savannah, GA - Debris

15OCT26: Train 41(13), operating with Locomotives 314 and 22, 11 coaches, and 172 customers, struck a tree north of the Savannah, GA station at MP 465.5 on the CSX Columbia Subdivision. Head-end power (HEP) remained active; however, the tree became wedged beneath the lead locomotive. No injuries were reported to the crew or customers. Damage to the locomotive could not initially be determined. The incident occurred on the Savannah River Bridge, making inspection of the train difficult. CSX Maintenance of Way personnel were en route to assist. The crew subsequently removed the tree, allowing Train 41(13) to resume operation. No damage was reported to the equipment. The crew completed a roll-by inspection and a running brake test, confirming no damage to the equipment and that the brake and air systems were operating properly.

Train	Delay	Comment
41(13)	55"	Witronix Estimate

Washington Terminal 'A' Interlocking - Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, Northeast Regional Services - M of W Work

05OCT26: Due to Diamond Replacement at Washington Terminal 'A' interlocking from Friday, October 16, 2026 to Monday, October 26,2026. There will be several service

To accommodate the above outlined infrastructure work, Amtrak's Palmetto, Cardinal, Crescent, Silver Meteor, Floridian, Carolinian, and Northeast Regional Services will be adjusted as follows:

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

PALMETTO
Northbound
- Train 90 (16Oct-26Oct) is canceled in its entirety.
- Train 1090 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between SAV and WAS.

Southbound
- Train 89 (15Oct-25Oct) is canceled in its entirety.
- Train 1089 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and SAV.

CARDINAL
Eastbound
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct), which normally operates between CHI and NYP, will terminate at IND.

Westbound
- Train 51 (18Oct, 21Oct, 23Oct, 25Oct), which normally operates between NYP and CHI, will originate at IND.

EQUIPMENT
- Train 50 (17Oct, 20Oct, 22Oct, 24Oct) will turn for Train 51 (18Oct, 21Oct, 23Oct, 25Oct) at IND.
  - (Note: Train 51's departure days from IND are 19Oct, 22Oct, 24Oct, and 26Oct)

CRESCENT
Northbound
- Train 20 (16Oct-25Oct), which normally operates between NOL and NYP, will terminate at ATL.
- Train 1020 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between ATL and WAS.

Southbound
- Train 19 (16Oct-25Oct), which normally operates between NYP and NOL, will originate at ATL.
- Train 1019 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and ATL.

EQUIPMENT
- Train 20 (16Oct-25Oct) will turn for Train 19 (16Oct-25Oct) at ATL.
  - (Note: Train 19's departure days from ATL are 17Oct-26Oct)

SILVER METEOR
Northbound
- Train 98 (16Oct-25Oct), which normally operates between MIA and NYP, will terminate at JAX.
- Train 1098 (17Oct-25Oct) will operate and provide service between WAS and NYP.
- There will be no service between JAX and WAS.

Southbound
- Train 97 (16Oct-25Oct), which normally operates between NYP and MIX, will originate at JAX.
- Train 1097 (17Oct-25Oct) will operate and provide service between NYP and WAS.
- There will be no service between WAS and JAX.

EQUIPMENT
- Train 98 (16Oct-25Oct) will turn for Train 97 (16Oct-25Oct) at JAX.
  - (Note: Train 97's departure days from JAX are 17Oct-26Oct)

FLORIDIAN
Northbound
- Train 40 (16Oct-24Oct), which normally operates between MIA and CHI, will originate at PGH.
- Train 1040 (17Oct-24Oct) will operate and provide service between MIA and JAX.
- There will be no service between JAX and PGH.

Southbound
- Train 41 (16Oct-24Oct), which normally operates between CHI and MIA, will terminate at PGH.

o (Note: Train 40's departure days from PGH are 17Oct-25Oct)

• Train 1040 (17Oct-24Oct) will turn for Train 1041 (18Oct-25Oct) at JAX

CAROLINIAN 27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026
Northbound

• Train 80 (17Oct-25Oct), which normally operates between CLT and NYP, will terminate at RGH.
• Train 1180 (17Oct-25Oct) is a new train that will operate between RGH and ALX, departing RGH at 11:00am.
• Train 1080 (17Oct-25Oct) is a new train that will operate between WAS and NYP, departing WAS at 5:15pm.

Southbound

• Train 79 (17Oct-25Oct), which normally operates between NYP and CLT, will originate at RGH.
• Train 1079 (17Oct-25Oct) is a new train that will operate between NYP and WAS, departing NYP at 7:05am.
• Train 1179 (17Oct-25Oct) is a new train that will operate between ALX and RGH, departing ALX at 1:00pm.

ALTERNATE TRANSPORTATION

• Train 1180 (17Oct-25Oct) will connect to Bus 1480 (17Oct-25Oct) at ALX
• Train 1079 (17Oct-25Oct) will connect to Bus 1479 (17Oct-25Oct) at WAS

EQUIPMENT

• Equipment for Train 1180 will deadhead on the rear of Train 79(16Oct) and will be cut in RGH
• Train 1179 (17Oct-24Oct) will turn at RGH for Train 1180 (18Oct-25Oct)
• Train 1179 (25Oct) will turn at RGH for Deadhead Train 80 to operate to WAS
• Northeast Regional Train 1094 (17Oct-25Oct) will make a same day turn at ALX for Train 1179 (17Oct-25Oct)
• Train 80 (17Oct-25Oct) will make a same day turn at RGH for Train 79 (17Oct-25Oct)

NORTHEAST REGIONAL

Norfolk

• Train 1094 (17Oct-25Oct) will operate between NFK and ALX
• Train 1095 (17Oct-25Oct) will operate between ALX and NFK

Roanoke

• Train 1071 (17Oct-25Oct) will operate between ALX and RNK
• Train 1078 (17Oct-25Oct) will operate between RNK and ALX

Newport News

• Train 65 (16OCt), which normally operates between BOS and NPN, will terminate at PHL.
• Train 65 (17Oct, 23OCt-24Oct), which normally operates between BOS and NPN, will terminate at WAS.
• Train 67 (15OCt, 18Oct-22Oct), which normally operates between BOS and NPN, will terminate at WAS.
• Train 67 (25Oct), which normally operates between BOS and NPN, is canceled in entirety with no alternate transportation.

ALTERNATE TRANSPORTATION

• Bus 1495 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1095 (17Oct-25Oct) at ALX
• Train 1094 (17Oct-25Oct) will connect to Bus 1494 (17Oct-25Oct) at ALX
• Bus 1471 (17Oct-25Oct) will operate WAS-ALX and connect to Train 1071 (17Oct-25Oct) at ALX
• Train 1078 (17Oct-25Oct) will connect to Bus 1478 (17Oct-25Oct) at ALX
• Bus 1454 (17-Oct- 25Oct) will operate RNK - LYH - WAS.
• Bus 1455 (17-Oct- 25Oct) will operate WAS - LYH - RNK.
• Bus 1456 (17-Oct- 25Oct) will operate CVS - WAS
• Bus 1457 (17-Oct- 25Oct) will operate WAS - CVS

ALX-WAS Buses will unload in front of Union Station utilizing the middle lane of Columbus Circle, with WAS-ALX buses boarding up on the Union Station bus deck

EQUIPMENT

• Carolinian Train 1180 (17Oct-25Oct) will make a same day turn at ALX for Train 1071 (17Oct-25Oct)

25Oct)

- Train 1095 (17Oct-24Oct) will turn for Train 1094 (18Oct-25Oct) at NFK
- Train 1095 (25Oct) will turn for Train 94 (26Oct) at NFK

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

WBS#: B.TR.100151.0856

Maintenance of Way Highlights

37 FOI 00066 - 000000008935 "UNCLASSIFIED" 10/19/2026

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division, Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound
- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound
- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).
EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

Monday, May 25 (Memorial Day)
Friday, July 3 (Independence Day)
Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:
To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:
- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug,

- Train 426 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct) is a new train that will operate Deadhead between NHV and HFD.

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Southbound:
- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-2Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION
- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region
Operating Highlights

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Train 714(15) East of Corcoran, CA - Third Party Contractor Engine Failure

16OCT26: Train 714(15) CC/6964, 7 cars, E/C2014, with 49 customers onboard, was delayed 8.6 miles east of Corcoran, CA station at MP942.2 on the BNSF Bakersfield Subdivision due to a reported loss of head-end power (H.E.P.) and no traction effort. The crew worked with TASI mechanical to troubleshoot the issue. Fault codes on the E/C2014 were reported as low fuel and high coolant temperatures. During this time they restarted the engine and were able to restore H.E.P. a few times, but unable to maintain it. Traction effort was able to be recovered and the decision was made to continue dark into Bakersfield. The weather at the time was a reported 69 degrees. Train 714(15) later became disabled east of Wasco, CA at Shafter/ MP903.5, when the battery power depleted, requiring a rescue from Train 716(15) that was operating only a few minutes behind them. An Amtrak Road Foreman arrived on scene to assist. Once 716(15) arrived, they tied onto the front of 715(16) and the combined trainset proceeded into Bakersfield, CA.

Train	Delay	Comment
714(15)	34"	E/COC
714(15)	57"	E/WAC
716(15)	40"	

Train 21(14) North of San Antonio, TX - Freight Train Interference

16OCT26: Train 21(14) was delayed beginning at MP250.6, 12.48 miles north of San Antonio, TX station on the UPRR Austin subdivision following UP Freight 4708. Train 21(14) followed the freight train until MP 259.1 where it was able to get around the freight and proceed into San Antonio TX station.

Train	Delay	Comment
21(14)	44"	

Train 822(15) South of Oklahoma City, OK - Freight Train Interference

16OCT26: Train 822(15) was delayed holding at MP389.6, 5.6 miles south of Oklahoma City, OK station on the BNSF Red Rock subdivision due to BNSF freight train 7105 stopped ahead with air issues. Train 7105 was able to recover air to clear the route and train 822(15) was able to get back on the move at 1108PM CT.

Train	Delay	Comment
822(15)	30"	

Train 8(15) Seattle, WA - Engine Failure

16OCT26: Train 8(15) was delayed departing Seattle, WA station /MP0.0 on the BNSF Scenic Subdivision, due to a late release from the yard. Engine E/57 had an inoperable overspeed sensor and it was necessary to add engine E/355 ahead. Once the engine was added and all safety checks complete, Train 8(15) was released from the yard and proceeded to the station to board 71 customers.

Train	Delay	Comment
8(15)	1'37"	

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026.

Train 8/28(14) West of Malta, MT - Freight Train Interference

16OCT26: Train 8/28(14) was delayed at Saxby/ MP376.1 on the BNSF Milk River Subdivision, 32.9 miles west of Malta, MT station, due to meeting BNSF 8095.

Train	Delay	Comment
8/28(14)	31"	

Train 786(15) South of Lompoc-Surf, CA - Passenger Train Interference

16OCT26: Train 786(15) was delayed at Tangair siding/MP293.6 5.5 miles south of Lompoc, CA/MP299.2 on the UP Santa Barbara subdivision, due to meeting Train 14(15).

Train	Delay	Comment
786(15)	35"	

Train 716(15) Oakland, CA - Third Party Contractor Car Failure

16OCT26: Train 716(15) was delayed departing Oakland, CA/ MP7.1 on the UPRR Niles Subdivision, due to a late release of equipment by TASI mechanical.

Train	Delay	Comment
716(15)	31"	

Train 354(15) East of Battle Creek, MI - Passenger Train Interference

15OCT26: Train 354(15) was delayed holding at MP122.4, .3 miles east of Battle Creek, MI station on the Amtrak Michigan line for a meet with Amtrak train 355(15). Train 354(15) was back on the move at 957PM ET after train 355(15) cleared to the west.

Train	Delay	Comment
354(15)	35"	

Train 822(15) South of Gainesville, TX - Freight Train Interference

15OCT26: Train 822(15) was delayed holding in the Justin siding/MP371.5, 39.3 miles south of Gainesville, TX station on the BNSF Fort Worth subdivision meeting BNSF Freight trains 6321, 6354 and 1112. Train 822(15) was back on the move at 640PM CT after the freight trains cleared.

Train	Delay	Comment
822(15)	33"	

Train 21(15) Carlinville, IL - Freight Train Interference

15OCT26: Train 21(15) was delayed holding at MP188.9, 36.4 miles north of Carlinville, IL station on the UPRR Springfield subdivision meeting UPRR freight train 7237. Train 21(15) was back on the move at 605PM CT after the freight cleared.

Train	Delay	Comment
21(15)	36"	

27-FOI-00056 00000008938 UNCLASSIFIED 10/19/2026

Train 318(15) South of Springfield, IL - Freight Train Interference

15OCT26: Train 318(15) was delayed holding at MP188.9 - 2.83 miles south of Springfield IL station on the UPRR Springfield subdivision meeting a Norfolk Southern freight train.

Train	Delay	Comment
318(15)	43"	

Train 11(14) North of San Luis Obispo, CA - Signal

15OCT26: Train 11(14) was delayed beginning at CO240-Serrano/ MP240.1 on the UPRR Coast Subdivision, 8.4 miles north of San Luis Obispo, CA station, due to a power signal failure, requiring the crew to hand throw the dual control switch. The train was further delayed flagging to CO244-Chorro/ MP244.

Train 794(15) was also delayed departing San Luis Obispo, CA station due to waiting for Train 11(14) to arrive at the station, in order to be given lights into station track.

Train	Delay	Comment
11(14)	30"	
794(15)	18"	ITD SLO

Train 519(15) Vancouver, BC - Freight Train Interference

15OCT26: Train 519(15) was delayed 0.5 mile south of Vancouver, B.C. on the CNRR New Westminster Subdivision, due to freight stack train L561-5150 blocking the route ahead at the Vancouver yard junction. Once the route was clear, Train 519(15) was able to proceed.

Train	Delay	Comment
519(15)	1'05"	

Metrolink Network Outage - Signal

15OCT26: The Metrolink Railroad experienced a full network outage affecting PTC, signaling and switch equipment on River Subdivision from approximately 5:03PM-PT to 6:15PM-PT. Multiple Amtrak trains were delayed, due to all trains being required to remain stationary at their positions until technicians had restored the service.

Train	Delay	Comment
777(15)	52"	
782(15)	50"	
587(15)	12"	
790(15)	54"	
786(15)	1'47"	
581(15)	07"	
584(15)	18"	
785(15)	50"	

Train 21(14) West of Fort Worth, TX - Freight Train Interference

15OCT26: Train 21(14) was delayed holding at Tower 55/MP345.3 near Fort Worth TX station on the UPRR Choctaw subdivision meeting UPRR freight train 8152. Train 21(14) was back on the move at 407PM CT once the route was cleared.

Train	Delay	Comment
21(14)	57"	

27-FOI-00056, 000000089036, "UNCLASSIFIED", 10/19/2026

Train 3(15) Chicago, IL - Engine Failure

15OCT26: Train 3(15), P40+5/104 Cars, was delayed departing Chicago, IL, due to air brake faults on engine 40 while in the yard. Mechanical forces resolved the issue and set the equipment in Chicago Union Station for boarding of 210 waiting customers. At 2:14PM-CT, Train 3(15) departed Chicago Union Station operating 44 minutes late.

Train	Delay	Comment
3(15)	44"	

Train 355(15) Pontiac, MI - Engine Failure

15OCT26: Train 355(15) was delayed departing Pontiac MI/MP25.9 on the CNRR Holly subdivision due to head end power issues with engine ID4631. Crew was met by two mechanical responders and the general foreman to assist troubleshooting and repairs. Mechanical on scene determined the issue to be a left side head end power contact stuck in the open position. The issue could not be fixed by the crew and mechanical in Pontiac. As a result train 355(15) was cancelled Pontiac MI. to Chicago IL with two buses providing limited alternate transportation to customers. Train 355(15) equipment deadheaded and operated dark to Chicago IL.

Train	Delay	Comment
355(15)	Cancelled	

Pacific Surfliners San Clemente Pier, CA - High Tide Affecting Track Indication

12OCT26: Pacific Surfliner service experienced delays due to high-tide conditions affecting the Metrolink Orange Subdivision east of San Clemente Pier between CP Pier (MP 205.14) and CP SONGS (MP 209.18). The high tides caused track indication failures, requiring trains to flag through the affected area at restricted speed. Single-track operations between CP Serra (MP 199.9) and CP SONGS contributed to additional train meets and cascading delays throughout the corridor.

The following equipment adjustments were implemented to mitigate service impacts:

-Equipment from Train 572(12) was turned at San Diego, CA, to operate Train 785(12) between San Diego and Los Angeles.
-Equipment from Train 774(12) was turned at San Diego to operate Train 587(12).
-Upon arrival in Los Angeles, CA, the Train 587(12) equipment was reassigned to operate Train 785(12) between Los Angeles and Goleta, CA.

13OCT26, continued high tides caused additional debris to accumulate on the right-of-way, resulting in multiple train movements being halted while Maintenance of Way personnel established track and time to inspect and clear the affected area. Once the debris was removed and the track was determined safe for service, rail traffic resumed normal operations. As a result of the service disruption, the following service adjustments were implemented:

Train 572(13), Train 579(13), Train 588(13), and Train 593(13) were canceled. Customers were accommodated on the next available trains.
Train 566(13) terminated at the San Juan Capistrano, CA station, with customers accommodated on Train 770(13). Train 566(13) returned to Los Angeles, CA Union Station.
Train 769(13) terminated at the Oceanside, CA station, with customers accommodated on Train 573(13). Train 769(13) returned to the San Diego, CA station and operated as Train 777(13).
Train 581(13) was canceled, with customers accommodated on Train 777(13).
Train 584(13) was canceled.

14OCT, the following service adjustments were implemented due to anticipated high-tide delays:
Trains 572, 579, 588, 593(14-15) were canceled. Customers were accommodated on the next available trains.

Train	Delay	Comment
769(12)	48"	
564(12)	48"	
566(12)	1'09"	
770(12)	1'12"	
777(12)	1'20"	
579(12)	36"	
774(12)	2'40"	
581(12)	38"	
581(12)	30"	late turn 770(12)
580(12)	14"	
587(12)	53"	late turn 774(12)
587(12)	38"	
785(12)	18"	late depart SAN equip swap
785(12)	55"	
785(12)	1'15"	equip swap at LAX
782(12)	20"	
584(12)	32"	
591(12)	44"	
593(12)	49"	
595(12)	1'12"	
588(12)	1'00"	
786(12)	18"	
790(12)	27"	late inbound 785(12) at LAX
790(12)	43"	
794(12)	18"	
769(13)	31"	LAX on time section
769(13)	40"	
573(13)	4'18"	
564(13)	4'20"	
770(13)	3'00"	
566(13)	1'46"	
786(13)	31"	
591(13)	1'05"	
591(13)	35"	late turn 580
790(13)	1'08"	
595(13)	1'15"	
782(13)	37"	
777(13)	1'47"	
777(13)	2'14"	SAN ITD
580(13)	1'25"	
785(13)	1'57"	
587(13)	1'14"	
774(13)	2'32"	
573(13)	4'41"	
794(13)	2'01"	late turn 765
794(13)	16"	
761(14)	11"	
564(14)	11"	Signal
562(14)	13"	
765(14)	18"	
769(14)	1'15"	Signal and Train Interference
573(14)	34"	Signal and Train Interference
770(14)	12"	
777(14)	26"	Signal and Train Meet
572(13-15)	Canceled	
593(13-15)	Canceled	
588(13-15)	Canceled	
579(13-15)	Canceled	
581(14)	37"	
774(14)	15"	
794(14)	1'39"	ITD SLO- Equip turn 765
587(14)	2'38"	
786(14)	1'38"	
584(14)	1'21"	
785(14)	1'36"	
790(14)	1'17"	
591(14)	2'07"	
595(14)	1'06"	
761(15)	14"	
562(15)	20"	
573(15)	22"	
564(15)	14"	
566(15)	23"	
770(15)	15"	
580(15)	15"	

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Train	Delay	Comment
777(15)	30"	
782(15)	43"	
786(15)	33"	
785(15)	13"	
595(15)	35"	ITD SAN- Turn off 584
794(15)	16"	

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Train 701(15) North of Lodi, CA - Trespasser Incident

15OCT26: At 1:09P-PT, Train 701(15), E/C2106-7 cars-CC/C8308, went into emergency after fatally striking a trespasser at MP 50.7, 21 miles north of Lodi, CA station, on the UPRR Fresno Subdivision in Elk Grove, in Sacramento County. This incident occurred at the Bond Rd crossing (DOT # 752749S) equipped with advanced warning signs, pavement markings, quad gate arms, flashing lights and bells. There were no reported injuries to the 105 customers and crew on board and no damage reported to the equipment with head-end power (HEP) remaining up and active. The crew held for local law enforcement, EMS, UPRR track inspector and Amtrak personnel to respond. Once investigation was complete, and tracks were released, Train 701(15) was able to proceed.

CA# 26-5366

National Response Center Number: 1476282

Train	Delay	Comment
701(15)	1'15"	

Train 516(15) North of Stanwood, WA - Unruly Customer

15OCT26: Train 516(15), operating with Airo set 2 and 190 customers on board, was delayed at Logen/ MP 57.6, 2 miles north of Stanwood, WA, on the BNSF Bellingham Subdivision holding for police to remove an unruly customer on board. The crew reported the customer was yelling obscenities and spitting while walking through entire train. Train 516(15) held for local police to respond and remove the customer. Train 517(15) held at MP 57.7 for open track.

Train	Delay	Comment
516(15)	36"	
517(15)	52"	

Train 21(14) South of Marshall, TX - Freight Train Interference

15OCT26: Train 21(14) held 9.7 miles south of Marshall, TX (MP66.5), on the UPRR Little Rock Subdivision, at Keokuk (MP76.2) in order to meet UP 7272, UP 8619, and BNSF 9217.

Train	Delay	Comment
21(14)	31"	

Train 20(15) Meridian, MS - Freight Train Interference

15OCT26: Train 20(15) was delayed into the Meridian, MS station (MP295), on the NSRR NO&NE and AGS South Subdivisions, following NS M30 from Savoy (MP9.9).

Train	Delay	Comment
20(15)	50"	

Train 22(14) North of Joliet, IL - Freight Train Interference

15OCT26: Train 22(14) held 30.7 miles north of Joliet, IL (MP37.3), on the CNRR Joliet Subdivision, at Corwith (MP6.6) waiting on cross traffic to clear.

27,FOI-00056 000000008936 "UNCLASSIFIED" 10/19/2026

Train 702(15) West of Turlock-Denair, CA - Third Party Contractor Cab Car Failure

15OCT26: Train 702(15), CC/90218-5cars-E/C2010 was delayed starting at MP 1059.4, 20 miles west of Turlock-Denair, CA, on the BNSF Stockton Subdivision due to PTC disengaging on CC/90218. The crew contacted mechanical to assist. With mechanical assistance, the crew reset the breaker which resolved the issue. Train 702(15) was further delayed at west of Merced with intermittent PTC issues. The crew received permission to cut PTC out and operated at restricted speed not exceeding 59 mph.

Train 717(15) was delayed departing Bakersfield, CA due to the equipment turning from 702(15). Due to this train operating late and Train 719(15) operating only a few minutes behind, in order to prevent train congestion in Oakland station, Train 717(15) was terminated at Emeryville. All remaining passengers were accommodated onto 719(15) between Emeryville and Oakland.

WBS#: B.TR.100150.7275

Train	Delay	Comment
702(15)	35"	TRK-MCD
702(15)	34"	PTC Cut out
717(15)	1'19"	ITD BFD- Turn off 702
717(15)	Terminated EMY	

Train 527(15) West of Suisun-Fairfield, CA - Third Party Contractor Engine Failure

15OCT26: Train 527(15), E/JPBX922-4 cars-CC/C8303 with 67 customers on board, was delayed at MP 48.7, just west of Suisun-Fairfield, CA, on the UPRR Martinez Subdivision due to PTC issues with E/JPBX922. The crew contacted mechanical to troubleshoot. With mechanical assistance, the crew reset the breaker to clear the PTC fault. Once the fault was cleared, Train 527(15) proceeded west. Train 11(14) was delayed holding at MP 52.3 for the crew on Train 527(15) to resolve PTC issues.

Train	Delay	Comment
527(15)	21"	
11(14)	22"	

Amtrak Network Outage - Miscellaneous Amtrak Responsible

15OCT26: At 1:47PM-ET, Amtrak experienced a nationwide network outage that impacted phone and internet access across the system. As a result, trains 335(15) and 1156(15) incurred delays during the disruption. At 2:35PM-ET, the issue was resolved, all affected systems were restored, and normal operations resumed.

Train 338(15) was delayed departing Milwaukee, WI (MP85.4), on the CPRR C&M Subdivision, due to a late turn of Train 335(15)'s equipment that arrived at 3:28PM-CT, 44 minutes late. Train 339(15) was delayed departing Chicago IL station due to a late turn of train 338(15)'s equipment. Train 342(15) was delayed departing Milwaukee station due to a late turn of train 339(15)'s equipment.

Train	Delay	Comment
335(15)	38"	ITD CHI
1156(15)	42"	Signal from K-Tower
338(15)	40"	ITD MKE - Turn of 335(15)
339(15)	1'02"	
342(15)	40"	

27-FOI-00056 0000008938 "UNCLASSIFIED" 10/15/2026

Train 757(15) North of Moorpark, CA - Commuter Train Interference

15OCT26: Train 757(15) was delayed at MP 426.7, 1 mile north of Moorpark, CA, on the Metrolink Ventura Subdivision holding for Metrolink 104. Once the Metrolink 104 cleared, Train 757(15) was further delayed flagging through signal issues at MP 418.

Train	Delay	Comment
757(15)	43"	Metrolink 104
757(15)	15"	Signal issues MP 418

Train 8/28(14) East of Libby, MT - Freight Train Interference

15OCT26: Train 8/28(14) was delayed starting at Riverview/ MP 1307.4, 12 miles east of Libby, MT, on the BNSF Kootenai Subdivision due to freight interference. The crew held at MP 1307.4 for BN3860 to clear. Once freight cleared, the crew followed BN7638 from Wolf Prairie/ MP 1283.2 to Twin Meadows/ MP 1264.5. A broken rail was reported near Radnor/MP 1242.3 causing freight interference and delays. Train 8/28(14) was further delayed at Radnor/ MP 1244.3 holding for a 10k freight BN6313 to be walked through affected area. Once BN6313 was cleared, Train 8/28(14) held for Maintenance of way crews to clear.

Train	Delay	Comment
8/28(14)	21"	BN3860
8/28(14)	51"	BN6313
8/28(14)	33"	BN7638
8/28(14)	27"	Hold for MoW to clear

Train 711(15) West of Fresno, CA - Trespasser Incident

15OCT26: At 7:05A-PT, Train 711(15), E/C2103-5 cars- CC/C6965, went into emergency at MP 999.7, 1 mile west of Fresno, CA, on the BNSF Stockton Subdivision after fatally striking a trespasser. There were no reported injuries to the crew or the 77 customers on board. The crew inspected the equipment and no noticeable damage was reported and head end power(HEP) remained up and active. The crew held while local law enforcement, EMS and an Amtrak Road Foreman responded. BNSF personnel were also on scene to assist. The coroner arrived at 8:15A. Due to the remains being lodged under the train, at 8:38A-PT, the crew advanced Train 711(15) to Figarden/ MP 1005.9 where it held for the recrew engineer and conductor. An Amtrak Road Foreman arrived with relief engineer at 9:30A-PT. The customers were all transferred to Train 701(15) where a bus was secured in Stockton, CA to accommodate customers traveling from Stockton, CA to Oakland, CA. The bus operated from Stockton to Martinez, CA where customers were reaccommodated in Martinez on the next available Capital Corridor service to their final destinations. All customers were transferred and Train 701(15) was back on the move at 9:43A-PT. The conductor recrew arrived at 10:10A-PT, and once their crew briefing and brake test were complete, Train 711(15) proceeded west. Due to the late operation of Train 711(15) it was terminated in Emeryville, CA and the equipment was deadheaded from Oakland to the Oakland Maintenance facility for serviced to turn for Train 718(15).

NRC # 1476225

CA # 26-5353

WBS#: **B.TR.100150.7271**

National Response Center Number: **1476225**

Train	Delay	Comment
711(15)	3'24"	
701(15)	35"	

27-FOI-00056 0000008936 UNCLASSIFIED 10/19/2026

Train 24(15) North of New Orleans, LA - Freight Train Interference

15OCT26: Train 24(15) was delayed starting 5.9 miles north of New Orleans, LA (MP0.0), on the NSRR New Orleans Terminal and CSX NO&M Subdivisions, following CSX M305 from Paris Road (MP5.9) to North Gentilly (MP799.2).

Train	Delay	Comment
24(15)	38"	

Train 2/422(14) Maricopa, AZ - Freight Train Interference

15OCT26: Train 2/422(14), with 214 customers onboard, was held extensively at the Maricopa, AZ station (MP897.7) on the UPRR Gila Subdivision due to UP 2762 being involved in a fatal trespasser strike at MP933. Both main tracks were taken out of service for the investigation. At 10:41AM-MST, Train 2/422(14) was released from the station and advanced to MP917.2, where it held beginning at 11:04AM-MST. Union Pacific anticipated the tracks would reopen shortly; however, after the medical examiner arrived, both main tracks remained out of service for the investigation and cleanup. At 12:23PM-MST, UP 2762 was released from official hold and proceeded west, after which a final track inspection was completed. At 12:57PM-MST, both main tracks were reopened, establishing a route for Train 2/422(14) to continue east. During this time, service recovery was enacted with complimentary snack packs and bottled water for all customers. Coach customers received beef stew and Sleeper customers received their regular lunch and dinner service.

WBS#: B.TR.100150.7274

Train	Delay	Comment
2/422(14)	3'33"	MRC Station Hold
2/422(14)	2'06"	E/MRC - MP917.2

Train 2/422(14) East of Palm Springs, CA - Signal Issues

15OCT26: Train 2/422(14), with 242 customers on board, was delayed starting at Myoma/ MP 604.5, 16 miles east of Palm Spring, CA, on the UPRR Yuma Subdivision due to signal issues. The crew stopped at MP 604.5 then proceeded at restricted speed from MP 604.5 until Coachella/ MP 615.0. Once through the affected area, Train 2/422(14) proceeded at track speed.

Train	Delay	Comment
2/422(14)	51"	

Train 11(14) South of Dunsmuir, CA - Bear Strike

15OCT26: Train 11(14), E/343-E/337-9 cars, was delayed at MP 307.5, 15 miles south of Dunsmuir, CA, on the UPRR Valley Subdivision after striking a bear. The strike cause a hose separation between C/61028 and C/39037. There were no reported injuries to the crew or the 223 customers on board. Once the crew resecured the hose and performed a brake test, Train 11(14) proceeded south.

Train	Delay	Comment
11(14)	18"	

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Train 21(14) South of Little Rock, AR - Freight Train Interference / Fire on Tracks

15OCT26: Train 21(14) held 24 minutes south of Little Rock, AR (MP345.7), on the UPRR Little Rock Subdivision, at Saline Jct (MP370.3) in order to meet UP 8181 and UP 6816. After those movements cleared, Train 21(14) advanced to Haskell (MP371.4), where it was held awaiting clearance of a track fire ahead. Once released, Train 21(14) proceeded to Traskwood (MP378.5) to meet UP 3976 and UP 5466 before continuing southward.

Train	Delay	Comment
21(14)	30"	Saline Jct
21(14)	40"	Fire Hold
21(14)	27"	Traskwood

Train 4(14) East of Needles, CA - Freight Train Interference

15OCT26: Train 4(14) was delayed starting at West Franconia/MP 553.7, 25 miles east of Needles, CA, on the BNSF Seligman Subdivision due to freight interference. The crew held to pick up a BNSF freight crew to assist with recrew. Train 4(14) was further delayed starting at MP 495 until MP 465.9 following BN7325. Once freight cleared, Train 4(14) proceeded at track speed.

Train	Delay	Comment
4(14)	37"	BN7325
4(14)	30"	

Maintenance of Way Highlights

27-FOF-00056 000000098936 "UNCLASSIFIED" 10/19/2026

CN Track Work South of Champaign-Urbana, IL - Saluki Service TWA 27-006

05OCT26: CN will perform tie replacement work south of Champaign, IL/MP127.9, on the CN Champaign Subdivision, between MP18 and MP164. The work curfews will take place 800AM-CT until 400PM-CT Mondays through Fridays beginning Monday October 5th through Friday October 30th. To accommodate this infrastructure work, Amtrak's Saluki Service will be adjusted as follows:

- Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will terminate at Champaign, IL, with Bus 3391 as alternate transportation between Champaign and Carbondale, IL.
- Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will originate at Champaign and will operate 1-hour later to Chicago, IL. Bus 3390 will provide alternate transportation between Carbondale and Champaign, operating 1-hour earlier than train schedule.

Trains 391(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) will operate with engines on both ends of the equipment to turn for Trains 390(05OCT-09OCT, 12OCT-16OCT, 19OCT-23OCT & 26OCT-30OCT) at Champaign.

WBS#: B.TR.100150.7220

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound
- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound
- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
506	TAC	1	TUK	N/A
506	PDX	1	SEA	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 516(15) Passenger Removal at Stanwood, Washington – Improper Conduct

15OCT26, Passenger on PNR 3C0573, traveling from Seattle, WA to Vancouver, BC was removed from the train by Snohomish County Sheriff. The passenger was yelling obscenities throughout the train. The passenger spit on the window in the train after being asked to step off the train to calm down. Amtrak Police notified.

Delay: 516(15) 37″

Train 319(15) Passenger Removal at St Louis, Missouri – Improper Conduct

15OCT26, Passenger on PNR 3F4D77, traveling from St. Louis MO to Washington, MO was removed from the train by the conductor. The passenger was yelling and disturbing the other passengers. Amtrak Police notified.

Delay: 319(15) None

Consist Deviations

27-FOI-00056 00000008936 "UNCLASSIFIED" 10/19/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
566 (15)	LAX	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	no bv	1	90215
562 (16)	LAX	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	no impact	0	90215
580 (16)	LAX	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	no impact	0	90215
581 (15)	SAN	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	no bv	6	90215
573 (16)	SAN	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	Pax impact	1	90215
591 (16)	SAN	Will not be able to accommodate passengers with BV reservation a/c 90215 in consist. CNOC CSV will need to reaccommodate any passengers impacted.	no impact	0	90215
8 (16)	SEA	Operating with sleeper in lieu of t-Dorm. Schedule changes has already been performed.	no impact	0	32057

Reverse Consists

Train Number	Station	Reason
1195 (15)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1163 (15)	BOS	Consist reversed | Business class seat orientation may have changed | At Front
1127 (15)	NYP	Consist reversed | Business class seat orientation may have changed | At Front
1135 (15)	BOS	Consist reversed | Business class seat orientation may have changed | At Front