



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, October 05, 2025

Rules: 0-0



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/04/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/04/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	264	37	86.0%	1,147	182	84.1%	1,147	182	84.1%
Central Division	85.5%	66	7	89.4%	263	38	85.6%	263	38	85.6%
Northeast Division	80.0%	77	9	88.3%	359	75	79.1%	359	75	79.1%
Southeast Division	72.5%	58	6	89.7%	268	18	93.3%	268	18	93.3%
Southwest Division	77.0%	63	15	76.2%	257	51	80.2%	257	51	80.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00028 00000004749 UNCLASSIFIED 10/13/2025

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	77%	92,562	13,999	85%	384,332	66,228	83%	384,332	66,228	83%
Northeast Corridor	81%	39,181	4,234	89%	167,346	21,209	87%	167,346	21,209	87%
Acela	83%	5,010	417	92%	30,155	3,280	89%	30,155	3,280	89%
Northeast Regional	79%	34,171	3,817	89%	137,191	17,929	87%	137,191	17,929	87%
Richmond / Newport News / Norfolk	77%	11,057	1,348	88%	45,507	8,562	81%	45,507	8,562	81%
Springfield Shuttles	89%	678	0	100%	2,885	249	91%	2,885	249	91%
Roanoke	79%	2,832	88	97%	11,803	1,063	91%	11,803	1,063	91%
On Spine Northeast Regional	80%	19,604	2,381	88%	76,996	8,055	90%	76,996	8,055	90%
State Supported	80%	42,106	6,410	85%	169,696	29,457	83%	169,696	29,457	83%
Borealis	60%	614	40	93%	2,480	872	65%	2,480	872	65%
Capitol Corridor	90%	2,842	326	89%	14,236	1,506	89%	14,236	1,506	89%
Carolinian	60%	1,123	368	67%	4,434	1,254	72%	4,434	1,254	72%
Cascades	63%	1,861	55	97%	8,952	1,457	84%	8,952	1,457	84%
Downeaster	82%	1,916	600	69%	6,239	672	89%	6,239	672	89%
Empire	78%	4,651	399	91%	20,522	4,390	79%	20,522	4,390	79%
Adirondack	72%	344	6	98%	1,361	591	57%	1,361	591	57%
Ethan Allen Express	70%	480	295	39%	2,287	835	63%	2,287	835	63%
Maple Leaf	70%	698	5	99%	2,847	859	70%	2,847	859	70%
New York - Albany	85%	1,829	93	95%	8,897	1,335	85%	8,897	1,335	85%
New York - Niagara Falls	75%	1,300	0	100%	5,130	770	85%	5,130	770	85%
Heartland Flyer	65%	208	18	91%	750	307	59%	750	307	59%
Hiawatha	90%	1,877	0	100%	7,236	1,362	81%	7,236	1,362	81%
Illinois	78%	2,651	1,045	61%	10,002	3,207	68%	10,002	3,207	68%
Carl Sandburg / Illinois Zephyr	85%	540	338	37%	1,544	1,023	34%	1,544	1,023	34%
Illini / Saluki	85%	913	513	44%	3,651	872	76%	3,651	872	76%
Lincoln Service	70%	1,198	194	84%	4,807	1,312	73%	4,807	1,312	73%
Keystone	92%	6,153	0	100%	33,732	1,334	96%	33,732	1,334	96%
Lincoln / Missouri	60%	928	380	59%	3,287	1,750	47%	3,287	1,750	47%
Mardi Gras Service	80%	578	193	67%	1,700	506	70%	1,700	506	70%
Michigan	69%	2,116	665	69%	7,136	1,358	81%	7,136	1,358	81%
Blue Water	70%	538	118	78%	2,000	479	76%	2,000	479	76%
Pere Marquette	85%	204	0	100%	1,002	0	100%	1,002	0	100%
Wolverine	65%	1,374	547	60%	4,134	879	79%	4,134	879	79%
Missouri	80%	354	16	95%	1,021	300	71%	1,021	300	71%
Pacific Surfliner	85%	8,782	583	93%	25,481	3,104	88%	25,481	3,104	88%
Pennsylvanian	72%	886	1	100%	3,519	408	88%	3,519	408	88%
Piedmont	73%	1,189	294	75%	4,202	743	82%	4,202	743	82%
San Joaquins	73%	2,061	1,343	35%	9,264	4,025	57%	9,264	4,025	57%
Vermont	75%	1,316	84	94%	5,503	902	84%	5,503	902	84%
Long Distance	56%	11,275	3,355	70%	47,290	15,562	67%	47,290	15,562	67%
Auto Train	57%	541	0	100%	2,226	226	90%	2,226	226	90%
California Zephyr	50%	951	238	75%	3,997	650	84%	3,997	650	84%
Cardinal	55%	387	20	95%	1,378	426	69%	1,378	426	69%
City Of New Orleans	75%	793	53	93%	2,808	415	85%	2,808	415	85%
Coast Starlight	60%	640	0	100%	3,508	1,521	57%	3,508	1,521	57%
Crescent	70%	852	133	84%	3,403	518	85%	3,403	518	85%
Empire Builder	55%	1,045	297	72%	4,481	1,909	57%	4,481	1,909	57%
Floridian	40%	1,667	1,398	16%	6,975	3,844	45%	6,975	3,844	45%
Lake Shore Ltd	73%	993	122	88%	3,765	414	89%	3,765	414	89%
Palmetto	65%	889	55	94%	3,491	364	90%	3,491	364	90%
Silver Meteor	45%	980	19	98%	3,323	651	80%	3,323	651	80%
Southwest Chief	40%	987	790	20%	3,726	2,958	21%	3,726	2,958	21%
Sunset Ltd	70%	0	0	-	856	91	89%	856	91	89%
Texas Eagle	50%	550	230	58%	3,353	1,575	53%	3,353	1,575	53%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00020 00000004740 "UNCLASSIFIED" 10/10/2025

Train Index Dates Through October 04, 2025

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	18,839	416,725	452	18,839	416,725	452

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	100	476	118,020	40	476	118,020	40
INFRASTRUCTURE PLANNED	130	488	118,020	41	488	118,020	41
FLEET RELIABILITY	90	3,003	416,725	72	3,003	416,725	72
TRAIN OPERATIONS	427	14,872	416,725	357	14,872	416,725	357

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 10/04/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/04/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	264	37	86.0%	1,147	182	84.1%	1,147	182	84.1%
Central Division	85.5%	66	7	89.4%	263	38	85.6%	263	38	85.6%
Northeast Division	80.0%	77	9	88.3%	359	75	79.1%	359	75	79.1%
Southeast Division	72.5%	58	6	89.7%	268	18	93.3%	268	18	93.3%
Southwest Division	77.0%	63	15	76.2%	257	51	80.2%	257	51	80.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

26-FOI-0001 Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/04/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/04/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	264	37	86.0%	1,147	182	84.1%	1,147	182	84.1%
Central Division	85.5%	66	7	89.4%	263	38	85.6%	263	38	85.6%
CDL	90.0%	2	0	100.0%	8	0	100.0%	8	0	100.0%
CHI	85.0%	27	2	92.6%	108	12	88.9%	108	12	88.9%
EUG	86.5%	2	0	100.0%	8	0	100.0%	8	0	100.0%
GRR	98.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
KCY	84.5%	2	0	100.0%	8	0	100.0%	8	0	100.0%
MKE	86.5%	6	0	100.0%	24	5	79.2%	24	5	79.2%
MSP	94.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
PDX	78.0%	4	0	100.0%	19	5	73.7%	19	5	73.7%
PTH	93.0%	1	0	100.0%	4	1	75.0%	4	1	75.0%
QCY	87.5%	2	1	50.0%	8	3	62.5%	8	3	62.5%
SEA	80.0%	8	1	87.5%	31	4	87.1%	31	4	87.1%
SPK	92.0%	1	0	100.0%	4	1	75.0%	4	1	75.0%
STL	88.0%	4	0	100.0%	16	2	87.5%	16	2	87.5%
TRM	-	3	1	66.7%	9	3	66.7%	9	3	66.7%
VAC	95.0%	2	2	0.0%	8	2	75.0%	8	2	75.0%
Northeast Division	80.0%	77	9	88.3%	359	75	79.1%	359	75	79.1%
ALB	91.5%	6	0	100.0%	24	0	100.0%	24	0	100.0%
BON	43.5%	5	2	60.0%	18	7	61.1%	18	7	61.1%
BOS	86.5%	13	1	92.3%	64	6	90.6%	64	6	90.6%
BRK	88.0%	5	0	100.0%	16	1	93.8%	16	1	93.8%
BTN	48.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
GFD	86.0%	2	0	100.0%	8	1	87.5%	8	1	87.5%
HFD	-	-	-	-	6	1	83.3%	6	1	83.3%
MTR	79.5%	1	0	100.0%	4	0	100.0%	4	0	100.0%
NFL	96.5%	2	0	100.0%	8	1	87.5%	8	1	87.5%
NHV	75.5%	4	0	100.0%	19	12	36.8%	19	12	36.8%
NYP	77.5%	30	6	80.0%	157	36	77.1%	157	36	77.1%
SAB	98.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
SPG	88.0%	6	0	100.0%	21	6	71.4%	21	6	71.4%
TWO	84.0%	1	0	100.0%	4	2	50.0%	4	2	50.0%
WEM	-	-	-	-	2	2	0.0%	2	2	0.0%
Southeast Division	72.5%	58	6	89.7%	268	18	93.3%	268	18	93.3%
CLT	92.0%	5	1	80.0%	20	1	95.0%	20	1	95.0%
HAR	62.0%	7	1	85.7%	46	1	97.8%	46	1	97.8%
LOR	69.5%	1	0	100.0%	4	1	75.0%	4	1	75.0%
MIA	87.5%	2	0	100.0%	8	0	100.0%	8	0	100.0%
MOE	94.0%	2	0	100.0%	8	0	100.0%	8	0	100.0%
NFK	86.0%	3	0	100.0%	12	1	91.7%	12	1	91.7%
NOL	92.0%	5	0	100.0%	18	0	100.0%	18	0	100.0%
NPN	96.0%	2	1	50.0%	8	2	75.0%	8	2	75.0%
PGH	92.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
PHL	45.0%	4	1	75.0%	19	1	94.7%	19	1	94.7%
RGH	97.0%	4	0	100.0%	16	0	100.0%	16	0	100.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 10/04/2025

Amtrak or Commuter: Amtrak

Location	Target	ITP 10/04/2025			ITP October 2025 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	78.5%	264	37	86.0%	1,147	182	84.1%	1,147	182	84.1%
Southeast Division	72.5%	58	6	89.7%	268	18	93.3%	268	18	93.3%
RNK	85.5%	2	0	100.0%	8	1	87.5%	8	1	87.5%
RVM	86.0%	1	0	100.0%	4	1	75.0%	4	1	75.0%
SAV	91.5%	1	0	100.0%	4	0	100.0%	4	0	100.0%
SFA	70.5%	1	0	100.0%	4	0	100.0%	4	0	100.0%
WAS	70.0%	17	2	88.2%	85	9	89.4%	85	9	89.4%
Southwest Division	77.0%	63	15	76.2%	257	51	80.2%	257	51	80.2%
ARN	60.5%	1	0	100.0%	4	1	75.0%	4	1	75.0%
BFD	75.5%	5	3	40.0%	20	10	50.0%	20	10	50.0%
EMY	50.0%	1	1	0.0%	4	3	25.0%	4	3	25.0%
FTW	89.5%	1	0	100.0%	4	1	75.0%	4	1	75.0%
GTA	72.5%	3	0	100.0%	12	1	91.7%	12	1	91.7%
LAX	77.5%	9	2	77.8%	39	7	82.1%	39	7	82.1%
OKC	96.0%	1	0	100.0%	4	0	100.0%	4	0	100.0%
OKJ	79.0%	9	3	66.7%	36	8	77.8%	36	8	77.8%
SAC	73.5%	11	3	72.7%	47	7	85.1%	47	7	85.1%
SAN	77.0%	12	2	83.3%	48	4	91.7%	48	4	91.7%
SAS	85.0%	1	0	100.0%	4	1	75.0%	4	1	75.0%
SJC	87.5%	7	1	85.7%	28	6	78.6%	28	6	78.6%
SLO	62.0%	2	0	100.0%	7	2	71.4%	7	2	71.4%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	35	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
4	99	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
5		3	1	66.7%	3	1	66.7%	4	1	75.0%	4	1	75.0%
6		4	3	25.0%	4	3	25.0%	4	0	100.0%	4	0	100.0%
7		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
8		4	2	50.0%	4	2	50.0%	4	2	50.0%	4	2	50.0%
14		4	2	50.0%	4	2	50.0%	3	1	66.7%	3	1	66.7%
19		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
20		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
21		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
22	693	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
23	76	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
24		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
25		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
26		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
27		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
28		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
40	80	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
41	61	4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
42		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
43		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
48		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
49		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
51		2	1	50.0%	2	1	50.0%	2	0	100.0%	2	0	100.0%
52		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
53		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
54		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
57		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
58		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
59		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
63	25	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
64		4	2	50.0%	4	2	50.0%	4	2	50.0%	4	2	50.0%
65		2	0	100.0%	2	0	100.0%	1	0	100.0%	1	0	100.0%
66		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
68		4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
69		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
71	11	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
72		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
73	18	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
74		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
75		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
76	124	4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
78		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
79		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
80		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
82		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
87		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
88		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
89		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
90		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
97		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
98		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
99		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
101		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
103		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
106		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
107		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
118		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
124		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
135	20	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
136		3	0	100.0%	3	0	100.0%	4	0	100.0%	4	0	100.0%
140	105	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
142		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
143		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
144		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
146		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
147		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
150		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
151		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
152		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
153		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
155		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
156		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
158		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
159		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
160		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
161		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
162		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
163	50	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
164		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
165		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
168		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
178		3	2	33.3%	3	2	33.3%	4	0	100.0%	4	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
179		3	0	100.0%	3	0	100.0%	4	0	100.0%	4	0	100.0%
194		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
195		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
232		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
233		4	3	25.0%	4	3	25.0%	4	2	50.0%	4	2	50.0%
234		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
236		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
237		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
239		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
240		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
241		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
244		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
280		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
281		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
283		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
284		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
290	26	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
291		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
300		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
301		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
302		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
305		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
306	24	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
307		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
311		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
316		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
318		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
319	41	4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
330		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
331		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
332		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
334		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
335		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
336		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
337		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
338		4	2	50.0%	4	2	50.0%	4	2	50.0%	4	2	50.0%
339		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
341		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
342		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
343	11	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
350	25	2	1	50.0%	2	1	50.0%	2	1	50.0%	2	1	50.0%
351		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
352		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
353	39	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
354	37	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
355		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
364		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
365		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
370	55	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
371		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
380	106	4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
381		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
382		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
383	19	4	0	100.0%	4	0	100.0%	4	4	0.0%	4	4	0.0%
390	18	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
391		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
392	31	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
393	36	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
400		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
405		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
450		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
460		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
461		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
463		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
464		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
467		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
488		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
499		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
500		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
502		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
503		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
504		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
505		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
507		4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
508		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
509		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
511		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
516		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
517	Cncld	4	1	75.0%	4	1	75.0%	3	1	66.7%	3	1	66.7%
518	No OS	4	0	100.0%	4	0	100.0%	4	2	50.0%	4	2	50.0%
519	215	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
562		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%
564		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
566		4	2	50.0%	4	2	50.0%	4	0	100.0%	4	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
572		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
573		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
577		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
580		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
581		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
582		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
586		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
587		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
591		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
593		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
595		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
611		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
624		3	0	100.0%	3	0	100.0%	4	0	100.0%	4	0	100.0%
660		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
661		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
662		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
663		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
664		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
665		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
666		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
667		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
669		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
670		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
671		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
672		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
674		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
689		2	2	0.0%	2	2	0.0%	2	0	100.0%	2	0	100.0%
690	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
691	15	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
692	26	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
693	12	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
694		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
695	22	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
696		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
697	20	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
698	15	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
702	55	4	2	50.0%	4	2	50.0%	4	3	25.0%	4	3	25.0%
703		4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
710	208	4	1	75.0%	4	1	75.0%	4	4	0.0%	4	4	0.0%
711		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
712	99	4	1	75.0%	4	1	75.0%	4	3	25.0%	4	3	25.0%
713	36	4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

25-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
714	25	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
715	88	4	4	0.0%	4	4	0.0%	4	3	25.0%	4	3	25.0%
716		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
718		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
719	99	4	2	50.0%	4	2	50.0%	4	1	75.0%	4	1	75.0%
720		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
723		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
724		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
727		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
728		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
729		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
732		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
733	No OS	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
734	17	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%
736		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
737		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
738	Cncld	1	1	0.0%	1	1	0.0%			0.0%			0.0%
741		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
742	20	1	0	100.0%	1	0	100.0%	1	1	0.0%	1	1	0.0%
743		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
744		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
745		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
746		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
747		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
748		1	1	0.0%	1	1	0.0%	1	0	100.0%	1	0	100.0%
749	Cncld	1	1	0.0%	1	1	0.0%			0.0%			0.0%
751		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
761		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
765		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
769		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
770	29	4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
774		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
779		4	0	100.0%	4	0	100.0%	3	0	100.0%	3	0	100.0%
784		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
785		4	0	100.0%	4	0	100.0%	4	0	100.0%	4	0	100.0%
790		4	1	75.0%	4	1	75.0%	4	0	100.0%	4	0	100.0%
794		4	1	75.0%	4	1	75.0%	4	1	75.0%	4	1	75.0%
821		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
822		4	1	75.0%	4	1	75.0%	4	2	50.0%	4	2	50.0%
1333		4	0	100.0%	4	0	100.0%	4	3	25.0%	4	3	25.0%
1340		4	0	100.0%	4	0	100.0%	4	1	75.0%	4	1	75.0%
2174		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%

Amtrak On Time Performance

Trains Arriving Through: 10/4/2025

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2203		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2205		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2216		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2218		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2248		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2249		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2250		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2251		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2252		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2253		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2254		1	0	100.0%	1	0	100.0%	1	0	100.0%	1	0	100.0%
2255	31	1	1	0.0%	1	1	0.0%	1	1	0.0%	1	1	0.0%

Amtrak Endpoint OTP Details

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/4/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
2255	WAS	31	ENG	27	ENG	27	BOS-BOS	AM	Other electrical failure, 2028, AM2255 needed to loop a/c of HVAC system and no water in First Class car. - DMD	
135	WAS	20	ADA	16	CTI	6	BRP-STM	MN	Follow metro north, Milepost w/Letters, bro, stm	
140	SPG	105	ENG	83	ENG	70	HFD-HFD	AM	Cab signal failure, 125, MP36.6 rpts issue trying to clear Cab Penalty Alerter and is unable to proceed. AM140/E125 rpts cutting alerter out.	
163	WAS	50	ENG	37	SMW	14	KIN-WLY	AM	Diversions around M/W work, Other, High Street Interlockin, Waited at High Street Interlocking Limits for AM162 to clear single track operations - DMD	
690	BON	26	DBS	26	DBS	26	ORB-SAO	CS	Debris strike Main res air hose separation, Trash can, Other, West end ORB platform	
691	BRK	15	ADA	6	DMW	6	WOB-HHL	MT	Waiting for MW clearance Control Point, FR	
692	BON	26	DCS	8	DCS	6	POR-ORB	CS	Restrictive signal(s) from unknown cause Stop, Control Point, Cooks	
693	BRK	12	DMW	10	DMW	10	WOB-HHL	MT	Waiting for MW clearance Control Point, FR	
695	BRK	22	RTE	24	RTE	14	WEM-SAO	CS	Inability to contact dispatcher Never received the message that we had to key tone the number two key in addition to 9494 to get a hold of DISPATCHER called the crew CHIEF and was given that information once again no messages from EB about this additional information, Control Point, Wing	
697	BRK	20	PTI	12	PTI	12	WEM-SAO	CS	Meet 698, Control Point, Wells	
698	BON	15	DCS	9	DCS	9	ORB-SAO	CS	Issue with automatic road crossing protection Other, temple ave	
63	TWO	25	ADA	10	SVS	5	ALB-ALB	AM	Planned set out / pick out of locomotives, cars or section of train	
290	NYP	26	DCS	22	DSR	18	BTN-VRN	VR	Per bulletin Milepost, 117.28, 117.17, 15, main, Milepost, 116.5, 116.5, 25, main, Milepost, 111.20, 109.71, 15, main, Milepost, 109.71, 107.0, 25, main, Milepost, 105.68, 104.97, 25, main	
71	CLT	11	ADA	10	ADA	10	CYN-CYN	NS	Mobility Impaired Group of 30 mobility impaired seniors needing assistance. Two needing lift	
73	CLT	18	FTI	8	FTI	8	DNC-BNC	NS	Meet #NSe50, Siding, Funston	
76	RGH	124	TEN	121	TEN	121	CLT-CLT	NS	Traction motor NC1810	

Amtrak Endpoint OTP Details

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/4/2025

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
40	CHI	80	PTI	104	FTI	65	SAV-DNK	CS	Meet 693, Siding, Stillwell
41	MIA	61	TRS	82	TRS	82	WTI-TOL	NS	Trespasser strike Milepost, 365.6, 365.6
23	NOL	76	TRS	77	TRS	77	XNO-XEJ	NS	Bridge strike by a vehicle or boat Waited until clearance and inspection was completed. Received 10 mph at mp 4.7 instructions given by Oliver Tower, Bridge, Marconi road Bridge
733	OAC	No OS Rpt	RTE	2	RTE	2	SAC-DAV	UP	Crossover(s) due to N.A.R. 2 to 1, Control Point, Webster
734	SAC	17	TCC	21	TCC	21	OKJ-OKJ	UP	This Cabs paperwork was almost 1 month old. Cars had door panels off and screws and nuts and bolts on stairs and tables. TASI supervisor said to take 738 equipment. The floors were dusty. Commissary was still doing their thing. TM Gillard has Pics C6963, I sent TM Gillard photos of everything vis
738	SAC	Trn Cancelled							
742	SAC	20	MBO	23	MBO	23	MTZ-SUI	UP	For maritime traffic Bridge open, Control Point, RV033
749	OKJ	Trn Cancelled							
517	PDX	Trn Cancelled							
518	VAC	No OS Rpt	TRS	209	TRS	209	STW-MVW	BN	BNSF 5497 trespasser strike Milepost, 68, 68
519	SEA	215	ENG	100	ENG	100	VAC-VAC	BN	72 dead compressor. Joined Train 516 equipment to outbound 517. Mechanical employees made up 480v and Air hoses. Performed air tests. PTC failed on 90251. We reinitialized PTC, and it failed again. Running without PTC. 72
343	MKE	11	SVS	2	SVS	2	X9L-XWA	ME	PTC - Initializing PTC (no failure) Control Point, Morgan
350	TRM	25	PTI	27	PTI	17	XB0-XA5	MI	Meet 353, Siding, albion
353	CHI	36	DCS	22	SYS	13	ARB-JXN	MI	Copy authority / restriction Milepost, 44, 65
354	TRM	37	TRS	26	TRS	26	ARB-DER	MI	Vehicle on track ahead Milepost, 10.15, 10.15
370	GRR	55	POL	43	POL	43	XTF-XH6	NS	Right of Way police hold
770	SAN	29	CTI	34	CTI	12	OSD-SOL	SN	Follow coaster, 676, Other, osd
702	BFD	55	FTI	34	PTI	17	MDR-FNO	BN	Meet amtrak 713, Control Point, figarden

Amtrak Endpoint OTP Details

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Late Trains For

Region: ALL

Service: ALL

Arriving On: 10/4/2025

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
710	BFD	208	TRS	153	TRS	153	FNO-HNF	BN	Trespasser strike Other, 968.4	
712	BFD	99	FTI	50	FTI	40	MCD-MDR	BN	Meet BNSF 4252, Siding, Kismet	
713	OKJ	36	DCS	19	DCS	19	FNO-MDR	BN	Restrictive signal(s) from known wayside signal failure DS flag pass stop due to broken rail at mp1021.9, stop, Control Point, west madera	
714	BFD	25	DCS	34	DCS	31	MCD-MDR	BN	Held at kismet due to broken rail at 1021.9 Control Point, kismet	
715	OKJ	88	TRS	57	TRS	57	COC-COC	BN	710 had a trespasser strike so dispatch held us at Corcoran station Other, CORCORAN	
719	OKJ	99								
3	LAX	35	FTI	81	PTI	43	LSV-LMY	BN	Meet AMTK # 4, Other, CANONCITO	
4	CHI	99	FTI	107	FTI	40	GLP-XIA	BN	Follow UNKN BNSF E, Milepost, 140.3, 27.5	
22	CHI	693	ENG	432	ENG	158	DAL-DAL	UP	Set out defective locomotive XUP7253	
306	CHI	24	FTI	45	FTI	34	SMT-XTF	CC	Cross Traffic unknown, Control Point, corwith	
380	CHI	106	TEN	42	ENG	25	PCT-MDT	BN	Loading problem ID4607	
383	QCY	19	CTI	15	CTI	10	LAG-NPV	BN	Follow Metra, Control Point, E NPV	
390	CHI	18	DSR	20	PTI	10	CHM-RTL	CC	Meet amt301, Control Point, leverett	
392	CHI	31	PTI	29	PTI	29	KKI-HMW	CC	Meet amtrak 59, Control Point, north peotone	
393	CDL	36	DSR	24	PTI	19	CHM-MAT	CC	Meet 392, Siding, TOLONO	
319	KCY	41	FTI	52	FTI	38	WAR-LEE	UP	Follow Followed then did a saw by, UP8259, Milepost, 238.9, 249.8	

Amtrak Initial Terminal Details

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/4/2025

Terminal	Train	Date	Late	Delay	Cause
CLT	76	10/04	121	121	Traction motor NC1810
HAR	666	10/04	1		
NPN	194	10/04	1	1	Had to get verbal release from FI Dispatcher for orders and not all doors would open (had to walk each car and key open)
PHL	151	10/04	1		
WAS	140	10/04	2	2	Water, commissary, toilet/trash dumping, WAITING FOR COFFEE POT FROM COMMISSARY
WAS	168	10/04	3	3	Other late crew, OUTBOUND CREW 168 WERE BOARDING WHILE MARC TRAIN 688.
BON	693	10/04	2	2	Passenger and/or baggage Elderly
BON	699	10/04	1		
BOS	2255	10/04	27	27	Other electrical failure, 2028, AM2255 needed to loop a/c of HVAC system and no water in First Class car. - DMD
NYP	63	10/04	2	2	Cross Traffic, NJT, NJ7821, Other, NYP-XEE, NJ7821 XING AHEAD AT "A" INT
NYP	103	10/04	3	3	Door, 43367, DOOR LIGHT IN CAFE CAR
NYP	233	10/04	3	3	Cross Traffic, NJT, NJ7837, Other, NYP-NYP
NYP	239	10/04	1		
NYP	241	10/04	1		
NYP	245	10/04	2	2	Passenger and/or baggage, LOADING
CHI	41	10/04	4	4	Cab signals were not signed off as being cut out. Mechanical had to walk and complete the paoer 314
CHI	350	10/04	1		
QCY	380	10/04	18	18	Loading problem Lost HEP as well as dropped load, ID4607
SEA	8	10/04	40	5	Toilet Car removed due to leak/smell, 32019
SEA	8	10/04	40	30	Injured or sick passenger Patricia Kandle, 82F8FA, removed by paramedics due to injury suffered prior to Amtrak property.
SEA	8	10/04	40	5	Downgraded passengers due to defective car not informed in advance
TRM	353	10/04	3		
BFD	703	10/04	8	8	Service, turn, or wye train 712, Waiting for late Amtrak train 712 and train preparation.
BFD	715	10/04	19	19	703 late in to BFD we use there equipment to turn as 715 703
BFD	719	10/04	103		

Amtrak Initial Terminal Details

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Late Trains For:

Region: ALL

Division: ALL

Data Through: 10/4/2025

Terminal	Train	Date	Late	Delay	Cause
EMY	6	10/04	24	24	Meet Freight train was delayed due to container door that ripped a mirror off AMTK 720, dispatcher had all trains stopped until freight train cleared there track. We stayed at Emeryville station until we got a signal to move., UP 9833, Control Point, E.Emeryville
LAX	14	10/04	7	7	Wheelchair Pax brought to train via redcap close to departure time. Then had difficulty with his wheelchair.
LAX	562	10/04	1		
OKJ	714	10/04	18	18	Water, commissary, toilet/trash dumping
OKJ	734	10/04	21	21	This Cabs paperwork was almost 1 month old. Cars had door panels off and screws and nuts and bolts on stairs and tables. TASI supervisor said to take 738 equipment. The floors were dusty. Commissary was still doing their thing. TM Gillard has Pics C6963, I sent TM Gillard photos of everything vis
OKJ	738	10/04	(Trn Cxld)		engine failure
SAC	702	10/04	1	1	Passenger and/or baggage Late arriving passengers
SAC	745	10/04	1	1	Passenger and/or baggage Older lady running to the train
SAC	749	10/04	(Trn Cxld)		engine failure
SAN	765	10/04	1		
SAN	769	10/04	1		
SJC	748	10/04	2	2	Meet cal train, Other, sjc
VAC	517	10/04	(Trn Cxld)		Locomotive Failure
VAC	519	10/04	100	100	72 dead compressor. Joined Train 516 equipment to outbound 517. Mechanical employees made up 480v and Air hoses. Performed air tests. PTC failed on 90251. We reinitialized PTC, and it failed again. Running without PTC. 72

Eastern Region

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.5	94.8	165	0
CDOT	95.0	100.0	98.7	92.4	16	0
MARC	95.0	100.0	95.2	83.5	18	0
SEPTA	95.0	92.0	96.6	91.5	100	8
NJT-NED	95.0	95.9	93.4	93.8	194	8
NJT-SED	95.0	100.0	98.9	97.2	20	0

Operating Highlights

Train 19(03) - South of Tuscaloosa, AL - Passenger Train Interference

04OCT25: Train 19(03) was delayed on the Norfolk Southern AGS South Subdivision at MP 230.3 due to meeting Train 20(04). Train 19(03) was diverted to the siding at CP McClure/MP 230.

Train	Delay	Comment
19(03)	38"	

Train 140(04) - Hartford, CT - Engine Failure

04OCT25: Train 140(04) was delayed at Hartford Station/MP 36.7 due to E/125 being stuck in cap signal penalty. The crew was initially unable to clear the cab signal penalty alerter alarm. After consulting with CNOC Mechanical, the crew cut out the alerter.

Train	Delay	Comment
140(04)	1'10"	

Train 76(04) - Charlotte, NC - Third Party Contractor Engine Failure

04OCT25: Train 76(04) was delayed at its initial terminal at Charlotte due to cutting out failed engine NC1810, then having to wye so E/1755 could be in the lead.

Train	Delay	Comment
76(04)	2'01"	

Train 52(04) - North of DeLand, FL - Vehicle Strike

04OCT25: At approximately 4:45 PM, Train 52(04) operating with E/358-E/334-38 Cars, struck an unoccupied vehicle 7 miles north of DeLand, FL/MP743.2 on the CSX Sanford Subdivision, at MP743.710 near De Leon Springs in Volusia County. The strike occurred at a private road crossing, at Lake Woodruff Wildlife Preservation (NATLREFUGE D) equipped with 2 crossbucks, 2 stop signs and an ENS sign, DOT #621289F. There were no injuries to the crew or 265 passengers onboard. Head end power was on for the duration. The weather was reported 75 degrees and cloudy. The vehicle occupant exited the vehicle prior to impact and was not injured. There was no damage reported to the engines. The crew did not request trauma relief on the scene. At 6:20PM, the police released the scene and Train 52(04) was back on the move north.

National Response Center Number: 1444626

Train	Delay	Comment
52(04)	2'09"	

Train 66(03) West of Old Saybrook, CT - Deer Strike

04OCT25: Train 66(03) operating with engine 640, 5 cars, and 200 passengers onboard struck a deer 18 miles west of Old Saybrook, CT station on the Amtrak NHB Line at milepost 87.5. The train stopped at MP85 where the crew inspected their equipment, reported no exceptions, then was able to continue east.

Train	Delay	Comment
66(03)	05"	

Train 23(04) East of New Orleans, LA - Bridge Strike

04OCT25: Train 23(04) was delayed at Paris Rd/MP5.9 on the NSRR New Orleans Terminal Subdivision, 6 miles east of New Orleans, LA due to a reported bridge strike at Marconi Road Bridge. Once engineering arrived and inspected the bridge, Train 23(04) was able to proceed by bridge at 10MPH, then continued to New Orleans station.

Train	Delay	Comment
23(04)	1'17"	

Train 41(03) East of Pittsburgh, PA - Engine Failure

04OCT25: Train 41(03) E/157, E/306 ,11 cars, was delayed 3 miles east of Pittsburgh, PA at MP328 on the CSX P&W Subdivision due to reporting issues with trail engine E/306. Pittsburgh mechanical was dispatched to train to troubleshoot. Engine E/306 had internal battery faults and was unable to be rectified. Train 41(03) proceeded east with power only from the Lead engine E/157 causing additional lost time. At Washington, the two engines were replaced with triple engines E/328, E/45 and E/307.

Train	Delay	Comment
41(03)	41"	
41(03)	30"	WAS - swapping engines
41(03)	14"	PGH-WAS

PW Line - Bush River Bridge Opening

04OCT25: All train traffic was severely delayed due to scheduled opening of the Bush River Bridge/MP 71.6 for marine traffic. Multiple Trains were delayed. Once the bridge was closed, all traffic was able to proceed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
98 (03)	24"	
54 (04)	28"	
89 (04)	18"	
2248 (04)	06"	

Train 82(04) South of Petersburg, VA - Freight Train Interference

04OCT25: Train 82(04) was delayed at BX/MP25.8 on the CSX South End Subdivision, 3.8 miles south of Petersburg, VA due to meeting freight unit I136.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
82 (04)	37"	

Train 690(04) Old Orchard Beach, ME - Debris Strike

04OCT25: Train 690(04), BC/90406, 4 cars, E/119, struck a trash can in the guage at Old Orchard Beach, ME/MP22.5 on the CSX Portland Subdivision. The train was stopped at MP22.5 for the crew to inspect and found a main reservoir air hose was disconnected. Once crew reconnected the hose, Train 690(04) was able to proceed south.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
690 (04)	26"	

Maintenance of Way Highlights

Metro North NHV Line - Weekend Outages

25-EO 40723 8000900746 "UNCLASSIFIED" 10/13/2025

25SEP25: Metro North Railroad has trackwork scheduled this weekend on their NHV Line. No.3trk CP217 to CP223 Saturday(04) 12:50A to 4P. No.1trk CP217 to CP223 Sunday 10A to 2P Catenary inspection. No.1 & 2trks Cp266 to Cp272 Replace ties and Rail. Friday(03) 11P to 6P Sunday(05). Rule 22 on 3 & 4trks

Sunday(05) on Overnight 12A to 5A Monday(06) in New Haven CP272 to CP273(including Cp272) 3,5 & R tracks for Church St. Bridge inspectors. No Access to Motor Storage.

Amtrak Post Road Branch North of Albany-Rensselaer, NY - Track Repairs

02JUN25: Train 448(01) was terminated at Albany due to track structure issues three miles north of Albany on the Amtrak Post Road Branch at MP 196.2. Buses were secured for all passengers between Albany and Boston. Train 449(02) was not effected due to being cancelled for trackwork already. Additionally, due to the issue and unknown time for repairs, trains 448(02-09JUN) and 449(02-09JUN) were cancelled between Albany and Boston with alternate bus transportation with the exceptions of stops of Framingham and Back Bay.

18JUN25: The trackwork is now extended through Sunday, July 27th. As a result, the following service adjustments are in place:

- Train 448(02JUN-26JUL) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-28JUL) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(20Jun, 27Jun, 3Jul, 11Jul, 18Jul, 25Jul) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(22Jun, 29Jun, 6Jul, 13Jul, 20Jul, 27Jul) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

24JUL25: The trackwork is now extended through Sunday, November 30th. As a result, the following service adjustments are in place:

- Train 448(02JUN-30Nov) will terminate at Albany with Bus#3448 providing alternate making all stops except Framingham and Boston Back Back.
- Train 449(02JUN-30Nov) will originate at Albany with Bus#3449 providing alternate making all stops except Boston Back Bay and Framingham.
- Train 1237(25Jul, 1Aug, 8Aug, 15Aug, 22Aug, 29Aug, 5Sep) will terminate at Albany with Bus #3237 providing alternate between Albany and Pittsfield.
- Train 1233(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will terminate at Albany with Bus# 3233 providing alternate between Albany and Pittsfield.
- Train 1246(27Jul, 3Aug, 10Aug, 17Aug, 24Aug, 1Sep, 7Sep) will originate at Albany with Bus# 3246 providing alternate between Pittsfield and Albany.

*Note: Due to Labor Day, Berkshire Flyer Trains 1233 and 1246 are not operating on Sunday August 31st, but will operate on Monday September 1st.

WBS#: B.TR.100150.5746

CSX Albany Division - Trackwork

12MAY25: CSX Albany Division / Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivisions. On Monday May 12, 2025 to Friday October 10, 2025 between Niagara Falls to Albany on various locations between MP QC 168 to MP QC 436 for Rail, Tie, Curve Patch and Surfacing Gangs.

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(12May-10Oct) will depart NFL 10-minutes EARLIER, at 3:42am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 284(12May-10Oct) will depart NFL 10-minutes EARLIER, at 6:37am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.
- Train 64(12May-10Oct) will depart NFL 10-minutes EARLIER, at 11:40am, have miscellaneous adjustments between ROC and AMS, and return to their normal schedule at SDY.

Westbound

- Train 281(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 7:45pm.
- Train 283(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF and arrive at NFL 10-minutes LATER, at 10:38pm.
- Train 63(12May-10Oct) will have miscellaneous adjustments to add time between AMS and BUF, will arrive at NFL 10-minutes LATER, at 4:52pm, will depart NFL 10-minutes LATER, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100151.0742

Eastern Region

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Seats	Number Operated Cars	Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 87(04) Passenger Removal at Washington, D.C. – Medical***

04OCT25, Passenger on PNR AF2347, traveling from Baltimore (Penn), MD to Washington, D.C. was removed by Amtrak Police at Washington, D.C. due to not feeling well. Amtrak Police notified.

Delay: 87 (04) None

Train 19(04) Passenger Removal at High Point, North Carolina – Improper Conduct

04OCT25, Both passengers were removed by the local police at High Point, NC due to smoking on the train. Amtrak Police notified.

Passenger on PNR ABA23D, traveling from Trenton, NJ to Charlotte, NC.

Passenger on PNR A98152, traveling from Wilmington, DE to Birmingham, AL.

Delay: 19 (04) 08"

Western Region

Operating Highlights

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train 306(04) North of Summit, IL - Freight Train Interference

05OCT25: Train 306(04) was delayed at Corwith crossing/MP6.6 5 miles north of Summit, IL/MP11.8 on the CN Joliet subdivision meeting freight. Once the route was clear, train 306(04) continued north into Chicago, IL/MP0.0.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
306(04)	34"	

Train 719(04) East of Antioch-Pittsburg, CA - Struck All Terrain Vehicle

05OCT25: Train 719(04) struck an unoccupied all terrain vehicle that was left in the foul while entering Antioch-Pittsburg Station, CA/MP1152.0 on the BNSF Stockton subdivision. There were no reported injuries among the passengers or crew, and there was no reported damage to the equipment. The owner of the ATV quickly climbed on and drove away. Once the BNSF dispatcher confirmed the report from the crew, train 719(04) departed Antioch-Pittsburgh, CA.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
719(04)	10"	

Train 22(03)/422(01) South of Chicago, IL - Freight Train Interference

05OCT25: Train 22(03)/422(01) was delayed at Brighton crossing/MP5.1 5 miles 5 south of Chicago Union Station, IL/MP0.0 on the CN Joliet subdivision meeting BNSF freight cross traffic. Once the route was clear, train 22(03)/422(01) continued into Chicago Union Station, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(03)/422(01)	38"	

Train 22(03)/422(01) South of Springfield, IL - Passenger Train Interference

05OCT25: Train 22(03)/422(01) was delayed at Auburn siding/MP200.1 15 miles south of Springfield, IL/MP185.1 on the UP Springfield subdivision meeting Amtrak train 305(04). Once the route was clear, train 22(03)/422(01) continued north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(03)/422(01)	38"	

Train 518(04) North of Stanwood, WA - Freight Train Interference

04OCT25: Train 518(04) was delayed north of Stanwood, WA (STW) at MP 57.8 pm the Burlington Northern Santa Fe Railway Bellingham Subdivision. A BNSF Freight train, H-VBTABN1-04A (BNSF/5497), was involved in a trespasser incident and tracks ahead were closed while authorities responded to and investigated the scene. Once the scene was released train 518(04) was able to resume operation.

Train 519(04) was also delayed until the route opened.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
518(04)	3'29"	
519(04)	1'40"	

Train 11(04) Eugene, OR - Freight Train Interference

04OCT25: Train 11(04) was delayed south of Eugene, OR (EUG) at CP Fields on the Union Pacific Railway Cascade Subdivision. a freight train, MPDRVB-03 (UP/5554), was stopped blocking the track ahead with a failed mid-train distributed power unit (DPU) locomotive. Technicians from Union Pacific mechanical responded to assist the freight crew in resolving the issue so the freight could climb the grade at CP Cascade Summit and clear into a siding track ahead. Once the track ahead was clear, train 11(04) was able to proceed south.

Train	Delay	Comment
11(04)	1'21"	

Train 8(04) Seattle, WA - Injured or Sick Passenger or Employee

04OCT25: Train 8(04) was delayed departing the initial terminal of Seattle, WA (SEA) on the Burlington Northern Santa Fe Railway Scenic Subdivision. Paramedics were called to assist a passenger who was having issues with a medical problem. Once the issue was resolved train 8(04) departed Seattle, WA at 5:35 PM-PT.

Train	Delay	Comment
8(04)	40"	

Train 8/28(03) East of Glasgow, MT - Freight Train Interference

04OCT25: Train 8/28(03) was delayed between Whatley siding/MP272.8 and Nashua siding/MP264.4 on the BNSF Glasgow subdivision meeting multiple BNSF freights., BN/7542 and BN/4415. Once the route was clear, train 8/28(03) continued east.

Train	Delay	Comment
8/28(03)	30"	

Train 22(04) West of Mineola, TX - Signal

04OCT25: Train 22(04) was delayed at Ash Lane/MP166.31 33 miles west of Mineola, TX/MP136.1 on the UP Mineola subdivision due to a problem with the automatic road crossing protection system. Train 22(04) was ordered to stop while damage to the crossing gate was assessed. Once clear of the affected area, train 22(04) continued east.

Train	Delay	Comment
22(04)	33"	

Train 702(04) Madera, CA - M of W Work

04OCT25: Train 702(04) was delayed at Madera, CA (MDR) on the Burlington Northern Santa Fe Railway Stockton Subdivision. There was a report of broken rail between Madera, CA (MDR) and Fresno, CA (FNO) at MP 1021.9. Trains were required to obtain verbal authority from the train dispatcher to pass the signals and then obtain verbal authority from the Track Foreman to operate over the broken section of rail at reduced speeds. Once clear of the affected area train 702(04) was able to resume operation at maximum authorised track speeds.

Train	Delay	Comment
702(04)	38"	
713(04)	19"	
712(04)	40"	Kismet Siding wait for BNSF/4254 to clear the affected area
710(04)	13"	
712(04)	19"	Broken Rail

Train 370(04) East of Chicago, IL - Police Related

04OCT25: Train 370(04) delayed behind Amtrak train 41(04) 16.0 miles east of Chicago, IL/MP0.0 on the NS Chicago subdivision due to a hold put on rail traffic while police investigated reports of trespassers on a freight ahead. Once the route was clear, train 370(04) continued east.

Train 41(04) was delayed behind Amtrak train 370(04) waiting for the route to open. Train 41(04) was further delayed following train 370(04) to Porter, IN/MP482.0.

Train	Delay	Comment
370(04)	43"	
41(04)	35"	POL holding for open route
41(04)	20"	PTI follow 370(04) to Porter

Train 710(04) West of Hanford, CA - Trespasser Incident

04OCT25: At approximately 1:13 PM-PT train 710(04) - operating with camera equipped cab car CC/8314, six (6) additional cars, and locomotive CDTX/2107 pushing - struck and fatally injured a trespasser at MP 967.7 on the Burlington Northern Santa Fe Railway Bakersfield Subdivision in the city of Hanford, Kings County, California. This incident did NOT occur on a public highway crossing at grade. Train 710(04) was operating east at an estimated 26 MPH on main track one with a posted track speed of 79 MPH. Tracks were closed in both directions while local authorities investigated the incident. Hanford police and fire along with Amtrak Police and Management responded to the scene. Once the investigation was complete and scene released by authorities at 3:33 PM-PT; train 710(04) advanced to Hanford, CA where it held for a relief crew. Once the relief crew arrived, train 710(04) departed Hanford, CA and resumed travel east at 4:02 PM-PT.

National Response Center: 1444629

California Office of Emergency Service: 25-5066

Google Maps Location of Incident:

<https://maps.app.goo.gl/bs3C522hXNm7DWGM7>

36.332944, -119.655922

Hanford, California 93230

WBS#: B.TR.100150.6155

National Response Center Number: 1444629

Train	Delay	Comment
710(04)	2'33"	Trespasser Strike
715(04)	57"	COC - Hold for route
710(04)	23"	HNF - Recrew
712(04)	34"	FNO - Hold for route
703(04)	08"	ITD - BFD - Late inbound equipment from 712(04)
719(04)	1'43"	ITD - BFD - Late inbound equipment from 710(04)

Train 22(04) North of Mineola, TX - Police Related

04OCT25: Train 22(04) was delayed at South Tyler St/MP113.0 23 miles north of Mineola, TX/MP136.1 on the UP Mineola subdivision due to a trespasser reportedly walking along the tracks around mile post 108.0. Once the route was opened for train traffic, train 22(04) continued north.

Train	Delay	Comment
22(04)	44"	

Train 319(04) South of Pontiac, IL - Debris

04OCT25: At 11:46AM-CT, Train 319(04), E/C14631 and 5 Cars, went into emergency 10.2 miles south of Pontiac, IL/MP92.1, on the UPRR Joliet Subdivision, after striking unknown debris when crossing over the Chenoa Diamond at MP102.3. The Conductor reported this caused them to lose the backup hose on E/ID4631. No injuries were reported to the crew or 208 passengers onboard. No damage to the equipment. Once the inspection was complete and air restored, Train 319(04) was back on the move south at 11:55AM-CT.

Train	Delay	Comment
319(04)	11"	

Train 21/421(03) Longview, TX - Freight Train Interference

04OCT25: Train 21/421(03) was delayed at Longview, TX/MP89.5, on the UPRR Little Rock Subdivision, from freight interference. MASAR-02 / UP5401 was setting out an engine at Gladewater/MP105.5. Once this was complete, MASAR-02 was on the move to clear into the Mineola siding. Train 21/421(03) had to follow UP7677, UP2666, and UP7640 until they were able to get by at Big Sandy/MP114.5.

Train	Delay	Comment
21/421(03)	1'06"	

Train 723(04) East of Richmond, CA - Struck Container Door

04OCT25: At approximately 7:15 AM-PT, Train 723(04), E/C2123-4 Cars, reported having their engineer side mirror ripped off by an open door on a container while operating by Union Pacific INPOA-01 /UP9833 at MP14.61. Located 5.6 miles east of Richmond, CA/MP20.2 on the UPRR Martinez Subdivision. This incident occurred in the city of Richmond, Contra Costa County, California. Train 723(04) was operating westbound at 60 MPH on main track two with a posted track speed of 60 MPH. No delay was incurred by 723(04). Trains 710(04) and 720(04) were delayed operating reduced speeds by INPOA-01. Train 727(04) had to follow the freight from MP12 to MP4.5.

Train 6(04) was delayed departing Emeryville, CA/MP4.5, on the UPRR Martinez Subdivision, waiting for the INPOA-01 to clear.

National Response Center: 1444595
California Office of Emergency Services: 25-5061

National Response Center Number: 1444595

Train	Delay	Comment
723(04)	No Delay	
6(04)	24"	
710(03)	02"	
720(04)	19"	
727(04)	13"	

Trains 517(04) and 506(04) Cancelled - Engine Failure

04OCT25: Train 517(04), E/ID4607-4 Cars, was cancelled in its entirety in Vancouver, BC/MP156.3, on the CNRR New Westminster Subdivision, from E/72 experiencing air compressor failure. There was no head end power during this time but the train was still at the station with 128 passengers onboard. The outside temperature was 50 degrees and cloudy. The crew contacted Seattle and CNOC mechanical to troubleshoot but efforts were unsuccessful. Attempts to source a freight unit were also unsuccessful. Three buses were secured arriving to Vancouver at 9:00AM-PT and departing by 9:58AM-PT to bring the passengers drop-off only to Seattle. One bus was secured at Bellingham making all stops to Seattle. Between Seattle and Portland, three buses were secured. Train 519(04) double drafted back to Seattle with 517(04)'s equipment.

Train 506(04) was also cancelled in its entirety due to no available equipment with three alternate buses secured.

Train 519(04) was delayed departing the initial terminal of Vancouver, BC (VAC) while the crew worked to combine the two sets of equipment to tow the disabled train to Seattle, WA for repair.

WBS#: B.TR.100150.6154

Train	Delay	Comment
517(04)	Cancelled	
506(04)	Cancelled	
519(04)	1'40"	Couple to disabled 517 equipt and PTC issues

Train 380(04) Quincy, IL - Engine Failure

04OCT25: Train 380(04), E/ID4607-4 Cars, was delayed departing Quincy, IL/MP258.6, on the BNSF Brookfield Subdivision, from engine issues. The crew reported that while deadheading the equipment from the yard to the station they experienced head end power loss and loading issues. They recycled the engine which resolved the issue and finished the move to station. At 6:30AM, Train 380(04) departed Quincy operating 18 minutes late. Additional delay was incurred at Kewanee, IL/MP131.1, on the BNSF Mendota Subdivision, to troubleshoot with mechanical after reported head end power and load was intermittent while in route. Upon entrance to the Kewanee station, E/ID4607 lost all load. There were 114 passengers onboard with the outside temperature 69 degrees and sunny. After recycling the engine, E/ID4607 was back to working as intended.

This same issue occurred a few more times while in route. Train 380(04) stopped 0.4 miles east of the Princeton, IL station/MP104.3 at MP103.9 and then again at the Plano, IL station/MP51.7. Each time the crew recycled the engine to get E/ID4607 to load as intended. Upon arrival to Chicago, E/ID4607 was shopped for repair.

Train	Delay	Comment
380(04)	18"	ITD QCY
380(04)	24"	KEE
380(04)	25"	E/PCT
380(04)	16"	PLO

Train 22(03)/422(01) South of Texarkana, AR - Passenger Train Interference

04OCT25: Train 22(03)/422(01) held 6.8 miles south of Texarkana, AR/MP0.0, on the UPRR Little Rock Subdivision, at Sulphur/MP6.8 meeting Train 21/421(03).

Train	Delay	Comment
22(03)/422(01)	50"	

Train 6(03) East of Glenwood Springs, CO - Debris

04OCT25: At 2:39PM-MT, Train 6(03) operating with E/205-E/182-E/377-8 Cars, reported striking a rock 40.3 miles east of Glenwood Springs, CO/MP360.1, on the UPRR Glenwood Springs Subdivision, on a single main track at MP144.63. As a result of the strike, the main reservoir valve on E/205 was damaged causing the main reservoir to not hold or build. The rock was reported 1.5x2 feet in diameter and was broken into pieces after striking. There were no injuries reported to the crew or 172 passengers onboard. Head end power was on for the duration. The Union Pacific Track Inspector responded to the location arriving at 4:00PM-MT. At 4:44PM-MT train 6(03) held at Dell siding/MP142.0 meeting Amtrak train 1005(03). Before shoving out of Dell siding, train 6(03) set out lead engine 205 at mile post 142,4.

Train 6(03) was further delayed at Fraser, CO waiting for a recrew.

Train 6(03) was delayed at Denver, CO. as crews worked to add UP freight UP/5859. The freight engine was declined after the crew encountered air issues and then managed to resolve the PTC issue on lead engine 182.

Due to the late operation of train 6(03) the following service recovery was put into effect:

- First class passenger meals were unaffected.
- Snack packs and water were distributed to all passengers.
- Lounge car offered coffee, tea, and juice as well as discounted and comp items as needed.
- Breakfast snack items were sent to Denver, CO Station for AM service.

WBS#: B.TR.100150.6156

Train	Delay	Comment
6(03)	3'13"	
6(03)	1'57"	Recrew

Oakland, CA - Capitol Corridor/San Joaquin Services - Third Party Contractor Engine Failure

23AUG25: Account on-going high shop counts for locomotives of state-support trains in Oakland, the following modifications to service have occurred:

23AUG25:

-Train 714(23) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

24AUG25:

-Train 711(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 716(24) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

25AUG25:

-Train 715(25) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

-Train 534(25) cancelled - passengers accommodated on later departure of train 534(27).

-Train 549(25) cancelled - passengers accommodated on later departure of train 549(27).

-Train 716(25) locomotive change at OMF, remove CDTX/2101 add CDTX/2123 (pulled from train 534(25))

26AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 535(26) Operating with CDTX/2007 Providing Head End Power , BNSF/4357 Providing tractive effort;

Delayed west of Sacramento when BNSF/4357 shut down after overspeed warning - PCS and Speedometer not synced.

- Train 535(26) Terminated in Emeryville for locomotives to be added to train 716(26).

transport to Emeryville.

- Train 534(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 549(26) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

27AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 715(27) operate with CDTX/2007 providing HEP and BNSF/4357 providing tractive effort.

- Train 714 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 717 (27) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 716(27) Originates Emeryville - Extended Servicing from train 711(27).

28AUG25:

Delays and short notice cancellations persist with a shortage of serviceable locomotives available in Oakland.

- Train 534(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 549(28) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 547(28) 27 Mins late departing Sacramento - Equipment Turn from 536(28) after cancellation of 534(28).

- Train 711(28) was terminated at Emeryville, CA. to turn for an on time 714(28) out of Jack London Square, Oakland, CA.

- Train 712(28) Cancelled after dynamic brake failure on locomotive CDTX/2103.

- Train 717(28) Cancelled - equipment turn from 712(28) (after manipulations)

- Train 714(28) 1 Hour 59 Mins delay while techs resolve compressed air issues with cab car AMTK/90278

- Train 716(30) 30 mins late departing Oakland Jack London - Extended servicing in Oakland Maintenance Facility

- Train 718(30) Originates Emeryville - Techs after replacing door seal on Cab Car CDTX/8305 unable to get 'trainline complete' indication or interior lights - swapped equipment with original 712(30)

29AUG25: Normal Service Operates with No Cancellations

01SEP25:

- Train 714(01) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 711(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

02SEP25:

- Train 714(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 717(02) Cancelled - Shortage of serviceable locomotives in Oakland Maintenance Facility.

- Train 534(02) Delayed Departing Oakland Jack London - Locomotive Compressed Air

- Train 718(02) Delayed Departing Oakland Jack London - Locomotive Wouldn't Start

03SEP25: Following discussions with Amtrak Transportation, Transit America (TASI) and our California State Partners; it has been determined that a temporary reduction in Capitol Corridor and San Joaquins service is essential to perform necessary inspections, maintenance and repairs on the California state owned locomotives.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 20SEP.

- 714 (03-19SEP) CANCELLED

- 717 (03-19SEP) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 20SEP.

- 520 (04-19SEP) CANCELLED

- 534 (04-19SEP) CANCELLED

03SEP25:

- Train 712(03) Cancelled - failure of locomotive CDTX 2101 (oil leak).
- Train 711(04) Cancelled - failure of locomotive CDTX 2101 (oil leak).

04SEP25:

26-FOI-00028 00000004749 "UNCLASSIFIED" 10/13/2025

- Train 718(04) Originate EMY - CDTX 2101 & CDTX Failure. -Late operation.
- Train 715(04) Terminate EMY to turn for 718(04).

05SEP25:

- Train 712(05) Cancelled - failure of locomotive CDTX/2106, passengers to 716(05).
- Train 703(05) Cancelled - passengers to earlier train 719(05).
- Train 540(05) Cancelled - passengers to train 542(02).

06SEP25:

- Train 738(06) Cancelled
- Train 745(06) Cancelled

08SEP25: The temporary reduction in Capitol Corridor and San Joaquins service has now been extended though October 4.

San Joaquin cancellations effective Wednesday 03SEP, service will resume on Saturday 04OCT.

- 714 (03SEP-03OCT) CANCELLED
- 717 (03SEP-03OCT) CANCELLED

Capitol Corridor cancellations effective Thursday 04SEP, service will resume on Saturday 04OCT.

- 520 (04SEP-03OCT) CANCELLED
- 534 (04SEP-03OCT) CANCELLED
- 535 (04SEP-03OCT) CANCELLED
- 549 (04SEP-03OCT) CANCELLED.

15SEP25:

To streamline departures and provide a stable service for passengers: Effective 15th September 2025.

Train #547 retimed to depart Sacramento 52 minutes later than advertised at 5:55PM-PT operating 52 mins later throughout to San Jose,.

Train #715 retimed to depart Bakersfield 01 hour later than advertised at 1:12PM-PT operating 52 mins later throughout to Oakland.

These changes will remain thru Saturday 4th October 2025

15SEP25: Train 716(15) Locomotive failed at OKJ. Train returned to OMF and new equipment was sourced. Train originate EMY, pax to train 536(15) OKJ-EMY.

03OCT25: Restoration of service planned to be phased in over the weekend of October 3rd as follows:

- 714(04OCT) will operate as planned.
- 717(04OCT) will remain cancelled with resumption scheduled for 717(05OCT) to allow for equipment to be positioned to BFD.
- 715(04OCT) will remain operating on the modified schedule with resumption of normal schedule with train 715(05OCT).
- 520/534/535/549 (06OCT) will be resumed on Monday, October 6th, 2025.

04OCT25: Train 734(04) incurred delays at Oakland Yard after crew discovered train was not serviced or ready to depart. To minimize delays there was an equipment swap with train 734(04) using equipment scheduled for train 738(04). Additionally train 738(04) and 749(04) were cancelled with passengers accommodated on later departures account the on-going equipment issues.

Cause: Pending

WBS#: B.TR.100150.6069

Train	Delay	Comment
-------	-------	---------

714 (23)	32"	OKJ - delay departing OMF
714 (23)	21"	Operating at reduced speeds account freight locomotive
716 (23)	25"	Follow 714 (23)
711 (24)	Terminate EMI	Pax to Bus 5011 "UNCLASSIFIED" EMY-OKJ SFC
716 (24)	26"	Operating at reduced speeds account freight locomotive.
711 (24)	32"	Reduced operating speeds account freight locomotive
715 (25)	27"	W. FNO - PTC Issue on freight loco
534 (25)	CANCELLED	Pax to 536 (25)
549 (25)	CANCELLED	Pax to 551 (25)
716 (25)	1'03"	Loco change at OMF
715 (25)	23"	Operate with freight locomotive
715 (25)	17"	SKN - Freight loco air compressor issue
535 (26)	41"	West Sac - Recovery from BNSF/4357 Penalty Brake
534 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
716 (26)	1'57"	Originates Emeryville - Receiving CDTX/2007 and BNSF/4357 from 535 (26)
535 (26)	Terminates Emeryville	Oakland Passengers to 537 (26)
549 (26)	Cancelled	OMF - Shortage of Serviceable Locomotives
545 (26)	11"	SAC - Short turn of 536 (26) after 534 (26) cancelled
716 (26)	43"	Restricted not to exceed 65 mph with BNSF/4357
714 (27)	Cancelled	
717 (27)	Cancelled	
716 (27)	Originates Emeryville	Passengers to 534 (27)
715 (27)	524"	Restricted not to exceed 65 mph with BNSF/4357
715 (27)	28"	Oakley - BNSF/4357 - Penalty Brake Application Overspeed
534 (28)	Cancelled	
549 (28)	Cancelled	
711 (28)	Term EMY	
712 (28)	Cancelled	Dynamic Brake Failure
717 (28)	Cancelled	Cancellation of 712 (28))
714 (28)	1'59"	OKJ - Techs Resolve Compressed Air Issues
716 (28)	30"	OKJ - Extended Servicing Oakland Maintenance Facility
718 (28)	1'48"	EMY - Swapped Equipment after failed door seal replacement -Originates EMY
547 (28)	27"	SAC - Equipment Turn From 536 (28) after 534 (28) cancelled
714 (02SEP)	Cancelled	
717 (02SEP)	Cancelled	
714 (01SEP)	Cancelled	
711 (02SEP)	Cancelled	
718 (02SEP)	31"	OKJ - Locomotive CDTX/2103 would not start
534 (02SEP)	40"	OKJ - Locomotive Compressed air Issues
712 (03SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
711 (04SEP)	Cancelled	OKJ - Loco CDTX 2101 failure - oil leak
718 (04SEP)	2'09"	originate EMY
715 (04SEP)		Terminate EMY
712 (05SEP)	CANCELLED	Passengers to 716 (05SEP)
703 (05SEP)	CANCELLED	Passengers to earlier 719 (05SEP)
540 (05SEP)	CANCELLED	Passengers to 542 (05SEP)
716 (05SEP)	1'15"	OKJ - late departure
738 (06SEP)	CANCELLED	
745 (06SEP)	CANCELLED	
549 (04SEP-03OCT)	Cancelled	
535 (04SEP-03OCT)	Cancelled	
534 (04SEP-03OCT)	Cancelled	
520 (04SEP-03OCT)	Cancelled	
717 (03SEP-03OCT)	Cancelled	
714 (03SEP-03OCT)	Cancelled	
547 (08SEP)	36"	SAC - ITD - Equipment from 536 (08)
715 (09SEP)	1'21"	BFD - ITD - Equipt from 702 (09)
547 (09SEP)	13"	SAC - ITD - Equipt from 536 (09)
715 (10SEP)	47"	BFD - ITD - Equipt from 702 (10)
547 (10SEP)	25"	SAC - ITD - Equipment from 536 (10)
715 (11SEP)	1'15"	BFD - Equipment Turn From 702 (11)
547 (11SEP)	21"	SAC - ITD - Equipment from 536 (11)

Train	Delay	Comment
716 (15SEP)	1'49"	Loco Failed
715 (16SEP)	16"	BFD- ITD - Equipment Turn from 702 (16)
717 (04OCT)	CANCELLED	Allow for equipment to rotate to BFD with resumption
	26-FOI-00028 00000004749	of train 714 (03OCT)
734 (04OCT)	21"	Unplanned equipment change
738 (04)	Cancelled	Passengers to later train 742 (04)
749 (04)	Cancelled	Passengers to later train 751 (04)

Maintenance of Way Highlights

CN Yazoo Subdivision Track Work - City of New Orleans

26-FOT-99028 90000014749 "UNCLASSIFIED" 10/13/2025

05OCT25: CN will have multiple work gangs on the CN Yazoo Subdivision, between Memphis, TN and Jackson, MS, working 5-hour work windows beginning Monday October 6th through Thursday October 9th. To accommodate this work, City of New Orleans Service adjusted as follows:

- Train 1059(05) will operate in lieu of Train 59(05), departing Chicago, IL, 2 hours earlier at 605PM-CT and will operate on an adjusted schedule to New Orleans.
- Train 59(06-08) will depart Chicago 2 hours earlier at 605PM-CT and operate on an adjusted schedule to New Orleans.
- Train 1058(06) will depart New Orleans, LA, 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.
- Train 58(07-09) will depart New Orleans 2 hours earlier at 1145AM-CT and operate on an adjusted schedule to Chicago.

WBS#: B.TR.100150.6117

Portland Marathon East of Portland, OR - Cascades Service Adjustments

05OCT25: On Sunday October 5th the Portland Marathon at SE Stark Street/MP769.78, 1 mile east of Portland, OR, on the UPRR Brooklyn Subdivision, will take place between 800AM-PT and 1200PM-PT. As a result, Cascades service adjustments as follows:

- Train 503(05) terminates at Portland, OR, with Bus 3503(05) as alternate transportation between Portland and Eugene, OR.
- Train 504(05) originates at Portland, OR and operate 1-hour later, departing Portland at 1140AM-PT. Bus 3504(05) will provide alternate transportation between Eugene and Portland, with adjusted departure times.

WBS#: B.TR.100150.6100

Union Pacific Track Work on the Moffat Tunnel Subdivision - California Zephyr Schedule Change

11SEP25: To accommodate a Union Pacific scheduled track work on the Moffat Tunnel Subdivision between Denver, CO and Glenwood Springs, CO, Train 5(19SEP and 03OCT) will be renumbered as Train 1005(19SEP AND 03OCT). The train departed Chicago, IL Union station at 5:00 p.m. (CDT), 3 hours after the normally scheduled departure time. It then continued to operate 3 hours later than the scheduled departure time through Emeryville, CA.

WBS#: B.TR.100150.6084

San Joaquins Wasco, CA - BNSF M of W Work

05OCT25: To accommodate track work in Bakersfield Subdivision, Amtrak's San Joaquins Service will be adjusted as follows:

-718(14SEP-18SEP / 21SEP-25SEP / 05OCT) - Replacement bus Fresno - Hanford - Bakersfield, CA.

-711(15SEP-19SEP / 22SEP-26SEP / 06OCT) - Replacement bus Bakersfield - Hanford - Fresno, CA.

NOTE: Replacement buses will not stop at Corcoran, CA (COC) or Wasco, CA (WAC).

WBS#: B.TR.100150.6075

Train	Delay	Comment
718(14SEP-18SEP))	Terminate FNO	Replacement Bu FNO-HNF-BFD
718(28SEP-02OCT)	Terminate FNO	Replacement Bu FNO-HNF-BFD
718(21SEP-25SEP)	Terminate FNO	Replacement Bu FNO-HNF-BFD
7(5OCT-09OCT)	Terminate FNO	Replacement Bu FNO-HNF-BFD
711(22SEP-26SEP)	Originate FNO	Replacement Bus BFD-HNF-FNO
711(15SEP-19SEP)	Originate FNO	Replacement Bus BFD-HNF-FNO
71(29SEP-03OCT)	Originate FNO	Replacement Bus BFD-HNF-FNO
711(06OCT-10OCT)	Originate FNO	Replacement Bus BFD-HNF-FNO
7141(16)	1'11"	FNO, crew transportation issue at BFD

Canadian National Holly Subdivision - Pontiac Station Track Project

02SEP25: September 2nd thru September 30th, Canadian National will be performing a track project at the Pontiac, MI station. Updated 24SEP25 to extend through October 15th. The follow trains will originate and terminate at Troy, MI:

Train 350 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep -28Sep, 03Oct- 05Oct, 10Oct - 12Oct) will terminate Troy, MI.

Train 352 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 354 (02SEP - 14SEP, 20SEP - 15OCT) will terminate Troy, MI.

Train 351 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

Train 353 (05SEP - 07SEP, 12SEP - 14SEP, 20SEP - 21SEP, 26SEP - 28SEP, 26Sep - 28Sep, 03Oct - 05Oct, 10Oct - 12Oct) will originate Troy, MI

Train 355 (02SEP - 14SEP, 20SEP - 15OCT) will originate Troy, MI.

There will be NO alternate transportation provided.

WBS#: B.TR.100150.6045

Michigan Department of Transportation Michigan Line affecting Wolverine Service - Scheduled M/W Work

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

05MAY25: Amtrak will be performing a track rehabilitation by modifying a curve between Chelsea, MI / MP 56.0 and Ypsilanti, MI / MP 28.2, which encompasses the Ann Arbor, MI station at MP 37.5, on the Michigan Department of Transportation Michigan Line. The follow operating plan will be placed in to effect:

May 5th through June 26th (except for May 26th and June 19th):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

August 4th through October 30th (except for September 1st):

Trains 350(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

Trains 353(Monday through Thursday) have been cancelled in their entirety. There will be NO alternate transportation provided.

WBS#: B.TR.100150.5512

Train	Delay	Comment
350 & 353(27MAY - 29MAY)	Cancel	
350 & 353(16JUN - 18JUN)	Cancel	
350 & 353(23JUN - 26JUN)	Cancel	
350 & 353(04AUG - 07AUG)	Cancel	
350 & 353(11AUG - 14AUG)	Cancel	
350 & 353(18AUG - 21AUG)	Cancel	
350 & 353(25AUG - 28AUG)	Cancel	
350 & 353(02SEP - 04SEP)	Cancel	
350 & 353(08SEP - 11SEP)	Cancel	
350 & 353(15SEP - 18SEP)	Cancel	
350 & 353(22SEP - 25SEP)	Cancel	
350 & 353(29SEP - 02OCT)	Cancel	
350 & 353(06OCT - 09OCT)	Cancel	
350 & 353(13OCT - 16OCT)	Cancel	
350 & 353(20OCT - 23OCT)	Cancel	
350 & 353(27OCT - 30OCT)	Cancel	

NCTD San Diego Subdivision East of Solana Beach, CA - M of W Work

19MAY24, Commencing 12th Feb 2028, 00000004749 Court UNCLASSIFIED 10/13/2025
on stabilizing tracks and track-bed around the area of Del Mar Bluffs. Work will take place in the vicinity of MP 243.92, San Diego Subdivision, San Diego Northern Railroad. Each project will be over selected Sunday and Monday nights:

from 10:00PM-PT thru 7:00AM-PT.

Selected work dates are:

Sunday August 4 - Tuesday August 6
Sunday August 11 - no extended window account Padres game
Sunday August 18th - Tuesday 20th
Sunday August 25 - Tuesday August 27
Sunday September 8 - Tuesday September 10.
Sunday September 15 - Monday September 16
Sunday September 22 - Tuesday September 24.
Sunday October 27 - Tuesday October 29.
Sunday November 3 - Tuesday November 5.
Sunday December 8-Tuesday December 10.
Sunday December 15-Tuesday December 17.
2025
Sunday February 9 - Tuesday February 11.
Sunday April 06th - Tuesday April 08th (CANCELLED)
Sunday May 20 - Tuesday May 22
Sunday July 20th - Tuesday July 22nd
Sunday August 3rd - Tuesday August 5th
Sunday August 10th - Tuesday August 12th
Sunday August 24th - Tuesday August 26th
Sunday October 5th - Tuesday October 7th.

During the project the following service adjustments will apply:

Train #790(SUN-MON) Terminates Solana Beach, Replacement Bus 4090(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #794(SUN-MON) Terminates Solana Beach, Replacement Bus 4094(SUN-MON) operates to Old Town (OLT) and San Diego (SAN) drop-off only.

Train #761(MON-TUE) Originates Solana Beach, Replacement Bus 4061(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 3:50AM-PT.

Train #765(MON-TUE) Originates Solana Beach, Replacement Bus 4065(MON-TUE) operates from San Diego (SAN) to Solana Beach (SOL) ONLY - Passengers travelling from Old Town (OLT) are advised to board in San Diego (SAN). Bus 4061 departs 11 minutes earlier than scheduled departure time of 761(MON-TUE) at 5:50AM-PT.

* Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W (version 5) is also attached.

05SEP Update: Please note the addition of Train 597 as part of the Summer Schedule which became effective on July 20th. The equipment for 597 (inbound 784) at SAN will deadhead to SOL as Train 867 with no alternate transportation. Corresponding TN-277-24-W is also attached. September 8th will be the final day of operation for Train 597.

WBS Element B.TR.100150.4661 has been issued for this operation.

WBSE Element Internal Order - B.CO.100026

WBS#: B.TR.100150.4661

Train	Delay	Comment
790(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN
761(Monday/Tuesday)	Originates SOL	Bus Service from SAN
765(Monday/Tuesday)	Originates SOL	Bus Service from SAN
794(Sunday/Monday Nights)	Terminates SOL	Bus Service to SAN

Western Region

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
5 (2)	GSC	51		Strike damage, will go in freight service to BEE
6 (3)	GSC	205		Boulder strike

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
22 (3)	DAL	UP2655	E/UP7253//faults speed reduced	CHI	10/5/25
6 (3)	DEN	UP5859	E/182 PTC issues		

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
502(04)	TAC	1	SEA	N/A
518(04)	MVW	1	BEL	N/A

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Train 2(03) Passenger Removal at Pomona, California – Improper Behavior

04OCT25, Passenger on PNR AC7070, traveling from Los Angeles, CA to El Paso, TX was belligerent and overly aggressive with the Conductor. Passenger jumped in Conductors' face yelling gibberish. Passenger was removed from the train by local Police. Amtrak Police notified.

Delay: 2 (03) 32"

Train 794(04) Passenger Removal at Ventura, California – Improper Conduct

04OCT25, Passengers on PNR's 986E42, 98BD1B and 988C80, traveling from Santa Barbara, CA to Moorpark, CA were removed by the local police at Ventura, CA due to throwing water in the face of two passengers that were wearing masks for their own safety and calling them names. Amtrak Police notified.

Delay: 794 (04) 07"

Consist Deviations

26-FOI-00028

00000004749

"UNCLASSIFIED"

10/13/2025

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
790 (04)	GTA	No BV space	Passengers notified	6	90215
769 (04)	SAN	No BV Space	Passengers notified	6	90215

Reverse Consists

Train Number	Station	Reason	Customer Impact	Affected Psgr
87 (04)	BOS	Consist reversed Business class oriented normal At Front	0	0
153 (04)	NYP	Consist reversed Business class oriented normal At Front	0	0
155 (04)	NYP	Consist reversed Business class oriented normal At Front	0	0
101 (04)	NYP	Consist reversed Business class oriented normal At Front	0	0
158 (05)	NFK	Consist reversed Business class oriented backward At Front	Passengers notified	0
88 (05)	NFK	Consist reversed Business class oriented backward At Front	Passengers notified	0
2255 (04)	BOS	Acela consist reversed First class at Rear	Passengers notified	0