

CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Sunday, August 02, 2026

Rules: 0-44



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/01/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	283	44	84.5%	283	44	84.5%	91,227	12,600	86.2%
Central Division	86.0%	56	10	82.1%	56	10	82.1%	17,484	1,584	90.9%
East Division	82.0%	143	21	85.3%	143	21	85.3%	47,813	7,443	84.4%
West Division	86.0%	84	13	84.5%	84	13	84.5%	25,930	3,573	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00636 00000008475 "UNCLASSIFIED" 8/3/2026 Endpoint Arrival Dates through 8/1/26

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	106,738	24,265	77%	106,738	24,265	77%	30,455,760	7,664,272	75%
Northeast Corridor	81%	45,629	5,783	87%	45,629	5,783	87%	13,356,360	3,262,561	76%
Acela	83%	6,364	960	85%	6,364	960	85%	2,667,276	702,609	74%
Northeast Regional	79%	39,265	4,823	88%	39,265	4,823	88%	10,689,084	2,559,952	76%
Richmond / Newport News / Norfolk	77%	12,274	787	94%	12,274	787	94%	3,318,475	963,203	71%
Springfield Shuttles	89%	543	0	100%	543	0	100%	189,293	30,087	84%
Roanoke	79%	4,394	321	93%	4,394	321	93%	1,009,906	218,782	78%
On Spine Northeast Regional	80%	22,054	3,715	83%	22,054	3,715	83%	6,171,410	1,347,880	78%
State Supported	80%	48,779	11,701	76%	48,779	11,701	76%	13,363,570	2,814,536	79%
Borealis	80%	594	297	50%	594	297	50%	170,247	35,944	79%
Capitol Corridor	90%	2,748	244	91%	2,748	244	91%	1,121,190	146,342	87%
Carolinian	70%	1,132	421	63%	1,132	421	63%	345,978	135,390	61%
Cascades	75%	3,017	919	70%	3,017	919	70%	786,537	216,022	73%
Downeaster	82%	2,193	53	98%	2,193	53	98%	462,404	55,878	88%
Empire	78%	5,969	1,597	73%	5,969	1,597	73%	1,650,411	385,444	77%
Adirondack	72%	398	47	88%	398	47	88%	100,401	30,910	69%
Ethan Allen Express	70%	590	273	54%	590	273	54%	169,534	60,649	64%
Maple Leaf	70%	860	356	59%	860	356	59%	201,804	77,498	62%
New York - Albany	85%	2,705	664	75%	2,705	664	75%	765,143	126,599	83%
New York - Niagara Falls	75%	1,416	257	82%	1,416	257	82%	405,408	85,972	79%
Berkshire Flyer	60%	0	0	-	0	0	-	8,121	3,816	53%
Gold Runner	73%	2,387	1,496	37%	2,387	1,496	37%	757,923	271,643	64%
Heartland Flyer	70%	371	234	37%	371	234	37%	65,038	25,660	61%
Hiawatha	90%	1,924	572	70%	1,924	572	70%	523,200	58,300	89%
Illinois	78%	2,786	1,279	54%	2,786	1,279	54%	749,171	205,888	73%
Carl Sandburg / Illinois Zephyr	85%	349	211	40%	349	211	40%	125,210	34,392	73%
Illini / Saluki	85%	1,014	635	37%	1,014	635	37%	261,013	62,569	76%
Lincoln Service	70%	1,423	433	70%	1,423	433	70%	362,948	108,927	70%
Keystone	92%	5,691	0	100%	5,691	0	100%	2,301,136	239,180	90%
Lincoln / Missouri	70%	891	646	27%	891	646	27%	233,339	118,764	49%
Mardi Gras Service	80%	387	57	85%	387	57	85%	123,488	27,407	78%
Michigan	70%	2,096	1,059	49%	2,096	1,059	49%	599,690	193,442	68%
Blue Water	70%	28	28	0%	28	28	0%	139,606	55,744	60%
Pere Marquette	85%	379	167	56%	379	167	56%	78,820	15,288	81%
Wolverine	70%	1,689	864	49%	1,689	864	49%	381,264	122,410	68%
Missouri	80%	475	257	46%	475	257	46%	66,242	16,716	75%
Pacific Surfliner	85%	12,661	1,834	86%	12,661	1,834	86%	2,412,955	429,236	82%
Pennsylvanian	80%	869	313	64%	869	313	64%	266,745	51,231	81%
Piedmont	80%	1,313	227	83%	1,313	227	83%	341,549	88,796	74%
Vermont	75%	1,275	196	85%	1,275	196	85%	386,327	113,253	71%
Long Distance	70%	12,330	6,781	45%	12,330	6,781	45%	3,696,563	1,584,712	57%
Auto Train	70%	927	0	100%	927	0	100%	235,334	80,750	66%
California Zephyr	70%	581	254	56%	581	254	56%	291,910	106,694	63%
Cardinal	70%	322	113	65%	322	113	65%	71,886	35,703	50%
City Of New Orleans	75%	646	300	54%	646	300	54%	191,648	58,330	70%
Coast Starlight	70%	1,442	710	51%	1,442	710	51%	346,020	121,247	65%
Crescent	70%	980	160	84%	980	160	84%	280,381	85,949	69%
Empire Builder	70%	678	644	5%	678	644	5%	290,798	144,304	50%
Floridian	60%	1,897	1,895	0%	1,897	1,895	0%	479,651	328,923	31%
Lake Shore Ltd	73%	1,304	77	94%	1,304	77	94%	289,541	85,544	70%
Palmetto	70%	1,423	783	45%	1,423	783	45%	277,253	83,205	70%
Silver Meteor	70%	1,000	795	21%	1,000	795	21%	306,222	138,138	55%
Southwest Chief	60%	478	398	17%	478	398	17%	250,732	162,804	35%
Sunset Ltd	70%	0	0	-	0	0	-	88,400	32,736	63%
Texas Eagle	70%	652	652	0%	652	652	0%	296,787	120,385	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00000 00000000475 "UNCLASSIFIED" 8/0/2020

Train Index Dates Through August 01, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	0	104,277	0	1,790,844	32,052,293	559

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107		27,889		86,374	9,224,891	94
INFRASTRUCTURE PLANNED	135		27,889		96,037	9,224,891	104
FLEET RELIABILITY	90		104,277		286,961	32,052,293	90
TRAIN OPERATIONS	424		104,277		1,321,472	32,052,293	412

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/01/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	283	44	84.5%	283	44	84.5%	91,227	12,600	86.2%
Central Division	86.0%	56	10	82.1%	56	10	82.1%	17,484	1,584	90.9%
East Division	82.0%	143	21	85.3%	143	21	85.3%	47,813	7,443	84.4%
West Division	86.0%	84	13	84.5%	84	13	84.5%	25,930	3,573	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/01/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	283	44	84.5%	283	44	84.5%	91,227	12,600	86.2%
Central Division	86.0%	56	10	82.1%	56	10	82.1%	17,484	1,584	90.9%
CDL	95.0%	2	1	50.0%	2	1	50.0%	578	26	95.5%
CHI	86.0%	26	5	80.8%	26	5	80.8%	8,076	972	88.0%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
FTW	92.5%	1	0	100.0%	1	0	100.0%	328	36	89.0%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	1	0	100.0%	289	8	97.2%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	2	0	100.0%	589	44	92.5%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	1	80.0%	5	1	80.0%	1,785	115	93.6%
MOE	97.5%	2	0	100.0%	2	0	100.0%	607	9	98.5%
MSP	96.5%	1	1	0.0%	1	1	0.0%	298	7	97.7%
NOL	94.5%	5	0	100.0%	5	0	100.0%	1,278	60	95.3%
OKC	97.0%	1	0	100.0%	1	0	100.0%	299	6	98.0%
PNT	88.0%	3	1	66.7%	3	1	66.7%	790	65	91.8%
PTH	93.0%	1	0	100.0%	1	0	100.0%	293	11	96.2%
QCY	91.0%	1	0	100.0%	1	0	100.0%	578	43	92.6%
SAS	90.5%	1	0	100.0%	1	0	100.0%	302	33	89.1%
STL	89.0%	4	1	75.0%	4	1	75.0%	1,179	101	91.4%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	143	21	85.3%	143	21	85.3%	47,813	7,443	84.4%
ALB	88.5%	8	1	87.5%	8	1	87.5%	2,258	176	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	5	1	80.0%	1,471	159	89.2%
BOS	85.5%	17	1	94.1%	17	1	94.1%	5,180	605	88.3%
BRK	92.5%	5	1	80.0%	5	1	80.0%	1,457	103	92.9%
BTN	82.0%	1	0	100.0%	1	0	100.0%	291	41	85.9%
CLT	91.5%	5	0	100.0%	5	0	100.0%	1,482	150	89.9%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	2	0	100.0%	595	57	90.4%
GRO	-	-	-	-	-	-	-	33	10	69.7%
HAR	79.5%	7	0	100.0%	7	0	100.0%	3,371	548	83.7%
HFD	-	-	-	-	-	-	-	191	15	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	1	0	100.0%	301	38	87.4%
MIA	89.5%	2	0	100.0%	2	0	100.0%	602	68	88.7%
MTR	79.0%	1	1	0.0%	1	1	0.0%	288	53	81.6%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/01/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	283	44	84.5%	283	44	84.5%	91,227	12,600	86.2%
East Division	82.0%	143	21	85.3%	143	21	85.3%	47,813	7,443	84.4%
NFK	84.5%	2	1	50.0%	2	1	50.0%	685	124	81.9%
NFL	93.5%	2	0	100.0%	2	0	100.0%	614	29	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	4	0	100.0%	4	0	100.0%	1,558	253	83.8%
NPN	93.0%	2	0	100.0%	2	0	100.0%	575	42	92.7%
NYP	75.5%	36	6	83.3%	36	6	83.3%	12,520	2,787	77.7%
PGH	93.0%	1	1	0.0%	1	1	0.0%	302	23	92.4%
PHL	48.0%	4	3	25.0%	4	3	25.0%	1,554	743	52.2%
PIT	76.0%	-	-	-	-	-	-	15	12	20.0%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	0	100.0%	4	0	100.0%	1,162	49	95.8%
RNK	83.5%	2	0	100.0%	2	0	100.0%	598	87	85.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	6	4	33.3%
SAB	98.0%	1	0	100.0%	1	0	100.0%	288	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	1	0	100.0%	298	10	96.6%
SFA	88.0%	1	0	100.0%	1	0	100.0%	301	41	86.4%
SPG	92.5%	6	0	100.0%	6	0	100.0%	1,813	105	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	1	0	100.0%	290	60	79.3%
WAS	84.0%	22	5	77.3%	22	5	77.3%	7,494	972	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	84	13	84.5%	84	13	84.5%	25,930	3,573	86.2%
ARN	92.0%	1	0	100.0%	1	0	100.0%	303	26	91.4%
BFD	79.0%	7	1	85.7%	7	1	85.7%	1,904	394	79.3%
EMY	72.0%	1	0	100.0%	1	0	100.0%	319	94	70.5%
EUG	86.5%	2	0	100.0%	2	0	100.0%	600	56	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	4	3	25.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	3	1	66.7%	912	144	84.2%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	1	90.0%	10	1	90.0%	3,009	327	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	9	3	66.7%	9	3	66.7%	3,270	831	74.6%
PDX	86.0%	5	1	80.0%	5	1	80.0%	1,493	182	87.8%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	2	83.3%	12	2	83.3%	4,278	464	89.2%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/01/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/01/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	283	44	84.5%	283	44	84.5%	91,227	12,600	86.2%
West Division	86.0%	84	13	84.5%	84	13	84.5%	25,930	3,573	86.2%
SAN	90.5%	13	0	100.0%	13	0	100.0%	3,654	344	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	8	2	75.0%	8	2	75.0%	2,393	349	85.4%
SJC	89.0%	7	1	85.7%	7	1	85.7%	2,131	210	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	1	66.7%	3	1	66.7%	675	66	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	1	-	100.0%	1	-	100.0%	299	26	91.3%
VAC	97.0%	2	0	100.0%	2	0	100.0%	593	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
3	182	1	0	100.0%	303	59	80.5%	1	1	0.0%	301	137	54.5%
4	171	1	0	100.0%	302	46	84.8%	1	1	0.0%	302	200	33.8%
5	No OS	1	0	100.0%	301	50	83.4%	1	1	0.0%	297	89	70.0%
6		1	0	100.0%	300	85	71.7%	1	0	100.0%	300	103	65.7%
7	236	1	0	100.0%	292	42	85.6%	1	1	0.0%	284	75	73.6%
8	572	1	1	0.0%	292	130	55.5%	1	1	0.0%	291	176	39.5%
11		1	0	100.0%	303	57	81.2%	1	0	100.0%	297	60	79.8%
14	112	1	0	100.0%	304	49	83.9%	1	1	0.0%	302	93	69.2%
19		1	0	100.0%	302	77	74.5%	1	0	100.0%	299	71	76.3%
20		1	0	100.0%	302	23	92.4%	1	0	100.0%	302	58	80.8%
21	162	1	0	100.0%	299	25	91.6%	1	1	0.0%	298	83	72.1%
22		1	0	100.0%	300	31	89.7%	1	0	100.0%	298	81	72.8%
23		1	0	100.0%	304	6	98.0%	1	0	100.0%	302	85	71.9%
24		1	0	100.0%	304	16	94.7%	1	0	100.0%	303	56	81.5%
25	17	1	0	100.0%	303	3	99.0%	1	1	0.0%	301	84	72.1%
26		1	0	100.0%	303	5	98.3%	1	0	100.0%	301	60	80.1%
27	119	0	0	0.0%	285	19	93.3%	1	1	0.0%	282	94	66.7%
28		1	1	0.0%	282	65	77.0%	1	0	100.0%	282	56	80.1%
40	133	1	0	100.0%	297	41	86.2%	1	1	0.0%	294	156	46.9%
41	243	1	0	100.0%	296	114	61.5%	1	1	0.0%	294	225	23.5%
42		1	1	0.0%	304	25	91.8%	1	0	100.0%	302	52	82.8%
43		1	0	100.0%	303	42	86.1%	1	0	100.0%	302	70	76.8%
48		1	0	100.0%	302	57	81.1%	1	0	100.0%	301	42	86.0%
49		1	1	0.0%	302	76	74.8%	1	0	100.0%	302	62	79.5%
51		0	0	0.0%	126	55	56.3%	1	0	100.0%	122	44	63.9%
52		1	0	100.0%	301	41	86.4%	1	0	100.0%	300	72	76.0%
53		1	0	100.0%	301	38	87.4%	1	0	100.0%	300	95	68.3%
54		1	0	100.0%	110	8	92.7%	1	0	100.0%	110	16	85.5%
57		1	0	100.0%	109	5	95.4%	1	0	100.0%	109	9	91.7%
59		1	1	0.0%	276	34	87.7%	1	0	100.0%	272	57	79.0%
63	46	1	0	100.0%	305	132	56.7%	1	1	0.0%	299	167	44.1%
64	22	1	0	100.0%	303	68	77.6%	1	1	0.0%	302	110	63.6%
65		1	0	100.0%	94	12	87.2%	1	0	100.0%	92	13	85.9%
66		1	0	100.0%	302	61	79.8%	1	0	100.0%	298	54	81.9%
68		1	1	0.0%	305	62	79.7%	1	0	100.0%	304	118	61.2%
69		1	1	0.0%	292	69	76.4%	1	0	100.0%	287	43	85.0%
71		1	0	100.0%	300	3	99.0%	1	0	100.0%	299	81	72.9%
72		1	0	100.0%	296	31	89.5%	1	0	100.0%	295	61	79.3%
73	28	1	0	100.0%	299	19	93.6%	1	1	0.0%	297	143	51.9%
74		1	0	100.0%	297	33	88.9%	1	0	100.0%	295	108	63.4%
75		1	0	100.0%	293	16	94.5%	1	0	100.0%	287	137	52.3%
76	11	1	0	100.0%	293	29	90.1%	1	1	0.0%	284	118	58.5%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
77		1	0	100.0%	295	20	93.2%	1	0	100.0%	293	123	58.0%
78	17	1	0	100.0%	299	25	91.6%	1	1	0.0%	298	64	78.5%
79	34	1	0	100.0%	302	56	81.5%	1	1	0.0%	301	102	66.1%
80		1	0	100.0%	302	33	89.1%	1	0	100.0%	299	63	78.9%
82		1	0	100.0%	73	9	87.7%	1	0	100.0%	73	24	67.1%
87		1	0	100.0%	113	24	78.8%	1	0	100.0%	113	39	65.5%
88		1	0	100.0%	109	15	86.2%	1	0	100.0%	109	23	78.9%
89		1	0	100.0%	300	65	78.3%	1	0	100.0%	298	85	71.5%
90		1	0	100.0%	300	10	96.7%	1	0	100.0%	299	51	82.9%
97	221	1	1	0.0%	302	199	34.1%	1	1	0.0%	300	101	66.3%
98	416	1	0	100.0%	302	26	91.4%	1	1	0.0%	300	109	63.7%
99		1	0	100.0%	112	12	89.3%	1	0	100.0%	109	61	44.0%
101		1	0	100.0%	72	6	91.7%	1	0	100.0%	72	11	84.7%
103	134	1	1	0.0%	111	22	80.2%	1	1	0.0%	111	10	91.0%
106	94	1	1	0.0%	88	10	88.6%	1	1	0.0%	87	13	85.1%
107	85	1	1	0.0%	88	29	67.0%	1	1	0.0%	87	14	83.9%
109		1	0	100.0%	55	8	85.5%	1	0	100.0%	55	6	89.1%
118		1	0	100.0%	111	8	92.8%	1	0	100.0%	111	8	92.8%
124		1	0	100.0%	110	9	91.8%	1	0	100.0%	109	30	72.5%
126		1	0	100.0%	51	8	84.3%	1	0	100.0%	51	12	76.5%
127		1	0	100.0%	51	14	72.5%	1	0	100.0%	51	6	88.2%
135		1	0	100.0%	112	17	84.8%	1	0	100.0%	112	56	50.0%
136		0	0	0.0%	192	24	87.5%	1	0	100.0%	191	25	86.9%
140		1	0	100.0%	111	12	89.2%	1	0	100.0%	110	24	78.2%
142		1	0	100.0%	71	7	90.1%	1	0	100.0%	70	9	87.1%
143		1	0	100.0%	110	11	90.0%	1	0	100.0%	110	25	77.3%
144	144	1	1	0.0%	73	49	32.9%	1	1	0.0%	72	10	86.1%
146		1	0	100.0%	110	17	84.5%	1	0	100.0%	110	39	64.5%
147		1	0	100.0%	74	8	89.2%	1	0	100.0%	74	24	67.6%
150		1	0	100.0%	109	57	47.7%	1	0	100.0%	107	51	52.3%
151		1	1	0.0%	301	96	68.1%	1	0	100.0%	300	95	68.3%
152		1	0	100.0%	73	6	91.8%	1	0	100.0%	73	27	63.0%
153		1	0	100.0%	111	10	91.0%	1	0	100.0%	111	16	85.6%
155		1	0	100.0%	113	18	84.1%	1	0	100.0%	113	40	64.6%
156		1	0	100.0%	113	11	90.3%	1	0	100.0%	113	38	66.4%
158		1	1	0.0%	112	21	81.3%	1	0	100.0%	112	26	76.8%
159		1	0	100.0%	71	8	88.7%	1	0	100.0%	71	11	84.5%
160		1	0	100.0%	110	6	94.5%	1	0	100.0%	107	26	75.7%
161		1	0	100.0%	111	9	91.9%	1	0	100.0%	110	72	34.5%
162		1	1	0.0%	111	8	92.8%	1	0	100.0%	111	55	50.5%
163	27	1	0	100.0%	71	15	78.9%	1	1	0.0%	71	58	18.3%
164		1	0	100.0%	113	9	92.0%	1	0	100.0%	113	47	58.4%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
165		1	0	100.0%	111	27	75.7%	1	0	100.0%	111	45	59.5%
167		1	0	100.0%	74	16	78.4%	1	0	100.0%	73	22	69.9%
168		1	1	0.0%	72	13	81.9%	1	0	100.0%	72	26	63.9%
178		0	0	0.0%	192	26	86.5%	1	0	100.0%	191	31	83.8%
179	168	0	0	0.0%	192	23	88.0%	1	1	0.0%	192	71	63.0%
194		1	0	100.0%	73	17	76.7%	1	0	100.0%	72	22	69.4%
195		1	0	100.0%	111	4	96.4%	1	0	100.0%	111	59	46.8%
198		0	0	0.0%	124	17	86.3%	1	0	100.0%	124	21	83.1%
230		1	0	100.0%	138	4	97.1%	1	0	100.0%	138	7	94.9%
232		1	0	100.0%	304	11	96.4%	1	0	100.0%	304	21	93.1%
233	18	1	0	100.0%	274	61	77.7%	1	1	0.0%	273	89	67.4%
234		1	0	100.0%	305	22	92.8%	1	0	100.0%	304	25	91.8%
235		1	0	100.0%	229	34	85.2%	1	0	100.0%	228	52	77.2%
236		1	0	100.0%	289	10	96.5%	1	0	100.0%	288	39	86.5%
237		1	0	100.0%	302	56	81.5%	1	0	100.0%	300	51	83.0%
238		1	0	100.0%	229	20	91.3%	1	0	100.0%	227	18	92.1%
239		1	0	100.0%	303	79	73.9%	1	0	100.0%	302	38	87.4%
240	57	1	0	100.0%	304	21	93.1%	1	1	0.0%	301	61	79.7%
241		1	0	100.0%	304	74	75.7%	1	0	100.0%	304	71	76.6%
243		1	0	100.0%	240	65	72.9%	1	0	100.0%	239	33	86.2%
244		1	0	100.0%	273	12	95.6%	1	0	100.0%	273	49	82.1%
245	32	1	0	100.0%	185	33	82.2%	1	1	0.0%	184	23	87.5%
280		1	0	100.0%	305	15	95.1%	1	0	100.0%	304	61	79.9%
281		1	0	100.0%	305	37	87.9%	1	0	100.0%	305	57	81.3%
283		1	0	100.0%	305	74	75.7%	1	0	100.0%	305	61	80.0%
284		1	0	100.0%	305	13	95.7%	1	0	100.0%	302	54	82.1%
290		1	0	100.0%	305	50	83.6%	1	0	100.0%	302	114	62.3%
291	26	1	1	0.0%	304	94	69.1%	1	1	0.0%	302	77	74.5%
300	45	1	0	100.0%	289	20	93.1%	1	1	0.0%	287	69	76.0%
301		1	0	100.0%	302	10	96.7%	1	0	100.0%	298	55	81.5%
302		1	0	100.0%	284	33	88.4%	1	0	100.0%	280	78	72.1%
305		1	0	100.0%	287	28	90.2%	1	0	100.0%	283	115	59.4%
306		1	0	100.0%	300	16	94.7%	1	0	100.0%	299	82	72.6%
307		1	1	0.0%	293	39	86.7%	1	0	100.0%	290	82	71.7%
311		1	1	0.0%	298	27	90.9%	1	0	100.0%	292	63	78.4%
316	16	1	0	100.0%	294	18	93.9%	1	1	0.0%	289	79	72.7%
318	54	1	0	100.0%	303	31	89.8%	1	1	0.0%	300	145	51.7%
319	28	1	0	100.0%	304	20	93.4%	1	1	0.0%	299	166	44.5%
330		1	0	100.0%	259	6	97.7%	1	0	100.0%	259	15	94.2%
331		1	0	100.0%	305	33	89.2%	1	0	100.0%	305	44	85.6%
334		1	0	100.0%	305	10	96.7%	1	0	100.0%	304	40	86.8%
335	85	1	0	100.0%	305	34	88.9%	1	1	0.0%	303	52	82.8%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
336		1	0	100.0%	305	10	96.7%	1	0	100.0%	303	28	90.8%
337	34	1	0	100.0%	305	18	94.1%	1	1	0.0%	301	37	87.7%
338	127	1	1	0.0%	305	48	84.3%	1	1	0.0%	303	95	68.6%
339	114	1	1	0.0%	305	51	83.3%	1	1	0.0%	305	54	82.3%
341		1	0	100.0%	293	44	85.0%	1	0	100.0%	287	41	85.7%
342		1	0	100.0%	305	24	92.1%	1	0	100.0%	303	60	80.2%
343		0	0	0.0%	43	3	93.0%	1	0	100.0%	43	10	76.7%
350	53	1	0	100.0%	282	18	93.6%	1	1	0.0%	275	152	44.7%
351	73	1	1	0.0%	288	28	90.3%	1	1	0.0%	286	79	72.4%
352	33	1	0	100.0%	272	21	92.3%	1	1	0.0%	266	82	69.2%
353		1	0	100.0%	243	13	94.7%	1	0	100.0%	237	38	84.0%
354	41	1	0	100.0%	286	35	87.8%	1	1	0.0%	279	102	63.4%
355		1	0	100.0%	295	31	89.5%	1	0	100.0%	288	99	65.6%
364	25	1	1	0.0%	294	66	77.6%	1	1	0.0%	288	108	62.5%
365	Cncld	1	0	100.0%	293	11	96.2%	0	0	0.0%	290	109	62.4%
370	17	1	0	100.0%	296	35	88.2%	1	1	0.0%	286	70	75.5%
371		1	0	100.0%	289	8	97.2%	1	0	100.0%	288	29	89.9%
381		1	0	100.0%	303	12	96.0%	1	0	100.0%	302	60	80.1%
382	18	1	0	100.0%	302	27	91.1%	1	1	0.0%	302	101	66.6%
390	20	1	1	0.0%	287	20	93.0%	1	1	0.0%	286	74	74.1%
391	20	1	0	100.0%	288	11	96.2%	1	1	0.0%	284	77	72.9%
392		1	0	100.0%	301	10	96.7%	1	0	100.0%	298	90	69.8%
393	25	1	0	100.0%	305	18	94.1%	1	1	0.0%	302	92	69.5%
400		1	0	100.0%	92	6	93.5%	1	0	100.0%	90	2	97.8%
405		1	0	100.0%	85	0	100.0%	1	0	100.0%	85	4	95.3%
448		1	1	0.0%	235	46	80.4%	1	0	100.0%	232	80	65.5%
449		1	0	100.0%	232	32	86.2%	1	0	100.0%	232	42	81.9%
450		1	0	100.0%	88	27	69.3%	1	0	100.0%	86	28	67.4%
460		1	0	100.0%	88	28	68.2%	1	0	100.0%	85	30	64.7%
461		1	0	100.0%	93	5	94.6%	1	0	100.0%	92	2	97.8%
463		1	0	100.0%	47	4	91.5%	1	0	100.0%	47	0	100.0%
464		1	0	100.0%	88	16	81.8%	1	0	100.0%	86	25	70.9%
467		1	0	100.0%	47	1	97.9%	1	0	100.0%	46	3	93.5%
488		1	0	100.0%	98	28	71.4%	1	0	100.0%	88	13	85.2%
499		1	0	100.0%	89	13	85.4%	1	0	100.0%	86	6	93.0%
500		1	0	100.0%	296	16	94.6%	1	0	100.0%	293	35	88.1%
502		1	0	100.0%	303	18	94.1%	1	0	100.0%	299	58	80.6%
503		1	0	100.0%	301	27	91.0%	1	0	100.0%	294	87	70.4%
504	16	1	0	100.0%	305	19	93.8%	1	1	0.0%	303	91	70.0%
505		1	0	100.0%	303	41	86.5%	1	0	100.0%	298	84	71.8%
506		1	0	100.0%	300	42	86.0%	1	0	100.0%	294	46	84.4%
507		1	0	100.0%	305	36	88.2%	1	0	100.0%	305	100	67.2%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
508	No OS	1	0	100.0%	300	41	86.3%	1	1	0.0%	296	69	76.7%
509		1	0	100.0%	302	14	95.4%	1	0	100.0%	302	66	78.1%
511		1	0	100.0%	297	24	91.9%	1	0	100.0%	296	50	83.1%
516	35	1	1	0.0%	296	30	89.9%	1	1	0.0%	295	135	54.2%
517	16	1	0	100.0%	305	8	97.4%	1	1	0.0%	301	128	57.5%
518	19	1	0	100.0%	305	37	87.9%	1	1	0.0%	303	208	31.4%
519		1	0	100.0%	296	9	97.0%	1	0	100.0%	294	66	77.6%
562		1	0	100.0%	296	23	92.2%	1	0	100.0%	292	35	88.0%
564		1	0	100.0%	297	19	93.6%	1	0	100.0%	289	38	86.9%
566		1	0	100.0%	295	25	91.5%	1	0	100.0%	292	45	84.6%
567		1	0	100.0%	182	10	94.5%	1	0	100.0%	180	9	95.0%
572		1	0	100.0%	292	24	91.8%	1	0	100.0%	285	83	70.9%
573		1	0	100.0%	294	40	86.4%	1	0	100.0%	287	51	82.2%
579		1	0	100.0%	182	11	94.0%	1	0	100.0%	177	37	79.1%
580		1	0	100.0%	297	16	94.6%	1	0	100.0%	290	28	90.3%
581		1	0	100.0%	297	50	83.2%	1	0	100.0%	295	64	78.3%
584	38	1	1	0.0%	181	26	85.6%	1	1	0.0%	176	109	38.1%
587		1	0	100.0%	290	16	94.5%	1	0	100.0%	281	53	81.1%
588		1	0	100.0%	182	18	90.1%	1	0	100.0%	181	33	81.8%
591		1	0	100.0%	294	21	92.9%	1	0	100.0%	288	39	86.5%
593		1	0	100.0%	291	47	83.8%	1	0	100.0%	270	37	86.3%
595		1	0	100.0%	292	53	81.8%	1	0	100.0%	289	60	79.2%
611		1	1	0.0%	44	31	29.5%	1	0	100.0%	44	4	90.9%
624		0	0	0.0%	119	38	68.1%	1	0	100.0%	120	31	74.2%
660		1	0	100.0%	82	12	85.4%	1	0	100.0%	81	25	69.1%
661		1	0	100.0%	110	12	89.1%	1	0	100.0%	109	41	62.4%
662		1	0	100.0%	46	0	100.0%	1	0	100.0%	46	1	97.8%
663		1	0	100.0%	83	14	83.1%	1	0	100.0%	82	8	90.2%
664		1	0	100.0%	82	8	90.2%	1	0	100.0%	82	11	86.6%
665		1	0	100.0%	83	10	88.0%	1	0	100.0%	83	24	71.1%
666		1	0	100.0%	81	22	72.8%	1	0	100.0%	81	7	91.4%
667		1	0	100.0%	81	7	91.4%	1	0	100.0%	79	16	79.7%
669		1	0	100.0%	81	7	91.4%	1	0	100.0%	79	22	72.2%
670		1	0	100.0%	83	13	84.3%	1	0	100.0%	81	15	81.5%
671		1	0	100.0%	81	8	90.1%	1	0	100.0%	79	9	88.6%
672		1	0	100.0%	83	8	90.4%	1	0	100.0%	83	15	81.9%
674		1	0	100.0%	81	26	67.9%	1	0	100.0%	81	7	91.4%
690		1	0	100.0%	87	2	97.7%	1	0	100.0%	86	4	95.3%
691		1	0	100.0%	87	7	92.0%	1	0	100.0%	85	23	72.9%
692		1	0	100.0%	87	3	96.6%	1	0	100.0%	86	14	83.7%
693	16	1	0	100.0%	87	12	86.2%	1	1	0.0%	85	25	70.6%
694		1	1	0.0%	86	10	88.4%	1	0	100.0%	86	14	83.7%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
695		1	0	100.0%	85	10	88.2%	1	0	100.0%	85	14	83.5%
696		1	0	100.0%	87	9	89.7%	1	0	100.0%	87	25	71.3%
697		1	1	0.0%	87	20	77.0%	1	0	100.0%	87	17	80.5%
698		1	0	100.0%	85	2	97.6%	1	0	100.0%	85	7	91.8%
701		1	0	100.0%	237	25	89.5%	1	0	100.0%	234	25	89.3%
702	18	1	0	100.0%	304	32	89.5%	1	1	0.0%	301	71	76.4%
703		1	0	100.0%	305	93	69.5%	1	0	100.0%	303	85	71.9%
704	50	1	0	100.0%	236	37	84.3%	1	1	0.0%	229	47	79.5%
710	23	1	0	100.0%	305	77	74.8%	1	1	0.0%	301	82	72.8%
711	29	1	0	100.0%	296	34	88.5%	1	1	0.0%	275	53	80.7%
712		1	0	100.0%	302	80	73.5%	1	0	100.0%	293	98	66.6%
713		1	0	100.0%	173	16	90.8%	1	0	100.0%	157	67	57.3%
714	Cncld	1	1	0.0%	186	76	59.1%	0	0	0.0%	171	76	55.6%
715	Cncld	1	0	100.0%	304	61	79.9%	0	0	0.0%	280	141	49.6%
716	51	1	1	0.0%	305	121	60.3%	1	1	0.0%	299	119	60.2%
717	No OS	1	1	0.0%	290	69	76.2%	1	1	0.0%	271	87	67.9%
718	161	1	0	100.0%	305	153	49.8%	1	1	0.0%	303	110	63.7%
719	16	1	0	100.0%	305	103	66.2%	1	1	0.0%	289	85	70.6%
720		1	0	100.0%	94	9	90.4%	1	0	100.0%	94	6	93.6%
723	21	1	0	100.0%	94	5	94.7%	1	1	0.0%	94	10	89.4%
724		1	0	100.0%	94	3	96.8%	1	0	100.0%	94	19	79.8%
727		1	0	100.0%	94	7	92.6%	1	0	100.0%	94	14	85.1%
728		1	0	100.0%	94	6	93.6%	1	0	100.0%	94	17	81.9%
729		1	0	100.0%	93	15	83.9%	1	0	100.0%	92	21	77.2%
732		1	0	100.0%	92	15	83.7%	1	0	100.0%	90	17	81.1%
733		1	0	100.0%	94	14	85.1%	1	0	100.0%	89	29	67.4%
734		1	0	100.0%	94	14	85.1%	1	0	100.0%	93	21	77.4%
736	12	1	0	100.0%	70	7	90.0%	1	1	0.0%	68	10	85.3%
737		1	1	0.0%	70	8	88.6%	1	0	100.0%	69	12	82.6%
738		1	0	100.0%	94	15	84.0%	1	0	100.0%	89	13	85.4%
741		1	0	100.0%	94	13	86.2%	1	0	100.0%	94	18	80.9%
742		1	1	0.0%	93	12	87.1%	1	0	100.0%	91	7	92.3%
743		1	0	100.0%	94	17	81.9%	1	0	100.0%	93	10	89.2%
744		1	0	100.0%	94	15	84.0%	1	0	100.0%	94	32	66.0%
745		1	0	100.0%	94	10	89.4%	1	0	100.0%	93	14	84.9%
746	26	1	1	0.0%	94	9	90.4%	1	1	0.0%	93	14	84.9%
747		1	1	0.0%	94	16	83.0%	1	0	100.0%	94	21	77.7%
748		1	0	100.0%	93	13	86.0%	1	0	100.0%	93	13	86.0%
749	29	1	0	100.0%	91	14	84.6%	1	1	0.0%	82	11	86.6%
751		1	0	100.0%	93	16	82.8%	1	0	100.0%	90	11	87.8%
757		1	0	100.0%	90	5	94.4%	1	0	100.0%	89	8	91.0%
761		1	0	100.0%	301	12	96.0%	1	0	100.0%	298	41	86.2%

Amtrak On Time Performance

Trains Arriving Through: 8/1/2026

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
765		1	0	100.0%	301	25	91.7%	1	0	100.0%	301	42	86.0%
769		1	0	100.0%	301	27	91.0%	1	0	100.0%	295	57	80.7%
770	29	1	0	100.0%	301	22	92.7%	1	1	0.0%	299	90	69.9%
774		1	0	100.0%	301	16	94.7%	1	0	100.0%	300	69	77.0%
777		1	0	100.0%	186	12	93.5%	1	0	100.0%	185	42	77.3%
782	18	1	1	0.0%	186	83	55.4%	1	1	0.0%	181	26	85.6%
785		1	0	100.0%	301	22	92.7%	1	0	100.0%	301	53	82.4%
786		1	0	100.0%	90	19	78.9%	1	0	100.0%	87	47	46.0%
790		1	0	100.0%	301	28	90.7%	1	0	100.0%	298	46	84.6%
794		1	1	0.0%	301	34	88.7%	1	0	100.0%	297	66	77.8%
821	20	1	0	100.0%	299	6	98.0%	1	1	0.0%	299	122	59.2%
822	12	1	0	100.0%	301	16	94.7%	1	1	0.0%	299	143	52.2%
1058	507	0	0	0.0%	5	1	80.0%	1	1	0.0%	5	4	20.0%
1333	21	1	1	0.0%	301	33	89.0%	1	1	0.0%	298	100	66.4%
1340		1	1	0.0%	300	7	97.7%	1	0	100.0%	300	51	83.0%
1689		1	0	100.0%	96	5	94.8%	1	0	100.0%	95	11	88.4%
2207		1	0	100.0%	24	5	79.2%	1	0	100.0%	24	5	79.2%
2208		1	0	100.0%	12	3	75.0%	1	0	100.0%	12	3	75.0%
2211		1	0	100.0%	7	1	85.7%	1	0	100.0%	7	1	85.7%
2219		1	0	100.0%	12	3	75.0%	1	0	100.0%	12	4	66.7%
2224		1	0	100.0%	27	5	81.5%	1	0	100.0%	27	4	85.2%
2250		1	1	0.0%	105	12	88.6%	1	0	100.0%	104	35	66.3%
2252		1	0	100.0%	107	9	91.6%	1	0	100.0%	105	32	69.5%
2254	19	1	0	100.0%	42	3	92.9%	1	1	0.0%	42	13	69.0%
2255	61	1	0	100.0%	109	11	89.9%	1	1	0.0%	108	51	52.8%
2258		1	0	100.0%	45	9	80.0%	1	0	100.0%	44	19	56.8%
2259		1	0	100.0%	65	24	63.1%	1	0	100.0%	64	30	53.1%
2260		1	0	100.0%	11	2	81.8%	1	0	100.0%	11	8	27.3%
2262	43	1	1	0.0%	22	5	77.3%	1	1	0.0%	22	8	63.6%
2265		1	0	100.0%	46	4	91.3%	1	0	100.0%	45	27	40.0%
2267		1	0	100.0%	9	3	66.7%	1	0	100.0%	8	5	37.5%
2271		1	0	100.0%	92	11	88.0%	1	0	100.0%	91	46	49.5%
2293		1	1	0.0%	10	2	80.0%	1	0	100.0%	10	3	70.0%

Amtrak Endpoint OTP Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
2254	BOS	19	RTE	26	RTE	20	STM-NHV	MN	Dispatcher hold Control Point, 240
2255	WAS	61	ENG	45	ENG	43	NHV-STM	MN	Air / Brake ENGINE FAULT :SERVICE BRAKE FAULT DE-PREPARED AT CP255 TO FIX AND CLEAR PROBLEM, 2144
2262	BOS	43	ENG	35	ENG	35	XHM-XCY	AM	HEP, 2136 NG NP, ENGR REPORTED STOPPED EAST OF HAM INT ON NO.2 TRK, PANTOGRAPH DROPPED AND NO HEP
103	WAS	134	ITI	121	ITI	121	NYP-NYP	AM	Service, turn, or wye train, 144, LATE TURN OFF AM144
106	NYP	94	ITI	100	ITI	100	WAS-WAS	AM	Service, turn, or wye train, 144, 144 ARRIVED LATE IN NYP DUE TO ENG ISSUE. 308 THE MTR HAD TO CAPPED. DELAYED 103 OUT OF THE S&I
107	WAS	85	ITI	91	ITI	91	NYP-NYP	AM	Service, turn, or wye train, 106
144	NYP	144	ITI	118	ITI	89	PHL-PHL	AM	Service, turn, or wye train, 179, late turn off 179
163	WAS	27	DSR	14	DSR	9	NHV-BRP	MN	Per dispatcher (radio/phone) Other, cat pole 816-815, 20, 1
179	PHL	168	ENG	127	ENG	37	KIN-KIN	AM	Cab signal failure, 608 EX ES, AM179 e/608 declared Cab Signal Failure at KIN
79	CLT	34	PTI	47	PTI	26	FBG-RVR	CS	Follow 89, Other, Ashland
693	BRK	16	ADA	7	PTI	4	EXR-DHM	CS	Meet 694, Control Point, Rockingham
63	TWO	46	FTI	14	CTI	10	CRT-POU	MN	Follow MNRR, 8805, Milepost, 56, 61
64	NYP	22	DSR	15	DMW	13	ALB-HUD	AM	Held for or routed around MW work or equipment Control Point, 125
233	ALB	18	CTI	13	DMW	12	CRT-POU	MN	Waiting for MW clearance Followed 8819 through work area. Alternative was holding for two. Thank you district d for the good move sir, Milepost, 61.3, 61.6
240	NYP	57	RTE	32	RTE	32	POU-POU	MN	Dispatcher hold Other, POU
245	ALB	32	TRS	37	TRS	37	NYP-XSD	AM	Vehicle strike, Other, NYP-XSD, STRUCK BICYCLE AT MP. 5.0
291	BTN	26	ITI	42	ITI	42	NYP-NYP	AM	Service, turn, or wye train, 240
73	CLT	28	FTI	33	FTI	30	HPT-SAL	NS	Follow #NS13r, Control Point, sharp
76	RGH	11	TEN	9	TEN	3	KAN-GRO	NS	Undesired emergency application Wheel slip caused PTC to cutout., NC1893

Amtrak Endpoint OTP Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
78	RGH	17	FTI	26	FTI	26	HPT-GRO	NS	Meet #NS134, Control Point, Elm
97	MIA	221	TRS	114	TRS	114	FLO-KTR	CS	Vehicle on track ahead Lowboy trailer hung up on crossing., Milepost, 305.0, 305.1
98	NYP	416	DBS	354	DBS	320	FLO-FLO	CS	Debris strike Tree strike south of CHS inbound was able to make to Florence . Outbound crew did the engine swaps, Tree strike , Other, A292
40	CHI	133	ENG	76	ENG	43	PGH-ALC	NS	Cab signal failure Approach every CP prepared to stop., 78
41	MIA	243	ENG	120	ENG	102	CHI-CHI	AM	Switch engines Switch out 335 for 77 .. engine 39 moved to lead unit as well, 77
25	NOL	17	PTI	18	PTI	18	BAS-XNO	CS	Meet 26, Control Point, Nicholson
5	EMY	No OS Rpt	ENG	207	ENG	207	CHI-CHI	AM	Late release of road power Late release of road power, 182, 169
723	SJC	21	DCS	32	DCS	14	HAY-FMT	UP	Restrictive signal(s) from unknown cause Authority 5-30, Red, Control Point, NI021
736	SAC	12	MBO	25	MBO	25	MTZ-SUI	UP	For maritime traffic Ship x 2, Bridge, Suisun
746	SAC	26	TEN	32	TEN	22	SJC-SJC	UP	Air / Brake C2106
749	OKJ	29	INJ	35	INJ	35	MTZ-RIC	UP	Injured or sick passenger Pax found to be having a seizure. Removed by EMR at mp 18
504	SEA	16	FTI	27	FTI	16	VAN-KEL	BN	Cross over or go around BNSF 7191, Control Point, filida
508	SEA	No OS Rpt	POL	140	POL	140	ORC-PDX	UP	Trespasser strike
516	VAC	35	FTI	40	FTI	21	XF2-X1J	BN	Cross Traffic CN 834, Bridge, Fraser River Br
517	PDX	16	FTI	13	FTI	8	CTL-KEL	BN	Pick up / drop off freight crew UNKNOWN BNSF, Control Point, CP 72
518	VAC	19	DSR	23	DCS	13	XA4-TUK	BN	Wayside detector failure including false actuation Box 2 Box 1 15mph, Milepost w/Letters, 19.65x, 19.65x, Milepost w/Letters, 19.17x, 19.17x
1058	CHI	507	ENG	552	ENG	513	FTN-CDL	CC	Other electrical failure Blown blower fuse, 150
14	SEA	112	PTI	69	MBO	44	MTZ-DAV	UP	For maritime traffic Double lift, Bridge, Suisun
7	SEA	236	FTI	276	ENG	101	CHI-CHI	AM	Unknown 335
8	CHI	181	FTI	179	OTH	49	SPK-SPK	BN	Engineer late call for duty

Amtrak Endpoint OTP Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
27	PDX	-50	CON	153	CON	153	SPK-SPK	BN	Late arrival of 7 into SPK
821	FTW	20	FTI	22	DSR	14	GLE-FTW	BN	Per bulletin Milepost, 401, 400.2, 25, M, Milepost, 396.3, 396.2, 30, M, Milepost, 389.7, 389, 25, M, Milepost, 385.5, 385.3, 30, M, Milepost, 383.6, 383.4, 30, M, Milepost, 350.4, 350, 30, 1
822	OKC	12	DSR	28	DSR	25	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, m, Milepost, 350.7, 351.1, 50, 1, Milepost, 353.7, 354.1, 60, 1, Milepost, 353.7, 354.1, 30, 2, Milepost, 354, 354.5, 70, 1, Milepost, 355.4, 355.5, 60, 2, Milepost, 355.5, 355.9, 50, 1, Milepost, 355.6, 355.8, 40, 2, Milepost, 357.3, 357.6, 29, m, Milepost, 36
335	MKE	85	TRS	83	TRS	83	SVT-MKA	CP	Bridge strike by a vehicle or boat Stopped near MP 76, vehicle hit nearby bridge. Had to wait some time for an inspector, Milepost, 76.0, 76.0
337	MKE	34	FTI	28	FTI	28	MKA-MKE	CP	Follow UP 7079, Other, MKE
338	CHI	127	ITI	81	ITI	81	MKE-MKE	CP	Service, turn, or wye train 335
339	MKE	114	ITI	111	ITI	111	CHI-CHI	AM	Service, turn, or wye train 338
350	PNT	53	DSR	44	PTI	30	XB0-XA5	MI	Meet Siding, Albion, 353
351	CHI	73	ITI	50	ITI	50	PNT-PNT	CC	Service, turn, or wye train 354, Trespasser strike with the crew of 354
352	PNT	33	PTI	33	PTI	33	JXN-ARB	MI	Meet am355, Control Point, 52
354	PNT	41	DSR	40	DSR	26	TRM-PNT	CC	Per bulletin Milepost, 17.9, 18, 30, 1, Milepost, 18.9, 22.3, 10, 1, Milepost w/Letters, MP 22.3, CP MAL Jct, 30, 1
364	PTH	25	DSR	24	WTR	14	XH6-XPI	NS	Flash flood warning Milepost, 507, 487
365	CHI	Trn Cancelled							
370	GRR	17	WTR	24	WTR	16	XH6-XPI	NS	Flash flood warning Milepost, 507.8, 487
584	SAN	38	PTI	24	PTI	18	SNC-SNP	SC	Meet 587, Control Point, serra
770	SAN	29	PTI	22	CTI	15	SNC-SNP	SC	Meet Metrolink, 1663, Control Point, Serra
782	SAN	18	CTI	17	PTI	9	X98-OSD	SN	Meet 587, Control Point, Eastbrook
702	BFD	18	PTI	24	PTI	10	MCD-MDR	BN	Meet AMT 701, Siding, E. Le Grand
704	BFD	50	PTI	59	PTI	35	XSK-MOD	BN	Meet 715/717, Control Point, East Escalon
710	BFD	23	POL	30	POL	30	WAC-WAC	BN	Removal of passenger by police Passenger altercation Wasco PD removed the aggressor

Amtrak Endpoint OTP Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/1/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
711	OKJ	29	FTI	19	FTI	8	HNF-FNO	BN	Meet Stopped short of Fresno Station due to meet., Control Point, Fresno, BNSF 4127, Grain Train
714	BFD	Trn Cancelled	TEN	44	TEN	44	SKN-SKN	BN	Other electrical failure C2003
715	OKJ	Trn Cancelled	TEN	274	TEN	274	MCD-TRK	BN	Failure of diesel engine C2013
716	BFD	51	PTI	40	PTI	14	TRK-TRK	BN	Waiting at Denair Station due to 717 and 715 717/715, Other, Denair Depot
717	OKJ	No OS Rpt	SYS	57	SYS	43	MCD-TRK	BN	Blocked by or assisting another, disabled Amtrak train
718	BFD	161	ITI	111	ITI	111	EMY-EMY	UP	Service, turn, or wye train 715
719	OKJ	16	PTI	34	DCS	15	EMY-OKJ	UP	Power switch failure Control Point, 10th st
3	LAX	182	FTI	219	FTI	63	WLO-FLG	BN	Follow BNSF 6123, Milepost, 311.9, 340.6
4	CHI	No OS Rpt	FTI	111	FTI	46	NDL-KNG	BN	Meet bnsf6581, Control Point, e Griffith
21	SAS	162	FTI	216	WTR	90	XGA-ACD	UP	Flash flood warning Milepost, 41, 79
300	CHI	45	DSR	18	PTI	16	DWT-JOL	UP	Meet Amtk 301, Control Point, X055
382	CHI	18	CTI	16	FTI	13	KEE-PCT	BN	Meet BNSF 4340, Control Point, BUDA
390	CHI	20	SYS	24	FTI	16	CDL-CDL	CC	Blocked from station track cn 2026, Other, carbondale station
391	CDL	20	PTI	31	PTI	22	RTL-CHM	CC	Wait for station track amtrak 390, Control Point, n champaign
393	CDL	25	DSR	19	FTI	19	EFG-CEN	CC	Meet 5775, Siding, TONTI
316	STL	16	FTI	23	FTI	17	SED-JEF	UP	Meet Siding, Centertown, UP5947
318	CHI	54	FTI	40	FTI	18	LEE-WAR	UP	Meet UP 7921, Siding, Centerview
319	KCY	28	DSR	25	SYS	17	STL-STL	TR	Other late crew Late mark off of outbound conductor, and no conductors available on call. Wait for inbound 318 conductor to arrive in STL to double out and work 319 outbound. Delay for job briefing with outbound engineer and boarding train., Other, STL Station
1333	MSP	21	ENG	57	ENG	53	CHI-CHI	AM	Fuel Fuel at 620, 518

Amtrak Initial Terminal Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/1/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	448	07/31	18	18	Crew rest
BON	697	08/01	1	1	Meet Stop signal waiting on commuter to come in., keolis, Control Point, Station track 10
BOS	2293	08/01	13	6	Water, commissary, toilet/trash dumping, late a/c of station congestion and leaned in SHSY
BOS	2293	08/01	13	7	Door, 3703 NG NB, door issues on c/3703 & 3704
BRK	694	08/01	1		
MTR	68	08/01	1		
NFK	158	08/01	19	19	Late bulletins due to Amtrak cause
NYP	49	08/01	89	91	Other electrical failure, 714 DX DM, brake release indicator not going out when the brakes were released, pulling for power the engineer reported another fault on the motor.
NYP	69	08/01	2	2	Cross Traffic, NJT, NJ7825, Other, NYP-NYP, HELD A/C NJ7825 XINHG AHEAD
NYP	97	08/01	28	28	Water, commissary, toilet/trash dumping, mechanical assisting with a brake test.
NYP	103	08/01	121	121	Service, turn, or wye train, 144, LATE TURN OFF AM144
NYP	107	08/01	91	91	Service, turn, or wye train, 106
NYP	291	08/01	42	42	Service, turn, or wye train, 240
PGH	42	08/01	3	3	Train 40 was late... came in while we were boarding. People needed to get their checked bags onto our connected train. Last person was transferring a bike. I told the AC to meet them up there.. not enough room for full explanation here ask conductor
PHL	144	08/01	118	29	Service, turn, or wye train, 179, late turn off 179
PHL	144	08/01	118	89	Service, turn, or wye train, 179, late turn off 179
PHL	151	08/01	1	1	Passenger and/or baggage
PHL	611	08/01	2	2	PTC - Stop Bypass Permission Required, Control Point, ., stop bypass 2x
WAS	106	08/01	100	100	Service, turn, or wye train, 144, 144 ARRIVED LATE IN NYP DUE TO ENG ISSUE. 308 THE MTR HAD TO CAPPED. DELAYED 103 OUT OF THE S&I
WAS	162	08/01	8	8	Removal of passenger by police, APD REMOVED TRESPASSAR FROM LOCATION B, TRESPASSAR REFUSED TO GET OFF TRAIN
WAS	168	08/01	1	1	Door, 43366 AX MF, DOOR ISSUE CLOSING AT DP TIME
WAS	2250	08/01	5	5	Air / Brake / Wheel, ., LATE RELEASE OF EQUIPMENT
WAS	2262	08/01	19	19	Service, turn, or wye train, 2255, 2255 26" delay out of Wilmington with door issues.
CDL	390	08/01	16	16	Blocked from station track cn 2026, Other, carbondale station

Amtrak Initial Terminal Details

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/1/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	59	08/01	70	70	Service, turn, or wye train 59, Yard crew had to put on an engine for our train 59. Amtk374
CHI	307	08/01	197	197	Service, turn, or wye train 365
CHI	339	08/01	111	111	Service, turn, or wye train 338
CHI	364	08/01	11	11	Loading problem 58, ID4605
CHI	1333	08/01	53	53	Fuel Fuel at 620, 518
MKE	338	08/01	81	81	Service, turn, or wye train 335
MSP	1340	08/01	1		
PNT	351	08/01	50	50	Service, turn, or wye train 354, Trespasser strike with the crew of 354
STL	311	08/01	1	1	Meet amt 22, Other, stl station
BFD	717	08/01	9	9	Hold for thruway bus
GTA	782	08/01	2	2	Meet 14, Control Point, CO 358
LAX	584	08/01	1	1	Meet Ahead to red at 5:10, 581, Control Point, terminal
OKJ	714	08/01	8	8	Wait for station track HELD IN YARD FOR 711 & 733 to work OKJ., 711, Control Point, MAGNOLIA
OKJ	716	08/01	11	11	PTC- IETMS recycle breaker to clear fault C6962
OKJ	742	08/01	1	1	Door C8204
PDX	28	08/01	60	60	Hold for connecting train Delay approved by management, 16 transfers. No eastbound trains for the next 2 days due to bridge construction., 14
SAC	737	08/01	1	1	Mobility Impaired Elderly, mobility impaired passenger arrived late to the platform. Extra assist needed to board.
SAC	747	08/01	1		
SEA	8	08/01	128	3	Follow Waiting for oil train clear king st tunnel, BNSF, Control Point, south portal
SEA	8	08/01	128	125	Service, turn, or wye train 7
SEA	516	08/01	6	6	Passenger and/or baggage Three carts of bags
SJC	746	08/01	22	22	Air / Brake C2106
SLO	794	08/01	3	3	Wait for station track AMTK 11, Control Point, CO 248
SPK	27	07/30	153	153	Late arrival of 7 into SPK

Eastern Region

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	99.4	99.4	94.8	166	1
CDOT	95.0	81.3	81.3	92.4	16	3
MARC	95.0	No Data	No Data	90.2	No Data	No Data
SEPTA	95.0	No Data	No Data	91.5	No Data	No Data
NJT-NED	95.0	98.0	98.0	88.6	195	4
NJT-SED	95.0	No Data	No Data	97.2	No Data	No Data

Operating Highlights

Train 89(01) North of Kingstree, SC - Freight Train Interference

02AUG26: Train 89(01) operating with engine 336, 7 cars, and 78 customers onboard was delayed 21 miles north of Kingstree, SC on the CSX Charleston subdivision meeting CSX M410-01 at milepost 352.9. Train 98(01) was delayed in addition holding at milepost 362.2 for the CSX freight and 89(01) to pass.

Train	Delay	Comment
89(01)	33"	
98(01)	25"	

Train 40(01) North of Winter Park, FL - Engine Failure

01AUG26: Train 40(01) operating with engines 15, 316, 10 cars, and 227 customers onboard was delayed 34 miles north of Winter Park, FL on the CFRC Orlando subdivision troubleshooting loss of tractive effort on lead unit 15 at milepost 751.4. The crew was able to ensure head end power was stable on trail unit 316 and worked with CNOC mechanical to resolve the tractive effort issue.

Train	Delay	Comment
40(01)	36"	

Train 2262(01) West of Newark, NJ - Engine Failure

01AUG26: Acela 2262(01) operating with power car 2136, 2144, and 186 customers onboard was delayed on the Amtrak NYP Line east of Ham interlocking at milepost 55.7 after 40 Office reported at 7:12 p.m. that the train did not have headend power and the pantographs were down. An Alstom tech was able to work with the crew to reset the equipment, raise the pantographs, perform a brake test, and proceed east at 7:20 p.m.

Train	Delay	Comment
2262(01)	35"	

Train 449(01) East of Springfield, MA - Freight Train Interference

01AUG26: Train 449(01) operating with locomotives 714-715-116, 7 cars and 113 customers was delayed 15 miles east of Springfield at MP 83 on the CSX Boston subdivision due to freight train interference meeting CSX M426-01 at CP 83. After M426-01 passed train 449(01) was able to occupy the single main line and proceed without further delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
449(01)	45"	

Train 49(01) New York, NY - Car Failure

01AUG26: Train 49(01) operating with locomotives 714-715-116, 7 cars and 182 customers was delayed at the initial terminal of New York due to brake indicators on the car consist not extinguishing in the yard. Mechanical was requested to assist in resolving the defect after the equipment was released. With the assistance of Mechanical the door issue was resolved, and the train was released from the yard and positioned in the station. The 182 customers were boarded and train 49(01) departed New York.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
49(01)	1'31"	Initial terminal delay

CSX Heat Orders - Weather

01AUG26: CSX has imposed heat orders in affect between 1pm and 7pm for the following subdivisions: Cumberland, Metropolitan, Old Main Line, Peninsula, Richmond Terminal, Auburndale, carters, Jacksonville Terminal, Nahunta, Sanford and NO&M.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(31)	35"	
41(31)	28"	
41(30)	09"	
98(01)	33"	
52(01)	08"	

Train 68(01) South of St-Lambert, QC - Weather

01AUG26: train 68(01) was delayed between MP2 and MP42 on the CN Rouses Point subdivision due to CN heat orders.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
68(01)	46"	

Train 240(01) Poughkeepsie, NY - Routing

01AUG26: Train 240(01) operating with locomotive 717, 5 cars, NPCU 9707 and 242 customers was delayed at Poughkeepsie Station holding for MN8819 and 233(01) to pass due routing delays resulting from single track operation between MP 61 and MP 72. After train 233(01) passed train 240(01) was able to proceed without further delay.

Due to the late operation of train 240(01) the equipment turn to train 291(01) at New York resulted in an initial terminal delay.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
240(01)	51"	
291(01)	44"	Initial terminal delay

Train 73(01) Salisbury, NC - Freight Train Interference

01AUG26: Train 73(01) operating with locomotives 1797-1869, 5 cars and 157 customers was delayed 10 miles east of Salisbury at MP 324 on the NS Montview-Salisbury subdivision for freight train interference following NS737 from Sharp to Duke.

Train	Delay	Comment
73(01)	33"	

Train 2255(01) East of Stamford, CT - Mechanical

01AUG26: Next Gen Acela 2255(01) operating with TS-28 stopped on the MNRR New Haven Line after receiving a service brake fault on PC 2144. Recovery from the brake fault required the crew to de-prepare and re-prepare the trainset. After the train was recycled the crew was able to perform a good Class II brake test and resume operations toward Stamford.

Train 2255(01) experienced door issues at Wilmington Station on the entire train consist. The crew de-prepared and re-prepared the trainset to resolve the door problems and were able to proceed once resolved.

Due to the late operation of train 2259(01) the equipment turn in Washington caused an initial terminal delay to train 2262(01).

Train	Delay	Comment
2255(01)	27"	WIL doors
2255(01)	43"	STM brakes
2262(01)	19"	Initial terminal delay

Train 98(01) South of Sebring, FL - Freight Train Interference

01AUG26: Train 98(01) operating with locomotives 10-121, 10 cars and 151 customers was delayed 24 miles south of Sebring at MP 891 on the CSX Auburndale subdivision due to CSX freight M452-01 crew expired on hours of service and being tied down on the single main line at SE Plains. Once a recrew arrived they were able to pull train M452-01 into the siding at Plains allowing train 98(01) to operate past on the main line.

Train	Delay	Comment
98(01)	49"	

Train 97(31) South of Florence, SC - Vehicle on Tracks

01AUG26: Train 97(31) operating with locomotives 37-326, 11 cars and 275 cars onboard was delayed 7 miles south of Florence at MP 299 on the CSX Charleston subdivision due to a tractor trailer pulling a low boy high centering the trailer on the crossing at MP 305. A local tow recovery service was contacted to respond to remove the trailer from the crossing. After the trailer was removed and the tracks were inspected train 97(31) was able to depart without further delay.

Train	Delay	Comment
97(31)	1'54"	

Train 54(01) South of Baltimore, MD - Animal Strike

01AUG26: At 7:46 am-26-F01-00636 0000008475 UNCLASSIFIED 8/3/2026 Train 54(01) operating with locomotive 642, 6 cars and 231 customers was delayed south of Baltimore at MP 116 on the Amtrak PW Line after striking a deer. Upon impact locomotive 642 shut down and the pantographs dropping causing a loss of HEP. The crew inspected the equipment and were able to recycle the locomotive to allow the pantographs to raise and HEP functionality to become restored at 8:00 am-et. The crew performed a good Class II brake test and were able to resume operations toward BWI.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
54(01)	25"	

Train 144(01) East of Philadelphia, PA - Engine Failure

01AUG26: Train 144(01) operating with locomotives, 663-608-603, 8 cars and 208 customers was delayed 3 miles east of Philadelphia at MP 85 on the NYP line due to smoke coming from the rear locomotive. The train stopped and the crew inspected the equipment and found a stuck parking brake on the rear locomotive 603. Upon releasing the parking brake the crew confirmed good brake pipe continuity with a Class II brake test and were able to resume operations proceeding toward Trenton.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
144(01)	31"	

Train 144(01) Philadelphia, PA - Initial Terminal Delay

01AUG26: Train 144(01) operating with locomotives 663-608-603, 8 cars and 208 customers was delayed at the initial terminal of Philadelphia due to the arrival of inbound train 179(31) operating 2'48" late arriving Philadelphia at 4:27 am-et. The equipment was released from Mechanical at 7:00 am-et and waited for the yard crew that went on duty at 7am to move the equipment. The equipment departed the yard at 7:39 am-et and arrived the station at 7:54 am-et. Upon arrival into the station the 208 customers were boarded and train 144(01) departed Philadelphia.

Due to the late operation of train 144(01) the equipment turn in New York to train 103(01) resulted in an initial terminal delay to train 103(01).

Due to the late operation of train 103(01) the equipment turn in Washington to train 106(01) resulted in an initial terminal delay to train 106(01).

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
144(01)	1'58"	Initial terminal delay
103(01)	2'01"	Initial terminal delay
106(01)	1'40"	Initial terminal delay
107(01)	1'31"	Initial terminal delay

Train 97(31) Florence, SC - Engine Failure

01AUG26: Train 97(31) operating with engines 37, 326, 10 cars, and 275 customers was delayed departing Florence, SC on the CSX Charleston subdivision due to a fuel fault on engine 37. The crew worked with Siemens technicians to set the engine up as a control stand to proceed south. During the troubleshooting, headend power was dropped to ensure safe conditions for the crew. The temperature was 89 degrees and clear and customers were reported comfortable.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
97(31)	56"	

Maintenance of Way Highlights

16-FOI00636F0000008475"UNCLASSIFIED"9/2/2026

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00636 00000008475 "UNCLASSIFIED" 8/3/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	
284(26)	25"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00636a 00000008475 UNCLASSIFIED 18/12/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

Eastern Region

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
None				

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Eastern Region

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train 50(01) North of Indianapolis, IN - Signal

02AUG26: Train 50(01) was delayed beginning at MP8.7, 8.9 miles north of Indianapolis IN station on the CSX Indianapolis Terminal subdivision due to restrictive signals caused by vandals breaking into one of the bungalows and ripping everything out. Train 50(01) had to be talked by the signals at South Hunt and Woods at restricted speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(01)	31"	

Train 8(01) Seattle, WA - Initial Terminal Delay

02AUG26: Train 8(01), operating with engine 63, 7 coaches and 92 customers, was delayed departing Seattle, WA, on BNSF Scenic subdivision, due to late turn of train 7(30). Train 7(30) was delayed 1'41" out of Chicago, IL, and an additional 3'10" due to freight train delays throughout the trip. this caused 7(30) to arrive in Seattle 3'56" late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8(01)	2'08"	

Train 22(01) South of Little Rock, AR - Signal

02AUG26: Train 22(01) was delayed at MP352.9, 7.49 miles south of Little Rock AR station on the UPRR Little Rock subdivision due to restrictive signal at CP352. Train 22(01) stopped and then proceeded through the signal at restricted speed.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(01)	33"	

Train 6(31) Denver, CO - Engine Failure

02AUG26: Train 6(31) was delayed at Denver CO. Station/MP0.0 flat switching engines due to engine 176 setting off alarms for dynamic brakes. Engine 176 was moved the trail and engine 124 was moved to the lead due to the dynamic braking alarms. After flat switching the engines the crew performed routine inspections on the engines. Train 6(31) departed Denver CO. station 3 hours late at 959PM MT.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(31)	1'19"	

Train 8/28(30) West of Wisconsin Dells, WI - Freight Train Interference

02AUG26: Train 8/28(30) was delayed holding at MP224.1, 16.16 miles west of Wisconsin Dells station on the CPKC Tomah subdivision due to CPKC Freight I-68 activating a dragging equipment detector. The freight crew inspected and found no issues. Train 8/28(3) was back on the move at 958PM CT after the freight cleared the route.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(30)	45"	

Train 50(01) North of Crawfordsville, IN - Signal

02AUG26: Train 50(01) ~~26-FOI-00636~~ ~~00000008475~~ ~~UNCLASSIFIED~~ at MP136.9, 11.5 miles north of Crawfordsville IN station on the CSX Chicago subdivision due to restrictive signals caused by flash flood water shorting signals. Train 50(01) was talked by the signals at restricted speed until MP147.4.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
50(01)	39"	

Train 508(01) Portland, OR - Car Failure

02AUG26: Train 508(01), operating with Engine 1407, four coaches, and carrying 93 customers, experienced a delay departing Portland, Oregon, on the UPRR Brooklyn Subdivision due to an overinflated air bellow. The crew worked with CNOC Mechanical personnel to troubleshoot and correct the issue. During the troubleshooting process, Portland Mechanical personnel arrived on scene to provide additional assistance. Through their combined efforts, the air bellow was adjusted and brought back within compliance standards. Once the condition was corrected and the equipment was confirmed suitable for service, Train 508(01) was authorized to proceed and continued its scheduled operation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
508(01)	16"	

Train 307(01) Chicago, IL - Initial Terminal Delay

01AUG26: Train 307(01) was delayed departing Chicago IL station/MP0.0 due to a late turn of equipment off train 365(01). Original engine ID4605 that was intended for train 307(01) was used for train 364(01) due to 365(01) engine issues. Train 365(01) arrived to Chicago IL station at 800PM CT. Engine ID4607 required fueling and due to no fuel truck driver being on duty it was fueled at the fuel tower and was released at 855PM CT. Train 307(01) was release by yard mechanical at 934PM, wyed from the yard at 935PM CT and arrived to the station at 1011PM CT. Train 307(01) departed Chicago station 3 hours and 17 minutes late at 1027PM with 168 passengers on board.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
307(01)	3'17"	

Train 4(01) Barstow, CA - Police Related

02AUG26: Train 4(01), operating with engines 160/30, 9 coaches, and 246 customers, was delayed at Barstow, CA, on BNSF Cajon subdivision, due to police meeting the train to remove an unruly passenger from the train. Local police responded to resolve the situation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
4(01)	38"	

Train 749(01) Martinez, CA - Injured or Sick Passenger or Employee

01AUG26: Train 749(01) was delayed at CP52, 17 miles west of Ann Arbor MI station on the Amtrak Michigan Line for a meet with Amtrak 355(01). Train 749(01) was back on the move at 746PM ET after 355(01) cleared to the west. 01AUG26: Train 749(01) was delayed beginning at MP323, 38.22 miles west of Osceola IA station on the BNSF Ottumwa subdivision following BNSF Freight 6399. Train 5(01) followed BNSF Freight 6399 until MP 356.9 at which time they were able to get around the freight and resume operating at track speed.

Once the ambulance arrived, the customer was safely transferred to EMS personnel and transported to a local hospital for further medical evaluation and treatment. After emergency responders completed their work and the customer had been removed from the train, Train 749(01) was authorized to resume service and continued its trip. No other injuries or operational issues were reported in connection with the incident.

Train	Delay	Comment
749(01)	35"	

Train 352(01) West of Ann Arbor, MI - Passenger Train Interference

01AUG26: Train 352(01) was delayed holding at CP52, 17 miles west of Ann Arbor MI station on the Amtrak Michigan Line for a meet with Amtrak 355(01). Train 352(01) was back on the move at 746PM ET after 355(01) cleared to the west.

Train	Delay	Comment
352(01)	33"	

Train 8/28(30) West of Tomah, WI - Passenger Train Interference

01AUG26: Train 8/28(30) was delayed holding at MP280.1, 40.78 miles west of Tomah WI station on the CPKC Tomah subdivision meeting Amtrak 7/27(01). Train 8/28(30) was back on the move at 820PM CT after 7/27(01) cleared to the west.

Train	Delay	Comment
8/28(30)	33"	

Train 5(01) West of Osceola, IA - Freight Train Interference

01AUG26: Train 5(01) was delayed beginning at MP323, 38.22 miles west of Osceola IA station on the BNSF Ottumwa subdivision following BNSF Freight 6399. Train 5(01) followed BNSF Freight 6399 until MP 356.9 at which time they were able to get around the freight and resume operating at track speed.

Train	Delay	Comment
5(01)	33"	

Train 508(01) North of Oregon City, OR - Trespasser Incident

01AUG26: Train 508(01) operating with engine 1407, 4 coaches, and carrying 88 customers, became stopped north of Oregon City, OR at Milepost 760.7 on the UPRR Brooklyn Subdivision after the crew reported striking an unknown object. Upon inspection, the crew observed blood on the locomotive plow and began searching the area to determine the nature of the incident.

The investigation subsequently confirmed that Train 508(01) had fatally struck a trespasser. The incident did not occur at a grade crossing. Head End Power (HEP) remained active throughout the event, and no damage to the equipment was reported. Additionally, there were no injuries to the crew or any of the 88 customers on board. Weather conditions at the time were reported as 71 degrees and sunny. Local police, fire department personnel, and EMS responded to the scene, while a Road Foreman was dispatched and later arrived to provide assistance.

Train 508(01) remained stopped for approximately 1 hour and 20 minutes while emergency responders conducted their investigation. After the Medical Examiner completed their work and released both the train and crew, Train 508(01) was authorized to continue service. The train subsequently resumed movement with a total delay of approximately 2 hours and 20 minutes.

NRC Number 1469573

National Response Center Number: 1469573

Train	Delay	Comment
508(01)	2'20"	

Train 59(01) Chicago, IL - Initial Terminal Delay

01AUG26: Train 59(01) was delayed departing initial terminal of Chicago IL station due to a late turn of equipment off train 22(31). Train 59(01) turned off train 22(31) equipment due to train 1058(31) arriving to Chicago IL station 8 hours and 27 minutes late. Train 59(01) was made up complete in the yard at 546PM CT and set in the station at 638PM CT. Train 59(01) departed Chicago IL station at 715PM CT.

Train	Delay	Comment
59(01)	1'10"	

Train 777(01) West of Goleta, CA - Passenger Train Interference

02AUG26: Train 777(01), operating with engine 2122, 6 coaches, and 121 customers, was delayed 2 miles west of Goleta, CA, on UPRR Santa Barbara subdivision due to meeting train 794(01) at control point Ellwood.

Train	Delay	Comment
777(01)	36"	

Train 338(01) West of Milwaukee Mitchell Airport, WI - Freight Train Interference

01AUG26: Train 338(01) was delayed holding at MP83.6 5.7 miles west of Milwaukee Mitchell Airport WI on the CPKC C & M subdivision meeting CPKC Freight train 247/2. Train 338(01) was back on the move at 510PM CT after the freight cleared to the west.

Train	Delay	Comment
338(01)	30"	

Train 21(01) North of Joliet, IL - Freight Train Interference

01AUG26: Train 21(01) ~~26-FOI-00638-00000008475~~ ~~UNCLASSIFIED~~ ~~8/3/2026~~ began its delay 46 miles north of Joliet IL station on the CN Joliet subdivision due to flash flood warnings. Train 21(01) proceeded through the flash warning until MP36 and resumed operating track speed after.

Train	Delay	Comment
21(01)	39"	

Train 6(01) East of Reno, NV - Heat Restrictions

02AUG26: Train 6(01) operating with engines 40/179, 9 coaches and 151 customers, was delayed east of Reno, NV, on UPRR Nevada Subdivision, due to operating through speed restrictions beginning at milepost 250 and ending at milepost 421 and then again between milepost 535 and milepost 599.

Train	Delay	Comment
6(01)	1'37"	

Train 715(01) East of Turlock-Denair, CA - Engine Failure

01AUG26: Train 715(01), operating with Engine 2013, became stopped east of Turlock-Denair, CA, at milepost 1071.8, on BNSF Stockton subdivision, due to engine-related issues. Head End Power (HEP) remained active, but the crew was unable to resolve the engine faults. TASI Mechanical was consulted and advised the crew to allow the locomotive to cool before attempting another restart.

Despite multiple troubleshooting attempts and following the guidance provided by TASI Mechanical, the crew was unsuccessful in restoring the locomotive to service. As a result of the mechanical failure and the operational limitations of the single-track territory, a decision was made to combine Train 715(01) with Train 717(01) in order to continue service.

Train 717(01) arrived at the location of Train 715(01) and preparations began to couple the two trainsets. While the combination was being completed and the necessary hose connections were made, Train 716(01) was held at Turlock-Denair (TRK) awaiting an open route. Once the coupling process was completed and all required connections were secured, the combined 715/717(01) train departed and continued westbound, restoring service for the affected passengers.

Train	Delay	Comment
715(01)	Term MCD	
717(01)	57"	
716(01)	14"	
704(01)	35"	Meet 715/717(01)

Train 714(01) Stockton, CA - Engine Failure

01AUG26: Train 714(01) operating with engine 2003 initially became stopped at Stockton, CA, on BNSF Stockton subdivision, due to loading issues. The crew worked with TASI Mechanical to troubleshoot the problem while efforts were made to restore normal operation. During troubleshooting, the crew reported an engine coolant pressure fault, and an additional technician was dispatched to assist. Throughout the incident, HEP remained active.

After working with TASI Mechanical, the crew successfully restarted the locomotive and Train 714(01) resumed movement. However, shortly thereafter the train experienced the same loading issues and became stopped again East of Stockton, CA. The crew continued troubleshooting with TASI Mechanical, but due to the recurring nature of the engine problems, a contingency plan was developed to either return to Stockton, CA and transfer passengers to Train 716(01) if the locomotive could be restarted, or perform a train-to-train transfer at the current location with train 716(01) if it could not.

Train 714(01) ultimately returned to Stockton, CA and a customer transfer was conducted upon the arrival of Train 716(01). Once the transfer was completed, Train 716(01) departed with the customers. TASI Mechanical personnel were on scene, and the equipment from Train 714(01) was subsequently deadheaded to OKJ for repairs.

As a result of the mechanical issues involving Engine 2003, Train 713(02) was canceled and no alternate service was provided. Affected customers were accommodated on Train 715(02).

Train	Delay	Comment
716(01)	12"	Receive 714(01) customers
714(01)	Term SKN	

Train 710(01) Wasco, CA - Police Related

02AUG26: Train 710(01) operating with engine 2107, 6 coaches, and 146 customers, was delayed at Wasco, CA, on BNSF Bakersfield subdivision, due to police meeting the train to remove passengers who had become unruly and were involved in an altercation. Local police responded to the train and removed the passengers in question.

Train	Delay	Comment
710(01)	30"	

Train 5(30) West of Elko, NV - Heat Restrictions

01AUG26: Train 5(30) was delayed starting at Elko, NV/ MP 557.0 on the UPRR Elko Subdivision due to heat restrictions put in place by the UPRR. The crew operated at restricted speed starting at Elko through to Winnemucca, NV/ MP 417.2 on the UPRR Nevada Subdivision not exceeding 50 MPH. Once through the affected area, Train 5(30) was able to proceed at track speed.

Train	Delay	Comment
5(30)	1'40"	

Train 28(01) Portland, OR - Initial Terminal Delay

02AUG26: Train 28(01) operating with engine 335, 4 coaches and 125 customers, was delayed departing Portland, OR, on UP Brooklyn subdivision, due to holding for 21 connecting customers from train 14(29). Train 14(01) arrived in Portland at 5:24pm-pt, approximately 40" after trains 28(01) departure time.

Train	Delay	Comment
28(01)	1'00"	

Train 335(01) East of Milwaukee Mitchell Airport, WI - Bridge Strike

01AUG26: Train 335(01) was delayed at 12.5 miles east of Milwaukee Mitchell Airport, WI (MP78.4), on the CPRR C&M Subdivision at MP75.9 due to a reported bridge strike ahead at MP76.73. A bridge inspector responded to the location, inspected the bridge, and released it for train operations. Upon receiving clearance, Train 335(01) was released to proceed and continued its trip to Milwaukee.

Train 338(01) was delayed departing Milwaukee, WI (MP85.4), on the CPRR C&M Subdivision, due to a late turn of Train 335(01) that arrived at 409PM CT, 1 hour and 25 minutes late.

Train 339(01) was delayed departing Chicago IL. I (MP0.0), due to a late turn of Train 338(01) that arrived at 636PM CT, 2 hours and 07 minutes late.

Train	Delay	Comment
339(01)	1'51"	Late Turn
335(01)	1'23"	
338(01)	1'21"	Late Turn

Train 770(01) East of San Juan Capistrano, CA - Commuter Train Interference/ Passenger Train Interference

01AUG26: Train 770(01) was delayed at MP 199.8, 2 miles east of San Juan Capistrano, CA, on the Metrolink Orange Subdivision due to meet with Metrolink 1663. Once the Metrolink cleared, Train 770(01) was further delayed holding for Train 573(01). Once route was clear, Train 770(01) proceeded east.

Train	Delay	Comment
770(01)	15"	Train 573(01)
770(01)	15"	Metrolink 1663

Train 5(31) East of Fraser-Winter Park, CO - Freight Train Interference

01AUG26: Train 5(31) held 12.2 miles east of Fraser-Winter Park, CO (MP62.3), on the UPRR Moffat Tunnel Subdivision, at East Portal (MP50.1) in order to meet eastbound UP 6020.

Train	Delay	Comment
5(31)	33"	

UPRR Niles Subdivision - Hayward Signal Issues

01AUG26: At 7:48A-PT, the UPRR reported a track light at MP 20.2/Hayward, CA on the Niles Subdivision. Multiple trains were delayed flagging through affected area until issue was resolved. Train 723(01) was first through the area.

Train 727(01) was also delayed operating through the affected area hold for Train 724(01) to flag through.

Train	Delay	Comment
724(01)	09"	
723(01)	23"	
727(01)	24"	

Train 7(30) West of Ephrata, WA - Freight Train Interference

01AUG26: Train 7(30) was delayed starting at MP 1635.6, 33.7 miles west of Ephrata, WA, on the BNSF Columbia River Subdivision due to BNSF freight S-CHCTAC1-26A ahead actuating a high-wide detector at MP 1633.7. The crew held while the freight crew inspected consists for issues. Once freight was inspected and cleared route, Train 7(30) followed freight until MP 1644.5 where they held for a freight to clear the yard. Once route was clear, Train 7(30) proceeded west.

Train	Delay	Comment
7(30)	1'38"	

Train 21/421(31) Marshall, TX - M of W Work

01AUG26: Train 21/421(31) was delayed at Marshall, TX (MP66.5), on the UPRR Little Rock Subdivision due to a possible issue with the frog at Keokuk (MP76.20). A UP freight train traversed the area and reported the condition, requiring Maintenance of Way personnel to respond and inspect the location. Maintenance of Way responded and placed a 10MPH speed restriction over the area. Train 21(31) was then released to continue south.

Train	Delay	Comment
21/421(31)	1'01"	

Train 5(30) West Salt Lake City, UT - Signal Issues

01AUG26: Train 5(30) was delayed starting at MP 798.0, 53 miles West of Salt Lake City, UT, on the UPRR Shafter Subdivision due to signal issues. There was signal issues at Pilot/ MP 788.4. The crew held while UPRR freight INPOA-30 worked through signal issues further complicated by flash flood warnings. Once freight was through affected area, the crew then stopped and flagged through signal issues. Once Train 5(30) was through the affected area, they were further delayed at Shafter/MP 767.1 for meet with freight. Once tracked were clear, Train 5(30) proceeded west.

Train	Delay	Comment
5(30)	1'54"	
5(30)	31"	Meet with INPOA-30

Train 40(30) Pittsburgh, PA - Cab Signal Failure

01AUG26: Train 40(30), E/78-E/82-10 cars, was delayed at Pittsburgh, PA (MP353.1) on the NSRR Pittsburgh Subdivision after a cab signal failure was reported on lead locomotive 78. Permission was granted to proceed with the cab signals cut out through cab signal territory to Cleveland, and the train continued operation.

Train	Delay	Comment
40(30)	12"	PGH
40(30)	1'04"	PGH-CLE Cutout

Train 1333(01) Chicago, IL - Fueling Delay

01AUG26: Train 1333(01), E/518-3 cars, was delayed departing Chicago Union Station, IL, after the equipment was required to return from the station to the yard for fueling. Train 1333(01) and Train 1340(02) operated with a single locomotive due to a lack of available units in Chicago. After the locomotive was fueled, Train 1333(01) departed Chicago Union Station.

Train	Delay	Comment
1333(01)	52"	

Train 350(01) West of Jackson, MI - Passenger Train Interference

01AUG26: Train 350(01) held 20.5 miles west of Jackson, MI (MP75.5), on the Michigan DOT Michigan Line, in order to meet Train 353(01) at Albion (MP96.2).

Train	Delay	Comment
350(01)	30"	

Train 7/27(30) East of Libby, MT - Freight Train Interference

01AUG26: Train 7/27(30) was delayed at Brimstone/MP 1251.8, 68 miles east of Libby, MT, on the BNSF Kootenai Subdivision due to freight interference. The crew held at Brimstone for BN8190 to clear then proceeded west.

Train	Delay	Comment
7/27(30)	32"	

Train 6(31) West of Salt Lake City, UT - Freight Train Interference

01AUG26: Train 6(31) was delayed starting at Silver Zone/ MP 771.8, 130 miles West of Salt Lake City, UT, on the UPRR Shafter Subdivision due to freight interference. The crew held at Silver Zone for UP5745 to clear route then advanced to Clifside/MP 780.3 for UP8097 to clear. Once tracks were clear, Train 6(31) proceeded east.

Train	Delay	Comment
6(31)	39"	UP8097
6(31)	09"	UP5745

Train 21(31) South of Texarkana, AR - Freight Train Interference

01AUG26: Train 21(31) was held 1.6 miles south of Texarkana, AR (MP0.0), on the UPRR Little Rock Subdivision at MP1.6 due to UP 5366 stopped ahead repairing a broken knuckle at National Jct (MP1.8). After the knuckle was repaired and the freight train cleared the main line, Train 21(31) was released to continue south. Additional freight interference delays were incurred en route to Marshall while meeting UP 5271 at Queen City (MP19.7), UP 7639 at Bivins (MP30.4), and UP 5764 at Jefferson (MP49.4).

Train	Delay	Comment
21(31)	15"	Queen City
21(31)	12"	Bivins
21(31)	57"	National Jct
21(31)	21"	Jefferson

Train 2/422(31) West of Maricopa, AZ - Freight Train Interference

01AUG26: Train 2/422(31) was delayed starting at Gila Bend/MP 857.4, 40 miles west of Maricopa, AZ, on the UPRR Gila Subdivision due to freight interference. The crew followed UP5484 from MP 857.4 to Estrella/MP 876.2 where they were able to operate around.

Train	Delay	Comment
2/422(31)	47"	

Train 383(01) and 380(02) Chicago, IL - Engine Failure

01AUG26: Due to a lack of available equipment, Trains 383(01) and 380(02) were canceled in their entirety with two alternate buses were secured to provide transportation for affected customers. For Train 383(01), Bus #1 operated from Chicago Union Station to Macomb and Quincy, while Bus #2 operated all intermediate stops between Chicago Union Station and Quincy. These same buses were scheduled to turn and operate as Train 380(02), with Bus #1 operating from Quincy to Macomb and Chicago Union Station and Bus #2 operating all intermediate stops.

WBS#: B.TR.100150.6970

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
383(01) and 380(02)	Cancelled	

Train 365(01) West of Port Huron, MI - Engine Failure

01AUG26: At 6:25AM-ET, Train 365(01), powered by E/ID4630-6 Cars-E/ID4607, stopped approximately 0.4 miles west of Port Huron, MI (MP 334.3) on CNRR Strathroy Subdivision at MP 333.9 after both locomotives shut down, resulting in a loss of Head End Power (HEP). There were 35 customers onboard, and the outside temperature was 71 degrees. The crew contacted CNOC Mechanical and the Road Foreman for troubleshooting assistance. At 7:00AM-ET, HEP was restored on locomotive ID4607. Mechanical personnel then worked to configure locomotive ID4630 as the controlling unit. Once those efforts were completed, Train 365(01) resumed westward movement at 7:15AM-ET.

At 7:35AM-ET, Train 365(01) stopped again at MP317.1 with the same issue and loss of HEP. At 8:04AM-ET, HEP was restored to the trainset. The crew continued to troubleshoot with CNOC and Siemens mechanical. The decision was made to reverse back to Port Huron arriving at 9:47AM-ET where the train was terminated. The customers detrained and held in the lobby until the bus arrived at 11:30AM-ET to continue to their final.. The equipment was wyed and was able to deadhead to Chicago for repair.

Train 351(01) assisted Train 365(01)'s customers boarding at Battle Creek, MI and made a special stop at New Buffalo to detrain one customer. All other customers were handled by alternate buses. Bus#1 operated Lansing to Chicago express. Bus#2 operated Lansing, Dowagiac, Niles to Chicago. Bus#3 operated Port Huron, Flint, Chicago. Bus#4 operated Lapeer, Durand, Battle Creek, Chicago. Bus#5 operated New Buffalo to Chicago. Bus#6 operated Kalamazoo to Chicago.

WBS#: B.TR.100150.6971

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
365(01)	3'27"	Total Delay on Train to Customers
365(01)	TERM PTH	

Train 7/27(31) East of Staples, MN - Trespasser Incident

01AUG26: At 2:30A-CT, ~~26:FDL-00636~~ ~~00000008475~~ E/5 - ~~UNCLASSIFIED~~ cars, ~~8/3/2026~~ at into emergency at MP 116.7, 42 miles east of Staples, MN, on the BNSF Staples Subdivision after striking a vehicle and a person. No injuries were reported to the crew or 125 customers on board. Head end power remained on and active, however upon inspecting the equipment, the crew found plow damage on lead locomotive E/5. Local authorities were notified and responded to the scene. The trespasser was transported from scene by local EMS. Crew requested relief and relief crew on duty at 4:30AM-CT in Saint Cloud. BNSF mechanical responded to the scene, arriving at 6:30A-CT to trim the plow. The track inspector arrived on scene and cleared tracks for movement once mechanical completed work. Once recrow arrived on scene and BNSF mechanical completed trimming the plow, Train 7/27(31) was able to proceed west at 6:54AM-CT.

Due to the late operation of Train 7/27(31), and the expected additional 2'00" to 3'00" of delay anticipated from BNSF heat restrictions west of Minot, ND between Williston, ND and Malta, MT, the following Empire Builder service adjustments are being implemented;

- Train 7(31) will terminate at Spokane, WA; alternate transportation secured between Spokane and Seattle, WA
- Train 8(02) will originate at Spokane, WA; alternate transportation secured between Seattle, WA and Spokane
- Train 27(31) will terminate at Spokane, WA; alternate transportation secured between Spokane and Portland, OR (previously planned due to scheduled trackwork on the BNSF Fallbridge Subdivision)
- Train 28(02) will originate at Spokane, WA; alternate transportation secured between Portland, OR and Spokane (previously planned due to scheduled trackwork on the BNSF Fallbridge Subdivision)

NRC: 1469500
MN state: 234610

National Response Center Number: 1469501

Train	Delay	Comment
7/27(31)	4'33"	
7(31)	Term SPK	
8(02)	Orig SPK	

Train 22(31) South of Walnut Ridge, AR - Passenger Train Interference

01AUG26: Train 22(31) held 1.4 miles south of Walnut Ridge, AR (MP224.9), on the UPRR Hoxie Subdivision, at Y226 (MP226.3) in order to meet Train 21(31).

Train	Delay	Comment
22(31)	31"	

Train 551(31) Emeryville, CA - vehicle on tracks ahead.

01AUG26:
Train 551(31) was held at Emeryville (EMY) after a vehicle was reported on the tracks at Oakland, CA, resulting in an estimated 60-minute delay. At the time, there were two customers on board the train. Subsequently, all customers from Trains 719(31) and 551(19) made their own transportation arrangements to OKJ. Due to the ongoing situation, both trains were terminated at EMY and moved into the yard. Operations remained suspended pending inspection and resolution of the track obstruction.

Train	Delay	Comment
551(31)	Term EMY	
719(31)	Term EMY	

Train 1058(31) South of Carbondale, IL - Engine Failure

01AUG26: At 12:27AM-CT, Train 1058(31) CN 504-7, stopped 35 miles south Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision, at Wetaug (MP343.) after engine 504 lost tractive effort. There was also a loss of head end power for 30 minutes from 1:00AM-CT until 1:30AM-CT with 139 customers onboard. The crew contacted CNOC Mechanical to troubleshoot the issue. Mechanical personnel were able to walk the crew through the steps to restore head end power; however, they were unable to restore tractive effort due to a blown fuse. Freight locomotive CN 2026 was sourced at Carbondale but could not be utilized due to PTC issues. St. Louis Mechanical subsequently arrived at the train, successfully changed out the fuse, and completed a load test. As a precaution, a southbound grain train cut freight locomotive CN 8958 at Wetaug to add ahead of Train 1058(31). Once this was completed, Train 1058(31) resumed movement toward Chicago Union Station at 8:41AM-CT. Service recovery was enacted with snack packs, bottled water, coffee, tea, coffee cakes, and muffins provided to all Coach customers. First Class customers continued to receive breakfast from the dining car as normal.

Train 390(01) was delayed departing Carbondale, IL (MP308.3), on the CNRR Centralia Subdivision, due to CN 2026 blocking the station track. Once the freight locomotive was moved, Train 390(01) was able to complete the move to the station, board 50 customers, and depart 16 minutes late.6 minutes late.

WBS#: B.TR.100150.6972

Train	Delay	Comment
1058(31)	8'33"	

Train 3(30) West of Winslow, AZ - Freight Train Interference

01AUG26: Train 3(30) was delayed beginning 26 miles west of Winslow, AZ (MP285.5) on the BNSF Seligman Subdivision while following BNSF Train 6123 from MP311.9 to East Flagstaff (MP340.8). Additional delay was incurred at East Flagstaff while meeting an eastbound BNSF freight train. Once the meet was completed, Train 3(30) experienced further delay while following an unspecified BNSF freight train beginning 15.5 miles west of Flagstaff, AZ (MP344.2), from MP359.7 to West Crookton (MP420.5). Once on the move, Train 3(30) proceeded to Peach Springs (MP467.7) to meet their recrew and pilots from Kingman. Once the fresh crew was onboard, Train 3(30) was able to proceed west.

Due to the late operation, service recovery was provided. Complimentary snack packs, bottled water, coffee and tea were provided to all customers. Customers connection to Train 14(01) were provided a lunch bag consisting of a sandwich, chips and a beverage.

Train	Delay	Comment
3(30)	1'03"	Follow BN 6123
3(30)	28"	Meet East Flagstaff
3(30)	1'17"	Follow W/FLG
3(30)	13"	Recrew

Train 354(31) East of Pontiac, MI - Trespasser Incident

01AUG26: Train 354(31) with engine 4626 and 4633, went into emergency south of Pontiac, Michigan, on the CN Holly Subdivision after striking a trespasser at Mile Post 25.5. At the time of the incident, the two locomotives were performing a wye move in preparation for morning service. There were no customers onboard. No injuries were reported to the crew, and no damage was reported to the equipment. Local authorities were notified and responded to the scene.

Train 351(01) was designated as the relief crew for Train 354(31). The incident was determined to be non-fatal, and the trespasser was transported to a local hospital for treatment. Operations remained on hold while awaiting the arrival and investigation of CN Police. The scene was released at 3:52 a.m. ET. A recrew reported for duty at 4:28 a.m. ET and completed the wye move, allowing the equipment to be properly positioned for scheduled morning service.

Update: Train 351(01) was delayed departing its initial terminal from Pontiac, MI (MP25.9), on the CNRR Holly Subdivision, while awaiting the equipment to be wyed and released by Mechanical. Once the equipment was released and ready for service, Train 351(01) departed Pontiac 50 minutes late.

National Response Center Number: 1469500

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(31)	50"	ITD PNT

Train 14(31) North of Martinez, CA - Drawbridge Opening

01AUG26: Train 14(31) was delayed at MP 32.7, 1 miles north of Martinez, CA, on the UPRR Martinez Subdivision holding for Suisun Bridge opening. Once maritime traffic cleared and the bridge was lowered, Train 14(31) was able to proceed north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
14(31)	44"	

Train 21(31) north of Arcadia, MO - Weather

01AUG26: Train 21(31) was delayed beginning at MP41.0, 47.22 miles north of Arcadia, MO station on the UPRR Desoto subdivision due to flash flood warnings. Train 21(31) operated through the warnings until MP79.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
21(31)	1'30"	
1(01)	1'07"	Held for connections

Train 383(31) Kewanee, IL - Engine Failure

01AUG26: Train 383(31) operating with engine 504, 4 coaches and 8 passengers lost head end power at Kewanee IL station on the BNSF Mendota subdivision. Crew called into CNOC mechanical to troubleshoot issues. CNOC mechanical had the crew short loop the engine to restore head end power but were unsuccessful. The weather was in the low 70s and clear. Train 383(31) operated dark all the way to Quincy IL Station. Quincy mechanical was on scene when the train arrived at 1247AM CT. Quincy mechanical was unable to repair engine 504 as a result train 380(01) was cancelled in it's entirety with no alternate transportation.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
380(01)		Cancelled
383(31)	34"	KEE

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures in the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

25JUL26: Train 7(23) arrived into Seattle, WA 2'46" late causing late departure of 8(25). Train 27(23) arrived into Portland, OR 3'51" late causing late departure of 28(25).

25JUL26: Temperatures continue to be in excess of 100°F in the Great Plains. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow, Milk River and Hi-Line Subdivision from Stanley, ND and Cutbank, MT. Train 7 / 27(24) and Train 8 / 28(24) were affected by the restrictions and freight interference caused by the restrictions.

Due to late operation of 7/27(24) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(24) from Spokane to Seattle and for 27(24) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(26) Seattle to Spokane and 28(26) Portland to Spokane with Train 8/28(26) originating Spokane, WA.

27JUL26: Due to late operation of 7/27(25) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(25) from Spokane to Seattle and for 27(25) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(27) Seattle to Spokane and 28(27) Portland to Spokane with Train 8/28(27) originating Spokane, WA.

WBS#: B.TR.100150.6937

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	
8/28(24)	2'16"	
7/27(24)	2'20"	Term SPK
28(25)	57"	late turn 27(23)
8(25)	2'00"	late turn 7(23)
7/27(25)	2'26"	Term SPK
8/28(27)		Orig SPK
8/28(25)	1'46"	
8/28(26)	1'16"	Orig SPK
7/27(26)		Term SPK
8/28(28)		Orig SPK
8/28(27)	2'15"	Orig SPK
8/28(28)	1'46"	Heat restrictions MAL-WTN
8/28(28)	1'31"	Frt congestion due to heat restrictions
7(31)	30"	WPT - GGW
7(31)	1'02"	WTN - WPT
8/28(01)	2'43"	MAL - GGW

Maintenance of Way Highlights

Burlington Northern Santa Fe Fallbridge Subdivision between Portland, OR and Spokane, WA - Scheduled M/W Work TWA 26-078

02AUG26: Burlington Northern Santa Fe will have a 36-hour outage affecting the Empire Builder service starting at 5:00A-PDT. They will be performing bridge work, slide fence replacement and switch maintenance at Bingen / MP 77.0 on the Fallbridge Subdivision.

To accommodate the above outlined infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(31JUL, 01AUG) will terminate at SPK.
- Train 28 (02AUG, 03AUG) will originate at SPK.

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between SPK and PDX making all stops except WIH.
- Bus 4028 will provide alternate transportation between PDX and SPK making all stops except WIH.

EQUIPMENT

- Equipment for Train 27(31Jul, 01AUG) will stay coupled to Train 7 at SPK
- Equipment for Train 28(02AUG, 03AUG) will be coupled to Train 8 departing SEA

WBS#: B.TR.100150.6891

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

-Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track "UNCLASSIFIED" project 8/3/2026 multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,

Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,

Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,

Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,

Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,

Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,

Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,

Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,

Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

Western Region

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Equipment Set Out & Damage Disposition

Train	Location	Eng	Car	Reason/Disposition
4 (20)	ABQ	76		Mu issues

Leased Freight Locomotives

Train	Location	Eng	Purpose	Location Returned	Date Returned
None					

Pair Only Locomotives

Loco	Date Failed	Train Failed	Failure	Date OK'd as single	OK'd as single by:
None					

Western Region

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00636

00000008475

"UNCLASSIFIED"

8/3/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
135 (01)	BOS	business class in lieu of coach. inventory reduced by 10 seats, no overages.	no impact	0	81522
135 (01)	BOS	using a biz coa in lieu of coa.. no impact to passengers			81522
41 (03)	CHI	VII sleeper in lieu of VI. schedule change performed for 4111 car. check war report.	No impact	0	62506
59 (01)	CHI	Operating with diner in lieu of diner/lounge.	No impact	0	38041
59 (02)	CHI	Operating with Sleeper in lieu of T-Dorm. CNOC Csv will need to block all DS/FS/HS rooms. Schedue changed been performed.	BLOCKED	0	32097
672 (01)	HAR	No cab car or cafe car to provide wifi. no impact on ridership	No impact	0	82586
562 (01)	LAX	NO BIKE SPACE!	Passengers notified	2	9700
580 (01)	LAX	NO BIKE SPACE!	Passengers notified	1	9700
566 (01)	LAX	NO BIKE SPACE!	Passengers notified	2	90225
584 (01)	LAX	NO BIKE SPACE!	No impact	0	90225
562 (02)	LAX	NO BIKE SPACE DUE TO HAVING CAR 90225.	No impact	0	90225
580 (02)	LAX	NO BIKE SPACE DUE TO CAR 90225 IN CONSIST.	Passengers notified	1	90225
566 (02)	LAX	NO BIKE SPACE DUE TO CAR 9700 BEIN IN CONSIST.	Passengers notified	2	9700
584 (02)	LAX	NO BIKE SPACE DUE TO CAR 9700 BEING THE IN CONSIST.	Passengers notified	2	9700
40 (01)	MIA	VIEW LINER 2 IN LIEW OF VIEW LINER 1 FOR THE 4011 CAR. SCHEDULE CHANGE HAS BEEN COMPLETED. CHECK WAR REPORT.	No impact	0	62506
164 (01)	NPN	CAFE-CLUB DINETTE IN LIEU OF TABLE CAR.	No impact	0	48147
153 (01)	NYP	BUSINESS CLASS CAR IN LIEU OF A COACH CAR.	No impact	0	81521
663 (01)	NYP	NO CAB CAR/ NO WIFI. 5TH COACH ADDED NOT OVER CAP.	Passengers notified	291	655
155 (01)	NYP	2ND BUSINESS CLASS CAR IN LIEU OF COACH, INVENTORY	No impact	0	81XXX

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
		26-FOI-00636 00000008475 "UNCLASSIFIED"			
		REDUCED, NO OVERAGES.			
43 (01)	NYP	WILL BE OPERATING WITH A COACH IN LIEU OF A BUSINESS CLASS. PLEASE NOTIFY PAX.			25083
150 (01)	PHL	business class in lieu of coach. inventory reduced by 10 seats, no overages.	No impact	0	81522
155 (01)	PHL	all table lounge added behind the 48xxx business class to provide food service due to b/o re Fridgeration on the CD.	No iimpact	0	43XXX
150 (01)	PHL	using a biz coa in lieu of coa.. no impact to passengers			81522
573 (01)	SAN	NO BIKE SPACE!	No impact	0	9700
591 (01)	SAN	NO BIKE SPACE!	Passengers notified	2	9700
579 (01)	SAN	NO BIKE SPACE!	Passengers notified	1	90225
595 (01)	SAN	NO BIKE SPACE!	No impact	0	90225
573 (02)	SAN	NO BIKE SPACE DUE TO CAR 90225 IN CONSIST.	Passengers notified	4	90225
591 (02)	SAN	NO BIKE SPACE DUE TO CAR 90225 IN CONSIST.	Passengers notified	1	90225
579 (02)	SAN	NO BIKE SPACE DUE TO CAR 9700 BEING THE IN CONSIST.	No impact	0	9700
595 (02)	SAN	NO BIKE SPACE DUE TO CAR 9700 BEING THE IN CONSIST.	Passengers notified	1	9700
8 (02)	SPK	Operating with diner in lieu of diner/lounge.	No impact	0	38028

Reverse Consists

Train Number	Station	Reason
109 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
101 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front
127 (01)	NYP	Consist reversed Business class seat orientation may have changed At Rear
150 (01)	PHL	Consist reversed Business class seat orientation may have changed At Front
103 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00636	00000008475 "UNCLASSIFIED" 8/3/2026
106 (01)	WAS	Consist reversed Business class seat orientation may have changed At Rear	
107 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front	
135 (01)	BOS	Consist reversed Business class seat orientation may have changed At Front	
153 (01)	NYP	Consist reversed Business class seat orientation may have changed At Front	
158 (02)	NFK	Consist reversed Business class seat orientation may have changed At Front.. **Train 158(02)**	
142 (01)	WAS	Consist reversed Business class seat orientation may have changed At Front	