



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Monday, August 03, 2026

Rules: 0-44



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

26-FOI-006Initial Terminal Performance By Division

Scheduled Departure Date:	08/02/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/02/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	43	85.1%	572	87	84.8%	91,516	12,643	86.2%
Central Division	86.0%	54	7	87.0%	110	17	84.5%	17,538	1,591	90.9%
East Division	82.0%	156	20	87.2%	299	41	86.3%	47,969	7,463	84.4%
West Division	86.0%	79	16	79.7%	163	29	82.2%	26,009	3,589	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00636 00000008476 "UNCLASSIFIED" 8/3/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	109,978	27,501	75%	222,346	53,295	76%	30,571,364	7,693,301	75%
Northeast Corridor	81%	45,581	9,062	80%	93,362	15,171	84%	13,404,090	3,271,949	76%
Acela	83%	9,670	1,824	81%	16,284	2,856	82%	2,677,196	704,505	74%
Northeast Regional	79%	35,911	7,238	80%	77,078	12,315	84%	10,726,894	2,567,444	76%
Richmond / Newport News / Norfolk	77%	11,582	3,459	70%	24,371	4,281	82%	3,330,572	966,697	71%
Springfield Shuttles	89%	724	67	91%	1,294	67	95%	190,043	30,154	84%
Roanoke	79%	2,772	110	96%	7,340	443	94%	1,012,852	218,904	78%
On Spine Northeast Regional	80%	20,833	3,602	83%	44,073	7,524	83%	6,193,427	1,351,689	78%
State Supported	80%	49,714	10,087	80%	101,237	22,339	78%	13,416,027	2,825,173	79%
Borealis	80%	600	0	100%	1,226	309	75%	170,879	35,956	79%
Capitol Corridor	90%	2,703	444	84%	5,654	705	88%	1,124,096	146,803	87%
Carolinian	70%	1,200	640	47%	2,387	1,092	54%	347,233	136,061	61%
Cascades	75%	2,320	920	60%	5,513	1,869	66%	789,033	216,972	73%
Downeaster	82%	2,389	0	100%	4,705	60	99%	464,916	55,885	88%
Empire	78%	6,678	1,563	77%	12,865	3,245	75%	1,657,307	387,092	77%
Adirondack	72%	489	0	100%	913	49	95%	100,916	30,912	69%
Ethan Allen Express	70%	664	68	90%	1,269	349	72%	170,213	60,725	64%
Maple Leaf	70%	993	510	49%	1,918	910	53%	202,862	78,052	62%
New York - Albany	85%	2,437	14	99%	5,211	698	87%	767,649	126,633	84%
New York - Niagara Falls	75%	1,513	395	74%	2,972	663	78%	406,964	86,378	79%
Berkshire Flyer	60%	582	576	1%	582	576	1%	8,703	4,392	50%
Gold Runner	73%	2,957	1,764	40%	5,519	3,340	39%	761,054	273,486	64%
Heartland Flyer	70%	355	345	3%	734	587	20%	65,401	26,013	60%
Hiawatha	90%	2,171	6	100%	4,168	599	86%	525,444	58,327	89%
Illinois	78%	2,675	556	79%	5,565	1,866	66%	751,950	206,475	73%
Carl Sandburg / Illinois Zephyr	85%	188	0	100%	549	218	60%	125,410	34,399	73%
Illini / Saluki	85%	923	371	60%	1,993	1,026	49%	261,992	62,960	76%
Lincoln Service	70%	1,564	185	88%	3,023	622	79%	364,548	109,116	70%
Keystone	92%	5,392	195	96%	11,452	195	98%	2,306,897	239,375	90%
Lincoln / Missouri	70%	1,095	790	28%	2,028	1,465	28%	234,476	119,583	49%
Mardi Gras Service	80%	431	202	53%	821	260	68%	123,922	27,610	78%
Michigan	70%	2,278	938	59%	4,535	2,135	53%	602,129	194,518	68%
Blue Water	70%	536	536	0%	669	669	0%	140,247	56,385	60%
Pere Marquette	85%	359	0	100%	747	176	76%	79,188	15,297	81%
Wolverine	70%	1,383	402	71%	3,119	1,290	59%	382,694	122,836	68%
Missouri	80%	298	0	100%	784	261	67%	66,551	16,720	75%
Pacific Surfliner	85%	12,467	1,548	88%	25,888	3,382	87%	2,426,182	430,784	82%
Pennsylvanian	80%	856	0	100%	1,756	325	81%	267,632	51,243	81%
Piedmont	80%	1,389	176	87%	2,780	443	84%	343,016	89,012	74%
Vermont	75%	1,460	0	100%	2,857	201	93%	387,909	113,258	71%
Long Distance	70%	14,683	8,352	43%	27,747	15,785	43%	3,711,980	1,593,716	57%
Auto Train	70%	922	0	100%	1,849	0	100%	236,256	80,750	66%
California Zephyr	70%	1,540	1,285	17%	2,122	1,539	27%	293,451	107,979	63%
Cardinal	70%	0	0	-	322	113	65%	71,886	35,703	50%
City Of New Orleans	75%	627	580	7%	1,295	901	30%	192,297	58,931	69%
Coast Starlight	70%	1,444	451	69%	2,936	1,194	59%	347,514	121,731	65%
Crescent	70%	846	104	88%	1,830	264	86%	281,231	86,053	69%
Empire Builder	70%	1,125	1,001	11%	1,808	1,650	9%	291,928	145,310	50%
Floridian	60%	1,732	1,501	13%	3,644	3,411	6%	481,398	330,439	31%
Lake Shore Ltd	73%	1,213	553	54%	2,529	633	75%	290,766	86,100	70%
Palmetto	70%	822	282	66%	2,291	1,065	54%	278,121	83,487	70%
Silver Meteor	70%	1,079	572	47%	2,088	1,376	34%	307,310	138,719	55%
Southwest Chief	60%	1,133	468	59%	2,159	1,410	35%	252,413	163,816	35%
Sunset Ltd	70%	400	400	0%	400	400	0%	88,800	33,136	63%
Texas Eagle	70%	1,800	1,155	36%	2,474	1,829	26%	298,609	121,562	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

20-FOI-00000 00000000470 "UNCLASSIFIED" 8/3/2026

Train Index Dates Through August 02, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	10,814	208,784	518	1,803,966	32,156,800	561

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	478	58,031	82	86,863	9,255,033	94
INFRASTRUCTURE PLANNED	135	564	58,031	97	96,619	9,255,033	104
FLEET RELIABILITY	90	1,178	208,784	56	289,021	32,156,800	90
TRAIN OPERATIONS	424	8,594	208,784	412	1,331,463	32,156,800	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/02/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	43	85.1%	572	87	84.8%	91,516	12,643	86.2%
Central Division	86.0%	54	7	87.0%	110	17	84.5%	17,538	1,591	90.9%
East Division	82.0%	156	20	87.2%	299	41	86.3%	47,969	7,463	84.4%
West Division	86.0%	79	16	79.7%	163	29	82.2%	26,009	3,589	86.2%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/02/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/02/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	43	85.1%	572	87	84.8%	91,516	12,643	86.2%
Central Division	86.0%	54	7	87.0%	110	17	84.5%	17,538	1,591	90.9%
CDL	95.0%	2	1	50.0%	4	2	50.0%	580	27	95.3%
CHI	86.0%	25	3	88.0%	51	8	84.3%	8,101	975	88.0%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
FTW	92.5%	1	0	100.0%	2	0	100.0%	329	36	89.1%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	2	0	100.0%	290	8	97.2%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	4	0	100.0%	591	44	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	5	0	100.0%	10	1	90.0%	1,790	115	93.6%
MOE	97.5%	2	0	100.0%	4	0	100.0%	609	9	98.5%
MSP	96.5%	1	0	100.0%	2	1	50.0%	299	7	97.7%
NOL	94.5%	4	0	100.0%	9	0	100.0%	1,282	60	95.3%
OKC	97.0%	1	0	100.0%	2	0	100.0%	300	6	98.0%
PNT	88.0%	3	0	100.0%	6	1	83.3%	793	65	91.8%
PTH	93.0%	1	1	0.0%	2	1	50.0%	294	12	95.9%
QCY	91.0%	1	0	100.0%	2	0	100.0%	579	43	92.6%
SAS	90.5%	1	1	0.0%	2	1	50.0%	303	34	88.8%
STL	89.0%	4	1	75.0%	8	2	75.0%	1,183	102	91.4%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	156	20	87.2%	299	41	86.3%	47,969	7,463	84.4%
ALB	88.5%	7	0	100.0%	15	1	93.3%	2,265	176	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	1	80.0%	10	2	80.0%	1,476	160	89.2%
BOS	85.5%	17	1	94.1%	34	2	94.1%	5,197	606	88.3%
BRK	92.5%	5	0	100.0%	10	1	90.0%	1,462	103	93.0%
BTN	82.0%	1	0	100.0%	2	0	100.0%	292	41	86.0%
CLT	91.5%	5	1	80.0%	10	1	90.0%	1,487	151	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	4	0	100.0%	597	57	90.5%
GRO	-	-	-	-	-	-	-	33	10	69.7%
HAR	79.5%	7	2	71.4%	14	2	85.7%	3,378	550	83.7%
HFD	-	-	-	-	-	-	-	191	15	92.1%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	2	0	100.0%	302	38	87.4%
MIA	89.5%	2	0	100.0%	4	0	100.0%	604	68	88.7%
MTR	79.0%	1	0	100.0%	2	1	50.0%	289	53	81.7%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/02/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/02/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	43	85.1%	572	87	84.8%	91,516	12,643	86.2%
East Division	82.0%	156	20	87.2%	299	41	86.3%	47,969	7,463	84.4%
NFK	84.5%	2	1	50.0%	4	2	50.0%	687	125	81.8%
NFL	93.5%	2	0	100.0%	4	0	100.0%	616	29	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	1	80.0%	9	1	88.9%	1,563	254	83.7%
NPN	93.0%	2	0	100.0%	4	0	100.0%	577	42	92.7%
NYP	75.5%	42	8	81.0%	78	14	82.1%	12,562	2,795	77.8%
PGH	93.0%	1	0	100.0%	2	1	50.0%	303	23	92.4%
PHL	48.0%	4	1	75.0%	8	4	50.0%	1,558	744	52.2%
PIT	76.0%	1	1	0.0%	1	1	0.0%	16	13	18.8%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	4	0	100.0%	8	0	100.0%	1,166	49	95.8%
RNK	83.5%	2	0	100.0%	4	0	100.0%	600	87	85.5%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	6	4	33.3%
SAB	98.0%	1	0	100.0%	2	0	100.0%	289	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	2	0	100.0%	299	10	96.7%
SFA	88.0%	1	0	100.0%	2	0	100.0%	302	41	86.4%
SPG	92.5%	7	0	100.0%	13	0	100.0%	1,820	105	94.2%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	2	0	100.0%	291	60	79.4%
WAS	84.0%	27	3	88.9%	49	8	83.7%	7,521	975	87.0%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	79	16	79.7%	163	29	82.2%	26,009	3,589	86.2%
ARN	92.0%	1	0	100.0%	2	0	100.0%	304	26	91.4%
BFD	79.0%	6	2	66.7%	13	3	76.9%	1,910	396	79.3%
EMY	72.0%	1	0	100.0%	2	0	100.0%	320	94	70.6%
EUG	86.5%	2	0	100.0%	4	0	100.0%	602	56	90.7%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	4	3	25.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	6	2	66.7%	915	145	84.2%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	2	80.0%	20	3	85.0%	3,019	329	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	8	4	50.0%	17	7	58.8%	3,278	835	74.5%
PDX	86.0%	4	1	75.0%	9	2	77.8%	1,497	183	87.8%
RNO	-	-	-	-	-	-	-	2	1	50.0%
SAC	88.5%	12	3	75.0%	24	5	79.2%	4,290	467	89.1%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/02/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/02/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	289	43	85.1%	572	87	84.8%	91,516	12,643	86.2%
West Division	86.0%	79	16	79.7%	163	29	82.2%	26,009	3,589	86.2%
SAN	90.5%	13	1	92.3%	26	1	96.2%	3,667	345	90.6%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	7	1	85.7%	15	3	80.0%	2,400	350	85.4%
SJC	89.0%	7	1	85.7%	14	2	85.7%	2,138	211	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	6	1	83.3%	678	66	90.3%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	1	-	100.0%	299	26	91.3%
VAC	97.0%	2	0	100.0%	4	0	100.0%	595	14	97.6%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
1	Cncld	1	0	100.0%	129	9	93.0%	0	0	0.0%	129	31	76.0%
2		1	1	0.0%	130	32	75.4%	1	0	100.0%	125	24	80.8%
3		2	0	100.0%	304	59	80.6%	2	1	50.0%	302	137	54.6%
4		2	0	100.0%	303	46	84.8%	2	1	50.0%	303	200	34.0%
5	63	2	0	100.0%	302	50	83.4%	2	2	0.0%	298	90	69.8%
6	135	2	0	100.0%	301	85	71.8%	2	1	50.0%	301	104	65.4%
7	Cncld	2	1	50.0%	293	43	85.3%	1	1	0.0%	284	75	73.6%
8	117	2	2	0.0%	293	131	55.3%	2	2	0.0%	292	177	39.4%
11		2	1	50.0%	304	58	80.9%	2	0	100.0%	298	60	79.9%
14	96	2	1	50.0%	305	50	83.6%	2	2	0.0%	303	94	69.0%
19		2	0	100.0%	303	77	74.6%	2	0	100.0%	300	71	76.3%
20		2	0	100.0%	303	23	92.4%	2	0	100.0%	303	58	80.9%
21		2	0	100.0%	300	25	91.7%	2	1	50.0%	299	83	72.2%
22		2	1	50.0%	301	32	89.4%	2	0	100.0%	299	81	72.9%
23	52	2	0	100.0%	305	6	98.0%	2	1	50.0%	303	86	71.6%
24	26	2	0	100.0%	305	16	94.8%	2	1	50.0%	304	57	81.3%
25		2	0	100.0%	304	3	99.0%	2	1	50.0%	302	84	72.2%
26		2	0	100.0%	304	5	98.4%	2	0	100.0%	302	60	80.1%
28	48	1	1	0.0%	282	65	77.0%	2	1	50.0%	283	57	79.9%
40		2	0	100.0%	298	41	86.2%	2	1	50.0%	295	156	47.1%
41	189	2	1	50.0%	297	115	61.3%	2	2	0.0%	295	226	23.4%
42		2	1	50.0%	305	25	91.8%	2	0	100.0%	303	52	82.8%
43		2	0	100.0%	304	42	86.2%	2	0	100.0%	303	70	76.9%
48		2	0	100.0%	303	57	81.2%	2	0	100.0%	302	42	86.1%
49		2	1	50.0%	303	76	74.9%	2	0	100.0%	303	62	79.5%
50	159	1	0	100.0%	125	30	76.0%	1	1	0.0%	125	77	38.4%
52		2	0	100.0%	302	41	86.4%	2	0	100.0%	301	72	76.1%
53		2	0	100.0%	302	38	87.4%	2	0	100.0%	301	95	68.4%
54		2	0	100.0%	111	8	92.8%	2	0	100.0%	111	16	85.6%
57		2	0	100.0%	110	5	95.5%	2	0	100.0%	110	9	91.8%
58	215	2	0	100.0%	279	16	94.3%	1	1	0.0%	277	74	73.3%
59	411	2	1	50.0%	277	34	87.7%	2	1	50.0%	273	58	78.8%
63	140	2	0	100.0%	306	132	56.9%	2	2	0.0%	300	168	44.0%
64		2	0	100.0%	304	68	77.6%	2	1	50.0%	303	110	63.7%
65	38	1	0	100.0%	94	12	87.2%	2	1	50.0%	93	14	84.9%
66		2	0	100.0%	303	61	79.9%	2	0	100.0%	299	54	81.9%
68		2	1	50.0%	306	62	79.7%	2	0	100.0%	305	118	61.3%
69		2	2	0.0%	293	70	76.1%	2	0	100.0%	288	43	85.1%
71		2	0	100.0%	301	3	99.0%	2	0	100.0%	300	81	73.0%
72		2	0	100.0%	297	31	89.6%	2	0	100.0%	296	61	79.4%
73		2	0	100.0%	300	19	93.7%	2	1	50.0%	298	143	52.0%
74		2	0	100.0%	298	33	88.9%	2	0	100.0%	296	108	63.5%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
75		2	0	100.0%	294	16	94.6%	2	0	100.0%	288	137	52.4%
76	18	2	0	100.0%	294	29	90.1%	2	2	0.0%	285	119	58.2%
77		2	0	100.0%	296	20	93.2%	2	0	100.0%	294	123	58.2%
78		2	0	100.0%	300	25	91.7%	2	1	50.0%	299	64	78.6%
79		2	0	100.0%	303	56	81.5%	2	1	50.0%	302	102	66.2%
80	39	2	1	50.0%	303	34	88.8%	2	1	50.0%	300	64	78.7%
87	155	2	0	100.0%	114	24	78.9%	2	1	50.0%	114	40	64.9%
88		2	0	100.0%	110	15	86.4%	2	0	100.0%	110	23	79.1%
89	44	2	0	100.0%	301	65	78.4%	2	1	50.0%	299	86	71.2%
90		2	0	100.0%	301	10	96.7%	2	0	100.0%	300	51	83.0%
96		1	0	100.0%	39	8	79.5%	1	0	100.0%	39	10	74.4%
97		2	2	0.0%	303	200	34.0%	2	1	50.0%	301	101	66.4%
98	48	2	0	100.0%	303	26	91.4%	2	2	0.0%	301	110	63.5%
99	23	2	0	100.0%	113	12	89.4%	2	1	50.0%	110	62	43.6%
100		1	0	100.0%	24	5	79.2%	1	0	100.0%	23	4	82.6%
103		2	1	50.0%	112	22	80.4%	2	1	50.0%	112	10	91.1%
104		1	0	100.0%	36	4	88.9%	1	0	100.0%	36	3	91.7%
105	29	1	1	0.0%	38	18	52.6%	1	1	0.0%	38	7	81.6%
117		1	1	0.0%	23	14	39.1%	1	0	100.0%	23	4	82.6%
118		2	0	100.0%	112	8	92.9%	2	0	100.0%	112	8	92.9%
120		1	0	100.0%	39	5	87.2%	1	0	100.0%	39	4	89.7%
121		1	0	100.0%	39	11	71.8%	1	0	100.0%	39	16	59.0%
122	25	1	0	100.0%	38	15	60.5%	1	1	0.0%	38	9	76.3%
123		1	0	100.0%	41	6	85.4%	1	0	100.0%	41	1	97.6%
124	20	2	0	100.0%	111	9	91.9%	2	1	50.0%	110	31	71.8%
128		2	0	100.0%	114	19	83.3%	1	0	100.0%	113	22	80.5%
132		1	0	100.0%	39	3	92.3%	1	0	100.0%	39	4	89.7%
135		2	0	100.0%	113	17	85.0%	2	0	100.0%	113	56	50.4%
140	21	2	0	100.0%	112	12	89.3%	2	1	50.0%	111	25	77.5%
143		2	0	100.0%	111	11	90.1%	2	0	100.0%	111	25	77.5%
145		1	1	0.0%	39	7	82.1%	1	0	100.0%	39	14	64.1%
146		2	0	100.0%	111	17	84.7%	2	0	100.0%	111	39	64.9%
149		1	0	100.0%	39	3	92.3%	1	0	100.0%	39	14	64.1%
150		2	0	100.0%	110	57	48.2%	2	0	100.0%	108	51	52.8%
151		2	1	50.0%	302	96	68.2%	2	0	100.0%	301	95	68.4%
153	18	2	0	100.0%	112	10	91.1%	2	1	50.0%	112	17	84.8%
154		1	0	100.0%	39	5	87.2%	1	0	100.0%	39	20	48.7%
155		2	0	100.0%	114	18	84.2%	2	0	100.0%	114	40	64.9%
156		2	0	100.0%	114	11	90.4%	2	0	100.0%	114	38	66.7%
157		1	0	100.0%	39	3	92.3%	1	0	100.0%	39	12	69.2%
158	83	2	2	0.0%	113	22	80.5%	2	1	50.0%	113	27	76.1%
160		2	1	50.0%	111	7	93.7%	2	0	100.0%	108	26	75.9%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
161	19	2	0	100.0%	112	9	92.0%	2	1	50.0%	111	73	34.2%
162		2	2	0.0%	112	9	92.0%	2	0	100.0%	112	55	50.9%
164		2	0	100.0%	114	9	92.1%	2	0	100.0%	114	47	58.8%
165		2	0	100.0%	112	27	75.9%	2	0	100.0%	112	45	59.8%
169		2	0	100.0%	112	12	89.3%	1	0	100.0%	111	24	78.4%
189	24	1	1	0.0%	38	12	68.4%	1	1	0.0%	38	16	57.9%
195	16	2	0	100.0%	112	4	96.4%	2	1	50.0%	112	60	46.4%
230		2	0	100.0%	139	4	97.1%	2	0	100.0%	139	7	95.0%
232		2	0	100.0%	305	11	96.4%	2	0	100.0%	305	21	93.1%
234		2	0	100.0%	306	22	92.8%	2	0	100.0%	305	25	91.8%
235		2	1	50.0%	230	35	84.8%	2	0	100.0%	229	52	77.3%
236		2	0	100.0%	290	10	96.6%	2	0	100.0%	289	39	86.5%
237		2	0	100.0%	303	56	81.5%	2	0	100.0%	301	51	83.1%
238		2	0	100.0%	230	20	91.3%	2	0	100.0%	228	18	92.1%
239		2	0	100.0%	304	79	74.0%	2	0	100.0%	303	38	87.5%
240		2	0	100.0%	305	21	93.1%	2	1	50.0%	302	61	79.8%
241		2	0	100.0%	305	74	75.7%	2	0	100.0%	305	71	76.7%
243		2	0	100.0%	241	65	73.0%	2	0	100.0%	240	33	86.3%
245		2	0	100.0%	186	33	82.3%	2	1	50.0%	185	23	87.6%
280		2	0	100.0%	306	15	95.1%	2	0	100.0%	305	61	80.0%
281		2	0	100.0%	306	37	87.9%	2	0	100.0%	306	57	81.4%
283	67	2	1	50.0%	306	75	75.5%	2	1	50.0%	306	62	79.7%
284		2	0	100.0%	306	13	95.8%	2	0	100.0%	303	54	82.2%
290		2	0	100.0%	306	50	83.7%	2	0	100.0%	303	114	62.4%
291		2	1	50.0%	305	94	69.2%	2	1	50.0%	303	77	74.6%
300		2	1	50.0%	290	21	92.8%	2	1	50.0%	288	69	76.0%
301		2	0	100.0%	303	10	96.7%	2	0	100.0%	299	55	81.6%
302		2	0	100.0%	285	33	88.4%	2	0	100.0%	281	78	72.2%
305		2	0	100.0%	288	28	90.3%	2	0	100.0%	284	115	59.5%
306		2	0	100.0%	301	16	94.7%	2	0	100.0%	300	82	72.7%
307	212	2	1	50.0%	294	39	86.7%	2	1	50.0%	291	83	71.5%
311		2	1	50.0%	299	27	91.0%	2	0	100.0%	293	63	78.5%
316		2	0	100.0%	295	18	93.9%	2	1	50.0%	290	79	72.8%
318		2	0	100.0%	304	31	89.8%	2	1	50.0%	301	145	51.8%
319	134	2	0	100.0%	305	20	93.4%	2	2	0.0%	300	167	44.3%
331		2	0	100.0%	306	33	89.2%	2	0	100.0%	306	44	85.6%
332		1	0	100.0%	305	17	94.4%	1	0	100.0%	305	43	85.9%
334		2	0	100.0%	306	10	96.7%	2	0	100.0%	305	40	86.9%
335		2	0	100.0%	306	34	88.9%	2	1	50.0%	304	52	82.9%
336		2	0	100.0%	306	10	96.7%	2	0	100.0%	304	28	90.8%
337		2	0	100.0%	306	18	94.1%	2	1	50.0%	302	37	87.7%
338	13	2	1	50.0%	306	48	84.3%	2	2	0.0%	304	96	68.4%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
339		2	1	50.0%	306	51	83.3%	2	1	50.0%	306	54	82.4%
341		2	0	100.0%	294	44	85.0%	2	0	100.0%	288	41	85.8%
342		2	0	100.0%	306	24	92.2%	2	0	100.0%	304	60	80.3%
350	31	2	0	100.0%	283	18	93.6%	2	2	0.0%	276	153	44.6%
351	24	2	1	50.0%	289	28	90.3%	2	2	0.0%	287	80	72.1%
352		2	0	100.0%	273	21	92.3%	2	1	50.0%	267	82	69.3%
353		2	0	100.0%	244	13	94.7%	2	0	100.0%	238	38	84.0%
354	17	2	0	100.0%	287	35	87.8%	2	2	0.0%	280	103	63.2%
355	102	2	0	100.0%	296	31	89.5%	2	1	50.0%	289	100	65.4%
364	103	2	2	0.0%	295	67	77.3%	2	2	0.0%	289	109	62.3%
365	208	2	1	50.0%	294	12	95.9%	1	1	0.0%	291	110	62.2%
370		2	0	100.0%	297	35	88.2%	2	1	50.0%	287	70	75.6%
371		2	0	100.0%	290	8	97.2%	2	0	100.0%	289	29	90.0%
381		2	0	100.0%	304	12	96.1%	2	0	100.0%	303	60	80.2%
382		2	0	100.0%	303	27	91.1%	2	1	50.0%	303	101	66.7%
390	36	2	2	0.0%	288	21	92.7%	2	2	0.0%	287	75	73.9%
391	37	2	0	100.0%	289	11	96.2%	2	2	0.0%	285	78	72.6%
392		2	0	100.0%	302	10	96.7%	2	0	100.0%	299	90	69.9%
393		2	0	100.0%	306	18	94.1%	2	1	50.0%	303	92	69.6%
400		2	0	100.0%	93	6	93.5%	2	0	100.0%	91	2	97.8%
405		2	0	100.0%	86	0	100.0%	2	0	100.0%	86	4	95.3%
409		1	0	100.0%	40	1	97.5%	1	0	100.0%	40	4	90.0%
416		1	0	100.0%	36	4	88.9%	1	0	100.0%	36	3	91.7%
448		2	1	50.0%	236	46	80.5%	2	0	100.0%	233	80	65.7%
449		2	0	100.0%	233	32	86.3%	2	0	100.0%	233	42	82.0%
450		2	0	100.0%	89	27	69.7%	2	0	100.0%	87	28	67.8%
460		2	0	100.0%	89	28	68.5%	2	0	100.0%	86	30	65.1%
461		2	0	100.0%	94	5	94.7%	2	0	100.0%	93	2	97.8%
464		2	1	50.0%	89	17	80.9%	2	0	100.0%	87	25	71.3%
465		1	0	100.0%	41	1	97.6%	1	0	100.0%	41	1	97.6%
488		2	0	100.0%	99	28	71.7%	2	0	100.0%	89	13	85.4%
497		1	0	100.0%	38	1	97.4%	1	0	100.0%	38	7	81.6%
499		2	0	100.0%	90	13	85.6%	2	0	100.0%	87	6	93.1%
500		2	0	100.0%	297	16	94.6%	2	0	100.0%	294	35	88.1%
502	17	2	0	100.0%	304	18	94.1%	2	1	50.0%	300	59	80.3%
503		2	0	100.0%	302	27	91.1%	2	0	100.0%	295	87	70.5%
504		2	0	100.0%	306	19	93.8%	2	1	50.0%	304	91	70.1%
505	22	2	0	100.0%	304	41	86.5%	2	1	50.0%	299	85	71.6%
506	Cncld	2	1	50.0%	301	43	85.7%	1	0	100.0%	294	46	84.4%
507	141	2	0	100.0%	306	36	88.2%	2	1	50.0%	306	101	67.0%
508	48	2	0	100.0%	301	41	86.4%	2	2	0.0%	297	70	76.4%
509	No OS	2	0	100.0%	303	14	95.4%	2	1	50.0%	303	67	77.9%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
511	No OS	2	0	100.0%	298	24	91.9%	2	1	50.0%	297	51	82.8%
516	58	2	1	50.0%	297	30	89.9%	2	2	0.0%	296	136	54.1%
517		2	0	100.0%	306	8	97.4%	2	1	50.0%	302	128	57.6%
518	134	2	0	100.0%	306	37	87.9%	2	2	0.0%	304	209	31.3%
519		2	0	100.0%	297	9	97.0%	2	0	100.0%	295	66	77.6%
562		2	0	100.0%	297	23	92.3%	2	0	100.0%	293	35	88.1%
564		2	0	100.0%	298	19	93.6%	2	0	100.0%	290	38	86.9%
566		2	1	50.0%	296	26	91.2%	2	0	100.0%	293	45	84.6%
567		2	0	100.0%	183	10	94.5%	2	0	100.0%	181	9	95.0%
572		2	0	100.0%	293	24	91.8%	2	0	100.0%	286	83	71.0%
573		2	0	100.0%	295	40	86.4%	2	0	100.0%	288	51	82.3%
579		2	0	100.0%	183	11	94.0%	2	0	100.0%	178	37	79.2%
580		2	0	100.0%	298	16	94.6%	2	0	100.0%	291	28	90.4%
581		2	1	50.0%	298	51	82.9%	2	0	100.0%	296	64	78.4%
584	34	2	1	50.0%	182	26	85.7%	2	2	0.0%	177	110	37.9%
587		2	0	100.0%	291	16	94.5%	2	0	100.0%	282	53	81.2%
588		2	0	100.0%	183	18	90.2%	2	0	100.0%	182	33	81.9%
591	19	2	0	100.0%	295	21	92.9%	2	1	50.0%	289	40	86.2%
593		2	0	100.0%	292	47	83.9%	2	0	100.0%	271	37	86.3%
595		2	0	100.0%	293	53	81.9%	2	0	100.0%	290	60	79.3%
612		1	1	0.0%	38	6	84.2%	1	0	100.0%	38	1	97.4%
615		1	0	100.0%	39	21	46.2%	1	0	100.0%	38	7	81.6%
637		2	0	100.0%	65	7	89.2%	1	0	100.0%	64	5	92.2%
660		2	0	100.0%	83	12	85.5%	2	0	100.0%	82	25	69.5%
661		2	0	100.0%	111	12	89.2%	2	0	100.0%	110	41	62.7%
663		2	0	100.0%	84	14	83.3%	2	0	100.0%	83	8	90.4%
664		2	0	100.0%	83	8	90.4%	2	0	100.0%	83	11	86.7%
665		2	0	100.0%	84	10	88.1%	2	0	100.0%	84	24	71.4%
666		2	0	100.0%	82	22	73.2%	2	0	100.0%	82	7	91.5%
667		2	0	100.0%	82	7	91.5%	2	0	100.0%	80	16	80.0%
669		2	0	100.0%	82	7	91.5%	2	0	100.0%	80	22	72.5%
670		2	0	100.0%	84	13	84.5%	2	0	100.0%	82	15	81.7%
671		2	0	100.0%	82	8	90.2%	2	0	100.0%	80	9	88.8%
672		2	0	100.0%	84	8	90.5%	2	0	100.0%	84	15	82.1%
674		2	1	50.0%	82	27	67.1%	2	0	100.0%	82	7	91.5%
690		2	0	100.0%	88	2	97.7%	2	0	100.0%	87	4	95.4%
691		2	0	100.0%	88	7	92.0%	2	0	100.0%	86	23	73.3%
692	12	2	0	100.0%	88	3	96.6%	2	1	50.0%	87	15	82.8%
693		2	0	100.0%	88	12	86.4%	2	1	50.0%	86	25	70.9%
694		2	1	50.0%	87	10	88.5%	2	0	100.0%	87	14	83.9%
695		2	0	100.0%	86	10	88.4%	2	0	100.0%	86	14	83.7%
696		2	0	100.0%	88	9	89.8%	2	0	100.0%	88	25	71.6%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
697		2	2	0.0%	88	21	76.1%	2	0	100.0%	88	17	80.7%
698		2	0	100.0%	86	2	97.7%	2	0	100.0%	86	7	91.9%
701		2	0	100.0%	238	25	89.5%	2	0	100.0%	235	25	89.4%
702		2	0	100.0%	305	32	89.5%	2	1	50.0%	302	71	76.5%
703		2	1	50.0%	306	94	69.3%	2	0	100.0%	304	85	72.0%
704		2	1	50.0%	237	38	84.0%	2	1	50.0%	230	47	79.6%
710		2	0	100.0%	306	77	74.8%	2	1	50.0%	302	82	72.8%
711	40	2	0	100.0%	297	34	88.6%	2	2	0.0%	276	54	80.4%
712	31	2	0	100.0%	303	80	73.6%	2	1	50.0%	294	99	66.3%
714	173	2	2	0.0%	187	77	58.8%	1	1	0.0%	172	77	55.2%
715	24	2	0	100.0%	305	61	80.0%	1	1	0.0%	281	142	49.5%
716	240	2	2	0.0%	306	122	60.1%	2	2	0.0%	300	120	60.0%
717	58	2	1	50.0%	291	69	76.3%	1	1	0.0%	271	87	67.9%
718	82	2	1	50.0%	306	154	49.7%	2	2	0.0%	304	111	63.5%
719	34	2	1	50.0%	306	104	66.0%	2	2	0.0%	290	86	70.3%
720		2	0	100.0%	95	9	90.5%	2	0	100.0%	95	6	93.7%
723		2	0	100.0%	95	5	94.7%	2	1	50.0%	95	10	89.5%
724	Cncld	2	1	50.0%	95	4	95.8%	1	0	100.0%	94	19	79.8%
727		2	0	100.0%	95	7	92.6%	2	0	100.0%	95	14	85.3%
728	11	2	0	100.0%	95	6	93.7%	2	1	50.0%	95	18	81.1%
729	205	2	0	100.0%	94	15	84.0%	2	1	50.0%	93	22	76.3%
732	59	2	1	50.0%	93	16	82.8%	2	1	50.0%	91	18	80.2%
733	34	2	0	100.0%	95	14	85.3%	2	1	50.0%	90	30	66.7%
734		2	0	100.0%	95	14	85.3%	2	0	100.0%	94	21	77.7%
736		2	0	100.0%	71	7	90.1%	2	1	50.0%	69	10	85.5%
737	19	2	1	50.0%	71	8	88.7%	2	1	50.0%	70	13	81.4%
738		2	0	100.0%	95	15	84.2%	2	0	100.0%	90	13	85.6%
741		2	0	100.0%	95	13	86.3%	2	0	100.0%	95	18	81.1%
743	Cncld	2	1	50.0%	95	18	81.1%	1	0	100.0%	93	10	89.2%
744		2	0	100.0%	95	15	84.2%	2	0	100.0%	95	32	66.3%
745		2	0	100.0%	95	10	89.5%	2	0	100.0%	94	14	85.1%
746		2	1	50.0%	95	9	90.5%	2	1	50.0%	94	14	85.1%
747		2	1	50.0%	95	16	83.2%	2	0	100.0%	95	21	77.9%
748		2	0	100.0%	94	13	86.2%	2	0	100.0%	94	13	86.2%
749		2	1	50.0%	92	15	83.7%	2	1	50.0%	83	11	86.7%
751		2	0	100.0%	94	16	83.0%	2	0	100.0%	91	11	87.9%
757		2	0	100.0%	91	5	94.5%	2	0	100.0%	90	8	91.1%
761		2	0	100.0%	302	12	96.0%	2	0	100.0%	299	41	86.3%
765		2	0	100.0%	302	25	91.7%	2	0	100.0%	302	42	86.1%
769		2	0	100.0%	302	27	91.1%	2	0	100.0%	296	57	80.7%
770	42	2	1	50.0%	302	23	92.4%	2	2	0.0%	300	91	69.7%
774		2	0	100.0%	302	16	94.7%	2	0	100.0%	301	69	77.1%

Amtrak On Time Performance

Trains Arriving Through: 8/2/2026

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
777		2	0	100.0%	187	12	93.6%	2	0	100.0%	186	42	77.4%
782		2	1	50.0%	187	83	55.6%	2	1	50.0%	182	26	85.7%
785	70	2	0	100.0%	302	22	92.7%	2	1	50.0%	302	54	82.1%
786		2	0	100.0%	91	19	79.1%	2	0	100.0%	88	47	46.6%
790		2	0	100.0%	302	28	90.7%	2	0	100.0%	299	46	84.6%
794		2	1	50.0%	302	34	88.7%	2	0	100.0%	298	66	77.9%
821	23	2	0	100.0%	300	6	98.0%	2	2	0.0%	300	123	59.0%
822	24	2	0	100.0%	302	16	94.7%	2	2	0.0%	300	144	52.0%
1233	38	1	0	100.0%	16	4	75.0%	1	1	0.0%	16	9	43.8%
1246	22	1	1	0.0%	16	13	18.8%	1	1	0.0%	16	8	50.0%
1333		2	1	50.0%	302	33	89.1%	2	1	50.0%	299	100	66.6%
1340		2	1	50.0%	301	7	97.7%	2	0	100.0%	301	51	83.1%
1689		2	0	100.0%	97	5	94.8%	2	0	100.0%	96	11	88.5%
2208		2	1	50.0%	13	4	69.2%	2	0	100.0%	13	3	76.9%
2209	30	1	0	100.0%	5	0	100.0%	1	1	0.0%	5	2	60.0%
2212		1	0	100.0%	6	0	100.0%	1	0	100.0%	6	1	83.3%
2213		1	1	0.0%	5	1	80.0%	1	0	100.0%	5	2	60.0%
2215		1	0	100.0%	25	9	64.0%	1	0	100.0%	25	13	48.0%
2216		1	0	100.0%	73	3	95.9%	1	0	100.0%	73	3	95.9%
2218	23	1	0	100.0%	70	14	80.0%	1	1	0.0%	70	14	80.0%
2219		2	0	100.0%	13	3	76.9%	2	0	100.0%	13	4	69.2%
2222		1	0	100.0%	55	4	92.7%	1	0	100.0%	54	7	87.0%
2223		1	0	100.0%	25	5	80.0%	1	0	100.0%	24	4	83.3%
2224		2	0	100.0%	28	5	82.1%	2	0	100.0%	28	4	85.7%
2226		1	0	100.0%	37	7	81.1%	1	0	100.0%	35	9	74.3%
2227		1	0	100.0%	5	1	80.0%	1	0	100.0%	5	0	100.0%
2233		1	0	100.0%	23	5	78.3%	1	0	100.0%	23	4	82.6%
2252		2	0	100.0%	108	9	91.7%	2	0	100.0%	106	32	69.8%
2254		2	0	100.0%	43	3	93.0%	2	1	50.0%	43	13	69.8%
2255		2	0	100.0%	110	11	90.0%	2	1	50.0%	109	51	53.2%
2258	23	2	0	100.0%	46	9	80.4%	2	1	50.0%	45	20	55.6%
2259		2	0	100.0%	66	24	63.6%	2	0	100.0%	65	30	53.8%
2260	59	2	0	100.0%	12	2	83.3%	2	1	50.0%	12	9	25.0%
2265		2	1	50.0%	47	5	89.4%	2	0	100.0%	46	27	41.3%
2267	18	2	0	100.0%	10	3	70.0%	2	1	50.0%	9	6	33.3%
2271		2	0	100.0%	93	11	88.2%	2	0	100.0%	92	46	50.0%
2290		1	0	100.0%	37	9	75.7%	1	0	100.0%	36	7	80.6%
2293		2	1	50.0%	11	2	81.8%	2	0	100.0%	11	3	72.7%

Amtrak Endpoint OTP Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/2/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2209	WAS	30	DMW	35	DMW	35	BAL-XNY	AM	Held for or routed around MW work or equipment, Control Point, ., 23 switch at Grove stuck on center	
2218	NYP	23	DCS	27	DCS	27	XHM-XCY	AM	T.O.L, Other, NO.2 TRACK HAM INT	
2258	BOS	23	OTH	15	DCS	8	NHV-XGX	AM	T.O.L, Milepost w/Letters, NHV, XGU, track circuit Treble Int. rule 241 issued	
2260	BOS	59	DCS	71	DCS	71	NHV-XGX	AM	Power switch failure, Milepost w/Letters, NHV, XGX, SHL dspr rpts 21sw at Fitter is out of correspondence, trouble desk ntfd. AM2260 is stopped on trk 2	
2267	WAS	18	DCS	12	DCS	12	XCY-XHM	AM	T.O.L, Other, OPERATED NO.4 TRACK A/C TOL NO.2 TRACK HAM INT	
65	NPN	38	INJ	31	INJ	31	ALX-QAN	CS	Injured or sick passenger Monica Kennedy Reservation # 8D1CD9 Stopped at WDB station, EMS boarded the train to provide medical treatment, and pax exited with 3 (three) other family members; 4 (four) total passengers of the same reservation left the train.	
87	NFK	155	ENG	136	ENG	136	WAS-WAS	AM	PTC- IETMS hard cutout, 130, THE DEL'S HAD TO SHIFT BACK TO THE PIT TWICE	
99	NPN	23	WTR	30	WTR	17	ALX-QAN	CS	Flash flood warning Other, cfp 112-74	
105	WAS	29	ITI	32	ITI	32	NYP-NYP	AM	Service, turn, or wye train, 120, LATE TURN OFF AM120	
122	NYP	25	DCS	27	DCS	27	XHM-PJC	AM	T.O.L, Other, TOL NO.2 TRACK HAM INT	
124	PHL	20	WTR	28	WTR	8	WDB-ALX	CS	Flash flood warning Control Point, WDB to ALX	
140	SPG	21	OTH	19	INJ	13	NHV-NHV	AM	Injured or sick passenger, medical emergency on board NHV	
153	WAS	18	DMW	20	DMW	20	BAL-BAL	AM	Held for or routed around MW work or equipment, Control Point, ., held for disposition a/c 23 switch at Grove stuck on center	
158	NYP	83	WTR	81	WTR	34	ASD-FBG	CS	High winds Stop by dispatcher b/c of tornado warning, Milepost w/Letters, cfp 24, cfp 47	
161	WAS	19	HLD	11	PTI	7	BAL-BWI	AM	Follow, 19, Control Point, .	
189	WAS	24	CAR	10	CAR	10	NYP-NYP	AM	Door, COACH CAR, delayed out of the yard due to needing a new door seal	
195	WAS	16	SMW	16	SMW	10	XSH-NYP	AM	Scheduled in track usage program, Other, XPB-XPB, HELD FOR AM162 A/C NO.2 TRK OOS PELHAM BAY TO LEGGETT	

Amtrak Endpoint OTP Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/2/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
80	NYP	39	PTI	34	FTI	16	SAL-HPT	NS	Follow P80, Control Point, Maybelle, Control Point, Varner	
692	BON	12	CTI	4	CTI	4	HHL-WOB	MT	Blocked from station track 121E station cutout. Commuter was in station., keolis, Control Point, Wilmington	
63	TWO	140	FTI	24	FTI	22	AMS-UCA	CS	Follow csx, Milepost, 215, 231	
283	NFL	67	ITI	70	ITI	70	NYP-NYP	AM	Service, turn, or wye train, 236, LATE F/SSYD A/C LATE TURN OFF AM236	
1233	PIT	38	CTI	31	CTI	26	CRT-POU	MN	Follow mnrr, 8819, Milepost, 35, 72	
1246	NYP	22	ITI	31	ITI	31	PIT-PIT	CS	Train was late inbound due to following a CSX freight and late into Albany. 1233	
76	RGH	18	TEN	11	TEN	6	KAN-GRO	NS	Undesired emergency application Wheel slip caused PTC to enforce over speed penalty. PTC enforced emergency brakes. Successfully recovery., NC1893	
89	SAV	44	FTI	79	FTI	34	XDJ-RVR	CS	Follow CSX031, Control Point, Dahlgren Jct.	
98	NYP	48	FTI	94	FTI	49	XDY-SBG	CS	Train on HOS Law Stopped MT, M452 on HOS law ahead at Plaines awaiting re-crew., M452-01, Control Point, NE Ft Basinger	
41	MIA		CON	145	CON	145	TOL-TOL	NS	Hold for bus with passengers from train Turned train 40 in TOL .. waited for 5 busses with passengers and crew members	
23	NOL	52	PTI	31	PTI	31	BAS-XNO	CS	Meet Amtrak 26, Siding, Claiborne	
24	MOE	26	FTI	42	FTI	42	XNO-BAS	CS	Meet Siding, lake carheine, 521	
5	EMY	63	FTI	128	FTI	48	XMS-RNO	UP	Hold due to broken knuckle Control Point, Glendale, UP 2672	
6	CHI	135	WTR	124	WTR	49	XMS-WNN	UP	Heat order Level 2 50MPH., Milepost, 291.00, 417.00	
724	SAC	Trn Cancelled	DCS	7	PTI	4	FMT-HAY	UP	Meet 727, Siding, Hayward	
728	SAC	11	PTI	28	PTI	26	OKJ-EMY	UP	Cross over or go around Due to trespasser, Amtk 729, Control Point, 10th St	
729	SJC	205	TRS	199	TRS	199	EMY-OKJ	UP	Trespasser strike Tran canceled from Cp RV004 to final station stop of San Jose due to trespasser strike All passengers transferred to AMTK733, Control Point, RV004	
732	SAC	59	POL	36	POL	32	DAV-SAC	UP	Right of Way police hold 87.3	

Amtrak Endpoint OTP Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
733	SJC	34	MBO	26	MBO	26	SUI-MTZ	UP	For maritime traffic Control Point, RV035
737	OKJ	19	TRS	13	TEN	9	SUI-MTZ	UP	Failure of diesel engine Multiple faults led to entire locomotive shut down shortly after departing SUI Depot. HEP motor also shut down. Engineer troubleshot the problem and was able to restart the engine., JPBX922
743	OKJ	Trn Cancelled							
50	NYP	159	PTI	104	PTI	77	STA-CVS	BB	Meet AMTK 51, Control Point, Ivy
502	SEA	17	PTI	14	PTI	14	XNI-TAC	ST	Meet 11, Control Point, manitou
505	PDX	22	PTI	17	PTI	17	XA4-XTW	BN	Wait for station track Train 500 delayed into Tacoma. Unable to access Tacoma until 500 departs, AMT500, Control Point, Stewart
506	SEA	Trn Cancelled							
507	EUG	141	FTI	26	DCS	23	ORC-SLM	UP	Restrictive signal(s) from known wayside signal failure Reatricked proceed, Milepost, 750, 745
508	SEA	48	PTI	15	DCS	9	XA4-TUK	BN	Issue with automatic road crossing protection Box 1 had to stop and protect crossing, Other, 16.2x
509	PDX	No OS Rpt	POL	182	POL	182	TUK-TUK	BN	RR blocked by trespasser or vehicle strike by another train Held due to trespasser strike by 518
511	PDX	No OS Rpt	TRS	66	TRS	66	SEA-TUK	BN	Trespasser strike Due to 518 trespasser strike 511 was holding at Black river 10.0x waiting for train to clear, Milepost, 16.1, 16.1
516	VAC	58	FTI	39	FTI	26	BEL-X8B	BN	Freight setting out a car with a broken axle BNSF 3924, Control Point, oliver
518	VAC	134	TRS	125	TRS	125	XA4-TUK	BN	Trespasser strike Milepost w/Letters, 16.1x, 15.8x
58	CHI	215	FTI	243	FTI	216	CDL-CDL	CC	Blocked from station track ns224, Control Point, centralia
59	NOL	411	FTI	433	FTI	340	CEN-CEN	CC	NS freight train with a broken draw bar.Had to wait for repairs. Stopped at Centralia Station for safety and good customer service., ns, Control Point, miller
14	SEA	96	POL	121	POL	121	XA4-SEA	BN	RR blocked by trespasser or vehicle strike by another train
7	SEA	Trn Cancelled	TRS	316	TRS	273	SCD-SPL	BN	Vehicle strike Vehicle & trespasser strike, Milepost, 116.42, 116.42

Amtrak Endpoint OTP Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
8	CHI	117	FTI	132	WTR	60	HAV-MAL	BN	Heat order Milepost, 427, 121
28	SPK	48	CON	60	CON	60	PDX-PDX	BN	Hold for connecting train Delay approved by management, 16 transfers. No eastbound trains for the next 2 days due to bridge construction., 14
821	FTW	23	DSR	25	DCS	20	ADM-GLE	BN	Power switch failure Control Point, S Marietta
822	OKC	24	DSR	25	DSR	20	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, m1, Milepost, 353.7, 354.1, 60, m1, Milepost, 355.5, 355.9, 50, m1, Milepost, 360.6, 361.1, 60, m1, Milepost, 371.4, 371.5, 50, m, Milepost, 374, 374.1, 60, m, Milepost, 377.5, 378.3, 75, m, Milepost, 379.5, 380, 60, m, Milepost, 382.7, 383.1, 50, m, Milepost,
338	CHI	13	DCS	7	DCS	7	XRO-GLN	ME	Issue with automatic road crossing protection Item #1 at Chestnut Ave, Milepost, 18.24, 18.24
350	PNT	31	DSR	36	DSR	30	TRM-PNT	CC	Per bulletin Milepost, 17.9, 18, 30, 1, Milepost, 18.19, 22.3, 10, 1, Milepost, 22.3, 25.3, 30, 1
351	CHI	24	DSR	53	DSR	43	PNT-TRM	CC	Per bulletin Milepost, 22.3, 18.19, 10, 1, Milepost, 25.3, 22.3, 30, 1
354	PNT	17	DSR	29	DSR	26	TRM-PNT	CC	Per bulletin Milepost, 17, 17.4, 30, MAIN ONE, Milepost, 17.9, 18, 30, MAIN, Milepost, 18.19, 22.3, 10, MAIN ONE
355	CHI	102	SYS	111	SYS	30	DER-ARB	MI	PTC problem or failure (cause unknown) No empty run 595 from Dearborn Station the rest of the way to Battle Creek, Control Point, 9
364	PTH	103	ITI	97	ITI	97	CHI-CHI	AM	Service, turn, or wye train 365
365	CHI	208	INJ	136	INJ	136	PTH-PTH	CC	Injured or sick employee Engineer injured on locomotive #58 Engineer was taken to local Port Huron Hospital.
584	SAN	34	PTI	27	CTI	17	SNC-SNP	SC	Meet mtlk, Control Point, serra
591	LAX	19	ENG	18	ENG	18	ANA-ANA	SC	HEP Lost all power arriving at ANA station., C2121
770	SAN	42	CAR	48	CAR	45	GTA-GTA	UP	Air / Brake / Wheel 6411
785	GTA	70	TRS	76	TRS	61	VEC-VEC	UP	Held for 794 trespasser strike outside of SBA Other, VEC
711	OKJ	40	POL	25	POL	15	EMY-EMY	UP	RR blocked by trespasser or vehicle strike by another train 729 trespasser strike

Amtrak Endpoint OTP Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/2/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
712	BFD	31	PTI	25	PTI	13	OKJ-EMY	UP	Wait for station track 724 was having mechanical problems and we were stopped ALL Red, 724, Control Point, RV005
714	BFD	173	TEN	144	TEN	87	OKJ-OKJ	UP	E 2003 coolant leak Equipment swap with 716 equipment, C2003
715	OKJ	24	PTI	20	PTI	17	EMY-EMY	UP	Wait for station track 724, Control Point, Emeryville
716	BFD	240	POL	69	POL	69	ACA-SKN	BN	Vehicle stuck on tracks at control point Sando.
717	OKJ	58	PTI	45	SYS	23	MCD-MCD	BN	Re-crew / job briefing
718	BFD	82	SYS	45	SYS	25	MCD-MCD	BN	Issues with logging in to PTC. Got help from PTC desk.
719	OKJ	34	RTE	41	RTE	19	MOD-SKN	BN	Dispatcher hold Held for AMTK 716 NAR, Control Point, west riverbank
1	MRC	Trn Cancelled	CON	67	CON	67	SAS-SAS	UP	Hold for connecting train Late train. Mechanical released train 1 at 243a.
307	STL	212	ITI	197	ITI	197	CHI-CHI	AM	Service, turn, or wye train 365
390	CHI	36	ITI	20	ITI	20	CDL-CDL	CC	Service, turn, or wye train 59
391	CDL	37	FTI	43	FTI	38	MAT-EFG	CC	Follow Passed FTI 2917 that was sitting in the siding and followed 8929 FTI to EFG along with ONE unknown FTI, Siding, Neoga, FTI 2917, FTI 8929, 1 unknown FTi
319	KCY	134	FTI	151	FTI	74	ALN-ALN	UP	Follow UP 9572, Control Point, ALN Station

Amtrak Initial Terminal Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/2/2026

Terminal	Train	Date	Late	Delay	Cause
BON	697	08/02	3	3	Radio not communicating with Boston Info desk. No announcements made.
BOS	2265	08/02	19	19	Routine inspections, paper work out of compliance
CLT	80	08/02	9	4	Passenger and/or baggage 157 boarding. Float of bags
CLT	80	08/02	9	5	Waiting for 27A to pass before CLT Dispatcher would give permission to line out of Office car track NS 27A, Control Point, AT&O, Control Point, Lidell
HAR	612	08/02	1	1	Passenger and/or baggage
HAR	674	08/02	1	1	Passenger and/or baggage
NFK	158	08/02	2	2	Water, commissary, toilet/trash dumping Water was coming out the hose in the cafe car., Other, NFK
NHV	464	08/02	4	4	Service, turn, or wye train, 409, Short turn of 409 in NHV, also crew had to reset cab stand
NYP	69	08/02	3	3	Cross Traffic, NJT, NJ7825, Other, NYP-NYP, HELD A/C NJ7825 XING AHEAD
NYP	97	08/02	4	4	Water, commissary, toilet/trash dumping, LATE RELEASE FROM CATERING
NYP	105	08/02	32	32	Service, turn, or wye train, 120, LATE TURN OFF AM120
NYP	145	08/02	4	4	Cross over or go around, AM105, Other, NYP-NYP, HELD A/C AM105 XING AHEAD
NYP	189	08/02	10	10	Door, COACH CAR, delayed out of the yard due to needing a new door seal
NYP	235	08/02	2	2	Passenger and/or baggage
NYP	283	08/02	70	70	Service, turn, or wye train, 236, LATE F/SSYD A/C LATE TURN OFF AM236
NYP	2213	08/02	2	2	Passenger and/or baggage, LOADING
PHL	117	08/02	1	1	Passenger and/or baggage
PIT	1246	08/02	36	31	Train was late inbound due to following a CSX freight and late into Albany. 1233
PIT	1246	08/02	36	5	Cross over or go around While waiting to depart from track 1 CSX freight train was going west through CP 150 track 2 to the main, Other, Pittsfield, CSX
WAS	160	08/02	5	5	Passenger and/or baggage, CNDR WAITING FOR THE GATE.
WAS	162	08/02	7	7	Delay in Block, STILL SHOWING DOORS OPEN NECESSARY TO PUT IN DOOR BYPASS.
WAS	2208	08/02	3	3	Other electrical failure, 2038, UNKNOWN SPEED RESTRICTION
CDL	390	08/02	20	20	Service, turn, or wye train 59
CHI	7	08/02	101	25	Service, turn, or wye train 8
CHI	7	08/02	101	65	Toilet 32063, Toilets were never pumped last night. Tank was full.
CHI	7	08/02	101	11	Commissary back order Train already delayed and commissary still did NOT provide all the necessary items.

Amtrak Initial Terminal Details

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/2/2026

Terminal	Train	Date	Late	Delay	Cause
CHI	41	08/02	19	7	Wheelchair 4 lifts in 3 different cars. 4th lift needed a respot due to a pillar blocking the way.
CHI	41	08/02	19	5	Passenger connections and luggage. 8
CHI	41	08/02	19	7	Toilet 25024, 3rd coach pulled out of service once it got onto the platform. I had to organize a loading plan and figure out with the station manager who was going with me and who was going on the bus.
CHI	364	08/02	97	97	Service, turn, or wye train 365
PTH	365	08/02	136	136	Injured or sick employee Engineer injured on locomotive #58 Engineer was taken to local Port Huron Hospital.
SAS	22	08/02	48	48	Service, turn, or wye train 2, Amtrak #2 arrived late. Waited for coach and sleeper to get attached and serviced by mechanical.
STL	300	08/02	3	3	Late inbound equipment 305
BFD	703	08/02	5	5	Service, turn, or wye train 712, Blue flagged until 1753.
BFD	719	08/02	12	12	Hold for thruway bus Route 5619
GTA	770	08/02	45	45	Air / Brake / Wheel 6411
LAX	14	08/02	93	93	Late leaving yard engine 343 not working swapped out in yard for engine 192 14
LAX	566	08/02	1		
OKJ	714	08/02	87	87	E 2003 coolant leak Equipment swap with 716 equipment, C2003
OKJ	716	08/02	(Trn Cxld)		Third Party Engine Failure
OKJ	718	08/02	47	47	Due to equipment failures, waited for TASI mechanical to service train that had not been tended to for several hours
OKJ	732	08/02	8	8	Air / Brake / Wheel C6964, Late release and air problems with cab. Tasi did not start class 1 brake test until 12:15. After completing and dropping of flags, cab car brake pipe was not responding to set, release or emergency brake application.
PDX	506	08/02	(Trn Cxld)		Brush fires
SAC	704	08/02	1		
SAC	743	08/02	(Trn Cxld)		Third Party Engine Failure
SAC	749	08/02	1		
SAN	581	08/02	4	4	770 arrived into SAN at 13:49, boarded passengers for 581 and complete necessary class 2 with engineer 770
SEA	11	08/02	7	7	Called management for documentation purposes: Will Browning (no answer) and David Blackmer. Notified that we'd be late due to coach attendant assigning seats. Other, SEA
SJC	724	08/02	1		

Eastern Region

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	100.0	99.7	94.8	166	0
CDOT	95.0	100.0	90.63	92.4	16	0
MARC	95.0	92.3	90.0	90.2	13	1
SEPTA	95.0	95.5	94.1	91.5	112	5
NJT-NED	95.0	92.75	95.36	88.6	193	14
NJT-SED	95.0	100.0	100.0	97.2	24	0

Operating Highlights

Train 40(01) East of Pittsburgh, PA - Freight Train Interference

03AUG26: Train 40(01) with 163 customers was delayed on the CSX Pittsburgh subdivision 16 miles east of Pittsburgh at Demmler/MP 11.7 due to meeting M331.

Train	Delay	Comment
40 (01)	39"	

Train 53(02) South of Charleston, SC - Freight Train Interference

03AUG26: Train 53(02) with 461 customers was delayed on the CSX Charleston subdivision eight miles south of Charleston at South Drayton Hall/MP 394.7 due to meeting M410-02.

Train	Delay	Comment
53 (02)	36"	

Train 245(02) North of Croton-Harmon, NY - Commuter Train Interference

03AUG26: Train 245(02) was delayed on the Metro North Hudson line five miles north of Croton-Harmon at Cortlandt/MP 38.4 due to single tracking and meeting a Metro North local account of a disabled freight ahead at CP 46.

Train	Delay	Comment
245 (02)	1'00"	

CSX Charleston Subdivision North of Charleston, SC - Police Related

02AUG26: Trains 89(02) and 52(02) were delayed on the CSX Charleston subdivision due to a vehicle on the tracks four miles north of Charleston at MP 383.7. Train 89(02) was held at Hannahan/MP 383.4 and train 52(02) was held at Charleston/MP 387.4 until the vehicle was removed and the tracks were inspected.

Train	Delay	Comment
89 (02)	25"	
52 (02)	26"	

Train 41(01) South of Hamlet, NC - Weather

02AUG26: Train 41(01) with 203 customers was delayed on the CSX Hamlet subdivision starting one mile south of Hamlet between MP 254.2 and MP 345.0 due to high wind warnings.

Train	Delay	Comment
41(01)	30"	

Train 98(02) South of Florence, SC - Freight Train Interference

02AUG26: Train 98(02) with 265 customers was delayed on the CSX Charleston subdivision seven miles south of Florence at Java/MP 300.0 due to meeting IO31-02.

Train	Delay	Comment
98(02)	40"	

Train 2260(02) West of Old Saybrook, CT - Signal

02AUG26: Train 2260(02) with 298 customers was delayed on the Amtrak New Haven to Boston line seven miles west of Old Say Brook due to the 21 switch failed at Fitter/MP 97.8. C&S responded to the scene, made repairs, and the switch operated as intended.

Train	Delay	Comment
2260(02)	1'11"	

Train 67(02) Kingston, RI - Police Related

02AUG26: Train 67(02) with 285 customers was delayed on the Amtrak New Haven to Boston line at Kingston/MP 158.1 due to meeting Amtrak Police to remove a fare evader. Once the fare evader was removed, 67(02) departed Kingston at 816PM-ET, 32 minutes late.

Train	Delay	Comment
67(02)	31"	

Amtrak Washington Terminal Washington, DC - Servicing

02AUG26: Trains 40(01) with 171 customers, 97(02) with 273 customers, and 87(02) with 381 customers were all delayed departing Washington due to service and inspection. Trains 97(02) and 87(02) were delayed due to late locomotives from the pit account of mechanical issues related to I-ETMS. Customers on train 97(02) received service recovery with the coach customers offered snack packs and bottled water. First class customers were offered ham or turkey sandwiches, chips, and soda.

Train	Delay	Comment
40(01)	53"	
87(02)	2'16"	
97(02)	2'19"	

Amtrak NYP Line East of Trenton, NJ - Signal

02AUG26: Trains were delayed on the Amtrak New York to Philadelphia line one mile east of Trenton due to a TOL at Ham/MP 55.7 with the 12 switch and 23 switches locked reverse. C&S responded to the scene, normalized the 12 and 23 switches, and train traffic continued as normal.

Train	Delay	Comment
122 (02)	27"	
669 (02)	07"	
2218 (02)	27"	
2267 (02)	12"	
149 (02)	06"	
NJ7861	10"	
NJ7859	05"	
NJ7856	38"	
NJ7858	28"	
SE1730	09"	

Train 49(02) South of Poughkeepsie, NY - Routing

02AUG26: Train 49(02) with 193 customers was delayed on the Metro North Hudson line 15 miles south of Poughkeepsie due to a dispatcher hold at CP 58.

Train	Delay	Comment
49 (02)	46"	

Train 449(02) East of Pittsfield, MA - Passenger Train Interference

02AUG26: Train 449(02) with 97 customers was delayed on the CSX Berkshire subdivision just west of Pittsfield station due to being held out to meet train 448(01).

Train	Delay	Comment
449 (02)	33"	

Train 448(01) East of Pittsfield, MA - Freight Train Interference

02AUG26: Train 448(01) was delayed on the CSX Berkshire subdivision 22 miles east of Pittsfield due to meeting unknown CSX at CP 171.

Train	Delay	Comment
448 (01)	35"	

Train 158(02) North of Ashland, VA - Weather

02AUG26: Train 158(02) with 344 customers was delayed on the CSX RF&P subdivision starting nine miles north of Ashland due to high wind warnings between MP 24.0 and MP 47.0. The train was further delayed north of Quantico for flash flood warnings. Train 53(02) was also delayed for high wind warnings and held at MP 47.9.

Train	Delay	Comment
158 (02)	34"	N/ASD - HWW
158 (02)	31"	N/QAN - FFW
53 (02)	25"	

Train 68(02) South of St-Lambert, QC - Weather

02AUG26: Train 68(02) was delayed due to operating thru heat orders on the CN Rouse Point subdivision from MP 42.7 to MP 0.0.

Train 1246(02) Pittsfield, MA - Initial Terminal Delay

02AUG26: Train 1246(02) with E/15 and 5 cars was delayed departing Pittsfield on the CSX Berkshire subdivision due to the late arriving equipment from train 1233(02) that arrived Pittsfield at 338PM-ET, 38 minutes late. Train 1246(02) departed Pittsfield at 351PM-ET, 36 minutes late.

Train	Delay	Comment
1246(02)	36"	

Train 51(02) South of Culpeper, VA - Utility Company Failure

02AUG26: Train 51(02) with E/83 and 5 cars was delayed on the Buckingham Branch North Mountain subdivision at MP CB 165.4 due to downed powerlines ahead at MP CB 170.0. This also delayed train 50(01) being held at MP CB 194.8 for train 51(02) to clear Charlottesville station. Buckingham Branch had a maintainer in a high rail vehicle inspecting the tracks. The initial report was down trees but that was corrected to down powerlines they were able to be cleared from the right of way. Train 51(02) was able to proceed south and then 50(01) north.

Train 50(01) was further delayed meeting 51(02) and one westbound freight.

Train	Delay	Comment
51(02)	1'37"	
50(01)	1'56"	

Train 283(02) New York, NY - Servicing

02AUG26: Train 283(02) with E/94, E/705 and 5 cars was delayed departing New York due to having issues getting to the yard for servicing resulting in the late release from the yard.

Train	Delay	Comment
283(02)	1'10"	

Train 105(02) New York, NY - Servicing

02AUG26: Train 105(02) was delayed departing New York due to servicing and the need to run the engine around due to train 120(02) arriving with one engine.

Train	Delay	Comment
105(02)	32"	

Train 2209(02) South of Baltimore, MD -Switch Failure/ Signal

02AUG26: Legacy Train 2209(02) with PC/2015, PC/2010 was delayed on the PW Line at MP 112.4/Grove Interlocking due to the 23SW being stuck on center. The maintainer arrived and the train was able to proceed south.

Train	Delay	Comment
153(02)	20"	
2209(02)	37"	
154(02)	09"	
MK681	17"	

Train 65(01) Woodbridge, VA - Injured or Sick Passenger or Employee

02AUG26: Train 65(01) ~~28-FOI-00656~~ ~~00000008476~~ ~~UNCLASSIFIED~~ ~~8/3/2026~~ delayed on the CSX RF&P subdivision at MP 88.9 due to a customer traveling under RES# 8D1CD9 in need of medical assistance. When EMS arrived and treated the customer she was removed and her family exited the train total of 4 customers.

Train	Delay	Comment
65(01)	31"	

Maintenance of Way Highlights

25-591-00635

00000008476

"UNCLASSIFIED"

M/A49

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00636 00000008476 "UNCLASSIFIED" 8/3/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	
284(26)	25"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS – NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00636a 00000008478 UNCLASSIFIED 18/12/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No Data

Eastern Region

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Western Region

Operating Highlights

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train 7/27(02) East of Red Wing, MN - Trespasser Near Miss

02AUG26: Train 7/27(02), with 266 customers onboard, was delayed at mile post 358.0, 12 miles east of Red Wing, MN/MP370.68, on the CPKC River subdivision after the engineer reported striking a trespasser. The conductor and assistant conductor walked the train and found the trespasser on the tracks. This was not a strike. Local police arrived at the scene and arrested the trespasser. Once the scene was released, train 7/27(02) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(02)	1'08"	

Train 794(02) South of Santa Barbara, CA - Trespasser Strike

02AUG26: At 7:26 PM PT, Train 794(02), operating with CC/6905, five cars, locomotive E/C2113, and 367 customers onboard, struck a trespasser at MP 368.9 on the Union Pacific Santa Barbara Subdivision, south of Santa Barbara, CA with city and county name the same. The incident did not occur at a grade crossing and took place on single-main-track territory. The trespasser sustained fatal injuries. There were no reported injuries to crew members or customers, and head-end power remained operational throughout the incident. Weather conditions were reported as approximately 70°F and sunny. Local law enforcement, Amtrak Police, and an Amtrak Road Foreman responded to the scene. The train crew requested relief and remained with the train pending the investigation. The Coroner responded to the scene, and once the investigation was completed and the remains removed, the track was cleared for service. The train then shoved back to Santa Barbara Station, where a relief crew assumed operation. Following the crew change, Train 794(02) departed Santa Barbara and resumed its trip.

As a result of the extended delay, the following Pacific Surfliner service adjustments were implemented:

- Equipment from Train 587(02) was used to operate an on-time section of Train 794(02) between Los Angeles and San Diego.
- Two buses were secured to accommodate customers from the affected Train 794(02) traveling south of Los Angeles.
- The equipment involved in the incident was routed directly to the Los Angeles 8th Street Yard for inspection and servicing.

WBS#: B.TR.100150.6982

National Response Center Number: 1469632

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
794(02)	3'22"	
785(02)	1'16"	

Train 319(02) West of Warrensburg, MO - Freight Train Interference

02AUG26: Train 319(02), with 230 customers onboard, was delayed between Warrensburg, MO/MP218.5 and Lee's Summit, MO/MP259.9 on the UP Sedalia subdivision following the UP freight UP/7312. Once the route was clear, train 319(02) continued west.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
319(02)	35"	

Train 716(02) East of Antioch-Pittsburg, CA - Car on Tracks

02AUG26: Train 716(02) delayed on the BNSF Stockton subdivision one miles east of Antioch-Pittsburg at West Sando/MP 1150.8 due to a vehicle on the tracks ahead at MP 1151.1. Once the vehicle was removed and the tracks were inspected, 716(02) continued to Stockton.

Train	Delay	Comment
716(02)	1'09"	

Train 716(02) East of Antioch-Pittsburg, CA - Vehicle on the Tracks

02AUG26: Train 716(02), with 123 customers onboard, was delayed at Sando/MP1148.5, 3.5 miles east of Antioch-Pittsburg, CA/MP1152.0, on the BNSF Stockton subdivision holding for local police to remove a vehicle from the tracks. Once the route was clear, train 716(02) continued east.

Train	Delay	Comment
716(02)	1'09"	E/ACA

Train 7/27(01) East of East Glacier Park, MT - M of W Work

02AUG26: Train 7/27(01), with 215 customers onboard, was delayed at mile post 1117.7, 21 miles east of East Glacier Park, MT/MP1138.1, on the BNSF Hi Line subdivision holding for maintenance of way crews to work on a bridge at mile post 1118.0. Once the route was opened, train 7/27(01) continued west.

Train	Delay	Comment
7/27(01)	2'01"	

Train 718(02) Oakland, CA - Third Party Contractor Engine Failure

02AUG26: Train 718(02), with engine CDTX2004, 8 cars, and 27 customers onboard, was delayed departing Oakland Jack London Station, CA/MP7.1 on the UP Niles subdivision due to the late release of the equipment by TASI. Once train 718(02) was serviced and inspected, it departed Jack London Station, CA.

Train	Delay	Comment
718(02)	47"	

Train 518(02) South of Tukwila, WA - Trespasser Strike

02AUG26: At 5:07 PM PT, Train 518(02), ~~UNCLASSIFIED~~ with locomotive E/186, three cars, CC/90340, and 156 customers onboard, struck a trespasser at MP 15.8 on the BNSF Seattle Subdivision, south of Tukwila, WA, in Kent, King County, Washington. The incident occurred at the East James Street grade crossing (DOT #085629K), a public crossing located on double main track territory and equipped with advance warning signs, pavement markings, and operational gate arms. The incident resulted in a fatality. There were no reported injuries to crew members or customers, and head-end power remained operational throughout the incident. Local law enforcement and an Amtrak Road Foreman responded to the scene to conduct the investigation. Train 518(02) remained stopped until the investigation was completed and the track was released for service.

The incident also affected several other trains operating in the corridor:

- Train 509(02), carrying 160 customers onboard, was held at Tukwila Station awaiting release of the track.
- Train 511(02) was delayed while holding behind Train 509(02) pending clearance through the affected area.
- Train 14(01) was delayed south of Tukwila as a result of the track blockage.

National Response Center Number: 1469635

Train	Delay	Comment
518(02)	2'05"	
509(02)	3'02"	
511(02)	1'06"	
14(01)	2'01"	

Train 6(02) East of Reno, NV - Heat Orders

02AUG26: Train 6(02), with 162 customers onboard, was delayed between Massie/MP282.0 and Weso Junction/MP421.26 beginning 50 miles east of Reno, NV/MP240.7, on the UP Nevada subdivision due to heat orders. Once clear of the affected area, train 6(02) continued east.

Train	Delay	Comment
6(02)	46"	

Train 716(02) Oakland, CA - Third Party Contractor Engine Failure

02AUG26: Train 716(02), with 26 customers to board, was delayed departing Jack London Station, CA/MP7.1 on the UP Niles subdivision due to the late release by mechanical. The decision was made to originate train 716(02) at Emeryville, CA., with customers boarding at Jack London Station taking train 738(02) to Emeryville. Train 716(02) departed Emeryville at 5:14PM PT, operating two hours and forty-six minutes late.

Train	Delay	Comment
716(02)	2'46"	ITD Originate EMY

Train 355(02) West of Dearborn, MI - ITCS Failure

03AUG26: Train 355(02), with engine IDTX4608, 5 cars, and 154 customers onboard, was delayed by ITCS issues beginning upon arrival at Dearborn Station, MI/MP9.7 on the Michigan Department of Transportation Michigan Line subdivision. After troubleshooting, the crew cut out ITCS system and continued west at a maximum of 59MPH under rule 595.

Train 354(02), with 277 customers onboard, was delayed at Kalamazoo, MI/MP143.4 on the Amtrak Michigan Line subdivision meeting Amtrak train 355(02).

Train	Delay	Comment
-------	-------	---------

Train 22(02)/422(31) West of Longview, TX - Freight Train Interference

02AUG26: Train 22(02)/422(31) p0000008476 184 "UNCLASSIFIED" 8/3/2026, was delayed at mile post 91.2, 1.7 miles west of Longview, TX/MP89.5, on the UP Little Rock subdivision meeting UP freight UP/5461. The freight was stopped and blocking access to Longview Station. Once the route was clear, train 22(02)/422(31) continued into Longview and parts north.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(02)/422(31)	45"	

Train 41(02) Chicago, IL - Car Failure

02AUG26: Train 41(02) required a supplemental bus operating between Chicago and Elkhart due to the late bad ordering of coach car 25024 for a mainline clog. The car remained dead in consist when train 41(02) departed.

WBS#: B.TR.100150.6980

Train 732(02) West of Sacramento, CA - Police Related

02AUG26: Train 732(02), with 63 customers onboard, was delayed at mile post 87.3, 1.8 miles west of Sacramento, CA/MP89.1, on the UP Martinez subdivision due to a police hold on rail traffic. Once the route was clear, train 732(02) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
732(02)	32"	

Train 7/27(02) Late Departure Chicago, IL - Car Failure

02AUG26: Train 7/27(02), E/196-E/193 & 11 cars, was delayed departing Chicago, IL, due to late turn of equipment off Train 8/28(30) which arrived at 217AM-CT, 9 hours and 32 minutes late. Train 7/27(02) was further delayed due to toilet issues in sleeper C/32063 once train was in the station. Mechanical responded to make repairs.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
7/27(02)	1'05"	

Train 724(02) Emeryville, CA - Third Party Contractor Engine Failure

02AUG26: Train 724(02), operating with CC/C6961, 4 cars, E/C2009 and carrying 88 customers onboard, was delayed departing Emeryville, CA Station on the Union Pacific Martinez Subdivision due to locomotive loading issues. Upon arrival at Emeryville, the crew reported that the locomotive was not loading properly and coordinated with TASI Mechanical to troubleshoot the problem. Despite troubleshooting efforts, the issue could not be resolved in a timely manner. As a result, Train 724(02) was terminated at Emeryville, and all customers were accommodated on Train 728(02) for continued travel. The affected equipment was subsequently removed from service for further mechanical inspection and repair.

Turn trains 743(02) and 742(02) were canceled with customers able to use next available services.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
724(02)	Term	EMY
743(02)	Canceled	
742(02)	Canceled	

Train 714(02) Oakland, CA - Third Party Contractor Engine Failure

02AUG26: Train 714(02) was delayed by locomotive C2003 was delayed departing Oakland, CA, on the UPRR Niles Subdivision due to a mechanical issue. Mechanical personnel identified a coolant leak on locomotive C2003. To minimize the impact on operations and reduce the delay, Train 714(02) exchanged equipment with Train 711(02), allowing service to continue.

Train 714(02) was further delayed at Turlock, CA/MP1079.5 when engine CDTX2001 shut down with oil overpressure faults. The engine was restarted after troubleshooting, and train 714(02) departed Turlock, CA.

Train	Delay	Comment
714(02)	57"	TRK
714(02)	1'27"	OKJ

Train 14(02) Los Angeles, CA - Engine Failure

02AUG26: Train 14(02) was delayed departing Los Angeles, CA, on the SCRRA/MetroLink River Subdivision due to locomotive mechanical issues. Locomotive E/349 was originally scheduled to lead the train; however, air brake problems were identified during pre-departure inspections. As a result, E/349 was removed from service and replaced with locomotive E/192, allowing the train to proceed.

Train	Delay	Comment
14(02)	1'33"	

Train 319(02) Alton, IL - Freight Train Interference

02AUG26: Train 319(02) was delayed at Alton, IL/MP255.1, on the UPRR Springfield Subdivision, due to IG4LB-02 (UP 9572) actuated a dragging equipment detector ahead. Train 319(02) held for UPRR crew to complete inspection of consist and operate freight in the clear.

Train	Delay	Comment
319(02)	1'14"	

Train 21(01) South of Little Rock, AR - Freight Train Interference

02AUG26: Train 21(01) was delayed at Alexander/MP358.9, 13 miles south of Little Rock, AR, on the UPRR Little Rock Subdivision, meeting UP6739.

Train	Delay	Comment
21(01)	57"	

Train 22(02)/422(31) Late Departure San Antonio, TX - Late Connecting Train 2/422(31)

02AUG26: Train 22(02)/422(31) was delayed departing San Antonio, TX, holding for late connecting Train 2/422(31) which arrived at 654AM-CT, 1 hour and 54 minutes late.

Train	Delay	Comment
22(02)/422(31)	48"	

Train 24(02) North of New Orleans, LA - Freight Train Interference

02AUG26: Train 24(02) was delayed at La Crosse/MP781.8, 30 miles north of New Orleans, LA, on the CSX NO&M Subdivision, meeting CSX 521 and then further delayed due to signal issues between MP780.3 and MP772.8. Train 23(02) was delayed at Claiborne/MP766.3 meeting Train 24(02).

Train	Delay	Comment
24(02)	42"	N/NOL, meet CSX521
24(02)	26"	N/NOL, signal issues
23(02)	31"	

Train 391(02) South of Mattoon, IL - Freight Train Interference

02AUG26: Train 391(02) was delayed south of Mattoon, IL/MP172.31, on the CN Champaign Subdivision, following southbound CN freight traffic between Neoga/MP184.4 and Effingham/MP199.2.

Train	Delay	Comment
391(02)	38"	

Train 729(02) Emeryville, CA - Trespasser Incident

02AUG26: Train 729(02), led by engine C2104 and carrying 63 customers, fatally struck a trespasser at 10:55 a.m. PT approximately one mile west of Emeryville, CA, on the UPRR Martinez Subdivision. The strike did not occur at a grade crossing. Weather conditions at the time were 69°F and sunny. There were no reported injuries to customers or crew. The engineer requested relief following the incident, while the conductor and assistant conductor remained on duty. A relief engineer arrived at 11:40 a.m. PT. All customers were transferred to train 733(02). Amtrak road foreman and local authorities responded to the scene. Due to freight train in the area of the incident, access to the site was challenging for the coroner, which extended the on-scene investigation and contributed to the overall delay. The coroner requested all rail traffic stopped upon accessing the scene.

NRC# 1469605

CA# 26-3894

National Response Center Number: 1469605

Train	Delay	Comment
733(02)	14"	pax transfer
737(02)	12"	
729(02)	3'19"	
728(02)	28"	

Train 1340(02) Supplemental Bus - Car Failure

02AUG26: Train 1340(02), E/518 & 3 cars, reported the third car, C/35004 HVAC inoperative and car operating deadhead only. Train 1340(02) was over capacity by 58 seats. One supplemental bus was secured and operated La Crosse-Tomah-Wisconsin Dells, Columbus-Milwaukee. Passengers for east of Milwaukee were reaccommodated on Hiawatha service. Due to C/35004 hot and no replacement cars available in Chicago, Train 341(02) was also over capacity by 59 seats. One supplemental bus was secured and operated Chicago to Milwaukee express.

Train 770(02) Goleta, CA - Car Failure

02AUG26: Train 770(02) is off line. C2140 six cars, and 13 passengers, experienced a delay departing Goleta, CA, on the UPRR Santa Barbara Subdivision. Mechanical personnel reported the train was unable to pass a Class I brake test due to a stuck brake on car 6411. After troubleshooting and correcting the issue, mechanical personnel successfully completed the brake test, and the train was released for service.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
770(02)	45"	

Train 365(02) Port Huron, MI - Injured or Sick Passenger or Employee

02AUG26: Train 365(02), E/58-6 cars-E/IDTX4605, was delayed departing Port Huron, MI, due to the engineer sustaining an injury and required medical attention. It was necessary to secure a replacement engineer. Train 365(02) was further delayed departing Port Huron waiting on CN 302 to clear route ahead. Train 364(02) was delayed departing Chicago, IL, due to late turn of equipment off Train 365(02) which arrived at 323PM-CT, 3 hours and 28 minutes late.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
365(02)	2'16"	PTH, recrew engineer
365(02)	58"	PTH, CN 302 a/h
364(02)	1'37"	CHI, late turn off 365(02)

Train 59(01) Centralia, IL - Freight Train Interference

02AUG26: Train 59(01), with 151 customers, was delayed holding at Centralia, IL station on the CN Centralia subdivision due to Norfolk Southern freight 224(31) stopped at the Centralia Diamond/MP253.2 with a wrong end draw bar. Norfolk responders arrived on scene at 220AM CT to assist the freight crew with the wrong end drawbar. Train 58(01), with 151 customers, was also delayed holding at Carbondale, IL Station/MP308.3 for open route ahead. Train 58(01) was further delayed at MP259, 7 miles south of Centralia, IL, meeting Train 59(01). Train 58(02) was delayed south of Jackson, MS/MP728.7, on the CN McComb Subdivision, due to engineer at Jackson turning off late Train 59(01). Train 58(02) was delayed holding for Train 59(01) to arrive in Jackson first.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
59(01)	5'40"	
58(01)	3'36"	CDL
58(01)	35"	S/CEN, meet 59(01)
58(02)	1'31"	S/JAN

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, BNSF was notified that rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse fire adjacent to the railroad right-of-way. Firefighting operations and concerns regarding the structural stability of the building required the closure of the rail corridor, affecting both Amtrak Cascades and long-distance services. Train 507(02), carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

WBS#: B.TR.100150.6981

Train	Delay	Comment
507(02)	1'41"	bus VAN-PDX
506(02)	Canceled	
508(02)	45"	bus PDX-VAN

UPRR Freight Derailment East of Grand Junction, CO - California Zephyr Service

01AUG26: At 609PM-MT, UPRR reported CAOUT-21 (UP8539) derailed forty-five cars at MP406.7, 42 miles east of Grand Junction, CO, on the UPRR Glenwood Springs subdivision. Cars were upright and on the ground. No hazardous material cars were involved in the derailment. Heavy equipment was expected to begin arriving on scene at approximately 0500AM-MT on 02AUG. Initial estimate was thirteen hours needed to clear derailed cars, then 24 hours needed for track work/repairs.

02AUG26: Due to the derailment and track estimate, a bus bridge was arranged for Trains 5(01) and 6(01) between Glenwood Springs, CO and Grand Junction, CO. Train 5(01), E/33-E/29 & 9 cars, wye trail E/29 at Denver to position engines back to back. At Glenwood Springs, Train 5(01) customers (243) were accommodated on four busses to Glenwood Springs and reboarded equipment off Train 6(01) which operated to Emeryville, CA, as Train 5(01). Engines, E/33-E/29 ran around the equipment at Glenwood Springs to be in position to continue east as Train 6(01). Train 6(01), E/40-E/179 & 9 cars, 165 customers, were delayed in Grand Junction, CO, holding for the busses enroute from Glenwood Springs. Customers were then bussed to Glenwood Springs and boarded equipment off Train 5(01) which operated to Chicago, IL as Train 6(01).

03AUG26: A bus bridge was also put in place for Trains 5(02) and 6(02) between Denver, CO and Grand Junction, CO. Five busses secured at Denver, CO, for Train 5(02) customers. Busses operated Denver-Winter Park-Granby-Glenwood Springs-Grand Junction, where customers boarded equipment off Train 6(02) which operated to Emeryville as Train 5(02). Four busses secured at Grand Junction for Train 6(02) customers. Busses operated Grand Junction-Glenwood Springs-Granby-Winter Park-Denver, where customers boarded equipment off Train 5(02) which operated to Chicago as Train 6(02).

WBS#: B.TR.100150.6977

Train	Delay	Comment
5(01)	45"	DEN, wye E/29
5(01)	GSC-GJT bus bridge	
6(01)	GJT-GSC bus bridge	
5(02)	DEN-GJT bus bridge	
6(02)	GJT-DEN bus bridge	

UPRR Freight Derailment East of Lordsburg, NM - Sunset Limited Service Adjustments

01AUG26: At 820PM-CT, Union Pacific reported train ZAILA-31 (UP 7849) derailed 39 cars at MP1157.56, 9 miles east of Lordsburg, NM, on the UPRR Lordsburg Subdivision, impacting both Mains One and Two. At the time of the report that was no ETA for open track or responders. UPRR advised Main One would be the first track to be cleared to allow for engineering work. UPRR estimated 45 panels needed on each track and that Main Two will need a westbound signal replacement.

02AUG26: UPRR estimated Main Two open at 700PM-MT August 2nd and Main 1 700PM-MT August 3rd. UPRR advised single tracking for 24 miles due to cross-over out of service at MP1158 and heavy traffic expected through the area once tracks reopened. As a result, Train 1(01)/421(31) terminated at El Paso, TX, with five busses secured as alternate transportation for 178 customers between El Paso and Los Angeles, CA. Train 2/422(02) originated at El Paso, with five busses secured as alternate transportation for 205 customers between Los Angeles and El Paso.

WBS#: B.TR.100150.6979

Train	Delay	Comment
1(01)	Terminated ELP	
421(31)	Terminated ELP	
2(02)	Originated ELP	
422(02)	Originated ELP	

Train 383(01) and 380(02) Chicago, IL - Engine Failure

01AUG26: Due to a lack of available equipment in Chicago, Trains 383(01) and 380(02) were canceled in their entirety with two alternate buses were secured to provide transportation for affected customers. For Train 383(01), Bus #1 operated from Chicago Union Station to Macomb and Quincy, while Bus #2 operated all intermediate stops between Chicago Union Station and Quincy. These same buses were scheduled to turn and operate as Train 380(02), with Bus #1 operating from Quincy to Macomb and Chicago Union Station and Bus #2 operating all intermediate stops.

02AUG26: Due to ongoing equipment issues in Chicago, Trains 383(02) and 380(03) were cancelled entirely, with alternate transportation between Chicago and Quincy.

WBS#: B.TR.100150.6970

Train	Delay	Comment
383(01-02)	Cancelled	
380(02-03)	Cancelled	

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures in the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

25JUL26: Train 7(23) arrived into Seattle, WA 2'46" late causing late departure of 8(25). Train 27(23) arrived into Portland, OR 3'51" late causing late departure of 28(25).

25JUL26: Temperatures continue to be in excess of 100°F in the Great Plains. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow, Milk River and Hi-Line Subdivision from Stanley, ND and Cutbank, MT. Train 7 / 27(24) and Train 8 / 28(24) were affected by the restrictions and freight interference caused by the restrictions.

Due to late operation of 7/27(24) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(24) from Spokane to Seattle and for 27(24) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(26) Seattle to Spokane and 28(26) Portland to Spokane with Train 8/28(26) originating Spokane, WA.

27JUL26: Due to late operation of 7/27(25) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(25) from Spokane to Seattle and for 27(25) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(27) Seattle to Spokane and 28(27) Portland to Spokane with Train 8/28(27) originating Spokane, WA.

01AUG26: Due to late operation of 7/27(31) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(31) from Spokane to Seattle and for 27(31) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(02) Seattle to Spokane and 28(02) Portland to Spokane with Train 8/28(02) originating Spokane, WA.

WBS#: B.TR.100150.6937

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	
8/28(24)	2'16"	
7/27(24)	2'20"	Term SPK
28(25)	57"	late turn 27(23)
8(25)	2'00"	late turn 7(23)
7/27(25)	2'26"	Term SPK
8/28(27)		Orig SPK
8/28(25)	1'46"	
8/28(26)	1'16"	Orig SPK
7/27(26)		Term SPK
8/28(28)		Orig SPK
8/28(27)	2'15"	Orig SPK
8/28(28)	1'46"	Heat restrictions MAL-WTN
8/28(28)	1'31"	Frt congestion due to heat restrictions
7(31)	30"	WPT - GGW
7(31)	1'02"	WTN - WPT
8/28(01)	2'43"	MAL - GGW

Maintenance of Way Highlights

Burlington Northern Santa Fe Fallbridge Subdivision between Portland, OR and Spokane, WA - Scheduled M/W Work TWA 26-078

02AUG26: Burlington Northern Santa Fe will have a 36-hour outage affecting the Empire Builder service starting at 5:00A-PDT. They will be performing bridge work, slide fence replacement and switch maintenance at Bingen / MP 77.0 on the Fallbridge Subdivision.

To accommodate the above outlined infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(31JUL, 01AUG) will terminate at SPK.
- Train 28 (02AUG, 03AUG) will originate at SPK.

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between SPK and PDX making all stops except WIH.
- Bus 4028 will provide alternate transportation between PDX and SPK making all stops except WIH.

EQUIPMENT

- Equipment for Train 27(31Jul, 01AUG) will stay coupled to Train 7 at SPK
- Equipment for Train 28(02AUG, 03AUG) will be coupled to Train 8 departing SEA

WBS#: B.TR.100150.6891

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

-Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple track construction project on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,
Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,
Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,
Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,
Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,
Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,
Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,
Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,
Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No Data

Western Region**Displaced Guests**

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need Cars	Projected Need Seats	Number Operated Cars	Number Operated Seats	Standees	Location
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
None				

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
149 (02)	BOS	EXTRA BUSINESS CLASS CAR IN LIEU OF A COACH CAR. INVENTORY REDUCED WITH NO OVERAGES.	No impact	0	81527
449 (02)	BOS	AM I cafe' (43349) in lieu of lounge(280xx) used.	NONE	0	43349
149 (02)	BOS	149(02) is operating with a club-dinette in lieu of a cafe car.	NONE	0	48173
67 (02)	BOS	Cafe car 43391 operating on 67(02) due to 48140 cafe B/O refrigeration.	NONE	821	43391
341 (02)	CHI	train 1340(02) has just reported car 35004 as (BYD-HVAC). Car will d/h and conductor is moving the passengers out. In lieu of this the train is over capacity. The turn is 341(02). Chi has stated they	SUPPLEMENTAL BUSSING	60	35004
98 (02)	HIA	AMI in lieu of AMII. inventory increased. no customer impact.	No impact	0	82612
1340 (02)	MSP	train 1340(02) has just reported car 35004 as (BYD-HVAC). Car will d/h and conductor is moving the passengers out. In lieu of this the train is over capacity. The turn is 341(02). Chi has stated they	SUPPLEMENTAL BUSSING	58	35004
158 (02)	NFK	158(02) is operating with a Business Class car in lieu of a coach.	NONE	0	81526
186 (03)	NPN	Cafe car 43391 operating on 186(03) due to 48140 cafe B/O refrigeration.	NONE	0	43391
97 (02)	NYP	schedule changes performed for 9710 and 9711 cars. crew moved to 9710 car. check war report.	No impact	0	62507
42 (02)	PGH	consist is operating 5 AMII coaches instead of 4 and a 1 AM I Business car. i have 0'd out the Bus sales an added the seat in to coach. due to door to Platform issues 25083 is in lieu of 815xx	NONE	48	25083

Reverse Consists

26-FOI-00636

00000008476

"UNCLASSIFIED"

8/3/2026

Train Number	Station	Reason
153 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
155 (02)	NYP	Consist reversed Business class seat orientation may have changed At Front
150 (02)	PHL	Consist reversed Business class seat orientation may have changed At Front
121 (02)	NYP	Business class change only Business class seating orientation may have changed At Rear
135 (02)	BOS	Consist reversed Business class seat orientation may have changed At Front
122 (02)	WAS	Business class change only Business class seating orientation may have changed At Front
158 (02)	NFK	Consist reversed Business class seat orientation may have changed At Front
146 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
125 (03)	SPG	Consist reversed Business class seat orientation may have changed At Front
94 (03)	NFK	Consist reversed Business class seat orientation may have changed At Front
88 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front
96 (02)	WAS	Consist reversed Business class seat orientation may have changed At Front