



CNOC

(CONSOLIDATED NATIONAL OPERATIONS CENTER)

Amtrak Status Report

Wednesday, August 05, 2026

Rules: 0-44



This report contains Confidential Information as defined in Amtrak's Confidential Information Policy. A failure to comply with Amtrak's Confidential Information Policy may lead to denial of access to Amtrak information, discipline up to and including termination of employment, and legal prosecution.

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/04/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	56	82.4%	1,208	193	84.0%	92,152	12,749	86.2%
Central Division	86.0%	58	4	93.1%	227	30	86.8%	17,655	1,604	90.9%
East Division	82.0%	176	28	84.1%	650	93	85.7%	48,320	7,515	84.4%
West Division	86.0%	85	24	71.8%	331	70	78.9%	26,177	3,630	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Customer On Time Performance

26-FOI-00644 00000008494 "UNCLASSIFIED" 8/7/2026

Service	Day				Month to Date			FY to Date		
	Target	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score	Total Customers	Late Customers	Score
Amtrak System	80%	97,774	25,732	74%	437,794	119,821	73%	30,786,798	7,759,827	75%
Northeast Corridor	81%	41,833	7,341	82%	187,811	40,423	78%	13,498,526	3,297,201	76%
Acela	83%	9,858	2,314	77%	37,530	9,117	76%	2,698,442	710,766	74%
Northeast Regional	79%	31,975	5,027	84%	150,281	31,306	79%	10,800,084	2,586,435	76%
Richmond / Newport News / Norfolk	77%	9,433	2,217	76%	48,155	14,086	71%	3,354,354	976,502	71%
Springfield Shuttles	89%	698	0	100%	2,688	155	94%	191,427	30,242	84%
Roanoke	79%	3,588	968	73%	14,063	1,915	86%	1,019,575	220,376	78%
On Spine Northeast Regional	80%	18,256	1,842	90%	85,375	15,150	82%	6,234,728	1,359,315	78%
State Supported	80%	44,460	12,442	72%	195,916	49,783	75%	13,510,705	2,852,617	79%
Borealis	80%	557	0	100%	2,401	309	87%	172,054	35,956	79%
Capitol Corridor	90%	3,999	713	82%	13,529	1,850	86%	1,131,970	147,948	87%
Carolinian	70%	982	118	88%	4,508	1,438	68%	349,354	136,407	61%
Cascades	75%	1,285	1,025	20%	8,556	3,903	54%	792,076	219,006	72%
Downeaster	82%	1,785	35	98%	8,349	415	95%	468,560	56,240	88%
Empire	78%	6,119	2,471	60%	25,763	8,223	68%	1,670,205	392,070	77%
Adirondack	72%	368	275	25%	1,824	457	75%	101,827	31,320	69%
Ethan Allen Express	70%	544	382	30%	2,466	1,190	52%	171,410	61,566	64%
Maple Leaf	70%	883	478	46%	3,796	1,829	52%	204,740	78,971	61%
New York - Albany	85%	2,984	1,259	58%	11,205	3,330	70%	773,643	129,265	83%
New York - Niagara Falls	75%	1,340	77	94%	5,873	824	86%	409,865	86,539	79%
Berkshire Flyer	60%	0	0	-	599	593	1%	8,720	4,409	49%
Gold Runner	73%	2,396	1,181	51%	10,399	6,163	41%	765,934	276,309	64%
Heartland Flyer	70%	186	183	2%	1,177	1,024	13%	65,844	26,450	60%
Hiawatha	90%	1,863	0	100%	8,322	599	93%	529,598	58,327	89%
Illinois	78%	2,217	559	75%	10,885	3,054	72%	757,270	207,663	73%
Carl Sandburg / Illinois Zephyr	85%	220	157	29%	1,140	519	54%	126,001	34,700	72%
Illini / Saluki	85%	688	268	61%	3,713	1,470	60%	263,712	63,404	76%
Lincoln Service	70%	1,309	134	90%	6,032	1,065	82%	367,557	109,559	70%
Keystone	92%	8,362	574	93%	28,958	1,766	94%	2,324,403	240,946	90%
Lincoln / Missouri	70%	706	630	11%	3,720	2,275	39%	236,168	120,393	49%
Mardi Gras Service	80%	421	158	62%	1,511	468	69%	124,612	27,818	78%
Michigan	70%	2,560	1,640	36%	10,198	5,947	42%	607,792	198,330	67%
Blue Water	70%	867	487	44%	2,210	1,829	17%	141,788	57,545	59%
Pere Marquette	85%	160	0	100%	1,338	176	87%	79,779	15,297	81%
Wolverine	70%	1,533	1,153	25%	6,650	3,942	41%	386,225	125,488	68%
Missouri	80%	168	48	71%	1,262	309	76%	67,029	16,768	75%
Pacific Surfliner	85%	8,327	2,641	68%	43,451	9,392	78%	2,443,745	436,794	82%
Pennsylvanian	80%	784	205	74%	3,459	894	74%	269,335	51,812	81%
Piedmont	80%	511	102	80%	4,043	558	86%	344,279	89,127	74%
Vermont	75%	1,232	159	87%	5,425	1,196	78%	390,477	114,253	71%
Long Distance	70%	11,481	5,949	48%	54,067	29,615	45%	3,738,300	1,607,546	57%
Auto Train	70%	819	0	100%	3,514	457	87%	237,921	81,207	66%
California Zephyr	70%	1,079	770	29%	4,138	3,001	27%	295,467	109,441	63%
Cardinal	70%	0	0	-	922	617	33%	72,486	36,207	50%
City Of New Orleans	75%	642	638	1%	2,711	2,054	24%	193,713	60,084	69%
Coast Starlight	70%	619	176	72%	4,956	2,183	56%	349,534	122,720	65%
Crescent	70%	839	28	97%	3,796	516	86%	283,197	86,305	70%
Empire Builder	70%	936	927	1%	3,868	3,560	8%	293,988	147,220	50%
Floridian	60%	1,682	1,106	34%	7,249	5,973	18%	485,003	333,001	31%
Lake Shore Ltd	73%	1,197	539	55%	5,063	1,457	71%	293,300	86,924	70%
Palmetto	70%	435	128	71%	3,890	1,513	61%	279,720	83,935	70%
Silver Meteor	70%	982	734	25%	4,229	2,815	33%	309,451	140,158	55%
Southwest Chief	60%	1,017	527	48%	4,228	2,537	40%	254,482	164,943	35%
Sunset Ltd	70%	202	66	67%	614	478	22%	89,014	33,214	63%
Texas Eagle	70%	1,032	310	70%	4,889	2,454	50%	301,024	122,187	59%
Seasonal Trains	%	0	0	-	0	0	-	39,267	2,463	94%
Winter Park Express	75%	0	0	-	0	0	-	39,267	2,463	94%

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Amtrak Caused Delay Per 10K Train Miles - By Department

26-FOI-00044 00000000404 "UNCLASSIFIED" 8/7/2026

Train Index Dates Through August 04, 2026

Service	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
Amtrak System	585	25,234	424,740	594	1,817,754	32,372,756	562

Department	Target	Month to Date			FY to Date		
		ACD Minutes	Train Miles	ACD per 10K TM	ACD Minutes	Train Miles	ACD per 10K TM
INFRASTRUCTURE UNPLANNED	107	1,320	126,607	104	87,770	9,323,610	94
INFRASTRUCTURE PLANNED	135	1,651	126,607	130	97,706	9,323,610	105
FLEET RELIABILITY	90	3,695	424,740	87	292,008	32,372,756	90
TRAIN OPERATIONS	424	18,568	424,740	437	1,340,270	32,372,756	414

Note: "This report contains preliminary data and is intended to be used for trend analysis. This report should not be used for outside reporting"

Information Management

Initial Terminal Performance By Division

Scheduled Departure Date: 08/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/04/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	56	82.4%	1,208	193	84.0%	92,152	12,749	86.2%
Central Division	86.0%	58	4	93.1%	227	30	86.8%	17,655	1,604	90.9%
East Division	82.0%	176	28	84.1%	650	93	85.7%	48,320	7,515	84.4%
West Division	86.0%	85	24	71.8%	331	70	78.9%	26,177	3,630	86.1%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/04/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	56	82.4%	1,208	193	84.0%	92,152	12,749	86.2%
Central Division	86.0%	58	4	93.1%	227	30	86.8%	17,655	1,604	90.9%
CDL	95.0%	2	0	100.0%	8	2	75.0%	584	27	95.4%
CHI	86.0%	27	3	88.9%	105	18	82.9%	8,155	985	87.9%
CHM	-	-	-	-	-	-	-	13	5	61.5%
DAL	-	-	-	-	-	-	-	1	0	100.0%
DEN	-	-	-	-	-	-	-	61	4	93.4%
DER	-	-	-	-	-	-	-	2	2	0.0%
ELP	-	-	-	-	1	1	0.0%	1	1	0.0%
FTW	92.5%	1	0	100.0%	4	0	100.0%	331	36	89.1%
GBB	-	-	-	-	-	-	-	13	11	15.4%
GRR	95.5%	1	0	100.0%	4	0	100.0%	292	8	97.3%
IND	-	-	-	-	-	-	-	1	0	100.0%
KCY	92.0%	2	0	100.0%	8	0	100.0%	595	44	92.6%
MEM	-	-	-	-	-	-	-	1	1	0.0%
MHL	-	-	-	-	-	-	-	28	11	60.7%
MKE	92.0%	6	0	100.0%	22	1	95.5%	1,802	115	93.6%
MOE	97.5%	2	0	100.0%	8	0	100.0%	613	9	98.5%
MSP	96.5%	1	0	100.0%	4	1	75.0%	301	7	97.7%
NOL	94.5%	4	0	100.0%	18	0	100.0%	1,291	60	95.4%
OKC	97.0%	1	0	100.0%	4	0	100.0%	302	6	98.0%
PNT	88.0%	3	0	100.0%	12	1	91.7%	799	65	91.9%
PTH	93.0%	1	0	100.0%	4	1	75.0%	296	12	95.9%
QCY	91.0%	2	1	50.0%	5	1	80.0%	582	44	92.4%
SAS	90.5%	1	0	100.0%	4	1	75.0%	305	34	88.9%
STL	89.0%	4	0	100.0%	16	3	81.3%	1,191	103	91.4%
TOL	-	-	-	-	-	-	-	4	4	0.0%
TRM	-	-	-	-	-	-	-	34	5	85.3%
WIP	-	-	-	-	-	-	-	57	5	91.2%
East Division	82.0%	176	28	84.1%	650	93	85.7%	48,320	7,515	84.4%
ALB	88.5%	8	1	87.5%	31	2	93.5%	2,281	177	92.2%
ATL	-	-	-	-	-	-	-	36	6	83.3%
BON	87.5%	5	0	100.0%	20	2	90.0%	1,486	160	89.2%
BOS	85.5%	18	1	94.4%	70	3	95.7%	5,233	607	88.4%
BRK	92.5%	5	0	100.0%	20	1	95.0%	1,472	103	93.0%
BTN	82.0%	1	0	100.0%	4	0	100.0%	294	41	86.1%
CLT	91.5%	5	0	100.0%	20	2	90.0%	1,497	152	89.8%
DOV	-	-	-	-	-	-	-	3	2	33.3%
GFD	88.0%	2	0	100.0%	8	0	100.0%	601	57	90.5%
GRO	-	2	0	100.0%	4	0	100.0%	37	10	73.0%
HAR	79.5%	13	4	69.2%	40	8	80.0%	3,404	556	83.7%
HFD	-	2	0	100.0%	4	1	75.0%	195	16	91.8%
JAX	-	-	-	-	-	-	-	4	1	75.0%
LOR	84.0%	1	0	100.0%	4	0	100.0%	304	38	87.5%
MIA	89.5%	2	0	100.0%	8	0	100.0%	608	68	88.8%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date:	08/04/2026
Amtrak or Commuter:	Amtrak

Location	Target	ITP 08/04/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	56	82.4%	1,208	193	84.0%	92,152	12,749	86.2%
East Division	82.0%	176	28	84.1%	650	93	85.7%	48,320	7,515	84.4%
MTR	79.0%	1	0	100.0%	4	1	75.0%	291	53	81.8%
NFK	84.5%	2	0	100.0%	8	2	75.0%	691	125	81.9%
NFL	93.5%	2	0	100.0%	8	0	100.0%	620	29	95.3%
NFS	-	-	-	-	-	-	-	7	6	14.3%
NHV	78.0%	5	0	100.0%	19	2	89.5%	1,573	255	83.8%
NPN	93.0%	2	1	50.0%	8	2	75.0%	581	44	92.4%
NYP	75.5%	50	15	70.0%	178	43	75.8%	12,662	2,824	77.7%
PGH	93.0%	1	0	100.0%	4	1	75.0%	305	23	92.5%
PHL	48.0%	5	3	40.0%	18	10	44.4%	1,568	750	52.2%
PIT	76.0%	-	-	-	1	1	0.0%	16	13	18.8%
POR	-	-	-	-	-	-	-	11	8	27.3%
RGH	95.0%	2	0	100.0%	12	0	100.0%	1,170	49	95.8%
RNK	83.5%	2	0	100.0%	8	0	100.0%	604	87	85.6%
ROC	-	-	-	-	-	-	-	2	2	0.0%
RVM	87.5%	-	-	-	-	-	-	113	13	88.5%
RVR	-	-	-	-	-	-	-	6	4	33.3%
SAB	98.0%	1	0	100.0%	4	0	100.0%	291	5	98.3%
SAO	-	-	-	-	-	-	-	1	1	0.0%
SAR	-	-	-	-	-	-	-	2	2	0.0%
SAV	96.0%	1	0	100.0%	4	0	100.0%	301	10	96.7%
SFA	88.0%	1	0	100.0%	4	0	100.0%	304	41	86.5%
SPG	92.5%	5	0	100.0%	23	0	100.0%	1,830	105	94.3%
STS	-	-	-	-	-	-	-	1	1	0.0%
TWO	73.0%	1	0	100.0%	4	0	100.0%	293	60	79.5%
WAS	84.0%	31	3	90.3%	110	12	89.1%	7,582	979	87.1%
WEM	-	-	-	-	-	-	-	20	12	40.0%
WOB	-	-	-	-	-	-	-	20	20	0.0%
West Division	86.0%	85	24	71.8%	331	70	78.9%	26,177	3,630	86.1%
ARN	92.0%	1	0	100.0%	4	0	100.0%	306	26	91.5%
BFD	79.0%	7	1	85.7%	27	7	74.1%	1,924	400	79.2%
EMY	72.0%	1	1	0.0%	4	1	75.0%	322	95	70.5%
EUG	86.5%	2	0	100.0%	8	0	100.0%	606	56	90.8%
EVR	-	-	-	-	-	-	-	2	2	0.0%
FNO	-	-	-	-	-	-	-	6	3	50.0%
GAC	-	-	-	-	-	-	-	4	3	25.0%
GJT	-	-	-	-	-	-	-	1	0	100.0%
GTA	90.0%	3	1	66.7%	12	4	66.7%	921	147	84.0%
IRV	-	-	-	-	-	-	-	4	2	50.0%
LAX	89.5%	10	0	100.0%	40	5	87.5%	3,039	331	89.1%
MCD	-	-	-	-	-	-	-	15	13	13.3%
OKJ	74.5%	13	7	46.2%	43	18	58.1%	3,304	846	74.4%
PDX	86.0%	2	2	0.0%	13	6	53.8%	1,501	187	87.5%
RNO	-	-	-	-	-	-	-	2	1	50.0%

Information Management

Initial Terminal Performance By Terminal

Scheduled Departure Date: 08/04/2026

Amtrak or Commuter: Amtrak

Location	Target	ITP 08/04/2026			ITP August 2026 To Date			ITP Fiscal Year 2026 To Date		
		Operated	Late	ITP	Operated	Late	ITP	Operated	Late	ITP
System	84.0%	319	56	82.4%	1,208	193	84.0%	92,152	12,749	86.2%
West Division	86.0%	85	24	71.8%	331	70	78.9%	26,177	3,630	86.1%
SAC	88.5%	16	1	93.8%	55	5	90.9%	4,321	467	89.2%
SAN	90.5%	13	4	69.2%	51	5	90.2%	3,692	349	90.5%
SBA	-	-	-	-	-	-	-	2	2	0.0%
SEA	85.0%	4	4	0.0%	23	10	56.5%	2,408	357	85.2%
SJC	89.0%	7	2	71.4%	27	4	85.2%	2,151	213	90.1%
SKN	-	-	-	-	-	-	-	5	4	20.0%
SLC	-	-	-	-	-	-	-	1	1	0.0%
SLO	90.0%	3	0	100.0%	12	2	83.3%	684	67	90.2%
SNC	-	-	-	-	-	-	-	31	13	58.1%
SOL	-	-	-	-	-	-	-	24	2	91.7%
SPK	90.0%	-	-	-	2	1	50.0%	300	27	91.0%
VAC	97.0%	2	0	100.0%	8	0	100.0%	599	14	97.7%
VAN	-	1	1	0.0%	2	2	0.0%	2	2	0.0%

Initial terminal tolerance = 0 minutes.
Report calculates based on scheduled departure date.

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2		1	1	0.0%	130	32	75.4%	2	0	100.0%	126	24	81.0%
3	392	4	1	75.0%	306	60	80.4%	4	2	50.0%	304	138	54.6%
4		4	0	100.0%	305	46	84.9%	4	2	50.0%	305	201	34.1%
5	31	4	0	100.0%	304	50	83.6%	4	4	0.0%	300	92	69.3%
6	76	4	1	75.0%	303	86	71.6%	4	3	25.0%	303	106	65.0%
7	292	4	2	50.0%	295	44	85.1%	3	3	0.0%	286	77	73.1%
8	149	4	4	0.0%	295	133	54.9%	4	4	0.0%	294	179	39.1%
11		4	2	50.0%	306	59	80.7%	4	0	100.0%	300	60	80.0%
14	Cncld	4	2	50.0%	307	51	83.4%	3	3	0.0%	304	95	68.8%
19		4	0	100.0%	305	77	74.8%	4	0	100.0%	302	71	76.5%
20		4	0	100.0%	305	23	92.5%	4	0	100.0%	305	58	81.0%
21		4	1	75.0%	302	26	91.4%	4	1	75.0%	301	83	72.4%
22		4	1	75.0%	303	32	89.4%	4	0	100.0%	301	81	73.1%
23	38	4	0	100.0%	307	6	98.0%	4	2	50.0%	305	87	71.5%
24	18	4	0	100.0%	307	16	94.8%	4	3	25.0%	306	59	80.7%
25		4	0	100.0%	306	3	99.0%	4	1	75.0%	304	84	72.4%
26		4	0	100.0%	306	5	98.4%	4	0	100.0%	304	60	80.3%
40		4	0	100.0%	300	41	86.3%	4	2	50.0%	297	157	47.1%
41	68	4	2	50.0%	299	116	61.2%	4	4	0.0%	297	228	23.2%
42	21	4	1	75.0%	307	25	91.9%	4	1	75.0%	305	53	82.6%
43		4	0	100.0%	306	42	86.3%	4	0	100.0%	305	70	77.0%
48		4	1	75.0%	305	58	81.0%	4	0	100.0%	304	42	86.2%
49		4	3	25.0%	305	78	74.4%	4	0	100.0%	305	62	79.7%
52		4	0	100.0%	304	41	86.5%	4	0	100.0%	303	72	76.2%
53		4	0	100.0%	304	38	87.5%	4	1	75.0%	303	96	68.3%
55		2	0	100.0%	192	7	96.4%	2	0	100.0%	189	38	79.9%
56		2	0	100.0%	193	23	88.1%	2	1	50.0%	189	35	81.5%
58	252	4	0	100.0%	281	16	94.3%	3	3	0.0%	279	76	72.8%
59	66	4	3	25.0%	279	36	87.1%	4	3	25.0%	275	60	78.2%
63	64	4	1	75.0%	308	133	56.8%	4	4	0.0%	302	170	43.7%
64	22	4	0	100.0%	306	68	77.8%	4	3	25.0%	305	112	63.3%
66		4	0	100.0%	305	61	80.0%	4	1	75.0%	301	55	81.7%
67	38	3	0	100.0%	211	13	93.8%	2	1	50.0%	210	37	82.4%
68	18	4	1	75.0%	308	62	79.9%	4	1	75.0%	307	119	61.2%
69	28	4	3	25.0%	295	71	75.9%	4	2	50.0%	290	45	84.5%
71		4	0	100.0%	303	3	99.0%	4	0	100.0%	302	81	73.2%
72	13	4	1	75.0%	299	32	89.3%	4	2	50.0%	298	63	78.9%
73		4	0	100.0%	302	19	93.7%	4	1	75.0%	300	143	52.3%
74	23	4	0	100.0%	300	33	89.0%	4	1	75.0%	298	109	63.4%
75		4	0	100.0%	296	16	94.6%	4	0	100.0%	290	137	52.8%
76		4	0	100.0%	296	29	90.2%	4	2	50.0%	287	119	58.5%
77		4	0	100.0%	298	20	93.3%	4	1	75.0%	296	124	58.1%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
78		4	0	100.0%	302	25	91.7%	4	1	75.0%	301	64	78.7%
79		4	1	75.0%	305	57	81.3%	4	1	75.0%	304	102	66.4%
80		4	1	75.0%	305	34	88.9%	4	1	75.0%	302	64	78.8%
84		2	0	100.0%	183	14	92.3%	2	0	100.0%	181	43	76.2%
85		2	0	100.0%	194	16	91.8%	2	0	100.0%	194	70	63.9%
86		2	0	100.0%	194	15	92.3%	2	1	50.0%	193	116	39.9%
89		4	1	75.0%	303	66	78.2%	4	2	50.0%	301	87	71.1%
90	48	4	0	100.0%	303	10	96.7%	4	1	75.0%	302	52	82.8%
93	40	2	0	100.0%	193	19	90.2%	2	1	50.0%	192	48	75.0%
94		2	0	100.0%	224	55	75.4%	2	0	100.0%	222	83	62.6%
95	39	2	0	100.0%	193	4	97.9%	2	2	0.0%	193	71	63.2%
97		4	3	25.0%	305	201	34.1%	4	2	50.0%	303	102	66.3%
98	35	4	0	100.0%	305	26	91.5%	4	3	25.0%	303	111	63.4%
110		2	0	100.0%	190	102	46.3%	2	0	100.0%	187	19	89.8%
111		2	0	100.0%	184	35	81.0%	2	0	100.0%	182	21	88.5%
112		2	0	100.0%	184	18	90.2%	2	0	100.0%	183	19	89.6%
113		2	2	0.0%	115	27	76.5%	2	0	100.0%	114	14	87.7%
119		2	1	50.0%	181	46	74.6%	2	0	100.0%	179	22	87.7%
125	23	2	0	100.0%	194	11	94.3%	2	1	50.0%	194	75	61.3%
129		2	1	50.0%	193	48	75.1%	2	0	100.0%	193	28	85.5%
130		2	0	100.0%	184	18	90.2%	2	0	100.0%	182	16	91.2%
131		2	1	50.0%	186	54	71.0%	2	0	100.0%	186	35	81.2%
134		2	0	100.0%	194	27	86.1%	2	0	100.0%	193	36	81.3%
136		2	0	100.0%	194	24	87.6%	2	0	100.0%	192	25	87.0%
137		2	0	100.0%	191	35	81.7%	2	0	100.0%	191	58	69.6%
138	78	2	0	100.0%	194	39	79.9%	2	1	50.0%	193	35	81.9%
141	39	2	0	100.0%	193	3	98.4%	2	2	0.0%	192	35	81.8%
148		2	0	100.0%	193	20	89.6%	2	0	100.0%	191	36	81.2%
151		4	2	50.0%	304	97	68.1%	4	0	100.0%	303	95	68.6%
170		2	0	100.0%	189	12	93.7%	2	0	100.0%	188	29	84.6%
171	31	2	0	100.0%	194	11	94.3%	2	1	50.0%	194	76	60.8%
172		2	0	100.0%	193	15	92.2%	2	1	50.0%	191	63	67.0%
173		2	0	100.0%	186	24	87.1%	2	1	50.0%	185	79	57.3%
174		2	0	100.0%	194	20	89.7%	2	1	50.0%	194	49	74.7%
175		2	0	100.0%	194	22	88.7%	2	0	100.0%	194	62	68.0%
176		2	0	100.0%	186	15	91.9%	2	0	100.0%	184	24	87.0%
177		2	0	100.0%	194	27	86.1%	2	0	100.0%	194	46	76.3%
178		2	0	100.0%	194	26	86.6%	2	0	100.0%	192	31	83.9%
179		2	1	50.0%	194	24	87.6%	2	1	50.0%	193	71	63.2%
181		2	2	0.0%	190	61	67.9%	2	1	50.0%	188	16	91.5%
182		2	0	100.0%	184	30	83.7%	2	0	100.0%	182	21	88.5%
183		2	2	0.0%	193	58	69.9%	2	1	50.0%	190	39	79.5%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
184		2	0	100.0%	194	33	83.0%	2	0	100.0%	193	27	86.0%
185		2	0	100.0%	194	37	80.9%	2	0	100.0%	194	14	92.8%
186	22	2	2	0.0%	193	23	88.1%	2	1	50.0%	192	54	71.9%
190		2	1	50.0%	193	70	63.7%	2	1	50.0%	192	44	77.1%
192	79	2	0	100.0%	191	24	87.4%	2	1	50.0%	191	18	90.6%
193		2	0	100.0%	190	78	58.9%	2	0	100.0%	189	88	53.4%
196	Cncld	2	0	100.0%	190	20	89.5%	1	0	100.0%	188	15	92.0%
197	17	2	0	100.0%	194	76	60.8%	2	1	50.0%	194	68	64.9%
198		2	0	100.0%	126	17	86.5%	2	0	100.0%	125	21	83.2%
230		4	0	100.0%	141	4	97.2%	4	0	100.0%	141	7	95.0%
232		4	0	100.0%	307	11	96.4%	4	1	75.0%	307	22	92.8%
233		3	1	66.7%	276	62	77.5%	3	2	33.3%	275	90	67.3%
234		4	0	100.0%	308	22	92.9%	4	0	100.0%	307	25	91.9%
235		4	3	25.0%	232	37	84.1%	4	1	75.0%	231	53	77.1%
236	18	4	0	100.0%	292	10	96.6%	4	2	50.0%	291	41	85.9%
237		4	0	100.0%	305	56	81.6%	4	0	100.0%	303	51	83.2%
238	20	4	1	75.0%	232	21	90.9%	4	1	75.0%	230	19	91.7%
239		4	0	100.0%	306	79	74.2%	4	0	100.0%	305	38	87.5%
240	18	4	0	100.0%	307	21	93.2%	4	2	50.0%	304	62	79.6%
241	25	4	1	75.0%	307	75	75.6%	4	1	75.0%	307	72	76.5%
243		4	1	75.0%	243	66	72.8%	4	1	75.0%	242	34	86.0%
244	19	3	0	100.0%	275	12	95.6%	3	2	33.3%	275	51	81.5%
245		4	0	100.0%	188	33	82.4%	4	2	50.0%	187	24	87.2%
280		4	0	100.0%	308	15	95.1%	4	0	100.0%	307	61	80.1%
281		4	0	100.0%	308	37	88.0%	4	0	100.0%	308	57	81.5%
283		4	2	50.0%	308	76	75.3%	4	1	75.0%	308	62	79.9%
284		4	0	100.0%	308	13	95.8%	4	0	100.0%	305	54	82.3%
290	18	4	0	100.0%	308	50	83.8%	4	2	50.0%	305	116	62.0%
291		4	3	25.0%	307	96	68.7%	4	1	75.0%	305	77	74.8%
300		4	1	75.0%	292	21	92.8%	4	1	75.0%	290	69	76.2%
301		4	0	100.0%	305	10	96.7%	4	1	75.0%	301	56	81.4%
302		4	0	100.0%	287	33	88.5%	4	0	100.0%	283	78	72.4%
305		4	0	100.0%	290	28	90.3%	4	0	100.0%	286	115	59.8%
306		4	1	75.0%	303	17	94.4%	4	0	100.0%	302	82	72.8%
307		4	1	75.0%	296	39	86.8%	4	1	75.0%	293	83	71.7%
311		4	1	75.0%	301	27	91.0%	4	0	100.0%	295	63	78.6%
316	36	4	0	100.0%	297	18	93.9%	4	2	50.0%	292	80	72.6%
318	49	4	0	100.0%	306	31	89.9%	4	2	50.0%	303	146	51.8%
319	58	4	0	100.0%	307	20	93.5%	4	4	0.0%	302	169	44.0%
329		2	0	100.0%	217	9	95.9%	2	0	100.0%	217	15	93.1%
330		3	0	100.0%	261	6	97.7%	3	0	100.0%	261	15	94.3%
331		4	0	100.0%	308	33	89.3%	4	0	100.0%	308	44	85.7%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
332		3	0	100.0%	307	17	94.5%	3	0	100.0%	307	43	86.0%
334		4	0	100.0%	308	10	96.8%	4	0	100.0%	307	40	87.0%
335		4	0	100.0%	308	34	89.0%	4	1	75.0%	306	52	83.0%
336		4	0	100.0%	308	10	96.8%	4	0	100.0%	306	28	90.8%
337		4	0	100.0%	308	18	94.2%	4	1	75.0%	304	37	87.8%
338		4	1	75.0%	308	48	84.4%	4	2	50.0%	306	96	68.6%
339		4	1	75.0%	308	51	83.4%	4	1	75.0%	308	54	82.5%
341		4	0	100.0%	296	44	85.1%	4	0	100.0%	290	41	85.9%
342		4	0	100.0%	308	24	92.2%	4	0	100.0%	306	60	80.4%
350	37	4	0	100.0%	285	18	93.7%	4	4	0.0%	278	155	44.2%
351	45	4	1	75.0%	291	28	90.4%	4	3	25.0%	289	81	72.0%
352	85	4	1	75.0%	275	22	92.0%	4	3	25.0%	269	84	68.8%
353		4	0	100.0%	246	13	94.7%	4	1	75.0%	240	39	83.8%
354	46	4	0	100.0%	289	35	87.9%	4	4	0.0%	282	105	62.8%
355	80	4	0	100.0%	298	31	89.6%	4	3	25.0%	291	102	64.9%
364		4	3	25.0%	297	68	77.1%	4	3	25.0%	291	110	62.2%
365		4	1	75.0%	296	12	95.9%	3	2	33.3%	293	111	62.1%
371		4	0	100.0%	292	8	97.3%	4	0	100.0%	291	29	90.0%
380	Cncld	1	1	0.0%	290	28	90.3%	0	0	0.0%	289	63	78.2%
381	23	4	0	100.0%	306	12	96.1%	4	1	75.0%	305	61	80.0%
382	29	4	0	100.0%	305	27	91.1%	4	3	25.0%	305	103	66.2%
383	31	2	0	100.0%	295	26	91.2%	2	2	0.0%	292	125	57.2%
390	17	4	2	50.0%	290	21	92.8%	4	3	25.0%	289	76	73.7%
391		4	1	75.0%	291	12	95.9%	4	3	25.0%	287	79	72.5%
392		4	0	100.0%	304	10	96.7%	4	0	100.0%	301	90	70.1%
393	17	4	0	100.0%	308	18	94.2%	4	2	50.0%	305	93	69.5%
417		2	0	100.0%	204	44	78.4%	2	0	100.0%	195	22	88.7%
425		2	0	100.0%	206	6	97.1%	2	0	100.0%	206	7	96.6%
448		4	1	75.0%	238	44	81.5%	4	0	100.0%	235	80	66.0%
449		4	0	100.0%	235	32	86.4%	4	0	100.0%	235	42	82.1%
470		2	0	100.0%	217	37	82.9%	2	0	100.0%	211	24	88.6%
471		2	0	100.0%	207	11	94.7%	2	0	100.0%	207	5	97.6%
473		2	0	100.0%	213	15	93.0%	2	0	100.0%	210	10	95.2%
474		2	0	100.0%	211	63	70.1%	2	1	50.0%	196	64	67.3%
475		2	0	100.0%	211	6	97.2%	2	0	100.0%	211	15	92.9%
478		2	1	50.0%	205	33	83.9%	2	0	100.0%	203	27	86.7%
479		2	0	100.0%	212	34	84.0%	2	0	100.0%	210	31	85.2%
486		2	0	100.0%	216	31	85.6%	2	0	100.0%	210	58	72.4%
494		2	0	100.0%	218	41	81.2%	2	0	100.0%	211	57	73.0%
495		2	0	100.0%	201	4	98.0%	2	0	100.0%	199	3	98.5%
503	99	4	2	50.0%	304	29	90.5%	4	2	50.0%	297	89	70.0%
504		4	0	100.0%	308	19	93.8%	4	1	75.0%	306	91	70.3%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
		Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
506	58	4	3	25.0%	303	45	85.1%	3	1	66.7%	296	47	84.1%
507	100	4	2	50.0%	308	38	87.7%	4	3	25.0%	308	103	66.6%
508	39	4	0	100.0%	303	41	86.5%	4	3	25.0%	299	71	76.3%
516	34	4	3	25.0%	299	32	89.3%	4	3	25.0%	298	137	54.0%
517	38	4	0	100.0%	308	8	97.4%	4	2	50.0%	304	129	57.6%
518	No OS	4	2	50.0%	308	39	87.3%	4	4	0.0%	306	211	31.0%
519	18	4	0	100.0%	299	9	97.0%	4	1	75.0%	297	67	77.4%
520		2	1	50.0%	175	26	85.1%	2	0	100.0%	172	9	94.8%
521		2	0	100.0%	213	7	96.7%	2	1	50.0%	213	28	86.9%
522		2	1	50.0%	213	40	81.2%	2	0	100.0%	210	20	90.5%
523		2	1	50.0%	213	8	96.2%	2	0	100.0%	212	22	89.6%
524	18	1	0	100.0%	212	16	92.5%	1	1	0.0%	209	24	88.5%
525		2	0	100.0%	211	16	92.4%	2	0	100.0%	207	14	93.2%
526		2	1	50.0%	187	35	81.3%	2	0	100.0%	184	15	91.8%
527		2	0	100.0%	213	10	95.3%	2	0	100.0%	212	37	82.5%
528		2	0	100.0%	213	17	92.0%	2	0	100.0%	212	30	85.8%
529	19	2	0	100.0%	213	12	94.4%	2	1	50.0%	212	59	72.2%
530		2	0	100.0%	167	16	90.4%	2	0	100.0%	167	32	80.8%
531		2	0	100.0%	187	13	93.0%	2	0	100.0%	187	13	93.0%
532		2	0	100.0%	213	51	76.1%	2	0	100.0%	212	31	85.4%
534		2	0	100.0%	172	25	85.5%	2	0	100.0%	170	16	90.6%
535		2	1	50.0%	200	26	87.0%	2	1	50.0%	195	24	87.7%
536		2	2	0.0%	213	57	73.2%	2	0	100.0%	209	38	81.8%
537		1	0	100.0%	182	22	87.9%	1	0	100.0%	176	20	88.6%
538		2	1	50.0%	213	25	88.3%	2	0	100.0%	212	43	79.7%
539	16	2	0	100.0%	167	24	85.6%	2	1	50.0%	167	72	56.9%
540		2	1	50.0%	212	39	81.6%	2	0	100.0%	204	18	91.2%
541		2	0	100.0%	212	22	89.6%	2	0	100.0%	206	36	82.5%
542	15	2	0	100.0%	212	24	88.7%	2	1	50.0%	209	38	81.8%
543		2	0	100.0%	213	24	88.7%	2	0	100.0%	213	63	70.4%
544	Cncld	2	1	50.0%	211	21	90.0%	1	0	100.0%	207	20	90.3%
545		2	0	100.0%	213	17	92.0%	2	0	100.0%	210	24	88.6%
547	24	2	2	0.0%	213	43	79.8%	2	1	50.0%	213	48	77.5%
548		2	0	100.0%	208	21	89.9%	2	1	50.0%	206	16	92.2%
549	12	2	0	100.0%	208	26	87.5%	2	2	0.0%	200	19	90.5%
550	14	2	0	100.0%	167	18	89.2%	2	2	0.0%	167	38	77.2%
551		2	0	100.0%	209	22	89.5%	2	1	50.0%	199	21	89.4%
562		4	0	100.0%	299	23	92.3%	4	0	100.0%	295	35	88.1%
564	23	4	0	100.0%	300	19	93.7%	4	1	75.0%	292	39	86.6%
566	27	4	1	75.0%	298	26	91.3%	4	2	50.0%	295	47	84.1%
567		4	0	100.0%	185	10	94.6%	4	1	75.0%	183	10	94.5%
572		4	0	100.0%	295	24	91.9%	4	0	100.0%	288	83	71.2%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
573		4	0	100.0%	297	40	86.5%	4	0	100.0%	290	51	82.4%
579	19	4	0	100.0%	185	11	94.1%	4	2	50.0%	180	39	78.3%
580	52	4	0	100.0%	300	16	94.7%	4	2	50.0%	293	30	89.8%
581	20	4	2	50.0%	300	52	82.7%	4	1	75.0%	298	65	78.2%
584	40	4	1	75.0%	184	26	85.9%	4	4	0.0%	179	112	37.4%
587	132	4	1	75.0%	293	17	94.2%	4	1	75.0%	284	54	81.0%
588	30	4	1	75.0%	185	19	89.7%	4	2	50.0%	184	35	81.0%
591	25	4	1	75.0%	297	22	92.6%	4	2	50.0%	291	41	85.9%
593		3	1	66.7%	293	48	83.6%	3	0	100.0%	272	37	86.4%
595		4	0	100.0%	295	53	82.0%	4	0	100.0%	292	60	79.5%
600		2	0	100.0%	221	9	95.9%	2	0	100.0%	219	19	91.3%
601		2	2	0.0%	204	85	58.3%	2	1	50.0%	201	26	87.1%
605		2	2	0.0%	211	132	37.4%	2	0	100.0%	207	22	89.4%
607		2	0	100.0%	220	30	86.4%	2	0	100.0%	217	25	88.5%
609	15	2	0	100.0%	211	23	89.1%	2	1	50.0%	210	20	90.5%
622		2	1	50.0%	122	33	73.0%	2	0	100.0%	120	5	95.8%
626		2	0	100.0%	125	16	87.2%	2	0	100.0%	123	18	85.4%
639		2	0	100.0%	191	38	80.1%	2	0	100.0%	190	19	90.0%
640	13	2	0	100.0%	211	7	96.7%	2	2	0.0%	209	82	60.8%
641		2	1	50.0%	193	39	79.8%	2	0	100.0%	193	26	86.5%
642		2	1	50.0%	209	10	95.2%	2	0	100.0%	208	26	87.5%
643	31	2	0	100.0%	223	44	80.3%	2	1	50.0%	220	37	83.2%
644		2	0	100.0%	215	28	87.0%	2	0	100.0%	213	52	75.6%
645		2	0	100.0%	223	41	81.6%	2	1	50.0%	220	47	78.6%
646	29	2	0	100.0%	212	51	75.9%	2	1	50.0%	210	102	51.4%
647		2	0	100.0%	223	32	85.7%	2	0	100.0%	222	49	77.9%
648		2	0	100.0%	219	56	74.4%	2	0	100.0%	219	34	84.5%
649		2	0	100.0%	224	42	81.3%	2	0	100.0%	221	34	84.6%
650		2	0	100.0%	223	41	81.6%	2	0	100.0%	220	36	83.6%
651		2	0	100.0%	223	16	92.8%	2	0	100.0%	221	42	81.0%
652		2	2	0.0%	224	31	86.2%	2	0	100.0%	220	37	83.2%
653		2	1	50.0%	212	34	84.0%	2	0	100.0%	209	39	81.3%
654		2	1	50.0%	213	41	80.8%	2	1	50.0%	209	19	90.9%
655		2	0	100.0%	221	72	67.4%	2	1	50.0%	219	74	66.2%
656		2	1	50.0%	223	48	78.5%	2	0	100.0%	222	30	86.5%
657		2	0	100.0%	212	27	87.3%	2	0	100.0%	211	29	86.3%
658		2	0	100.0%	223	35	84.3%	2	0	100.0%	221	33	85.1%
680		2	0	100.0%	218	12	94.5%	2	0	100.0%	217	27	87.6%
681		2	0	100.0%	218	17	92.2%	2	1	50.0%	212	87	59.0%
682		2	0	100.0%	217	6	97.2%	2	1	50.0%	217	39	82.0%
683	16	2	0	100.0%	200	17	91.5%	2	1	50.0%	199	68	65.8%
684		2	0	100.0%	199	32	83.9%	2	0	100.0%	199	45	77.4%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
685		2	0	100.0%	214	31	85.5%	2	0	100.0%	211	53	74.9%
686		2	0	100.0%	219	37	83.1%	2	0	100.0%	218	47	78.4%
687		2	0	100.0%	218	34	84.4%	2	0	100.0%	217	36	83.4%
688		2	0	100.0%	217	13	94.0%	2	0	100.0%	216	36	83.3%
689		1	0	100.0%	146	20	86.3%	1	0	100.0%	145	21	85.5%
701		4	0	100.0%	240	25	89.6%	4	0	100.0%	237	25	89.5%
702		4	0	100.0%	307	32	89.6%	4	2	50.0%	304	72	76.3%
703	No OS	4	3	25.0%	308	96	68.8%	4	2	50.0%	306	87	71.6%
704		4	0	100.0%	239	37	84.5%	4	1	75.0%	232	47	79.7%
710		4	0	100.0%	308	77	75.0%	4	2	50.0%	304	83	72.7%
711	20	4	0	100.0%	299	34	88.6%	4	3	25.0%	278	55	80.2%
712	199	4	1	75.0%	305	81	73.4%	4	3	25.0%	296	101	65.9%
713	32	3	0	100.0%	175	16	90.9%	2	1	50.0%	158	68	57.0%
714	115	4	4	0.0%	189	79	58.2%	3	3	0.0%	174	79	54.6%
715		4	1	75.0%	307	62	79.8%	3	2	33.3%	283	143	49.5%
716	16	4	3	25.0%	308	123	60.1%	4	4	0.0%	302	122	59.6%
717		4	1	75.0%	293	69	76.5%	2	1	50.0%	272	87	68.0%
718		4	2	50.0%	308	155	49.7%	4	3	25.0%	306	112	63.4%
719	40	4	2	50.0%	308	105	65.9%	3	3	0.0%	291	87	70.1%
757		4	0	100.0%	93	5	94.6%	4	0	100.0%	92	8	91.3%
761		4	0	100.0%	304	12	96.1%	4	0	100.0%	301	41	86.4%
765		4	0	100.0%	304	25	91.8%	4	1	75.0%	304	43	85.9%
769		4	0	100.0%	304	27	91.1%	4	1	75.0%	298	58	80.5%
770		4	1	75.0%	304	23	92.4%	4	2	50.0%	302	91	69.9%
774		4	0	100.0%	304	16	94.7%	4	0	100.0%	303	69	77.2%
777		4	0	100.0%	189	12	93.7%	4	1	75.0%	188	43	77.1%
782	33	4	3	25.0%	189	85	55.0%	4	2	50.0%	184	27	85.3%
785		4	0	100.0%	304	22	92.8%	4	1	75.0%	304	54	82.2%
786	44	4	1	75.0%	93	20	78.5%	3	1	66.7%	89	48	46.1%
790		4	0	100.0%	304	28	90.8%	4	0	100.0%	301	46	84.7%
794		4	1	75.0%	304	34	88.8%	4	0	100.0%	300	66	78.0%
821	39	4	0	100.0%	302	6	98.0%	4	4	0.0%	302	125	58.6%
822	24	4	0	100.0%	304	16	94.7%	4	4	0.0%	302	146	51.7%
1333		4	1	75.0%	304	33	89.1%	4	1	75.0%	301	100	66.8%
1340		4	1	75.0%	303	7	97.7%	4	0	100.0%	303	51	83.2%
2102		2	1	50.0%	70	14	80.0%	2	0	100.0%	69	6	91.3%
2103	165	2	0	100.0%	134	12	91.0%	2	1	50.0%	133	10	92.5%
2104		2	0	100.0%	160	10	93.8%	2	0	100.0%	158	12	92.4%
2107		2	0	100.0%	191	34	82.2%	2	0	100.0%	188	20	89.4%
2108		2	1	50.0%	191	27	85.9%	2	1	50.0%	185	21	88.6%
2109		2	1	50.0%	84	12	85.7%	2	1	50.0%	82	5	93.9%
2112		2	0	100.0%	31	4	87.1%	2	0	100.0%	29	2	93.1%

Amtrak On Time Performance

Trains Arriving Through: 8/4/2026

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

		Initial Terminal						Endpoint					
		Month to Date			Year to Date			Month to Date			Year to Date		
Train	Late	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score	Opr	Late	Score
2113		2	0	100.0%	70	8	88.6%	2	0	100.0%	70	10	85.7%
2115		2	0	100.0%	70	11	84.3%	2	0	100.0%	69	11	84.1%
2116		2	0	100.0%	31	1	96.8%	2	0	100.0%	31	7	77.4%
2118	40	2	1	50.0%	31	3	90.3%	2	1	50.0%	31	10	67.7%
2119		2	1	50.0%	31	5	83.9%	1	0	100.0%	30	10	66.7%
2120	31	2	1	50.0%	31	10	67.7%	2	2	0.0%	30	15	50.0%
2123		2	0	100.0%	69	8	88.4%	2	0	100.0%	68	15	77.9%
2124		1	0	100.0%	162	34	79.0%	1	0	100.0%	160	22	86.3%
2127		2	0	100.0%	31	8	74.2%	2	0	100.0%	30	7	76.7%
2128		2	0	100.0%	31	3	90.3%	2	1	50.0%	31	3	90.3%
2131		2	1	50.0%	31	7	77.4%	2	0	100.0%	31	3	90.3%
2150		2	0	100.0%	184	22	88.0%	2	1	50.0%	181	74	59.1%
2151		2	0	100.0%	133	6	95.5%	2	0	100.0%	131	37	71.8%
2152		2	0	100.0%	89	6	93.3%	2	0	100.0%	88	30	65.9%
2154	16	2	0	100.0%	92	23	75.0%	2	1	50.0%	88	43	51.1%
2155	55	2	0	100.0%	193	16	91.7%	2	2	0.0%	189	98	48.1%
2158		2	0	100.0%	30	4	86.7%	2	1	50.0%	30	13	56.7%
2159		2	0	100.0%	186	14	92.5%	2	1	50.0%	184	60	67.4%
2160	40	2	0	100.0%	31	2	93.5%	2	2	0.0%	30	20	33.3%
2162	18	2	0	100.0%	192	18	90.6%	2	1	50.0%	186	86	53.8%
2165		2	0	100.0%	28	2	92.9%	2	1	50.0%	28	14	50.0%
2167		2	0	100.0%	179	20	88.8%	2	0	100.0%	179	39	78.2%
2171		2	0	100.0%	120	10	91.7%	2	0	100.0%	116	23	80.2%
2190	29	2	0	100.0%	189	27	85.7%	2	1	50.0%	187	24	87.2%
2193		2	0	100.0%	184	25	86.4%	2	0	100.0%	182	49	73.1%

Amtrak Endpoint OTP Details

Late Trains For

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Region: ALL

Service: ALL

Arriving On: 8/4/2026

Train	Terminal	Late	Max Type		Max Single Delay Item					
			Type	Mins	Type	Mins	Between	Host	Delay Reason	
2103	WAS	165	ENG	163	ENG	34	XPV-BAL	AM	Undesired emergency application, 2142 NG NP, TRIPOD FAULT, RECYCLED TRAIN. OPR 50 MPH.	
2118	NYP	40	ITI	32	ITI	32	WAS-WAS	AM	Service, turn, or wye train, 2155, AM2155 ARRIVED LATE DUE TO TRAINLINE ISSUES	
2120	NYP	31	ENG	23	ENG	23	XHM-XCY	AM	Unrecoverable penalty (PCS), 2135 NG NP, STOPPED AT MP.35 A/C PCB FAULT	
2154	BOS	16	CTI	21	DSR	12	STM-NHV	MN	Per bulletin Milepost, 32.3, 33.6, 30, 2, Milepost, 40.4, 41.7, 30, 4, Milepost, 41.7, 42, 15, 4, Control Point, 248, 30, 2	
2155	WAS	55	ENG	69	ENG	17	PHL-WIL	AM	PTC - On Board Cab Signal or PTC Failure, 2116 NG NP, OPERATING 79 MPH A/C ACSES FAILURE AND SCREENS WENT BLANK	
2160	BOS	40	DSR	26	DSR	16	STM-NHV	MN	Per bulletin Milepost, 33.6, 48.6, 30, 2	
2162	BOS	18	CTI	25	CTI	18	STM-XNH	MN	Follow mnrr, Control Point, 234/273	
2190	BOS	29	DSR	33	DSR	23	STM-NHV	MN	Per dispatcher (radio/phone) Control Point, 257, 15, 2	
67	NPN	38	OTH	20	DCS	11	WBG-NPN	CS	Issue with automatic road crossing protection Stop and flag the railroad crossing at grade, Milepost, 25.3, 25.3	
93	NFK	40	DMW	35	WTR	27	RVR-PTB	CS	Flash flood warning Milepost w/Letters, cfp 1.0, a 22.9	
95	NFK	39	FTI	42	FTI	24	FBG-RVR	CS	Follow IO31, Other, FBG	
125	NPN	23	WTR	29	WTR	25	RVM-WBG	CS	Flash flood warning Milepost w/Letters, ca 85.4, ca 47.9	
138	NYP	78	MTI	61	MTI	61	XPV-WIL	AM	Disabled train ahead, Milepost, 34.3, .., received transfer from disabled 196	
141	WAS	39	DCS	35	DCS	34	NHV-BRP	MN	Signal issues between 266 and 257 Control Point, 266	
171	RNK	31	CTI	34	CTI	12	BWI-NCR	AM	Follow, MARC, 439, Milepost, 112.4, 127	
186	PHL	22	WTR	24	WTR	20	WBG-RVM	CS	Flash flood warning Milepost, 47.9, 61.8, Milepost, 70.9, 83.9	
192	NYP	79	MTI	76	MTI	76	XPV-WIL	AM	Disabled train ahead, Milepost, 34.3, .., received transfer from disabled 196	
196	NYP	Trn Cancelled	ENG	228	ENG	228	XPV-WIL	AM	HEP, 617 EX ES, LOSS OF POWER. CREW REPORTED NO HEP ON E/617.	
197	WAS	17	CTI	17	CTI	13	BAL-XNY	AM	Follow, MARC, 455, Milepost, 112.4, 134.6	

Amtrak Endpoint OTP Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
609	HAR	15	DCS	23	DCS	23	PHL-PAO	AM	T.O.L, Control Point, ., TOL 3 trk Bryn Mawr - Paoli	
640	NYP	13	CTI	19	CTI	11	CWH-TRE	AM	Follow, SE, SE783, Other, CWH-XMO	
643	HAR	31	MTI	15	MTI	15	PHL-PAO	AM	Disabled train ahead, Control Point, PHL TO ZOO, FOLLOW 646 WHICH HAD TO WYE OUTBOUND	
646	NYP	29	ENG	29	ENG	29	PHL-XHM	AM	PTC - On Board Cab Signal or PTC Failure, 9638 CB CC, WYE OUTBOUND A/C NO ACSES	
683	BRK	16	PTI	12	PTI	9	SAO-ORB	CS	Meet 686, Control Point, Ocean park	
63	TWO	64	PTI	19	PTI	15	XSV-ROC	CS	Meet Held at cp349 due to single tracking waiting for 64 to pass, 64, Control Point, CP349	
64	NYP	22	CTI	28	CTI	20	POU-CRT	MN	Follow MN, 890, Milepost, 72, 34	
68	NYP	18	WTR	38	WTR	38	SLQ-RSP	CN	Heat order Milepost, 40, 0	
69	MTR	28	WTR	44	WTR	44	XLQ-SLQ	CN	Heat order Milepost, 0, 43	
236	NYP	18	DCS	23	DCS	15	ALB-HUD	AM	Restrictive signal(s) from unknown cause Stop and proceed, Stop, Milepost, 124, 118	
238	NYP	20	PTI	18	PTI	18	ALB-HUD	AM	Wait for station track Single tracking 124-114 had to wait for 281 to depart HUD and pass us at cp 124, 281, Control Point, 124	
240	NYP	18	CTI	18	CTI	18	POU-CRT	MN	Meet man, ?, Control Point, 46	
241	ALB	25	CTI	19	CTI	19	CRT-POU	MN	Follow metro north, 869, Milepost, 34, 72	
244	NYP	19	CTI	16	PTI	13	ALB-HUD	AM	Meet Single tracking 124-114. Held at 124 for 291, amt291, Control Point, cp124	
290	NYP	18	CTI	18	CTI	16	POU-CRT	MN	Follow metro, 870, Milepost, 62, 39	
42	NYP	21	OTH	12	CTC	6	PHL-PHL	AM	PTC - Stop Bypass Permission Required, Control Point, ., E/602	
72	GRO	13	FTI	11	FTI	11	CLT-KAN	NS	Follow NS5135, Other, Shamrock to Kannapolis	
74	RGH	23	PTI	30	PTI	15	CLT-KAN	NS	Meet #Amt75, Control Point, Adams	
90	NYP	48	MTI	42	MTI	42	XPV-WIL	AM	Disabled train ahead, Milepost, 34.3, ., 196 disabled on 2 trk at Churchman's Crossing	
98	NYP	35	PTI	92	PTI	62	WTH-XP8	CS	Meet po-41, Control Point, Auburndale sdg	
41	MIA	68	FTI	144	CAR	31	WAS-WAS	AM	Heat / AC, 62019 VX VS, HOT	

Amtrak Endpoint OTP Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/4/2026

			Max Type		Max Single Delay Item					
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason	
23	NOL	38	FTI	28	FTI	28	BAS-XNO	CS	Follow Run around at Michoud, Milepost w/Letters, Claiborne, Paris Rd, 521-02	
24	MOE	18	FTI	57	FTI	22	PAG-MOE	CS	Meet unknown, Control Point, 699.9	
5	EMY	31	WTR	95	DCS	29	XMS-RNO	UP	Signal suspension Milepost, 283.5, 275.3	
6	CHI	76	WTR	128	WTR	46	XMS-WNN	UP	Heat order Milepost, 292.0, 421.26	
524	SAC	18	CCR	18	CCR	18	OKJ-OKJ	UP	PTC - On Board Cab Signal or PTC Failure C8301	
529	SJC	19	PTI	19	PTI	19	FMT-GAC	UP	Meet amtk530, Control Point, CO035	
539	SJC	16	PTI	19	PTI	15	GAC-SCC	UP	Meet Shuffle at expressway, 538, Control Point, CO044	
542	SAC	15	PTI	18	PTI	10	OKJ-EMY	UP	Wait for station track AMT5, AMT545, Control Point, W. EMERYVILLE	
544	SAC	Trn Cancelled								
547	SJC	24	PTI	17	PTI	17	HAY-FMT	UP	Meet Amtk 550, Other, NI021	
549	OKJ	12	PTI	11	DCS	8	BKY-EMY	UP	Issue with automatic road crossing protection XG at 2 crossings, Milepost, 4.9, 4.89	
550	SAC	14	PTI	8	DCS	7	EMY-BKY	UP	Issue with automatic road crossing protection Milepost, 4.6, 4.9	
503	EUG		WTR	37	WTR	18	ALY-EUG	UP	Heat order Level 2 heat restriction in effect on the entire Brooklyn Subdivision, timetable speed reduced to 50 MPH., Other, Brooklyn Subdivision	
506	SEA		CON	63	CON	63	VAN-VAN	BN	Hold for bus with passengers from train Holding for passengers on 7 buses from train 14	
507	EUG		DSR	13	DSR	6	PDX-ORC	UP	Per bulletin Milepost, 768.73, 768.63, 45, 1, Milepost, 768.4, 768.28, 25, 1, Milepost, 768.12, 767.92, 30, 1, Milepost, 766.60, 766.1, 40, 2, Milepost, 765.25, 764.94, 40, 2, Milepost, 763.9, 763.7, 25, 1	
508	PDX	39	WTR	34	WTR	15	EUG-ALY	UP	Heat order Level 2 heat restriction in effect for the entire Brooklyn Subdivision, timetable speed reduced to 50 MPH., Other, Brooklyn Subdivision	
516	VAC	34	ENG	33	ENG	33	SEA-SEA	BN	HEP Faults on WDTX 1408 due to issues with cab car 90253 and extra engine WDTX 1400., WDTX 1408	

Amtrak Endpoint OTP Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/4/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
517	VAN	38	DCS	42	DCS	33	OLW-CTL	BN	Power switch failure Took switch and swing nose frog into hand due to switches not locking properly, Control Point, Plumb
518	VAC	No OS Rpt	CON	87	CON	87	SEA-SEA	BN	Hold for thruway bus Hold for busses from PDX due to service disruption south of SEA
519	SEA	18	FTI	35	FTI	29	X1J-XF2	BN	Meet CP 7596, Control Point, Piper
58	CHI	252	SYS	133	SYS	128	MKS-MEM	CC	Re-crew / job briefing Engineer went dead after lining south Florida street. Waited on relief engineer and a pilot to coordinate the engineer through the yard towards the y&mv/CN jct
59	NOL	66	DSR	68	ENG	26	CHI-CHI	AM	Set out defective locomotive Engine 135 used on another train, replaced 164, 135
14	SEA	Trn Cancelled	PTI	65	PTI	36	SBA-SLO	UP	Meet Honda siding is still being used for long term freight car storage and Surf is out of service., 786, Siding, sudden
7	SEA	292	FTI	199	TRS	68	WIN-RDW	CP	Near-miss Near miss with trespasser @ mp 358. Engineer thought he had struck the trespasser. Conductor and AC walked back. Found the individual stumbling in the gauge. Assisted law enforcement with locating individual, having him arrested removed from right of way., Milepost, 358.0, 358.4
8	CHI	146	FTI	178	FTI	40	SPL-SCD	BN	Follow Freight, train air hose problem, BNSF 7520, Milepost, 119, 119
821	FTW	39	DBS	38	DBS	38	GLE-FTW	BN	Debris blocking track (no debris strike) Large concrete beam. Industrial Blvd, Milepost, 353.1, 353.1
822	OKC	24	DSR	31	DSR	24	FTW-GLE	BN	Per bulletin Milepost, 350, 350.4, 30, m1, Milepost, 350.3, 350.4, 30, crossover, Milepost, 353.7, 354.1, 30, m2, Milepost, 368.6, 361.1, 60, m2, Milepost, 364.7, 365.1, 45, m1, Milepost, 366.3, 367.8, 15, m2, Milepost, 368.6, 369.1, 15, m, Milepost, 371.4, 371.5, 50, m, Milepost, 374, 374.1, 60, m,
350	PNT	37	PTI	49	PTI	26	XB0-XA5	MI	Meet Amtrak 353, Control Point, CP96
351	CHI	45	DSR	37	DSR	27	PNT-TRM	CC	Per bulletin Milepost, 25.3, 20.5, 30, 1, Milepost, 20.5, 16.58, 10, 1
352	PNT	85	DSR	52	PTI	33	JXN-ARB	MI	Meet am355, Control Point, 52
354	PNT	46	DSR	40	DSR	24	TRM-PNT	CC	Per bulletin Milepost, 17.4, 20.5, 10, 1, Milepost, 20.6, 25.3, 30, 1

Amtrak Endpoint OTP Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/4/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
355	CHI	80	RTE	50	RTE	50	PNT-TRM	CC	Dispatcher hold Control Point, MAL
564	SAN	23	CTI	18	CTI	16	SNA-IRV	SC	Cross Traffic Metrolink, Other, sna-irv
566	SAN	27	CTI	24	CTI	18	XRJ-FUL	BN	Disabled Metrolink train causing severe train congestion Location of broken down train unknown, METROLINK, UNK, Control Point, SANTA FE SPRINGS
579	LAX	19	CTI	16	CTI	12	SOL-OSD	SN	Meet COASTER, 638, Control Point, SWAMI
580	SAN	52	TRS	32	TRS	30	SOL-OLT	SN	Trespasser strike Control Point, cudahy
581	LAX	20	CTI	12	CTI	6	SOL-OSD	SN	Meet coaster, Control Point, swami
584	SAN	40	PTI	20	PTI	13	XRJ-FUL	BN	Wait for station track Amtk 4, Other, Station FUL
587	LAX	132	POL	119	POL	119	SAN-SAN	SN	RR blocked by trespasser or vehicle strike by another train
588	SAN	30	PTI	34	PTI	13	SNC-SNP	SC	Meet 591, Control Point, Serra
591	LAX	25	PTI	20	CTI	11	SAN-OLT	SN	Meet nctc, 646, Control Point, ash
782	SAN	33	PTI	29	PTI	15	SNC-SNP	SC	Meet A785, Control Point, Serra
786	SAN	44	PTI	58	PTI	20	GUA-LPS	UP	Meet 765, Siding, Tangier
703	SAC	No OS Rpt	ITI	153	ITI	153	BFD-BFD	BN	Service, turn, or wye train 712
711	OKJ	20	PTI	17	PTI	8	XPR-MTZ	UP	Wait for station track AMTK 6, Control Point, Ferry
712	BFD	199	TCC	120	TCC	120	EMY-EMY	UP	Replaced hand break then replaced wiper motor did not fix problem. Then had to wye one locomotive C8303
713	OKJ	32	DCS	23	DCS	10	RIC-EMY	UP	Issue with automatic road crossing protection Procedure XG., Milepost, 4.9, 4.6
714	BFD	115	TEN	112	TEN	112	OKJ-OKJ	UP	712 WIPER BLADE BROKE CAUSING MULTIPLE TRAIN SWITCHES IN YARD. C2009
716	BFD	16	PTI	20	TEN	10	OKJ-OKJ	UP	Late leaving the yard due to tasi inspecting locomotives 2013, 2014 C2004
719	OKJ	40	DCS	18	FTI	8	MOD-SKN	BN	Meet bnsf?, Control Point, escalon
3	LAX	392	FTI	425	FTI	143	FLG-KNG	BN	Follow BNSF, Other, flagstaff
380	CHI	Trn Cancelled							
381	QCY	23	DSR	12	DMW	11	GBB-MAC	BN	Held for or routed around MW work or equipment Siding, Avon

Amtrak Endpoint OTP Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For

Region: ALL

Service: ALL

Arriving On: 8/4/2026

			Max Type		Max Single Delay Item				
Train	Terminal	Late	Type	Mins	Type	Mins	Between	Host	Delay Reason
382	CHI	29	RTE	12	CTI	9	LAG-XUA	BN	Follow Mwtra, Milepost, 13.7, 1.0
383	QCY	31	FTI	38	FTI	26	MAC-QCY	BN	Meet Siding, colechester, bnsf 7905
390	CHI	17	DSR	17	PTI	12	CHM-RTL	CC	Meet Amtk391, Control Point, Leverett
393	CDL	17	PTI	20	PTI	20	CHM-MAT	CC	Meet 392, Siding, Tolono
316	STL	36	FTI	23	FTI	14	WAR-SED	UP	Meet UP 5297, Siding, Dresden
318	CHI	49	DSR	48	DCS	15	XW1-ALN	UP	Power switch failure SWITCH OUT OF CORRESPONDENCE HAD TO TAKE OFF POWER AND HAND LINE MT1-MT RESTRICTED SPEED, Control Point, CPX262
319	KCY	58	FTI	38	FTI	18	IDP-XRC	UP	Follow unk, Milepost w/Letters, idp ZEV, xrc

Amtrak Initial Terminal Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/4/2026

Terminal	Train	Date	Late	Delay	Cause
ALB	238	08/04	10	10	Door latch on engine broken and would not keep door shut. Mechanical fixed the door latch 708
BOS	179	08/04	7	7	Water, commissary, toilet/trash dumping, Commissary late loading cafe car BOS
HAR	622	08/04	1	1	Passenger and/or baggage
HAR	642	08/04	1	1	High passenger count
HAR	652	08/04	1	1	PTC - Stop Bypass Permission Required, Control Point, ., E/651
HAR	656	08/04	1	1	Passenger and/or baggage
NPN	186	08/04	6	6	Hold for thruway bus NPN station
NYP	49	08/04	107	47	Water, commissary, toilet/trash dumping, LATE F/SSYD A/C LATE CATERING
NYP	49	08/04	107	60	Electrical failure, 68007 VY VF, LATE RELEASE F/SSYD A/C DOOR ISSUES
NYP	63	08/04	4	4	Meet, AM230, Other, NYP, HELD F/INBOUND AM230
NYP	69	08/04	4	4	Meet, AM232, Other, NYP, HELD F/INBOUND AM232
NYP	97	08/04	81	81	Planned set out / pick out of locomotives, cars or section of train, LATE F/SSYD A/C NECESSARY TO WAIT FOR BAGGAGE CAR AND DINER CAR
NYP	113	08/04	3	3	Passenger and/or baggage, LOADING
NYP	129	08/04	12	12	Per MW foreman, Other, MNRR, 30, 2, CONGESTION ON LOOPS A/C DELAYED AM173 RTD AHD DUE TO SPEED RESTRICTIONS ON METRO NORTH
NYP	181	08/04	6	6	Signal suspension, Other, NYP-NYP, LATE FROM SSYD A/C C&S 39 31293436 Signals Q Tower
NYP	183	08/04	3	3	Meet, NJT, NJ3312, Other, NYP, NJ3312 XING AHD
NYP	235	08/04	4	4	Service, turn, or wye train, 238, LATE TURN OFF AM238
NYP	241	08/04	7	7	Door, 82695 AX AS, MECHANICAL ISSUES WITH FIRST CAR
NYP	283	08/04	3	3	Passenger and/or baggage, LOADING
NYP	291	08/04	9	9	Service, turn, or wye train, 240, LATE TURN OFF AM240
NYP	653	08/04	2	2	Passenger and/or baggage, BOARDING
NYP	2109	08/04	5	5	Delay due to mechanical problems on a Commuter train, HELD A/C NJ6613 DISABLED IN NORTH TUBE
NYP	2131	08/04	10	10	Service, turn, or wye train, 2118, LATE TURN OFF AM2118
PHL	151	08/04	1	1	Passenger and/or baggage
PHL	601	08/04	2	2	Passenger and/or baggage
PHL	605	08/04	1	1	Passenger and/or baggage
WAS	2102	08/04	4	4	Electrical failure, 3374 NG ND, NO WATER IN CAR CAFE REPORTED LATE

Amtrak Initial Terminal Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/4/2026

Terminal	Train	Date	Late	Delay	Cause
WAS	2108	08/04	21	21	Disabled train ahead, Other, X, DUE TO 2103 EQUIPMENT BEING SHOPPED NEC'Y TO BUILD, MAKE UP ENTIRE ORDER FROM IVY CITY AND THEN DELIVER
WAS	2118	08/04	32	32	Service, turn, or wye train, 2155, AM2155 ARRIVED LATE DUE TO TRAINLINE ISSUES
CHI	21	08/04	15	15	Air / Brake / Wheel 32015, BRAKE INDICATOR DEFECT
CHI	48	08/04	41	41	Other electrical failure Headlight, 107
CHI	59	08/04	67	67	Service, turn, or wye train 58, Bad order diner
QCY	380	08/04	(Trn Cxld)		Engine Issue
BFD	703	08/04	153	153	Service, turn, or wye train 712
EMY	6	08/04	83	83	Loading problem 40
GTA	782	08/04	7	7	Meet AMTK 14, Control Point, ELWOOD
OKJ	522	08/04	4	4	Changed headlight in cab car. C8311, Blue flags were dropped late in yard, at 604am for changing out a headlight on cab car. Late arrival to jack London. Caused late departure from jack London
OKJ	526	08/04	2	2	Meet 11, Control Point, North Jack London
OKJ	536	08/04	8	8	Follow Held at Oakland maintenance facility waiting for train 541 to arrive, Amtk541west, Control Point, NI005
OKJ	540	08/04	1	1	Meet 543, Control Point, ni007
OKJ	712	08/04	(Trn Cxld)		Third Party Cab Car Failure
OKJ	714	08/04	112	112	712 WIPER BLADE BROKE CAUSING MULTIPLE TRAIN SWITCHES IN YARD. C2009
OKJ	716	08/04	15	10	Late leaving the yard due to tasi inspecting locomotives 2013, 2014 C2004
OKJ	716	08/04	15	5	Restrictive signal(s) from unknown cause Red, Control Point, magnolia
PDX	503	08/04	67		
PDX	507	08/04	96		
SAC	547	08/04	1		
SAN	581	08/04	2	2	Door C6852, Could not get door circuit. Tried for 4 minutes to fix the issue. Door 3. I called CNOC to get permission to go in to override since the door was closed
SAN	587	08/04	119	119	RR blocked by trespasser or vehicle strike by another train
SAN	591	08/04	11	11	Service, turn, or wye train 580, Late from from inbound 580
SAN	593	08/04	2	2	Per dispatcher (radio/phone) No signal- account dispatcher confirming form X restriction., Control Point, ash, 0, 2
SEA	8	08/04	245	245	Service, turn, or wye train 7

Amtrak Initial Terminal Details

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Late Trains For:

Region: ALL

Division: ALL

Data Through: 8/4/2026

Terminal	Train	Date	Late	Delay	Cause
SEA	11	08/04	12	12	High passenger count
SEA	516	08/04	33	33	HEP Faults on WDTX 1408 due to issues with cab car 90253 and extra engine WDTX 1400., WDTX 1408
SEA	518	08/04	90	87	Hold for thruway bus Hold for busses from PDX due to service disruption south of SEA
SJC	538	08/04	6	6	HEP Shut down 1345 per LSA couldn't get it going moved to take 529 EQP TRK 2 swapped LSAs, JPBX920
SJC	544	08/04	(Trn Cxld)		Third Party Engine Failure
VAN	506	08/04	63	63	Hold for bus with passengers from train Holding for passengers on 7 buses from train 14

Eastern Region

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Commuter Services

Service Type	OTP Goal	OTP Day	OTP MTD	OTP Prior Month	Trains Operated	Trains Late
MBTA	95.0	98.3	98.9	98.3	342	6
CDOT	95.0	100	91.7	85.6	20	0
MARC	95.0	No Data	No Data	No Data	No Data	No Data
SEPTA	95.0	No Data	No Data	No Data	No Data	No Data
NJT-NED	95.0	92.5	94.4	88.4	348	26
NJT-SED	95.0	No Data	No Data	No Data	No Data	No Data

Operating Highlights

Train 89(04) Charleston, SC - Passenger Related

05AUG26: Train 89(04) was delayed holding at Charleston, SC station/MP387.4 on the CSX Charleston subdivision due a CSX freight train departing the yard. Train 89(04) departed Charleston SC station at 1207AM CT after the freight cleared the route.

Train	Delay	Comment
89 (04)	32"	

Train 52(04) South of Florence, SC - Freight Train Interference

05AUG26: Train 52(04) was delayed beginning at MP394.7, 102.5 miles south of Florence SC Station on the CSX Charleston subdivision following CSX freight 491 train.

Train	Delay	Comment
52 (04)	30"	

Train 98(04) South of Kingstree, SC - Freight Train Interference

05AUG26: Train 98(04) was delayed beginning at MP38.4, 55.8 miles south of Kingstree SC on the CSX Charleston subdivision following CSX freight train 410. Train 98(04) was able to get around the freight after departing Kingstree station and resumed operating at track speed.

Train	Delay	Comment
98 (04)	45"	

Train 67(04) New Haven, CT - Servicing

04AUG26: Train 66(04) was delayed at New Haven CT station/MP72.3 on the MNRR New Haven line due to a planned set out of engine 100 in New Haven. After the engine was set out train 66(04) was further delayed because the pantographs on engine 646 wouldn't raise. Crew was able to get the pantographs raised after troubleshooting and departed New Haven station at 1008PM ET.

Train	Delay	Comment
67 (04)	49"	

Train 196(04) South of Wilmington, DE - Engine Failure

04AUG26: Train 196(04) with engine 609 and 617 and 430 customers was delayed beginning at MP 34.3, 9.0 miles south of Wilmington DE, on the Amtrak PHL Line due to HEP and power loss on lead engine 617. Crew attempted to restart engine 617 but the battery charge fault persisted. Crew worked with CNOC mechanical and were able to switch HEP to running off trail engine 609. Passengers from 196(04) were transferred to trains 138(04) and 192(04). Rescue diesel engine came out of Wilmington station and were added to train 196(04)'s consist. Train 196(04) was towed into Wilmington station by the rescue engine and arrived at 1127AM ET and the trail engine routed around to be added to the lead. Train 196(04) was back on the move north towards New York Penn Station at 1258AM ET. Train 196(04) deadhead equipment arrive New York Penn Station 255AM ET.

Train	Delay	Comment
138(04)	1'01"	
90(04)	42"	
192(04)	1'16"	
196(04)	3'48"	
196(04)	XX	Term WIL
2128(04)	05"	
55(04)	08"	
137(04)	03"	
2171(04)	09"	
2131(04)	06"	
175(04)	06"	

Train 69(04) Rouses Point, NY - Weather

04AUG26: Train 69(04) was delayed upon departing Rouses Point, NY station/MP0.0 on the CN Rouses Point subdivision operating through heat restrictions. Train 69(04) operated at reduced speed until MP43 at which point the train was able to resume operating at track speed.

Train	Delay	Comment
69(04)	44"	

Train 49(04) New York, NY - Servicing

04AUG26: Train 49(04) was delayed departing New York due to C/68007 being shopped and replaced with C/68011 and late servicing by catering.

Train	Delay	Comment
49(04)	1'47"	

Train 68(04) South of St-Lambert, QC - Heat Orders/Weather

04AUG26: Train 68(04) with E/112 and 5 cars was delayed on the CN Rouses Point subdivision due to heat orders from MP 40.0 to MP 0.0.

Train	Delay	Comment
68(04)	38"	

Train 97(04) New York, NY - Servicing

04AUG26: Train 97(04) was delayed departing New York due to needing a baggage car and diner off inbound train 98(03) that arrived at 1125A-ET 35 minutes late.

Train	Delay	Comment
97(04)	1'21"	

Train 2155(04) West of Newark, NJ - Engine Failure

04AUG26: Next Gen train 2155(04) with PC/2116 was delayed at Newark due to having PTC issues and ACSES issues on PC/2116. The crew was able to clear but it occurred again. Upon arrival into Philadelphia it occurred again but this time the screen went blank. They departed but were restricted to 79MPH and this occurred at Wilmington and Baltimore again. They also had door issues at Baltimore throughout the entire consist that the crew was able to clear.

This also cause train 2118(04) to be delayed due to turning off late 2155(04).

Train	Delay	Comment
2155(04)	16"	NWK
2155(04)	17"	PHL
2155(04)	08"	WIL
2155(04)	14"	BAL
2118(04)	32"	LATE TURN OFF 2155(04)

CSX Heat Orders - Weather

04AUG26: Multiple trains were affected by today's CSX heat orders that were in place from 1300-1900 on the following subdivisions Jacksonville Terminal, Nahunta, Savannah.

Train	Delay	Comment
98(04)	25"	

Train 41(03) East of Connellsville, PA - Engine Failure

04AUG26: Train 41(03) with E/15, E/316 and 11 cars was delayed on the CSX Keystone BF subdivision at MP 200.1 due to E/316 shutting down. The train was able to maintain HEP from E/15. The crew was trouble shooting with CNOC Mechanical. They had determined that E/316 was having problems communicating to E/15. They pulled the M/U Cables between the two engines but it did not correct the issue. Amtrak Road Foreman was enroute. A request was made to CSX for a freight engine due to the location of the train and not able to flat switch at the current location.

As 1225P-ET, Engineer was able to get a good brake test and PTC activated they were going to try and pull again. They were successful and back on the move as of 1232P-ET.

Train 41(03) was further delayed waiting on recrew to reach the train at Point of Rocks they held at MP 68.6 on the CSX Metropolitan BA subdivision.

Train	Delay	Comment
41(03)	2'32"	
41(03)	55"	recrew

Train 41(03) East of Pittsburgh, PA - Freight Train Interference

04AUG26: Train 41(03) with E/15, E/316 and 11 cars was delayed on the CSX Pittsburgh PLY due to following CSX I116 from MP 11.3 to MP 270.4.

Train	Delay	Comment
41(03)	44"	

Train 2103(04) West of Metropark, NJ - Engine Failure

04AUG26: Next Gen 2103(04) at 1:00:11h PC/0142 DG/2115 reported that they had a tri pod failure and would operate at 50MPH into Philadelphia. Upon arrival into Philadelphia they were met by High Speed mechanical and a rider that rode the head end into Washington. They were able to clear the fault prior to departing Philadelphia and able to operate normal speed to Washington. As of 850A-ET, Engineer reported the tri pod failure happened again and they will now operate at 50MPH to Washington.

Train	Delay	Comment
2103(04)	33"	
2108(04)	21"	
2103(04)	2'10"	PHL

MNRR New Haven Line - Code Green - Signal

04AUG26: At 640A-ET, Code Green is in effect on the MNRR New Haven main line from CP 257 to CP 266 Code Lines A and B down on all tracks at CP 261 and maintainers were unable to local control. The Director of Signals advised a short on the B12 bus circuit was and removed. Maintainers remain on scene investigating the cause of incident. AT 708A-ET, The code green was cancelled.

Train	Delay	Comment
141(04)	34"	
66(03)	14"	
2190(04)	26"	

Maintenance of Way Highlights

Piedmont and Carolinian NS Trackwork - Scheduled M/W Work

03AUG26: The NS / NC Line trackwork between MP NC 0.0 and MP NC 34.0 for Rail Train, Plate Truck and Live Wire Aviation Helicopter Cutting occurring between 930A-ET and 330P-ET on Monday, August 3 to Thursday, August 6 and Monday, August 24 to Thursday, August 27.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Piedmont and Carolinian Services will be adjusted as follows:

EASTBOUND

- Train 72 (3Aug-6Aug, 24Aug-27Aug), which normally operates between CLT and RGH, will terminate at GRO.
- Train 74 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between CLT and GRO, 50-minutes Later at BNC, and 55-minutes Later between DNC and RGH.
- Train 76 (3Aug-6Aug, 24Aug-27Aug) will arrive at DNC 17-minutes Later and operate 22-minutes Later between CYN and RGH.
- Train 78 (3Aug-6Aug, 24Aug-27Aug) will operate 30-minutes Later between CLT and GRO, 35-minutes Later at BNC, and 45-minutes Later between DNC and RGH.
- Train 80 (3Aug-6Aug, 24Aug-27Aug) will operate 10-minutes Earlier between CLT and BNC and resume normal schedule at DNC.

WESTBOUND

- Train 71 (3Aug-6Aug, 24Aug-27Aug) will have a BNC stop added and will operate 14-minutes Later between GRO and CLT.
- Train 73 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, and will operate 70-minutes Later between GRO and CLT.
- Train 75 (3Aug-6Aug, 24Aug-27Aug), which normally operates between RGH and CLT, will originate at GRO, will operate 10-minutes Later GRO- CLT.
- Train 77 (3Aug-6Aug, 24Aug-27Aug) will operate 40-minutes Later between RGH and DNC, 51-minutes Later at BNC, and 61-minutes Later between GRO and CLT.
- Train 79 (3Aug-6Aug, 24Aug-27Aug) will operate 5-minutes Later between DNC and GRO and 15-minutes Later between GRO and CLT.

ALTERNATE TRANSPORTATION:

- Bus 3172 will provide alternate transportation between GRO and RGH, making all stops except BNC.
- Buses 3173 and 3175 will provide alternate transportation between RGH and GRO, making all stops except BNC.

WBS#: B.TR.100150.6916

MNRR Hudson Line North of Croton-Harmon, NY - Scheduled M/W Work 6/15 - 8/5

15JUN26-05AUG26: Trains were delayed Monday through Friday between June 15 and August 05 for a tie renewal project on the Metro North Hudson line with MOW work taking place on track 2 between CP 39 and CP 46 and single tracking on track 1.

Train	Delay	Comment
-------	-------	---------

236(15)	30"	
69(15)	43"	
233(15)	12"	NYP - late turn of equip 236(15)
240(15)	20"	
233(15)	10"	26-FOI-00644 00000008494 "UNCLASSIFIED" 8/7/2026
283(15)	37"	
69(16)	37"	
236(16)	33"	
233(16)	04"	NYP - late turn of equip 236(16)
284(16)	36"	
290(16)	44"	
291(17)	25"	
291(17)	14"	Initial Terminal
234(17)	36"	
281(17)	21"	Initial Terminal
63(17)	59"	
69(17)	41"	
236(17)	26"	
240(17)	18"	
64(17)	30"	
284(23)	0'46"	
283(23)	0'30"	
291(23)	0'40"	
290(24)	0'45"	
284(25)	35"	CP39-CP46
290(25)	44"	CP39-CP46
233(25)	31"	CP39-CP46
236(26)	30"	CP39-CP46
63(26)	11"	CP39-CP46
69(26)	09"	CP39-CP46
281(29)	35"	
280(01)	04"	
284(01)	16"	
240(01)	28"	
69(01)	10"	
233(01)	35"	
291(01)	38"	Initial Terminal
290(07)	30"	
284(08)	35"	
291(08)	41"	
48(07)	47"	
240(09)	30"	
240(13)	25"	
233(13)	30"	
284(14)	10"	
238(14)	23"	
240(14)	19"	
233(14)	30"	
233(15)	30"	
236(15)	05"	
240(15)	37"	
238(15)	08"	
281(15)	27"	
291(15)	15"	Initial Terminal Delay
283(15)	06"	
280(16)	19"	
233(16)	44"	
235(16)	45"	
290(16)	32"	
284(17)	25"	
236(17)	30"	
69(17)	35"	
1233(17)	15"	
280(17)	04"	
240(17)	15"	
290(17)	12"	
283(17)	23"	Initial Terminal Delay
2291(17)	27"	Initial Terminal Delay
233(20)	30"	
240(23)	31"	
233(23)	30"	
235(23)	30"	
284(23)	27"	
290(23)	52"	
291(23)	47"	
281(23)	31"	
284(26)	25"	

CSX Trackwork - Empire Division - 5/25 - 11/1 - Scheduled M/W Work

21MAY26: CSX Albany Division Buffalo Terminal, Syracuse Terminal, Rochester and Mohawk Subdivision trackwork between MP175 and MP437 from Monday May 25th to Sunday November 1st.

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Empire and Maple Leaf Services will be adjusted as follows:

Eastbound

- Train 280(25May-1Nov) will depart NFL 10-minutes Earlier, at 3:42am and return to their normal schedule at UCA.
- Train 284(25May-1Nov) will depart NFL 10-minutes Earlier, at 6:37am and return to their normal schedule at UCA.
- Train 64(25May-1Nov) will depart NFL 10-minutes Earlier, at 11:40am and return to their normal schedule at UCA.

Westbound

- Train 281(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 7:45pm.
- Train 283(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL and arrive at NFL 10-minutes Later, at 10:38pm.
- Train 63(25May-1Nov) will have miscellaneous adjustments to add time between UCA and NFL, will arrive at NFL 10-minutes Later, at 4:52pm, will depart NFL 10-minutes Later, at 5:00pm, and subsequently, dwell time at NFS will be 10-minutes less to resume normal schedule departing at 5:45pm.

WBS#: B.TR.100150.6692

Amtrak Hartford Line & Valley Flyer Service Adjustments - 4/21 - 10/30 – Trackwork

09MAR26: Beginning April 21, 2026, and continuing through October 30, 2026, weekday Amtrak Hartford Line and Valley Flyer services will be modified to accommodate Windsor Locks Station Project trackwork on the Amtrak MRS Main Line / Northeast Division between New Haven, CT (NHV) and Springfield, MA (SPG).

Work will occur Monday-Friday, 8:30 AM - 2:00 PM, at Windsor Locks (MP 47.4).

EXCEPTIONS - NO WORK ON MAJOR HOLIDAYS:

- Monday, May 25 (Memorial Day)
- Friday, July 3 (Independence Day)
- Monday, September 7 (Labor Day)

AMTRAK OPERATING PLAN:

To accommodate the above outlined infrastructure work, Amtrak's Hartford Line and Valley Flyer Services will be adjusted as follows:

Northbound:

- Train 490 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will be canceled in its entirety and replaced by bus; 1 express and 1 local.
- Train 470 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between NHV and SPG, will terminate

29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD. 26-FOI-00644a 00000008494 UNCLASSIFIED 187/2026

Southbound:

- Train 471 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.
- Train 473 (21Apr-24Apr, 27Apr-1May, 4May-8May, 11May-15May, 18May-22May, 26May-29May, 1Jun-5Jun, 8Jun-12Jun, 15Jun-19Jun, 22Jun-26Jun, 29Jun-2Jul, 6Jul-10Jul, 13Jul-17Jul, 20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug, 10Aug-14Aug, 17Aug-21Aug, 24Aug-28Aug, 31Aug-4Sep, 8Sep-11Sep, 14Sep-18Sep, 21Sep-25Sep, 28Sep-20Oct, 5Oct-9Oct, 12Oct-16Oct, 19Oct-23Oct, 26Oct-30Oct), which normally operates between SPG and NHV, will originate at HFD.

ALTERNATE TRANSPORTATION

- Bus 3490 will provide alternate transportation between NHV and SPG making all local stops
- Bus 3590 will provide alternate transportation between NHV and SPG, express, stopping at STS, HFD, and SPG only
- Bus 3470 will provide alternate transportation between HFD and SPG
- Buses 3471 and 3473 will provide alternate transportation between SPG and HFD
- Bus 3125 will provide alternate transportation between SPG and NHV Only if Train 425 is delayed and misses the connection to Train 125 at SPG.

WBS#: B.TR.100150.6530

No Data

Eastern Region

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations***Train 55(04) Passenger Medical Issues at New Haven Connecticut – Medical***

04AUG26, Passenger on, PNR 42DD87 traveling from Hartford, CT to Washington, DC. Companion advised crew that passenger was unable to transfer from the restroom toilet back into his wheelchair and requested assistance. Due to Amtrak policy and the passenger's medical condition, crew could not provide physical assistance. APD and EMS responded; assisted passenger back into his wheelchair. Passenger refused further medical treatment. Passenger and companion remained onboard and continued to Washington. Amtrak Police notified.

Delay 55(04) 27"

Western Region

Operating Highlights

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Train 11(04) South of Klamath Falls, OR - Freight Train Interference

05AUG26: Train 11(04), carrying 274 customers onboard, was delayed approximately 3.6 miles south of Klamath Falls, OR, at Wocus (MP 433.6) on the UP Cascade Subdivision while meeting UP 2683.

Train	Delay	Comment
11(04)	49"	

Train 58(04) South of Carbondale, IL - Passenger Train Interference

04AUG26: Train 58(04), with 128 customers onboard, was delayed at Anna siding/MP325.8, 17.5 miles south of Carbondale, IL/MP308.3, on the CN Centralia subdivision meeting Amtrak train 59(04). Once the route was clear, train 58(04) continued north.

Train	Delay	Comment
58(04)	49"	

Train 518(04) South of Stanwood, WA - Undesired Emergency Application

05AUG26: Train 518(04), carrying 184 customers onboard and operating with locomotive E/186 and 13 cars, was delayed approximately 6.5 miles south of Stanwood, WA, at MP 48.9 on the BNSF Bellingham Subdivision due to an undesired emergency brake application. The crew inspected the equipment and identified valves requiring isolation in the cab car and baggage car. Following the corrective actions, the train recovered from the brake application and continued northbound.

Train	Delay	Comment
518(04)	32"	

Train 8/28(04) Seattle, WA - Initial Terminal Delay

05AUG26: Train 8/28(04) was delayed departing its initial terminal in Seattle, WA, due to the late arrival of inbound equipment from Train 7/27(02) by 4 hours and 52 minutes. Mechanical forces conducted the required daily inspections and servicing activities upon arrival of the equipment and released the consist for service upon completion.

Train	Delay	Comment
8/28(04)	4'05"	

Train 4(04) Barstow, CA - Freight Train Interference

04AUG26: Train 4(04), carrying 178 customers onboard, was delayed west of Barstow, CA, due to freight traffic congestion on the BNSF Cajon Subdivision. The train followed a disabled freight train to a red signal at Hodge, where it met BNSF 7548W and an additional freight movement. The train continued eastward following BNSF 1051E through to Lenwood on yellow signals. After departing Barstow, Train 4(04) encountered additional freight traffic interference following an unknown BNSF train on approach medium or approach signals between MP 54.4 and MP 61.9.

Train	Delay	Comment
4(04)	37"	VRV-BAR
4(04)	20"	BAR-NDL

Train 48/448(04) Chicago, IL - Replace Headlight

04AUG26: Train 48/448(04) with engine IDTX4626, 12 cars, and 323 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago South subdivision due to a failed headlight on engine 107. Chicago Mechanical responded. Once repairs were complete, train 48/448(04) departed Chicago, IL.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
48/448(04)	41"	

Train 354(04) West of Niles, MI - Animal Strike

04AUG26: Train 354(04), with engine IDTX4626, 5 cars, and 215 customers onboard, struck a deer at mile post 199.0, 8 miles west of Niles, MI/MP191.9, on the Amtrak Michigan Line subdivision. There were no injuries reported by the customers or crew. The crew had to reconnect an air hose on the front end of engine IDTX4626. No other damage was reported. After rebuilding air pressure and performing a successful air test, train 354(04) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
354(04)	04"	

Train 5(03) West of Grand Junction, CO - Engine Locked Axle Fault

04AUG26: Train 5(03), operating with locomotives E/25 and E/48, nine cars, and 187 customers onboard, was delayed west of Grand Junction, CO, due to a locked axle alarm on trailing locomotive E/48. The crew inspected the locomotive and coordinated with the CNOC Mechanical Desk to troubleshoot the issue. Following the inspection, traction motor #1 and the associated speed sensors were cut out, allowing the train to continue operating to its destination.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
5(03)	33"	

Train 1(03)/421(02) West of Lordsburg, NM - Freight Train Interference

04AUG26: Train 1(03)/421(02), with 171 customers onboard, was delayed between Lordsburg, NM/MP1148.4 and Benson, AZ/MP1032.6 on the UP Lordsburg subdivision following UP freight UP/6294. Once the route was clear, train 1(03)/421(02) continued west.

Train 1(03)/421(02) was further delayed west of Benson, AZ between mile post 1035.0 and mile post 985.0 following UP freight UP/8158.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(03)/421(02)	2'35"	
1(03)/421(02)	48"	

Train 352(04) West of Ann Arbor, MI - Passenger Train Interference

04AUG26: Train 352(04), with 207 customers onboard, was delayed at Chelsea siding/MP52.0, 14.5 miles west of Ann Arbor, MI/MP37.5 on the Michigan Department of Transportation Michigan Line subdivision meeting Amtrak train 355(04). Once the route was clear, train 352(04) continued east.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
352(04)	33"	

Train 587(04) San Diego, CA - NCTD Coaster Trespasser Strike

04AUG26: Train 587(04) ~~26-FOI-00644 00000008494~~ ~~UNCLASSIFIED~~ San Diego, CA, due to a non-fatal trespasser strike involving NCTD Coaster Train 641 west of the station at MP 265.5 on Main Track 2. Local authorities and Maintenance of Way personnel responded to the scene while emergency response, investigative, and track inspection activities were conducted. Once the incident was cleared and the tracks were released for service, train movements resumed through the area.

Train 580(04), carrying 179 customers onboard, was delayed near Cudahy (MP 262.0) while awaiting the reopening of the affected territory. Train 591(04) was delayed departing San Diego as its equipment was turning from the late inbound Train 580(04).

Train	Delay	Comment
587(04)	1'59"	
580(04)	30"	
794(04)	30"	wait for crew of 587(04)
591(04)	11"	late turn 580(04)

Train 59(04) Chicago, IL - Initial Terminal Delay

04AUG26: Train 59(04), with 177 customers onboard, was delayed departing Chicago Union Station, IL/MP0.0 on the Amtrak Chicago subdivision due to the late release of the equipment of late train 58(03). Train 58(03) arrived in Chicago at 11:27AM CT, running four hours, twelve minutes late.

Train	Delay	Comment
59(04)	1'07"	

Train 538(04) San Jose, CA - Third Party Contractor Engine Failure

04AUG26: Train 538(04), operating with locomotive JPBX 920 and five cars, experienced a head-end power (HEP) failure in San Jose, CA. To minimize service impacts, a decision was made to swap equipment with Train 542(04). Mechanical forces continued troubleshooting efforts; however, the issue could not be resolved, resulting in equipment from Train 539(04) being used to operate Train 542(04). The affected equipment was subsequently reassigned to Train 544(04), but additional troubleshooting efforts were unsuccessful. As a result, the following service adjustments were implemented:

- Train 544(04) was canceled, with customers accommodated on Train 550(04).
- Train 525(05) was canceled, with customers accommodated on the next available service.

The affected equipment was deadheaded to the Oakland Maintenance Facility for further inspection and repair.

Train	Delay	Comment
538(04)	06"	
544(04)	Canceled	
525(05)	Canceled	

Train 4(03) East of Las Vegas, NM - High Wind Warnings

04AUG26: Train 4(03) operated at reduced speeds east of Las Vegas, NM, on the BNSF Raton Subdivision due to high wind warnings in effect across multiple portions of the route. Speed restrictions were implemented between MP 770 and MP 774, MP 706 and MP 661, and MP 662 and MP 639, requiring the train to reduce speed while traversing the affected territory.

Train	Delay	Comment
4(03)	42"	LSV-RAT
4(03)	12"	RAT-LAJ

Train 20(04) North of Meridian, MS - Freight Train Interference

04AUG26: Train 20(04) 26-FD-00644 00000008494 BERNHARDT, 53 miles north of Meridian, MS, on the NS AGS District, meeting NS 29S. UNCLASSIFIED 8/7/2026

Train	Delay	Comment
20(04)	31"	

Train 355(04) South of Pontiac, MI - Freight Train Interference

04AUG26: Train 355(04), with 9 customers onboard, was delayed at M.A.L. Junction/MP25.5, 0.4 miles south of Pontiac, MI/MP25.9 on the CN Holly subdivision meeting a freight. Once the freight had cleared the route, train 355(04) continued to Troy, MI.

Train	Delay	Comment
355(04)	50"	

Train 517(04) South of Olympia-Lacey, WA - Power Switch Failure

04AUG26: Train 517(04), carrying 110 customers, was delayed near Plumb (MP 37.2), approximately five miles south of Olympia-Lacey Station on the BNSF Seattle Subdivision, due to a power switch failure. The switch and swing-nose frog failed to lock properly, requiring the crew to place both in hand operation to safely route the train through the interlocking.

Train	Delay	Comment
517(04)	33"	

Train 1(03)/421(02) West of El Paso, TX - Heat Restrictions

04AUG26: Train 1(03)/421(02), with 167 customers onboard, was delayed between mile post 1274.0 and mile post 1148.0, beginning 22 miles west of El Paso, TX/MP1296.0, on the UP Lordsburg subdivision following heat restrictions. Once clear of the affected area, train 1(03)/421(02) continued west.

Train	Delay	Comment
1(03)/421(02)	1'00"	

Train 22(04)/422(02) Fort Worth, TX - Fuel Delays

04AUG26: Train 22(04)/422(02), with 169 customers onboard, was delayed at Fort Worth Central Station, TX/MP611.29 on the TRE Mainline subdivision due to issues fueling the equipment. The vendor did not bring the correct tools and equipment to fuel the train efficiently. Once the equipment was fueled, train 22(04)/422(02) continued north.

Train	Delay	Comment
22(04)/422(02)	37"	

Train 712(04) Oakland, CA - Third Party Contractor Cab Car Failure

04AUG26: Train 712(04) operating with C2013 and C8303, experienced a delayed departure from Oakland, CA, on the UP Niles Subdivision. Prior to departure, the crew reported a defective windshield wiper blade on cab car C8303. When repairs could not be completed, a plan was developed to wye locomotive C2013 and cap cab car C8303. However, the wye movement could not be performed due to engineering work on the north end of the yard, where asphalt had been placed over the tracks. To minimize customer and operational impacts, the equipment from Train 711(04) was turned and utilized for Train 712(04), allowing the train to depart with reduced delay.

Train 703(04) was delayed departing Bakersfield, CA turning from late inbound 712(04).

WBS#: B.TR.100150.6994

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
712(04)	2'50"	
716(04)	10"	
714(04)	1'52"	
703(04)	2'33"	

Train 1(03)/421(02) West of Alpine, TX - Freight Train Interference

04AUG26: Train 1(03)/421(02) was delayed at Collado/MP702.8, 95 miles west of Alpine, TX, on the UPRR Valentine Subdivision, meeting UP7946 and further delayed at Sierra Blanca/MP737, meeting UP 6517.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
1(03)/421(02)	50"	

Train 821(04) North of Fort Worth, TX - Debris

04AUG26: Train 821(04) was delayed at MP353.9, five miles north of Fort Worth, TX, on the BNSF Fort Worth Subdivision, due to a large concrete beam on the track ahead. Train 821(04) reversed to cross-over and operate around the debris on No 1 track.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
821(04)	38"	

Train 6(04) Emeryville, CA - Car Failure

04AUG26: Train 6(04), operating with E/40 and E/179 and carrying 115 customers, experienced a delayed departure from Emeryville, CA, on the UP Martinez Subdivision. Shortly before departure from the Oakland Mechanical Facility, the crew reported loading issues and the train became immobilized. Mechanical personnel were dispatched to inspect the locomotives, and the trailing locomotive was initially suspected to be defective, prompting consideration of a locomotive swap with E/81. Further inspection determined the issue was caused by a handbrake that remained applied on the dormitory car. Mechanical forces repaired the handbrake, the train's protective flags were removed, and Train 6 resumed normal operations.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
6(04)	1'23"	

Train 516(04) Seattle, WA - Engine Failure

04AUG26: Train 516(04) was cancelled with WDTX 1408 and WDTX 1400, experienced a delayed departure from Seattle, WA, on the BNSF Scenic Subdivision due to HEP faults on WDTX 1408. The HEP issues were attributed to problems with Cab Car 90253 and the additional locomotive, WDTX 1400.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
516(04)	33"	

Train 380(04) Quincy, IL - Engine Failure

04AUG26: Train 380(04) was cancelled with no alternate transportation available due to an issue with engine 176. Mechanical forces in Quincy reported a contactor issue and traction motor problems. The engine shut down and could not be restarted. BNSF freight 8135 was secured at West Quincy to couple up and take the 380(04) equipment back to Chicago for repair and balance.

WBS#: B.TR.100150.6990

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
380(04)	Cancelled	

Train 3(02) Victorville, CA - Freight Train Interference

04AUG26: Train 3(02), carrying 179 customers, experienced delays east of Victorville, California, on the BNSF Cajon Subdivision while following freight traffic, including a brief stop near MP 11.2 before proceeding into Victorville Station. Following its station stop, the train incurred an additional delay near Cajon (MP 62.3), approximately 26 miles west of Victorville, while meeting BNSF 6858 and conducting a job briefing with a patch crew taking over for continued travel to Los Angeles.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
3(02)	36"	following E/ VRV
3(02)	29"	BNSF 6858 @ Cajon
3(02)	30"	recrew @ Cajon

Train 22(04)/422(02) North of Austin, TX - Debris Strike

04AUG26: Train 22(04)/422(02), E/319-E/188 & 8 cars, with 176 customers, stopped in emergency at MP169.7, 10 miles north of Austin, TX, on the UPRR Austin Subdivision, due to striking a bicycle on the track. There were no reported injuries to passengers or crew. The crew inspected consist and reported E/319 with a damaged brake pipe hose between E/319 and E/188. There were no other exceptions to the equipment reported. The crew changed out the damaged hose and issues resolved. Train 22(04)/422(02) was back on the move north after air restored and crew performed Class II brake test.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
22(04)/422(02)	45"	

Train 8/28(02) East of Staples, MN - Freight Train Interference

04AUG26: Train 8/28(02) was delayed east of Staples, MN/MP148.3, on the BNSF Staples Subdivision, following BNSF 7520 between MP119 and St. Cloud/MP73.8 and further delayed due to BNSF 7520 experienced enroute air issues.

<u>Train</u>	<u>Delay</u>	<u>Comment</u>
8/28(02)	40"	

Train 3(02) West of Flagstaff, AZ - Recrew

04AUG26: Train 3(02), 26-FDI-00644 7300000008494, was delayed approximately 85 miles west of Flagstaff, AZ, at MP 429.2 on the BNSF Seligman Subdivision. The crew expired on Hours of Service due to enroute freight delays that prevented the train from arriving in Kingman, AZ, on time. Since alternate transportation was unavailable, the recrew traveled on Train 4(03) to meet Train 3(02).

B.TR.100150.6991

WBS#: B.TR.100150.6991

Train	Delay	Comment
3(02)	33"	Freight delay/crew expired
3(02)	2'23"	hold for recrew

Train 8/28(02) West of Detroit Lakes, MN - Passenger Train Interference

04AUG26: Train 8/28(02) was delayed at Richards Spur/MP213.6, 3 miles west of Detroit Lakes, MN, on the BNSF Staples Subdivision, meeting Train 7/27(03).

Train	Delay	Comment
8/28(02)	30"	

Midwest Corridor State Supported Service Adjustments - Engine Availability

04AUG26: Due to equipment availability in Chicago, IL, the following Midwest Corridor state supported service adjustments are in effect:

Pere Marquette:

- Train 370(04) cancelled entirely, with alternate transportation between Chicago, IL and Grand Rapids, MI.
- Train 371(05) cancelled entirely, with alternate transportation between Grand Rapids and Chicago.

Lincoln Service:

- Train 305(05) cancelled entirely, with alternate transportation between Chicago, IL and St. Louis, MO.
- Train 302(06) cancelled entirely, with alternate transportation between St. Louis and Chicago.

Wolverine Service:

- Train 352(06) cancelled entirely, sourcing alternate buses.
- Train 351(07) cancelled entirely, sourcing alternate buses.

WBS#: B.TR.100150.6992

Train	Delay	Comment
370(04)	Cancelled	
371(05)	Cancelled	
305(05)	Cancelled	
302(06)	Cancelled	
352(06)	Cancelled	
351(07)	Cancelled	

Train 507(02) East of Portland, OR - Warehouse Fire

02AUG26: At 4:58 PM PT, CNOC was notified that all rail traffic had been suspended east of Portland, OR, near CP 05 on the BNSF Fallbridge Subdivision, due to a major warehouse

carrying 139 customers onboard, was held at Vancouver, WA, while Train 506(02) remained at Portland Union Station awaiting a route to open. Train 508(02), operating northbound, was also impacted by the outage.

A bus bridge between Portland and Vancouver was established with Train 507(02) equipment turned at Vancouver and operated as Train 508(02) Vancouver-Seattle. Train 508(02) equipment turned at Portland and operated as Train 507(02) Portland-Eugene.

Train 506(02) continued to hold in Portland pending restoration of rail service and was ultimately canceled entirely with no alternate transportation provided.

Union Pacific pilots were ordered to facilitate a detour around the affected area for Trains 509(02) and 511(02).

Due to the prolonged closure, the following August 3 Cascades service adjustments were implemented:

- Train 500(03) canceled, no alternate transportation.
- Train 502(03) canceled, with alternate bus transportation provided.
- Train 504(03) terminated at Portland, with alternate bus transportation being sourced.
- Train 518(03) canceled between Portland and Seattle, with alternate transportation provided.
- Train 517(03) operated Vancouver-Seattle as scheduled, then used alternate equipment for Seattle-Vancouver service before terminating.
- Train 506(03) originated Vancouver, WA using the 517(03) equipment.
- Train 508(03) terminated at Portland, with alternate transportation provided Portland to Seattle.
- Train 503(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 505(03) canceled, with alternate transportation provided.
- Train 507(03) canceled between Seattle and Portland, with alternate transportation provided.
- Train 509(03) canceled between Seattle and Portland, with alternate bus transportation being sourced.
- Train 511(03) canceled, no alternate transportation.

Additionally, Union Pacific pilots were sourced to support reroute operations for Trains 11(03) and 14(02) if required by continuing service disruptions.

04AUG26: Cascade, Coast Starlight, and Empire Builder services adjusted through to Friday August 7, 2026.

- Train 500 (04,05,06,07) Cancelled entirely, No alternative Transportation.
- Train 502 (04,05,06, 07) Cancelled entirely. Will source alternate transportation.
- Train 504 (04,05,06,07) Will terminate in Portland, OR. Will source alternate transportation Portland, OR -Seattle, WA
- Train 518 (04,05,06,07) Cancelled Portland, OR-Seattle, WA. Will source alternate transportation.
- Train 517 (04,05,06,07) Will terminate in Vancouver, WA. No alternate Transportation from Vancouver, WA to Portland, OR.
- Train 506 (04,05,06,07) originating in Vancouver, WA. No alternate Transportation Portland, OR to Vancouver, WA.
- Train 508 (04,05,06,07) Will terminate Portland, OR. Will source alternate transportation Portland, OR-Seattle, WA.
- Train 503 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 505 (04,05,06,07) Cancelled entirely. Will source alternate transportation.
- Train 507 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 509 (04,05,06,07) Cancelled Seattle, WA-Portland, OR. Will source alternate transportation.
- Train 511 (04,05,06,07) Cancelled entirely. No alternate transportation.

Empire Service Equipment will operate through to Seattle for servicing

-Will source alternate transportation. Train 27 (02,03,04,05) Spokane, WA to Portland, OR.

-Will source alternate transportation. Train 28 (04,05,06,07) Portland, OR to Spokane,

Union Pacific pilots were sourced to support reroute operations for Trains 11(04) and 14(03). Union Pacific did advise they would not be able to support after these trains. As a result, 14(04) will terminate in Portland, OR.

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

WBS#: B.TR.100150.6981

Train	Delay	Comment
507(02)	1'41"	bus VAN-PDX
506(02)	Canceled	
508(02)	45"	bus PDX-VAN
509(02)	77"	couple 509-511(02)
509(02)	75"	Detour through UP yard
511(02)	76"	Detour through UP yard
500(03)	Canceled	
502(03)	Canceled	
511(03)	Canceled	
505(03)	Canceled	
518(03)	Canceled	between SEA-PDX
507(03)	Canceled	between SEA-PDX
508(03)	Term PDX	
504(03)	Term PDX	
509(03)	Canceled	
517(03)	Term VAN	
506(03)	Orig VAN	
503(03)	24"	canceled SEA-PDX
507(03)	1'10"	waiting for bus at PDX
14(02)	58"	detour
11(03)	51"	detour
14(04)	term PDX	
506(04)	1'03"	wait for inbound bus
518(04)	1'27"	wait for inbound bus

Havre, MT and Williston, ND - Heat Restrictions

24JUL26: Temperatures in the Great Plains reached temperatures exceeding 100°F. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow and Milk River Subdivision from Havre, MT to Williston, ND. Trains were restricted to 40MPH maximum authorized speed through the affected limits until temperatures recedes below 95°F. Train 7 / 27(23) and Train 8 / 28(23) were affected by the restrictions and freight interference.

25JUL26: Train 7(23) arrived into Seattle, WA 2'46" late causing late departure of 8(25). Train 27(23) arrived into Portland, OR 3'51" late causing late departure of 28(25).

25JUL26: Temperatures continue to be in excess of 100°F in the Great Plains. Burlington Northern Santa Fe placed several heat restrictions on the Glasgow, Milk River and Hi-Line Subdivision from Stanley, ND and Cutbank, MT. Train 7 / 27(24) and Train 8 / 28(24) were affected by the restrictions and freight interference caused by the restrictions.

Due to late operation of 7/27(24) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(24) from Spokane to Seattle and for 27(24) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(26) Seattle to Spokane and 28(26) Portland to Spokane with Train 8/28(26) originating Spokane, WA.

27JUL26: Due to late operation of 7/27(25) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(25) from Spokane to Seattle and for 27(25) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(27) Seattle to Spokane and 28(27) Portland to Spokane with Train 8/28(27) originating Spokane, WA.

01AUG26: Due to late operation of 7/27(31) to include heat order delays, this train will terminate in Spokane, WA. Buses were sourced for customers of 7(31) from Spokane to Seattle and for 27(31) Spokane to Portland, OR. These buses will also operate back to Spokane replacing train 8(02) Seattle to Spokane and 28(02) Portland to Spokane with Train 8/28(02) originating Spokane, WA.

WBS#: B.TR.100150.6937

Train	Delay	Comment
8/28(23)	2'16"	
7/27(23)	2'55"	
8/28(24)	2'16"	
7/27(24)	2'20"	Term SPK
28(25)	57"	late turn 27(23)
8(25)	2'00"	late turn 7(23)
7/27(25)	2'26"	Term SPK
8/28(27)		Orig SPK
8/28(25)	1'46"	
8/28(26)	1'16"	Orig SPK
7/27(26)		Term SPK
8/28(28)		Orig SPK
8/28(27)	2'15"	Orig SPK
8/28(28)	1'46"	Heat restrictions MAL-WTN
8/28(28)	1'31"	Frt congestion due to heat restrictions
7(31)	30"	WPT - GGW
7(31)	1'02"	WTN - WPT
8/28(01)	2'43"	MAL - GGW

Maintenance of Way Highlights

Burlington Northern Santa Fe Fallbridge Subdivision between Portland, OR and Spokane, WA - Scheduled M/W Work TWA 26-078

02AUG26: Burlington Northern Santa Fe will have a 36-hour outage affecting the Empire Builder service starting at 5:00A-PDT. They will be performing bridge work, slide fence replacement and switch maintenance at Bingen / MP 77.0 on the Fallbridge Subdivision.

To accommodate the above outlined infrastructure work, Amtrak's Empire Builder Service will be adjusted as follows:

- Train 27(31JUL, 01AUG) will terminate at SPK.
- Train 28 (02AUG, 03AUG) will originate at SPK.

ALTERNATE TRANSPORTATION

- Bus 4027 will provide alternate transportation between SPK and PDX making all stops except WIH.
- Bus 4028 will provide alternate transportation between PDX and SPK making all stops except WIH.

EQUIPMENT

- Equipment for Train 27(31Jul, 01AUG) will stay coupled to Train 7 at SPK
- Equipment for Train 28(02AUG, 03AUG) will be coupled to Train 8 departing SEA

WBS#: B.TR.100150.6891

BNSF Ottumwa Subdivision East of Creston, IA - Scheduled M/W Work 26-083

22JUL26: BNSF has bridge change out trackwork scheduled 14 miles east of Creston, IA at MP 378.51. The work schedule starts at 5:00AM on Monday, July 27th through 5:00AM on Wednesday, July 29th. As a result, train 6(25JUL-27JUL) will terminate at Denver with no alternate transportation. Train 5(26JUL-28JUL) will originate at Denver with no alternate transportation.

WBS#: B.TR.100150.6923

CN Yazoo Subdivision Track Work South of Memphis, TN - TWA 26-075

26JUL26: CN rail production gangs will be working on the CN Yazoo Subdivision south of Memphis, TN, between MP21.11 and MP168.90 beginning Monday July 27th through Wednesday September 30th. To accommodate this infrastructure work, City of New Orleans service adjusted as follows:

- Train 1059(26Jul, 30Jul) will operate in lieu of Train 59(26Jul, 30Jul), departing Chicago 2-hours Earlier, at 6:05pm, and will operate 2-hours earlier between Chicago and New Orleans.
- Train 59(27Jul-29Jul, 31Jul-29Sep) will depart Chicago 2-hours Earlier, at 6:05pm, and operate 2-hours earlier between Chicago and New Orleans.
- Train 1058(27Jul, 31Jul) will operate in lieu of Train 58(27Jul, 31Jul), departing New Orleans 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.
- Train 58(28Jul-30Jul, 1Aug-30Sep) will depart NOL 2-hours Earlier, at 11:45am, and will operate 2-hours earlier between New Orleans and Chicago.

WBS#: B.TR.100150.6867

Wolverine Track Work- Scheduled M/W Work 26-079

15JUL26:

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

To accommodate the above outlined infrastructure work, Amtrak's Wolverine Service will be adjusted as follows:

Westbound

· Trains 351, 353, and 355 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options.

Eastbound

· Trains 350, 352, and 354 (20Jul-24Jul, 27Jul-31Jul, 3Aug-7Aug) will bypass TRM. Passengers will be redirected to ROY or PNT as alternate options

WBS#: B.TR.100150.6897

CPKC Watertown Subdivision - Scheduled M/W Work 26-067

20APR26: CPKC has tie replacement trackwork on the Watertown Subdivision starting April 20th through June 21st between Columbus, WI and Milwaukee, WI. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (20Apr-21Jun) will have 12-minutes of recovery added at Columbus, 5-minutes of recovery added at Wisconsin Dells, and will arrive at St. Paul 15-minutes later at 6:56pm

-Train 1340 (20Apr-21Jun) will operate 10-minutes Earlier between St. Paul and Milwaukee, departing St. Paul at 11:39am, and will operate 5-minutes Later between Milwaukee and Chicago, departing Milwaukee at 5:49pm.

22JUN26: CPKC has tie replacement trackwork on the River Subdivision starting June 22nd through September 20th between St. Paul, Minneapolis and La Crosse, Wisconsin. In order to accommodate the infrastructure work, Amtrak's Borealis Service is adjusted as follows:

-Train 1333 (22Jun-20Sep) will arrive at St. Paul-Minneapolis 20-minutes later at 7:01pm.

-Train 1340 (22Jun-20Sep) will depart St. Paul-Minneapolis 20-minutes earlier at 11:29am, will depart Red Wing 10-minutes earlier at 12:27pm, and return to normal schedule departing Winona.

WBS#: B.TR.100150.6620

BNSF Southwest Chief Service - Scheduled M/W Work 26-049

13APR26: BNSF will perform multiple trackwork project on multiple subdivisions along the entire Southwest Chief route between Los Angeles, CA and Chicago, IL, May 31st, 2026 through October 9th, 2026. Multiple rail, tie, surfacing and undercutting gangs will work multiple curfews throughout this period. To accommodate this infrastructure work, the following Amtrak's Southwest Chief service adjustments are in effect:

- Train 4(29MAY-07OCT) will operate on an adjusted schedule as follows:

Depart Los Angeles, CA twenty-four minutes Earlier at 4:55PM-PT,

Depart Albuquerque, NM one minute Earlier at 11:31AM-MT,

Depart Kansas City, MO twelve minutes Later at 7:13AM-CT,

Depart Naperville, IL forty-seven minutes Later at 2:40PM-CT,

Arrive at Chicago, IL, forty-seven minutes Later at 3:29PM-CT.

Note: Naperville, IL will be a "discharge only" stop and the train may depart ahead of schedule.

- Train 1003(29MAY) and Train 3(30MAY-07OCT) will operate on an adjusted scheduled as follows:

Depart Chicago, IL fifty-five minutes Earlier at 1:30PM-CT,

Depart Kansas City, MO forty minutes Earlier at 9:37PM-CT,

Depart Albuquerque, NM twenty minutes Earlier at 3:14PM-MT,

Depart Fullerton, CA fifteen minutes Later at 7:18AM-PT,

Arrive Los Angeles, CA fifteen minutes later at 8:12AM-PT.

Note: Fullerton, CA will be a "discharge only" stop and the train may depart ahead of schedule.

WBS#: B.TR.100150.6626

Metra C&M Subdivision - Scheduled M/W Work 26-055

16MAY26: Metra has trackwork scheduled on the C&M Subdivision at Western Avenue - Rondout starting on May 16th through November 1st on Saturday and Sundays only. In order to accommodate the outlined infrastructure work, Amtrak's Hiawatha Service will be adjusted as follows:

Northbound

- Train 331 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 10:04am
- Train 335 (Saturday and Sunday) will arrive at Milwaukee 10-minutes Later at 2:44pm

Southbound

- Train 330 (Saturday ONLY) will arrive at Chicago 10-minutes Later at 8:07am.
- Train 332 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 9:44am
- Train 334 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 12:39pm
- Train 336 (Saturday and Sunday) will arrive at Chicago 10-minutes Later at 2:44pm

WBS#: B.TR.100150.6663

No Data

Western Region

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Displaced Guests

Train	Number of Guests	Planned (Yes/No)	Details
None			

Physical Distancing

Train	Number of Passengers Re-accommodated	Seating Option Provided (café, dining car, other)	Segment Customer Occupied Temporary Space (stations)
None			

Standees

Train	Projected Need		Number Operated		Standees	Location
	Cars	Seats	Cars	Seats		
None						

Misconnects

Station	From Train	To Train	Passengers	Rooms	Cost
None					

Carry-By

Train	Location	Passengers	Disposition	Cost
			SMT	

Station Service Recovery

Train/Bus	Station	# of Psgr's	Type of Service Recovery	Cost
None				

Passenger Removals and/or Isolations

Consist Deviations

26-FOI-00644

00000008494

"UNCLASSIFIED"

8/7/2026

Train Number	Station	Reason	Customer Impact	Affected Psgr	Unit Number(s)
179 (04)	BOS	Cafe car 43366 added rearmost in BOS due to 43386 B/O refrigeration and unable to carry perishable items.	NONE	0	43386
98 (04)	MIA	Due to train 98(04)-line 9811 changing equipment it was necessary to perform a schedule change. Please utilize the WAR report to ensure all affected customers have been accommodated.	PASSENGERS RELOCATED	2	62507
94 (04)	NFK	94(04) will operate with a Business Class car in lieu of a coach.	NONE	0	81511
86 (04)	NPN	43386 reported B/O refrigeration cannot stock perishable items.	NONE	0	43386
151 (04)	PHL	Cafe car 43391 added rearmost due 48140 cafe B/O refrigeration.	NONE	0	43391
66 (04)	RNK	Cafe car 43391 added rearmost due 48140 cafe B/O refrigeration.	NONE	0	43391
517 (04)	VAC	Consist operating with Amfleet equipment and not Talgo-reduced capacity and now oversold in business and coach. Re-accommodate overbooked passengers.	PASSENGERS NOTIFIED OVER CAPACITY	34	

Reverse Consists

Train Number	Station	Reason
95 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
93 (04)	BOS	Consist reversed Business class seat orientation may have changed At Front
181 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front
136 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front
134 (04)	WAS	Consist reversed Business class seat orientation may have changed At Front
197 (04)	NYP	Consist reversed Business class seat orientation may have changed At Front

Train Number	Station	Reason	
		26-FOI-00644	00000008494 "UNCLASSIFIED" 8/7/2026
		Rear	
125 (05)	SPG	Consist reversed Business class seat orientation may have changed At Front	
86 (05)	NPN	Consist reversed Business class seat orientation may have changed At Front	
179 (05)	BOS	Consist reversed Business class seat orientation may have changed At Front	
138 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front	
94 (05)	NFK	Consist reversed Business class seat orientation may have changed At Front	