STANDARD OPERATING PROCEDURE

STANDARD OPERATING PROCEDURE

COLD STORAGE TEMPERATURE MONITORING

Document No: SOP-OPS-2024-113

Revision: 2.4

Effective Date: January 15, 2024

1. PURPOSE

1 This Standard Operating Procedure (SOP) establishes the requirem

2. SCOPE

1 This SOP applies to all Company facilities and customer installation
-
Ultra-low temperature freezers (-40 C to -20 C)
-
Standard freezers (-20 C to -0 C)
-
Refrigerated areas (0 C to 8 C)
-
Temperature transition zones

3. DEFINITIONS

1 "AMR" means autonomous mobile robot units manufactured by the

2 "Blue@ore(TM)" means the Company's proprietary cold-environmen
3 "Critical Temperature Range" means the specified temperature range
4 "Temperature Excursion" means any deviation outside the Critical T
4. RESPONSIBILITIES
1 Facility Operations Manager shall:
- Ensure implementation of this SOP
- Review temperature monitoring reports weekly
- Authorize corrective actions when needed
-

5. EQUIPMENT AND MATERIALS
Calibrate monitoring equipment quarterly
-
Document any temperature excursions
-
Conduct daily system checks
-
Monitor real-time temperature data
-
2 AMR Technical Supervisor shall:
Maintaing compliance documentation

1 Required monitoring equipment:

BlueCore(TM) integrated temperature sensors
-
Backup digital thermometers (calibrated)
-
Network connectivity devices
-
Data logging system
-
Emergency notification system
6. PROCEDURE

1 Temperature Monitoring

1.1 Automated Monitoring

BlueCore(TM) sensors shall record temperatures at 5-minute intervals
-
Data shall be transmitted to central monitoring system
-
System shall maintain 12-month rolling temperature history
-
Automated alerts trigger when temperatures deviate by 2 C
1.2 Manual Verification
-
Physical temperature checks twice per shift
-
Record readings in electronic log
-
Compare against automated readings

- -6-

Document any discrepancies

2 Documentation Requirements

2.1 Required Records

-

Continuous temperature logs

_

Equipment calibration records

-

Deviation reports

-

Corrective action documentation

-

Maintenance records
2.2 Record Retention
-
Electronic records: 5 years minimum
-
Calibration certificates: Duration of equipment life plus 1 year
-
Deviation reports: 3 years minimum
7. TEMPERATURE EXCURSION RESPONSE
1 Upon temperature excursion:
-
Initiate immediate investigation
-

Document extent and duration
-
Assess impact on AMR operations
-
Implement corrective actions
-
Prepare deviation report
2 Notification Requirements
-
Alert Facility Operations Manager within 30 minutes
-
Notify Technical Support if AMR performance affected
-
Document all communications

- -9-

Update customer if applicable

8. QUALITY CONTROL

1 System Verification

-

Monthly accuracy checks of all sensors

_

Quarterly calibration verification

-

Annual third-party validation

-

Documentation of all verification activities

2 Data Review

10 -
Daily review of temperature logs
_
Weekly trend analysis
-
Monthly compliance review
-
Quarterly system performance evaluation

9. TRAINING REQUIREMENTS

1 Personnel must complete:

_

Initial SOP training

-

Annual refresher training

Temperature monitoring system operation training

Emergency response procedures training

10. REFERENCES

1 Related Documents

Equipment Operating Manual Rev 3.2

Quality Management System Manual

Emergency Response Plan

- 12 -

Calibration SOP Rev 1.8

11. REVISION HISTORY

| Version | Date | Description | Approved By |

2.4 2024-01-15 Updated temperature ranges and monitoring inter
Wells, CFO
2.3 2023-08-10 Added BlueCore(TM) specific procedures M. Ch

| 2.2 | 2023-03-22 | Revised notification requirements | S. Nordstrom,

12. APPROVALS

Document Owner: Operations Department

Approved By: Dr. Elena Frost, CEO



