




MANIFOLDED/SEALED/WRAP DATE:












Mark Qty Size Description Strut Width Rod 1 Rod 2 Insulation Length 01 1 3/4" 0'-9 13/16" Cerro Type L Hard Copper - CFOS 02 1 3/4" Cerro Type L Hard Copper - CFOS 2'-4 1/8" 03 1 1/2" 1'-5 5/8" Cerro Type L Hard Copper - CFOS 3 3/4"x1/2"x3/4" Nibco 611R-CB CFOS Wrot Copper Reducing Tee 1/2" Nibco 607-CB CFOS Wrot 90 Elbow

CONNECT TO CO2-L03-039  02  CO2  SHIP  LOOSE  ADD 8" PIPE BRAZED SHUT	1 <u>3</u> )
CONNECT TO CO2-L03-043  O4 UP  CONNECT TO CO2-L03-043  O4 UP  SCALE:	05 UP SHIP LOOSE




PRONT ELEVATION

SCALE: 3/4" = 1'-0"

A1	А3	B1	В3
A2	A4	B2	B4

BIM 360://WUSM NRB/WUSM\_RB\_PUF.rvt 16-08-2021 15:43:00



DATE REQ:

тіскет: CO2-L03-040

JOB: WASH U NRB

