


Vue X7



	Coordonnés		
Points	$\overline{\chi}$	Y	Z
5000	-Lo/2	- La12	-H/2
5100	+Lo/2	-La/2	~H/2
5010	· Lo/z	+La12	- H/2 .
5110	+L0/2	+ La/2	-H/2
5001	-Lo/2	- La/2	+ H/2
5 1 0 1	+ L012	-Lalz	+4/2
5011	- Lo/2	+ Lala	+ H 12
5 111	+ L0/2	+ Lalz	+H/2