week 4 QA

R1 – Boot

status16:38:48.560 > ets Jul 29 2019 12:21:46
16:38:48.561 >
16:38:48.561 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:38:48.562 > configsip: 0, SPIWP:0xee
16:38:48.562 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:38:48.562 > mode:DIO, clock div:2
16:38:48.562 > load:0x3fff0030,len:1156
16:38:48.562 > load:0x40078000,len:11456
16:38:48.562 > ho 0 tail 12 room 4
16:38:48.562 > load:0x40080400,len:2972
16:38:48.562 > entry 0x400805dc
16:38:49.341 > [BOOT] reset_reason=POWER_ON
16:38:49.350 > [WDT] enabled timeout=4000 ms
16:38:49.350 > Commands:
16:38:49.350 > help
16:38:49.350 > status
16:38:49.350 > sensor
16:38:49.350 > relay on
16:38:49.350 > relay off
16:38:49.350 > save
16:38:49.350 > sleep <seconds>
16:38:49.350 > hang
16:38:49.350 > powerloss
16:38:49.350 > reboot
status
16:39:01.113 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}

Reboot

16:44:18.386 > ets Jul 29 2019 12:21:46
16:44:18.387 >
16:44:18.387 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:44:18.387 > configsip: 0, SPIWP:0xee
16:44:18.387 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:44:18.387 > mode:DIO, clock div:2

16:44:18.387 > load:0x3fff0030,len:1156
16:44:18.387 > load:0x40078000,len:11456
16:44:18.387 > ho 0 tail 12 room 4
16:44:18.387 > load:0x40080400,len:2972
16:44:18.387 > entry 0x400805dc
16:44:19.174 > [BOOT] reset_reason=POWER_ON
16:44:19.188 > [WDT] enabled timeout=4000 ms
16:44:19.188 > Commands:
16:44:19.188 > help
16:44:19.188 > status
16:44:19.188 > sensor
16:44:19.188 > relay on
16:44:19.188 > relay off
16:44:19.188 > save
16:44:19.188 > sleep <seconds>
16:44:19.188 > hang
16:44:19.188 > powerloss
16:44:19.188 > reboot
reboot
16:44:49.535 > ets Jul 29 2019 12:21:46
16:44:49.535 >
16:44:49.535 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:44:49.535 > configsip: 0, SPIWP:0xee
16:44:49.535 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:44:49.586 > mode:DIO, clock div:2
16:44:49.586 > load:0x3fff0030,len:1156
16:44:49.586 > load:0x40078000,len:11456
16:44:49.586 > ho 0 tail 12 room 4
16:44:49.586 > load:0x40080400,len:2972
16:44:49.586 > entry 0x400805dc
16:44:50.357 > [BOOT] reset_reason=SOFTWARE_RESET
16:44:50.358 > [WDT] enabled timeout=4000 ms
16:44:50.371 > Commands:
16:44:50.371 > help
16:44:50.371 > status
16:44:50.371 > sensor
16:44:50.371 > relay on
16:44:50.371 > relay off
16:44:50.371 > save
16:44:50.371 > sleep <seconds>
16:44:50.371 > hang
16:44:50.371 > powerloss
16:44:50.371 > reboot

status
16:44:55.448 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":false,"counter":0,"heap":336332,"sensor_ok":true}

Sleep 5

16:45:19.242 > ets Jul 29 2019 12:21:46
16:45:19.242 >
16:45:19.242 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:45:19.243 > configsip: 0, SPIWP:0xee
16:45:19.243 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:45:19.243 > mode:DIO, clock div:2
16:45:19.243 > load:0x3fff0030,len:1156
16:45:19.243 > load:0x40078000,len:11456
16:45:19.243 > ho 0 tail 12 room 4
16:45:19.243 > load:0x40080400,len:2972
16:45:19.243 > entry 0x400805dc
16:45:20.027 > [BOOT] reset_reason=POWER_ON
16:45:20.039 > [WDT] enabled timeout=4000 ms
16:45:20.039 > Commands:
16:45:20.039 > help
16:45:20.039 > status
16:45:20.039 > sensor
16:45:20.039 > relay on
16:45:20.039 > relay off
16:45:20.039 > save
16:45:20.039 > sleep <seconds>
16:45:20.039 > hang
16:45:20.039 > powerloss
16:45:20.039 > reboot
sleep 5
16:45:32.456 > [STORE] saved
16:45:32.456 > [STATE] SLEEP timer=5 s
16:45:32.993 > ets Jul 29 2019 12:21:46
16:45:32.993 >
16:45:32.993 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:45:32.994 > configsip: 0, SPIWP:0xee
16:45:32.994 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:45:33.005 > mode:DIO, clock div:2
16:45:33.005 > load:0x3fff0030,len:1156
16:45:33.006 > load:0x40078000,len:11456
16:45:33.006 > ho 0 tail 12 room 4

16:45:33.006 > load:0x40080400,len:2972
16:45:33.006 > entry 0x400805dc
16:45:33.842 > [BOOT] reset_reason=DEEP_SLEEP
16:45:33.842 > [WAKE] cause=4
16:45:33.842 > [WDT] enabled timeout=4000 ms
16:45:33.860 > Commands:
16:45:33.860 > help
16:45:33.860 > status
16:45:33.860 > sensor
16:45:33.860 > relay on
16:45:33.860 > relay off
16:45:33.860 > save
16:45:33.860 > sleep <seconds>
16:45:33.860 > hang
16:45:33.860 > powerloss
16:45:33.860 > reboot
status
16:45:38.848 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1,"heap":336332,"sensor_ok":true}

---

hang

16:46:10.338 > ets Jul 29 2019 12:21:46
16:46:10.339 >
16:46:10.339 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:46:10.339 > configsip: 0, SPIWP:0xee
16:46:10.339 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:46:10.339 > mode:DIO, clock div:2
16:46:10.339 > load:0x3fff0030,len:1156
16:46:10.339 > load:0x40078000,len:11456
16:46:10.339 > ho 0 tail 12 room 4
16:46:10.339 > load:0x40080400,len:2972
16:46:10.339 > entry 0x400805dc
16:46:11.122 > [BOOT] reset_reason=POWER_ON
16:46:11.134 > [WDT] enabled timeout=4000 ms
16:46:11.134 > Commands:
16:46:11.134 > help
16:46:11.134 > status
16:46:11.134 > sensor
16:46:11.134 > relay on

16:46:11.134 > relay off
16:46:11.134 > save
16:46:11.134 > sleep <seconds>
16:46:11.134 > hang
16:46:11.134 > powerloss
16:46:11.134 > reboot
hang
16:46:18.512 > [FAULT] firmware hang
16:46:22.672 > E (23596) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
16:46:22.672 > E (23596) task_wdt: - loopTask (CPU 1)
16:46:22.672 > E (23596) task_wdt: Tasks currently running:
16:46:22.969 > E (23596) task_wdt: CPU 0: IDLE0
16:46:22.969 > E (23596) task_wdt: CPU 1: loopTask
16:46:22.969 > E (23596) task_wdt: Aborting.
16:46:22.969 >
16:46:22.969 > abort() was called at PC 0x400dbf11 on core 0
16:46:22.970 >
16:46:22.970 >
16:46:22.970 > Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED
16:46:22.970 >
16:46:22.970 >
16:46:22.970 >
16:46:22.970 >
16:46:22.970 > ELF file SHA256: 7bf4d35d2b731f75
16:46:22.970 >
status
16:46:27.946 > ets Jul 29 2019 12:21:46
16:46:27.947 >
16:46:27.947 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
16:46:27.947 > configsip: 0, SPIWP:0xee
16:46:27.947 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
16:46:27.952 > mode:DIO, clock div:2
16:46:27.952 > load:0x3fff0030,len:1156
16:46:27.952 > load:0x40078000,len:11456
16:46:27.952 > ho 0 tail 12 room 4
16:46:27.966 > load:0x40080400,len:2972
16:46:27.966 > entry 0x400805dc
16:46:28.765 > [BOOT] reset_reason=INT_WDT
16:46:28.781 > [WDT] enabled timeout=4000 ms
16:46:28.781 > Commands:
16:46:28.781 > help
16:46:28.781 > status

16:46:28.781 > sensor
16:46:28.781 > relay on
16:46:28.781 > relay off
16:46:28.781 > save
16:46:28.781 > sleep <seconds>
16:46:28.781 > hang
16:46:28.781 > powerloss
16:46:28.781 > reboot

R2

- -- Terminal on rfc2217://localhost:4000 | 115200 8-N-1
  --- Available filters and text transformations: debug, default, direct, esp32_exception_decoder, hexlify, log2file, nocontrol, printable, send_on_enter, time
  --- More details at https://bit.ly/pio-monitor-filters
  --- Quit: Ctrl+C | Menu: Ctrl+T | Help: Ctrl+T followed by Ctrl+H
  16:57:42.513 > ets Jul 29 2019 12:21:46
  16:57:42.513 >
  16:57:42.513 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
  16:57:42.513 > configsip: 0, SPIWP:0xee
  16:57:42.513 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
  16:57:42.514 > mode:DIO, clock div:2
  16:57:42.514 > load:0x3fff0030,len:1156
  16:57:42.514 > load:0x40078000,len:11456
  16:57:42.514 > ho 0 tail 12 room 4
  16:57:42.514 > load:0x40080400,len:2972
  16:57:42.514 > entry 0x400805dc
  16:57:43.295 > [BOOT] reset_reason=POWER_ON
  16:57:43.306 > [WDT] enabled timeout=4000 ms
  16:57:43.306 > Commands:
  16:57:43.306 > help
  16:57:43.306 > status
  16:57:43.306 > sensor
  16:57:43.306 > relay on
  16:57:43.306 > relay off
  16:57:43.306 > save
  16:57:43.306 > sleep <seconds>
  16:57:43.306 > hang
  16:57:43.306 > powerloss
  16:57:43.306 > reboot
  sensor
  16:58:05.685 > [CLI] ERROR unknown command
  sensor

16:58:09.837 > [SENSOR] temp=24.5C humidity=45.0%
status
16:58:17.032 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336020,"sensor_ok":true}

```
  "esp:D13",
```

17:09:31.636 > ets Jul 29 2019 12:21:46
17:09:31.636 >
17:09:31.636 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
17:09:31.637 > configsip: 0, SPIWP:0xee
17:09:31.637 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
17:09:31.637 > mode:DIO, clock div:2
17:09:31.637 > load:0x3fff0030,len:1156
17:09:31.637 > load:0x40078000,len:11456
17:09:31.637 > ho 0 tail 12 room 4
17:09:31.637 > load:0x40080400,len:2972
17:09:31.637 > entry 0x400805dc
17:09:32.422 > [BOOT] reset_reason=POWER_ON
17:09:32.429 > [WDT] enabled timeout=4000 ms
17:09:32.429 > Commands:
17:09:32.429 > help
17:09:32.430 > status
17:09:32.430 > sensor
17:09:32.430 > relay on
17:09:32.430 > relay off
17:09:32.430 > save
17:09:32.430 > sleep <seconds>
17:09:32.430 > hang
17:09:32.430 > powerloss
17:09:32.430 > reboot
sensor
17:09:45.331 > [CLI] ERROR unknown command
sensor
17:09:48.266 > [SENSOR] temp=0.0C humidity=0.0%
status
17:09:52.368 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336300,"sensor_ok":false}

esp:D15

17:17:57.550 > ets Jul 29 2019 12:21:46
17:17:57.550 >
17:17:57.550 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
17:17:57.550 > configsip: 0, SPIWP:0xee
17:17:57.550 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
17:17:57.551 > mode:DIO, clock div:2
17:17:57.551 > load:0x3fff0030,len:1156
17:17:57.551 > load:0x40078000,len:11456
17:17:57.551 > ho 0 tail 12 room 4
17:17:57.551 > load:0x40080400,len:2972
17:17:57.551 > entry 0x400805dc
17:17:58.343 > [BOOT] reset_reason=POWER_ON
17:17:58.350 > [WDT] enabled timeout=4000 ms
17:17:58.350 > Commands:
17:17:58.350 > help
17:17:58.351 > status
17:17:58.351 > sensor
17:17:58.351 > relay on
17:17:58.351 > relay off
17:17:58.351 > save
17:17:58.351 > sleep <seconds>
17:17:58.351 > hang
17:17:58.351 > powerloss
17:17:58.351 > reboot
sensor
17:18:02.461 > [SENSOR] temp=24.5C humidity=45.0%
status
17:18:06.506 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336068,"sensor_ok":true}

R3 — Кнопка

17:43:24.235 > ets Jul 29 2019 12:21:46
17:43:24.236 >
17:43:24.236 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
17:43:24.236 > configsip: 0, SPIWP:0xee
17:43:24.236 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
17:43:24.236 > mode:DIO, clock div:2
17:43:24.236 > load:0x3fff0030,len:1156
17:43:24.236 > load:0x40078000,len:11456
17:43:24.236 > ho 0 tail 12 room 4
17:43:24.236 > load:0x40080400,len:2972

17:43:24.236 > entry 0x400805dc
17:43:25.028 > [BOOT] reset_reason=POWER_ON
17:43:25.035 > [WDT] enabled timeout=4000 ms
17:43:25.035 > Commands:
17:43:25.035 > help
17:43:25.035 > status
17:43:25.035 > sensor
17:43:25.035 > relay on
17:43:25.035 > relay off
17:43:25.035 > save
17:43:25.035 > sleep <seconds>
17:43:25.035 > hang
17:43:25.035 > powerloss
17:43:25.035 > reboot
status
17:43:30.165 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}
17:43:35.704 > [STORE] saved
17:43:35.704 > [BUTTON] relay=ON
17:43:40.324 > [STORE] saved
17:43:40.334 > [BUTTON] relay=OFF
status
17:44:21.230 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":2,"heap":336332,"sensor_ok":true}
17:44:33.892 > [STORE] saved
17:44:33.902 > [BUTTON] relay=ON
17:44:34.841 > [STORE] saved
17:44:34.850 > [BUTTON] relay=OFF
17:44:35.740 > [STORE] saved
17:44:35.740 > [BUTTON] relay=ON
17:44:36.653 > [STORE] saved
17:44:36.654 > [BUTTON] relay=OFF
17:44:37.622 > [STORE] saved
17:44:37.622 > [BUTTON] relay=ON
17:44:38.623 > [STORE] saved
17:44:38.623 > [BUTTON] relay=OFF
17:44:39.853 > [STORE] saved
17:44:39.853 > [BUTTON] relay=ON
17:44:40.891 > [STORE] saved
17:44:40.900 > [BUTTON] relay=OFF
17:44:41.922 > [STORE] saved

17:44:41.922 > [BUTTON] relay=ON
17:44:42.936 > [STORE] saved
17:44:42.936 > [BUTTON] relay=OFF
status
17:44:59.295 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":12,"heap":336332,"sensor_ok":true}

R4 — Сон (Sleep / Wake)

14:59:12.094 > ets Jul 29 2019 12:21:46
14:59:12.095 >
14:59:12.095 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
14:59:12.095 > configsip: 0, SPIWP:0xee
14:59:12.095 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
14:59:12.095 > mode:DIO, clock div:2
14:59:12.095 > load:0x3fff0030,len:1156
14:59:12.095 > load:0x40078000,len:11456
14:59:12.095 > ho 0 tail 12 room 4
14:59:12.095 > load:0x40080400,len:2972
14:59:12.095 > entry 0x400805dc
14:59:12.861 > [BOOT] reset_reason=POWER_ON
14:59:12.873 > [WDT] enabled timeout=4000 ms
14:59:12.873 > Commands:
14:59:12.873 > help
14:59:12.873 > status
14:59:12.873 > sensor
14:59:12.873 > relay on
14:59:12.873 > relay off
14:59:12.873 > save
14:59:12.873 > sleep <seconds>
14:59:12.873 > hang
14:59:12.873 > powerloss
14:59:12.873 > reboot
relay on
14:59:26.125 > [CLI] ERROR unknown command
relay on
14:59:31.240 > [CLI] ERROR unknown command
relay on
14:59:35.022 > [STORE] saved
14:59:35.022 > [RELAY] ON

status
14:59:45.030 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":true,"counter":1,"heap":336332,"sensor_ok":true}
sleep 5
15:00:07.574 > [STORE] saved
15:00:07.574 > [STATE] SLEEP timer=5 s
15:00:08.114 > ets Jul 29 2019 12:21:46
15:00:08.115 >
15:00:08.115 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:00:08.115 > configsip: 0, SPIWP:0xee
15:00:08.115 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:00:08.149 > mode:DIO, clock div:2
15:00:08.149 > load:0x3fff0030,len:1156
15:00:08.149 > load:0x40078000,len:11456
15:00:08.149 > ho 0 tail 12 room 4
15:00:08.149 > load:0x40080400,len:2972
15:00:08.149 > entry 0x400805dc
15:00:08.949 > [BOOT] reset_reason=DEEP_SLEEP
15:00:08.949 > [WAKE] cause=4
15:00:08.949 > [WDT] enabled timeout=4000 ms
15:00:08.958 > Commands:
15:00:08.958 > help
15:00:08.958 > status
15:00:08.958 > sensor
15:00:08.958 > relay on
15:00:08.958 > relay off
15:00:08.958 > save
15:00:08.958 > sleep <seconds>
15:00:08.958 > hang
15:00:08.958 > powerloss
15:00:08.958 > reboot
status
15:00:43.616 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":true,"counter":2,"heap":336332,"sensor_ok":true}

14:59:12.094 > ets Jul 29 2019 12:21:46
14:59:12.095 >
14:59:12.095 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
14:59:12.095 > configsip: 0, SPIWP:0xee
14:59:12.095 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
14:59:12.095 > mode:DIO, clock div:2
14:59:12.095 > load:0x3fff0030,len:1156
14:59:12.095 > load:0x40078000,len:11456
14:59:12.095 > ho 0 tail 12 room 4
14:59:12.095 > load:0x40080400,len:2972
14:59:12.095 > entry 0x400805dc
14:59:12.861 > [BOOT] reset_reason=POWER_ON
14:59:12.873 > [WDT] enabled timeout=4000 ms
14:59:12.873 > Commands:
14:59:12.873 > help
14:59:12.873 > status
14:59:12.873 > sensor
14:59:12.873 > relay on
14:59:12.873 > relay off
14:59:12.873 > save
14:59:12.873 > sleep <seconds>
14:59:12.873 > hang
14:59:12.873 > powerloss
14:59:12.873 > reboot
relay on
14:59:26.125 > [CLI] ERROR unknown command
relay on
14:59:31.240 > [CLI] ERROR unknown command
relay on
14:59:35.022 > [STORE] saved
14:59:35.022 > [RELAY] ON
status
14:59:45.030 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":true,"counter":1,"heap":336332,"sensor_ok":t
rue}
sleep 5
15:00:07.574 > [STORE] saved
15:00:07.574 > [STATE] SLEEP timer=5 s

15:00:08.114 > ets Jul 29 2019 12:21:46
15:00:08.115 >
15:00:08.115 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:00:08.115 > configsip: 0, SPIWP:0xee
15:00:08.115 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:00:08.149 > mode:DIO, clock div:2
15:00:08.149 > load:0x3fff0030,len:1156
15:00:08.149 > load:0x40078000,len:11456
15:00:08.149 > ho 0 tail 12 room 4
15:00:08.149 > load:0x40080400,len:2972
15:00:08.149 > entry 0x400805dc
15:00:08.949 > [BOOT] reset_reason=DEEP_SLEEP
15:00:08.949 > [WAKE] cause=4
15:00:08.949 > [WDT] enabled timeout=4000 ms
15:00:08.958 > Commands:
15:00:08.958 > help
15:00:08.958 > status
15:00:08.958 > sensor
15:00:08.958 > relay on
15:00:08.958 > relay off
15:00:08.958 > save
15:00:08.958 > sleep <seconds>
15:00:08.958 > hang
15:00:08.958 > powerloss
15:00:08.958 > reboot
status
15:00:43.616 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":true,"counter":2,"heap":336332,"sensor_ok":t
rue}
sleep 10
15:01:47.605 > [STORE] saved
15:01:47.605 > [STATE] SLEEP timer=10 s
15:01:48.264 > ets Jul 29 2019 12:21:46
15:01:48.264 >
15:01:48.264 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:01:48.272 > configsip: 0, SPIWP:0xee
15:01:48.272 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:01:48.272 > mode:DIO, clock div:2
15:01:48.272 > load:0x3fff0030,len:1156
15:01:48.272 > load:0x40078000,len:11456
15:01:48.273 > ho 0 tail 12 room 4
15:01:48.289 > load:0x40080400,len:2972
15:01:48.289 > entry 0x400805dc

15:01:48.643 > ets Jul 29 2019 12:21:46
15:01:48.644 >
15:01:48.644 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:01:48.654 > configsip: 0, SPIWP:0xee
15:01:48.654 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:01:48.672 > mode:DIO, clock div:2
15:01:48.672 > load:0x3fff0030,len:1156
15:01:48.672 > load:0x40078000,len:11456
15:01:48.692 > ho 0 tail 12 room 4
15:01:48.692 > load:0x40080400,len:2972
15:01:48.692 > entry 0x400805dc
15:01:49.531 > [BOOT] reset_reason=DEEP_SLEEP
15:01:49.531 > [WAKE] cause=4
15:01:49.531 > [WDT] enabled timeout=4000 ms
15:01:49.531 > Commands:
15:01:49.531 > help
15:01:49.539 > status
15:01:49.539 > sensor
15:01:49.539 > relay on
15:01:49.539 > relay off
15:01:49.539 > save
15:01:49.540 > sleep <seconds>
15:01:49.540 > hang
15:01:49.540 > powerloss
15:01:49.540 > reboot
status
15:01:54.065 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":true,"counter":3,"heap":336332,"sensor_ok":t
rue}
sleep abc
15:02:07.978 > [STORE] saved
15:02:07.978 > [STATE] SLEEP timer=1 s
15:02:08.115 > ets Jul 29 2019 12:21:46
15:02:08.116 >
15:02:08.116 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:02:08.116 > configsip: 0, SPIWP:0xee
15:02:08.116 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:02:08.123 > mode:DIO, clock div:2
15:02:08.123 > load:0x3fff0030,len:1156
15:02:08.123 > load:0x40078000,len:11456
15:02:08.123 > ho 0 tail 12 room 4
15:02:08.123 > load:0x40080400,len:2972
15:02:08.139 > entry 0x400805dc

15:02:08.959 > [BOOT] reset_reason=DEEP_SLEEP
15:02:08.959 > [WAKE] cause=4
15:02:08.971 > [WDT] enabled timeout=4000 ms
15:02:08.971 > Commands:
15:02:08.971 > help
15:02:08.971 > status
15:02:08.971 > sensor
15:02:08.971 > relay on
15:02:08.971 > relay off
15:02:08.971 > save
15:02:08.971 > sleep <seconds>
15:02:08.971 > hang
15:02:08.971 > powerloss
15:02:08.971 > reboot
status
15:02:16.629 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":true,"counter":4,"heap":336332,"sensor_ok":true}

Підтвердження багу.

15:04:55.250 > ets Jul 29 2019 12:21:46
15:04:55.253 >
15:04:55.253 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:04:55.253 > configsip: 0, SPIWP:0xee
15:04:55.253 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:04:55.253 > mode:DIO, clock div:2
15:04:55.253 > load:0x3fff0030,len:1156
15:04:55.253 > load:0x40078000,len:11456
15:04:55.253 > ho 0 tail 12 room 4
15:04:55.253 > load:0x40080400,len:2972
15:04:55.253 > entry 0x400805dc
15:04:56.043 > [BOOT] reset_reason=POWER_ON
15:04:56.054 > [WDT] enabled timeout=4000 ms
15:04:56.054 > Commands:
15:04:56.054 > help
15:04:56.054 > status
15:04:56.054 > sensor
15:04:56.054 > relay on
15:04:56.054 > relay off
15:04:56.054 > save
15:04:56.054 > sleep <seconds>

15:04:56.054 > hang
15:04:56.054 > powerloss
15:04:56.054 > reboot
status
15:05:11.820 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}
sleep 10
15:05:21.275 > [STORE] saved
15:05:21.275 > [STATE] SLEEP timer=10 s
15:05:21.929 > ets Jul 29 2019 12:21:46
15:05:21.929 >
15:05:21.929 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:21.929 > configsip: 0, SPIWP:0xee
15:05:21.929 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:21.939 > mode:DIO, clock div:2
15:05:21.939 > load:0x3fff0030,len:1156
15:05:21.939 > load:0x40078000,len:11456
15:05:21.939 > ho 0 tail 12 room 4
15:05:21.939 > load:0x40080400,len:2972
15:05:21.958 > entry 0x400805dc
15:05:22.310 > ets Jul 29 2019 12:21:46
15:05:22.310 >
15:05:22.310 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:22.321 > configsip: 0, SPIWP:0xee
15:05:22.321 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:22.351 > mode:DIO, clock div:2
15:05:22.351 > load:0x3fff0030,len:1156
15:05:22.351 > load:0x40078000,len:11456
15:05:22.351 > ho 0 tail 12 room 4
15:05:22.364 > load:0x40080400,len:2972
15:05:22.364 > entry 0x400805dc
15:05:23.200 > [BOOT] reset_reason=DEEP_SLEEP
15:05:23.200 > [WAKE] cause=4
15:05:23.200 > [WDT] enabled timeout=4000 ms
15:05:23.200 > Commands:
15:05:23.200 > help
15:05:23.200 > status
15:05:23.200 > sensor
15:05:23.200 > relay on
15:05:23.200 > relay off
15:05:23.200 > save
15:05:23.200 > sleep <seconds>

15:05:23.206 > hang
15:05:23.206 > powerloss
15:05:23.206 > reboot
status
15:05:29.029 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1,"heap":336332,"sensor_ok":true}
sleep 10
15:05:35.826 > [STORE] saved
15:05:35.826 > [STATE] SLEEP timer=10 s
15:05:36.479 > ets Jul 29 2019 12:21:46
15:05:36.479 >
15:05:36.479 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:36.489 > configsip: 0, SPIWP:0xee
15:05:36.489 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:36.489 > mode:DIO, clock div:2
15:05:36.489 > load:0x3fff0030,len:1156
15:05:36.489 > load:0x40078000,len:11456
15:05:36.489 > ho 0 tail 12 room 4
15:05:36.510 > load:0x40080400,len:2972
15:05:36.510 > entry 0x400805dc
15:05:36.860 > ets Jul 29 2019 12:21:46
15:05:36.860 >
15:05:36.860 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:36.872 > configsip: 0, SPIWP:0xee
15:05:36.872 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:36.891 > mode:DIO, clock div:2
15:05:36.891 > load:0x3fff0030,len:1156
15:05:36.891 > load:0x40078000,len:11456
15:05:36.908 > ho 0 tail 12 room 4
15:05:36.908 > load:0x40080400,len:2972
15:05:36.908 > entry 0x400805dc
15:05:37.748 > [BOOT] reset_reason=DEEP_SLEEP
15:05:37.749 > [WAKE] cause=4
15:05:37.749 > [WDT] enabled timeout=4000 ms
15:05:37.749 > Commands:
15:05:37.749 > help
15:05:37.756 > status
15:05:37.756 > sensor
15:05:37.756 > relay on
15:05:37.756 > relay off
15:05:37.756 > save
15:05:37.757 > sleep <seconds>

15:05:37.757 > hang
15:05:37.757 > powerloss
15:05:37.757 > reboot
status
15:05:42.027 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":2,"heap":336332,"sensor_ok":true}
sleep 10
15:05:49.456 > [STORE] saved
15:05:49.456 > [STATE] SLEEP timer=10 s
15:05:50.113 > ets Jul 29 2019 12:21:46
15:05:50.113 >
15:05:50.113 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:50.122 > configsip: 0, SPIWP:0xee
15:05:50.122 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:50.122 > mode:DIO, clock div:2
15:05:50.122 > load:0x3fff0030,len:1156
15:05:50.122 > load:0x40078000,len:11456
15:05:50.122 > ho 0 tail 12 room 4
15:05:50.140 > load:0x40080400,len:2972
15:05:50.140 > entry 0x400805dc
15:05:50.493 > ets Jul 29 2019 12:21:46
15:05:50.493 >
15:05:50.493 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:05:50.504 > configsip: 0, SPIWP:0xee
15:05:50.504 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:05:50.522 > mode:DIO, clock div:2
15:05:50.522 > load:0x3fff0030,len:1156
15:05:50.522 > load:0x40078000,len:11456
15:05:50.547 > ho 0 tail 12 room 4
15:05:50.547 > load:0x40080400,len:2972
15:05:50.547 > entry 0x400805dc
15:05:51.382 > [BOOT] reset_reason=DEEP_SLEEP
15:05:51.382 > [WAKE] cause=4
15:05:51.382 > [WDT] enabled timeout=4000 ms
15:05:51.382 > Commands:
15:05:51.382 > help
15:05:51.382 > status
15:05:51.390 > sensor
15:05:51.390 > relay on
15:05:51.390 > relay off
15:05:51.390 > save
15:05:51.390 > sleep <seconds>

15:05:51.390 > hang
15:05:51.390 > powerloss
15:05:51.390 > reboot
status
15:05:55.782 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":3,"heap":336332,"sensor_ok":true}
sleep 10
15:06:02.206 > [STORE] saved
15:06:02.206 > [STATE] SLEEP timer=10 s
15:06:02.862 > ets Jul 29 2019 12:21:46
15:06:02.863 >
15:06:02.863 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:06:02.872 > configsip: 0, SPIWP:0xee
15:06:02.872 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:06:02.873 > mode:DIO, clock div:2
15:06:02.873 > load:0x3fff0030,len:1156
15:06:02.873 > load:0x40078000,len:11456
15:06:02.873 > ho 0 tail 12 room 4
15:06:02.890 > load:0x40080400,len:2972
15:06:02.890 > entry 0x400805dc
15:06:03.245 > ets Jul 29 2019 12:21:46
15:06:03.245 >
15:06:03.245 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:06:03.264 > configsip: 0, SPIWP:0xee
15:06:03.264 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:06:03.273 > mode:DIO, clock div:2
15:06:03.273 > load:0x3fff0030,len:1156
15:06:03.273 > load:0x40078000,len:11456
15:06:03.298 > ho 0 tail 12 room 4
15:06:03.298 > load:0x40080400,len:2972
15:06:03.298 > entry 0x400805dc
15:06:04.130 > [BOOT] reset_reason=DEEP_SLEEP
15:06:04.130 > [WAKE] cause=4
15:06:04.130 > [WDT] enabled timeout=4000 ms
15:06:04.130 > Commands:
15:06:04.130 > help
15:06:04.139 > status
15:06:04.139 > sensor
15:06:04.139 > relay on
15:06:04.139 > relay off
15:06:04.139 > save
15:06:04.139 > sleep <seconds>

15:06:04.140 > hang
15:06:04.140 > powerloss
15:06:04.140 > reboot
status
15:06:07.126 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":4,"heap":336332,"sensor_ok":true}
sleep 10
15:06:11.989 > [STORE] saved
15:06:11.989 > [STATE] SLEEP timer=10 s
15:06:12.646 > ets Jul 29 2019 12:21:46
15:06:12.646 >
15:06:12.646 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:06:12.656 > configsip: 0, SPIWP:0xee
15:06:12.656 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:06:12.656 > mode:DIO, clock div:2
15:06:12.656 > load:0x3fff0030,len:1156
15:06:12.656 > load:0x40078000,len:11456
15:06:12.656 > ho 0 tail 12 room 4
15:06:12.676 > load:0x40080400,len:2972
15:06:12.676 > entry 0x400805dc
15:06:13.028 > ets Jul 29 2019 12:21:46
15:06:13.029 >
15:06:13.029 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:06:13.039 > configsip: 0, SPIWP:0xee
15:06:13.039 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:06:13.059 > mode:DIO, clock div:2
15:06:13.059 > load:0x3fff0030,len:1156
15:06:13.059 > load:0x40078000,len:11456
15:06:13.098 > ho 0 tail 12 room 4
15:06:13.098 > load:0x40080400,len:2972
15:06:13.098 > entry 0x400805dc
15:06:13.909 > [BOOT] reset_reason=DEEP_SLEEP
15:06:13.909 > [WAKE] cause=4
15:06:13.910 > [WDT] enabled timeout=4000 ms
15:06:13.910 > Commands:
15:06:13.910 > help
15:06:13.910 > status
15:06:13.921 > sensor
15:06:13.921 > relay on
15:06:13.921 > relay off
15:06:13.921 > save
15:06:13.921 > sleep <seconds>

15:06:13.921 > hang
15:06:13.921 > powerloss
15:06:13.921 > reboot
status
15:06:17.634 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":5,"heap":336332,"sensor_ok":true}

R5

15:12:22.636 > ets Jul 29 2019 12:21:46
15:12:22.638 >
15:12:22.638 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:12:22.638 > configsip: 0, SPIWP:0xee
15:12:22.638 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:12:22.638 > mode:DIO, clock div:2
15:12:22.638 > load:0x3fff0030,len:1156
15:12:22.638 > load:0x40078000,len:11456
15:12:22.638 > ho 0 tail 12 room 4
15:12:22.638 > load:0x40080400,len:2972
15:12:22.638 > entry 0x400805dc
15:12:23.427 > [BOOT] reset_reason=POWER_ON
15:12:23.439 > [WDT] enabled timeout=4000 ms
15:12:23.439 > Commands:
15:12:23.439 > help
15:12:23.439 > status
15:12:23.439 > sensor
15:12:23.439 > relay on
15:12:23.439 > relay off
15:12:23.439 > save
15:12:23.439 > sleep <seconds>
15:12:23.439 > hang
15:12:23.439 > powerloss
15:12:23.439 > reboot
status
15:12:55.704 > [CLI] ERROR unknown command
status
15:12:58.663 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336284,"sensor_ok":true}
relay on
15:13:06.256 > [STORE] saved
15:13:06.256 > [RELAY] ON

hand
15:14:14.889 > [CLI] ERROR unknown command
hang
15:14:19.261 > [FAULT] firmware hang
15:14:23.439 > E (133088) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
15:14:23.440 > E (133088) task_wdt: - loopTask (CPU 1)
15:14:23.440 > E (133088) task_wdt: Tasks currently running:
15:14:23.744 > E (133088) task_wdt: CPU 0: IDLE0
15:14:23.744 > E (133088) task_wdt: CPU 1: loopTask
15:14:23.744 > E (133088) task_wdt: Aborting.
15:14:23.744 >
15:14:23.744 > abort() was called at PC 0x400dbf11 on core 0
15:14:23.744 >
15:14:23.744 >
15:14:23.744 > Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED
15:14:23.745 >
15:14:23.745 >
15:14:23.745 >
15:14:23.745 >
15:14:23.745 > ELF file SHA256: 7bf4d35d2b731f75
15:14:23.745 >
15:14:28.714 > ets Jul 29 2019 12:21:46
15:14:28.714 >
15:14:28.714 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:14:28.714 > configsip: 0, SPIWP:0xee
15:14:28.715 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:14:28.715 > mode:DIO, clock div:2
15:14:28.720 > load:0x3fff0030,len:1156
15:14:28.720 > load:0x40078000,len:11456
15:14:28.720 > ho 0 tail 12 room 4
15:14:28.720 > load:0x40080400,len:2972
15:14:28.731 > entry 0x400805dc
15:14:29.572 > [BOOT] reset_reason=INT_WDT
15:14:29.572 > [WDT] enabled timeout=4000 ms
15:14:29.572 > Commands:
15:14:29.572 > help
15:14:29.572 > status
15:14:29.573 > sensor
15:14:29.573 > relay on
15:14:29.573 > relay off
15:14:29.573 > save
15:14:29.573 > sleep <seconds>

15:14:29.573 > hang
15:14:29.573 > powerloss
15:14:29.573 > reboot
status
15:14:38.791 >
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":true,"counter":1,"heap":336332,"sensor_ok":true
}
hang
15:14:50.688 > [FAULT] firmware hang
15:14:54.848 > E (28861) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
15:14:54.849 > E (28861) task_wdt: - loopTask (CPU 1)
15:14:54.849 > E (28861) task_wdt: Tasks currently running:
15:14:55.139 > E (28861) task_wdt: CPU 0: IDLE0
15:14:55.139 > E (28861) task_wdt: CPU 1: loopTask
15:14:55.139 > E (28861) task_wdt: Aborting.
15:14:55.139 >
15:14:55.139 > abort() was called at PC 0x400dbf11 on core 0
15:14:55.139 >
15:14:55.139 >
15:14:55.139 > Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED
15:14:55.139 >
15:14:55.139 >
15:14:55.139 >
15:14:55.139 >
15:14:55.139 > ELF file SHA256: 7bf4d35d2b731f75
15:14:55.139 >
15:15:00.105 > ets Jul 29 2019 12:21:46
15:15:00.106 >
15:15:00.106 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:15:00.106 > configsip: 0, SPIWP:0xee
15:15:00.106 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:15:00.111 > mode:DIO, clock div:2
15:15:00.112 > load:0x3fff0030,len:1156
15:15:00.112 > load:0x40078000,len:11456
15:15:00.112 > ho 0 tail 12 room 4
15:15:00.118 > load:0x40080400,len:2972
15:15:00.118 > entry 0x400805dc
15:15:00.958 > [BOOT] reset_reason=INT_WDT
15:15:00.958 > [WDT] enabled timeout=4000 ms
15:15:00.958 > Commands:
15:15:00.958 > help
15:15:00.958 > status

15:15:00.958 > sensor
15:15:00.958 > relay on
15:15:00.958 > relay off
15:15:00.958 > save
15:15:00.958 > sleep <seconds>
15:15:00.958 > hang
15:15:00.958 > powerloss
15:15:00.958 > reboot
status
15:15:05.510 >
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":true,"counter":1,"heap":336332,"sensor_ok":true
}
hang
15:15:13.145 > [FAULT] firmware hang
15:15:17.308 > E (19363) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
15:15:17.309 > E (19363) task_wdt: - loopTask (CPU 1)
15:15:17.309 > E (19363) task_wdt: Tasks currently running:
15:15:17.603 > E (19363) task_wdt: CPU 0: IDLE0
15:15:17.603 > E (19363) task_wdt: CPU 1: loopTask
15:15:17.603 > E (19363) task_wdt: Aborting.
15:15:17.603 >
15:15:17.603 > abort() was called at PC 0x400dbf11 on core 0
15:15:17.604 >
15:15:17.604 >
15:15:17.604 > Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED
15:15:17.604 >
15:15:17.604 >
15:15:17.604 >
15:15:17.604 >
15:15:17.604 > ELF file SHA256: 7bf4d35d2b731f75
15:15:17.604 >
15:15:22.537 > ets Jul 29 2019 12:21:46
15:15:22.537 >
15:15:22.537 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:15:22.537 > configsip: 0, SPIWP:0xee
15:15:22.537 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:15:22.537 > mode:DIO, clock div:2
15:15:22.542 > load:0x3fff0030,len:1156
15:15:22.543 > load:0x40078000,len:11456
15:15:22.543 > ho 0 tail 12 room 4
15:15:22.543 > load:0x40080400,len:2972
15:15:22.551 > entry 0x400805dc

15:15:23.394 > [BOOT] reset_reason=INT_WDT
15:15:23.394 > [WDT] enabled timeout=4000 ms
15:15:23.394 > Commands:
15:15:23.394 > help
15:15:23.394 > status
15:15:23.394 > sensor
15:15:23.394 > relay on
15:15:23.394 > relay off
15:15:23.394 > save
15:15:23.394 > sleep <seconds>
15:15:23.394 > hang
15:15:23.394 > powerloss
15:15:23.394 > reboot
status
15:15:33.777 >
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":true,"counter":1,"heap":336332,"sensor_ok":true
}
hang
15:15:37.690 > [FAULT] firmware hang
15:15:41.851 > E (23035) task_wdt: Task watchdog got triggered. The following tasks did not reset the watchdog in time:
15:15:41.851 > E (23035) task_wdt: - loopTask (CPU 1)
15:15:41.851 > E (23035) task_wdt: Tasks currently running:
15:15:42.147 > E (23035) task_wdt: CPU 0: IDLE0
15:15:42.147 > E (23035) task_wdt: CPU 1: loopTask
15:15:42.147 > E (23035) task_wdt: Aborting.
15:15:42.148 >
15:15:42.148 > abort() was called at PC 0x400dbf11 on core 0
15:15:42.148 >
15:15:42.148 >
15:15:42.148 > Backtrace: 0x400835b5:0x3ffbea8c |<-CORRUPTED
15:15:42.148 >
15:15:42.148 >
15:15:42.148 >
15:15:42.148 >
15:15:42.148 > ELF file SHA256: 7bf4d35d2b731f75
15:15:42.148 >
15:15:47.118 > ets Jul 29 2019 12:21:46
15:15:47.118 >
15:15:47.118 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:15:47.118 > configsip: 0, SPIWP:0xee
15:15:47.118 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:15:47.123 > mode:DIO, clock div:2

15:15:47.124 > load:0x3fff0030,len:1156
15:15:47.124 > load:0x40078000,len:11456
15:15:47.124 > ho 0 tail 12 room 4
15:15:47.135 > load:0x40080400,len:2972
15:15:47.135 > entry 0x400805dc
15:15:47.981 > [BOOT] reset_reason=INT_WDT
15:15:47.981 > [WDT] enabled timeout=4000 ms
15:15:47.981 > Commands:
15:15:47.981 > help
15:15:47.981 > status
15:15:47.981 > sensor
15:15:47.981 > relay on
15:15:47.981 > relay off
15:15:47.981 > save
15:15:47.981 > sleep <seconds>
15:15:47.981 > hang
15:15:47.981 > powerloss
15:15:47.981 > reboot
status
15:15:52.056 >
{"state":"ACTIVE","reset_reason":"INT_WDT","relay":true,"counter":1,"heap":336332,"sensor_ok":true
}

R6

15:21:19.188 > ets Jul 29 2019 12:21:46
15:21:19.189 >
15:21:19.189 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:21:19.189 > configsip: 0, SPIWP:0xee
15:21:19.189 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:21:19.189 > mode:DIO, clock div:2
15:21:19.189 > load:0x3fff0030,len:1156
15:21:19.190 > load:0x40078000,len:11456
15:21:19.190 > ho 0 tail 12 room 4
15:21:19.190 > load:0x40080400,len:2972
15:21:19.190 > entry 0x400805dc
15:21:19.958 > [BOOT] reset_reason=POWER_ON
15:21:19.969 > [WDT] enabled timeout=4000 ms
15:21:19.969 > Commands:
15:21:19.969 > help
15:21:19.969 > status

15:21:19.969 > sensor
15:21:19.969 > relay on
15:21:19.969 > relay off
15:21:19.969 > save
15:21:19.969 > sleep <seconds>
15:21:19.969 > hang
15:21:19.969 > powerloss
15:21:19.969 > reboot
relay on
15:21:39.304 > [STORE] saved
15:21:39.304 > [RELAY] ON
save
15:21:45.094 > [CLI] ERROR unknown command
save
15:21:47.603 > [STORE] saved
status
15:21:51.926 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":true,"counter":2,"heap":336332,"sensor_ok":t
rue}
powerloss
15:22:06.763 > [FAULT] power loss DURING save
15:22:06.774 > ets Jul 29 2019 12:21:46
15:22:06.774 >
15:22:06.774 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:22:06.794 > configsip: 0, SPIWP:0xee
15:22:06.794 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:22:06.795 > mode:DIO, clock div:2
15:22:06.795 > load:0x3fff0030,len:1156
15:22:06.795 > load:0x40078000,len:11456
15:22:06.815 > ho 0 tail 12 room 4
15:22:06.815 > load:0x40080400,len:2972
15:22:06.815 > entry 0x400805dc
15:22:07.645 > [BOOT] reset_reason=SOFTWARE_RESET
15:22:07.646 > [WDT] enabled timeout=4000 ms
15:22:07.646 > Commands:
15:22:07.646 > help
15:22:07.646 > status
15:22:07.646 > sensor
15:22:07.653 > relay on
15:22:07.653 > relay off
15:22:07.653 > save
15:22:07.654 > sleep <seconds>
15:22:07.654 > hang

15:22:07.654 > powerloss
15:22:07.654 > reboot
status
15:22:17.730 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":102,"heap":336332,"sensor_ok":true}
powerloss
15:22:34.243 > [FAULT] power loss DURING save
15:22:34.254 > ets Jul 29 2019 12:21:46
15:22:34.254 >
15:22:34.254 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:22:34.279 > configsip: 0, SPIWP:0xee
15:22:34.279 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:22:34.279 > mode:DIO, clock div:2
15:22:34.279 > load:0x3fff0030,len:1156
15:22:34.279 > load:0x40078000,len:11456
15:22:34.294 > ho 0 tail 12 room 4
15:22:34.294 > load:0x40080400,len:2972
15:22:34.294 > entry 0x400805dc
15:22:35.128 > [BOOT] reset_reason=SOFTWARE_RESET
15:22:35.128 > [WDT] enabled timeout=4000 ms
15:22:35.128 > Commands:
15:22:35.128 > help
15:22:35.128 > status
15:22:35.138 > sensor
15:22:35.138 > relay on
15:22:35.138 > relay off
15:22:35.138 > save
15:22:35.138 > sleep <seconds>
15:22:35.138 > hang
15:22:35.138 > powerloss
15:22:35.138 > reboot
status
15:22:39.528 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":202,"heap":336332,"sensor_ok":true}
powerloss
15:22:45.832 > [FAULT] power loss DURING save
15:22:45.842 > ets Jul 29 2019 12:21:46
15:22:45.842 >
15:22:45.842 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:22:45.863 > configsip: 0, SPIWP:0xee
15:22:45.863 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00

15:22:45.863 > mode:DIO, clock div:2
15:22:45.863 > load:0x3fff0030,len:1156
15:22:45.863 > load:0x40078000,len:11456
15:22:45.880 > ho 0 tail 12 room 4
15:22:45.880 > load:0x40080400,len:2972
15:22:45.880 > entry 0x400805dc
15:22:46.714 > [BOOT] reset_reason=SOFTWARE_RESET
15:22:46.714 > [WDT] enabled timeout=4000 ms
15:22:46.714 > Commands:
15:22:46.714 > help
15:22:46.714 > status
15:22:46.714 > sensor
15:22:46.722 > relay on
15:22:46.722 > relay off
15:22:46.722 > save
15:22:46.722 > sleep <seconds>
15:22:46.722 > hang
15:22:46.722 > powerloss
15:22:46.722 > reboot
status
15:22:52.238 > [CLI] ERROR unknown command
status
15:22:54.828 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":302,"heap":336332,"se
nsor_ok":true}
powerloss
15:23:00.099 > [FAULT] power loss DURING save
15:23:00.108 > ets Jul 29 2019 12:21:46
15:23:00.108 >
15:23:00.108 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:23:00.128 > configsip: 0, SPIWP:0xee
15:23:00.128 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:23:00.128 > mode:DIO, clock div:2
15:23:00.128 > load:0x3fff0030,len:1156
15:23:00.128 > load:0x40078000,len:11456
15:23:00.144 > ho 0 tail 12 room 4
15:23:00.144 > load:0x40080400,len:2972
15:23:00.144 > entry 0x400805dc
15:23:00.980 > [BOOT] reset_reason=SOFTWARE_RESET
15:23:00.980 > [WDT] enabled timeout=4000 ms
15:23:00.980 > Commands:
15:23:00.980 > help
15:23:00.980 > status

15:23:00.987 > sensor
15:23:00.987 > relay on
15:23:00.987 > relay off
15:23:00.987 > save
15:23:00.987 > sleep <seconds>
15:23:00.987 > hang
15:23:00.988 > powerloss
15:23:00.988 > reboot
status
15:23:05.261 > [CLI] ERROR unknown command
status
15:23:07.914 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":402,"heap":336332,"se
nsor_ok":true}
powerloss
15:23:11.848 > [FAULT] power loss DURING save
15:23:11.858 > ets Jul 29 2019 12:21:46
15:23:11.858 >
15:23:11.858 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:23:11.881 > configsip: 0, SPIWP:0xee
15:23:11.881 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:23:11.881 > mode:DIO, clock div:2
15:23:11.881 > load:0x3fff0030,len:1156
15:23:11.910 > load:0x40078000,len:11456
15:23:11.910 > ho 0 tail 12 room 4
15:23:11.910 > load:0x40080400,len:2972
15:23:11.910 > entry 0x400805dc
15:23:12.731 > [BOOT] reset_reason=SOFTWARE_RESET
15:23:12.731 > [WDT] enabled timeout=4000 ms
15:23:12.731 > Commands:
15:23:12.731 > help
15:23:12.739 > status
15:23:12.739 > sensor
15:23:12.739 > relay on
15:23:12.739 > relay off
15:23:12.739 > save
15:23:12.739 > sleep <seconds>
15:23:12.739 > hang
15:23:12.739 > powerloss
15:23:12.739 > reboot
status
15:23:15.913 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":502,"heap":336332,"se

nsor_ok":true}
powerloss
15:23:24.099 > [FAULT] power loss DURING save
15:23:24.108 > ets Jul 29 2019 12:21:46
15:23:24.109 >
15:23:24.109 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:23:24.129 > configsip: 0, SPIWP:0xee
15:23:24.129 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:23:24.129 > mode:DIO, clock div:2
15:23:24.129 > load:0x3fff0030,len:1156
15:23:24.129 > load:0x40078000,len:11456
15:23:24.142 > ho 0 tail 12 room 4
15:23:24.142 > load:0x40080400,len:2972
15:23:24.142 > entry 0x400805dc
15:23:24.976 > [BOOT] reset_reason=SOFTWARE_RESET
15:23:24.977 > [WDT] enabled timeout=4000 ms
15:23:24.977 > Commands:
15:23:24.978 > help
15:23:24.978 > status
15:23:24.986 > sensor
15:23:24.986 > relay on
15:23:24.986 > relay off
15:23:24.986 > save
15:23:24.986 > sleep <seconds>
15:23:24.986 > hang
15:23:24.986 > powerloss
15:23:24.986 > reboot
status
15:23:29.013 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":602,"heap":336332,"se
nsor_ok":true}
reboot
15:23:36.703 > ets Jul 29 2019 12:21:46
15:23:36.703 >
15:23:36.703 > rst:0xc (SW_CPU_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:23:36.703 > configsip: 0, SPIWP:0xee
15:23:36.703 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:23:36.715 > mode:DIO, clock div:2
15:23:36.715 > load:0x3fff0030,len:1156
15:23:36.715 > load:0x40078000,len:11456
15:23:36.715 > ho 0 tail 12 room 4
15:23:36.715 > load:0x40080400,len:2972
15:23:36.715 > entry 0x400805dc

15:23:37.528 > [BOOT] reset_reason=SOFTWARE_RESET
15:23:37.537 > [WDT] enabled timeout=4000 ms
15:23:37.537 > Commands:
15:23:37.538 > help
15:23:37.538 > status
15:23:37.538 > sensor
15:23:37.538 > relay on
15:23:37.538 > relay off
15:23:37.538 > save
15:23:37.538 > sleep <seconds>
15:23:37.538 > hang
15:23:37.538 > powerloss
15:23:37.538 > reboot
statur
15:23:47.336 > [CLI] ERROR unknown command
status
15:23:50.661 >
{"state":"ACTIVE","reset_reason":"SOFTWARE_RESET","relay":true,"counter":602,"heap":336332,"sensor_ok":true}

T09

15:32:29.627 > ets Jul 29 2019 12:21:46
15:32:29.629 >
15:32:29.629 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:32:29.629 > configsip: 0, SPIWP:0xee
15:32:29.629 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:32:29.629 > mode:DIO, clock div:2
15:32:29.629 > load:0x3fff0030,len:1156
15:32:29.629 > load:0x40078000,len:11456
15:32:29.629 > ho 0 tail 12 room 4
15:32:29.629 > load:0x40080400,len:2972
15:32:29.629 > entry 0x400805dc
15:32:30.400 > [BOOT] reset_reason=POWER_ON
15:32:30.410 > [WDT] enabled timeout=4000 ms
15:32:30.410 > Commands:
15:32:30.411 > help
15:32:30.411 > status
15:32:30.411 > sensor
15:32:30.411 > relay on
15:32:30.411 > relay off

15:32:30.411 > save
15:32:30.411 > sleep <seconds>
15:32:30.411 > hang
15:32:30.411 > powerloss
15:32:30.411 > reboot
status
15:32:42.884 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}
sleep 60
15:32:48.764 > [STORE] saved
15:32:48.764 > [STATE] SLEEP timer=60 s
15:32:49.419 > ets Jul 29 2019 12:21:46
15:32:49.419 >
15:32:49.419 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:32:49.420 > configsip: 0, SPIWP:0xee
15:32:49.420 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:32:49.428 > mode:DIO, clock div:2
15:32:49.428 > load:0x3fff0030,len:1156
15:32:49.428 > load:0x40078000,len:11456
15:32:49.428 > ho 0 tail 12 room 4
15:32:49.428 > load:0x40080400,len:2972
15:32:49.448 > entry 0x400805dc
15:32:50.273 > [BOOT] reset_reason=INT_WDT
15:32:50.273 > [WDT] enabled timeout=4000 ms
15:32:50.280 > Commands:
15:32:50.280 > help
15:32:50.280 > status
15:32:50.280 > sensor
15:32:50.281 > relay on
15:32:50.281 > relay off
15:32:50.281 > save
15:32:50.281 > sleep <seconds>
15:32:50.281 > hang
15:32:50.281 > powerloss
15:32:50.281 > reboot
15:32:54.820 > ets Jul 29 2019 12:21:46
15:32:54.821 >
15:32:54.821 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:32:54.829 > configsip: 0, SPIWP:0xee
15:32:54.829 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:32:54.844 > mode:DIO, clock div:2
15:32:54.844 > load:0x3fff0030,len:1156

15:32:54.844 > load:0x40078000,len:11456
15:32:54.844 > ho 0 tail 12 room 4
15:32:54.868 > load:0x40080400,len:2972
15:32:54.868 > entry 0x400805dc
15:32:55.704 > [BOOT] reset_reason=DEEP_SLEEP
15:32:55.705 > [WAKE] cause=4
15:32:55.705 > [WDT] enabled timeout=4000 ms
15:32:55.705 > Commands:
15:32:55.705 > help
15:32:55.705 > status
15:32:55.705 > sensor
15:32:55.705 > relay on
15:32:55.705 > relay off
15:32:55.705 > save
15:32:55.705 > sleep <seconds>
15:32:55.711 > hang
15:32:55.711 > powerloss
15:32:55.711 > reboot
status
15:32:59.855 >
{"state":"ACTIVE","reset_reason":"DEEP_SLEEP","relay":false,"counter":1,"heap":336332,"sensor_ok":true}

T11

15:40:18.216 > ets Jul 29 2019 12:21:46
15:40:18.216 >
15:40:18.216 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:40:18.216 > configsip: 0, SPIWP:0xee
15:40:18.216 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:40:18.217 > mode:DIO, clock div:2
15:40:18.217 > load:0x3fff0030,len:1156
15:40:18.217 > load:0x40078000,len:11456
15:40:18.217 > ho 0 tail 12 room 4
15:40:18.217 > load:0x40080400,len:2972
15:40:18.217 > entry 0x400805dc
15:40:19.007 > [BOOT] reset_reason=POWER_ON
15:40:19.013 > [WDT] enabled timeout=4000 ms
15:40:19.013 > Commands:
15:40:19.013 > help
15:40:19.014 > status

15:40:19.014 > sensor
15:40:19.014 > relay on
15:40:19.014 > relay off
15:40:19.014 > save
15:40:19.014 > sleep <seconds>
15:40:19.014 > hang
15:40:19.014 > powerloss
15:40:19.014 > reboot
status
15:40:25.719 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}
sleep 60
15:40:43.548 > [STORE] saved
15:40:43.548 > [STATE] SLEEP timer=60 s
15:40:44.204 > ets Jul 29 2019 12:21:46
15:40:44.204 >
15:40:44.204 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:40:44.204 > configsip: 0, SPIWP:0xee
15:40:44.213 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:40:44.213 > mode:DIO, clock div:2
15:40:44.213 > load:0x3fff0030,len:1156
15:40:44.214 > load:0x40078000,len:11456
15:40:44.214 > ho 0 tail 12 room 4
15:40:44.214 > load:0x40080400,len:2972
15:40:44.231 > entry 0x400805dc
15:40:45.039 > [BOOT] reset_reason=INT_WDT
15:40:45.047 > [WDT] enabled timeout=4000 ms
15:40:45.047 > Commands:
15:40:45.047 > help
15:40:45.047 > status
15:40:45.047 > sensor
15:40:45.047 > relay on
15:40:45.047 > relay off
15:40:45.047 > save
15:40:45.047 > sleep <seconds>
15:40:45.047 > hang
15:40:45.047 > powerloss
15:40:45.047 > reboot
15:40:49.585 > ets Jul 29 2019 12:21:46
15:40:49.586 >
15:40:49.586 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:40:49.596 > configsip: 0, SPIWP:0xee

15:40:49.596 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:40:49.613 > mode:DIO, clock div:2
15:40:49.613 > load:0x3fff0030,len:1156
15:40:49.613 > load:0x40078000,len:11456
15:40:49.613 > ho 0 tail 12 room 4
15:40:49.655 > load:0x40080400,len:2972
15:40:49.655 > entry 0x400805dc
15:40:50.474 > [BOOT] reset_reason=DEEP_SLEEP
15:40:50.474 > [WAKE] cause=4
15:40:50.475 > [WDT] enabled timeout=4000 ms
15:40:50.475 > Commands:
15:40:50.475 > help
15:40:50.475 > status
15:40:50.475 > sensor
15:40:50.475 > relay on
15:40:50.475 > relay off
15:40:50.482 > save
15:40:50.482 > sleep <seconds>
15:40:50.482 > hang
15:40:50.482 > powerloss
15:40:50.483 > reboot

replay

15:41:36.457 > ets Jul 29 2019 12:21:46
15:41:36.458 >
15:41:36.458 > rst:0x1 (POWERON_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:41:36.458 > configsip: 0, SPIWP:0xee
15:41:36.458 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:41:36.458 > mode:DIO, clock div:2
15:41:36.458 > load:0x3fff0030,len:1156
15:41:36.458 > load:0x40078000,len:11456
15:41:36.458 > ho 0 tail 12 room 4
15:41:36.458 > load:0x40080400,len:2972
15:41:36.458 > entry 0x400805dc
15:41:37.238 > [BOOT] reset_reason=POWER_ON
15:41:37.246 > [WDT] enabled timeout=4000 ms
15:41:37.246 > Commands:
15:41:37.246 > help
15:41:37.246 > status
15:41:37.246 > sensor
15:41:37.246 > relay on
15:41:37.246 > relay off
15:41:37.246 > save

15:41:37.246 > sleep <seconds>
15:41:37.246 > hang
15:41:37.246 > powerloss
15:41:37.247 > reboot
status
15:41:42.791 >
{"state":"ACTIVE","reset_reason":"POWER_ON","relay":false,"counter":0,"heap":336332,"sensor_ok":true}
sleep 60
15:41:57.685 > [STORE] saved
15:41:57.686 > [STATE] SLEEP timer=60 s
15:41:58.335 > ets Jul 29 2019 12:21:46
15:41:58.335 >
15:41:58.335 > rst:0x8 (TG1WDT_SYS_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:41:58.336 > configsip: 0, SPIWP:0xee
15:41:58.346 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:41:58.346 > mode:DIO, clock div:2
15:41:58.346 > load:0x3fff0030,len:1156
15:41:58.346 > load:0x40078000,len:11456
15:41:58.346 > ho 0 tail 12 room 4
15:41:58.346 > load:0x40080400,len:2972
15:41:58.363 > entry 0x400805dc
15:41:59.172 > [BOOT] reset_reason=INT_WDT
15:41:59.172 > [WDT] enabled timeout=4000 ms
15:41:59.180 > Commands:
15:41:59.180 > help
15:41:59.180 > status
15:41:59.180 > sensor
15:41:59.180 > relay on
15:41:59.180 > relay off
15:41:59.181 > save
15:41:59.181 > sleep <seconds>
15:41:59.181 > hang
15:41:59.181 > powerloss
15:41:59.181 > reboot
15:42:03.718 > ets Jul 29 2019 12:21:46
15:42:03.719 >
15:42:03.719 > rst:0x5 (DEEPSLEEP_RESET),boot:0x13 (SPI_FAST_FLASH_BOOT)
15:42:03.729 > configsip: 0, SPIWP:0xee
15:42:03.729 > clk_drv:0x00,q_drv:0x00,d_drv:0x00,cs0_drv:0x00,hd_drv:0x00,wp_drv:0x00
15:42:03.746 > mode:DIO, clock div:2
15:42:03.746 > load:0x3fff0030,len:1156
15:42:03.746 > load:0x40078000,len:11456

15:42:03.746 > ho 0 tail 12 room 4
15:42:03.764 > load:0x40080400,len:2972
15:42:03.764 > entry 0x400805dc
15:42:04.609 > [BOOT] reset_reason=DEEP_SLEEP
15:42:04.609 > [WAKE] cause=4
15:42:04.609 > [WDT] enabled timeout=4000 ms
15:42:04.610 > Commands:
15:42:04.610 > help
15:42:04.610 > status
15:42:04.610 > sensor
15:42:04.610 > relay on
15:42:04.610 > relay off
15:42:04.610 > save
15:42:04.610 > sleep <seconds>
15:42:04.616 > hang
15:42:04.616 > powerloss
15:42:04.616 > reboot